

03997363

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Ins.
Box 45064 Regent Postal O
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



Date Inspection Started DAY: 09 MO: 01 YR: 26	Station Number A53917	Station Name Sunny HD Service	City Winnipeg	Province MB	Postal Code R2C 5C7	Phone A983987
Date Inspection Completed DAY: 09 MO: 01 YR: 26	Mechanic Number M010810	Mechanic Signature [Signature]	Station Phone Number 204 6321818			
Inspection Expiry Date DAY: 31 MO: 01 YR: 27	Vehicle Owner [Blank]					
Address [Blank]						
City [Blank]						
Province [Blank]						
Postal Code [Blank]						
Phone [Blank]						
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number FWE236	Prov. MB	NSC # MB913383	Odometer Reading 1030766	Odom. Type km ☒ mi ☐	Unit # [Blank]
Vehicle Identification Number 2FUTAB6CV65L409789						
Make Ford						
Model G6000						
Year 05						
Confirmed legible Vehicle Identification Number on vehicle ☒						

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☒ GVWR ☒ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section												
X	X	Section 1 - Power Train: Defects (if any) Engine Fan Clutch Air leak, exhaust tip loose (2E)												
X	X	Hyd pump cl-oints loose (4A)												
X	X	Section 2 Suspension: Defects (if any) Rear drive Airbags cracked cords showing (5B)												
X	X	Section 3 - Brake Systems: 3H (3A)												
		Defects (if any) Circle Brake Type												
		Both front steer shoes cracking (15B)												
		All rear drums cracked (15B)												
X	X	Section 4 - Steering: Defects (if any) Kingpins (1B)												
		Tie rods excessive play (1B)												
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) windshield wipers, Fire extinguisher not mounted (1B)												
X	X	Section 6 - Lamps: Defects (if any) Left lower E+M Marker lights inop (1A)												
		top clearance light (2), RF-LF head light covered (1A)												
X	X	Section 7 - Electrical System: Defects (if any) No battery hold down (2C)												
X	X	Section 8 - Body: Defects (if any) No battery cover												
		Driver's steps (10A), Passenger door mirror missing, Drivers windshield cracked												
X	X	Section 9 - Tire & Wheel: Defects (if any) Front steer wheel bearings discolored 6B												
		Front steer tires (20)												
		Tread Depth												
		Axle	Initial	Corrected	Air Pressure	Initial	Corrected							
			L	R	L	R	L	R						
		1	1/2	1/2	66	100	100	100						
		2												
		3	9	10	9	68	70	70	100	100	100	100		
		4	8	20	6	10	65	60	70	71	100	100	100	100
		5												
X	X	Section 10 - Coupling Devices: Defects (if any) Rear Hitch bent (1A)												

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: