

03637370

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Post
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

Date Inspection Started

30

07

24

DAY

MO.

YR.

Date Inspection Completed

30

07

24

DAY

MO.

YR.

Inspection Expiry Date

31

07

25

DAY

MO.

YR.

Station Number

C011917

Station Name

C+B STIRLING ENT L

City

Winnipeg

Station Phone Number

204-546-2311

Mechanic Number

Station Phone Number

204-546-2311

Pass/Safe Vehicle

Fail/Unsafe Vehicle

Fail/Hazardous

Licence Number

Vehicle Identification Number

AM11AA18PX SWC46498

Confirmed legible Vehicle Identification Number on vehicle

Prov.

MB

NSC #

Odometer Reading

373324

Odom. Type

km

Make

MAZDA

Model

613

Year

94

Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																											
X		Section 1 - Power Train: Defects (if any)																																																																											
X		Section 2 Suspension: Defects (if any)																																																																											
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																											
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																											
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>112</td><td>112</td><td>15.52</td><td>15.52</td><td>1</td><td>1</td></tr><tr><td>2</td><td>5/8</td><td>5/8</td><td>16.56</td><td>16.56</td><td>1</td><td>1</td></tr><tr><td>3</td><td>5/8</td><td>5/8</td><td>16.56</td><td>16.56</td><td>1</td><td>1</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	112	112	15.52	15.52	1	1	2	5/8	5/8	16.56	16.56	1	1	3	5/8	5/8	16.56	16.56	1	1	4							5							Final Measurement																										
Axle	Lining			Drum/Rotor		Stroke																																																																							
	L	R	L	R	L	R																																																																							
1	112	112	15.52	15.52	1	1																																																																							
2	5/8	5/8	16.56	16.56	1	1																																																																							
3	5/8	5/8	16.56	16.56	1	1																																																																							
4																																																																													
5																																																																													
Final Measurement																																																																													
X		Section 4 - Steering: Defects (if any)																																																																											
X		Section 5 - Instruments & Auxilliary Equipment: Defects (if any)																																																																											
X		Section 6 - Lamps: Defects (if any)																																																																											
X		Section 7 - Electrical System: Defects (if any)																																																																											
X		Section 8 - Body: Defects (if any)																																																																											
X		Section 9 - Tire & Wheel: Defects (if any)																																																																											
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td></td><td>15</td><td>15</td><td></td><td></td><td>105</td><td>105</td><td></td><td></td></tr><tr><td>2</td><td>4</td><td>6</td><td>8</td><td>7</td><td></td><td>105</td><td>105</td><td>105</td><td>105</td></tr><tr><td>3</td><td>22</td><td>11</td><td>5</td><td>3</td><td></td><td>105</td><td>105</td><td>105</td><td>105</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1		15	15			105	105			2	4	6	8	7		105	105	105	105	3	22	11	5	3		105	105	105	105	4										5									
Axle	Tread Depth				Air Pressure																																																																								
	Initial			Corrected		Initial		Corrected																																																																					
	L	R	L	R	L	R	L	R																																																																					
1		15	15			105	105																																																																						
2	4	6	8	7		105	105	105	105																																																																				
3	22	11	5	3		105	105	105	105																																																																				
4																																																																													
5																																																																													
X		Section 10 - Coupling Devices: Defects (if any)																																																																											

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

FVS0022-01-(R-09/15) Ce document peut être obtenu en français sur demande.