



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A249935

Station #: 71821

Station Name: Lonestar Auto Repair & Towing

Technician #: 88286

Technician Name: Leonard Lanegraff

Signing Officer #: 87961

Signing Officer Name: Cody Hobelsberger

Customer Details:

Name: CROPMAX ACRES LTD

Address: BOX 488, CUT KNIFE, Saskatchewan, S0M 0N0

Inspection Completed Date: 21Nov2025

Inspection Expiry Date: 30Nov2026

Vehicle Details:

VIN: 2DEGBSA29J2038684

Hubometer Reading:

Year: 2018

Vehicle Make/Model: DOEPKER TRAILER/TRAILER

Plate: 538 KVC

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71821	Station Name: Lonestar Auto Repair & Towing
Technician #: 88286	Technician Name: Leonard Lanegraff
Signing Officer #: 87961	Signing Officer Name: Cody Hobelsberger

Customer Details:	
Name: CROPMAX ACRES LTD	Address: BOX 488, CUT KNIFE, Saskatchewan, S0M 0N0

Vehicle Details:	
VIN: 2DEGBSA29J2038684	Hubometer Reading:
Year: 2018	Vehicle Make/Model: DOEPKER TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

**Axle 1-Pass**

Wheel1 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 42 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 56 degrees • Brake Stroke: 1 7/16 in

Wheel4 : Tire Tread Depth: 7 mm

Brake(1): No Brake

N/A

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 42 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 56 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A249935

Inspection Completed Date: 21Nov2025