



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A291573

Station #: 70207	Station Name: Frontline Truck & Trailer
Technician #: 90551	Technician Name: Oliver Moseley
Signing Officer #: 90414	Signing Officer Name: Howard Thomson

Customer Details:	
Name: TREWIN FARM CORP	Address: BOX 102, LAIRD, Saskatchewan, S0K 2H0

Inspection Completed Date: 16Jun2026	Inspection Expiry Date: 31Dec2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 3AKJGND11LDKV5826	Odometer Reading: 76561 km
Year: 2020	Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE
Plate:	Jurisdiction:
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70207

Station Name: Frontline Truck & Trailer

Technician #: 90551

Technician Name: Oliver Moseley

Signing Officer #: 90414

Signing Officer Name: Howard Thomson

Customer Details:

Name: TREWIN FARM CORP

Address: BOX 102, LAIRD, Saskatchewan, S0K 2H0

Vehicle Details:

VIN: 3AKJGND11LDKV5826

Odometer Reading: 76561 km

Year: 2020

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
			x	Lamps (6)	FOG LAMPS INOPERABLE
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

		x		Air Brake System/Components (3.2)	- RF STEER, LF STEER BRAKES DRAGGING/SEIZED. Replaced clevis pins on steer & also on all 4 drive wheels, seized & sticking.
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25 degrees • Brake Stroke: 1 1/4 in

Wheel2-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25 degrees • Brake Stroke: 1 1/4 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 19/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 19/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 19/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 19/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 25.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A291573

Inspection Completed Date: 16Jun2026