

Veh#	Date	W/O#	Description	Notes	Odometer
216	09/30/2026	1373092	Mechanic entered - Elec and Light Flat Batteries	Jump started bus with 48 volts as it was completely dead. Bought it to work shop and put it on charge	1423861
216	09/30/2026	1364219		COMPLETED 16.08.2026	1423861
216	07/31/2026	1358400	Service	VEHICLE SAFETY INSPECTION Bus decommissioned for sale	1423861
216	07/31/2026	1358400	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1423861
216	07/27/2026	1357208	Service	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Bus decommission for auction	1423861
216	07/22/2026	1356234		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1423861
216	07/22/2026	1356234		PRE ANNUAL SAFETY INSPECTION CHECK Bus not in service and ready for sending to auction	1423861
216	06/12/2026	1345216		Removed the stickers from the bus and radio	1423861
216	06/12/2026	1345216		removed 2way radio and ventura stickers.	1423861
216	06/12/2026	1345216		Removed the two way radio and all the exterior ventura stickers. Completed	1423861
216	06/12/2026	1345216	Consumables		1423861
216	06/10/2026	1346806	Service	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Bus decommissioned for sale and pending	1423861
216	06/10/2026	1346806		CARRY OUT A/C - A SERVICE AS PER CHECK LIST As above	1423861
216	06/09/2026	1345216		checked for all the eletronic and eletrical items to be removed ok. number plates rivets taken and put the screws for rear. c/o	1423861
216	06/02/2026	1345216		Removed e tag. bus minder push to talk and mdvr	1423861
216	06/02/2026	1345216	Decommission of Bus for Auction	removed etag busminder push and talk and MDVR.	1423861
216	05/05/2026	1338753	Mechanic entered - Warning Lights Engine Red warning light o	Checked found engine oil in max level. Drained engine oil level and checked ok.	1423744
216	04/27/2026	1336805		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Lachlan.	1423568
216	04/27/2026	1336805		Assisted indika with safety inspection.	1423568
216	04/27/2026	1336805		VEHICLE SAFETY INSPECTION carried out safety inspection as per check list.	1423568
216	04/27/2026	1336814	VALVE OVERFLOW MERC 0500LE 50G4604W D9195221		1423568
216	04/27/2026	1336814	Mechanic entered - Air System Air_Leak Rear Air leaking from	Replaced overflow valve.	1423568
216	04/17/2026	1334704		completed carried out air sytem service as per checked list. and repair air line broked hose.	1423568
216	04/17/2026	1334704	ELBOW COUPLING 90 DEGREES MERC BENZ 0500LE		1423568
216	04/17/2026	1334704	VOSS NUT 232 22MM MERC BENZ 0500LE		1423568
216	04/17/2026	1334704	AIR DRYER ASSY MERC 0500LE		1423568
216	04/17/2026	1334704	O-RING SEAL AIR DRYER CIRCUIT PROT VALVE MERC 0500LE		1423568
216	04/17/2026	1334704		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed air system checked and repaired broken air line wiwth new fitting	1423568
216	04/17/2026	1334704	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1423568
216	03/24/2026	1321246	BELT MICRO V SERPENT 9 RIB 2010mm LNG	FOUND IN STORE - MARKED DO NOT USE FOR BUS 216 ???	1423568
216	03/23/2026	1329543	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Retension wheel nuts w/ Guri pos.34 to 600Nm.	1423568
216	03/23/2026	1329543		Assisted Abraham	1423568
216	03/23/2026	1329543	Consumables		1423568
216	03/22/2026	1328451		Fire Extinguisher Test & Tag - Completed by ATS – February 2026	1423568
216	03/20/2026	1328535	BELT MICRO V SERPENTINE BELT 9	Creditor #;GB-MUL001 MULTISPARES LTD P/O #;G406763 Receiving #;432452 Date :2026-03-20 BELT	1423568
216	03/20/2026	1328535	PIPE OIL FILTER TO BLOCK 0500LE 50A7701		1423568
216	03/20/2026	1328535		replaced engine drivr belt oil filter pipe	1423568
216	03/20/2026	1328535		Assisted Sisil replace engine driver belt then went on road test with Sisil stopped half way to check belts okay. Came back and found that oil filter pipe leaking. Replaced oil filter pipe then cleaned the engine then went on road test to make sure it isnt leaking anymore found everything okay. Completed.	1423568
216	03/20/2026	1328535		replaced leaked oil pipe fitted new belt steam cleaned road tested ok	1423568
216	03/19/2026	1328535	Breakdown Belts Pulleys & Idler Bearings	Bus B/D south road left from W/S 8am back 9.30am used B/D van temprry repaired with cable tie driver drive the bus to depot. steam cleaned c/o	1423568
216	03/19/2026	1328535	BELT MICRO V SERPENT 9 RIB 201	Creditor #;GB-MUL001 MULTISPARES LTD P/O #;G406763 Receiving #;432518 Date :2026-03-23	1423568
216	03/17/2026	1328002	PTI Tablet Entered -Wheels and Tyres - Flat or LeakingP3	Fitted orig tread runout tyre pos.4 scraped paint on rim surface and tensioned wheel nuts pos.34 w/ Kuma to 600Nm.	1423372
216	03/17/2026	1328002	Consumables		1423372
216	02/20/2026	1321246		Put new belt for Ac but it was coming out when engine is started adjusted ac compressor and tensioner behind the pulley. Checked all pulleys are staright and belt is tight and moving around. Put all belts and made sure they are tight as well as the bolts Checked everything is in place and working fine after driving Complet	1422853
216	02/20/2026	1321246		Observed and helped Zakir put all the new belts onto the bus. Dulkith taught us how to tighten and untighten the AC compressor belt. Checked that all belts were sitting properly by half cranking the engine. Completed	1422853
216	02/20/2026	1321963	STRUT GAS STAY 350Nm 565mm LONG		1422853
216	02/20/2026	1321963	Mechanic entered - Body Other Rear hatches struts faulty.	Replaced Rear hatches struts as the previous ones were faulty. Completed.	1422853
216	02/20/2026	1321963	Consumables		1422853
216	02/20/2026	1321889		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Carried out CCTV A service as per check list. Found that their was an error light on because of the SSD hard drive being to old. Replaced with a new one and checked everything is working. Completed	1422853
216	02/20/2026	1321889		Assisted in replacing hard rive checked new one is recording fine Complete.	1422853
216	02/18/2026	1321246	BELT MICRO V SERPENT 9 RIB 201	Creditor #;GB-MUL001 MULTISPARES LTD P/O #;G404911 Receiving #;430711 Date :2026-02-24	1423028
216	02/17/2026	1321246	Engine Belts_Loose Noisy Missing	part on orderc/o.	1422853
216	02/17/2026	1321246	Engine Belts_Loose Noisy Missing		1422853
216	01/30/2026	1317482		VEHICLE SAFETY INSPECTION Completed VSI.	1422664
216	01/30/2026	1317482		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Retensioned wheel nuts w/ Guri.	1422664
216	01/30/2026	1317482		Assisted and retensioned wheel nuts w/ Abraham.	1422664
216	11/07/2025	1301586		Assisted Abraham with Saftey inspection and tensioned all wheelnuts to 600Nm with Abraham	1422213
216	11/07/2025	1301586		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Retensioned wheel nuts w/ Aaron to 600Nm.	1422213
216	11/07/2025	1301586		VEHICLE SAFETY INSPECTION Completed VSI.	1422213
216	10/21/2025	1298105	PTI Tablet Entered -Elec and Light - Exterior Lights o/s hea	Replaced globe	1422013
216	10/21/2025	1298105	Consumables		1422013
216	10/21/2025	1298106	Driver Tablet Entered -Body - Mirrors Exterior left side. lo	Secured mirror.	1422013
216	10/17/2025	1297215		CARRY OUT A SERVICE AS PER CHECK LIST carried out a service as per check list and tensioned all wheel nuts with indika 600nm	1422013
216	10/17/2025	1297215	Consumables		1422013
216	10/17/2025	1297215	Consumables		1422013
216	10/17/2025	1297215	Consumables		1422013
216	09/01/2025	1282511	Annaul ASI - 13.08.2025 - 593	Creditor #;GB-ROA001 ROAD SAFETY INSPECTIONS P/O #;G393202 Receiving #;419317 Date :2025-09-09	1420948
216	08/31/2025	1286878		FIRE EXTINGUISHER TEST & TAG - COMPLETED BY ATS	1420940
216	08/13/2025	1282511		VEHICLE SAFETY INSPECTION - Assisting Assisted.	1420867
216	08/13/2025	1282511		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS - Assisting	1420867
216	08/13/2025	1282511		ANNUAL SAFETY INSPECTION SERIAL #RSI 070516 - PASS - 13.08.2025 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 - Assisting	1420867
216	08/11/2025	1281923	Carryout final inspection for RSI	Assist Satheesh with final inspection	1420862
216	08/11/2025	1281923		completed.	1420862
216	08/11/2025	1281923	Consumables		1420862
216	07/28/2025	1278899		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list descale coils	1420828
216	07/28/2025	1278899	MIZU A/C FOAM CLEANER SPRAY		1420828
216	07/17/2025	1276652		Assisted and steam cleaned.	1420801
216	07/17/2025	1276652	DECAL EMERGENCY EXIT ROCK BLACK/WHITE		1420801
216	07/17/2025	1276652	Service	Assisted and steam cleaned.	1420801
216	07/17/2025	1276824	Mechanic entered - Elec and Light Exterior Lights O/s Low Be	Replaced the headlamp as it was rusted from inside checked new one is working fine Complete.	1420801
216	07/17/2025	1276824	HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525		1420801
216	07/17/2025	1276824	Consumables		1420801
216	07/17/2025	1276802	Mechanic entered - Air System Air_Leak Rear o/s near rear w	fixed leaks in the fittings with the Repair kit and connector. secured Air lines with Cable ties. (Connections Around the Air Drier abd 4Way valve.)	1420801
216	07/17/2025	1276802	FITTING STRAIGHT JOINER 8MM SMC		1420801
216	07/17/2025	1276802	O-RING KIT LARGE VOSS A6739970145		1420801
216	07/16/2025	1276597		Assisted.	1420801
216	07/16/2025	1276597		VEHICLE SAFETY INSPECTION completed.	1420799
216	07/16/2025	1276597		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Re-tensioned wheel nuts with Aaron.	1420799
216	07/16/2025	1276652		PRE ANNUAL SAFETY INSPECTION CHECK completed and Re-tensioned wheel nuts with Aaron. Fitted new Emergency exit Decal.	1420799
216	07/16/2025	1276652		c/o completed.	1420799
216	07/14/2025	1276127		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Replaced used driver rear parker/brake light assembly secured small wires near engin bay rear parker lights wiring with cable ties. Installed new battery positive terminal protector. Carried out fire safety inspection as per checklist. Complete	1420794
216	06/18/2025	1268998	CLAW CATCH STEEL MALE(Each)	ADJUST	1420731

216	06/18/2025	1268998		perp maskup and paint wheels unmask and remove from booth	1420731
216	06/18/2025	1269099	DECAL VENTURA ROUTE SMALL 490MM x 145MM		1420731
216	06/18/2025	1269099	DECAL DO NOT OVERTAKE 100MM X 300MM		1420731
216	06/18/2025	1269099		refit panels and refit wheelarch plastic inset and rubber and refit reflectors and refit n\s rear decal and clean and mop	1420731
216	06/18/2025	1269099		put sticker on o/s reflectors	1420731
216	06/18/2025	1269099	DECAL PTV D - PASS BOTTOM REAR		1420731
216	06/18/2025	1269099	REFLECTOR RED 94MM X 4MM NR84052BL		1420731
216	06/18/2025	1269099	DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL		1420731
216	06/18/2025	1269099	WHEEL ARCH RUBBER BACKING P/LENGTH		1420731
216	06/18/2025	1269099	REFLECTOR AMBER 94mm X 44MM (84051)		1420731
216	06/17/2025	1268998	STEEL CLAW CATCHES (SET UES2132)	adjust	1420729
216	06/17/2025	1269099		alot of time spend on sanding due to poor prep and priming. maskup and painted white/orange/black started wheels.	1420729
216	06/16/2025	1269099	VENT ROOF INTAKE POD		1420727
216	06/16/2025	1269099	PANEL LIGHT COWL REAR O/SIDE CNR		1420727
216	06/13/2025	1269099		refit top d mould and sika back panel and repair top and refit lid	1420720
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/11/2025	1268998	STEEL CLAW CATCHES (SET UES2132)		1420715
216	06/10/2025	1268998	SAUSAGE BLACK BOSTIK		1420713
216	06/10/2025	1269099		remove 2 panels and cut welds and weld panels and angles and replace rubber	1420713
216	06/10/2025	1268998		make 2 panels welded brackets	1420713
216	06/06/2025	1268998	ACCIDENT # 58965 - N/S/F DAMAGE	4 panels made 2 made by offcuts	1420703
216	06/06/2025	1268998	SHEET ALUM 5050 240cm x120cm x 3mm		1420703
216	06/06/2025	1268998	SHEET ALUM 5050 240cm x120cm x 3mm		1420703
216	06/06/2025	1269099		remove 4 panels and cut and fold	1420703
216	06/03/2025	1268195	PTI Tablet Entered -Body - Body Damage ns rear wheel guard	hes been reported on accident 58065	1420696
216	05/27/2025	1266672	PTI Tablet Entered -Wheels and Tyres - Damaged ns rear whee	refit wheel brush	1420679
216	05/27/2025	1266672	Consumables		1420679
216	05/12/2025	1263810	Mechanic entered - Body Other rear glass loose.	Retrieved the bus and removed old seal around rear windscreen and masked up around and re-sealed the rear windscreen removed the masking tape and parked the bus at the yard. job completed 12/05/2025	1419006
216	05/12/2025	1263810	Consumables		1419006
216	05/12/2025	1263810	Consumables		1419006
216	04/28/2025	1260333		Assisting	1419006
216	04/28/2025	1260333		Removed 4x air lines and replaced o-rings with new kit. Refitted air lines. Removed 4x tank fittings and replaced o-rings with consumable o-rings. Refitted fittings. Checked for air leaks no leaks from newly fitted o-rings.	1419006
216	04/24/2025	1260333	O-RING KIT LARGE VOSS A6739970	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O386194 Receiving #:409353 Date :2025-04-24	1419006
216	04/24/2025	1260333	Mechanic entered - Air System Other o/s/r air tank air fitt		1419006
216	04/24/2025	1260333	O-RING KIT SMALL VOSS A0309971	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O386194 Receiving #:409353 Date :2025-04-24	1419006
216	04/22/2025	1259679		VEHICLE SAFETY INSPECTION	1419006
216	04/22/2025	1259679		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1419006
216	04/22/2025	1259733	Mechanic entered - Fluid Leaks Other diff top pluge oil leak	repaired diff pluge ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Engine Other o/s/r saloon light not worki	replaced o/s/r saloon light tube ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Elec and Light Other buzzer reversing not	replaced buzzer reversing and repaired wires ok.	1419006
216	04/22/2025	1259733	BUZZER REVERSING 24V 97DB HL6015		1419006
216	04/22/2025	1259733	Mechanic entered - Elec and Light Other o/s/r saloon light d	replaced o/s/r saloon light diffuser interior ok.	1419006
216	04/22/2025	1259733	DIFFUSER INTERIOR LIGHT		1419006
216	04/22/2025	1259733	Mechanic entered - Elec and Light Other n/s and o/s middle p	repaired n/s and o/s middle pax switch ok.	1419006
216	04/22/2025	1259733	SWITCH STOP YELLOW (62628)(50V2242)		1419006
216	04/22/2025	1259733	Mechanic entered - Body Other n/s/r seat top roll cut.	repaired n/s/r seat top roll ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Body Other engine hatch pin off.	put in engine hatch pin ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Body Other disabled seat backs all loose	bent out seat back side brackets checked for movement ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Body Other rear modesty panel loose	drilled out rivet at top of pole rivetted checked for movement ok.	1419006
216	04/22/2025	1259733	Mechanic entered - Body Other N/S/F stuanchion pole loose	drilled out rivet at top of pole rivetted tightened all bolts checked for movement ok.	1419006
216	04/22/2025	1259733	Consumables		1419006
216	04/22/2025	1259733	Mechanic entered - Air System Other o/s/r air leaks.	replaced only o/s/r air fitting kit ok.	1419006
216	04/01/2025	1241949	body deadner undercoat peeling.		1419006
216	04/01/2025	1241949	Consumables		1419006
216	03/16/2025	1252634	PTI Tablet Entered -Elec and Light - Exterior Lights	N/S/R bottom park light / brake light out. Removed and fited new LED park light / brake light assembly.	1418777
216	03/16/2025	1252634	STOP LAMP DURALED L.E.D 177 X 100		1418777
216	03/16/2025	1252634	Consumables		1418777
216	02/27/2025	1248899		COMPLETED BY ATS 20-2-25	1418753
216	02/12/2025	1244478	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	CAMPAIGN DOES NOT APPLY TO RAIL BUSES	1418753
216	02/11/2025	1243286		Fitted 2x new idler bearings. Tensioned belt. Road tested by Sadid all ok.	1418753
216	02/11/2025	1243286	PULLEY ADJUSTER IDLER PULLEY 0500 - UPPER		1418753
216	02/07/2025	1243286	Engine idler u/s	ordered	1418753
216	02/04/2025	1242484		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1418753
216	01/31/2025	1241950	body deadner undercoat peeling.	Job complete.	1418753
216	01/31/2025	1241950	STONEGUARD PLUS SZ L253 1000ML		1418753
216	01/31/2025	1241950	Consumables		1418753
216	01/29/2025	1241348		VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.	1418753
216	01/29/2025	1241348		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1418753
216	01/29/2025	1241348		Assisting	1418753
216	01/29/2025	1241422	Mechanic entered - Body Other O/S/F emergency exit sticker m	Fitted new emergency sticker.	1418753
216	01/29/2025	1241422	Consumables		1418753
216	01/29/2025	1241422	Mechanic entered - Air System Air_Leak Front Front air tank	Replaced air tank drain tap with new. Checked for air leaks all ok.	1418753
216	01/29/2025	1241422	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1418753
216	01/29/2025	1241422	Mechanic entered - Air System Air_Leak Rear N/S/R air pressu	Remover test port fitting and replaced o-rings. Refitted test port and checked for air leaks. All ok.	1418753
216	01/09/2025	1237802	Vandalism Graffiti- GLASS FILM AUDIT # 1143	DELETE - WRONGLY ENTERED INTO SYSTEM	1418753
216	11/29/2024	1230324	PTI Tablet Entered -Vandalism - Vandalism/ Graffiti interior	clean graffiti off interior windows.	1418071
216	11/07/2024	1225542		VEHICLE SAFETY INSPECTION	1417820
216	11/07/2024	1225542		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1417820
216	11/07/2024	1225542	RADIATOR WASH	complete	1417820
216	11/07/2024	1225542	Consumables		1417820
216	10/23/2024	1207469	ANNUAL SAFETY INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G370396 Receiving #:397177 Date :2024-10-24	1417643
216	10/14/2024	1220831	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	Complete campaign 11/24.	1417643
216	10/01/2024	1205443	Consumables		1417125
216	10/01/2024	1205443	HANDLE GRAB GREY STRAP BRV001	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G369893 Receiving #:395589 Date :2024-10-01	1417125
216	09/04/2024	1203029	BELT MICRO V SERPENT 9 RIB 2010mm LNG	belt booked out on different work order for same bus	1416797
216	08/29/2024	1210942		COMPLETED BY ATS 20/8/2024	1416797
216	08/14/2024	1207469		VEHICLE SAFETY INSPECTION completed	1416754
216	08/14/2024	1207469		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1416754

216	08/14/2024	1207469	ANNUAL SAFETY INSPECTION SERIAL #RSI 065545. Pass. 14/08/2024. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 completed	1416754
216	08/13/2024	1207165	Carryout final inspection for RSI	1416754
216	08/13/2024	1207251	Consumables	1416754
216	08/13/2024	1207165	Consumables	1416754
216	08/13/2024	1207227	Consumables	1416754
216	08/13/2024	1207251	Mechanic entered - Body Other both please hold on decals mis	1416754
216	08/13/2024	1207227	Mechanic entered - Body Other N/S Emerjuncy sticker damage	1416754
216	08/13/2024	1207227	DECAL EMERGENCY EXIT ROCK BLACK/WHITE	1416754
216	08/13/2024	1207165	Assisted.	1416754
216	08/12/2024	1205443	Fitted new 3X hand strap.	1416754
216	08/12/2024	1205443	fitted 3 new grab handles and straps	1416754
216	08/12/2024	1205443	Consumables	1416754
216	08/12/2024	1206989	Consumables	1416754
216	08/12/2024	1206989	Mechanic entered - Body Other Wheel arc and rubber pos.123	1416754
216	08/12/2024	1206989	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M	1416754
216	08/12/2024	1206989	WHEEL ARCH BRUSH 2.5M LENGTH 12065	1416754
216	08/12/2024	1206989	Replaced both rear wheel arc/brush.	1416754
216	08/09/2024	1206717	Consumables	1416754
216	08/09/2024	1206717	Mechanic entered - Body Other Paint rusted areas. RSI steam	1416754
216	08/08/2024	1205433	steem clean.	1416754
216	08/08/2024	1205443	Replaced heater hose at the top aof transmission. Refitted all hoses to water pump. Filled coolant and start the bus and checked leaks ok.	1416754
216	08/08/2024	1205443	HANDLE GRAB GREY STRAP BRV001	1416754
216	08/07/2024	1205433	A442201038064 SEAL	1416754
216	08/07/2024	1205433	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G369909 Receiving #:391839 Date :2024-08-07	1416754
216	08/07/2024	1205433	Cl,eaned/ fitted new water pump gasket. C/O	1416754
216	08/07/2024	1205443	HANDLE GRAB GREY STRAP BRV001	1416754
216	08/06/2024	1205433	GASKET WATER PUMP LWR MERC BEN	1416754
216	08/06/2024	1205433	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G369909 Receiving #:391840 Date :2024-08-07	1416754
216	08/06/2024	1205433	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G369909 Receiving #:391840 Date :2024-08-07	1416754
216	08/05/2024	1205406	PRE ANNUAL SAFETY INSPECTION CHECK PASI Completed.	1416754
216	08/05/2024	1205406	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST CCTV B service completed.	1416754
216	08/05/2024	1205406	Replaced wiper blades.	1416754
216	08/05/2024	1205424	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	1416754
216	08/05/2024	1205424	WIPER BLADE ASSEMBLY 39037 S/S FROM TX1000	1416754
216	08/05/2024	1205419	Mechanic entered - Engine Other Exhaust rubber mount faulty.	1416754
216	08/05/2024	1205433	Mechanic entered - Engine Other Rectify coolant leak.	1416754
216	08/05/2024	1205419	MOUNT EXHAUST MERC BENZ 0500LE E3 A0004910285	1416754
216	08/05/2024	1205429	Consumables	1416754
216	08/05/2024	1205444	Consumables	1416754
216	08/05/2024	1205429	Mechanic entered - Elec and Light Other Indicator lever stal	1416754
216	08/05/2024	1205444	Mechanic entered - Elec and Light Interior Lights Dash switc	1416754
216	08/05/2024	1205441	Consumables	1416754
216	08/05/2024	1205442	Consumables	1416754
216	08/05/2024	1205447	Consumables	1416754
216	08/05/2024	1205448	Consumables	1416754
216	08/05/2024	1205441	Mechanic entered - Body Other n/s rear panel lock needs secu	1416754
216	08/05/2024	1205448	Mechanic entered - Body Windows Side n/s #4 window glass nee	1416754
216	08/05/2024	1205442	Mechanic entered - Body Other o/s rear bumper loose.	1416754
216	08/05/2024	1205447	Mechanic entered - Body Other n/s overhead panel needs secur	1416754
216	08/05/2024	1205443	Mechanic entered - Body Other Hand strap grab handle worn. r	1416754
216	08/05/2024	1205406	Mechanic entered - Brakes Other Brake pedal rubber pad worn.	1416754
216	08/05/2024	1205406	PEDAL RUBBER BRAKE PAD FLAT MERC 500LE A110291018201	1416754
216	08/05/2024	1205439	Mechanic entered - Air System Air_Leak Rear Rectify air leak	1416754
216	07/26/2024	1203364	VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list and tensioned all wheel nuts with indika and carried out tightening gear box cooler hose clamp and carried out fitting back yellow floor strip and fit new screw into panel exhacust	1416594
216	07/26/2024	1203364	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1416594
216	07/26/2024	1203223	removed decal and applied correct 'AO' decal.	1416594
216	07/25/2024	1203029	BELT MICRO V BELT 6 RIB 0500 ALT 1308mm LONG	1416594
216	07/25/2024	1202887	booked out twice.	1416594
216	07/25/2024	1202887	Carried out fire safety inspection as per check list. complete	1416594
216	07/25/2024	1202887	Assisted Mehdi with fire safety inspection completed	1416594
216	07/25/2024	1203223	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR	1416594
216	07/25/2024	1203223	DECAL ACCREDITATION CROY KNOX OAK & RAIL	1416594
216	07/24/2024	1203029	Mechanic entered - Engine Belts_Loose Noisy Missing	1416594
216	07/24/2024	1203029	BELT MICRO V BELT 6 RIB 0500 ALT 1308mm LONG	1416594
216	07/24/2024	1203029	BELT MICRO V BELT 6 RIB 0500 ALT 1308mm LONG	1416594
216	07/24/2024	1203029	BELT MICRO V SERPENT 9 RIB 2010mm LNG	1416594
216	07/24/2024	1202887	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G369044 Receiving #:390822 Date :2024-07-25	1416594
216	07/24/2024	1202887	replaced x2 drive belts completed	1416594
216	06/17/2024	1194683	FILTER DRYER AIR COND THERMO KING 2750300 DML305R	1416186
216	06/17/2024	1194683	RELAY 5 PIN CHANGE-OVER C/W DIODE	1416186
216	06/17/2024	1194683	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list	1416186
216	06/17/2024	1194683	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list replaced return air filter medium replaced boost punp relay	1416186
216	05/24/2024	1190350	A/C Heating Demister Not Heating fan nw	1415135
216	05/19/2024	1189215	LOOKS LIKE SOMEONE HAS TRIED TO OPEN POWER AREA FOR CHARGING	1414613
216	05/09/2024	1187337	Found the charging port on cradle was broken removed and fit the cradle removed from bus 17 checked charging okay	1413615
216	05/02/2024	1185753	complete	1412926
216	04/30/2024	1185271	removed intercooler washer cleaned radiator and intercooler ok.	1412924
216	04/30/2024	1185271	VEHICLE SAFETY INSPECTION Carried out Safety Inspection as per checklist.	1412924
216	04/30/2024	1185349	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1412924
216	04/30/2024	1185349	Consumables	1412924
216	04/30/2024	1185349	Mechanic entered - Elec and Light Other 1x passenger stop be	1412924
216	04/30/2024	1185349	Consumables	1412924
216	04/30/2024	1185349	Consumables	1412924
216	04/30/2024	1185349	Mechanic entered - Body Other Emergency exit button covers m	1412924
216	04/30/2024	1185349	SWITCH STOP YELLOW (62628)(50V2242)	1412924
216	04/30/2024	1185349	COVER EMERGENCY EXIT BUTTON	1412924
216	03/18/2024	1176994	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	1411280
216	02/28/2024	1173221	Mechanic entered - Elec and Light Other not starting	1411175
216	02/20/2024	1170849	battery solenoid won't turn on. checked the batteries new but voltage was down as the bus hasn't been started/running for long period of time. got started charging ok 27.53V starting ok	1410956
216	02/15/2024	1169707	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list - by Zakir	1410588
216	02/15/2024	1169707	VEHICLE SAFETY INSPECTION	1410588
216	02/15/2024	1169595	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1410588
216	02/15/2024	1169595	Incorrect Part No Used	1410588
216	02/14/2024	1169595	Incorrect Part No Used	1410588
216	02/14/2024	1169595	removed and fitted new battery.	1410588
216	02/14/2024	1169595	BATTERY EXSN94SCMF 1350AAC EMFN150L	1410588
216	01/11/2024	1162954	N/A	1410080
216	01/11/2024	1162954	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	1410080

[illegible]

216	06/27/2023	1122803	Consumables			1400886
216	06/26/2023	1122549	Fault#:38765 - Ops Entered - Fault - Breakdown Miscellaneou	Unjammed the drivers seat belt and tested.OK		1400580
216	06/26/2023	1122549	Workshop Tablet Entered -Elec and Light - AM-FM Radiowhen			1400580
216	06/26/2023	1122549	Drv entered - Elec and Light AM-FM Radio	Is working OK		1400580
216	06/26/2023	1122549	Consumables			1400580
216	06/19/2023	1121029	Drv entered - Elec and Light Indicators Not Working	checked all indicators and hazards operation no faults foundok		1398543
216	06/19/2023	1121029	Consumables			1398543
216	06/19/2023	1121028	Drv entered - Body Front_Door Operation Faulty	checked operation of both doors no faults found ok		1398543
216	06/19/2023	1121028	Consumables			1398543
216	06/15/2023	1120464	PTI Tablet Entered -Wheels and Tyres - WornP 3 tread	p3 tread fine		1397824
216	06/15/2023	1120464	Consumables			1397824
216	06/15/2023	1120462	Drv entered - Steering Shakes/ Wobbles	test run bus no shakes from steering		1397824
216	06/15/2023	1120461	Drv entered - Gearbox Driveline Rough Gear Change	test run bus gearchange normal		1397824
216	06/02/2023	1118283	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	Check radio and secure in mounting and working ok		1395678
216	06/02/2023	1118283	Consumables			1395678
216	05/23/2023	1116234	Mechanic entered - Engine Other Wash engine	Washed engine Found output shaft really dirty. washed and will monitor seal		1393940
216	05/23/2023	1116247	Mechanic entered - Engine Other Engine breather blocked	Fitted new breather		1393940
216	05/23/2023	1116247	BREATHER OIL MIST MERC BENZ 0500LE A5410100163			1393940
216	05/23/2023	1116186		CARRY OUT A SERVICE AS PER CHECK LIST A service completed		1393940
216	05/23/2023	1116186	Consumables			1393940
216	05/23/2023	1116186	Consumables			1393940
216	05/23/2023	1116186	Consumables			1393940
216	05/17/2023	1115180		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1393318
216	05/17/2023	1115180	Service	Assisting		1393318
216	05/17/2023	1115180	FAN MOTOR A/C EVAPORATOR	store items used by contractor		1393318
216	05/11/2023	1114042		VEHICLE SAFETY INSPECTION		1392685
216	05/11/2023	1114042		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1392685
216	04/14/2023	1108202		retensioned to specs.		1388600
216	04/14/2023	1108202	Consumables			1388600
216	04/14/2023	1108767	PTI Tablet Entered -Engine - Warning Lightcoolant leak	Inspect coolant leak drain coolant and replace trans cooler hose refill coolant test drive to temp and top up coolant check for leaks		1388600
216	04/14/2023	1108767	HOSE ELBOW RADIATOR HOSE VOLVO B10M MK2 (49N-010)			1388600
216	04/14/2023	1100921	Consumables			1388600
216	04/14/2023	1100921	Drv entered - Elec and Light AM-FM Radio	Checked working OK.		1388600
216	04/12/2023	1108202	Mechanic entered - Wheels and Tyres Wheel Nut Retension p1	completed retension		1388310
216	04/11/2023	1107963	PTI Tablet Entered -Wheels and Tyres - WornP1 sidewall	replaced p1 and tensioned wheelnuts to spec		1388310
216	04/11/2023	1107963	TYRE 295/80R22.5 NEW			1388310
216	04/11/2023	1107963	Consumables			1388310
216	04/05/2023	1107385	PTI Tablet Entered -Wheels and Tyres - WornP1 sidewall wor	p1 sidewall still ok		1387808
216	04/05/2023	1107023	Cen Sgl Back Cvr - CI	Creditor #:PT-RP AUTO RP AUTO UPHOLSTERY PTY LTD P/O #:PE340819 Receiving #:358585 Date :2023-04-13		1388600
216	04/05/2023	1107023	DIRECT PURCHASE - VANDALISM	Creditor #:PT-RP AUTO RP AUTO UPHOLSTERY PTY LTD P/O #:PE340819 Receiving #:358585 Date :2023-04-13 NO REPLACMENT FOR RP10024		1388600
216	04/05/2023	1107023	Consumables			1388600
216	04/03/2023	1107023	Mechanic entered - Body Passenger Seat Torn rear row seat ba	replaced missing seat with new		1387630
216	04/03/2023	1107023	SEAT SINGLE BACK CEN CVR CI			1387630
216	03/29/2023	1106099	Mechanic entered - Wheels and Tyres Worn P1 sidewall	Inspect tyre and no steel showing ok for service		1386950
216	03/29/2023	1106099	Consumables			1386950
216	03/22/2023	1104753		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1386041
216	03/22/2023	1104753		Assisting		1386041
216	03/17/2023	1103643	Fluid Leaks Rear of busTrans Output Seal leaks	removed tailshaft removed flange checked seal running surface still ok refit flange properly tightend bolts to spec refit tailshaft washed back of trans		1385200
216	03/17/2023	1103643	FLANGE PLATE LOCK OUTPUT 49D8525			1385200
216	03/17/2023	1100805	CAMERA INTERNAL 2.1mm LENS			1383850
216	03/09/2023	1102108		VEHICLE SAFETY INSPECTION		1383850
216	03/09/2023	1102108		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1383850
216	03/09/2023	1101911	Consumables			1383850
216	03/09/2023	1102115	Consumables			1383850
216	03/09/2023	1101911	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	replaced next stop button		1383850
216	03/09/2023	1101911	BELL PUSH STOP SUPPORT POLE GREY (12020)			1383850
216	03/09/2023	1102115	Mechanic entered - Elec and Light Warning Light On Dash Door	Checked and found faulty alternator replaced the same checked ok		1383850
216	03/09/2023	1102115	ALTERNATOR 24V 140AMP MERC BENZ 0500LE			1383850
216	03/09/2023	1102109		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		1383850
216	03/03/2023	1100920	Consumables			1383020
216	03/03/2023	1100920	Mechanic entered - Wheels and Tyres Wheel Nut Retension p3 a	Retorqued as per spec.		1383020
216	03/03/2023	1100805	CCTV CCTV not recording Driver's Compartment Camera Rear	ordered the extension cable for the camera waiting for the parts install the new camera cable and install the new camera in the fffth position and adjust the cameras		1383020
216	03/03/2023	1100786	CCTV (None) Check External Forward Facing Camera (Images	adjust trhe camera directions all of them.		1383020
216	02/24/2023	1099059	Consumables			1380733
216	02/24/2023	1099059	Mechanic entered - Wheels and Tyres Worn p4 tyre worn	replaced tyre p4 tenisoned to spec. and booked a retension		1380733
216	02/24/2023	1099059	TYRE 295/80R22.5 RECAP			1380733
216	02/23/2023	1098916	Ops Entered - Fault - Engine Low Power - Route: 833 - Sanda	Pulled bus in and lifted with hoists. Removed alternator brushes and found then worn down. Fitted new brushes and started okay		1380733
216	02/23/2023	1098916	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315			1380036
216	02/22/2023	1098444	Consumables			1380036
216	02/22/2023	1098444	Consumables			1380036
216	02/22/2023	1098444	Mechanic entered - Body Rear_Door Operation Faulty	checked rear door operation no faults found		1380036
216	02/22/2023	1097881	Consumables			1380036
216	02/22/2023	1097881	Consumables			1380036
216	02/22/2023	1097881	Consumables			1380036
216	02/22/2023	1097881	FILTER AIR DRYER COALESCING VOLVO B13R 21620181			1380036
216	02/20/2023	1097881		CARRY OUT A SERVICE AS PER CHECK LIST completed.		1378776
216	02/18/2023	1096365	Apply print film	stage-1 completed on the 9/2/23.		1378776
216	02/18/2023	1096365	Consumables			1379316
216	02/18/2023	1096365	Consumables			1379316
216	02/16/2023	1097453	Fault#:38604 - Ops Entered - Fault - Breakdown Overheating/C	breakdown at mcomiks road taped up the blown hose and sent to depot for repair. Trans cooler heater tap hose replaced by Jess.		1379316
216	02/14/2023	1096525	Consumables			1378776
216	02/14/2023	1096525	Consumables			1378776
216	02/14/2023	1096525	Mechanic entered - Body Other yellow strip on wheel chair ra	added yellow strip on wheelchair ramp		1378776
216	02/14/2023	1096525	EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER			1378776
216	02/14/2023	1096365	L1 L3 R1 R2	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE337426 Receiving #:354714 Date :2023-02-16		1379316
216	02/13/2023	1096461	Consumables			1378776
216	02/13/2023	1096461	Consumables			1378776
216	02/13/2023	1096461	Drv entered - Body Rear_Door Operation Faulty	checked both front and rear doors no faults found ok		1378776
216	02/13/2023	1096358		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list		1378776
216	02/13/2023	1096358	DRYER AIR ASSY MERC 0500LE(A0004302915)			1378776
216	02/13/2023	1096358	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)			1378776
216	02/13/2023	1096358	VALVE AIR FILTER CHECK 22mm CYCLONE			1378776
216	02/10/2023	1095894	Consumables			1378311

216	02/10/2023	1095894	Consumables			1378311
216	02/10/2023	1095894	Drv entered - Body Rear_Door Operation Faulty	checked all good		1378311
216	02/02/2023	1094218	Wheels and Tyres Worn Replace Pos 3 and 4.	both p3 and p4 still road legal.		1376638
216	02/02/2023	1094218	Consumables			1376638
216	01/30/2023	1093540		VEHICLE SAFETY INSPECTION		1376318
216	01/30/2023	1093540		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1376318
216	01/30/2023	1093574	Mechanic entered - Elec and Light Exterior Lights o/s tail l	tested wiring all good. replaced light and tested. all good		1376318
216	01/30/2023	1093574	LAMP STOP/TAIL LED HELLA			1376318
216	01/13/2023	1090892	Consumables			1374516
216	01/13/2023	1090892	Consumables			1374516
216	01/13/2023	1090892	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	Operate door multiple times and no fault found		1374516
216	01/12/2023	1090774	Consumables			1374516
216	01/12/2023	1090774	Consumables			1374516
216	01/12/2023	1090774	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	adjusted door speed ok		1374516
216	12/30/2022	1088764	Consumables			1373244
216	12/30/2022	1088764	Consumables			1373244
216	12/30/2022	1088764	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	Checked and found faulty wiring at nsr booster plug repaired the same checked door brake and RPD function ok.		1373244
216	12/23/2022	1088498	Consumables			1373452
216	12/23/2022	1088498	Consumables			1373452
216	12/23/2022	1088498	Mechanic entered - Body Windows Front windscreen cracked	Assisting		1372933
216	12/23/2022	1088498	Mechanic entered - Body Windows Front windscreen cracked	Creditor # :PT-ALP003 ALPHA BUS GLASS PTY LTD P/O # :PE334530 Receiving #:352080 Date :2022-12-31		1372933
216	12/23/2022	1088498	Replace windscreen plus clean	replaced power steering pump refilled power steering oil and bled checked for leaks ok		1373452
216	12/21/2022	1087635	Mechanic entered - Steering Other pws pump worn			1372863
216	12/21/2022	1087635	PUMP POWER STEERING MERCEDES 0500			1372863
216	12/21/2022	1087539	Consumables			1372863
216	12/21/2022	1087539	Consumables			1372863
216	12/21/2022	1087539	Drv entered - Body Rear_Door Operation Faulty	rear door seems fine		1372863
216	12/20/2022	1087400	Consumables			1372932
216	12/20/2022	1087400	Consumables			1372932
216	12/20/2022	1087400	Mechanic entered - Body Windows Side window smashed	Assisting Replaced by O'Brien glass		1372863
216	12/20/2022	1087400	Mechanic entered - Body Windows Side window smashed	Creditor # :PT-OBRO01 O'BRIENS GLASS INDUSTRIES P/O # :PE334665 Receiving #:351613 Date :2022-12-21 Replace Smashed N/S/R side glass		1372932
216	12/20/2022	1087400	888882 SIDE GLASS CUT TO SIZE			1372136
216	12/15/2022	1081015	Fluid Leaks Rear of bus Check and rectify Trans oil leak.			1371426
216	12/12/2022	1081015	FLANGE PLATE LOCK OUTPUT 49D8525	replaced trans output shaft seal		1371426
216	12/12/2022	1081015	Fluid Leaks Rear of bus Check and rectify Trans oil leak.			1371426
216	12/12/2022	1081015	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734 319 052 01	found door brake to be working ok		1371426
216	12/12/2022	1086015	Ops Entered - Fault - Body Rear_Door Operation Faulty - TH			1371426
216	12/12/2022	1086015	Consumables			1371426
216	12/12/2022	1086015	Consumables			1371426
216	12/08/2022	1085412	Workshop Tablet Entered -Elec and Light - Exterior Lights RH	loose wiring fixed		1370641
216	12/08/2022	1085412	Consumables			1370641
216	12/07/2022	1085166	Body Bus moves with passenger doors open. Door interlock sys	Inspect and operate doors and brake systems and all working correctly		1370641
216	12/07/2022	1085166	Consumables			1370641
216	12/07/2022	1085166	Consumables			1370641
216	12/05/2022	1081015	HOSE COMP - UNLOADER MERC BENZ 0500LE 50G0910			1370162
216	12/05/2022	1084660	Mechanic entered - Body Other front door pannel dropping			1370162
216	12/05/2022	1084660	Consumables			1370162
216	12/05/2022	1084660	Consumables			1370162
216	11/17/2022	1079005	COVER STRG COLUMN MERC BENZ 0500LE	re-open & fix as w/o# not put in at time of receiving nor mech booked out		1368210
216	11/17/2022	1079005	SHELL MB- 0500LE E3 BACK COVER STEER COLUMN	re-open & fix as w/o# not put in at time of receiving nor mech booked out		1368210
216	11/17/2022	1079005	Consumables			1368210
216	11/11/2022	1080542		VEHICLE SAFETY INSPECTION completed		1367779
216	11/11/2022	1080542		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1367779
216	11/09/2022	1079883	Workshop Tablet Entered -Elec and Light - Interior Lightsbu	sign in middle of bus globe is working		1366060
216	11/09/2022	1079883	Consumables			1366060
216	11/08/2022	1079005	Mechanic entered - Body Other both steering colum covers cr			1366060
216	11/07/2022	1079583	Mechanic entered - Suspension Other o/s/f sway bar drop arm	replaced o/s/f sway bar link ok		1366399
216	11/07/2022	1079583	LINK SWAY BAR OSF MERC 0500LE A6283201189			1366399
216	11/07/2022	1079005	Mechanic entered - Body Other both steering colum covers cra	fitted new steering column cover		1366399
216	11/07/2022	1079584	Drv entered - Body Front_Door Operation Faulty	checked operation of door no faults found		1366399
216	11/07/2022	1079584	Consumables			1366399
216	11/05/2022	1078260	Drv entered - Warning Lights Brakes	Fitted original sensor back to aux tank		1366399
216	11/03/2022	1078727	GLASS RESEAL	Creditor # :PT-OBRO01 O'BRIENS GLASS INDUSTRIES P/O # :PE331771 Receiving #:348582 Date :2022-11-03 Fit Windshield supplied by Volgren		1366060
216	11/03/2022	1078727	Consumables			1366060
216	11/02/2022	1078826	Mechanic entered - Fluid Leaks Rear of bus Transmission oil	fitted 2 genuine hoses topped up coolant road tested up once came back checked for leaks no leaks present all in working order topped excess coolant once thermostat opened		1364388
216	11/02/2022	1078826	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G			1364388
216	11/02/2022	1078727	Body Windows Wind shield cracked.			1364388
216	11/02/2022	1078727	Body Windows Wind shield cracked.	O'Brian glass fitted the windshield that supplied by Volgren		1364388
216	11/02/2022	1078727	GLASS WINDSCREEN VOLGREN CR228	Creditor # :PT-VOLGRE VOLGREN AUSTRALIA PTY LTD P/O # :PE331584 Receiving #:348544 Date :2022-11-03 216		1366060
216	11/02/2022	1078730		CARRY OUT C SERVICE AS PER CHECK LIST completed as per checklist.		1364388
216	11/02/2022	1078730		Assisting		1364388
216	11/02/2022	1078730	FILTER FUEL FILTER MERCEDES BENZ (H233WK)			1364388
216	11/02/2022	1078730	FILTER AIR MERC 0500LE(A0040941704)			1364388
216	11/02/2022	1078730	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709			1364388
216	11/02/2022	1078730	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151			1364388
216	11/02/2022	1078730	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)			1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730		CARRY OUT B SERVICE AS PER CHECK LIST		1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730		CARRY OUT A SERVICE AS PER CHECK LIST		1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730	Consumables			1364388
216	11/02/2022	1078730	Consumables			1364388
216	10/31/2022	1078260	Drv entered - Warning Lights Brakes	replaced protection valve. Gauges now working. Alarm on in bus because a rollaway sender was fitted to the auxiliary tank.		1364388
216	10/31/2022	1078260	VALVE FOUR WAY KNORR BREMSE MERC BENZ 0500LE A0034316806			1364388
216	10/29/2022	1077215	Apply Print Film	Completed 17/10/22		1364388
216	10/28/2022	1078172	air pressure issue	complete replacement rear brake booster hose and oring kit		1365977
216	10/28/2022	1078172	O-RING KIT LARGE VOSS(A6739970145)			1365977
216	10/28/2022	1078260	Drv entered - Warning Lights Brakes	fit new sensor to front tank secondary gauge still not working checked wiring and circuit protection valve		1365977

216	10/28/2022	1078260	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4.0 BAR MERC 0500			1365977
216	10/26/2022	1077215	Apply print film 17/10/22 L1	Creditor #::PT-GLA010 GLASSPROTECH MELBOURNE P/O #::PE331252 Receiving #:348192 Date :2022-10-27		1365583
216	10/26/2022	1077696	Drv entered - Elec and Light Indicators Not Working	replaced indicator stalk		1364964
216	10/26/2022	1077696	Drv entered - Elec and Light Horn			1364964
216	10/26/2022	1077696	Consumables			1364964
216	10/26/2022	1077696	Drv entered - Brakes Park_Brake Not Holding	hand brake works correctly and holds spoke with drive and stated that the hand brake works but you must use footbrake so the bus doesnt move forward slightly once hand brake applied foot brake should always be used to come to a stop prior to applying handbrake		1364964
216	10/18/2022	1075936	Mechanic entered - Wheels and Tyres Wheel Nut Retension P3	tensioned to spec		1362536
216	10/18/2022	1075936	Consumables			1362536
216	10/17/2022	1075346	Mechanic entered - Wheels and Tyres Wheel Nut Retension p3	Retensioned P3+4 wheel nuts to 600NM		1362536
216	10/17/2022	1075346	Consumables			1362536
216	10/13/2022	1075069	Mechanic entered - Wheels and Tyres Worn p3 tyre worn	replaced p3 tesioned wheel nuts		1361636
216	10/13/2022	1075069	TYRE 295/80R22.5 RECAP			1361636
216	10/13/2022	1075069	Consumables			1361636
216	10/07/2022	1066399	EXHAUST FLEXI MB-0500LE E3	Creditor #::PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #::PE328215 Receiving #:347066 Date :2022-10-11		1361390
216	10/06/2022	1073615	Mechanic entered - Engine Belts_Loose Noisy Missing Drive be	Took another bus out and found when belt came off it took out the oil return line from filters finley came with van with new pipe fit and used cable ties as temp belts drove back to depot		1361313
216	10/06/2022	1073615	HOSE OIL RETURN FILTER HOUSING TO BLOCK A4571800920			1361313
216	10/06/2022	1073615	Mechanic entered - Engine Belts_Loose Noisy Missing Drive be	Fitted and adjusted new belts with idler road tested ok.		1361313
216	10/06/2022	1073615	PULLEY IDLER/ADJUSTER MERCEDES 0500LE(50N0041G)			1361313
216	10/06/2022	1073615	BELT MICRO V SERPENT 9 RIB 2010mm LNG			1361313
216	10/06/2022	1073615	BELT MICRO V SERPENT BELT 6 RIB 1308mm LNG			1361313
216	10/04/2022	1072714	Ops Entered - Fault - Dash Switches Not Working - Route: 83	checked switches function. no apparent issues		1360531
216	10/04/2022	1072714	Consumables			1360531
216	10/04/2022	1072783	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	completed		1360531
216	09/21/2022	1070932	Ops Entered - Fault - Warning Lights Batteries - Route: 775	replaced main and alt belts		1360269
216	09/21/2022	1070932	BELT MICRO V SERPENT 9 RIB 2010mm LNG			1360269
216	09/21/2022	1070932	BELT MICRO V SERPENT BELT 6 RIB 1308mm LNG			1360269
216	09/21/2022	1070932	Consumables			1360269
216	09/15/2022	1069391	DIRECT PURCHASE - BUS INSPECTI	Creditor #::PT-ROASAF ROAD SAFETY INSPECTIONS P/O #::PE329006 Receiving #:345761 Date :2022-09-16 Road Safety Inspections		1359623
216	09/15/2022	1069806	Suspension Noisy tighten Rear Shock tower bolt loose	tightened all shock tower bolts		1359200
216	09/15/2022	1069806	Fluid Leaks Rear of bus Replace Trans Output Shaft Seal an	removed trans output shaft flange with special tool removed seal cleaned up flange and gearbox and fitted new seal fitted flange back on with special tool and tightened the 2 bolts for the flange to 60nm with locktite and fitted locking ring for the bolts fitted tailshaft back on tightened and roadtested bus rechecked after		1359200
216	09/15/2022	1069806	FLANGE PLATE LOCK OUTPUT(49D8525)			1359200
216	09/14/2022	1069806	Suspension Noisy tighten Rear Shock tower bolt loose			1359200
216	09/14/2022	1069806	Fluid Leaks Rear of bus Replace Trans Output Shaft Seal an	removed tail shaft and tried to remove transmission flange with puller and the oxy could not remove need right tool		1359200
216	09/14/2022	1069806	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734 319 052 01			1359200
216	09/13/2022	1069391		VEHICLE SAFETY INSPECTION		1359200
216	09/13/2022	1069391		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1359200
216	09/13/2022	1069391		ANNUAL SAFETY INSPECTION SERIAL #RSI 042184 _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1359200
216	09/09/2022	1068864	Body Complete RSI repairs and finalise.			1359200
216	09/09/2022	1068864	Consumables			1359200
216	09/06/2022	1068043	Body Steamclean for RSI.	completed		1357485
216	09/06/2022	1068043	Consumables			1357485
216	09/05/2022	1067693	Mechanic entered - Suspension Other bottom rear shock rubber	replaced shock rubbers		1357485
216	09/05/2022	1067693	VOLVO B7RLE REAR SHOCK BUSH KIT (30Y4919)			1357485
216	09/05/2022	1067693	VOLVO B7RLE REAR SHOCK BUSH KIT (30Y4919)			1357485
216	09/05/2022	1067670	Body RSI repairs	RSI repairs completed. chassis to be washed		1357485
216	09/05/2022	1067670	Consumables			1357485
216	09/05/2022	1067695	Mechanic entered - Air System Air_Leak Doors	replaced door spool valve		1357485
216	09/05/2022	1067695	VALVE 5 PORT PILOT			1357485
216	09/02/2022	1066399	Engine Noisy Replace muffler.			1357485
216	09/02/2022	1067369		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1357485
216	08/31/2022	1066987	MUDFLAP 605MM X 330MM			1358000
216	08/31/2022	1066987	Consumables			1358000
216	08/31/2022	1066987	Mechanic entered - Body Other rear mudflaps worn	replaced rear mudflaps		1358000
216	08/29/2022	1066399	SILENCER MERC BENZ 0500LE E3	Creditor #::PT-MUL001 MULTISPARES LTD P/O #::PE327994 Receiving #:344700 Date :2022-08-31 216		1358004
216	08/29/2022	1066149	RPD not working	Creditor #::PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #::PE327906 Receiving #:344450 Date :2022-08-30 Rectify RPD fault		1357771
216	08/26/2022	1066149	Mechanic entered - Brakes Other Door brakes not working	Check curciuts and replace faulty roll away switch		1357272
216	08/26/2022	1066149	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4.0 BAR MERC 0500			1357272
216	08/24/2022	1065426		PRE ANNUAL SAFETY INSPECTION CHECK		1357272
216	08/24/2022	1065426		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1357272
216	08/23/2022	1062385	O-RING KIT LARGE VOSS(A6739970145)	mech didnt book correct amount used		1357027
216	08/16/2022	1063687	Consumables			1355407
216	08/16/2022	1063687	Mechanic entered - Wheels and Tyres Wheel Nut Retension ALL	complete both rear wheel nuts retension		1355407
216	08/16/2022	1063687	Ops Entered - Fault - CCTV System Noisy - Route: 833 - Car			1355407
216	08/15/2022	1062385	Mechanic entered - Brakes Other burning smell	Assisting		1355086
216	08/15/2022	1062385	Mechanic entered - Brakes Other burning smell	mech booked out x2 RHR should be x1 RHR only & x1 LHR 50G2546KNORR		1355086
216	08/15/2022	1062385	BOOSTER BRAKE RHR MERC BENZ 0500LE E6 20/24	correct number used now booked		1355086
216	08/15/2022	1062385	BOOSTER BRAKE LHR MERC BENZ 0500LE E6 20/24	Creditor #::PT-GLA010 GLASSPROTECH MELBOURNE P/O #::PE326502 Receiving #:343343 Date :2022-08-15		1355086
216	08/12/2022	1061471	Apply Print Film L2			1355407
216	08/12/2022	1062385	Mechanic entered - Brakes Other burning smell			1355086
216	08/12/2022	1062385	BRAKE PAD SET SCANIA MERC BENZ 0500LE			1355086
216	08/12/2022	1062385	Mechanic entered - Brakes Other burning smell	FITTED NEW REAR CALIPERS AND BOOSTERS ETC ROAD TESTED ALL IN WORKING ORDER		1355086
216	08/12/2022	1062385	BOOSTER BRAKE RHR MERC BENZ 0500LE E6 20/24			1355086
216	08/12/2022	1062385	VALVE SHUTTLE T PIECE			1355086
216	08/12/2022	1062385	O-RING KIT LARGE VOSS(A6739970145)			1355086
216	08/12/2022	1062385	O-RING KIT LARGE VOSS(A6739970145)			1355086
216	08/10/2022	1062385	CALIPER BRAKE RH/RR MERC BENZ	Creditor #::PT-MUL001 MULTISPARES LTD P/O #::PE326772 Receiving #:343245 Date :2022-08-12		1355086
216	08/10/2022	1062385	CALIPER BRAKE LH/RR MERC BENZ	Creditor #::PT-MUL001 MULTISPARES LTD P/O #::PE326772 Receiving #:343245 Date :2022-08-12		1355086
216	08/06/2022	1061471	Apply Print film	Completed 04/8/22		1354358
216	08/05/2022	1061347	Mechanic entered - Elec and Light Exterior Lights reverse le	wired up new LED reverse lights tested works fine		1354358
216	08/05/2022	1061347	LAMP LED REVERSE RECTANGULAR			1354358
216	08/05/2022	1061347	Consumables			1354358
216	08/04/2022	1038160	Consumables			1354358
216	08/04/2022	1038160	Mechanic entered - Elec and Light Other busminder stand nee			1354358
216	08/02/2022	1060546		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		1353950
216	08/02/2022	1060546	Service	Assisting Completed		1353950
216	07/27/2022	1059512				1353665
216	07/27/2022	1059512		VEHICLE SAFETY INSPECTION		1353665
216	07/27/2022	1059512		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1353665
216	07/27/2022	1059538	Mechanic entered - Wipers and Washers Washers Not Working	fitted new washer pump tested operation of washers all in working order		1353665
216	07/27/2022	1059538	PUMP WASHER 24 VOLT			1353665
216	07/27/2022	1038160	Consumables			1353665
216	07/27/2022	1038160	Mechanic entered - Elec and Light Other busminder stand need	busminder stand ok		1353665
216	07/15/2022	1057386	Ops Entered - Fault - Gearbox Driveline Clutch Slipping -	Checked and tested no faults found.		1351762

216	07/12/2022	1056628	Ops Entered - Fault - Brakes Park_Brake Not Releasing - Rou	Inspect brake and door brake systems and could not fault	1351366
216	07/01/2022	1054825	Drv entered - Brakes Warning Light On	checked no warning lights	1350115
216	07/01/2022	1054824		CARRY OUT A SERVICE AS PER CHECK LIST completed	1350115
216	07/01/2022	1054824	Consumables		1350115
216	07/01/2022	1054824	Consumables		1350115
216	07/01/2022	1054824	Consumables		1350115
216	07/01/2022	1054824	Consumables		1350115
216	06/20/2022	1052700	VALVE RELAY R/REAR BRAKE MERC 0500LE A0044297644		1348091
216	06/20/2022	1052700	LATCH DOOR COOLANT HATCH 1/4 TURN		1348091
216	06/20/2022	1052613	Drv entered - Brakes Park_Brake Not Holding	could not fault handbrake or door brake	1348091
216	06/20/2022	1052700	Mechanic entered - Brakes Park_Brake Not Holding		1348091
216	06/20/2022	1052700	O-RING KIT SMALL VOSS(A0309971748)		1348091
216	06/20/2022	1052700	O-RING KIT LARGE VOSS(A6739970145)		1348091
216	06/20/2022	1052700	VALVE PARK BRAKE MERC BENZ 0500LE A0034307581		1348091
216	06/16/2022	1052087	Mechanic entered - Body Passenger Seat Torn seat base cover	replaced seat base cover	1347309
216	06/16/2022	1052087	SEAT FOLD CEN 2 PLC CUSH CVR RD		1347309
216	06/16/2022	1052110	Mechanic entered - Body Passenger Seat Torn folding seat bas	seat cover replaced by Roman Ear	1347309
216	06/16/2022	1052087	Consumables		1347309
216	06/16/2022	1052110	Consumables		1347309
216	06/15/2022	1051820	Mechanic entered - Engine Other coolant cap gets stuck when	replaced old coolant cap with a new one checked and okay.	1347309
216	06/15/2022	1051820	CAP RADIATOR 70KPA MERC 0500LE(A0005014615)		1347309
216	06/08/2022	1045765	ASSY VALVE ASSY EMERGENCY DOOR MERCEDES	mech only book x1 used x2	1346590
216	06/07/2022	1047459	Dignose and Fix RPD problem	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE322755 Receiving #:338827 Date :2022-06-08 Repair RPD and pass door operation problem	1346590
216	06/07/2022	1047459	Consumables		1346590
216	06/03/2022	1050024	Mechanic entered - BusMinder No Power usb lead broken	Had to fit a usb charger as what is fitted is hard wired used one of my usb charging leads as we dont stock usb c leads	1346066
216	06/03/2022	1050024	SOCKET DUAL USB NARVA (BUS MIN	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE322772 Receiving #:338662 Date :2022-06-06	1346101
216	06/03/2022	1050024	Consumables		1346101
216	05/30/2022	1046951	AIR CONDITIONING REPAIR	Creditor #:PT-22C001 22 CELSIUS P/O #:PE321877 Receiving #:338160 Date :2022-05-30 216 B-SERV	1346066
216	05/20/2022	1047459	Body Doors not working.		1346066
216	05/20/2022	1047459	Body Doors not working.	Assisting Repaired by Lonsdale Street Auto Electrics.	1346066
216	05/20/2022	1047459	Consumables		1346590
216	05/18/2022	1046951		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	1346066
216	05/18/2022	1046951	Service	Assisting Completed by 22Celcius	1346066
216	05/18/2022	1046951		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1346066
216	05/18/2022	1046953		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1346066
216	05/18/2022	1046953	Service	Assisting Refer to Job #1046951	1346066
216	05/18/2022	1046953	FAN MOTOR A/C EVAPORATOR		1346066
216	05/18/2022	1046952		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1346066
216	05/18/2022	1046952	Service	AssistingRefer to Job #1046951	1346066
216	05/17/2022	1046735	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REMO	Completed.	1345825
216	05/13/2022	1045983	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos5	completed retension of pos 5/6	1345094
216	05/13/2022	1045983	Consumables		1345094
216	05/12/2022	1045734		VEHICLE SAFETY INSPECTION carried out safety inspection as per checklist	1345094
216	05/12/2022	1045734		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1345094
216	05/12/2022	1045829	Mechanic entered - Wipers and Washers Wipers Loose o/s wiper	fitted new wiper on o/s	1345094
216	05/12/2022	1045829	WIPER BLADE ASSY 1000mm N102(TRP1000)		1345094
216	05/12/2022	1045814	Consumables		1345094
216	05/12/2022	1045814	Mechanic entered - Wheels and Tyres Worn pos 5/6 worn	replaced pos5/6 tyres. tensioned wheelnuts with ryan	1345094
216	05/12/2022	1045814	TYRE 295/80R22.5 RECAP		1345094
216	05/12/2022	1045820	Consumables		1345094
216	05/12/2022	1045824	Consumables		1345094
216	05/12/2022	1045825	Consumables		1345094
216	05/12/2022	1045826	Consumables		1345094
216	05/12/2022	1045827	Consumables		1345094
216	05/12/2022	1045820	Drv entered - BusMinder No Power	Checked bus minder is charging the device	1345094
216	05/12/2022	1045824	Drv entered - BusMinder Damaged	found busminder loose tightend clamp with special tool	1345094
216	05/12/2022	1045825	Drv entered - BusMinder Damaged	found busminder loose tightend clamp with special tool	1345094
216	05/12/2022	1045826	Drv entered - BusMinder No Power	Bus minder is charging	1345094
216	05/12/2022	1045827	Drv entered - BusMinder No Power	Checked bus minder is charging the device	1345094
216	05/12/2022	1045821	Consumables		1345094
216	05/12/2022	1045822	Consumables		1345094
216	05/12/2022	1045823	Consumables		1345094
216	05/12/2022	1045821	Drv entered - Body Windows Front	Chip has been repaired a few weeks ago	1345094
216	05/12/2022	1045822	stone chip windscreen	chip had been repaired a few weeks ago	1345094
216	05/12/2022	1045823	Mechanic entered - Body Windows Front Chip in windscreen	chip had been repaired a few weeks ago	1345094
216	05/12/2022	1045765	Mechanic entered - Air System Air_Leak Doors	Removed and replaced faulty front door exit switch found door button under bumper was back feeding into e-exit switch replaced button and rechecked no leaks	1345094
216	05/12/2022	1045765	ASSY VALVE ASSY EMERGENCY DOOR MERCEDES		1345094
216	05/12/2022	1045765	BUTTON CLIPPARD DOOR VALVE 11916-2		1345094
216	05/12/2022	1045765	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1345094
216	05/06/2022	1044585	Consumables		1344360
216	05/06/2022	1044585	Mechanic entered - Body Windows Front windscreen chip	inspected chip has already been repaired no further action required	1344360
216	04/30/2022	1042045	Repair windscre chip	completed 21/4/22	1341930
216	04/30/2022	1042045	Consumables		1342800
216	04/26/2022	1041941	Mechanic entered - Elec and Light Exterior Lights o/s/r park	faulty connection replaced terminals now in working order	1341930
216	04/26/2022	1041941	Consumables		1341930
216	04/23/2022	1041225	Apply Print Film	Completed 8/4/22	1341930
216	04/21/2022	1041225	Apply Print Film L1L2R1R2	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE319926 Receiving #:335700 Date :2022-04-26 Completed 8/4 - Stage 1	1342800
216	04/21/2022	1042045	Repair windscreen chip	Creditor #:PT-KNIO05 KNIGHTS WINDSCREEN PENINSULA P/O #:PE320187 Receiving #:335712 Date :2022-04-26	1342800
216	04/11/2022	1039961	Drv entered - BusMinder No Power	busminder powering up ok	1340660
216	04/11/2022	1039961	Consumables		1340660
216	04/08/2022	1039821	Gearbox Driveline. Bus jerking with gear change. Its only we	road tested bus no fault found	1340660
216	03/30/2022	1037886	Consumables		1338734
216	03/30/2022	1037886	Ops Entered - Fault - BusMinder No Power - Route: - DISPLA	busminder has damaged charge cable and likely charge socket bus minder usb c charger cable broken and needs to be replaced when we have stock.	1338734
216	03/21/2022	1036266	Consumables		1337668
216	03/21/2022	1036266	Rear door is opening whilst driving	Diagnosed and found no doors working reset the body control node doors started working still no door brake checked the door brake pressure switch at NSR booster found ok checked wiring ok reset the RPD device by removing and reconnecting the plug all door brake system started working normally road tested twice (	1337668
216	03/21/2022	1036317	Mechanic entered - Air System Other Air drier silencer missi	Fitted new one	1337668
216	03/21/2022	1036317	SILENCER AIR VALVE CLIP ON 69MM 432-407-070-0		1337668
216	03/16/2022	1035326	Wipers and Washers loose on body/arm/blades	cleaned wiper splines and tightened ok	1337102
216	03/16/2022	1035326	Suspension front sway links worn ?	checked sway bar links ok	1337102
216	03/16/2022	1035326	Engine muffler mount worn ?	checked muffler mounts ok	1337102
216	03/16/2022	1035326	Fluid Leaks oil leak from top incooler hose ?	found intercooler piping clamps loose tightened ok	1337102
216	03/16/2022	1035326	Air System Air_Leak Rear air dryer area/front bumper	replaced emergency exit switch and checked ok	1337102
216	03/16/2022	1035326	ASSY VALVE ASSY EMERGENCY DOOR MERCEDES		1337102

216	03/11/2022	1034760		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	1336544
216	03/11/2022	1034760	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		1336544
216	03/11/2022	1034759		VEHICLE SAFETY INSPECTION	1336544
216	03/11/2022	1034759		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1336544
216	03/11/2022	1034803	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	1336544
216	03/03/2022	1033085		CARRY OUT A SERVICE AS PER CHECK LIST completed as per check list	1335122
216	03/03/2022	1033085	Consumables		1335122
216	03/03/2022	1033085	Consumables		1335122
216	03/03/2022	1033085	Consumables		1335122
216	03/03/2022	1033085	Consumables		1335122
216	02/28/2022	1032326		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Completed	1333789
216	02/28/2022	1032235		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1333789
216	02/28/2022	1032235	DRYER AIR ASSY MERC 0500LE(A0004302915)		1333789
216	02/28/2022	1032235	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)		1333789
216	02/26/2022	1030493		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1333789
216	02/26/2022	1030493		done	1333789
216	02/26/2022	1031703	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	done	1333789
216	02/24/2022	1031332	Consumables		1333897
216	02/24/2022	1031332	Mechanic entered - Body Other minor scrape on o/s rear mark	painted over scrapes	1333897
216	02/09/2022	1027652	Consumables		1331230
216	02/09/2022	1027652	Drv entered - Body Rear_Door Operation Faulty	done	1331230
216	02/09/2022	1027652	Drv entered - Body Rear_Door Operation Faulty	checked operation no faults found	1331230
216	02/08/2022	1027346	Consumables		1331230
216	02/08/2022	1027346	Drv entered - Body Rear_Door Operation Faulty	checked for operation and safety edges no faults found	1331230
216	02/03/2022	1026284	Drv entered - Body Rear_Door Operation Faulty	checked rear and front door operation. cannot fault. checked sensitive edges for response. all ok	1330619
216	02/03/2022	1026284	Consumables		1330619
216	01/28/2022	1025128	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	front and rear door operation as normal. road tested and tried to drive with doors open multiple times and tried to reinact someone hitting the sensitive edge and the bus moving but could not fault.	1330209
216	01/28/2022	1025128	Consumables		1330209
216	01/18/2022	1023289	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	completed	1329048
216	01/18/2022	1023289	Consumables		1329048
216	01/17/2022	1023049	Mechanic entered - Wheels and Tyres Worn P5 worn	fitted runout tyre to p5 and checked p6 tyre all in good condition. fitted tyres back to hub and tensioned to 600nm	1329047
216	01/17/2022	1023049	Consumables		1329047
216	01/13/2022	1022433	Mechanic entered - Elec and Light Exterior Lights reverse li	cleaned reverse light connections and tested all ok	1328449
216	01/13/2022	1022433	Consumables		1328449
216	01/10/2022	1017567	BRAKE HOSE RHF MERC BENZ 0500	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE312728 Receiving #:329265 Date :2022-01-11	1328243
216	01/07/2022	1021404	Suspension Leaning N/S	leaning fixed after replacing all rear airbags.	1327774
216	01/07/2022	1021403	Suspension replace all rear air bags	jacked bus up on hoist. supported rear of bus with stands lowered bus onto stands removed old airbags and fitted new airbags.	1327774
216	01/07/2022	1021403	AIRBAG FRONT/RR MERC 0405 0500LE VOLVO B10BLE RR		1327774
216	01/07/2022	1021405	Gearbox clean	gearbox and engine degreased and steamcleaned	1327774
216	01/07/2022	1021405	Gearbox clean	completed	1327774
216	01/07/2022	1021405	DECAL DO NOT OVERTAKE 100MM X 300MM		1327774
216	01/07/2022	1020733	Fluid Leaks Rear of bus radiator leak	removed brackets shroud and fan from old radiator and fitted to new radiator. mocked up to bus with trolley jack and put in mounting bolts/ brackets and hose clamps put back intercooler and intercooler cowlings. tested radiator for leaks. everything ok	1327774
216	01/06/2022	1020733	Fluid Leaks Rear of bus radiator leak	removed intercooler removed hose clamps from radiator and mounting brackets removed fan shaft bolts and electrical connections. used trolly to remove radiator from bus.	1327774
216	01/05/2022	1020980	Suspension Soft replace front shocks	placed stands under body of bus while on hoist dropped body on to jack stands removed both front shocks and cleaned surfaces replaced with new front shocks.	1327774
216	01/05/2022	1020980	SHOCKER FRONT MERC 0500LE		1327774
216	01/05/2022	1020733	RADIATOR MERCEDES 0500 NO FRA	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE313737 Receiving #:329133 Date :2022-01-07	1328092
216	01/05/2022	1020734	Brakes rear brake modulator valve leaking	removed all pipes and electrical connections from old modulator. took photos and replaced fitted back new modulator. cannot test as bus does not have a radiator.	1327774
216	01/05/2022	1020734	VALVE MODULATOR RR MERC BENZ	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE313616 Receiving #:329076 Date :2022-01-06	1328092
216	01/04/2022	1020723		VEHICLE SAFETY INSPECTION Carry out inspection as per list	1327774
216	01/04/2022	1020723		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tension all nuts to spec	1327774
216	01/04/2022	1020733	Fluid Leaks Rear of bus radiator leak	complete	1327774
216	01/04/2022	1020733	Fluid Leaks Rear of bus radiator leak	complete	1327774
216	01/04/2022	1020734	Brakes rear brake modulator valve leaking	comkplted	1327774
216	12/31/2021	1020263	Mechanic entered - Engine Other Fan drive shaft worn		1327774
216	12/31/2021	1020263	BEARING TAPERED ROLLER		1327774
216	12/31/2021	1020263	SEAL TENSIONER HUB M1095		1327774
216	12/31/2021	1020263	BEARING A/C COMP CLUTCH SEALED(52102NS)		1327774
216	12/30/2021	1020263	Mechanic entered - Engine Other Fan drive shaft worn	Replace faulty fan drive hub with reco unit	1327774
216	12/23/2021	1019504		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1327119
216	12/20/2021	1018758	Mechanic entered - Engine Other Fan angle drive shaft worn	found fanshaft to be ok. i think its not very old	1325995
216	12/13/2021	1017567	Brakes replace both front brake hoses	replaced both front brake lines and checked ok	1325326
216	12/13/2021	1017567	HOSE BRAKE LHF MERC BENZ 0500LE		1325326
216	12/13/2021	1017568	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C	Completed as per the Chacklist.	1325326
216	12/10/2021	1017168	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	completed	1324937
216	12/10/2021	1017168	Consumables		1324937
216	12/09/2021	1016936	Mechanic entered - Wheels and Tyres Damaged p4	REPLACED	1324937
216	12/09/2021	1016936	TYRE 295/80R22.5 RECAP		1324937
216	12/09/2021	1016936	Mechanic entered - Wheels and Tyres Damaged p4	Replaced damaged tyre with a new recap and tensioned to the specs.	1324937
216	12/09/2021	1016936	Consumables		1324937
216	11/17/2021	1012015	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSF	completed	1321835
216	11/17/2021	1012015	Consumables		1321835
216	11/16/2021	1011976	Mechanic entered - Wheels and Tyres Worn NSF sidewall worn	Replaced with new tyre torqued wheel nuts as per spec.	1321835
216	11/16/2021	1011976	TYRE 295/80R22.5 NEW		1321835
216	11/16/2021	1011976	Consumables		1321835
216	11/08/2021	1010147	Mechanic entered - Body Drivers Seat Controls switch broken	Replaced checked function ok	1320413
216	11/08/2021	1010147	KNOB QUICK RELEASE LH 6860/875		1320413
216	11/08/2021	1010147	Consumables		1320413
216	11/08/2021	1010137	FILTER OIL MERC(A0001801709)		1320413
216	11/08/2021	1010137	OIL SAMPLE KIT AMPOL		1320413
216	11/08/2021	1010137	FILTER AIR MERC 0500LE(A0040941704)		1320413
216	11/08/2021	1010137		CARRY OUT B SERVICE AS PER CHECK LIST	1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	11/08/2021	1010137	Consumables		1320413
216	10/29/2021	1008458		VEHICLE SAFETY INSPECTION Completed as per the Checklist.	1319394
216	10/29/2021	1008458		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned to the specs.	1319394
216	10/18/2021	1006083	Brakes door brake not working driver complaint	repaired switch wiring at N/S rear axle	1317387

216	10/18/2021	1006083	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4BAR MERC 0500			1317387
216	10/01/2021	996107	reseal side windows	Creditor #::PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #::PE306018 Receiving #:324279 Date :2021-10-22		1318068
216	10/01/2021	996107	Consumables			1318068
216	09/17/2021	1000383	Drv entered - Wipers and Washers Wipers Not Working	secured o/s wiper arm top up washer bottle tested all good.		1312425
216	09/14/2021	999438	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	completed		1311730
216	09/14/2021	999438	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	Assisting		1311730
216	09/07/2021	997688		VEHICLE SAFETY INSPECTION		1310082
216	09/07/2021	997688		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1310082
216	09/07/2021	997688		ANNUAL SAFETY INSPECTION SERIAL #_L541061_____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1310082
216	09/07/2021	997688		Assisting		1310082
216	09/07/2021	997688	DIRECT PURCHASE - BUS INSPECTI	Creditor #::PT-FLE010 FLEETCHECK BUS PTY LTD P/O #::PE306476 Receiving #:321166 Date :2021-09-09		1311074
216	09/06/2021	997401	Consumables			1310082
216	09/06/2021	997401	clean and paint Wheel rims	completed		1310082
216	09/06/2021	997401	Consumables			1310082
216	09/06/2021	997401	mop out all driver and front door areas of RSi buses	completed		1310082
216	09/05/2021	997115	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	done		1310082
216	09/02/2021	996640	Consumables			1310082
216	09/02/2021	996640	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retensioned to specs.		1310082
216	09/02/2021	996724	Steam clean for RSi	completed and greased		1310082
216	09/02/2021	996107	Consumables			1310082
216	09/02/2021	996107	Body Windows Side need resealing			1310082
216	09/02/2021	996107	Body Windows Side need resealing	Assisting		1310082
216	09/01/2021	996416	Consumables			1310452
216	09/01/2021	996416	Final RSi	checked and finalised.		1310452
216	09/01/2021	996416	LAMP INDICATOR AMBER LED (HELLA 1406/LLX41212)			1310452
216	09/01/2021	996416		Fr top indicator U/S. Replaced and tested.		1310452
216	08/31/2021	995965	Mechanic entered - Wheels and Tyres Worn N/S/R	Replace n/s/r tyres and torque to spec		1310082
216	08/31/2021	995965	TYRE 295/80R22.5 RECAP			1310082
216	08/31/2021	995965	Consumables			1310082
216	08/31/2021	995965	Consumables			1310082
216	08/31/2021	994958	carry out RSi repairs defect as you go	Replace various seat bases and backs. 3 foldown covers and gas strut Repair broken n/s/r seat frame hinge		1310082
216	08/31/2021	994958	CEN FOLD 2PLC CUSH CVR - CL			1310082
216	08/31/2021	994958	SUPER SLIM SGL CUSH CVR - CL			1310082
216	08/31/2021	994958	SEAT BASE PLASTIC SUPERSLIM BLACK DISABLED SEAT			1310082
216	08/31/2021	994958	SINGLE SEAT BACK REST			1310082
216	08/31/2021	994958	SEAT CUSH SINGLE CEN CVR CI			1310082
216	08/31/2021	994958	GAS STRUT STAY 800Nm 565mm LONG			1310082
216	08/31/2021	994958	Consumables			1310082
216	08/31/2021	994958	Consumables			1310082
216	08/26/2021	994958	carry out RSi repairs defect as you go			1309676
216	08/24/2021	994246	Ops Entered - Fault - Body Front_Door Operation Faulty - R	Adjusted the pressure and closing sequence of the fr door and tested.		1309210
216	08/24/2021	994246	Consumables			1309210
216	08/24/2021	994246	Consumables			1309210
216	08/17/2021	992611		VEHICLE SAFETY INSPECTION		1307506
216	08/17/2021	992611		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1307506
216	08/17/2021	992611		Assisting		1307506
216	08/17/2021	992613		PRE ANNUAL SAFETY INSPECTION CHECK		1307506
216	08/17/2021	992613		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1307506
216	08/17/2021	992613		Assisting		1307506
216	08/17/2021	992668	Mechanic entered - Suspension Noisy OSF sway bar link noisy	Replaced with new one.		1307506
216	08/17/2021	992668	LINK SWAY BAR OSF MERC BENZ 0500LE A6283201189			1307506
216	08/17/2021	992668	Mechanic entered - Suspension Noisy OSF sway bar link noisy			1307506
216	08/17/2021	992675	Mechanic entered - Elec and Light Exterior Lights Both Low b	Replaced both Low beam and high beam unitsadjusted and tested.		1307506
216	08/17/2021	992675	HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500 (9314365038525)			1307506
216	08/17/2021	992675	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204			1307506
216	08/17/2021	992675	Consumables			1307506
216	08/17/2021	992675	Consumables			1307506
216	08/11/2021	991274		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		1306119
216	08/11/2021	991274		Assisting		1306119
216	08/02/2021	989254	Mechanic entered - Engine Other one muffler mounting bush sp	fitted new mount		1304289
216	08/02/2021	989254	EXHAUST MOUNT MERC BENZ 0500LE A0004910285			1304289
216	08/02/2021	989196		CARRY OUT A SERVICE AS PER CHECK LIST completed and fitted one grease nipple to prop shaft uni joint		1304289
216	08/02/2021	989196	Consumables			1304289
216	08/02/2021	989196	Consumables			1304289
216	08/02/2021	989196	Consumables			1304289
216	08/02/2021	989196	Consumables			1304289
216	08/02/2021	989196	Consumables			1304289
216	08/02/2021	989196	Consumables			1304289
216	07/28/2021	988311	Mechanic entered - Body Passenger Seat Torn rear passenger s	replaced cut seat with new		1303695
216	07/28/2021	988311	SEAT CUSH SINGLE CEN CVR CI			1303695
216	07/28/2021	985488	repair acc # 52282	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE302768A Receiving #:318001 Date :2021-07-29		1304026
216	07/28/2021	985488	Consumables			1304026
216	07/28/2021	988311	Consumables			1303695
216	07/21/2021	986968	Mechanic entered - Body Front_Door Operation Faulty	Replace faulty pilot valve		1302104
216	07/21/2021	986968	VALVE 5 PORT PILOT			1302104
216	07/21/2021	986968	Consumables			1302104
216	07/20/2021	986646	Mechanic entered - Body Front_Door Operation Faulty	INspect door fault and lube air valves remount front cylinder mounting plate and test function working ok		1302104
216	07/20/2021	986646	Mechanic entered - Body Front_Door Operation Faulty	Assisting		1302104
216	07/20/2021	986646	Consumables			1302104
216	07/15/2021	985702	Ops Entered - Fault - Wipers and Washers Wipers Loose - Rou	Realigned the wiper arms position checked function ok.		1300826
216	07/15/2021	985696	Mechanic entered - Body Other side panel clip broken	replaced panel catch and checked ok		1300826
216	07/15/2021	985696	CATCH CLAW PLASMA ENGINE HATCH DOOR			1300826
216	07/15/2021	985701	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	Checked and found bent ramp hinge repaired the same washed the dirt checked for funtion ok.		1300826
216	07/15/2021	985696	Consumables			1300826
216	07/15/2021	985701	Consumables			1300826
216	07/14/2021	985478	Mechanic entered - Fluid Leaks Other radiator cap missing	replaced radiator cap ok		1300826
216	07/14/2021	985478	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615			1300826
216	07/14/2021	985191	Ops Entered - Fault - Body Windows Front - Route: - Arriv	REPLACED		1300826
216	07/14/2021	985191	Ops Entered - Fault - Body Windows Front - Route: - Arriv	Assisting		1300826
216	07/14/2021	985488	Body N/S panel damage	replaCED		1300826
216	07/14/2021	985488	Body N/S panel damage	Assisting		1300826
216	07/14/2021	985536	Ops Entered - Fault - Body Windows Front - Route: - Arriv	REWPLACED		1300826
216	07/14/2021	985536	Ops Entered - Fault - Body Windows Front - Route: - Arriv	Assisting		1300826

216	07/14/2021	985191	replace windscreen	Creditor #:	PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:	PE302659	Receiving #:	316996	Date :	2021-07-16	1301987
216	07/14/2021	985191	Consumables								1301987
216	07/14/2021	985536	Consumables								1300826
216	07/13/2021	985191	Body Windows Front damaged windscreen	REPLACED							1300826
216	07/13/2021	985191	Body Windows Front damaged windscreen	Assisting							1300826
216	07/12/2021	984873	Mechanic entered - Body Front_Door Operation Faulty	Checked front door operation ok							1300826
216	07/12/2021	984873	Consumables								1300826
216	07/09/2021	984555	Drv entered - Body Front_Door Operation Faulty	checked front door operation front door closes and opens with no struggle every time. bottom door lock in unlocked position. no fault found.							1300826
216	07/09/2021	984555	Consumables								1300826
216	07/06/2021	983835	Drv entered - A/C Heating Not Heating	Checked for any coolent leakstesteddriven and testedthe demister and AC heating OK.							1300233
216	07/06/2021	983648	SOCKET EXH BRAKE CYL MERC 05	Creditor #:	PT-MUL001 MULTISPARES LTD P/O #:	PE302188	Receiving #:	316410	Date :	2021-07-07	1300826
216	07/06/2021	983648	50T0211 BALL STUD EXH BRAKE	Creditor #:	PT-MUL001 MULTISPARES LTD P/O #:	PE302188	Receiving #:	316410	Date :	2021-07-07	1300826
216	07/05/2021	983648	Engine Low Power ex brake cylinder faulty	dean fitted new cylinder							1300233
216	07/05/2021	983648	Exhaust Brake Cylinder Mercede	Creditor #:	PT-MUL001 MULTISPARES LTD P/O #:	PE302188	Receiving #:	316276	Date :	2021-07-06	1300567
216	07/05/2021	983336	Air System air compressor pumping coolant into air system	Refit power steering pump top up p/s oil and refill coolant test drive and recheck all levels and check for oil leaks drain all air tanks of moisture							1300233
216	07/02/2021	983336	GASKET AIR COMPRESSOR MT MERC BENZ 0500LE A4571310180								1300233
216	07/02/2021	983336	Air System air compressor pumping coolant into air system	Modify floor and fittings as nec and mount new compressor							1300233
216	07/02/2021	983261	Mechanic entered - Air System Other found over heating and n	found compressor head gasket pumping coolant into air system need to replace							1300233
216	07/02/2021	983261	Mechanic entered - Air System Other found over heating and n	removed compressor							1300233
216	07/02/2021	983336	AIR COMPRESSOR VOITH MERC BENZ 0500LE								1300233
216	06/29/2021	982571	Only 3 cameras operating	Reconnected the plugs behind DVR checked for all cameras ok							1299397
216	06/25/2021	981981	Mechanic entered - Wheels and Tyres Wheel Nut Retension P 2.	completed							1298841
216	06/25/2021	981981	Consumables								1298841
216	06/25/2021	981992	Mechanic entered - Accident - MIRROR N/S mirror arm broken	Replace broken n/s mirror arm.							1298841
216	06/25/2021	981992	MIRROR ARM LONG LH 19mm								1298841
216	06/24/2021	981805		VEHICLE SAFETY INSPECTION Completed as per checklist.							1298841
216	06/24/2021	981805		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS							1298841
216	06/24/2021	981859	Mechanic entered - Wipers and Washers Washers Not Working Ra	Replaced all the damaged washer hoses and tested.OK.							1298841
216	06/24/2021	981859	SILENCER AIR VALVE CLIP ON 69MM 432-407-070-0								1298841
216	06/24/2021	981859	TYRE 295/80R22.5 NEW								1298841
216	06/24/2021	981859		Pos 2 worn. Replaced with a new cleanskin and tensioned to the specs.							1298841
216	06/24/2021	981859	Consumables								1298841
216	06/24/2021	981859		Air dryer silencer blocked. Replaced with a new one.							1298841
216	06/21/2021	981084	Engine wash	engine steam cleaned.							1298443
216	06/17/2021	980531		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked all good							1298297
216	06/14/2021	979416	L2 MODESTY RD	Creditor #:	PT-GLA010 GLASSPROTECH MELBOURNE P/O #:	PE300789	Receiving #:	314754	Date :	2021-06-15	1298016
216	06/12/2021	979416	Apply print film	xx							1297261
216	06/10/2021	979414	Fault#:37920 - Ops Entered - Fault - Breakdown Belts broke	Assisting							1297261
216	06/10/2021	979414	Fault#:37920 - Ops Entered - Fault - Breakdown Belts broke	Replaced alt and main beltsBoth idler pulleys and the Alt top bush/adjuster assy a non stock itemadjusted and tested.OK.							1297261
216	06/10/2021	979414	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE 50N0041G								1297261
216	06/10/2021	979414	BUSH ALTERNATOR MTG 12MM X 25MM X 37MM MERC 0500LE								1297261
216	06/10/2021	979414	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG								1297261
216	06/10/2021	979414	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG								1297261
216	05/31/2021	976873	carry out A service	Creditor #:	PT-22C001 22 CELSIUS P/O #:	PE299873	Receiving #:	313945	Date :	2021-06-02	1295675
216	05/28/2021	976873	MOTOR A/C EVAPORATOR FAN MOTOR	part used by 22 cel							1295223
216	05/28/2021	976873	CONDENSOR FAN A/C CITI-RT	part used by 22cel							1295223
216	05/27/2021	976873		CARRY OUT A/C - A SERVICE AS PER CHECK LIST by 22							1295223
216	05/27/2021	976873		Assisting							1295223
216	05/21/2021	975581	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	replaced front R/H headlight all ok							1294096
216	05/21/2021	975581	Consumables								1294096
216	05/07/2021	972911	Ops Entered - Fault - Warning Lights Coolant - Route: 775 -	Trace to and replace split bleed hose ontop of gearbox. Refill coolant and road test to temp. Recheck coolant ok							1291928
216	05/04/2021	971984	Mechanic entered - Body Rear_Door Operation Faulty	Replace front door rear leaf sensitive edge switch							1291157
216	05/04/2021	971984	EDGE SENSITIVE EDGE DOOR SWITCH								1291157
216	05/04/2021	971984	Consumables								1291157
216	04/22/2021	969679		VEHICLE SAFETY INSPECTION							1289452
216	04/22/2021	969679		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed							1289452
216	04/22/2021	969679		Assisting							1289452
216	04/22/2021	969679		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed							1289452
216	04/22/2021	969679	AIR DRYER ASSY MERC BENZ 0500LE A0004302915								1289452
216	04/22/2021	969679	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE A0054327401								1289452
216	04/22/2021	969679	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE								1289452
216	04/22/2021	969679	KIT O-RING SMALL VOSS (A0309971748)								1289452
216	04/22/2021	969679	KIT O-RING LARGE VOSS (A6739970145)								1289452
216	04/22/2021	969679		CARRY OUT A SERVICE AS PER CHECK LIST completed							1289452
216	04/22/2021	969679	Consumables								1289452
216	04/22/2021	969679	Consumables								1289452
216	04/22/2021	969679	Consumables								1289452
216	04/16/2021	968516	Ops Entered - Fault - Dash - Route: 833 - Forest Dr Shops 2	replaced combo switch							1288779
216	04/16/2021	968516	COMBINATION SWITCH MERC BENZ 0500LE A0085450124								1288779
216	04/16/2021	968516	Consumables								1288779
216	04/15/2021	968164	Drv entered - Elec and Light Indicators Not Working	secured the indicator stalk							1288312
216	04/15/2021	968164	Consumables								1288312
216	04/14/2021	968070	Place new poster over the top attach hangers to hand rails	completed.							1288312
216	03/31/2021	965610	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECALS	fitted.							1285627
216	03/31/2021	965611	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	C							1285627
216	03/24/2021	962875	Drv entered - Steering Steering Wheel Faulty	Checked and tested no faults found.							1284335
216	03/20/2021	961982	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI								1283856
216	03/17/2021	961276	Mechanic entered - CCTV Warning Light On Passenger camera no	Reconnect the plug at camera ok							1283413
216	03/15/2021	960713		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Could not complete the check list due to no training							1282942
216	03/12/2021	960064	Ops Entered - Fault - Elec and Light - Route: - LHS head l	Replaced globe							1282472
216	03/12/2021	960064	Consumables								1282472
216	03/11/2021	956097	Mechanic entered - Elec and Light Other Battery terminal mel	Replaced batteries and damaged terminal							1282472
216	03/11/2021	956097	Consumables								1282472
216	03/10/2021	959545	Ops Entered - Fault - Body - Route: 770 - Frankston Station	Replace missing screws in steering column plastic covers and secure covers							1282233
216	03/10/2021	959545	Consumables								1282233
216	02/27/2021	956979	Keep ol poster in holder and place Travel off Peak and Sav	xx							1280514
216	02/27/2021	957052	Leave old poster in and fit you must wear a maskover the	xx							1280514
216	02/22/2021	956058		VEHICLE SAFETY INSPECTION							1279942
216	02/22/2021	956058		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS							1279942
216	02/22/2021	956079	Mechanic entered - Engine Belts_Loose Noisy Missing Main bel	Replaced the belt road tested ok							1279942
216	02/22/2021	956079	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG								1279942
216	02/22/2021	956097	BATTERY 1100CCA POS ON LHS								1279942
216	02/15/2021	953608	Consumables								1278980

[illegible]

216	12/10/2020	940450	Consumables			1267724
216	12/10/2020	940471	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 8	Checked all brakes and testdriven no faults found. Could be a result of the P1 going flat as it had a puncture. Test driven after relpacing the tyre.		1267148
216	11/27/2020	937739	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	completed		1265245
216	11/21/2020	934869	Remove old poster and fit you must wear a face mask when t	xx		1263685
216	11/19/2020	934777	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG			1263685
216	11/19/2020	934777	HOSE ELBOW RADIATOR MERC 0500LE 50N0544 A6285017782			1263685
216	11/19/2020	934777	HOSE COOLANT HOSE 90DEG TAPERED 60/70 MERC 0500LE 50N0543			1263685
216	11/19/2020	934777	BEARING A/C			1263685
216	11/19/2020	934777	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE 50N0041G			1263685
216	11/19/2020	934777	Ops Entered - Fault - Warning Lights Temperature - Route: 7	Temp repair and bring bus back from Karingle drive. Replace main engine belt. O/S top idler pulley. Found also fan idler hub main bearing colapsed. Replace hub assy Road test and found engine temp running around 95 so replace 2x thermostats and road test at 82. check coolant level ok		1263685
216	11/19/2020	934777	THERMOSTAT 71 DEG MERCEDES 0405+0500LE			1263685
216	11/19/2020	934805	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed.		1263685
216	11/18/2020	928439	REPAIR ACC # 51320	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE286244 Receiving #:300323 Date :2020-11-19		1263924
216	11/14/2020	931601	Apply print film	xx		1262072
216	11/12/2020	931601	Apply print film L1			1262661
216	11/09/2020	931748	Vern changed over bus and returned to depot requested break	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE287116 Receiving #:299904 Date :2020-11-13		1262072
216	11/09/2020	931747	Ops Entered - Fault - Warning Lights Temperature - Route: 8	refer to w/o #931747		1262072
216	11/09/2020	931747	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG	repalced main and alternator belts readjusted main belt pulley checked belts for alignment and walking all ok road tested and parked		1262072
216	11/09/2020	931747	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG			1262072
216	11/02/2020	930112	Ops Entered - Fault - Breakdown - Route: 770 - Karingal Hub			1260689
216	11/02/2020	930112	HOSE COOLANT HOSE 90DEG TAPERED 60/70 MERC 0500LE 50N0543	Replace blown hose refill coolant run up to temp and top up check for leaks		1260689
216	11/02/2020	930372	Fit new Myki Decals & refit COVID-19 decals new position fo	fitted.		1260689
216	10/29/2020	929426		VEHICLE SAFETY INSPECTION		1260689
216	10/29/2020	929426		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1260689
216	10/29/2020	929426		assisted sri		1260689
216	10/29/2020	929435	SINGLE SEAT BASE			1260689
216	10/29/2020	929435	Mechanic entered - Vandalism Other Several seat bases kinfe	Replaced 8 seat bases.		1260689
216	10/29/2020	929435	Mechanic entered - Vandalism Other Several seat bases kinfe			1260689
216	10/29/2020	929466	Mechanic entered - Steering Other steering heavy at idle ne	Steering oil was dirty flushed the system replaced the filter road tested ok		1260689
216	10/29/2020	929466	FILTER STEERING FILTER (153468) (0153468)(349619)			1260689
216	10/29/2020	929466	Mechanic entered - Steering Other steering heavy at idle ne	assisted in flushing power steering oil found oil to be dirty		1260689
216	10/29/2020	929547	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG			1260689
216	10/29/2020	929508	Engine clean	degreased and steam cleaned top of transmission and engine area		1260689
216	10/29/2020	929508	Engine clean			1260689
216	10/29/2020	929547	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG			1260689
216	10/29/2020	929547	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833			1260689
216	10/29/2020	929547	Mechanic entered - Engine Belts_Loose Noisy Missing	replaced the belt with new and idler pulley adjusted road tested ok		1260689
216	10/29/2020	929191	CCTV CCTV not recordingMost cameras are not recording in			1260689
216	10/29/2020	929401		CARRY OUT A SERVICE AS PER CHECK LIST		1260689
216	10/29/2020	929401	Consumables			1261112
216	10/29/2020	929401	Consumables			1261112
216	10/29/2020	929401	Consumables			1261112
216	10/28/2020	929191	CCTV CCTV not recordingMost cameras are not recording in	Reconnect the plugs checked ok		1260689
216	10/28/2020	928439	Accident # 51320	repaired by ECTB		1260689
216	10/22/2020	927997	Mechanic entered - Wheels and Tyres Flat or Leaking P5 low p	checked _P5 and P6 pressure slightly under pressure topped up and checked for leaks ok		1259373
216	10/22/2020	927997	Consumables			1260218
216	10/22/2020	928163	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			1259373
216	10/22/2020	928163	Mechanic entered - Elec and Light Exterior Lights clearance	replaced clearance light		1259373
216	10/22/2020	928163	Consumables			1260218
216	10/15/2020	926450	BusMinder Unable To Log In	Checked log in several times no fault found		1257686
216	10/15/2020	926450	Consumables			1258163
216	10/14/2020	926186	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	etag fitted.		1257686
216	10/07/2020	924482	Mechanic entered - Fluid Leaks Rear of bus	Checked no bad leaks found.		1256007
216	10/06/2020	924083	BusMinder Unable To Log In	Replaced the faulty BMN1086 With BMN1047 and tested.OK.		1256007
216	10/06/2020	924083	Consumables			1256489
216	09/10/2020	919205		VEHICLE SAFETY INSPECTION		1250858
216	09/10/2020	919205		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1250858
216	09/10/2020	919205		ANNUAL SAFETY INSPECTION SERIAL #_ K921951_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1250858
216	09/10/2020	919205	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-FLE010 FLEETCHECK BUS PTY LTD P/O #:PE283475 Receiving #:295640 Date :2020-09-10		1251100
216	09/08/2020	918573	final RSI	Carry out RSI final check and defects Carry out rsi final check and defects. grease.		1250731
216	09/08/2020	918573	Consumables			1250858
216	09/07/2020	918573	final RSI			1250493
216	09/03/2020	917477	Suspension rear leaning	Rermove O/S rear air bag fittings and reseal and refit		1250013
216	09/02/2020	917477	KIT O-RING LARGE VOSS (A6739970145)			1249908
216	09/02/2020	917477	Suspension rear leaning			1249908
216	09/02/2020	917665	CCTV hard drive not conncting to the computer.	Replaced with spare one checked for all lights in the panel ok		1249908
216	09/01/2020	917477	Suspension rear leaning			1249908
216	09/01/2020	917387		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Completed by Lonsdale		1249908
216	09/01/2020	917387	FIRE SAFETY INSPECTION	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE282888 Receiving #:295138 Date :2020-09-02		1249908
216	08/31/2020	917056	steam clean for RSI	completed		1249659
216	08/31/2020	917056	Consumables			1249908
216	08/31/2020	917056	Consumables			1249908
216	08/28/2020	916834	Suspension Leaning rigth rear	Replace o/s/r air bags and replace o rings at suspension valve for supply line req's o rings at top of rear air bags		1249533
216	08/28/2020	916834	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR			1249533
216	08/28/2020	916834	KIT O-RING LARGE VOSS (A6739970145)			1249533
216	08/25/2020	915947	carry out RSI repairs	completed RSI repairs as per chceklist ok (Voss fittings OSR)		1248850
216	08/25/2020	915947	Air System Air_Leak Rear	found air leaks on OSR near air dryer and NSR near air tanks replaced VOSS fitting ORing kits checked for leaks ok		1248850
216	08/25/2020	915947	KIT O-RING LARGE VOSS (A6739970145)			1248850
216	08/20/2020	867066	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833	Parts used were non stock from Seaford Cupboard		1248161
216	08/20/2020	914996	Body replace panel above rear door	Fitted by Scott		1248161
216	08/20/2020	915126	carry out RSI repairs			1248161
216	08/20/2020	915126	SEAT BASE DOUBLE SEAT BASE RETRIMMED			1248161
216	08/20/2020	915126	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1248161
216	08/20/2020	915126	carry out RSI repairs			1248161
216	08/20/2020	915126	STRUT GAS STAY 350Nm 565mm LONG			1248161
216	08/20/2020	915126	LED INTERIOR LAMP GREY (also refer 33531)			1248161
216	08/20/2020	915126	HANDLE GRAB HARD PLASTIC PASSENGER (GREY)			1248161
216	08/20/2020	915126	SEAT BASE PLASTIC SUPERSLIM BLACK DISABLED SEAT			1248161
216	08/20/2020	914996	Consumables			1248609
216	08/20/2020	914996	Consumables			1248609
216	08/20/2020	915126	Consumables			1248609
216	08/20/2020	915126	Consumables			1248609

216	08/19/2020	914865		PRE ANNUAL SAFETY INSPECTION CHECK	1248161
216	08/19/2020	914865		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1248161
216	08/19/2020	913722	Ops Entered - Fault - Body Drivers Seat Belt - Route: - Ar	Replace buckle Replace broken bell button	1248161
216	08/19/2020	913722	BUCKLE SEAT BELT DRIVERSEAT 6860 FATBOYWITH SEATBELT LIGHT		1248161
216	08/19/2020	913722	SWITCH BELL PUSH		1248161
216	08/19/2020	914996	panel # 32565	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA PTY LTD P/O #:PE282034 Receiving #:294110 Date :2020-08-20	1248609
216	08/19/2020	913722	KIT ZF ACCUMULATOR PISTON & S	Creditor #:PT-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:PE281991 Receiving #:294128 Date :2020-08-20	1248609
216	08/19/2020	913722	Consumables		1248609
216	08/19/2020	913722	Consumables		1248609
216	08/15/2020	912938	Remove old A3 Poster and fit with You can no longer top up	xx	1246699
216	08/14/2020	913722	Ops Entered - Fault - Body Drivers Seat Belt - Route: - Ar	Replace buckle cover and secure awaiting parts	1247169
216	08/06/2020	911395	Mechanic entered - Wheels and Tyres Wheel Nut Retension P34	Retensioned to the specs.	1245750
216	08/06/2020	911395	Consumables		1246228
216	08/04/2020	910642	Mechanic entered - Wheels and Tyres Other Check rear brakes.	see w/o 910655	1245498
216	08/04/2020	910642	Consumables		1245750
216	08/04/2020	910655	BOLT CALIPER MTG MERC BENZ 0500LE A9429900114		1245498
216	08/04/2020	910641	Mechanic entered - Brakes Other Rear brakes low.	Completed see w/o 910642	1245498
216	08/04/2020	910655	WIPER ARM N/S (NEW MET)		1245498
216	08/04/2020	910655	Brakes replace O/S brake caliper	replaced both rear calipers road tested with john. everything good.	1245498
216	08/04/2020	910655	Brakes replace O/S brake caliper	Replace worn n/s wiper arm. Replace both rear brake calipers Road test ok	1245498
216	08/03/2020	910534		VEHICLE SAFETY INSPECTION	1245498
216	08/03/2020	910534		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1245498
216	08/03/2020	910534			1245498
216	08/03/2020	910534	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1245498
216	08/03/2020	910640	TYRE 295/80R22.5 RECAP		1245498
216	08/03/2020	910640	Mechanic entered - Wheels and Tyres Damaged P34		1245498
216	08/03/2020	910642	Mechanic entered - Wheels and Tyres Other Check rear brakes.	Removed rear tyres and checked the brakes OSR is low and caliper rubbers worn reported the same fitted tyres and torqued wheel nuts .	1245498
216	08/03/2020	910642	SET DISC PAD SET SCANIA / MERCEDES 0500		1245498
216	08/03/2020	910640	Consumables		1245738
216	08/03/2020	910536	clean Engine and wheel rims		1245498
216	08/03/2020	910655	N/S rear brake caliper 50G8424	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE280937 Receiving #:292914 Date :2020-08-04	1245738
216	08/03/2020	910655	O/S rear brake caliper 50G8423	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE280937 Receiving #:292914 Date :2020-08-04	1245738
216	08/03/2020	910641	Mechanic entered - Brakes Other Rear brakes low.	Replaced NSR only need to replace OSR pads and caliper	1245498
216	08/03/2020	910641	SET DISC PAD SET SCANIA / MERCEDES 0500		1245498
216	08/03/2020	910537	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204		1245498
216	08/03/2020	910537	LAMP NUMBER PLATE		1245498
216	08/03/2020	910537	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1245498
216	08/03/2020	910537	Air System leaking	Replaced o rings at air drier area.	1245498
216	08/03/2020	910537	KIT O-RING SMALL VOSS (A0309971748)		1245498
216	08/03/2020	910537	KIT O-RING LARGE VOSS (A6739970145)		1245498
216	08/03/2020	910537	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG		1245498
216	08/03/2020	910537	FILTER STEERING FILTER (153468) (0153468)(349619)		1245498
216	08/03/2020	910537	FILTER FUEL FILTER VOLVO B7 (8193841-7)		1245498
216	08/03/2020	910533		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1245498
216	08/03/2020	910533	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1245498
216	08/03/2020	910533	AIR DRYER ASSY MERC BENZ 0500LE A0004302915		1245498
216	08/03/2020	910533	SILENCER AIR VALVE CLIP ON 69MM 432-407-070-0		1245498
216	08/03/2020	910535		CARRY OUT A SERVICE AS PER CHECK LIST	1245498
216	08/03/2020	910535	Consumables		1245738
216	08/03/2020	910535	Consumables		1245738
216	08/03/2020	910535	Consumables		1245738
216	08/03/2020	910535	Consumables		1245738
216	07/30/2020	909621	Fluid Leaks Rear of bus radiator leaking	replaced radiator road tested up to temp all ok.	1245151
216	07/29/2020	909621	Fluid Leaks Rear of bus radiator leaking		1245151
216	07/29/2020	909621	radiator 50N0115V	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE280545 Receiving #:292492 Date :2020-07-30	1245258
216	07/29/2020	909621	Fluid Leaks Rear of bus radiator leaking	assisted in fitment of new radiator into bus.	1245151
216	07/29/2020	909621	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615		1245151
216	07/28/2020	909422	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -	replaced gearbox oil and filter test driven no noises shifts smoothly ok	1245151
216	07/28/2020	909422	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1245151
216	07/17/2020	907331	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -	Checked oil level and condition at cold and hot its clean and level ok. road tested slightly jerky on 2nd gear when cold servicable.	1243508
216	07/08/2020	902397	rep[air acc # 50900	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE277961 Receiving #:291046 Date :2020-07-10	1242451
216	07/07/2020	902397	Service - Accident	Repaired by Dandenong Bodysop	1241298
216	06/23/2020	902524	CCTV CCTV not recording. Driver camera not working	Reconnect the plug for driver camera checked ok	1241298
216	06/23/2020	902397	Accident # 50900 O/S panels		1241298
216	06/20/2020	902021	Fit A3 Poster in poster frame and fit decals as requested i	xx	1241298
216	06/16/2020	896931	Apply print film L2R1 R2	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE276333 Receiving #:289257 Date :2020-06-18	1241058
216	06/06/2020	899057		CARRY OUT FIRE EXTINGUISHER TEST & TAG completed	1239128
216	05/30/2020	896931	Apply Print film	xx	1236791
216	05/26/2020	895871	carry out B service	Creditor #:PT-22C001 22 CELSIUS P/O #:PE275922 Receiving #:287818 Date :2020-05-28	1237027
216	05/21/2020	895834		VEHICLE SAFETY INSPECTION	1236085
216	05/21/2020	895834		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1236085
216	05/21/2020	895891	Mechanic entered - Engine Belts_Loose Noisy Missing	Replaced damaged main belt and alt belt.	1236085
216	05/21/2020	895891	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		1236085
216	05/21/2020	895891	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG		1236085
216	05/21/2020	895891	Mechanic entered - Engine Belts_Loose Noisy Missing	Fitted fan belt adjusted and started engine checked ok	1236085
216	05/21/2020	895891	BELT FAN DRIVE MERC 0500LE A0139971992		1236085
216	05/21/2020	895783	CCTV CCTV not recording Forward Facing and Disability Sec	Diagnosed and found forward facing camera is disconnected behind the hard drive connected back and checked ok. Disable area camera was faulty. replaced with new wiring checked for recording ok.	1236085
216	05/21/2020	895871		CARRY OUT A/C - B SERVICE AS PER CHECK LIST by 22	1236085
216	05/21/2020	895871		Assisting	1236085
216	05/21/2020	895871		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1236085
216	05/12/2020	891138	PIPE COOLANT AIR COMPRESSOR	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE274308 Receiving #:286757 Date :2020-05-13	1234654
216	05/05/2020	892271	Drv entered - BusMinder No Power	Chcked bus minder working good	1232979
216	05/05/2020	892271	Consumables		1233452
216	05/02/2020	891138	HOSE OIL FILT HSG - OIL COOLE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE274153 Receiving #:285956 Date :2020-05-04	1232090
216	05/02/2020	891138	HOSE OIL FILT HSG - OIL COOLE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE274153 Receiving #:285956 Date :2020-05-04	1232090
216	04/30/2020	891138	Fluid Leaks Rear of bus oil return pipes leaking		1231355
216	04/30/2020	891138	Fluid Leaks Rear of bus oil return pipes leaking	Replace leaking cooler pipes run and check for leaks	1231355
216	04/29/2020	891089	Drv entered - Exhaust leak 3 hose has come loose in the en	intake pipe rubber hose from manifold poppd off fitted back and tested ok	1231355
216	04/24/2020	890422		CARRY OUT B SERVICE AS PER CHECK LIST Completed.	1230796
216	04/24/2020	890422	FILTER OIL FILTER MERCEDES A0001801709		1231115
216	04/24/2020	890422	Consumables		1231115
216	04/24/2020	890422	Consumables		1231115
216	04/24/2020	890422	Consumables		1231115

216	04/24/2020	890422		CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1230796
216	04/24/2020	890422	Consumables		1231115
216	04/24/2020	890422	Consumables		1231115
216	04/24/2020	890422	Consumables		1231115
216	04/18/2020	888076	A4 notification to be printed off in colour laminated and		1228911
216	04/11/2020	887732	Mechanic entered - Air System Air_Leak Rear o/s/r		1228911
216	04/11/2020	887732	KIT O-RING LARGE VOSS (A6739970145)		1228911
216	04/09/2020	887161	MOTOR A/C EVAPORATOR FAN MOTOR		1228769
216	04/09/2020	887161	Drv entered - A/C Heating Demister Not Heating		1228769
216	04/03/2020	885963		replaced demister motor	1227496
216	04/03/2020	885963		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1227496
216	03/31/2020	885155		done	1226431
216	03/25/2020	883881		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1225727
216	03/25/2020	883881		VEHICLE SAFETY INSPECTION Completed.	1225727
216	03/25/2020	884058	Mechanic entered - Brakes Other pedal rubber missing.	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned to the specs.	1225727
216	03/25/2020	884058	PAD BRAKE PEDAL RUBBER MERC BENZ 500LE A1072910182	Replaced.	1225727
216	03/24/2020	883431	Remove old poster and fit Reduce Your Risk of Coronavirus		1225727
216	03/24/2020	883432	Tape off front Seats of All Route and Rail Buses with spec	done	1224365
216	03/20/2020	881728	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG	done	1224365
216	03/20/2020	881728	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		1224365
216	03/20/2020	881728	Mechanic entered - Engine Belts_Loose Noisy Missing	Fitted new belts aligned road tested ok	1224365
216	03/20/2020	881728	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1224365
216	03/20/2020	881728	replace all belts and align A/C comp and pulleys		1224126
216	03/18/2020	881188	Drv entered - A/C Heating Not Cooling	warranty work carried out by coachair	1224126
216	03/18/2020	881188	Drv entered - A/C Heating Not Cooling		1224126
216	03/18/2020	881188	Ops Entered - Fault - A/C Heating Not Cooling - Route: 832		1221614
216	02/28/2020	877678	Drv entered - A/C Heating Not Cooling	by 22	1221614
216	02/28/2020	877678	Drv entered - A/C Heating Not Cooling	Assisting	1222087
216	02/27/2020	877678	AIR CONDITIONING REPAIR	Creditor #:PT-22C001 22 CELSIUS P/O #:PE270044 Receiving #:281164 Date :2020-03-03	1220942
216	02/25/2020	876454	Mechanic entered - Wheels and Tyres Damaged P3 tyre cut in s	checked tyre and found small cut in sidewall not showing any steel still ok	1221255
216	02/25/2020	876454	Consumables		1221255
216	02/25/2020	876454	Consumables		1220460
216	02/18/2020	871759	repair acc # 50307	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE268092 Receiving #:280075 Date :2020-02-20	1219673
216	02/07/2020	868456	AIR CONDITIONING REPAIR after	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE266992 Receiving #:279341 Date :2020-02-12	1219673
216	02/05/2020	871759	Accident # 50307 & 50308	by ECTB	1219673
216	02/05/2020	871759	Accident # 50307 & 50308	Assisting	1221101
216	02/01/2020	865953	convert compressor to X430	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE266184 Receiving #:280437 Date :2020-02-25	1219673
216	01/30/2020	865528	AIR CONDITIONING REPAIR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE266044 Receiving #:278685 Date :2020-02-04	1217808
216	01/25/2020	869185	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	xx	1217808
216	01/23/2020	869126	Mechanic entered - Engine Belts_Loose Noisy Missing A/C belt	Replace belt and align pulleys fit locking bolt to l/h idler pulley	1217808
216	01/23/2020	869126	BELT MICRO V SERPENTINE BELT 9 RIB 2010mm LONG		1216764
216	01/20/2020	868456	A/C repaires after compresor installation	coachair	1216764
216	01/20/2020	868456	A/C repaires after compresor installation	Assisting	1216764
216	01/17/2020	867066	A/C convert to X430		1216764
216	01/17/2020	867922	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Carry out service as per specs wash down trans and engine	1216764
216	01/16/2020	867066	A/C convert to X430	refit intake pipe and refit header tank to[p up coolant	1216764
216	01/16/2020	867066	CONDENSOR FAN A/C CITI-RT		1216764
216	01/14/2020	867066	A/C convert to X430	Assisting Position new compressor in position weld plates and mark out holes remove plates and drill tap holes to bottom plate refit and mount compressor remove and reposition plates refit compressor fit new idler pulleys fit belts run and test remove header tank for access to a/c pipes for repairs	1216764
216	01/14/2020	867066	A/C convert to X430	carried out by coachair	1216764
216	01/14/2020	867066	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1216764
216	01/10/2020	865953	A/C compressor leaking convert to X430		1216764
216	01/10/2020	865953	clean engine and A/C compressor area	helped convert old AC compressor for to now type	1216445
216	01/07/2020	865528	Drv entered - A/C Heating Not Cooling	done by coachair	1216445
216	01/07/2020	865528	Drv entered - A/C Heating Not Cooling	Assisting	1216445
216	01/07/2020	865528	Drv entered - A/C Heating Not Cooling		1215630
216	01/02/2020	864575	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	retensioned to spec	1216445
216	01/02/2020	864575	Consumables		1217808
216	01/01/2020	841359	repair acc # 49544	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE257628 Receiving #:277624 Date :2020-01-22	1215630
216	12/31/2019	864427		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Completed.	1215630
216	12/31/2019	864427	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1215630
216	12/31/2019	864478	Mechanic entered - Wheels and Tyres Worn P1 tyre sidewall wo	Replaced the side wall damaged tyre with a new cleanskin and tensioned to specs.	1215630
216	12/31/2019	864484	Mechanic entered - Wheels and Tyres Damaged sidewall damaged	refer to 864478	1215630
216	12/31/2019	864478	TYRE 295/80R22.5 NEW		1216129
216	12/31/2019	864478	Consumables		1215630
216	12/31/2019	864484	Consumables		1216129
216	12/31/2019	864428		CARRY OUT A SERVICE AS PER CHECK LIST Completed	1215630
216	12/31/2019	864428	Consumables		1216129
216	12/31/2019	864428	Consumables		1216129
216	12/31/2019	864428	Consumables		1216129
216	12/31/2019	864428	Consumables		1215630
216	12/28/2019	864030	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Carry out retension	1215974
216	12/28/2019	864030	Consumables		1215630
216	12/27/2019	863952		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned to specs.	1215630
216	12/27/2019	863952		VEHICLE SAFETY INSPECTION Completed.	1215630
216	12/27/2019	863970	Mechanic entered - Wheels and Tyres Worn Pos 5 and 6.	Replaced with 2 new retreads and tensioned to specs.	1215630
216	12/27/2019	863970	TYRE 295/80R22.5 RECAP		1215974
216	12/27/2019	863970	Consumables		1215630
216	12/18/2019	862381	video loss repair 18/12/19	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE265259 Receiving #:275908 Date :2019-12-27	1213828
216	12/17/2019	862381	CCTV	xx	1213828
216	12/17/2019	862455	Mechanic entered - Body Windows Front small crack in windsc	replaced	1214227
216	12/17/2019	862455	Consumables		1214227
216	12/17/2019	862455	Consumables		1215195
216	12/12/2019	862381	CCTV 6 month service/video los	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE265059 Receiving #:275844 Date :2019-12-24	1214443
216	12/12/2019	862455	supply and install windscreen	Creditor #:PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:PE265261 Receiving #:275414 Date :2019-12-19	1209008
216	12/08/2019	860496		CARRY OUT FIRE EXTINGUISHER TEST & TAG completed	1209008
216	12/08/2019	859916	A3 Poster Frame Adhesive Decal Campaign please remove old	xx	1209008
216	12/07/2019	858719	PERFORM CAMPAIGN 28/19 ROUTE BUS WHEELCHAIR TRIAL DECAL INS	xx	1209647
216	12/02/2019	857856	starter motor A457151030180	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE263709 Receiving #:274046 Date :2019-12-04	1209647
216	12/02/2019	857856	400AMP fuse N000000002682	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE263709 Receiving #:274046 Date :2019-12-04	1210043
216	12/01/2019	857856	tow cranbourne to seaford	Creditor #:PT-EAG001 EAGLE TOWING & SALVAGE P/O #:PE263763 Receiving #:274137 Date :2019-12-05	1208833
216	11/29/2019	857856	Fault#:37117 - Ops Entered - Fault - Breakdown Not Starting		1208833
216	11/29/2019	857856	Fault#:37117 - Ops Entered - Fault - Breakdown Not Starting	found blown starter fuse replaced fuse and removed starter motor cleanedcontacts GREASED and refitted started motor tested and started bus several times ok	1208833
216	11/29/2019	857856	Ops Entered - Fault - Elec and Light Flat Batteries - Rout		1208833

216	11/29/2019	857856	Ops Entered - Fault - Elec and Light Flat Batteries - Route		1208833
216	11/29/2019	857856	Consumables		1209008
216	11/27/2019	857309	Mechanic entered - Elec and Light Exterior Lights	Replace n/s park globe	1208035
216	11/27/2019	857309	Consumables		1208833
216	11/25/2019	856720	Mechanic entered - Body Windows Front Broken front windscre	done by alhpa	1207638
216	11/25/2019	856720	Mechanic entered - Body Windows Front Broken front windscre	Assisting	1207638
216	11/25/2019	856720	Small chip caused by wind in the front windscreen		1207638
216	11/25/2019	856720	Consumables		1208035
216	11/22/2019	856720	repair windscreen		1208434
216	11/19/2019	855524	Drv entered - Body Front_Door Operation Faulty	Creditor #:PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:PE261000 Receiving #:273431 Date :2019-11-27	1206887
216	11/19/2019	855524	Consumables	fitted door breather on exhaust port for opening no fault found	1206955
216	11/18/2019	855120	Drv entered - Body Front_Door Operation Faulty	Checked operation ok	1206206
216	11/18/2019	855120	Consumables		1206887
216	11/14/2019	854457	Mechanic entered - Wheels and Tyres Wheel Nut Retension P2	retensioned ps 2 wheel	1205290
216	11/14/2019	854457	Consumables		1206206
216	11/14/2019	854626	SWITCH DOOR CONTACT (NORMALLY OPEN)		1205290
216	11/14/2019	854626	Mechanic entered - Body Front_Door Operation Faulty	no fault found but replaced door button micro switch all working good.	1205290
216	11/14/2019	854511	Drv entered - Body Front_Door Operation Faulty	lubricated door track doors working ok	1205290
216	11/14/2019	854511	Consumables		1206206
216	11/14/2019	854626	Consumables		1206206
216	11/13/2019	854215	Drv entered - Body Windows SideLH mirror arm loose	tightened mirror arm	1205290
216	11/13/2019	854215	Consumables		1206088
216	11/12/2019	853988		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1205290
216	11/12/2019	853988		VEHICLE SAFETY INSPECTION completed	1205290
216	11/12/2019	854004	TYRE 295/80R22.5 NEW		1205290
216	11/12/2019	854004	Mechanic entered - Wheels and Tyres Worn P2 is 1mm	Replaced P2 torqued wheel nuts as per spec	1205290
216	11/12/2019	854004	Consumables		1205686
216	11/04/2019	851777	AIR CONDITIONING REPAIR	Creditor #:PT-22C001 22 CELSIUS P/O #:PE261596 Receiving #:272118 Date :2019-11-12	1205686
216	11/02/2019	851690	Apply print film for Graffiti	xx	1203256
216	11/01/2019	840276	DIRECT PURCHASE - BRAKES	Creditor #:PT-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:PE257279 Receiving #:272732 Date :2019-11-19	1206887
216	10/31/2019	851777	Drv entered - A/C Heating Not Cooling		1203256
216	10/31/2019	851777	Drv entered - A/C Heating Not Cooling	repaired by 22	1203256
216	10/30/2019	851412	CCTV repairs		1203028
216	10/24/2019	850133	Consumables		1201493
216	10/24/2019	850132	Consumables		1201493
216	10/24/2019	850131	Consumables		1201493
216	10/24/2019	850133	Drv entered - BusMinder Unable To Log In		1200962
216	10/24/2019	850132	Drv entered - BusMinder Unable To Log In		1200962
216	10/24/2019	850131	Drv entered - BusMinder Unable To Log In	inspect bus minder system has power but wont log in	1200962
216	10/24/2019	850083		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Carry out air system service as per specs inspect dryer and change filter	1200962
216	10/24/2019	850083	FILTER AIR DRYER C/W COALESCING VOLVO B13R 21620181		1200962
216	10/24/2019	850082	Consumables		1201493
216	10/24/2019	850082	Consumables		1201493
216	10/24/2019	850082	Consumables		1201493
216	10/24/2019	850082	Consumables		1201493
216	10/24/2019	850082		CARRY OUT A SERVICE AS PER CHECK LIST Carry out A service as per specs	1200962
216	10/23/2019	851690	Apply print film for Graffiti	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE261574 Receiving #:271556 Date :2019-10-31	1203483
216	10/21/2019	849238	Consumables		1200466
216	10/21/2019	849238	Drv entered - BusMinder Unable To Log In	no fault found	1199774
216	10/18/2019	844605	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE258849 Receiving #:270308 Date :2019-10-18	1199774
216	10/17/2019	848710	Ops Entered - Fault - Wipers and Washers Wipers Not Working	removed wiper arms and cleaned splines fitted back and tested speeds ok	1199572
216	10/17/2019	848710	Ops Entered - Fault - Wipers and Washers Wipers Not Working		1199572
216	10/08/2019	846774	CCTV - 6 month service and loss of video repair	xx	1196802
216	10/07/2019	846774	6 months service and video los	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE259657 Receiving #:271537 Date :2019-10-31	1203483
216	10/06/2019	845974	PERFORM CAMPAIGN 21/19 PUSH TO TALK / BUS MINDER SECURITY C	done	1196099
216	10/04/2019	846005	Consumables		1196683
216	10/04/2019	846005	Ops Entered - Fault - BusMinder No Power - Route: 780 - Ca	done	1196273
216	10/01/2019	844109	drag link 50L227	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE258645 Receiving #:269169 Date :2019-10-08	1196802
216	09/26/2019	844605		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1194988
216	09/26/2019	844605		VEHICLE SAFETY INSPECTION	1194988
216	09/26/2019	844605		ANNUAL SAFETY INSPECTION SERIAL # _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1194988
216	09/26/2019	844527	Consumables		1195169
216	09/26/2019	844527	Mechanic entered - Wheels and Tyres Wheel Nut Retension P 2	tensioned to spec	1194988
216	09/25/2019	844413	Consumables		1194988
216	09/25/2019	844413	Mechanic entered - Wheels and Tyres Wheel Nut Retension	Reetensioned to specs.	1194988
216	09/25/2019	844109	Steering ball joint boots split replace drag link	Replaced the draglink adjusted and testedReplaced the kneeling switch.	1194988
216	09/25/2019	844109	SWITCH BUS KNEELING MERC BENZ 0500LE		1194988
216	09/24/2019	844147	Consumables		1194988
216	09/24/2019	844147	TYRE 295/80R22.5 RECAP		1194988
216	09/24/2019	844147	Mechanic entered - Wheels and Tyres Worn	Replace n/s/r tyres and torque to 600nm	1194988
216	09/24/2019	844146	Consumables		1194988
216	09/24/2019	844145	Consumables		1194988
216	09/24/2019	843362	Consumables		1194988
216	09/24/2019	843362	steam clean for RSI	completed	1194988
216	09/24/2019	844146	KIT O-RING LARGE VOSS (A6739970145)		1194988
216	09/24/2019	844146	final RSI		1194988
216	09/24/2019	844145	final RSI		1194988
216	09/20/2019	843602	KIT O-RING LARGE VOSS (A6739970145)		1194668
216	09/20/2019	843602	MUDFLAP 605MM X 330MM		1194668
216	09/20/2019	843602	complete RSI repairs	Completed all defects listed.	1194668
216	09/20/2019	839993	carry out RSI repairs	Completed all defects listed.	1194668
216	09/20/2019	839993	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1194668
216	09/19/2019	843362	steam clean for RSI	steam cleaned under and over gearbox and motor/kingspins	1194668
216	09/10/2019	841359	Accident # 49544	done by ECTB	1194668
216	09/06/2019	840681	Consumables		1194668
216	09/06/2019	840681	Mechanic entered - Wheels and Tyres Wheel Nut Retension from	Retensioned to the specs.	1193639
216	09/06/2019	839993	carry out RSI repairs		1193639
216	09/06/2019	839993	SWITCH STOP/START REAR 0500		1193639
216	09/05/2019	839993	5 inch Exhaust Flex 500mm appr	Creditor #:PT-DAA001 DAALDER EXHAUSTS P/O #:PE257326 Receiving #:266786 Date :2019-09-06	1194041
216	09/04/2019	839993	carry out RSI repairs		1193538
216	09/04/2019	839993	carry out RSI repairs		1193538
216	09/04/2019	839993	BOOT SUPPORT		1193538
216	09/04/2019	840276	ROTOR FRONT & REAR MERC 0500LE A9424230112		1193538
216	09/04/2019	840276	SET DISC PAD SET SCANIA / MERCEDES 0500		1193538

216	09/04/2019	840276	Mechanic entered - Brakes Other Front rotors worn	Replaced front rotors with new pads fitted wheels adjusted the brakesroad tested and checked the temps ok	1193538
216	09/03/2019	839993	carry out RSI repairs		1193538
216	09/03/2019	839993	carry out RSI repairs		1193538
216	09/03/2019	839993	VOLVO B7RLE REAR SHOCK BUSH KIT		1193538
216	09/03/2019	839993	HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500 (9314365038525)		1193538
216	09/03/2019	839991	Consumables		1193538
216	09/03/2019	839991	MIRROR ARM LONG LH 19mm		1193538
216	09/03/2019	839991	replace N/S mirror bracket	removed old mirror bracker and replaced with a new mirror bracket	1193538
216	09/02/2019	839528		PRE ANNUAL SAFETY INSPECTION CHECK	1192386
216	09/02/2019	839543	Consumables		1193538
216	09/02/2019	839543	Mechanic entered - Elec and Light Exterior Lights L/H/F park		1192386
216	09/02/2019	839544	Air System Air_Leak Rear rear booster leak	Check for brake air leaks. Only found slight leak from n/s/f brake chamber clamp. Tightend and check ok	1192386
216	09/01/2019	836830	Consumables		1193381
216	09/01/2019	836830	WINDSCREEN		1195467
216	09/01/2019	837098	FIRE SAFETY INSPECTION	Creditor #:PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:PE256023 Receiving #:268725 Date :2019-10-02	1193639
216	08/31/2019	839421	Drv entered - Brakes Foot_Brakes Noisy	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE256203 Receiving #:266685 Date :2019-09-05	1192386
216	08/31/2019	839421	Drv entered - Brakes Foot_Brakes Noisy	Checked the brakes operationFixed minor air leak at rear booster checked all pads thicknessok. Road tested checked temps NSF 27OSF 29 NSR 32 OSR 33	1192386
216	08/27/2019	830805	GEAR SELECTOR B10M		1191185
216	08/27/2019	830805	GEAR SELECTOR B10M		1191185
216	08/26/2019	837282	Steering drag link ball worn wornaxle side replacable	Replaced the same adjusted the steering straightness secured the clamp road tested ok	1189970
216	08/26/2019	837282	TIE ROD END RHT		1189970
216	08/22/2019	837098		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed by lonsdale auto	1189970
216	08/21/2019	836830	Consumables		1191990
216	08/21/2019	836830	Body Windows Front Front screen broken	done	1189694
216	08/21/2019	836831	Accident # 49433	Replaced centre bumper	1189694
216	08/20/2019	836599		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed	1189694
216	08/20/2019	836599		VEHICLE SAFETY INSPECTION Completed	1189694
216	08/20/2019	836675	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1189694
216	08/20/2019	836675	Mechanic entered - Wipers and Washers Other	Replaced wiper blades.	1189694
216	08/20/2019	836404	Mechanic entered - Elec and Light Exterior Lights	replaced headlight bulb	1189694
216	08/17/2019	836035	Mechanic entered - Elec and Light Exterior Lights	O/S/F LED parker replaced.	1188721
216	08/07/2019	833905	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)		1185523
216	08/07/2019	833905		CARRY OUT C SERVICE AS PER CHECK LIST	1185523
216	08/07/2019	833905	FILTER AIR FILTER MERCEDES BENZ		1185523
216	08/07/2019	833905	FILTER FUEL MERCEDES (A5410900151)		1185523
216	08/07/2019	833905	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		1185523
216	08/07/2019	833905	FILTER OIL FILTER MERCEDES A0001801709		1185523
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST	1185523
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST carry out A B C services as per spec sheet	1185523
216	08/07/2019	833905	Consumables		1191990
216	08/07/2019	833905	Consumables		1191990
216	08/04/2019	832863	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	xx	1183976
216	08/01/2019	832473	Consumables		1183976
216	08/01/2019	832473	Drv entered - Body Drivers Seat Belt	Remounted driver seat belt	1183152
216	07/30/2019	831837	Consumables		1183152
216	07/30/2019	831837	Mechanic entered - Elec and Light Indicators Not Working	Refit the fallen plug behind the Hazzard switch and tested.	1182346
216	07/25/2019	830805	Mechanic entered - Gearbox Driveline Other Gear selector wo		1179618
216	07/24/2019	830727		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed.	1179618
216	07/24/2019	830727		VEHICLE SAFETY INSPECTION Completed.	1179618
216	07/24/2019	830805	GEAR SELECTOR B10M		1179618
216	07/24/2019	830805	Mechanic entered - Gearbox Driveline Other Gear selector wor	Replaced the switch with a modified cover.	1179618
216	07/24/2019	830728	Mechanic entered - Fluid Leaks Other found coolant level low	Leak detected at the heater pipes near radiator. tightened all the clampscleaned the area and released for further investigations.	1179618
216	07/23/2019	830424	Ops Entered - Fault - Eng Cool - Route: 760 - Carrum Downs	replaced heater hose rear of transmission	1179618
216	07/19/2019	829809	KIT O-RING LARGE VOSS (A6739970145)		1178495
216	07/19/2019	829809	Mechanic entered - Air System Air_Leak Rear	fitted new VOSS fitting kit to hose in side hatch compartment next to air dryer all good. air pressure built to 10bar no leaks	1178495
216	07/17/2019	829288	Consumables		1178495
216	07/17/2019	829288	Consumables		1178495
216	07/17/2019	829288	Mechanic entered - Body Drivers Seat Belt drivers seat belt	checked drivers seat belt function ok	1178054
216	07/11/2019	828135	Consumables		1177338
216	07/11/2019	828135	Consumables		1177338
216	07/11/2019	828135	SEAT ISRI FAT BOY 6860-875 LH Control		1176951
216	07/11/2019	828135	Drv entered - Body Drivers Seat Controls		1176951
216	07/11/2019	828135	Drv entered - Body Drivers Seat Leaningseat back collapses	Check and found seat back ratchet faulty. Replace drivers seat	1176951
216	06/25/2019	825033	cctv service	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE251239 Receiving #:260336 Date :2019-06-27	1174160
216	06/25/2019	825033	CCTV service		1173245
216	06/25/2019	824962	Consumables		1173759
216	06/25/2019	824962	Consumables		1173759
216	06/25/2019	824962	Mechanic entered - Body Windows Side NS loose	Resealedwith Slikaflex.	1173245
216	06/11/2019	822092		VEHICLE SAFETY INSPECTION	1170567
216	06/11/2019	822092		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1170567
216	06/06/2019	821475	Consumables		1170567
216	06/06/2019	821475	Consumables		1170567
216	06/06/2019	821475	Ops Entered - Fault - Body Windows Front - Route: - Off s	replaced by alhpa	1170273
216	06/01/2019	801805	A0005000364 Fan	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE242599 Receiving #:259206 Date :2019-06-18	1171820
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables		1169447
216	05/29/2019	819805	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	1168985
216	05/27/2019	819266	KIT O-RING SMALL VOSS (A0309971748)		1168763
216	05/27/2019	819266	KIT O-RING LARGE VOSS (A6739970145)		1168763
216	05/27/2019	819266	AIR DRYER ASSY A0004302915		1168763
216	05/27/2019	819266	CIRCUIT PROTECTION VALVE		1168763
216	05/27/2019	819266	Mechanic entered - Air System Other not building	Faulty airdrier and 6way valve leaking. Replaced both with new Orings.	1168763

216	05/23/2019	818834	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE			1167898
216	05/19/2019	817190	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	xx		1167898
216	05/16/2019	817140	Drv entered - A/C Heating Not Heating	by 22		1167898
216	05/16/2019	817140	repair not heating	Creditor #:PT-22C001 22 CELSIUS P/O #:PE248152 Receiving #:257124 Date :2019-05-22		1168487
216	05/16/2019	817140	carry out A service	Creditor #:PT-22C001 22 CELSIUS P/O #:PE248152 Receiving #:257124 Date :2019-05-22		1168487
216	05/16/2019	817140		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1167898
216	05/12/2019	815237	Please remove all old poster and fit MYKI has gone mobil	xx		1167148
216	05/05/2019	813172		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1167148
216	05/05/2019	813172		xx		1167148
216	05/02/2019	813482	FILTER AIR FILTER MERCEDES BENZ			1167573
216	05/02/2019	813482	Drv entered - Engine Low Power	Checked and found exhaust brake butterfly valve disconnected fitted back replaced air filter was dirty road tested ok		1167573
216	05/01/2019	798450	DIRECT PURCHASE ACCIDENT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE242328CR Receiving #:256617 Date :2019-05-16		1168115
216	04/30/2019	812556	Brake Pedal Rubber 0500 Mercedes (A1072910182)			1167148
216	04/30/2019	812556	Mechanic entered - Brakes Other pedal rubber missing	fitted new rubber		1167148
216	04/24/2019	811925	Breakdown Overheating/Cooling System	removed raditor to fit new fan angle drive refitted raditor with new parts tested and checked for leaks ok		1166265
216	04/24/2019	811558	Engine Orange warning light of overheating	found defective angle drive need to remove and fit new one		1166265
216	04/24/2019	811926	Consumables			1166930
216	04/24/2019	811926	Consumables			1166930
216	04/24/2019	811926	Body Wheel Chair Ramp. Needs new hook			1166265
216	04/23/2019	811558	FAN DRIVE SHAFT	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE246280 Receiving #:255107 Date :2019-05-01		1167573
216	04/23/2019	811558	FAN DRIVE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE246280 Receiving #:255107 Date :2019-05-01		1167573
216	04/23/2019	811558	Engine Orange warning light of overheating	removed radiator and intercooler assembly for angle drive repair		1166265
216	04/18/2019	811184	CCTV 6-months service and repair	done by Johnny on 17/04/2019 PO#: O246165		1166107
216	04/13/2019	810188	Consumables			1165682
216	04/13/2019	810188	Wheel Nut Retension Retension n/s/r wheels	retorque n/s/r wheel nuts.		1165231
216	04/11/2019	809928	Consumables			1165231
216	04/11/2019	809928	Mechanic entered - Wheels and Tyres Worn n/s/r wheels worn			1165191
216	04/04/2019	808225	Ops Entered - Fault - Engine Low Power - Route: 833 - Frank	Replaced n/s/r worn out wheels with two run out tyres		1164359
216	04/04/2019	807845	Consumables	Repaired see w/order 807845		1164559
216	04/04/2019	807845	Elec and Light Warning Light On Dash			1164359
216	04/02/2019	807845	a004153422801 Engine Sensor Oi	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE244872 Receiving #:253240 Date :2019-04-04		1164359
216	04/02/2019	807845	temp sender	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE244871 Receiving #:253237 Date :2019-04-04		1164359
216	04/02/2019	807845	Elec and Light Warning Light On Dash	removed engine ECU plug		1164359
216	04/01/2019	807345	Consumables			1164359
216	04/01/2019	807345	Mechanic entered - Elec and Light Interior Lights Front half	checked all interior lights ok		1163931
216	04/01/2019	798450	repair # 48534	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE242328 Receiving #:253100 Date :2019-04-03		1164359
216	03/26/2019	798450	Accident - NEAR SIDE FRONTacc # 48534	buffed near side panel		1162108
216	03/25/2019	798450	Accident - NEAR SIDE FRONTacc # 48534	the damage has being repaired.Checked OK.		1162108
216	03/21/2019	805289	Consumables			1162108
216	03/21/2019	805289	Consumables			1162108
216	03/21/2019	805289	Drv entered - Body Windows Side	completed		1161897
216	03/18/2019	804241		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1161395
216	03/18/2019	804241		VEHICLE SAFETY INSPECTION		1161395
216	03/13/2019	803229	Consumables			1160580
216	03/13/2019	803229	Consumables			1160580
216	03/13/2019	803229	Drv entered - Body Rear_Door Operation Faulty	checked rear door operation could not fault		1160155
216	03/07/2019	801805	MOUNT EXHAUST RUBBER VOLVO (6850149-3) (6850149)			1158695
216	03/07/2019	801805	Fluid Leaks Rear of bus fan angle drive bracket broken	Fitted the radiator to the bus and the surrounding unitsfilled coolent bled the cooling and the heating circuits and testdriven		1158695
216	03/06/2019	801805	MOUNT RADIATOR MOUNT LOWER MERCEDES 0500LE			1158695
216	03/06/2019	801805	BUSH RUBBER SLEEVE RADIATOR - 0500LE A0009872143			1158695
216	03/06/2019	801805	RADIATOR MOUNT-(STUD TYPE)			1158695
216	03/06/2019	801805	Fluid Leaks Rear of bus fan angle drive bracket broken	Dismantled the rad and intercooler cleanedremoved the fan frme and welded all the crackessilver soldered the Bronze pipe that rubbed and Re assembled the cooling unit.		1158695
216	03/05/2019	801805	Fluid Leaks Rear of bus fan angle drive bracket broken	Removed the Radiator and the intercooler dismantledwashedinspected and replaced the all heater hoses to and from the lift pump.		1158695
216	02/21/2019	784030	REFLECTOR AMBER 94 X 44mm			1156835
216	02/18/2019	798450	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1155975
216	02/18/2019	798450	Accident - NEAR SIDE FRONTacc # 48534			1155975
216	02/18/2019	798502	FILTER AIR DRYER C/W COALESCING VOLVO B13R / B8RLEA E6			1155975
216	02/18/2019	798502	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE			1155975
216	02/18/2019	798502	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE			1155975
216	02/18/2019	798502		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed air system service as per checklist		1155975
216	02/16/2019	798337	CCTV CCTV not recording - Drivers Camra and I believe 1 ot	re connected camera 2 & 4 to hard drive		1155975
216	02/11/2019	784030	REFLECTOR AMBER 94 X 44mm			1155339
216	02/05/2019	793725	AIR CONDITIONING REPAIR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE239763 Receiving #:249225 Date :2019-02-13		1155550
216	02/04/2019	795312	Consumables			1154500
216	02/04/2019	795312	Consumables			1154500
216	02/04/2019	795312	Consumables			1154500
216	02/04/2019	795312		CARRY OUT A SERVICE AS PER CHECK LIST Completed.		1154348
216	01/26/2019	793109	Please remove old 2018 fare decals and fit new 2019 fare de	xx		1152796
216	01/25/2019	793725	A/C Heating Not Cooling	by coachair		1153390
216	01/22/2019	791245	KIT O-RING LARGE VOSS (A6739970145)			1152796
216	01/22/2019	791758	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)			1152796
216	01/21/2019	792457	Consumables			1152796
216	01/21/2019	792457	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	retorqued as per spec		1151736
216	01/18/2019	791758	Mechanic entered - Brakes Other Rear brake pads worn at 5mm	fitted wheels and adjusted brakes road tested and checked brake temps and diff oil level		1151730
216	01/17/2019	791758	ROTOR FRONT & REAR MERC 0500LE A9424230112			1151730
216	01/17/2019	791758	SET DISC PAD SET SCANIA / MERCEDES 0500			1151730
216	01/17/2019	791758	Mechanic entered - Brakes Other Rear brake pads worn at 5mm	removed hub and replaced rotors pads and fitted new hub seal kits on both rear hubs		1151730
216	01/15/2019	791245		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1151370
216	01/15/2019	791245		VEHICLE SAFETY INSPECTION		1151370
216	01/14/2019	790944	Consumables			1151370
216	01/14/2019	790944	EMERGENCY HAMMER COMPLETE WITH CRADLE 2740044	Fitted new hammer		1150567
216	01/14/2019	790944	Mechanic entered - Body Other exit hammer missing	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE236205 Receiving #:246365 Date :2019-01-09		1150567
216	01/08/2019	784030	repair acc damage acc#48214	found 4 defective air bags and replaced ok		1149504
216	01/02/2019	788608	Air System Air_Leak Rearrear suspension dropping			1147456
216	01/02/2019	788608	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR			1147456
216	01/02/2019	788608	KIT O-RING LARGE VOSS (A6739970145)			1147456
216	12/15/2018	785235	Apply print film	Apply print film		1145847
216	12/11/2018	784853	50A3504 O Ring	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE236571 Receiving #:244640 Date :2018-12-13		1145982
216	12/11/2018	784853	50A3501 T/Stat	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE236571 Receiving #:244640 Date :2018-12-13		1145982
216	12/10/2018	784853	Fluid Leaksheater/a/c hose leaking at rear transmissionrep	replaced the hose filled coolant opened the taps road tested ok		1145847
216	12/10/2018	784732	Consumables			1145982
216	12/10/2018	784732	Consumables			1145982
216	12/10/2018	784732	Body O/S rear / rear shock bracket broken off	Repaired by Dandenong		1145847

216	12/10/2018	784731	Accident - OFF SIDE REAR acc # 48214	Repaired by Dandenong	1145847
216	12/08/2018	784670	Breakdown#:35908 - Ops Entered - Breakdown - Breakdown Over	heater hose blownclosed tapsfilled coolant and returned to depot	1145847
216	12/05/2018	784020	Mechanic entered - Elec and Light Exterior Lights OSR marker	w/o/ # 784030	1145340
216	12/05/2018	784030	REFLECTOR AMBER 94 X 44mm		1145340
216	12/05/2018	784030	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1145340
216	12/05/2018	784030	Accident - OFF SIDE REAR # 48214		1145340
216	12/01/2018	785235	Apply Print film	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE236765 Receiving #:244780 Date :2018-12-14	1145982
216	11/23/2018	781372	trans cooler hoses need replacment	Checked the condition of all hoses and coolent leaks.All hoses are in good condition and no coolent leaks detected.	1143787
216	11/22/2018	781252	Consumables		1143787
216	11/22/2018	781252	Elec and Light Exterior Lights N/S/R Side Marker light u/s	checked and repair wiring	1143578
216	11/08/2018	778229		VEHICLE SAFETY INSPECTION	1140862
216	11/08/2018	778229		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1140862
216	11/01/2018	775390	REPAIR ACC # 47928	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE232659 Receiving #:243760 Date :2018-12-03	1145124
216	10/31/2018	776545	Consumables		1139816
216	10/31/2018	776545	Consumables		1139816
216	10/31/2018	776545	Consumables		1139816
216	10/31/2018	776545	FILTER OIL FILTER MERCEDES A0001801709		1139538
216	10/31/2018	776545	FILTER OIL FILTER MERCEDES A0001801709		1139538
216	10/31/2018	776545			1139538
216	10/30/2018	776545		CARRY OUT B SERVICE AS PER CHECK LIST	1139239
216	10/30/2018	776545	Consumables		1139538
216	10/30/2018	776545	Consumables		1139538
216	10/30/2018	776545	Consumables		1139538
216	10/30/2018	776545		CARRY OUT A SERVICE AS PER CHECK LIST	1139239
216	10/24/2018	775390	Accident#:47928 - Ops Entered - Accident - To Be Advised (a		1137239
216	10/23/2018	775112	LAMP INDICATOR LED (HELLA 1406/LLX41212)		1137239
216	10/23/2018	775112	LAMP LED FRONT PARK LAMP WHITE		1137239
216	10/23/2018	775112	Mechanic entered - Elec and Light Exterior Lights OSF top ma	Replace top front lights with LED by Dandy sparkys	1137239
216	10/13/2018	773158	Consumables		1135960
216	10/13/2018	773158	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	retensioned wheel nuts to spec	1135327
216	10/13/2018	772367	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	xx	1135327
216	10/12/2018	772908	Consumables		1135960
216	10/12/2018	772908	TYRE 295/80R22.5 RECAP		1135537
216	10/12/2018	772908	Mechanic entered - Wheels and Tyres Worn P6 tyre will need r	Pos 5 and 6 replaced with 2 new recaps.tensioned to 600Nm and booked for a retension.	1135537
216	10/12/2018	772901	Mechanic entered - Elec and Light Exterior Lights o/s top ma	fitted new marker light and indicator globe lok	1135537
216	10/01/2018	767886	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE230069 Receiving #:239114 Date :2018-10-08	1134897
216	10/01/2018	762727	repair acc # 47700	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE228267 Receiving #:238735 Date :2018-10-03	1134003
216	09/27/2018	769511	Ops Entered - Fault - Engine Low Power - Route: 785 - Rober	Found ramp request light flashing. Clean ramp housing and road test ok	1132422
216	09/23/2018	767477	CCTV	xx	1130701
216	09/22/2018	768435	Mechanic entered - Elec and Light Indicators Not Working	Repair contacts to o/s/f side ind blobe	1130947
216	09/20/2018	767886		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1130701
216	09/20/2018	767886		VEHICLE SAFETY INSPECTION RSI 015627	1130701
216	09/20/2018	767886		ANNUAL SAFETY INSPECTION SERIAL # _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1130701
216	09/19/2018	767462	Consumables		1130701
216	09/19/2018	767462	Consumables		1130701
216	09/19/2018	767462	paint wheel rims	paint wheels and tyres	1130701
216	09/18/2018	767340	final RSI		1130701
216	09/18/2018	767340	Steam clean for RSI		1130701
216	09/18/2018	767037	Carry out RSI final		1130701
216	09/17/2018	767037	PIPE COOLANT VOITH COMPRESS	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE229765 Receiving #:237564 Date :2018-09-19	1130701
216	09/17/2018	767037	Carry out RSI final		1130701
216	09/17/2018	767037	GASKET AIR COMPRESSOR MERCEDES 0500LE		1130701
216	09/16/2018	766224		xx	1130129
216	09/16/2018	766224		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1130129
216	09/13/2018	763003	BUSH RR TORQUE ROD MERC 0500LE A0003302011	rcvg: 235912	1130434
216	09/13/2018	763003	RR SWAY BAR BUSHES 0500	rcvg: 235909	1130434
216	09/13/2018	763003	DIRECT PURCHASE - CHASSIS	rcvg: 236038	1130434
216	09/13/2018	763003	DIRECT PURCHASE - CHASSIS	rcvg: 235912	1130434
216	09/13/2018	763003	carryu out RSI repairs		1130129
216	09/12/2018	765815		VEHICLE SAFETY INSPECTION compleated	1130129
216	09/12/2018	765815		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1130129
216	09/12/2018	763003	KIT O-RING LARGE VOSS (A6739970145)		1130129
216	09/12/2018	763003	carryu out RSI repairs	Replaced orings on suspension valve and brake fitting	1130129
216	09/11/2018	765519	Drv entered - CCTV Warning Light On	no fault found	1129916
216	09/05/2018	763003	LAMP INTERIOR AND REVERSING (1413)		1128606
216	09/05/2018	763003	KIT O-RING SMALL VOSS (A0309971748)		1128606
216	09/05/2018	763003	carryu out RSI repairs	repaired doors wont shut repaired 2 air leaks replaced decal gas struts.	1128606
216	09/01/2018	767477	CCTV 6 month services	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE229953 Receiving #:238176 Date :2018-09-26	1132059
216	09/01/2018	767477	FDI Campaign	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE229966 Receiving #:237787 Date :2018-09-21	1130947
216	09/01/2018	762407	CARRY OUT FIRE SAFETY INSP	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE228194 Receiving #:237451 Date :2018-09-18	1130701
216	08/29/2018	762727	Accident#:47700 - Ops Entered - Accident - Bus Hitting Obje	done	1128236
216	08/28/2018	762433		PRE ANNUAL SAFETY INSPECTION CHECK compleated	1128115
216	08/28/2018	762407		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Completed.	1128115
216	08/25/2018	761850		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1127115
216	08/25/2018	761850		done	1127115
216	08/25/2018	760822	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	xx	1127115
216	08/24/2018	761627	Consumables		1127901
216	08/24/2018	761283	Consumables		1127901
216	08/24/2018	761627	Mechanic entered - Elec and Light Exterior Lights clearance	checked and found new lamp fitted.	1127901
216	08/24/2018	761283	A364327730101 Air Bag	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE227828 Receiving #:235464 Date :2018-08-24	1127901
216	08/24/2018	761627	Air System Air_Leak Front both front air bags leaking	Replaced both front air bags	1127901
216	08/23/2018	761283	A364327730101 Air Bag	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE227828 Receiving #:235454 Date :2018-08-24	1127901
216	08/23/2018	761283	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1127330
216	08/23/2018	761283	Mechanic entered - Elec and Light Exterior Lights NSR clearn	replaced lamp	1127330
216	08/13/2018	758931	Consumables		1125303
216	08/13/2018	758931	Consumables		1125303
216	08/13/2018	758931	Consumables		1125303
216	08/13/2018	758931		CARRY OUT A SERVICE AS PER CHECK LIST A Service completed as per checklist	1124920
216	08/07/2018	757709	CCTV (None) - Not Connecting to Server - unit number does	done	1124132
216	08/03/2018	757071	Consumables		1123921
216	08/03/2018	756931	Consumables		1123921
216	08/03/2018	757071	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Retensioned to 600 Nm.	1123491
216	08/03/2018	756931	TYRE 295/80R22.5 NEW		1123491

216	08/03/2018	756931	Mechanic entered - Wheels and Tyres Damaged Side wall.	Replaced with a new clenskintensioned to 600NM and booked for a retension.	1123491
216	07/28/2018	755644	Suspension Leaningrear	Checked all rear air bag and for leaks.ECAS valve air fitting leak found. Replaced the oring and tested OK.	1122537
216	07/24/2018	754531	CCTV forward facing camera		1121632
216	07/21/2018	753537	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	D	1120439
216	07/14/2018	752329	Consumables		1119717
216	07/14/2018	752329	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Retorqued as per spec	1119717
216	07/13/2018	752081		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1119717
216	07/13/2018	752081		VEHICLE SAFETY INSPECTION Completed.	1119717
216	07/13/2018	752169	Consumables		1119717
216	07/13/2018	752169	TYRE 295/80R22.5 NEW		1119717
216	07/13/2018	752169	Mechanic entered - Wheels and Tyres Worn Pos 2.	Replaced with a new cleanskinTensioned to 600 NM and booked for a retension.	1119717
216	07/13/2018	752167	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		1119717
216	07/13/2018	752167	Mechanic entered - Suspension Leaning	O/S/R/F air bag replaced and tested.	1119717
216	07/07/2018	750171	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	v	1116096
216	07/07/2018	750170	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	v	1116096
216	07/07/2018	750169	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	v	1116096
216	06/30/2018	749194	Vandalism	xx	1115551
216	06/27/2018	748327	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed Campaign	1114975
216	06/18/2018	746157	Consumables		1113311
216	06/18/2018	746157	Mechanic entered - Elec and Light Other wont start	diagnosed and founq 400 amps fuse blown at battery box. replaced the same ok	1113221
216	06/15/2018	745566	Consumables		1113221
216	06/15/2018	745566	Mechanic entered - Wheels and Tyres Damaged P4 sidewall spli	Checked ok only slight cut from stone/rock not deep.	1112898
216	06/15/2018	745495	HEADER TANK	Creditor #:PT-MUL001 MULTISPARES LTD P/O #::PE222277 Receiving #:229877 Date :2018-06-18	1113221
216	06/15/2018	745565	Consumables		1113221
216	06/15/2018	745565	Consumables		1113221
216	06/15/2018	745565	Mechanic entered - Body Other W/chair seat back pin missing	Replace pin	1112898
216	06/14/2018	745495	Fluid Leaks Rear of bus	Mark Holt replaced header tank	1112898
216	06/13/2018	745026	Fluid Leaks Rear of bus	Tighten hose clamp to header tank	1112469
216	06/07/2018	743973	KIT CYCLONE CONDENSER VALVE KIT		1110402
216	06/07/2018	743973	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		1110402
216	06/07/2018	743973		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air system service completed	1110402
216	06/07/2018	743973	KIT O-RING LARGE VOSS (A6739970145)		1110402
216	06/07/2018	743973	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		1110402
216	06/06/2018	743621	Consumables		1111354
216	06/06/2018	743621	Consumables		1111354
216	06/06/2018	743621	Mechanic entered - Body Passenger Seat Torn back rest missin	fitted new back rest	1110402
216	06/05/2018	743307	Mechanic entered - Fluid Leaks Rear of bus coolant leak	secured clamp ok	1110402
216	05/30/2018	742103	Consumables		1110193
216	05/30/2018	742103	Wheels and Tyres Wheel Nut Retension N/S/R	Retensioned to 600 NM.	1109580
216	05/29/2018	741792	Consumables		1109985
216	05/29/2018	741792	TYRE 295/80R22.5 RECAP		1109580
216	05/29/2018	741792	Wheels and Tyres Worn N/S/R at 3mm	Replaced worn and punctured Pos 3and4 tyrestensioned to 600 NM and booked in for a retension.	1109580
216	05/28/2018	741625		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1109580
216	05/28/2018	741625		VEHICLE SAFETY INSPECTION	1109580
216	05/28/2018	741634	Consumables		1109775
216	05/28/2018	741634	Consumables		1109775
216	05/28/2018	741634	Consumables		1109775
216	05/28/2018	741634			1109580
216	05/25/2018	741172	Mechanic entered - Fluid Leaks Rear of bus	CARRY OUT A SERVICE AS PER CHECK LIST A Service Completed	1108501
216	05/22/2018	740311	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	Trace to and tighten hose clamp on header tank	1108171
216	05/21/2018	739384	carry out B service	donme	1108501
216	05/17/2018	739384		Creditor #:PT-COA003 COACHAIR PTY LTD P/O #::PE220313 Receiving #:227955 Date :2018-05-23	1107219
216	05/17/2018	739384		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	1107219
216	05/17/2018	739384		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1104970
216	05/05/2018	736895	Consumables		1104756
216	05/05/2018	736895	Mechanic entered - Elec and Light Exterior Lights N/S lowbea	Replaced and tested.	1103231
216	04/28/2018	735073	Install Anti Graffiti/ Printed film on 17 April	xx	1103886
216	04/24/2018	735073	Window filming	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #::PE218182 Receiving #:226097 Date :2018-04-27 Anti GraffitiPrinted Film 17 April	1102172
216	04/17/2018	729030	Mechanic entered - Steering Excessive Play		1101070
216	04/14/2018	732837	Mechanic entered - Elec and Light Exterior Lights O/S hed li	Replaced and tested.	1100699
216	04/11/2018	729030	Mechanic entered - Steering Excessive Play	removed old steering colume fitted new one road tested and straightend steering wheel	1099604
216	04/05/2018	730961	Consumables		1099239
216	04/05/2018	730961	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	Re-Tensioned wheel nuts	1100699
216	04/04/2018	729030	A973460373101 Steering Column	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #::PE217128 Receiving #:224845 Date :2018-04-11	1098750
216	04/03/2018	730504		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1098750
216	04/03/2018	730504		VEHICLE SAFETY INSPECTION	1098876
216	04/03/2018	730511	Consumables		1098750
216	04/03/2018	730511	TYRE 295/80R22.5 RECAP		1098750
216	04/03/2018	730511	Mechanic entered - Wheels and Tyres Damaged large splits in	replaced o/s/r tyre	1098750
216	03/29/2018	729916	Consumables		1098750
216	03/29/2018	729916	Consumables		1098750
216	03/29/2018	729916	Drv entered - Body Front_Door Operation Faulty	Check no fault found	1098099
216	03/22/2018	728580	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	1097300
216	03/20/2018	727906	A3 Poster Campaign for Seaford Depot only. Wallara Art Com	DJ	1096698
216	03/16/2018	720038	INVOICE ENTERED WITH GST	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE214362REV Receiving #:223376 Date :2018-03-20	1096698
216	03/16/2018	720038	RE-ENTER WITHOUT GST	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE214362A Receiving #:223375 Date :2018-03-20	1096698
216	03/16/2018	720038	Panel Repairs.	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE214362 Receiving #:223173 Date :2018-03-19	1096632
216	03/15/2018	727079	Vandalism Vandalism/ Graffiti Interior		1095711
216	03/15/2018	727079	Vandalism Vandalism/ Graffiti Interior		1095711
216	03/09/2018	726019	Mechanic entered - Fluid Leaks Rear of bus rear radiator pip	found coolant leak at rear of bus checked and found coolant hiose with a split replaced hose and replaced top engine coolant hose topped up coolant roadtest ok	1094500
216	03/09/2018	726019	HOSE ENG UPPER 0500LE		1094500
216	03/07/2018	725356	Consumables		1094299
216	03/07/2018	725356	Consumables		1094299
216	03/07/2018	725356	Consumables		1094299
216	03/07/2018	725356	FILTER FUEL FILTER MERCEDES 0500LE		1094198
216	03/07/2018	725356	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911)		1094198
216	03/07/2018	725356	FILTER FUEL FILTER MERCEDES 0500LE		1094198
216	03/07/2018	725356		Completed.	1094198
216	03/07/2018	725356	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618(E10H02)		1094198
216	03/07/2018	725356			1094198
216	03/07/2018	725356	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1094198
216	03/07/2018	725356	Consumables		1094299
216	03/07/2018	725356	Consumables		1094299
216	03/07/2018	725356	Consumables		1094299

216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356		Completed.		1094198
216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356	Consumables			1094299
216	03/07/2018	725356		Completed.		1094198
216	02/26/2018	722478	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAKE	campaign complete		1092388
216	02/17/2018	720129	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	xx		1090657
216	02/16/2018	720038	Accident - NEAR SIDE MID			1090657
216	02/13/2018	719436	Consumables			1090657
216	02/13/2018	719436	Consumables			1090657
216	02/13/2018	719436	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	replaced broken pop rivets holding front door leaf		1090444
216	02/10/2018	718054		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1089476
216	02/10/2018	718054		DJ done		1089476
216	02/08/2018	718500	(1) fan drive shaft worn (2) fan drive hub bearings siezed	replaced both fan drive hub and and shaft tested ok. complete		1089882
216	02/06/2018	717641	Consumables			1089476
216	02/06/2018	717641	Consumables			1089476
216	02/06/2018	717641	Drv entered - Body Drivers Seat Controls	tighten drivers seat controls		1089072
216	02/01/2018	716716	Consumables			1088637
216	02/01/2018	716716	Mechanic entered - Wheels and Tyres Wheel Nut Retension REAR	Retension pos 3 4 5 and 6 to 670nm complete.		1088422
216	02/01/2018	716716	Elec and Light rear step light n/w	No fault found tested all lights saloon step emerg all working.		1088422
216	01/31/2018	716387		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1088110
216	01/31/2018	716387		VEHICLE SAFETY INSPECTION		1088110
216	01/31/2018	716442	Mechanic entered - Brakes Other	Replace uneven worn rear pads with good used ones Torque rear wheels to 600nm Low pressure in P4 tyre. Inflate and check for leaks none found. Refit to vehicle		1088110
216	12/23/2017	709018	Vandalism Vandalism/ Graffit	Cleaned by Contractor 17/12		1080631
216	12/23/2017	708982	November Audit carried out by GlassProtect completed 29th N	xx		1080631
216	12/22/2017	709707	Mechanic entered - Elec and Light Exterior Lights O/STop hea	Both parker and indicator globes replaced and tested.		1080909
216	12/20/2017	709087	Mechanic entered - Fluid Leaks Rear of bus coolant leak.	replaced coolant hose that had a split resecurd angle drive radiator fan assembly to braket tested okay.		1080730
216	12/19/2017	709087	HOSE ENG UPPER 0500LE			1080631
216	12/19/2017	709087	Mechanic entered - Fluid Leaks Rear of bus coolant leak.			1080631
216	12/15/2017	708341	Engine replace ex muffler	weld up muffler...did not replace		1079988
216	12/15/2017	707841	Ops Entered - Fault - Engine Low Power - Route: 781 - Rober	replaced exhaust brake cylinder tested okay.		1079988
216	12/14/2017	707434	muffle to repair	repair muffler repair muffler		1079988
216	12/13/2017	707841	Exhaust Brake Cylinder Mercedes	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE209516 Receiving #:216632 Date :2017-12-14		1080176
216	12/13/2017	707841	Ops Entered - Fault - Engine Low Power - Route: 781 - Rober	Testdriven replaced both fuel filtertested again no porgress.Could not carry on with advised the Workshop Manager.		1079988
216	12/13/2017	707841	FILTER FUEL FILTER MERCEDES 0500LE			1079988
216	12/13/2017	707841	FILTER FUEL FILTER MERCEDES 0500LE			1079988
216	12/13/2017	707434	muffle to repair			1079988
216	12/12/2017	707434	muffle to repair			1079988
216	12/11/2017	708982	DIRECT PURCHASE - VANDALISM	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE209916 Receiving #:217049 Date :2017-12-20 November Audit carried out 29th Nov		1080730
216	12/07/2017	706517	Top front offside height marker	replaced globe		1079206
216	12/05/2017	706011	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911L)			1078773
216	12/05/2017	706011	Ops Entered - Fault - Engine Low Power - Route: 833 - Fores	Checked and found air filter dirty replaced ok		1078773
216	11/30/2017	705184		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1077670
216	11/30/2017	705184		VEHICLE SAFETY INSPECTION		1077670
216	11/30/2017	705183	Consumables			1078381
216	11/30/2017	705183	Consumables			1078381
216	11/30/2017	705183	Consumables			1078381
216	11/30/2017	705183		CARRY OUT A SERVICE AS PER CHECK LIST		1077670
216	11/29/2017	704743	Drv entered - Engine Low Power			1077670
216	11/29/2017	704753	Mechanic entered - Elec and Light Exterior Lights	O/S/F indicator globe replaced.		1077670
216	11/24/2017	703937	Drv entered - Engine Low Power	Road test no fault found		1076294
216	11/19/2017	701121	Consumables			1075574
216	11/19/2017	701121	Consumables			1075574
216	11/19/2017	701121	Requires wheelchair hook holder	xx		1073516
216	11/17/2017	700277	DIRECT PURCHASE ACCIDENT # 463	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE206784 Receiving #:215266 Date :2017-11-28		1077670
216	11/15/2017	701645	Consumables			1074849
216	11/15/2017	701645	Mechanic entered - Wheels and Tyres Wheel Nut Retension P 5	Retorqued as per spec		1074190
216	11/14/2017	701351	Consumables			1074190
216	11/14/2017	701351	TYRE 11R22.5R RECAP			1074190
216	11/14/2017	701351	Mechanic entered - Wheels and Tyres Worn p56	Replaced p56 tyres torqued as per spec booked for retorque		1074190
216	11/14/2017	701541	Drv entered - Gearbox Driveline Rough Gear Change	found retarter switched on number 2 set back to number 1 tested okay.		1074190
216	11/12/2017	700781	Please remove the 2 x Do Not Enter decals at the exterio	xx		1073516
216	11/09/2017	700277	Accident#:46329 - Ops Entered - Accident - Other - Route:	completed by ECTB		1073516
216	11/04/2017	699716	offside top front parker light	Checked working OK.		1073118
216	11/01/2017	698787	Consumables			1072904
216	11/01/2017	698787	front left tyre sidewall			1072689
216	10/31/2017	698452	Consumables			1072689
216	10/31/2017	698452	Consumables			1072689
216	10/31/2017	698452	Drv entered - Body Windows Side hinge has detached from gl	reseal side windows		1072474
216	10/29/2017	696973	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	Completed.		1071725
216	10/22/2017	695675	Remove old poster and fit new A3 Posters and hangers	done		1070850
216	10/17/2017	694652	Drv entered - Gearbox Driveline Rough Gear Change	Checked trans oil level and cannon plug connection. Road tested could not fault gear shifting.		1070191
216	10/12/2017	689875	repair acc # 46135	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE203659 Receiving #:213216 Date :2017-10-30		1072255
216	09/28/2017	689970	Vandalism Vandalism/ Graffiti Interior	done by eastcoast		1069071
216	09/27/2017	689875	Accident#:46135 - Ops Entered - Accident - Bus Hitting Obje	done by eastcoast		1069071
216	09/25/2017	689187	Remove old A3 Posters with Seniors Festival please leave			1068780
216	09/22/2017	688086	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE203275 Receiving #:210702 Date :2017-09-27	1	1069071
216	09/21/2017	688086		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1067622
216	09/21/2017	688086		VEHICLE SAFETY INSPECTION Completed		1067622
216	09/21/2017	688086		ANNUAL SAFETY INSPECTION SERIAL #		1067622
216	09/21/2017	688086		Assisting		1067622
216	09/20/2017	687680	Suspension Leaning rear O/S please repair	replaced air suspension valve rekitted all leaky fittings tested okay		1067622
216	09/20/2017	687680	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			1067622
216	09/20/2017	687680	Final RSI check	completed a brief overview of RSI final checklist items. found gearbox was wet with gearbox oil cleaned with brakecleaner no time to investigate further.		1067622
216	09/20/2017	687680	REFLECTOR AMBER HELLA 94x44mm			1067622
216	09/20/2017	687680	ECAS CONTROL VALVE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE203161 Receiving #:210243 Date :2017-09-20		1067622
216	09/20/2017	687680	Final RSI check	remove electroyres on body and fit new decals		1067622
216	09/20/2017	681153	Button Shift N HORIZONTAL SERIES 3			1067622
216	09/18/2017	687069	Drv entered - Wipers and Washers Wipers Noisy	no fault found ref Anthony		1067571
216	09/18/2017	687081	Suspension Leaning	Check for air leaks ok check all link rods for adjustment ok. Ropad test ok		1067571

216	09/18/2017	686866	Low Water Probe 0500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE203028 Receiving #:210112 Date :2017-09-19	1067571
216	09/18/2017	687069	Drv entered - Elec and Light Exterior Lights	Replaced low beam lights.	1067571
216	09/18/2017	687069	Drv entered - Elec and Light Horn		1067571
216	09/18/2017	687069	Drv entered - Elec and Light Horn	changed stalk for faulty high beam flash.	1067571
216	09/18/2017	687069	Drv entered - Elec and Light Exterior Lights	Anthony replaced and adjusted front headlights	1067571
216	09/18/2017	687069	LAMP HEADLAMP VOLGREN		1067571
216	09/18/2017	687069	Consumables		1067622
216	09/18/2017	687069	Consumables		1067622
216	09/18/2017	687069	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		1067571
216	09/18/2017	687069	(1) clean and paint wheel rims (2) buff up front body and ne	Cleaned and painted rims. complete buffed entire front end of bus. and fixed top N/S cracks with body filler and painted.	1067571
216	09/18/2017	687069	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	Completed campaign 09/17	1067571
216	09/15/2017	686866	Drv entered - Suspension Knee/ Raise	replaced o/s/r ball joint on suspension level sensor	1067171
216	09/15/2017	686581	Consumables		1067522
216	09/15/2017	686581	Consumables		1067522
216	09/15/2017	686581	replace broken exterior speaker n/s with black painted plate	fit blanking plate	1067171
216	09/14/2017	686581	replace broken exterior speaker n/s with black painted plate	makie blanking platefor speaker hole	1067171
216	09/13/2017	686296	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		1067171
216	09/13/2017	686296		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed.	1067171
216	09/13/2017	686180	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1067171
216	09/13/2017	686180	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		1067171
216	09/13/2017	686180	Suspension Leaningn/sdown after 3mins	replaced two rear n/s airbags and rekittd suspension valve.	1067171
216	09/13/2017	686182	complete RSI repairs	checked the sheet all rsi repairs marked off already.	1067171
216	09/13/2017	686181	Consumables		1067171
216	09/13/2017	686181	Consumables		1067171
216	09/13/2017	686181	steam clean for RSI		1067171
216	09/13/2017	686171	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)	completed.	1067171
216	09/13/2017	686171	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		1067171
216	09/13/2017	686171	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1067171
216	09/13/2017	686171	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1067171
216	09/13/2017	686171	SILENCER SNAP ON SILENCER AIR DRYER (49G3202)		1067171
216	09/13/2017	686171	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		1067171
216	09/13/2017	686171	KIT CYCLONE CONDENSER VALVE KIT		1067171
216	09/13/2017	686171			1067171
216	09/08/2017	685013	RSI repairs	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed.	1067171
216	09/08/2017	685013	SWAY BAR DROP ARM REAR 0500LE	Replaced N/S rear sway bar link and interior rear door top air con panel. Replaced driver console dimister vent.	1066736
216	09/08/2017	685013	LOW WATER PROBE 500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE202334 Receiving #:209466 Date :2017-09-08	1066736
216	09/08/2017	685013	RSI repairs	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE202334 Receiving #:209466 Date :2017-09-08	1066736
216	09/07/2017	685013	KIT AIR LINE FITTING VOSS 22MM (50Z0114)	replaced oring kit x6 fitted wheel arch brush nsr	1066516
216	09/07/2017	685013	SINGLE SEAT BASE		1066516
216	09/07/2017	685013	PAD BRAKE & CLUTCH PEDAL PAD MERCEDES 0500LE		1066516
216	09/07/2017	685013	RSI repairs		1066516
216	09/07/2017	685013	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1066516
216	09/07/2017	685013	RSI repairs		1066516
216	09/04/2017	684133	Consumables		1066299
216	09/04/2017	684133	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos		1066058
216	09/01/2017	683887		PRE ANNUAL SAFETY INSPECTION CHECK	1065429
216	09/01/2017	683971	Consumables		1065430
216	09/01/2017	683971	TYRE 11R22.5R RECAP		1065429
216	09/01/2017	683971	Wheels and Tyres n/s 34 worn	Changed P3 and P4 tyres torqued to 600nm	1065429
216	09/01/2017	683969	STEAM CLEAN FOR RSI		1065429
216	09/01/2017	683175	fire safety insp	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE201655 Receiving #:209413 Date :2017-09-07	1066736
216	08/29/2017	683175		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed.	1064304
216	08/25/2017	682484	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	Completed	1063717
216	08/25/2017	682484	Consumables		1063830
216	08/24/2017	682460	Suspension u bolt broken on rear end.	replaced one o/s/r u bolt	1063717
216	08/24/2017	682459	Engine rear engine mount broken.	replaced both front engine mounts	1063717
216	08/24/2017	679538	Manufacture new pipe	Creditor #:PT-ENZED ENZED DANDENONG P/O #:PE201195 Receiving #:208187 Date :2017-08-25	1063717
216	08/23/2017	682137	A6342400117 Eng Mount Pulley E	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE201049 Receiving #:208182 Date :2017-08-25	1063717
216	08/23/2017	682137		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1063717
216	08/23/2017	682137		VEHICLE SAFETY INSPECTION	1063717
216	08/23/2017	682171	TYRE 11R22.5N NEW		1063717
216	08/23/2017	682171	Mechanic entered - Wheels and Tyres Worn pos 1 tyre very wor	Replace P1 tyre and torque to 600nm	1063717
216	08/23/2017	682171	Consumables		1063717
216	08/23/2017	682137	Diff U Bolts	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE201049 Receiving #:208182 Date :2017-08-25	1063717
216	08/23/2017	682136		CARRY OUT A SERVICE AS PER CHECK LIST	1063717
216	08/23/2017	682137	Consumables		1063717
216	08/23/2017	682137	Consumables		1063717
216	08/23/2017	682136	Consumables		1063717
216	08/23/2017	682136	Consumables		1063717
216	08/21/2017	681454	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	Done	1063270
216	08/19/2017	681153	SELECTOR BUTTON N HORIZONTAL		1062614
216	08/19/2017	681153	Consumables		1062942
216	08/19/2017	681154	Drv entered - Elec and Light Two Way Radio	Checked the operation.Works OK.	1062614
216	08/19/2017	681153	Drv entered - Dash Switches Not Working	D button cover replaced and checkd all switches for operation.All works OK.	1062614
216	08/19/2017	681154	Consumables		1062942
216	08/16/2017	680242	Install graffiti film	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE200352 Receiving #:207474 Date :2017-08-16	1062097
216	08/15/2017	680242	Vandalism	Install Graffiti film	1061594
216	08/15/2017	680126	Consumables		1062097
216	08/15/2017	680125	Consumables		1062097
216	08/15/2017	680126	Drv entered - Dash Switches Not Working	Checked ok	1061594
216	08/15/2017	680125	Drv entered - Elec and Light Two Way Radio	Checked funtion ok	1061594
216	08/15/2017	680127	Consumables		1062097
216	08/15/2017	680127	Consumables		1062097
216	08/15/2017	680124	Consumables		1062097
216	08/15/2017	680124	Consumables		1062097
216	08/15/2017	680127	Drv entered - Body Drivers Seat Leaning	Replaced damaged base	1061594
216	08/15/2017	680124	Drv entered - Body Drivers Seat Cover	Replaced base with new one	1061594
216	08/15/2017	680124	ASSEMBLY RETRIMMED BASE ASSY 6008		1061594
216	08/13/2017	679631	Please remove old posters and fit new one along with hangers	xx	1060825
216	08/11/2017	679538	Campaign 07/17 WIFI CCTV UPGRADE.Coordinate upgrade of		1060825
216	08/03/2017	678033	Mechanic entered - Accident - NEAR SIDE MID	Refer Units R.O. 199775	1060108
216	08/01/2017	677231	Consumables		1060108
216	08/01/2017	677231	Consumables		1060108

216	08/01/2017	677231	Drv entered - Body Front_Door Operation Faulty	Checked front door operation and sensitive edge could not fault doors.	1060108
216	07/27/2017	646483	Consumables		1059165
216	07/27/2017	646483	EMERGENCY HAMMER COMPLETE WITH	Creditor #:PP-KIR001 KIRG IMPORTERS PTY LTD P/O #:PP198976 Receiving #:205962 Date :2017-07-28	1058944
216	07/25/2017	675868	Drv entered - Elec and Light Exterior Lights		1058274
216	07/25/2017	675868	Elec and Light hazzard lights not working	Trace to and replace plug to hazard warning switch	1058274
216	07/07/2017	672437		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1053993
216	07/07/2017	672437		VEHICLE SAFETY INSPECTION	1053993
216	07/07/2017	672460	Fluid Leaks Rear of bus ENGINE	Secured clamp on coolant pipe steam cleaned .	1053993
216	07/07/2017	672464	Mechanic entered - Engine Belts_Loose Noisy Missing fan belt	Replaced belt	1053993
216	07/07/2017	672464	BELT DOUBLE V-BELT MERCEDES 0500LE (A0139971992)		1053993
216	07/01/2017	670269	Consumables		1052269
216	07/01/2017	670269	Consumables		1052269
216	07/01/2017	670269	Remove old Green 2016/17 registration Label and/ or Blue EF	xx	1050898
216	06/21/2017	668442	Gear selector sticking	Cleaned switches checked ok	1049313
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1048140
216	06/17/2017	667944	FILTER AIR FILTER MERCEDES BENZ 0500LE (E491L)		1048140
216	06/17/2017	667944		CARRY OUT B SERVICE AS PER CHECK LIST	1048140
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944	Consumables		1048514
216	06/17/2017	667944		CARRY OUT A SERVICE AS PER CHECK LIST	1048140
216	06/03/2017	664308	Vandalism	xx	1044182
216	06/01/2017	664722	Ops Entered - Fault - CCTV Warning Light On - Route: P15 -	reconfigured cctv system tested okay recording :)	1044520
216	05/31/2017	664722	Ops Entered - Fault - CCTV Warning Light On - Route: P15 -		1044300
216	05/30/2017	664296	Breakdown#:33417 - Ops Entered - Breakdown - Breakdown Road		1044182
216	05/30/2017	664295	Fluid Leaks Rear of bus at thermostat and refit main belt	Refitted orings on thermostats used sealant as well. tested okay. refit main bgelt the correct way.	1044182
216	05/29/2017	664308	DIRECT PURCHASE - VANDALISM	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE194818 Receiving #:201664 Date :2017-05-30	1044182
216	05/29/2017	664028	carry out A service	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE194722 Receiving #:201730 Date :2017-05-31	1044182
216	05/29/2017	664028		CARRY OUT A/C - A SERVICE AS PER CHECK LIST by coachair	1043962
216	05/27/2017	664732	Breakdown - PBL - Melways Ref 104 H12 - Mornington - Overhe	Attended b/down & refitted water pump belt without bottom guide pulley	1043962
216	05/26/2017	663573	Elec and Light Horn**Horn doesnt work throughout the d	Diagnosed and cleaned connectors ok	1043379
216	05/25/2017	662767	Elec and Light Exterior Lights**High-beam not working*	checked ok	1043379
216	05/25/2017	662767	Consumables		1043599
216	05/25/2017	662767	Consumables		1043599
216	05/25/2017	662767	Body Rear_Door Operation Faulty**Rear doors only open		1043379
216	05/22/2017	662751		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1042117
216	05/22/2017	662751		VEHICLE SAFETY INSPECTION Completed	1042117
216	05/22/2017	662434	Fluid Leaks rear	Replaced water pump.	1042117
216	05/22/2017	662434	Fluid Leaks rear		1042117
216	05/22/2017	662767	Drv entered - CCTV Warning Light On	Check cctv system not getting power checked fuse and wiring all good. Needs a electrician to further diagnose fault.	1042117
216	05/20/2017	662434	THERMOSTAT 83 DEGREE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE194088 Receiving #:200860 Date :2017-05-22	1042674
216	05/20/2017	661919	Fit A3 Poster/Hangers	xx	1042117
216	05/19/2017	662434	THERMOSTAT 83 DEGREE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE194088 Receiving #:200876 Date :2017-05-22	1042674
216	05/19/2017	662434	SEAL THERMOSTAT	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE194088 Receiving #:200876 Date :2017-05-22	1042674
216	05/19/2017	662434	Water Pump 0500	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE194088 Receiving #:200876 Date :2017-05-22	1042674
216	05/16/2017	661367	Ops Entered - Fault - Elec and Light Horn - Route: 785 - Fr	Check horn operation ok	1041681
216	05/08/2017	659941	Vandalism Vandalism/ Graffiti Exterior	remove graffiti from rear f bus and cut and polish	1039625
216	05/08/2017	659857	Mechanic entered - Elec and Light Exterior Lights N/S head l	Replaced globe	1039625
216	05/02/2017	658766	Consumables		1038605
216	05/02/2017	658766	Wheels and Tyres retension no 2	completed.	1038382
216	05/01/2017	658531	Warning Lights EngineEngine oil light comes on with both	checked oil level oil is at max on dipstick tube no warning lights coming up cannot fault.	1038078
216	04/28/2017	657612	Consumables		1037885
216	04/28/2017	657612	Mechanic entered - Wheels and Tyres Worn pos 2.		1037885
216	04/28/2017	657612	Mechanic entered - Suspension Noisy O/S/F swaybar link worn	Replaced.	1037885
216	04/28/2017	658440	Drv entered - Steering Pulling		1037885
216	04/28/2017	657179	REGULATOR BOSCH 140AMP 1197311315 (VR3014G)		1037885
216	04/28/2017	657179	Oil Leak (severe)	Fitted the sump and tested.	1037885
216	04/27/2017	657612	Consumables		1037885
216	04/27/2017	657612	Consumables		1037885
216	04/27/2017	657612	Mechanic entered - Body Drivers Seat Cover	clean seat cover	1037885
216	04/26/2017	657612	TYRE 11R22.5N NEW		1037885
216	04/26/2017	657612	Mechanic entered - Wheels and Tyres Worn pos 2.	Replaced torqued to 600 NM.and rebooked for a retoque.	1037885
216	04/26/2017	657612	Mechanic entered - Suspension Noisy O/S/F swaybar link worn		1037885
216	04/24/2017	657612	DROP LINK SWAY BAR A6283201189	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE192160 Receiving #:198986 Date :2017-04-26	1037885
216	04/24/2017	657612	Mechanic entered - Suspension Noisy O/S/F swaybar link worn		1037885
216	04/21/2017	657179	Sump Gasket 49a3401	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE192030 Receiving #:198961 Date :2017-04-26	1037885
216	04/20/2017	657179	Oil Leak (severe)		1037048
216	04/12/2017	655994	Drv entered - Elec and Light Exterior Lights	Replaced Globe	1034775
216	04/10/2017	655633	Consumables		1034436
216	04/10/2017	655633	Ops Entered - Fault - Wheels and Tyres Noisy - Route: 779 -	All tyres checked ok P2 at 3mm but ok. Trace noise to o/s/f Swaybar link worn	1034136
216	04/10/2017	655605	Consumables		1034436
216	04/10/2017	655605	Consumables		1034436
216	04/10/2017	655605	Consumables		1034436
216	04/10/2017	655605		CARRY OUT A SERVICE AS PER CHECK LIST	1034136
216	04/04/2017	654483	Consumables		1033217
216	04/04/2017	654483	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	Retorqued pos 5 and 6 wheel nuts to 600 NM.	1032876
216	04/03/2017	654298		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1032720
216	04/03/2017	654298		VEHICLE SAFETY INSPECTION	1032720
216	04/03/2017	654340	Consumables		1032876
216	04/03/2017	654340	TYRE 11R22.5R RECAP		1032720
216	04/03/2017	654340	Wheels and Tyres worn position 6	Replace o/s/r tyres and torque to 600nm	1032720
216	04/03/2017	654361	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)		1032720
216	04/03/2017	654361	LED FRONT POSITION MARKER LIGHT		1032720
216	04/03/2017	654361	GLOBE 24V 5W BAYONET		1032720
216	04/03/2017	654361	Mechanic entered - Elec and Light Interior Lights Inspection	Replace bus stop globes x2 rear door exit led lamp. Door ok globe	1032720
216	03/31/2017	653947	Consumables		1032337
216	03/31/2017	653947	Mechanic entered - Wheels and Tyres Worn P6	Checked okay feathered 3mm can go another week.	1031690
216	03/25/2017	652270	Please remove any old poster and fit either Good News for T	xx	1029356
216	03/22/2017	640020	VALVE 4 WAY CIRCUIT PROTECTION VALVE		1029356
216	03/17/2017	651403	FILTER WATER TRAP/FUEL FILTER MAN NL202		1028102

216	03/17/2017	651403		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		1028102
216	03/04/2017	648197	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	xx		1023759
216	03/03/2017	649091	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	Completed dash switch labeling		1024502
216	03/01/2017	648473	GLOBE 24V SW BAYONET (17181)			1023759
216	03/01/2017	648473	GLOBE 24V 18W			1023759
216	03/01/2017	648473	Mechanic entered - Elec and Light Exterior Lights o/s/f top	Replace globes in front desto panel		1023759
216	02/23/2017	647018	Consumables			1022731
216	02/23/2017	647018	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	torqued to spec.		1022510
216	02/21/2017	646367		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1022201
216	02/21/2017	646367		VEHICLE SAFETY INSPECTION Completed.		1022201
216	02/21/2017	646483	Consumables			1022292
216	02/21/2017	646483	TYRE 11R22.5R RECAP			1022201
216	02/21/2017	646483	Mechanic entered - Wheels and Tyres Worn Pos 3 and 4.	Replaced and torqued to 600 NM.		1022201
216	02/21/2017	646487	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR			1022201
216	02/21/2017	646487	Mechanic entered - Suspension Soft Both Fr airbags U/S.	Both replaced and tested.		1022201
216	02/21/2017	646366	KIT HALDEX CONDENSER KIT TOP (CYCLONE)			1022201
216	02/21/2017	646366	KIT CYCLONE CONDENSER VALVE KIT			1022201
216	02/21/2017	646366	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER			1022201
216	02/21/2017	646366		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed.		1022201
216	02/14/2017	644481	Drv entered - Elec and Light Horn	Tested works OK.		1020505
216	02/08/2017	633077	DIRECT PURCHASE - MECHANICAL GENERAL	PE184234 Whitehorse Dipstick Rec 191065		1019029
216	02/07/2017	643291	Consumables			1019029
216	02/07/2017	643291	Consumables			1019029
216	02/07/2017	643291	Consumables			1019029
216	02/07/2017	643291		CARRY OUT A SERVICE AS PER CHECK LIST completed.		1018806
216	01/20/2017	639793		incorrectly entered		1013543
216	01/20/2017	639554	Fluid Leaks / engine oil leaks	Checked for leak could'nt fault.		1013543
216	01/20/2017	640020	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			1013543
216	01/20/2017	640020	VALVE 4 WAY CIRCUIT PROTECTION VALVE			1013543
216	01/20/2017	640020	Mechanic entered - Air System Air_Leak Rear	replaced defective 6way valve and replaced o rings on fittings.		1013543
216	01/18/2017	639554	Fluid Leaks / engine oil leaks			1013347
216	01/13/2017	638816		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1011779
216	01/13/2017	638816		VEHICLE SAFETY INSPECTION Completed.		1011779
216	01/10/2017	637783	Consumables			1010746
216	01/10/2017	637783	Consumables			1010746
216	01/10/2017	637783	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	Build up air no defects found with rear door.		1010403
216	01/07/2017	636993	Fit New 2107 Large and Small Fares Small Concessionand AO		1	1009420
216	01/07/2017	636947	A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE CAMPAIGN A		1	1009420
216	12/20/2016	633077	DIRECT PURCHASE - MECHANICAL G	Creditor #:PT-HYD010 HYDROSTEER PTY LTD P/O #:PE183477 Receiving #:190318 Date :2016-12-22 Replace Leaking Input shaft seal only		1005043
216	12/13/2016	633077	Steering box replace	replaced box		1004992
216	12/12/2016	632867	Steering box oil leak			1004992
216	12/12/2016	632781	Drv entered - Elec and Light AM-FM Radio	radio had fallen in dash refitted and resecured tested okay.		1004992
216	12/12/2016	632781	Consumables			1004992
216	12/12/2016	632867	Mechanic entered - Body Other	replace striker plate on drivers door		1004992
216	12/12/2016	632784	Drv entered - Body Drivers Seat LeaningSeat rocking back a	checked drivers seat movement is not excessive checked okay.		1004992
216	12/12/2016	632782	Drv entered - Body Drivers Seat Leaning	checked drivers seat cannot fault.		1004992
216	12/12/2016	632867	Consumables			1004992
216	12/12/2016	632784	Consumables			1004992
216	12/12/2016	632782	Consumables			1004992
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106		CARRY OUT C SERVICE AS PER CHECK LIST		1003780
216	12/07/2016	632106	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911)			1003780
216	12/07/2016	632106	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)			1003780
216	12/07/2016	632106	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618-0_153468			1003780
216	12/07/2016	632106	FILTER FUEL FILTER MERCEDES 0500LE			1003780
216	12/07/2016	632106	FILTER FUEL FILTER MERCEDES 0500LE			1003780
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106		CARRY OUT B SERVICE AS PER CHECK LIST		1003780
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106	Consumables			1003898
216	12/07/2016	632106		CARRY OUT A SERVICE AS PER CHECK LIST		1003780
216	12/07/2016	632106	Consumables			1003898
216	12/01/2016	607323	Consumables			1002230
216	12/01/2016	607323	KIT ROLLAWAY PROTECTION DEVIC	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE179200 Receiving #:189824 Date :2016-12-15		1004992
216	12/01/2016	607323	DIRECT PURCHASE - ELECTRICAL	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE183229 Receiving #:189480 Date :2016-12-09 Bus rollaway		1004107
216	11/28/2016	630305		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1001252
216	11/28/2016	630305		VEHICLE SAFETY INSPECTION		1001252
216	11/22/2016	629113	Mechanic entered - Wheels and Tyres Wheel Nut Retension P3&4	Tension wheels P34		999473
216	11/21/2016	629012	Mechanic entered - Wheels and Tyres Vibration P4 tyre scollo	Jack up bus check wheel bearings. all ok. found Position 4 tyre US. changed tyre (fitted run out tyre) tension wheel nuts. Test drive. no further viabrations found.		999473
216	11/21/2016	628956	Ops Entered - Fault - Warning Lights Batteries - Route: 78	Repair alternator tensioner bolt and lower mount hole. Tested ok. Test fix for rollaway device service mode fault with Ellios. Test drive.		999473
216	11/21/2016	628956	wig-wag globes	Creditor #:PT-BURSON BURSON AUTOMOTIVE PTY LTD P/O #:PE181861 Receiving #:188109 Date :2016-11-22 Switches and cover		999783
216	11/21/2016	628956	Breakdown#:32979 - Ops Entered - Breakdown - Breakdown Road			999473
216	11/20/2016	629194	Elec and Light - Bus wont move	Attended Tanti Ave Mornington - Bus wont move - Found alt belt broken adjuster bolt snapped and alt seized arranged tow		999473
216	11/20/2016	628956	DIRECT PURCHASE - TOWING	Creditor #:PT-EAG001 EAGLE TOWING AND SALVAGE P/O #:PE182254 Receiving #:188445 Date :2016-11-25		1000444
216	11/14/2016	626347	Body	Cut and polished panels brush touched up O/S/F bumper corner		998064
216	11/14/2016	626347	BODY SHOP SUPPLIES			998064
216	11/14/2016	626347	CLEANER GRAFFITI REMOVER AMERASE PER LITRE			998064
216	11/14/2016	626347	HARDENER DELFLEET GRAFFITI RESISTANT PER 500ML			998064
216	11/14/2016	626347	PAINT ANTI GRAFFITI PAINT DARK GREY			998064
216	11/14/2016	626347	PAINT ANTI GRAFFITI PAINT LIGHT GREY			998064
216	11/14/2016	626347	PAINT ANTI GRAFFITI PAINT SATIN BLACK			998064
216	11/11/2016	626347	Vandalism - Interior graffiti paint	refitted rear seats back into bus		998064
216	11/10/2016	626347	Vandalism - Interior graffiti paint	Graffiti repairs		998064
216	11/10/2016	626347	Vandalism - Interior graffiti paint	Graffiti repairs		998064
216	11/09/2016	626347	Vandalism - Interior graffiti paint	removed seats painted top corners o/s n/s and rear top cont masking		998064
216	11/07/2016	626220	Accident - FRONT	COMPLETED BY DANNY		998064

216	11/01/2016	612739	DIRECT PURCHASE - VANDALISM	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE176338 Receiving #:187641 Date :2016-11-16 4 x covers/1 x back/9 x bases/ 1 x disabled cover	998354
216	11/01/2016	617179	Consumables		996832
216	11/01/2016	617179	Consumables		996832
216	11/01/2016	617179	DOUBLE SEAT BASE RETRIMMED	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE177549 Receiving #:187637 Date :2016-11-16	998354
216	11/01/2016	617179	SINGLE SEAT BASE	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE177549 Receiving #:187637 Date :2016-11-16	998354
216	11/01/2016	617179	SINGLE SEAT BASE	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE177549 Receiving #:187637 Date :2016-11-16	998354
216	10/28/2016	624453	Fit A3 poster to holder either Explore Melbourne or PTV Ap	COMPLETE	995446
216	10/24/2016	623386	BATTERY 12V 200AMP 1100CCA + LHS EMFN200L		994376
216	10/24/2016	623386	NUT BRASS BATTERY TERMINAL NEGATIVE (-)		994376
216	10/24/2016	623386	BATTERY12V190 AMP1000CCA MFN200 + RHS		994376
216	10/24/2016	623386	Mechanic entered - Elec and Light Flat Batteries wont start.	Checked for starting checked battries on load both showed no amp on cold crank. Replaced battries.	994376
216	10/07/2016	620603		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	990647
216	10/07/2016	620603		VEHICLE SAFETY INSPECTION Completed.	990647
216	10/07/2016	620607	Drv entered - Gearbox Driveline Vibration	Pos 4 tyre found unevenly worn and vibration is minor.Still11 to 8 mm left on the tyre released for further investigations.	990647
216	10/07/2016	620573	Consumables		990939
216	10/07/2016	620573	Consumables		990939
216	10/07/2016	620573	Consumables		990939
216	10/07/2016	620573	Consumables		990939
216	10/07/2016	620573		CARRY OUT A SERVICE AS PER CHECK LIST Completed.	990647
216	10/05/2016	620135	Consumables		990426
216	10/05/2016	620135	Drv entered - Body Drivers Seat Controls	secure drivers seat back	990188
216	10/01/2016	612739	DIRECT PURCHASE - VANDALISM	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE176087 Receiving #:186338 Date :2016-10-26 2 x back 2 x bases 1 x cover	995008
216	10/01/2016	615434	DIRECT PURCHASE - MECHANICAL G	Creditor #:PT-RPWALL R P WALLIS WHOLESAL P/O #:PE176871 Receiving #:186222 Date :2016-10-25 22mm oil resistant hose	994789
216	09/30/2016	618975	Consumables		989167
216	09/30/2016	618975	A3 Poster Change please remove old poster and fit Vitorian	x	988367
216	09/26/2016	617430	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE177647 Receiving #:184400 Date :2016-09-29	988643
216	09/26/2016	618065	Consumables		988031
216	09/26/2016	618065	Display Frame - A3	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE177957 Receiving #:184126 Date :2016-09-27	988031
216	09/26/2016	618065	REPLACE DRIVERS MODISTY PANEL	fit drivers modesty panel perspex	987299
216	09/25/2016	617676	Campaign 14/16 Destination signs Setting and loadig Files.	X	987299
216	09/22/2016	617430		Assisting	987073
216	09/22/2016	617430		ANNUAL SAFETY INSPECTION SERIAL #	987073
216	09/22/2016	617179	Consumables		987299
216	09/22/2016	617179	RADIATOR MOUNT-(STUD TYPE)	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE177556 Receiving #:183908 Date :2016-09-23	987299
216	09/22/2016	613360	Consumables		987299
216	09/22/2016	613360	Consumable - BODYWORK	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE176074 Receiving #:183780 Date :2016-09-22	987073
216	09/21/2016	617313	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	x	987073
216	09/21/2016	617179	DECAL EMERGENCY EXIT HAMMER SYMBOL		987073
216	09/21/2016	617179	Body Passenger Seat Torn	Replaced 2x graffitied seat backs and 1x graffitied seat base	987073
216	09/21/2016	616694	Consumables		987073
216	09/21/2016	616694	Haldex Kit Oil Sperator HAL87	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE177455 Receiving #:183696 Date :2016-09-21	987073
216	09/20/2016	616833	Consumables		987073
216	09/20/2016	616833	Body Front_Door Operation Faulty	secure plates on back door adjust sensitive edges	987073
216	09/19/2016	616704	Consumables		987073
216	09/19/2016	616694	final RSI		987073
216	09/19/2016	616704	Drv entered - Body Drivers Seat Leaning	no fault found	987073
216	09/19/2016	616704	Drv entered - Body Drivers Seat Controls	no fault found	987073
216	09/13/2016	615597	Steam clean for RSI	Steam cleaned for RSI	985729
216	09/12/2016	615434	ALTERNATOR MOUNTING BUSH	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE176885 Receiving #:183008 Date :2016-09-13	985729
216	09/12/2016	615434	(1) replace oil return pipes ref; vern (2) replace alt moun	replaced both oil filter pipes and bottom alternator bushes	985618
216	09/09/2016	614926	Consumables		985043
216	09/09/2016	614926	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	Tensioned to 600NM.	984824
216	09/08/2016	612739	Vandalism/ seats vandalized	fit new seat covers to dissabled seats	984824
216	09/07/2016	612739	Vandalism/ seats vandalized	fit new clip to back o/s rear door modify same to close properly	984824
216	09/07/2016	613712	STEERING WHEEL 0500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE176388 Receiving #:182628 Date :2016-09-07	984824
216	09/07/2016	613712	Suspension (1) N/S/F sway bar link (2) O/S/R sway bar link	replaced n/s/f sway bar link and o/s/r sway bar link	984824
216	09/07/2016	613239	ex flex leaking	fitted exhaust flex	984824
216	09/07/2016	614522	Engine mounts ?	found in good condition	984824
216	09/07/2016	614626	LED FRONT POSITION MARKER LIGHT		984824
216	09/07/2016	614626	Mechanic entered - Elec and Light Exterior Lights one no. pl	replaced o/s no. plate light	984824
216	09/06/2016	612739	SINGLE SEAT BACK REST		984824
216	09/06/2016	612739	SINGLE SEAT BASE		984824
216	09/06/2016	612739	Vandalism/ seats vandalized	fit overhead panel back door tighten n/s mirror secure panel bolts fit wheel arch brush repair o/s rear door	984824
216	09/06/2016	613712	ARM INDICATOR ARM MERCEDES	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE176362 Receiving #:183079 Date :2016-09-13	985729
216	09/05/2016	612883	GLOBE 24V 5W BAYONET (17181)		984824
216	09/05/2016	612883	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)		984824
216	09/05/2016	612883	LED FRONT POSITION MARKER LIGHT		984824
216	09/05/2016	612883	Mechanic entered - Elec and Light Next Stop Button replace a	repalced all next stop lights	984824
216	09/05/2016	612883	Mechanic entered - Elec and Light Interior Lights all switch	replaced all switch lights	984824
216	09/05/2016	612883	Mechanic entered - Elec and Light Interior Lights two emerge	replaced two emergency exit lights	984824
216	09/05/2016	612883	Consumables		984824
216	09/05/2016	612883	RSI repairs / (1) Front_Door Operation Faulty (2) loose int	fit new seat end covers secure rear modesty panel fit new seat backs andbases r/r dabled seats remove back door overhead panel	984824
216	09/02/2016	613712	SWAY BAR DROP ARM REAR 0500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE176221 Receiving #:182866 Date :2016-09-09	984824
216	09/02/2016	613712	LINK SWAY BAR LH MB 0500	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE176221 Receiving #:182866 Date :2016-09-09 ZF	984824
216	09/02/2016	613712	Suspension (1) N/S/F sway bar link (2) O/S/R sway bar link		984824
216	09/02/2016	612743	Consumables		984824
216	09/02/2016	612743	Direct Purchase - BODYWORK	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE175836 Receiving #:182784 Date :2016-09-08 Modesty Panel and Panel above Rear Door	984824
216	09/02/2016	612883	RSI repairs / (1) Front_Door Operation Faulty (2) loose int	fit seat caps	984824
216	09/01/2016	604657	DIRECT PURCHASE - AIR CONDITIO	Creditor #:PT-QTK001 QTK GROUP P/O #:PE171658 Receiving #:182940 Date :2016-09-12 visit 06/07/2016	985618
216	08/31/2016	613239	ex flex leaking	Removed exhaust flex with dan.g.	984824
216	08/31/2016	612883	Consumables		984824
216	08/31/2016	612883	PASSENGER GRAB HANDLE		984824
216	08/31/2016	612883	RSI repairs / (1) Front_Door Operation Faulty (2) loose int	securerear bell poles remove decals replace yellow step edging rep[lace brab handles secure front modesty panel replace ac ducting	984824
216	08/31/2016	613360	Body drivers modesty panel damaged		984824
216	08/31/2016	613360	Consumables		984824
216	08/31/2016	612858	carry out safety insp	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE175921 Receiving #:182710 Date :2016-09-08	984824
216	08/30/2016	612883	RSI repairs / (1) Front_Door Operation Faulty (2) loose int	repair front door bracket at top r/r air con ducting near side and secure lower section	984824
216	08/30/2016	612930	Please remove old poster and fit new Legacy poster	Replaced Poster	984824
216	08/30/2016	612930	Consumables		984824
216	08/30/2016	612858		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	984824
216	08/29/2016	612752		PRE ANNUAL SAFETY INSPECTION CHECK	984748
216	08/29/2016	612739	Vandalism/ seats vandalized		984748
216	08/29/2016	612734	LIGHT SIDE INDICATOR L/H		984748

216	08/29/2016	612734	Elec and Light/ L/H side indicator		984748
216	08/29/2016	612743	Consumables		984824
216	08/29/2016	612743	Body/ (1) interior panel above rear door (2) drivers modist		984748
216	08/16/2016	610206		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	981745
216	08/16/2016	610206		VEHICLE SAFETY INSPECTION	981745
216	08/16/2016	610215	UNIT WIPER BLADE UNIT 1000mm		981745
216	08/16/2016	610215	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	replaced wiper arms	981745
216	08/16/2016	610243	Mechanic entered - Brakes Foot_Brakes Leaking Air o/s/f diap	replaced o/s/f diaphragm	981745
216	08/15/2016	609828	Consumables		981745
216	08/15/2016	609828	Mechanic entered - Body Other	Drivers sun blind falling down. Fit 2 x new screws and refit blind. Lubricate Gear selector switch with curtain track lubricant.	981634
216	08/09/2016	609047	Drv entered - Elec and Light AM-FM Radio	NO FAULT FOUND	980746
216	08/09/2016	609047	Consumables		980965
216	08/09/2016	609047	Drv entered - Body Drivers Seat Leaning	TIGHTEN BACK OF DRIVERS SEAT AND GREASE CONTROLS	980746
216	08/09/2016	609047	Drv entered - Body Drivers Seat Controls		980746
216	08/09/2016	609047	Drv entered - Body Windows Front		980746
216	08/06/2016	608452	Consumables		980197
216	08/06/2016	608452	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER		979892
216	08/04/2016	608099	Drv entered - Steering Pulling	v	979759
216	08/04/2016	607323	springs	Check steering ok	980746
216	08/04/2016	608099	Drv entered - Elec and Light Warning Light On Dash	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE173861 Receiving #:180510 Date :2016-08-10 A0015454109	979759
216	08/04/2016	608099	Consumables	All dash lights checked no fault found	979892
216	08/04/2016	608099	Drv entered - Body Drivers Seat Controls	Replace recliner handle return spring	979759
216	08/04/2016	608099	front Brakes smoking	Check and adjust ok. Possible overhear due to retarder turned off. Road test ok	979759
216	08/04/2016	608099	Drv entered - Brakes Foot_Brakes Pulling	Check ok	979759
216	08/01/2016	607323	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)		979759
216	07/26/2016	605939		Tensioned to 600 NM.	978265
216	07/23/2016	605626	SET DISC PAD SET SCANIA / MERCEDES 0500		977726
216	07/23/2016	605626	Mechanic entered - Brakes Warning Light On	Check and replaced front and rear brake pads.	977726
216	07/19/2016	604657	A/C Heating A/C not working at allinterior lights not w	Checked all working OK.	976713
216	07/19/2016	604863	DIMISSTERS N/W	checked demisters are working perfectly cannot fault all vents blowing air and air is warm like they are supposed to be.	976713
216	07/19/2016	604862	Consumables		976989
216	07/19/2016	604862	Consumables		976989
216	07/19/2016	604862	DECAL SAFETY TRIANGLE BEHIND PANEL WHITE STBP100		976713
216	07/19/2016	604862	DECAL MAKE YOUR MARK		976713
216	07/19/2016	604862	DECAL PARK BRAKE/ NO WINDOW ACCESS		976713
216	07/19/2016	604862	Mechanic entered - Body Other campaign interior decals		976713
216	07/19/2016	604862	DECAL WARNING MAXIMUM HEIGHT		976713
216	07/19/2016	604862	DECAL FIRE EXTINGUISHER DOWN ARROW		976713
216	07/19/2016	604705	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST carried out service as stated on sheet	976713
216	07/19/2016	604863	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		976713
216	07/19/2016	604863	KIT CYCLONE CONDENSER VALVE KIT		976713
216	07/19/2016	604863		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed air system service tested okay.	976713
216	07/15/2016	598244	LIGHT BRAKE LIGHT LED		976713
216	07/15/2016	598244	GAS STRUT 350NM X 565MM		976713
216	07/15/2016	598244	Supply and apply PTV Acc Whole	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G172251 Receiving #:178616 Date :2016-07-18	976713
216	07/15/2016	598244	BUMPER BOLT SPECIAL		976713
216	07/15/2016	598244	PLASTIC WASHER		976713
216	07/15/2016	598244	INDICATOR LAMP L.E.D.		976713
216	07/14/2016	603816	Air System Air_Leak Rear		976713
216	07/14/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Assembly	976713
216	07/13/2016	603816	INVOICE RECEIVED WITH GST IN E	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE172471REV Receiving #:178791 Date :2016-07-20	976989
216	07/13/2016	603816	RE ENTER WITHOUT GST	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE172471-1 Receiving #:178793 Date :2016-07-20	976989
216	07/13/2016	603816	SOLENOID VALVE ZFAUTO (0501 31	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE172471 Receiving #:178401 Date :2016-07-13	976713
216	07/13/2016	598244	Remove and replace O/S/R windo	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G172417 Receiving #:178383 Date :2016-07-13	976713
216	07/12/2016	598244	RED REFLECTOR 94X44MM 84052		976713
216	07/12/2016	598244	AMBER REFLECTOR		976713
216	07/12/2016	598244	BODY SHOP SUPPLIES		976713
216	07/12/2016	598244	PAINT SUPPLIES		976713
216	07/11/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	prep work maskup painted PTV orange	976713
216	07/08/2016	598244	BUMPER BOLT SPECIAL		976713
216	07/08/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Continued repairs	976713
216	07/08/2016	598244	COOLANT HATCH SURROUND 165x194mm (WHITE)		976713
216	07/07/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	continued repair work on os rear corner panel area fibre glass repaired c/o	976713
216	07/07/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	repairing accident damage	976713
216	07/04/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Continued repairs	976713
216	07/01/2016	598244	F/GLASS REAR PANEL CR222L	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G171900 Receiving #:177854 Date :2016-07-05	976713
216	07/01/2016	598244	SCREW TORX SCREW 8x20mm SIDE PANEL		976713
216	06/29/2016	600670	Vandalism/ Vandalism/ Graffiti Interior in rear	fault eneterd twice	976713
216	06/24/2016	598244	STEEL CLAW CATCHES		976713
216	06/24/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Continued repairs	976713
216	06/23/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Continued repairs	976713
216	06/22/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	Started repairs	976713
216	06/22/2016	598244	OSR BUMPER CORNER	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G170418 Receiving #:176503 Date :2016-06-22	976713
216	06/22/2016	598244	OSR PUNCH PANEL	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G170418 Receiving #:176503 Date :2016-06-22	976713
216	06/17/2016	598568	Please remove any old poster and fit new A3 poster and add		976713
216	06/17/2016	598568	Consumables		976713
216	06/17/2016	598568	Consumables		976713
216	06/16/2016	598244	tow from seaford depot to Dand	Creditor #:PT-EAG001 EAGLE TOWING AND SALVAGE P/O #:PE170393 Receiving #:177095 Date :2016-06-28	976713
216	06/16/2016	598244	Accident damage - O/S/R - Acc # PEN 43345.	towed top danednong	976713
216	06/10/2016	593453	DOUBLE SEAT BASE RETRIMMED		975243
216	06/10/2016	593453	Consumables		975458
216	06/10/2016	593453	Consumables		975458
216	06/08/2016	596325	AIRBAG FRONT AND REAR 0405/0500REAR/ B10M/B7R REAR		974693
216	06/08/2016	596325	Drv entered - Suspension Soft	Testdriven and checked.Two R/R air bags were leaking detected.Both replaced and checked.	974693
216	06/07/2016	596226		CARRY OUT A SERVICE AS PER CHECK LIST	974475
216	06/07/2016	596226	Consumables		974693
216	06/07/2016	596226	Consumables		974693
216	06/07/2016	596226	Consumables		974693
216	06/07/2016	596226	Consumables		974693
216	06/06/2016	562534	BRACKET MIRROR-LONG		974258
216	06/06/2016	562534	ARM MIRROR N/S ARTIC UES 2066900		974258
216	06/06/2016	595992	MAP POCKETS COACH SEATS		974258
216	06/06/2016	595992	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTAL	fit drivers wallet holder	974258

216	06/06/2016	595992	Consumables			974475
216	06/06/2016	595992	Consumables			974475
216	06/03/2016	595550	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	ben were		973217
216	06/01/2016	595550	DIRECT PURCHASE - ELECTRICAL	Creditor #:-PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:-PE171060 Receiving #:176873 Date :2016-06-27		976713
216	05/31/2016	594714		Retensioned pos 3 and 4 wheel nuts to 600 NM.		972349
216	05/30/2016	593346	COMPRESSOR OIL AIR CON			972349
216	05/30/2016	593346	FILTER DRIER A/C THERMO KING			972349
216	05/28/2016	594385	Consumables			972045
216	05/28/2016	594385	Ops Entered - Fault - Wheels and Tyres Flat or Leaking - Ro	Swop bus at Forest dr. return to depot and replace punctured position 3 tyre with matching part worn at 12mm Torque to 600nm		971824
216	05/27/2016	594090	Mechanic entered - Gearbox Driveline Other Selector hard to	Remove selector clean out slides and check over. refit and check. no further faults found		971368
216	05/27/2016	594089	Mechanic entered - Elec and Light Indicators Not Working Haz	Check connector on switch found it had fallen off.		971368
216	05/27/2016	594264	Consumables			971824
216	05/27/2016	594264	DECAL # 8 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 4 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 6 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 6 25MM WHITE			971368
216	05/27/2016	594264	DECAL # 7 25MM WHITE			971368
216	05/27/2016	594264	DECAL # 0 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 8 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 1 25MM WHITE			971368
216	05/27/2016	594264	DECAL # 8 25MM WHITE			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 7 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 2 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 3 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 7 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 5 25MM BLACK			971368
216	05/27/2016	594264	DECAL # 7 25MM BLACK			971368
216	05/27/2016	594264	Mechanic entered - Body Other maximum safe carrying capacity	FITTED STICKERS TO BUS;216 357 355 209 407 1052 433 218 427 319 214 318 473		971368
216	05/27/2016	594264	DECAL # 7 25MM BLACK			971368
216	05/26/2016	593464	DOUBLE SEAT BASE RETRIMMED	Creditor #:-PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-PE168808 Receiving #:174917 Date :2016-05-27		971607
216	05/25/2016	593713	NUT BATTERY TERMINAL NEG (BRASS)			971368
216	05/25/2016	593713	Mechanic entered - Engine Other Engine cut out at Boonong Av	Arrive at vehicle and started up straight away. Drive back to depot but kept cutting out. Clean and dry engine ECU plugs. Starts after approx 20mins. Trace and replace faulty engine brake soleniod and pipe. Replace neg battery terminal. Road test ok.		971368
216	05/25/2016	593451	3/2 Way Solenoid Valve Exhaust	Creditor #:-PT-MUL001 MULTISPARES LTD P/O #:-PE168804 Receiving #:174773 Date :2016-05-26		971368
216	05/24/2016	593345	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115			971367
216	05/24/2016	593345		Comp0leted saftey inspection.		971367
216	05/24/2016	593345		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		971367
216	05/24/2016	593345		VEHICLE SAFETY INSPECTION		971367
216	05/24/2016	593464	Vandalism repair two seater	replaced seat		971367
216	05/24/2016	593453	DOUBLE SEAT BASE RETRIMMED			971367
216	05/24/2016	593453	Ops Entered - Fault - Body Passenger Seat Torn - and dirty s	replaced		971367
216	05/24/2016	593453	Consumables			971368
216	05/24/2016	593451	Air System Air_Leak Rear/ SOLINIOD VALVE LEAKING	fitted by john		971367
216	05/24/2016	593346		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		971367
216	05/24/2016	593346		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		971367
216	05/24/2016	593346		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		971367
216	05/23/2016	588116	Consumables			971367
216	05/23/2016	588116	N/S/F SLACK ADJUSTER VOLVO B7R			971044
216	05/11/2016	591087	Consumables			968436
216	05/11/2016	591087	Seat Belt Buckle			968219
216	05/11/2016	591087	Drv entered - Body Drivers Seat Controls	re[place drivers door hinges tighten drivers seat back and lubricate secure lumber air switch fit drivers seat belt buckle		968219
216	05/01/2016	581577	repaint interior	Creditor #:-PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:-PE164345 Receiving #:175010 Date :2016-05-30		972349
216	05/01/2016	579193	BUTTON CLIPPARD DOOR VALVE	Creditor #:-PT-SMC001 SMC PNEUMATICS (AUST) PTY LTD P/O #:-PE163463 Receiving #:174859 Date :2016-05-27		971607
216	05/01/2016	579193	CLIPPARD VALVE DOOR OPEN/CLOSE	Creditor #:-PT-SMC001 SMC PNEUMATICS (AUST) PTY LTD P/O #:-PE163463 Receiving #:174859 Date :2016-05-27		971607
216	04/29/2016	589133	Ops Entered - Fault - Dimister Not Heating - Route: 780 -	Replace broken demister valve cable and repair seized valve. Check saloon heating ok		965228
216	04/23/2016	588116	Consumables			963778
216	04/23/2016	588116	Consumables			963778
216	04/23/2016	588116	loose mirror arm changeover and secured bracket			963778
216	04/11/2016	585567		VEHICLE SAFETY INSPECTION		961130
216	04/11/2016	585567		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		961130
216	04/11/2016	585649	AIR DRYER UNLOADER KIT			961130
216	04/11/2016	585649	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)			961130
216	04/11/2016	585649	Air System/ air dryer leaking	Rekited air dryer and replaced filter all okay		961130
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	AIR FILTER MERC 0500LE E491L			959818
216	04/06/2016	584905	OIL FILTER 1725+0500LE E161H01D28			959818
216	04/06/2016	584905		CARRY OUT B SERVICE AS PER CHECK LIST		959818
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	Consumables			959910
216	04/06/2016	584905	Gasket Rocker Cover Mercedes 0500			959910
216	04/06/2016	584905		CARRY OUT A SERVICE AS PER CHECK LIST		959818
216	04/05/2016	584452	Ops Entered - Fault - Passenger Doors - Route: 832 - Frank-	repeatedly tested passenger doors the opened and closed perfectly couldnt fault.		959818
216	04/01/2016	579193	VOSS ADAPTOR 232 - 230 M22 X 1	Creditor #:-PT-MUL001 MULTISPARES LTD P/O #:-PE163499 Receiving #:171792 Date :2016-04-14		959091
216	04/01/2016	579193	BRAKE PEDAL RUBBER	Creditor #:-PT-MUL001 MULTISPARES LTD P/O #:-PE163499 Receiving #:171790 Date :2016-04-14		961894
216	04/01/2016	579193	VOSS ADAPTOR 232 - 230 M22 X 1	Creditor #:-PT-MUL001 MULTISPARES LTD P/O #:-PE163499 Receiving #:171790 Date :2016-04-14		961894
216	03/31/2016	582046	Direct Purchase - MECHANICAL	Creditor #:-PT-EAG001 EAGLE TOWING AND SALVAGE P/O #:-PE165205 Receiving #:170849 Date :2016-03-31 tow Mornington to Seaford		957860
216	03/29/2016	583381	Consumables			957528
216	03/29/2016	583381	Consumables			957528
216	03/29/2016	583381	Mechanic entered - Body Front_Door Operation Faulty	secure front door ram base plate		957296
216	03/18/2016	582046	Breakdown#:32412 - Ops Entered - Breakdown - Breakdown Road	Fit the half shafttopprd up diffoiland fuelled.replaced the main air line to the air dryer and tested.		954390
216	03/17/2016	581576	RE-ENTER WITHOUT GST	Creditor #:-PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:-PE164940 Receiving #:170587 Date :2016-03-24		955927
216	03/17/2016	581576	ENTERED WITH GST IN ERROR	Creditor #:-PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:-PE164345REV Receiving #:170586 Date :2016-03-24		955927
216	03/17/2016	581576	repair acc damage # 42196	Creditor #:-PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:-PE164345 Receiving #:170071 Date :2016-03-17		954390
216	03/17/2016	581576	Consumables			954390
216	03/17/2016	581576	Consumables			954390
216	03/16/2016	581577	Vandalism interior			954177

216	03/16/2016	581576	Body ACC # 42196 repairs			954177
216	03/10/2016	580655	adjust alt belt...noisy		adjusted both alternator belts tested okay.	952407
216	03/09/2016	580537	Breakdown#:32390 - Ops Entered - Breakdown - Breakdown Road		removed brass fitting on air line from 6 way valve port 22 rerouted air line and secured with cable ties refitted line tested okay.	952407
216	03/09/2016	580537	Breakdown#:32390 - Ops Entered - Breakdown - Breakdown Road		went out to bus found air line coming from port 22 on 6 way valve has air joinwer blown apart replaced with brass air line joiner drove bus back to depot.	952407
216	03/03/2016	579193	springs		Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #::PE163505 Receiving #:169411 Date :2016-03-07 A0029902971	951909
216	03/02/2016	579106			completed re-torque.	950478
216	03/02/2016	579193	Air System leak		REPAIRED	950478
216	02/29/2016	578800			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	950126
216	02/29/2016	578800			VEHICLE SAFETY INSPECTION	950126
216	02/29/2016	578800			Completed inspection.	950126
216	02/29/2016	578806	Consumables			950478
216	02/29/2016	578806	TYRE RECAP 11R22.5R			950126
216	02/29/2016	578806	TYRE NEW 11R22.5N			950126
216	02/29/2016	578806	Mechanic entered - Wheels and Tyres Worn Pos 2 and 5.		Replaced pos 1 5 and 6 tyres and torque wheel nuts to 600 NM.	950126
216	02/29/2016	578806	Mechanic entered - Elec and Light Exterior Lights O/S/F hea			950126
216	02/29/2016	578805	RH headlight n/w			950126
216	02/29/2016	578805	GLOBE H1 24V 70W HLC2470			950126
216	02/29/2016	578683	Consumables			950478
216	02/29/2016	578683	Consumables			950478
216	02/29/2016	578683	The Campaign requires all Bus destinations systems to be in			950126
216	02/29/2016	578780	Ops Entered - Accident - Bus Hit Pedestrian - Route: 779 -		repaired by knox	950126
216	02/29/2016	578786	Accident Damaged # 35039 R/R.front bumper decals. Repair f		repaired by knox	950126
216	02/29/2016	578785	Ops Entered - Accident - Bus Hit Stationary Object - Route		repaired by knox	950126
216	02/29/2016	578784	Ops Entered - Accident - Bus Hit Stationary Object - Route		repaired by knox	950126
216	02/29/2016	578783	Ops Entered - Accident - Bus Hit Stationary Object - Route		repaired by knox	950126
216	02/29/2016	578781	Ops Entered - Accident - Bus Hit Stationary Object - Route		repaired by knox	950126
216	02/29/2016	528958	HALDEX COIL BASE OIL SEPERATOR (49G0031)			950126
216	02/29/2016	528958	HALDEX COIL KIT 0500LE 49G0027HALDEX			950126
216	02/29/2016	528958	DRAIN VALVE KIT BOTTOM			950126
216	02/22/2016	577395	Consumables			950126
216	02/22/2016	577395	Consumables			950126
216	02/22/2016	577395	Camapign 20/15 Audit & Update of Safety Decals.Requires a			950126
216	02/11/2016	575202	GLOBE H1 24V 70W HLC2470			950126
216	02/11/2016	575202	Mechanic entered - Elec and Light Exterior Lights O/S/F head			950126
216	02/10/2016	575202	Ops Entered - Accident - Vehicle ran into Bus - Route: 833			950126
216	02/10/2016	575201	Ops Entered - Accident - Vehicle ran into Bus - Route: 833		job being done at Knox	950126
216	02/09/2016	574501	SPACER IDLER PULLEY MERCEDES		Creditor #:PT-WHIO02 WHITES DIESELS AUSTRALIA P/O #::PE161800 Receiving #:167806 Date :2016-02-12	950126
216	02/08/2016	574501	SPACER IDLER PULLEY MERCEDES		Creditor #:PT-WHIO02 WHITES DIESELS AUSTRALIA P/O #::PE161800 Receiving #:167561 Date :2016-02-10	950126
216	02/06/2016	574501	bottom main belt pulley worn		Removed the broken stud replaced the bottom main belt pulleyand boltadjudted and tested.	949131
216	02/01/2016	558366	Consumables			948473
216	02/01/2016	558366	Consumables			948473
216	02/01/2016	558366	REPAIR DRIVER SEAT BASE CUSTIO		Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #::PE158045 Receiving #:168118 Date :2016-02-18	950126
216	02/01/2016	573336	KIT AIR LINE FITTING VOSS 22MM 50Z0114			948368
216	02/01/2016	573336	Air System LEAK PIPE ON o/s REAR TOP OF AIR TANK		Replaced 5 big air fitting on E-cas valve and susp. air tank.Tested all OK.	948368
216	01/28/2016	572834	Drv entered - Elec and Light Exterior Lights		Checked all lights no fault found	947741
216	01/28/2016	572834	Elec and LightHigh Beam not working		Checked ok	947741
216	01/21/2016	571423	Ops Entered - Fault - Elec and Light Indicators Not Working		Completed.	946353
216	01/21/2016	571402	GLOBE 24V 21W SINGLE CONTACT HLR2421			946353
216	01/21/2016	571402	Elec and Light Exterior Lights - Highbeam not working at a		Both Fr lower indicator globes replaced.	946353
216	01/20/2016	569421	Switch Door Button Normally O		Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE160108 Receiving #:166449 Date :2016-01-20 216	946353
216	01/16/2016	570540	Consumables			945017
216	01/16/2016	570540	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS			944769
216	01/15/2016	570321	Ops Entered - Fault - Elec and Light Electric Mirrors Faulty			944710
216	01/15/2016	570321	Ops Entered - Fault - Elec and Light Exterior Lights - Rout		done by Emre	944710
216	01/15/2016	570321	Consumables			944769
216	01/15/2016	570321	Ops Entered - Fault - Body Front_Handrail. from roof to floo			944710
216	01/14/2016	569802			Retnsion pos 3 & 4 wheel nuts to 600 NM.	944040
216	01/14/2016	569801	Consumables			944710
216	01/14/2016	569801	Wheels and Tyres Worn Position 2 5 and 6 worn		Checked the above tyres pos 2 thread between 3 and 4 mm pos 5 & 6 thread between 7 & 8 mm. Tyres still road worthy.	944040
216	01/12/2016	569421	Ops Entered - Fault - Passenger Doors - Route: 781 - Frank		Diagnose and replace faulty door open / close switch.	943801
216	01/12/2016	569204	VALVE 50G2808WABCO		Creditor #:PT-MUL001 MULTISPARES LTD P/O #::PE160405 Receiving #:167103 Date :2016-02-02	948473
216	01/12/2016	569204	brake booster 50G2546KNORR		Creditor #:PT-MUL001 MULTISPARES LTD P/O #::PE160405 Receiving #:167103 Date :2016-02-02	948473
216	01/11/2016	569204	Brakes/ L/H rear		completed brake job fitted new booster and shuttle valve.	943038
216	01/11/2016	569204	Brakes Foot_Brakes Pulling - Rear N/S Caliper locked on R		completed brake job fitted new booster and shuttle valve.	943038
216	01/04/2016	568119	Air System - air leak when bus is stationary (Seaford ops s		check air system could not fault noise . rang Vern at Seaford . he stated this is normal for this model bus and its ok	941800
216	12/30/2015	567347	Consumables			942391
216	12/30/2015	567347	Front door anti slip missing		Replaced the strip.	941800
216	12/30/2015	567348	Consumables			942391
216	12/30/2015	567348	Consumables			942391
216	12/30/2015	567348	Consumables			942391
216	12/30/2015	567348			CARRY OUT A SERVICE AS PER CHECK LIST Completed.	941800
216	12/29/2015	567146	GLOBE H1 24V 70W HLC2470			941800
216	12/29/2015	567146	Mechanic entered - Elec and Light Exterior Lights N/S Headli			941800
216	12/23/2015	566684	Consumables			940563
216	12/23/2015	566684	Campaign 23_15 A3 Poster Change		fit A3 poster as required	940230
216	12/22/2015	566133			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	939944
216	12/22/2015	566133			VEHICLE SAFETY INSPECTION Completed saftey inspection.	939944
216	12/22/2015	566133	KIT AIR LINE FITTING VOSS 22MM 50Z0114			939944
216	12/17/2015	565462	TYRE NEW 11R22.5N			938602
216	12/17/2015	565462	Drv entered - Steering Shakes Wobbles		Checked wheels and king pins for movment adjust bearing movment on both front wheels. Check and adjust steering drag link Replaced pos 1 tye and adjusted toe in. Roadf test OK.	938602
216	12/17/2015	565462	Drv entered - Steering Shakes Wobbles			938602
216	12/14/2015	564713	Consumables			938175
216	12/14/2015	564713	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i		Campaign completed as required	937733
216	12/10/2015	564282	CYCLONE CONDENSER VALVE KIT			936824
216	12/10/2015	564282	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)			936824
216	12/10/2015	564282			CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Replaced air drier base and air cyclon seperator from shelf. remove and clean ping tank and pipes.	936824
216	12/10/2015	564282	HALDEX CONDENSER KIT TOP(CYCLONE)			936824
216	12/04/2015	559055	TORQUE ROD BUSH		Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE158654 Receiving #:164671 Date :2015-12-04 bus 216 w/o 559055	935760
216	12/04/2015	559055	PULLEY ADJUSTER IDLER PULLEY O		Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE158654 Receiving #:164671 Date :2015-12-04 bus 216 w/o 559055	935760
216	12/04/2015	563200	GLOBE 24V 18W			935545
216	12/04/2015	563200	GLOBE 24V SW BAYONETT 17181			935545
216	12/04/2015	563200	Mechanic entered - Elec and Light Exterior Lights O/S front		Replaced indicator and park light globes in o/s front top corner.	935545
216	12/02/2015	562721	Complete task as instructed in Fleet Campaign 09/15			934906

216	12/01/2015	562534	ARM MIRROR N/S ARTIC			934664
216	12/01/2015	562534	Ops Entered - Fault - Steering Pulling - Route: 833 - Frank	servicable		934664
216	11/26/2015	561226	Consumables			933481
216	11/26/2015	561226	Remove Old Poster and Fit new All Night Public Transport Po			933049
216	11/20/2015	560094	Suspension/ rear torque rod bushes	replaced worn bushes tested okay.		932047
216	11/16/2015	559055	Drv entered - Steering Shakes Wobbles	Test drive found bus pulling left under retarder check over suspension and found rear lower trailing arm bushes worn.		931218
216	11/12/2015	558366	Consumables			930406
216	11/12/2015	558366	Drv entered - Body Drivers Seat Controls	tighten air switch and fit new cushion on drivers seat		930167
216	11/10/2015	557913		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		929626
216	11/10/2015	557913		VEHICLE SAFETY INSPECTION		929626
216	11/10/2015	557913		CLEAN A/C FILTERS		929626
216	11/10/2015	557912	Consumables			929795
216	11/10/2015	557912	Body Front_Door Operation Faulty Plate for door buttons I	re drilled and put in new pot rivits all ok		929626
216	11/02/2015	556589		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST service completed		927506
216	10/30/2015	556423	Consumables			927506
216	10/30/2015	556423	Consumables			927506
216	10/30/2015	556423	Consumables			927506
216	10/30/2015	556423		CARRY OUT A SERVICE AS PER CHECK LIST		927283
216	10/29/2015	556085	Drv entered - Steering Shakes Wobbles	Testdriven and checkedall fr axel components no defects found.Greased the king pins and released		927111
216	10/26/2015	555602	O RING KIT LARGE VOSS A6739970145			926422
216	10/26/2015	555602	Rectify air leaks	Replace o-rings on Voss fittings at air dryer.		926422
216	10/15/2015	553332	Consumables			924159
216	10/15/2015	553332	Mechanic entered - Body Other Drivers door hinge u/s	Replace lower drivers door hinge.		923616
216	10/13/2015	552865		Tension wheels position 3 & 4 to 600NM		922802
216	10/12/2015	552630	Consumables			923181
216	10/12/2015	552630	TYRE RECAP 11R22.5R			922802
216	10/12/2015	552630	Mechanic entered - Wheels and Tyres Damaged Position 3 tyre	Remove position 3 & 4 tyres replace both and keep inner tyre for run-out later on.		922802
216	10/09/2015	542621	PARKBRAKE VALVE 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE156469 Receiving #:162072 Date :2015-10-09		922122
216	10/03/2015	550807		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY		919853
216	10/03/2015	550807		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY		919853
216	10/03/2015	550807		CLEAN A/C FILTERS		919853
216	10/03/2015	550807		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		919853
216	10/03/2015	550807		VEHICLE SAFETY INSPECTION completed.		919853
216	10/01/2015	548768	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE156194 Receiving #:162135 Date :2015-10-12		922802
216	10/01/2015	547488	Direct Purchase - BODYWORK	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE155926 Receiving #:162136 Date :2015-10-12		922802
216	09/30/2015	550293	Consumables			919481
216	09/30/2015	550237	Consumables			919481
216	09/30/2015	550293	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fit decals as required		919107
216	09/30/2015	550237	Replace A3 poster with Victorian Seniors Festival Poster	Replaced A3 Poster as required		919107
216	09/29/2015	549504	Mechanic entered - Fluid Leaks Rear of bus Possible fuel lea	Steam clean engine Road test and trace to fuel leak on pipe to engine block. Repair steam again and road test ok. Found and repair intercooler hose clamp broken		918695
216	09/25/2015	549074	Consumables			918288
216	09/25/2015	549074	Ops Entered - Fault - Body Passenger Seat Torn - Route: 833	replace pass seat		918096
216	09/24/2015	548768		ANNUAL SAFETY INSPECTION (RWC #)		917946
216	09/22/2015	547962	GLOBE 24V SW BAYONETT			917946
216	09/22/2015	547962	GLOBE 24V 18W			917946
216	09/22/2015	547962	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			917946
216	09/22/2015	547962	finalize for RSI	Completed last day checks.		917946
216	09/21/2015	547962	finalize for RSI			917946
216	09/21/2015	548058	steam clean for RSI	Completed. and checked		917946
216	09/18/2015	547488	Driver seat repairs	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE155923 Receiving #:161561 Date :2015-09-24		917946
216	09/18/2015	547488	repair seats	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE155923 Receiving #:161561 Date :2015-09-24		917946
216	09/17/2015	547488	Vandalism seats	replace 10 vandalised seats		917767
216	09/17/2015	547265	Ops Entered - Fault - Passenger Doors - Route: 773a - Frank	secure rear bumper secure body panels replace n/s front m/flap secure windscreen rubber replace step edging glue floor down in side paint wheels and tyres		917767
216	09/16/2015	547265	Ops Entered - Fault - Passenger Doors - Route: 773a - Frank			917767
216	09/16/2015	547265	Consumables			917767
216	09/16/2015	547265	carry out RSI repairs	rsi repairs new hinges on drivers door repair drivers blinds secure plastic cover on steering column secure rear modesty panel secure grab rails in bus		917767
216	09/16/2015	547330	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01			917767
216	09/16/2015	547330		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST		917767
216	09/14/2015	546426	Consumables			917767
216	09/14/2015	546426	RSI Body Repairs	repair front modesty panel		916507
216	09/11/2015	546426	Body RSI Body Repairs	PRE ANNUAL SAFETY INSPECTION CHECK		916507
216	08/28/2015	543996		PRE ANN SAFETY CHECK AND SECURE BOOT LID FIT GAS STRUTS TO BOOT LID		913806
216	08/28/2015	543996				913806
216	08/28/2015	543976	Mechanic entered - Elec and Light Reverse Buzzer			913806
216	08/28/2015	544080	NARVA 24V REVERSING BUZZER			913806
216	08/28/2015	544080	Elec and Light Reverse Buzzer	Fit new buzzer		913806
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	AIR FILTER MERC 0500LE E491L			913806
216	08/28/2015	543976	GLOBE 24V SW BAYONETT			913806
216	08/28/2015	543976	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468			913806
216	08/28/2015	543976	OIL FILTER 1725+0500LE			913806
216	08/28/2015	543976	FUEL FILTER 0500LE			913806
216	08/28/2015	543976	FUEL FILTER MERC 0500LE			913806
216	08/28/2015	543976		CARRY OUT C SERVICE AS PER CHECK LIST		913806
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976		CARRY OUT B SERVICE AS PER CHECK LIST		913806
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976	Consumables			913894
216	08/28/2015	543976		CARRY OUT A SERVICE AS PER CHECK LIST		913806
216	08/21/2015	542621	Drv entered - Steering Pulling			911705
216	08/21/2015	541292	BOSCH REGULATOR 0500LE ALT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE154773 Receiving #:160297 Date :2015-08-21 94V0003		912040
216	08/21/2015	542621	Drv entered - Brakes Park_Brake Not Holding			911705
216	08/21/2015	542621	Drv entered - Brakes Park_Brake Leaking Air	replaced the park brakevalve.		911705
216	08/20/2015	542621	Drv entered - Steering Pulling			911380
216	08/20/2015	542621	Drv entered - Brakes Park_Brake Not Holding			911380
216	08/20/2015	542621	Drv entered - Brakes Park_Brake Leaking Air			911380
216	08/18/2015	540474	M/B AIR CHARGE VALVE 16mm			910608
216	08/17/2015	541292	Ops Entered - Fault - Elec and Light Warning Light On Dash -	Trace to and replace lower alternator brush reg pack		909969

216	08/17/2015	540854	carry out fire safety inspecti	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE154735 Receiving #:160568 Date :2015-08-28	913806
216	08/14/2015	539812	STARTER M/BENZ 0500RF A4571510	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE154551 Receiving #:159992 Date :2015-08-14	909287
216	08/13/2015	540823		CLEAN A/C FILTERS	909060
216	08/13/2015	540823		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	909060
216	08/13/2015	540823		VEHICLE SAFETY INSPECTION safety completed	909060
216	08/13/2015	540854		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	909060
216	08/11/2015	540474	Ops Entered - Fault - Air System Air Not Building_Up - Rou	Repair air fitting to n/s/r air tank and return to depot	908486
216	08/07/2015	539812	Elec and Light (None) Not Starting		907672
216	08/01/2015	538755	Drv entered - Steering Shakes Wobbles	checked by Dan on friday no fault found	906120
216	07/31/2015	533926	PULLEY ADJUSTER IDLER PULLEY 0	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE153275 Receiving #:159373 Date :2015-07-31	906330
216	07/31/2015	533926	SPACER IDLER PULLEY MERCEDES	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE153275 Receiving #:159373 Date :2015-07-31	906330
216	07/31/2015	533926	IDLE PULLEY BOLT 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE153275 Receiving #:159373 Date :2015-07-31	906330
216	07/31/2015	534104	BUTTON CLIPPARD DOOR VALVE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE153275 Receiving #:159373 Date :2015-07-31	906330
216	07/31/2015	534104	VALVE CLIPPARD DOOR OPEN/CLOSE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE153275 Receiving #:159373 Date :2015-07-31	906330
216	07/29/2015	538184	Complete Campaign 6/15 A3 Marketing Poster Change	Completed campaign as required	905597
216	07/23/2015	537158	Consumables		904631
216	07/23/2015	537158	Mechanic entered - Wheels and Tyres Worn pos 5	Replaced pos 5 tyre with run out and torque wheel nuts to 600NM	904478
216	07/23/2015	537172	clean Engine breather	cleaned engine breather and steam cleaned engine	904478
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST Completed service	904478
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables		904631
216	07/23/2015	537097	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	904478
216	07/22/2015	536985	Ops Entered - Fault - Body Windows Side - Route: 776r - Fr	no fault found	904478
216	07/21/2015	536711	Mechanic entered - Body Other	secure all mirrors inside and out	904224
216	07/15/2015	535630	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route:	tested and no fault found	901812
216	07/09/2015	535014		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	900412
216	07/09/2015	535014		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	900412
216	07/09/2015	535014		CLEAN A/C FILTERS	900412
216	07/09/2015	535014		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	900412
216	07/09/2015	535014		VEHICLE SAFETY INSPECTION	900734
216	07/09/2015	535025	Consumables		900412
216	07/09/2015	535025	TYRE RECAP 11R22.5R		900412
216	07/09/2015	535025	Mechanic entered - Wheels and Tyres Flat or Leaking		900412
216	07/03/2015	533926	tension idler bolt broken	replaced with the one out of 234 and tested.	898802
216	07/03/2015	534036	Ops Entered - Fault - Eng Cool - Route: 785 - Nepean Hwy/C	repaired by Andrew	898802
216	07/03/2015	534108	Ops Entered - Fault - Air System Air Not Building_Up - Rou	fitted door valve.	898802
216	07/03/2015	534104	Ops Entered - Fault - Air System Air_Leak Front - Route: 7	fitted door valve.	898802
216	07/02/2015	533926	A/C BELT 0500 BENZ		898649
216	07/02/2015	533926	tension idler bolt broken		898649
216	06/26/2015	532915	Consumables		897339
216	06/26/2015	532915	Audit Route buses for correct Decals and positions. Replace		896859
216	06/16/2015	526882	Consumables		894467
216	06/16/2015	526882	INDICATOR LAMP L.E.D.	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE151995 Receiving #:157121 Date :2015-06-16	894467
216	06/15/2015	531060	KIT AIR LINE FITTING VOSS 22MM 5020114		894025
216	06/15/2015	531060	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115		894025
216	06/15/2015	531060	Drv entered - Air System Air_Leak Rear	Checked and fixed air leak at two air fittings behind drier area	894025
216	06/15/2015	531081	Consumables		894025
216	06/15/2015	531081	Consumables		894025
216	06/15/2015	531081	Consumables		894025
216	06/15/2015	531081		Grease AC Compressor Clutch Bearing	894025
216	06/15/2015	531081		Tension Wheel Nuts To OEM Specification	894025
216	06/15/2015	531081		A Service Completed service	894025
216	06/15/2015	531081		Clean A/C filter	894025
216	06/03/2015	498309	Consumables		891118
216	06/03/2015	498309	replace windscreen	Creditor #:PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:PE145866 Receiving #:156640 Date :2015-06-03	890781
216	06/01/2015	528959		VEHICLE SAFETY INSPECTION saftey completed	890366
216	06/01/2015	528959		CLEAN A/C FILTERS	890366
216	06/01/2015	528959		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	890366
216	06/01/2015	528959		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	890366
216	06/01/2015	528959		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	890366
216	06/01/2015	528795	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		890366
216	06/01/2015	528795	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		890366
216	06/01/2015	528795	Ops Entered - Fault - Brakes Warning Light On - Route: 784	Air drier was leaking.replaced with a rekittd unit and a new filter and tested.	890366
216	06/01/2015	528958	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	890366
216	06/01/2015	528958		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	890366
216	06/01/2015	528958	HALDEX COIL KIT 0500LE 49G0027HALDEX	Coil Kit	890366
216	06/01/2015	528958	DRAIN VALVE KIT BOTTOM	Valve Kit	890366
216	06/01/2015	528958	HALDEX COIL BASE OIL SEPERATOR (49G0031)	Base	890366
216	06/01/2015	528958		Re-kit Air Cyclone Separator	890366
216	05/29/2015	528198	carry out annaul service	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE151880 Receiving #:156466 Date :2015-06-01	890366
216	05/27/2015	528198		C Service	889020
216	05/27/2015	528198		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	889020
216	05/27/2015	528198		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	889020
216	05/27/2015	528198		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	889020
216	05/27/2015	528198		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	889020
216	05/27/2015	528198		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	889020
216	05/27/2015	528198		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	889020
216	05/27/2015	528198		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	889020
216	05/27/2015	528198		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	889020
216	05/27/2015	528198		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensorpressure switches; check evaporator auto fan speed; check de-ice cut out/in;check operation of fresh air ram; check electrical centre connections lightsand operation -----annaul carried out by coachair	889020
216	05/27/2015	528198		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	889020
216	05/27/2015	528198		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	889020
216	05/20/2015	527058	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	replace n/s rear indicator led check opertion ok	887137
216	05/19/2015	526882	Elec and Light INDICATOR N/W	swapped indicators top to bottom.	886934
216	05/15/2015	526418	GLOBE H1 24V 70W		885771
216	05/15/2015	526418	Mechanic entered - Elec and Light Exterior Lights	replaced o/s headlight globe.	885771
216	05/05/2015	524587	GLOBE 24V 18W		882378
216	05/05/2015	524587	GLOBE WEDGE INSTRUMENT 24V 5W		882378
216	05/05/2015	524587	Mechanic entered - Elec and Light Exterior Lights n/s side i	Replace globes and repair holders	882378

216	05/05/2015	524587	EMERGENCY EXIT (HAMMER)			882378
216	05/04/2015	521717	ACCIDENT DAMAGE #41000	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE151031 Receiving #:155288 Date :2015-05-13		885104
216	05/04/2015	521717	DIRECT PURCHASE - IMAGE REPAIR	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE150450 Receiving #:155282 Date :2015-05-13 accident # 41000 - APN panel damage due to removal of decals.		885104
216	04/17/2015	521717	Accident damage # 41000 for decal removal by APN.	CARRIED OUT BY ECTB		882378
216	04/16/2015	521423	reverse Beeper mounts broken	Secure beeper mounts		882378
216	04/11/2015	520742	air slow to build up	no fault found		881218
216	04/09/2015	520446	Update destination Files and Check display	Campaign completed.		880602
216	04/07/2015	519957		Clean A/C filter.		880183
216	04/07/2015	519957		Tension Wheel Nuts		880183
216	04/07/2015	519957		Perform & Complete TSV Bus Safety Inspection		880183
216	04/07/2015	519957		Rotate Rear Axle Tyres Left to Right - MT & IBS only		880183
216	04/07/2015	519957		Rotate Front Axle Tyres Left to Right - MT & IBS only		880183
216	03/30/2015	518755	Replace See Something Say Something Poster	Campaign completed.		877855
216	03/26/2015	518090	heater pipes leaking	Remove heater pipes over radiator and replace with hoses and secure. Repair and secure heater pipes above engine bay cross member		876956
216	03/25/2015	517981	GLOBE WEDGE 24V/5W			876956
216	03/25/2015	517981	CLEAR FRONT INDICATOR WRAP-AROUND			876956
216	03/25/2015	517981	O/F park/Indicator lens has a hole	Replaced lamp and park globe		876956
216	03/25/2015	517969	Consumables			876956
216	03/25/2015	517969	Consumables			876956
216	03/25/2015	517969	Consumables			876956
216	03/25/2015	517969		A Service		876956
216	03/25/2015	517969		Clean A/C filter		876956
216	03/25/2015	517969		Grease AC Compressor Clutch Bearing		876956
216	03/25/2015	517969		Tension Wheel Nuts To OEM Specification		876956
216	03/23/2015	517512	Ops Entered - Fault - Passenger Doors Not Operating - Rout	Adjust rear door speed		876087
216	03/19/2015	517009	Drv entered - Trntable Other	No Fault as No turntable		875010
216	03/19/2015	517001	Drv entered - Passenger Doors Faulty Controls	Check doors and road tested Ok		875010
216	03/19/2015	517009	Drv entered - Engine Other	No fault found		875010
216	03/12/2015	515863	TYRE RECAP 11R22.5R			872859
216	03/12/2015	515863	position 6 side wall worn	replaced position 6 tyre and torqued		872859
216	03/06/2015	514871	Complete AM/FM radio saloon speaker modification	Campaign completed.		871169
216	03/01/2015	505235	THERMOSTAT 83 DEGREE	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE147239 Receiving #:150060 Date :2015-01-30		860735
216	03/01/2015	505235	RADIATOR 0500LE	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE147239 Receiving #:150060 Date :2015-01-30		860735
216	02/26/2015	513569		Tension Wheel Nuts		868892
216	02/26/2015	513569		Perform & Complete TSV Bus Safety Inspection		868892
216	02/26/2015	513569		Clean A/C filter.		868892
216	02/26/2015	513577	Consumables			868979
216	02/26/2015	513577	Drv entered - Body & Acc Other	Driver entered by mistake		868690
216	02/26/2015	513576	Drv entered - Brakes Other	Fit spring washers to handbrake valve screws and tightened. Air coming from exhaust OK. Road tested and could not fault handbrake		868892
216	02/23/2015	512844	MINATURE GLOBE 24V - 4 W			867701
216	02/23/2015	512844	RHF parker out	Replaced globe		867701
216	02/17/2015	512045	GLOBE WEDGE 24V/5W			866151
216	02/17/2015	512045	LH parker out			866151
216	02/11/2015	510807	Ops Entered - Accident - To Be Advised - Route: 773 - Kars	repair b/bar		863825
216	02/10/2015	510807	Ops Entered - Accident - To Be Advised - Route: 773 - Kars	repir o/s front pillar repair o/s front b/bar		863825
216	02/09/2015	510706	GLOBE WEDGE 24V/5W			863488
216	02/09/2015	510706	LH parker globe out			863488
216	02/06/2015	510337	Service			862609
216	02/04/2015	509875	GLOBE H1 24V 70W			861935
216	02/04/2015	509875	Ops Entered - Fault - Elec & Light Headlights - Route: 785	Replaced N/S headlight globe		861935
216	01/30/2015	509029	Consumables			860735
216	01/30/2015	509029	TYRE RECAP 11R22.5R			860657
216	01/30/2015	509029	LH rear outer tyre 3mm	Replaced both N/S drives with 2 retreads And tortqed to 600NM.		860657
216	01/30/2015	509032	SYNTHETIC GEAR LUBRICANT FM 75W-140 (LU27)			860657
216	01/30/2015	509032	Service	Replace Differential oil Completed		860657
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031		Grease AC Compressor Clutch Bearing		860657
216	01/30/2015	509031	AIR FILTER MERC 0500LE E491L			860657
216	01/30/2015	509031	OIL FILTER 1725+0500LE			860657
216	01/30/2015	509031	OIL ENGINE DELO 400LE 15W40 (LU18)			860657
216	01/30/2015	509031		A Service & Bus Safety Inspection		860657
216	01/30/2015	509031		D-Service & Bus Safety Inspection Completed		860657
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031	Consumables			860735
216	01/30/2015	509031		A Service		860657
216	01/30/2015	509031		Clean A/C filter		860657
216	01/30/2015	509031		Tension Wheel Nuts To OEM Specification		860657
216	01/22/2015	507975		Rotate Front Axle Tyres Left to Right - MT & IBS only		858467
216	01/22/2015	507975		Tension Wheel Nuts		858467
216	01/22/2015	507975		Perform & Complete TSV Bus Safety Inspection		858467
216	01/22/2015	507975		Clean A/C filter.		858467
216	01/22/2015	507975		Rotate Rear Axle Tyres Left to Right - MT & IBS only		858467
216	01/22/2015	507977	Consumables			858654
216	01/22/2015	507977	Consumables			858654
216	01/22/2015	507977	Consumables			858654
216	01/22/2015	507977		A Service		858467
216	01/22/2015	507977		Clean A/C filter		858467
216	01/22/2015	507977		Grease AC Compressor Clutch Bearing		858467
216	01/22/2015	507977		Tension Wheel Nuts To OEM Specification		858467
216	01/09/2015	505177	FILTER REGULATOR DOOR RAM (AW2	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE146977 Receiving #:149643 Date :2015-01-20		858217
216	01/09/2015	505981	Consumables			855362
216	01/09/2015	505981	Mechanic entered - Body & Acc Exterior	adjust and lubricate doors		855110
216	01/07/2015	505235	Complete rad change and replace thermostats	Completed and road tested and fuelled		854835
216	01/07/2015	505235	MOUNT RUBBER EXHAUST VOLVO (6850149)(30T0001)			854835
216	01/07/2015	505235	engine coolant leaks	Remove radiator and install new radiator and install intercooler after washing		854835
216	01/06/2015	505177	Drv entered - Passenger Doors Require Adjusted	Replaced door regulator valve and adjust pressure		854835
216	01/06/2015	505235	engine coolant leaks	Check for coolant leaks radiator and thermostat housing leaking drain coolant and start dismanteling radiator		854835
216	01/06/2015	505180	Consumables			854835
216	01/06/2015	505180	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	Carried out aduit report		854835
216	01/02/2015	504548	Consumables			854096

216	01/02/2015	504548	Drv entered - Body & Acc Passenger Seat Back [See printed de	Repair n/s seat mounts	853622
216	12/16/2014	502505		Clean A/C filter.	849431
216	12/16/2014	502505		Tension Wheel Nuts	849431
216	12/16/2014	502505		Perform & Complete TSV Bus Safety Inspection	849431
216	12/16/2014	502441	A3 Poster Change	Campaign completed.	849431
216	12/05/2014	500392	Consumables		0
216	12/05/2014	500392	RH parker in header out	completed	846917
216	12/05/2014	500421		Re-kit Air Cyclone Separator completed service	846917
216	12/05/2014	500421	GLOBE S/CONTACT 24V-10W		846917
216	12/05/2014	500421		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	846917
216	12/05/2014	500421	DRAIN VALVE KIT BOTTOM	Valve Kit	846917
216	12/05/2014	500421	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	846917
216	12/01/2014	492357	HEADER TANK 0405NH+0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE144712 Receiving #:147041 Date :2014-10-31	837727
216	12/01/2014	483620	PARKBRAKE VALVE 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE144712 Receiving #:147041 Date :2014-10-31	837727
216	11/28/2014	499242	Drv entered - Other		844716
216	11/28/2014	499242	Drv entered - Other		844716
216	11/28/2014	499242	Drv entered - Other		844716
216	11/27/2014	499027	Consumables	no fault found	0
216	11/27/2014	499027	Consumables		0
216	11/27/2014	499027	Consumables		0
216	11/27/2014	499027	Consumables		0
216	11/27/2014	499027	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)		844510
216	11/27/2014	499027		A Service	844510
216	11/27/2014	499027		Clean A/C filter	844510
216	11/27/2014	499027		Grease AC Compressor Clutch Bearing	844510
216	11/27/2014	499027		Tension Wheel Nuts To OEM Specification	844510
216	11/25/2014	498491	Consumables		0
216	11/25/2014	498491	Mechanic entered - Body & Acc Passenger Seat Cushion vandali	repaired pasenger seat cushion	843846
216	11/24/2014	498382	Wiper arm loose and sits off screen	Tightened both arms	843703
216	11/24/2014	498309	Consumables		0
216	11/24/2014	498309	windscreen cracked		843703
216	11/19/2014	497588	Drv entered - Passenger Doors Not Operating	Removed switches cleaned micro switches secured and tested.	842310
216	11/19/2014	497585	GLOBE 24V 5W BAYONETT		842310
216	11/19/2014	497585	RH clearance light in header out	Replaced.	842310
216	11/14/2014	496759		re-tensioned o/s/f nuts	841092
216	11/13/2014	496515	TYRE NEW 11R22.5N		840812
216	11/13/2014	496515	RH front tyre under 3mm	Replaced tyre and tension to 600 Nm	840812
216	11/12/2014	496015	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Ref managers meeting 05/11/14	840473
216	11/12/2014	496433	RH front tyre under 3mm	rebooked	840812
216	11/12/2014	496432	GLOBE WEDGE 24V/5W		840812
216	11/12/2014	496432	LH parker out		840812
216	11/12/2014	496096	Consumables		0
216	11/12/2014	496096	Remove Legacy Poster and replace with See Something Say So	Campaign done.	840473
216	11/11/2014	495843		safety ins completed	840341
216	11/11/2014	495843		Tension Wheel Nuts	840341
216	11/11/2014	495843		Perform & Complete TSV Bus Safety Inspection	840341
216	11/11/2014	495843		Clean A/C filter.	840341
216	11/11/2014	495843		Rotate Rear Axle Tyres Left to Right - MT & IBS only	840341
216	11/11/2014	495843		Rotate Front Axle Tyres Left to Right - MT & IBS only	840341
216	10/22/2014	492357	Header tank to replace	Replaced header tank and road tested	834721
216	10/22/2014	492356	Ops Entered - Fault - Eng Cool Leaking - Route: - Off ser	Travel to Mt Eliza and found header tank lower pipe broken. Temp repair and top up coolant and return to depot	834721
216	10/17/2014	487913	BATTERY12V190 AMP1000CCA E	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE144080 Receiving #:146491 Date :2014-10-17	833415
216	10/16/2014	487712	BUS INSPECTION LARGE >25 SEATS	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE143927 Receiving #:146458 Date :2014-10-16	832750
216	10/10/2014	490510	seal side window	Reseal 2nd o/s window	830841
216	10/08/2014	490068		Perform & Complete TSV Bus Safety Inspection	830301
216	10/08/2014	490068		Tension Wheel Nuts	830301
216	10/08/2014	490068		Clean A/C filter.	830301
216	10/08/2014	490067	Consumables		0
216	10/08/2014	490067		Tension Wheel Nuts To OEM Specification	830301
216	10/08/2014	490067		Grease AC Compressor Clutch Bearing	830301
216	10/08/2014	490067		Clean A/C filter	830301
216	10/08/2014	490067		A Service	830301
216	10/02/2014	488774	Mechanic entered - Eng Cool Leaking	Header tank cap leakingReplaced.	828397
216	10/02/2014	488774	RAD CAP MERC BENZ. SIGHT GLASS SIDE		828397
216	10/01/2014	493332	GLOBE WEDGE 24V/5W		825428
216	10/01/2014	493332	LH parker out		825428
216	09/30/2014	486022	MIRROR GLASS (330111LH/RH)	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE143468 Receiving #:145881 Date :2014-09-30 MM units - 20-A06-03	828397
216	09/28/2014	487913	NUT BATTERY TERMINAL NEG (BRASS)		827896
216	09/28/2014	487913	Replace batteries	Replace 2x N200 batteries and 1x neg terminal	827379
216	09/25/2014	487712	Annaul inspection		827379
216	09/25/2014	487853	Bus has to be jump started every day. Batteries to replace		827379
216	09/25/2014	487853	NUT BATTERY TERMINAL NEG (BRASS)		827379
216	09/25/2014	487853	NUT BRASS BATTERY TERMINAL POSITIVE		827379
216	09/25/2014	487853	BATTERY CABLE LUG		827379
216	09/24/2014	487636	steam clean for RSI	steam cleaned for rsi	827379
216	09/18/2014	486367	EMERGENCY EXIT (HAMMER)		826312
216	09/18/2014	486367	FAN DRIVE OIL 0500LE		826312
216	09/18/2014	486367		Carried out R.S.I service	826312
216	09/18/2014	486367		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	826312
216	09/18/2014	486367		Inspect radiator and charge air cooler for dirt - clean	826312
216	09/18/2014	486367		Check oil level in transmission - top up if required	826312
216	09/18/2014	486367		Check and clean cartridge in dry type air cleaner	826312
216	09/18/2014	486367		Replace pre and main fuel filters	826312
216	09/18/2014	486367		Replace air dryer cansiter clean silence and drain reservoir	826312
216	09/18/2014	486367		Replace angle drive oil	826312
216	09/18/2014	486367		Test coolant level - top up if required to equate to 37C frost protection	826312
216	09/18/2014	486367		Replace power steering filter and check level (Replace oil if required)	826312
216	09/18/2014	486367	FUEL FILTER MERC 0500LE		826312
216	09/18/2014	486367	FUEL FILTER 0500LE		826312
216	09/18/2014	486367	AIR DRYER CANISTER VOLVO+ NL202		826312
216	09/18/2014	486367	POWER STEERING FILTER VOLVO		826312
216	09/18/2014	486426	rotate positions 3 and 6	Rotated rear outer tyres	826312
216	09/18/2014	486022	Mechanic entered - Body & Acc Interior		826312

216	09/18/2014	486405	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		826312
216	09/18/2014	486405	CIRCUIT PROTECTION VALVE		826312
216	09/18/2014	486405	repair air leaks	replaced 16 air line kits on 6 way vale and ecas valve replaced 6 way valve and 1X 16mm airline joiner	826312
216	09/17/2014	486022	Mechanic entered - Body & Acc Interior	rsi work	826312
216	09/16/2014	486022	Mechanic entered - Body & Acc Interior	repair drivers blinds fit emergency sticker fix front door rubber adjust front doors secure modesty panel fix front door step	826312
216	09/12/2014	485605		Adjust Tappets	825226
216	09/12/2014	484289	MIRROR HEAD	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE142968 Receiving #:145291 Date :2014-09-12	825428
216	09/11/2014	485229	steam clean chassis for RSI	completed	824909
216	09/05/2014	484289	Check over for RSI	completed	823274
216	09/05/2014	484297	Remove old decal and fit new Authorised Officers Decal DO N	Decal fitted.	823274
216	09/04/2014	484032	Drv entered - Passenger Doors Require Adjusted	adjusted doors	823274
216	09/04/2014	484032	Drv entered - Other		823274
216	09/03/2014	483620	Ops Entered - Fault - Brakes Hand Brake - Route: 785 - Fra	Replaced hand brake valve	823003
216	09/01/2014	483136	Drv entered - Body & Acc Passenger Seat Cushion [See printed	secure back seat secure back seat	822728
216	08/29/2014	480135	LEVELLING VALVE SENSOR	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE142453 Receiving #:144786 Date :2014-08-29	822182
216	08/29/2014	482745	Drv entered - Elec & Light Park Lights	Replaced	821526
216	08/29/2014	482745	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		821526
216	08/29/2014	482745	Drv entered - Elec & Light Park Lights	Replaced	821526
216	08/29/2014	476873	FOOT BRAKE VALVE	Creditor #::PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #::PE142453 Receiving #:144786 Date :2014-08-29	822182
216	08/28/2014	481890	DISPOSAL CHARGE	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE142752 Receiving #:144816 Date :2014-09-01	822728
216	08/28/2014	481890	FITTING	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE142752 Receiving #:144816 Date :2014-09-01	822728
216	08/28/2014	481890	11R22.5 DRIVE MICHELIN RETREAD	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE142752 Receiving #:144816 Date :2014-09-01	822728
216	08/26/2014	482205		Retension to 600 Nm	820836
216	08/26/2014	482191		Rotate Rear Axle Tyres Left to Right - MT & IBS only	820836
216	08/26/2014	482191		Rotate Front Axle Tyres Left to Right - MT & IBS only	820836
216	08/26/2014	482191		Tension Wheel Nuts	820836
216	08/26/2014	482191		Perform & Complete TSV Bus Safety Inspection	820836
216	08/26/2014	482191	GLOBE WEDGE 24V 1.2W (47706 SWFLED E-596WLED)		820836
216	08/26/2014	482191		Clean A/C filter.	820836
216	08/26/2014	482191	AMBER REFLECTOR		820836
216	08/25/2014	481890	repalce pos 5	Replaced O/S rear inner tyre and torque wheel nuts	820716
216	08/25/2014	481918	Drv entered - Suspension Noisy	done by anthony	820716
216	08/25/2014	481918	Drv entered - Other	done by anthony	820716
216	08/22/2014	481545	suspension / wheel bumping	Checked tyres suspension components road tested could not fault it.	820337
216	08/22/2014	481383	Remove old A3 poster & replace with Legacy or Penalty Fares	Campaign done.	819987
216	08/19/2014	480653	Drv entered - Other	no fault found	819073
216	08/19/2014	480653	Drv entered - Body & Acc Drivers Seat Controls	drivers seat needs replacing	819073
216	08/15/2014	480245	check O/S rear tyre pressures	pumped up o/s/r tyres	818167
216	08/15/2014	480135	Drv entered - Suspension Leaning	replaced rear level valve sensors	818167
216	08/15/2014	480135	Drv entered - Suspension Soft		818167
216	08/15/2014	480055	TOP ALT BELT 0500LE		818167
216	08/15/2014	480055	Mechanic entered - Elec & Light Altern Light Top belt broke	Replaced top altern belt	818167
216	08/15/2014	480135	Drv entered - Body & Acc Passenger Seat Back		818167
216	08/11/2014	479334	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	817407
216	08/11/2014	479334	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	817407
216	08/11/2014	479334		Service T - Replace Transmission Oil & Filter	817407
216	08/08/2014	478646	L/H rear coner damage	finish paint work reposition exhaust at rear	815996
216	08/07/2014	478646	L/H rear coner damage	repair and paint n/s rear corner cut and polish side	815996
216	08/05/2014	478261		A Service & Bus Safety Inspection	815530
216	08/05/2014	478261		D-Service & Bus Safety Inspection	815530
216	08/05/2014	478261		Grease AC Compressor Clutch Bearing	815530
216	08/05/2014	478261	AIR FILTER MERC 0500LE E491L		815530
216	08/05/2014	478261	OIL FILTER 1725+0500LE		815530
216	08/05/2014	478261	ENGINE OIL DELO 400LE 15W40 (LU18)		815530
216	08/05/2014	478261		Tension Wheel Nuts to Spec	815530
216	08/05/2014	478261		A Service service complete	815530
216	08/05/2014	478261		Clean A/C filter	815530
216	08/01/2014	476873	foot brake valve leaking		813282
216	07/30/2014	477352	Fit Wheel Nut Pointers to all wheel nuts on the front axle	completed	813948
216	07/30/2014	477359	Mechanic entered - Elec & Light Headlights	Replaced O/S headlight globe	813948
216	07/30/2014	477359	GLOBE H1 24V 70W		813948
216	07/30/2014	477351	foot brake valve leaking	Replaced foot valve	813948
216	07/30/2014	477351	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		813948
216	07/24/2014	476334	Drv entered - Body & Acc Drivers Seat Mount	Checked and found slight play in rails	812346
216	07/24/2014	476334	Drv entered - Body & Acc Drivers Seat Cushion	Replaced Cushion	812346
216	07/24/2014	476334	Drv entered - Brakes Hand Brake	Checked and found foot valve leaking	812346
216	07/21/2014	475439		Perform & Complete TSV Bus Safety Inspection Completed Safety inspection as per schedule.	811660
216	07/21/2014	475439		Tension Wheel Nuts Tensioned	811660
216	07/21/2014	475439		Rotate Front Axle Tyres Left to Right - MT & IBS only	811660
216	07/21/2014	475439		Rotate Rear Axle Tyres Left to Right - MT & IBS only	811660
216	07/21/2014	475439		Clean A/C filter.	811660
216	07/21/2014	475700	Mechanic entered - Elec & Light Headlights	Replaced N/R marker lamp	811660
216	07/21/2014	475700	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		811660
216	07/17/2014	473017	DISPOSAL CHARGE	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE141074 Receiving #:143184 Date :2014-07-17	810373
216	07/17/2014	473017	BALANCE	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE141074 Receiving #:143184 Date :2014-07-17	810373
216	07/17/2014	473017	FITTING	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE141074 Receiving #:143184 Date :2014-07-17	810373
216	07/17/2014	473017	11R22.5 XZU3+ TL 148/145J MI	Creditor #::PT-MIC002 MICHELIN AUSTRALIA P/O #::PE141074 Receiving #:143184 Date :2014-07-17	810373
216	07/15/2014	474535	Ops Entered - Fault - Elec & Light Park Lights - Route: oto	Trace fault for no n/s/r parklights. Check and replace n/s/r side marker lamp due to short.	809965
216	07/15/2014	474535		Repair drivers blind	809965
216	07/15/2014	474535	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		809965
216	07/10/2014	473498	Drv entered - Suspension Leaning	all in good working order	808486
216	07/10/2014	473498	Drv entered - Body & Acc Passenger Seat Cushion	checked and fault found	808486
216	07/09/2014	473284	Drv entered - Other	completed	808259
216	07/09/2014	473284	Drv entered - Other		808259
216	07/09/2014	473284	Drv entered - Elec & Light Interior Lights [See printed def	completed	808259
216	07/09/2014	473284	Drv entered - Elec & Light Interior Lights		808259
216	07/08/2014	473016	Rh front tyre under 3mm	Replaced O/S front tyre rotate front tyres and torque wheel nuts	808034
216	07/08/2014	473017	Rh front tyre under 3mm	Refer wo # 473016	808034
216	07/08/2014	473018	front step light out	Front step light working good	808034
216	07/03/2014	472155	Drv entered - Cool & AC Sys Other		806541
216	07/03/2014	472155	Drv entered - Heat & Demist Leaking	install missing driver foot heater vent.	806541
216	06/30/2014	471472	Drv entered - Other	secure back seat secure back seat	806133
216	06/30/2014	471472	Drv entered - Other [See printed defect for more informatio	completed	806133

216	06/30/2014	471564	Drv entered - Comm Equip Not Opertating	no fault found	806133
216	06/30/2014	471472	Ops Entered - Fault - Body & Acc Passenger Seat Back - Rou	secure back seat	806133
216	06/27/2014	470896		remove ping tabk all air lines clean remove carbon blockage re fit and overhaul cyclone seperator	805267
216	06/26/2014	471047	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	DECALS FITTED	805041
216	06/26/2014	470982	Fit Myki decals as requiredFit Recruitment decal as requi	Decal fitted.	805041
216	06/26/2014	470990	Fit New Myki Decal as Per PTV fitting instructions	completed	805041
216	06/26/2014	470895		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	805041
216	06/26/2014	470895	HALDEX COIL KIT 0500LE	Coil Kit	805041
216	06/26/2014	470895	DRAIN VALVE KIT BOTTOM	Valve Kit	805041
216	06/26/2014	470895	HALDEX COIL BASE OIL SEPERATOR	Base	805041
216	06/26/2014	470895	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	805041
216	06/26/2014	470895		Re-kit Air Cyclone Separator	805041
216	06/26/2014	470896		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	805041
216	06/26/2014	470896	HALDEX COIL BASE OIL SEPERATOR	Base	805041
216	06/26/2014	470896		Re-kit Air Cyclone Separator	805041
216	06/25/2014	470516	Ops Entered - Fault - Elec & Light Interior Lights - Route:	completed	804841
216	06/18/2014	468169	RH front clearance light out	completed	800894
216	06/18/2014	468061	RH clearance light in header out	completed	800894
216	06/16/2014	468973	GLOBE WEDGE 24V 1.2W		802022
216	06/16/2014	468973		Rotate Rear Axle Tyres Left to Right - MT & IBS only	802022
216	06/16/2014	468973		Perform & Complete TSV Bus Safety Inspection	802022
216	06/16/2014	468973		Clean A/C filter.	802022
216	06/16/2014	468973		Rotate Front Axle Tyres Left to Right - MT & IBS only	802022
216	06/16/2014	468973		Tension Wheel Nuts	802022
216	06/13/2014	468521		wheels fitted by jesse torqued by andrew.n with jesse	800894
216	06/13/2014	468521	retension n/s rear wheel nuts to 600nm	completed	800894
216	06/13/2014	468302	o/sfront sway bar	replaced os sway bar link ball joints seized oxyed out	800894
216	06/13/2014	468632	Door alarm light flashing		800894
216	06/12/2014	468302	o/sfront sway bar		800894
216	06/11/2014	468111	remove to carry out brake repair		800894
216	06/11/2014	468111	remove to carry out brake repair		800894
216	06/11/2014	468173	Mechanic entered - Vandalism Graffiti		800894
216	06/11/2014	468060	Drv entered - Heat & Demist Demisters Cold		800894
216	06/11/2014	468169	RH front clearance light out		800894
216	06/11/2014	468061	RH clearance light in header out		800894
216	06/11/2014	468107	DIAPHRAGM TYPE 20 D SHAPE		800894
216	06/11/2014	468107	n/s rear brake booster leaking	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE139966 Receiving #:141825 Date :2014-06-12	800894
216	06/11/2014	468055		replaced diapham	800894
216	06/11/2014	468055		Clean A/C filter	800894
216	06/11/2014	468055		Grease AC Compressor Clutch Bearing	800894
216	06/11/2014	468055		Tension Wheel Nuts To OEM Specification	800894
216	06/11/2014	468055		A Service	800894
216	05/31/2014	466290	Drv entered - Suspension Leaning	checked and no fault found	797794
216	05/28/2014	465667	Drv entered - Other	repair drivers seat	796795
216	05/28/2014	465667	Drv entered - Body & Acc Passenger Seat Back	completed by Ross S	796795
216	05/27/2014	465402	Drv entered - Elec & Light Cab Light	checked operation of cab light working ok	796550
216	05/26/2014	464088	FILTER DRIER THERMO KING		796055
216	05/20/2014	464088		INSPECT MOTORS & BRUSHES: Replace 3 evap motors left bank	794653
216	05/20/2014	464088		COMPRESSOR:repair short in unloader	794653
216	05/20/2014	464088		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	794653
216	05/20/2014	464088		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	794653
216	05/20/2014	464088		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	794653
216	05/20/2014	464088		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	794653
216	05/20/2014	464088		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	794653
216	05/20/2014	464088		COMPRESSOR: Carryout efficiency test; check unloader control; checkL/P switch operation;check H/P switchoperation; check suction hose; check dischargehose	794653
216	05/20/2014	464088		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	794653
216	05/20/2014	464088		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	794653
216	05/20/2014	464088		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	794653
216	05/20/2014	464088		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	794653
216	05/20/2014	464088		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	794653
216	05/19/2014	463866	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing		794455
216	05/13/2014	462412		Clean A/C filter.	792661
216	05/13/2014	462412		Tension Wheel Nuts	792661
216	05/13/2014	462412	Drv entered - Elec & Light Cab Light	Perform & Complete TSV Bus Safety Inspection	792661
216	05/13/2014	462412	alt belt worn	Repair globe socket	792661
216	05/13/2014	462412	front door down light n/w	Replace alternator belt	792661
216	05/13/2014	462412	TAPERED ROLLER BEARING	Replace front door emer exit lamp	792661
216	05/13/2014	462412	SEAL TENSIONER HUB		792661
216	05/13/2014	462412	fan drive bearings worn		792661
216	05/13/2014	462412	BELT BOTTOM ALTERNATOR MERC 0500LE		792661
216	05/13/2014	462412	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		792661
216	05/13/2014	462412	LED FRONT POSITION MARKER LIGHT		792661
216	05/13/2014	462412	GLOBE 24V 5W BAYONETT		792661
216	05/13/2014	462412	air leaking o/s/rear	Replace 3x air fitting kits	792661
216	05/06/2014	461271	Drv entered - Body & Acc Drivers Seat Mount	seat needs rebuild	790459
216	04/28/2014	459206	SUPPORT FAN IDLER TENSIONER PU	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P138058 Receiving #:141942 Date :2014-06-16	801760
216	04/23/2014	459206	A/C BELT 0500 BENZ		786553
216	04/23/2014	459206	main pulley worn	Fit pulley from 341 and replaced top alt belt and a/c belt	786553
216	04/23/2014	459206	main pulley worn		786553
216	04/22/2014	458930	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	completed	785998
216	04/20/2014	458744	Engine oil level very high and warning coming on	Drain engine oil to correct level and test	785639
216	04/20/2014	458742	Ops Entered - Fault - Body & Acc Drivers Seat Mount - Rout	Checked operation	785639
216	04/20/2014	458742	Drv entered - Body & Acc Drivers Seat Mount	Checked drivers seat and screw up weight adjuster	785639
216	04/18/2014	458659	O/F sway bar link worn	servicable	785404
216	04/17/2014	458436		A Service Carried out service	785404
216	04/17/2014	458436		Clean A/C filter	785404
216	04/17/2014	458436		Grease AC Compressor Clutch Bearing	785404
216	04/17/2014	458436		Tension Wheel Nuts To OEM Specification	785404
216	04/11/2014	457495	Drv entered - Other	repair back rest fit new seat cushion	783479
216	04/11/2014	457495	Drv entered - Other	completed	783479
216	04/11/2014	457495	Drv entered - Other	completed	783479
216	04/11/2014	457495	Drv entered - Other	completed	783479
216	04/11/2014	457495	Drv entered - Other	completed	783479

216	04/11/2014	457495	Drv entered - Body & Acc Drivers Seat Cushion	completed	783479
216	04/11/2014	457495	Drv entered - Body & Acc Drivers Seat Mount	completed	783479
216	04/11/2014	457495	Ops Entered - Fault - Body & Acc Drivers Seat Controls - R	completed	783479
216	04/11/2014	457495	Ops Entered - Fault - Body & Acc Drivers Seat Cushion - R	completed	783479
216	04/10/2014	457100	OIL PIPE	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:P137610 Receiving #:139401 Date :2014-04-10	782981
216	04/10/2014	457435	replace oil pipe	Replaced pipe	782981
216	04/10/2014	457435	replace oil pipe	Fixed	782981
216	04/10/2014	457100	GLOBE WEDGE 24V/SW		782981
216	04/10/2014	457100	Mechanic entered - Elec & Light Park Lights	Replaced L/H front park globe	782981
216	04/09/2014	457100	oil pipe leaking	completed	782981
216	04/08/2014	456950	GLOBE WEDGE 24V 1.2W		782810
216	04/08/2014	456950			782810
216	04/08/2014	456950	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR	Replaced front of O/R air bag	782810
216	04/08/2014	456950			782810
216	04/08/2014	456950		Clean A/C filter.	782810
216	04/08/2014	456950		Rotate Rear Axle Tyres Left to Right - MT & IBS only	782810
216	04/08/2014	456950		Rotate Front Axle Tyres Left to Right - MT & IBS only	782810
216	04/08/2014	456950		Tension Wheel Nuts	782810
216	04/08/2014	456950		Perform & Complete TSV Bus Safety Inspection Replaced globes as required	782810
216	04/08/2014	456949	Drv entered - Body & Acc Interior	Refit step edges to rear	782810
216	04/01/2014	455186	LH clearance light out. Hit the wall	Replace n/s/r clearance lamp	780805
216	03/23/2014	453640	Drv entered - Heat & Demist Leaking	opened tap no fault found	778100
216	03/20/2014	453165	Perform Campaign 1_14 School Bus Light Globe Check Check	n/a	777531
216	03/18/2014	452837	SELECTOR BUTTON N HORIZONTAL		776876
216	03/18/2014	452837	n button missing	Replaced button	776876
216	03/17/2014	452483	RAD CAP MERC BENZ SIGHT GLASS SIDE		776534
216	03/17/2014	452483	replace radiator cap	replaced	776534
216	03/15/2014	452345	GLOBE WEDGE 24V/SW		775879
216	03/15/2014	452345	Mechanic entered - Elec & Light Park Lights	replaced N/F park light globe	775879
216	03/13/2014	451922	L.E.D SIDE MARKER PEREI RED/AMBER		775543
216	03/13/2014	451922	Mechanic entered - Elec & Light Park Lights N/S Rear corner	Replaced broken N/S reatr clearence light.	775543
216	03/04/2014	450548		Clean A/C filter.	772912
216	03/04/2014	450548		Tension Wheel Nuts	772912
216	03/03/2014	450124	rear seat hinges to repair	Perform & Complete TSV Bus Safety Inspection	772912
216	02/24/2014	448479	FITTING TRUCK	remove and refit rear seat weld up broken hinge	772734
216	02/24/2014	448479	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135511 Receiving #:137538 Date :2014-03-05	773114
216	02/24/2014	449058	Ops Entered - Fault - Body & Acc Interior - Route: 771 - Fr	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135511 Receiving #:137538 Date :2014-03-05	773114
216	02/21/2014	448834	Mechanic entered - Whls & Tyres Other Retorque n/s/r wheels	Repair and refit drivers blind	770808
216	02/20/2014	448479	LH rear tyre 3mm	retensioned n/s/r wheels	769903
216	02/20/2014	448479	GLOBE WEDGE 24V/SW	Replace worn n/s/r tyres. Torque to 600nm. Position 4 back to rack	769784
216	02/20/2014	448479	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)		769784
216	02/20/2014	448479	AIR FILTER MERC 0500LE		769784
216	02/20/2014	448479	OIL FILTER 1725+0500LE		769784
216	02/20/2014	448479	ENGINE OIL DELO 400LE 15W40		769784
216	02/20/2014	448479			769784
216	02/20/2014	448479		Replace Engine Oil Breather Kit	769784
216	02/20/2014	448479		Grease AC Compressor Clutch Bearing	769784
216	02/20/2014	448479		Tension Wheel Nuts to Spec	769784
216	02/20/2014	448479		A Service & Bus Safety Inspection	769784
216	02/20/2014	448479		D-Service & Bus Safety Inspection	769784
216	02/20/2014	448479		A Service	769784
216	02/20/2014	448479		Grease AC Compressor Clutch Bearing	769784
216	02/20/2014	448479		Tension Wheel Nuts To OEM Specification	769784
216	02/20/2014	448479		Clean A/C filter	769784
216	02/17/2014	447763	AIR FILTER MERC 0500LE		768802
216	02/17/2014	447763		Tension Wheel Nuts To OEM Specification	768802
216	02/03/2014	445717	Remove BTS Equipment Fuses	completed	764792
216	02/03/2014	445673	DRAIN VALVE KIT BOTTOM	Valve Kit	764792
216	02/03/2014	445673	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	764792
216	02/03/2014	445673		Re-kit Air Cyclone Separator	764792
216	02/02/2014	445557	retorque wheel pos 1	Retension to spec	763973
216	02/01/2014	444794	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P134480 Receiving #:136378 Date :2014-02-06	765518
216	02/01/2014	444794	DP 11R22.5 148/145L TL SP350A	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P134480 Receiving #:136378 Date :2014-02-06	765518
216	01/31/2014	445516		Rotate Rear Axle Tyres Left to Right - MT & IBS only	763722
216	01/31/2014	445516		Rotate Front Axle Tyres Left to Right - MT & IBS only	763722
216	01/31/2014	445516		Clean A/C filter.	763722
216	01/31/2014	445516		Tension Wheel Nuts	763722
216	01/31/2014	445515	replace cyclone sperator	Perform & Complete TSV Bus Safety Inspection	763722
216	01/28/2014	444885	Drv entered - Suspension Leaning [See printed defect for mo	completed	763722
216	01/28/2014	444838	replace disto glass	checked no fault found	762831
216	01/28/2014	444838	cracked desto glass	Creditor #:PT-GLA001 GLASS ASSIST PTY LTD P/O #:P134419 Receiving #:136014 Date :2014-01-29	763412
216	01/26/2014	444794	Mechanic entered - Whls & Tyres Worn N/S/F tyre low on tread	completed	762831
216	01/26/2014	444790	Mechanic entered - Elec & Light Other	Replaced and torqued.	762108
216	01/23/2014	444505	Mechanic entered - Air Cond Other	Top Alt belt U/S Top Alt belt replaced with a 13x1065.correct belt 13x1040 s NIS.	762108
216	01/17/2014	443655	GLOBE 24V 18W	Check water in bus. Unblock and flush both drain pipes and checked OK	761671
216	01/17/2014	443655	RH sid indicator out		760135
216	01/14/2014	443146	Mechanic entered - Air System Other Leaking from auxiliary ta		760135
216	01/07/2014	442195	L.E.D SIDE MARKER PEREI RED/AMBER	Remove test fitting on air tank and block leak by welding fitting.	759138
216	01/07/2014	442195	LHS clearance light out		758241
216	01/07/2014	442277	Organise Mbenz Recall SM949 to be performed by Whitehorse T		758241
216	01/01/2014	423825	BUMP STOP MERC 0500	completed by white house trucks	758241
216	01/01/2014	423825	ROCKER COVER PLASTIC 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:136021 Date :2014-01-29	763412
216	12/30/2013	441041	FITTING TRUCK	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:136021 Date :2014-01-29	763412
216	12/30/2013	441041	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P133426 Receiving #:135178 Date :2014-01-07	758241
216	12/27/2013	441056	retension position 5 & 6 to 600nm	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P133426 Receiving #:135178 Date :2014-01-07	758241
216	12/26/2013	441041	retension position 5 & 6 to 600nm	retensioned wheeels 5 and 6 to 600nm	755388
216	12/23/2013	440655		completed	755388
216	12/23/2013	440655		Clean A/C filter.	754430
216	12/23/2013	440655		Tension Wheel Nuts	754430
216	12/23/2013	440655		Rotate Rear Axle Tyres Left to Right - MT & IBS only	754430
216	12/23/2013	440655		Rotate Front Axle Tyres Left to Right - MT & IBS only	754430
216	12/23/2013	440655		Perform & Complete TSV Bus Safety Inspection	754430
216	12/23/2013	440758	Mechanic entered - Whls & Tyres Worn	Replaced tyres Pos 5 and 6 and tension to 600 Nm	754430

216	12/23/2013	440757	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		754430
216	12/23/2013	440757	Mechanic entered - Suspension Leaking	Replaced rear of right rear air bag	754430
216	12/23/2013	440559	repair driver screen in 7.33am-9am	secure security screen	754430
216	12/23/2013	440656	GLOBE WEDGE 24V 1.2W		754430
216	12/23/2013	440656	AIR FILTER MERC 0500LE		754430
216	12/23/2013	440656		A Service Replaced dash and switch globes. Replaced pass bell button (Ex 433)	754430
216	12/23/2013	440656		Clean A/C filter	754430
216	12/23/2013	440656		Grease AC Compressor Clutch Bearing	754430
216	12/23/2013	440656		Tension Wheel Nuts To OEM Specification	754430
216	12/13/2013	439159	Drv entered - Other [See printed defect for more informatio	repaired button	751967
216	12/13/2013	439159	Drv entered - Elec & Light Horn	repaired button	751967
216	12/11/2013	438562	Drv entered - Suspension Leaning	completed	751166
216	12/11/2013	438562	Drv entered - Suspension Leaning	completed	751166
216	12/09/2013	438316	both front parkers		750897
216	12/09/2013	438316	GLOBE WEDGE 24V/5W		750897
216	12/06/2013	437535	CONSUMABLE DELIVERY CHARGE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P132681 Receiving #:134324 Date :2013-12-10	751166
216	12/06/2013	437535	HOSE FUEL FILTER TO RAIL	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P132681 Receiving #:134324 Date :2013-12-10	751166
216	12/03/2013	437538	O/S top indicator n/w	completed	749259
216	12/03/2013	437532	LH side indicator n/w	Replaced O/S front top indicator and park light globes.	749259
216	12/03/2013	437532	GLOBE 24V16W		749259
216	12/03/2013	437532	GLOBE 24V 5W BAYONETT		749259
216	12/03/2013	437532	O/S top indicator n/w		749259
216	12/03/2013	437535	Mechanic entered - Fuel Other Attend Break down Mt. Martha.	Attend B/Down replaced fuel line below fuel filter housing.	749259
216	12/01/2013	433673	CONSUMABLE DELIVERY CHARGE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P131582 Receiving #:134249 Date :2013-12-06	750127
216	12/01/2013	433673	NEXT STOP BELL BUTTON	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P131582 Receiving #:134249 Date :2013-12-06	750127
216	12/01/2013	433673	LED DOWNLIGHT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P131582 Receiving #:134249 Date :2013-12-06	750127
216	11/29/2013	436225	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P132365 Receiving #:134008 Date :2013-12-02	748923
216	11/29/2013	436225	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P132365 Receiving #:134008 Date :2013-12-02	748923
216	11/26/2013	436567	NSR retorque wheels	retorqued to 670nm	747048
216	11/24/2013	436225	Mechanic entered - Whls & Tyres Other N/S inner tyre flat.	Replaced N/S rear inner tyre.	746166
216	11/22/2013	436042	GLOBE WEDGE 24V/5W		745830
216	11/22/2013	436042	LH parker out	globe replaced	745830
216	11/19/2013	435619		Clean A/C filter.	744972
216	11/19/2013	435619		Tension Wheel Nuts	744972
216	11/19/2013	435619		Perform & Complete TSV Bus Safety Inspection	744972
216	11/14/2013	434954	GLOBE WEDGE 24V/5W		743410
216	11/14/2013	434954	front parkers out x 2		743410
216	11/06/2013	433673	rear door down light out	completed	740878
216	11/04/2013	433458	SYNTHETIC GEAR LUBRICANT FM 75W-140		740489
216	11/04/2013	433458	Service	Replace Differential oil	740489
216	11/04/2013	433459		A Service	740489
216	11/04/2013	433459		Clean A/C filter	740489
216	11/04/2013	433459		Grease AC Compressor Clutch Bearing	740489
216	11/04/2013	433459		Tension Wheel Nuts To OEM Specification	740489
216	10/30/2013	432876	Check & diagnose red warning bar on dash.	Checked warning and found oil level fault. Checked oil and found overfull. Drained excess oil and roadtested. No faults returned.	739070
216	10/28/2013	432338	GLOBE WEDGE 24V/5W		738407
216	10/28/2013	432338	LH parker out		738407
216	10/25/2013	424805	BRAKE INTERLOCK PROGRAMME INST	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P131161 Receiving #:132927 Date :2013-11-01	739612
216	10/23/2013	431033	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130920 Receiving #:132677 Date :2013-10-28	738407
216	10/23/2013	431033	SP 11R22.5 SP327 CUST/STOR CAS	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130920 Receiving #:132677 Date :2013-10-28	738407
216	10/23/2013	431754	GLOBE WEDGE 24V/5W		736867
216	10/23/2013	431754	RH parker out		736867
216	10/21/2013	431315	LH clearance light out in header	Globe replaced	736204
216	10/18/2013	430993		Clean A/C filter.	735529
216	10/18/2013	430993		Rotate Rear Axle Tyres Left to Right - MT & IBS only	735529
216	10/18/2013	430993		Rotate Front Axle Tyres Left to Right - MT & IBS only	735529
216	10/18/2013	430993		Tension Wheel Nuts	735529
216	10/18/2013	430993		Perform & Complete TSV Bus Safety Inspection	735529
216	10/17/2013	430807	Drv entered - Suspension Leaning	no fault found	735216
216	10/15/2013	430174	BALANCE EQUAL POWDER	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130726 Receiving #:132341 Date :2013-10-21	736204
216	10/15/2013	430174	TYRE RECYCLE/DISP RECOV TRK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130726 Receiving #:132341 Date :2013-10-21	736204
216	10/15/2013	430174	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130726 Receiving #:132341 Date :2013-10-21	736204
216	10/15/2013	430174	DP 11R22.5 148/145L TL SP350A	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130726 Receiving #:132341 Date :2013-10-21	736204
216	10/15/2013	430174	TIME AFTER HOURS(1 HOUR)	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P130726 Receiving #:132341 Date :2013-10-21	736204
216	10/15/2013	430174	replace tyre	replaced by beaurepairs	734531
216	10/15/2013	429036	EVAPORATOR FAN MOTOR		734531
216	10/15/2013	430124	GLOBE WEDGE 24V/5W	Globe replaced	734531
216	10/15/2013	430124	LH parker out	Globe replaced	734531
216	10/14/2013	425146	HEADLIGHT ASSY VOLGREN	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129490 Receiving #:132149 Date :2013-10-16	734862
216	10/08/2013	429036	Drv entered - Air Cond Other [See printed defect for more i	replace all fans right bank evap section. Run new d36 wiring loom	732462
216	10/07/2013	428779	LAMP LOW BEAM H1 VOLGREN	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P130325 Receiving #:132776 Date :2013-10-30	739070
216	10/07/2013	428934	Ops Entered - Fault - Elec & Light Headlights - Route: 771	as w/o 428779	731741
216	10/07/2013	428779	loe beam head lamp dull dusty	replaced lamps and focused	731741
216	10/04/2013	428315	replace windscreen	Creditor #:PT-GLA001 GLASS ASSIST PTY LTD P/O #:P130230 Receiving #:132189 Date :2013-10-17	735216
216	10/03/2013	428244	Drv entered - Elec & Light Headlights [See printed defect f	set head lamp focus by Josh	731594
216	10/03/2013	428315	Drv entered - Body & Acc Windowsreplace cracked windscreen.	completed by glassassist	731594
216	10/02/2013	428177	Drv entered - Body & Acc Drivers Seat Controls [See printed	no fault found	731422
216	09/27/2013	427441	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed.	730213
216	09/24/2013	426909	Drv entered - Vandalism Graffiti	noted	729369
216	09/24/2013	426908	Drv entered - Vandalism Wndow Etch	noted	729369
216	09/24/2013	426911	Drv entered - Other	no fauklt found	729369
216	09/24/2013	426902	BATTERY 12V 190 AMP 1000CCA (+ on right side)	replaced batts	729369
216	09/24/2013	426902	Drv entered - Elec & Light Headlights		729369
216	09/23/2013	425371	ANNUAL INSPECTION	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:P129636 Receiving #:131540 Date :2013-10-01	731172
216	09/17/2013	425817	Drv entered - Elec & Light Headlights [See printed defect fo	adjusted headlights	727239
216	09/17/2013	425705	Drv entered - Body & Acc Water Leak	completed	727239
216	09/16/2013	425629	Drv entered - Wipers & Washers Not Cleaning Screen	REPLACED WIPER BLADES AND CLEANED WINDSCREEN	726898
216	09/16/2013	425630	Drv entered - Wipers & Washers Other	REPLACED WIPER BLADES AND CLEANED WINDSCREEN	726898
216	09/16/2013	425629	1MT MULTI FIT WIPER REFILL		726898
216	09/16/2013	425629	BLADE WIPER 900MM		726898
216	09/14/2013	425371	annaul inspection	Completed F 375839.	726480
216	09/14/2013	425375	clean and park ready for RSI	COMPLETED	726480
216	09/13/2013	425112	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		726480

216	09/13/2013	425112	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)			726480
216	09/13/2013	425112	1MT MULTI FIT WIPER REFILL			726480
216	09/13/2013	425112	carry out last day check for RSI	COMPLETED		726480
216	09/13/2013	425112	carry out last day check for RSI	COMPLETED		726480
216	09/13/2013	425146	high beam lamp faded	Replaced both high beam light assemblies		726480
216	09/13/2013	425146	high beam lamp faded	COMPLETED		726480
216	09/12/2013	425104	Mechanic entered - Investigation/Inspection	steam cleaned for rsi		726282
216	09/12/2013	423825	RELAY VALVE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130810 Date :2013-09-12		726282
216	09/12/2013	423825	FILTER ENGINE BREATHER MB 0500	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130810 Date :2013-09-12		726282
216	09/11/2013	424438	Mechanic entered - Annaul Body Inspection	cut and polish rear of bus paint tyres secure staunchens inside of bus		726065
216	09/11/2013	424805	Brake Interlock Re-install to be performed as per Campaign	completed by EC		726065
216	09/10/2013	424438	Mechanic entered - Annaul Body Inspection	paint wheels CUT AND POLISH NS OF BUS CUT AND POLISH FRONT CUT AND POLISH ROOF FINISH OVERHEAD PANEL REAR DOOR		726065
216	09/10/2013	424439	Complete Campaign 16/12 as required	completed		726065
216	09/10/2013	424440	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	completed		726065
216	09/10/2013	423825	INTERCOOLER 500LE MB	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130753 Date :2013-09-11		726065
216	09/10/2013	423825	ZF SOLENOID VALVE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130753 Date :2013-09-11		726065
216	09/10/2013	423825	CLUTCH PEDAL PAD MERC	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130753 Date :2013-09-11		726065
216	09/10/2013	423825	UPPER RADIATOR MOUNT 500LE MB	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P129149 Receiving #:130753 Date :2013-09-11		726065
216	09/10/2013	424533	Rebrand to VENTURA	Creditor #:PT-TRA009 TRANSICAL P/O #:P128972 Receiving #:131004 Date :2013-09-18		727573
216	09/10/2013	424533	Carry out campaign as per Fleet re-branding Procedure.	completed		726065
216	09/10/2013	424327	panel above rear damaged	completed		726065
216	09/09/2013	424327	panel above rear damaged	remove inside panel dissasemble rebuild new panel and refit		726065
216	09/09/2013	424283	Perform sticker audit on vehicles ensuring that correct stic	COMPLETED		726065
216	09/06/2013	423757	rear bump stops broken	replaced both rear bump stops		725943
216	09/06/2013	424072	Mechanic entered - Engine Other Intercooler is split & poss	replaced breather		725943
216	09/06/2013	423757	rocker cover cracked	replaced rocker cover		725943
216	09/06/2013	423757	top rad mount broken	replaced one top radiator mount		725943
216	09/06/2013	423825	860/1060mm REAR DOOR MECH	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:P129184 Receiving #:130817 Date :2013-09-12		726282
216	09/06/2013	423757	hand brake relay valve leaking	replaced relay valve		725943
216	09/05/2013	423826	GLOBE 24V 5W BAYONETT			725676
216	09/05/2013	423826	next stop light not working	Replaced Globes		725676
216	09/05/2013	423826	dash lights not working	Replaced switch globes		725676
216	09/05/2013	423826	GLOBE WEDGE 24V 1.2W			725676
216	09/05/2013	423757	top rad mount broken			725676
216	09/05/2013	423825	panel above rear damaged	replaced		725676
216	09/05/2013	423826	BRAKE PEDAL PAD			725676
216	09/05/2013	423826	brake pedal rubber worn	Replaced pedal pad		725676
216	09/05/2013	423826	emeg exit decals faded	replaced		725676
216	09/05/2013	423826	air leak transmission	Replaced accumulator solenoid		725676
216	09/03/2013	423357	ROCKER COVER GASKET 0500LE	Rocker Cover Gasket		725222
216	09/03/2013	423357		Adjust Tappets		725222
216	09/03/2013	423359		Rotate Rear Axle Tyres Left to Right - MT & IBS only		725222
216	09/03/2013	423359		Tension Wheel Nuts		725222
216	09/03/2013	423359		Perform & Complete TSV Bus Safety Inspection		725222
216	09/03/2013	423359		Clean A/C filter.		725222
216	09/03/2013	423359		Rotate Front Axle Tyres Left to Right - MT & IBS only		725222
216	09/03/2013	423356		Replace angle drive oil		725222
216	09/03/2013	423356		Replace power steering filter and check level (Replace oil if required)		725222
216	09/03/2013	423356	FUEL FILTER MERC 0500LE			725222
216	09/03/2013	423356	FUEL FILTER 0500LE			725222
216	09/03/2013	423356	AIR DRYER CANISTER VOLVO+ NL202			725222
216	09/03/2013	423356	POWER STEERING FILTER VOLVO			725222
216	09/03/2013	423356		completed		725222
216	09/03/2013	423356		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals		725222
216	09/03/2013	423356		Inspect radiator and charge air cooler for dirt - clean		725222
216	09/03/2013	423356		Check oil level in transmission - top up if required		725222
216	09/03/2013	423356		Check and clean cartridge in dry type air cleaner		725222
216	09/03/2013	423356		Replace pre and main fuel filters		725222
216	09/03/2013	423356		Replace air dryer cansiter clean silence and drain reservoir		725222
216	09/03/2013	423356		Test coolant level - top up if required to equate to 37C frost protection		725222
216	09/03/2013	423358	ENGINE OIL DELO 400LE 15W40			725222
216	09/03/2013	423358		Tension Wheel Nuts to Spec		725222
216	09/03/2013	423358		A Service & Bus Safety Inspection		725222
216	09/03/2013	423358		D-Service & Bus Safety Inspection		725222
216	09/03/2013	423358		Replace Engine Oil Breather Kit		725222
216	09/03/2013	423358	ENGINE OIL BREATHER KIT 0500LE			725222
216	09/03/2013	423358		Grease AC Compressor Clutch Bearing		725222
216	09/03/2013	423358	AIR FILTER MERC 0500LE			725222
216	09/03/2013	423358	OIL FILTER 1725+0500LE			725222
216	09/03/2013	423358		A Service		725222
216	09/03/2013	423358		Clean A/C filter		725222
216	09/03/2013	423358		Grease AC Compressor Clutch Bearing		725222
216	09/03/2013	423358		Tension Wheel Nuts To OEM Specification		725222
216	09/02/2013	423056	Drv entered - Vandalism Graffiti	servicable		725047
216	09/02/2013	421787	repair cctv fault	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:P129220 Receiving #:131097 Date :2013-09-19		727906
216	09/02/2013	421787	SMALL PARTS	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:P129220 Receiving #:131097 Date :2013-09-19 bus 216		727906
216	08/27/2013	422233	wiper washers n/w	Refilled W/S washer resivor. Replaced W/S washer pump. Blead washers and cheaked system.		723155
216	08/27/2013	422198	Drv entered - Steering Not Self Centering [See printed defec	cheacked and testdrive cant find worne ok		723155
216	08/27/2013	422233	PUMP WIPER-WASHER 24 VOLT			723155
216	08/27/2013	422233	Drv entered - Other	no fault found		723155
216	08/23/2013	421787	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Complete by Lonsdale Auto's.		721932
216	08/23/2013	421536	GLOBE WEDGE 24V/5W			721932
216	08/23/2013	421536	Mechanic entered - Elec & Light Park Lights N/S/F park globe	replaced		721932
216	08/23/2013	421788	Ops Entered - Fault - Security CCTV System Faulty - Route:	COMPLETED		721932
216	08/20/2013	420897	GLOBE WEDGE 24V/5W			720933
216	08/20/2013	420897	LH parker out			720933
216	08/16/2013	420487	Ops Entered - Accident - Bus Hit Stationery Vehicle - Rout	Completed.		720011
216	08/14/2013	420039	RAD CAP MERC BENZ SIGHT GLASS SIDE			719455
216	08/14/2013	420039	repair coolant leak	Cut out damaged section of brass feed pipe. replaced with Merc. hose. Toped up cooling system adjusted top Alt. belt. Cleaned area run and test.		719455
216	08/12/2013	419701	LED FRONT POSITION MARKER LIGHT			718796
216	08/12/2013	419701	Number plate light out	Replaced O/S Number plate light LED.		718796
216	08/07/2013	419018		Clean A/C filter.		717387
216	08/07/2013	419018		Rotate Rear Axle Tyres Left to Right - MT & IBS only		717387

216	08/07/2013	419018	Rotate Front Axle Tyres Left to Right - MT & IBS only	717387
216	08/07/2013	419018	Tension Wheel Nuts	717387
216	08/07/2013	419018	Perform & Complete TSV Bus Safety Inspection	717387
216	08/07/2013	419015	rear of the engine leaking oil	717387
216	08/07/2013	419015	Drv entered - Other [See printed defect for more information	717387
216	08/07/2013	419015	coolant pipe out of header tank leaking coolant	717387
216	08/07/2013	419015	2 x grab handles missing at rear	717387
216	08/07/2013	419019	Bus Safety Inspection	717387
216	08/07/2013	419019	FILTER TRANSMISSION ZF 4139-298-038E39HD119	717387
216	08/07/2013	419019	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	717387
216	08/07/2013	419019	Service T - Replace Transmission Oil & Filter	717387
216	08/07/2013	419016	HALDEX COIL KIT 0500LE	717387
216	08/07/2013	419016	DRAIN VALVE KIT BOTTOM	717387
216	08/07/2013	419016	HALDEX COIL BASE OIL SEPERATOR	717387
216	08/07/2013	419016	CYCLONE CONDENSER VALVE KIT	717387
216	08/07/2013	419016	Re-kit Air Cyclone Separator re-kitted air cyclone seperator	717387
216	08/06/2013	418735	GLOBE WEDGE 24V/5W	717048
216	08/06/2013	418735	RH parker out	717048
216	07/30/2013	417296	OR booster u/s oil leak at sump water leak at bottom & w/	714764
216	07/30/2013	417295	coolant pipe out of header tank leaking coolant	714764
216	07/29/2013	417287	EMERGENCY EXIT BUTTON PULL COVER	714764
216	07/29/2013	417287	Drv entered - Elec & Light Interior Lights	714764
216	07/26/2013	417011	PLASTIC HEATER TAP VOLTGREEN	715094
216	07/22/2013	416300	rear of engine leaking oil	712609
216	07/20/2013	416200	GLOBE WEDGE 24V/5W	712198
216	07/20/2013	416200	RH parker out	712198
216	07/17/2013	415626	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER	711034
216	07/17/2013	415626	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM	711034
216	07/17/2013	415626	Drv entered - Other	711034
216	07/14/2013	414970	Ops Entered - Fault - Brakes Hand Brake - Route: - DISPLA	710370
216	07/07/2013	413782	Mechanic entered - Body & Acc Other	709007
216	07/06/2013	413782	Mechanic entered - Body & Acc Other	709007
216	07/01/2013	412656	Mechanic entered - Whls & Tyres Worn o/s outter rear	707738
216	06/28/2013	412355	BRAKE BOOSTER R/H/REAR 0500-50	707738
216	06/28/2013	412489	replaced o/s rear brake booster	707173
216	06/27/2013	412418	Clean A/C filter.	706685
216	06/27/2013	412418	Rotate Rear Axle Tyres Left to Right - MT & IBS only	706685
216	06/27/2013	412418	Rotate Front Axle Tyres Left to Right - MT & IBS only	706685
216	06/27/2013	412418	Tension Wheel Nuts	706685
216	06/27/2013	412418	Complete safety inspection	706685
216	06/27/2013	416778	Dipstick broken	707173
216	06/27/2013	412666	Engine hatch struts U/S	707173
216	06/27/2013	412355	Mechanic entered - Brakes Losing Air	706685
216	06/27/2013	412355	A Service	706685
216	06/27/2013	412355	Clean A/C filter	706685
216	06/27/2013	412355	Grease AC Compressor Clutch Bearing	706685
216	06/27/2013	412355	Tension Wheel Nuts To OEM Specification	706685
216	06/17/2013	410565	Drv entered - Elec & Light Park Lights [See printed defect f	703858
216	06/17/2013	410564	GLOBE WEDGE 24V/5W	703858
216	06/17/2013	410564	parker RH out	703858
216	06/12/2013	409092	Service	702634
216	06/09/2013	409426	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR	701586
216	06/09/2013	409426	Drv entered - Suspension Leaning [See printed defect for mor	701586
216	06/09/2013	409428	Drv entered - Other [See printed defect for more information	701586
216	06/09/2013	409427	Drv entered - Body & Acc Exterior [See printed defect for mo	701586
216	06/06/2013	409092	REPOART FLAT BATTERYS AT KARINAGL HUB	701138
216	06/04/2013	408844	Drv entered - Elec & Light Headlights	700588
216	06/03/2013	408724	Perform Campaign as per Instructions Ensure that appropri	700588
216	05/30/2013	407000	MIRROR METAGAL L/H	699219
216	05/28/2013	406803	11R22.5-A GRADE CASE CHG	698684
216	05/28/2013	406803	TYRE RECYCLE/DISP RECOV TRK	698684
216	05/28/2013	406803	FITTING TRUCK	698684
216	05/28/2013	406803	SP 11R22.5 SP327 8A GRADE CASE	698684
216	05/28/2013	407504	Drv entered - Passenger Doors Faulty Controls	69

216	05/21/2013	406360	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	696135
216	05/21/2013	406360	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	696135
216	05/21/2013	406360	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	696135
216	05/21/2013	406360	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	696135
216	05/21/2013	406360	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	696135
216	05/21/2013	406360	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	696135
216	05/21/2013	406360	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	696135
216	05/21/2013	406360	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	696135
216	05/21/2013	406360	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	696135
216	05/21/2013	406360	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	696135
216	05/21/2013	406360	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	696135
216	05/21/2013	406360	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	696135
216	05/13/2013	405168	GLOBE H1 24V 70W	693654
216	05/13/2013	405168	RH headlight out	693654
216	05/13/2013	405069	GLOBE H1 24V 70W	693654
216	05/13/2013	405069	Drv entered - Elec & Light Headlights [See printed defect f	693654
216	05/09/2013	404655	A Service	692580
216	05/09/2013	404655	Clean A/C filter	692580
216	05/09/2013	404655	Grease AC Compressor Clutch Bearing	692580
216	05/09/2013	404655	AIR FILTER MERC 0500LE	692580
216	05/09/2013	404655	TOP ALT BELT 0500LE	692580
216	05/09/2013	404655	LED FRONT POSITION MARKER LIGHT	692580
216	05/09/2013	404655		692580
216	05/01/2013	402288	AIR COMPRESSOR	693854
216	04/30/2013	403352	Drv entered - Other [See printed defect for more information	690006
216	04/22/2013	402277	Perform & Complete TSV Bus Safety Inspection Safety Inspection & replaced intercooler hose	687484
216	04/22/2013	402277	Tension Wheel Nuts	687484
216	04/22/2013	402277	Rotate Front Axle Tyres Left to Right - MT & IBS only	687484
216	04/22/2013	402277	Rotate Rear Axle Tyres Left to Right - MT & IBS only	687484
216	04/22/2013	402277	Clean A/C filter.	687484
216	04/22/2013	402288	Drv entered - Ticket Equip VAL	687484
216	04/22/2013	402288	Drv entered - Ticket Equip VAL	687484
216	04/22/2013	402288	CIRCUIT PROTECTION VALVE	687484
216	04/22/2013	402288	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	687484
216	04/22/2013	402288	Mechanic entered - Air System Losing Air 6 Way Valve leaking	687484
216	04/22/2013	402277	air leak from air dryer	687484
216	04/22/2013	402277	air leak from air dryer	687484
216	04/22/2013	402277	air leak from air dryer	687484
216	04/09/2013	400210	Mechanic entered - Elec & Light Headlights N/S head light no	682887
216	04/09/2013	400210	GLOBE H1 24V 70W	682887
216	04/09/2013	400210	GLOBE 24V 5W BAYONETT	682887
216	04/05/2013	398240	MUFFLER MOUNT 0500LE	681943
216	04/02/2013	399131	neutral button will not stay in	680971
216	03/27/2013	398682	Drv entered - Passenger Doors Intermittent	678830
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/25/2013	398386	ENGINE OIL DELO 400LE 15W40	678622
216	03/25/2013	398386	OIL FILTER 1725+0500LE	678622
216	03/25/2013	398386	AIR FILTER MERC 0500LE	678622
216	03/25/2013	398386		678622
216	03/25/2013	398386	ENGINE OIL BREATHER KIT 0500LE	678622
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/25/2013	398386		678622
216	03/22/2013	398240	Perform & Complete TSV Bus Safety Inspection	677774
216	03/22/2013	398240	Tension Wheel Nuts	677774
216	03/22/2013	398240	Rotate Front Axle Tyres Left to Right - MT & IBS only	677774
216	03/22/2013	398240	Clean A/C filter.	677774
216	03/22/2013	398240	Rotate Rear Axle Tyres Left to Right - MT & IBS only	677774
216	03/22/2013	398240	GLOBE WEDGE 24V 1.2W	677774
216	03/22/2013	397685	BALANCE	681597
216	03/22/2013	397685	FITTING	681597
216	03/22/2013	397685	11R22.5 SP327 P/C RTD	681597
216	03/22/2013	397685	Direct Purchase - TYRES	681597
216	03/22/2013	397685	BALANCE	681597
216	03/22/2013	397685	11R22.5 SP327 P/C RTD	681597
216	03/22/2013	397685	Direct Purchase - TYRES	681597
216	03/22/2013	397685	FITTING	681597
216	03/22/2013	398240	Drv entered - Suspension Leaning bus leaning to left	677774
216	03/22/2013	398240	Drv entered - Suspension Leaning [See printed defect for mo	677774
216	03/22/2013	398240	air con duct above rear door cracked	677774
216	03/22/2013	398240	Mechanic entered - Exhaust Broken Mount	677774
216	03/22/2013	398167	O/S. Front lower park light out.	677774
216	03/22/2013	398167	GLOBE WEDGE 24V/5W	677774
216	03/22/2013	398240	Mechanic entered - Elec & Light Dash	677774
216	03/22/2013	398240	intercooler leaking	677774
216	03/22/2013	398240	both rear & front door switch red button missing	677774
216	03/22/2013	398240	Drv entered - Body & Acc Drivers Seat Mount seat leans to l	677774
216	03/22/2013	398240	Internal panel above rear door cracked	677774
216	03/19/2013	397685	chang worn o/s rera outer tyre	676699
216	03/19/2013	397685	chang worn o/s rera outer tyre	676699
216	03/13/2013	396676	No hazards	675402
216	03/13/2013	396676	Service	675402
216	03/13/2013	396769	CYCLONE CONDENSER VALVE KIT	674759
216	03/13/2013	396769	HALDEX COIL BASE OIL SEPERATOR	674759
216	03/13/2013	396769	DRAIN VALVE KIT BOTTOM	674759
216	03/13/2013	396769	HALDEX COIL KIT 0500LE	674759
216	03/13/2013	396769		674759
216	03/13/2013	396769	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	674759
216	03/01/2013	394220	FITTING	681597
			Creditor #:BEA002 BEAUREPAIRS FOR TYRES P/O #:P120772 Receiving #:123082 Date :2013-04-03 CLEANSKIN	

216	03/01/2013	394220	BALANCE	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P120772 Receiving #:123082 Date :2013-04-03 CLEANSKIN	681597
216	03/01/2013	394220	Direct Purchase - TYRES	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P120772 Receiving #:123082 Date :2013-04-03 CLEANSKIN	681597
216	02/22/2013	394191		Perform & Complete TSV Bus Safety Inspection Carried out saftey inspection as per schedule.	668217
216	02/22/2013	394191		Tension Wheel Nuts	668217
216	02/22/2013	394191		Rotate Front Axle Tyres Left to Right - MT & IBS only	668217
216	02/22/2013	394191		Rotate Rear Axle Tyres Left to Right - MT & IBS only	668217
216	02/22/2013	394191		Clean A/C filter.	668217
216	02/22/2013	394220	Mechanic entered - Whls & Tyres Worn	Replaced O/S front tyre road test and retension wheel nuts.	668217
216	02/22/2013	394450	Drv entered - Vandalism Damaged Seat	checked ok	668722
216	02/22/2013	394450	Drv entered - Vandalism Wndow Etch	checked ok	668722
216	02/22/2013	394223	Mechanic entered - Steering Pulls Left	Check toe in adjust toe in. road test O.K.	668217
216	02/22/2013	394450	Drv entered - Engine Low Oil Pressure	engine oil level low on dipstick	668722
216	02/21/2013	393907	Drv entered - Passenger Doors Faulty Controls	as per w/o 393906	667952
216	02/21/2013	393906	Drv entered - Passenger Doors Faulty Controls	Replaced the rear door operating button cover.Checked all operation of doors all OK.	667952
216	02/07/2013	392126	Drv entered - Passenger Doors Require Adjusted	Adjusted the operating sequence and sensitive edge of both fr and rear pass doors.	663332
216	02/07/2013	392126		Tensioned all wheel nuts and replaced squirrells.	663332
216	02/07/2013	392126		AC comp clutch bearing greased.	663332
216	02/07/2013	392126		AC return air filter washed and cleaned.	663332
216	02/07/2013	392126		A Service Carried out A service as per schedule.	663332
216	02/07/2013	392126	AIR FILTER MERC 0500LE		663332
216	02/05/2013	391709	leaking water pump	Replaced water pump.	662850
216	02/05/2013	391709	WATER PUMP	Creditor # :MUL001 MULTISPARES LTD P/O # :P119849 Receiving #:121174 Date :2013-02-19	667605
216	02/01/2013	391286	Drv entered - Vandalism Graffiti	graffiti removed	661536
216	01/25/2013	390079	VOSS ADAPTOR 232 TP 230 M16X1.	Creditor # :MUL001 MULTISPARES LTD P/O # :P119520 Receiving #:120239 Date :2013-01-30 49G4524WABCO	660885
216	01/25/2013	390079	VOSS ADAPTOR 232 TO 230 M22X1.	Creditor # :MUL001 MULTISPARES LTD P/O # :P119520 Receiving #:120239 Date :2013-01-30 494525WABCO	660885
216	01/25/2013	390079	VOSS ADAPTOR 232 TP 230 M16X1.	Creditor # :MUL001 MULTISPARES LTD P/O # :P119520 Receiving #:120240 Date :2013-01-30 49G4524WABCO	660885
216	01/25/2013	390079	VOSS ADAPTOR 232 TO 230 M22X1.	Creditor # :MUL001 MULTISPARES LTD P/O # :P119520 Receiving #:120240 Date :2013-01-30 494525WABCO	660885
216	01/23/2013	390073		Perform & Complete TSV Bus Safety Inspection	659141
216	01/23/2013	390073		Tension Wheel Nuts	659141
216	01/23/2013	390073		Rotate Front Axle Tyres Left to Right - MT & IBS only	659141
216	01/23/2013	390073		Rotate Rear Axle Tyres Left to Right - MT & IBS only	659141
216	01/23/2013	390073		Clean A/C filter.	659141
216	01/23/2013	390012	replace n/s front parker	replaced front parker globes	659141
216	01/23/2013	390089	replace main engine belt	replace main engine belt	659141
216	01/23/2013	390089	A/C BELT 0500 BENZ		659141
216	01/23/2013	390079	front brake proprtioNing valve u/s	Replaced valve & tested	659141
216	01/23/2013	390079	DIRECT BRAKES	Creditor # :MUL001 MULTISPARES LTD P/O # :P119357 Receiving #:120074 Date :2013-01-23	659232
216	01/11/2013	388531	LH Parker in header out		655498
216	01/11/2013	388531	GLOBE 24V 5W BAYONETT		655498
216	01/10/2013	388061	Drv entered - Passenger Doors Faulty Controls	as per w/o 388063	654820
216	01/10/2013	388062	Drv entered - Passenger Doors Not Operating	as per w/o 388063	654820
216	01/10/2013	388063	Drv entered - Passenger Doors Intermittent	adjust front door s/edge	654820
216	01/09/2013	387884	Drv entered - Vandalism Wndow Etch	windows checked safe for operation	654521
216	01/02/2013	387518	Drv entered - Vandalism Graffiti	clean rear seats a/c duct work floors seat squbs repaint a/c duct work	652619
216	12/21/2012	385336	SP 11R22.5 SP327 A GRADE CASE	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P118248 Receiving #:119280 Date :2013-01-07	653823
216	12/21/2012	385336	FITTING	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P118248 Receiving #:119280 Date :2013-01-07	653823
216	12/21/2012	385336	11R22.5 - A GRADE CASE CHG	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P118248 Receiving #:119280 Date :2013-01-07	653823
216	12/18/2012	385351		Perform & Complete TSV Bus Safety Inspection	648440
216	12/18/2012	385351		Tension Wheel Nuts	648440
216	12/18/2012	385351		Rotate Front Axle Tyres Left to Right - MT & IBS only	648440
216	12/18/2012	385351		Rotate Rear Axle Tyres Left to Right - MT & IBS only	648440
216	12/18/2012	385351		Clean A/C filter.	648440
216	12/18/2012	385319	Mechanic entered - Elec & Light Headlights		648440
216	12/18/2012	385319	GLOBE H1 24V 70W		648440
216	12/18/2012	385319	Ops Entered - Accident - Broken Window-Windscreen - Route:	replace cracked windscreen	648440
216	12/18/2012	385319	Ops Entered - Accident - Broken Window-Windscreen - Route:		648440
216	12/18/2012	385351	Ops Entered - Accident - Broken Window-Windscreen - Route:	Checked repaired	648440
216	12/18/2012	385336		Tension Wheel Nuts To OEM Specification	648440
216	12/18/2012	385336		Grease AC Compressor Clutch Bearing	648440
216	12/18/2012	385336		Clean A/C filter	648440
216	12/18/2012	385336		A Service	648440
216	12/18/2012	385336	AIR FILTER MERC 0500LE		648440
216	12/18/2012	385336	TOP ALT BELT 0500LE		648440
216	12/17/2012	385194	Drv entered - Vandalism Graffiti	All graffiti removed	648119
216	12/17/2012	385194	Drv entered - Vandalism Graffiti		648119
216	12/17/2012	385194	Drv entered - Vandalism Graffiti		648119
216	12/17/2012	385194	Drv entered - Vandalism Graffiti		648119
216	12/17/2012	385194	Drv entered - Vandalism Graffiti		648119
216	12/17/2012	385194	Drv entered - Vandalism Wndow Etch		648119
216	12/17/2012	385194	Drv entered - Vandalism Wndow Etch		648119
216	12/17/2012	385194	Drv entered - Vandalism Other		648119
216	12/01/2012	383363	RH headlight out	replace globe	644409
216	12/01/2012	383363	GLOBE H1 24V 70W		644409
216	11/30/2012	382983	replace starter motor	Remove starter motor replaced solenoid with old spare.	642569
216	11/29/2012	382983	replace starter motor		642395
216	11/08/2012	380150		Perform & Complete TSV Bus Safety Inspection	635740
216	11/08/2012	380150		Tension Wheel Nuts	635740
216	11/08/2012	380150		Rotate Front Axle Tyres Left to Right - MT & IBS only	635740
216	11/08/2012	380150		Rotate Rear Axle Tyres Left to Right - MT & IBS only	635740
216	11/08/2012	380150		Clean A/C filter.	635740
216	11/08/2012	380299	Drv entered - Passenger Doors Other front door senitive edge		635936
216	11/08/2012	380299	Drv entered - Other		635936
216	11/05/2012	379767	Drv entered - Other	no fault found	634809
216	10/31/2012	378507	11R22.5 SP327 P/C RTD	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P115779 Receiving #:116805 Date :2012-11-08	635936
216	10/31/2012	378507	FITTING	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P115779 Receiving #:116805 Date :2012-11-08	635936
216	10/26/2012	378507	replace o/s outter tyre	REPLACE SIDE WALL DAMMAGED O/S REAR TYRE	633005
216	10/26/2012	378475	OIL FILTER 1725+0500LE		633005
216	10/26/2012	378475		Grease AC Compressor Clutch Bearing	633005
216	10/26/2012	378475	ENGINE OIL BREATHER KIT 0500LE		633005
216	10/26/2012	378475		Replace Engine Oil Breather Kit	633005
216	10/26/2012	378475		D-Service & Bus Safety Inspection	633005
216	10/26/2012	378475		A Service & Bus Safety Inspection	633005
216	10/26/2012	378475		Tension Wheel Nuts to Spec	633005

[illegible]

216	07/10/2012	362944	Clean A/C filter	602483
216	07/10/2012	362944	A Service	602483
216	07/09/2012	362707	Drv entered - Elec & Light Altern Light [See printed defect	601954
216	07/09/2012	362707	BRUSH KIT 55AMP ALT B10M MK3	601954
216	06/10/2012	358677	repair indicators	594209
216	06/10/2012	358677	GLOBE 24V16W	594209
216	06/05/2012	356794	DIVIDER RUBBER FOR DESTO	593064
216	06/05/2012	356794	KEY RUBBER	593064
216	06/04/2012	357704	Drv entered - Passenger Doors Other [See printed defect for	592259
216	05/31/2012	357165	Check boost pumpcondition	591081
216	05/31/2012	357165	Replace compressor oil	591081
216	05/31/2012	357165	Check & replace electricmotor brushes	591081
216	05/31/2012	357165	D Service	591081
216	05/31/2012	357165	Replace filter drier	591081
216	05/31/2012	357165	C Service	591081
216	05/31/2012	357165	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	591081
216	05/31/2012	357165	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	591081
216	05/31/2012	357165	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	591081
216	05/31/2012	357165	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	591081
216	05/31/2012	357165	DRIVE PULLEY'S: IDLER PULLEY - inspect idlerbearings; inspect idlerpulley for wear; inspectidler post & bush forwear	591081
216	05/31/2012	357165	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	591081
216	05/31/2012	357165	REFRIGERATION FILTER DRYER: Replace filterdryer; check pumpoperation;	591081
216	05/31/2012	357165	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	591081
216	05/31/2012	357165	INSPECT MOTORS &BRUSHES: Blow outcarbon dust on allevaporator & condensormotors; check brushwear; check blowermotor wheels & clean;check mountingbrackets; checkelectrical connections;check condensor fangrills	591081
216	05/31/2012	357165	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	591081
216	05/31/2012	357165	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	591081
216	05/30/2012	356794	ONE PIECE WINDSCREEN	592642
216	05/30/2012	356794	S&F DESTO	592642
216	05/29/2012	354761	SCRAPPED TYRE	591081
216	05/29/2012	356909	wire in missing unloader	591081
216	05/29/2012	356794	R/H top clearance light out in header	591081
216	05/29/2012	356794	GLOBE 24V 5W BAYONETT	591081
216	05/29/2012	356794	Ops Entered - Accident - Bus Hit Stationary Object - Route	591081
216	05/29/2012	356794	CURVED WINDSCREEN RUBBER	593064
216	05/24/2012	353758	STARTER MOTOR WITH PINION HOUS	595772
216	05/23/2012	355899	Front N/S bottom park light out	590022
216	05/23/2012	355899	L/H top front park light out	590022
216	05/22/2012	355901	Perform & Complete TSV Bus Safety Inspection	590022
216	05/22/2012	355901	Tension Wheel Nuts	590022
216	05/22/2012	355901	Rotate Front Axle Tyres Left to Right - MT & IBS only	590022
216	05/22/2012	355901	Rotate Rear Axle Tyres Left to Right - MT & IBS only	590022
216	05/22/2012	355901	Clean A/C filter.	590022
216	05/22/2012	355901	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM	590022
216	05/22/2012	355899	tie rod assy u/s	590022
216	05/22/2012	355899	STEERING TIE ROD E4	593064
216	05/22/2012	355989	Drivers seat cushion needs padding	590022
216	05/14/2012	354761	Scrap - side wall damage	587819
216	05/09/2012	353758	STARTER MOTOR	591214
216	05/09/2012	354035	replace starter assy and main fuse	587428
216	05/09/2012	354035	400 AQMP FUSE	590022
216	05/08/2012	353758	replace starter and fuse	587208
216	05/08/2012	353758	AIR LINE FITTING KIT 0500LE AIR DRYER	587208
216	05/08/2012	353758	L.E.D SIDE MARKER PEREI RED/AMBER	587208
216	05/08/2012	353758	STARTER MOTOR WITH PINION HOUS	591214
216	05/07/2012	352492	11R22.5 SP327 P/C RTD	590022
216	05/07/2012	352492	TYRE RECYCLE	590022
216	05/07/2012	352492	FITTING	590022
216	04/30/2012	352492	O/S rear inner tyre U/S	584673
216	04/30/2012	352492	Tension Wheel Nuts to Spec	584673
216	04/30/2012	352492	Replace Engine Oil Breather Kit	584673
216	04/30/2012	352492	Grease AC Compressor Clutch Bearing	584673
216	04/30/2012	352492	A Service & Bus Safety Inspection	584673
216	04/30/2012	352492	D-Service & Bus Safety Inspection	584673
216	04/30/2012	352492	OIL FILTER 1725+0500LE	584673
216	04/30/2012	352492	Carry out service as per schedule.	584673
216	04/30/2012	352492	ENGINE OIL DELO 400LE 15W40	584673
216	04/30/2012	352492	AIR FILTER MERC 0500LE	584673
216	04/30/2012	352492	ENGINE OIL BREATHER KIT 0500LE	584673
216	04/30/2012	352492	Tension Wheel Nuts To OEM Specification	584673
216	04/30/2012	352492	Clean A/C filter	584673
216	04/30/2012	352492	Grease AC Compressor Clutch Bearing	584673
216	04/30/2012	352492	A Service	584673
216	04/23/2012	351561	Drv entered - Air System Losing Air	582484
216	04/23/2012	351561	reg	587208
216	04/20/2012	351425	air leak at rear	581511
216	04/17/2012	350699	040S ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR	580586
216	04/17/2012	350699	replace n/s rear/rear air bag	580586
216	04/14/2012	350418	air leaking rear suspension	579881
216	04/12/2012	350050	HALDEX COIL BASE OIL SEPERATOR	579805
216	04/12/2012	350050	CYCLONE CONDENSER VALVE KIT	579805
216	04/12/2012	350050	Re-kit Air Cyclone Separator	579805
216	04/12/2012	350050	Coil Kit	579805
216	04/12/2012	350050	Valve Kit	579805
216	04/05/2012	349401	Perform & Complete TSV Bus Safety Inspection	577747
216	04/05/2012	349401	Tension Wheel Nuts	577747
216	04/05/2012	349401	Rotate Front Axle Tyres Left to Right - MT & IBS only	577747
216	04/05/2012	349401	Rotate Rear Axle Tyres Left to Right - MT & IBS only	577747
216	03/27/2012	346973	STOP LAMP DURALED L.E.D	576202
216	03/26/2012	347897	O/S lower brake/tail LED U/S	574820
216	03/22/2012	346610	Direct Purchase - TYRES	576537
216	03/22/2012	346610	FITTING	576537
216	03/22/2012	346610	BALANCE	576537
216	03/20/2012	346970	Light over driver out	572816
			Down light replaced	

216	03/20/2012	346973	Bottom R/H LED stop light		572816
216	03/18/2012	346610	n/s tyre side wall damage		572427
216	03/16/2012	346743	replace rear tyres		572427
216	03/16/2012	346544	seat mounts Broken		572427
216	03/16/2012	346545	seat wieght adjustment not working		572427
216	03/16/2012	346743	Drv entered - Body & Acc Drivers Seat Cushion		572427
216	03/16/2012	346486	AIR LINE FITTING KIT 0500LE AIR DRYER		572427
216	03/16/2012	346486		A Service	572427
216	03/16/2012	346486		Clean A/C filter	572427
216	03/16/2012	346486		Grease AC Compressor Clutch Bearing	572427
216	03/16/2012	346486		Tension Wheel Nuts To OEM Specification	572427
216	02/23/2012	342811	CABLE HARNESS A/BAG+P/BRAKE SENDER		565513
216	02/21/2012	342811	Gradually the front rises while driving. Can correct by lowe	FOUND BROKEN PLUG REPLACE WITH NEW ONE CHECK OK	565069
216	02/20/2012	342434	Drv entered - Suspension High [See printed defect for more	should this happen again we will have to replace the suspension valve	564472
216	02/17/2012	342351			564174
216	02/17/2012	342351		Tension Wheel Nuts	564174
216	02/17/2012	342351		Perform & Complete TSV Bus Safety Inspection	564174
216	02/17/2012	342394	sat sytem rework		564174
216	02/14/2012	341694	Drv entered - Suspension Kneeling System [See printed defec	fault code NR4240 active wont reset. checked all leveling valves & link rods. Bus riding level warning light wont go out. Bus rises when door closed	563560
216	01/25/2012	338434	STOP LAMP DURALED L.E.D	Creditor #:MUL001 MULTISPARES LTD P/O #:#P103284 Receiving #:#104175 Date :2012-01-25	556767
216	01/25/2012	338434	REAR HUB SEAL KIT 0500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:#P103284 Receiving #:#104175 Date :2012-01-25	556767
216	01/21/2012	338434	replace all brake rotos and pads		556165
216	01/20/2012	338434	DISC PAD SET SCANIA MB0500		556165
216	01/20/2012	338434	replace all brake rotos and pads		556165
216	01/20/2012	338434	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		556165
216	01/17/2012	337486	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P103017 Receiving #:#103892 Date :2012-01-18 RECAP 11.22R	555783
216	01/17/2012	337486	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P103017 Receiving #:#103892 Date :2012-01-18 RECAP 11.22R	555783
216	01/16/2012	337486	RECAP X 2 11.22R		555411
216	01/13/2012	337137	Drv entered - Air System Slow To Build [See printed defect f	over hauled air dryer	555107
216	01/13/2012	337137	AIR DRYER CANISTER VOLVO+ NL202	OVERHAULED AIR DRYER	555107
216	01/13/2012	337137	AIR DRYER UNLOADER KIT		555107
216	01/13/2012	337137	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		555107
216	01/12/2012	337137	Drv entered - Air System Slow To Build [See printed defect f		554951
216	01/12/2012	337061		A Service	554951
216	01/12/2012	337061		Clean A/C filter	554951
216	01/12/2012	337061		Grease AC Compressor Clutch Bearing	554951
216	01/12/2012	337061		Tension Wheel Nuts To OEM Specification	554951
216	01/10/2012	334608	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P102204 Receiving #:#103559 Date :2012-01-10	554577
216	01/10/2012	334608	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P102204 Receiving #:#103559 Date :2012-01-10	554577
216	01/10/2012	335579	joiner	Creditor #:ENZ001 Enzed Dandenong P/O #:#P102468 Receiving #:#103510 Date :2012-01-10	554577
216	01/03/2012	335579	air line joiner u/s	Replaced 16 mm air line joiner secured checked ok	551658
216	01/03/2012	335579	air line joiner u/s		551658
216	12/21/2011	334608	2 x caps		550334
216	12/17/2011	334025	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		549143
216	12/17/2011	334025	AIR LEAK AND REPLACE RAER O/S AIR BAG		549143
216	11/28/2011	331137	Grab handle missing N/S/R	removed broken handle	542485
216	11/24/2011	330713		Tension Wheel Nuts	541034
216	11/24/2011	330713		Perform & Complete TSV Bus Safety Inspection	541034
216	11/22/2011	329777	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P100674 Receiving #:#101849 Date :2011-11-28	542770
216	11/22/2011	329777	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P100674 Receiving #:#101849 Date :2011-11-28	542770
216	11/22/2011	329777	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:#P100674 Receiving #:#101849 Date :2011-11-28	542770
216	11/22/2011	330287	Drv entered - Air Cond Air Conditioner	rebrushed bottom alt	540737
216	11/22/2011	330326	Drv entered - Air Cond Air Conditioner [See printed defect f	rebrushed bottom alt	540737
216	11/22/2011	330287	BRUSH KIT 55AMP ALT B10M MK3		540737
216	11/22/2011	330287	BOTTOM ALT NOT CHARGING		540737
216	11/19/2011	330048	alt not charging	replaced top alt reg brushes	539783
216	11/19/2011	330048	BRUSH KIT 55AMP ALT B10M MK3		539783
216	11/17/2011	329777	o/s front tyre worn	replaced front o/s tyre with cleanskin	539408
216	11/17/2011	329709		D-Service & Bus Safety Inspection	539408
216	11/17/2011	329709		Tension Wheel Nuts to Spec	539408
216	11/17/2011	329709	ENGINE OIL DELO 400LE 15W40		539408
216	11/17/2011	329709		A Service & Bus Safety Inspection	539408
216	11/17/2011	329709	OIL FILTER 1725+0500LE		539408
216	11/17/2011	329709	AIR FILTER MERC 0500LE		539408
216	11/17/2011	329709		Grease AC Compressor Clutch Bearing	539408
216	11/17/2011	329709	ENGINE OIL BREATHER KIT 0500LE		539408
216	11/17/2011	329709		Replace Engine Oil Breather Kit	539408
216	11/17/2011	329709		Tension Wheel Nuts To OEM Specification	539408
216	11/17/2011	329709		Grease AC Compressor Clutch Bearing	539408
216	11/17/2011	329709		Clean A/C filter	539408
216	11/17/2011	329709		A Service	539408
216	11/09/2011	328323	Drv entered - Passenger Doors Other [See printed defect for	adjusted and repositioned rear passdoor	536814
216	11/08/2011	323127	SEAL RELEASE SHAFT	Creditor #:MUL001 MULTISPARES LTD P/O #:#P100261 Receiving #:#101078 Date :2011-11-08	536814
216	10/27/2011	326443		replaced o/s top parker globe check o.k	532342
216	10/27/2011	326443	GLOBE 24V SW BAYONETT		532342
216	10/27/2011	326443		Tension Wheel Nuts	532342
216	10/27/2011	326443		Perform & Complete TSV Bus Safety Inspection	532342
216	10/27/2011	326443	light flashing on dash...oil/coolant?	checked done	532342
216	10/27/2011	326443	Park/stop-warning light comes up when u take foot off brake	done	532342
216	10/27/2011	326443	secure rear pass door top rollers	done	532342
216	10/24/2011	325596	windscreen	Creditor #:ELI001 ELITE WINDSCREENS P/O #:#P99491 Receiving #:#100645 Date :2011-10-28	533010
216	10/21/2011	325596	Ops Entered - Accident - Malicious Damage - Route: 775 - H		531605
216	10/18/2011	324844	Drv entered - indicator switch faulty jamming	found faulty indicator arm replace with new one	530659
216	10/17/2011	324844	COMBINATION SWITCH	Creditor #:MUL001 MULTISPARES LTD P/O #:#P99248 Receiving #:#101039 Date :2011-11-08	536814
216	10/11/2011	323747	rear suspection valve leaking		529387
216	10/11/2011	323747	ECAS VALVE	Creditor #:MUL001 MULTISPARES LTD P/O #:#P98937 Receiving #:#99786 Date :2011-10-11	529557
216	10/10/2011	323747	rear suspection valve leaking		529387
216	10/05/2011	323127		Re-kit Air Cyclone Separator	528144
216	10/05/2011	323127	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	Water Seperator Kit	528144
216	10/05/2011	323127	HALDEX COIL BASE OIL SEPERATOR	Base	528144
216	10/05/2011	323127	DRAIN VALVE KIT BOTTOM	Valve Kit	528144
216	10/05/2011	323127	HALDEX COIL KIT 0500LE	Coil Kit	528144
216	10/05/2011	323127		Remove dis mantle clean assemble and fit air cyclone separator.	528144

216	10/05/2011	323127	BEARING RELEASE SHAFT	Creditor #::MUL001 MULTISPARES LTD P/O #::P100261 Receiving #::101079 Date :2011-11-08	536814
216	10/05/2011	323127	CHECK VALVE 22MM	Creditor #::MUL001 MULTISPARES LTD P/O #::P100262 Receiving #::101081 Date :2011-11-08 SEE P98789	536814
216	09/30/2011	322266		A Service	526379
216	09/30/2011	322266			526379
216	09/23/2011	321238		Carry out safety inspection tension wheel nuts and road test.	524143
216	09/23/2011	321238		Tension Wheel Nuts	524143
216	09/23/2011	321238		Perform & Complete TSV Bus Safety Inspection	524143
216	09/23/2011	321238	N/S/R stabilizer bar ball joint (drop arm) U/S		524143
216	09/21/2011	320810	Drv entered - Wipers & Washers Other [See printed defect for	Wipers & washers checked works ok	523448
216	09/21/2011	320811	Drv entered - Wipers & Washers Faulty Switch [See printed de	Needs a new multry switch	523448
216	09/20/2011	320672	N/S front indicator N/W	found n/s front indicator globe blown replace with new one ok	523448
216	09/20/2011	320672	GLOBE 24V 21W SINGLE CONTACT		523448
216	09/19/2011	320270	ROAD SAFETY INSPECTIONS		524809
216	09/17/2011	320270	annual inspection	Creditor #::ROA001 Road Safety Inspections P/O #::P98019 Receiving #::99034 Date :2011-09-23	522402
216	09/15/2011	319594	Accident Damaged # 33865 R/R. n/s. lower panel reflectors n		522402
216	09/13/2011	319147	GLOBE WEDGE 24V/5W		522402
216	09/13/2011	319147			522402
216	09/13/2011	319188	REPLACE REAR SWAY BAR DROP ARMS		522402
216	09/13/2011	319239	replace broken door glass		522402
216	09/13/2011	319239	door glass		522402
216	09/13/2011	319594	Accident Damaged # 33865 R/R. n/s. lower panel reflectors		522402
216	09/12/2011	319147		Replace final drive oil	522402
216	09/12/2011	319147		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	522402
216	09/12/2011	319147		Inspect radiator and charge air cooler for dirt - clean	522402
216	09/12/2011	319147		Check oil level in transmission - top up if required	522402
216	09/12/2011	319147		Check and clean cartridge in dry tyre air cleaner	522402
216	09/12/2011	319147		Replace pre and main fuel filters	522402
216	09/12/2011	319147		Replace air dryer cansiter clean silence and drain reservoir	522402
216	09/12/2011	319147		Replace angle drive oil	522402
216	09/12/2011	319147		Test coolant level - top up if required to equate to 37C frost proctection	522402
216	09/12/2011	319147		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	522402
216	09/12/2011	319147		Replace power steering filter and check level (Replace oil if required)	522402
216	09/12/2011	319147	FUEL FILTER MERC 0500LE		522402
216	09/12/2011	319147	POWER STEERING FILTER VOLVO		522402
216	09/12/2011	319147	AIR DRYER CANISTER VOLVO+ NL202		522402
216	09/12/2011	319147	FUEL FILTER 0500LE		522402
216	09/12/2011	319147			522402
216	09/12/2011	319188	REPLACE REAR SWAY BAR DROP ARMS		522402
216	09/12/2011	319188	SWAYBAR LINK	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P97762 Receiving #::98821 Date :2011-09-16	522402
216	09/12/2011	319188	CONSUMABLE DELIVERY CHARGE	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P97762 Receiving #::98821 Date :2011-09-16	522402
216	09/12/2011	319239	replace broken door glass		522402
216	09/09/2011	318744	SWAY BAR DROP ARM L/H	Creditor #::MUL001 MULTISPARES LTD P/O #::P97613 Receiving #::99104 Date :2011-09-26	525752
216	09/08/2011	318744	N/S stabiliser bar drop arm worn		521196
216	09/05/2011	318284	Drv entered - Vandalism Graffiti		520532
216	09/05/2011	318284	Drv entered - Elec & Light Other wiper knob hard to turn on		520532
216	09/05/2011	318284	Drv entered - Heat & Demist Demisters Cold		520532
216	09/05/2011	318284	Drv entered - Other [See printed defect for more informatio		520532
216	09/05/2011	318284	Drv entered - Other		520532
216	09/05/2011	318284	Drv entered - Other [See printed defect for more informatio		520532
216	09/05/2011	318284	Dashlight toggle switch for interior rear lights = toggle		520532
216	09/05/2011	318284	Drv entered - Elec & Light Indicators [See printed defect f		520532
216	09/05/2011	318284	Drv entered - Elec & Light Switches	Replaced	520532
216	09/05/2011	318282	Ops Entered - Accident - Broken Window-Windscreen - Route:	Checked repairs done	520532
216	09/05/2011	318284	Ops Entered - Accident - Bus Hit Stationary Object - Route		520532
216	09/05/2011	318284	ACCIDENT DAMAGED # 33013 R/R. n/s/r. wheel-arch brush & tri	Checked work completed	520532
216	09/05/2011	318284	Ops Entered - Accident - Bus Hit Other Bus - Route: - Arr		520532
216	09/05/2011	318284	Ops Entered - Accident - Malicious Damage - Route: 833 - F		520532
216	09/05/2011	318284	Ops Entered - Accident - Malicious Damage - Route: 833 - F		520532
216	09/05/2011	318284	Accident Damaged # 32638 R/R. n/s/r. fleet Nos. Repair n/s		520532
216	09/05/2011	318284	Drv entered - Accident		520532
216	09/05/2011	318284	Ops Entered - Accident - To Be Advised - Route: 833 - Fore		520532
216	09/05/2011	318284	Drv entered - Accident		520532
216	09/05/2011	318284	Accident Damaged # 32977 R/R. n/s/r. fleet No decals clear		520532
216	09/05/2011	317982		Service T - Replace Transmission Oil & Filter	519378
216	09/05/2011	317982	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	519378
216	09/05/2011	317982	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	519378
216	09/05/2011	317982		Bus Safety Inspection	519378
216	09/05/2011	317982			519378
216	09/05/2011	317982			519378
216	09/05/2011	317982	AIR FILTER MERC 0500LE		519378
216	09/05/2011	317982			519378
216	09/05/2011	317982	GLOBE WEDGE 24V 1.2W		519378
216	09/02/2011	317915	Rear O/S marker light lens broken		519378
216	09/02/2011	317915	Rear O/S marker light lens broken		519378
216	08/24/2011	315957		Perform & Complete TSV Bus Safety Inspection	515770
216	08/24/2011	315957	GLOBE S/CONTACT 24V-10W	Bus Stopping Light Globe.	515770
216	08/24/2011	315957		Tension wheel nuts	515770
216	08/23/2011	315751	air leak at curcut protection valve		515770
216	08/23/2011	315751	CIRCUIT PROTECTION VALVE		515770
216	08/16/2011	314483	Drv entered - Wipers & Washers Washers Not Working [See prin	Wip Washer rectified refilledRev Buzzer rectified both works OK	513407
216	08/09/2011	313376	Ops Entered - Fault - Elec & Light - Route: 771 - Frankston	replaced n/s head light globe	42900
216	08/09/2011	313376	GLOBE H1 24V 70W		42900
216	08/04/2011	311759	C-O THERMOKING SCREW COMPRESSOR		509752
216	08/04/2011	311759	AIR CON REFRIDGERANT		509752
216	08/03/2011	312510	Drv entered - Passenger Doors Other [See printed defect for	Fr half of Fr door got a crack	42900
216	08/03/2011	311759	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P97264 Receiving #::98139 Date :2011-08-31	519006
216	08/03/2011	311759	FITTING	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P97264 Receiving #::98139 Date :2011-08-31	519006
216	08/02/2011	311759	3 X TYRES NEED REPLACING	replaced	508998
216	08/02/2011	311759	Mechanic entered - Body & Acc Other	Engine hatch strut N/Smissing replaced	508998
216	08/02/2011	311759	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P97264 Receiving #::98138 Date :2011-08-31	519006
216	08/02/2011	311759	FITTING	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P97264 Receiving #::98138 Date :2011-08-31	519006
216	08/02/2011	311626	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P98376 Receiving #::99118 Date :2011-09-26	525393
216	08/02/2011	311626	FITTING	Creditor #::BEA002 BEAUREPAIRES FOR TYRES P/O #::P98376 Receiving #::99118 Date :2011-09-26	525393

216	07/29/2011	311204	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P95829 Receiving #:97410 Date :2011-08-12	513052
216	07/29/2011	311204	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P95829 Receiving #:97410 Date :2011-08-12	513052
216	07/28/2011	311125	Direct Purchase - TYRES	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P95683 Receiving #:97411 Date :2011-08-12	513052
216	07/28/2011	311125	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P95683 Receiving #:97411 Date :2011-08-12	513052
216	07/28/2011	311125	BALANCE	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P95683 Receiving #:97411 Date :2011-08-12	513052
216	07/28/2011	311759	a/c compressor front seal leaking	Remove and replace com pressor	42900
216	07/28/2011	311626		Tension Wheel Nuts To OEM Specification	507807
216	07/28/2011	311626		Grease AC Compressor Clutch Bearing	507807
216	07/28/2011	311626		Clean A/C filter	507807
216	07/28/2011	311626			507807
216	07/28/2011	311626	GLOBE 24V 21W SINGLE CONTACT		507807
216	07/28/2011	311626	GLOBE 24V 5W BAYONETT		507807
216	07/28/2011	311626	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		507807
216	07/28/2011	311626	A/C BELT 0500 BENZ		507807
216	07/28/2011	311626	AIR DRYER CANISTER VOLVO+ NL202		507807
216	07/28/2011	311626	0405 ANSAR FRONT AND REAR AIR BAG B10M/B7R REAR		42900
216	07/28/2011	311626		A Service	507807
216	07/25/2011	311204		Perform & Complete PTSV Bus Safety Inspection	507377
216	07/25/2011	311204		Tension wheel nuts	507377
216	07/25/2011	311204		R/N/S stbilizer drop arm joint U/SO/S/R drive tyres replaced	507377
216	07/25/2011	311192	Drv entered - Passenger Doors Require Adjusted		507377
216	07/25/2011	311192	Drv entered - Passenger Doors Require Adjusted		507377
216	07/23/2011	311125	N/S REAR & N/S FRONT		507153
216	07/16/2011	309869	Drv entered - Engine Other [See printed defect for more info	Top alt belt replaced with a similar in stock	503953
216	07/04/2011	307860	S&F SIDE WINDOW	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P94729 Receiving #:96915 Date :2011-08-02 replace o/s window 1165mm x 1570mm	509395
216	07/02/2011	307860	o/s window smashed		500456
216	06/25/2011	306784			497644
216	06/25/2011	306784		Tension wheel nuts	497644
216	06/25/2011	306784		Perform & Complete PTSV Bus Safety Inspection	497644
216	06/10/2011	304672		D-Service & Bus Safety Inspection	492582
216	06/10/2011	304672		A Service & Bus Safety Inspection	492582
216	06/10/2011	304672		Tension Wheel Nuts to Spec	492582
216	06/10/2011	304672	ENGINE OIL DELO 400LE 15W40		492582
216	06/10/2011	304672	OIL FILTER 1725+0500LE		492582
216	06/10/2011	304672	AIR FILTER MERC 0500LE		492582
216	06/10/2011	304672		Grease AC Compressor Clutch Bearing	492582
216	06/10/2011	304672	ENGINE OIL BREATHER KIT 0500LE		492582
216	06/10/2011	304672		Replace engine oil breather kit	492582
216	06/10/2011	304672		Tension Wheel Nuts To OEM Specification	492582
216	06/10/2011	304672		Grease AC Compressor Clutch Bearing	492582
216	06/10/2011	304672		Clean A/C filter	492582
216	06/10/2011	304672		A Service	492582
216	06/07/2011	303110	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P94441 Receiving #:95327 Date :2011-06-28 SEE P93175	499113
216	06/07/2011	303110	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P94441 Receiving #:95327 Date :2011-06-28	499113
216	05/30/2011	303110	O/S rear tyre fiat	Tyre replaced	489603
216	05/26/2011	302573		Remove dismantle clean and re-assemble air cyclone separator with same parts. New parts not available	488106
216	05/26/2011	302573		Re-kit Air Cyclone Separator	488106
216	05/25/2011	302171		A Service & Bus Safety Inspection	487540
216	05/25/2011	302171		Tension Wheel Nuts To OEM Specification	487540
216	05/25/2011	302171		Grease AC Compressor Clutch Bearing	487540
216	05/25/2011	302171		Clean A/C filter	487540
216	05/13/2011	300476	S&F SIDE	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P92342 Receiving #:93507 Date :2011-05-19	485514
216	05/13/2011	300476	replace broken o/s no 3 window		484771
216	05/12/2011	300250	MIRROR HEAD 1/3 CONVEX L/H	Creditor #::PSS001 PARTS SUPPLY SOLUTIONS P/O #::G92291 Receiving #:93232 Date :2011-05-12	484405
216	04/20/2011	297930		A Service & Bus Safety Inspection	477562
216	04/20/2011	297930		Tension Wheel Nuts To OEM Specification	477562
216	04/20/2011	297930		Grease AC Compressor Clutch Bearing	477562
216	04/20/2011	297930		Clean A/C filter	477562
216	04/14/2011	294393	11R22.5 - A GRADE CASE CHG	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P90279 Receiving #:91962 Date :2011-04-14	475827
216	04/14/2011	294393	PUNTURE BUS-FITTED	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P90279 Receiving #:91962 Date :2011-04-14	475827
216	04/14/2011	294393	SP 11R22.5 SP327 A GRADE CASE	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P90279 Receiving #:91962 Date :2011-04-14	475827
216	04/14/2011	294393	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P90279 Receiving #:91962 Date :2011-04-14	475827
216	04/04/2011	294197	FILTER DRIER THERMO KING		472156
216	04/04/2011	294197	COMPRESSOR OIL AIR CON		472156
216	03/23/2011	294393	REPLACE BROKEN O/S WINDOWS X3		467571
216	03/23/2011	294393	SIDE WINDOWS	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P90049 Receiving #:91113 Date :2011-03-24	467882
216	03/22/2011	294197		Replace filter drier	467526
216	03/22/2011	294197		Replace compressor oil	467526
216	03/22/2011	294197		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	467526
216	03/22/2011	294197		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	467526
216	03/22/2011	294197		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	467526
216	03/22/2011	294197		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	467526
216	03/22/2011	294197		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	467526
216	03/22/2011	294197		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	467526
216	03/22/2011	294197		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	467526
216	03/22/2011	294197		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	467526
216	03/22/2011	294197		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	467526
216	03/22/2011	294197		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	467526
216	03/22/2011	294197		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	467526
216	03/21/2011	294014	side window	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P89913 Receiving #:91012 Date :2011-03-23	467571
216	03/21/2011	294014	replace n/s no 4 window		467526
216	03/21/2011	294180		Clean A/C filter	467526
216	03/21/2011	294180		Grease AC Compressor Clutch Bearing	467526
216	03/21/2011	294180		Tension Wheel Nuts To OEM Specification	467526
216	03/21/2011	294180		A Service & Bus Safety Inspection	467526
216	03/01/2011	291662	WINDSCREEN	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P89085 Receiving #:90817 Date :2011-03-18	467526
216	03/01/2011	291662	Ops Entered - Accident - Broken Window-Windscreen - Route:		460741
216	02/19/2011	290495		Tension Wheel Nuts To OEM Specification	457717
216	02/19/2011	290495		A Service & Bus Safety Inspection	457717
216	02/19/2011	290495		Clean A/C filter	457717
216	02/19/2011	290495		Grease AC Compressor Clutch Bearing	457717
216	02/03/2011	287365	CONSUMABLE SUPPLIES SURCHARGE	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P87849 Receiving #:89631 Date :2011-02-16 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	456646
216	02/03/2011	287365	BALANCE	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P87849 Receiving #:89631 Date :2011-02-16 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	456646

216	02/03/2011	287365	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P87849 Receiving #:89631 Date :2011-02-16 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	456646
216	02/03/2011	287365	Direct Purchase - TYRES	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P87849 Receiving #:89631 Date :2011-02-16 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	456646
216	01/29/2011	287365	CHANGE WORN OUT FRONT TYRE.		451327
216	01/19/2011	286043		A Service & Bus Safety Inspection	447863
216	01/19/2011	286043		Grease AC Compressor Clutch Bearing	447863
216	01/19/2011	286043	AIR FILTER MERC 0500LE		447863
216	01/19/2011	286043	OIL FILTER 1725+0500LE		447863
216	01/19/2011	286043			447863
216	01/19/2011	286043	ENGINE OIL DELO 400LE 15W40		447863
216	01/19/2011	286043			447863
216	01/19/2011	286044		Tension Wheel Nuts to Spec	447863
216	01/19/2011	286044		Re-kit Air Cyclone Separator	447863
216	01/19/2011	286044	WATER SEPERATOR SCANIA+VOLVO	Water Seperator Kit	447863
216	01/19/2011	286044		Grease AC Compressor Clutch Bearing	447863
216	01/19/2011	286043		A Service & Bus Safety Inspection	447863
216	01/19/2011	286044		A Service & Bus Safety Inspection	447863
216	01/19/2011	286044		Clean A/C filter	447863
216	01/19/2011	286043		Clean A/C filter	447863
216	01/19/2011	286043		Grease AC Compressor Clutch Bearing	447863
216	01/14/2011	285457	header tank assy	Creditor #::MUL001 MULTISPARES LTD P/O #::P87210 Receiving #:88314 Date :2011-01-14	447093
216	01/14/2011	285457	header tank assy leaking		446725
216	01/12/2011	285167	Drv entered - Body & Acc Other [See printed defect for more		446162
216	01/10/2011	284821	o/s rear window	wheel spray brush refitted	454588
216	01/10/2011	284821	replace broken o/s rear no 6 window	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P86980 Receiving #:89410 Date :2011-02-10	445540
216	12/31/2010	283400	TRADE IN		444577
216	12/31/2010	283400	BALANCE	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P86626 Receiving #:87892 Date :2011-01-05 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	444577
216	12/31/2010	283400	FITTING	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P86626 Receiving #:87892 Date :2011-01-05 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	444577
216	12/31/2010	283400	Direct Purchase - TYRES	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P86626 Receiving #:87892 Date :2011-01-05 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	444577
216	12/26/2010	283400	O/S Front tyre flat at Frankston.		441468
216	12/24/2010	283236	GLOBE H1 24V 70W		440304
216	12/24/2010	283236	O/S headlight globe needs replacing	Globe replaced	440304
216	12/20/2010	282547	rear hopper window	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P86334 Receiving #:87573 Date :2010-12-22	440304
216	12/20/2010	282547	replace broken o/s rear hopper window		439520
216	12/20/2010	282550	CIRCUIT PROTECTION VALVE		440304
216	12/20/2010	282550	curcut protection valve u/s leaking	Creditor #::MUL001 MULTISPARES LTD P/O #::P86406 Receiving #:87574 Date :2010-12-22	439520
216	12/17/2010	282298	Drv entered - Passenger Doors. Rear brakes not releasing.		438881
216	12/15/2010	282073	Drv entered - Wipers & Washers Worn [See printed defect for	Replaced 6 way valve	438563
216	12/15/2010	281374	FITTING	Tightened spindles in body work. Refitted both wiper arms	442542
216	12/15/2010	281374	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P85927 Receiving #:87815 Date :2010-12-31 REPLACE BROKEN VALVE STEM IN 1 FLAT 11.00R 22.5 RECAP.	442542
216	12/13/2010	281603	S&F WINDSCREEN	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P85927 Receiving #:87815 Date :2010-12-31 REPLACE 1 WORN OUT 11.00R 22.5 RECAP.	442542
216	12/13/2010	281603	REPLACE SMASHED FRON TWIND SCREEN.	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P86018 Receiving #:87217 Date :2010-12-14 REPLACE FRONT WIND SCREEN.	438138
216	12/09/2010	281374	Replace worn and flat rear tyres.		438023
216	12/09/2010	281374	Ops Entered - Breakdown - 3-Change Over Other Request - Ro		437091
216	12/09/2010	281374	Ops Entered - Breakdown - 3-Change Over Other Request - Ro		437091
216	12/09/2010	281281	repalce rear brake pads		437091
216	12/09/2010	281281	DISC PAD SET-BERAL		438138
216	12/08/2010	279660	R/EMERGENCY GLASS 1934X800	Creditor #::MULTI MULTISPARES LIMITED VIC P/O #::P85910 Receiving #:87219 Date :2010-12-14	436800
216	11/29/2010	279660	fit supplied rear window	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #::P85357 Receiving #:86927 Date :2010-12-08 SUPPLY REAR WINDOW GLASS.	434198
216	11/29/2010	279660	Drv entered - Vandalism Other [See printed defect for more	Creditor #::ELI001 ELITE WINDSCREENS P/O #::P85365 Receiving #:86596 Date :2010-11-30	433076
216	11/27/2010	278581	CONSUMABLE SUPPLIES SURCHARGE		439520
216	11/27/2010	278581	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P84957 Receiving #:87382 Date :2010-12-20 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	439520
216	11/19/2010	278581	Replace both N/S rear drive tyres.	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P84957 Receiving #:87382 Date :2010-12-20 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	430671
216	11/19/2010	278510			430257
216	11/19/2010	278510		Grease AC Compressor Clutch Bearing	430257
216	11/19/2010	278510		Tension Wheel Nuts To OEM Specification	430257
216	11/19/2010	278510		A Service & Bus Safety Inspection	430257
216	10/26/2010	274967	CONSUMABLE SUPPLIES SURCHARGE	Clean A/C filter	430671
216	10/26/2010	274967	11R22.5 SP327 P/C RTD	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P83762 Receiving #:86014 Date :2010-11-18 REPLACE 1 WORN OUT 11.00R 22.5 RECAP.	430671
216	10/21/2010	274967	Replace worn out N/S rear drive tyre.	Creditor #::BEA002 BEAUREPAIRS FOR TYRES P/O #::P83762 Receiving #:86014 Date :2010-11-18 REPLACE 1 WORN OUT 11.00R 22.5 RECAP.	420221
216	10/21/2010	274766	with ignition off: Unable to secure vehicle by closing fron		419929
216	10/21/2010	274766	Drv entered - Passenger Doors Require Adjusted		419929
216	10/21/2010	274766	Drv entered - Passenger Doors Not Operating [See printed de		419929
216	10/21/2010	274766	Drv entered - Passenger Doors Faulty Controls [See printed		419929
216	10/21/2010	274766	Drv entered - Other		419929
216	10/21/2010	274766	INTERIOR MIRROR ROUND		422851
216	10/21/2010	274766	Drv entered - Body & Acc Mirrors Interior [See printed defe	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #::P83707 Receiving #:85202 Date :2010-10-27	419929
216	10/21/2010	274766	ZF GEARBOX FILTER		419929
216	10/21/2010	274766	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Transmission Filter	419929
216	10/21/2010	274766		ZF Ecofluid A Plus Synthetic Transmission Oil	419929
216	10/21/2010	274766		Service T - Replace Transmission Oil & Filter	419929
216	10/21/2010	274766		Bus Safety Inspection	419929
216	10/21/2010	274766		A Service & Bus Safety Inspection	419929
216	10/21/2010	274766		Tension Wheel Nuts To OEM Specification	419929
216	10/21/2010	274766		Grease AC Compressor Clutch Bearing	419929
216	10/21/2010	274766		Clean A/C filter	419929
216	10/13/2010	273586	LED CLEARANCE LIGHT (RED AMBER)		417404
216	10/13/2010	273586	n/s rear marker LED broken		417404
216	10/07/2010	272953	Drv entered - Wipers & Washers Faulty Switch		415368
216	10/01/2010	272215	Indicator stalk appears to be broken....Stalk worn due for		413768
216	10/01/2010	272215		A Service & Bus Safety Inspection	413768
216	10/01/2010	272215		Tension Wheel Nuts To OEM Specification	413768
216	10/01/2010	272215		Grease AC Compressor Clutch Bearing	413768
216	10/01/2010	272215		Clean A/C filter	413768
216	09/20/2010	270540	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #::P82351 Receiving #:83778 Date :2010-09-21	410701
216	09/18/2010	270540	annual inspection	bc130222	409700
216	09/17/2010	269279	LED LAMP	Creditor #::BUR003 BURSON AUTO PARTS P/O #::P82343 Receiving #:83673 Date :2010-09-20	410382
216	09/15/2010	270109	annual body inspection		409700
216	09/15/2010	270108	replace oring kits on air dryer		409700
216	09/14/2010	270108	CONSUMABLE DELIVERY CHARGE	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P82369 Receiving #:83674 Date :2010-09-20	410382
216	09/14/2010	270108	VALVE SOLENOID	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P82369 Receiving #:83674 Date :2010-09-20	410382
216	09/14/2010	270108	AIR LINE FITTING KIT 0500LE AI	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P82369 Receiving #:83674 Date :2010-09-20	410382
216	09/14/2010	270108	AIR LINE FITTING KIT 0500LE AI	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #::P82369 Receiving #:83674 Date :2010-09-20	410382
216	09/09/2010	269279		Replace angle drive oil	408219
216	09/09/2010	269279	FUEL FILTER 0500LE		408219
216	09/09/2010	269279	FUEL FILTER MERC 0500LE		408219

216	09/09/2010	269279	Replace power steering filter and check level (Replace oil if required)	408219
216	09/09/2010	269279	Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	408219
216	09/09/2010	269279	Test coolant level - top up if required to equate to 37C frost protection	408219
216	09/09/2010	269279	Replace air dryer cansiter clean silence and drain reservoir	408219
216	09/09/2010	269279	Replace pre and main fuel filters	408219
216	09/09/2010	269279	Check and clean cartridge in dry tyre air cleaner	408219
216	09/09/2010	269279	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	408219
216	09/09/2010	269279	Check oil level in transmission - top up if required	408219
216	09/09/2010	269279	Inspect radiator and charge air cooler for dirt - clean	408219
216	09/09/2010	269279	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	408219
216	09/09/2010	269279	Replace final drive oil	408219
216	09/09/2010	269279	POWER STEER FILTER B10M	408219
216	09/09/2010	269279	AIR DRYER CANISTER VOLVO+ NL202	408219
216	09/09/2010	269279	Drv entered - Vandalism Wndow Etch	408219
216	09/09/2010	269279	Drv entered - Suspension Other	408219
216	09/09/2010	269279	Drv entered - Passenger Doors Faulty Controls	408219
216	09/09/2010	269279	Front door doesnt open from the outside	408219
216	09/09/2010	269279	Under bumper front- door switch faulty. With engine immobli	408219
216	09/09/2010	269279	Drv entered - Other [See printed defect for more informatio	408219
216	09/09/2010	269279	Drv entered - Other	408219
216	09/09/2010	269279	Drv entered - Elec & Light Indicators	408219
216	09/09/2010	269279	Drv entered - Comm Equip Faulty	408219
216	09/09/2010	269279	Front door wont close from outside switches when bus turne	408219
216	09/09/2010	269279	Drv entered - Body & Acc Water Leak [See printed defect for	408219
216	09/09/2010	269279	Drv entered - Air System Losing Air	408219
216	09/09/2010	269279	Drv entered - Air System Losing Air [See printed defect for	408219
216	09/09/2010	269279	Accident damage no - 31266 - Replace n/s panel no 3 reflac	408219
216	09/08/2010	269063	INDICATOR ARM 0500LE	409700
216	09/07/2010	267740	PUNCTURE BUS-FITTED	409700
216	09/07/2010	267740	TUBELESS VALVE	409700
216	09/07/2010	269063	Drv entered - Elec & Light Indicators	407894
216	09/07/2010	269063	Drv entered - Elec & Light Indicators	407894
216	08/30/2010	267526	FILTER DRIER THERMO KING	404848
216	08/27/2010	267740	CHANGE DRIVE TYRE.	403986
216	08/27/2010	267640	Replace engine oil breather kit	403986
216	08/27/2010	267640	D-Service & Bus Safety Inspection	403986
216	08/27/2010	267640	A Service & Bus Safety Inspection	403986
216	08/27/2010	267640	Tension Wheel Nuts to Spec	403986
216	08/27/2010	267640	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	403986
216	08/27/2010	267640	OIL FILTER 1725+0500LE	403986
216	08/27/2010	267640	AIR FILTER MERC 0500LE	403986
216	08/27/2010	267640	Grease AC Compressor Clutch Bearing	403986
216	08/27/2010	267640	Tension Wheel Nuts To OEM Specification	403986
216	08/27/2010	267640	Grease AC Compressor Clutch Bearing	403986
216	08/27/2010	267640	Clean A/C filter	403986
216	08/27/2010	267640	A Service & Bus Safety Inspection	403986
216	08/26/2010	267526	Drv entered - Air Cond Other [See printed defect for more i	403779
216	08/26/2010	267526	Drv entered - Air Cond Cooling Fault Light	403779
216	08/26/2010	267526	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	403779
216	08/26/2010	267526	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	403779
216	08/26/2010	267526	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	403779
216	08/26/2010	267526	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	403779
216	08/26/2010	267526	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	403779
216	08/26/2010	267526	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	403779
216	08/26/2010	267526	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	403779
216	08/26/2010	267526	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	403779
216	08/26/2010	267526	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	403779
216	08/26/2010	267526	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	403779
216	08/26/2010	267526	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	403779
216	08/20/2010	266826	Drv entered - Vandalism Graffiti	401622
216	08/18/2010	266278	Drv entered - Vandalism Graffiti	400906
216	08/18/2010	266270	n/s INDICATOR FRONT OUT	400906
216	08/18/2010	266270	Drv entered - Elec & Light Indicators [See printed defect f	400906
216	08/18/2010	266270	Drv entered - Elec & Light Other [See printed defect for mo	400906
216	08/18/2010	266270	Drv entered - Elec & Light Indicators	400906
216	08/18/2010	266270	GLOBE 24V SW	400906
216	08/16/2010	265824	N200 12V BATTERYS	400906
216	08/16/2010	265937	O/S Number plate LED	400150
216	08/14/2010	265824	replace batteries	399728
216	08/03/2010	264165	WINDOWS: side x2 & door glass	398852
216	08/03/2010	264165	REPLACE BROKEN DOOR GLASS NO 2 ANS 3 N/S WINDOWS	396149
216	08/02/2010	264131	Grease AC Compressor Clutch Bearing	396149
216	08/02/2010	264131	Clean A/C filter	396149
216	08/02/2010	264131	A Service & Bus Safety Inspection	396149
216	08/02/2010	264131	Tension Wheel Nuts To OEM Specification	396149
216	07/28/2010	263508	Drv entered - Elec & Light Indicators [See printed defect f	394794
216	07/28/2010	263508	N/S front parker out	394794
216	07/28/2010	263508	Drv entered - Elec & Light Other	394794
216	07/28/2010	263508	Drv entered - Elec & Light Indicators	394794
216	07/28/2010	263508	GLOBE INDICATOR 24V-18W SINGLE CONTACT	394794
216	07/14/2010	261684	Drv entered - Passenger Doors Other [See printed defect for	390790
216	07/07/2010	260911	Drv entered - Ticket Equip TIM	388541
216	07/01/2010	260087	Service	386823
216	07/01/2010	260087	REPLACE FRONT BRAKE PADS.	386823
216	06/29/2010	259869	Replace all 4 rear drive wheels.	386474
216	06/29/2010	259835	Drv entered - Body & Acc Passenger Seat Cushion	386474
216	06/29/2010	259835	Drivers seat lumbar support faulty	386474
216	06/29/2010	259835	A Service & Bus Safety Inspection	386474
216	06/29/2010	259835	Tension Wheel Nuts To OEM Specification	386474
216	06/29/2010	259835	Grease AC Compressor Clutch Bearing	386474
216	06/29/2010	259835	Clean A/C filter	386474
216	06/07/2010	267150	Drv entered - Passenger Doors Faulty Controls	379642
216	06/03/2010	256866	GLOBE 24V 75/70W H4	378120
			Globe replaced	

216	06/03/2010	256866	N/S Head Light out	Globe replaced	378120
216	06/02/2010	256706		Clean A/C filter	377665
216	06/02/2010	256706		Grease AC Compressor Clutch Bearing	377665
216	06/02/2010	256706		Tension Wheel Nuts To OEM Specification	377665
216	06/02/2010	256706		A Service & Bus Safety Inspection	377665
216	06/01/2010	256656	Drv entered - Passenger Doors Not Operating [See printed de		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Faulty Controls [See printed		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Faulty Controls		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Not Operating		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Faulty Controls [See printed		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Other [See printed defect for		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Not Operating [See printed de		377665
216	06/01/2010	256656	Drv entered - Passenger Doors Not Operating [See printed de		377665
216	06/01/2010	256656	Drv entered - Other		377665
216	06/01/2010	256656	Drv entered - Other		377665
216	05/17/2010	254430	replace broken n/s rear no 4 window		371879
216	05/17/2010	254430	side window 1470mmx1170mm		375730
216	05/05/2010	253594		Creditor #:ELI001 ELITE WINDSCREENS P/O #:P77497 Receiving #:79167 Date :2010-05-25	368627
216	05/05/2010	253594		Clean A/C filter	368627
216	05/05/2010	253594		Grease AC Compressor Clutch Bearing	368627
216	05/05/2010	253594		Tension Wheel Nuts To OEM Specification	368627
216	05/05/2010	253594		A Service & Bus Safety Inspection	368627
216	05/04/2010	252634	Fitting	Creditor #:BEA001 BEAUREPAIRES P/O #:P76976 Receiving #:79045 Date :2010-05-21	374107
216	05/04/2010	252634	11R22.5 SP327 P/C RTD	Creditor #:BEA001 BEAUREPAIRES P/O #:P76976 Receiving #:79045 Date :2010-05-21	374107
216	05/03/2010	252745	1MT MULTI FIT WIPER REFILL		366510
216	05/03/2010	252745	Drv entered - Wipers & Washers Rubber Adrift		366510
216	04/30/2010	252634	replace n/s rear outer tyre	REPLACED WIPER BLADE DRIVERS SIDE	366510
216	04/09/2010	250105		replace sidewall damaged n/s rear tyre	358227
216	04/09/2010	250105		A Service & Bus Safety Inspection	358227
216	04/09/2010	250105		Tension Wheel Nuts to Spec	358227
216	04/09/2010	250105	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		358227
216	04/09/2010	250105	OIL FILTER 1725+0500LE		358227
216	04/09/2010	250105	AIR FILTER MERC 0500LE		358227
216	04/09/2010	250105		Grease AC Compressor Clutch Bearing	358227
216	04/09/2010	250105		Replace engine oil breather kit	358227
216	04/09/2010	250105		D-Service & Bus Safety Inspection	358227
216	04/09/2010	250105		A Service & Bus Safety Inspection	358227
216	04/09/2010	250105		Grease AC Compressor Clutch Bearing	358227
216	04/09/2010	250105		Tension Wheel Nuts To OEM Specification	358227
216	04/09/2010	250105		Clean A/C filter	358227
216	04/08/2010	250048	SWAY BAR LINK ROD LEFT	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P76299 Receiving #:78229 Date :2010-04-28	366125
216	04/07/2010	250048	Drv entered - Suspension Noisy [See printed defect for more	replace n/s sway bar drop arm	357866
216	04/07/2010	250046	Drv entered - Suspension Noisy		357866
216	03/31/2010	248226	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75819 Receiving #:77830 Date :2010-04-12 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	359756
216	03/31/2010	248226	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75819 Receiving #:77830 Date :2010-04-12 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	359756
216	03/31/2010	248226	11R22.5 148/145L TL SP350A DUN	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75819 Receiving #:77830 Date :2010-04-12 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	359756
216	03/25/2010	248719	Drv entered - Other security camara light not flashing	inspectd found red light flashing conected moniotr to check system all ok all cmareas are working date and timer ok	353947
216	03/20/2010	248226	FRONT O/S TYRE WORN OUT.		352753
216	03/20/2010	248172		Clean A/C filter	352456
216	03/20/2010	248172		Grease AC Compressor Clutch Bearing	352456
216	03/20/2010	248172		Tension Wheel Nuts To OEM Specification	352456
216	03/20/2010	248172		A Service & Bus Safety Inspection	352456
216	03/01/2010	245250	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75012 Receiving #:77378 Date :2010-03-24 REPLACE 3 WORN OUT 11.00R 22.5 RECAPS.	354274
216	03/01/2010	245250	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75012 Receiving #:77378 Date :2010-03-24 REPLACE 3 WORN OUT 11.00R 22.5 RECAPS.	354274
216	03/01/2010	245250	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75012 Receiving #:77378 Date :2010-03-24 REPLACE 3 WORN OUT 11.00R 22.5 RECAPS.	354274
216	03/01/2010	245250	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75012 Receiving #:77378 Date :2010-03-24 REPLACE 3 WORN OUT 11.00R 22.5 RECAPS.	354274
216	03/01/2010	363232	BALD	Creditor #:BEA001 BEAUREPAIRES P/O #:P110790 Receiving #:111767 Date :2012-07-24 new	607086
216	03/01/2010	363232	11R22.5 SP327 P/C RTD	Creditor #:BEA001 BEAUREPAIRES P/O #:P110787 Receiving #:111770 Date :2012-07-24 retreads x 2	607086
216	03/01/2010	363232	Fitting	Creditor #:BEA001 BEAUREPAIRES P/O #:P110787 Receiving #:111770 Date :2012-07-24 retreads x 2	607086
216	03/01/2010	259869	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P78959 Receiving #:80655 Date :2010-07-08	389204
216	03/01/2010	259869	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P78959 Receiving #:80655 Date :2010-07-08 REPLACE 4 WORN OUT 11.00R 22.5 RECAPS.	389204
216	03/01/2010	260087	OIL FILTER VOLVO	Creditor #:MUL001 MULTISPARES LTD P/O #:P79033 Receiving #:80423 Date :2010-07-01	387280
216	03/01/2010	260087	BRAKEPADS M/B O500LE (AFTERMAR	Creditor #:MUL001 MULTISPARES LTD P/O #:P79033 Receiving #:80423 Date :2010-07-01	387280
216	03/01/2010	260087	DIRECT BRAKES	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:P79052 Receiving #:80426 Date :2010-07-01 BRAKE PADs	387280
216	02/25/2010	245249	kit	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P75011 Receiving #:76556 Date :2010-02-25	344554
216	02/22/2010	245250	REPLACE ALL REAR DRIVE TYRES.		342385
216	02/22/2010	245231	Drv entered - Vandalism Graffiti	clean rear seats and floors	342385
216	02/22/2010	245231	Drv entered - Vandalism Graffiti	clean rear engine bay door	342385
216	02/22/2010	245231	Drv entered - Elec & Light Altern Light	remove and replace upper alt drive belt	342385
216	02/22/2010	245249	pad set	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P75011 Receiving #:76449 Date :2010-02-22	342385
216	02/22/2010	245249	replace rear brake pads	replace front and rear brake pads	342385
216	02/22/2010	245230		A Service & Bus Safety Inspection	342385
216	02/22/2010	245230		Grease AC Compressor Clutch Bearing	342385
216	02/22/2010	245230		Clean A/C filter	342385
216	02/22/2010	245230		Tension Wheel Nuts To OEM Specification	342385
216	02/12/2010	244312	dASH SHOWING NEXT STOP CONTINUOUSLY		339019
216	02/12/2010	244311	Front door wont close from outside. Inspected & found front		339019
216	02/12/2010	244312	Drv entered - Passenger Doors Other [See printed defect for		339019
216	02/12/2010	244312	Drv entered - Passenger Doors.Front Door would not close wh		339019
216	02/12/2010	244312	Unable to close front door from outside bus. Button under f		339019
216	02/12/2010	244312	Drv entered - Passenger Doors Other		339019
216	02/12/2010	244312	Drv entered - Passenger Doors Other [See printed defect for		339019
216	02/12/2010	244312	Drv entered - Other [See printed defect for more informatio		339019
216	02/12/2010	244311	Drv entered - Brakes Shuddering		339019
216	01/29/2010	242580	STEP LAMP		332996
216	01/29/2010	242580	Drv entered - Elec & Light Interior Lights		332996
216	01/19/2010	241652		Clean A/C filter	330271
216	01/19/2010	241652		Grease AC Compressor Clutch Bearing	330271
216	01/19/2010	241652		Tension Wheel Nuts To OEM Specification	330271
216	01/19/2010	241652		A Service & Bus Safety Inspection	330271
216	12/15/2009	238510	Paint wheels	Painted	321306
216	12/11/2009	238389	Straighten mirror	Straighten & adjusted the n/f mirror	320668
216	12/11/2009	238389	BRAZILLIAN MIRROR L/H		320903
216	12/08/2009	237467	Cannot open or shut front door from button under front b/bar	Checked out front door getting voltage reading of 11.48 volts where it should be earth reading	318548
216	12/08/2009	237467	Cannot open or shut front door from button under front b/bar	Send to Volgren for repairs	318548

216	12/08/2009	238025	steam cleaned radiator	cleaned radiator	320097
216	12/08/2009	238025	steam cleaned radiator	cleaned radiator	320002
216	12/08/2009	238025	tighten radiator fan bolt	tightened bolt	320002
216	12/08/2009	238025	radiator fan shaft too much side play	tightened radiator fan bolt	320002
216	12/08/2009	237963		Bus Safety Inspection	320002
216	12/08/2009	237963	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	320002
216	12/08/2009	237963		Service T - Replace Transmission Oil & Filter	320002
216	12/08/2009	237963	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	320002
216	12/08/2009	237963		Tension Wheel Nuts To OEM Specification	320002
216	12/08/2009	237963		Grease AC Compressor Clutch Bearing	320002
216	12/08/2009	237963		Clean A/C filter	320002
216	12/08/2009	237963	Service	A Service & Bus Safety Inspection	320002
216	12/04/2009	237467	Cannot open or shut front door from button under front b/bar	Checked changed solenoid still not working computer fault	318928
216	12/02/2009	237218	Wiper washer n/w	Replaced motor and clean nozzle	317966
216	12/02/2009	237218	PUMP WIPER-WASHER 24 VOLT		318349
216	12/02/2009	237277	CRANK DRIVE BELT 0500LE MERC		318349
216	12/02/2009	237277	A/C BELT 0500 BENZ		318349
216	12/02/2009	237277	transmission cooling pipe benjo leak.	Removed banjo and put new washer on it	318349
216	12/02/2009	237277	radiator fan belt crack.	Replaced fan belt	318349
216	12/02/2009	237277	oil in intake pipe under engine	Tightened hose clamp	318349
216	12/02/2009	237277	Fleet # missing off top of bus above door N/S	Put new numbers	318349
216	12/01/2009	237143	Clean a/c filter	Cleaned	317966
216	11/16/2009	235588	Ops Entered - Fault - Whls & Tyres - Route: 889 - Springva	Checked OK	313495
216	11/16/2009	235588	Ops Entered - Fault - Whls & Tyres - Route: 889 - Springva	Checked OK	313495
216	11/16/2009	235544	Adjust rear door	Adjusted	313495
216	11/16/2009	235588	Clean radiator	S/cleaned	313495
216	11/16/2009	235588	Clean radiator	S/cleaned	313495
216	11/16/2009	235513		D-Service & Bus Safety Inspection	313495
216	11/16/2009	235513		A Service & Bus Safety Inspection	313495
216	11/16/2009	235513		Tension Wheel Nuts to Spec	313495
216	11/16/2009	235513	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		313495
216	11/16/2009	235513	AIR FILTER MERC 0500LE		313495
216	11/16/2009	235513		Grease AC Compressor Clutch Bearing	313495
216	11/16/2009	235513	OIL FILTER 1725+0500LE		313495
216	11/16/2009	235513		Tension Wheel Nuts To OEM Specification	313495
216	11/16/2009	235513		Grease AC Compressor Clutch Bearing	313495
216	11/16/2009	235513		Clean A/C filter	313495
216	11/16/2009	235513		A Service & Bus Safety Inspection	313495
216	11/11/2009	234227	POS 5 11R225 CAP LOOSE	Creditor #:BEA001 BEAUREPAIRES P/O #:G71876 Receiving #:73655 Date :2009-11-11	312076
216	11/06/2009	234095	A4570704232 FUEL LINE TO FILTE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G71787 Receiving #:73491 Date :2009-11-06	310865
216	11/04/2009	234227	Replace tyre pos 5 - cap loose	Replaced	310351
216	11/04/2009	234312	Replace tyre # 5	Replaced	310351
216	11/04/2009	234312	Replace tyre # 5	Replaced	310351
216	11/04/2009	234312	Replace tyre # 5	Defect # 78859 Replaced tyre cleaned rims & torqued w/nuts	310351
216	10/30/2009	232129	pos 5-6 11r225 caps	Creditor #:BEA001 BEAUREPAIRES P/O #:G71340 Receiving #:73367 Date :2009-10-30	309361
216	10/30/2009	234095	Fuel leak	S/cleaned wet area in engine and assisted Glen remove broken engine flexible hose	309361
216	10/30/2009	234095	Fuel leak	Checked & found fuel leak replaced hose & bled	309533
216	10/30/2009	234095	Fuel leak	Assist to find leak	309533
216	10/30/2009	234100	Rear offside panel loose	Fit new catch for panel	309361
216	10/30/2009	234100	STEEL CLAW CATCHES		309533
216	10/29/2009	233940	remove graffitti	removed graffitti	309021
216	10/29/2009	233945	replace alternator belt	assist Glen to replace alternator belt	309021
216	10/29/2009	233945	replace alternator belt	Replaced	309361
216	10/29/2009	233945	replace alternator belt	assist Glen to replace alternator belt	309361
216	10/29/2009	233945	MERC ALTERNATOR BELT TOP 0500LE (A39)		309361
216	10/21/2009	233149	add coolant	added coolant	306253
216	10/21/2009	233161	clean a/c filter	cleaned filter	306253
216	10/15/2009	232129	replace worn tyres pos 5-6		304623
216	10/14/2009	232142	change tyres 5 & 6	changed tyres 5 & 6	304450
216	10/14/2009	232142	change tyres 5 & 6	changed tyres 5 & 6	304623
216	10/14/2009	232066	Service	A Service & Bus Safety Inspection. Completed.	304450
216	10/14/2009	232066	Service	A Service & Bus Safety Inspection. Completed.	304623
216	10/14/2009	232066		Tension Wheel Nuts To OEM Specification. Completed.	304450
216	10/14/2009	232066		Grease AC Compressor Clutch Bearing. Completed.	304450
216	10/14/2009	232066		Clean A/C filter. Completed.	304450
216	10/07/2009	230770	COMPRESSOR OIL AIR CON		302421
216	10/07/2009	230770	AIR CON REFRIDGERANT		302421
216	10/01/2009	230770	A/C need to be repaired	replace discharge vibra sorber top up comp oil leak check & vac charge system & run up ok	300182
216	09/26/2009	230451	Air con fault light on	Checked OK	299098
216	09/25/2009	229599	662092-l vibra sorber	Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #:G70676 Receiving #:72385 Date :2009-09-25 216	298882
216	09/24/2009	230189	Check coolant cap	Fixed coolant cap door latch	298882
216	09/19/2009	229599	Drv entered - Air Cond Cooling Fault Light		297483
216	09/19/2009	229599	A/C light flashing		297483
216	09/19/2009	229599	Climate control n/w	Run unit up found discharge vibra sorber N/S. Repaired ref to w/order # 230770	297270
216	09/18/2009	228300	POS 3-4 11R225 REAR CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G70245 Receiving #:72167 Date :2009-09-18	297270
216	09/17/2009	226475	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G69671 Receiving #:72122 Date :2009-09-17	296953
216	09/12/2009	229056	Outside door switch	Checked switches working OK	295731
216	09/11/2009	228899	Retarder switch missing on dash	No retarder in bus in fuse panel	295177
216	09/11/2009	228913		A Service & Bus Safety Inspection	295177
216	09/11/2009	228913		A Service & Bus Safety Inspection	295400
216	09/11/2009	228913		Tension Wheel Nuts To OEM Specification	295177
216	09/11/2009	228913		Grease AC Compressor Clutch Bearing	295177
216	09/11/2009	228913		Clean A/C filter	295177
216	09/07/2009	228300	Replace tyre pos 34 - worn	Replaced	294069
216	09/07/2009	228393	Change tyre # 34	Changed	294069
216	09/07/2009	228393	Change tyre # 34	Changed	294069
216	09/05/2009	228332	Wiper arm loose L hand side	Fit wiper	294069
216	09/04/2009	227919	REPLACE W/SCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G70117 Receiving #:71790 Date :2009-09-04	293806
216	09/02/2009	227919	Accident Damage no 30211 - Broken windscreen	Repaired by Elite	293396
216	09/01/2009	227907	Both upper & lower lumber supports on drivers seat n/w	Removed drivers seat air line hose squashed under seat base relocated air supply & refitted drivers seat	293139
216	09/01/2009	227907	UNION STRAIGHT AIR LINE FITTING		293396
216	08/24/2009	227015	R/H headlight n/w		290808
216	08/24/2009	227015	GLOBE HIGH BEAM 24V70W H1	Changed globe	290808

216	08/23/2009	226475	Annual inspection	DN 135693	289598
216	08/19/2009	226519	Rectifi air leak R/H/R brake chamber brake applied	Checked ok	289598
216	08/19/2009	226519	Drv entered - Brakes Other		289598
216	08/19/2009	226519	Rectifi air leak R/H/R brake chamber brake applied	Change tyre & clean rim N/S rear. Check for air leak ok	289598
216	08/19/2009	226522	Repair/paint front b/bar	Has been done by Rsi jobs.	289598
216	08/17/2009	226330	Amber warning light BS 6141	Checked for codes NONE NO abs light on	288913
216	08/15/2009	226249	Stereo aerial laying down on roof	Stright up	288236
216	08/15/2009	226249	left mirror loose	Secured	288236
216	08/12/2009	225855	N/S/R air bag cracked	Replaced both N/S rear airbags & O/SR rear airbag	287860
216	08/12/2009	225855	AIR BAG REAR VOLVO+0500LE		288022
216	08/12/2009	225855	Replace g/box cooler pipe	Replaced pipe	287860
216	08/12/2009	225737	Replace emergency exit push button under b/bar	Replaced	287555
216	08/12/2009	225855	Replace air valve next to air dryer	Replaced valve	287860
216	08/12/2009	225855	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		288022
216	08/12/2009	225737	N/S passenger window cracked - behind back door	Done on 10/08/09	287860
216	08/10/2009	225147	a0049975536 solenoid valve	Creditor #:MUL001 MULTISPARES LTD P/O #:G69357 Receiving #:71080 Date :2009-08-10 216	287422
216	08/10/2009	225541	Secure rear engine hatch door hinge	Secured	287422
216	08/10/2009	225541	Paint wheels	cleaned painted wheel	287422
216	08/10/2009	225541	MUD FLAPS GRENDAS MF60X30GRE RED		287422
216	08/10/2009	225541	SAFETY TRIANGLE DECAL		287422
216	08/10/2009	225541	EMERGENCY EXIT BUTTON PULL COVER		287422
216	08/10/2009	225541	Replace mud flaps - NSF	Fabricated new backing plate dirll hole and re fitted	287422
216	08/10/2009	225541	Secure all lower skit panels	Secured	287422
216	08/10/2009	225541	Wheel chair ramp - operation/clean	Wheel chair ramp cleaned	287422
216	08/10/2009	225541	Replace emergency exit decals with safety hammers - rear	Replaced with new one	287422
216	08/10/2009	225541	Remove timetable holder	Removed and cleaned	287422
216	08/10/2009	225541	Clean graffiti - floor seats & side walls	Cleaned	287422
216	08/10/2009	225541	Replace interior decclas - No Smoking - N/S R	Replaced decal	287422
216	08/10/2009	225541	Clean air condition filter secure vents	Clean and secured	287422
216	08/10/2009	225541	Hand rails secure rear door at floor	Secured and replaced screw	287422
216	08/10/2009	225541	Adjust front doors	Adjusted	287422
216	08/10/2009	225541	Destination blind - secure screws	Secured	287422
216	08/10/2009	225541	Replace wheel arch rubber & brush - O/S F & R	Replaced	287422
216	08/10/2009	225541	Replace safety triangle decal - on d/shield new buses	replaced	287422
216	08/10/2009	225541	Safety triangles & decals - replace	Replaced	287422
216	08/10/2009	225541	Paint till stand	Painted	287422
216	08/10/2009	225541	Polish exterior panels/headers & touch up paint work	Polished N/S O /S heardes N/S rear columns rail also upper panel 4.5.6..tuchup paint work and O/S front above bumperbar	287422
216	08/10/2009	225541	Accident Damaged #21520 R/R. rear door aperture rubber sea	Job completed	287422
216	08/07/2009	225147	Repair unloder valve	repaired	286770
216	08/07/2009	225147	OVERFLOW VALVE	Creditor #:MUL001 MULTISPARES LTD P/O #:G69297 Receiving #:70973 Date :2009-08-07	286770
216	08/05/2009	225147	Power steering leak behind diesel tank	Retighten connections	286277
216	08/05/2009	225147	Angle drive sweat s/clean & check	Cleaned checked OK	286277
216	08/05/2009	225245	Replace broken rocker cover	Replaced No 4 s/cleaned	286277
216	08/05/2009	225147	Steamclean bus	Cleaned	286277
216	08/05/2009	225147	Valve behind air dryer leaking air	Ordered parts	286277
216	08/05/2009	225079	ROCKER COVER 0500LE		286277
216	08/05/2009	225079		A Service & Bus Safety Inspection	285877
216	08/05/2009	225079		Tension Wheel Nuts To OEM Specification	285877
216	08/05/2009	225079		Grease AC Compressor Clutch Bearing	285877
216	08/05/2009	225079		Clean A/C filter	285877
216	08/05/2009	225079		A Service & Bus Safety Inspection	286389
216	07/30/2009	224617		R.S.Inspection of bus	284483
216	07/30/2009	224617		Check and clean cartridge in dry tyre air cleaner	284483
216	07/30/2009	224617		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	284483
216	07/30/2009	224617	WATER SEPERATOR SCANIA+VOLVO		284483
216	07/30/2009	224617	BRAKE+ CLUTCH PEDAL PAD 0500LE		284483
216	07/30/2009	224617		Replace final drive oil	284483
216	07/30/2009	224617		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	284483
216	07/30/2009	224617		Inspect radiator and charge air cooler for dirt - clean	284483
216	07/30/2009	224617		Replace pre and main fuel filters	284483
216	07/30/2009	224617		Replace air dryer cansiter clean silence and drain reservoir	284483
216	07/30/2009	224617		Replace angle drive oil	284483
216	07/30/2009	224617		Test coolant level - top up if required to equate to 37C frost protection	284483
216	07/30/2009	224617		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	284483
216	07/30/2009	224617		Replace power steering filter and check level (Replace oil if required)	284483
216	07/30/2009	224617	FUEL FILTER MERC 0500LE		284483
216	07/30/2009	224617	FUEL FILTER 0500LE		284483
216	07/30/2009	224617	AIR DRYER CANISTER VOLVO+ NL202		284483
216	07/30/2009	224617	POWER STEER FILTER B10M		284483
216	07/30/2009	224617		Check oil level in transmission - top up if required	284483
216	07/30/2009	224617		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	284483
216	07/30/2009	224617		Check and clean cartridge in dry tyre air cleaner	284483
216	07/30/2009	224617		Inspected	284483
216	07/30/2009	224625	Annual body inspection	Fixed new bolt & tightened both of them	284483
216	07/30/2009	224704	Angle drive mount bolt 1 missing 1 loose	Replaced	284483
216	07/30/2009	224662	Replace clearance light LHS		284483
216	07/30/2009	224662	GLOBE S/CONTACT 24V-10W		284483
216	07/30/2009	224704	Brake pedal pad rubber worn	Replaced	284483
216	07/30/2009	224704	Air leak behind the air dryer	Had to remove air cyclone seperator from bus 277	284483
216	07/30/2009	224704	Replace air cyclone seperator	Had to remove from bus 277 to fit to this bus	284483
216	07/28/2009	224358	Replace LHS headlight	Replaced	283862
216	07/28/2009	224358	GLOBE HIGH BEAM 24V70W H1		283862
216	07/22/2009	223731	Replace alternator belt	Replaced 2 alt belts	282430
216	07/22/2009	223731	Replace alternator belt	Assist with replacng	282430
216	07/22/2009	223731	MERC ALTERNATOR BELT TOP 0500LE (A39)		282430
216	07/22/2009	223731	BELT BOTTOM ALTERNATOR MERC 0500LE		282430
216	07/14/2009	222936	Right side mirror	Replaced O/S mirror bracket & replaced mirror head	280134
216	07/14/2009	222936	R/H MIRROR ARM SHORT (PM8844-2)		280134
216	07/11/2009	222791	Drv entered - Passenger Doors Intermittent	Checked OK	279316
216	07/10/2009	221512	POS 3 11R225 REAR CAP FLAT	Creditor #:BEA001 BEAUREPAIRES P/O #:G68129 Receiving #:70142 Date :2009-07-10	278937
216	07/07/2009	222403	Rear door slow to open	Adjusted rear doors	277949
216	07/03/2009	222023	Ops Entered - Fault - Body & Acc - Route: 888 - Springvale	Moved drivers seat 30mm backward	277153
216	07/03/2009	222023	Drivers seat wont go back as far as other buses	Moved drivers seat 30mm backward	277153
216	07/02/2009	221937		A Service & Bus Safety Inspection	276976

216	07/02/2009	221937	Tension Wheel Nuts To OEM Specification	276976
216	07/02/2009	221937	Grease AC Compressor Clutch Bearing	276976
216	07/02/2009	221937	Clean A/C filter	276976
216	07/02/2009	221937	A Service & Bus Safety Inspection	276976
216	06/29/2009	221512	Replaced	275925
216	06/27/2009	221563	Replaced & torqued w/nuts	275434
216	06/25/2009	220581	Creditor #::BEA001 BEAUREPAIRES P/O #:G67864 Receiving #:69779 Date :2009-06-25	275091
216	06/18/2009	220581	Replaced	272874
216	06/18/2009	220542	Replaced rear brake pads & four tyres	272874
216	06/18/2009	220542		272874
216	06/18/2009	220542	Replaced all rear tyres	273069
216	06/18/2009	220542	Added	272499
216	06/17/2009	220472	Jump started	272499
216	06/15/2009	219145	Creditor #::BEA001 BEAUREPAIRES P/O #:G67429 Receiving #:69435 Date :2009-06-15	272032
216	06/11/2009	220031	Jump started	270973
216	06/09/2009	219796	Add broom	270367
216	06/09/2009	219796		270601
216	06/09/2009	219796		270601
216	06/02/2009	219145	Replaced	268480
216	06/01/2009	219140	Changed	268347
216	06/01/2009	219140	Replaced tyre pos 12	268480
216	06/01/2009	219016	D-Service & Bus Safety Inspection	268347
216	06/01/2009	219016	A Service & Bus Safety Inspection	268347
216	06/01/2009	219016	Tension Wheel Nuts to Spec	268347
216	06/01/2009	219016		268347
216	06/01/2009	219016	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	268347
216	06/01/2009	219016	OIL FILTER 1725+0500LE	268347
216	06/01/2009	219016	AIR FILTER MERC 0500LE	268347
216	06/01/2009	219016		268347
216	06/01/2009	219016	Grease AC Compressor Clutch Bearing	268347
216	06/01/2009	219016	Clean A/C filter	268347
216	06/01/2009	219016	A Service & Bus Safety Inspection	268347
216	06/01/2009	219016	Tension Wheel Nuts To OEM Specification	268347
216	06/01/2009	219016	Grease AC Compressor Clutch Bearing	268347
216	05/24/2009	218348	Cleaned	266657
216	05/23/2009	218336	Checked r/tested OK	265916
216	05/20/2009	217986	Inflated	264972
216	05/20/2009	217986	Inflated	265215
216	05/15/2009	217513	Checked OK	263486
216	05/15/2009	217513	Checked a/c & demister OK	263486
216	05/06/2009	216683	Replaced	261042
216	05/06/2009	216683		261042
216	04/28/2009	215916	Replaced belt	258782
216	04/28/2009	215916	Fuelled & parked	258875
216	04/28/2009	215916		258875
216	04/28/2009	215916	Replaced alternator belt	258875
216	04/28/2009	215786	A Service & Bus Safety Inspection	258782
216	04/28/2009	215786	Tension Wheel Nuts To OEM Specification	258782
216	04/28/2009	215786	Grease AC Compressor Clutch Bearing	258782
216	04/28/2009	215786	Clean A/C filter	258782
216	04/28/2009	215786	A Service & Bus Safety Inspection	258875
216	04/22/2009	215339	Polished	257465
216	03/27/2009	212814	Repaired by Volgren	257465
216	03/27/2009	212814	Repaired by Volgren	257465
216	03/20/2009	212114	Repaired by Tudor on 19/3/09	255258
216	03/19/2009	211927	Adjusted locking pin down so lock would close also adjusted locking lock	254951
216	03/19/2009	211927	Parked bus	255258
216	03/18/2009	211927	Tried to fix	254736
216	03/18/2009	211927	Assist Siri un jammed but still has problem	254951
216	03/17/2009	211786	C/O bus 114. Returned to depot	254556
216	03/17/2009	211622	Temp repairs	254556
216	03/16/2009	211527	Repaired washer	254359
216	03/16/2009	211527	Checked OK	254359
216	03/16/2009	211415	Put broom in bus	254359
216	03/16/2009	211415	Completed	254359
216	03/16/2009	211415	Completed	254359
216	03/16/2009	211467	Replaced	254359
216	03/02/2009	210060	Repaired by Whitehorse	250847
216	03/02/2009	210240	Retightened door hinges	250847
216	02/25/2009	209733	A Service	249598
216	02/25/2009	209733	Tension Wheel Nuts To OEM Specification	249598
216	02/25/2009	209733	Grease AC Compressor Clutch Bearing	249598
216	02/25/2009	209733	A Service	249598
216	02/23/2009	209468	Replace brush and nut	248482
216	02/23/2009	209468		249024
216	02/23/2009	209468		249024
216	02/21/2009	209467	Replace both door hinges	248482
216	02/18/2009	209033	C Service	247740
216	02/18/2009	209033	B Service	247740
216	02/18/2009	209033	Replace compressor oil	247740
216	02/18/2009	209033	Replace filter drier	247740
216	02/18/2009	209033	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	247740
216	02/18/2009	209033	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	247740
216	02/18/2009	209033	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	247740
216	02/18/2009	209033	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	247740
216	02/18/2009	209033	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	247740
216	02/18/2009	209033	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	247740
216	02/18/2009	209033	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	247740
216	02/18/2009	209033	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	247740
216	02/18/2009	209033	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	247740
216	02/18/2009	209033	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	247740
216	02/18/2009	209033	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	247740
216	02/17/2009	209090	added	247740
216	02/17/2009	209033	added	247740
216	02/17/2009	209033	FILTER DRIER THERMO KING	247740

[illegible]

216	09/09/2008	177669	Replace tyre pos 34 - bald	Replaced	205806
216	09/08/2008	177660	Change wiper washer motor	DULKITH Changed	205806
216	09/08/2008	177660	Change N/S/R tyres	Changed	205806
216	09/08/2008	177660	Change N/S/R tyres	DULKITH Changed	205925
216	09/08/2008	177579	PUMP WIPER-WASHER 24 VOLT		205806
216	09/08/2008	177657		A Service	205806
216	09/08/2008	177657		Tension Wheel Nuts To OEM Specification	205806
216	09/08/2008	177657	DULKITH	A Service	205806
216	09/06/2008	177579	Cannot manually close front door	Checked no fault found	205806
216	09/06/2008	177560	Tint windscreens & door glassesas req.	Done by Tint FX	205539
216	08/29/2008	175569	Service	ADJUSTED ON SERVICE	203504
216	08/28/2008	176741	Replace windscreen - Sub/con - elite glass - destination gl	Repaired by Elite	202983
216	08/28/2008	176741	N/F top destination glass cracked	Repaired by Elite	202983
216	08/28/2008	176741	DESTINATION GLASS	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G59634 Receiving #:61432 Date :2008-08-28	202983
216	08/26/2008	175569	Front door sensor needs adjusting	Adjusted front door sensitive edges still door sensititve wont work	200322
216	08/26/2008	176554	Accident damage - replace front of front door glass.	Fit front door and replace glass	202582
216	08/26/2008	176554	Accident damage - replace front of front door glass.	Replaced	202582
216	08/26/2008	176554	BRAZILLIAN MIRROR L/H		202582
216	08/26/2008	176554	Accident damage - replace front of front door glass.	Replaced the broken glass panel	202582
216	08/25/2008	175802	Bus wont start	Jump started	202582
216	08/25/2008	175569	Front door sensor needs adjusting	Removed front door	202582
216	08/24/2008	176008	Annual Inspection - DN 120455	Passed	201294
216	08/22/2008	175802	Engine door gas struts need replacing	Replaced	201137
216	08/22/2008	176008	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G59480 Receiving #:61279 Date :2008-08-22	201844
216	08/21/2008	176180	Outside door switch n/w	Repaired	201598
216	08/21/2008	176180	Loose mirror at back door	tightened	201598
216	08/21/2008	176008	CONSUMABLE DELIVERY CHARGE	Creditor #:UNI001 UNIVERSAL ENG. SUPPLIES P/L P/O #:G59357 Receiving #:61248 Date :2008-08-21	201598
216	08/21/2008	176008		Creditor #:UNI001 UNIVERSAL ENG. SUPPLIES P/L P/O #:G59357 Receiving #:61248 Date :2008-08-21 216	201598
216	08/20/2008	175569	GLOBE INDICATOR 24V-18W SINGLE CONTACT	Replaced	201294
216	08/19/2008	175802	GAS STAY 370N 390MM EXT LENGHT.		201137
216	08/19/2008	175802	Touch up paint work - N/S/R bar front bar	Touched up	201137
216	08/19/2008	175802	Secure replace paint exterior mirrors and arms	Secured	201137
216	08/19/2008	175802	Wheel chair ramp - touches door	Repaired	201137
216	08/19/2008	175802	Secure or replace side reflectors - N/S O/S		201137
216	08/19/2008	175802	Paint wheels	Painted	201137
216	08/19/2008	175802	Replace mud flaps - O/S/F	Adjusted to the size drilled etc	201137
216	08/19/2008	175802	Polish exterior panels/headers - N/S 3456	Polished	201137
216	08/19/2008	175802	Replace mud flaps - O/S/F	Adjusted to the size drilled etc	201294
216	08/19/2008	175802	Engine door gas struts need replacing	Ordered	201137
216	08/19/2008	175802	O/S 84 repair & paint		201294
216	08/19/2008	175802	Accident Damaged NO 17600 Repairs to n/s. lower panels No 2		201137
216	08/19/2008	175802	O/S 84 repair & paint		201137
216	08/19/2008	175802	MUD FLAPS GRENDAS MF60X30GRE RED		201137
216	08/18/2008	175802	Paint till stand	Painted	201137
216	08/18/2008	175802	Clean graffiti - N/S & O/S 9 and walls	Cleaned	201137
216	08/18/2008	175802	Replace wheel arch rubber and brush - N/S/F	Replaced	201137
216	08/18/2008	175802	Adjust drivers blind	Adjusted	201137
216	08/18/2008	175802	Replace exit only on rear doors	Replaced	201137
216	08/18/2008	175802	Secure all lower skit panels	Secured	201137
216	08/18/2008	175802	Secure replace seat frames - O/S 1	Secured	201137
216	08/18/2008	175802	Replace interior decals - O/S disabled	Replaced	201137
216	08/18/2008	175802	Accident damage no 17224 Polish n/s panels 1234567		201137
216	08/14/2008	175569	Repair air leak on g/box retarder	Repaired	200322
216	08/14/2008	175569	Front door sensor needs adjusting	Adjusted front door sensitive edges still door sensititve wont work	200322
216	08/14/2008	175569	Oil in intercooler pipe	Removed air pipe from turbo to air cooler found some oil in the pipe. Removed engine breather unit dismantled cleaned and fitted back	200322
216	08/14/2008	175569	Inter cooler protective hose cover damaged	Removed & refitted	200322
216	08/13/2008	175482	Steamclean bus	Cleaned	200322
216	08/13/2008	175482	Coolant leak on heater hose in front of diff	Repaired	200322
216	08/13/2008	175482	Clean & check lenses	Cleaned & checked OK	200322
216	08/13/2008	175482	Air leak near air dryer	Repaired air fitting	200322
216	08/08/2008	174800	OIL FILLER CAP + PIPE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G58954 Receiving #:60954 Date :2008-08-08 216	199202
216	08/07/2008	174533	A0005011607 ELBOW RAD TO EXP T	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G59006 Receiving #:60904 Date :2008-08-07	199028
216	08/07/2008	174533	Secured fittings to radiator ordered parts for overflow pip	Fit rest of pipes & panels fill with coolant r/test checked OK fuelled & parked. Cleaned up work area	198123
216	08/06/2008	174533	Secured fittings to radiator ordered parts for overflow pip	Inspect radiator and charge air cooler for dirt - clean	199028
216	08/06/2008	174533	Secured fittings to radiator ordered parts for overflow pip	Inspect radiator and charge air cooler for dirt - clean	198123
216	08/06/2008	174800	Oil leak from oil filler tube	Fitted hose clamp	199028
216	08/06/2008	174800	Check oil filler cap	Replaced	199028
216	08/06/2008	174800	Replace lower coolant hose	Replaced	199028
216	08/05/2008	174533	Assisted Tristram	Inspect radiator and charge air cooler for dirt - clean	199028
216	08/05/2008	174533	Removed intercooler & radiator for cleaning & started to rei	Inspect radiator and charge air cooler for dirt - clean	198123
216	08/05/2008	174800	Check oil filler cap	Checked need to replace - ordered	199028
216	08/01/2008	174533		Check and clean cartridge in dry tyre air cleaner	198123
216	08/01/2008	174533		Replace pre and main fuel filters	198123
216	08/01/2008	174533		R.S.I Inspection	198123
216	08/01/2008	174533		R.S.I Inspection	198239
216	08/01/2008	174533		Replace final drive oil	198123
216	08/01/2008	174533		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	198123
216	08/01/2008	174533		Check oil level in transmission - top up if required	198123
216	08/01/2008	174533		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	198123
216	08/01/2008	174533		Replace air dryer cansiter clean silence and drain reservoir	198123
216	08/01/2008	174533		Replace angle drive oil	198123
216	08/01/2008	174533		Test coolant level - top up if required to equate to 37C frost proctionction	198123
216	08/01/2008	174533		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	198123
216	08/01/2008	174533		Replace power steering filter and check level (Replace oil if required)	198123
216	08/01/2008	174533	FUEL FILTER MERC 0500LE		198123
216	08/01/2008	174533	FUEL FILTER 0500LE		198123
216	08/01/2008	174533	AIR DRYER CANISTER MAN NL202+VOLVO		198123
216	08/01/2008	174533	POWER STEER FILTER B10M		198123
216	07/30/2008	174256	Service		197599
216	07/30/2008	174256	Annual body check list	Checked	197599
216	07/25/2008	173928		A Service	196236
216	07/25/2008	173928	MERC ALTERNATOR BELT TOP 0500LE (A39)		196420
216	07/25/2008	173928		Tension Wheel Nuts To OEM Specification	196236

216	07/25/2008	173928	A Service	196420
216	07/24/2008	173805	Secured	196009
216	07/24/2008	173805		196009
216	07/24/2008	173805	Secured drivers blind and cord	196009
216	07/16/2008	170940	A/C and heater working	193740
216	07/16/2008	170940	Checked OK	193740
216	07/16/2008	170940		193952
216	07/16/2008	173107		193740
216	07/16/2008	173107	Replaced	193740
216	07/16/2008	170940	Refitted 2way	193952
216	07/14/2008	170940	Creditor #::REB001 CIM CONCEPTS P/O #:G58316 Receiving #:60088 Date :2008-07-14	192957
216	06/23/2008	171287	Removed	187443
216	06/23/2008	171250	A Service	187443
216	06/23/2008	171250	Tension Wheel Nuts To OEM Specification	187443
216	06/23/2008	171250	A Service	187443
216	06/19/2008	170940	Replaced 2way with spare sent for repairs	186463
216	06/18/2008	170940	Replaced missing bolts in door mechanism top r/tested as req	186178
216	06/12/2008	158841	Creditor #::SOU005 SOUTHERN STATES THERMO KING P/O #:G52269 Receiving #:50349 Date :2008-06-12 WARRANTY	184487
216	06/09/2008	170209	Replaced	183451
216	06/09/2008	170209		183789
216	06/09/2008	170209	Changed tyre pos 1 with pos 2	183451
216	06/09/2008	170209		183451
216	06/09/2008	170209	Stereo still working OK	183451
216	06/09/2008	170209		183451
216	06/04/2008	121145	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:34653 Receiving #:50096 Date :2008-06-04 Fault code - INS 0508	182169
216	06/04/2008	136864	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G41647 Receiving #:50109 Date :2008-06-04 Brake warning light comes on while driving	182169
216	06/04/2008	150140	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G49444 Receiving #:50081 Date :2008-06-04 WARRANTY	182169
216	06/04/2008	150140	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G49444 Receiving #:50081 Date :2008-06-04 WARRANTY	182169
216	05/28/2008	169263	Replaced both	180261
216	05/28/2008	169263	Fixed	180261
216	05/27/2008	169089	Replaced	179876
216	05/27/2008	169089		179876
216	05/27/2008	169089		179876
216	05/22/2008	167080	Creditor #::BEA001 BEAUREPAIRES P/O #:G55291 Receiving #:49653 Date :2008-05-22	178249
216	05/21/2008	168609	Fitted during service	178164
216	05/21/2008	168523		178164
216	05/21/2008	168523		178164
216	05/21/2008	168523	Tension Wheel Nuts to Spec	178164
216	05/21/2008	168523	A Service	178164
216	05/21/2008	168523	D-Service	178164
216	05/21/2008	168523		178249
216	05/21/2008	168523	A Service	178164
216	05/21/2008	168523	Tension Wheel Nuts To OEM Specification	178164
216	05/16/2008	167851	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G55727 Receiving #:49548 Date :2008-05-16 216	177221
216	05/12/2008	167851		175982
216	05/12/2008	167851	Used van 619. Replaced with temp bolt returned to depot.NOTE: need to put original type back on bus	175656
216	05/12/2008	167851		175982
216	05/02/2008	167106	Replaced	172900
216	05/02/2008	167080	Replaced	172900
216	05/02/2008	167106	Replaced	172900
216	05/02/2008	167106	Replaced	173050
216	05/02/2008	166983	A Service	173050
216	05/02/2008	166983		172900
216	05/02/2008	166983	Tension Wheel Nuts To OEM Specification	172900
216	05/02/2008	166983	A Service	172900
216	04/20/2008	165923		169402
216	04/20/2008	165923	Replaced	169402
216	04/16/2008	165530	Repaired by Whitehorse	168685
216	04/16/2008	164112	Creditor #::BEA001 BEAUREPAIRES P/O #:G54233 Receiving #:48724 Date :2008-04-16 NEW REAR	168685
216	04/13/2008	165325		167516
216	04/13/2008	165325	Top-up oil.	167399
216	04/05/2008	164763		165424
216	04/05/2008	164763	Replaced globe	165235
216	04/04/2008	161461	Creditor #::BEA001 BEAUREPAIRES P/O #:G53195 Receiving #:48345 Date :2008-04-04 2 CAPS(POS3+5) 1 NEW(POS2)	165235
216	03/31/2008	164112	Rep. tyre pos.3 & 4 Bald.	163609
216	03/31/2008	164168	Replaced	163609
216	03/31/2008	164148	Tension Wheel Nuts To OEM Specification	163609
216	03/31/2008	164148	A Service	163609
216	03/18/2008	163393		159085
216	03/18/2008	163468	Replaced belts	159085
216	03/18/2008	163468		159367
216	03/18/2008	163393	Repaired broken wire on alternator	159085
216	03/18/2008	163825	*Attended by P.B.L C/O. Bus jump started on site drivercontinued on run. Replaced alternator belt.	159085
216	03/17/2008	163468		159085
216	03/17/2008	163468	Began to replace belt and found broken wire need to replace top belt	159085
216	03/09/2008	162879	LUBED DRIVERS WINDOWS & CHECKED O/K.	157028
216	03/01/2008	162220	refitted air linecame off from joint	155059
216	02/29/2008	162220	check repair air leaksnear rear axle.	154465
216	02/25/2008	161770		153191
216	02/25/2008	161770	Torqed and fit indicators	152899
216	02/25/2008	161727	B Service	152521
216	02/25/2008	161727	Replace filter drier	152521
216	02/25/2008	161727	Replace compressor oil	152521
216	02/25/2008	161727	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	152521
216	02/25/2008	161727	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	152521
216	02/25/2008	161727	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	152521
216	02/25/2008	161727	COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	152521
216	02/25/2008	161727	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	152521
216	02/25/2008	161727	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	152521
216	02/25/2008	161727	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	152521
216	02/25/2008	161727	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	152521
216	02/25/2008	161727	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	152521
216	02/25/2008	161727	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	152521

216	02/25/2008	161727	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	152521
216	02/23/2008	161727		152899
216	02/22/2008	161636	Replaced coolant sender and topped up coolant	152214
216	02/22/2008	161636	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G53299 Receiving #:47400 Date :2008-02-22 216	152521
216	02/22/2008	161636	Checked out code Fit new sender in header tank tested OK	152214
216	02/22/2008	161636		152521
216	02/22/2008	158841	Replaced	152020
216	02/20/2008	161461	Replaced	152020
216	02/20/2008	161506	Replaced	152020
216	02/20/2008	161506	Replaced	152020
216	02/20/2008	161506	Replaced	152020
216	02/20/2008	161506	A Service	151707
216	02/20/2008	161425	Tension Wheel Nuts To OEM Specification	151707
216	02/20/2008	161425	A Service	151707
216	02/20/2008	161425	Creditor #:BEA001 BEAUREPAIRES P/O #:G52079 Receiving #:47225 Date :2008-02-18 POS4	151300
216	02/18/2008	158333		146113
216	01/26/2008	159615		146113
216	01/26/2008	159615	Replace belt	146113
216	01/26/2008	159615	C/O bus return to depot and replace both alternator belts	146113
216	01/26/2008	159615	Checked ok	146113
216	01/26/2008	159615	Carry out random audit	146113
216	01/26/2008	159653	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G52504 Receiving #:46587 Date :2008-01-25 Replace side window	146113
216	01/25/2008	159604	Replaced by Elite	146113
216	01/25/2008	159469	Creditor #:BEA001 BEAUREPAIRES P/O #:G52166 Receiving #:46557 Date :2008-01-24 POS4	146113
216	01/25/2008	159469	Rep. globe	145264
216	01/25/2008	159574		145264
216	01/25/2008	159469	Completed by Thermoking	144458
216	01/24/2008	158595		144458
216	01/21/2008	159135	Fitted	144458
216	01/20/2008	159135	rep. tyre pos. 4 Flat	143846
216	01/20/2008	159135	Checked refrigerant levels low discharge vibra sorber is oily and has hyper extended leak check all main joints couldn't raise a leak	143846
216	01/16/2008	158841	Rep. tyre pos.4	143315
216	01/16/2008	158850	rep. tyre pos 4 - Worn	142760
216	01/16/2008	158850	Replaced	142617
216	01/16/2008	158850	Replaced	142617
216	01/16/2008	158850	A Service	142617
216	01/16/2008	158850	Tension Wheel Nuts To OEM Specification	142617
216	01/16/2008	158850	A Service	141790
216	01/16/2008	158850	Checked Ok	138037
216	01/16/2008	158850	Checked all OK	137272
216	01/16/2008	158850		137085
216	01/16/2008	158850	rep. alt. belt	136061
216	01/16/2008	158850	Adjusted OK	136061
216	01/16/2008	158850		135153
216	01/16/2008	158850	Replaced sun blind	134922
216	01/16/2008	158850		133500
216	01/16/2008	158850	Replace belt	133500
216	01/16/2008	158850	D-Service	133500
216	01/16/2008	158850		133500
216	01/16/2008	158850	Tension Wheel Nuts to Spec	133500
216	01/16/2008	158850	A Service	133500
216	01/16/2008	158850	D-Service	133500
216	01/16/2008	158850	Tension Wheel Nuts To OEM Specification	133500
216	01/16/2008	158850	A Service	133500
216	01/16/2008	158850	Replaced broom	132292
216	01/16/2008	158850		128814
216	01/16/2008	158850	Fitted new blade	128814
216	01/16/2008	158850	C/O bus 217. Repaired & replaced	128814
216	01/16/2008	158850	Reploaced windscreen rubber	128593
216	01/16/2008	158850		128593
216	01/16/2008	158850	Tension Wheel Nuts To OEM Specification	128258
216	01/16/2008	158850	A Service	128258
216	01/16/2008	158850	Creditor #:BEA001 BEAUREPAIRES P/O #:G49362 Receiving #:44480 Date :2007-10-24	124908
216	01/16/2008	158850	Repaired by Volgren	124664
216	01/16/2008	158850	Road tested no code up	124664
216	01/16/2008	158850		121191
216	01/16/2008	158850	Repaired by Whitehorse	121191
216	01/16/2008	158850	Replaced all brake pads	121191
216	01/16/2008	158850		121191
216	01/16/2008	158850	Replaced all brake pads	121191
216	01/16/2008	158850	Replaced tyre 5 & 6 - worn	120057
216	01/16/2008	158850	ZF Transmission Filter	119867
216	01/16/2008	158850	ZF Ecofluid A Plus Synthetic Transmission Oil	119867
216	01/16/2008	158850	Service T - Replace Transmission Oil & Filter	119867
216	01/16/2008	158850	Tension Wheel Nuts To OEM Specification	119867
216	01/16/2008	158850	A Service	119867
216	01/16/2008	158850	ZF Transmission Filter	119242
216	01/16/2008	158850	ZF Ecofluid A Plus Synthetic Transmission Oil	119242
216	01/16/2008	158850	Service T - Replace Transmission Oil & Filter	119242
216	01/16/2008	158850	Tension Wheel Nuts To OEM Specification	119242
216	01/16/2008	158850	A Service	119242
216	01/16/2008	158850	CHECKED O/K	114999
216	01/16/2008	158850		115118
216	01/16/2008	158850	REPLACED ALTERNATOR BELT.	115118
216	01/16/2008	158850	Creditor #:ROA001 Road Safety Inspections P/O #:G48137 Receiving #:43232 Date :2007-08-30	114404
216	01/16/2008	158850	Secured pivot and replaced locknut	113288
216	01/16/2008	158850	Repaired	113288
216	01/16/2008	158850	Annual Inspection - BC 111610	112408
216	01/16/2008	158850	Checked out driver blind	113288
216	01/16/2008	158850	Checked for leak ok	113113
216	01/16/2008	158850	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G47731 Receiving #:42899 Date :2007-08-17 216	110931

216	08/15/2007	146705	Replace emergency exit push button under B/Bar			110558
216	08/15/2007	146705	Repair and paint front bumper bar	Painted		110644
216	08/15/2007	146705	Repair and paint front bumper bar	Repaired		110558
216	08/14/2007	146705	Polish exterior panels/headers & touch up paint work			110558
216	08/14/2007	146705	Paint rear bumper bar			110558
216	08/14/2007	146705	O/S/F wheel brush missing			110558
216	08/14/2007	146705	Secure all lower skit panels			110478
216	08/14/2007	146705	Clean air condition filter secure vents			110478
216	08/14/2007	146705	Replace emergency exit push button under panel			110478
216	08/14/2007	146705	Paint exterior mirrors and arms			110478
216	08/14/2007	146705	Drivers window sliders catches - replace			110478
216	08/14/2007	146705	Replace O/S No 6 panel & paint & decals	Paint panels as required		110558
216	08/14/2007	146705	Replace rear door pillar rubber			110558
216	08/14/2007	146705	STEEL CLAW CATCHES			110558
216	08/14/2007	146705	2MM X 1200MM X 2400MM FLAT ALUMINIUM			110558
216	08/14/2007	146705	Replace O/S No 6 panel & paint & decals	Paint panels as required		110478
216	08/14/2007	146705	N/S/R panel damage & O/S middle panel damage & O/S/R panel			110478
216	08/13/2007	146567	Front saloon heater leaking again	Checked OK		110478
216	08/13/2007	146567	Steam clean for inspection	CLEANED CHASSIS		110478
216	08/13/2007	146705	Paint wheels			110478
216	08/13/2007	146705	Paint wheels			110478
216	08/13/2007	146705	Repair No 7 panels O/S 8-9 & paint			110478
216	08/10/2007	146567	Power steering line leaking oil between fuel tank & air tank	SECURED & TIGHTENED HOSE O/K.		110478
216	08/10/2007	146567	Power steering line leaking oil between fuel tank & air tank	CHECKED O/K.		110478
216	08/10/2007	146567	A/C BELT 0500 BENZ			110478
216	08/10/2007	146567	Water pump belt cracked.	REPLACED		110478
216	08/10/2007	146567	Secure air conditioning hose behind power steering filter.	SECURED		110478
216	08/10/2007	146567	Front saloon heater leaking again	NO LEAKS FOUND		110478
216	08/10/2007	146567	inter cooler hose under bus damaged.	CHECKED O/K.		110478
216	08/10/2007	146567	Secure oil filler hose away from bolt on to engine.	SECURED		110478
216	08/10/2007	146567	N/S interior led light not working	REPLACEDCOMPLETE UNIT		110478
216	08/10/2007	146567	Alternator belt needs adjusting.	ADJUSTED		110478
216	08/10/2007	146567	N/S interior led light not working	REPLACEDCOMPLETE UNIT		110478
216	08/10/2007	146587	Paint till stand	REPAINTED TILL TRAY		110478
216	08/10/2007	146587	Secure replace repair drivers blind - 1 fit cord	REPAIRED		110478
216	08/10/2007	146587	wheel chair ramp -clean	CLEANED & CHECKED		110478
216	08/10/2007	146587	Clean graffiti - walls	CLEANED OFF GRAFFITTI		110478
216	08/10/2007	146587	N/S/R panel damage	POLISHED & TOUCHED UP		110478
216	08/10/2007	146587	Refit gutter rubber above rear door	REFITTED GUTTER		110478
216	08/10/2007	146587	Repair N/S/R wheel arch panel	POLISHED & TOUCHED UP		110478
216	08/09/2007	146416	Power steering line leaking oil between fuel tank & air tank			110017
216	08/06/2007	146217	Service	Replace air dryer cannister		109767
216	08/06/2007	146217	AIR DRYER CANISTER MAN NL202+VOLVO			109592
216	08/06/2007	146217	POWER STEER FILTER B10M			109592
216	08/06/2007	146217	FUEL FILTER MERC 0500LE			109592
216	08/06/2007	146217	FUEL FILTER 0500LE			109592
216	08/06/2007	146217	Service	Rsi inspection.		109767
216	08/06/2007	146217	Service	Changed fuel/water filter		109767
216	08/06/2007	146217	Service	Change fuel filter.		109767
216	08/06/2007	146217	Service	Changed power steering filter.		109767
216	08/06/2007	146217	Service	Changed diff oil.		109767
216	08/06/2007	145856	POS 3+4	Creditor #:BEA001 BEAUREPAIRES P/O #:G47274 Receiving #:42640 Date :2007-08-06		109592
216	08/01/2007	145787	Annual body check	Completed		108040
216	08/01/2007	145813	Replace N/S/R tyres	Replaced		108040
216	08/01/2007	145856	TYRES POS 3+4 BALD	Replaced		108040
216	08/01/2007	145813	Replace N/S/R tyres	Replaced		108040
216	08/01/2007	145813	Front visor keeps slipping up - catch is U.S	Unable to locate fault		108040
216	08/01/2007	145785		Tension Wheel Nuts To OEM Specification		108040
216	08/01/2007	145785		A Service		108040
216	08/01/2007	145785		A Service		108040
216	07/26/2007	145400	Vibration of the front end mainly between 0 - 50 KPH worst	Replaced N/S/F tyre & r/tested		106362
216	07/24/2007	114967	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:32648 Receiving #:42287 Date :2007-07-24 Code FR1125		105316
216	07/17/2007	144350	Constant rattle from A/C unit	Remove replace centre right evap fan SSTK warranty		102882
216	07/13/2007	144350	Constant rattle from A/C unit	Remove lid disconnect centre right evap fan found bush was worn away.SSTK will be out Monday to replace fan		102882
216	07/13/2007	144349	Windcreen sun blind wont hold on	Repaired		102882
216	07/13/2007	144349	Check front wheel rims	Checked		102882
216	06/25/2007	143100	Drv entered - Vandalism Graffiti	Cleaned		97447
216	06/25/2007	142929		A Service		97447
216	06/25/2007	142929		Tension Wheel Nuts To OEM Specification		97447
216	06/25/2007	142929		A Service		97678
216	06/11/2007	141864	REPLACE BROOM	rep. broom		93462
216	06/11/2007	141864	Brake warning light stays on.	R/Tested all o/k.		93462
216	06/06/2007	140829	POS 4	Creditor #:BEA001 BEAUREPAIRES P/O #:G44428 Receiving #:41213 Date :2007-06-06 11R FRONT PATTERN NEW		91932
216	06/04/2007	141382	O/S headlight not working	Replaced		91443
216	06/04/2007	141382	GLOBE HIGH BEAM			91443
216	05/29/2007	140829	POS 4 tyre flat	Replaced No 4 tyre and torqued w/nuts		90319
216	05/22/2007	140471	Replace N/S headlight globe	Replaced		88552
216	05/22/2007	140398		D-Service		88552
216	05/22/2007	140398		A Service		88552
216	05/22/2007	140398		Tension Wheel Nuts to Spec		88552
216	05/22/2007	140398	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL			88552
216	05/22/2007	140398	OIL FILTER 1725+0500LE			88552
216	05/22/2007	140398	AIR FILTER MERC 0500LE			88552
216	05/22/2007	140398	GLOBE HIGH BEAM			88552
216	05/22/2007	140398	WEDGE GLOBE INSTRUMENT 24V 3W			88633
216	05/22/2007	140398		A Service		88552
216	05/22/2007	140398		Tension Wheel Nuts To OEM Specification		88552
216	05/18/2007	140166	2 way radio not working	Checked working OK		87476
216	05/17/2007	140010	Service			87087
216	05/17/2007	140010	MIRROR TOP BRAZILLIAN GLASS			87476
216	05/17/2007	140010	CONVEX MIRROR			87476
216	05/16/2007	139935	1175X1470 GREY TINT	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G43720 Receiving #:40722 Date :2007-05-16 216		87068
216	05/16/2007	139935	Broken side window behind rear door on n/s/r.	Replaced by Elite		87068

216	05/04/2007	139109	L H mirror bent	Replace mirror	86143
216	04/30/2007	138356	Braided hose f/filter to top rail leaking	Replaced	85191
216	04/30/2007	138356	Steamclean back of engine	Cleaned	84952
216	04/30/2007	138356	Repair indicator	Replaced	84952
216	04/27/2007	138356	A0004761075 FUEL BRAIDED HOSE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G43094 Receiving #:40173 Date :2007-04-27 216	84479
216	04/27/2007	137373	POS 5+6	Creditor #::BEA001 BEAUREPAIRES P/O #:G41947 Receiving #:40204 Date :2007-04-27	84479
216	04/26/2007	138356	Braided hose f/filter to top rail leaking	Removed hose and taking to w/horse ordered parts	84209
216	04/24/2007	138302	MERC ALTERNATOR BELT TOP 0500LE		84209
216	04/24/2007	138302	Red & amber oil lights coming on	Drain excess oil from engine & r/tested	83969
216	04/24/2007	138302	Alternator belts	Replaced top A/C belt.	83969
216	04/20/2007	138077	Breakdown - Oil warning light on - Nunnawading Stn.Left at	c/o. bus & returned to depot & checked oil levels all is o/k. No faults coming up.	82728
216	04/12/2007	137373	REPLACED TYRES POS. 5 & 6 - WORN.	Replaced	80892
216	04/12/2007	137485	Replace mirror	Replaced	80892
216	04/12/2007	137485	BRAZILLIAN MIRROR L/H		81131
216	04/12/2007	137520	N/S mirror damaged Hampton Stn.	Was sent to Highett first & waited for bus. Was told bus at Hampton. Go to Hampton & replace N/S mirror.	80892
216	04/12/2007	137520	MIRROR METAGAL L/H		81131
216	04/11/2007	137387	Replace 2 rear tyres	Replaced	80736
216	04/11/2007	137326	Annual random audit	Completed	80736
216	04/11/2007	137327		A Service	80736
216	04/11/2007	137327		Tension Wheel Nuts To OEM Specification	80736
216	04/04/2007	136864	Stop light and park warning alerts showing on dash when bra	Waranty job done by White horse	80598
216	04/02/2007	136735	Air conditioner not working.	Repaired by Volgren	80433
216	04/02/2007	136735	Air conditioner not working.	Solidenid burnt out	80433
216	03/22/2007	135974	Park brake light comes on sometimes when brakes are applied	Road tested checked park brake light	77926
216	03/15/2007	135288		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	76447
216	03/15/2007	135288		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	76447
216	03/15/2007	135288		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	76447
216	03/15/2007	135288		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	76447
216	03/15/2007	135288		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	76447
216	03/15/2007	135288		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	76447
216	03/15/2007	135288		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	76447
216	03/15/2007	135288		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	76447
216	03/15/2007	135288		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	76447
216	03/15/2007	135288	5AMP BLADE FUSE		76447
216	03/15/2007	135288	Service as per list	Adjusted clutch repaired a short on clutch electrics traced a fault with the unloader & fixed a refrigerant leak in the trans	76447
216	03/15/2007	135288		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	76447
216	03/15/2007	135288		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	76622
216	03/15/2007	135288	FILTER DRIER THERMO KING		76622
216	03/15/2007	135288	AIR CON REFRIDGERANT		75646
216	03/13/2007	135049	Replace top alternator bolts x3 realign belt and tension	Replaced	75230
216	03/07/2007	134806	Arm on mirror bent	Straightened	73390
216	02/27/2007	133423	POS 4+6	Creditor #::BEA001 BEAUREPAIRES P/O #:G39569 Receiving #:38585 Date :2007-02-27	73390
216	02/27/2007	132950	POS 3	Creditor #::BEA001 BEAUREPAIRES P/O #:G39296 Receiving #:38588 Date :2007-02-27	71678
216	02/20/2007	133423	Replaced tyre pos. 4 & 6 bald.	Replaced	71483
216	02/19/2007	133453	Change tyres O/S/N/S inner tyres	Changed	71678
216	02/19/2007	133350	Air conditioner not working.	Checked OK	71483
216	02/19/2007	133350	Air conditioner not working.	Cleaned A/C return air filter & tested (not very cold)	71483
216	02/19/2007	133381	Annual random audit	Completed	71483
216	02/19/2007	130366	BOTTOM ALT ADJUSTER	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:37263 Receiving #:38444 Date :2007-02-19	71483
216	02/19/2007	133380		A Service	71483
216	02/19/2007	133380		A Service	71483
216	02/19/2007	133380		Tension Wheel Nuts To OEM Specification	70950
216	02/16/2007	133218	MERC ALTERNATOR BELT TOP 0500LE		70950
216	02/16/2007	133218	Replace top alternator belt	Replaced	70373
216	02/14/2007	133007	Replace N/S/R outer tyre	Replaced	70077
216	02/14/2007	133007	Replace N/S/R outer tyre	Replaced	70077
216	02/14/2007	132950	TYRE POS 3 WALL DAMAGE	Replaced	65873
216	01/26/2007	131614	WEDGE GLOBE INSTRUMENT 24V 3W		65625
216	01/26/2007	131614	R/H/F lower park light	Replace globe	63569
216	01/18/2007	130599	FRONT BUMPER	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #:G37936 Receiving #:37810 Date :2007-01-18	62670
216	01/15/2007	130599	Accident damaged - Replace complete front bumper bar & rep	Refit bumper bar	62892
216	01/15/2007	130599	Accident damaged - Replace complete front bumper bar & rep	Paint bumper yellow	62670
216	01/12/2007	130691	Drv entered - Vandalism Graffiti	Checked OK	62670
216	01/12/2007	130645	Annual random audit.	Completed	62670
216	01/12/2007	130691	Fuel flexi pipe leaking	Tightened up	62670
216	01/12/2007	130599	Accident damaged - Replace complete front bumper bar & rep	repaired bumper irons & prepared new bumper bar for fitting up.	62670
216	01/11/2007	130644	Accident Damaged - Centre Dandy Rd Dingley - OUT 12.00pm BA	C/O bus 34. Returned to depot for repairs	62141
216	01/09/2007	130366	Secure alternator bracket	Secured	62141
216	01/09/2007	130344		Tension Wheel Nuts To OEM Specification	62141
216	01/09/2007	130344		A Service	62141
216	01/09/2007	130344		A Service	62141
216	12/16/2006	128936	Stop light on dash on with code FR1125	Replace a/c alternator belt and adjuster	56240
216	12/16/2006	128936	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		56240
216	12/16/2006	128936	A/C BELT 0500 BENZ		56240
216	12/08/2006	116062	DECALS 2 PANELS	Creditor #::ATT001 ATTITUDE SIGNS P/O #:33198 Receiving #:36896 Date :2006-12-08	54527
216	12/06/2006	128184	Air hose split under drivers seat.	Repaired air supply line on drivers seat	54129
216	12/05/2006	128108	Check for fault in indicators	Replaced indicator relay & tested (EX43)	53837
216	12/05/2006	128108	Check for fault in indicators	Replaced flasher relay checked. working properly	53837
216	12/05/2006	128108	RELAY 24V MERC 0500LE INDICATORS		54129
216	12/04/2006	128019	Replace alternator belt	Replaced	53665
216	12/04/2006	128019	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		53837
216	11/30/2006	127645	Replace top alternator belt	Replaced	52919
216	11/30/2006	127645	MERC ALTERNATOR BELT TOP 0500LE		52919
216	11/30/2006	127645	Replace air supply decal	Replaced	52919
216	11/30/2006	127645	Replace air supply decal		52919
216	11/30/2006	127603		Tension Wheel Nuts To OEM Specification	52919
216	11/30/2006	127603		A Service	52919
216	11/30/2006	127603		A Service	52919
216	11/20/2006	126673			52655
216	11/20/2006	126673	Accident damage No 12271 - Repair & repaint n/s lower panel	Repaired by Volgren	52655
216	11/14/2006	126153		Tension Wheel Nuts To OEM Specification	52655
216	11/14/2006	126153		A Service	52655
216	11/13/2006	126146	Breakdown - Fountain Gate Shopping Centre - OUT 2.30pm BACK	C/O bus 202 returned to depot. L/H panels & smashed windows	52655

216	10/26/2006	124852	LED CLEARANCE LIGHT (RED AMBER)		49042
216	10/26/2006	124852	Drv entered - Elec & Light Stop lights	Replaced N/S/R clearance light (A/D)	49042
216	10/26/2006	124852	Drv entered - Elec & Light Stop lights	Replaced N/S/R clearance light (A/D)	49042
216	10/24/2006	124590	Disarm front door interlock	Repaired by Volgren	48429
216	10/18/2006	124153	Replace N/S/R clearance lamp	Replaced	47059
216	10/18/2006	124153	LED CLEARANCE LIGHT (RED AMBER)		47059
216	10/04/2006	123191	Fit alternator air hose		43639
216	10/04/2006	123110	CLEANED AIR FILTER MERC 0500LE	Fitted	43639
216	10/04/2006	123110	FUEL FILTER 0500LE		43639
216	10/04/2006	123110		D-Service	43639
216	10/04/2006	123110		A Service	43639
216	10/04/2006	123110		Tension Wheel Nuts to Spec	43639
216	10/04/2006	123110	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		43639
216	10/04/2006	123110	OIL FILTER 1725+0500LE		43639
216	10/04/2006	123110		A Service	43639
216	10/04/2006	123110		Tension Wheel Nuts To OEM Specification	43639
216	10/03/2006	122989	Air leaks - driver seat	Repaired broken hose	43437
216	09/30/2006	122860	Drv entered - Elec & Light Stop lights	Checked ok	42593
216	09/27/2006	122638	Repair O/S splash guard & fit new mud flap	Repaired and fitted new mud flap	41990
216	09/27/2006	122638	MUD FLAPS GRENDAS MF60X30GRE RED		41990
216	09/06/2006	121145	Fault codes - comes up INS 0508	Completed	37660
216	09/04/2006	120080	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #:34335 Receiving #:34602 Date :2006-09-04	37099
216	08/29/2006	120514	Rectify all fuel and air lines fouling at fuel tank	Repaired by Whitehorse	36438
216	08/29/2006	120514	Correctly fit fuel tank brackets	Repaired by Whitehorse	36438
216	08/29/2006	120514	Rectify fuel tank balance pipe fouling on chassis cross me	Repaired by Whitehorse	36438
216	08/27/2006	120080	Annual Inspection - DN 099284	Annual Inspection - DN 099284	35797
216	08/25/2006	120319	Replace licence to carry (No) seat (No) adult passengers	Replace	36438
216	08/25/2006	120319	Secure all lower skit panels	Secure panels	36438
216	08/25/2006	120319	Clean air condition filter secure vents	Cleaned	36438
216	08/25/2006	120319	Paint till stand	Painted	36438
216	08/25/2006	120319	R/H/R mud flap broken	Repaired	36438
216	08/25/2006	120319	Clean graffiti- seats side walls	Cleaned	36438
216	08/25/2006	120319	Polish and touch up all exterior panel/headers	Polished	36438
216	08/25/2006	120319	MUD FLAPS GRENDAS MF60X30GRE RED		36438
216	08/25/2006	120319	6-8 panels O/S repair	Polished	36438
216	08/25/2006	120319	N/S No6+7 repair	Polished & touched up	36438
216	08/25/2006	120319	N/S No 4 panel repair & paint & decal	Polished & touched up	36438
216	08/25/2006	120371		Tension Wheel Nuts To OEM Specification	36438
216	08/25/2006	120371	AIR FILTER MERC 0500LE		36438
216	08/25/2006	120371		A Service	36438
216	08/23/2006	119609	POS 3+4+5+6	Creditor #::BEA001 BEAUREPAIRES P/O #:34338 Date :2006-08-23	36042
216	08/16/2006	119062	Service		34803
216	08/16/2006	119062	Service		34803
216	08/16/2006	119638	Replace all rear tyres	Replaced and painted wheels	34742
216	08/16/2006	119638	Replace all rear tyres	Replaced and painted wheels	34742
216	08/16/2006	119609	Replace pos 3456 tyre - bald	Replaced by Beaufepairs	34742
216	08/16/2006	119638	Oil leak on power steering pipe connection	Retightened	34742
216	08/16/2006	119638	S/Clean all bus	Cleaned	34742
216	08/16/2006	119638	S/Clean all bus	Cleaned	34742
216	08/16/2006	119638	Graffiti on rear passenger seat	Cleaned	34742
216	08/11/2006	119307	Annual body check	Carry out body check	34087
216	08/07/2006	118852	Replace fuel tank - Warranty		34087
216	07/10/2006	116837	Engine cut off switch under rear door slipped out onto grou	Checked switch working O.K it's not loose	28153
216	07/07/2006	116062	Door seal	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #:33013 Receiving #:33212 Date :2006-07-07	28153
216	07/03/2006	116241	TEXAMATIC 1888	Transmission Oil	27183
216	07/03/2006	116241	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	27183
216	07/03/2006	116241		Service T - Replace Transmission Oil & Filter	27183
216	07/03/2006	116241		A Service	27183
216	07/03/2006	116241		A Service	27183
216	07/03/2006	116241		Tension Wheel Nuts To OEM Specification	27183
216	06/30/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Fit wheel arch brush and rear door seal	27183
216	06/29/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Paint panels	27183
216	06/29/2006	116062	SCREW TORX 8 X 15MM SIDE PANEL		27183
216	06/29/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Fit panels	27183
216	06/28/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Manfature panels and frames	27183
216	06/28/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Manfature panels and frames	27183
216	06/27/2006	116062	3MM X 1200MM X 2400MM FLAT ALUMINIUM		27183
216	06/27/2006	116062	Accident damage no 11575 - Replace rear door seal(rear)bat	Remove panels and clean up	27183
216	06/13/2006	114967	Red light on dash -Battery light on	Repaired by Whitehorse	24997
216	05/25/2006	113761	Service		22201
216	05/25/2006	113761	CONVEX MIRROR		22201
216	05/25/2006	113761	MOUNTING CONVEX MIRROR		22201
216	05/11/2006	112766	Annual random audit	AUDIT COMPLETED	19506
216	05/11/2006	112767		Tension Wheel Nuts To OEM Specification	19506
216	05/11/2006	112767		A Service	19506
216	05/11/2006	112767		A Service	19506
216	05/03/2006	112090	Reversing buzzer not working.	Replace reversing buzzer	17561
216	05/03/2006	112090	24V REV BUZZER		17561
216	04/27/2006	111697	BRAZILLIAN MIRROR L/H		16384
216	04/27/2006	111697	N/S. Rear vision mirror cracked	Fit n/s front mirror	16384
216	04/10/2006	110774	LED CLEARANCE LIGHT (RED AMBER)		12526
216	04/10/2006	110774	Accident damage n/s/r. corner - replace clearance light.	rep. n/s/r. clearance light.	12526
216	04/08/2006	110671	Loud noise coming from behind driver.	drivers microphone was switched on.	12526
216	03/30/2006	109583	1st warranty service	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:30852 Receiving #:31059 Date :2006-03-30	10594
216	03/29/2006	109946		Tension Wheel Nuts To OEM Specification	10269
216	03/29/2006	109946		A Service	10269
216	03/24/2006	109583	Warranty service - 5000kms	Serviced by Whitehorse Trucks	10027
216	03/24/2006	109539	FAN BELT AIR/CON ARTIC		10027
216	03/24/2006	109539	Service	rep. alt. belt	10027
216	03/23/2006	109539	A/C u/s	Removed belt none in stock	10027
216	03/23/2006	109589	Replaced gear selector buttons.	rep. selector button unit	10027
216	03/07/2006	108438	Air leak	Check for air leak - no leak but found fuel leak and alternator belt need tobe replaced [under warranty job]	6854
216	02/28/2006	107900	Made covers for retader and door over ride switch	Made covers for retader and door over ride switch	4683

216	02/21/2006	107373	Front parker near side U/S	REP. GLOBE	2991
216	02/21/2006	107373	WEDGE GLOBE INSTRUMENT 24V 3W		2991
216	02/21/2006	107373	CHECK FOR WARNING LIGHT DEFECT	LOCATED FAULT- SWITCH WAS IN WRONG POSITION FOR RETARDER.	2991
216	02/21/2006	107373	OUT SIDE DOOR SWITCHES U/S.	NO FAULT	2991
216	02/16/2006	107117	Breakdown Gladston rd.Dandy Nth. Front doors wont close. Le	c/o. bus returned to depot & adjusted front door sensitive edge.	2211
216	02/14/2006	106918	A/C fan very low	rep. under warranty - s.s thermo king	1813
216	02/09/2006	105810	Replace rear tyres with recaps	Creditor #:BEA001 BEAUREPAIRES P/O #:29656 Receiving #:29961 Date :2006-02-09	894
216	02/06/2006	106360	fit notice holder	fit holder	392
216	02/02/2006	106102	Annual Inspection - BC 081820 - New Registration	New Registration	392
216	02/01/2006	105892	POWDER COATED NOTICE BOARDS		0
216	02/01/2006	105892	Fit decalsemergency radio bottoms	Check for details of chassis	0
216	02/01/2006	105892	Fit decalsemergency radio bottoms	Fit decalstill pin and time table holder and two way radio emergency buttom	0
216	02/01/2006	105892	32MM LOOSE WHEEL NUT INDICATOR		0
216	01/31/2006	105892	FUSE BLADE 10AMP		0
216	01/31/2006	105892	Fit decalsemergency radio bottoms	Fit decalstill pin and time table holder	0
216	01/31/2006	105892	DO NOT OVERTAKE TURNING DECAL		0
216	01/31/2006	105892	GIVE WAY SIGN (SMALL)		0
216	01/31/2006	105892	SWITCH-SOLENOID STARTER		0
216	01/31/2006	105892	TWIN TIME TABLE HOLDER		0
216	01/31/2006	105892	BROOM HANDLE (8232715)		0
216	01/31/2006	105892	BROOM HEAD (09803211)		0
216	01/31/2006	105892	SAFETY TRIANGLE DECAL		0
216	01/30/2006	105810	Service	Pick up bus	0
216	01/30/2006	105810	Replace rear tyres x 4		0