

Veh#	Date	W/O#	Description	Notes	Odometer
217	09/16/2026	1370417	Mechanic entered - Elec and Light Other	Went to bus to check if the e tag was there could see it on the top so opened up the frame above the drivers head and checked and found only the bracket for the E tag. Let Dulkieth know its already been taken out as it wasnt in the bus and secured everything. Completed	1551869
217	07/16/2026	1355042	Mechanic entered - Body Drivers Seat Controls DRIVER SEAT N	REPLACED DRIVER SEAT WITH THE OLD SEAT	1551869
217	05/29/2026	1343277	oil leak at engine	Bus will be decommission.	1551869
217	05/25/2026	1343277	oil leak at engine	Oil leak from engine sump need new sump gasket. Cleaned with brake clean found still wet at sump.	1551869
217	05/21/2026	1342486	Torn n/s disabled seat torn	replaced n/s disabled seat cover as it was torn.	1551869
217	05/21/2026	1342486	SEAT CUSH SUPER SLIM SGL CVR - CL		1551869
217	05/21/2026	1342370	advertisement company require this bus.	Done.	1551869
217	05/21/2026	1342486		replaced n/s disabled seat cover as it was torn.	1551869
217	05/21/2026	1342486	Consumables		1551869
217	05/21/2026	1342370	Consumables		1551869
217	05/20/2026	1342138	Mechanic entered - Engine Will Not Start in Neutral	drive to Hasting jump start the bus live it running hazard light on contact Paul Taylor to aware	1551869
217	04/15/2026	1269002	LED FRONT POSITION MARKER LIGH	Creditor #PP-MUL001 MULTISPARES LTD P/O #PP407567 Receiving #435700 Date :2026-04-30	1551869
217	04/15/2026	1269002	Consumables		1551869
217	03/22/2026	1326548		FIRE EXTINGUISHER TEST & TAG completed by ATS 15.02.26	1551825
217	03/02/2026	1323293	DIRECT PURCHASE - BUS INSPECTI	Creditor #PP-ROASAF ROAD SAFETY INSPECTIONS P/O #PP405533 Receiving #431360 Date :2026-03-03 217 ASI complete	1551825
217	02/26/2026	1323293		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1551825
217	02/26/2026	1323293		VEHICLE SAFETY INSPECTION	1551825
217	02/26/2026	1323293		Assisting	1551825
217	02/26/2026	1323293		ANNUAL SAFETY INSPECTION SERIAL #RSI 070457 ____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1551825
217	02/26/2026	1323217		CARRY OUT COMPLETE VEHICLE UNDER CARRIAGE WASH complete under vehicle wash	1551825
217	02/25/2026	1322914	Consumables		1551825
217	02/25/2026	1322914	Mechanic entered - Elec and Light Reverse Buzzer	replaced faulty reverse buzzer. tested all ok	1551825
217	02/25/2026	1322914	BUZZER REVERSING 24V 1020B NR72602		1551825
217	02/24/2026	1322559		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	1551825
217	02/24/2026	1322559		VEHICLE SAFETY INSPECTION complete	1551825
217	02/24/2026	1322599	Consumables		1551825
217	02/24/2026	1322599	Mechanic entered - Body Other air leaks in front of diff an	Replace oring (under bus) 8 port block air line connection and 3 air tank drain tap p/n 49G7901	1551825
217	02/12/2026	1330241	Consumables		1551686
217	02/12/2026	1320240	Consumables		1551686
217	02/12/2026	1320239	Consumables		1551686
217	02/12/2026	1320171	Consumables		1551686
217	02/12/2026	1320239	Mechanic entered - Body Other rear n/s panel damaged and not	fitted catch tested and all good	1551686
217	02/12/2026	1320171	CLAW CATCH & ANGLE		1551686
217	02/12/2026	1320171	Mechanic entered - Body Other n/s/r side hatch claw missing	fitted new claw and catch tested and all good- roman	1551686
217	02/12/2026	1320241	Mechanic entered - Body Other fold down disable seat not sta	fixed	1551686
217	02/12/2026	1320240	Mechanic entered - Body Other o/s disabled seats wont hold u	tighten hinges for seats tested and all good (duplicate)	1551686
217	02/12/2026	1320173	O-RING KIT LARGE VOSS A6739970145		1551686
217	02/12/2026	1320173	Mechanic entered - Air System Air_Leak Rear air leak near th	replaced all the o rings on the air tank fittings tested and all good -roman	1551686
217	02/11/2026	1319926	Mechanic entered - Wipers and Washers Other wiper blades req	refit wiper blades and check operation	1551686
217	02/11/2026	1319926	Consumables		1551686
217	02/11/2026	1319926	Mechanic entered - Driver Tablet Not Charging	replaced charging cable and usb converter. (second hand converter used) tested all charging well	1551686
217	02/11/2026	1319926	Consumables		1551686
217	02/11/2026	1319926	Mechanic entered - Body Other bulk head behind destos needs s	removed bulk head panel. re thread mounting holes refit panel	1551686
217	02/11/2026	1319926	Mechanic entered - Body Other drivers blind damaged	repair front drivers blind	1551686
217	02/10/2026	1319583		PRE ANNUAL SAFETY INSPECTION CHECK complete	1551686
217	02/10/2026	1319583		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST complete	1551686
217	02/10/2026	1319566	Consumables		1551686
217	02/10/2026	1319566	Mechanic entered - Elec and Light Other air gauge 2 not work	checked the system hanting the second pressure sender can't find it. need more information.	1551686
217	02/10/2026	1319566	Mechanic entered - Elec and Light Other alternator warning l	checked the system repair the connections.	1551686
217	02/10/2026	1319661	Consumables		1551752
217	02/10/2026	1319661	DIRECT PURCHASE - GLASS		1551752
217	02/10/2026	1319661	Mechanic entered - Body Other some side windows require re	Creditor #PP-NAT002 NATIONAL WINDSCREENS P/O #PP404402 Receiving #429795 Date :2026-02-11 Reseal four windows glasses bus 217	1551686
217	02/10/2026	1319661	Mechanic entered - Body Other some side windows require re	Assisting four windows been reseal by national windscreen	1551686
217	02/10/2026	1319446		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safety inspection as per checklist	1551686
217	02/09/2026	1319336	Consumables		1551686
217	02/09/2026	1319336	PTI Tablet Entered -Elec and Light - Exterior Lights all ext	checked all lights. could not find fault.	1551686
217	11/25/2025	1305040	Workshop Tablet Entered -Engine - struggling to start	check bus for hard starting. found fuel leak on return pipe from injector 4. tightened pipenut. test drive fuel leak has stopped and started first kick	1550289
217	11/20/2025	1304203		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1549909
217	11/20/2025	1304203		VEHICLE SAFETY INSPECTION completed as per check list	1549909
217	11/20/2025	1303590		removed sensor on tank 2 and cleaned. tested all ok	1549909
217	11/18/2025	1303590	PTI Tablet Entered -Brakes - Warning number 2 air tank not		1549107
217	10/29/2025	1299837	Body Windows Front chip	Assisting chip repair completed	1549107
217	10/10/2025	1295762	PUMP WIPER WASHER 24 VOLT		1547926
217	10/10/2025	1295762	PTI Tablet Entered -Body - Windows Front windshield washer	replaced washer motor. has one way vales fitted. checked operation of valves all ok. topped up washer bottle all ok	1547926
217	10/01/2025	1299837	DIRECT PURCHASE - GLASS	Creditor #PP-KNID06 KNIGHTS WINDSCREEN PENINSULA P/O #PP398091 Receiving #422763 Date :2025-10-30 217 windshield chip repair	1549107
217	09/20/2025	1291708	Mechanic entered - Elec and Light Other n/s/r parker light n	replaced globe and checked ok	1547636
217	09/20/2025	1291685	Drv entered - Elec and Light Indicators Not Working/Drivers	removed old globe and found faulty fitted new one and rechecked ok	1547636
217	09/20/2025	1291686	Consumables		1547636
217	09/20/2025	1291686	Consumables		1547636
217	09/20/2025	1291686	Consumables		1547636
217	09/19/2025	1291444	Drv entered - Elec and Light Indicators Not Working/front dr	CARRY OUT A SERVICE AS PER CHECK LIST completed as per check list	1547636
217	09/17/2025	1290985	Drv entered - Brakes Warning Light On	replaced globe and checked ok	1547636
217	09/12/2025	1279701	PULLEY IDLER/ADJUSTER MERCEDES 0500LE(50N0041G)	found the only brake related warning light on dash was the one to warn driver for low air build up air pressure and warning light was gone	1547636
217	09/10/2025	1289536	Consumables	ADVISED USED NOT BOOKED	1547394
217	09/10/2025	1289536	Drv entered - Body Rear_Door Operation Faulty/Rear doors no		1547154
217	09/09/2025	1289106	Mechanic entered - Fluid Leaks Other radiator cap leaking	fix rear door	1547154
217	09/09/2025	1289106	CAP RADIATOR 70KPA MERC 0500LE A0005014615	replaced radiator cap	1547154
217	09/02/2025	1287659	Consumables		1546260
217	09/02/2025	1287658	Drv entered - Body Front_Door Operation Faulty	checked operation found a bit loose on the bottom tightened allen key bolt ok	1546260
217	09/02/2025	1287540		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service as per checklist	1546260
217	08/31/2025	1283788		Completed by ATS 06.08.25	1546260
217	08/29/2025	1286595		VEHICLE SAFETY INSPECTION completed as per check list	1546741
217	08/29/2025	1286595		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1546741
217	08/18/2025	1279452	Service	replaced indicator globe	1546260
217	08/18/2025	1279452	Consumables		1546260
217	08/05/2025	1280601	CCTV Camera Adjust Camera 5 (Rear Saloon - Incorrectly	checked the system repair the connection and adjust the camera working now	1545571
217	08/05/2025	1280601	CCTV Camera Check Camera 4 (Intermittent Video Loss Alarm	checked the system repair the connection and adjust the camera working now	1545571
217	08/01/2025	1279701	DIRECT PURCHASE - AIR CONDITIO	Creditor #PP-COLO04 COLD DRIVE PTY LTD P/O #PP392451 Receiving #416704 Date :2025-08-05 217 a/c B service	1545571
217	07/31/2025	1279701		CARRY OUT A/C - B SERVICE AS PER CHECK LIST a/c B service been completed by Jimmy	1545292
217	07/31/2025	1279701		Assisting complete	1545292
217	07/31/2025	1279701		CARRY OUT A/C - A SERVICE AS PER CHECK LIST a/c A service been completed by Jimmy	1545292
217	07/02/2025	1248041	BRAKE PADS FRT / RR MERC 0500LE E3-ES 49G7501BERAL	mech used not booked	1544692
217	06/25/2025	1272510	Drv entered - Elec and Light Exterior Lights/Left headlight	replaced headlight globe. tested all ok	1544174
217	06/25/2025	1272510	Consumables		1544174
217	06/20/2025	1243137	CLUTCH A/C FIELD THERMOKING		1544174
217	06/20/2025	1243137	FAN CONDENSOR A/C CITI-RT	Items used by contractor	1544174
217	06/12/2025	1269002	TYRE 295/80R22.5 NEW		1543408
217	06/12/2025	1269002	Consumables	mech used not booked	1543408

217	06/07/2025	1269206	Mechanic entered - Wheels and Tyres Wheel Nut Retension P1	re tensioned pos 1	1543408
217	06/07/2025	1269206	Mechanic entered - Wheels and Tyres Wheel Nut Retension P1	re tensioned pos 1	1543408
217	06/07/2025	1269206	Consumables		1543408
217	06/06/2025	1268944		VEHICLE SAFETY INSPECTION Carried out safety and wheelnut tensions as per checklist.	1543408
217	06/06/2025	1268944		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Carried out safety and wheelnut tensions as per checklist.	1543408
217	06/06/2025	1269002	Mechanic entered - Wheels and Tyres Worn Front tyre mismatch	Changed P1 tyre to correct tread pattern.	1543408
217	06/06/2025	1269006	Mechanic entered - Elec and Light Interior Lights Emergency	Fit new emergency exit light x1.	1543408
217	06/06/2025	1269006	Consumables		1543408
217	05/03/2025	1255243	LAMP LED SIDE RED/AMBER PERE1 S2-98002 85760BL		1541813
217	04/02/2025	1255243	Accident#98658 PT1 Tablet Entered -Body - Body Damage. N/S	Strightened damaged rear panel so it latches fit new side marker light.	1541395
217	04/20/2025	1259459	Apply print film	Audit 1160 Job stage 1 completed 15.04.25	1541395
217	04/15/2025	1259459	Apply print film - AUDIT 1160	Creditor #PP-GLAD10 GLASSPROTECH MELBOURNE P/O #PP385819 Receiving #409248 Date :2025-04-23	1541395
217	04/01/2025	1252139	DIRECT PURCHASE - BUS INSPECTION	PP-ROASAF REC4V 406689 14/3/25	1541256
217	03/28/2025	1255524	Drv entered - Body Drivers Seat Controls	checked drivers seat controls all working well at time of test	1541256
217	03/28/2025	1255524	Consumables		1541256
217	03/13/2025	1252139		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1539988
217	03/13/2025	1252139		VEHICLE SAFETY INSPECTION	1539988
217	03/13/2025	1252139		ANNUAL SAFETY INSPECTION SERIAL HRS1 067104_WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1539988
217	03/12/2025	1251780		CARRY OUT COMPLETE VEHICLE UNDER CARRIAGE WASH complete	1539988
217	03/08/2025	1249712		Rail	1539988
217	03/04/2025	1249998	Elec and Light WarningLight On Dash air filter restrictio	Changed air filter and exhaust brake actuator fittings was missing and not working	1540181
217	03/04/2025	1249998	FILTER AIR MERC BENZ 0500LE E3 - ES A0040941704		1540181
217	03/04/2025	1249998	SOCKET EXH BRAKE CYL MERC BENZ 0500LE A5419910022		1540181
217	03/04/2025	1249998	STUD BALL EXH BRAKE CYL MERC 0500LE		1540181
217	03/04/2025	1249999	Drv entered - Elec and Light Horn	Repaired damaged earth wire in horn circuit.	1540181
217	03/04/2025	1249997	Air System Air_Leak Front door	Repaired leaking airline at top of front door.	1540181
217	03/04/2025	1249984		CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Carried out diff service.	1540181
217	03/04/2025	1249984	OIL GEAR HP 85W-140 VALVOLUME		1540181
217	03/03/2025	1249426	Mechanic entered - Wheels and Tyres Wheel Nut Retension P 1	complete wheel nuts retension p56 to OEM spec	1539988
217	03/03/2025	1249426	Consumables		1539988
217	02/27/2025	1248938	Consumables		1539988
217	02/27/2025	1248938	Mechanic entered - Wheels and Tyres Worn p5	replaced tyre p5 with new recap and fitted p6 on p5 tensioned to spec. and booked a retension	1539988
217	02/27/2025	1248938	TYRE 295/80R22.5 RECAP		1539988
217	02/27/2025	1248041		Fit new front RH caliper + pads tensioned wheelnuts.	1539988
217	02/26/2025	1248187		PRE ANNUAL SAFETY INSPECTION CHECK completed as per check list on w/o 1247959	1539988
217	02/26/2025	1248187		CARRY OUT CCTV - 8 SERVICE AS PER CHECK LIST complete	1539988
217	02/25/2025	1247959		VEHICLE SAFETY INSPECTION completed as per check list	1539988
217	02/25/2025	1247959		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1539988
217	02/25/2025	1247958	Mechanic entered - Fluid Leaks Rear of bus oil filter return	replaced with genuine line and checked ok	1539988
217	02/25/2025	1247958	HOSE OIL RETURN FILTER HOUSING TO BLOCK A4571800920		1539988
217	02/25/2025	1248040	Fluid Leaks Rear of bus. Pinion seal leaks.	found pinion seal a bit sweaty washed and need to monitor	1539988
217	02/25/2025	1248041	Mechanic entered - Brakes Warning Light On front brake call	complete replacement both front caliper and pad	1539988
217	02/25/2025	1248041	CALIPER BRAKE OSF MERC BENZ	Creditor #PP-MULD01 MULTISPARES LTD P/O #PP382102 Receiving #405472 Date :2025-02-27	1540058
217	02/25/2025	1248041	CALIPER BRAKE FRT LH MERC B	Creditor #PP-MULD01 MULTISPARES LTD P/O #PP382102 Receiving #405472 Date :2025-02-27	1540058
217	02/22/2025	1247270	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	complete	1539750
217	02/20/2025	1246620	PT1 Tablet Entered -Body - Body coolant header tank inspec	Fit latch to hatch and removed bluetack	1539750
217	02/13/2025	1244898	Drv entered - Elec and Light AM-FM RadioMissing	fitted tested secured allogg.	1539117
217	02/13/2025	1244898	RADIO 12/24V 3' LCD MULTIMEDIA RECEIVER		1539117
217	02/13/2025	1244898	Consumables		1539117
217	02/11/2025	1244089	Drv entered - Elec and Light AM-FM Radio		1538418
217	02/11/2025	1244089	Consumables		1538418
217	02/06/2025	1243064	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	tensioned to spec	1537820
217	02/06/2025	1243064	Consumables		1537820
217	02/06/2025	1243137	A/C Heating		1537820
217	02/06/2025	1243137	A/C Heating	Assisting. All 6 evop fans replaced by Cold drive.	1537820
217	02/06/2025	1243137	FAN MOTOR A/C EVAPORATOR		1537820
217	02/06/2025	1243137	Repair AC		1539356
217	02/06/2025	1243071		Creditor #PT-COLO04 COLD DRIVE PTY LTD P/O #PE381292 Receiving #404581 Date :2025-02-14	1537820
217	02/04/2025	1242579	Fault#-39511 - Ops Entered - Fault - Breakdown Brakes - Ro	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safety inspection as per chechlist complete fire safety inspection as per checklist	1537395
217	02/04/2025	1242579	Fault#-39511 - Ops Entered - Fault - Breakdown Brakes - Ro	Assisting	1537395
217	02/04/2025	1242579	O-RING KIT LARGE VOSS A6739970145	Attended the breakdown. fitted the disconnected main input air line to the air dryer with a new horse shoe and tested. Advised Fin to remove rear wheels and check and repair rear brakes for any abnormally worn.Check the Brake rotors. both Rotors were got hot not overly burnt and still verymuch within the specs.	1537395
217	02/04/2025	1242601	Mechanic entered - Brakes Other rear break pads need changin	fit new break pads to rear all wheelnuts tensioned to spec	1537395
217	02/04/2025	1242601	BRAKE PADS FRT / RR MERC 0500LE E3-ES 49G7501BERAL		1537395
217	01/14/2025	1234692	Driver Tablet Entered -A/C Heating - Not Cooling	replaced clutch	1534045
217	01/14/2025	1234692	Driver Tablet Entered -A/C Heating - Not Cooling	Assisting	1534045
217	01/14/2025	1238552	Ops Entered - Fault - A/C Heating Not Cooling - Route: 781		1534045
217	01/14/2025	1238552	Drv entered - A/C Heating Not Cooling		1534045
217	01/14/2025	1238552	Ops Entered - Fault - A/C Heating Not Cooling - Route: 833	Checked by Cold Drive and found no signal to the clutch coil and repaired.	1534045
217	01/14/2025	1234692	DIRECT PURCHASE - AIR CONDITIO	Creditor #PT-COLO04 COLD DRIVE PTY LTD P/O #PE379468 Receiving #402988 Date :2025-01-23 217 repairs	1535811
217	01/10/2025	1234692	CLUTCH ARMATURE A/C		1534045
217	01/10/2025	1234692	PULLEY A/C		1534045
217	01/10/2025	1234692	BEARING A/C CLUTCH /YD 50MM O/D 90MM W 30MM 3210 6210 RSR	replaced broken filter housing and changed oil filter while there.	1534045
217	01/10/2025	1237996	Mechanic entered - Fluid Leaks Rear of bus oil filter housin		1534045
217	01/10/2025	1237996	FILTER OIL MERC BENZ 0500LE ES OH1830 ES A0001801709		1534045
217	01/10/2025	1237996	COVER FILTER OIL 0500Q/H161H(A0001802438)		1534045
217	01/10/2025	1238010	Driver Tablet Entered -Engine - Low Power 18 to 20 kph uphil		1534045
217	01/10/2025	1238011	Driver Tablet Entered -Warning Lights - Brakes	Tayla took it for a drive and did not find any faults.	1534045
217	01/09/2025	1237836	Driver Tablet Entered -A/C Heating - Not Cooling	Refer WOH1234692. Booked for Cold drive on14/01/2024	1534045
217	01/09/2025	1237837	Workshop Tablet Entered -A/C Heating - Not Cooling	Refer WOH 1234692. Booked for Cold drive on 14/01/2025.	1534045
217	01/08/2025	1237341	Drv entered - Brakes Foot_Brakes Pulling	Road tested. Got brakes nice and hot. No pulling when applying brakes	1533507
217	01/01/2025	1234692	AC Repairs	Creditor #PT-COLO04 COLD DRIVE PTY LTD P/O #PE378630 Receiving #401656 Date :2025-01-02	1533180
217	12/30/2024	1235981		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked and completed.	1532570
217	12/20/2024	1234836	ALTERNATOR 24V 140AMP MERC 0500LE VOLVO B128		1532444
217	12/20/2024	1234836	Replace alternator	removed old alternator and removed pulley off the old one fitted onto new alternator fitted all wires back adjusted belt tested and all good	1532444
217	12/20/2024	1234836	Consumables		1532444
217	12/20/2024	1234837		CARRY OUT A SERVICE AS PER CHECK LIST completed a services as per checklist	1532444
217	12/20/2024	1234837	Consumables		1532444
217	12/20/2024	1234837	Consumables		1532444
217	12/20/2024	1234837	Consumables		1532444
217	12/20/2024	1234837	Consumables		1532444
217	12/19/2024	1234691	PT1 Tablet Entered -Driver complaint air conditioning not w	duplicate defect	1532444
217	12/19/2024	1234691	Consumables		1532444
217	12/18/2024	1239964	AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE377073 Receiving #400868 Date :2024-12-18 DEFECT	1532444
217	12/17/2024	1234190	LAMP LED REVERSE RECTANGULAR		1532444
217	12/17/2024	1234190	Elec and Light one Reverse light missing - Not in stock.	fitted new reverse lamp. tested and secured.	1532444
217	12/17/2024	1234190	Consumables		1532444
217	12/13/2024	1233301		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed tune up service as per check list	1531950
217	12/13/2024	1233301	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221		1531950
217	12/13/2024	1233374		VEHICLE SAFETY INSPECTION completed	1531950
217	12/13/2024	1233374		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1531950

217	12/09/2024	1229964	BEARING A/C CLUTCH (D 50MM O/D 90MM W 30MM 3210 6210 RSR	booked wong # should be -ZNS	1531141
217	12/09/2024	1229964	BEARING A/C COMP CLUTCH SEALED S2102NS	correct item # used booked	1531141
217	12/04/2024	1231458	SENDER UNIT FUEL	Creditor #:PP-WH002 WHITEHORSE TRUCK CENTRE P/O #:PP377333 Receiving #:400251 Date :2024-12-11 REP KIT	1531699
217	12/04/2024	1231458	Drv entered - Dash Guages Not Working'uel guage shows empt	Changed sender but wiring not present	1530532
217	12/04/2024	1231458	Consumables		1531699
217	12/02/2024	1230670	Ops Entered - Fault - Wipers and Washers Washers Not Workin	repair wiper arm by fitting two pop rivet test found good	1530018
217	12/02/2024	1230670	Drv entered - Wipers and Washers Wipers Not WorkingDriver'	repair completed	1530018
217	11/28/2024	1230054	Driver Tablet Entered -A/C Heating - Not Cooling	duplicate defect	1529620
217	11/28/2024	1230055	Drv entered - A/C Heating Not Cooling	duplicate defect	1529620
217	11/27/2024	1229964	Ops Entered - Fault - A/C Heating Not Cooling - Route: 833	repaired by 22 celcius	1529620
217	11/27/2024	1229964	Ops Entered - Fault - A/C Heating Not Cooling - Route: 833	Assisting	1529620
217	11/27/2024	1229964	PULLEY A/C		1529620
217	11/27/2024	1229964	BEARING A/C CLUTCH (D 50MM O/D 90MM W 30MM 3210 6210 RSR		1529620
217	11/27/2024	1229964	CLUTCH ARMATURE A/C		1529620
217	11/27/2024	1229964	CLUTCH A/C FIELD THERMOKING		1529620
217	11/22/2024	1228784	PT1 Tablet Entered -Elec and Light - right hand side front h	Replace faulty globe and repair wiring	1528666
217	11/22/2024	1228784	Consumables		1528666
217	11/20/2024	1228285	HAMMER EMERGENCY C/W CRADLE HINO FD240 2740044		1528183
217	11/20/2024	1228285	PT1 Tablet Entered -emergency hammer missing	fitted new hammer	1528183
217	11/20/2024	1228285	Consumables		1528183
217	11/15/2024	1227411	Drv entered - Elec and Light Exterior LightsPassenger sign	check the circuit change the globes	1527547
217	11/15/2024	1227411	Consumables		1527547
217	11/04/2024	1205044	T-FITTING MERC	x3 more ord ex germany	1525890
217	11/04/2024	1205044	AIRBAG FR/RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200		1525890
217	11/04/2024	1205044	Mechanic entered - Suspension Other Leaning to os	Found OSRR airbag top fitting leaking no access to remove the fitting ordered new fitting and need to break the old one and take it out fit new fitting.	1525890
217	11/04/2024	1205044		Removed airbag to see the access as per instruction could not find any access from the bottom fitted new airbag due to damage during removal.	1525890
217	11/01/2024	1205044	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4	In store as consumable	1525723
217	11/01/2024	1223487	SEAL AIR DRYER - CIRCUIT PROT	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE374920 Receiving #:398031 Date :2024-11-08 217	1526633
217	10/30/2024	1224153	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	retensioned to spec.	1525060
217	10/30/2024	1224153	Consumables		1525060
217	10/30/2024	1205044	O-RING KIT LARGE VOSS A6739970145		1525060
217	10/30/2024	1205044	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1525060
217	10/30/2024	1205044	VALVE SIX WAY CIRCUIT PROTECTION VALVE KNORR-BREMSE 0500LE		1525060
217	10/30/2024	1205044		broke the t fitting above OSRR air bag removed the fitting fitted new fitting with new oring kit Checked leaks ok	1525060
217	10/30/2024	1205044		Found faulty 5 way valve leaking from ID plate mount replaced the valve with new orings	1525060
217	10/28/2024	1223554	SENSOR ABS RHR & RHF 4000mm MERC BENZ 0500LE	checked alternator brush pack found old brush pack was completely wornout replaced with new brush pack still no door brakes	1524450
217	10/28/2024	1223554	Mechanic entered - Body Front_Door Operation Faulty DOOR bra		1524450
217	10/28/2024	1223554	REGULATOR BRUSH PACK 140AMP 0500 ALT 94V0003		1524450
217	10/28/2024	1223554		replaced abs sensor with new 6tested and all good	1524450
217	10/28/2024	1223554	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4.0 BAR MERC BENZ 0500LE		1524450
217	10/28/2024	1223554	Consumables		1524450
217	10/26/2024	1223532		VEHICLE SAFETY INSPECTION completed as per check list	1524450
217	10/26/2024	1223537	Mechanic entered - Brakes Other rear brake pads low	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1524450
217	10/26/2024	1223537	TYRE 295/80R22.5 RECAP	replaced rear brake pads and measured discs still within spec. adjusted brake pads and fitted two new wheels on p3 and p4 fitted all rear wheels back on tensioned to spec. and booked a retension roadtested and checked brake temps everything is in good working order	1524450
217	10/26/2024	1223537	BRAKE PADS FR / RR MERC 0500LE E3-ES 49G7501BERAL		1524450
217	10/26/2024	1223487		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list	1524450
217	10/26/2024	1223487	VALVE AIR FILTER CHECK 22mm CYCLONE		1524450
217	10/26/2024	1223487	O-RING KIT SMALL VOSS A0309971748		1524450
217	10/26/2024	1223487	AIR DRYER ASSY MERC 0500LE A0004302915		1524450
217	10/26/2024	1223487	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401	secured indicator stalk	1524450
217	10/25/2024	1223199	PT1 Tablet Entered -Indicator stalk brokenloosedriver repo	Creditor #:PT-RP RP AUTO UPHOLSTERY PTY LTD P/O #:PE374847 Receiving #:397161 Date :2024-10-24 no replac for RP10024	1524746
217	10/23/2024	1221737	DIRECT PURCHASE - VANDALISM		1524746
217	10/23/2024	1221737	Consumables		1522615
217	10/18/2024	1221737	Mechanic entered - Body Other passenger seat back missing	fitted ok	1522615
217	10/18/2024	1221737	SEAT SINGLE BACK CEN CVR CI		1522615
217	10/17/2024	1221421	Consumables		1522615
217	10/17/2024	1221424	Consumables		1522615
217	10/17/2024	1221421	PT1 Tablet Entered -Body - Rear emergency hammer missing	fitted new hammer and secured	1522615
217	10/17/2024	1221421	HAMMER EMERGENCY SIDE GLASS RED 12035		1522615
217	10/17/2024	1221424	PT1 Tablet Entered -Body - Rear emergency hammer missing	fixed on another work order	1522615
217	10/16/2024	1221198	Consumables		1522615
217	10/16/2024	1221198	Driver Tablet Entered -Body - Rear_Door Operation Faultyno	found door brakes not working replaced sensor on n/s booster and checked again door brakes working	1522615
217	10/16/2024	1221198	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4.0 BAR MERC BENZ 0500LE		1522615
217	10/15/2024	1220874	Consumables		1522615
217	10/15/2024	1220875	Consumables		1522615
217	10/15/2024	1220874	PT1 Tablet Entered -Body - Rear_Door Operation Faulty	Tested both doors. bntho door operate as should	1522615
217	10/15/2024	1220875	Drv entered - Body Rear_Door Operation Faulty	Double jobs	1522615
217	10/10/2024	1220197	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	Checked and completed.	1522092
217	10/07/2024	1214191	Engine Noisy or Rattling. Fan hub worn.	Tested the angle drive and found no faults by Harley and Dean.	1521316
217	10/04/2024	1214191	FAN ANGLE DRIVE ASSY MERC 0500LE A6295000422 A0005004122	NLR put into store	1521141
217	10/03/2024	1218130	Consumables		1520667
217	10/03/2024	1218130	Workshop Tablet Entered -Elec and Light - Indicators lever b	Fitted new indicator stalk. Tested. okay	1520667
217	10/03/2024	1218130	SWITCH COMBINATION MERC BENZ 0500LE A0085450124		1520667
217	10/03/2024	1218140	Consumables		1520667
217	10/03/2024	1218141	Consumables		1520667
217	10/03/2024	1218140	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	reset rollaway module	1520667
217	10/03/2024	1218141	Workshop Tablet Entered -Body - rear_Door Operation Faulty y	reset rollaway box	1520667
217	09/16/2024	1214651	Consumables		1518958
217	09/16/2024	1214651	PT1 Tablet Entered -front park Light out	Fitted parker light. tested. okay	1518958
217	09/13/2024	1214191	FAN ANGLE DRIVE ASSY MERC 0500	Creditor #:PT-CBM001 CBM COMPANY P/O #:PE372409 Receiving #:394637 Date :2024-09-17	1519530
217	09/12/2024	1205044	T-FITTING MERC	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE368904 Receiving #:394757 Date :2024-09-18 Ex Germany	1519703
217	09/06/2024	1212962	Consumables		1517787
217	09/06/2024	1212962	Elec and Light Dr fan not working.	checked the system repaire the fan connection adjust the fan blade	1517787
217	09/06/2024	1212970		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service	1517787
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	OIL ENGINE ALL FLEET PLUS E900 15W-40	CARRY OUT B SERVICE AS PER CHECK LIST completed as per checklist	1517220
217	09/04/2024	1212450	OIL SAMPLE TEST KIT		1517220
217	09/04/2024	1212450	FILTER OIL MERC BENZ 0500LE ES A0001801709		1517220
217	09/04/2024	1212450	BREATHER OIL MIST MERC BENZ 0500LE AS410100163		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/04/2024	1212450	Consumables		1517220
217	09/03/2024	1208691	Apply print film MODESTY	CARRY OUT A SERVICE AS PER CHECK LIST completed as per checklist	1517220
217	09/03/2024	1211989	Consumables	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE370779 Receiving #:393764 Date :2024-09-04	1517591
					1516563

217	09/03/2024	1211989	Consat (None)Not connecting to desto	Started bus. Desto comes up. switched between destonations. Okay	1516563
217	09/02/2024	1211738	Mechanic entered - Suspension Noisy Front sway bar broken	Removed sway bar from 218 on saturday 31/8/24 and fit to this bus used new sway bar bushes	1516563
217	09/02/2024	1211738	BUSH FRT & RR SWAY BAR 70MM MERC BENZ 0500LE A6283220050		1516563
217	09/01/2024	1202250	Consumables		1519530
217	09/01/2024	1202250	Direct Purchase - BODYWORK	Creditor #PT-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #PE368902 Receiving #394647 Date :2024-09-17 T-FITTING 6x4mm	1519530
217	09/01/2024	1202250	Direct Purchase - BODYWORK	Creditor #PT-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #PE368902 Receiving #394647 Date :2024-09-17 4mm air line	1519530
217	08/31/2024	1211672		VEHICLE SAFETY INSPECTION carried out safety inspection as per checklist	1516563
217	08/31/2024	1211672		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1516563
217	08/24/2024	1208691	Apply print film	Completed week 19-25th August	1514684
217	08/23/2024	1209542	Consumables		1515400
217	08/23/2024	1209542	PTI Tablet Entered -emergency hammer missing		1515400
217	08/23/2024	1209542	HAMMER EMERGENCY SIDE GLASS RED 12035		1515400
217	08/15/2024	1200229	VALVE ECAS MERC BENZ 0500LE ->	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE370456 Receiving #393315 Date :2024-08-28	1516388
217	08/12/2024	1206867	Driver door unable to remain lock	drilled and tapped drivers door for bigger hinge bolts they were stripped	1513277
217	08/12/2024	1206867	Consumables		1513277
217	08/09/2024	1206637	CCTV Camera. Driver cabin camera noise is loud and cannot	change the camera	1513277
217	08/09/2024	1206638	CCTV Camera. Driver volume is distorted and extremely nois	checked the system the volume is very low maybe need to change the camera but this camera not avilable any more. finally find the used camera and change it.	1513277
217	08/09/2024	1206695	Consumables		1513277
217	08/09/2024	1206695	PTI Tablet Entered -Body - Body Damagemmmn	Checked no damages detectcd	1513277
217	08/06/2024	1205559	Consumables		1512318
217	08/06/2024	1205560	Consumables		1512318
217	08/06/2024	1205559	Drv entered - Body Drivers Seat Controls	replaced missing lumbar switch cover	1512318
217	08/06/2024	1205560	Drv entered - Body Body Damage	no body damage found	1511030
217	07/29/2024	1203697	Consumables		1511030
217	07/29/2024	1203697	Consumables		1511030
217	07/29/2024	1203697	Drv entered - Body Passenger Seat Torn/Passenger seat upper	fitted the cusion back. used the cusion that is off this bus	1509975
217	07/22/2024	1202250	Consumables		1509975
217	07/22/2024	1202250	Consumables		1509975
217	07/22/2024	1202250	Consumables		1509975
217	07/22/2024	1202250	Consumables		1509975
217	07/22/2024	1202250	Consumables	Repaired the leak at front door box ok	1509975
217	07/22/2024	1202250	PTI Tablet Entered - air leaking front left side plz check	small air fittings and hose needs replacement no stock	1509437
217	07/18/2024	1201618	Ops Entered - Fault - A/C Heating Demister Not Heating - Ro		1509437
217	07/18/2024	1201618	PTI Tablet Entered -heater system not working properly	revved bus in gear untill reached operating temp demister and a/c blowing hot air through whole bus.	1509080
217	07/12/2024	1200229	Suspension Leaning Replace the ECAS Valve.	replaced ecas valve and replaced all o rings labled which each airline goes tested and all good	1509080
217	07/12/2024	1200229	O-RING KIT SMALL VOSS A0309971748		1509080
217	07/12/2024	1200229	O-RING KIT LARGE VOSS A0639970145		1509080
217	07/12/2024	1196175	A service	Creditor #PT-22C001 22 CELLIUS P/O #PE367572 Receiving #390099 Date :2024-07-15	1509213
217	07/10/2024	1199624		VEHICLE SAFETY INSPECTION	1509080
217	07/10/2024	1199624		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1509080
217	07/10/2024	1199680	Consumables		1509080
217	07/10/2024	1199680	Mechanic entered - Elec and Light Interior Lights	fit led strip to light	1509080
217	07/10/2024	1199680	HARNES LED STRIP CONNECTORS 50mm NEW STYLE		1509080
217	07/10/2024	1199680	LED LIGHT STRIP ASSY ROOF (NEW STYLE)		1509080
217	07/10/2024	1199675	Consumables		1509080
217	07/10/2024	1199675	Consumables		1509080
217	07/10/2024	1199653	Mechanic entered - Body Other yellow floor strips missing	fitted new strips fitted strips	1509080
217	07/10/2024	1199653	EDGE STEP INSERT YELLOW 40MM P/M 28103785ER		1509080
217	07/10/2024	1199675	Mechanic entered - Body Other rear hatch struts u/s	replaced struts	1509080
217	07/10/2024	1199675	STRUT GAS STAY 350NM 565mm LNG		1509080
217	07/10/2024	1199653	Consumables		1509080
217	07/10/2024	1199653	Consumables		1509080
217	07/10/2024	1199708	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR		1509080
217	06/26/2024	1196715		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1507620
217	06/26/2024	1196715		Assisting	1507620
217	06/24/2024	1196153	Ops Entered - Fault - Elec and Light Indicators Not Working	replaced indicator bulb with a new one. allgood tested and secured	1507250
217	06/24/2024	1196153	Consumables		1507250
217	06/14/2024	1194336	PTI Tablet Entered -LH side headline not working	found n/s headlight n/w replaced with new and checked ok	1505590
217	05/30/2024	1191485		CARRY OUT FIRE EXTINGUISHER TEST & TAG still in date and pressure in the green.	1503222
217	05/24/2024	1190355	Fluid Leaks Rear of bus. Rectify and clean Sump leak.	re torqued sump bolts then washed	1502502
217	05/24/2024	1190259	PTI Tablet Entered -Leaking airFront_Door Operation Faulty	Inspect and repair rubbed air line	1502502
217	05/24/2024	1190259	Consumables		1502223
217	05/21/2024	1189725	Gearbox Driveline Tighten Pinion nut.	tightened pinion nut to the best i could	1502223
217	05/21/2024	1189637		CARRY OUT A SERVICE AS PER CHECK LIST completed	1502223
217	05/21/2024	1189637	Consumables		1502223
217	05/21/2024	1189637	Consumables		1502223
217	05/21/2024	1189637	Consumables		1502223
217	05/16/2024	1188807	Drivers door lock loose.	fixed. door locking now	1501400
217	05/16/2024	1188807	Consumables		1501400
217	05/14/2024	1188060		VEHICLE SAFETY INSPECTION	1500635
217	05/14/2024	1188060		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed as per checklist.	1500635
217	05/14/2024	1188130	Mechanic entered - Elec and Light Other engine hatch switch	replaced with new	1500635
217	05/14/2024	1188130	SWITCH R/RIGHT ENGINE HATCH INHIBITOR MERC 0500LE 50V2223		1500635
217	05/14/2024	1188130	Consumables		1500635
217	05/06/2024	1186231	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	retentioned p6 to spec	1499152
217	05/06/2024	1186231	Consumables		1499152
217	05/03/2024	1185958	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking P6 re	fitted recap on p6	1499152
217	05/03/2024	1185958	TYRE 295/80R22.5 RECAP		1499152
217	05/03/2024	1185958	Consumables		1499152
217	05/03/2024	1182308		Replaced new hinge and the hinge rubber and fitted to the panel fitted panel to the bus and removed and fitted new clow catches x 02 fitted gas struts (used) Job completed at seaford (work order # 1181807 - copied from seaford workshop TIM5) 12/04/2024	1499152
217	04/23/2024	1172318	TORQUE ROD FRT UPPER RH MERC B	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE359665RET Receiving #384769 Date :2024-04-30 RFC ref inv XA950042372-01	1499152
217	04/23/2024	1182308	CATCH CLAW PLASMA ENGINE HATCH DOOR 2132-001-2		1497787
217	04/16/2024	1182308		prep and painted white/black	1496852
217	04/15/2024	1182308		fabricated panel	1496543
217	04/12/2024	1181807	Fault#:39157 - Ops Entered - Fault - Breakdown Accident/Drv	Replaced new hinge and the hinge rubber and fitted to the panel and fitted panel to the bus and removed fitted new clow catches x 02 fitted gas struts (used) Job completed	1496543
217	04/12/2024	1181807	CATCH CLAW PLASMA ENGINE HATCH DOOR 2132-001-2		1496543
217	04/12/2024	1181807	CLAW CATCH & ANGLE		1496543
217	03/26/2024	1172991	AIRBAG FRT/RR MERC BENZ 0500LE E3 - ES OH1830 49Y200	Mech double up already booked to 1172318	1494753
217	03/19/2024	1177384	PTI Tablet Entered -Body - Mirrors Exterior LH side loose	tightened n/s mirror	1493512
217	03/19/2024	1177384	Consumables		1493512
217	03/18/2024	1176411	DIRECT PURCHASE - BUS INSPECTI	Creditor #PT-ROASAF ROAD SAFETY INSPECTIONS P/O #PE361230 Receiving #382154 Date :2024-03-21 Annual Safety Inspections	1493965
217	03/16/2024	1176919	PTI Tablet Entered -rear hammer missing	checked all emergencies hammers they are all in place	1492945
217	03/14/2024	1176411		VEHICLE SAFETY INSPECTION	1492394
217	03/14/2024	1176411		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1492394
217	03/14/2024	1176411		ANNUAL SAFETY INSPECTION SERIAL #RS1064672 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 rs1064672	1492394
217	03/14/2024	1176255	PTI Tablet Entered -Body - Body Damagerear emergency hammer	replaced rear missing em hammer with new	1492394
217	03/14/2024	1176255	HAMMER EMERGENCY SIDE GLASS RED 12035		1492394
217	03/14/2024	1176255	Consumables		1492394
217	03/08/2024	1175219	PTI Tablet Entered -Brakes - Right hand side rear air leak .	found air leak on one of the voss fittings removed and found orings damaged replaced with new fitted back and checked ok	1491803
217	03/04/2024	1172640		replaced drag link	1490596

217	03/04/2024	1173266	Service	camera replaced	1490596
217	03/04/2024	1173266	CAMERA INTERNAL 2.8MM LENS (SA-2545-13AHD)		1490596
217	03/04/2024	1173267		fitted aluminium brace	1490596
217	03/04/2024	1173268		repaired hole in driver area with fiberglass filler and sprayed under front of bus with body deadener	1490596
217	03/04/2024	1173267	Consumables		1490596
217	03/04/2024	1173268	Consumables		1490596
217	03/02/2024	1172357	Apply print film	Completed 09/02/24	1490596
217	03/01/2024	1172318	AIRBAG FRT - RR MERC BENZ 0500	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE359665 Receiving #381363 Date :2024-03-08	1492169
217	03/01/2024	1172318	TORQUE ROD FRT UPPER RH MERC B	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE359665 Receiving #381363 Date :2024-03-08 RFC NLR	1492169
217	02/29/2024	1172640	DRAGLINK ASSY MERC BENZ 0500LE	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE360103 Receiving #380642 Date :2024-02-29	1490972
217	02/29/2024	1172640	NUT DRAG LINK M24 X 1.5 MERC B	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE360103 Receiving #380642 Date :2024-02-29	1490972
217	02/28/2024	1172991	Mechanic entered - Suspension Soft Replace all air bags	Replace all 6 air bags due to fatigue	1490596
217	02/28/2024	1172991	AIRBAG FRT/RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200		1490596
217	02/28/2024	1172988	MOUNT RADIATOR TOP MERC BENZ 0500LE A000987043901		1490596
217	02/28/2024	1172988	Mechanic entered - Engine Other Radiator mounts n/s	*Replace top and bottom radiator mounts	1490596
217	02/28/2024	1172988	BUSH RADIATOR LVR MTG MERC BENZ 0500LE A0009872143		1490596
217	02/28/2024	1173266	CCTV Camera Camera facing Rear Passenger Saloon is blurry		1490596
217	02/28/2024	1173265	Body Carryout RSI repairs.	Replace rear of rear shockers	1490596
217	02/28/2024	1173267	Drivers fan panel cracked		1490596
217	02/28/2024	1173268	Rust under driver area (hole)		1490596
217	02/28/2024	1173265	Consumables		1490596
217	02/28/2024	1173267	Consumables		1490596
217	02/28/2024	1173268	Consumables		1490596
217	02/27/2024	1172357	Apply print film L1 L2 R2 R3	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE360132 Receiving #380479 Date :2024-02-28	1490596
217	02/27/2024	1172318	o/s/r/ shock absorber leaking (replace both o/s)	Refer WOR1173265Completed by Scott.	1490596
217	02/27/2024	1172640	Steering Replace Drag link Complete.		1490596
217	02/27/2024	1172666	A/C Heating Belt Loose or_Missing	Assisting Adjusted and aligned the main belt by Cold Drive.	1490596
217	02/27/2024	1172666	A/C Heating Belt Loose or_Missing	Creditor #PT-COLO04 COLD DRIVE PTY LTD P/O #PE360405 Receiving #380714 Date :2024-02-29	1490972
217	02/27/2024	1172666	align belt	completed	1490596
217	02/27/2024	1172697	Mechanic entered - Body Other yellow step missing rear		1490596
217	02/27/2024	1172697	EDGE STEP INSERT YELLOW 40MM P/M 28103785ER		1490596
217	02/27/2024	1172697	Consumables		1490596
217	02/26/2024	1172239		PRE ANNUAL SAFETY INSPECTION CHECK Completed	1490596
217	02/26/2024	1172239		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed	1490596
217	02/26/2024	1172425	Mechanic entered - Wipers and Washers Washers Not Working	Replace necessary parts and hoses to get washers operational	1490596
217	02/26/2024	1172425	PUMP WIPER WASHER 24 VOLT		1490596
217	02/26/2024	1172425	WIPER WASHER NON-RETURN VALVE WP10		1490596
217	02/26/2024	1172318	SHOCKER REAR MERC 0500LE A3563	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE360103 Receiving #380406 Date :2024-02-27	1490596
217	02/26/2024	1172388	Mechanic entered - Engine Other Idle pulley worn	Fitted pulley	1490596
217	02/26/2024	1172388	PULLEY ADJUSTER IDLER PULLEY 0500 - UPPER		1490596
217	02/24/2024	1172115		Completed	1490596
217	02/24/2024	1172115	Oil ZF GEARBOX SYNTHETIC ECOFLUID A PLUS		1490596
217	02/24/2024	1172115	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081		1490596
217	02/24/2024	1172137	BELT FAN DRIVE MERC BENZ 0500LE A0139971992		1490596
217	02/24/2024	1172137	Mechanic entered - Engine Belts_Loose Noisy Missing engine b	Fitted new bfan belt and drive belt.Aultinator belt got damaged when removing. None is stock need to order	1490596
217	02/24/2024	1172137	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696		1490596
217	02/24/2024	1172138	Front lower radiator mount broken	Job not done. Accidentally closed	1490596
217	02/19/2024	1168533	RUBBER WHEEL ARCH 41294 2.5	mech booked wrongt should be 10258	1489138
217	02/19/2024	1168533	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1489138
217	02/19/2024	1168533	Consumables		1489138
217	02/13/2024	1169303		VEHICLE SAFETY INSPECTION	1488080
217	02/13/2024	1169303		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1488080
217	02/09/2024	1168533	Mechanic entered - Body Other N/S wheel arch rubber missing	fitted new rubber	1487450
217	02/09/2024	1168533	RUBBER WHEEL ARCH 41294 2.5		1487450
217	02/09/2024	1168450		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist aply split conduct tube and few zipties	1487450
217	02/09/2024	1168523	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	removed old smoking decals	1487450
217	02/09/2024	1168420		CARRY OUT A SERVICE AS PER CHECK LIST completed a service as per checklist	1487450
217	02/09/2024	1168420	Consumables		1487450
217	02/09/2024	1168420	Consumables		1487450
217	02/07/2024	1167685	PTI Tablet Entered -Body - cooling fan shaft bairring loss	replaced both fan shaft and fan shaft hub as both were wornout and broken.	1486444
217	02/07/2024	1167685	SHAFT FAN DRIVE MERC 0500(A629500082)(50M0029)		1486444
217	02/07/2024	1167685	PULLEY ENGINE FAN DRIVE MERC 0500LE A6295000668		1486444
217	02/07/2024	1167685	Consumables		1486444
217	02/06/2024	1167458	Fault#39071 - Ops Entered - Fault - Breakdown Air System Fa	Replaced braided air hose from ping tank to cooling coil also replaced 1 voss fitting seal kit now builds up air.	1486444
217	02/06/2024	1167458	O-RING KIT LARGE VOSS A6739970145		1486444
217	02/06/2024	1167459	HOSE MERC 0500 COMP BRAIDED PING TANK TO UNLOADER		1486444
217	02/06/2024	1167459	PTI Tablet Entered -Body - air pressure going low	W/O 1167458 refers	1486444
217	02/06/2024	1167459	Consumables		1486444
217	02/05/2024	1167293	Workshop Tablet Entered -Body - Front_Door Operation Faulty	W/O 1167139 refers	1486444
217	02/05/2024	1167293	Consumables		1486444
217	02/05/2024	1167294	Ops Entered - Fault - Air System Air_Leak Doors - Route: 83	W/O 1167139 refers	1486444
217	01/22/2024	1164798	PTI Tablet Entered -Engine - Belts_Loose Noisy MissingAC be	when front door is closed leaking air from small split in one of the air lines in the door mechanism cut and re joined pipe all ok	1484793
217	01/22/2024	1164798	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696	replaced main belt and adjusted	1484793
217	01/10/2024	1162762	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	campaign completed.oki	1483562
217	12/29/2023	1160293	PTI Tablet Entered -Elec and Light - right hand side low bea	replaced headlight globe with new tested and all good	1481858
217	12/29/2023	1160293	Consumables		1481858
217	12/28/2023	1159919	411366 VOLGREN MID CAT SIDE 1	Creditor #PT-OB0001 O'BRIENS GLASS INDUSTRIES P/O #PE356743 Receiving #376447 Date :2023-12-29 Replace cracked window	1482015
217	12/28/2023	1159919	Consumables		1482015
217	12/27/2023	1159919	N/S/R last window cracked	n/s/r last window replaced by o'briens glass	1481858
217	12/22/2023	1159548	Consumables		1481858
217	12/22/2023	1159548	PTI Tablet Entered -Leaking Air	found rubbered through air line on front door front leaf when door closed cut and re joined air line no more leak done by finley	1481858
217	12/22/2023	1159548	Ops Entered - Fault - Air System Air_Leak Front - Route: 77	built air till it blew off pumped down with brakes exited bus to check for leaks no leaks found checked door operation for leaks and inspected seat base	1480120
217	12/15/2023	1158199	Consumables		1480120
217	12/15/2023	1158199	PTI Tablet Entered -Elec and Light - Left hand side rear cle	Re moved and fitted new light. tested. okay	1480120
217	12/15/2023	1158199	LAMP LED SIDE RED/AMBER PERI 52-98002		1479555
217	12/12/2023	1157660		VEHICLE SAFETY INSPECTION	1479555
217	12/12/2023	1157660		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1479555
217	12/08/2023	1156998	Consumables		1479090
217	12/08/2023	1156998	Workshop Tablet Entered -Elec and Light - Exterior LightsN	Repair wiring to n/s clearance light	1479090
217	12/08/2023	1156958	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1479090
217	12/08/2023	1156958	AIR DRYER ASSY MERC 0500LE A0004302915		1479090
217	12/08/2023	1156958		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air system service done. Started. okay	1479090
217	12/07/2023	1156520	Consumables		1478422
217	12/07/2023	1156520	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	completed retention on p1	1478422
217	12/06/2023	1156245	Consumables		1478422
217	12/06/2023	1156245	PTI Tablet Entered -Wheels and Tyres - WornP1 sidewall	replaced p1 tyre with new	1478422
217	12/06/2023	1156245	TYRE 285/80R22.5 NEW		1478422
217	11/02/2023	1150267	Fault#:38953 - Ops Entered - Fault - Breakdown Belts Pulleys	replaced alternator belts and a/c belt adjusted tested and all good	1473970

11/02/2023	1150267	BELT MICRO V SERPENT 9 RIB 2120mm LING A0019935696	CARRY OUT FIRE EXTINGUISHER TEST & TAG checked fire extinguisher gauge is on green and is up to date allgood
217	11/02/2023	1150267	Removed and arms and refitted ok
217	10/31/2023	1149676	Relightened ok
217	10/26/2023	1148930	Creditor #PT-ZC001 22 CELSIUS P/O #P-E353021 Receiving #-373135 Date :2023-11-08 217 DEFECT replaced oil feed pipe from filter to timing case second hand pipe from 330. replaced a/c compressor drive belt. Washed tested all ok.
217	10/25/2023	1144052	AIR CONDITIONING REPAIR
217	10/25/2023	1148436	Mechanic entered - Fluid Leaks Rear of bus engine oil leak
217	10/25/2023	1148436	BELT MICRO V SERPENT 9 RIB 2120mm LING A0019935696
217	10/25/2023	1137797	Consumables
217	10/25/2023	1137797	HAMMER EMERGENCY HAMMER
217	10/23/2023	1147936	Vehicle safety inspection carried out safety inspection as per checklist
217	10/23/2023	1147936	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheel nuts to 600NM
217	10/23/2023	1147835	Consumables
217	10/23/2023	1147835	Mechanic entered - Body Other missing rear seat back and rea
217	10/23/2023	1147835	SEAT SINGLE BACK CEN CVR CI
217	10/23/2023	1147835	HANDLE GRAB GREY STRAP(BRV001)
217	10/23/2023	1147049	Apply print film
217	10/20/2023	1147579	Workshop Tablet Entered - Gearbox Driveline - Rough Gear Chan
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	FILTER FUEL MERC BENZ O500LE -> ES A5410900151
217	10/20/2023	1147516	FILTER P/STRG MERC SCANIA VOLVO [D153468](349619)
217	10/20/2023	1147516	FILTER OIL MERC BENZ O500LE E5 OH1830 ES A0001801709
217	10/20/2023	1147516	FILTER AIR MERC BENZ O500LE E3 - ES A0040941704
217	10/20/2023	1147516	OIL SAMPLE TEST KIT
217	10/20/2023	1147516	CARRY OUT C SERVICE AS PER CHECK LIST completed
217	10/20/2023	1147516	FILTER FUEL FILTER MERCEDES BENZ (H233WK)
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	CARRY OUT B SERVICE AS PER CHECK LIST
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	Consumables
217	10/20/2023	1147516	CARRY OUT A SERVICE AS PER CHECK LIST
217	10/19/2023	1147049	Apply print film MODESTY R1
217	10/18/2023	1146893	Workshop Tablet Entered - Suspension - extremely Hard
217	10/17/2023	1144052	Service
217	10/17/2023	1144052	PULLEY A/C
217	10/12/2023	1144052	BEARING A/C CLUTCH I/D 50MM Q/D 90MM W 30MM 3210 6210 ISR
217	10/12/2023	1144052	RING RETAIN THERMO KING CLUTCH
217	10/11/2023	1144165	Refer WOW1144052.
217	10/04/2023	1144052	Mechanic entered - A/C Heating Other a/c compressor siezed
217	10/04/2023	1144052	BELT MICRO V SERPENT 9 RIB 2120mm LING A0019935696
217	10/04/2023	1144165	Fault# 38900 - Ops Entered - Fault - Breakdown Belts Pulley
217	10/04/2023	1144165	Fault# 38900 - Ops Entered - Fault - Breakdown Belts Pulley
217	09/27/2023	1143104	Drv entered - Wipers and Washers Washers Not Working
217	09/08/2023	1139579	CCCTV CH3 Front saloon camera video loss
217	09/08/2023	1139578	CARRY OUT CCCTV - A SERVICE AS PER CHECK LIST complete CCCTV A service as per checklist repair the video connections
217	09/05/2023	1138604	PERFORM CAMPAIGN 06/23 REPLACE ETAG
217	09/04/2023	1138309	Consumables
217	09/04/2023	1138309	Dash- Fuel gauge showing empty Brakes need to be adjusted d
217	09/04/2023	1138309	test drove found brake pedal travel excessive found clevis pin had worn away in the cam lever from the pedal temporarily fixed by adjusting rod length still needs to be brought back in for permanent fix painted over graffiti
217	09/02/2023	1138085	Vandalism/Vandalism/Graffiti Interior
217	09/01/2023	1137879	Consumables
217	09/01/2023	1137879	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete
217	09/01/2023	1137797	PT1 Tablet Entered -Body - Body DamageRear hammer missing
217	08/31/2023	1137529	Drv entered - A/C Heating Not Heating
217	08/30/2023	1137204	Consumables
217	08/30/2023	1137204	PT1 Tablet Entered -Body - Body DamageDriver reports burning
217	08/30/2023	1137204	Brakes O/S/R Hub Seal Leaks.
217	08/30/2023	1137204	SEAL KIT REAR HUB MERC BENZ O500LE E3 - ES 1F1304
217	08/25/2023	1135910	O/S/R hub seal leaking
217	08/23/2023	1135458	Inspect hub seal and repairs to be arranged
217	08/23/2023	1135458	VEHICLE SAFETY INSPECTION
217	08/23/2023	1135458	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS
217	08/21/2023	1133545	Consumables
217	08/21/2023	1133545	A0008250AD ENG HATCH LIGHT
217	08/15/2023	1133545	PT1 Tablet Entered -Elec and Light - Exterior Lights/Engine
217	08/14/2023	1133038	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING
217	08/14/2023	1133038	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAP

06/09/2023	1119602	Drv entered - Body Drivers Seat Controls	Requires front seat tilt control cable tilt seat control broken		1459002
217	05/29/2023	1117362 PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	Consat fitted by volgren		1448865
217	05/26/2023	1116914 WHEEL ARCH RUBBER BACKING P/LENGTH			1448865
217	05/26/2023	1116914 Consumables			1448865
217	05/26/2023	1113116	Fitted nsr wheel arch panel and bonded panel fitted clow catches and gas struts replaced backing strip (supplied) replaced amber reflectors x 01		1448865
217	05/25/2023	1116914 PT1 Tablet Entered -Body - Body DamageLHF panel damage	Removed and fitted nsr wheel arch panel and bond panel replaced wheel arch backing strip (supplied) replaced clow catches and amber reflectors x 01 job completed		1448865
217	05/22/2023	1116079 Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	completed retension to spec		1448181
217	05/22/2023	1116079 Consumables			1448181
217	05/19/2023	1115642	VEHICLE SAFETY INSPECTION carried out safety inspection as per checklist		1447682
217	05/19/2023	1115642	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1447682
217	05/19/2023	1115699 Mechanic entered - Wheels and Tyres Worn p2 5 and 6 tyre wor	replaced p2 and p5 and 6 tyre		1447682
217	05/19/2023	1115699 TYRE 295/BOR22.5 NEW			1447682
217	05/19/2023	1115699 TYRE 295/BOR22.5 RECAP			1447682
217	05/19/2023	1115699 Consumables			1447682
217	05/18/2023	1113116	Welded and bonded panel supports to the skin and the extrusion (17/05/2023/Wednesday)		1447682
217	05/13/2023	1113116	Cut rear supports and L-channel and welded to the panel re-sealed backing supports scotch brite inner of the panel c/o		1446645
217	05/10/2023	1113524 LIGHT INDICATOR SIDE L/H			1445976
217	05/10/2023	1113524 PT1 Tablet Entered -Elec and Light - Exterior LightsLHF PA	Replace broken indicator assy		1445976
217	05/10/2023	1113524 Consumables			1445976
217	05/09/2023	1113116 SHEET ALUM 5050 240cm x120cm x 3mm			1445976
217	05/08/2023	1113116 Accident#55044 - Offside front damage	made access panel skin made wheelarch panel welded and bonded lower hinge to access panel		1445780
217	05/04/2023	1112302 Ops Entered - Fault - Elec and Light Desto Fault - Route: 7	desto working fine		1444944
217	05/04/2023	1112302 Consumables			1444944
217	05/04/2023	1112302 PT1 Tablet Entered -Body - Body DamageNoisy exhaust	exhaust fine. minor scrapes on body		1444944
217	05/04/2023	1112302 Consumables			1444944
217	04/26/2023	1110626 PT1 Tablet Entered -Engine - Noisy or RattlingMuffler nois	re fitted exhaust v band		1443258
217	04/21/2023	1110160 Consumables			1443010
217	04/21/2023	1110160 Drv entered - Elec and Light Desto Fault	checked desto with multiple routes could not fault		1443010
217	04/17/2023	1109230	CARRY OUT A SERVICE AS PER CHECK LIST		1442105
217	04/06/2023	1107671 PT1 Tablet Entered -Body - Drivers Seat Controls seat base m	correctly fitted seat base		1441021
217	04/06/2023	1107671 Consumables			1441021
217	03/29/2023	1106102 Mechanic entered - Elec and Light Reverse Buzzer Not working	Check reverse buzzer and working ok		1439870
217	03/29/2023	1106102 Consumables			1439870
217	03/27/2023	1104198 DIRECT PURCHASE - STEERING	Creditor #:PT-BIG001 BIG WHEELS TRUCK ALIGNMENT P/O #:PE339751 Receiving #:357701 Date :2023-03-29 Replace both Kingpins		1440390
217	03/27/2023	1105752	Assisting		1439833
217	03/27/2023	1105752	CARRY OUT FIRE EXTINGUISHER TEST & TAG		1439833
217	03/21/2023	1103258 DIRECT PURCHASE - BUS INSPCTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:P339527 Receiving #:357065 Date :2023-03-22 Annual Safety Inspections		1439833
217	03/20/2023	1104198 Steering Excessive Play Replace both king pins.	Assisting Both King pins replaced and Wheel aligned.		1439833
217	03/20/2023	1104198 Steering Excessive Play Replace both king pins.	Run a/c system and check temp working ok		1439540
217	03/17/2023	1103524 Drv entered - A/C Heating Not Cooling	VEHICLE SAFETY INSPECTION		1439540
217	03/16/2023	1103258	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1439540
217	03/16/2023	1103258	ANNUAL SAFETY INSPECTION SERIAL RS1 051478 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1439540
217	03/16/2023	1101711 Apply print film L1 L2 MODESTY	Creditor #:PT-GLAD10 GLASSPROTECT MELBOURNE P/O #:PE339089 Receiving #:356745 Date :2023-03-17		1439540
217	03/16/2023	1103327 Mechanic entered - Suspension Other Shocker rubbers u/s	Replace worn shocker rubbers		1439540
217	03/16/2023	1103327 VOLVO B7RLE REAR SHOCK BUSH KIT (30Y4019)			1439540
217	03/15/2023	1102944 Consumables			1439540
217	03/15/2023	1102944 Body carryout RSI repairs.	All whels painted		1439540
217	03/11/2023	1101711 Apply print film	Completed 06/03/23		1438636
217	03/09/2023	1101882 Consumables			1438636
217	03/09/2023	1101882 Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	retentioned p3 to 600nm		1438636
217	03/09/2023	1101926 Consumables			1438636
217	03/09/2023	1101941 Consumables			1438636
217	03/09/2023	1101943 Consumables			1438636
217	03/09/2023	1101969 Consumables			1438636
217	03/09/2023	1102057 Consumables			1438636
217	03/09/2023	1101941 Mechanic entered - Body Other Wheel arch rubbers and brush m	Done		1438636
217	03/09/2023	1101941 Mechanic entered - Body Other Grabs at rear of bus worm	Fitted new hand grabs		1438636
217	03/09/2023	1101926 Mechanic entered - Body Other disabled seat n/s gas strut n/	replaced with new		1438636
217	03/09/2023	1101943 HANDLE GRAB GREY STRAP(BRV001)			1438636
217	03/09/2023	1101943 Mechanic entered - Body Other disabled seat n/s gas strut n/	replaced with new		1438636
217	03/09/2023	1101943 STRUT GAS STAY 200NM 128mm LMG			1438636
217	03/09/2023	1101969 Mechanic entered - Body Other N.S.R mudflap broken	Replaced broken mudflap. Done by Thea		1438636
217	03/09/2023	1101969 MUDFLAP 605MM X 330MM			1438636
217	03/09/2023	1102057 Mechanic entered - Body Other Steering wheel colum broken	Fitted new top part of steering column stroud. Okay		1438636
217	03/08/2023	1101630	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Carry out inspection as per list		1438636
217	03/08/2023	1101630	PRE ANNUAL SAFETY INSPECTION CHECK Carry out inspection and list all faults		1438636
217	03/08/2023	1101741 Consumables			1438636
217	03/08/2023	1101741 Mechanic entered - Wheels and Tyres Damaged p3 and 4 tyre ha	replaced p3 and 4 tyre with new		1438636
217	03/08/2023	1101741 TYRE 295/BOR22.5 RECAP			1438636
217	02/22/2023	1098557	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safeti inspection		1437336
217	02/15/2023	1097017	VEHICLE SAFETY INSPECTION complete VSI as per check list		1436996
217	02/15/2023	1097017	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete wheel nuts retension to oem spec 600nm		1436996
217	02/15/2023	1097037 Mechanic entered - Body Other busminder USB n/w	complete replacement USB module test found unit charging		1436996
217	02/15/2023	1097037 USB SV 3A DUAL CONVERTER MODULE BUS MINDER			1436996
217	02/07/2023	1095210 Mechanic entered - Fluid Leaks Rear of bus Engine oil leak r	washed need to monitor		1434667
217	02/07/2023	1095211 Consumables			1434667
217	02/07/2023	1095211 Mechanic entered - Elec and Light Desto Fault	checked ok		1434667
217	02/07/2023	1095101 VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)			1434667
217	02/07/2023	1095101 DRYER AIR ASSY MERC 0500LE(A004302915)			1434667
217	02/07/2023	1095101 VALVE AIR FILTER CHECK 22mm CYCLONE			1434667
217	02/07/2023	1095101	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed		1434667
217	01/20/2023	1092123 Drv entered - Elec and Light Desto Fault	Start bus and operate desto and could not fault		1432713
217	12/23/2022	1087905 Consumables			1429910
217	12/23/2022	1087905 Mechanic entered - Wheels and Tyres Wheel Nut Retension p1	retensioned to specs.		1429910
217	12/22/2022	1087815	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed tune up service as per checklist.		1429910
217	12/22/2022	1087801 Consumables			1429910
217	12/22/2022	1087801 Mechanic entered - Wheels and Tyres Other check p2 sidewall	found p2 still in good condition. found p1 sidewall worn replaced with new and tensioned to specs		1429910
217	12/22/2022	1087801 TYRE 295/BOR22.5 NEW			1429910
217	12/22/2022	1087801 CYLINDER EXHAUST BRAKE MERC BENZ 0500LE A0001400359			1429910
217	12/22/2022	1087801 Engine Noisy or RattlingReplace the exaust brake throttle	removed old seized exhaust brake throttle body and fitted rebuilt exhaust brake throttle body with new ram.		1429910
217	12/22/2022	1087801 SOCKET EXH BRAKE CYL MERC BENZ 0500LE A5419910022			1429910
217	12/22/2022	1087801 Consumables			1429910
217	12/22/2022	1087801 Consumables			1429910
217	12/22/2022	1087801 Mechanic entered - Body Other damage rh side	found o/s/r below window skirting coming away from body secured in place		1429910
217	12/16/2022	1086988	VEHICLE SAFETY INSPECTION		1429127
217	12/16/2022	1086988	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1429127
217	12/15/2022	1086585 Drv entered - Elec and Light Exterior Lights	replaced ns indicator light		1428586
217	12/15/2022	1086585 LIGHT INDICATOR SIDE L/H			1428586
217	12/15/2022	1086585 Consumables			1428586

217	12/13/2022	1086168	Mechanic entered - Elec and Light Exterior Lights	replaced headlight bulb	1428065
217	12/13/2022	1086168	Consumables		1428065
217	12/01/2022	1084258	Mechanic entered - Body Other n/s/f wheel arch rubber missin	fitted new wheel arch rubber ok	1426329
217	12/01/2022	1084258	RUBBER WHEEL ARCH 41294		1426329
217	12/01/2022	1084258	Consumables		1426329
217	12/01/2022	1084258	Consumables		1426329
217	12/01/2022	1084232		CARRY OUT B SERVICE AS PER CHECK LIST completed as per check list	1426329
217	12/01/2022	1084232	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1426329
217	12/01/2022	1084232	Consumables		1426329
217	12/01/2022	1084232	Consumables		1426329
217	12/01/2022	1084232	Consumables		1426329
217	12/01/2022	1084232	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST completed as per check list	1426329
217	12/01/2022	1084232	Consumables		1426329
217	12/01/2022	1084232	Consumables		1426329
217	12/01/2022	1084232	Consumables		1426329
217	11/28/2022	1083267	Mechanic entered - Body Other rear emergency hammer missing	fitted new hammer	1425147
217	11/28/2022	1083267	Consumables		1425147
217	11/25/2022	1082984	HAMMER EMERGENCY RED		1425147
217	11/25/2022	1082984	Mechanic entered - Body Other emergency hammer missing	replaced missing emergency hammer with new.	1425147
217	11/25/2022	1082984	Consumables		1425147
217	11/07/2022	1079428	Mechanic entered - Wheels and Tyres Wheel Nut Retension P.5	tensioned to spec	1421685
217	11/07/2022	1079428	Consumables		1421685
217	11/07/2022	1079559	Mechanic entered - Engine Low Power	test drove found exhaust brake sticks when slowing down disconnected air supply to exhaust brake cylinder test drove drives good now need to order new cylinder	1421577
217	11/03/2022	1079033	SEAL KIT REAR HUB MERC 0500LE(1F1304)(SOF1317)		1421577
217	11/03/2022	1079033	Mechanic entered - Fluid Leaks Rear of bus O/S/R Hub seal le	Replaced OSR hub seal kit inclusive remove and refit hub and wheels . torqued wheel nuts as per spec.	1421577
217	11/01/2022	1075180	APPLY PRINT FILM R1	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE330691 Receiving #348942 Date :2022-11-09	1420510
217	10/28/2022	1078063	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rear	tensioned to spec	1420510
217	10/28/2022	1078063	Consumables		1420510
217	10/28/2022	1077907	Body Air box hatch hinge broken	Replaced the hinge and secured the panel.	1420510
217	10/28/2022	1077907	Consumables		1420510
217	10/27/2022	1077982	Mechanic entered - Fluid Leaks Rear of bus	replaced and insulated hoses on top of radiator. Replaced worn p clamps on brass bleed lines	1420510
217	10/26/2022	1077659		VEHICLE SAFETY INSPECTION	1420510
217	10/26/2022	1077659		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1420510
217	10/26/2022	1077775	BRAKE PAD SET SCANIA MERC BENZ 0500LE		1420510
217	10/26/2022	1077775	Brakes Replace rear rotors and pads.	Replaced NSR rotor hub seal brakes. torqued hub nut and locked adjusted brakes fitted wheels and torqued to spec. bus is disable due to cooling system repairs still needs a roadtest	1420510
217	10/26/2022	1077775	SEAL KIT REAR HUB MERC 0500LE(1F1304)(SOF1317)		1420510
217	10/26/2022	1077775	ROTOR FRONT & REAR MERC BENZ 0500LE A9424230112		1420510
217	10/26/2022	1077775	Brakes Replace rear Rotors and pads.	Replaced OSR rotor hub seal brakes. torqued hub nut and locked adjusted brakes fitted wheels and torqued to spec. bus is disable due to cooling system repairs still needs a roadtest	1420510
217	10/26/2022	1077775	BOLT CALIPER MTG SHANKED LOCATING BOLT 0500LE A9429900114		1420510
217	10/26/2022	1077684	Mechanic entered - Air System Air_Leak Rear	replaced leaking overflow valve	1420510
217	10/26/2022	1077684	VALVE OVERFLOW MERC 0500LE(4341002490)(A0054291844)		1420510
217	10/26/2022	1077810		CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Replaced oil.	1420510
217	10/18/2022	1076075	N/S/R 2nd last window cracked		1418731
217	10/18/2022	1076075	N/S/R 2nd last window cracked Replaced by O'Briens	Assisting	1418731
217	10/18/2022	1076075	411338 VOLGREN OC500 SIDE (117	Creditor #MT-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #PE330889 Receiving #347523 Date :2022-10-18 Replace O/S/R side Window	1419199
217	10/18/2022	1076075	Consumables		1419199
217	10/15/2022	1075180	Apply print film 12/10/22	Completed 12/10/22	1418731
217	10/11/2022	1074395	Mechanic entered - Elec and Light Other Loose switch on stee	tightened loose screws on indicator stalk tested all ok.	1417950
217	10/11/2022	1074395	Consumables		1417950
217	10/11/2022	1074631	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING		1417950
217	09/21/2022	1070926	Mechanic entered - Elec and Light Exterior Lights number pla	replaced light	1415870
217	09/21/2022	1070926	LAMP LED NUMBER PLATE EXIT LIGHT 250120 2559		1415870
217	09/21/2022	1070926	Consumables	found ecos module leaking tightened bolts and checked again for leaks no leaks found	1414790
217	09/13/2022	1069562	Suspension Leaning	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1414270
217	09/09/2022	1068929		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed	1414270
217	09/09/2022	1068930		Replace and adjust broken mirror	1413584
217	09/06/2022	1067946	Mechanic entered - Body Mirrors Exterior		1413584
217	09/06/2022	1067946	MIRROR L/H 380mm SHORT(UES1411E)		1413584
217	09/06/2022	1067946	Consumables		1413584
217	08/29/2022	1066353	Fluid Leaks N/S/Rear hub Seal sweaty Engine breather moun	washed around the engine and under also washed the gear box top to bottom and around the differential jacked up rear of bus put two stands under the chassis started bus up and put it in drive and sprayed brake cleaner on it first then blown it off with a blower	1411960
217	08/29/2022	1066353	Fluid Leaks N/S/R hub seal sweaty and engine breather mount		1411960
217	08/24/2022	1065580		VEHICLE SAFETY INSPECTION completed	1411444
217	08/24/2022	1065580		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1411444
217	08/24/2022	1065583	Consumables		1411444
217	08/24/2022	1065583	Mechanic entered - Elec and Light Exterior Lights o/s cleare	replaced and checked ok	1411444
217	08/24/2022	1065583	LAMP LED SIDE RED/AMBER PERE(52-98002)		1411444
217	08/24/2022	1065579	Consumables		1411444
217	08/24/2022	1065579	Consumables		1411444
217	08/24/2022	1065579	Consumables		1411444
217	08/24/2022	1065579	Consumables		1411444
217	08/24/2022	1065579	Consumables		1411444
217	08/16/2022	1062920	AIR CONDITIONING REPAIR	CARRY OUT A SERVICE AS PER CHECK LIST completed	1410148
217	08/12/2022	1062920	FAN CONDENSOR A/C CITY-RT	Creditor #PT-2ZC001 22 CELSIUS P/O #PE326981 Receiving #343516 Date :2022-08-17 BUS 217 A SERVICE	1409281
217	08/12/2022	1062920		BOOKED OUT FOR DANIEL	1409281
217	08/12/2022	1062920		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1409281
217	08/12/2022	1062920		Assisting Completed by 22Celsius	1409281
217	08/02/2022	1060512	Mechanic entered - Fluid Leaks Rear of bus coolant leak from	replaced low coolant sensor	1407107
217	08/02/2022	1060512	SENSOR LOW COOLANT MERC 0500LE(A0045400917)		1407107
217	07/08/2022	1056181		VEHICLE SAFETY INSPECTION	1403180
217	07/08/2022	1056181		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1399664
217	06/15/2022	1051819	Wheels and Tyres Wheel Nut Retension	rententioned to spec	1399664
217	06/15/2022	1051903	Mechanic entered - Wheels and Tyres Worn p6	Refer Job # 1051745	1399664
217	06/15/2022	1051819	Consumables		1399664
217	06/15/2022	1051903	Consumables		1399664
217	06/14/2022	1051537	Mechanic entered - Wheels and Tyres Worn p6 tyre worn	checked tyre 2mm tread	1399664
217	06/14/2022	1051745	Mechanic entered - Wheels and Tyres Worn p6	fitted 2 recaps and tensioned to 600nm	1399664
217	06/14/2022	1051745	TYRE 295/80R22.5 RECAP		1399664
217	06/14/2022	1051537	Consumables		1399664
217	06/14/2022	1051745	Consumables		1399664
217	06/14/2022	1051523	Mechanic entered - Body Front_Door Operation Faulty front do	sensiotive edge put back in correctly and checked	1399664
217	06/14/2022	1051523	Consumables		1399664
217	06/06/2022	1050243	Mechanic entered - Elec and Light Interior Lights	Check all interior and exterior lighting and no fault found	1398088
217	06/06/2022	1050243	Consumables		1398088
217	05/27/2022	1048696		CARRY OUT A SERVICE AS PER CHECK LIST Carry out A service as per list	1396600
217	05/27/2022	1048696		Assisting	1396600
217	05/27/2022	1048696	Consumables		1396600
217	05/27/2022	1048696	Consumables		1396600
217	05/27/2022	1048696	Consumables		1396600
217	05/27/2022	1048696	Consumables		1396600
217	05/17/2022	1046598		VEHICLE SAFETY INSPECTION	1394020

217 05/17/2022 1046598	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1934020
217 05/17/2022 1046660 PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID-19 DECAL REMOVED	Completed.	1940420
217 05/14/2022 1045541 Apply Print Film	Completed 22/4/22	1940420
217 05/11/2022 1045541 Apply print film L1L3LAR3A	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:#PE321251 Receiving #:337308 Date :2022-05-12	1904777
217 04/08/2022 1039650 Retension P3-P4 wheel nuts to 600NM	retensioned p3p4 to spec.	1930042
217 04/08/2022 1039650 Consumables		1930042
217 04/06/2022 1039333 Mechanic entered - Wheels and Tyres Worn tyre at 2mm to be	removed and replaced N/S/R tyres	1898914
217 04/06/2022 1039333 TYRE 295/80R22.5 RECAP		1898914
217 04/06/2022 1039333 Consumables		1898914
217 03/30/2022 1038046 O-RING KIT SMALL VOSS(A6739971748)		1888496
217 03/30/2022 1038046 VALVE DRAIN CONDENSOR MERC OSOOLE(A0054327401)		1888496
217 03/30/2022 1038046 DRYER AIR ASSY MERC OSOOLE(A0004302915)		1888496
217 03/30/2022 1038046	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1888496
217 03/30/2022 1038046 O-RING KIT LARGE VOSS(A6739970145)		1888496
217 03/18/2022 1035572 DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:#PE317970 Receiving #:333524 Date :2022-03-21	1866656
217 03/17/2022 1035572 VEHICLE SAFETY INSPECTION		1857777
217 03/17/2022 1035572 TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1857777
217 03/17/2022 1035572 ANNUAL SAFETY INSPECTION SERIAL # _____ 043071 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	done	1857777
217 03/09/2022 1034139 Mechanic entered - Wheels and Tyres Other i roman painted th	completed	1857777
217 03/09/2022 1034138 Wheels and Tyres paint wheel rims		1857777
217 03/09/2022 1034138 Consumables		1857777
217 03/09/2022 1034139 Consumables		1857777
217 03/09/2022 1034138 final RSI		1857777
217 03/09/2022 1034138 Consumables		1857777
217 03/09/2022 1034138 Air System Air_Leaks suspension leaning		1857777
217 03/09/2022 1034274 Mechanic entered - Air System Air_Leak Rear Protection valae	Replaced the valve and tested.OK.	1857777
217 03/09/2022 1034274 VALVE CIRC PROTECTION KNORR BREMSE MERC OSOOLE		1857777
217 03/08/2022 1033848	PRE ANNUAL SAFETY INSPECTION CHECK Completed inspection and listed all defects. CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed. completed steam clean for rsi.	1857777
217 03/08/2022 1034034 steam clean for RSI		1857777
217 03/08/2022 1034034 Consumables		1857777
217 03/04/2022 1033286 Steering column play and covers loose	Remove covers and adjust column slides and refit covers correctly	185442
217 03/04/2022 1033287 Elec and Light focus head lamps	Align head lights	185442
217 03/04/2022 1033142 Mechanic entered - Elec and Light Warning Light On Dash Batt	repair by Lonsdale replaced battery cable between starter and alternator repaired all other wiring at alt old alt to have new + stud fitted	1860338
217 03/04/2022 1033142 repair alt wiring	Creditor #:PT-LONDALE ST AUTO ELECTRICS P/O #:#PE317309 Receiving #:332977 Date :2022-03-09	185442
217 03/04/2022 1033142 Consumables		185442
217 03/04/2022 1033287 Consumables		185442
217 03/03/2022 1033142 Mechanic entered - Elec and Light Warning Light On Dash Batt	Alternator +ve terminal burnt and wiring damaged Removed burnt alternator fitted new one. need to remove wiring and investigate.	185442
217 03/03/2022 1033142 ALTERNATOR 24V 140AMP MERC OSOOLE		185442
217 03/02/2022 1032807 Mechanic entered - Wipers and Washers Other o/s wiper rivets	replaced blades	185179
217 03/02/2022 1032807 WIPER BLADE ASSY 1000mm N10Z(TRP1000)		185179
217 03/02/2022 1032767 Mechanic entered - Elec and Light Exterior Lights replaced o	replaced n/s indicator and o/s high beam and adjusted.	185179
217 03/02/2022 1032767 LAMP CLEAR FRIT INDICATOR WRAP-AROUND		185179
217 03/02/2022 1032767 HEAD LAMP INSERT HELIX 90MM L/FLOOR 0500 (9314365038525)		185179
217 03/02/2022 1032767 Consumables		185179
217 03/02/2022 1032851 carry out RSI repairs	carry out repairs as per list	185179
217 03/02/2022 1032713 Mechanic entered - Body Other o/s twin seat strut weak	fitted new strut	185179
217 03/02/2022 1032713 STRUT GAS STAY 200NM 128mm LNG		185179
217 03/02/2022 1032713 Consumables		185179
217 03/02/2022 1032851 Consumables		185179
217 02/26/2022 1030494	CARRY OUT FIRE EXTINGUISHER TEST & TAG	183658
217 02/26/2022 1030494	done	183658
217 02/26/2022 1031684 REMOVE OLD 2020 DECALAND FIT NEW 2022 DECAL POSITION AS S	done	183658
217 02/25/2022 1031882 Drv entered - A/C Heating Not Cooling	all in good working order	184707
217 02/15/2022 1028935 Consumables		183020
217 02/15/2022 1028935 Body Windows Front repair chip	repaid by knights	182580
217 02/15/2022 1029048	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Completed by Csaba.	182580
217 02/14/2022 1028935 Windscreen repair	Creditor #:PT-KNI005 KNIGHTS WINDSCREEN PENINSULA P/O #:#PE316059A Receiving #:331518 Date :2022-02-16	181468
217 02/08/2022 1027455 Consumables		181468
217 02/08/2022 1027455 Mechanic entered - Body Other replace fuel filter P/N FS199	done	181468
217 02/04/2022 1026553 Mechanic entered - Wheels and Tyres Wheel Nut Retension P2	retensioned to specs.	180836
217 02/04/2022 1026553 Consumables		180836
217 02/04/2022 1026749 Mechanic entered - Gearbox Driveline Other diff pinion nut	within spec	180836
217 02/03/2022 1026380 Mechanic entered - Wheels and Tyres Worn p2 tyre at 3mm need	fitted new tyre	180836
217 02/03/2022 1026380 TYRE 295/80R22.5 NEW		180836
217 02/03/2022 1026380 Consumables		180836
217 02/03/2022 1026313	CARRY OUT C SERVICE AS PER CHECK LIST	180836
217 02/03/2022 1026313 FILTER FUEL MERCEDES(A5410900151)		180836
217 02/03/2022 1026313 FILTER STEERING(153468)(0153468)(349619)		180836
217 02/03/2022 1026313 FILTER AIR MERC OSOOLE(A0040941704)		180836
217 02/03/2022 1026313	assisted fin	180836
217 02/03/2022 1026313 FILTER OIL MERC(A0001801709)		180836
217 02/03/2022 1026313 FILTER FUEL FILTER MERCEDES BENZ (H233WK)		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836
217 02/03/2022 1026313 Consumables		180836</

217	01/15/2022	1022837	Mechanic entered - Wheels and Tyres Wheel Nut Retension p1	re tensioned pos 1	1377075
217	01/15/2022	1022837	Consumables		1377075
217	01/14/2022	1022647	Mechanic entered - Wheels and Tyres Worn p1 on 2mm	replaced tyre p1 with new tensioned to spec. and booked a retension	1377075
217	01/14/2022	1022647	TYRE 295/80R22.5 NEW		1377075
217	01/14/2022	1022647	Consumables		1377075
217	01/07/2022	1021336	Mechanic entered - Elec and Light Exterior Lights N/S/F park	reattached electrical connection	1375420
217	01/07/2022	1021336	Consumables		1375420
217	12/20/2021	1018378	AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE312984 Receiving #:328391 Date :2021-12-21	1372448
217	12/20/2021	1018831	Mechanic entered - Accident - NEAR SIDE REAR minor marks on	completed	1371312
217	12/16/2021	1018417	Wipers and Washers Wipers Loose to the body.	Welded the spindle tube to the body checked ok	1370988
217	12/16/2021	1018378	Drv entered - A/C Heating Not Cooling	repaired by 22	1370988
217	12/16/2021	1018378	Drv entered - A/C Heating Not Cooling	Assisting	1370988
217	12/16/2021	1018378	Ops Entered - Fault - A/C Heating Not Cooling - Route: 832	completed	1370988
217	12/16/2021	1018378	Drv entered - A/C Heating Not Cooling	completed	1370988
217	12/16/2021	1018417	Fluid Leaks Rear of busOil filter return lines starting	One hose was sweaty. Replaced both oil pipes checked for leaks ok	1370988
217	12/16/2021	1018417	HOSE OIL FILT HSG OIL COOL MERC 0500LE(A4571801620)		1370988
217	12/16/2021	1018417	HOSE OIL FILT HSG - OIL COOLER MERC BENZ 0500LE A4571801720		1370988
217	12/15/2021	1018006		VEHICLE SAFETY INSPECTION	1370988
217	12/15/2021	1018006		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1370988
217	12/15/2021	1018034	Mechanic entered - Wipers and Washers Washers Not Working	replaced washer pump	1370988
217	12/15/2021	1018034	PUMP WASHER 24 VOLT		1370988
217	12/09/2021	1016875	Back right Brake Light out	re wired new stop lamp to bus tested operation all in good working order	1370111
217	12/09/2021	1016875	Consumables		1370111
217	12/09/2021	1016881	Mechanic entered - Body Other n/s/r wheelarch panel loose	fitted new claw to panel	1370111
217	12/09/2021	1016881	CATCH CLAW PLASMA ENGINE HATCH DOOR		1370111
217	12/09/2021	1016881	Consumables		1370111
217	12/08/2021	1016420	Fluid Leaks Rear of bus(1) repair a/c coolant copper pipe	Removed the AC heater lines repaired the leakFilled coolant and tested OK.	1370111
217	12/08/2021	1016420	Fluid Leaks Rear of bus(1) repair a/c coolant copper pipe	assisted jag in repairing coolant leak at ac copper heater pipes	1370111
217	12/07/2021	1016420	Fluid Leaks Rear of bus(1) repair a/c coolant copper pipe	secured bracket for header tank secured a/c cooling pipes to back wall removed clamps for roof heater pipes cut damaged pieces off and went to bunnings to get joiner pieced repaired pipes fit back secured pipes fit tank back fill coolant ran till hot still slight leak from repair.	1369901
217	12/07/2021	1016420	fittings for a/c piping	Creditor #PT-BUNNINGS BUNNINGS KNOX P/O #PE312351 Receiving #:327450 Date :2021-12-07	1370111
217	12/07/2021	1016420	fitting as required	Creditor #PT-AIRO01 AIR MAINTENANCE PTY LTD P/O #PE312333 Receiving #:327664 Date :2021-12-09	1370357
217	12/03/2021	1015772		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed as per check list	1369743
217	12/03/2021	1015772	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		1369743
217	11/27/2021	1014394	Mechanic entered - Fluid Leaks Rear of bus minor coolant lea	Nipped up clamp ok	1368384
217	11/26/2021	1014076	Mechanic entered - Elec and Light Reverse Buzzer n/w	tapped reverse buzzer and checked ok	1368384
217	11/26/2021	1014076	Consumables		1368384
217	11/25/2021	1013851	Drv entered - Steering Steering Wheel Faulty	1 tyre down to 50psi. pumped it up no other fault found	1368384
217	11/23/2021	1013356	Air System replace N/S front brake hose	Inspect brake pipes and found ok for service	1368089
217	11/19/2021	1012822	Mechanic entered - Brakes Foot_Brakes Leaking Air o/s/f brak	Inspected where leaking air was coming from found o/s/f brake hose to be split removed both hose connections and all cable ties / 8mm bolts holding brake hose. replaced with new brake hose and secured both abs sensor and pad wear sensor to the hose with spacers. tested for leaks all ok	1367935
217	11/19/2021	1012822	HOSE BRAKE RHF MERC BENZ 0500LE		1367935
217	11/19/2021	1012821	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C	completed	1367935
217	11/19/2021	1012802		CARRY OUT A SERVICE AS PER CHECK LIST completed service as per checklist.	1367935
217	11/19/2021	1012802	Consumables		1367935
217	11/19/2021	1012802	Consumables		1367935
217	11/19/2021	1012802	Consumables		1367935
217	11/19/2021	1012802	Consumables		1367935
217	11/15/2021	1011582	Mechanic entered - Elec and Light Exterior Lights front n/s/	removed n/s top park light and indicator light assembly repaired park light wiring replaced both park and indicator globes tested ok fitted back .	1367049
217	11/15/2021	1011582	Consumables		1367049
217	10/28/2021	1008150	Drv entered - A/C Heating Not Cooling	no fault found	1364287
217	10/22/2021	1006317	Fluid Leaks Rear of bus trans cooler pipe leaking replac	removed exhaust muffler and air cleaner intake hose and pipe to excess the transmission coolant pipe. Removed old trans coolant pipe eliminated all body sharp edges from rubbing with coolant pipe fitted new pipe fitted all other parts together test drive bus all good	1363295
217	10/22/2021	1006317	CLAMP P G/BOX COOLING PIPE MERC 0500LE		1363295
217	10/22/2021	1006317	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE SON0547G		1363295
217	10/20/2021	1006317	Fluid Leaks Rear of bus trans cooler pipe leaking repla	cooler	1362880
217	10/20/2021	1006317	A6345006772 TRANS COOLER PIPE	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE309197 Receiving #:324346 Date :2021-10-22 #368 IN DIA	1363295
217	10/18/2021	1006123		VEHICLE SAFETY INSPECTION Completed as per the checklist.	1362796
217	10/18/2021	1006123		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned to the specs.	1362796
217	10/16/2021	1004702	Apply Print Film	Completed 16/9/21	1361214
217	10/16/2021	1005898	Mechanic entered - Body Drivers Seat Controls Air switch bro	Fitted 2 new switch cover . Used parts from incomplete/ donot book kit from stock.	1361214
217	10/16/2021	1005898	Consumables		1361214
217	10/13/2021	1004702	Apply Print Film L112R1R2	Creditor #PT-GLAG10 GLASSPROTECH MELBOURNE P/O #PE308644 Receiving #:323720 Date :2021-10-14	1361836
217	10/12/2021	1004884	Mechanic entered - Elec and Light Indicators Not Working n/s	replaced globe and checked ok	1361214
217	10/12/2021	1004884	Consumables		1361214
217	10/02/2021	1003132	Mechanic entered - Elec and Light Exterior Lights O/S headli	replaced headlight globe and checked ok	1358934
217	10/02/2021	1003132	Consumables		1358934
217	09/13/2021	999252		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Could not complete the check list due to no training.	1355280
217	09/06/2021	996370	Fluid Leaks Rear of bus oil cooler gasket leak	Secured bus and lifted with hoists drained coolant and engine oil from oil cooler removed banjo bolts and mounting bolts removed cooler and old gasket cleaned oil cooler housing and matting surfaces fit new gasket and fit new copper washers to banjo bolts and coolant drain plug ran engine and filled up coolant and t	1353635
217	09/06/2021	996370	Fluid Leaks Rear of bus oil cooler gasket leak	done	1353635
217	09/05/2021	997155	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE306138 Receiving #:320689 Date :2021-09-02	1354117
217	09/01/2021	996370	GASKET OIL COOLER HOUSING MERC	VEHICLE SAFETY INSPECTION	1353375
217	08/31/2021	996101		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1353375
217	08/31/2021	996101		Replace 1 wiper insert and 1 wiper blade Repair washers	1353375
217	08/31/2021	996130	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc		1352780
217	08/31/2021	996130	WIPER REFILL 1000mm MULTI FIT (TRP1000)		1352780
217	08/31/2021	996130	WIPER BLADE ASSY 1000mm N102(TRP1000)		1352780
217	08/25/2021	994709		CARRY OUT A SERVICE AS PER CHECK LIST	1352780
217	08/25/2021	994709	Consumables		1352780
217	08/25/2021	994709	Consumables		1352780
217	08/25/2021	994709	Consumables		1352780
217	08/25/2021	994709	Consumables		1352780
217	08/25/2021	994709	Consumables		1352780
217	08/25/2021	994709	Consumables		1352780
217	07/27/2021	988150	Engine drain A/C comp seal and clean engine	completed	1347895
217	07/26/2021	987547	Elec and Light' can fault to taco	repaired wiring left off during demister job	1347546
217	07/26/2021	987547	Consumables		1347546
217	07/22/2021	987278	A/C Heating Demister Not Heating - No Air blowing from Dem	fitted new demister blower to bus checked all vents once completed found all in good working order	1347406
217	07/22/2021	987278	MOTOR A/C EVAPORATOR FAN		1347406
217	07/22/2021	987278	ADAPTOR 2 DEMISTER OUTLETS 11255		1347406
217	07/22/2021	987278	DEMISTER AIR DUCT 50MM I.D (PER METER)		1347406
217	07/22/2021	987330	Drv entered - A/C Heating Demister Not Heating	fitted new demister blower motor	1347406
217	07/19/2021	986173	carry out B service	Creditor #PT-22C001 22 CELSIUS P/O #PE303013 Receiving #:317260 Date :2021-07-20	1347050
217	07/16/2021	986173		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	1346336
217	07/16/2021	986173		Assisting	1346336
217	07/16/2021	986173		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1346336
217	07/15/2021	985843	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	completed	1346130
217	07/15/2021	985843	Consumables		1346130
217	07/14/2021	985553	Mechanic entered - Wheels and Tyres Other Removed wheels to	Removed the both front wheels to replace the tierod.fitted the tyres back and tensioned to the specs.	1345894
217	07/14/2021	985553	Consumables		1345894
217	07/14/2021	984942	Steering Excessive Play Slight play in tie rod joints	Replaced the complete tierod adjusted and tested OK.	1345894
217	07/14/2021	985546	Drv entered - A/C Heating Demister Not Heating	checked the demister works OK.	1345894

217	07/12/2021	984942	Steering Excessive Play Slight play in tie rod joints	foitted		1344520
217	07/12/2021	984942	TIE ROD ASSY MERC BENZ 0500LE	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE302605 Receiving #316762 Date :2021-07-13		1345687
217	07/08/2021	984457		VEHICLE SAFETY INSPECTION		1344520
217	07/08/2021	984457		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1344520
217	07/08/2021	984489		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST replaced air dryer and condenser and checked for air leaks no leaks found ok		1344520
217	07/08/2021	984489	AIR DRYER ASSY MERC BENZ 0500LE(A0004302915)			1344520
217	07/08/2021	984489	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE A0054327401			1344520
217	07/07/2021	984118	Drv entered - Wipers and Washers Washers Not Working	washer lines eaten by rats. replaced washer lines. working good.		1344520
217	06/24/2021	981763	Mechanic entered - Engine Belts_ Loose Noisy Missing Lower id	Found bolt broken in engine so fit new belt without lower pulley. Adjust and check ok. Road test ok		1341709
217	06/24/2021	981763	BELT MICRO V SERPENTINE BELT 3 RIB 2120mm LONG			1341709
217	06/24/2021	981763	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG			1341709
217	06/07/2021	978757	Camera 5 which records the internal rear section of the bus	Repositioned the camera ok		1339218
217	05/26/2021	976642	Vehicle Rework complete B service as per workorder.	steam cleaned engine top and bottom all ok		1337373
217	05/26/2021	976642	Consumables			1337373
217	05/25/2021	976386		CARRY OUT FIRE EXTINGUISHER TEST & TAG completed		1337244
217	05/25/2021	976361		CARRY OUT B SERVICE AS PER CHECK LIST completed		1337244
217	05/25/2021	976361	FILTER OIL FILTER MERCEDES A0001801709			1337244
217	05/25/2021	976361	OIL SAMPLE KIT CALTEX			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/25/2021	976361	Consumables			1337244
217	05/17/2021	974513	Mechanic entered - Wheels and Tyres Wheel Nut Retension OSR	retensioned to spec		1335626
217	05/17/2021	974513	Consumables			1335626
217	05/14/2021	974359		VEHICLE SAFETY INSPECTION completed		1335626
217	05/14/2021	974359		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed		1335626
217	05/14/2021	974359		replaced P5 and 6 tyres with 295 recaps and tensioned to spec		1335626
217	05/14/2021	974385	Mechanic entered - Wheels and Tyres Worn P5 and 6			1335626
217	05/14/2021	974385	TYRE 295/80R22.5 RECAP			1335626
217	05/14/2021	974385	Consumables			1335626
217	05/13/2021	972915	SIGN FRONT WHITE ULTIMA DEST	Creditor #PT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #PE296600-1 Receiving #312550 Date :2021-05-14 NEW TO REPLACE REFURBISH INV 0016358 TO BE RET FOR CREDIT		1335626
217	05/13/2021	972915	Consumables			1335626
217	05/10/2021	972915	Ops Entered - Fault - Desto Signs - not working driver tri	Replace faulty desto assy wire in and program and test operation		1334918
217	05/07/2021	972915	Ops Entered - Fault - Desto Signs - not working	Check power supply to desto rewired to suit desto has power but no operation		1334918
217	05/04/2021	972039	Mechanic entered - Engine Belts_ Loose Noisy Missing Rebuild	Replace bearings and seals in fan hub assy		1333681
217	05/04/2021	972039	TAPERED ROLLER BEARING			1333681
217	05/04/2021	972039	SEAL TENSIONER HUB M1095			1333681
217	05/04/2021	972163	Mechanic entered - Body Other o/s rear panel loose	secured rad panel.		1333681
217	05/04/2021	972163	Consumables			1333681
217	04/28/2021	970898	Accident# S1755 needs to be checked for unreported damage	no damage found		1332512
217	04/19/2021	968738	Mechanic entered - Elec and Light Exterior Lights OSF Indica	Replaced globe		1330292
217	04/19/2021	968738	Consumables			1330292
217	04/19/2021	968707	Left mirror arm moves at high speed need tighten	Secured the mirror arm		1330292
217	04/19/2021	968707	Consumables			1330292
217	04/19/2021	956015	repair acc # S1755	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE293652 Receiving #311185 Date :2021-04-28		1330292
217	04/17/2021	967787	Place new poster over the top attach hangers to hand rails	C		1330292
217	04/14/2021	967081	Ops Entered - Fault - Elec and Light - Route: 784 - Dunns R	Replaced with new desto programmed and checked the function ok		1330292
217	04/14/2021	968006	Mechanic entered - Elec and Light Other Desto is not working	Done on WDM967081		1330292
217	04/14/2021	967081	SIGN FRONT WHITE ULTIMA DEST	Creditor #PT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #PE296600 Receiving #310487 Date :2021-04-19 refurbished if available		1331241
217	04/14/2021	967081	UNIT CONTROL UNIT ICU 402	Creditor #PT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #PE296600 Receiving #310487 Date :2021-04-19		1331241
217	04/14/2021	967081	BATCH ADAPTER ICL400/402 MOBIT	Creditor #PT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #PE296600 Receiving #310487 Date :2021-04-19		1331241
217	04/14/2021	967081	Consumables			1331241
217	04/14/2021	968006	Consumables			1330292
217	04/09/2021	967081	Ops Entered - Fault - Elec and Light - Route: 784 - Dunns R	checked desto nothing ashowing on board unplugged desto checked for power to board no power at desto but to cable tried other desto control panels still not working need to new desto head board		1330292
217	04/08/2021	966608		Tappets adjusted when engine repairs carried out		1329709
217	04/08/2021	966608		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		1329709
217	04/08/2021	966677	Mechanic entered - Elec and Light Other n/s park light not w	replaced n/s park light globe ok		1329709
217	04/08/2021	966677	Consumables			1328551
217	04/03/2021	965561	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	C		1328551
217	04/01/2021	965697	Elec and Light Interior Lights - N/S Headlight out	replaced headlight bulb and outside door switch fitting		1328551
217	04/01/2021	965698	Drv entered - Elec and Light Exterior Lights	replaced headlight bulb		1328551
217	04/01/2021	965697	Consumables			1328551
217	04/01/2021	965698	Consumables			1328551
217	03/20/2021	961983	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI			1326160
217	03/18/2021	961458		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1326031
217	03/18/2021	961458		VEHICLE SAFETY INSPECTION		1326031
217	03/18/2021	961458		ANNUAL SAFETY INSPECTION SERIAL # L158196_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1326031
217	03/18/2021	961458	DIRECT PURCHASE - BUS INSPECTI	Creditor #PT-FLED10 FLEETCHECK BUS PTY LTD P/O #PE295293 Receiving #308564 Date :2021-03-19		1326160
217	03/18/2021	961493	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retensioned to spec.		1326031
217	03/18/2021	961493	Consumables			1326031
217	03/16/2021	960953	Mechanic entered - Wheels and Tyres Damaged P3 sidewall spli	Replace tyres P4 back to runout pile		1326031
217	03/16/2021	960953	TYRE 295/80R22.5 RECAP			1326031
217	03/16/2021	960953	Consumables			1326031
217	03/16/2021	960925	Mechanic entered - Body Other N/S/F Wheel arch panel loose.	Replace arch clip		1326031
217	03/16/2021	960909	Body (None) RSI Final and repairs			1326031
217	03/16/2021	960909	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1326031
217	03/16/2021	960909	HANDLE GRAB HARD PLASTIC PASSENGER (GREY)			1326031
217	03/16/2021	960909	Body (None) RSI Final and repairs			1326031
217	03/16/2021	960909	PAD BRAKE PEDAL RUBBER MERC BENZ 500LE A129710182			1326031
217	03/16/2021	960909	Consumables			1326031
217	03/16/2021	960925	Consumables			1326031
217	03/15/2021	960507	Body (None) RSI Steam Clean	steam cleaned and greased kingpins		1325630
217	03/15/2021	960507	Consumables			1325630
217	03/10/2021	959316	Ops Entered - Fault - Body Wheel Chair Ramp - Route: 833 -	adjusted sensor		1324739
217	03/10/2021	959316	Consumables			1324739
217	03/05/2021	958378	Suspension (None) Rear shock absorber leaking and steering	replaced rear shocks and steering shaft		1324599
217	03/03/2021	958317		PRE ANNUAL SAFETY INSPECTION CHECK		1324283
217	03/03/2021	958317		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1324283
217	03/03/2021	958317				1324283
217	03/03/2021	958378	50Y3040ZF SHOCK ABSORBER REAR	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE294404 Receiving #307569 Date :2021-03-04		1324599
217	03/03/2021	958378	Suspension (None) Rear shock absorber leaking and steerin			1324283
217	03/03/2021	958378	LINK ANGLE DRIVE - STRG BOX	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE294407 Receiving #307831 Date :2021-03-09		1325057
217	03/03/2021	958437	Mechanic entered - Body Other	fitted new shocks to rear secured 2 Interior poles repaired n/s rear air leaks replaced dash bulbs		1324283
217	03/03/2021	958428	Mechanic entered - Body Other o/s mudflap missing	replaced missing mudflap.		1324283
217	03/03/2021	958428	MUDFLAP 605MM X 330MM			1324283

217	03/03/2021	958428	Consumables			1324283
217	03/03/2021	958437	Consumables			1324283
217	03/02/2021	957143	Fluid Leaks sump gasket leaking			1324283
217	03/02/2021	957143	TUBE DIPSTICK TUBE MERC BENZ 0500LE 50A&205			1324283
217	03/02/2021	957143	BUSH ALTERNATOR MTG 12MM X 25MM X 37MM MERC 0500LE			1324283
217	03/02/2021	957143	FAN DRIVE SHAFT 0500 (A6295000882) (50N0929)			1324283
217	03/02/2021	957143	Fluid Leaks sump gasket leaking	removed sump and oil pickup pressure washed remaining oil and grime from sump all surfaces cleaned and inspected new gasket fitted with super glue to make sure of no tears while fitting sump back sump and oil pickup fitted back to motor run and no leaks found.		1324283
217	02/27/2021	956978	Keep oil poster in holder and place Travel off Peak and Sav	xx		1324283
217	02/27/2021	957053	Leave oil poster in and fit you must wear a maskover the	xx		1324283
217	02/26/2021	957143	Fluid Leaks sump gasket leaking			1324283
217	02/25/2021	957143	GASKET OIL SUMP 457942 MERC	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE294017 Receiving #:307197 Date :2021-03-01		1324598
217	02/23/2021	956015	Accident side panel			1323263
217	02/23/2021	956015	Accident side panel	Assisting		1323263
217	02/22/2021	955935	Ops Entered - Fault - Breakdown - Route: otoco_2 - Somerse	test drive to temp heavy use of retarder and temp stays under 80deg. Return to depot clean radiator. Found to be not dirty ok		1323263
217	02/18/2021	955141	Consumables			1323263
217	02/18/2021	955141	Mechanic entered - Wheels and Tyres Damaged cut in pos 3 tyr	checked tyre minor cut fine for use		1322416
217	02/18/2021	955285	FIRE SAFETY INSPECTION	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		1322416
217	02/17/2021	954767	Consumables	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE293483 Receiving #:306750 Date :2021-02-23		1323523
217	02/17/2021	954767	Consumables			1322996
217	02/17/2021	954767	Consumables			1322996
217	02/17/2021	954767	Consumables			1322996
217	02/17/2021	954767	Consumables			1322996
217	02/17/2021	954767	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Carry out A service as per checklist		1322416
217	02/10/2021	952464	Consumables			1321660
217	02/10/2021	952464	Mechanic entered - Elec and Light Indicators Not Working n/s	Replace faulty indicator assy		1321344
217	02/10/2021	952464	LAMP LED AMBER 177 X 100			1321344
217	02/10/2021	952475	Consumables			1321660
217	02/10/2021	952475	Mechanic entered - Body Drivers Seat Belt Buckle broken	Replace broken buckle		1321344
217	02/10/2021	952475	BULKIE WITH SEAT BELT LIGHT SWITCH 6860/875 (D9500979)			1321344
217	02/08/2021	951927	Roof unit leaking red coolant fluid	replaced A/C flex hoses on roof		1321343
217	02/08/2021	951875	Mechanic entered - Fluid Leaks Middle of bus coolant leak at			1321343
217	02/08/2021	951875	Ops Entered - Fault - Fluid Leaks Middle of bus - Route: RA	Remove a/c covers and locate coolant leak replace all hoses connecting heater cores pressurise system and check for leaks refill all covers run up and top up coolant		1321343
217	02/03/2021	950773	Consumables			1320832
217	02/03/2021	950773	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	retensioned all wheels		1320522
217	02/03/2021	950448	clean engine	washed engine and checked for leaks		1320522
217	02/03/2021	950242	50G8452KNORR LHR CALIPER	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE292191 Receiving #:305408 Date :2021-02-05		1321018
217	02/03/2021	950242	50G8452KNORR RHR CALIPER	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE292191 Receiving #:305408 Date :2021-02-05		1321018
217	02/03/2021	950242	SOCKET EXH BRAKE CYL MERC 05	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE292191 Receiving #:305408 Date :2021-02-05		1321018
217	02/03/2021	950242	50T0211 EXH BRAKE CYL STUD	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE292191 Receiving #:305408 Date :2021-02-05		1321018
217	02/03/2021	950243	Brakes replace both rear brake calipers....check rotors	checked rotors replaced caliprs and pads test run fine		1320522
217	02/02/2021	950506	Mechanic entered - Wheels and Tyres Worn p4 flat spot on rec	fitted runout tyre to replace p4		1320522
217	02/02/2021	950447	Consumables			1320808
217	02/02/2021	950449	Consumables			1320808
217	02/02/2021	950506	Consumables			1320808
217	02/02/2021	950447	Wheels and Tyres Noisy front when turning like at flat sp	p2 tyre changed on another workorder		1320522
217	02/02/2021	950449	Wheels and Tyres N/S front tyre side wall worn	tyre changed on another workorder		1320522
217	02/02/2021	950448	clean engine			1320522
217	02/02/2021	950242	Engine ex brake cylinder faulty			1320522
217	02/02/2021	950243	Brakes replace both rear brake calipers....check rotors	replaced exhaust brake cylinder		1320522
217	02/02/2021	950243	SET DISC PAD SET SCANIA / MERCEDES 0500			1320522
217	02/01/2021	950112		VEHICLE SAFETY INSPECTION		1320522
217	02/01/2021	950112		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1320522
217	02/01/2021	950133	Consumables			1320808
217	02/01/2021	950305	Consumables			1320808
217	02/01/2021	950133	Mechanic entered - Wheels and Tyres Worn p5 worn	fitted runout to p5		1320522
217	02/01/2021	950305	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	retensioned p5		1320522
217	02/01/2021	950307	Mechanic entered - Wheels and Tyres Damaged p1 sidewall dama	replaced both front tyres put 1 in the runout pile		1320522
217	02/01/2021	950307	TYRE 295/80R22.5 NEW			1320522
217	02/01/2021	950307	Consumables			1320808
217	02/01/2021	950242	Exhaust Brake Cylinder Mercedes	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE292191 Receiving #:305119 Date :2021-02-02		1320808
217	02/01/2021	950152	Mechanic entered - Brakes Foot_Brakes Leaking Air split nsf	replaced brake hose		1320522
217	02/01/2021	950152	BRAKE HOSE LHF MERC BENZ 0500LE			1320522
217	01/27/2021	949361	Consumables			1320235
217	01/27/2021	949361	Consumables			1320235
217	01/27/2021	949361	Ops Entered - Fault - Desto Signs - Route: 775 - Heatherhil	test driven around yard to find fault happend twice proceded to take desto back board off and desto control pannel off. followed wires from both control pannel and desto found loose connection on back of desto replaced connectors with new plugs restuck wires to back of desto tested works good.		1320088
217	01/22/2021	948695	Removed N/S/F window COVID-19 & MYKI decals and reposition o	removed old stickers refitted as per campaign.		1319223
217	01/15/2021	947107	Consumables			1318067
217	01/15/2021	947107	Consumables			1318067
217	01/15/2021	947107	Mechanic entered - Elec and Light Exterior Lights o/s/ft top	Replace light assy with led assy wire up and check operation		1317810
217	01/15/2021	947107	LAMP LED FRONT PARK LAMP WHITE			1317810
217	01/12/2021	945981	Ops Entered - Fault - Warning Lights Temperature - Route: 7	Replace broken fan idler hub		1316510
217	01/12/2021	945981	Consumables			1317041
217	01/12/2021	945981	Consumables			1317041
217	01/12/2021	945981	Desto external flickers and dim	checked ok		1316510
217	01/08/2021	945110	Suspension Leaning again			1315661
217	01/07/2021	945110	KIT O-RING SMALL VOSS (A0309971748)			1315438
217	01/07/2021	945110	KIT O-RING LARGE VOSS (A6739970145)			1315438
217	01/07/2021	945110	Suspension Leaning again	Replaced all orings on ECAS valve and several orings at air drier area.		1315438
217	01/05/2021	944576	KIT O-RING SMALL VOSS (A0309971748)			1315138
217	01/05/2021	944576	Suspension Leaning	Fixed air leaks at air drier area Checked ok		1315138
217	01/05/2021	944576	KIT O-RING LARGE VOSS (A6739970145)			1315138
217	01/05/2021	944278	Engine (None) Misfire	Repaired wiring on no4 injector ok		1315138
217	01/05/2021	944577	Consumables			1315150
217	01/05/2021	944577	Consumables			1315150
217	01/05/2021	944577	Div entered - Elec and Light AM-FM Radio	Replaced the radio ok		1315138
217	01/05/2021	944577	RADIO 12/24V 3' LCD MULTIMEDIA RECEIVER			1315138
217	01/04/2021	944278	Engine (None) Misfire	Bypass fuel tank pickup with external fuel container to pre filter. Run up and still had misfire. Replace filter and wash ready for further checks		1315138
217	01/04/2021	944278	FILTER FUEL FILTER MERCEDES BENZ (H233WK)			1315138
217	01/01/2021	929076	CONSUMABLE DELIVERY CHARGE	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304206 Date :2021-01-19 VOR		1318451
217	01/01/2021	929076	A0299977945 O-RING UNIT PUMP	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304210 Date :2021-01-19		1318451
217	01/01/2021	929076	A0239976548 O-RING / SEAL INI	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304210 Date :2021-01-19		1318451
217	01/01/2021	929076	INJECTOR O-RING MERC 0500	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304210 Date :2021-01-19		1318451
217	01/01/2021	929076	A0289978045 O-RING / SEAL FOR	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304210 Date :2021-01-19		1318451
217	01/01/2021	929076	A9060170860 COPPER NOZZLE SEAL	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:304210 Date :2021-01-19		1318451
217	12/23/2020	943030	Drv entered - Breakdown	Fause entry		1314447
217	12/17/2020	941882	Mechanic entered - Engine Other Overheating	Drain coolant replace faulty thermostats refill coolantn run up to tekp test drive and top up coolant		1313950
217	12/17/2020	941882	THERMOSTAT 71 DEG MERC 0405+0500LE A0032033275 A0042038475			1313950
217	12/17/2020	941882	O-RING THERMOSTAT MERC BENZ 0500LE A004997284801			13131350
217	12/17/2020	941882	HOSE COOLANT HOSE 90DEG TAPERED 60/70 MERC 0500LE 50N0543			1313350

217	12/17/2020	941972	Ops Entered - Fault - Eng Cool - Route: 760 - Carrum Downs	Re job no 941882	1313950
217	12/10/2020	940638	Drv entered - Engine Noisy or Rattling	could not fault	1311781
217	12/07/2020	939667		VEHICLE SAFETY INSPECTION	1310333
217	12/07/2020	939667		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1310333
217	12/07/2020	939667		assisted sri	1310333
217	12/07/2020	939683	Mechanic entered - Engine Belts_Loose Noisy Missing Fan hub	Replace bearings and seals	1310333
217	12/07/2020	939683	TAPERED ROLLER BEARING		1310333
217	12/07/2020	939683	SEAL TENSIONER HUB M1095		1310333
217	12/07/2020	939683	BEARING A/C CLUTCH BEARING		1310333
217	12/04/2020	938795	Gearbox Driveline Vibration - Driver reporting big vibrati	Replaced both top rear axle torque rod bushes and lower diff end bushes ok	1310333
217	12/04/2020	939465	Destination board flickering	Reprogrammed ok	1310333
217	12/04/2020	939465	Consumables		1313065
217	12/03/2020	938795	TOQUE ROD REAR UPPER 0500 (A63	Creditor #:PT-MUL001 MULTISPARES LTD P/O #PE288944 Receiving #:301520 Date :2020-12-04	1310829
217	12/02/2020	938795	BUSH RR TORQUE ROD MERC BENZ 0500LE A0003302011		1310333
217	12/02/2020	938795	Gearbox Driveline Vibration - Driver reporting big vibrati	Checked and found rear torque rod bushes u/s Replaced rear OS top torqued rod bushes.	1310333
217	12/02/2020	938795	Gearbox Driveline Vibration - Driver reporting big vibrati	assisted in replacing upper and lower torque rod bushes	1310333
217	12/01/2020	926478	CAMERA INTERNAL 2.1M	Creditor #:PT-TH005 THOREB AUSTRALIA PTY LTD P/O #PE285679 Receiving #:302246 Date :2020-12-15	1310665
217	11/26/2020	937081	Consumables		1310053
217	11/26/2020	937081	Elec and Light repair engine hatch safety switch	secured engine hatch safety switch with rivets and tested everything is in good working order	1309767
217	11/26/2020	937163		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked ok	1309767
217	11/26/2020	937281	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	completed	1309767
217	11/24/2020	936272	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed	1309197
217	11/23/2020	934870	Remove old poster and fit you must wear a face mask when t	xx	1308334
217	11/17/2020	933784	Fluid Leaks Rear of bus fuel leaking after filling up	replaced faulty hose clamp on fuel tank crossover hose	1307993
217	11/17/2020	933784	Ops Entered - Fault - Breakdown - Route: 771 - Langwarrin -	bus ran out of fuel was filled and returned to depot	1307993
217	11/16/2020	933215	HOSE COOLANT HOSE 900EG TAPERED 60/70 MERC 0500LE 50N0543		1307649
217	11/16/2020	933215	Ops Entered - Fault - Breakdown - Route: 780 - Frankston St	Found top engine elbow hose come off pipe. Replace with genuine hose. Fill coolant and roadtest to temp ok Wash engine of coolant	1307649
217	11/13/2020	929076	Ops Entered - Fault - Engine Low Power - Route: - Arrive S	replaced # 6 unit injector and all other o rings found fuel tank pick pipe blocked	1307649
217	11/10/2020	929076	CLUTCH ARMATURE A/C		1307649
217	11/10/2020	929076	FIELD CLUTCH A/C THERMOKING		1307649
217	11/09/2020	929076	A0239976548 O RING / SEAL INJ	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	INJECTION PUMP	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	CORE DEPOSIT	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	A0299977945 O-RING UNIT PUMP	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	INJECTOR O-RING MERC 0500	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	A028978045 O-RING / SEAL FOR	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	A9060170860 COPPER NOZZLE SEAL	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/09/2020	929076	INJECTOR LINE 0500LE A4600700	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE287104 Receiving #:299686 Date :2020-11-10	1307649
217	11/02/2020	929076	Ops Entered - Fault - Engine Low Power - Route: - Arrive S		1307649
217	11/02/2020	930389	Fit new Myki Decals & refit COVID-19 decals new position fo	fitted.	1307649
217	11/01/2020	929076	Monitor live data with scan to	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE284956 Receiving #:299620 Date :2020-11-10	1307649
217	10/30/2020	929076	ECU PIN / BUSH HOUSING MERC	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE286644 Receiving #:299049 Date :2020-10-30	1307649
217	10/30/2020	929076	Exhaust Brake Cylinder Mercedes	Creditor #:PT-MUL001 MULTISPARES LTD P/O #PE286590 Receiving #:299054 Date :2020-10-30	1307649
217	10/30/2020	929076	VALVE SOLENOID EXH BRAKE MER	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE286588 Receiving #:299050 Date :2020-10-30	1307649
217	10/28/2020	929076	FILTER FUEL FILTER MERCEDES 1418 (LATE)(WK1156/1 4601-F5)		1307163
217	10/28/2020	929076	FILTER FUEL MERCEDES (A5410900151)		1307163
217	10/28/2020	929076	BOWL CHASSIS FILTER MERC BENZ 0500LE A000477251601		1307163
217	10/28/2020	929076	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)		1307163
217	10/27/2020	928659	Mechanic entered - Elec and Light Exterior Lights R/H parker	Checked all lights:All works OK.	1307163
217	10/27/2020	928659	Consumables		1307649
217	10/27/2020	928779	Air System replace air comp intake hose	Replaced with new one	1307163
217	10/27/2020	928779	HOSE SUCTION AIR FILTER MERC 0500LE		1307163
217	10/27/2020	928791		CARRY OUT A SERVICE AS PER CHECK LIST	1307163
217	10/27/2020	928791	Consumables		1307649
217	10/27/2020	928791	Consumables		1307649
217	10/27/2020	928791	Consumables		1307649
217	10/19/2020	927290	Mechanic entered - Wheels and Tyres Wheel Nut Retension p3	retensioned p34 & p56 to spec.	1305764
217	10/19/2020	927290	Consumables		1306055
217	10/16/2020	926678	Mechanic entered - Elec and Light Interior Lights Replace fr	Replaced 4 saloon lights	1305230
217	10/16/2020	926678	Consumables		1305522
217	10/16/2020	926678	LED INTERIOR LAMP GREY (also refer 33531)		1305230
217	10/16/2020	926503	Body interior A/C ducting to be refitted lower sections t	Removed all the ac ductings revited the bottom section to the body. washed and refitted the ac ducts. Replaced the Rear door upper panel.	1305230
217	10/16/2020	926503	Body interior A/C ducting to be refitted lower sections t		1305230
217	10/16/2020	926502	Body cut bigger slot in floor for air compssor intake hose	Completed	1305230
217	10/16/2020	926502	Consumables		1305230
217	10/16/2020	926502	Consumables		1305522
217	10/16/2020	926503	Consumables		1305522
217	10/16/2020	926503	Consumables		1305522
217	10/15/2020	926478	CCTV replace three cameras	replaced	1305230
217	10/15/2020	926502	suction hose 30mm i.d. airpipe	Creditor #:PT-ENZED ENZED DANDENONG P/O #PE285716 Receiving #:298226 Date :2020-10-19	1305764
217	10/15/2020	926502	Body cut bigger slot in floor for air compssor intake hose		1305230
217	10/14/2020	926308	Mechanic entered - Wheels and Tyres Other re oiled wheel nut	re oiled all rear wheel nuts and retensioned to spec.	1305230
217	10/14/2020	926308	Consumables		1305522
217	10/14/2020	926115	HORN 24V		1305230
217	10/14/2020	926115	Mechanic entered - Elec and Light Horn	Trace to and replace faulty horn	1305230
217	10/14/2020	926115	Consumables		1305522
217	10/14/2020	926249	CCTV Rear Camera has been broken	Replace broken rear camera and test ok	1305230
217	10/07/2020	924506	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	etag fitted.	1303189
217	09/29/2020	922785		VEHICLE SAFETY INSPECTION Completed.	1301326
217	09/29/2020	922785		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1301326
217	09/29/2020	922836	Mechanic entered - Wheels and Tyres Flat or Leaking p6 tyre	Checked all pressures OK.	1301326
217	09/29/2020	922836	Consumables		1301710
217	09/29/2020	922837	BusMinder Unable To Log In - keeps re booting - jo	Checked and tested working OK.	1301326
217	09/29/2020	922837	Consumables		1301710
217	09/29/2020	922796	Mechanic entered - Brakes Foot_Brakes Leaking Air O/S/F diap	Replaced and tested.OK.	1301326
217	09/29/2020	922796	DIAPHRAGM TYPE 20 D SHAPE		1301326
217	09/25/2020	921733	See w/o921738		1300944
217	09/25/2020	921684	See w/o921738		1300944
217	09/25/2020	921737	See w/o 921738		1300944
217	09/24/2020	921735	Fluid Leaks Rear of busrepair transmission oil leaks	Cleaned the breather washed the gearbox ok	1300741
217	09/24/2020	921736	Fluid Leaks Rear of bus repair engine oil leaks		1300741
217	09/24/2020	921994	Mechanic entered - Engine Other Rear engine start switch not	Replaced the switch. ok	1300741
217	09/24/2020	921994	SWITCH STOP/START REAR 0500		1300741
217	09/24/2020	921734	GASKET AIR COMPRESSOR MT MERCEDES 0500LE		1300741
217	09/24/2020	921734	Air System oily diagnose air compressor		1300741
217	09/24/2020	921734	AIR COMPRESSOR VOITH MERC BENZ 0500LE		1300741
217	09/23/2020	921735	Fluid Leaks Rear of busrepair transmission oil leaks		1300741
217	09/23/2020	921736	Fluid Leaks Rear of bus repair engine oil leaks	Replaced the compressor gasket ok	1300741
217	09/23/2020	921734	Air System oily diagnose air compressor	Checked and found compressor output line is oily input is clean.Replaced with new one returned the faulty one to store for warranty	1300741

217 09/23/2020 921738 Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	1300741
217 09/23/2020 921738	Assisting	1300741
217 09/23/2020 921688	Could not complete the check list due to no training.	1300741
217 09/23/2020 921688	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1300741
217 09/23/2020 921686	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1300741
217 09/23/2020 921686		1300741
217 09/23/2020 921686		1300741
217 09/23/2020 921686		1300741
217 09/23/2020 921686 KIT O-RING LARGE VOSS (A6739970145)		1300741
217 09/23/2020 921686 VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		1300741
217 09/23/2020 921686 KIT O-RING SMALL VOSS (A0309971748)		1300741
217 09/22/2020 919602 Accident # 51142. O/S panel damage		1300741
217 09/22/2020 919602 Accident # 51142. O/S panel damage	Assisting	1300741
217 09/22/2020 919602 repair acc # 51142	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE283593 Receiving #:296490 Date :2020-09-23	1300741
217 09/08/2020 918500 Drv entered - Gearbox Driveline Rough Gear Change		1299990
217 09/08/2020 918500 FILTER FUEL FILTER HEAD (A00)	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE283198 Receiving #:295596 Date :2020-09-09	1300173
217 09/08/2020 918500 Engine fuel starvation/ex brake butterfly/engine smokes whe	Replaced the filter housing and the filter and tested.	1299990
217 09/08/2020 918500 FILTER FUEL FILTER MERCEDES 1418 (LATE)(WK1156/J 4601-F5)	Checked the Prim Fuel filter and primer faultyBypassed and sent for service as the parts being ordered.	1299990
217 09/07/2020 918500 Drv entered - Gearbox Driveline Rough Gear Change		1299741
217 09/07/2020 918500 Engine fuel starvation/ex brake butterfly/engine smokes whe		1299741
217 09/01/2020 916001 apply print film L1 L2 L4 R	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE282358 Receiving #:295142 Date :2020-09-02	1298577
217 09/01/2020 917425 Mechanic entered - Gearbox Driveline Other Not kicking down	checked transmission for gear changed kickdown and temps oil level. All in working order	1298289
217 08/29/2020 916001 Apply print film	xx	1296852
217 08/20/2020 877688 SEAL FRONT COVER ZF G/BOX	Part used was a non stock item from the Seaford Cupboard	1295986
217 08/15/2020 913720 Handbrake cover broken and is quite sharp when realising han	fitted new park brake vavve and tested ok	1293977
217 08/15/2020 913971 VALVE PARK BRAKE VALVE MERCEDES BENZ O500LE (A0034307581)		1293977
217 08/15/2020 913971 Air System replace hand brake valve	xx	1293977
217 08/15/2020 912939 Remove old A3 Poster and fit with You can no longer top up	Remove boot from lever and cover hole and replace awaiting parts	1293977
217 08/14/2020 913720 Handbrake cover broken and is quite sharp when realising han	Checked all lights no faulty lights found.	1294545
217 08/06/2020 911397 Mechanic entered - Elec and Light Interior Lights		1293004
217 08/06/2020 911397 Consumables		1293409
217 08/05/2020 911226 Body grab handles broken	relpaced 5x grab handles	1293004
217 08/05/2020 911226 Body seat mount crack N/S behind rear door	welded cracks in seat base	1293004
217 08/05/2020 911226 Body panel over rear door broken	SERVICEABLE	1293004
217 08/05/2020 911226 HANDLE GRAB HARD PLASTIC PASSENGER (GREY)		1293004
217 08/05/2020 911226 Consumables		1293120
217 08/05/2020 911226 Consumables		1293120
217 07/31/2020 910231	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tension all nuts to spec	1291964
217 07/31/2020 910231	VEHICLE SAFETY INSPECTION Carry out inspection as per sheets	1291964
217 07/31/2020 910277 clean engine	degreased and cleaned.	1291964
217 07/31/2020 910277 clean engine		1291964
217 07/31/2020 910276 Ops Entered - Fault - Air System Air_Leak Interior - Route:	Inspect air system and found no fault	1291964
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102		1291964
217 07/31/2020 910102 FILTER AIR FILTER MERCEDES BENZ (C27-1170)		1291964
217 07/31/2020 910102 REFLECTOR AMBER HELLA 94x44mm		1291964
217 07/31/2020 910102	CARRY OUT C SERVICE AS PER CHECK LIST completed abc service	1291964
217 07/31/2020 910102		1291964
217 07/31/2020 910102 FILTER OIL FILTER MERCEDES A0001801709		1291964
217 07/31/2020 910102 FILTER STEERING FILTER (153468) (0153468)(349619)		1291964
217 07/31/2020 910102 FILTER FUEL MERCEDES (A5410900151)		1291964
217 07/31/2020 910102 FILTER FUEL FILTER MERCEDES 1418 (LATE)(WK1156/J 4601-F5)		1291964
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables	CARRY OUT B SERVICE AS PER CHECK LIST	1291964
217 07/31/2020 910102		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102 Consumables		1292431
217 07/31/2020 910102	CARRY OUT A SERVICE AS PER CHECK LIST	1291964
217 07/15/2020 906722 Mechanic entered - Wheels and Tyres Wheel Nut Retension p3p	retentioned wheels p3p4 to spec	1291964
217 07/15/2020 906722 Consumables		1288460
217 07/14/2020 906605 TYRE 295/80R22.5 NEW		1288460
217 07/14/2020 906605 Ops Entered - Fault - Wheels and Tyres Noisy - Route: - Ar	replaced p3 wheel tightend to spec.	1288460
217 07/14/2020 906605 Consumables		1288460
217 07/13/2020 906127 Mechanic entered - Accident - NEAR SIDE FRONT N/SR marker II	Replace lamp and reflector	1288561
217 07/13/2020 906117 LAMP LED SIDE LAMP RED/AMBER PERE1 (52-98002)		1287123
217 07/13/2020 904361 AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE278675 Receiving #:291304 Date :2020-07-15	1287123
217 07/08/2020 905413 Drv entered - A/C Heating Demister Not Heating	Checked and testedboth demister and the Ac are heating up OK.	1285651
217 07/02/2020 904361	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1284670
217 07/02/2020 904361	Assisting	1284670
217 06/25/2020 903022 LED DOWNLIGHT ROUND ENT DOOR		1282544
217 06/25/2020 903022 door light on	Replaced the blown halegon globe with a Led downlight and tested Ok	1282544
217 06/25/2020 903022 Consumables		1283152
217 06/22/2020 902278	VEHICLE SAFETY INSPECTION completed	1282129
217 06/22/2020 902278	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	1282129
217 06/20/2020 902020 Fit A3 Poster in poster frame and fit decals as requested I	xx	1281404
217 06/15/2020 900782 Drv entered - Elec and Light Exterior Lights	Replaced globe	1279316
217 06/15/2020 900782 Consumables		1280562
217 06/11/2020 898100 repair hole in body	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE276734 Receiving #:288888 Date :2020-06-12	1279316
217 06/11/2020 898100 Consumables		1279316
217 06/10/2020 899612	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1278902
217 06/10/2020 899612 Consumables		1279018
217 06/10/2020 899612 Consumables		1279018
217 06/10/2020 899612 Consumables		1279018
217 06/10/2020 899612 Consumables		1279018
217 06/07/2020 898738 Drv entered - Vandalism/Vandalism/ Graffiti Interior	done	1276943
217 06/02/2020 898100 Bodyrepair hole in body	repaired by ectb	1276157
217 06/02/2020 898100 Bodyrepair hole in body	Assisting	1276157
217 06/02/2020 897984	CARRY OUT FIRE EXTINGUISHER TEST & TAG fire extinguisher test and tag completed	1276157
217 05/29/2020 897256 AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE276454 Receiving #:288280 Date :2020-06-03	1276554
217 05/28/2020 897256 A/C comp not kicking in	REPAIRED BY 22	1275735
217 05/28/2020 897256 A/C comp not kicking in	Assisting	1275735
217 05/28/2020 897141 TANK COOLANT HEADER MERC BENZ 0405NH O500LE		1275735
217 05/28/2020 897141 Fluid Leaks Rear of bus header tank leaking	replaced by 22	1275735
217 05/27/2020 896847 Breakdown Belts Pulleys & Idler BearingsSmall and sound	Remove all belts and check pulleys replace 3 idler pulleys and dismantle a/c compressor clutch and pulley assy replace seized bearings and fit new magnet and clutch refit all belts run and check operation	1275596
217 05/27/2020 896847 PULLEY IDLER/ ADJUSTER MERC BENZ O500LE A000501833		1275596
217 05/27/2020 896847 BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG		1275596

05/27/2020	896847	mechine pulley	Creditor #PT-HMG001 HM GEN ENGINES P/O #PE276282 Receiving #:287797 Date :2020-05-08	1275735
217	05/25/2020	896286	Body Windows SideSide NS mirror hanging a little and can	1274676
217	05/25/2020	896286	Consumables	1275334
217	05/22/2020	895738	Mechanic entered - Engine Other topped up 5L coolant no vis	1274676
217	05/22/2020	895738	drain coolant from air system replace dryer filter	1274676
217	05/22/2020	895738	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE	1274676
217	05/22/2020	895738	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE	1274676
217	05/22/2020	895738	KIT O-RING SMALL VOSS (A0309971748)	1274676
217	05/22/2020	895738	AIR DRYER ASSY MERC BENZ 0500LE A0004302915	1274676
217	05/22/2020	895738	SILENCER AIR VALVE CLIP ON 6MM 432-407-070-0	1274676
217	05/22/2020	895738	KIT O-RING LARGE VOSS (A6739970145)	1274676
217	05/21/2020	895738	Mechanic entered - Engine Other topped up 5L coolant no vis	1274676
217	05/21/2020	895738	PIPE COOLANT VOITH COMPRESSOR - BLOCK 0500LE	1274676
217	05/21/2020	895738	GASKET AIR COMPRESSOR MT MERCEDES 0500LE	1274676
217	05/21/2020	895738	drain coolant from air system replace dryer filter	1274676
217	05/21/2020	895738	AIR COMPRESSOR VOITH MERC BENZ 0500LE	1274676
217	05/19/2020	895095	Ops Entered - Fault - Body Drivers Seat Belt - Route: - Ar	1274107
217	05/19/2020	895095	Consumables	1274676
217	05/18/2020	894834	Ops Entered - Fault - Warning Lights Temperature - Route: 7	1274107
217	05/07/2020	892733	Fluid Leaks Rear of bus radiator leaking	1271664
217	05/07/2020	892733	Fluid Leaks Rear of bus radiator leaking	1271664
217	05/07/2020	892733	FITTING BLEEDER FITTING RADIATOR	1271664
217	05/07/2020	892733	RADIATOR TOP MOUNT MERC BENZ 0500LE A000987043901	1271664
217	05/07/2020	892733	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615	1271664
217	05/07/2020	892733	BELT FAN DRIVE MERC 0500LE A0139971992	1271664
217	05/07/2020	892733	RADIATOR MERCEDES 0500 NO FRA	1272034
217	05/07/2020	892733	FAN SHROUD (50N0104)	1271664
217	05/06/2020	892646		1271664
217	05/06/2020	892646		1271664
217	05/06/2020	892733	Fluid Leaks Rear of bus radiator leaking	1270365
217	05/01/2020	891595	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	1269814
217	05/01/2020	891595	Consumables	1269814
217	04/18/2020	888077	A4 notification to be printed off in colour laminated and	1265701
217	04/09/2020	887135	Drv entered - Body Front Door Operation FaultyAir leak at	1265701
217	04/09/2020	887135	VALVE CLIPPARD DOOR VALVE 11916-2	1265701
217	04/09/2020	887135	VALVE CLIPPARD DOOR OPEN/CLOSE 11916-2 BUTTON	1265701
217	04/09/2020	887135	Consumables	1266079
217	04/07/2020	886731	Drv entered - A/C Heating Not Cooling	1265316
217	04/04/2020	885275	Apply print film	1263304
217	04/01/2020	885275	Apply print film L3 R2	1263969
217	04/01/2020	877313	Seal crankshaft rear - fluoid	1270074
217	03/31/2020	885227	Fluid Leaks Rear of bus N/5 rear hub seal leaking...third	1263304
217	03/31/2020	885227	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)	1263304
217	03/31/2020	885227	KIT O-RING LARGE VOSS (A6739970145)	1263304
217	03/26/2020	884335		1263103
217	03/26/2020	884333		1263103
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/26/2020	884333	Consumables	1263304
217	03/25/2020	883683	Mechanic entered - Wheels and Tyres Damaged P1 sidewall worn	1262256
217	03/25/2020	883683	TYRE 295/80R22.5 NEW	1262256
217	03/25/2020	883683	Consumables	1263103
217	03/25/2020	883683	Consumables	1263103
217	03/25/2020	883684	Mechanic entered - Dash Switches Not Working gear selector j	1262256
217	03/25/2020	883684	GEAR SELECTOR ZF	1262256
217	03/25/2020	883684	Consumables	1263103
217	03/25/2020	883684	Consumables	1263103
217	03/24/2020	883433	Tap off front Seats of All Route and Rail Buses with spec	1262256

217	03/12/2020	880048	Consumables			1260250
217	03/12/2020	880048	Consumables			1260250
217	03/12/2020	880079	Hazard indication not working	Check hazard operation and no fault found		1260102
217	03/12/2020	880079	Consumables			1260250
217	03/12/2020	880079	Consumables			1260250
217	03/12/2020	880048	Steam clean for RSI			1260102
217	03/12/2020	880048	Consumables			1260250
217	03/12/2020	880048	Consumables			1260250
217	03/12/2020	880048	Consumables			1260250
217	03/12/2020	880048	Consumables			1260250
217	03/11/2020	879785	Fluid Leaks: Rear of bus n/s rear hub seal leaking			1259956
217	03/11/2020	879785	Fluid Leaks: Rear of bus n/s rear hub seal leaking	Fitted P34 tyres. Hub seal and rest of the jobs done by other mechanics.		1259956
217	03/11/2020	879785	Fluid Leaks: Rear of bus n/s rear hub seal leaking			1259956
217	03/11/2020	879785	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)			1259956
217	03/10/2020	877688	trans torque convertor seal leaking	REPLACE TORQUE CONVERTER SEAL AS REQUESTED.		1259801
217	03/10/2020	877319	carry out RSI repairs			1259801
217	03/10/2020	877319	carry out RSI repairs	secured modesty panels seats and indicator stalk. replaced exit lamp.		1259801
217	03/10/2020	877313	Fluid Leaks: Rear of busengine rear main leaking			1259801
217	03/10/2020	877313	Fluid Leaks: Rear of busengine rear main leaking	Assisting		1259801
217	03/10/2020	877319	LAMP LED NUMBER PLATE & EXIT LIGHT (Z50120) (Z559)			1259801
217	03/10/2020	877319	carry out RSI repairs			1259801
217	03/10/2020	877319	carry out RSI repairs	Assisting		1259801
217	03/10/2020	879325		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Carry out air service and replace voss o ring kits as nec		1259801
217	03/10/2020	879325	AIR DRYER ASSY MERC BENZ 0500LE A0004302915			1259801
217	03/10/2020	879325	KIT O-RING SMALL VOSS (A0309971748)			1259801
217	03/10/2020	879325	KIT O-RING LARGE VOSS (A6739970145)			1259801
217	03/10/2020	879325	SILENCER AIR VALVE CLIP ON 69MM 432-407-070			1259801
217	03/06/2020	877688	trans torque convertor seal leaking	Remove trans - flywheel and rear main seal fit new seal and refit in reverse seal still leaking remove again and inspect found seal incorrect await parts fit seal runner to flywheel and refit trans in reverse test drive and recheck all fluid levels		1259801
217	03/06/2020	877313	49A0002 WEAR RING - REAR MAIN	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE269542 Receiving #281467 Date :2020-03-06 PICK UP		1259801
217	03/06/2020	877313	Fluid Leaks: Rear of busengine rear main leaking	Remove trans and replace rear main seal refit in reverse		1259801
217	03/06/2020	877319	carry out RSI repairs	Complete rsi repairs as per checklist		1259801
217	03/05/2020	877688	trans torque convertor seal leaking			1259618
217	03/04/2020	877688	trans torque convertor seal leaking			1259618
217	03/04/2020	877688	HOSE ELBOW RADIATOR MERC 0500LE A0008321794			1259618
217	03/03/2020	878304	Mechanic entered - Wheels and Tyres Flat or Leaking p4 LEAKI	replaced pos 4 leaking		1259618
217	03/03/2020	878304	TYRE 295/80R22.5 RECAP			1259618
217	03/03/2020	878304	Consumables			1259801
217	03/03/2020	878304	Consumables			1259801
217	03/03/2020	877688	SEAL FRONT COVER ZF G/BOX			1259618
217	03/03/2020	877319	carry out RSI repairs			1259618
217	03/03/2020	878253	Mechanic entered - Fluid Leaks Rear of bus n/s hub seal leak	replaced n/s rear hub seal		1259618
217	03/03/2020	878253	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)			1259618
217	03/03/2020	877319	HOSE INTERCOOLER PIPE MERC BENZ 0500LE			1259618
217	03/03/2020	877319	BUSH RUBBER SLEEVE RADIATOR - 0500LE A0009872143			1259618
217	03/03/2020	877313	HOSE 120MM 50X60 50N0547	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE270272 Receiving #281441 Date :2020-03-06		1259801
217	03/02/2020	877313	SEAL RR CRANKSHAFT 447.971 MERC BENZ 0405NH A0139971447			1259618
217	03/02/2020	877313	Fluid Leaks: Rear of busengine rear main leaking			1259618
217	03/02/2020	877319	carry out RSI repairs			1259618
217	03/02/2020	877319	REFLECTOR AMBER HELLA 94x44mm			1259618
217	03/02/2020	877319	gasket paper	Creditor #PT-BURSON BURSON AUTOMOTIVE PTY LTD P/O #PE270122 Receiving #281166 Date :2020-03-03		1259801
217	03/01/2020	876983	FIRE SAFETY INSPECTION	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE269817 Receiving #281276 Date :2020-03-04		1259801
217	02/27/2020	877257		PRE ANNUAL SAFETY INSPECTION CHECK		1259618
217	02/27/2020	877257		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1259618
217	02/26/2020	876983		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		1259618
217	02/17/2020	874595		VEHICLE SAFETY INSPECTION Carry out inspection as per specs		1256620
217	02/17/2020	874595		tension wheel nuts to spec		1256620
217	02/17/2020	874682	SINGLE SEAT BASE			1256620
217	02/17/2020	874767	Drv entered - Body Drivers Seat Controls	adjust and lubricate seat back controls		1256620
217	02/17/2020	874682	Mechanic entered - Body Other Gas strut missing from disable	Carry out repairs as per list		1256620
217	02/17/2020	874682	STRUT GAS STAY 200Nm 128mm LONG			1256620
217	02/17/2020	874682	Consumables			1257959
217	02/17/2020	874682	Consumables			1257959
217	02/17/2020	874767	Consumables			1257959
217	02/17/2020	874767	Consumables			1257959
217	02/17/2020	874682	Consumables			1257959
217	02/17/2020	874682	Consumables			1257959
217	02/17/2020	874767	Consumables			1257959
217	02/17/2020	874767	Consumables			1257959
217	02/04/2020	871558	Fault#:#37319 - Ops Entered - Fault - Breakdown Passenger Do	mechanic did not attend driven back to workshop by driver The RPD controle box was inactive.Disabling all door operations.Rebooted and tsted.Works OK.		1253283
217	02/04/2020	861601	acc # 49360	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE264758 Receiving #278787 Date :2020-02-05		1253746
217	02/01/2020	866662	AIR CONDITIONING REPAIR	Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE266467 Receiving #280436 Date :2020-02-25		1259333
217	01/29/2020	869923	MIRROR GLASS CONVEX REPLACEMENT			1252040
217	01/28/2020	869923	Fault#:#37288 - Ops Entered - Fault - Breakdown Runout Of Fu			1250974
217	01/25/2020	869247	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRI	xx		1250974
217	01/23/2020	869086	Wipers n/s SPINDAL/ARM	Remove n/s spindle and repair. Refit and test ok		1250974
217	01/22/2020	868966	Front door cracked needs to be replaced - Incident #42252	done		1250974
217	01/22/2020	868966	Front door cracked needs to be replaced - Incident #42252	Assisting		1250974
217	01/22/2020	868966	Consumables			1251303
217	01/21/2020	868697		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed		1249443
217	01/20/2020	868305	Mechanic entered - Elec and Light Flat Batteries	Load test batteries and replace faulty batteries		1249443
217	01/20/2020	868305	BATTERY 110CCA POS ON LHS			1249443
217	01/20/2020	868305	Consumables			1250859
217	01/18/2020	867073	Apply Graffiti Film	xx		1249443
217	01/16/2020	867671	Mechanic entered - Wipers and Washers Wipers Loose	Repaired the spindle lock		1250131
217	01/15/2020	867283	Drv entered - Brakes Park_Brake Not Holding	replaced valve		1249443
217	01/15/2020	867283	VALVE PARK BRAKE VALVE MERCEDES BENZ 0500LE (A0034307581)			1248894
217	01/14/2020	867073	Apply Graffiti film	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE266530 Receiving #277547 Date :2020-01-21		1250859
217	01/13/2020	866662	Ring retain. Thermoking clutch			1248894
217	01/13/2020	866662	Fault#:#37237 - Ops Entered - Fault - Breakdown Not Starting	repairs by coachair		1248894
217	01/13/2020	866662	CLUTCH ARMATURE A/C			1248894
217	01/13/2020	866662	PULLEY A/C			1248894
217	01/13/2020	866662	FIELD CLUTCH A/C THERMOKING			1248894
217	01/13/2020	866662	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG			1248894
217	01/13/2020	866662	BEARING A/C 123087 5306-2RS	Creditor #PT-BSC001 BSC INDUSTRIAL SUPPLIES P/O #PE266420 Receiving #277041 Date :2020-01-15		1248899
217	01/13/2020	866662	Ring retain. Thermoking clutc	Creditor #PT-QTK001 QTK GROUP P/O #PE266425 Receiving #277336 Date :2020-01-20		1250859
217	01/08/2020	865697	Drv entered - Body Drivers Seat Controls	found broken driver seat control handle replaced ok. No other faults with seat all working good.		1247697
217	01/08/2020	865697	Consumables			1247733
217	01/08/2020	865784	Accident # 49460	DONE BY ETCB		1247697
217	01/08/2020	865784	Accident # 49460	Assisting		1247697

217	01/08/2020	865696		CARRY OUT B SERVICE AS PER CHECK LIST completed	1247697
217	01/08/2020	865696	FILTER OIL FILTER MERCEDES A0001801709		1247697
217	01/08/2020	865696	Consumables		1247733
217	01/08/2020	865696	Consumables		1247733
217	01/08/2020	865696	Consumables		1247733
217	01/08/2020	865695		CARRY OUT A SERVICE AS PER CHECK LIST completed	1247697
217	01/08/2020	865696		CARRY OUT A SERVICE AS PER CHECK LIST completed	1247697
217	01/08/2020	865695	Consumables		1247733
217	01/08/2020	865695	Consumables		1247733
217	01/08/2020	865695	Consumables		1247733
217	01/08/2020	865696	Consumables		1247733
217	01/08/2020	865696	Consumables		1247733
217	01/06/2020	865118	Mechanic entered - Elec and Light Exterior Lights Fr top ind	Removed/fixed the broken wires and tested.OK.	1246758
217	01/06/2020	865118	Consumables		1247697
217	01/04/2020	865028	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Retensioned to specs.	1246758
217	01/04/2020	865028	Consumables		1247231
217	01/03/2020	864889		VEHICLE SAFETY INSPECTION Completed.	1246758
217	01/03/2020	864889		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned to specs.	1246758
217	01/03/2020	864930	Mechanic entered - Wheels and Tyres Worn Pos4.	Replaced worn pos 4 and tensioned to the specs.	1246758
217	01/03/2020	864930	TYRE 295/80R22.5 RECAP		1246758
217	01/03/2020	864930	Consumables		1247231
217	01/03/2020	864890	Mechanic entered - Fluid Leaks Rear of bus coolant leak from	Removed and resealed the hose and tested OK.	1246758
217	01/03/2020	864896	Mechanic entered - Elec and Light Exterior Lights Front R/H	replaced q/s/f marker light and tested ok	1246758
217	01/03/2020	864896	Consumables		1247231
217	12/24/2019	863756	Accident # 50056 door glass & side window	DONE SATURDAY	1244171
217	12/23/2019	863756	Repair side window glass and d	Creditor #PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #PE265577 Receiving #:275926 Date :2019-12-27	1244635
217	12/17/2019	862367	Drv entered - Body Drivers Seat Controls	Checked all the operations and adjustments of the drivers seat and controls.No faults found.	1242636
217	12/17/2019	862367	Consumables		1242902
217	12/17/2019	862367	Consumables		1242902
217	12/13/2019	861601	Accident # 49360	REPLACED DOOR AND SIDE WINDOW GLASS	1241289
217	12/08/2019	859915	A3 Poster Frame Adhesive Decal Campaign please remove old	xx	1238158
217	12/07/2019	858835	CCTV 6 month service	xx	1238158
217	12/07/2019	858718	PERFORM CAMPAIGN 28/19 ROUTE BUS WHEELCHAIR TRIAL DECAL INS	xx	1238158
217	12/06/2019	860005		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1238390
217	12/02/2019	858835	6 months service	Creditor #PT-BWE001 BWERE ELECTRICS PTY LTD P/O #PE263939 Receiving #:274703 Date :2019-12-11	1241090
217	11/28/2019	857619	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSR	Completed	1237586
217	11/28/2019	857619	Consumables		1237892
217	11/25/2019	856752		VEHICLE SAFETY INSPECTION completed	1236783
217	11/25/2019	856752		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	1236783
217	11/25/2019	856801	Mechanic entered - Wheels and Tyres Worn P3	replaced P3 tyre with 295 Recap and tensioned to spec	1236783
217	11/25/2019	856801	TYRE 295/80R22.5 RECAP		1236783
217	11/25/2019	856801	Consumables		1237048
217	11/16/2019	855046	Mechanic entered - Elec and Light Other Rear camera vandals		1234656
217	11/16/2019	855046	Consumables		1235236
217	11/14/2019	854514	Mechanic entered - Elec and Light Exterior Lights number pla	re fitted light ass	1234126
217	11/14/2019	854514	Consumables		1234656
217	11/04/2019	852440	Mechanic entered - Elec and Light Exterior Lights N/S/f park	Replaced and tested.	1231221
217	11/04/2019	852440	Consumables		1232535
217	11/03/2019	852119		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1231221
217	11/03/2019	852119		xx	1231221
217	11/02/2019	851693	Apply print film for Graffiti	xx	1231221
217	11/02/2019	852376	BUCKLE SEAT BELT - TWIN WIRE GREY		1231221
217	11/02/2019	852376	Mechanic entered - Body Drivers Seat Belt buckle starting to	replaced drivers seatbelt buckle	1231221
217	11/02/2019	852376	Consumables		1231950
217	11/01/2019	851469	AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE261596 Receiving #:272117 Date :2019-11-12	1233862
217	11/01/2019	851469	AIR CONDITIONING REPAIR	Creditor #PT-22C001 22 CELSIUS P/O #PE261596 Receiving #:272103 Date :2019-11-12	1233862
217	10/31/2019	851469	Drv entered - A/C Heating Not Cooling	repaired by 22	1231221
217	10/31/2019	851469	Ops Entered - Fault - A/C Heating Not Heating - Route: 832		1231221
217	10/30/2019	851469	overhaul compressor	Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE261513 Receiving #:271574 Date :2019-10-31	1231454
217	10/30/2019	851418	Mechanic entered - Engine Other oil leak rear of engine	Inspect and report oil leak a/s/c compressor leaking to be repaired by contractor	1231221
217	10/30/2019	851471	REFLECTOR AMBER HELLA 9x44mm		1231221
217	10/30/2019	851471	Mechanic entered - Body Other n/s rear reflector missng		1231221
217	10/30/2019	851471	Consumables		1231221
217	10/30/2019	851371		CARRY OUT A SERVICE AS PER CHECK LIST Carry out A service as per sheet	1231221
217	10/30/2019	851371	Consumables		1231221
217	10/30/2019	851371	Consumables		1231221
217	10/30/2019	851371	Consumables		1231221
217	10/23/2019	851693	Apply print film for Graffiti	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE261574 Receiving #:271556 Date :2019-10-31	1231454
217	10/19/2019	849084	LAMP STOP/TAIL LED HELLA		1228978
217	10/19/2019	849084	Mechanic entered - Elec and Light Exterior Lights	replaced top rear tiltlight ass	1228978
217	10/19/2019	849084	Consumables		1229243
217	10/18/2019	848951		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1228978
217	10/15/2019	847997	Consumables		1228337
217	10/15/2019	847997	Mechanic entered - Elec and Light Exterior Lights F/LH park	replaced globe	1227139
217	10/12/2019	847682	Mechanic entered - Engine Other Coolant level low	checked adn topped up coolant ran bus for several minutes ok	1227139
217	10/11/2019	847513	Consumables		1227668
217	10/11/2019	847446	Consumables		1227668
217	10/11/2019	847513	Mechanic entered - Elec and Light Exterior Lights o/s park l	replaced park light globe ok replaced o/s park light globe o k	1227139
217	10/11/2019	847446	Mechanic entered - Dash Other coolant level saying low	checked coolant level and dash for faults ok	1227139
217	10/09/2019	846993	Consumables		1227139
217	10/09/2019	846993	Mechanic entered - Wheels and Tyres Wheel Nut Retension P56	done to spec	1226877
217	10/09/2019	847009	Consumables		1227139
217	10/09/2019	847009	Elec and Light myki repairs....needs hoist	Repaired	1226877
217	10/08/2019	846735		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1226724
217	10/08/2019	846735		VEHICLE SAFETY INSPECTION completed	1226724
217	10/08/2019	846769	Consumables		1226877
217	10/08/2019	846769	TYRE 295/80R22.5 RECAP		1226724
217	10/08/2019	846769	Mechanic entered - Wheels and Tyres Damaged cracked P5		1226724
217	10/08/2019	846769	Mechanic entered - Wheels and Tyres Damaged cracked P5	Replaced Tyre P5. torqued wheel nuts.	1226724
217	10/08/2019	846768	Consumables		1225724
217	10/08/2019	846768	W/ARCH RUBBER EXTRUSION		1225724
217	10/08/2019	846768	Mechanic entered - Body Other wheel arch nubser missing	fitted new	1226724
217	10/07/2019	846352	Consumables		1226724
217	10/07/2019	846352	Mechanic entered - Elec and Light Exterior Lights n/s park l	replaced park light globe all working	1225780
217	10/05/2019	846242	LOW WATER PROBE 500LE		1225780
217	10/05/2019	846242	Mechanic entered - Fluid Leaks Rear of bus coolant level fal	Tighten heater pipe clamp and replace header tank low coolant sensor top up coolant	1225780
217	10/05/2019	846233	Consumables		1225240
217	10/05/2019	846233	Drv entered - Elec and Light AM-FM Radio	Reset ok	1225780

217	10/05/2019	846233	Drv entered - Elec and Light AM-FM Radio	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE258584 Receiving #:269919 Date :2019-10-15	1225780
217	10/03/2019	843897	push to talk		1228073
217	10/02/2019	845397	Consumables	replaced bulb	1225572
217	10/02/2019	845397	Mechanic entered - Elec and Light Exterior Lights front lh i	very minor leak ok	1224590
217	09/30/2019	844914	Mechanic entered - Fluid Leaks Rear of bus coolant leak at p		1224590
217	09/23/2019	843897	PERFORM CAMPAIGN 21/19 PUSH TO TALK / BUS MINDER SECURITY C		1220903
217	09/20/2019	843575	Consumables		1221698
217	09/20/2019	843575	Drv entered - Elec and Light AM-FM Radio	no faults found	1220903
217	09/20/2019	843575	Elec and Light TAIL LAMP N/W	checked all tail lights and they were all in good working order	1220903
217	09/04/2019	840519	Consumables		1218270
217	09/04/2019	840119	Mechanic entered - Wheels and Tyres Flat or Leaking Pos2.	Removed and replaced the leaking valve and tested OK.	1217711
217	09/03/2019	839894	Consumables		1217913
217	09/03/2019	839894	Mechanic entered - Elec and Light Exterior Lights N/S Headli	Replaced both headLIGHT AND THE INDICATOR GLOBES.	1217711
217	09/02/2019	838211	Air System Air_Leak Rear brake relay valve leaking when b	Replace faulty relay valve and check operation	1217428
217	09/01/2019	838211	replace side window	Creditor #PT-ALP003 ALPHA BUS GLASS PTY LTD P/O #PE256744 Receiving #:268695 Date :2019-10-01	1224590
217	08/30/2019	838863	Vandalism SIDE WINDOW	alpha	1215797
217	08/30/2019	838211	Air System Air_Leak Rear brake relay valve leaking when		1215797
217	08/30/2019	838211	Air System Air_Leak Rear brake relay valve leaking when b		1215797
217	08/30/2019	830768	steel as required		1217711
217	08/30/2019	839264	Consumables	Creditor #PT-FRA010 FRANKSTON STEEL SUPPLIES PTY LTD P/O #PE255031 Receiving #:266370 Date :2019-09-03	1217428
217	08/30/2019	839264	Consumables		1217428
217	08/30/2019	839264	Consumables		1217428
217	08/30/2019	839264	Consumables		1215797
217	08/30/2019	839264	Consumables	completed as per check list	1215797
217	08/27/2019	838047		CARRY OUT A SERVICE AS PER CHECK LIST	1215797
217	08/27/2019	838047		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed.	1215797
217	08/27/2019	838047		VEHICLE SAFETY INSPECTION Completed.	1215797
217	08/27/2019	838211	VALVE RELAY VALVE RR MERC OS	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE256511 Receiving #:266135 Date :2019-08-30	1217205
217	08/26/2019	837633	Consumables		1216675
217	08/26/2019	837633	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s	retensioned o/s rear wheels	1215797
217	08/26/2019	837621	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7		1215797
217	08/22/2019	837135	Consumables		1216675
217	08/22/2019	837135	TYRE 295/80R22.5 RECAP		1215326
217	08/22/2019	837135	Mechanic entered - Wheels and Tyres Worn pos 6 at 2mm		1215326
217	08/22/2019	837044	SILENCER AIR VALVE 69MM (432-407-070-0)		1215326
217	08/22/2019	837044	KIT O-RING LARGE VOSS (A6739970145)		1215326
217	08/22/2019	837044	AIR DRYER ASSY A0004302915		1215326
217	08/22/2019	837044		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK UST Completed air service as per specs	1215326
217	08/22/2019	837044	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1215326
217	08/15/2019	835703	MIRROR L/H 380mm SHORT (UES1411E)	Replaced and adjusted.	1213700
217	08/15/2019	835703	Mechanic entered - Accident - MIRROR N/S smashed.	Creditor #PT-BWE001 BWERE ELECTRICS PTY LTD P/O #PE255393 Receiving #:264873 Date :2019-08-16	1213700
217	08/13/2019	835122	Video loss repair	xx	1213932
217	08/13/2019	835122	CCTV service		1211339
217	08/09/2019	834418	hole saw set	Creditor #PT-BUNNINGS BUNNINGS KNOX P/O #PE255082 Receiving #:264512 Date :2019-08-13	1213139
217	08/09/2019	834418	Wipers and Washers N/S wiper	Repair wier arm pivot replace wiper arm adjust and weld spindle to arm paint affected areas and repair washer fill tube after breakage	1212317
217	08/05/2019	833403	Drv entered - Brakes Foot_Brakes Pulling	Top pass on the brake test thereults attached to the job sheet.The temps are 108112122128 in 4 positions.Checked all braking components and performance no faults found.	1210834
217	08/05/2019	833403	Drv entered - Brakes Foot_Brakes Pulling	Top pass in the brake test the results are attached to the jobsheet.The temps are 108112122128 in 4 positions.Checked all brake components and performance no faults found.	1210834
217	08/04/2019	832864	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	xx	1210834
217	08/01/2019	830768	Accident # 49300		1210568
217	07/31/2019	832239	Consumables		1210568
217	07/31/2019	832239	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1210400
217	07/31/2019	832239	Mechanic entered - Elec and Light Exterior Lights L/H/R Clea	replaced broken clearance lamp	1210400
217	07/31/2019	832370	Consumables		1210568
217	07/31/2019	832370	Consumables	seat base replaced	1210568
217	07/31/2019	832370	Drv entered - Body Drivers Seat Leaning		1210400
217	07/31/2019	832240	KIT O-RING LARGE VOSS (A6739970145)		1210400
217	07/31/2019	832240	CIRCUIT PROTECTION VALVE		1210400
217	07/31/2019	832240	Drv entered - Brakes Park_Brake Not Holding	replaced defective circuit protection valve	1210400
217	07/29/2019	831533	Consumables		1210133
217	07/29/2019	831533	Consumables	secured	1210133
217	07/29/2019	831533	Mechanic entered - Body Other rear seat loose .		1208962
217	07/27/2019	831497	Consumables		1209576
217	07/27/2019	831497	Mechanic entered - Elec and Light Exterior Lights NS marker	Repaired wiring	1208962
217	07/24/2019	830768	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1208404
217	07/24/2019	830768	REFLECTOR AMBER HELLA 9x44mm		1208404
217	07/15/2019	828508		Creditor #PT-22C001 22 CELSIUS P/O #PE252499 Receiving #:262046 Date :2019-07-17	1206119
217	07/15/2019	827721	AIR CONDITIONING REPAIR		1206513
217	07/15/2019	828881	Breakdown Overheating/Cooling System		1206119
217	07/15/2019	828881	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG		1206119
217	07/15/2019	828881	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1206119
217	07/15/2019	828881	Breakdown Overheating/Cooling System	Replace seized top r/h pulley and engine belt	1206119
217	07/15/2019	828881	Breakdown Overheating/Cooling System	Assisting	1206119
217	07/15/2019	828540	Fluid Leaks Rear of buscoolant leak from A/C pipes		1206119
217	07/15/2019	828526	Fluid Leaks Rear of bus oil return hose	Trace to and tighten various hose clamps in engine bay	1206119
217	07/15/2019	828528	Consumables	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE252598 Receiving #:263600 Date :2019-08-02	1206513
217	07/15/2019	828528	Consumables		1206513
217	07/15/2019	828528	Body replace engine door struts		1206119
217	07/12/2019	828508		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1206119
217	07/12/2019	828508		VEHICLE SAFETY INSPECTION done	1206119
217	07/12/2019	828540	Fluid Leaks Rear of buscoolant leak from A/C pipes	removed header tank and fixed A/C pipes behind tank. Road tested bus and checked water levels. ok	1206119
217	07/12/2019	828526	Fluid Leaks Rear of bus oil return hose	fitted new oil return hose and checked for leaks ok	1206119
217	07/12/2019	828526	HOSE OIL RETURN		1206119
217	07/12/2019	782277	50V0207 Starter motor	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE235489CR Receiving #:262030 Date :2019-07-17	1206513
217	07/12/2019	782277	Consumables		1206375
217	07/12/2019	828528	Body replace engine door struts	fitted new longer struts to door ok	1206119
217	07/11/2019	828080	Mechanic entered - Fluid Leaks Rear of bus		1205200
217	07/11/2019	828005	REPAIR ACC # 48833		1210834
217	07/10/2019	828005	REPAIR Accident # 48833	ECTB	1205200
217	07/09/2019	827721	A/C problem not heating	repaired by 22	1204663
217	07/09/2019	827566	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE		1204663
217	07/09/2019	826941	carry out B service	Creditor #PT-22C001 22 CELSIUS P/O #PE252228 Receiving #:261542 Date :2019-07-11	1205657
217	07/05/2019	827014	Consumables		1204662
217	07/05/2019	827014	Consumables	Check seat and seat frame for security and alignment ok also check with spirit level ok Found one of two lumbar suport bladder pipes pinched relase and check ok	1204662
217	07/05/2019	826941	Drv entered - Body Drivers Seat Leaning	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	1204662
217	07/05/2019	826941		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1204662
217	07/05/2019	826941	PUMP BOOST PUMP COACH 90 Ltr		1204662
217	06/15/2019	823148	Consumables		1203139
217	06/15/2019	823148	Mechanic entered - Elec and Light Exterior Lights	Replace n/s/f park globe	1203139
217	06/07/2019	821880	Fluid Leaks dipstick area		1202096

217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables	CARRY OUT C SERVICE AS PER CHECK LIST		1202096
217	06/07/2019	821873			1202096
217	06/07/2019	821873 FILTER AIR FILTER MERCEDES BENZ			1202096
217	06/07/2019	821873 FILTER OIL FILTER MERCEDES A0001801709			1202096
217	06/07/2019	821873 FILTER FUEL MERCEDES (A5410900151)			1202096
217	06/07/2019	821873 FILTER FUEL FILTER MERCEDES BENZ (A0004771302)			1202096
217	06/07/2019	821873 HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204			1202096
217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables	CARRY OUT B SERVICE AS PER CHECK LIST		1202096
217	06/07/2019	821873			1202096
217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables			1202096
217	06/07/2019	821873 Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		1202096
217	06/07/2019	821873	Creditor #PT-BWED01 BWERE ELECTRICS PTY LTD P/O #PE249336 Receiving #258368 Date :2019-06-05		1202096
217	06/01/2019	820126 CCTV 6 month service/repair	xx		1201657
217	06/01/2019	820126 CCTV 6 months service/repair	all in good working order		1200404
217	05/25/2019	819050 Drv entered - A/C Heating Not Cooling	retensioned pos 1 wheel		1198613
217	05/21/2019	818041			1196973
217	05/21/2019	818042 Consumables			1198075
217	05/21/2019	818042 Consumables			1198075
217	05/21/2019	818042 Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	re tensioned pos 1 wheel		1196973
217	05/19/2019	817233 PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	xx		1196973
217	05/18/2019	817704 Consumables			1197501
217	05/18/2019	817704 Consumables			1197501
217	05/18/2019	817704 TYRE 295/80R22.5 NEW			1197236
217	05/18/2019	817704 Mechanic entered - Wheels and Tyres Damaged	replaced pos 1 tyre sidewall damage		1197236
217	05/13/2019	816220 Consumables			1197236
217	05/13/2019	816220 Consumables			1196383
217	05/13/2019	816220 Mechanic entered - Wheels and Tyres Wheel Nut Retension re t	done to spec		1196383
217	05/12/2019	815238 Please remove all old poster and fit MYKI has gone mobil	xx		1195243
217	05/11/2019	816173 Consumables			1195243
217	05/11/2019	816173 Consumables			1196112
217	05/11/2019	816173 Consumables			1196112
217	05/11/2019	816173 Mechanic entered - Wheels and Tyres Worn Sidewall worn	Checked ok		1195845
217	05/09/2019	815672	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1195512
217	05/09/2019	815672	VEHICLE SAFETY INSPECTION		1195512
217	05/09/2019	815694 Consumables			1195845
217	05/09/2019	815694 Consumables			1195845
217	05/09/2019	815694 TYRE 295/80R22.5 RECAP			1195512
217	05/09/2019	815694 Mechanic entered - Wheels and Tyres Worn pos 5 worn	replaced pos 5 tyre		1195512
217	05/05/2019	813176	CARRY OUT FIRE EXTINGUISHER TEST & TAG		1193636
217	05/05/2019	813176	xx		1193636
217	05/01/2019	783758 rectify vehicle not starting i	Creditor #PT-BWED01 BWERE ELECTRICS PTY LTD P/O #PE246758 Receiving #255736 Date :2019-05-08		1195243
217	04/15/2019	810459 Fault#36481 - Ops Entered - Fault - Breakdown Brakes - Rou	got to breakdown. checked operation of hand brake and footbrake . could not fault. drove bus back to oakleigh depot . inspected brakes . front brake pads 90 % rear brake pads 90 % . adjusted all brakes off 1 click . checked brake system for air leaks . could not fault . road tested and brake tested all okay		1190744
217	04/14/2019	810249 Consumables			1191160
217	04/14/2019	810249 n/s mirror arm broken	R&R mirror bracket . adjusted mirror all okay		1190744
217	04/14/2019	810249 ARM MIRROR BRAZILIAN N/S			1190744
217	04/08/2019	808913 Brakes - soft	Checked bus for soft brakes checked all brake pads they are 80% carried out brake test Checked for inactive fault code 85 5343 as indicates for o/s/r pad wear sensor got no signal		1190671
217	03/25/2019	805804 Consumables			1188057
217	03/25/2019	805804 Consumables			1188057
217	03/25/2019	805804 Consumables			1188057
217	03/25/2019	805804	CARRY OUT A SERVICE AS PER CHECK LIST A Service completed as per checklist		1187130
217	03/15/2019	803553 DIRECT PURCHASE - BUS INSPECTI	Creditor #PT-ROASAF ROAD SAFETY INSPECTIONS P/O #PE243470 Receiving #252446 Date :2019-03-26		1187392
217	03/14/2019	803553	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1185206
217	03/14/2019	803553	VEHICLE SAFETY INSPECTION		1185206
217	03/14/2019	803553	Assisting		1185206
217	03/14/2019	803553	ANNUAL SAFETY INSPECTION SERIAL # _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1185206
217	03/14/2019	803512 Consumables			1185206
217	03/14/2019	803512 Mechanic entered - Wheels and Tyres Wheel Nut Retension re t	retensioned wheel nuts to spec		1185206
217	03/13/2019	803349 Gearbox Driveline fit drive shaft	fitted drive shaft and greased ok		1185206
217	03/13/2019	803351 Consumables			1185206
217	03/13/2019	803351 Consumables			1185206
217	03/13/2019	803351 Final RSI	carried out final RSI and recorded brake temps ok		1185206
217	03/13/2019	803313 AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR			1185206
217	03/13/2019	803313 Mechanic entered - Air System Air_Leak Front Front air bags	fitted 2 new front air bags and tested ok		1185206
217	03/13/2019	803350 PERFORM CAMPAIGN 04/19 APV-5 SEATBELT ANCHORAGE BOLT SAFETY	fitted new anchorage bolt provided and tested o k .		1185206
217	03/08/2019	802712 DRIVE SHAFT 0500	Creditor #PT-CBM001 CBM COMPANY P/O #PE242999 Receiving #251298 Date :2019-03-13		1185206
217	03/08/2019	802712 fan drive shaft	replaced fan drive shaft		1185206
217	03/08/2019	802672 LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			1185206
217	03/08/2019	802672 Brake Pedal Rubber 0500 Mercedes (A1072910182)			1185206
217	03/08/2019	802672 HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500 (9314365038525)			1185206
217	03/08/2019	802672 Final RSI	checked handbrake warning light fitted switch globe and trans temp globereplaced brake pedal pad		1185206
217	03/08/2019	802506 KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (SOF1317)			1185206
217	03/08/2019	802506 Fluid Leaks rear axle	fitted new o/s/r hub seal kit		1185206
217	03/07/2019	802440 Consumables			1185206
217	03/07/2019	802440 Mechanic entered - Wheels and Tyres Wheel Nut Retension re t			1185206
217	03/07/2019	802506 Fluid Leaks rear axle	steam cleaned chassis and wheels for RSI retensioned all wheel nuts to 600nm		1185206
217	03/07/2019	802440 steam clean for RSI			1185206
217	03/05/2019	801663 Consumables			1185110
217	03/05/2019	801663 Mechanic entered - Wheels and Tyres Worn pos 3 & 4 worn	pos 3 & 4 changed. wheel tension done W/O 801270		1185110
217	03/05/2019	801270 KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (SOF1317)			1185110
217	03/05/2019	801270 replace all brake rotos	replaced all rotors replaced rear hub seals and test run. checked brake temps and tensioned all wheelnuts		1185110
217	03/05/2019	801270 SET DISC PAD SET SCANIA / MERCEDES 0500			1185110
217	03/05/2019	801999 KIT O-RING LANGE VOSS (A6739970145)			1185110
217	03/05/2019	801999 Mechanic entered - Air System Air_Leak Rear	replaced o ring kit on cyclopac voss fitting		1185110
217	03/04/2019	801663 TYRE 295/80R22.5 RECAP			1185110
217	03/04/2019	801663 Mechanic entered - Wheels and Tyres Worn pos 3 & 4 worn			1185110
217	03/04/2019	801221 Consumables			1185110
217	03/04/2019	801221 A0025453914 Low Air switch	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE242406 Receiving #250858 Date :2019-03-06		1185110
217	03/04/2019	801270 ROTOR FRONT & REAR MERC 0500LE A9424230112			1185110
217	03/01/2019	801156	PRE ANNUAL SAFETY INSPECTION CHECK		1185110
217	03/01/2019	801221 Mechanic entered - Elec and Light Warning Light On Dash H/R	Trace to and replace faulty switch		1185110
217	03/01/2019	801270 replace all brake rotos			1185110
217	03/01/2019	799008 FIRE SAF INSP	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE241477 Receiving #250870 Date :2019-03-06		1185110
217	03/01/2019	801220 Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST		1185110
217	02/22/2019	799706	VEHICLE SAFETY INSPECTION completed		1183051
217	02/22/2019	799706	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1183051

217	02/19/2019	799008		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Done by Lonsdale elect	1181785
217	02/16/2019	798324	CCTV CCTV not recording - Drivers Camra and i believe 1 ot	re connected camera wiring to hard drive camera 2 & 3	1181785
217	02/16/2019	798320	Consumables		1182593
217	02/16/2019	798320	Consumables		1182593
217	02/16/2019	798320	Body Drivers Seat Leaning. Reported seat wobbly and broken	removed seat base and tightened loose bolts on seat frame	1181785
217	02/14/2019	798021	Consumables		1182444
217	02/14/2019	798021	Elec and Light hand brake warning light n/w		1181785
217	02/14/2019	798021	Consumables		1182444
217	02/14/2019	798021	Consumables		1182444
217	02/14/2019	797841	Consumables		1182444
217	02/14/2019	797841	Consumables		1182444
217	02/14/2019	798021	Drv entered - Body Drivers Seat Leaning	found drives seat back too much freeplay / check w/o 798320	1181785
217	02/14/2019	797841	Mechanic entered - Body Other seat back insecure	secured wheelchair area seat back	1181785
217	02/11/2019	796828	Mechanic entered - Fluid Leaks Rear of bus coolant leaking f	tightened hse clamp on thermostat housing hose	1181519
217	02/05/2019	795612	Consumables		1180714
217	02/05/2019	795612	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	Retensioned P2 tyre to spec	1180180
217	02/04/2019	795541	Consumables		1180448
217	02/04/2019	795541			1180180
217	02/04/2019	795541	TYRE 295/80R22.5 NEW		1180180
217	02/04/2019	795541	Mechanic entered - Wheels and Tyres Worn pos 2	replaced worn pos2 tyre	1180180
217	01/26/2019	793110	Please remove old 2018 fare decals and fit new 2019 fare de	xx	1177720
217	01/17/2019	791621	AIR CONDITIONING REPAIR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #PE238977 Receiving #:247525 Date :2019-01-23	1177720
217	01/16/2019	791621	Ops Entered - Fault - A/C Heating Not Cooling - Route: 785	DONE BY COACHAIR	1175737
217	01/09/2019	790110	Mechanic entered - Elec and Light Exterior Lights N/S/F/Top	Replaced and tested.	1173686
217	01/07/2019	789603		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1173279
217	01/07/2019	789603		VEHICLE SAFETY INSPECTION	1173279
217	01/07/2019	789650	Consumables		1173385
217	01/07/2019	789650	Ops Entered - Fault - Body Wheel Chairamp when not unfolded	Fitted antislip tapes ok	1173279
217	01/02/2019	788731	Consumables		1172113
217	01/02/2019	788731	Consumables		1172113
217	01/02/2019	788731	Consumables		1172113
217	01/02/2019	788731	Consumables		1172113
217	01/02/2019	788731		CARRY OUT A SERVICE AS PER CHECK LIST completed	1171807
217	12/24/2018	787740	Drv entered - A/C Heating Not Cooling	Checked the ac works Ok.Cleaned out the condensation drains and tested.	1169017
217	12/24/2018	787730	Consumables		1169471
217	12/24/2018	787730	Consumables		1169471
217	12/24/2018	787730	Consumables		1169017
217	12/24/2018	787730	Drv entered - Body Water Leaks Roof	Check and clean blocked A/C drain tubes	1169017
217	12/24/2018	787701	FILTER AIR DRYER C/W COALESCING VOLVO B13R / B8LEA E6		1169017
217	12/24/2018	787701	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1169017
217	12/24/2018	787701		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed.	1169017
217	12/15/2018	785237	Apply print film	Apply print film	1166705
217	12/11/2018	784588	AIR CONDITIONING REPAIR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #PE236679 Receiving #:244635 Date :2018-12-13	1167157
217	12/10/2018	784588	Ops Entered - Fault - A/C Heating Not Cooling - Route: 833		1166549
217	12/10/2018	784588	Drv entered - A/C Heating Not Cooling	repaired by coachair	1166549
217	12/08/2018	784702	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	done	1166549
217	12/04/2018	783758	Elec and Light (None) Intermittant non start	tested no fault found	1166505
217	12/01/2018	785237	Apply Print film	Creditor #:PT-GLA001 GLASSPROTECH MELBOURNE P/O #PE236765 Receiving #:244780 Date :2018-12-14	1167424
217	11/28/2018	782277	Consumables		1169962
217	11/28/2018	782277	50V0037 Starter Motor	Creditor #:PT-MUL001 MULTISPARES LTD P/O #PE235489 Receiving #:243398 Date :2018-11-29	1165962
217	11/28/2018	782277	Elec and Light (None) Starter Motor U/S	Replaced starter motor	1165921
217	11/28/2018	782277	Elec and Light (None) Starter Motor U/S		1165921
217	11/19/2018	780311		carried out vehicle safety inspection ok	1163444
217	11/19/2018	780311		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1163444
217	11/19/2018	780311		VEHICLE SAFETY INSPECTION	1163444
217	10/30/2018	776556	Drv entered - Vandalism Vandalism/ Graffiti Interior	done	1159278
217	10/29/2018	776381	Drv entered - A/C Heating Not Cooling	done	1159008
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	FILTER OIL FILTER MERCEDES A0001801709		1156474
217	10/20/2018	774736	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST Completed.	1156474
217	10/20/2018	774736	Consumables		1156474
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736	Consumables		1156624
217	10/20/2018	774736		CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1156474
217	10/15/2018	773225	Drv entered - Suspension Kneeel/ Raise	checked and found front suspension valve fitted in wrong position removed and refit properly checked ok	1155188
217	10/09/2018	772104	Drv entered - Suspension Kneeel/ Raise		1154313
217	10/09/2018	771900	SENSOR LEVELLING VALVE ECAS M BENZ 0500LE A0015420018		1154313
217	10/09/2018	771900	Drv entered - Suspension Kneeel/ Raise	Fixed the faulty wiring at the fr levelling senderreplaced the fr and O/S/R levelling senders and tested.OK.	1154313
217	10/09/2018	771901	HOSE ENG UPPER 0500LE		1154313
217	10/09/2018	771901	Mechanic entered - Fluid Leaks Rear of bus coolant leak at	Replaced bottom coolent elbow hosefilled with coolant and tested.	1154313
217	10/09/2018	772104	Mechanic entered - CCTV Other driver's camera nw	The drivers camera was disconnected by someone.Reconnected and tested.OK.	1154313
217	10/09/2018	772104	Consumables		1154646
217	10/09/2018	772104	Consumables		1154646
217	10/09/2018	772104	Mechanic entered - Body Other o/s/r wheel arch hatch loose		1154313
217	10/08/2018	769914	Consumables		1154586
217	10/08/2018	769914	DECAL EMERGENCY EXIT (HAMMER)		1154313
217	10/08/2018	769914	Consumables		1154586
217	10/05/2018	771195	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	carried out campaign as required	1153308
217	10/02/2018	769914	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #O230747 Receiving #:238964 Date :2018-10-05 glass to be resealed and 2 x to be replaced as required	1153358
217	10/01/2018	769739		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	1153308
217	10/01/2018	769739		VEHICLE SAFETY INSPECTION carried out safety ins as per check list	1153308
217	10/01/2018	769888	Consumables		1153358
217	10/01/2018	769888	Mechanic entered - Wheels and Tyres Other nsf inner side wal	pushed the brake hose bracket further in and secured ok	1153308
217	10/01/2018	769888	Consumables		1153358
217	10/01/2018	769888	Mechanic entered - Elec and Light Other dash switch lights x	replaced dash switch globes	1153308
217	10/01/2018	769888	Consumables		1153358
217	10/01/2018	769888	Consumables		1153358
217	10/01/2018	769914	Mechanic entered - Body Other nsr window glass crack	O230747	1153308
217	10/01/2018	769914	Mechanic entered - Body Other os middle window needs resael	O230747	1153308
217	10/01/2018	769888	Mechanic entered - Body Other rear no smoking and make your	fitted decals	1153308
217	09/29/2018	769620	Mechanic entered - Suspension Rear not sitting high.	road testsuspension working okcould not fault.	1153308
217	09/25/2018	768887	Suspension - o/s/r air bag u/s	R&R o/s/r air bag road test all okay	1153168
217	09/25/2018	768887	AIRBAG FRONT+REAR MERC 0405/	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #O230410 Receiving #:238125 Date :2018-09-26	1153302
217	09/24/2018	768685	Consumables		1153302
217	09/24/2018	768685	headlight out	replaced globe	1153168
217	09/23/2018	767493	CCTV	xx	1150623
217	09/18/2018	767181	Ops Entered - Fault - Air System Air Not Building_Up - Rout	replace air line to lumber support on drivers seat	1150623
217	09/16/2018	766225		xx	1150623
217	09/16/2018	766225		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1150623

217	09/15/2018	766721	Mechanic entered - Fluid Leaks Rear of bus coolant leak near		1151153
217	09/11/2018	765518	Drv entered - CCTV Warning Light On	no fault found	1150093
217	09/11/2018	765296	Consumables		1150623
217	09/11/2018	765296	Consumables		1150623
217	09/11/2018	765296	SINGLE SEAT BASE		1150093
217	09/11/2018	765296	Mechanic entered - Body Passenger Seat Torn Rear passenger s	fitted new seat base to bus ok	1150093
217	09/05/2018	764146	Consumables		1149134
217	09/05/2018	764146	Consumables		1149134
217	09/05/2018	764146	Mechanic entered - Body Other emergency hammer rear of bus i	fixed back	1148595
217	09/01/2018	767493	CCTV 6 month services	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE229953 Receiving #:238167 Date :2018-09-26	11533802
217	09/01/2018	767493	FOI Campaign	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE229966 Receiving #:237792 Date :2018-09-21	1152772
217	08/25/2018	761386	Vandalism/ Vandalism/ Graffiti Interior	xx	1146153
217	08/25/2018	761383	Ops Entered - Fault - Vandalism/ Vandalism/ Graffiti Exterio	xx	1146153
217	08/25/2018	761793	Consumables		1147080
217	08/25/2018	761793	Mechanic entered - Elec and Light Exterior Lights O/S Top Fr	Replaced the both marker and indicator globes and tested.	1146153
217	08/25/2018	760820	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	xx	1146153
217	08/24/2018	761719	Consumables		1147080
217	08/24/2018	761719	Mechanic entered - Elec and Light Exterior Lights front top		1146949
217	08/24/2018	761719	Air System Air_Leak InteriorAir Leaking under drivers	fitted and secured broken air line for drivers seat	1146949
217	08/21/2018	760969	Brakes Foot_Brakes Pulling front rotos	found in good order	1146153
217	08/13/2018	759022		VEHICLE SAFETY INSPECTION	1144045
217	08/09/2018	758398	Campaign 07/17 WIFI CCTV UPGRADE. Cordinate upgrade of	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1144045
217	08/09/2018	758397	CCTV Timestamp Incorrect - Not Connecting to Server	done	1142906
217	08/09/2018	758325	Consumables		1142906
217	08/09/2018	758325	Consumables		1143698
217	08/09/2018	758129	Consumables		1143698
217	08/09/2018	758129	Consumables		1143698
217	08/09/2018	758129	Consumables		1143698
217	08/09/2018	758325	Drv entered - Body Drivers Seat Controls	no fault found	1142906
217	08/09/2018	758129	SINGLE SEAT BASE		1142906
217	08/09/2018	758129	Mechanic entered - Body Passenger Seat Torn	Replaced.	1142906
217	08/01/2018	754175	Consumables		1141970
217	08/01/2018	754175	UNIT CONTROL UNIT ICU 402	Creditor #:PT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #:PE225128 Receiving #:233884 Date :2018-08-07	1142906
217	07/31/2018	755950	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Retensioned to 600 Nm.	1140903
217	07/31/2018	755950	Consumables		1144709
217	07/28/2018	755640	Mechanic entered - Wheels and Tyres Worn Pos 5 and 6 tyres n		1140903
217	07/28/2018	755640	TYRE 295/80R22.5 RECAP	Replaced tyres pos 5 and 6 with 295 recaps and tensioned wheel nuts to spec.	1140903
217	07/28/2018	755640	Consumables		1141173
217	07/28/2018	755599	Consumables		1141173
217	07/28/2018	755599	Consumables		1141173
217	07/28/2018	755599	Consumables		1141173
217	07/23/2018	754175	Consumables		1140903
217	07/23/2018	754175	Ops Entered - Fault - Desto Signs - Route: 782 - Frankston	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service as checklist requires.	1140028
217	07/23/2018	754175	Ops Entered - Fault - Desto Signs - Route: - Take a Low F	Checked and swapped desto control from 218 ok. fitted new one to 218 and programed it.	1139137
217	07/21/2018	753538	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	D	1139137
217	07/18/2018	753040	Consumables		1139137
217	07/18/2018	753040	Mechanic entered - Elec and Light Horn N/w	Diagnosed and found horn plug was disconnected under dash plugged the same ok	1138642
217	07/18/2018	753040	Ops Entered - Fault - Desto Signs - Route: 774 - Frankston	Reset power ok	1138642
217	07/13/2018	752253	Drv entered - A/C Heating Not Heating	DONE	1137630
217	07/13/2018	752065	Consumables		1138372
217	07/13/2018	752065	Drv entered - Elec and Light Exterior Lights	Checked all works OK.	1137630
217	07/12/2018	751899	Consumables		1138068
217	07/12/2018	751899	Wheels and Tyres flat spots	Checked is still serviceable.	1137630
217	07/07/2018	750926	Consumables		1136411
217	07/07/2018	750926	Mechanic entered - Elec and Light Horn	repaired	1135048
217	07/07/2018	750200	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	v	1135048
217	07/07/2018	750199	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	v	1135048
217	07/07/2018	750198	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	v	1135048
217	07/06/2018	750624	Drv entered - Wipers and Washers Wipers Noisy	Lubricate and adjust wiper linkage	1135048
217	07/04/2018	750032	Consumables		1136111
217	07/04/2018	750032	Consumables		1136111
217	07/04/2018	750032	Body rear modisty panel loose	secured	1135048
217	06/30/2018	748345	Graffiti film	xx	1133521
217	06/29/2018	749028	Mechanic entered - A/C Heating Other NO driver floor heater	Fitted new vent	1134018
217	06/29/2018	749027	Mechanic entered - Elec and Light Exterior Lights OSF top ma	replicd globe inclusive remove and refit the blinds	1134018
217	06/29/2018	749027	Consumables		1134680
217	06/27/2018	748557	Elec and Light REAR DOOR NOT WORKING	found rear door switch under rear door button had fallen off reconnected tested working. complete	1133521
217	06/27/2018	748557	Consumables		1134018
217	06/27/2018	748329	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed campaign	1133521
217	06/26/2018	747983	REFLECTOR AMBER HELIA 94x44mm	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1133521
217	06/26/2018	747983	Consumables		1133521
217	06/26/2018	747983	Consumables		1133521
217	06/19/2018	746209	Consumables		1133521
217	06/19/2018	746209	Mechanic entered - Wheels and Tyres Wheel Nut Retension P34	VEHICLE SAFETY INSPECTION	1132218
217	06/19/2018	746209	Consumables		1131149
217	06/19/2018	746209	Consumables		1132218
217	06/19/2018	746209	Consumables		1132218
217	06/19/2018	746209	Drv entered - Body Drivers Seat Controls	Checked all works OK.	1131149
217	06/16/2018	745915	Consumables		1131586
217	06/16/2018	745915	Mechanic entered - Wheels and Tyres Worn P34	replaced tyre 34 torqued as per spec	1131149
217	06/16/2018	745915	TYRE 295/80R22.5 RECAP		1131149
217	06/15/2018	745598	Drv entered - A/C Heating Not Heating	donje	1131149
217	06/13/2018	745152	carry out A service	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE222132 Receiving #:229868 Date :2018-06-18	1131686
217	06/13/2018	745152		CARRY OUT A/C - A SERVICE AS PER CHECK LIST....coachair	1131019
217	06/07/2018	748345	Graffiti Film	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE223204 Receiving #:230700 Date :2018-06-28	1134018
217	06/04/2018	743244	Consumables		1129429
217	06/04/2018	743244	Ops Entered - Fault - Elec and Light Warning Light On Dash -	road tested bus a couple times could not fault	1128775
217	06/02/2018	742905	Consumables		1129231
217	06/02/2018	742905	Mechanic entered - Wheels and Tyres Wheel Nut Retension p56	Completed	1128775
217	06/01/2018	742655	Consumables		1129231
217	06/01/2018	742655	Mechanic entered - Elec and Light Interior Lights Saloon lig	Switch and the globe replaced and tested.	1128775
217	06/01/2018	742785	Brakes (Hornel) O/S/R outer brake pad low	Replaced pad on OSR outer from used one fit wheels torqued as per spec road tested ok	1128775
217	05/30/2018	742248	Gasket Rocker Cover Mercedes 0500		1128775
217	05/30/2018	742248		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Completedcleaned and tested.	1128775
217	05/30/2018	742285	Drv entered - Brakes Warning Light On	Testdriven and checked and tested allbrake components and performance no faults found.	1128775
217	05/21/2018	739347	Consumables		1126314
217	05/21/2018	739347	Consumables		1126314
217	05/21/2018	739347	Consumables		1126314
217	05/21/2018	739347	Consumables		1126314
217	05/21/2018	739347		A service completed 19/5/18	1125410

217	05/19/2018	739347	CARRY OUT A SERVICE AS PER CHECK LIST	1125410
217	05/17/2018	739108	AIR CONDITIONING REPAIR	1126584
217	05/16/2018	739108	Drv entered - A/C Heating Not Heating	1125162
217	05/16/2018	739108	Drv entered - A/C Heating Not Heating	1125162
217	05/15/2018	738610	Consumables	1125162
217	05/15/2018	738610	Consumables	1125162
217	05/15/2018	738610	Body loose rear modisty panerl	1124469
217	05/11/2018	738102	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	1123672
217	05/11/2018	737777	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115	1123672
217	05/11/2018	737777		1123672
217	05/11/2018	737777	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER	1123672
217	05/11/2018	737777	KIT AIR LINE FITTING VOSS 22MM (5020114)	1123672
217	05/10/2018	737776	Consumables	1123672
217	05/10/2018	737776	Mechanic entered - Wheels and Tyres Wheel Nut Retension Tyre	1123418
217	05/10/2018	737776	Fluid Leaks Rear of bus reseal compressor to block	1123418
217	05/10/2018	737777	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE	1123418
217	05/10/2018	737777		1123418
217	05/09/2018	737291	49G4S23W Fitting	1123418
217	05/08/2018	737399	Consumables	1123418
217	05/08/2018	737399	Wheels and Tyres position 5 worn	1123201
217	05/08/2018	737411	Engine clean	1123201
217	05/08/2018	737175	Fluid Leaks Rear of bus	1123201
217	05/08/2018	737291	Air System Air Leak Rear	1123201
217	05/08/2018	737291	49G4S23W Fitting	1123201
217	05/07/2018	737134		1123201
217	05/07/2018	737134	KIT AIR LINE FITTING VOSS 22MM (5020114)	1123201
217	05/07/2018	737134		1123201
217	05/07/2018	737175	Fluid Leaks Rear of bus	1123201
217	05/04/2018	733516	Consumables	1123201
217	05/04/2018	733516	Consumables	1123201
217	05/04/2018	733516	HAMMER EMERGENCY HAMMER	1122678
217	05/04/2018	733516	HAMMER EMERGENCY	1122678
217	05/01/2018	735918	Suspension Leaningrear	1122078
217	05/01/2018	735918	CCTV vandalized	1122078
217	04/27/2018	735194	Consumables	1122078
217	04/27/2018	735194	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	1121050
217	04/27/2018	735194	Consumables	1122078
217	04/27/2018	735194	Consumables	1122078
217	04/27/2018	735194	Drv entered - Body Drivers Seat Controls	1121050
217	04/26/2018	734923	Consumables	1121776
217	04/26/2018	734923	Mechanic entered - Wheels and Tyres Worn pos 6 tyre worn	1121050
217	04/23/2018	734430	Mechanic entered - Engine Noisy or Rattling	1120508
217	04/18/2018	733635	Vandalism Vandalism/ Graffiti Interior	1120162
217	04/18/2018	733516	Consumables	1120241
217	04/18/2018	733516	Consumables	1120241
217	04/18/2018	733516	EMERGENCY HAMMER COMPLETE WITH CRADLE 2740044	1120162
217	04/18/2018	733516	Body emerg hammer bracket cracked	1120162
217	04/18/2018	733516	EMERGENCY HAMMER	1119621
217	04/16/2018	732911	Mechanic entered - Fluid Leaks Rear of bus coolant leak rear	1119621
217	04/16/2018	732911	HOSE ENG UPPER 0500LE	1119621
217	04/14/2018	732820	Mechanic entered - Fluid Leaks Other engine coolant leak	1119283
217	03/28/2018	729732	Consumables	1118086
217	03/28/2018	729732	Consumables	1118086
217	03/28/2018	729732	BEIT SEAT BELT ISRI A6008 L/H	1117699
217	03/28/2018	729732	Ops Entered - Fault - Body Drivers Seat Belt - Route: 772 -	1117699
217	03/28/2018	729733	Drv entered - Body Passenger Seat Belt	1117699
217	03/28/2018	729733	Consumables	1118086
217	03/28/2018	729733	Consumables	1118086
217	03/26/2018	729078	Drv entered - Body Drivers Seat Belt	1116743
217	03/26/2018	729078	Consumables	1117699
217	03/26/2018	729078	Consumables	1117699
217	03/26/2018	729083	Ops Entered - Fault - Air System Air_Leak Interior - Route:	1116743
217	03/21/2018	728104	WIPER REFILL 1000mm MULTI FIT	1115732
217	03/21/2018	728104	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	1115732
217	03/21/2018	728099	Consumables	1116474
217	03/21/2018	728099	Mechanic entered - Wheels and Tyres Wheel Nut Retension P1 &	1115732
217	03/20/2018	727780	TYRE 295/50R22.5 NEW	1115732
217	03/20/2018	727780	Drv entered - Steering Shakes/ Wobbles	1115732
217	03/20/2018	727842	Consumables	1116208
217	03/20/2018	727842	Consumables	1116208
217	03/20/2018	727841	Consumables	1116208
217	03/20/2018	727841	Consumables	1116208
217	03/20/2018	727842	Body Passenger Seat loose	1115732
217	03/20/2018	727841	Mechanic entered - Body Other O/S/R seat mount bolts broken	1115732
217	03/20/2018	727907	A3 Poster Campaign for Seaford Depot only. Wallara Art Com	1115732
217	03/13/2018	725515	DIRECT PURCHASE - BUS INSPECTI	1115467
217	03/08/2018	725515		1112952
217	03/08/2018	725515		1112952
217	03/08/2018	725515		1112952
217	03/08/2018	725515		1112952
217	03/08/2018	725556	Mechanic entered - Air System Air_Leak Front park brakes va	1112952
217	03/07/2018	725355	DECAL EMERGENCY EXIT (HAMMER)	1112952
217	03/07/2018	725355	final RSI check clean and park ready	1112952
217	03/07/2018	725355	final RSI check clean and park ready	1112952
217	03/06/2018	720341	Consumables	1112952
217	03/06/2018	720341	Consumables	1112952
217	03/06/2018	720341	BEIT SEAT BELT ISRI A6008 L/H	1112317
217	03/05/2018	724388	Consumables	1112689
217	03/05/2018	724388	Consumables	1112689
217	03/05/2018	724388	Drv entered - Body Drivers Seat Belt	1112317
217	03/02/2018	722427	Consumables	1112317
217	03/02/2018	722427	Consumables	1112317
217	03/02/2018	722427	drivers seat belts as per pic	1112689
217	02/28/2018	723340	Consumables	1111780
217	02/28/2018	723340	Consumables	1111780
217	02/28/2018	723340	Steam clean for RSI	1111060
217	02/28/2018	723176	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	1111060
217	02/28/2018	722614	Consumables	1111780
217	02/28/2018	722614	Consumables	1111780
DONE BY COOCHAIR				
secured panel				
done				
retensioned pos 5/6 wheels				
CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST				
Creditor #PT-MUL001 MULTISPARES LTD P/O #PE219474 Receiving #:226893 Date :2018-05-09				
removed tyre pos 5 and 6 and fitted r/o 295 to pos 5. Tensioned wheel nuts with Griff				
steam cleand under and over engine bay.				
checked found minor oil leak at top cover on engine bell housing removed cover and resealed				
checked found air leaks at air drier changed voss fitting checked ok				
Creditor #PT-MUL001 MULTISPARES LTD P/O #PE219474 Receiving #:226825 Date :2018-05-08				
VEHICLE SAFETY INSPECTION				
TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS				
Cleaned camera lenses				
retensioned pos 5/6 wheels				
removed seat base found air line cable tied over fitted new air line and re joined to seat controls tested ok				
replaced pos 6 wheel with run out				
checked found water pump pully bolts lose tighted ok				
fit new hammer for emergency extreplace all missing step edging inside back of busfit clip to nearside rear wheel arch panel fit new clip to offside rear panel repair nearside rear panel cut and polish marks off body				
checked and found split coolant hose replaced hose and topped up coolant				
check i t found loose hose clamp tention it no key to start ready to start coolant fill				
Replaced the seatbelt and tested.				
Replaced and tested.				
Replaced and tested.				
rectified.				
Replace n/s wiper insert				
Completed				
Trace to and change both front uneven worn tyres at 4mm Road test ok				
Repaired				
Drill and tap new bolt hole. Secure seat ok				
D)				
Creditor #PT-ROASAF ROAD SAFETY INSPECTIONS P/O #PE215403 Receiving #:223118 Date :2018-03-16				
TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS				
VEHICLE SAFETY INSPECTION				
Assisting				
ANNUAL SAFETY INSPECTION SERIAL # _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 DONE RSI				
fitted new park brake valve				
checked for final RSI and steam cleanded engine again to clean leaks				
Creditor #PT-VOLGRE VOLGREN AUSTRALIA PTY LTD P/O #PE214576 Receiving #:222402 Date :2018-03-06				
complete				

217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722614		CARRY OUT C SERVICE AS PER CHECK LIST		1111060
217	02/28/2018	722614		done		1111060
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722615		CARRY OUT B SERVICE AS PER CHECK LIST		1111060
217	02/28/2018	722615		CARRY OUT B SERVICE AS PER CHECK LIST		1111060
217	02/28/2018	722615		done		1111060
217	02/28/2018	722616	Consumables			1111780
217	02/28/2018	722616	Consumables			1111780
217	02/28/2018	722616	Consumables			1111780
217	02/28/2018	722616	Consumables			1111780
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722615	Consumables			1111780
217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722614	Consumables			1111780
217	02/28/2018	722615		CARRY OUT A SERVICE AS PER CHECK LIST		1111060
217	02/28/2018	722614		CARRY OUT A SERVICE AS PER CHECK LIST		1111060
217	02/28/2018	722616		done		1111060
217	02/28/2018	722616		CARRY OUT A SERVICE AS PER CHECK LIST		1111060
217	02/26/2018	722427	Body Drivers Seat Belt	friday		1111060
217	02/26/2018	722427	Consumables			1111373
217	02/26/2018	722427	Consumables			1111373
217	02/21/2018	719509	Superslim Plastic Base		Creditor #PT-MACCON MCCONNELL SEATS AUSTRALIA P/O #P:211404S Receiving #:221934 Date :2018-02-28	1111551
217	02/19/2018	720952				1109967
217	02/19/2018	720950	50A1908		Creditor #PT-MUL001 MULTISPARES LTD P/O #PE214199 Receiving #:221389 Date :2018-02-20	1109985
217	02/19/2018	720950	Fluid Leaks Rear of bus fuel filter bowl leaking fuel	fitted new fuel filter bowl no leaks.		1109967
217	02/19/2018	720341	BELT SEAT BELT ISRI A6008 L/H			1109967
217	02/19/2018	720341	Body entry door lower rubber	refit door rubber		1109967
217	02/19/2018	720340	Mechanic entered - Body Passenger Seat Belt	fit drivers seat belt refit disabled seat		1109967
217	02/19/2018	720341	Consumables			1109985
217	02/19/2018	720341	Consumables			1109985
217	02/19/2018	720340	Consumables			1109985
217	02/19/2018	720340	Consumables			1109985
217	02/19/2018	720830		Carried out C service as per checklist. complete		1109967
217	02/19/2018	720830	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618(E10H02)			1109967
217	02/19/2018	720830	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911)			1109967
217	02/19/2018	720830	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)			1109967
217	02/19/2018	720830	FILTER FUEL FILTER MERCEDES 0500LE			1109967
217	02/19/2018	720830	FILTER FUEL FILTER MERCEDES 0500LE			1109967
217	02/19/2018	720830		CARRY OUT C SERVICE AS PER CHECK LIST		1109967
217	02/19/2018	720830				1109967
217	02/19/2018	720830	KIT AIR LINE FITTING VOSS 22MM (5020114)			1109967
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830		CARRY OUT B SERVICE AS PER CHECK LIST		1109967
217	02/19/2018	720830				1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830		CARRY OUT A SERVICE AS PER CHECK LIST		1109967
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/19/2018	720830	Consumables			1109985
217	02/16/2018	719509	Service			1109967
217	02/16/2018	719032	(1) Steering box seal leaking (2) number of coolant leaks (3	topped up power steering fluid and bleed steering system. run bus for several minutes and full locked steering side-to-side. No air in steering system.		1109967
217	02/16/2018	720341	Body entry door lower rubber	secure drivers seat refit covers to disabled seats fix drivers blind fit new step edging to front step refit all recovered pass seats		1109967
217	02/16/2018	720340	Mechanic entered - Body Passenger Seat Belt			1109967
217	02/16/2018	719115	Consumables			1109967
217	02/16/2018	719115	Consumables			1109967
217	02/16/2018	719115	Consumables			1109967
217	02/16/2018	719115	Body Front_Door Operation Faultyfront door leaf opens	operated doors several times. could not fault		1109967
217	02/15/2018	719509	repair vandalised seats		Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE213726 Receiving #:221179 Date :2018-02-16	1109967
217	02/15/2018	719032	DIRECT PULCHASE - STEERING		Creditor #PT-HYD010 HYDROSTEER PTY LTD P/O #PE213658 Receiving #:222343 Date :2018-03-05	1112317
217	02/15/2018	719032	LAMP LED SIDE LAMP RED/AMBER PERE((52-98002)			1109967
217	02/15/2018	719032	LAMP LED SIDE MARKER PERE(RED/AMBER (LX30131)			1109967
217	02/13/2018	719509	Vandalism pass seats torn....backs single 17base single 1			1109967
217	02/13/2018	719032	RR SWAY BAR BUSHES 0500		Creditor #PT-MUL001 MULTISPARES LTD P/O #PE213597 Receiving #:220749 Date :2018-02-13	1109967
217	02/13/2018	719032	(1) Steering box seal leaking (2) number of coolant leaks (3			1109967
217	02/13/2018	719527	Mechanic entered - Body Other drivers compartment step cover	removed of floor covering and made up plate to cover old stop removed exterior pannel specker and made plate to cover hole		1109967
217	02/13/2018	719527	Consumables			1109967
217	02/13/2018	719527	Consumables			1109967
217	02/12/2018	719032	LAMP LED SIDE MARKER PERE(RED/AMBER (LX30131)			1109967
217	02/12/2018	719032	POWER STEERING PUMP SEALING O		Creditor #PT-MUL001 MULTISPARES LTD P/O #PE213638 Receiving #:220771 Date :2018-02-13	1109967
217	02/12/2018	719032	POWER STEERING PUMP 0500 MERCE		Creditor #PT-MUL001 MULTISPARES LTD P/O #PE213638 Receiving #:220771 Date :2018-02-13	1109967
217	02/12/2018	719032	KIT AIR LINE FITTING VOSS 22MM (5020114)			1109967
217	02/12/2018	719032	(1) Steering box seal leaking (2) number of coolant leaks (	Assisting		1109967
217	02/12/2018	719032	(1) Steering box seal leaking (2) number of coolant leaks (	fixed rsi defects removed steering box for repairs.		1109967
217	02/12/2018	719115	Body Front_Door Operation Faultyfront door leaf opens			1109967
217	02/10/2018	718055		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1108720
217	02/10/2018	718055		Di done		1108720
217	02/08/2018	717945	carry out fire safety insp		Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE213256 Receiving #:220823 Date :2018-01-23	1109967
217	02/07/2018	717945			CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Completed.	1107290
217	02/05/2018	717435			PRE ANNUAL SAFETY INSPECTION CHECK completed.	1108634
217	02/01/2018	704876	OVERFLOW VALVE			1108092
217	01/30/2018	714768	Field Clutch Thermoking		Creditor #PT-QTK001 QTK GROUP P/O #PE211980 Receiving #:219928 Date :2018-02-01	1108092
217	01/30/2018	716046	Consumables			1107825
217	01/30/2018	716046	Consumables			1107825
217	01/30/2018	716046	Mechanic entered - Body Other	Refit o/s/r seat back cushion		1107290
217	01/24/2018	715194	Consumables			1106269
217	01/24/2018	715194	Consumables			1106269
217	01/24/2018	715194	SINGLE SEAT BACK REST			1105640
217	01/24/2018	715194	Mechanic entered - Body Passenger Seat Torn	REPLACED SEAT BACK X1		1105640
217	01/23/2018	712760	clean and paint graffiti		Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE211184 Receiving #:219567 Date :2018-01-29	1107290
217	01/23/2018	714768	AIR CONDITIONING REPAIR		Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE212031 Receiving #:219403 Date :2018-01-25	1106369
217	01/23/2018	714768	5210-2NS Must be Nachi		Creditor #PT-FRANBA FRANKSTON BEARINGS (AUST) P/L P/O #PE212001 Receiving #:219255 Date :2018-01-24	1105966

217	01/22/2018	714768	Armature clutch	Creditor #PT-QTK001 QTK GROUP P/O #PE211980 Receiving #219615 Date :2018-01-30	1107290
217	01/22/2018	714768	N0800036 Pulley	Creditor #PT-QTK001 QTK GROUP P/O #PE211980 Receiving #219615 Date :2018-01-30	1107290
217	01/22/2018	714768	Ring retain. Thermoking clutc	Creditor #PT-QTK001 QTK GROUP P/O #PE211980 Receiving #219615 Date :2018-01-30	1107290
217	01/22/2018	714768	BELT MICRO V SERPENTINE BELT 0 RIB 2120mm LONG	Creditor #PT-QTK001 QTK GROUP P/O #PE211980 Receiving #219615 Date :2018-01-30	1105465
217	01/22/2018	714768	A/C Heating Warning Light On clutch burnt out	DONE BY COACHAIR	1105466
217	01/19/2018	714417	Consumables		1104736
217	01/19/2018	714417	Consumables		1104736
217	01/19/2018	714417	Ops Entered - Fault - Body Drivers Seat Controls - Route:	could not fault in driver seat controls	1104148
217	01/13/2018	713363		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1102930
217	01/13/2018	713363		VEHICLE SAFETY INSPECTION	1102930
217	01/10/2018	712760	Graffiti - interior rear of bus	done by ecib	1102482
217	01/09/2018	704876	Wipers and Washers body ??		1101875
217	01/07/2018	710928	replace screw type compressor	Creditor #PT-CA0003 COACHAIR PTY LTD P/O #PE210770 Receiving #218081 Date :2018-01-09	1101875
217	01/07/2018	711777	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	q	1100416
217	01/05/2018	711919	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		1101131
217	01/05/2018	711919		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	1101131
217	01/03/2018	704876	OVERFLOW VALVE		1100416
217	01/03/2018	704876	VALVE 4 WAY CIRCUIT PROTECTION VALVE		1100416
217	01/03/2018	704876	Wipers and Washers body ??		1100416
217	01/03/2018	704876	KIT AIR LINE FITTING VOSS 22MM (5020114)		1100416
217	01/03/2018	704876			1100416
217	01/02/2018	710928	Drv entered - A/C Heating Not Cooling	Air leaks o/s/r	1100416
217	01/02/2018	710928	Drv entered - A/C Heating Not Cooling	Commission tested found that the compressor is leaking through the seals and will need to be replaced	1100416
217	12/24/2017	709974	Consumables	compressor replaced by coachair	1100416
217	12/24/2017	709974	Consumables		1099774
217	12/24/2017	709974	Mechanic entered - Body Passenger Seat Torn	Replaced.	1099774
217	12/24/2017	709974	SINGLE SEAT BASE		1098473
217	12/23/2017	709031	Drv entered - Vandalism Vandalism/ Graffiti Interior	Cleaned by Contractor 17/12	1098473
217	12/13/2017	707945	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	remove graf	1097522
217	12/08/2017	706906	Consumables		1097000
217	12/08/2017	706906	Consumables		1097000
217	12/08/2017	706906	Ops Entered - Fault - Body Water Leaks Roof - Route: 784 -	no leak found	1096470
217	12/06/2017	703535	Drv entered - Elec and Light AM-FM Radio		1094811
217	12/06/2017	703535	Ops Entered - Fault - Elec and Light AM-FM Radio - Route: 7	aerial for the am/fm radio broken off on the roof	1094811
217	12/06/2017	703535	Drv entered - Elec and Light AM-FM Radio		1094811
217	12/06/2017	703535	Drv entered - Elec and Light AM-FM Radio	found no fault with radio antenna looks fine.	1096051
217	12/06/2017	703535	Ops Entered - Fault - Elec and Light AM-FM Radio - Route: 7	found no fault with radio antenna looks fine.	1096051
217	12/06/2017	706358	CCTVdrivers cam not working	replaced camera with new one tested okay.	1096051
217	12/04/2017	705659	Ops Entered - Fault - Elec and Light Interior Lights - Rout	checked and working	1095277
217	11/30/2017	705225	Ops Entered - Fault - Warning Lights Air Conditioning - Ro	REPLACED FUSE	1095003
217	11/29/2017	704876	LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND		1094811
217	11/29/2017	704961		CARRY OUT A SERVICE AS PER CHECK LIST completed.	1094811
217	11/29/2017	704961	Consumables		1095003
217	11/29/2017	704961	Consumables		1095003
217	11/29/2017	704961	Consumables		1095003
217	11/27/2017	703535	Aerial	Creditor #PT-VOLGRE VOLGREN AUSTRALIA PTY LTD P/O #PE208161 Receiving #215347 Date :2017-11-29	1095003
217	11/23/2017	703701	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean graf	1094548
217	11/23/2017	703565	Consumables		1092973
217	11/23/2017	703565	Body engine hatch struts	secure boot lid hinge fit new gas struts	1093415
217	11/23/2017	703565	Consumables		1092973
217	11/22/2017	703536	LAMP INTERIOR AND REVERSING (1413)		1093415
217	11/22/2017	703536		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1092973
217	11/22/2017	703536		VEHICLE SAFETY INSPECTION	1092973
217	11/19/2017	701125	Consumables		1092973
217	11/19/2017	701125	Requires wheelchair hook holder	xx	1092445
217	11/18/2017	701451	Please remove the 2 x Do Not Enter decals at the exterior	xx	1090429
217	11/16/2017	702116	Breakdown#:33963 - Ops Entered - Breakdown - Breakdown Road	??	1090429
217	11/14/2017	701468	Drv entered - Body Drivers Seat Leans and rocks when driving	remove drivers seat base tighten loose bolts	1090429
217	11/14/2017	701468	Consumables		1090429
217	11/14/2017	701468	Consumables		1090429
217	11/14/2017	701468	Consumables		1090429
217	11/03/2017	699457	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: - T	Repaired coolant leak in trans hose top up checked ok	1088588
217	11/02/2017	699106	BELT DOUBLE V-BELT MERCEDES 0500LE (A0139971992)		1088858
217	11/02/2017	699106	Fan Belt	Replaced and tested.	1088858
217	11/01/2017	698716	Consumables		1088858
217	11/01/2017	698716	Consumables		1088858
217	11/01/2017	698716	Drv entered - Body Water Leaks Roof	done	1088472
217	10/29/2017	696565	Remove old poster and fit new A3 Posters and hangers	dj	1086877
217	10/19/2017	695527	Consumables		1086343
217	10/19/2017	695527	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	Retorqued pos 5 wheel nuts to 600 NM.	1085420
217	10/18/2017	695189	Consumables		1085767
217	10/18/2017	695189	TYRE 11R22.5R RECAP		1085420
217	10/18/2017	695189	Mechanic entered - Wheels and Tyres Damaged pos 5 side wall	Replaced pos 5 tyre and torqued wheel nuts to 600 NM.	1085420
217	10/17/2017	694964	Consumables		1085420
217	10/17/2017	694964	Consumables		1085420
217	10/17/2017	694964	ASSEMBLY RETRIMMED BASE ASSY 6008		1085420
217	10/17/2017	694964	Drv entered - Body Drivers Seat Leaning	FIT NEW DRIVERS SEAT BASE	1085420
217	10/05/2017	691719		Ref wo 691718	1081587
217	10/05/2017	691718	Consumables		1080258
217	10/05/2017	691718	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S		1081587
217	10/04/2017	691341		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1081587
217	10/04/2017	691341		VEHICLE SAFETY INSPECTION	1081587
217	10/04/2017	691389	Consumables		1082001
217	10/04/2017	691389	TYRE 11R22.5R RECAP		1081587
217	10/04/2017	691389	Mechanic entered - Wheels and Tyres Worn N/S/R	Replace n/s/r tyres and torque to 600nm	1081587
217	10/04/2017	691349	Consumables		1082001
217	10/04/2017	691349	LIGHT SIDE INDICATOR L/H		1081587
217	10/04/2017	691349	Mechanic entered - Elec and Light Exterior Lights	Replace n/s side indicator lamp.Door ok and fault globes.Front park globes.N/S wheel chair sticker.Repair panel clamps x2. Secure ind stalk	1081587
217	10/04/2017	691392	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT		1081587
217	09/29/2017	690575	Consumables		1081322
217	09/29/2017	690575	Consumables		1081322
217	09/29/2017	690575	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	completed	1081059
217	09/25/2017	680188	Remove old A3 Posters with Seniors Festival please leave		1080273
217	09/25/2017	688392	49G8736Wabco Purge Valve Kit	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE203427 Receiving #210491 Date :2017-09-25	1080273
217	09/22/2017	688392		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed.	1079429
217	09/22/2017	688392	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		1079429
217	09/22/2017	688392	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		1079429
217	09/22/2017	688392	KIT CYCLONE CONDENSER VALVE KIT		1079429
217	09/22/2017	688392	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		1079429

217	09/22/2017	688381	Consumables			1079534
217	09/22/2017	688381	Consumables			1079534
217	09/22/2017	688381	Consumables			1079534
217	09/22/2017	688381	MOUNT MUFFLER MOUNT MERCEDES 0500LE (S0T0010)			1079429
217	09/22/2017	688381		CARRY OUT A SERVICE AS PER CHECK LIST completed.		1079429
217	08/30/2017	683325	Drv entered - Brakes Park, Brake Not Holding	road tested brakes park brake holding and doesnt pull bus to one side cannot fault park brakes.		1073703
217	08/22/2017	681576	MIRROR LEFT HAND 380mm			1071730
217	08/22/2017	681576	Accident#:45944 - Ops Entered - Accident - Bus Hitting Objec	Replace broken n/s mirror		1071730
217	08/21/2017	681286	LED NO PLATE+EXIT LIGHT (26674)			1071442
217	08/21/2017	681286		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1071442
217	08/21/2017	681286		VEHICLE SAFETY INSPECTION Completed.		1071442
217	08/21/2017	681375	Consumables			1071730
217	08/21/2017	681375	LED NO PLATE+EXIT LIGHT (26674)			1071442
217	08/21/2017	681375	Mechanic entered - Elec and Light Exterior Lights Both No pl			1071442
217	08/21/2017	681378	KIT AIR LINE FITTING VOSS 22MM (5020114)			1071442
217	08/21/2017	681378	Mechanic entered - Air System Air, Leak Rear	2 Fitting in the back of the air dryer replaced and teasted.		1071442
217	08/21/2017	681455	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	Done		1071442
217	08/16/2017	680245	Install graffiti film	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE200352 Receiving #:207474 Date :2017-08-16		1069837
217	08/15/2017	680245	Vandalism	install graffiti film		1069478
217	08/13/2017	679632	Please remove old posters and fit new one along with hangers	xx		1068152
217	08/03/2017	677753	Consumables			1065701
217	08/03/2017	677753	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	Retorqued pos 2 wheel nuts to 600 NM		1065439
217	08/03/2017	677833	Consumables			1065701
217	08/03/2017	677833	reset horn system	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE199542 Receiving #:207444 Date :2017-08-16		1069837
217	08/03/2017	677833	HORN 24V			1065439
217	08/03/2017	677833	Elec and Light replace horn	repaired by lonsdale		1065439
217	08/02/2017	677590	Drv entered - Steering Shakes/ Wobbles	Checked all steering components tyres and teste driven no defects found. Checked the balance of the tyres replaced the pos 2 outerbalance tyre and tested. All OK.		1065439
217	08/02/2017	677568	Accident#:45492 - Ops Entered - Accident - Bus being hit by	COMPLETED		1065439
217	08/01/2017	677056	Consumables			1065439
217	08/01/2017	677056	Consumables			1065439
217	08/01/2017	677056	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911)			1065083
217	07/31/2017	677055	Drv entered - Steering Shakes/ Wobbles	Checked all steering components tyres and road tested no defects found.		1064742
217	07/31/2017	677072	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Completed.		1064742
217	07/31/2017	677056	Consumables			1065083
217	07/31/2017	677056	Consumables			1065083
217	07/31/2017	677056	Consumables			1065083
217	07/31/2017	677056	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST Completed.		1065083
217	07/31/2017	677056	Consumables			1065083
217	07/31/2017	677056	Consumables			1065083
217	07/31/2017	677056	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed.		1064742
217	07/20/2017	675103	Consumables			1061393
217	07/20/2017	675103	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	completed.		1061036
217	07/19/2017	674905	LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND			1060864
217	07/19/2017	674905		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1060864
217	07/19/2017	674905		VEHICLE SAFETY INSPECTION Completed		1060864
217	07/19/2017	674994	Consumables			1061036
217	07/19/2017	674994	TYRE 13R22.5R RECAP			1060864
217	07/19/2017	674994	Mechanic entered - Wheels and Tyres Worn O/S rear.	Replaced pos 5 and 6 tyres and torqued wheel nuts to 600 NM.		1060864
217	07/19/2017	674993	Ops Entered - Fault - A/C Heating Not Heating - Route: 771	Checked heater taps for open or close position road tested to warm up motor. Checked demister and A/C vents for temp found 41 degrees at demister vents and 21.8 degrees at A/C vents. Could not fault heating.		1060504
217	07/18/2017	674447	Ops Entered - Fault - Steering Shakes/ Wobbles - Route: 78	cannot fault steering no fault found.		1060504
217	07/18/2017	674446	Ops Entered - Fault - Heat & Demist - Route: 771 - Frankst	engine warmed up to normal temp demister working fine.		1060504
217	07/15/2017	674025	AIR CONDITIONING REPAIR	Creditor #:PT-CDAA03 COACHAIR PTY LTD P/O #:PE197956 Receiving #:205014 Date :2017-07-18		1059355
217	07/14/2017	674025	Drv entered - A/C Heating Not Heating	COACHAIR		1059355
217	07/14/2017	673910	Breakdown no steering !!	replaced copper washer on the pressure side of the pump		1059257
217	07/13/2017	673354	Water Pump 0500	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE197757 Receiving #:204645 Date :2017-07-13		1059257
217	07/13/2017	673354	POWER STEERING PUMP SEALING O	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE197757 Receiving #:204645 Date :2017-07-13		1059257
217	07/13/2017	673354	POWER STEERING PUMP 0500 MERCE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE197757 Receiving #:204645 Date :2017-07-13		1059257
217	07/13/2017	673354	Fluid Leaks - Rear of bus (1) at water pump (2) replace st	replaced the water pump and the power steering pump and the suction hose for the power steering		1058997
217	07/05/2017	672016	AIR CONDITIONING REPAIR	Creditor #:PT-CDAA03 COACHAIR PTY LTD P/O #:PE197253 Receiving #:204584 Date :2017-07-12		1057128
217	07/05/2017	672016	Drv entered - A/C Heating Not Heating			1057128
217	07/05/2017	672016	Drv entered - A/C Heating Not Heating	completed by coachair		1054414
217	07/01/2017	671275	Drv entered - Steering Shakes/ Wobbles	Checked front tyres torque rod bushs steering ball joints and sway bar links checked shockers for leaks and toe in. Road tested at 60 to 80 kms could not fault steering.		1056314
217	07/01/2017	670270	Consumables			1056314
217	07/01/2017	670270	Consumables			1054414
217	07/01/2017	670270	Remove old Green 2036/17 registration Label and/ or Blue EF	xx		1054930
217	06/28/2017	670372	Drv entered - Steering Shakes/ Wobbles	road tested couldn't fault steering wheel didnt shake or wobble as described performed correctly and within spec.		1053345
217	06/24/2017	669778	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced.		1052266
217	06/21/2017	668459	RH side parker out	Replaced globe		1051909
217	06/19/2017	660586	Consumables			1051909
217	06/19/2017	660586	Panel above rear door	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE193421-1 Receiving #:203010 Date :2017-06-20		1051111
217	06/16/2017	667781		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1051111
217	06/16/2017	667781		VEHICLE SAFETY INSPECTION Completed.		1050930
217	06/15/2017	666982	FILTER DRYER AIR COND THERMO KING			1050930
217	06/15/2017	666982	COMPRESSOR OIL AIR CON			1051111
217	06/15/2017	667487	Consumables			1051111
217	06/15/2017	667487	Consumables			1051111
217	06/15/2017	667487	Consumables			1050930
217	06/15/2017	667487		CARRY OUT A SERVICE AS PER CHECK LIST		1050248
217	06/14/2017	667262	Brakes Park_Brake Not Releasing door brakes not releasing	Check for park brakes not releasing micro switch on accelerator pedal roller in wrong direction. Remove micro switch face roller in direction of pedaltravel adjust micro switch for door brakes to release at tap of pedal.		1050248
217	06/13/2017	666982		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		1050248
217	06/13/2017	666982		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1050248
217	06/13/2017	666982		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1050248
217	06/13/2017	666982	CONDENSOR FAN A/C CITI-RT			1046110
217	05/29/2017	663957	replace side window	Creditor #:PT-GLA001 GLASS ASSIST PTY LTD P/O #:PE194663 Receiving #:201584 Date :2017-05-30		1046110
217	05/29/2017	663957	Vandalism Vandalism/ Graffiti Exterior			1046110
217	05/29/2017	663919	PULLEY ADJUSTER IDLER PULLEY MERCEDES 0500 (A0005501833)			1046110
217	05/29/2017	663919	Mechanic entered - Engine Belts_Loose Noisy Missing	Bottom mainbelt idler and the bolt and adjuster pulley bolt replaced and tested.		1046110
217	05/25/2017	663377	Drv entered - Engine Noisy or Rattling	no fault found		1045393
217	05/20/2017	661918	Fit A3 Poster/Hangers	xx		1042890
217	05/18/2017	662276	Accident#:45413 - Ops Entered - Accident - Bus hits 3rd Part	replaced n/s/r/t indicator lamp		1043104
217	05/18/2017	662276	LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND			1042890
217	05/17/2017	660586	LAMP INTERIOR AND REVERSING (1413)			1042890
217	05/17/2017	660586	replace rear centre bumper	r/r rear b/bar and asseble		1043104
217	05/17/2017	660586	Consumables			1043104
217	05/17/2017	660586	Consumables			1043104
217	05/17/2017	660586	Consumables			1043104
217	05/16/2017	660586	Interior panel above rear door	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE193421 Receiving #:200675 Date :2017-05-18 VP0476		1043104
217	05/16/2017	660584	Consumables			1042890
217	05/16/2017	660584	Rear Bumper Bar Painted Orange	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE193421 Receiving #:200675 Date :2017-05-18 VP0476		1043104

217	05/16/2017	660584	Consumables			1042890
217	05/15/2017	660585	image - buff up body work	cut and polish both sides of bus paint o/s front paint wheel rims		1042352
217	05/11/2017	660585	Consumables			1042535
217	05/15/2017	660585	Consumables			1042535
217	05/13/2017	661059	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	Cleaned and secured door checked operation ok		1042134
217	05/13/2017	661059	Consumables			1042140
217	05/13/2017	661059	Consumables			1042140
217	05/11/2017	660586	replace rear centre bumper			1041911
217	05/11/2017	660572	Consumables			1041911
217	05/11/2017	660572	Consumables			1041911
217	05/11/2017	660585	image - buff up body work			1041911
217	05/11/2017	660584	replace panel above rear door	complete job as required		1041911
217	05/11/2017	660572	BAC ducts loose	r/ a/c ducting and secure		1041911
217	05/10/2017	660319	Consumables			1041911
217	05/10/2017	660319	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retorqued pos 3 and 4 wheel nuts to 600 Nm.		1041428
217	05/09/2017	660261	EMERGENCY EXIT (HAMMER)			1041428
217	05/09/2017	660261		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1041428
217	05/09/2017	660261		VEHICLE SAFETY INSPECTION		1041428
217	05/09/2017	660268	Consumables			1041619
217	05/09/2017	660268	Mechanic entered - Wheels and Tyres Damaged P4 sidewall spli	Replace P4 and torque to 600nm		1041428
217	05/09/2017	660268	TYRE 11R22.5R RECAP			1041428
217	05/06/2017	659823	Consumables			1041071
217	05/06/2017	659823	Consumables			1041071
217	05/06/2017	659823	SWITCH DOOR BUTTON NORMALLY OPEN			1041071
217	05/06/2017	659823	Drv entered - Body Front_Door Operation Faulty	Check and replace front door switch		1041071
217	05/05/2017	647879	Consumables			1040715
217	05/05/2017	647879	Consumables			1040715
217	05/05/2017	647879	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS			1040715
217	05/04/2017	659334	Vandalism	xx		1040360
217	05/01/2017	659334	DIRECT PURCHASE - VANDALISM	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE192925 Receiving #:199754 Date :2017-05-05		1040360
217	04/27/2017	654254	GLOBE 24V 5W WEDGE			1037984
217	04/21/2017	657239	Consumables			1036799
217	04/21/2017	657239	Consumables			1036799
217	04/21/2017	657239	Body (None) leak over driver seat onto dash	seal roof aerials		1036679
217	04/19/2017	656196	Consumables			1036323
217	04/19/2017	656196	Consumables			1036323
217	04/19/2017	656196	replace rear door floor tile	replace rear step floor tile		1036323
217	04/13/2017	656108	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG			1034691
217	04/13/2017	656108	Mechanic entered - Engine Belts_Loose Noisy Missing			1034691
217	04/13/2017	656108	WASHER SPRING PIN 3.97mm MERCEDES 1418			1034691
217	04/13/2017	656108	Engine Noisy or Rattling 2X front engine mounts u/s	replaced front engine mounts		1034691
217	04/13/2017	656196	replace rear door floor tile			1034691
217	04/13/2017	656224	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115			1034691
217	04/13/2017	656224	KIT AIR LINE FITTING VOSS 22MM (5020114)			1034691
217	04/13/2017	656224	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)			1034691
217	04/13/2017	656224	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER			1034691
217	04/13/2017	656224	KIT HALDEX CONDENSER KIT TOP (CYCLONE)			1034691
217	04/13/2017	656224	KIT CYCLONE CONDENSER VALVE KIT			1034691
217	04/13/2017	656224		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST		1035983
217	04/12/2017	656108	Engine mounts	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE191633 Receiving #:198445 Date :2017-04-18		1034777
217	04/12/2017	656097	Consumables			1034777
217	04/12/2017	656097	Consumables			1034777
217	04/12/2017	656097	Consumables			1034777
217	04/12/2017	656097	Consumables			1034691
217	04/06/2017	654972	Mechanic entered - Elec and Light Exterior Lights O/S front	Replaced globe		1032650
217	04/03/2017	654235	Consumables			1032389
217	04/03/2017	654235	Mechanic entered - Wheels and Tyres Wheel Nut Retension P 3	Retorqued pos 345 and 6 wheel nuts to 600 NM.		1031853
217	04/03/2017	654254	GLOBE 24V 5W WEDGE			1031853
217	04/03/2017	654254	Mechanic entered - Elec and Light Exterior Lights o/s front	Replaced globe		1031853
217	03/31/2017	654091		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Checked wheel nut torque as per spec		1031417
217	03/31/2017	654091		VEHICLE SAFETY INSPECTION Done safety check as per check list		1031417
217	03/31/2017	654109	Consumables			1031853
217	03/31/2017	654091	Consumables			1031853
217	03/31/2017	654109	Mechanic entered - Wheels and Tyres Worn P345	Replaced tyre p345 , torqued wheel nuts as per spec booked for retorqued		1031417
217	03/31/2017	654109	TYRE 11R22.5R RECAP			1031417
217	03/31/2017	654091	Mechanic entered - Wheels and Tyres Worn P345	WO no 654109		1031417
217	03/28/2017	653276	Consumables			1029587
217	03/28/2017	653276	Mechanic entered - Wheels and Tyres Vibration Wheels squeaki	road tested no noise found.		1029693
217	03/25/2017	652271	Please remove any old poster and fit either Good News for T	xx		1028004
217	03/24/2017	652730	GLOBE 24V 5W BAYONET (17181)			1028362
217	03/24/2017	652730	GLOBE 24V 18W			1028362
217	03/24/2017	652730	Mechanic entered - Elec and Light Exterior Lights O/S/F/Top	Removed the drivers blindreplaced both indicator and parker globes and tested.		1028362
217	03/20/2017	651668	Drv entered - Brakes Park_Brake Not Releasing	Checked the park brakes working OK.		1027282
217	03/16/2017	650773	Consumables			1026392
217	03/16/2017	650773	Consumables			1026392
217	03/16/2017	650773	seat covers	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:PE189442 Receiving #:196239 Date :2017-03-17		1026392
217	03/14/2017	650773	Body Drivers Seat Cover			1025478
217	03/14/2017	650631	Breakdown#:33265 - Ops Entered - Breakdown - Breakdown Road	Replaced the ruptured heater hose from lift pump to the transtoppped upbled the system and tested.		1025478
217	03/12/2017	650931	Breakdown - Tyrbid - Coolant Leak	Found from heater hose turned heater tap off topped up coolant send bus to PBL (need to replace heater hose)		1025478
217	03/10/2017	650066	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE189173 Receiving #:19563 Date :2017-03-21		1027642
217	03/09/2017	650135		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		1024523
217	03/09/2017	650066		ANNUAL SAFETY INSPECTION SERIAL# COMPLETED.		1024523
217	03/08/2017	649916	GLOBE 24V 18W			1024523
217	03/08/2017	649916	GLOBE 24V 5W WEDGE			1024523
217	03/08/2017	649916	Final Rsi	completed.		1024523
217	03/06/2017	649232	Consumables			1024164
217	03/06/2017	649232	Mechanic entered - Wheels and Tyres Wheel Nut Retension P2	completed.		1023515
217	03/04/2017	648198	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	xx		1022129
217	03/03/2017	648566	carry out RSI repairs	completed all rsi repairs.		1023050
217	03/03/2017	649056	TYRE 11R22.5R RECAP			1023050
217	03/03/2017	649056	Drv entered - Steering Shakes/ Wobbles	replaced o/s/rf tyre as it was unevenly worn tested okay.		1023050
217	03/03/2017	649056	tube silicone	Creditor #:PT-BURSON BURSON AUTOMOTIVE PTY LTD P/O #:PE188822 Receiving #:195364 Date :2017-03-06		1023806
217	03/03/2017	649056	steam clean for RSI	completed.		1023050
217	03/03/2017	649056	Drv entered - Elec and Light Exterior Lights -b Headlight Po			1023050
217	03/03/2017	648744	KIT AIR LINE FITTING VOSS 22MM (5020114)			1023050
217	03/03/2017	648744	Air System Air_Leak Rear	replaced ecas suspension valve tested okay rekkitted air fittings that were leaking.		1023050
217	03/03/2017	649102	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	Completed dash switch labeling		1023050
217	03/02/2017	648566	sway bar link 50Y3522ZF	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE188628 Receiving #:195118 Date :2017-03-02		1023050
217	03/02/2017	648566	nut 50L0003	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE188628 Receiving #:195115 Date :2017-03-02		1023050

[illegible]

217	11/10/2016	626964	SET DISC PAD SET SCANIA / MERCEDES 0500		990989
217	11/10/2016	626964	n/s rear hub seal	Replace rear axle brake pads. fit new hub seal to near side rear.	990989
217	11/10/2016	626953	Consumables		991083
217	11/10/2016	626953	Consumables		991083
217	11/10/2016	626953	Mechanic entered - Body Passenger Seat Torn	replace step edging in back of bus	990989
217	11/09/2016	626813	Consumables		990989
217	11/09/2016	626813	Consumables		990989
217	11/09/2016	626813	Consumables		990989
217	11/09/2016	626813	Consumables		990989
217	11/08/2016	626553	Drv entered - Ticket Equip	CARRY OUT A SERVICE AS PER CHECK LIST	990989
217	11/08/2016	626488	AIR DRYER ASSY VOLVO R10 (A004	Could not find any faults.	990901
217	11/08/2016	626488	KIT CYCLONE CONDENSER VALVE KIT	Creditor # :PT-MUL001 MULTISPARES LTD P/O # :PE180910 Receiving #:187189 Date :2016-11-09	990989
217	11/08/2016	626488	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		990901
217	11/08/2016	626488		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Remove clean and fit ping tank air cyclone separator air lines and replaced air drier since threads on purge plug stripped.	990901
217	11/02/2016	625248	KIT AIR LINE FITTING VOSS 22MM (5020114)		988768
217	11/02/2016	625248	Fluid Leaks Rear of bus N/S/R Hub seal leaking	Steam clean rotor and brake caliper - unable to clean middle of hub. clean out 100% blocked diffy breather. to be re-inspected.	988768
217	10/31/2016	624968		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed.	988768
217	10/31/2016	624968		VEHICLE SAFETY INSPECTION completed.	988768
217	10/28/2016	624454	Fit A3 poster to holder either Explore Melbourne or PTV Ap	COMPLETE	988110
217	10/24/2016	623406	Consumables		987012
217	10/24/2016	623406	Drv entered - Body Drivers Seat Controls	no fault found	986558
217	10/24/2016	623406	Drv entered - Body Drivers Seat Leaning	no fault found	986558
217	10/21/2016	623166	Drv entered - GPS	Reported to op's	986558
217	10/18/2016	622232	Lower eng Pulley	Creditor # :PT-MUL001 MULTISPARES LTD P/O # :PE179564 Receiving #:185682 Date :2016-10-18	985502
217	10/17/2016	622232	Breakdown#:32890 - Ops Entered - Breakdown - Breakdown Road	went out to bus found idler pulley was missing had collapsed and fallen off limped bus back to yard refitted new idler pulley refit belt roadtested okay.	985220
217	10/12/2016	621512	Drv entered - Elec and Light Exterior Lights	no fault found	983665
217	10/12/2016	621512	Consumables		983914
217	10/12/2016	621512	Drv entered - Body Drivers Seat Controls	adjust drivers seat belt re route air lines for lumbar support	983665
217	10/12/2016	621512	Drv entered - Body Drivers Seat Controls		983665
217	10/12/2016	621512	Drv entered - Body Drivers Seat Belt		983665
217	10/11/2016	621048	GLOBE 24V 70W H1		983326
217	10/11/2016	621048	GLOBE 24V 5W WEDGE		983326
217	10/11/2016	621048	Mechanic entered - Elec and Light Exterior Lights	Replace offside front headlight globe and park light globe.	983326
217	10/04/2016	619733	Drv entered - Trmtable		980953
217	10/04/2016	619733	STALK INDICATOR MERCEDES 0500	Creditor # :PT-MUL001 MULTISPARES LTD P/O # :PE178459 Receiving #:184649 Date :2016-10-04	980953
217	10/04/2016	619733	Drv entered - Elec and Light Indicators Not Working	Replaced broken and loose indicator arm Assy.	980953
217	10/04/2016	619733	Drv entered - Elec and Light Indicators Not Working		980953
217	10/04/2016	619733	Drv entered - Elec and Light Indicators Not Working		980953
217	09/30/2016	618977	A3 Poster Change please remove old poster and fit Vitorian	x	979390
217	09/30/2016	618977	Consumables		980151
217	09/28/2016	618962	Wipers and Washers Wipers Loose - Drivers side goes up th		979390
217	09/27/2016	618738		VEHICLE SAFETY INSPECTION Completed.	979114
217	09/27/2016	618738		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed.	979114
217	09/25/2016	617677	Campaign 14/16 Destination signs Setting and loadig Films.	X	978006
217	09/22/2016	613363	Consumables		978006
217	09/22/2016	613363	Consumable - BODYWORK	Creditor # :PT-VOLGRE VOLGREN AUSTRALIA P/O # :PE176074 Receiving #:183780 Date :2016-09-22	977752
217	09/21/2016	617289	Drv entered - A/C Heating Not Heating		977492
217	09/21/2016	617282	Ops Entered - Fault - A/C Heating Not Heating - Route: 771		977492
217	09/21/2016	617133	Left hand rear side metal strip off inside bus	replace metal strip on near side of bus	977492
217	09/21/2016	617133	Consumables		977752
217	09/19/2016	616574	Mechanic entered - Body Windows Side	fit side window moulding	977039
217	09/19/2016	616574	Consumables		977236
217	09/16/2016	616412	Vandalism/ graffiti all over the back of the bus.	Cleaned	976971
217	09/16/2016	616272	replace side window	Creditor # :PT-GLA001 GLASS ASSIST PTY LTD P/O # :PE177214 Receiving #:183558 Date :2016-09-20	977236
217	09/16/2016	616272	replace windscreen	Creditor # :PT-GLA001 GLASS ASSIST PTY LTD P/O # :PE177214 Receiving #:183558 Date :2016-09-20	977236
217	09/16/2016	616272	DOUBLE SEAT BASE RETRIMMED		976971
217	09/16/2016	616272	Drv entered - Body Windows Rear	glassassist	976971
217	09/16/2016	616272	Drv entered - Body Drivers Seat Controls	no fault found	976971
217	09/16/2016	616272	Drv entered - Body Water Leaks Windows	glassassist	976971
217	09/16/2016	616272	Drv entered - Body Drivers Seat Leaning	no faults found	976971
217	09/16/2016	616272	Consumables		977039
217	09/15/2016	616036	Wipers and Washers not wiping	readjusted wipers tested okay.	975951
217	09/15/2016	616035	Drv entered - Wipers and Washers Wipers Loose	tightened wipers cannot fault.	975951
217	09/14/2016	615848	Anti graffiti film - L1L2L3 R1		975951
217	09/14/2016	615712	Drv entered - Body Drivers Seat Leaning		975951
217	09/14/2016	615712	Ops Entered - Fault - Body Windows Side - Route: - Take a		975951
217	09/14/2016	615712	Drv entered - Body Drivers Seat Controls		975951
217	09/14/2016	615712	Consumables		976619
217	09/13/2016	615712	Drv entered - Body Drivers Seat Leaning	FIT NEW DRIVERS SEAT BASE	975951
217	09/13/2016	615712	Retrimmed Base Assy 6008		975951
217	09/13/2016	615712	Ops Entered - Fault - Body Windows Side - Route: - Take a		975951
217	09/13/2016	615712	Drv entered - Body Drivers Seat Controls		975951
217	09/13/2016	615701	Consumables		976268
217	09/13/2016	615701	Consumables		975951
217	09/13/2016	615701	FILTER AIR FILTER MERCEDES BENZ 0500LE (E4911)	CARRY OUT B SERVICE AS PER CHECK LIST Completed.	975951
217	09/13/2016	615701	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		975951
217	09/13/2016	615701	Consumables		976268
217	09/13/2016	615701	Consumables		976268
217	09/13/2016	615701	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	975951
217	09/08/2016	614788	Consumables		975008
217	09/08/2016	614788	Ops Entered - Fault - Body Drivers Seat Leaning - Route: 77	seat inspected no fault found	974773
217	09/07/2016	614523	Consumables		974773
217	09/07/2016	614523	Drv entered - Body Water Leaks Roof. Water started drippin	no leaks found	974418
217	09/05/2016	613961	Consumables		974067
217	09/05/2016	613961	Consumables		974067
217	09/05/2016	613961	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST completed.	973406
217	09/02/2016	613860	Consumables		973082
217	09/02/2016	613860	Body Water Leaks Windows and above the driver's seat.(bul	double fault recorded	972729
217	09/01/2016	611990	DIRECT PURCHASE - VANDALISM	Creditor # :PT-GLA010 GLASSPROTECH MELBOURNE P/O # :PE175619 Receiving #:183543 Date :2016-09-20 Replace window film	972736
217	08/31/2016	613363	Consumables		972375
217	08/31/2016	613363	Body drivers modesty panel damaged	REPLACE PANEL	972023
217	08/30/2016	612931	Consumables		972023
217	08/30/2016	612931	Please remove old poster and fit new Legacy poster	Replaced Poster	971670
217	08/25/2016	611990	Vandalism Vandalism/ Graffiti Interior - replace window f		970627
217	08/20/2016	610984		Tension wheel nuts P 56 to 600Nm	968880
217	08/19/2016	610815		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	968880
217	08/19/2016	610815		VEHICLE SAFETY INSPECTION Completed.	968880
217	08/19/2016	610882	Consumables		968996

217	08/19/2016	610882	TYRE 11R22.5R RECAP			968880
217	08/19/2016	610882	Mechanic entered - Wheels and Tyres Worn Pos 5 and 6 worn.	Replaced and torqued to 600 NM.Needs rebooked for retorqe and clean the rims.		968880
217	08/18/2016	610557	Drv entered - Elec and Light Indicators Not Working	Test indicators no lights out found indicator stalk loose. Tighten indicator stalk. re test no further faults found		968880
217	08/18/2016	610555	Drv entered - Elec and Light Indicators Not Working	Test indicators no lights out found externally indicator stalk loose tightened up and checked ok.		968880
217	08/18/2016	610559	Consumables			968880
217	08/18/2016	610559	Drv entered - Body Drivers Seat Leaning	replace air switch on drivers seat		968880
217	08/18/2016	610559	Drv entered - Body Drivers Seat Cover	no fault found		968880
217	08/18/2016	610559	Drv entered - Body Drivers Seat Controls	replace air switch on drivers seat		968880
217	08/09/2016	608873	GLOBE 24V 5W WEDGE			965821
217	08/09/2016	608873	Mechanic entered - Elec and Light Exterior Lights R/H/F/L pa	Replaced.		965821
217	08/06/2016	608453	Consumables			965182
217	08/06/2016	608453	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	v		964542
217	08/03/2016	607946	Elec and Light / fit relay	completed		964035
217	07/28/2016	606473	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	fitted by elias...repaired by ben were		962347
217	07/23/2016	605591	Consumables			960999
217	07/23/2016	605591	Consumables			960999
217	07/23/2016	605591	Drv entered - Body Drivers Seat Leaning	Checked driver seat could not fault it. bus suspension is not leaning either. checked seat with spirit level found to be straight.		960646
217	07/23/2016	605591	Drv entered - Body Drivers Seat Belt	Checked seat belt for extension retracting and lock on jolt all working good.		960646
217	07/23/2016	605591	Drv entered - Body Drivers Seat Controls	Tried all driver seat control could mnot fault controls.		960646
217	07/21/2016	605251	Consumables			960646
217	07/21/2016	605251	Consumables			960646
217	07/21/2016	605251	DECAL FIRE EXTINGUISHER DOWN ARROW			960447
217	07/21/2016	605251	DECAL SAFETY TRIANGLE BEHND PANEL WHITE STBP100			960447
217	07/21/2016	605251	decal campaign			960447
217	07/15/2016	604268		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		958949
217	07/15/2016	604268		VEHICLE SAFETY INSPECTION		958949
217	07/15/2016	604296	repair Fluid Leaks	clean out engine breather		958949
217	07/14/2016	604044		reverse alarm U/S. Replaced.		958548
217	07/14/2016	604044		Fr O/S parker out. Replaced.		958548
217	07/14/2016	604044	NARVA 24V REVERSING BUZZER			958548
217	07/14/2016	604044	GLOBE 24V 5W WEDGE			958548
217	07/14/2016	604044	Steam clean engine and check fluid Leaks			958548
217	07/14/2016	603815	Air System Air_Leak Rear	replacde the accumulator solonoid valve and tested.		958548
217	07/13/2016	603815	INVOICE RECEIVED WITH GST IN E	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE172471REV Receiving #178791 Date :2016-07-20		959738
217	07/13/2016	603815	RE ENTER WITHOUT GST	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE172471-1 Receiving #178793 Date :2016-07-20		959738
217	07/13/2016	603815	SOLENOID VALVE FAULTO (0501 31	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE172471 Receiving #178401 Date :2016-07-13		958548
217	07/13/2016	603865	Mechanic entered - Air System Air_Leak Rear Trans. Accumulat	Replaced and tested.		958623
217	07/13/2016	603808	Consumables			958623
217	07/13/2016	603808	Consumables			958623
217	07/13/2016	603808	Consumables			958623
217	07/13/2016	603808	Consumables			958623
217	06/29/2016	600636	Fluid Leaks. Interior/ above the window screen behind CCTV	CARRY OUT A SERVICE AS PER CHECK LIST Completed.		954458
217	06/27/2016	600182	LAMP LED SIDE MARKER PERI RED/AMBER (LLX30131)	Unable to locate any water leaks.		954094
217	06/27/2016	600182	Elec and Light/ clearance lights at the rear. front clearanc	Fit 2 x new rear clearance lights. no fault found with front lights Fit 2 x new rear clearance lights.		954094
217	06/27/2016	600182	Ops Entered - Fault - Elec and Light Exterior Lights - Rout			954094
217	06/27/2016	600182	Consumables			954197
217	06/23/2016	599609	Drv entered - Wipers and Washers Wipers Not Working	Repair loose o/s wiper arm and replace blade		953485
217	06/23/2016	599609	Drv entered - Elec and Light Exterior Lights			953485
217	06/23/2016	599609	Consumables			953485
217	06/23/2016	599609	Drv entered - Elec and Light Indicators Not Working	Check all indicators ok		953485
217	06/23/2016	599609	Drv entered - Elec and Light Two Way Radio	Checked ok		953485
217	06/23/2016	599609	Drv entered - Elec and Light Interior Lights	Check all int lights no fault found		954197
217	06/20/2016	598586	front screen one piece track b	Creditor #PT-GLA001 GLASS ASSIST PTY LTD P/O #PE170483 Receiving #177132 Date :2016-06-28		952138
217	06/20/2016	598586	Body Windows Front	DONE3 BY GLASSASSIST		952779
217	06/20/2016	598586	Consumables			952779
217	06/20/2016	598586	Consumables			952138
217	06/20/2016	598586	Mechanic entered - Air System Air_Leak Rear			952138
217	06/17/2016	598532	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			952138
217	06/17/2016	598532		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST		952138
217	06/17/2016	598569	Phase remove any old poster and fit new A3 poster and add			952138
217	06/17/2016	598569	Consumables			952138
217	06/17/2016	598569	Consumables			952138
217	06/14/2016	597451	A/C Heating Not Cooling	Found the stem seal was leaking due to pulled threads helicoil failed threadsandassemble pressure tested and vac system run unit up tested ok Note the seals had gone hard will check again in a week or so		951345
217	06/14/2016	597303	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a			951345
217	06/14/2016	597354		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		951345
217	06/10/2016	596903	ACCUMULATOR RETARDER VALVE	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE170098 Receiving #176245 Date :2016-06-20		952462
217	06/10/2016	596903	Mechanic entered - Air System Air_Leak Rear	Minor leak at the accumulator area.		950162
217	06/09/2016	596560		Retentioned to 600NM. Horn adjusted and tested Accumulator valve leaking.		949766
217	06/09/2016	596513	HEAD LAMP INSERT HELLA 100MM L	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE169940 Receiving #175881 Date :2016-06-10		950048
217	06/09/2016	596513	Elec and Light R/S head lamp replacment	replaced o/s headlight and focused both of them		949766
217	06/09/2016	596513	Consumables			950162
217	06/08/2016	596458	head Light focus	focused headlights o/s needs replacing		949766
217	06/08/2016	596458	Consumables			950048
217	06/06/2016	595986		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		949412
217	06/06/2016	595986		VEHICLE SAFETY INSPECTION		949412
217	06/06/2016	595985	TYRE RECAP 11R22.5R			949412
217	06/06/2016	595985	Mechanic entered - Wheels and Tyres Worn replaced n/s/r tyre	replaced n/s/r tyres		949412
217	06/06/2016	595985	Consumables			949412
217	06/06/2016	595985	A/C Heating grease clutch betring			949412
217	06/06/2016	595985	focus head lamp	checked ok		949412
217	06/06/2016	595985	Consumables			949412
217	06/06/2016	597303	DIRECT PURCHASE - ELECTRICAL	Creditor #PT-BWE001 BWERE ELECTRICS PTY LTD P/O #PE171060 Receiving #176869 Date :2016-06-27		954094
217	06/06/2016	595985	Drv entered - Comm Equip			949412
217	06/06/2016	595826	MAP POCKETS COACH SEATS			949412
217	06/06/2016	595826	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTAL	fit drivers wallet holder		949412
217	06/06/2016	595826	Consumables			949412
217	06/06/2016	595826	Consumables			949412
217	06/03/2016	595470		Retentioned pos 345 and 6 wheel nuts to 600 NM.		948327
217	06/03/2016	595540	Mechanic entered - Vandalism Vandalism/ Graffiti Exterior	remove graffiti from back of bus		948327
217	06/02/2016	595325	Wheels and Tyres position 5 & 6 worn	swapped tyres around still at above 3mm good to use for at least another week.		948327
217	06/02/2016	595325	Consumables			948610
217	05/30/2016	594654	Elec and Light number plate lamp n/w	replaced light only all ok but bumper need replacing		947386
217	05/30/2016	594659	Drv entered - Brakes Warning Light On	checked all in good working order Checked all brakes and tested. No warning lights or defects found.		947386
217	05/26/2016	593953	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204			946377
217	05/26/2016	593953	GLOBE H1 24V 70W			946377
217	05/26/2016	593953	GLOBE 24V 18W			946377
217	05/26/2016	593953	Elec and Light/ number plate light n/w	replaced headlight and re adjusted aim checked ok		946377
217	05/26/2016	593953	N/S low beam head light needs replacing	Focused and tested.		946377
217	05/23/2016	593175	focus head lights			945460

217	05/23/2016	593175	rear marker incorrectly installed	Refitted the correct way.	945460
217	05/23/2016	593175	Drv entered - Diff & Hubs	Completed.	945460
217	05/23/2016	593136	Mechanic entered - CCTV Timestamp Incorrect		945460
217	05/23/2016	593212	Consumables		945661
217	05/23/2016	593212	Ops Entered - Fault - Body Drivers Seat Belt - Route: 781	Checked both seat belt and the buckle and in good condition.	945460
217	05/23/2016	593174	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Completed.	945460
217	05/23/2016	593176	Consumables		945661
217	05/23/2016	593176	Consumables		945661
217	05/23/2016	593176	Consumables		945661
217	05/23/2016	593176	Consumables		945661
217	05/18/2016	591395	THERMOSTAT 71DEG	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	945460
217	05/18/2016	592255	Consumables	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE168024 Receiving #:174283 Date :2016-05-19	944148
217	05/18/2016	592255	Ops Entered - Fault - Body Drivers Seat Controls - Route: 8	Checked no defects found	944148
217	05/12/2016	591395	Fluid Leaks Rear of bus	Replaced the thermostat valves and the sealediff coolent and tested.	941764
217	05/12/2016	591246	As per Campaign 2/16 Review and Reset Camera Angles and ensu	completed	941764
217	05/12/2016	591211	Consumables		942125
217	05/12/2016	591211	Mechanic entered - Body Drivers Seat Controls		941764
217	05/12/2016	591256	KIT AIR LINE FITTING VOSS 22MM 5020114	SECURE BODY PANELS TIGHTVE DRIVERS SEAT BACKREPAIR DRIVERS BLNDS REPAIR STRIKER PLATE FOR DRIVERS DOOR SECURE FRONT MODESTY PANEL	941764
217	05/12/2016	591256	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115		941764
217	05/12/2016	591256	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		941764
217	05/12/2016	591256			941764
217	05/12/2016	591256			941764
217	05/12/2016	591256	CYCLONE CONDENSER VALVE KIT	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST clean out air cyclone seperator and ping tank. clean out engine breather.	941764
217	05/12/2016	591256	HALDEX CONDENSER KIT TOP(CYCLONE)		941764
217	05/03/2016	589429	Consumables		939517
217	05/03/2016	589429	Ops Entered - Fault - Body Water Leaks Roof - Route: 781 -	no fault found	939156
217	05/02/2016	589430		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	939010
217	05/02/2016	589430		VEHICLE SAFETY INSPECTION Completed.	939010
217	05/02/2016	589429	Ops Entered - Fault - Body Water Leaks Roof - Route: 781 -		939010
217	05/01/2016	579175	SINGLE SEAT BASE	Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE163436 Receiving #:173917 Date :2016-05-16	941077
217	04/30/2016	589244	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 771	Repaired see w/o 589199	938757
217	04/30/2016	589199	RADIATOR HOSE UPPER 0500LE		938580
217	04/30/2016	589199	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 771	Replace top engine elbow hose	938580
217	04/29/2016	589119	Consumables		938580
217	04/29/2016	589119	Consumables		938580
217	04/29/2016	589119	body interior water leak		938417
217	04/28/2016	572345	REAR REFLECTOR 85050	Seal o/s/f roof area	938060
217	04/28/2016	588736	Drv entered - Heat & Demist air blowing no heat	Open front hatch turn heater tap on. close front hatch.	938060
217	04/27/2016	588438	Mechanic entered - Elec and Light Exterior Lights	Drill new hole and fit new screw to rear stop light.	937395
217	04/19/2016	587172	1MT MULTI FIT WIPER REFILL		935227
217	04/19/2016	587172	Mechanic entered - Wipers and Washers Other blade broken	Replaced O/S wiper refill.	935227
217	04/12/2016	585509	rebrand rear	Creditor #PT-LAB010 LABEL CONCEPTS P/O #PE165563 Receiving #:171847 Date :2016-04-15	934632
217	04/11/2016	585584	Consumables		933209
217	04/11/2016	585584	Consumables		933209
217	04/11/2016	585584	Mechanic entered - Body Windows Side 2 cracked windows on L/	no fault found	933016
217	04/08/2016	585206	Mechanic entered - Vandalism Vandalism/Graffiti Interior	fit new seat bases and seat backs	933016
217	04/06/2016	583509	Vandalism	done by labelconcepts	933016
217	04/04/2016	583509	SINGLE SEAT BACK REST	Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE165158 Receiving #:171062 Date :2016-04-04	933016
217	04/04/2016	583509	SINGLE SEAT BASE	Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE165158 Receiving #:171062 Date :2016-04-04	933016
217	04/01/2016	583509	Vandalism		933016
217	04/01/2016	583509	Vandalism rear rego plate 5994 AO		933016
217	03/30/2016	583509	Vandalism	REMOVE SEAT BACKS AND SEAT BASES FOR RECOVERING DUE TO VANDALISM	933016
217	03/30/2016	578316	M/B AIR CHARGE VALVE 16mm	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE164064 Receiving #:170787 Date :2016-03-30	933016
217	03/22/2016	582606	Ops Entered - Fault - Ticket Equip - Route: 779 - Kananook	Checked all OK.	930708
217	03/22/2016	582606	Consumables		930959
217	03/22/2016	582606	Consumables		930959
217	03/22/2016	582606	AIR FILTER MERC 0500LE E491L		930708
217	03/22/2016	582606	FUEL FILTER MERC 0500LE		930708
217	03/22/2016	582606	FUEL FILTER 0500LE		930708
217	03/22/2016	582606	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468		930708
217	03/22/2016	582606	Consumables	CARRY OUT C SERVICE AS PER CHECK LIST	930959
217	03/22/2016	582606	Consumables		930959
217	03/22/2016	582606	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST	930708
217	03/22/2016	582606	Consumables		930959
217	03/22/2016	582606	Consumables		930959
217	03/22/2016	582606	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	930959
217	03/22/2016	582606	Consumables		930708
217	03/17/2016	581667		Tension wheel nuts P2 to 600Nm	928695
217	03/15/2016	581358		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	928586
217	03/15/2016	581358		VEHICLE SAFETY INSPECTION Completed.	928586
217	03/15/2016	581390	Consumables		928695
217	03/15/2016	581390	FESTOON GLOBE 24V/18W		928586
217	03/15/2016	581390	TYRE NEW 11R22.5N	Pos 2 replaced and torqued to 600 NM.N/5/R red reflector replaced.	928586
217	03/15/2016	581390	Mechanic entered - Wheels and Tyres Worn Pos 2 worn.	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE163868 Receiving #:169857 Date :2016-03-15	928586
217	03/15/2016	580214	WATER PUMP	Creditor #PT-ROASAF ROAD SAFETY INSPECTIONS P/O #PE164062 Receiving #:170172 Date :2016-03-21	930353
217	03/11/2016	580725	DIRECT PURCHASE - BUS INSPECTI	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE164064 Receiving #:168830 Date :2016-03-15	928586
217	03/11/2016	578316	M/B AIR CHARGE VALVE 16mm	ANNUAL SAFETY INSPECTION SERIAL # Completed	927066
217	03/10/2016	580725			927333
217	03/10/2016	580701	Consumables		927066
217	03/10/2016	580701	Consumables		927333
217	03/10/2016	580701	Body	lube door joints	927066
217	03/09/2016	580513	Consumables		927066
217	03/09/2016	580513	Consumables		927066
217	03/09/2016	580513	The Campaign requires all Bus destinations systems to be in		927066
217	03/09/2016	580525	Brakes	checked all in good working order	927066
217	03/08/2016	580214	THERMOSTAT 71DEG	Creditor #PT-AUJ001 MULTISPARES LTD P/O #PE163915 Receiving #:169524 Date :2016-03-08	926713
217	03/08/2016	580214	Fluid Leaks Rear of bus water pump leaking	replaced water pump and all gaskets to and from water pump tested okay needs a roadtest to complete.	927066
217	03/08/2016	579859	Consumables		927066
217	03/08/2016	579859	Consumables		927066
217	03/08/2016	579859	STEERING WHEEL 0500LE		927066
217	03/08/2016	579859	Mechanic entered - Body Other steeringwheel missing a 2cm ch	replaced steering wheel. tested okay.	927066
217	03/07/2016	579859	Mechanic entered - Body Other steeringwheel missing a 2cm ch	filled with foam and taped over to temporarily fix bus so it can go out bus will need a new steering wheel ordered.	926417
217	03/03/2016	579176	repair ctzv	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE163433 Receiving #:170167 Date :2016-03-21	930353
217	03/03/2016	578316	M/B AIR CHARGE VALVE 16mm	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE163403 Receiving #:169416 Date :2016-03-07	926710
217	03/02/2016	579116		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	925278
217	03/02/2016	579175	Vandalism seat base x2	replaced seats	925278
217	03/02/2016	579176	Hard drive have no footage recorded since 29/01/2015. (Mile	reset date	925278
217	03/02/2016	579116	Mechanic entered - Air System Air Leak Rear		925278
217	03/02/2016	579116	AIRBAG FRONT AND REAR 0405/0500REAR/ B10M/B7R REAR		925278

217	03/02/2016	579115	Consumables			925407
217	03/02/2016	579115	Consumables			925407
217	03/02/2016	579115	AIR FILTER MERC 0500LE E491L			925278
217	03/02/2016	579115	OIL FILTER 1725+0500LE E161H01D28			925278
217	03/02/2016	579115		CARRY OUT B SERVICE AS PER CHECK LIST		925278
217	03/02/2016	579115	Consumables			925407
217	03/02/2016	579115	Consumables			925407
217	03/02/2016	579115		CARRY OUT A SERVICE AS PER CHECK LIST		925278
217	03/01/2016	578771	Vandalism interior grafiti/ floors/windows/roof	done		924860
217	03/01/2016	578019	PARKBRAKE VALVE 0500LE A00343	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE163067 Receiving #170151 Date :2016-03-21		930353
217	02/29/2016	578022	HEAD LAMP H7 HIGH BEAM	Creditor #PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #PE163069 Receiving #169002 Date :2016-03-01		925221
217	02/26/2016	570743	REGULATOR VOLTAGE 0405NH 94V0003 VR3014G			923983
217	02/26/2016	578318	Breakdown#:32330 - Ops Entered - Breakdown - Breakdown Road			923983
217	02/26/2016	578316	Breakdown#:32330 - Ops Entered - Breakdown - Breakdown Road	as above		923983
217	02/26/2016	578316	Ops Entered - Fault - Air System Air Not Building_Up - Rou	replaced air test fitting and returned to depot		923983
217	02/25/2016	578025	Elec and Light/ HEAD LAMP	replaced u/s/o/s high beam light tested okay.		923631
217	02/25/2016	578003	GLOBE WEDGE 24V 1.2W H/W241.2 47706 SWFLED E-596FWLED			923631
217	02/25/2016	578003	carry out RSJ repairs and steam clean	replaced blown dash switch globes. rektitted leaking air fitting on n/s non top of triple air tanks. completed rsi repairs and steamcleaned.		923631
217	02/25/2016	578003	KIT AIR LINE FITTING VOSS 22MM 5020114			923631
217	02/25/2016	578003	Consumables			923983
217	02/25/2016	578003	Consumables			923983
217	02/25/2016	578019	SWITCH - PARKBRAKE MB0500			923983
217	02/25/2016	578019	PARKBRAKE VALVE 0500LE A00343	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE163056 Receiving #168752 Date :2016-02-25		923983
217	02/25/2016	578019	Air System Air_Leak Front	Replaced the Brake foot valve and tested.		923983
217	02/25/2016	578019	VALVE FOOT BRAKE M/BENZ 0500LE	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE163066 Receiving #168751 Date :2016-02-25		923983
217	02/25/2016	578019	Air System Air_Leak Front			923983
217	02/22/2016	577432	Consumables			923275
217	02/22/2016	577432	Consumables			923275
217	02/22/2016	577432	Campaign 20/15 Audit & Update of Safety Decals.Requires a			922912
217	02/18/2016	576055	A/C Heating O- clean return filter	clean a/c return filter		921546
217	02/18/2016	576055	Consumables			922253
217	02/18/2016	576055	Consumables			922253
217	02/18/2016	576055	anti slip strip missing	fit new anti slip to back		921546
217	02/16/2016	576078				921024
217	02/16/2016	576099	Elec and Light / step lamps / rocker cover			921024
217	02/15/2016	576078		PRE ANNUAL SAFETY INSPECTION CHECK Checked and listed all defects.		921024
217	02/15/2016	572453	Elec and Light / step lamps / rocker cover			921024
217	02/15/2016	576099	Elec and Light / step lamps / rocker cover	Replaced.		921024
217	02/15/2016	576055	anti slip strip missing	replace step edging		921024
217	02/05/2016	572453	DOWN LIGHT LED	Creditor #PT-VOLGRE VOLGREN AUSTRALIA P/O #PE161612 Receiving #167575 Date :2016-02-10		919763
217	02/03/2016	572453	Elec and Light / step lamps / rocker cover			917651
217	02/03/2016	573614	carry out fire insp	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #PE161449 Receiving #168107 Date :2016-02-18		921899
217	02/02/2016	573614		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		919404
217	02/01/2016	572453	ROCKER COVER 0500LE			919052
217	01/27/2016	572269		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		917651
217	01/27/2016	572269		VEHICLE SAFETY INSPECTION		917651
217	01/27/2016	572345	REAR REFLECTOR 85050			917651
217	01/27/2016	572345	BLADE WIPER LMTV			917651
217	01/27/2016	572345	Mechanic entered - Wipers and Washers Other	Replace n/s wiper blade assy. Secure loose indicator stalk. Trace and repair short to n/s revers light. N/S/R reflector missing		917651
217	01/19/2016	570743	REGULATOR VOLTAGE 0405NH 94V00	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE160726 Receiving #167097 Date :2016-02-02		916419
217	01/18/2016	570730	DIRECT PURCHASE - GLASS	Creditor #PT-GLA001 GLASS ASSIST PTY LTD P/O #PE160709 Receiving #166681 Date :2016-01-22 replace rear door glass		915443
217	01/18/2016	570731	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	Rear door glass replaced		915443
217	01/18/2016	570730	Vandalism rear door glass	Glass replaced		915443
217	01/18/2016	570743	A/C BELT 0500 BENZ			915443
217	01/18/2016	570743	Replace lower seized idler pulley and Main engine belt	replaced main belt and lower pulley which had seized tested okay.		915443
217	01/16/2016	570541	Consumables			915443
217	01/16/2016	570541	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS			915324
217	01/05/2016	568112	Mechanic entered - Air System Air_Leak Front	replaced front modulator valve		912884
217	01/04/2016	568112	valve front brake modulator	Creditor #PT-MUL001 MULTISPARES LTD P/O #PE160168 Receiving #167127 Date :2016-02-02		919404
217	12/23/2015	566685	Consumables			909672
217	12/23/2015	566685	Campaign 23_15 A3 Post Change	fit A3 poster as required		909672
217	12/21/2015	565296	AIR CONDITIONING REPAIR	Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE159629 Receiving #165702 Date :2015-12-23		909309
217	12/21/2015	565999	CIRCUIT PROTECTION VALVE			909309
217	12/21/2015	565999	KIT AIR LINE FITTING VOSS 22MM 5020114			909309
217	12/21/2015	565999	Air System Air_Leak Rear			909309
217	12/21/2015	565999	Air System Air_Leak Rear			909309
217	12/21/2015	565949	Consumables			909415
217	12/21/2015	565949	Consumables			909415
217	12/21/2015	565949	Consumables			909309
217	12/21/2015	565949	Consumables			909309
217	12/16/2015	565296	Drv entered - AC Heating Not Cooling	CARRY OUT A SERVICE AS PER CHECK LIST		907920
217	12/14/2015	564651		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY		907322
217	12/14/2015	564651		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY		907322
217	12/14/2015	564651		CLEAN A/C FILTERS		907322
217	12/14/2015	564651		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		907322
217	12/14/2015	564651		VEHICLE SAFETY INSPECTION Completed.		906096
217	12/08/2015	563845	Consumables			905832
217	12/08/2015	563845	Drv entered - Body Drivers Seat Belt	fit new seat belt		902154
217	11/26/2015	561227	Consumables			901458
217	11/26/2015	561227	Remove Old Poster and Fit new All Night Public Transport Po			904171
217	11/19/2015	559831	AIR CONDITIONING REPAIR	Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE158339 Receiving #164615 Date :2015-12-03		899619
217	11/19/2015	559831	Drv entered - Cool & AC Sys			899619
217	11/19/2015	559831	Ops Entered - Fault - A/C Heating Not Cooling - Route: 773	done by coachair		899619
217	11/18/2015	556315	windows and roof lining	Creditor #PT-GLA010 GLASSPROTECH MELBOURNE P/O #PE158107 Receiving #164568 Date :2015-12-03		898737
217	11/13/2015	558786	Consumables			898463
217	11/13/2015	558786	Consumables			898463
217	11/13/2015	558786	Complete task as instructed in Fleet Campaign 09/15			898463
217	11/13/2015	558707	GLOBE H1 24V 70W			898463
217	11/13/2015	558707	Mechanic entered - Elec and Light Exterior Lights			898463
217	11/06/2015	556949	Consumables			897756
217	11/06/2015	556949	back	Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE157720 Receiving #163685 Date :2015-11-13		897756
217	11/06/2015	556949	base	Creditor #PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #PE157720 Receiving #163685 Date :2015-11-13		897756
217	11/05/2015	556949	Body Passenger Seat Torn	REPLACE TORN SEATS		897756
217	11/04/2015	556803	Consumables			897756
217	11/04/2015	556803	install pass seats	fitted		897756
217	11/02/2015	556315	replaced riched side windows	Creditor #PT-GLA001 GLASS ASSIST PTY LTD P/O #PE157678 Receiving #163665 Date :2015-11-13		897756
217	11/02/2015	556651	Consumables			898463
217	11/02/2015	556651	replace windscreen	Creditor #PT-GLA001 GLASS ASSIST PTY LTD P/O #PE157679 Receiving #163667 Date :2015-11-13		898463

217	11/02/2015	556651	windscreen cracked	replace windscreen	897756
217	10/30/2015	556315	Vandalism Vandalism/ Graffiti Interior and icked windows	remove seats	897756
217	10/30/2015	556315	Vandalism Vandalism/ Graffiti Interior and icked windows	clean and painted side windows replaced	897756
217	10/27/2015	555652		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	896792
217	10/27/2015	555652		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	896792
217	10/27/2015	555652		CLEAN A/C FILTERS	896792
217	10/27/2015	555652		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	896792
217	10/27/2015	555652		VEHICLE SAFETY INSPECTION Completed safety inspection.	896792
217	10/27/2015	555653	Ops Entered - Fault - Passenger Doors - Route: - Off servi	Checked passegner doors and sensitive edge all working good.	896792
217	10/27/2015	555651	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		896792
217	10/27/2015	555651	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		896792
217	10/27/2015	555651		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed service as per check list.	896792
217	10/21/2015	554405		Retensioned.	894827
217	10/21/2015	554501	1MT MULTI FIT WIPER REFILL		894827
217	10/21/2015	554501	Ops Entered - Fault - Wipers and Washers Washers Not Working	replaced wiper blades	894827
217	10/19/2015	554104	Mechanic entered - Wheels and Tyres Worn	replaced o/s/r inner tyre fitted run out tyre half worn	894677
217	10/19/2015	554104	Consumables		894827
217	10/19/2015	554115	DISC PAD SET SCANIA MB0500		894677
217	10/19/2015	554115	Mechanic entered - Brakes Warning Light On front brake pads	replaced front brake pads	894677
217	10/19/2015	554093		CARRY OUT A SERVICE AS PER CHECK LIST	894677
217	10/19/2015	554093	Consumables		894827
217	10/19/2015	554093	Consumables		894827
217	10/19/2015	554093	Consumables		894827
217	10/09/2015	552514	Ops Entered - Fault - Air System Air_Leak Rear - Route: 83	Repair broken air fitting to n/s/r air tank	891904
217	10/07/2015	551526	CYCLONE CONDENSER VALVE KIT		891465
217	10/07/2015	551526	HALDEX CONDENSER KIT TOP(CYCLONE)		891465
217	10/07/2015	551526	Mechanic entered - Air System Air_Leak Rear from cyclone sep		891465
217	10/06/2015	551206	Air System Air_Leak Rear - Air is leaking from around the	Checked for air leaks air leaks slightly after tanks full at air cyclone separator exhaust. Replaced air cyclone separator.	891168
217	09/30/2015	550294	Consumables		890570
217	09/30/2015	550218	Consumables		890570
217	09/30/2015	550294	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fit decals as required	890188
217	09/30/2015	550218	Replace A3 poster with Victorian Seniors Festival Poster	Replaced A3 Poster as required	890188
217	09/28/2015	549451	Consumables		889891
217	09/28/2015	549451	Mechanic entered - Body Drivers Seat Controls	repair air leak to seat	889457
217	09/28/2015	549463	Ops Entered - Fault - Air System Air_Leak Interior - Route	re route air lines on drivers seat	889457
217	09/24/2015	548904	RH Side Window	Creditor #PT-GLA001 GLASS ASSIST PTY LTD P/O #PE156513 Receiving #161845 Date :2015-10-05	890570
217	09/24/2015	548904	Vandalism / L/H side window	completed by glassassist	889174
217	09/24/2015	548905	Consumables		889174
217	09/24/2015	548905	Body/ R/H side windscreen	done by glassassist	889174
217	09/19/2015	547237	FILTER REGULATOR DOOR RAM (AW2)	Creditor #PT-EA5001 EASTCOAST TRUCK & BUS SERVICE P/O #PE155753 Receiving #161318 Date :2015-09-19 bus 217	887936
217	09/16/2015	547273	Consumables		887275
217	09/16/2015	547273	Ops Entered - Fault - Body Water Leaks Roof - Route: 833 -	could not find	887033
217	09/16/2015	547237	Ops Entered - Fault - Air System Air_Leak Interior - Route:	REPAIRED AIR LEAK	887033
217	09/14/2015	546765		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	886536
217	09/14/2015	546765		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	886536
217	09/14/2015	546765		CLEAN A/C FILTERS	886536
217	09/14/2015	546765		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	886536
217	09/14/2015	546765		VEHICLE SAFETY INSPECTION completed.	886536
217	09/14/2015	546852	TYRE NEW 11R22.5N		886536
217	09/14/2015	546852	GLOBE WEDGE 24V/SW		886536
217	09/14/2015	546852	Mechanic entered - Wheels and Tyres Worn	Replaced pos 1 tyre and adjusted alignment.Torqued both fr Wheelnuts to 600 NM.	886536
217	09/14/2015	546762	Consumables		886716
217	09/14/2015	546762	Mechanic entered - Body Other	secure rear b/bar and body panel	886536
217	09/12/2015	546670		Tension wheels position 3&4 to 600NM.	885666
217	09/11/2015	546447	TYRE RECAP 11R22.5R		885666
217	09/11/2015	546447	Mechanic entered - Wheels and Tyres Worn Pos 3&4 worn.	Replaced Pos 3 an 4 tyres and torqued to 600 NM.	885666
217	09/11/2015	546416	Consumables		886388
217	09/11/2015	546416	Ops Entered - Fault - Body Windows Front - Route: 782 - Bit	fix sticky window catches and lubricate	885666
217	09/11/2015	546416	Ops Entered - Fault - Body Windows Front - Route: 833 - Bal	fix sticky catches	885666
217	09/11/2015	546416	Ops Entered - Fault - Body Drivers Seat Controls - Route: 7	re route squashed air line in seat	885666
217	08/28/2015	541957	Consumables		882168
217	08/28/2015	541957	Drv entered - Body Drivers Seat Controls	fit new drivers seat	881713
217	08/21/2015	541957	SEAT ASSY ISRI 6008 AIR LUMBA	Creditor #PT-EA5001 EASTCOAST TRUCK & BUS SERVICE P/O #PE154773 Receiving #160297 Date :2015-08-21 MM 217	880491
217	08/20/2015	542569	Consumables		880182
217	08/20/2015	542569	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	completed as per campaign details	879849
217	08/19/2015	541910	Drv entered - Suspension Leaning	Replace n/s/r level sensor adjust and road test	879542
217	08/19/2015	541957	Drv entered - Body Drivers Seat Controls	bus needs new seat	879542
217	08/19/2015	541910	Ops Entered - Fault - Air System Air_Leak Front - Driver be		879542
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295		CARRY OUT B SERVICE AS PER CHECK LIST	879166
217	08/17/2015	541295	OIL FILTER 1725+0500LE		879166
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295	Consumables		879259
217	08/17/2015	541295		CARRY OUT A SERVICE AS PER CHECK LIST	879166
217	08/14/2015	537581	BOSCH REGULATOR 0500LE ALT	Creditor #PT-EA5001 EASTCOAST TRUCK & BUS SERVICE P/O #PE154551 Receiving #159992 Date :2015-08-14 94V0003	878736
217	08/05/2015	539317		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	876185
217	08/05/2015	539317		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	876185
217	08/05/2015	539317		CLEAN A/C FILTERS	876185
217	08/05/2015	539317		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	876185
217	08/05/2015	539317		VEHICLE SAFETY INSPECTION safety completed	876185
217	07/29/2015	538185	Complete Campaign 6/15 A3 Marketing Poster Change	Completed campaign as required	874596
217	07/27/2015	537581	Elec and Light/hot starting	Travel to pearcedale and start bus follow back to yard jump start in klauer street Seaford. Remove alternator brush pack found U/S. Fit new brush pack and test with headlights on battery voltage ok and transmission not dropping out.	874102
217	07/22/2015	536902	Ops Entered - Fault - CCTV System Noisy - Route: 833 - Fore	Test with CCTV checking tool all 4 cameras functioning time and date correct. unable to replicate fault.	873923
217	07/20/2015	536371	GLOBE 24V SW BAYONETT		872568
217	07/20/2015	536371	Mechanic entered - Elec and Light Exterior Lights OSF top pa	remove drivers sun blind remove light assembly from header board replace globe test refit light assembly and sun-blind.	872568
217	07/15/2015	535770	Ops Entered - Fault - A/C Heating Not Heating - Route: 781	ops entered incorrectly	871037
217	07/13/2015	535362	Ops Entered - Fault - Body Water Leaks Roof - Route: 785 -	sealed aeral hole	870458
217	07/13/2015	535337	Ops Entered - Fault - Body Water Leaks Roof - Route: 771 -	checked and no fault found	869457
217	07/09/2015	534809	Drv entered - Cool & AC Sys	Checked bus for heater demister operation road tested vehicle checked heater air temp at vents found at 40 degrees could not fault heater demister.	869457
217	07/09/2015	534844	Ops Entered - Fault - Heat & Demist - Route: 785 - Mt Eliza	seat back torn	869457
217	07/09/2015	534942	Ops Entered - Fault - Body Drivers Seat Cover - Route: 784		869457
217	07/07/2015	534803	AIR CONDITIONING REPAIR	Creditor #PT-COA003 COACHAIR PTY LTD P/O #PE153572 Receiving #159281 Date :2015-07-30	875059
217	06/29/2015	533151	Drv entered - Steering Steering Wheel Faulty	lubricate steering adjuster mechanism to stop noise and improve movment.	867271
217	06/24/2015	532447		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	866203
217	06/24/2015	532447		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	866203
217	06/24/2015	532447		CLEAN A/C FILTERS	866203

217	06/24/2015	532447	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	866203
217	06/24/2015	532447	VEHICLE SAFETY INSPECTION Completed.	866203
217	06/24/2015	532458 Consumables	complete campaign	866242
217	06/24/2015	532458 Audit Route buses for correct Decals and positions. Replace	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE152559 Receiving #:157732 Date :2015-06-29	866203
217	06/23/2015	530988 carry out annual service	B Service	867271
217	06/15/2015	530988	Replace filter drier	864111
217	06/15/2015	530988	Replace compressor oil	864111
217	06/15/2015	530988	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	864111
217	06/13/2015	530988	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	864111
217	06/15/2015	530988	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	864111
217	06/15/2015	530988	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	864111
217	06/15/2015	530988	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	864111
217	06/15/2015	530988	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	864111
217	06/15/2015	530988	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	864111
217	06/13/2015	530988	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	864111
217	06/15/2015	530988	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	864111
217	06/15/2015	530988	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	864111
217	06/15/2015	530988	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	864111
217	06/12/2015	530783 Mechanic entered - Vandalism Vandalism/ Graffiti Exterior	all removed	863245
217	06/11/2015	530632 Consumables	not found	863245
217	06/11/2015	530632 Ops Entered - Fault - Body Water Leaks Roof - Route: 781 -		862988
217	06/11/2015	530667 Consumables		863245
217	06/11/2015	530667 Consumables		863245
217	06/11/2015	530667 Consumables		863245
217	06/11/2015	530667	A Service a service completed	862988
217	06/11/2015	530667	Clean A/C filter	862988
217	06/11/2015	530667	Grease AC Compressor Clutch Bearing	862988
217	06/11/2015	530667	Tension Wheel Nuts To OEM Specification	862988
217	06/03/2015	529247 Drv entered - AC Heating Not Heating	Checked heater works OK.	860697
217	05/24/2015	527622 Consumables		858604
217	05/24/2015	527622 Ops Entered - Fault - Body Water Leaks Roof - Route: 771 -	no fault found	858401
217	05/15/2015	525880 replace hard drive	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE151379 Receiving #:156108 Date :2015-05-27	859159
217	05/13/2015	525880 Mechanic entered - CCTV Other CCTV Recorder u/s	replaced hard drive	855645
217	05/13/2015	525880 CCTV not working		855645
217	05/11/2015	525476	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	855397
217	05/11/2015	525476	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	855397
217	05/11/2015	525476	CLEAN A/C FILTERS	855397
217	05/11/2015	525476	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	855397
217	05/11/2015	525476	VEHICLE SAFETY INSPECTION	855397
217	05/11/2015	525535	Check and try to repair CCTV recorder. Requires repair by Lonsdale Cameras oh but recorder fault	855397
217	05/11/2015	525535 GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)		855397
217	05/11/2015	525535 GLOBE 24V 5W BAYONETT		855397
217	05/11/2015	525535 Mechanic entered - Elec and Light Exterior Lights n/s/f top	Replace ind and park globes Replace 1x switch globe	855397
217	05/11/2015	525535 GLOBE 24V 18W		855397
217	05/11/2015	525535 Mechanic entered - Air System Air_Leak Front	Strip and try to repair leaking door regulator. New reg required	855397
217	05/08/2015	525485 GLOBE WEDGE 24V/SW		854781
217	05/08/2015	525485 LH parker out		854781
217	05/08/2015	525484 GLOBE WEDGE 24V/SW		854781
217	05/08/2015	525484 RH parker out		854781
217	05/01/2015	524368 GLOBE WEDGE 24V/SW		853246
217	05/01/2015	524368 RH parker out		853246
217	04/28/2015	523431 FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)	ZF Transmission Filter	852337
217	04/28/2015	523431 ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR	ZF Ecofluid A Plus Synthetic Transmission Oil	852337
217	04/28/2015	523431	REPLACE TRANSMISSION OIL & FILTER replaced trans oil filter	852337
217	04/20/2015	522134 Ops Entered - Fault - Heat & Demist - Route: - Arrive Seaf	Road test to temp. Check all fuses and heater taps ok. Systeme seems to be working ok	850813
217	04/20/2015	522133 Mechanic entered - Air System Air_Leak Rear	Trace and repair various air leaks by air dryer. Trace and replace faulty timer relay for cyclopac	850813
217	04/20/2015	522133 AIR LINE FITTING KIT OSOOLE AIR DRYER SMALL		850813
217	04/20/2015	522133 KIT AIR LINE FITTING VOSS 22MM 5020114		850813
217	04/20/2015	521986 HALDEX CONDENSER KIT TOP(CYCLONE)		850813
217	04/20/2015	521986 CYCLONE CONDENSER VALVE KIT		850813
217	04/20/2015	521986	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes Completed	850813
217	04/20/2015	521986	Re-kit Air Cyclone Separator Completed	849775
217	04/16/2015	521726 GLOBE WEDGE 24V/SW		849775
217	04/16/2015	521726 LH parker out		848230
217	04/10/2015	520700 Consumables		848230
217	04/10/2015	520700 Consumables		848230
217	04/10/2015	520700 Consumables		848230
217	04/10/2015	520700	A Service	848230
217	04/10/2015	520700	Clean A/C filter	848230
217	04/10/2015	520700	Grease AC Compressor Clutch Bearing	848230
217	04/10/2015	520700	Tension Wheel Nuts To OEM Specification	848230
217	04/09/2015	520447 Update destination Files and Check display	Campaign completed.	847754
217	04/04/2015	519645 Ops Entered - Fault - Passenger Doors - Route: 782 - King	checked door operation	846333
217	04/01/2015	515726 DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASF ROAD SAFETY INSPECTIONS P/O #:PE149285 Receiving #:153803 Date :2015-04-15	848992
217	04/01/2015	519196 RH rear outer tyre under 3mm	Being replacedRetorqued to 600NM and Released.	845922
217	03/30/2015	518756 Replace See Something Say Something Poster	Campaign completed.	845576
217	03/30/2015	518559 Consumables		845576
217	03/30/2015	518743 Consumables		845576
217	03/30/2015	518743 Ops Entered - Fault - Body & Acc Water Leak - Route: - Arr	secure air con ducts	845576
217	03/30/2015	518559 Drv entered - Body & Acc Water Leak	no fault found	845576
217	03/28/2015	518470 TYRE RECAP 11R22.5R		845026
217	03/28/2015	518470 RH rear outer tyre under 3mm	Replaced pos 6 tyre and torqued wheel nuts	845026
217	03/28/2015	518470 Drv entered - Suspension Hard	Checked air bags shockers and torque rod bushes found ok. Road tested bus operating normal.	845026
217	03/28/2015	518470 Drv entered - Steering Shimmy	Checked steering ball joint on drag link and tir rod checked for movement on king pins and wheel bearings front found ok. Road tested could not fault steering.	845026
217	03/28/2015	518470 Drv entered - Other		845026
217	03/28/2015	518470 Consumables		845287
217	03/28/2015	518470 Drv entered - Body & Acc Interior [See printed defect for mo		845026
217	03/28/2015	518470 Drv entered - Body & Acc Water Leak		845026
217	03/25/2015	517970 Consumables		844904
217	03/25/2015	517970 Loose N/S mirror arm	Tightened arm	844641
217	03/24/2015	517573 repair coolant leak	replaced heater hoses	844421
217	03/24/2015	518809 INVOICE ENTERED WITH GST IN ER	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE149236REV Receiving #:153298 Date :2015-04-02	845922
217	03/24/2015	518809 INVOICE ENTERED WITH GST IN ER	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE150058 Receiving #:153299 Date :2015-04-02	845922
217	03/24/2015	518809 repair accident # 40591	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE149236 Receiving #:153073 Date :2015-03-30	845576
217	03/24/2015	518809 Ops Entered - Accident - Bus Hit Stationary Object - Route		838357
217	03/23/2015	517487 Wiper Blade Volgren Track Bus		844421
217	03/23/2015	517487	Clean A/C filter.	844421

217	03/23/2015	517487	Tension Wheel Nuts	844421
217	03/23/2015	517487	Perform & Complete TSV Bus Safety Inspection	844421
217	03/18/2015	516447 Consumables		843299
217	03/18/2015	516447 Dry entered - Body & Acc Mirrors Exterior		842522
217	03/13/2015	515962 Consumables		842017
217	03/13/2015	515962 wiper blade broken	repl,aced wiper blade	841699
217	03/12/2015	515726 annaul inspection	completed	841524
217	03/11/2015	515515 AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		841524
217	03/11/2015	515515 LED FRONT POSITION MARKER LIGHT		841524
217	03/11/2015	515515 EMERGENCY EXIT DECAL 600MM X 80MM		841524
217	03/11/2015	515515 Finalize RSI		841524
217	03/11/2015	515515 EMERGENCY EXIT (HAMMER)		841524
217	03/11/2015	515515 MINATURE GLOBE 24V - 4 W		841524
217	03/11/2015	515515 GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)		841524
217	03/11/2015	515515 Finalize RSI	Carry out RSI final insp defects and grease. Replace switch and dash globes.Rear exit sticker and light assy. Rear door button cover. Replace 8x air fitting kits to air dryer and suspension module	841524
217	03/11/2015	515275 Consumables		841524
217	03/11/2015	515275 EMERGENCY EXIT DECAL 600MM X 80MM		841524
217	03/10/2015	515173 HEADER TANK 0405NH+0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:151932 Date :2015-03-10	841524
217	03/10/2015	515275 wiper blade broken		841210
217	03/08/2015	515173 HEADER TANK 0405NH+0500LE		840698
217	03/08/2015	515173 Header tank pipe broken	Replaced header tank and road test	840698
217	03/06/2015	514794 BUTTON CLIPPARD DOOR VALVE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:151909 Date :2015-03-06	840698
217	03/06/2015	514794 VALVE CLIPPARD DOOR OPEN/CLOSE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:151909 Date :2015-03-06	840359
217	03/05/2015	514718 steam clean for RSI	done	840359
217	03/05/2015	514794 DOOR VALVES LEAKING	REPLACED VALVES	840359
217	03/02/2015	513730 header tank sight glass leaking		839450
217	03/01/2015	502752 TAPPET COVER 50A8515	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE146719 Receiving #:151970 Date :2015-03-10	841210
217	02/28/2015	513730 header tank sight glass leaking	Replaced coolant sight glass on header tank road test. ok	839450
217	02/27/2015	513665	Replace angle drive oil	839450
217	02/27/2015	513665	Test coolant level - top up if required to equate to 37C frost protection	839450
217	02/27/2015	513665	Replace power steering filter and check level (Replace oil if required)	839450
217	02/27/2015	513665 FUEL FILTER MERC 0500LE		839450
217	02/27/2015	513665 FUEL FILTER 0500LE		839450
217	02/27/2015	513665 FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		839450
217	02/27/2015	513665 FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468		839450
217	02/27/2015	513666	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	839450
217	02/27/2015	513666	Inspect radiator and charge air cooler for dirt - clean	839450
217	02/27/2015	513666	Check oil level in transmission - top up if required	839450
217	02/27/2015	513666	Replace power steering filter and check level (Replace oil if required)	839450
217	02/27/2015	513666	Check and clean cartridge in dry type air cleaner	839450
217	02/27/2015	513666	Replace pre and main fuel filters	839450
217	02/27/2015	513666	Replace air dryer canister clean silence and drain reservoir	839450
217	02/27/2015	513666	Replace angle drive oil	839450
217	02/27/2015	513666 FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468		839450
217	02/27/2015	513666 FUEL FILTER MERC 0500LE		839450
217	02/27/2015	513666 FUEL FILTER 0500LE		839450
217	02/27/2015	513666 FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		839450
217	02/27/2015	513666	Test coolant level - top up if required to equate to 37C frost protection	839450
217	02/27/2015	513665		839450
217	02/27/2015	513665	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	839450
217	02/27/2015	513665	Inspect radiator and charge air cooler for dirt - clean	839450
217	02/27/2015	513665	Check oil level in transmission - top up if required	839450
217	02/27/2015	513665	Check and clean cartridge in dry type air cleaner	839450
217	02/27/2015	513665	Replace pre and main fuel filters	839450
217	02/27/2015	513665	Replace air dryer canister clean silence and drain reservoir	839450
217	02/27/2015	513665	PRE ANNUAL BUS SAFETY INSPECTION CHECK	839450
217	02/27/2015	513666	Carried out R.S.I service	839450
217	02/27/2015	513666	PRE ANNUAL BUS SAFETY INSPECTION CHECK	839450
217	02/27/2015	513730 COOLANT SIGHT GLASS ASSY 0405N	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:151504 Date :2015-02-27	839450
217	02/26/2015	513419 Consumables		839450
217	02/26/2015	513419 Ops Entered - Fault - Body & Acc Mirrors Exterior - Route:	Checked all external mirrors could not fault them	839181
217	02/23/2015	512745 Mechanic entered - Throttle Other	Rewired and replaced the throttle position switch and tested.	838357
217	02/23/2015	512675 Consumables		838653
217	02/23/2015	512675 Mechanic entered - Body & Acc Exterior	cut hole in offside panel for fuel cap	838357
217	02/23/2015	512680 Service		838357
217	02/12/2015	510806 BRAKE BOOSTER REAR N/S MB0500L	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:150764 Date :2015-02-12	838460
217	02/12/2015	510806 REAR BRAKE CALIPER LH 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE147941-1 Receiving #:150764 Date :2015-02-12	838460
217	02/12/2015	510806 Ops Entered - Fault - Elec & Light W'ming Light - Route: 7		838357
217	02/11/2015	510806 Ops Entered - Fault - Elec & Light W'ming Light - Route:	remove hub disc and caliber fit hub seals hub disc and caliper with new pads fitted wheels brakes adjusted and test driven	838357
217	02/03/2015	509582	C Service	836548
217	02/03/2015	509582	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	836548
217	02/03/2015	509582	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	836548
217	02/03/2015	509582	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	836548
217	02/03/2015	509582	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	836548
217	02/03/2015	509582	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	836548
217	02/03/2015	509582	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	836548
217	02/03/2015	509582	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	836548
217	02/03/2015	509582	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	836548
217	02/03/2015	509582	COMPRESSOR DRIVE BELTS: inspect belt wear; Retention belts;	836548
217	02/03/2015	509582	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	836548
217	02/03/2015	509582	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	836548
217	02/01/2015	502740 PARKBRAKE VALVE 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE146540 Receiving #:149047 Date :2014-12-31	828703
217	02/01/2015	501738 Booster RHR 0500 634.220	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE146063 Receiving #:148475 Date :2014-12-12 MM	824975
217	01/29/2015	509114 GLOBE 24V 18W		833515
217	01/29/2015	509114 LH indicator globe out		833515
217	01/23/2015	508199 Dry entered - Air Cond Air Conditioner	tested and AC works OK.	833958
217	01/23/2015	508135 Dry entered - Passenger Doors Not Operating	checked doors for operation could not fault it. lubricated air system.	833958
217	01/23/2015	508255 CCTV Not recording	Tested CCTV Date and time ok. Recording OK	833958
217	01/21/2015	507924	wheel nuts retensioned	833485
217	01/20/2015	507698	Clean A/C filter.	833485
217	01/20/2015	507698	Tension Wheel Nuts	833485
217	01/20/2015	507697 Consumables	Perform & Complete TSV Bus Safety Inspection	833485
217	01/20/2015	507719 TYRE RECAP 11R22.5R		833485
217	01/20/2015	507719 Tyres 3 & 4 worn	Replaced tyres and tension to 600Nmm	833485
217	01/20/2015	507697 Consumables		833485
217	01/20/2015	507697 Consumables		833485
217	01/20/2015	507697 Consumables		833485
217	01/20/2015	507697 Consumables		833485
217	01/20/2015	507697 AIR FILTER MERC 0500LE E491L		833485

2017/01/20/2015	507697	Tension Wheel Nuts to Spec	833485
2017/01/20/2015	507697	A Service & Bus Safety Inspection	833485
2017/01/20/2015	507697	D-Service & Bus Safety Inspection	833485
2017/01/20/2015	507697	Grease AC Compressor Clutch Bearing	833485
2017/01/20/2015	507697 OIL FILTER 1725+0500LE		833485
2017/01/20/2015	507697 OIL ENGINE DELO 400LE 15W40 (LU18)		833485
2017/01/20/2015	507697 Consumables		833485
2017/01/20/2015	507697 Consumables		833485
2017/01/20/2015	507697 Consumables		833485
2017/01/20/2015	507697	A Service	833485
2017/01/20/2015	507697	Clean A/C filter	833485
2017/01/19/2015	507326	re torqued both 5 and 6 tyres to 600nm	833089
2017/01/19/2015	507478 Consumables		833326
2017/01/19/2015	507478 COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	Details Taken	833089
2017/01/16/2015	507132 Consumables		832584
2017/01/16/2015	507132 TYRE RECAP 11R22.5R		832369
2017/01/16/2015	507132 Mechanic entered - WHls & Tyres Worn Position 5 tyre worn	replaced tyre	832369
2017/01/09/2015	505839	Retorqued Q/S front wheel nuts	830410
2017/01/08/2015	505694 Consumables		830655
2017/01/08/2015	505694 Mechanic entered - Body & Acc Exterior	adjust and lubricate doors	830410
2017/01/07/2015	505576 Consumables		830410
2017/01/07/2015	505576 TYRE NEW 11R22.5N		830411
2017/01/07/2015	505576 Q/S/F TYRE WORN	Replaced tyre Pos 2 and tension to 600Nm	830411
2017/01/07/2015	505569 Door not working	checked and replaced switch	830234
2017/12/30/2014	504080 Consumables		0
2017/12/30/2014	504080 Ops Entered - Fault - Elec & Light Hazard Lights - Route: 7	Check indicator and hazard lights no fault found	828225
2017/12/29/2014	503998 RAD CAP MERC BENZ SIGHT GLASS SIDE		828225
2017/12/29/2014	503998 Drv entered - Eng Cool Coolant Low	replaced cap	828225
2017/12/23/2014	503440 Ops Entered - Fault - Passenger Doors Not Operating - Route	Checked all doors for correct operation no defects found.	826997
2017/12/18/2014	502810 Consumables		0
2017/12/18/2014	502999 Consumables		0
2017/12/18/2014	502999 MIRROR METAGAL L/H (UES1411E)		825917
2017/12/18/2014	502999 Broken N/S Mirror and arm mount	replaced n/s mirror and arm	825917
2017/12/18/2014	502810 Mechanic entered - Body & Acc Interior	secure air con ducts above rear door	825917
2017/12/17/2014	502731 ROCKER COVER GASKET 0500LE	Rocker Cover Gasket	825917
2017/12/17/2014	502731	Adjust Tappets	825917
2017/12/17/2014	502752 TAPPET COVER CRACK	Replace # 6 rocker cover (Needs # 4)	825917
2017/12/17/2014	502782 Consumables		0
2017/12/17/2014	502782 MAKE UP PLATE FOR HAND BRAKE VALVE	Make and fit plate	825917
2017/12/17/2014	502740 hand brake valve faulty	Replaced handbrake valve and assist trevor with plate	825917
2017/12/17/2014	502732 SYNTHETIC GEAR LUBRICANT FM 75W-140 (LU27)		825917
2017/12/17/2014	502732 Service	Replace Differential oil	825917
2017/12/16/2014	502443 A3 Poster Change	Campaign completed.	825682
2017/12/15/2014	502274 Drv entered - Passenger Doors Not Operating	Checked and adjusted doors and lubricated	825555
2017/12/15/2014	502186 Consumables		0
2017/12/15/2014	502186 Mechanic entered - Body & Acc Interior	repair drivers blinds	825555
2017/12/12/2014	501718	Perform & Complete TSV Bus Safety Inspection	824635
2017/12/12/2014	501718	Clean A/C filter.	824635
2017/12/12/2014	501718	Rotate Rear Axle Tyres Left to Right - MT & IBS only	824635
2017/12/12/2014	501718	Rotate Front Axle Tyres Left to Right - MT & IBS only	824635
2017/12/12/2014	501718	Tension Wheel Nuts	824635
2017/12/12/2014	501738 Mechanic entered - Body & Acc Passenger Seat Cushion	repaired passenger seat arseparts x2	824635
2017/12/12/2014	501738 Consumables		0
2017/12/12/2014	501738	Replace n/s/r rear air bag	824635
2017/12/12/2014	501738 R/H rear spring brake leaking	Replace o/s/r spring brake and check for leaks ok.	824635
2017/12/12/2014	501738 R/H rear spring brake leaking		824635
2017/12/12/2014	501738 OMS ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		814805
2017/12/01/2014	492248 CIRCUIT PROTECTION VALVE	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE144712 Receiving #:147041 Date :2014-10-31 5062809G	814805
2017/11/28/2014	497553 TAPERED ROLLER BEARING	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE145567 Receiving #:147967 Date :2014-11-28 MM	821750
2017/11/19/2014	497553 over haul fan drive	Strip clean and replace bearings and seals. Grease and assemble	818793
2017/11/17/2014	497056 Fab Belt drive siezed	Fitted changeover drive	818603
2017/11/17/2014	497025 Consumables		0
2017/11/17/2014	497025 Consumables		0
2017/11/17/2014	497025 Consumables		0
2017/11/17/2014	497025 Consumables		0
2017/11/17/2014	497025	A Service	818603
2017/11/17/2014	497025	Clean A/C filter	818603
2017/11/17/2014	497025	Grease AC Compressor Clutch Bearing	818603
2017/11/17/2014	497025		818603
2017/11/17/2014	497025 AIR FILTER MERC 0500LE E491L	Tension Wheel Nuts to OEM Specification	818603
2017/11/12/2014	495981 Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Ref managers meeting 05/11/14.	817298
2017/11/12/2014	496108 Consumables		0
2017/11/12/2014	496108 Remove Legacy Poster and replace with See Something Say So	Campaign done.	817298
2017/11/07/2014	495272 GLOBE 24V SW BAYONETT	Clean A/C filter.	816026
2017/11/07/2014	495272	Tension Wheel Nuts	816026
2017/11/07/2014	495272	Perform & Complete TSV Bus Safety Inspection	816026
2017/10/28/2014	493559 RH parker out		814023
2017/10/28/2014	493559 GLOBE WEDGE 24V/SW		814023
2017/10/28/2014	493264 Complete AM/FM radio saloon speaker modification	Campaign done.	813761
2017/10/22/2014	492297 GLOBE 24V SW BAYONETT		812216
2017/10/22/2014	492297 n/s/f top marker light out	replaced top n/s park light	812216
2017/10/22/2014	492248 AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		812459
2017/10/22/2014	492248 DRAIN VALVE KIT BOTTOM	Valve Kit	812459
2017/10/22/2014	492248 HALDEX COIL BASE OIL SEPARATOR	Base	812459
2017/10/22/2014	492248 CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	812459
2017/10/22/2014	492248	Re-kit Air Cyclone Separator rekitet air cyclon system and clean ping tank also replaced 6 way valve	812459
2017/10/22/2014	492248	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	812459
2017/10/22/2014	492248 Replace away valve		812459
2017/10/17/2014	491646 Drv entered - Gearbox Harsh Thumping [See printed defect f	Checked gear selector cannon plug and oil level on trans found ok. Road tested could not fault it.	811229
2017/10/17/2014	498639 DIAPHRAGM TYRE 20 D SHAPE	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #PE144080 Receiving #:146491 Date :2014-10-17	811229
2017/10/08/2014	493532 GLOBE WEDGE 24V/SW		809165
2017/10/08/2014	493532 RH & LH parker out		809165
2017/10/02/2014	488855	Retensioned to 600 NM.	807308
2017/10/01/2014	488568	Perform & Complete TSV Bus Safety Inspection	806930
2017/10/01/2014	488568	Tension Wheel Nuts	806930
2017/10/01/2014	488568	Rotate Front Axle Tyres Left to Right - MT & IBS only	806930
2017/10/01/2014	488568	Rotate Rear Axle Tyres Left to Right - MT & IBS only	806930
2017/10/01/2014	488568	Clean A/C filter.	806930

[illegible]

217	06/17/2014	469111	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	782939
217	06/17/2014	469111	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	782939
217	06/17/2014	469111	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	782939
217	06/17/2014	469111	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	782939
217	06/17/2014	469111	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	782939
217	06/17/2014	469111	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	782939
217	06/17/2014	469111	COMPRESSOR DRIVE BELTS: inspect belt wear; Retention belts;	782939
217	06/17/2014	469111	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	782939
217	06/17/2014	469111	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	782939
217	06/17/2014	469111	Clean A/C filter.	782939
217	06/04/2014	467118	Rotate Rear Axle Tyres Left to Right - MT & IBS only	779706
217	06/04/2014	467118	Rotate Front Axle Tyres Left to Right - MT & IBS only	779706
217	06/04/2014	467118	Tension Wheel Nuts	779706
217	06/04/2014	467118	Perform & Complete TSV Bus Safety Inspection	779706
217	05/27/2014	465304	Checkeddoors and sensitive edge operation all works OK.	777905
217	05/23/2014	464840	completed by E/C	777385
217	05/21/2014	464416	repair drivers seat and fit new cushion	776870
217	05/21/2014	464347	no fault found by Ross S	776870
217	05/19/2014	463906	COMPLETED	776696
217	05/19/2014	463906	repairs carried out by E/C	776696
217	05/19/2014	463904	repaired by e/c	776696
217	05/19/2014	463878	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	776696
217	05/09/2014	461014	BATTERY 12V 190 AMP 1000CCA (+ on right side)	775096
217	05/09/2014	461014	NUT BRASS BATTERY TERMINAL POSITIVE	775096
217	05/09/2014	461014	NUT BATTERY TERMINAL NEG (BRASS)	775096
217	05/09/2014	461014	not starting	775096
217	05/06/2014	461014	not starting	775096
217	05/05/2014	460929	NUT BRASS BATTERY TERMINAL POSITIVE	774340
217	05/05/2014	460929	check batts charging rate etc not starting in mornings	774340
217	05/05/2014	460929	install hard drivecamera and test cctv	774340
217	05/05/2014	460929	check batts charging rate etc not starting in mornings	774340
217	05/02/2014	460624	SMALL PARTS	776183
217	05/02/2014	460624	supply camera	776183
217	05/02/2014	460624	REPAIR HARD DRIVE NOISY	776183
217	05/02/2014	460624	Mechanic entered - Security CCTV System Faulty Front CCTV C	773965
217	04/28/2014	459576	Mechanic entered - Elec & Light Battery Flat	772870
217	04/22/2014	458931	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	771986
217	04/22/2014	458858	Service	771986
217	04/22/2014	458858	HALDEX COIL KIT 0500LE	771986
217	04/22/2014	458858	DRAIN VALVE KIT BOTTOM	771986
217	04/22/2014	458858	Service	771986
217	04/16/2014	458154	Drv entered - Gearbox Harsh Thumping	770796
217	04/16/2014	458155	Drv entered - Engine Surging	770796
217	04/15/2014	457959	Mechanic entered - Elec & Light Battery Flat Parked too clo	770494
217	04/14/2014	457902		770382
217	04/14/2014	457902	Rotate Rear Axle Tyres Left to Right - MT & IBS only	770382
217	04/14/2014	457902	Rotate Front Axle Tyres Left to Right - MT & IBS only	770382
217	04/14/2014	457902	Tension Wheel Nuts	770382
217	04/14/2014	457902	Perform & Complete TSV Bus Safety Inspection	770382
217	04/14/2014	457902	Clean A/C filter.	770382
217	04/14/2014	457915	Adjust and check front door speeds. OK	770382
217	04/11/2014	457514	Drv entered - Gearbox No Retarder	769889
217	04/11/2014	457514	Drv entered - Gearbox Harsh Thumping [See printed defect f	769889
217	04/11/2014	457514	Drv entered - Gearbox No Kickdown	769889
217	04/11/2014	457514	Drv entered - Gearbox Harsh Thumping	769889
217	04/11/2014	457514	Drv entered - Gearbox Harsh Thumping [See printed defect f	769889
217	04/11/2014	457514	Drv entered - Gearbox No Kickdown [See printed defect for m	769889
217	04/11/2014	439597	CONSUMABLE DELIVERY CHARGE	769889
217	04/11/2014	439597	DRIVERS SEAT SUSPENSION KIT 60	769889
217	04/11/2014	457514	Ops Entered - Fault - Body & Acc Water Leak - Route: 833 -	769889
217	04/11/2014	457514	Drv entered - Body & Acc Water Leak	769889
217	04/11/2014	457514	Ops Entered - Fault - Body & Acc Water Leak - Route: 771 -	769889
217	04/11/2014	457602	Mechanic entered - Body & Acc Exterior	769889
217	04/10/2014	457379	rear door cover	769650
217	04/09/2014	449778	rear door cover	769343
217	04/01/2014	451889	RADIATOR 0500LE	768851
217	04/01/2014	449778	860/1060mm REAR DOOR MECH	769087
217	04/01/2014	452008	SOLENOID VALVE ZFAUTO	768851
217	03/23/2014	453639	Drv entered - Gearbox Harsh Thumping [See printed defect f	764765
217	03/23/2014	453641	Drv entered - Engine Lacking Power [See printed defect for	764765
217	03/19/2014	452698	Mechanic entered - Body & Acc Interior	764094
217	03/18/2014	452698	Mechanic entered - Body & Acc Interior	763843
217	03/14/2014	451879	BUS INSPECTION LARGE -25 SEATS	765560
217	03/14/2014	452325	0405 ANSAIR FRONT AND REAR AIR BAG 810M/87R REAR	762814
217	03/14/2014	452325	o/s front air bag	762814
217	03/13/2014	451879	Annual Inspection	762810
217	03/13/2014	451889		762810
217	03/13/2014	451889	rad leaking	762810
217	03/13/2014	451889	rad leaking	762810
217	03/13/2014	452008	trans soliniod valve leak	762810
217	03/12/2014	451686		762810
217	03/12/2014	451686		762810
217	03/12/2014	451686		762810
217	03/12/2014	451686		762810
217	03/12/2014	451686		762810
217	03/12/2014	451686		762810
217	03/12/2014	451686	FUEL FILTER MERC 0500LE	762810
217	03/12/2014	451686	FUEL FILTER 0500LE	762810
217	03/12/2014	451686	AIR DRYER CANISTER VOLVO+ NL202	762810
217	03/12/2014	451686	POWER STEERING FILTER VOLVO	762810
217	03/12/2014	451686		762810
217	03/12/2014	451736	retorque wheels postion 3 & 4	762810
217	03/11/2014	450792	FITTING TRUCK	766323
217	03/11/2014	450792	SP 11R22.5 MCA-R DHR CUST/STOR	766323
217	03/11/2014	451451	Mechanic entered - Whis & Tyres Retension Wheel Nuts Pos 3 a	762676
217	03/11/2014	451451	Mechanic entered - Whis & Tyres Retension Wheel Nuts Pos 3 a	762676
217	03/11/2014	451451	SENSITIVE EDGE DOOR SWITCH DW40	762676

217	03/11/2014	451451	Finalize RSI	Checked and finalised	762676
217	03/11/2014	451451	Finalize RSI	completed	762676
217	03/11/2014	451451	repair eng oil leak	Tightened bottom sump bolts and cleaned.	762676
217	03/11/2014	451512	Perform Campaign 1_14 School Bus Light Globe Check	completed	762676
217	03/11/2014	450806	top radiator mount	Replaced top radiator mount near air drier.	762676
217	03/11/2014	451451	Fit Myki decals as requiredFit Recruitment decal as requir		762676
217	03/11/2014	451451	Fit Myki decals as requiredFit Recruitment decal as requir	completed	762676
217	03/11/2014	451451	repair air leaks	competed	762676
217	03/11/2014	451451	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		762676
217	03/11/2014	451451	repair air leaks	Replaced air fitting kits on two air line fittings	762676
217	03/06/2014	450806	top radiator mount	completed	762413
217	03/06/2014	450938	body check for RSI	fit new lock to drivers window repair striker plate on drivers door secure modesty panel back and front secure front pass seat	762413
217	03/06/2014	450798	repair air leaks round air dryer area	completed by ross	762413
217	03/05/2014	450792	Mechanic entered - Whils & Tyres Worn	replaced position 3 & 4	762413
217	03/05/2014	450758	steam clean for RSI	cleaned for rsi	762413
217	03/05/2014	450794	Mechanic entered - Body & Acc Other	Replaced D.N.O.T.V decal	762413
217	03/05/2014	450793	BRAKE PEDAL PAD		762413
217	03/05/2014	450793	Mechanic entered - Brakes Other	Replaced brake pedal pad	762413
217	03/05/2014	450791	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		762413
217	03/05/2014	450791	Mechanic entered - Air System Leaking	Repair air leaks	762413
217	03/03/2014	450366	L.E.D SIDE MARKER PEREI RED/AMBER		761889
217	03/03/2014	450366	Mechanic entered - Elec & Light Park Lights	REPLACED N/R MARKER LIGHT	761889
217	02/27/2014	449778	rear door cover		760846
217	02/25/2014	449188		Clean A/C Filter.	760437
217	02/25/2014	449188		Tension Wheel Nuts	760437
217	02/25/2014	449188		Perform & Complete TSV Bus Safety Inspection	760437
217	02/25/2014	449188	NUT BRASS BATTERY TERMINAL POSITIVE		760437
217	02/25/2014	449188	NUT BATTERY TERMINAL NEG (BRASS)		760437
217	02/25/2014	449188			760437
217	02/25/2014	449269	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		760437
217	02/25/2014	449269	air leaking	Stip and repair various air fittings around alr dryer	760437
217	02/17/2014	447764	Drv entered - Gearbox	no fault found	758562
217	02/17/2014	447764	AIR FILTER MERC 0500LE		758562
217	02/06/2014	446113	Drv entered - Body & Acc Security Door [See printed defect f	Both driver s door hinges replaced and adjusted the door.	755308
217	02/05/2014	446045	Ops entered - Fault - Elec & Light Battery Flat - Route: 7		755308
217	02/05/2014	446045	Ops Entered - Fault - Elec & Light Altern Light - Route:	no fault found	755308
217	02/01/2014	445539	Drv entered - Eng Cool Coolant Low	Repair coolant leak and top up coolant and tested Ok	754150
217	01/28/2014	444891	Ops Entered - Fault - Body & Acc Water Leak - Route: - PA	completed	753428
217	01/25/2014	444669	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	752737
217	01/25/2014	444669	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	752737
217	01/23/2014	444669		Service T - Replace Transmission Oil & Filter Carried out A&T Service as per schedule.	752737
217	01/22/2014	443673	FITTING TRUCK	Creditor #PT-BEAD01 BEAUREPAIRES P/O #P134107 Receiving #:135760 Date :2014-01-22	752264
217	01/22/2014	443673	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #PT-BEAD01 BEAUREPAIRES P/O #P134107 Receiving #:135760 Date :2014-01-22	752264
217	01/17/2014	443815	retorque wheel pos 6	Retention to spec	751042
217	01/16/2014	443460	Mechanic entered - Whils & Tyres Other Retension O/S rear whe	Retensioned os rear wheel nuts.	750522
217	01/15/2014	443348	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		750522
217	01/15/2014	443348		Carried out inspection replaced O/S rear outer tyre and rekitet air fitting on auxiliary air tank.	750522
217	01/15/2014	443348		Clean A/C filter	750522
217	01/15/2014	443348		Rotate Rear Axle Tyres Left to Right - MT & IBS only	750522
217	01/15/2014	443348		Rotate Front Axle Tyres Left to Right - MT & IBS only	750522
217	01/15/2014	443348		Tension Wheel Nuts	750522
217	01/15/2014	443348		Perform & Complete TSV Bus Safety Inspection	750522
217	01/15/2014	442921	BALANCE	Creditor #PT-BEAD01 BEAUREPAIRES P/O #P133911 Receiving #:135756 Date :2014-01-22	752264
217	01/15/2014	442921	FITTING TRUCK	Creditor #PT-BEAD01 BEAUREPAIRES P/O #P133911 Receiving #:135756 Date :2014-01-22	752264
217	01/15/2014	442921	DP 11R22.5 148/145L TL SP430 D	Creditor #PT-BEAD01 BEAUREPAIRES P/O #P133911 Receiving #:135756 Date :2014-01-22	752264
217	01/15/2014	443673	replace tyre pos 6 worn	Tyre replaced	750807
217	01/15/2014	443001	re torque tyre pos 1	Retensioned Pos 1 wheel nuts.	750522
217	01/13/2014	443001	re torque tyre pos 1	completed	750040
217	01/13/2014	442959	flat batt	Jump started	750040
217	01/12/2014	442921	Mechanic entered - Whils & Tyres Damaged	Replaced tyres pos 1 and 2 due to damage to 1 and tread match on 2. tension to 600 Nm	750040
217	01/12/2014	442966	LH indicator out		750040
217	01/12/2014	442966	GLOBE 24V 18W		750040
217	01/11/2014	442882	N/S rear tyres have side wall damage	Checked sidewall and found minor scrubbing on sidewall	749497
217	01/11/2014	442886	Drv entered - Air Cond Other [See printed defect for more in	Checked A/C Ok Turn on Vents above driver	749497
217	01/09/2014	442624	Drv entered - Vandalism Graffiti	completed	749254
217	01/08/2014	442354	Drv entered - Body & Acc Water Leak	repaired by mick	749018
217	01/04/2014	442011	RAO CAP MERC BENZ SIGHT GLASS SIDE		748345
217	01/04/2014	442011	Radiator cap missing		748345
217	01/02/2014	441626	Drv entered - Body & Acc Water Leak [See printed defect for	reseal front windscreen	747563
217	12/31/2013	440536	soleniod on trans acc leaking air	completed	747084
217	12/31/2013	441515	soleniod on trans acc leaking air	Replaced trans accumulator solenoid valve	747084
217	12/25/2013	442033	GLOBE H1 24V 70W		745857
217	12/25/2013	442033	headlight globe RH out		745857
217	12/23/2013	441515	SOLENOID VALVE ACCUMULATOR	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P133339-1 Receiving #:135154 Date :2014-01-07	744877
217	12/22/2013	440545	# 210 trans out put shaft seal leaking	wrongly inputted	744443
217	12/21/2013	440536	soleniod on trans acc leaking air	completed	744443
217	12/19/2013	440269	worn drivers seat tension bar	fitted by mick	744137
217	12/19/2013	440169	Remove BTS Equipment Fuses	removed bts fuses ok	744137
217	12/19/2013	439597	Ops Entered - Fault - Body & Acc Drivers Seat Cushion - Rou	as above	744137
217	12/19/2013	439597	Ops Entered - Fault - Body & Acc Drivers Seat Controls - Ro	as above	744137
217	12/19/2013	439597	worn drivers seat tension bar	fitted new part	744137
217	12/18/2013	439597	CONSUMABLE DELIVERY CHARGE	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P133102 Receiving #:134781 Date :2013-12-20	744443
217	12/18/2013	439597	OUTER LEVEL ISRI 6008	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P133102 Receiving #:134781 Date :2013-12-20	744443
217	12/17/2013	439875	Ops Entered - Fault - Air Cond Cooling Fault Light - Route:	repaired fault with new a/c relay	744026
217	12/17/2013	439949	Drv entered - Gearbox Harsh Thumping	gearbox thumping down from 3 to 2 gears	744026
217	12/17/2013	439878	FUEL FILTER 0500LE		744026
217	12/17/2013	439878		Replace Engine Oil Breather Kit	744026
217	12/17/2013	439878	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)		744026
217	12/17/2013	439878		Grease AC Compressor Clutch Bearing	744026
217	12/17/2013	439878	AIR FILTER MERC 0500LE		744026
217	12/17/2013	439878	OIL FILTER 1725+0500LE		744026
217	12/17/2013	439878	ENGINE OIL DELO 400LE 15W40		744026
217	12/17/2013	439878		Tension Wheel Nuts to Spec	744026
217	12/17/2013	439878		A Service & Bus Safety Inspection	744026
217	12/17/2013	439878		D-Service & Bus Safety Inspection	744026
217	12/17/2013	439878		A Service	744026
217	12/17/2013	439878		Clean A/C filter	744026
217	12/17/2013	439878		Grease AC Compressor Clutch Bearing	744026
217	12/17/2013	439878		Tension Wheel Nuts To OEM Specification	744026

217	12/16/2013	439597	worn tension bar	REPLACED BAR	743800
217	12/11/2013	438802	GLOBE WEDGE 24V/SW		742361
217	12/11/2013	438802	LH parker & LH indicator out	completed	742361
217	12/11/2013	438607	LH indicator out	Rectified loose connection at L/H front bottom indicator wire.	742361
217	12/10/2013	438467	Drv entered - Body & Acc Drivers Seat Controls	inspected drivers seat it needs a new shocker	742361
217	12/09/2013	438301	GLOBE 24V SW BAYONETT		742125
217	12/09/2013	438301	GLOBE WEDGE 24V/SW		742125
217	12/09/2013	438301	LH parker		742125
217	12/04/2013	437771		Clean A/C filter.	740896
217	12/04/2013	437771		Rotate Rear Axle Tyres Left to Right - MT & IBS only	740896
217	12/04/2013	437771		Rotate Front Axle Tyres Left to Right - MT & IBS only	740896
217	12/04/2013	437771		Tension Wheel Nuts	740896
217	12/04/2013	437771		Perform & Complete TSV Bus Safety Inspection	740896
217	12/04/2013	437677	GLOBE 24V16W		740896
217	12/04/2013	437677	GLOBE 24V SW BAYONETT		740896
217	12/04/2013	437677	OS top parker out	Replaced O/S front top indicator and park light globes.	740896
217	12/01/2013	434566	AC COMPRESSOR UNLOADER COIL	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P131784 Receiving #134253 Date :2013-12-06	741297
217	12/01/2013	437259	Drv entered - Gearbox Other [See printed defect for more in	tested and found servicable	740158
217	11/27/2013	436684	RH clearance in header out	completed	738676
217	11/22/2013	436071	replace unloader coil	install unloader solinoid replace air con relay check operation ok	737679
217	11/14/2013	434952	GLOBE WEDGE 24V/SW		735140
217	11/14/2013	434952	RH parker out		735140
217	11/14/2013	434928	air compressor pumping oil	servicable	735140
217	11/13/2013	434245	BALANCE	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131714 Receiving #133524 Date :2013-11-20	736897
217	11/13/2013	434245	FITTING TRUCK	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131714 Receiving #133524 Date :2013-11-20	736897
217	11/13/2013	434245	DP 11R22.5 148/145L TL SP430 D	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131714 Receiving #133524 Date :2013-11-20	736897
217	11/13/2013	434879	RH parker out	checked loose globe	734654
217	11/12/2013	434567	RE-TORQUE OSF	re-torque -osf	734654
217	11/12/2013	434566	Drv entered - Air Cond Cooling Fault Light	Found clutch coil fuse blown. Remove & replaced. Tested OK. Return air filter was 100% blocked. Commission tested both coils need to be replaced	734654
217	11/12/2013	434566	Drv entered - Air Cond Cooling Fault Light		734654
217	11/11/2013	434245	RH front tyre 3.5mm	replaced o/s front tyre ranout	734654
217	11/11/2013	434321	Organise MbENZ Recall SM949 to be performed by Whitehorse T	Sent to Whitehorse.	734654
217	11/06/2013	433661	LED FRONT POSITION MARKER LIGHT		733369
217	11/06/2013	433661	number plate light RH n/w	replaced both no. plate lights	733369
217	11/06/2013	433517	Drv entered - Body & Acc Mirrors Exterior [See printed defec	O/S RV mirror tightened and adjusted.	733369
217	11/04/2013	433118	BALANCE	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131469 Receiving #133513 Date :2013-11-20	736897
217	11/04/2013	433118	FITTING TRUCK	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131469 Receiving #133513 Date :2013-11-20	736897
217	11/04/2013	433118	DP 11R22.5 148/145L TL SP350A	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131469 Receiving #133513 Date :2013-11-20	736897
217	11/04/2013	433484	retension both front wheel nuts to 600nm	completed	731851
217	11/04/2013	433118	Replace NSF & OSF	completed	731851
217	11/02/2013	433574	GLOBE 24V16W		732675
217	11/02/2013	433574	LH indicator out		732675
217	10/30/2013	432837		replaced globe	731734
217	10/30/2013	432837		Clean A/C filter.	731734
217	10/30/2013	432837		Rotate Rear Axle Tyres Left to Right - MT & IBS only	731734
217	10/30/2013	432837		Rotate Front Axle Tyres Left to Right - MT & IBS only	731734
217	10/30/2013	432837		Tension Wheel Nuts	731734
217	10/30/2013	432837		Perform & Complete TSV Bus Safety Inspection	731734
217	10/29/2013	432543	Brake Interlock Re-install to be performed as per Campaign	Checked ok.	731465
217	10/28/2013	432369	Ops Entered - Fault - Body & Acc Drivers Seat Cushion - Ro	seat cushion removed and inspected does not appear to be faulty or damaged	731233
217	10/28/2013	432341	DRIVERS SEAT SHOCKER		731233
217	10/28/2013	432341	Ops Entered - Fault - Body & Acc Drivers Seat Controls - R	remove old seat shocker replace with new one inspect front seat control and adjust control	731233
217	10/25/2013	431697	FITTING TRUCK	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131058 Receiving #132981 Date :2013-11-04	732879
217	10/25/2013	431697	SP 11R22.5 SP327 CUST/STOR CAS	Creditor #PT-BEAD001 BEAUREPAIRES P/O #P131058 Receiving #132981 Date :2013-11-04	732879
217	10/25/2013	432543	Brake Interlock Re-install to be performed as per Campaign	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P131161 Receiving #132927 Date :2013-11-01	731107
217	10/23/2013	431763	Drv entered - Eng Cool Coolant Low [See printed defect for	topped up	729928
217	10/22/2013	431698	Replace OSF tyre	Replaced front tyre OS	729785
217	10/22/2013	431697	Replace pos 3 & 4	Tyres replaced	729785
217	10/22/2013	431598	Drv entered - Cool & AC Sys Drivers Fan [See printed defect	no fault found	729785
217	10/22/2013	431558	CYCLONE CONDENSER VALVE KIT		729785
217	10/22/2013	431558		Re-kit Air Cyclone Separator Rekit cyclone filter	729785
217	10/22/2013	431558	HALDEX CONDENSER KIT TOP(CYCLONE)		729785
217	10/22/2013	431557		Tension Wheel Nuts To OEM Specification	729785
217	10/22/2013	431557		A Service Service Replaced 2 switch lights and 2 gearbutton globes and coolant hose from water pump to cooler rail	729785
217	10/22/2013	431557		Clean A/C Filter	729785
217	10/22/2013	431557		Grease AC Compressor Clutch Bearing	729785
217	10/22/2013	431557	GLOBE WEDGE 24V 1.2W		729785
217	10/18/2013	431033	tyre pos 3 & 4 low	still has 4mm on tyres	728751
217	10/17/2013	430619	Drv entered - GearboxRetarder is causing the bus to bun	test drove and no fault found	728487
217	10/17/2013	430620	Drv entered - Other [See printed defect for more informatio	no fault found	728487
217	10/14/2013	429870	Perform sticker audit on vehicles ensuring that correct sti	completed	727497
217	10/10/2013	429594	ROCKER COVER GASKET 0500LE	Rocker Cover Gasket	726762
217	10/10/2013	429594		Adjust Tappets	726762
217	10/10/2013	429621	Drv entered - Suspension Noisy	no fault found	726762
217	10/10/2013	429621	top rad mount broken	no top radiator mounts in stock/fitted	726762
217	10/07/2013	428876	repair 2nd from front n/s panel; paint n/s front wheel	touched up panel	726128
217	10/07/2013	428851	alternator light on	removed top alt	726128
217	10/07/2013	428875	Accident Damaged #37858 Repair n/s/r. corner panels. Polish	completed	726128
217	10/06/2013	428776	air leak under drivers seat	repaired air under seat	725489
217	10/03/2013	428606	Drv entered - Gearbox Other [See printed defect for more in	test drove and found no fault with retarder	725245
217	10/01/2013	427813	Drv entered - Elec & Light Interior Lights	fitted	724536
217	10/01/2013	427811	Downlight out over driver	Replaced globe at driver cab light.	724536
217	10/01/2013	427811	light over driver out no parts in stock	fitted	724536
217	10/01/2013	427871	Rebrand to VENTURA	Creditor #PT-TRA009 TRANSVAL P/O #P130124 Receiving #132789 Date :2013-10-30	731734
217	10/01/2013	427811	LED DOWNLIGHT	Creditor #PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #P131000 Receiving #132392 Date :2013-10-22	729785
217	10/01/2013	427871	Carry out campaign as per Fleet re-branding Procedure.	Completed by Transcal.	724536
217	10/01/2013	427812	Drv entered - Body & Acc Drivers Seat Mount [See printed def	Checked driver seat could not fault it.	724536
217	10/01/2013	427811	Ops Entered - Fault - Body & Acc Drivers Seat Mount - Route	Checked driver seat could not fault it	724536
217	09/27/2013	427442	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed.	732769
217	09/27/2013	427442	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed	732769
217	09/24/2013	426907	Drv entered - Gearbox Harsh Thumping [See printed defect f	test drove and fault found	723050
217	09/23/2013	426447	hose aps	Creditor #PT-ENZED ENZED DANENONING P/O #P129788 Receiving #113115 Date :2013-09-25	723283
217	09/23/2013	426551	steering hose leaking	removed Replaced topped up and tested	722955
217	09/23/2013	426447	Mechanic entered - Steering Leaking	completed	722955
217	09/21/2013	426447	Mechanic entered - Steering Leaking	Checked for power steering leak. Found suction hose from pump to res rubbed through. No stock of part	722955
217	09/20/2013	422275	CHECK CCTV OPERATION	Creditor #PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #P130029 Receiving #131444 Date :2013-09-27	732769
217	09/19/2013	426218		Clean A/C filter.	722573
217	09/19/2013	426218		Rotate Rear Axle Tyres Left to Right - MT & IBS only	722573
217	09/19/2013	426218		Rotate Front Axle Tyres Left to Right - MT & IBS only	722573
217	09/19/2013	426218		Tension Wheel Nuts	722573

217	09/19/2013	426218		Perform & Complete TSV Bus Safety Inspection	722573
217	09/19/2013	426218	Drv entered - Elec & Light Other [See printed defect for mor	no fault found	722573
217	09/19/2013	426218	Drv entered - Body & Acc Other	no fault found	722573
217	09/16/2013	425447	Drv entered - Passenger Doors Slow	re gisedn from door ok	721506
217	09/02/2013	423058	Drv entered - Vandalism Graffiti	servicable	718338
217	09/02/2013	423057	Drv entered - Vandalism Other	servicable	718338
217	09/02/2013	423050	Drv entered - Vandalism Graffiti	servicable	718338
217	09/01/2013	423006	GLOBE WEDGE 24V/SW		717830
217	09/01/2013	423006	Mechanic entered - Elec & Light Park Lights	Replaced N/F park light globe	717830
217	08/21/2013	421122		Completed "A" Service as per schedule.	715256
217	08/21/2013	421122		Clean A/C filter	715256
217	08/21/2013	421122		Grease AC Compressor Clutch Bearing	715256
217	08/21/2013	421122		Tension Wheel Nuts To OEM Specification	715256
217	08/13/2013	419956	EMERGENCY EXIT BUTTON PULL COVER		713327
217	08/13/2013	419956	GLOBE WEDGE 24V 1.2W		713327
217	08/13/2013	419956	A/C BELT 0500 BENZ		713327
217	08/13/2013	419956		Clean A/C filter.	713327
217	08/13/2013	419956		Rotate Rear Axle Tyres Left to Right - MT & IBS only	713327
217	08/13/2013	419956		Rotate Front Axle Tyres Left to Right - MT & IBS only	713327
217	08/13/2013	419956		Tension Wheel Nuts	713327
217	08/13/2013	419956		Perform & Complete TSV Bus Safety Inspection Replaced globes as required. Replaced a/c belt.	713327
217	08/06/2013	418738	GLOBE WEDGE 24V/SW		711486
217	08/06/2013	418738	RH parker out	replaced	711486
217	08/03/2013	418440	1MT MULTI FIT WIPER REFILL		710810
217	08/03/2013	418440	Mechanic entered - Wipers & Washers Rubber Adrift	Replaced O/S wiper blade	710810
217	08/03/2013	418439	GLOBE H1 24V 70W		710810
217	08/03/2013	418439	Mechanic entered - Elec & Light Headlights	Replaced all rivet nuts to L/H headlight mount & replaced globe	710810
217	07/29/2013	416971	Drv entered - Heat & Demist Heater Cold [See printed defect		709516
217	07/29/2013	417393	replace heater tap	replaced tap	709516
217	07/27/2013	416971		Replaced heater tap and repair cable & mount	709257
217	07/26/2013	417011	PLASTIC HEATER TAP VOLGREN	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P127540 Receiving #:128808 Date :2013-07-29	709771
217	07/25/2013	416971	Drv entered - Heat & Demist Heater Cold [See printed defect	Heater tap siezed (No Parts)	708742
217	07/24/2013	416587	GLOBE WEDGE 24V/SW		708470
217	07/24/2013	416587	LH front parker globe blown	Replaced N/S front lower park light globe.	708470
217	07/19/2013	416034	Drv entered - Vandalism Graffiti	graffiti needs to be cleaned	707185
217	07/19/2013	416034	Drv entered - Ticket Equip Other	Found no fault ticket equipment possibly internal electrical fault	707185
217	07/18/2013	415820	SYNTHETIC GEAR LUBRICANT FM 75W-140		706920
217	07/18/2013	415820	Service		706920
217	07/14/2013	414973	Drv entered - Other [See printed defect for more informatio	Replace Differential oil replaced diff oil	705634
217	07/14/2013	414972	Drv entered - Comm Equip Not Operating [See printed defect	checked on other !! no fault found	705634
217	07/12/2013	414779	Drv entered - Other	checkede no fault found	705634
217	07/12/2013	414777	Drv entered - Other	no fault found	705387
217	07/12/2013	414777	Drv entered - Other	no fault found	705387
217	07/11/2013	414475	emergency exit light rear door out	Checked Emrg. Exit light and door step light no fault found. Plastic cover above rear door with Emrg. exit button and light is badly cracked and broken.	705126
217	07/06/2013	413768	LED FRONT POSITION MARKER LIGHT		703784
217	07/06/2013	413768		Clean A/C filter.	703784
217	07/06/2013	413768		Rotate Rear Axle Tyres Left to Right - MT & IBS only	703784
217	07/06/2013	413768		Rotate Front Axle Tyres Left to Right - MT & IBS only	703784
217	07/06/2013	413768		Tension Wheel Nuts	703784
217	07/06/2013	413768		Perform & Complete TSV Bus Safety Inspection Safety Inspection Replaced rear door emergency light	703784
217	06/28/2013	412483	emergency exit light rear door out	found no fault	702029
217	06/18/2013	409435	BALANCE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P126453 Receiving #:127522 Date :2013-07-01	702812
217	06/18/2013	409435	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P126453 Receiving #:127522 Date :2013-07-01	702812
217	06/18/2013	409435	DP 11R22.5 148/145L TL SP430 D	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P126453 Receiving #:127522 Date :2013-07-01	702812
217	06/18/2013	409490	AIR CON REFRIGERANT		699745
217	06/18/2013	409490	COMPRESSOR OIL AIR CON		699745
217	06/18/2013	409490	FILTER DRIER THERMO KING		699745
217	06/17/2013	410557	GLOBE WEDGE 24V/SW		699508
217	06/17/2013	410557	Mechanic entered - Elec & Light Park Lights o/s park light u	replaced globe	699508
217	06/14/2013	409435	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P125578 Receiving #:126838 Date :2013-06-19	699860
217	06/14/2013	409435	SP 11R22.5 SP327 CUST/STOR CAS	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P125578 Receiving #:126838 Date :2013-06-19	699860
217	06/14/2013	410238	ENGINE OIL DELO 400LE 13W40		698872
217	06/14/2013	410238		Tension Wheel Nuts to Spec	698872
217	06/14/2013	410238		A Service & Bus Safety Inspection	698872
217	06/14/2013	410238		D-Service & Bus Safety Inspection	698872
217	06/14/2013	410238		Grease AC Compressor Clutch Bearing	698872
217	06/14/2013	410238	AIR FILTER MERC 0500LE		698872
217	06/14/2013	410238	OIL FILTER 1725+0500LE		698872
217	06/14/2013	410238		Replace Engine Oil Breather Kit	698872
217	06/14/2013	410238	ENGINE OIL BREATHER KIT 0500LE		698872
217	06/14/2013	410296		A Service	698872
217	06/14/2013	410296		Clean A/C filter	698872
217	06/14/2013	410296		Grease AC Compressor Clutch Bearing	698872
217	06/14/2013	410296		Tension Wheel Nuts To OEM Specification	698872
217	06/14/2013	410238		Clean A/C filter	698872
217	06/14/2013	410238		Grease AC Compressor Clutch Bearing	698872
217	06/14/2013	410238		A Service	698872
217	06/14/2013	410238		Tension Wheel Nuts To OEM Specification	698872
217	06/12/2013	409661	retension o/s/rear wheel nuts to 600nm	retensioned	698303
217	06/12/2013	409661	retension o/s/rear wheel nuts to 600nm	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P125519 Receiving #:126758 Date :2013-06-18	698303
217	06/12/2013	409516	RADIATOR HOSE UPPER 0500LE	carried out campaign	699745
217	06/12/2013	408725	Service	Replaced tyres Pos 5 & 6 To retorque 12/6	698605
217	06/11/2013	409651	Mechanic entered - Whls & Tyres Worn	Retensioned.	698303
217	06/11/2013	409629	retension L/F wheel nuts to 600nm		698303
217	06/11/2013	409537	Drv entered - Vandalism Damaged Seat [See printed defect fo	Demister works OK	698303
217	06/11/2013	409490	Drv entered - Heat & Demist Heater Cold	Test driven and checked the operation of the retarder and trans. all works OK.Oil level is OK.	698303
217	06/11/2013	409490	Drv entered - Gearbox Harsh Thumping [See printed defect fo	Checked for abnormal noise of the HDD of the sec system.Is operating OK.	698303
217	06/11/2013	409490	Drv entered - Other [See printed defect for more information		698303
217	06/11/2013	409516	RADIATOR HOSE UPPER 0500LE		698303
217	06/11/2013	409516	top hose leaking	replaced hose	698303
217	06/11/2013	409490		B Service	698303
217	06/11/2013	409490		Replace filter drier	698303
217	06/11/2013	409490		Replace compressor oil	698303
217	06/11/2013	409490		DRIVE PULLEY'S: CLUTCH - Adjust air gap	698303
217	06/11/2013	409490		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	698303
217	06/11/2013	409490		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	698303
217	06/11/2013	409490		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	698303
217	06/11/2013	409490		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	698303
217	06/11/2013	409490		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	698303
217	06/11/2013	409490		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	698303

217	06/11/2013	409490	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	698303
217	06/11/2013	409490	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	698303
217	06/11/2013	409490	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	698303
217	06/11/2013	409490	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	698303
217	06/11/2013	409490	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	698303
217	06/10/2013	409435	Replaced tyre Pos 1 & Tension wheel	697438
217	06/09/2013	409621	Jump started	697951
217	06/03/2013	408725		696377
217	06/02/2013	408363	Installed missing top alt belt;	695690
217	06/02/2013	408363	Creditor #:PT-MUL001 MULTISPARES LTD P/O #P123562 Receiving #:124512 Date :2013-05-02	695690
217	06/01/2013	403205	Clean A/C filter.	688366
217	05/28/2013	407541	Tension Wheel Nuts	694741
217	05/28/2013	407541	Perform & Complete TSV Bus Safety Inspection	694741
217	05/28/2013	407541	replaced washer jet	694741
217	05/28/2013	407541		694741
217	05/28/2013	407637	replaced n/s clearance light	694518
217	05/28/2013	407637	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124032 Receiving #:125267 Date :2013-05-21	694518
217	05/28/2013	407637	Creditor #:PT-BEA001 BEAUREPAIRES P/O #P124032 Receiving #:125267 Date :2013-05-21	692716
217	05/28/2013	407637	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124032 Receiving #:125267 Date :2013-05-21	692716
217	05/28/2013	407637	Removed and welded a broken rear seat bracket and fitted.	692716
217	05/28/2013	407637		691428
217	05/28/2013	407637	fit new mirror ns	691130
217	05/28/2013	407637	replace n/s mirror arm and head	691428
217	05/28/2013	407637	Replaced sensor	680389
217	05/28/2013	407637	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124161 Receiving #:124785 Date :2013-05-10	690096
217	05/28/2013	407637	swnder unit replaced	687671
217	05/28/2013	407637	Valve Kit	687671
217	05/28/2013	407637	Base	687671
217	05/28/2013	407637	Condenser Valve Kit.	687671
217	05/28/2013	407637	Re-kit Air Cyclone Separator	687671
217	05/28/2013	407637	Coil Kit	687671
217	05/28/2013	407637	checked safe for operation	685921
217	05/28/2013	407637	paint a/c rear duct work	685921
217	05/28/2013	407637		685921
217	05/28/2013	407637	cleaned seat	684330
217	05/28/2013	407637	Clean A/C filter.	684330
217	05/28/2013	407637	Rotate Rear Axle Tyres Left to Right - MT & IBS only	684330
217	05/28/2013	407637	Rotate Front Axle Tyres Left to Right - MT & IBS only	684330
217	05/28/2013	407637	Tension Wheel Nuts	684330
217	05/28/2013	407637	Perform & Complete TSV Bus Safety Inspection Carried safety inspection as per schedule.	684330
217	05/28/2013	407637	A Service Carried out service as per schedule. Replaced N/S rear tyres road test and retension wheel nuts.	684330
217	05/28/2013	407637	Clean A/C filter	684330
217	05/28/2013	407637	Grease AC Compressor Clutch Bearing	684330
217	05/28/2013	407637	Tension Wheel Nuts To OEM Specification	681569
217	05/28/2013	407637	Completed by Eastcoast.	680951
217	05/28/2013	407637	Checked brake pads control arm bushs tie rod ends and brake caliper adjustment. checked king pin clearance found N/S front wheel bearing loose. adjusted wheel bearing road tested ok for service. Note: a bit of movement in both front caliper bushs. Brake temps.: O/S front 28degrees N/S from 33 degrees O/S rear 81	679020
217	05/28/2013	407637	Tightend indicator stalk mount screws.	679020
217	05/28/2013	407637	Checked brake pad thickness and ABS connectors found in good order. Found one event on fault diagnoses on ABS deleted event and road tested found no warning light. OK for service.	677256
217	05/28/2013	407637	Creditor #:EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #P122241 Receiving #:123475 Date :2013-04-10	677256
217	05/28/2013	407637	Clean A/C filter.	677256
217	05/28/2013	407637	Tension Wheel Nuts	677256
217	05/28/2013	407637	Rotate Front Axle Tyres Left to Right - MT & IBS only	677256
217	05/28/2013	407637	Perform & Complete TSV Bus Safety Inspection Carried out safety inspection as per schedule.	677256
217	05/28/2013	407637	Rotate Rear Axle Tyres Left to Right - MT & IBS only	677256
217	05/28/2013	407637		674460
217	05/28/2013	407637	service performed by 22 celsius	675091
217	05/28/2013	407637	Creditor #:ROA001 Road Safety Inspections P/O #:P121540 Receiving #:122525 Date :2013-03-19	675091
217	05/28/2013	407637	Creditor #:ROA001 Road Safety Inspections P/O #:P121540 Receiving #:122512 Date :2013-03-19	673361
217	05/28/2013	407637	(gs)R021839	673361
217	05/28/2013	407637		673361
217	05/28/2013	407637	Creditor #:CELO01 22 CELSIUS P/O #:P122183 Receiving #:122906 Date :2013-03-28	673361
217	05/28/2013	407637	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensorpressure switches; check evaporator auto fan speed; check de-ice cut out/in;check operation of fresh air ram; check electrical centre connections lightsand operation	673361
217	05/28/2013	407637	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	673361
217	05/28/2013	407637	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	673361
217	05/28/2013	407637	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	673361
217	05/28/2013	407637	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	673361
217	05/28/2013	407637	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	673361
217	05/28/2013	407637	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	673361
217	05/28/2013	407637	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	673361
217	05/28/2013	407637	COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	673361
217	05/28/2013	407637	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	673361
217	05/28/2013	407637	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	672982
217	05/28/2013	407637	see WO; 396531	672982
217	05/28/2013	407637		672982
217	05/28/2013	407637	Replaced trans cooler hose.	672982
217	05/28/2013	407637		671355
217	05/28/2013	407637	replaced rear drop arms and o/s front replace worn rear brake pads	671355
217	05/28/2013	407637	Replaced fr radiator mount.	671355
217	05/28/2013	407637		671355
217	05/28/2013	407637	remove front door and place glass replace damaged header glass performed by elete windscreens repair damgged front header replace broken n/s mirrir arm and mirror head	671355
217	05/28/2013	407637	Tension Wheel Nuts To OEM Specification	671355
217	05/28/2013	407637	Grease AC Compressor Clutch Bearing	671355
217	05/28/2013	407637	Clean A/C filter	671355
217	05/28/2013	407637	A Service	671355

[illegible]

217	10/11/2012	376204	GLOBE 24V16W			628615
217	10/11/2012	376204	RH INDICATOR OUT			628615
217	10/09/2012	375358	panel as per sample	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #P114781 Receiving #:116505 Date :2012-10-31		635539
217	10/05/2012	375371	TOP ALT BELT 0500LE			628178
217	10/05/2012	375358	Ops Entered - Accident - reworkplace of/s #5 panel prep and pai			628178
217	10/02/2012	374939				627373
217	10/02/2012	374939		Adjust Tappets		627373
217	10/02/2012	374939	ROCKER COVER GASKET 0500LE	Rocker Cover Gasket		627373
217	10/02/2012	374940	Service	fit rear door exit decals		628615
217	10/01/2012	374659	AIR FILTER MERC 0500LE	A Service		626728
217	10/01/2012	374659	GLOBE WEDGE 24V/SW	A Service		626728
217	10/01/2012	374659		A Service		626728
217	10/01/2012	374659		Clean A/C filter		626728
217	10/01/2012	374659		Grease AC Compressor Clutch Bearing		626728
217	10/01/2012	374659		Tension Wheel Nuts To OEM Specification		626728
217	09/21/2012	381394	Drv entered - Engine Other [See printed defect for more inf			624246
217	09/21/2012	381393	Bus hard to start first thing in the morning			624246
217	09/21/2012	378239	Both front bottom parkers out	reset electrical node and check operation		624246
217	09/07/2012	371620	Drv entered - Other [See printed defect for more information			618822
217	09/06/2012	371446	replace clearance lamp			618484
217	09/06/2012	371313	L.E.D SIDE MARKER PERE1 RED/AMBER			618484
217	09/06/2012	371313	o/s rear end damaged			618484
217	09/03/2012	370778	GLOBE WEDGE 24V/SW			617408
217	09/03/2012	370778	Drv entered - Elec & Light Interior Lights [See printed def	downlight replaced MR16		617408
217	08/30/2012	378167	Front LH indicator in header out	globe replaced		616454
217	08/28/2012	369726	MIRROR METAGAL R/H			615300
217	08/27/2012	369726	RAD CAP MERC BENZ SIGHT GLASS SIDE			614958
217	08/27/2012	369726	fit n/s mirror			614958
217	08/21/2012	369726	BODY DECALS OS PANELS 5 6	Creditor #:ATT001 ATTITUDE SIGNS P/O #P113290 Receiving #:113674 Date :2012-09-04		618061
217	08/14/2012	367745	HOSE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #P112254 Receiving #:113707 Date :2012-09-05		618484
217	08/13/2012	367745	LEVEL VALVE E4 BUS	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #P112254 Receiving #:113709 Date :2012-09-05		618484
217	08/13/2012	367745	TOP RADIATOR CAP HEADER TANK MERC BENZ			610896
217	08/13/2012	367745	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR			610896
217	08/13/2012	367745	Drv entered - Body & Acc Windows [See printed defect for mor			610896
217	08/13/2012	367745	Drv entered - Body & Acc Windows [See printed defect for mor			610896
217	08/11/2012	367719	horn not very audible	Suspension leaning towards NS due to excessive air bag height in OS		610896
217	08/07/2012	366956				609324
217	08/07/2012	366956	GLOBE WEDGE 24V/SW			609324
217	08/07/2012	366956				609324
217	08/07/2012	366956		Replace Engine Oil Breather Kit		609324
217	08/07/2012	366956	ENGINE OIL BREATHER KIT 0500LE			609324
217	08/07/2012	366956		Grease AC Compressor Clutch Bearing		609324
217	08/07/2012	366956	AIR FILTER MERC 0500LE			609324
217	08/07/2012	366956	OIL FILTER 1725+0500LE			609324
217	08/07/2012	366956	ENGINE OIL DELO 400LE 15W40			609324
217	08/07/2012	366956		Tension Wheel Nuts to Spec		609324
217	08/07/2012	366956		A Service & Bus Safety Inspection		609324
217	08/07/2012	366956		D-Service & Bus Safety Inspection		609324
217	08/07/2012	366956	INSERT LAMP QH			609324
217	08/07/2012	366956		A Service		609324
217	08/07/2012	366956		Clean A/C filter		609324
217	08/07/2012	366956		Grease AC Compressor Clutch Bearing		609324
217	08/07/2012	366956		Tension Wheel Nuts To OEM Specification		609324
217	08/02/2012	363872	CONSUMABLE DELIVERY CHARGE	Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #P110965 Receiving #:112205 Date :2012-08-02		608728
217	08/02/2012	363872	HUB & ARMATURE ASS'LY	Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #P110965 Receiving #:112205 Date :2012-08-02		608728
217	08/02/2012	363872	FIELD COIL CLUTCH AIR CON	Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #P110965 Receiving #:112205 Date :2012-08-02		608728
217	08/02/2012	363872	Pulley	Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #P110965 Receiving #:112204 Date :2012-08-02		608728
217	07/24/2012	363872	COMPRESSOR CLUTCH BEARING(METAL CAGE)			605740
217	07/24/2012	363872	AIR CON REFRIGERANT			605740
217	07/24/2012	363872	O RING AIR CON			605740
217	07/24/2012	363872	C-O THERMOKING SCREW COMPRESSOR			605740
217	07/24/2012	363872	AIR CON REFRIDGERANT			605740
217	07/24/2012	365067	Horn not working			605740
217	07/24/2012	365018	HALDEX COIL KIT 0500LE	Coil Kit		605740
217	07/24/2012	365018	DRAIN VALVE KIT BOTTOM	Valve Kit		605740
217	07/24/2012	365018	HALDEX COIL BASE OIL SEPERATOR	Base		605740
217	07/24/2012	365018	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.		605740
217	07/24/2012	365018				605740
217	07/23/2012	364783	Drv entered - Wipers & Washers Worn [See printed defect for	Re-kit Air Cyclone Separator		604675
217	07/23/2012	364782	Drv entered - Body & Acc Passenger Seat Back [See printed de	Checked wipers works fine		604675
217	07/23/2012	365018	4967904 DRAIN VALVE KIT CYCLON	Checked all OK		604675
217	07/20/2012	364890	Top left clearance light out	Creditor #:MUL001 MULTISPARES LTD P/O #P112083 Receiving #:112472 Date :2012-08-08		610105
217	07/20/2012	364890	Drv entered - Elec & Light Desto Control Panel			604675
217	07/17/2012	363872	A/C COMPRESSOR SEIZED	rEMOVE & REPLACE compressor assy.		603379
217	07/13/2012	363543	Drv entered - Other	Check rear passenger seat mount and locks all ok.		602825
217	07/13/2012	363544		Carry out service as per schedule.		602825
217	07/13/2012	363544		A Service		602825
217	07/13/2012	363544		Clean A/C filter		602825
217	07/13/2012	363544	Service	Grease AC Compressor Clutch Bearing		602825
217	07/13/2012	363544		Tension Wheel Nuts To OEM Specification		602825
217	06/28/2012	361265	GLOBE 24V SW BAYONETT			597634
217	06/28/2012	361265	Ops Entered - Fault - Elec & Light Park Lights - Route: -	Replaced N/S/F/Top park light & indicator globes & modified the wiring		597634
217	06/28/2012	361265	GLOBE 24V16W			597634
217	06/25/2012	361505	Replace o/s rear tyres			597399
217	06/23/2012	360964	GLOBE H1 24V 70W			596668
217	06/23/2012	360964	globe needs replacing			596668
217	06/12/2012	358849	GLOBE WEDGE 24V/SW			592613
217	06/12/2012	358849	Front parkers out			592613
217	06/12/2012	358881	Int panel door broken & noisy	remove and repair lock catch and reft		592613
217	06/11/2012	358889	Drv entered - Other [See printed defect for more informatio	repaired as per defect 358682		591590
217	06/11/2012	358862	Drv entered - Elec & Light Horn	repaired wiring (soft sound) needs new horn		591590
217	05/31/2012	357125	Drv entered - Other	Tested horn works ok		587934
217	05/22/2012	355360	BALANCE	Creditor #:BEA002 BEAUREPAIRS FOR TYRES P/O #P108394 Receiving #:109020 Date :2012-05-28		587036
217	05/22/2012	355360	FITTING	Creditor #:BEA002 BEAUREPAIRS FOR TYRES P/O #P108394 Receiving #:109020 Date :2012-05-28		587036
217	05/22/2012	355360	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRS FOR TYRES P/O #P108394 Receiving #:109020 Date :2012-05-28		587036
217	05/21/2012	355597	TOP ALT BELT 0500LE			584339
217	05/21/2012	355597	GLOBE 24V16W			584339

217	05/21/2012	355597	Drv entered - Elec & Light Indicators [See printed defect fo	Top alt belt replacedrectified lose indicator stalk	584339
217	05/18/2012	355372	engine oil leak	secured filler cap	584016
217	05/18/2012	355371	GLOBE INDICATOR 24V-18W SINGLE CONTACT	no fault found	584016
217	05/18/2012	355371	SINGLE CONTACT GLOBE 24V SW	no fault found	584016
217	05/18/2012	355371	Drv entered - Elec & Light Indicators	no fault found	584016
217	05/17/2012	355360	N/S/F tyre low tread		583740
217	05/12/2012	354672	R/H parker out		582302
217	05/11/2012	353959	11R22.5 - A GRADE CASE CHG	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P107929 Receiving #:108523 Date :2012-05-16	583035
217	05/11/2012	353959	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P107929 Receiving #:108523 Date :2012-05-16	583035
217	05/11/2012	353959	SP 11R22.5 SP327 A GRADE CASE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P107929 Receiving #:108523 Date :2012-05-16	583035
217	05/10/2012	353957	SWAY BAR DROP ARM	Creditor #:MUL001 MULTISPARES LTD P/O #:P109339 Receiving #:109664 Date :2012-06-07	591252
217	05/09/2012	353959	replace both n/s rear and inner o/s rear-3x retreats		581313
217	05/09/2012	353957	WATER PUMP	Creditor #:MUL001 MULTISPARES LTD P/O #:P109094 Receiving #:109420 Date :2012-06-04	590131
217	05/09/2012	353957	SWAY BAR DROP ARM	Creditor #:MUL001 MULTISPARES LTD P/O #:P109094 Receiving #:109421 Date :2012-06-04	590131
217	05/09/2012	353957	N/S/F sway bar drop arm worn		581313
217	05/09/2012	353957	RWC CHECK		581313
217	05/09/2012	353957	sat system rework		581313
217	05/09/2012	353957		A Service	581313
217	05/09/2012	353957		Clean A/C filter	581313
217	05/09/2012	353957		Grease AC Compressor Clutch Bearing	581313
217	05/09/2012	353957		Tension Wheel Nuts To OEM Specification	581313
217	05/07/2012	353630	replace o/s no 4 panel and o/s no 5 panel prep and panit a		581313
217	05/05/2012	353578	repair drivers blind		580117
217	04/30/2012	352444	GLOBE H1 24V 70W		578164
217	04/30/2012	352444	MIRROR METAGAL L/H		578164
217	04/30/2012	352444	Ops Entered - Accident - Bus Hit Stationary Object - Route:	L/H mirror arm & Mirror head replaced N/S head light globe replaced	578164
217	04/16/2012	350669	R/H bottom front parking light out		574974
217	04/16/2012	350669	GLOBE WEDGE 24V/SW		574974
217	04/12/2012	350103	GLOBE H1 24V 70W		574093
217	04/12/2012	350103	GLOBE 24V 75/70W H4		574093
217	04/12/2012	350103	Drv entered - Elec & Light Indicators [See printed defect fo		574093
217	04/12/2012	350090	Drv entered - Elec & Light Park Lights [See printed defect fo	REPLACE INDICATOR GLOBE	574093
217	03/27/2012	345323	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P105429 Receiving #:106533 Date :2012-03-27	569576
217	03/27/2012	345323	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P105429 Receiving #:106533 Date :2012-03-27	569576
217	03/23/2012	347555	Coolant leak	Transcooler elbowhose was leaking. Replacedtopped up tested is ok	568383
217	03/23/2012	347582	Drv entered - Comm Equip Other	2 Way handset cable shorting out replaced works ok	568383
217	03/23/2012	347582	Drv entered - Comm Equip Other		568383
217	03/23/2012	347580	seat adjuster doesnt work. Seat tilt forward doesnt work	Roll pin on the adjuster dial was broken replaced is ok	568383
217	03/23/2012	347580	seat adjuster doesnt work. Seat tilt forward doesnt work		568383
217	03/16/2012	346258	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P105602 Receiving #:106402 Date :2012-03-23	568383
217	03/13/2012	346258	annual inspection		565680
217	03/14/2012	345957	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		565486
217	03/14/2012	345957	replace n/s sway bar drop arm		565486
217	03/14/2012	345957	replace n/s sway bar drop arm		565486
217	03/14/2012	345956	Service	REPLACE LAMP UNIT	565486
217	03/13/2012	345755	LEAD BATTERY 9IN.		565486
217	03/13/2012	345755	rsi repairs		565486
217	03/13/2012	345755	AIR LINE FITTING KIT 0500LE AIR DRYER		565486
217	03/09/2012	345576		Replace angle drive oil	565486
217	03/09/2012	345576	POWER STEERING FILTER VOLVO		565486
217	03/09/2012	345576	AIR DRYER CANISTER VOLVO+ NL202		565486
217	03/09/2012	345576	FUEL FILTER 0500LE		565486
217	03/09/2012	345576	FUEL FILTER MERC 0500LE		565486
217	03/09/2012	345576		Replace power steering filter and check level (Replace oil if required)	565486
217	03/09/2012	345576		Test coolant level - top up if required to equate to 37C frost protection	565486
217	03/09/2012	345576		Replace air dryer canister clean silence and drain reservoir	565486
217	03/09/2012	345576		Replace pre and main fuel filters	565486
217	03/09/2012	345576		Check and clean cartridge in dry type air cleaner	565486
217	03/09/2012	345576		Check oil level in transmission - top up if required	565486
217	03/09/2012	345576		Inspect radiator and charge air cooler for dirt - clean	565486
217	03/09/2012	345576		Replace final drive oil	565486
217	03/09/2012	345576		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	565486
217	03/09/2012	345575		Replace power steering filter and check level (Replace oil if required)	565486
217	03/09/2012	345575		Replace angle drive oil	565486
217	03/09/2012	345575		Check and clean cartridge in dry type air cleaner	565486
217	03/09/2012	345575		Check oil level in transmission - top up if required	565486
217	03/09/2012	345575		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	565486
217	03/09/2012	345575	POWER STEERING FILTER VOLVO		565486
217	03/09/2012	345575	AIR DRYER CANISTER VOLVO+ NL202		565486
217	03/09/2012	345575	FUEL FILTER 0500LE		565486
217	03/09/2012	345575	FUEL FILTER MERC 0500LE		565486
217	03/09/2012	345575		Test coolant level - top up if required to equate to 37C frost protection	565486
217	03/09/2012	345575		Replace air dryer canister clean silence and drain reservoir	565486
217	03/09/2012	345575		Replace pre and main fuel filters	565486
217	03/09/2012	345575		Inspect radiator and charge air cooler for dirt - clean	565486
217	03/09/2012	345575		Replace final drive oil	565486
217	03/09/2012	345575			565486
217	03/09/2012	0	Imported Service History	Imported Service History	565486
217	03/07/2012	345323	ENGINE OIL DELO 400LE 15W40		565370
217	03/07/2012	345323			565370
217	03/07/2012	345323		Replace Engine Oil Breather Kit	565370
217	03/07/2012	345323	AIR FILTER MERC 0500LE		565370
217	03/07/2012	345323	OIL FILTER 1725+0500LE		565370
217	03/07/2012	345323		Tension Wheel Nuts to Spec	565370
217	03/07/2012	345323		A Service & Bus Safety Inspection	565370
217	03/07/2012	345323		D-Service & Bus Safety Inspection	565370
217	03/07/2012	345323		Grease AC Compressor Clutch Bearing	565370
217	03/07/2012	345323	ENGINE OIL BREATHER KIT 0500LE		565370
217	03/07/2012	345323		A Service	565370
217	03/07/2012	345323		Clean A/C filter	565370
217	03/07/2012	345323		Grease AC Compressor Clutch Bearing	565370
217	03/07/2012	345323		Tension Wheel Nuts To OEM Specification	565370
217	02/29/2012	344132	top alt belt needs replacing		565370
217	02/23/2012	343064	CHECK VALVE 22MM CYCLONE AIR FILTER		565370
217	02/23/2012	343064	AIR LINE FITTING KIT 0500LE AIR DRYER		565370
217	02/23/2012	343064		Re-kit Air Cyclone Separator	565370
217	02/23/2012	341825	FILTER DRIER THERMO KING		565370
217	02/22/2012	342059	Drv entered - Comm Equip Faulty [See printed defect for mor	disconnected emg switch wiring	565370
217	02/15/2012	341948	unable to rear desto controller display	desto controller replaced under warranty	565370

217	02/14/2012	341780	check sysetpon operation stuck in raised position		558387
217	02/14/2012	341825	Drv entered - Air Cond Cooling Fault Light [See printed def		558387
217	02/14/2012	341825		C Service	558387
217	02/14/2012	341825		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	558387
217	02/14/2012	341825		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	558387
217	02/14/2012	341825		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	558387
217	02/14/2012	341825		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	558387
217	02/14/2012	341825		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	558387
217	02/14/2012	341825		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	558387
217	02/14/2012	341825		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	558387
217	02/14/2012	341825		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	558387
217	02/14/2012	341825		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	558387
217	02/14/2012	341825		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	558387
217	02/14/2012	341825		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	558387
217	02/07/2012	340774	Air con blowing hot air	replace condensor fans	556502
217	02/07/2012	340771	Blowing hot air: Needs gas		556502
217	02/07/2012	340774	Air con blowing hot air		556502
217	01/23/2012	338516	repair acc damage/ volgren		555802
217	01/17/2012	337494	BALANCE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P103022 Receiving #:103889 Date :2012-01-18 SUPPLY 1 X NEW 11.22R	554688
217	01/17/2012	337494	FITTING	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P103022 Receiving #:103889 Date :2012-01-18 SUPPLY 1 X NEW 11.22R	554688
217	01/17/2012	337494	Direct Purchase - TYRES	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P103022 Receiving #:103889 Date :2012-01-18 SUPPLY 1 X NEW 11.22R	554688
217	01/16/2012	337494	SUPPLY 1 X NEW 11.22R		554022
217	01/10/2012	333488	BALANCE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101819 Receiving #:103545 Date :2012-01-10	552359
217	01/10/2012	333488	Direct Purchase - TYRES	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101819 Receiving #:103545 Date :2012-01-10	552359
217	01/10/2012	333488	FITTING	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101819 Receiving #:103545 Date :2012-01-10	552359
217	01/09/2012	336506	replace worn n/s sterr tyre	Replace n/s front tyre road test and retension wheel nuts.	551983
217	01/09/2012	336418	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		551983
217	01/09/2012	336418		Bus Safety Inspection	551983
217	01/09/2012	336418	FILTER TRANSMISSION ZF 4139-298-03BE39HD119	ZF Transmission Filter	551983
217	01/09/2012	336418	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	551983
217	01/09/2012	336418		Service T - Replace Transmission Oil & Filter Carry out service as per schedule and replace N/S/R rear air bag.	551983
217	12/19/2011	334126	replace broken n/s rear window		547590
217	12/19/2011	334126	side window	Creditor #ELU001 ELITE WINDSCREENS P/O #P102051 Receiving #:102965 Date :2011-12-22	548069
217	12/19/2011	334126	Ops Entered - Accident - Broken Window-Windscreen - Route:		547590
217	12/19/2011	334126	24 VOLT FLASHER RELAY		547590
217	12/19/2011	334126	GLOBE H1 24V 70W		547590
217	12/19/2011	334126	GLOBE H1 24V 70W		547590
217	12/14/2011	333488	O/S front low needs changing	Replace front o/s tyre road test and retension front o/s wheel nuts.	546141
217	12/13/2011	333417	REAR HUB SEAL KIT 0500LE	Creditor #MUL001 MULTISPARES LTD P/O #P101758 Receiving #:102752 Date :2011-12-16	546141
217	12/13/2011	333417	replace leaking rear hub seal		547590
217	12/12/2011	332700	FITTING	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101615 Receiving #:102794 Date :2011-12-19	547590
217	12/12/2011	332700	TYRE RECYCLE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101615 Receiving #:102794 Date :2011-12-19	547590
217	12/12/2011	332700	11R22.5 - A GRADE CASE CHG	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101615 Receiving #:102794 Date :2011-12-19	547590
217	12/12/2011	332700	SP 11R22.5 SP327 A GRADE CASE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P101615 Receiving #:102794 Date :2011-12-19	547590
217	12/08/2011	332700		N/S hub seal leaks checked diff oil topped up	543994
217	12/08/2011	332700	N/S outer needs replacing	Replaced both N/C drivesretorqued.	543994
217	12/08/2011	332697	GLOBE H1 24V 70W		543994
217	12/08/2011	332697	Drv entered - Elec & Light Headlights [See printed defect fo		543994
217	12/07/2011	332696	Drv entered - Body & Acc Passenger Seat Cushion [See printed		543994
217	11/24/2011	330745	Drv entered - Elec & Light Desto Control Panel [See printed	checkrd out desto desto working ok. control panel lcd screen dot matrix faulty display	539609
217	11/23/2011	330535	1MT MULTI FIT WIPER REFIL		538707
217	11/23/2011	330535	WASHER PUMP 24VOLT		538707
217	11/23/2011	330535	washer machine not working	replaced washer motor and wiper refills	538707
217	11/23/2011	330535	washer machine not working		538707
217	11/08/2011	343450		A Service	534041
217	11/08/2011	343450		Clean A/C filter	534041
217	11/08/2011	343450		Grease AC Compressor Clutch Bearing	534041
217	11/08/2011	343450		Tension Wheel Nuts To OEM Specification	534041
217	10/05/2011	343447		Adjust Tappets	523927
217	09/23/2011	321299	HALDEX COIL KIT 0500LE	Coil Kit	521214
217	09/23/2011	321299	DRAIN VALVE KIT BOTTOM	Valve Kit	521214
217	09/23/2011	321299	HALDEX COIL BASE OIL SEPARATOR	Base	521214
217	09/23/2011	321299	WATER SEPARATOR SCANIA+VOLVO+MB (HAL90364)	Water Separator Kit	521214
217	09/23/2011	321299		Re-kit Air Cyclone Separator	521214
217	09/23/2011	321299		Remove dismantle clean assemble and fit air cyclone separator.	521214
217	09/19/2011	320428	Internal screen 1/2 not working		519574
217	09/19/2011	320427	Drv entered - Desto Signs	Checked all works ok	519574
217	09/19/2011	320388			519574
217	09/19/2011	320388	ENGINE OIL BREATHER KIT 0500LE	Replace engine oil breather kit	519574
217	09/19/2011	320388	ENGINE OIL DELO 400LE 15W40		519574
217	09/19/2011	320388		D-Service & Bus Safety Inspection	519574
217	09/19/2011	320388		Tension Wheel Nuts to Spec	519574
217	09/19/2011	320388		A Service & Bus Safety Inspection	519574
217	09/19/2011	320388		Grease AC Compressor Clutch Bearing	519574
217	09/19/2011	320388	AIR FILTER MERC 0500LE		519574
217	09/19/2011	320388	OIL FILTER 1725+0500LE		519574
217	09/19/2011	320388		Clean A/C filter	519574
217	09/19/2011	320388		Tension Wheel Nuts To OEM Specification	519574
217	09/19/2011	320388		Grease AC Compressor Clutch Bearing	519574
217	09/05/2011	317983	Drv entered - Desto Signs [See printed defect for more info	Desto LCD back globe blown is clearly visibal with drivers light on at night	513932
217	09/02/2011	317695	GLOBE 24V 21W SINGLE CONTACT		513932
217	09/02/2011	317695	GLOBE 24V 5W BAYONETT		513932
217	09/02/2011	317695	Drv entered - Elec & Light indicators	Removed dr blind & Fr O/S Top Indicator & Park light globes replaced	513932
217	08/31/2011	317426	GLOBE 24V 21W SINGLE CONTACT		513560
217	08/31/2011	317426	Drv entered - Elec & Light indicators [See printed defect fo	replace blown globe	513560
217	08/30/2011	317025			513287
217	08/30/2011	317025		Tension Wheel Nuts	513287
217	08/30/2011	317025		Perform & Complete TSV Bus Safety Inspection	513287
217	08/29/2011	315754	FITTING	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P97061 Receiving #:98848 Date :2011-09-19	520113
217	08/29/2011	315754	11R22.5 SP327 P/C RTD	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P97061 Receiving #:98848 Date :2011-09-19	520113
217	08/26/2011	315478	TYRE RECYCLE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P96888 Receiving #:98849 Date :2011-09-19	520113
217	08/26/2011	315478	BALANCE	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P96888 Receiving #:98849 Date :2011-09-19	520113
217	08/26/2011	315478	FITTING	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P96888 Receiving #:98849 Date :2011-09-19	520113
217	08/26/2011	315478	Direct Purchase - TYRES	Creditor #BEA002 BEAUREPAIRS FOR TYRES P/O #P96888 Receiving #:98849 Date :2011-09-19	520113
217	08/23/2011	315754	replace o/s rear tyres		510797
217	08/23/2011	315893	N/S Front stabiliser drop arm ball joints U/S		510797
217	08/23/2011	315738	Heater not working		510797

217	08/23/2011	315738	Engine Dipstick broken			510797
217	08/23/2011	315738	Drv entered - Other [See printed defect for more informatio			510797
217	08/23/2011	315738	Battery door lock broken			510797
217	08/23/2011	315738	Engine door hatch does not stayup. Needs new struts			510797
217	08/23/2011	315738		A Service		510797
217	08/23/2011	315738		Tension Wheel Nuts To OEM Specification		510797
217	08/23/2011	315738		Grease AC Compressor Clutch Bearing		510797
217	08/23/2011	315738		Clean A/C filter		510797
217	08/23/2011	315738				510797
217	08/23/2011	315738	1MT MULTI FIT WIPER REFILL			510797
217	08/23/2011	315738				510797
217	08/23/2011	315738		Adjust alt belt replace broken reflectors and n/s rear indicator assy.		510797
217	08/23/2011	315738	AMBER REFLECTOR			510797
217	08/20/2011	315478	replaced n/s front tyre....clean skin			510137
217	08/15/2011	314287	Ops Entered - Fault - Elec & Light - Route: - Take a Rigid	N/S/T/F indicator globe blown replaced.OK		508076
217	08/13/2011	314247	Desto control display panel needs new globe.			508076
217	08/11/2011	313742	N/S rear lower indicator lens U/S	NEW REAR INDICATOR LAMP NEEDED		503703
217	07/28/2011	311668	Drv entered - Elec & Light Park Lights [See printed defect			503703
217	07/28/2011	311668	Top left clearance light N/W			503703
217	07/22/2011	310881	Drv entered - Elec & Light Other [See printed defect for mor			501904
217	07/22/2011	310881	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER			501904
217	07/18/2011	316289		Tension wheel nuts		500825
217	07/18/2011	316289		Perform & Complete TSV Bus Safety Inspection		500825
217	07/14/2011	309734	Drv entered - Vandalism Graffiti [See printed defect for mor			499366
217	07/14/2011	309733	Drv entered - Ticket Equip Not Printing [See printed defect			499366
217	07/08/2011	308864	Ops Entered - Fault - Wipers & Washers - Route: 832 - Frank			497454
217	07/05/2011	308087	GLOBE WEDGE 24V/SW	Re fitted wiper rubber and lubed noisy wiper pivot arms		496467
217	07/05/2011	308087	Drv entered - Elec & Light Switches [See printed defect for	C/O Driver control switch globes.		496467
217	07/02/2011	307848		Tension Wheel Nuts To OEM Specification		495574
217	07/02/2011	307848		A Service		495574
217	07/02/2011	307848		Clean A/C filter		495574
217	07/02/2011	307848		Grease AC Compressor Clutch Bearing		495574
217	06/27/2011	306855	side window	Creditor # :ELI001 ELITE WINDSCREENS P/O # :P94347 Receiving # :95363 Date :2011-06-28		494822
217	06/27/2011	306855	replace broken o/s no 4 window			494780
217	06/24/2011	306561	Ops Entered - Fault - Eng Cool - Route: - Take a Low Floor	replaced thermostat hose		493680
217	06/24/2011	306543	Drv entered - Eng Cool Overheating [See printed defect for m	Replaced top coolant hose topped up cleaned tested		493680
217	06/20/2011	305747		Tension wheel nuts		491756
217	06/20/2011	305747		Perform & Complete PTSV Bus Safety Inspection		491756
217	06/20/2011	305822	FITTING	Creditor # :BEA002 BEAUREPAIRS FOR TYRES P/O # :P94034 Receiving # :95339 Date :2011-06-28		494822
217	06/20/2011	305822	11R22.5 SP327 P/C RTD	Creditor # :BEA002 BEAUREPAIRS FOR TYRES P/O # :P94034 Receiving # :95339 Date :2011-06-28		494822
217	06/20/2011	305822	n/s rear tyres u/s			491756
217	06/08/2011	304411	Drv entered - Elec & Light Park Lights [See printed defect			487717
217	05/26/2011	302406		A Service & Bus Safety Inspection		482643
217	05/26/2011	302406		Tension Wheel Nuts To OEM Specification		482643
217	05/26/2011	302406		Grease AC Compressor Clutch Bearing		482643
217	05/26/2011	302406		Clean A/C filter		482643
217	05/23/2011	301890		Re-Air Air Cyclone Separator		481856
217	05/23/2011	301890	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	Water Separator Kit		481856
217	05/13/2011	300477	Drv entered - Cool & AC Sys Water Leak [See printed defect			478853
217	05/12/2011	300173	Drv entered - Passenger Doors Faulty Controls			478132
217	05/12/2011	300173	Drv entered - Passenger Doors Faulty Controls			478132
217	05/12/2011	300173	Drv entered - Passenger Doors Faulty Controls			478132
217	05/12/2011	300173	Drv entered - Passenger Doors Other [See printed defect for			478132
217	05/12/2011	300173	Drv entered - Passenger Doors Faulty Controls [See printed	Removed lubed & tested both door switches. Both working properly now.		478132
217	05/10/2011	299030	FILTER DRIER THERMO KING			477233
217	05/10/2011	299030	COMPRESSOR OIL AIR CON			477233
217	05/03/2011	299030		Replace compressor oil		475487
217	05/03/2011	299030		Replace filter drier		475487
217	05/03/2011	299030		B Service		475487
217	05/03/2011	299030		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		475487
217	05/03/2011	299030		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension		475487
217	05/03/2011	299030		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		475487
217	05/03/2011	299030		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray		475487
217	05/03/2011	299030		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;		475487
217	05/03/2011	299030		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		475487
217	05/03/2011	299030		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		475487
217	05/03/2011	299030		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		475487
217	05/03/2011	299030		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;		475487
217	05/03/2011	299030		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		475487
217	05/03/2011	299030		Clean R/A & F/A filters; inspect and report on condition; Replace filter media		475487
217	04/29/2011	298619		Tension Wheel Nuts to Spec		474132
217	04/29/2011	298619				474132
217	04/29/2011	298619	ENGINE OIL BREATHER KIT 0500LE	Grease AC Compressor Clutch Bearing		474132
217	04/29/2011	298619				474132
217	04/29/2011	298619		Replace engine oil breather kit		474132
217	04/29/2011	298619		D-Service & Bus Safety Inspection		474132
217	04/29/2011	298619		A Service & Bus Safety Inspection		474132
217	04/29/2011	298619		A Service & Bus Safety Inspection		474132
217	04/29/2011	298619		Tension Wheel Nuts To OEM Specification		474132
217	04/29/2011	298619		Grease AC Compressor Clutch Bearing		474132
217	04/29/2011	298619		Clean A/C filter		474132
217	04/15/2011	297967		A Service & Bus Safety Inspection		469913
217	04/15/2011	297967		Clean A/C filter		469913
217	04/15/2011	297967		Grease AC Compressor Clutch Bearing		469913
217	04/15/2011	297967		Tension Wheel Nuts To OEM Specification		469913
217	04/13/2011	322447	BOD - Cracked window front NS	replaced on w/o 294016		469209
217	04/08/2011	296590	CUSTOMER REPORT VIA METLINK DATA BASE POOR BRAKING PEROFRMA	CHECKED OPERATION FOUND OK		467367
217	03/21/2011	293562	Direct Purchase - TYRES	Creditor # :BEA002 BEAUREPAIRS FOR TYRES P/O # :P89759 Receiving # :91204 Date :2011-03-28		463703
217	03/21/2011	293562	CONSUMABLE SUPPLIES SURCHARGE	Creditor # :BEA002 BEAUREPAIRS FOR TYRES P/O # :P89759 Receiving # :91204 Date :2011-03-28		463703
217	03/21/2011	294016	replace broken o/s rear window			461416
217	03/21/2011	294016	side window	Creditor # :ELI001 ELITE WINDSCREENS P/O # :P89911 Receiving # :91013 Date :2011-03-23		461870
217	03/18/2011	293704	ROAD SAFETY INSPECTIONS	Creditor # :ROA001 Road Safety Inspections P/O # :P89799 Receiving # :91007 Date :2011-03-23		461870
217	03/17/2011	293704	annual inspection			460888
217	03/16/2011	293001	DISC SECURING BOLT	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving # :91754 Date :2011-04-08		467859
217	03/11/2011	293562	REPLACE N/S REAR TYRES			460557
217	03/11/2011	293001	replace front and rear brake pads and disk rotors			460272

217	03/11/2011	293001	MUFFLER MOUNT 0500LE	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving #:91812 Date :2011-04-08	467859
217	03/11/2011	293001	DISC SECURING BOLT	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving #:91812 Date :2011-04-08	467859
217	03/11/2011	293001	DISC PAD SET	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving #:91812 Date :2011-04-08	467859
217	03/11/2011	293001	DISC NOTION 016-295-00	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving #:91812 Date :2011-04-08	467859
217	03/11/2011	293001	DISC SECURING BOLT	Creditor # :MUL001 MULTISPARES LTD P/O # :P89602 Receiving #:91812 Date :2011-04-08	467859
217	03/11/2011	292998		Clean A/C filter	460272
217	03/11/2011	292998		Grease AC Compressor Clutch Bearing	460272
217	03/11/2011	292998		Tension Wheel Nuts To OEM Specification	460272
217	03/11/2011	292998		A Service & Bus Safety Inspection	460272
217	02/23/2011	293202	Drv entered - Passenger Doors Faulty Controls	door operation checked. No fault found	456090
217	02/23/2011	293202	Faulty front door switch		456090
217	02/23/2011	293202	Door opens then closes on the passengers		456090
217	02/23/2011	293202	Drv entered - Body & Acc Security Door		456090
217	02/14/2011	289987	low water sender u/s	low water sender replaced	452987
217	02/09/2011	288884		Service T - Replace Transmission Oil & Filter	451126
217	02/09/2011	288884	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	451126
217	02/09/2011	288884	ZF GEARBOX FILTER	ZF Transmission Filter	451126
217	02/09/2011	288884		Bus Safety Inspection	451126
217	02/09/2011	288884		Tension Wheel Nuts To OEM Specification	451126
217	02/09/2011	288884		Grease AC Compressor Clutch Bearing	451126
217	02/09/2011	288884		Clean A/C filter	451126
217	02/09/2011	288884		A Service & Bus Safety Inspection	451126
217	01/20/2011	286264	TEST AND REPLACE BATTERYS		443874
217	01/20/2011	286264	12V 200AMP 1100CCA		443874
217	01/13/2011	285389		Clean A/C filter	441326
217	01/13/2011	285389		Grease AC Compressor Clutch Bearing	441326
217	01/13/2011	285389		A Service & Bus Safety Inspection	441326
217	01/13/2011	285389		Tension Wheel Nuts To OEM Specification	441326
217	01/07/2011	284689	Drv entered - Brakes Shuddering	Checked brakes Rear disc rotors are out of paralal.	439212
217	01/06/2011	283836	FITTING	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P86709 Receiving #:89211 Date :2011-02-04 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	449501
217	01/06/2011	283836	11R22.5 SP327 P/C RTD	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P86709 Receiving #:89211 Date :2011-02-04 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	449501
217	12/31/2010	283836	Change rear 2 tyres.		436848
217	12/31/2010	283421	SHIM GASKET SUIT 0500LE COMPRE		436848
217	12/31/2010	283421	COOLANT PIPE COMPRESSOR TO BLO	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P86713 Receiving #:87828 Date :2010-12-31	455583
217	12/31/2010	283421	Replace air compessor.	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P87590 Receiving #:88638 Date :2011-01-24	436848
217	12/31/2010	283421	Replace rear brake pads.		436848
217	12/30/2010	283421	Drv entered - Passenger Doors		436848
217	12/30/2010	283421	Drv entered - Passenger Doors		436848
217	12/29/2010	283421	0500LE O RING STEER PUMP-COMP	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P86634 Receiving #:87803 Date :2010-12-31 GASKET COMPRESSOR TO BLOCK	436848
217	12/29/2010	283421	COMPRESSOR O RING 0500LE	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P86634 Receiving #:87803 Date :2010-12-31 GASKET COMPRESSOR TO BLOCK	436848
217	12/29/2010	283421	Service		436848
217	12/29/2010	283421	WASHER COOLANT PIPE	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P86634 Receiving #:87803 Date :2010-12-31 WATER FEED PIPE	436848
217	12/29/2010	283421	AIR COMPRESSOR	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P86634 Receiving #:87803 Date :2010-12-31 AIR COMPRESSOR	436848
217	12/29/2010	283421	Drv entered - Other [See printed defect for more informatio		436848
217	12/29/2010	283421	DISC PAD SET	Creditor # :MUL001 MULTISPARES LTD P/O # :P86638 Receiving #:87801 Date :2010-12-31 Rear disc pads.	436848
217	12/29/2010	283421	Rear Brakes Holding on.Low Air.		436848
217	12/27/2010	283412	No Air Won't Move.		436848
217	12/17/2010	282296	Drv entered - Passenger Doors Faulty Controls		433382
217	12/17/2010	282353	O/S headlight out	Replaced	433382
217	12/17/2010	282353	H1 GLOBE 24V 70W		433382
217	12/16/2010	282235	Drv entered - Passenger Doors Faulty Controls		433382
217	12/15/2010	297970		Re-kit Air Cyclone Separator	433382
217	12/15/2010	297970	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	Water Separator Kit	433382
217	12/13/2010	281666	Drv entered - Other. DOOR TO DRIVERS AREA WON'T STAY SHUT .		432594
217	11/29/2010	279768		D-Service & Bus Safety Inspection	427754
217	11/29/2010	279768		A Service & Bus Safety Inspection	427754
217	11/29/2010	279768	ENGINE OIL DELO 400LE 15W40		427754
217	11/29/2010	279768	AIR FILTER MERC 0500LE		427754
217	11/29/2010	279768	ENGINE OIL BREATHER KIT 0500LE	Replace engine oil breather kit	427754
217	11/29/2010	279768		Grease AC Compressor Clutch Bearing	427754
217	11/29/2010	279768			427754
217	11/29/2010	279768	OIL FILTER 1725+0500LE		427754
217	11/29/2010	279768		A Service & Bus Safety Inspection	427754
217	11/29/2010	279768		Tension Wheel Nuts To OEM Specification	427754
217	11/29/2010	279768		Grease AC Compressor Clutch Bearing	427754
217	11/29/2010	279768		Clean A/C filter	427754
217	11/10/2010	277258	Coolant leak	remove and repair transmission cooler supply pipe refit to bus and billed cooling system	421999
217	11/04/2010	276498	Drv entered - Comm Equip Not Operatating		420094
217	11/04/2010	276498	Drv entered - Comm Equip Other		420094
217	11/03/2010	276383	EL - Back light on GPS n/w	Bus gone to Peninsula	419597
217	10/30/2010	278097		A Service & Bus Safety Inspection	419267
217	10/30/2010	278097		Tension Wheel Nuts To OEM Specification	419267
217	10/30/2010	278097		Grease AC Compressor Clutch Bearing	419267
217	10/30/2010	278097		Clean A/C filter	419267
217	10/28/2010	275163	Direct Purchase - TYRES	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P83827 Receiving #:86005 Date :2010-11-18 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	425276
217	10/28/2010	275163	FITTING	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P83827 Receiving #:86005 Date :2010-11-18 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	425276
217	10/28/2010	275163	BALANCE	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P83827 Receiving #:86005 Date :2010-11-18 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	425276
217	10/28/2010	275163	TRADE IN	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P83827 Receiving #:86005 Date :2010-11-18 SUPPLY FIT AND BALANCE 1 NEW 11.00R 22.5 CLEAN SKIN TYRE.	425276
217	10/25/2010	275320	Service		417172
217	10/25/2010	275320	MIRROR HEAD 1/3 CONVEX R/H		417172
217	10/22/2010	274970	WASHER PUMP	Creditor # :PSS001 PARTS SUPPLY SOLUTIONS P/O # :G83349 Receiving #:85036 Date :2010-10-25	416058
217	10/22/2010	274970	No washers		416058
217	10/22/2010	275163	Replace worn N/S front tyre.		416432
217	10/22/2010	274927	Drv entered - Air Cond Other	Run full comission test. All ok. Road tested for pver 1hr unable to fault	416058
217	10/15/2010	273947	Drv entered - Air Cond Air Conditioner		413405
217	10/15/2010	273947	Drv entered - Air Cond Air Conditioner		413405
217	10/15/2010	273947	Drv entered - Air Cond Air Conditioner		413405
217	10/15/2010	273947	Drv entered - Air Cond Air Conditioner		413405
217	10/12/2010	273484	O/S front top parker out		413035
217	10/01/2010	272023	ROAD SAFETY INSPECTIONS	Creditor # :ROA001 Road Safety Inspections P/O # :P82823 Receiving #:84280 Date :2010-10-05	410806
217	09/30/2010	272023	annual inspection	bc128059	408844
217	09/29/2010	271889	REPAINT REAR OF BUS PANT WHEELS AND TYRES BUFF AND CUT R		408844
217	09/28/2010	271183	11R22.5 SP327 P/C RTD	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P82582 Receiving #:84247 Date :2010-10-04 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	410426
217	09/28/2010	271183	FITTING	Creditor # :BEA002 BEAUREPAIRES FOR TYRES P/O # :P82582 Receiving #:84247 Date :2010-10-04 REPLACE 2 WORN OUT 11.00R 22.5 RECAPS.	410426
217	09/27/2010	271638	LOW AIR BUZZER NOT WORKING.PURGE VALVE AT CYCLONE SEPERA		408844
217	09/23/2010	271183	REPLACE BOTH O/S REAR DRIVE TYRES.		408844
217	09/23/2010	271164	TOP ALT BELT 0500LE	Creditor # :BUR003 BURSON AUTO PARTS P/O # :P82575 Receiving #:83884 Date :2010-09-23 V BELTS 13A1040 FOR TOP ALTINATOR.	408844
217	09/23/2010	271164	Replace top Alt. belt. 13A1040		408844
217	09/23/2010	270844	KIT CENTRIFUGAL FILTER 0500	Creditor # :WHT001 WHITEHORSE TRUCKS P/O # :P82564 Receiving #:83882 Date :2010-09-23 CYCLOPAC REBUILD KIT	408844

217	09/23/2010	271169	Grease AC Compressor Clutch Bearing	408844
217	09/23/2010	271169	Clean A/C filter	408844
217	09/23/2010	271169	Tension Wheel Nuts To OEM Specification	408844
217	09/23/2010	271169	A Service & Bus Safety Inspection	408844
217	09/21/2010	270844	POWER STEER FILTER 810M	408844
217	09/21/2010	270844	AIR DRYER CANISTER VOLVO+ NL202	408844
217	09/21/2010	270844	FUEL FILTER 0500LE	408844
217	09/21/2010	270844	FUEL FILTER MERC 0500LE	408844
217	09/21/2010	270844		408844
217	09/21/2010	270844	Replace power steering filter and check level (Replace oil if required)	408844
217	09/21/2010	270844	Adjust engine valve clearances 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	408844
217	09/21/2010	270844	Test coolant level - top up if required to equate to 37C frost protection	408844
217	09/21/2010	270844	Replace angle drive oil	408844
217	09/21/2010	270844	Replace air dryer canister clean silence and drain reservoir	408844
217	09/21/2010	270844	Replace pre and main fuel filters	408844
217	09/21/2010	270844	Check and clean cartridge in dry tyre air cleaner	408844
217	09/21/2010	270844	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	408844
217	09/21/2010	270844	Check oil level in transmission - top up if required	408844
217	09/21/2010	270844	Inspect radiator and charge air cooler for dirt - clean	408844
217	09/21/2010	270844	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	408844
217	09/21/2010	270844	Replace final drive oil	408844
217	09/21/2010	270844	Creditor #:BUR003 BURSON AUTO PARTS P/O #P82477 Receiving #:83779 Date :2010-09-21 13A1140 V BELTS	408844
217	09/21/2010	270893	Direct Purchase - MECHANICAL	408844
217	09/21/2010	270893	INSPECT BODY FOR REPAIRS FOR R.S.I.	408844
217	09/21/2010	270893	Inspect body for R.S.I.	408844
217	09/21/2010	270844	Drv entered - Gearbox Harsh Thumping [See printed defect f	408844
217	09/21/2010	270844	Drv entered - Other	408844
217	09/21/2010	270844	Drv entered - Other	408844
217	09/21/2010	270844	Drv entered - Elec & Light Cab Light	408844
217	09/21/2010	270844	Drv entered - Elec & Light	408844
217	09/21/2010	270844	Drv entered - Desto Signs [See printed defect for more info	408844
217	09/21/2010	270844	Step LED not working	408844
217	09/21/2010	270844	Drv entered - Desto Signs [See printed defect for more info	408844
217	09/21/2010	270844	DESTO CONTROLLER PANEL BACKLIGHT NOT WORKING	408844
217	09/21/2010	270844	Drv entered - Air System Other	408844
217	09/06/2010	267739	11R22.5 SP327 P/C RTD	406818
217	09/06/2010	267739	FITTING	406818
217	09/02/2010	268247	wiper blade 1000mm	402365
217	09/01/2010	268247	repalace broken rh wiper blade assy	402365
217	09/01/2010	268247	Drivers side wiper blade not contacting screen on top half	401386
217	08/30/2010	266791	FILTER DRIER THERMO KING	401386
217	08/30/2010	266791	COMPRESSOR OIL AIR CON	400704
217	08/28/2010	267739	Drive tyres worn.	400704
217	08/28/2010	267737		400704
217	08/28/2010	267737		400704
217	08/28/2010	267737		400704
217	08/26/2010	267527	change compressor oil	399920
217	08/23/2010	266791	Drv entered - Cool & AC Sys Poor	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner [See printed defect	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner	398740
217	08/23/2010	266791	Drv entered - Air Cond Other [See printed defect for more i	398740
217	08/23/2010	266791	Drv entered - Air Cond Air Conditioner	398740
217	08/23/2010	266791		398740
217	08/23/2010	266791	D Service	398740
217	08/23/2010	266791	Replace filter drier	398740
217	08/23/2010	266791	Check & replace electric motor brushes	398740
217	08/23/2010	266791	Check boost pump condition	398740
217	08/23/2010	266791	Replace compressor oil	398740
217	08/23/2010	266791	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retention belts;	398740
217	08/23/2010	266791	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	398740
217	08/23/2010	266791	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	398740
217	08/23/2010	266791	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	398740
217	08/23/2010	266791	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	398740
217	08/23/2010	266791	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	398740
217	08/23/2010	266791	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	398740
217	08/23/2010	266791	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	398740
217	08/23/2010	266791	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	398740
217	08/23/2010	266791	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	398740
217	08/23/2010	266791	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	398740
217	08/20/2010	266827	Drv entered - Vandalism Graffiti	398367
217	08/20/2010	266827	Drv entered - Vandalism Graffiti	398367
217	08/20/2010	266827	Drv entered - Vandalism Graffiti	398367
217	08/20/2010	266827	Drv entered - Vandalism Damaged Seat	398367
217	08/20/2010	266827	Drv entered - Vandalism Damaged Seat	398367
217	08/20/2010	266829	Drv entered - Vandalism Damaged Seat	398367
217	08/04/2010	264397	1 Battery flat every day. Test and replace batterys as req	392608
217	08/04/2010	264397	BATTERY 12V 190 AMP 1000CCA	392608
217	08/04/2010	264397	BATTERY 200CCA	397595
217	08/02/2010	264080	rwspalace broken n/s window	391261
217	07/29/2010	263621	Drv entered - Suspension Noisy	390839
217	07/29/2010	263621	NOISE IN FRONT END	390839
217	07/29/2010	263621	n/s top parker out	390839
217	07/29/2010	263621		390839
217	07/29/2010	263621	Re-kit Air Cyclone Separator	390839
217	07/29/2010	263621	A Service & Bus Safety Inspection	390839
217	07/29/2010	263621	Tension Wheel Nuts To OEM Specification	390839
217	07/29/2010	263621	Grease AC Compressor Clutch Bearing	390839
217	07/29/2010	263621	Clean A/C filter	390839
217	07/12/2010	261446	Alt belt missing.	386051
217	06/28/2010	259665		381529
217	06/28/2010	259665	D-Service & Bus Safety Inspection	381529
217	06/28/2010	259665	Tension Wheel Nuts to Spec	381529
217	06/28/2010	259665	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	381529
217	06/28/2010	259665	OIL FILTER 1725+0500LE	381529
217	06/28/2010	259665	AIR FILTER MERC 0500LE	381529
217	06/28/2010	259665		381529
217	06/28/2010	259665	Grease AC Compressor Clutch Bearing	381529
217	06/28/2010	259665	Replace engine oil breather kit	381529
217	06/28/2010	259665	Clean A/C filter	381529
217	06/28/2010	259665	A Service & Bus Safety Inspection	381529
217	06/28/2010	259665	Grease AC Compressor Clutch Bearing	381529

217	06/17/2010	258440	A Service & Bus Safety Inspection	377215
217	06/17/2010	258440	Tension Wheel Nuts To OEM Specification	377215
217	06/17/2010	258440	Grease AC Compressor Clutch Bearing	377215
217	06/17/2010	258440	Clean A/C Filter	377215
217	06/07/2010	257226	Drv entered - Elec & Light Altern Light [See printed defect	374492
217	06/03/2010	256877	Drv entered - Elec & Light Desto Light [See printed defect	374056
217	05/28/2010	230741	REAR DOOR BRAKE LOCK	372189
217	05/24/2010	254618	11R22.5 148/145L TL SP350A DUN	372189
217	05/24/2010	254618	FITTING	372189
217	05/24/2010	254618	BALANCE	372189
217	05/24/2010	254618	TRADE-IN CASINGS 11R22.5	372189
217	05/15/2010	254618	Replace worn front tyre.	368529
217	05/15/2010	254393		367809
217	05/15/2010	254393		367809
217	05/15/2010	254393		367809
217	05/04/2010	252610	11R22.5 SP327 P/C RTD	370467
217	05/04/2010	252610	FITTING	370467
217	05/04/2010	251995	11R22.5 148/145L TL SP350A DUN	370467
217	05/04/2010	251995	FITTING	370467
217	05/04/2010	251995	BALANCE	370467
217	05/04/2010	251995	TRADE-IN CASINGS 11R22.5	370467
217	04/30/2010	252610	Replace N/S rear outer flat tyre.	363042
217	04/24/2010	251995	N/S Front Tyre Worn.	360872
217	04/20/2010	251352	Service	359668
217	04/20/2010	251352	replace broken indicator stalk	359668
217	04/20/2010	251352	indicator stalk	365709
217	04/20/2010	251353	drivers entry door hinges worn out	359668
217	04/20/2010	251353	hinges	362717
217	04/19/2010	251145	replace o/s front air bag	359668
217	04/19/2010	251144	replace front and rear brake pads	359668
217	04/19/2010	251144	AIR BAG REAR	359668
217	04/19/2010	251144	DISC PADS SCANIA L94-0500 MERC	362717
217	04/17/2010	251150		359668
217	04/17/2010	251150		359668
217	04/17/2010	251150		359668
217	04/15/2010	250868	Drv entered - Air System Leaking	359075
217	04/15/2010	249787	Service	356294
217	04/13/2010	249440	11R22.5 SP327 P/C RTD	363556
217	04/13/2010	249440	FITTING	363556
217	04/13/2010	250028	11R22.5 SP327 P/C RTD	363556
217	04/13/2010	250028	FITTING	363556
217	04/08/2010	250028	blown rear tyre coolart road and frankston flinders road ba	356986
217	04/08/2010	249787	airdryer assy	359075
217	04/07/2010	249787	RECTIFY AIR LEAK AT AIR DRIER ASSY	356294
217	04/01/2010	249440	Flat N/S Rear Inner tyre at Hastings Depot.	354077
217	03/22/2010	248384	ZF TRANSMISSION FILTER	351391
217	03/22/2010	248384	ZF ECOFLUID A PLUS SYNTHETIC TRANSMISSION OIL	351391
217	03/22/2010	248384	Service T - Replace Transmission Oil & Filter	351391
217	03/22/2010	248384	Grease AC Compressor Clutch Bearing	351391
217	03/22/2010	248384	Tension Wheel Nuts To OEM Specification	351391
217	03/22/2010	248384	A Service & Bus Safety Inspection	351391
217	03/22/2010	248384	Clean A/C Filter	351391
217	03/01/2010	361505	11R22.5 - A GRADE CASE CHG	600393
217	03/01/2010	361505	TYRE RECYCLE	600393
217	03/01/2010	361505	FITTING	600393
217	03/01/2010	361505	SP 11R22.5 SP 927 A GRADE CASE	600393
217	03/01/2010	264080	DRIVERS SIDE	393608
217	02/08/2010	244498	Drv entered - Brakes Other. Intermittant problem causing Aut	317520
217	02/03/2010	243095	Oil leak around oil filter housing	335872
217	02/03/2010	243095		335872
217	02/03/2010	243095		335872
217	02/03/2010	243095	OIL FILTER 1725+0500LE	335872
217	02/03/2010	243095	AIR FILTER MERC 0500LE	335872
217	02/03/2010	243095		335872
217	02/03/2010	243095	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	335872
217	02/03/2010	243095		335872
217	02/03/2010	243095		335872
217	02/03/2010	243095		335872
217	02/03/2010	243095		335872
217	01/28/2010	242462	Drv entered - Body & Acc Other	333633
217	01/28/2010	242462	Drv entered - Body & Acc Other	333633
217	01/12/2010	240189	1100 recaps	331001
217	01/05/2010	240189	REPLACE N/S REAR TYRES	327284
217	01/05/2010	240190	A/C BELT 0500 BENZ	327284
217	01/05/2010	240190	REPLACE ENGINE DRIVE BELT	327284
217	01/05/2010	240139		327284
217	01/05/2010	240139		327284
217	01/05/2010	240139		327284
217	12/23/2009	239343	Drv entered - Elec & Light Interior Lights	323410
217	12/14/2009	238742	HOGKINS ROAD HASTINGS BUS WILL NOT MAKE AIR	320636
217	12/01/2009	237161	CHECK BUS BEFORE PUT INTO USE.	317299
217	11/24/2009	236377	Check coolant leak on top of engine.	317299
217	11/20/2009	235023	POS 3-4 11R225 CAPS	317299
217	11/11/2009	235023	replace worn tyres pos 3-4	317022
217	11/11/2009	235029	MERC ALTERNATOR BELT TOP 0500LE (A39)	317022
217	11/11/2009	235029	change alternator belt	316960
217	11/10/2009	235031	change tyres 3 & 4	316960
217	11/10/2009	235032	steam clean radiator	316960
217	11/10/2009	234913		316960
217	11/10/2009	234913		316960
217	11/10/2009	234913		316960
217	11/10/2009	234913	Service	317022
217	11/10/2009	234913	Service	316960
217	11/06/2009	234565	Add coolant	315570
217	11/05/2009	234078	Door brake holds on	315570

11/02/2009	234078	GLOBE 24V 1.2W SWF SWITCH		315654
217	10/29/2009	234078	Door brake holds on	315654
217	10/29/2009	234078	Door brake holds on	315654
217	10/20/2009	220308	POS 3-4 11R REAR CAP	313103
217	10/20/2009	232975	adjust rear door sensor	313103
217	10/19/2009	232701	Clean A/C filter	312010
217	10/17/2009	232453	Graffiti inside rear on seats and wall	312344
217	10/16/2009	232541	graffiti inside rear on seats and wall	312344
217	10/15/2009	229220	ROAD SAFETY INSPECTIONS	311958
217	10/14/2009	232225	top up coolant	311639
217	10/13/2009	230741	YAD00446821 INSTRUMENT CLUSTE	311393
217	10/13/2009	230741	Check code INS 1432	311393
217	10/13/2009	231861	the following messages came up: INS 1432 RS 3015	311393
217	10/12/2009	230916	Oil leak around oil filter housing	308492
217	10/12/2009	231818	warning codes: INS1432 RS3015	311393
217	10/01/2009	230875	Service	308492
217	10/01/2009	230875	Service	308492
217	10/01/2009	230875	Clean A/C filter	308492
217	10/01/2009	230875	Grease AC Compressor Clutch Bearing	308492
217	10/01/2009	230875	A service completed	308492
217	09/30/2009	230741	Check code INS 1432	308442
217	09/28/2009	230479	Add coolant	307627
217	09/23/2009	230008	Adjust rear doors closing wrong way - rear section closes f	306680
217	09/23/2009	230008	Adjust front doors - top door rubber sticking out when the	306680
217	09/23/2009	230008	Front modresty panel pillar loose on top	306680
217	09/23/2009	230008	Rear door pillar loose on top	306680
217	09/23/2009	230008	Air leak at rear of gear box	306680
217	09/20/2009	229220	Annual inspection	304457
217	09/20/2009	229220	Annual inspection	304457
217	09/17/2009	229483	Warning INS 1432 came on dashboard - amber	305001
217	09/17/2009	229490	Add coolant	305001
217	09/17/2009	228612	G/box cool pipe leaks - small hole	302383
217	09/08/2009	228612	Streamclean engine & bus	301033
217	09/08/2009	228512	Add coolant	302383
217	09/06/2009	228348	INS 1432	301981
217	09/04/2009	228012	24V DRIVERS FAN (USE FASCO ONLY)	301453
217	09/04/2009	228012	Driver fan n/w	301453
217	09/01/2009	227798	AIR LINE FITTING KIT 0500LE AIR DRYER	301033
217	09/01/2009	227798	Air dryer air leak	300835
217	08/31/2009	227774	SINGLE AIR DRYER KIT 0500LE	300835
217	08/31/2009	227774	AIR LINE FITTING KIT 0500LE AIR DRYER	300835
217	08/31/2009	227774	Breakdown - Gladstone Rd - OUT 10.15 pm BACK 11.45 pm - Not	300628
217	08/28/2009	227450	Polish exterior panels/headers & touch up paint work	300031
217	08/28/2009	227450	A/C ducting cracked above rear door - replace	300031
217	08/28/2009	227450	Repair & paint rear b/bar	300031
217	08/28/2009	227450	Repair & paint O/S rear corner	300031
217	08/28/2009	227450	Repair & paint O/S 45678 & 9 panels	300032
217	08/28/2009	227450	Repair & paint O/S 45678 & 9 panels	300031
217	08/27/2009	227325	Clean graffiti	300031
217	08/27/2009	227325	Engine hatch door gas stays need replacing	300031
217	08/27/2009	227325	Remove timetable holder	300031
217	08/27/2009	227325	Replace emergency exit decal - N/S/F	300031
217	08/27/2009	227325	Remove timetable holder	300031
217	08/27/2009	227325	MUD FLAPS GRENDA S MF60X30GRE RED	300031
217	08/27/2009	227325	300N GAS STAY 10-21-247L	300031
217	08/27/2009	227325	SAFETY TRIANGLE DECAL	300031
217	08/27/2009	227325	Secure & adjust front doors	300031
217	08/27/2009	227325	Wheel chair ramp - clean	300031
217	08/27/2009	227325	Replace safety triangle decal - on d/shield new buses	300031
217	08/27/2009	227325	Replace mud flaps - N/S/F O/S/F	300031
217	08/27/2009	227325	Safety triangles and decals - replace	300031
217	08/27/2009	227325	Replace O/S front wheelarch brush	300031
217	08/27/2009	227325	Replace gas stays on lift up panels - rear	300031
217	08/27/2009	227325	Replace emergency exit decal - N/S/F	300031
217	08/27/2009	227325	Paint exterior mirrors and arms	300031
217	08/27/2009	227325	Repair floor - front entry	300031
217	08/27/2009	227325	Replace interior decals - No smoking rear	300031
217	08/27/2009	227325	Clean air condition filter secure vents	300031
217	08/27/2009	227325	Hand rails secure rear modesty panel	300031
217	08/27/2009	227325	Paint till stand	300031
217	08/27/2009	227325	Secure all lower skit panels	300031
217	08/27/2009	227325	Paint wheels	299730
217	08/26/2009	227345	Error code INS 1472	299730
217	08/26/2009	227345	Amber warning light INS 1432	299730
217	08/25/2009	227109		299590
217	08/25/2009	227109	Replace pre and main fuel filters	299590
217	08/25/2009	227109	Test coolant level - top up if required to equate to 37C frost protection	299590
217	08/25/2009	227109	R.S.inspection	299730
217	08/25/2009	227109	Check oil level in transmission - top up if required	299590
217	08/25/2009	227109	Remove disassemble and clean air cyclone seperator (Apply water repellant grease to electrical connection) Check drainage function for leaks	299590
217	08/25/2009	227109	Check and clean cartridge in dry tyre air cleaner	299590
217	08/25/2009	227109	Replace air dryer canister clean silence and drain reservoir	299590
217	08/25/2009	227109		299590
217	08/25/2009	227109	FUEL FILTER MERC 0500LE	299590
217	08/25/2009	227109	FUEL FILTER 0500LE	299590
217	08/25/2009	227109	AIR DRYER CANISTER VOLVO+ NL202	299590
217	08/25/2009	227109	POWER STEER FILTER B10M	299590
217	08/25/2009	227109		299590
217	08/25/2009	227109	Inspect radiator and charge air cooler for dirt - clean	299590
217	08/25/2009	227109	Replace final drive oil	299590
217	08/25/2009	227109	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	299590
217	08/25/2009	227109	Replace power steering filter and check level (Replace oil if required)	299590
217	08/25/2009	227109	Replace angle drive oil	299590
217	08/25/2009	227109	Adjust engine valve clearances 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	299590
217	08/25/2009	227077	Annual body inspection	299590
217	08/25/2009	227211	HALDEX COIL KIT OIL SEPARATOR	299730
217	08/25/2009	227211	BRAKE+ CLUTCH PEDAL PAD 0500LE	299730
217	08/25/2009	227211	WATER SEPARATOR SCANIA+VOLVO	299730
217	08/25/2009	227211	SNAP ON SILENCER A/DRYER	299730
217	08/25/2009	227211	Air leak near g/box dipstick (Checked on 11/06/09 servica	299590
			Repaired air leak on g/box accumulator valve	299590

217	08/25/2009	227035	A Service & Bus Safety Inspection	299356
217	08/25/2009	227035	A Service & Bus Safety Inspection	299730
217	08/25/2009	227035	Clean A/C filter	299356
217	08/25/2009	227035	Grease AC Compressor Clutch Bearing	299356
217	08/25/2009	227035	Tension Wheel Nuts To OEM Specification	299356
217	08/24/2009	227000	Added	299356
217	08/19/2009	226657	Cleaned	298038
217	08/19/2009	226657	Cleaned	298301
217	08/19/2009	226648	MERC ALTERNATOR BELT TOP 0500LE (A39)	298301
217	08/19/2009	226648	Ops Entered - Fault - Elec & Light - Route: - Change over	298038
217	08/19/2009	226648	Breakdown - Nunawading Station - OUT 5.30 pm BACK 7.30 pm -	298038
217	08/18/2009	226526	Check 4way valve	297801
217	08/18/2009	226526	4way valve leaking	297801
217	08/18/2009	226526	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)	298038
217	08/17/2009	226289	Add coolant	297420
217	08/12/2009	225878	Add coolant	296264
217	08/07/2009	225511	Add coolant	294964
217	08/04/2009	223405	POS 1 11R225 NEW	293976
217	07/24/2009	224149	Steamclean engine	291246
217	07/24/2009	224149	Steamclean engine	291039
217	07/24/2009	223943		290743
217	07/24/2009	223943	Air FILTER MERC 0500LE	290743
217	07/24/2009	223943	OIL FILTER 1725-0500LE	290743
217	07/24/2009	223943	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	290743
217	07/24/2009	223943		290743
217	07/24/2009	223943	Tension Wheel Nuts to Spec	290743
217	07/24/2009	223943	A Service & Bus Safety Inspection	290743
217	07/24/2009	223943	D-Service & Bus Safety Inspection	290743
217	07/24/2009	223943	Clean A/C filter	290743
217	07/24/2009	223943	Grease AC Compressor Clutch Bearing	290743
217	07/24/2009	223943	Tension Wheel Nuts To OEM Specification	290743
217	07/24/2009	223943	A Service & Bus Safety Inspection	290743
217	07/20/2009	223405	Replace tyre pos 1 - bald	289271
217	07/20/2009	223492	Replace tyre # 1	290086
217	07/20/2009	223492	Replace tyre # 1	290086
217	07/20/2009	223492	Replace tyre # 1	290086
217	07/19/2009	223475	Add oil	289884
217	07/16/2009	223190	Add coolant	288970
217	07/13/2009	222839	Add coolant	288102
217	06/29/2009	220016	POS 5-6 11R225 REAR CAPS	285450
217	06/25/2009	221318	MIRROR TOP BRAZILLIAN GLASS	285450
217	06/25/2009	221318	Service	285450
217	06/23/2009	220981	Accident damage no 21270 - n/s damage	285450
217	06/16/2009	220308	Replace tyre pos 34 - hole & worn	285272
217	06/15/2009	220253	O/R brake pads 4mm	285450
217	06/15/2009	220253	O/R brake pads 4mm	285272
217	06/15/2009	220253	DISC PADS SCANIA L94+0500 MERC	285272
217	06/12/2009	220016	Replace tyre pos 56 - bald	284755
217	06/11/2009	220022	Change tyre 56	284461
217	06/11/2009	219968	Add coolant	284461
217	06/11/2009	219986		284755
217	06/11/2009	219986	A Service & Bus Safety Inspection	284461
217	06/11/2009	219986	Clean A/C filter	284461
217	06/11/2009	219986	Grease AC Compressor Clutch Bearing	284461
217	06/11/2009	219986	Tension Wheel Nuts To OEM Specification	284461
217	06/11/2009	219986	A Service & Bus Safety Inspection	284461
217	06/04/2009	219394	Accident damage no 19037 - Polish o/s panels 89 and b/bar	283085
217	06/04/2009	219394	Accident Damaged 17602 Polish & touch up front bumper bar.	283085
217	06/04/2009	219394	Accident damage no - 18608 - Replace n/s panels 45 side r	283085
217	06/04/2009	219394	Accident damage no - 21047 - front	283085
217	06/02/2009	219286	Breakdown - Accident - Springvale Rd Forrest Hills - OUT 11	283085
217	05/15/2009	217563	PLASTIC cover on emergency button rear door must be replaced	277957
217	05/15/2009	217563	EMERGENCY EXIT BUTTON PULL COVER	277957
217	05/07/2009	216797	HALOGEN GLOBE 24V20W	275809
217	05/07/2009	216797	Replace downlight over driver	275809
217	05/05/2009	216627	Change O/S/F tyre	275575
217	05/05/2009	216490		275575
217	05/05/2009	216490	A Service & Bus Safety Inspection	275575
217	05/05/2009	216490	Clean A/C filter	275575
217	05/05/2009	216490	Grease AC Compressor Clutch Bearing	275575
217	05/05/2009	216490	Tension Wheel Nuts To OEM Specification	275575
217	05/05/2009	216490	A Service & Bus Safety Inspection	275575
217	05/04/2009	216438	Add coolant	274967
217	05/03/2009	216390	GLOBE HIGH BEAM	274967
217	05/03/2009	216390	Drv entered - Elec & Light Headlights	274794
217	05/03/2009	216390	Burnt out headlight	274794
217	05/03/2009	216390	Interior drivers light	274794
217	05/03/2009	216390	Drv entered - Elec & Light Interior Lights	274794
217	05/03/2009	216390	Drv entered - Elec & Light Headlights	274794
217	04/28/2009	215926	R/R side lens cover broken off	273463
217	04/27/2009	215672	Replace red/amber LED	273260
217	04/27/2009	215672	LED CLEARANCE LIGHT (RED AMBER)	272879
217	04/27/2009	215672	Replace red/amber LED	272879
217	04/23/2009	214457	Air-con blowing hot air	271987
217	04/15/2009	214457	No cool air from air con	269556
217	04/14/2009	214054	POS 1 11R NEW FRONT	269556
217	04/08/2009	214054	Replace tyre pos 1 - side wall worn	268490
217	04/08/2009	214108	Change tyre pos 1	268673
217	04/08/2009	214108	Change tyre pos 1	268977
217	04/08/2009	214108	Change tyre pos 1	268673
217	04/07/2009	213995	Add coolant	268490
217	04/03/2009	213806	Ops Entered - Engine	267380
217	04/03/2009	213806	Ops Entered - Fault - Engine - Route: 889 - Chelsea Heights	267380
217	04/03/2009	213746	Replace R/H/F headlight globe	267380
217	04/03/2009	213634	04/03/2009 213634 Add coolant	267380
217	04/03/2009	213805	MERC ALTERNATOR BELT TOP 0500LE (A39)	267576
217	04/03/2009	213805	Breakdown - Springvale - OUT 8.30 am BACK 9.30 am - Alterna	267380
217	03/30/2009	213045	Random Vehicle Audit	266242
217	03/30/2009	213044		266242
217	03/30/2009	213044	A Service	266242
217	03/30/2009	213044	Grease AC Compressor Clutch Bearing	266242
217	03/30/2009	213044	Clean A/C filter	266242
217	03/30/2009	213044	Tension Wheel Nuts To OEM Specification	266242

217	03/30/2009	213044	A Service	266242
217	03/27/2009	212888	Add	265751
217	03/26/2009	212807	Replaced mirror	265485
217	03/17/2009	211659	Checked OK	263091
217	03/16/2009	210462	Creditor #:BEA001 BEAUREPAIRES P/O #:G64842 Receiving #:66915 Date :2009-03-16	262633
217	03/05/2009	210656	Completed by w/horse	259646
217	03/05/2009	210462	Replaced	259646
217	03/04/2009	210478	Changed	259308
217	03/02/2009	210159		258847
217	03/02/2009	210159	Replaced	258847
217	02/24/2009	209618	A Service	256952
217	02/24/2009	209618	Grease AC Compressor Clutch Bearing	256952
217	02/24/2009	209618	Tension Wheel Nuts To OEM Specification	256952
217	02/18/2009	209034	A Service	255245
217	02/18/2009	209034	C Service	255245
217	02/18/2009	209034	B Service	255245
217	02/18/2009	209034	Replace filter drier	255245
217	02/18/2009	209034	Replace compressor oil	255245
217	02/18/2009	209034	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	255245
217	02/18/2009	209034	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	255245
217	02/18/2009	209034	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	255245
217	02/18/2009	209034	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	255245
217	02/18/2009	209034	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	255245
217	02/18/2009	209034	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	255245
217	02/18/2009	209034	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	255245
217	02/18/2009	209034	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	255245
217	02/18/2009	209034	COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	255245
217	02/18/2009	209034	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	255245
217	02/18/2009	209034	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	255245
217	02/18/2009	209034		255739
217	02/18/2009	209034		255739
217	02/18/2009	209034		255739
217	02/17/2009	209091	Add coolant	255245
217	02/16/2009	209071	Checked by Joe	254931
217	02/13/2009	207650	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G63916 Receiving #:66020 Date :2009-02-13 217	254350
217	02/09/2009	208298	Overhauled oil separator	253190
217	02/09/2009	208305		253190
217	02/09/2009	208305		253190
217	02/09/2009	208305		253190
217	02/09/2009	208305	C/o bus 145. Returned to depot and overhauled oil separator	253190
217	02/09/2009	208305	Add	252093
217	02/05/2009	207968	R/nested checked OK	251423
217	02/03/2009	207650	Drv entered - Whls & Tyres Noisy	251423
217	02/03/2009	207650	heat control knob is broken can not turn it to cold it	251423
217	02/03/2009	207650	Demister/heater knob missing	251423
217	01/31/2009	207034	Replaced	250613
217	01/31/2009	207034	Checked and ordered knob for demister control (ref to w/o # 207650)	250768
217	01/23/2009	206945	Add	248951
217	01/23/2009	206945	Add	248493
217	01/21/2009	206244	Creditor #:BEA001 BEAUREPAIRES P/O #:G63495 Receiving #:65386 Date :2009-01-21	247949
217	01/21/2009	206771	Add	247949
217	01/20/2009	206632		247949
217	01/20/2009	206632	ZF Transmission Filter	247774
217	01/20/2009	206632	Service T - Replace Transmission Oil & Filter	247774
217	01/20/2009	206632	ZF Ecofluid A Plus Synthetic Transmission Oil	247774
217	01/20/2009	206632	Tension Wheel Nuts To OEM Specification	247774
217	01/20/2009	206632	Grease AC Compressor Clutch Bearing	247774
217	01/20/2009	206632	A Service	247774
217	01/15/2009	206244	Replaced	246723
217	01/13/2009	206095	Changed	246220
217	01/13/2009	206006	Checked working OK	246220
217	01/13/2009	206039		246427
217	01/13/2009	206039	Tension Wheel Nuts to Spec	246220
217	01/13/2009	206039		246220
217	01/13/2009	206039	Grease AC Compressor Clutch Bearing	246220
217	01/13/2009	206039	A Service	246220
217	01/13/2009	206039	D-Service	246220
217	01/13/2009	206039		246220
217	01/13/2009	206039	A Service	246220
217	01/13/2009	206039	Tension Wheel Nuts To OEM Specification	246220
217	01/13/2009	206039	Grease AC Compressor Clutch Bearing	246220
217	01/07/2009	205576	Replaced	246220
217	01/07/2009	205576		244452
217	01/05/2009	205228	Add	243381
217	12/20/2008	204339	Replaced mirror	239871
217	12/20/2008	204339		239871
217	12/19/2008	204171	Checked OK	239495
217	12/12/2008	203684	Replaced	237636
217	12/12/2008	203684	LED CLEARANCE LIGHT (RED AMBER)	237636
217	12/12/2008	203684	Replace LED park light	237841
217	12/12/2008	203795	Removed graffiti	237636
217	12/12/2008	203702	A Service	237636
217	12/12/2008	203702	Tension Wheel Nuts To OEM Specification	237636
217	12/12/2008	203702	A Service	237636
217	12/12/2008	203702	Grease AC Compressor Clutch Bearing	237636
217	12/03/2008	202790	Checked OK	235206
217	12/01/2008	200572	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G61583 Receiving #:64046 Date :2008-12-01 217	234618
217	11/28/2008	201557		234287
217	11/20/2008	201557	Creditor #:REB001 CIM CONCEPTS P/O #:G61773 Receiving #:63801 Date :2008-11-20 BUS 217	231981
217	11/19/2008	201557	Replace 2 way radio	231830
217	11/11/2008	200572		230041
217	11/11/2008	200572	Creditor #:ELU001 ELITE WINDSCREENS P/O #:G61681 Receiving #:63450 Date :2008-11-11	230041
217	11/10/2008	177514	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G59752 Receiving #:63423 Date :2008-11-10	229041
217	11/05/2008	200139	Replaced 3way valve seals	229858
217	11/03/2008	200007	Fitted seat belt	229563
217	11/03/2008	200005	C/O bus 146. Found 3way valve near air dryer leaks	229563
217	11/03/2008	200005		229858
217	10/31/2008	182367	Replaced	228970
217	10/31/2008	182205	A Service	228970

217	10/31/2008	182205		Tension Wheel Nuts To OEM Specification	228970
217	10/31/2008	182205	MERC ALTERNATOR BELT TOP 0500LE (A39)		228970
217	10/31/2008	182205		A Service	228970
217	10/21/2008	181251	Replace halogen globe	Replaced	225894
217	10/21/2008	181261	HALOGEN GLOBE 24V20W		225894
217	10/20/2008	181192	Secure battery box	Secured	225584
217	10/15/2008	180661	A/C ducts N/S between front and rear doors come out of roof	Remove ducts secure mount bracket and repair cracked sections off angles	224476
217	10/08/2008	180156	Warning code BS 6241 displayed	Cleaned codes and r/tested	223022
217	09/30/2008	179001	POS 5+6 11R225 REAR CAPS	Creditor #:BEAD01 BEAU REPAIRS P/O #:G60399 Receiving #:62316 Date :2008-09-30	220883
217	09/26/2008	178342	ROAD SAFETY INSPECTIONS	Creditor #:ROAD01 Road Safety Inspections P/O #:G60194 Receiving #:62277 Date :2008-09-26	220196
217	09/26/2008	179255	INDICATOR LAMP SUIT B12BLE		220196
217	09/26/2008	179255	Replace indicator lens	Replaced	220196
217	09/24/2008	179097	Change O/S rear tyre	Changed	219643
217	09/24/2008	179001	Replace tyre pos 56 - bald	Replaced	219643
217	09/24/2008	179097	Remove graffiti on roof & rear seat	Removed	219643
217	09/24/2008	178974		A Service	219871
217	09/24/2008	178974		Tension Wheel Nuts To OEM Specification	219643
217	09/24/2008	178974		A Service	219643
217	09/21/2008	178342	AnnualInspections - BC 114062	Passed	217650
217	09/15/2008	177174		Inspect radiator and charge air cooler for dirt - clean	215886
217	09/15/2008	177174		Replace air dryer canister clean silence and drain reservoir	215886
217	09/15/2008	177766	0014605648 R/H TIE ROD	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G59952 Receiving #:61889 Date :2008-09-15	217216
217	09/15/2008	177766	Passenger address mic bracket to be secured	REP AIR	215886
217	09/12/2008	177561	TINT W/SCREEN	Creditor #:TIN002 TINT FX P/O #:G59915 Receiving #:61846 Date :2008-09-12	216268
217	09/10/2008	177766	O/S/F tie end ball joint worn 2.5 mm	Replaced	215886
217	09/10/2008	177766	Front door sensor n/w	Assisted Nick	216019
217	09/10/2008	177766	Front door sensor n/w	Replaced both	215886
217	09/10/2008	177766	Rear heater tap behind diff leaking coolant	Repaired	215886
217	09/10/2008	177766	SENSITIVE EDGE DOOR SWITCH		215886
217	09/10/2008	177766	GLOBE INDICATOR 24V-18W SINGLE CONTACT		215886
217	09/10/2008	177766	Drv entered - Elec & Light Indicators	Replaced globes	215886
217	09/10/2008	177766	Secure hoses in front panel	Secured	215886
217	09/09/2008	177514	AIR BAG REAR VOLVO+0500LE		215886
217	09/09/2008	177514	A/C BELT 0500 BENZ		215886
217	09/08/2008	177514	N/S rear air bag with small crack	Replaced 3 rear airbags	215886
217	09/08/2008	177514	Steamclean bus	Cleaned	215886
217	09/08/2008	177514	Replace serpentine belt	Replaced & tensioned alt belt	215886
217	09/08/2008	177514	N/S/F front indicator loose connection or broken wire	Repaired	215886
217	09/08/2008	177514	Header tank leaking	Repaired sensor	215886
217	09/06/2008	177561	Tint windcreens & door glasses as req.	Done by Tint FX	215886
217	09/05/2008	177188	Polish & touch up front bumper bar	Touched up	215886
217	09/05/2008	177188	Paint wheels	Painted	215886
217	09/05/2008	177188	Touch up paint work exterior panels above panel 5 body are		215886
217	09/05/2008	177188	Replace wheel arch brush - N/S/F 1 O/S/F 1	Replaced	215886
217	09/05/2008	177067	Clean air condition filter secure vents	Cleaned	215886
217	09/04/2008	177188	Replace wheel arch brush - N/S/F 1 O/S/F 1	Replaced	215886
217	09/04/2008	177188	Touch up paint work exterior panels above panel 5 body are		215886
217	09/04/2008	177188	SAFETY TRIANGLE DECAL	Replaced	215886
217	09/04/2008	177188	Replace safety triangles decal	Replaced	215886
217	09/04/2008	177188	Wheel chair ramp - operation clean & adjust the door	Cleaned & adjusted	215886
217	09/04/2008	177188	Replace seat capsules - O/S 11	Replaced	215886
217	09/04/2008	177188	O/S rear bumper bar to be secured (bolt missing)	Secured	215886
217	09/04/2008	177188	Clean rear doors	Cleaned	215886
217	09/04/2008	177188	Replace Exit Only on rear doors	Replaced	215886
217	09/03/2008	177188	Secure all lower skit panels		215886
217	09/03/2008	177188	Polish exterior panels N/S 3 O/S end above b/bar	Polished	215886
217	09/03/2008	177188	Touch up paint work - N/S 7 O/S 7	Touched up	215886
217	09/03/2008	177188	Replace emergency exit push button under b/bar	Replaced	215886
217	09/03/2008	177188	N/S panel damaged	Repaired	215886
217	09/02/2008	177174		RSI Inspection	215886
217	09/02/2008	177174		RSI Inspection	215886
217	09/02/2008	177174	WATER SEPARATOR SCANIA+VOLVO		215886
217	09/02/2008	177174	WEDGE GLOBE INSTRUMENT 24V 3W		215886
217	09/02/2008	177174		Replace final drive oil	215886
217	09/02/2008	177174		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	215886
217	09/02/2008	177174		Check oil level in transmission - top up if required	215886
217	09/02/2008	177174		Remove disassemble and clean air cyclone seperater (Apply water repellent grease to electrical connection) Check drainage function for leaks	215886
217	09/02/2008	177174		Check and clean cartridge in dry tyre air cleaner	215886
217	09/02/2008	177174		Replace pre and main fuel filters	215886
217	09/02/2008	177174		Replace angle drive oil	215886
217	09/02/2008	177174		Test coolant level - top up if required to equate to 37C frost protection	215886
217	09/02/2008	177174		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST SONM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	215886
217	09/02/2008	177174		Replace power steering filter and check level (Replace oil if required)	215886
217	09/02/2008	177174	FUEL FILTER MERC 0500LE		215886
217	09/02/2008	177174	FUEL FILTER 0500LE		215886
217	09/02/2008	177174	AIR DRYER CANISTER VOLVO+ NL202		215886
217	09/02/2008	177174	POWER STEER FILTER B10M		215886
217	09/02/2008	177067	Paint exterior mirrors and arms	Painted	215886
217	09/02/2008	177067	Replace licensed to carry (No) seat (No) adult passengers	Replaced	215886
217	09/02/2008	177067	Clean graffiti - seats side walls	Cleaned	215886
217	09/02/2008	177067	Fix passenger seat hand grips - O/S 10	Repaired	215886
217	09/02/2008	177067	Hand rails secure	Secured	215886
217	09/02/2008	177067	Touch up door handles - front	Touched up	215886
217	09/02/2008	177067	Paint till stand	Painted	215494
217	09/02/2008	177067	AMBER REFLECTOR SIDE MOUNT		215886
217	09/02/2008	177067	Acc damage repairs to panel Nos 456 N/S to be replaced	Repaired	215886
217	09/01/2008	176990	BUTTERFLY AIR VENT		215886
217	08/31/2008	176990	Heater hose under dash is loose	Replaced heater vent	215494
217	08/31/2008	176990	Handbrake handle is loose	Replaced hand brake lever top cover	215494
217	08/28/2008	176836	F/L hazard light n/w	Checked hazard light and indicator light working OK	214610
217	08/26/2008	176470	ANNUAL BODY CHECK LIST	Completed	213765
217	08/26/2008	175338	LOW COOLANT SENSOR	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G59177 Receiving #:61326 Date :2008-08-26 217	214146
217	08/22/2008	176354	Fit LED	Fitted	212913
217	08/21/2008	176234	Fit LED clearance	Fitted	212536
217	08/13/2008	175338	Amber warning light on dash - FR3130	Checked and found coolant low level senses u.s removed from 231 fitted to bus topped up coolant r/tested	210250
217	08/13/2008	175338	Drv entered - Brakes Noisy	Checked OK	210250
217	08/13/2008	175338	O-RING VIPS FITTING		210462
217	08/13/2008	175338	Found air leak on air tank regulator	Rekit regulator and fitted back	210250
217	08/12/2008	175338	BVWSK13-6 AIR REGULATOR VALVE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G59132 Receiving #:61015 Date :2008-08-12	210250

217	08/11/2008	175338	Amber warning light on dash - FR3130	Removed and checked air filter sender & coolant low level sender wires	210250
217	08/11/2008	175338	Found air leak on air tank regulator	Ordered parts	210250
217	08/11/2008	175248		Tension Wheel Nuts to OEM Specification	210250
217	08/11/2008	175248		A Service	210250
217	08/11/2008	175248		A Service	210250
217	08/06/2008	174626	Oil light orange 4.01 displayed	Repaired by merc benz	209089
217	08/06/2008	174895	Replace alternator belt	Replaced	209089
217	08/06/2008	174895	Replace alternator belt	Replaced	209089
217	08/04/2008	174626	Drv entered - Vandalism Damaged Seat		208442
217	08/04/2008	174626	Oil light orange 4.01 displayed	R/test to find fault code find the problem but need repair by benz	208442
217	08/04/2008	174626	Back of seat ripped off - 3rd from back	Refitted passenger seat	208442
217	08/01/2008	174598	Check oil level	Checked OK	207880
217	07/31/2008	172546	BALD	Creditor #:BEA001 BEAUREPAIRES P/O #:G58289 Receiving #:60748 Date :2008-07-31 Fit rear cap - 11.00	207880
217	07/11/2008	172889	Check oil levels	R/test drain oil and top up for oil level	201917
217	07/10/2008	172833	Check warning light	R/tested no warning light come up	201730
217	07/09/2008	172546	Replace tyre pos 5 - bald	Replaced	201188
217	07/08/2008	172551	Replace O/S rear inner tyre	Replaced	201188
217	07/08/2008	172471	AIR FILTER MERC 0500LE		200868
217	07/08/2008	172471	OIL FILTER 1725+0500LE		200868
217	07/08/2008	172471	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		200868
217	07/08/2008	172471		Tension Wheel Nuts to Spec	200868
217	07/08/2008	172471		A Service	200868
217	07/08/2008	172471		D-Service	200868
217	07/08/2008	172471		Tension Wheel Nuts to OEM Specification	200868
217	07/08/2008	172471		A Service	200868
217	07/01/2008	170279	POS 1+3+4	Creditor #:BEA001 BEAUREPAIRES P/O #:G57145 Receiving #:50846 Date :2008-07-01	199469
217	06/29/2008	171819	Disabled passenger seat broken	Repaired	198478
217	06/27/2008	171709	Loose panels on ceiling of the back of the bus creates lots	checked o/k.	198011
217	06/24/2008	171375	Replace headlight globe	Replaced	197026
217	06/24/2008	171375	GLOBE HIGH BEAM		197026
217	06/18/2008	170954	Breakdown - Glen Waverley Station - OUT 10.15 pm BACK 11.15	C/O bus 203. Topped up oil and returned to depot	195324
217	06/17/2008	170839	Fit control unit to bus	Fitted	195082
217	06/17/2008	170780	LED CLEARANCE LIGHT (RED AMBER)		195324
217	06/17/2008	170780	Replace LED clearance lamp	Replaced	195324
217	06/17/2008	170780	Replace side light	Replaced	195082
217	06/11/2008	170279	Replace tyres pos. 1 & 3 & 4 - worn & bald	rep. tyres pos.1 3 &4 worn & bald.	193433
217	06/11/2008	170334	Change N/S/F tyre & N/S/R	Changed & cleaned rim	193433
217	06/11/2008	170256		A Service	193102
217	06/11/2008	170256		Tension Wheel Nuts to OEM Specification	193102
217	06/11/2008	170256		A Service	193102
217	06/05/2008	169962	Able to drive bus with front doors open safety issue	Volgren programmed like is OK	191654
217	06/05/2008	169962	Sunblind flapping around	Secured blind	191654
217	06/04/2008	150577	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G49597 Receiving #:50087 Date :2008-06-04 Turbo pumping oil	191352
217	06/04/2008	136246	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G41261 Receiving #:50108 Date :2008-06-04 Fault code comes - BS 5506	191352
217	05/29/2008	168453	Replace emergency exit globe	Replaced	189884
217	05/29/2008	168453	Replace emergency exit globe		189884
217	05/29/2008	168453	GLOBE FESTOON 24V-3W		189884
217	05/21/2008	168453	N/S headlight out	Replaced	187383
217	05/21/2008	168453	GLOBE HIGH BEAM		187937
217	05/21/2008	168685	GLOBE HIGH BEAM		187937
217	05/21/2008	168685	Replace head light globe	Replaced	187383
217	05/21/2008	168454	Check fuel tank sender & remove foreign body from tank.	Checked fuel sender changed hose positions removed hose from tank	187383
217	05/21/2008	168454	Check fuel tank sender & remove foreign body from tank.	Pulled fuel sender out removed hose in tank fit hoses back on the right way	187383
217	05/21/2008	168453	Front door brake not working		187383
217	05/20/2008	168546	Breakdown - Glen Waverley Station - OUT 12.30 am BACK 2.30	Took van 619. Bled system and fuelled	187383
217	05/08/2008	166178	DIP STICK MERCEDES 0500LE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G54919 Receiving #:49298 Date :2008-05-08	184248
217	05/08/2008	167583	MERC ALTERNATOR BELT TOP 0500LE		184512
217	05/08/2008	167583	Fan belt	Put new top alternator belt	184248
217	05/07/2008	167412	GLOBE S/CONTACT 24V-10W		183980
217	05/07/2008	167412		Tension Wheel Nuts to OEM Specification	183980
217	05/07/2008	167412		A Service	183980
217	05/05/2008	167169	Front door motion sensor not closing door when moving off	Checked out door brake unable to fix	183430
217	04/24/2008	166331	Service		180607
217	04/24/2008	166331	GLOBE S/CONTACT 24V-10W		180607
217	04/24/2008	166331	Replace interior light	Replaced by Abdul	180607
217	04/23/2008	166178	Fit new engine oil dipstick	Fitted	180352
217	04/17/2008	165573	Replace lower alternator pulley and belt to suit 6PK	Replaced by Whitehorse	179167
217	04/17/2008	165747	Drivers cabin light is out	Replaced globe	179446
217	04/07/2008	160598	POS 6+5	Creditor #:BEA001 BEAUREPAIRES P/O #:G52920 Receiving #:48362 Date :2008-04-07 CAPS	176530
217	04/02/2008	162848	POS 6	Creditor #:BEA001 BEAUREPAIRES P/O #:G53734 Receiving #:48315 Date :2008-04-02 CAPS	175318
217	04/02/2008	164466	Breakdown - Springvale Rd. bus ran out of fuel Left at 11.0	Took van 619 & topped up fuel on site followed driver back to depot.	174958
217	04/01/2008	164220	Annual random vehicle audit	Completed	174713
217	04/01/2008	164221		Tension Wheel Nuts to OEM Specification	174713
217	04/01/2008	164221	Service	A Service	174713
217	03/29/2008	164129	Breakdown - Officer - OUT 8.00 pm BACK 9.30 pm - Ran out of	Used breakdown van 619.	173749
217	03/19/2008	163569	Breakdown - Glen Waverley Shopping Centre - OUT 12.30 am BA	Used car 1. Filled with diesel bled system and returned to depot	170241
217	03/14/2008	163157	Service	Assisted greg rep. belts & battery	169765
217	03/14/2008	163157	BATTERY 12V 190 AMP 1000CCA	Creditor #AANH001 ANV POWER BATTERIES P/O #:G53836 Receiving #:47812 Date :2008-03-14 217 MERC	169765
217	03/14/2008	163157	Replace batteries.	Changed batteries and alt belts	169765
217	03/14/2008	163214	Breakdown - Noble Park - OUT 6.30 am BACK 8.30 am - No gears	C/O bus 148. No gears no start & found battery had collapsed	169765
217	03/13/2008	163197	Breakdown - Springvale & Hutton Rds - OUT 5.00 pm BACK 7.00	Took out jumpstart	169765
217	03/13/2008	163197	Breakdown - Springvale & Hutton Rds - OUT 5.00 pm BACK 7.00	C/O bus 218. Had to wait for jumpstarter	169523
217	03/11/2008	162924	Replace O/S/R outer tyre	Replaced	168995
217	03/11/2008	162924	Replace O/S/R outer tyre	Replaced	168995
217	03/11/2008	162848	Rep. tyres pos. 6 - Flat	rep. tyre pos. 5 & 6	168995
217	03/05/2008	160594	Breakdown - Glen Waverley - OUT 12.00 BACK 2.00 am - Ran o	Used TQD 750. Topped up diesel bled & bought back to workshop	167297
217	02/26/2008	160710	Indicator arm loose	Retentioned flasher switch	163804
217	02/22/2008	161635	LOWER ALT BELT 0500 BENZ		164073
217	02/22/2008	161635		B Service	163804
217	02/22/2008	161635		Replace filter drier	163804
217	02/22/2008	161635		Replace compressor oil	163804
217	02/22/2008	161635	FILTER DRIER THERMO KING		164073
217	02/22/2008	161635	Serviced as per list. Repaired leak at pressure relief valve	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	163804
217	02/22/2008	161635		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	163804
217	02/22/2008	161635		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	163804
217	02/22/2008	161635		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	163804
217	02/22/2008	161635		REFRIGERATION FILTER DRIER: Replace filter dryer; check pump operation;	163804
217	02/22/2008	161635		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	163804

217	02/22/2008	161635	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	163804
217	02/22/2008	161635	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	163804
217	02/22/2008	161635	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	163804
217	02/22/2008	161635	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	163804
217	02/22/2008	161635	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	163804
217	02/21/2008	160710	Replaced belt	163804
217	02/18/2008	158187	Creditor #:BEA001 BEAUREPAIRES P/O #:G52038 Receiving #:47223 Date :2008-02-18	163804
217	02/11/2008	160633	Repaired by Whitehorse	163804
217	02/08/2008	160598	rep. tyre pos 5 & 6	163804
217	02/07/2008	160634	Changed	163804
217	02/07/2008	160634	Changed	163804
217	02/07/2008	160633	R/tested brakes still grabbing	163804
217	02/07/2008	160562	A Service	163804
217	02/07/2008	160562	Tension Wheel Nuts To OEM Specification	163804
217	02/07/2008	160562	A Service	163804
217	02/04/2008	160237	Adjusted belts	163043
217	01/11/2008	158477		155948
217	01/11/2008	158477	MERC ALTERNATOR BELT TOP 0500LE	155948
217	01/11/2008	158477	Breakdown - Glen Waverley Station - OUT 9.30 am BACK 11.30	155621
217	01/09/2008	158187	rep. tyre pos.3 & 4 bald	155363
217	01/09/2008	158211	Replaced	155363
217	01/09/2008	158211	Missing bolt from exhaust manifold shield	155363
217	01/09/2008	158211	Cleaned	155363
217	01/08/2008	157148	Creditor #:BEA001 BEAUREPAIRES P/O #:G51734 Receiving #:46117 Date :2008-01-08 POS 2	155238
217	01/08/2008	158204	Replaced	155238
217	01/08/2008	158204	Replaced	155238
217	01/08/2008	158141	Replaced	155238
217	01/08/2008	158141	AIR FILTER MERC 0500LE	155238
217	01/08/2008	158141	OIL FILTER 1725+0500LE	155238
217	01/08/2008	158141	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	155238
217	01/08/2008	158141	Tension Wheel Nuts To Spec	155238
217	01/08/2008	158141	A Service	155238
217	01/08/2008	158141	D-Service	155238
217	01/08/2008	158141	Tension Wheel Nuts To OEM Specification	155238
217	01/08/2008	158141	A Service	155238
217	01/07/2008	157962		154926
217	01/07/2008	157962	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz	154926
217	01/07/2008	157962	COMPRESSOR BELT MERC1418 12.5X1038MM	154721
217	12/29/2007	157436	rep. both alternator belts	154721
217	12/24/2007	157185	Top up oil too low on dip stick	152485
217	12/24/2007	157185	Replaced	151086
217	12/24/2007	157185	Replaced	151086
217	12/22/2007	157148	Rep. tyre pos. 2 - Bald	150817
217	12/19/2007	156840	Checked no fault found	150095
217	12/19/2007	156840	Repaired	150025
217	12/15/2007	156578	bled fuel system & cleaned up graffiti	149374
217	12/11/2007	156119	Replace windscreen washer motor	148179
217	12/11/2007	156119	Checked ok	148179
217	12/11/2007	155654	checked for codes & r/tested all o/k.	148179
217	12/07/2007	155973	Adjusted	147218
217	12/06/2007	155655	Changed	146880
217	12/06/2007	155906	Passenger Doors Require Adjusted	146880
217	12/06/2007	155906	Change interior tube	147218
217	12/06/2007	155906	HALOGEN GLOBE 24V20W	146321
217	12/05/2007	155655	Inspected	146321
217	12/05/2007	155655	Inspect for driveline warranty - Due on 3/12/07	146321
217	12/05/2007	155654	ZF Transmission Filter	146321
217	12/05/2007	155654	ZF Ecofluid A Plus Synthetic Transmission Oil	146321
217	12/05/2007	155654	Service T - Replace Transmission Oil & Filter	146321
217	12/05/2007	155654	Tension Wheel Nuts To OEM Specification	146321
217	12/05/2007	155654	A Service	146321
217	11/21/2007	154644	Replaced wiper blades	143220
217	11/21/2007	154644	Breakdown - Sandown Park - OUT 6.00 am BACK 6.30 am - Wiper	143220
217	11/21/2007	154644	WIPER REFILL SUIT TX800+TX900	143220
217	11/21/2007	154644	Breakdown - Sandown Park - OUT 6.00 am BACK 6.30 am - Wiper	142580
217	11/19/2007	154712	Tightened nut on top of door repositioned and put on lock nut. Door works with no sensitive edge on one side	141785
217	11/15/2007	152635	Replaced horn put cover on retarder switch	141656
217	11/15/2007	152635	Fitted	141656
217	11/15/2007	152635	Replaced horn	136320
217	11/15/2007	152635	Fixed top of handbrake knob	140330
217	11/10/2007	153804	Replace globe	138702
217	11/05/2007	152109	Creditor #:AS0001 ASSOCIATED TOWING P/O #:G50056 Receiving #:44782 Date :2007-11-05 Tow bus from Brandon Park to depot	138080
217	11/02/2007	153264	rep. hinge section & repaired panels	138080
217	11/02/2007	153216	A Service	138080
217	11/02/2007	153216	Tension Wheel Nuts To OEM Specification	138080
217	11/02/2007	153216	A Service	138080
217	10/25/2007	152635	seat working OK	136320
217	10/25/2007	152635	Ordered parts	136320
217	10/22/2007	152209	Creditor #:XN001 KNIGHTS WINDSCREEN REPAIRS P/O #:G50083 Receiving #:44396 Date :2007-10-22	135266
217	10/20/2007	152209	Repair windscreen chip	134594
217	10/19/2007	152145	Fuel and bleed system	134594
217	10/19/2007	152109	Towed to depot	134594
217	10/19/2007	150052	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G49451 Receiving #:44357 Date :2007-10-19	134594
217	10/18/2007	152045	COMPRESSOR BELT MERC1418 12.5X1038MM	134594
217	10/18/2007	152045	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz	134594
217	10/17/2007	152045	Rep. both alternator belts.	134556
217	10/08/2007	151177	Cleaned	131874
217	10/04/2007	149705	Creditor #:ROAD01 Road Safety Inspections P/O #:G49332 Receiving #:44046 Date :2007-10-04	130366
217	10/04/2007	150052	REPLACE WINDSCREEN REAR	130366
217	09/29/2007	150577	Turbo has oil in inlet pipe	129539
217	09/23/2007	149705	Annual Inspection - BC 111661	129075
217	09/22/2007	150092	Secure hose clamp	129075
217	09/21/2007	149957	Park	129075
217	09/21/2007	149957	Replace gear box oil and filter	129075
217	09/21/2007	149957	FILTER TRANSMISSION ZF 4139-298-038	129075
217	09/21/2007	149957	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	129075
217	09/21/2007	149957	Replace gear box oil and filter	129075
217	09/21/2007	150052	Accident damage - Broken rear window	129075
217	09/21/2007	150052	Accident damage - Broken rear window	129075
217	09/20/2007	149790	Paint wheels	129075
217	09/20/2007	149790	Polish front bumper bar	129075
217	09/20/2007	149790	Polish exterior panels/headers & touch up paint work	129075
217	09/20/2007	149790	Paint wheels	129075
217	09/20/2007	149790	Polish front bumper bar	129075
217	09/20/2007	149790	Repair & paint rear bumper bar	129075

217	09/20/2007	149790	Replace emergency exit decal - rear window	Replaced	129075
217	09/20/2007	149790	Replace front and door seals	N/A	129075
217	09/20/2007	149790	Secure replace paint arms		129075
217	09/20/2007	149790	Replace Licence to carry (No) adult passengers	Replaced	129075
217	09/20/2007	149790	Hand rails secure rivet - rear modesty panel post	Secured	129075
217	09/20/2007	149790	Replace N/S 4-5-6 panels	Repaired & polished	129075
217	09/20/2007	149790	Repair & paint 5-6-7 panels	Repaired & polished	129075
217	09/20/2007	149790	Replace & paint O/S No 4 panel & decals	Repaired & polished	129075
217	09/19/2007	149790	Replace mud flaps - O/S/r	Replaced	129075
217	09/19/2007	149790	MUD FLAPS GRENADAS MF50X30GRE RED		129075
217	09/19/2007	149790	O/S/R mudflap missing		129075
217	09/19/2007	149790	Wheel chair ramp - clean	Cleaned	129075
217	09/19/2007	149790	O/S/R mudflap missing	Replaced	129075
217	09/19/2007	149790	Clean air condition filter secure vents	Cleaned	129075
217	09/19/2007	149790	Clean graffiti - seats	Cleaned	129075
217	09/18/2007	149707	Paint til stand	Painted	129075
217	09/18/2007	149707	Secure all lower skit panels	Secured	129075
217	09/18/2007	149707	Polish N/S 4-5-6 panels	Polished	129075
217	09/17/2007	149625		A Service	129013
217	09/17/2007	149625		Tension Wheel Nuts To OEM Specification	129013
217	09/17/2007	149625		A Service	129013
217	09/05/2007	148673	Steam clean for inspection	Cleaned	125560
217	09/04/2007	148567	Secure A/C lines above power steering reservoir	Secured	125560
217	09/04/2007	148567	Adjust alt belts	Adjusted	125279
217	09/04/2007	148567	CLEAR FRONT INDICATOR WRAP-AROUND		125560
217	09/04/2007	148567	Lens cracked N/S/F lower	Replaced	125560
217	09/04/2007	148567	Clean reverse lenses	Cleaned	125560
217	09/04/2007	148567	Secure header tank overflow line	Secured	125560
217	09/04/2007	148567	DISC PADS SCANIA USA-0500 MERC		125560
217	09/04/2007	148567	O/S/R brakes not braking evenly between pads inner pad 11mm	Replaced front & rear pads	125560
217	09/04/2007	148567	Secure air lines above O/S/R air bag		125560
217	09/04/2007	148567	Air hose rubbing against air tank from air dryer	Secured	125560
217	09/01/2007	148486	Drv entered - Whls & Tyres Noisy	R/TESTED O/K	125080
217	08/29/2007	148203	Service	Change air dryer cannister	124407
217	08/29/2007	148203	Service	Change diff oil	124407
217	08/29/2007	148203	Service	Change power steering filter	124407
217	08/29/2007	148203	Service	Change fuel water separator	124407
217	08/29/2007	148203	Service	Change fuel filter	124407
217	08/29/2007	148203	FUEL FILTER MERC 0500LE		123830
217	08/29/2007	148203	FUEL FILTER 0500LE		123830
217	08/29/2007	148203	AIR DRYER CANISTER MAN NL202+VOLVO		123830
217	08/29/2007	148203	POWER STEER FILTER B10M		123830
217	08/29/2007	148203	Service	Inspection of bus	124407
217	08/29/2007	148214	Annual body check	Completed	123830
217	08/19/2007	147314	Riding up & down not riding smoothly	Checked is riding on road test o/k.	121994
217	08/15/2007	146378	POS 5	Creditor #:BEA001 BEAUREPAIRES P/O #:G47572 Receiving #:42846 Date :2007-08-15	120923
217	08/08/2007	146378	TYRE BALD POS 5	Replaced o/s/r tyres	119393
217	08/08/2007	146378	Service	Replaced o/s/r tyres	119618
217	08/08/2007	146369		Tension Wheel Nuts To OEM Specification	119393
217	08/08/2007	146369		A Service	119393
217	07/18/2007	144243	POS 5	Creditor #:BEA001 BEAUREPAIRES P/O #:G46421 Receiving #:42135 Date :2007-07-18	112577
217	07/16/2007	144586	LED CLEARANCE LIGHT (RED AMBER)		112243
217	07/16/2007	144586	Replace globe	Replaced	111851
217	07/14/2007	144457	N/S, clearance light out	R/E.P. CLEARANCE LIGHT	111373
217	07/12/2007	144243	Replaced tyre pos. 5 - bald.	Replaced	110749
217	07/10/2007	144087	Change tyres N/S/R	Replaced	110241
217	07/10/2007	144087	Change tyres N/S/R	Replaced	110241
217	07/10/2007	144087	N/S/R brake caliper is braking unevenly	Needs to be bought back soon 5mm left	110241
217	07/10/2007	144045	AIR FILTER MERC 0500LE		110241
217	07/10/2007	144045	OIL FILTER 1725+0500LE		110241
217	07/10/2007	144045	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		110241
217	07/10/2007	144045		Tension Wheel Nuts to Spec	110241
217	07/10/2007	144045		A Service	110241
217	07/10/2007	144045		D-Service	110241
217	07/10/2007	144045		Tension Wheel Nuts To OEM Specification	110241
217	07/10/2007	144045		A Service	110241
217	06/20/2007	142579	GLOBE HIGH BEAM		104288
217	06/20/2007	142579	Near side head light out	Replaced globe	104288
217	06/08/2007	141777	Service	REMOVED WHEELS CHECK FOR DISC PADS.	100240
217	06/08/2007	141777	Service	A SERVICE	100240
217	06/08/2007	141777		Tension Wheel Nuts To OEM Specification	100240
217	06/08/2007	141777		A Service	100240
217	06/07/2007	141748	LED CLEARANCE LIGHT (RED AMBER)		100240
217	06/07/2007	141748	GLOBE HIGH BEAM		100240
217	06/07/2007	141748	Fit N/S rear clearance lamp	Fitted	99957
217	06/07/2007	141748	Fit O/S front H/lamp globe	Fitted	99957
217	05/24/2007	140544	Breakdown - Springvale Junction - OUT 1.00 am BACK 2.15 am	Took breakdown van. Fuelled and bled the system	95761
217	05/17/2007	140017	Service		94353
217	05/17/2007	140017	MIRROR TOP BRAZILLIAN GLASS		94353
217	05/17/2007	140135	Sunvisor support arm front left bottom has come adrift	Replaced missing screws	93884
217	05/16/2007	139569		Assisted Greg	93884
217	05/16/2007	139569	Fault code B5 5506 comes on dash	Checked out brake code road tested working OK	93807
217	05/10/2007	139569	Fault code B5 5506 comes on dash		93807
217	04/30/2007	136246	Fault - B5 5506	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G43029 Receiving #:40250 Date :2007-04-30 Merc to pay 50%	91274
217	04/30/2007	138718	Drv entered - Vandalism Graffiti	Checked OK	91274
217	04/30/2007	138718	Drv entered - Elec & Light Indicators	Checked OK	91274
217	04/30/2007	138627		Tension Wheel Nuts To OEM Specification	91274
217	04/30/2007	138627		A Service	91274
217	04/23/2007	138194	BRAZILLIAN MIRROR RH		89918
217	04/23/2007	138194	Replace O/S mirror	Replaced	89632
217	03/27/2007	136246	Fault code comes up - B5 5506	Repaired by Whitehorse	84065
217	03/22/2007	136001	Breakdown - Cnr Springvale & Wellington Rds - OUT 11.50 pm	Took van 203. Put in 50 ltr bled & returned fuelled bus & jerry cans	82477
217	03/21/2007	135735	Annual random audit	Completed	82088
217	03/21/2007	135736	Drv entered - Comm Equip Net Operatng	Checked 2way radio working OK	82088
217	03/21/2007	135734		A Service	82088
217	03/21/2007	135734	AIR FILTER MERC 0500LE		82267
217	03/21/2007	135734		Tension Wheel Nuts To OEM Specification	82088
217	03/21/2007	135734		A Service	82088
217	03/20/2007	135701	WEDGE GLOBE INSTRUMENT 24V 3W		82088

217	03/20/2007	135701	GLOBE INDICATOR 24V21W SINGLE CONTACT			82088
217	03/20/2007	135701	Indicator L/H U.S	Replaced N/S/F indicator lens and globe		82088
217	03/16/2007	135438		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		81219
217	03/16/2007	135438	AIR CON REFRIDGERANT			81355
217	03/16/2007	135438	FILTER DRIER THERMO KING			81355
217	03/16/2007	135438	Service	reset air gap on clutch to stop 67b revision		81219
217	03/16/2007	135438		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		81219
217	03/16/2007	135438		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension		81219
217	03/16/2007	135438		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		81219
217	03/16/2007	135438		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray		81219
217	03/16/2007	135438		REFRIGERATION FILTER DRIER: Replace filter dryer; check pump operation;		81219
217	03/16/2007	135438		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		81219
217	03/16/2007	135438		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		81219
217	03/16/2007	135438		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		81219
217	03/16/2007	135438		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		81219
217	03/16/2007	135438		Clean R/A & F/A filters; inspect and report on condition; Replace filter media		81219
217	03/13/2007	135050	Replace top alternator bolts x3 realign belt and tension	Replaced		79993
217	02/27/2007	132759	POS 3+4+5+6	Creditor #:BEA001 BEAUREPARES P/O #:G39175 Receiving #:38591 Date :2007-02-27		76881
217	02/21/2007	133559	Drv entered - Elec & Light Park Lights	Replaced lamp		75152
217	02/21/2007	133559	LED CLEARANCE LIGHT (RED AMBER)			75152
217	02/18/2007	133339	Air con not working	Checked and cleaned return air filter - Blocked		74569
217	02/17/2007	133276	Alternator belts slipping	Adjust belts		74070
217	02/12/2007	132759	TYRES POS 3456 BALD	Replaced		73391
217	02/09/2007	132694	Replace rear tyres	Replace tyres		72825
217	02/09/2007	132627		A Service		72825
217	02/09/2007	132627		A Service		72825
217	02/09/2007	132627		Tension Wheel Nuts To OEM Specification		72825
217	01/25/2007	131610	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz			69580
217	01/25/2007	131610	Fan belts has come off pulley	Replace alternator belt		69352
217	01/16/2007	129901	POS 1	Creditor #:BEA001 BEAUREPARES P/O #:37527 Receiving #:37753 Date :2007-01-16		66642
217	01/11/2007	130563	Check brake pedal and belts	Checked		65623
217	01/08/2007	130286	Remove graffiti off of rear seats	Removed		64803
217	01/08/2007	130158		D-Service		64130
217	01/08/2007	130158		A Service		64130
217	01/08/2007	130158		Tension Wheel Nuts to Spec		64130
217	01/08/2007	130158	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL			64130
217	01/08/2007	130158	OIL FILTER 1725+0500LE			64130
217	01/08/2007	130158	CLEANED AIR FILTER MERC 0500LE			64803
217	01/08/2007	130158		A Service		64130
217	01/03/2007	129901	REPLACED TYRE POS. 1 FLAT.	Replaced		63685
217	01/03/2007	129920	Drv entered - Vandalism Graffiti			63685
217	01/03/2007	129920	Drv entered - Vandalism Graffiti	Cleaned		63685
217	01/03/2007	129920	Coolant door missing door latch	Replaced		63685
217	01/03/2007	129920	MUD FLAPS GRENDAS MF60X30GRE RED			63685
217	01/03/2007	129920	Need to replace O/S/R mud flap	Replaced		63685
217	01/02/2007	129841	Flat tyre	Assisted Daniel with flat tyre		63514
217	01/02/2007	129841	Flat tyre			63514
217	01/02/2007	129860	Breakdown - Dandenong Frankston Rd - OUT 10.45am BACK 11.45	C/O bus 29 changed tyre and returned to depot		63514
217	01/02/2007	129860	Breakdown - Dandenong Frankston Rd - OUT 10.45am BACK 11.45	C/O bus 29 changed tyre and returned to depot		63514
217	12/12/2006	128697	Bus stopping light on dash staying on when doors shut	Checked OK		58931
217	12/04/2006	127882	Belt off on alternator	Replaced lower belt		56681
217	12/04/2006	127882	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz			57237
217	11/29/2006	127562	HALOGEN GLOBE 24V20W			56407
217	11/29/2006	127562	Drv entered - Elec & Light Interior Lights	Replaced globe		56317
217	11/29/2006	127562	Drv entered - Passenger Doors Not Operating	Checked OK		56317
217	11/29/2006	127561		A Service		56317
217	11/29/2006	127561		Tension Wheel Nuts To OEM Specification		56317
217	11/29/2006	127561		A Service		56317
217	11/27/2006	127310	Adjust both alternator belts	Adjusted		55852
217	11/03/2006	125549	COMPRESSOR BELT MERC1418 12.5X1038MM			50357
217	11/03/2006	125549	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz			50357
217	11/03/2006	125549	Service	REPLACED LOWER ALTERNATOR BELT		50357
217	11/03/2006	125549	Bottom alternator hits on chassis fan edge wearing	Checked ok. Assist to change belts. Road tested		50357
217	10/25/2006	124716	Disarm front door interlock	Repaired by Volgren		48504
217	10/25/2006	124451	Direct Purchase - BODYWORK	Creditor #:ELI001 ELITE WINDSCREENS P/O #:35771 Receiving #:35791 Date :2006-10-25 Replace rear window		48504
217	10/25/2006	124715	DO NOT OVERTAKE TURNING DECAL			48504
217	10/25/2006	124715	GIVE WAY SIGN (SMALL)			48504
217	10/25/2006	124715	Accident damage - Replace decals on rear window	Replaced		48504
217	10/23/2006	124451	Replace rear window glass	Replaced by Elite		47885
217	10/13/2006	123801	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter		46580
217	10/13/2006	123801	TEXAMATIC 1888	Transmission Oil		46580
217	10/13/2006	123801		Service trans oil NOT replaced		46580
217	10/13/2006	123801		Tension Wheel Nuts To OEM Specification		46580
217	10/13/2006	123801		A Service		46580
217	10/10/2006	123615	Replace lower alt belt	Replaced		45766
217	10/02/2006	122141	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:34998 Receiving #:35210 Date :2006-10-02		43834
217	09/24/2006	122141	Annual Inspection - BC 100861	Annual Inspection - BC 100861		43013
217	09/22/2006	122349	Replace bus stop light globe	Replaced		43217
217	09/21/2006	122206	GLOBE S/CONTACT 24V-10W			43217
217	09/21/2006	122206	Paint wheels	Painted		43213
217	09/21/2006	122206	Replace mud flaps - O/S/R	Replaced		43213
217	09/21/2006	122206	Polish and touch up exterior panels / headers	Polished		43213
217	09/21/2006	122206	Polish N/S 4-5 + 6 panels	Polished		43013
217	09/21/2006	122206	Polish O/S No 6-7 panels	Polished		43213
217	09/21/2006	122206	Polish rear engine door - graffiti	Polished		43213
217	09/21/2006	122206	Paint till stand	Painted		43213
217	09/21/2006	122206	Clean air condition filter secure vents	Cleaned		43213
217	09/21/2006	122206	Replace interior decals	Replaced		43213
217	09/21/2006	122206	Clean graffiti- seats and side walls	Cleaned		43213
217	09/21/2006	122206	Clean back seat - rubbish	Cleaned		43213
217	09/21/2006	122206	Replace Licence to carry (No) seat (No) Adult passengers	Replaced		43213
217	09/21/2006	122206	Replace emergency exit decals with safety hammers	Replaced		43213
217	09/21/2006	122206	Fit air supply decal	Fitted		43213
217	09/21/2006	122206	Polish front bumper bar	Polished		43213
217	09/21/2006	122206	Secure all lower skit panels	Secured		43213
217	09/21/2006	122206	MUD FLAPS GRENDAS MF60X30GRE RED			43213
217	09/19/2006	122039	Inspection of bus			42894
217	09/19/2006	122039	Inspection of bus			42894
217	09/19/2006	122074	Adjust windscreen washer jet	Adjusted		42894

217	09/19/2006	122074	Retighten heater pipe hose clamps	Retightened	42894
217	09/19/2006	122074	Steam clean the bus	Steamcleaned	42894
217	09/19/2006	122074	LED CLEARANCE LIGHT (RED AMBER)		42894
217	09/19/2006	122074	Replace O/S/R clearance lamp	Replaced	42894
217	09/19/2006	122074	Mop floor road test and park	Mopped tested and parked	42894
217	09/15/2006	121902	Red light on dash - doors ?	topped up coolant & checked o/k.	42235
217	09/04/2006	120647	Rectify fuel tank balance pipe and fit brackets correctly	Rectified	40168
217	09/01/2006	120335	POS 3+4	Creditor #:BEA001 BEAUREPAIRES P/O #:34416 Receiving #:34553 Date :2006-09-01	39766
217	09/01/2006	120979	Fit top alternator belt	Fitted	39766
217	08/31/2006	120749	Annual Body check 1st.	check list completed	39549
217	08/31/2006	120749	SAFETY TRIANGLE DECAL		39549
217	08/31/2006	120647	COMPRESSOR BELT MERC1418 12.5X1038MM		39766
217	08/30/2006	120647	Fuel guage not working	Found faulty fuel guage	39386
217	08/30/2006	120647	Fuel guage not working	Assisted Ranjith	39386
217	08/30/2006	120647	O/S/R mudflap needs replacing	REPLACED 21/09/06	39386
217	08/25/2006	120367	Replace O/S/R indicator tag rear wheel	Replaced	38687
217	08/25/2006	120365	Replace N/S/R tyres	Replaced	38687
217	08/25/2006	120335	Replace tyre pos. 3 & 4 - BALD.	Replaced	38687
217	08/25/2006	120290	33MM LOOSE WHEEL NUT INDICATOR		38687
217	08/25/2006	120367	Replace O/S/F parker	Replaced	38687
217	08/25/2006	120367	Replace O/S/F parker		38687
217	08/25/2006	120365	hole in air line near angle drive	Cut and fitted a joiner	38687
217	08/25/2006	120290	5/16inch AIR LINE JOINER		38687
217	08/25/2006	120290		A Service	38687
217	08/25/2006	120290	WEDGE GLOBE INSTRUMENT 24V 3W		38687
217	08/25/2006	120290		Tension Wheel Nuts To OEM Specification	38398
217	08/25/2006	120290		A Service	38398
217	08/17/2006	119791	Radio RLS	Checked OK	36879
217	08/11/2006	119258	Replace fuel tank - Warranty	Replace under warranty	36481
217	07/20/2006	116594	POS 4 +5+6	Creditor #:BEA001 BEAUREPAIRES P/O #:33176 Receiving #:33485 Date :2006-07-20	31687
217	07/06/2006	116594	Replaced tyres pos. 4 & 5 & 6 Bald.	rep. tyres pos. 456.	29384
217	07/05/2006	116795	Replace rear tyres	Replace rear tyres	29384
217	07/05/2006	116795	Replace rear tyres	Replace rear tyres	29303
217	07/05/2006	116556	Service	audit completed	29384
217	07/05/2006	116556	Annual random audit	audit completed	29303
217	07/05/2006	116555		A Service	29303
217	07/05/2006	116555		Tension Wheel Nuts To OEM Specification	29303
217	07/05/2006	116555	AIR FILTER MERC 0500LE		29384
217	07/05/2006	116555	Service	A service	193754
217	06/06/2006	106017	75X105STEEL+100X10 STEEL	Creditor #:MUR001 MURRAY AGRICULTURAL EQUIP P/O #:32489 Receiving #:32516 Date :2006-06-06	193754
217	05/19/2006	111865	POS 3	Creditor #:BEA001 BEAUREPAIRES P/O #:31610 Receiving #:32077 Date :2006-05-19	193754
217	05/19/2006	112383	COULANT DECAL	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:31774 Receiving #:32057 Date :2006-05-19	193754
217	05/19/2006	112383	INSPECTION COVER	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:31774 Receiving #:32057 Date :2006-05-19	193754
217	05/16/2006	113048	Annual random audit	audit completed	192820
217	05/16/2006	113048	Annual random audit	audit completed	192820
217	05/16/2006	113046		D-Service	192820
217	05/16/2006	113046		D-Service	192820
217	05/16/2006	113046			193100
217	05/16/2006	113046	ENGINE OIL FILTER 1725+0500		192820
217	05/16/2006	113047		Service T - Replace Transmission Oil & Filter	192820
217	05/16/2006	113047	TEXAMATIC 1888	Transmission Oil	192820
217	05/16/2006	113047	FILTER TRANSMISSION Zf 4139-298-038	ZF Transmission Filter	192820
217	05/16/2006	113047		A Service	192820
217	05/16/2006	113046		Tension Wheel Nuts To OEM Specification	192820
217	05/16/2006	113047		A Service	192820
217	05/16/2006	113046		A Service	192820
217	05/16/2006	113047		Tension Wheel Nuts To OEM Specification	192820
217	05/09/2006	112383	Service	finished off	18293
217	05/08/2006	112383	Accident damage no 11195 - Replace fleet no o/s/r clearanc	Paint accident damage	17819
217	05/08/2006	112383	Accident damage no 11195 - Replace fleet no o/s/r clearanc	Repair accident damage	16920
217	05/01/2006	111892	Flat tyr n/s/r outer	Replace tyre with correct rim and torque nuts	16239
217	05/01/2006	111865	Replace pos 3 - flat		15444
217	04/19/2006	111206	Replace alternator	Replace alternator belts	15444
217	04/19/2006	111206	MERC ALTERNATOR BELT		15444
217	04/19/2006	111205	Breakdown - Alternator light on - Dingley Dep 7.00 Ret 7.45	C/O bus - Return to depot and replace alternator belt	14876
217	04/15/2006	111078	Replaced alternator belt .	fitted alternator belt	11607
217	03/30/2006	109377	1st Warranty Service	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:30781 Receiving #:31061 Date :2006-03-30	11340
217	03/29/2006	109947		A Service	11340
217	03/29/2006	109947		Tension Wheel Nuts To OEM Specification	9688
217	03/23/2006	109590	Replaced gear selector buttons.	rep. gear selector unit	9239
217	03/22/2006	109377	Warranty service - 5000kms	Service at Whitehorse	4022
217	03/03/2006	108129	LED CLEARANCE LIGHT (RED AMBER)		4022
217	03/03/2006	108129	Rear clearance light broken	Replace rear clearance light	2566
217	02/20/2006	107293	MR 1615 - warning light on dash	Repaired under warranty was metal particles on e.c.u box repaired o/k.	2566
217	02/20/2006	107293	MR 1615 - warning light on dash	Road test check engine computer - take toWhite horse	2566
217	02/20/2006	107293	MR 1615 - warning light on dash	Road test check engine computer - take toWhite horse	1935
217	02/18/2006	107225	Graffiti on back seat	Clean graffiti	1935
217	02/16/2006	105869	Replace rear tyres x4 with rec	Creditor #:BEA001 BEAUREPAIRES P/O #:29671 Receiving #:30114 Date :2006-02-16 Return tyres come off	1856
217	02/15/2006	106920	Knocking A/C condition when turned on	repaired under warranty - s.s.thermo king	1667
217	02/14/2006	106920	A/C not working	repaired - warranty	1086
217	02/10/2006	106734	New registration - BC 092018	New registration	811
217	02/09/2006	106617	A/C low power not working effectively Loud knock noisy	Checked - unable to locate fault	811
217	02/09/2006	106694	Stop and red light comes on shut everything down which clea	Checked unable to locate fault	373
217	02/07/2006	106427	Air conditioner not working when its on thumping noise are	Checked and water by pass valve needs to done	0
217	02/06/2006	106352	Fit notice holder	fit notice holder	0
217	02/06/2006	106349	Drop off & pick up from Volgren.	drop off & pick up from Volgren.	0
217	02/03/2006	106017	32MM LOOSE WHEEL NUT INDICATOR		0
217	02/03/2006	106017	POWDER COATED NOTICE BOARDS		0
217	02/03/2006	106017	Service	fit emergency button & decal r/test & fuelclean bus.	0
217	02/02/2006	106017	Fit decals and two way radio emergency button	Fit decals	0
217	02/02/2006	106017	Fit decals and two way radio emergency button	Fit decals	0
217	02/01/2006	106017	SAFETY TRIANGLE DECAL		0
217	02/01/2006	106017	DO NOT OVERTAKE TURNING DECAL		0
217	02/01/2006	106017	TWIN TIME TABLE HOLDER		0
217	02/01/2006	106017	SWITCH-SOLENOID STARTER		0
217	02/01/2006	106017	BROOM HANDLE (8232715)		0
217	02/01/2006	106017	BROOM HEAD (09803211)		0
217	02/01/2006	106017	Fit decals and two way radio emergency button	Fit decals	0
217	01/31/2006	105869	Replace rear tyre x 4 with recaps	Pick up bus from B/repairs	0

