pacifichire

SERVICE HISTORY

BASIC INFORMATION	Asset No.	Serial No.	Make	Model
	8117	JNCMB22D7NU068622	UD	GW26460KAA
	Asset Description			
	Water Truck (14000 Litre)			

DATE	FORM TYPE	REPORT No.	SERVICE TYPE	HOURS	SERVICE BY
09/12/2025	Service Report 2024	SR0002302	Service Report 2024,	1753	Matthew Lonsdale
04/12/2025	Service Report 2024	SR0002280	Service Report 2024,	1740	Matthew Lonsdale
02/10/2025	Service Report 2024	SR0002131	Service Report 2024,		Kyle Dunn
26/06/2025	Service Report 2024	SR0001896	Service Report 2024,	14770	Kyle Dunn
16/06/2025	Service Report 2024	SR0001842	Service Report 2024,	14731	Kyle Dunn
11/11/2024	Service Report 2024	SR0000428	Service Report 2024,	11433	Carl Chapman
21/10/2024	Vehicles	VE0000011	Vehicles	11.274	Shaun Simpson
09/10/2024	Vehicle Inspection	901281	Vehicle Inspection,	10564	Lachlan Connor
18/07/2024	Service Report 2024	SR0000230	Engine Service,	10286	CMV Technician
09/07/2024	Vehicle Inspection	901264	Vehicle Inspection,	10.254	Shaun Simpson
17/05/2024	Vehicle Inspection	901243	Vehicle Inspection,	10184	Phillip Hopkins
21/02/2024	Vehicle Inspection	901230	Vehicle Inspection,	8201.0	Shaun Simpson
22/12/2023	General Equipment PreHire Check	921142	Pre-Hire,	7329	Alan Polwarth
04/12/2023	General Equipment PreHire Check	920851	Pre-Hire,	7259	Steven Wyatt
16/11/2023	Vehicle Inspection	901218	Vehicle Inspection,	7226	Mick davis
27/10/2023	Vehicle Inspection	901212	Vehicle Inspection,	6134	Phillip Hopkins
26/05/2023	Service Report	902789	Warranty Work,	4951	Dean Pearce
28/04/2023	Vehicle Inspection	901156	Vehicle Inspection,	4766	Phillip Smith
21/03/2023	Damage Report	900124	Damage Report,	4475	Tony Giarrusso

Silhouette