

Veh#	Date	W/O#	Description	Notes	Odometer
8228	09/05/2026	1367344		COMPLETED BY ATS 12/8/26	1312501
8228	08/01/2026	1342481	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O412060 Receiving #:444246 Date :2026-08-21 fit air fittings to suspension as required	1312501
8228	05/22/2026	1342481		getting bus ready for decommission.	1312501
8228	05/22/2026	1342481		assisting REMOVE STICKERS AND TWO WAY ETC..	1312501
8228	05/22/2026	1342481	BELT MICRO V SERPENT 9 RIB 212	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O410939 Receiving #:437275 Date :2026-05-22	1312501
8228	05/21/2026	1342481	Decommission of Bus for SALE	removed the batteries and put on charge	1312501
8228	02/26/2026	1323410		COMPLETED BY ATS 15/2/26	1312501
8228	08/28/2025	1286282		COMPLETED BY ATS	1312501
8228	07/30/2025	1279395	Mechanic entered - Vandalism Vandalism/ Graffiti Interior G	rebooked once approval has been made by fleet for repairs to be carried out	1312501
8228	07/04/2025	1274432	Consumables		1312501
8228	05/08/2025	1263139		Assisting	1312501
8228	05/08/2025	1263139		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1312501
8228	05/08/2025	1263139		PRE ANNUAL SAFETY INSPECTION CHECK Completed safety inspection as per checklist.	1312501
8228	05/08/2025	1263187	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Replaced N/S wiper blade assembly with new. Checked now clearing.	1312501
8228	05/08/2025	1263187	WIPER BLADE ASSEMBLY 39037 S/S FROM TX1000		1312501
8228	05/08/2025	1263187	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696		1312501
8228	05/08/2025	1263187	Mechanic entered - Engine Other Engine drive belt u/s	Removed fan and alternator belt. Removed and replaced engine belt with new. Refitted alternator and fan belts. Tensioned all belts.	1312501
8228	05/08/2025	1263187	Consumables		1312501
8228	05/08/2025	1263187	Consumables		1312501
8228	05/08/2025	1263187	Mechanic entered - Body Other Rear door emergency exit butto	Removed and replaced emergency exit button cover with new.	1312501
8228	05/08/2025	1263187	COVER EMERGENCY EXIT BUTTON		1312501
8228	05/08/2025	1263187	Mechanic entered - Body Other Accreditation sticker need to	Replaced old accreditation sticker with rail fleet accreditation.	1312501
8228	05/08/2025	1263187	DECAL ACCREDITATION CROY KNOX OAK & RAIL		1312501
8228	05/08/2025	1263187	Mechanic entered - Body Other Wheel chair ramp corner not re	Straightened wheel chair ramp.	1312501
8228	05/08/2025	1263187	Mechanic entered - Body Other 1x disabled seat back rest bol	Removed back seat rest and fitted new bolt. Refitted back rest.	1312501
8228	05/08/2025	1263187	Mechanic entered - Air System Air_Leak Front	Tightened front air tank drainer plug.	1312501
8228	04/24/2025	1260382	Deinstall smartrack and fit to bus 1688	Completed by Project tracking	1312194
8228	04/24/2025	1260382	Consumables		1312194
8228	04/22/2025	1259783	Driver Tablet Entered -p00r headlights	check and secure ns head light globe conector lights ok	1311933
8228	04/22/2025	1259783	Consumables		1311933
8228	04/17/2025	1259549	Drv entered - Suspension Hard	Checked front and rear air bags for leaks all ok. Operate high/lower and kneening all working fine.	1311707
8228	04/17/2025	1259552	Drv entered - Steering Shakes/ Wobbles	Checked the condition of the front tyre all the tie rod and kin pin all ok. Drive tested steering is ok.	1311707
8228	04/17/2025	1259553	Drv entered - Gearbox Driveline Rough Gear Change	Drive tested and checked the operation of the gear box normal.	1311707
8228	04/17/2025	1259551	Drv entered - Engine Low Power	Went for a long drive engine is in very good performed.	1311707
8228	04/17/2025	1259546	Drv entered - Brakes Park_Brake Not Holding	Checked the condition of front and rear brake pads all ok. Checked air leaks ok. operate park brake ok. Performed brake test PASSED.	1311707
8228	04/14/2025	1256197	CLEAN SET OF AIR PIPES	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G385048 Receiving #:408754 Date :2025-04-14	1310999
8228	04/14/2025	1258550		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Secured small wires around starter motor & alternator with conduit. Carried out fire safety inspection as per checklist. Complete	1310749
8228	04/10/2025	1258101	Mechanic entered - Fluid Leaks Rear of bus power steering oi	removed the floor hatch and tighten the olive nut start the bus checked for leak no leak all ok	1310667
8228	04/10/2025	1258099	Consumables		1310667
8228	04/10/2025	1258099	Workshop Tablet Entered -- Drivers Seat uncomfortable	checked the seat found seat cushion u/s. r/r the cushion fitted second hand seat cushion	1310667
8228	04/10/2025	1258058	Consumables		1310667
8228	04/10/2025	1258058	Consumables		1310667
8228	04/10/2025	1258058	Consumables		1310667
8228	04/10/2025	1258058		assisted with the service	1310667
8228	04/10/2025	1258058		CARRY OUT A SERVICE AS PER CHECK LIST completed. RE-tensioned wheel nuts with Justin.	1310667
8228	04/04/2025	1256197		Assisted Indika by reinstalling compessor lines and installing a new air drier filter. Gave engine bay a thorough wash. Topped up neccesary filters. Road tested and checked area for leaks again. No leaks found.	1309776
8228	04/04/2025	1256197	FILTER AIR DRY MAN A91 MERC 0500LE OH1830 SCANIA K94		1309776
8228	04/04/2025	1256197		Re-installed lines and checked for leaks. All good. Gave area a through wash. Road tested checked again for leak. All good	1309776
8228	04/03/2025	1256197		instoll air compressor and other remove assasary C/O	1309776
8228	04/03/2025	1256197		Assisted Indika with re-installing compresor. Secured fittings. Topped up necessary fluids that were lost due to leakage.	1309776
8228	04/02/2025	1256197	COMPRESSOR AIR MERC 0500 (NO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G384975 Receiving #:408005 Date :2025-04-02	1309776
8228	04/02/2025	1256197	O-RING POWER STEERING PUMP MER	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G384975 Receiving #:408005 Date :2025-04-02	1309776
8228	04/02/2025	1256197		Assisted Indika to further remove the compressor. Cleaned gasket mating surface (where new compressor will bolt up to) and using the parts washer cleaned various hoses etc. Assisted Indika with Re-installing new AC compressor unit. Secured all hose fittings. Topped up fluids that were lost due to failed compressor and	1309670
8228	04/02/2025	1256197		Removed Air compressor removed pink tank and line and cleaned line and gasketC/O	1309670
8228	04/02/2025	1256197	GASKET AIR COMPRESSOR MT MERC BENZ 0500LE 49A9446		1309670
8228	04/01/2025	1256197	Mechanic entered - Fluid Leaks Rear of bus Oil leaking from	Began dissassembling bus to remove compressor.	1309670
8228	03/28/2025	1255494		VEHICLE SAFETY INSPECTION Assisted Indika with Vehicle Safety Inspection. All wheel nuts were tensioned to OEM spec.	1309670
8228	03/28/2025	1255494		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1309670
8228	03/28/2025	1255494		Carried out safety inspection as per check list tensioned all wheel nuts with Antony	1309670
8228	03/28/2025	1255570	Vehicle Mechanical Audit	Completed bus audit document # 000072	1309670
8228	03/27/2025	1255341	Drv entered - Brakes Foot_Brakes Pulling	check all the brake pads adjusted front pads done road test and brake test , all ok.	1309670
8228	03/20/2025	1253740	Fault#:39568 - Ops Entered - Fault - Breakdown Overheating/C	Attended breakdown found coolant leaking from the heater tap hose on the gearbox removed and replaced hose topped up with water checked for leaks not leaking so safe to drive back to depot.	1308489
8228	03/20/2025	1253740	Fault#:39568 - Ops Entered - Fault - Breakdown Overheating/C	Replaced coolant in the system. Steam cleaned drive tested and top up coolant. Checked leaks all ok.	1308489
8228	03/17/2025	1252916	Fluid Leaks rear of the bus.	Repair coolant leak	1307852
8228	02/27/2025	1248701		COMPLETED BY ATS 23/2/2025	1304840
8228	02/19/2025	1246436	Mechanic entered - Wheels and Tyres Worn tyre 5 worn.	changed tyre 5 (worn). nuts on wheels 5 and 6 tensioned with jimmy. odo. 303460 kms. runout used.	1303021
8228	02/19/2025	1246559	Mechanic entered - Wheels and Tyres Wheel Nut Retension re-t	Retensioned wheel nuts pos 5 and 6.	1303021
8228	02/19/2025	1246559		Assisted	1303021
8228	02/19/2025	1246436	Consumables		1303021
8228	02/19/2025	1246559	Consumables		1303021
8228	02/14/2025	1245330	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	DONE 13/02/2025	1302389
8228	02/13/2025	1244681	Mechanic entered - A/C Heating Air Conditioning Air flow dow	Replaced rear and center left side evaporator fan motors replaced right number 2 condenser fan motors tested ok	1302044
8228	02/13/2025	1244681	FAN MOTOR A/C EVAPORATOR		1302044
8228	02/13/2025	1244681	FAN CONDENSOR A/C CITI-RT		1302044
8228	02/13/2025	1244982	Driver Tablet Entered -Engine - Low Power	reffer wo 1244691	1302044
8228	02/13/2025	1244982	Driver Tablet Entered -Engine - Low Power		1302044
8228	02/13/2025	1244691	Driver Tablet Entered -Brakes - Park_Brake Not Releasing	found that air pressure wasn't buliding up to full pressure due to test nipple on wet tank being broken. fitted drain valve instead tested for leaks no leaks found and buliding up to full pressure and park brake releasing	1302044
8228	02/13/2025	1244691	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 49G7901		1302044
8228	02/06/2025	1241742	THERMOSTAT 83 DEG 0500LE A004203837501 MAN 51.06402.0063		1301206
8228	02/06/2025	1241742		Fitted new thermostat and filled coolant in the system. Steam cleaned engine. Drive tested and checked temp high warning light on dash ok. Rechecked coolant level and leaks all ok.	1301206
8228	02/05/2025	1241742	HOSE COOLANT 90 DEG TAPERED 60/70 MERC 0500LE 50N0543		1301206
8228	02/05/2025	1241742		Drained coolant and replaced water pump. C/O	1301206
8228	02/03/2025	1241742	Ops Entered - Fault - Warning Lights Temperature - Route: 8		1301206
8228	02/03/2025	1241742	WATER PUMP MERC BENZ 0500LE A4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G380930 Receiving #:403758 Date :2025-02-04	1301206
8228	02/03/2025	1241742	THERMOSTAT 83 DEG M/ BENZ 0500	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G380930 Receiving #:403758 Date :2025-02-04	1301206
8228	01/30/2025	1241742	Ops Entered - Fault - Warning Lights Temperature - Route: 8	Checked coolant level and leaks ok.Steam cleaned intercooler/radiator. Drive tested and checked temp reach 100 degrees. Checked temp eith heat gun found top of radiator is colder than the bottom. Possible cooling system is not ciculating. Order parts C/O	1301206
8228	01/29/2025	1241414	Air System replace rear suspension solenoid fitting seal.	Repaired iar leaks.	1301062
8228	01/29/2025	1241414	O-RING KIT LARGE VOSS A6739970145		1301062
8228	01/25/2025	1240828		VEHICLE SAFETY INSPECTION Completed as per checklist with kumar	1300900
8228	01/25/2025	1240828		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Kumar	1300900
8228	01/25/2025	1240828		VEHICLE SAFETY INSPECTION Completed as per checklis.	1300900
8228	01/24/2025	1240602	Temperature guage reading 100 degrees usually sits on 80	steam clean radiator topup coollant adjusted fan drive belt road tested temperature ok.	1300900

8228	01/24/2025	1240602	Consumables			1300900
8228	01/21/2025	1240012	Ops Entered - Fault - Engine Noisy or Rattling - Route: 90	reoad tested checked ok when A/C on engine vibrate bit check A/C compressor could not fault it.		1300421
8228	01/20/2025	1239778	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	retension pos 3-4 wheel nuts		1300157
8228	01/20/2025	1239778	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	retension pos 3-4 wheel nuts		1300157
8228	01/20/2025	1239778	Consumables			1300157
8228	01/17/2025	1239418	PTI Tablet Entered -Wheels and Tyres - Damaged Tyre # 3	Fitted run out tyre @ pos 3 and tensioned wheel nuts with Abraham.		1299885
8228	01/17/2025	1239418		Assisted Satheesh tensioned wheel nuts pos.34. Steam cleaned rim.		1299885
8228	01/17/2025	1239418	Consumables			1299885
8228	01/10/2025	1237900	PTI Tablet Entered -Coolant leaking	check and fixed coolant leak from thrmostat housing topup coolant steam clean engine road test check leak all ok		1299034
8228	12/30/2024	1236004	Ops Entered - Fault - Warning Lights Brakes - Route: 900v -	Checked over front and rear brakes all looking good servicable steam cleaned underneath around air dryer and engine bay. Road tested bus only light on dash is for retarder being on which is normal. Brake test completed.		1297795
8228	12/23/2024	1222877	PTI Tablet Entered -Fluid Leaks - Rear of bus	checked compressor air intake it's fitted to air filter outlet steam clean air dryer.		1297191
8228	12/19/2024	1234752	Consumables			1296709
8228	12/19/2024	1234752	PTI Tablet Entered -Elec and Light - Exterior Lights right h	Replaced o/s park/indicator light assembly.		1296709
8228	12/19/2024	1234752	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1296709
8228	12/13/2024	1231669	Accident #58067 NEARSIDE - Rear window and body damage	Completed repair by east coast and refer w/o 1231649		1295661
8228	12/13/2024	1231649	DECAL VENTURA ROUTE SMALL 490MM x 145MM			1295661
8228	12/13/2024	1231649	REFLECTOR AMBER 94mm X 44MM (84051)			1295661
8228	12/13/2024	1231649	REFLECTOR RED 94MM X 4MM NR84052BL			1295661
8228	12/13/2024	1231649	D/S LOWER BLACK STRIPES - SMART BUS			1295661
8228	12/13/2024	1231649	D/S LOWER ORANGE STRIPES - SMART BUS			1295661
8228	12/13/2024	1231649	DOOR PILLAR RUBBER			1295661
8228	12/13/2024	1231649		Fit Smart Bus livery and Ventura decal. Fit upper and lower nsr tail-lights. Fit red and amber reflectors wheelarch rubber. Cut and fit 1x rear door rubber. Fit nsr bumper corner. Cleaned interior.		1295661
8228	12/13/2024	1231649	LAMP LED SIDE RED/AMBER PEREI 52-98002			1295661
8228	12/12/2024	1231649	LEFT SIDE STRIPE AND ARROW ABO	Creditor #:EA-TRA013 TRANSCAL P/O #:EA377686 Receiving #:400527 Date :2024-12-12		1295661
8228	12/12/2024	1231649	LEFT SIDE ARROW AND STRIPE BEL	Creditor #:EA-TRA013 TRANSCAL P/O #:EA377686 Receiving #:400527 Date :2024-12-12		1295661
8228	12/12/2024	1231649	FREIGHT	Creditor #:EA-TRA013 TRANSCAL P/O #:EA377686 Receiving #:400527 Date :2024-12-12		1295661
8228	12/11/2024	1225723		perp for paint		1295430
8228	12/11/2024	1225723	ETCH VALSPAR BLACK			1295430
8228	12/11/2024	1225723	PRIMER DEBEER ETCH 1K 4LTR			1295430
8228	12/11/2024	1225723		prep work maskup and painted silver where needed.		1295430
8228	12/11/2024	1225723	Consumables			1295430
8228	12/11/2024	1231649		prep work maskup and painted silver. move buses.		1295430
8228	12/10/2024	1231649		fit vents to air box		1295430
8228	12/09/2024	1231649		remove rear bumper corner do repairs air intake near side rear primer all repairs		1295430
8228	12/09/2024	1231649	SIDE GLASS - CUT TO SIZE LAM (	Creditor #:EA-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:EA377624 Receiving #:400533 Date :2024-12-12		1295661
8228	12/06/2024	1231649	VENT ROOF INTAKE POD			1295430
8228	12/06/2024	1231649		Cut out damaged section of nsr upper d-mould cut and fit new section prep/filled. Removed necessary nsr cant decals prep/filled damage to cant. Prep/filled damage to nsr corner panels. Completed 1x bonded panel fab and fit to body. Removed damaged rear door infill strip cut new strip and fit to body.		1295430
8228	12/05/2024	1231649		Continued decal removal. Removed 1x bonded panel and began fabrication.		1295430
8228	12/05/2024	1231669	Accident #58067 NEARSIDE - Rear window and body damage	Bus at east coast and repairing accident damage		1295430
8228	12/04/2024	1231649		Removed nsr wheelarch rubber nsr top & bottom tail-lights reflectors. Began decal removal. (Wed 04/12/24).		1295430
8228	12/02/2024	1222877	PTI Tablet Entered -Fluid Leaks - Rear of bus	checked new air compressor replaced on 16/1/2023		1295430
8228	11/27/2024	1229741	PIPE OIL FILTER TO BLOCK 0500LE 50A7701			1295208
8228	11/27/2024	1229975	Mechanic entered - Engine Other Engine oil leaking from valv	Replaced 1X rocker rubber gasket. Steam cleaned engine drive tested and checked ok.		1295208
8228	11/27/2024	1229975	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221			1295208
8228	11/27/2024	1229741	PTI Tablet Entered -Engine -leaking engine oil.	Replaced oil pipe.		1295208
8228	11/27/2024	1229953		Assisted nick with cleaning a/c filter tensioed the wheel nuts.		1295208
8228	11/27/2024	1229953		CARRY OUT A SERVICE AS PER CHECK LIST Completed		1295208
8228	11/27/2024	1229953	Consumables			1295208
8228	11/27/2024	1229953	Consumables			1295208
8228	11/27/2024	1229953	Consumables			1295208
8228	11/26/2024	1229741	PTI Tablet Entered -Engine -leaking engine oil.	Checked found plastic pipe from oil filter to engine block is leaking. Ordered parts. C/O		1294814
8228	11/20/2024	1228505	Mechanic entered - Wheels and Tyres Wheel Nut Retension at	Retension pos 2 wheelnuts.		1293605
8228	11/20/2024	1228505	Mechanic entered - Wheels and Tyres Wheel Nut Retension at	Retension pos 2 wheelnuts.		1293605
8228	11/20/2024	1228505	Consumables			1293605
8228	11/19/2024	1226181		fitted back the hub tighten the hub nut according to the specs. fitted back caliper brake bads and booster. fitted back drag link and tie rod . tighten all the nuts and bolt according to the specs. Adjusted the brake pads. check the play in king pin fitted back the wheel and tensioned the wheel nuts with Abraham(p.o.w 2) . C		1293487
8228	11/18/2024	1226181	A6553300719 KING PIN FOR BUS 8	Creditor #:GB-HGV001 HGV PSV PARTS AUSTRALIA P/O #:G375897 Receiving #:398556 Date :2024-11-18		1293487
8228	11/18/2024	1226181	SPACER WASHER 2.40MM KINGPIN MERC BENZ 0500LE			1293487
8228	11/18/2024	1226181		Assisted Guri to fitted new king pin.		1293487
8228	11/18/2024	1226181	0500 KING PIN PARTS FOR BUS 82	Creditor #:GB-HGV001 HGV PSV PARTS AUSTRALIA P/O #:G375897 Receiving #:398556 Date :2024-11-18		1293487
8228	11/18/2024	1226181		fitted new lower needle bearing axial taper roller bearing and shaft sealing ring to the axle. then putttd back the axle to the axle casing with spacer washer. Aligned the axle and then installed the new king pin with special tool. installed the new upper roller bearing and messure the gap on top and bottom . fitted back t		1293335
8228	11/12/2024	1226181		Remove stub axle bearing c/o		1293335
8228	11/11/2024	1226181		setup the king pin removal tool removed the king pin bearing and cleaned the axle and all the components.c/o		1293335
8228	11/11/2024	1226181		assisted with removing kingpin and cleaning components		1293335
8228	11/11/2024	1224007	Driver Tablet Entered -fuel gauge not working	checked the gauge worked this time order a fuel gauge sender		1293335
8228	11/11/2024	1224007	Driver Tablet Entered -fuel gauge not working			1293335
8228	11/11/2024	1224007		checked the circuit change the fuel sender		1293335
8228	11/11/2024	1224007	SENDER UNIT FUEL TANK MERC BENZ 0500LE (RECONDITIONED)			1293335
8228	11/11/2024	1224007	Consumables			1293335
8228	11/11/2024	1226487		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.		1293335
8228	11/08/2024	1226181	Mechanic entered - Suspension Other o/s/f king pin up and do	jack up the bus and secured on the stands. removed the o/s/f wheel brake booster cliper hub tie rod and draglink. c/o		1293335
8228	11/07/2024	1225723		Tested for leaks. Found at ns windscreen. Repositioned rubbers and sealed. Repaired f/g hole in nsf header and primed.		1293335
8228	11/07/2024	1225723	Consumables			1293335
8228	11/07/2024	1225723		test for water leaks		1293335
8228	11/06/2024	1225609	SCREW IDLER PULLEY MTG MERC BENZ 0500LE			1293335
8228	11/06/2024	1225609		Extract broken ider pulley bolt. Fitted new bolt and a/c belt.		1293335
8228	11/06/2024	1225609	Fault#:39388 - Ops Entered - Fault - Breakdown Gearbox Fault	attened to B/Down main belt lower idler bolt damage fixed temperaly bus send to depot. need to remove broken idler bolt		1293335
8228	11/06/2024	1225609	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696			1293335
8228	11/02/2024	1225085		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with KUMA		1292104
8228	11/02/2024	1225085		VEHICLE SAFETY INSPECTION completed as per check list		1292104
8228	11/02/2024	1225086	PTI Tablet Entered -coolant leaking	check amd found that transmission cooler hose clamp was loose . tighten the clamp and topped up the coolant. steam clean under the bus done road test . check after all ok.		1292104
8228	10/23/2024	1222876	PTI Tablet Entered -oil Leaks - Rear of bus	defect entered twice.		1290783
8228	10/23/2024	1222877	PTI Tablet Entered -Fluid Leaks - Rear of bus	Checked & found air compressor pumping oil Parts on order		1290783
8228	10/16/2024	1220817		fitted the compressor intake hose and steam cleaned the bus		1289297
8228	10/15/2024	1220917		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed as per check list and tensioned the nuts and bolts to spec		1289297
8228	10/15/2024	1220917	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221			1289297
8228	10/15/2024	1220816	hose as per sample	Creditor #:GB-ENZ001 ENZED DANDENONG P/O #:G374299 Receiving #:396535 Date :2024-10-15		1289581
8228	10/14/2024	1220816	Mechanic entered - Engine Other coolant leaking from back of	removed the coolant pipe waiting to be repaired removed the coolant pipe from 8231 fitted the cool pipe and secured		1289297
8228	10/14/2024	1220817	Mechanic entered - Engine Other compressor intake hose U/S	removed the hose waiting for parts		1289297
8228	10/14/2024	1220650		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list completed		1289297
8228	10/14/2024	1220650	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE			1289297
8228	10/14/2024	1220650	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401			1289297
8228	10/14/2024	1220650	AIR DRYER ASSY MERC 0500LE A0004302915			1289297
8228	10/08/2024	1219498	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	DONE		1288515

8228	10/01/2024	1206075	CORE POWER STEERING PUMP	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370100CORE Receiving #:397160 Date :2024-10-24 VEHICLE SAFETY INSPECTION completed as per check list. TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with lochi Assisted Guri carry out Safety inspection. Tensioned all wheel nutswith Guri	1290976
8228	09/13/2024	1214531			1283776
8228	09/13/2024	1214531			1283776
8228	09/13/2024	1214531			1283776
8228	09/10/2024	1213751	Consumables		1283200
8228	09/10/2024	1213751	PTI Tablet Entered -Elec and Light - Front right hand side c		1283200
8228	08/29/2024	1211020			1281092
8228	08/28/2024	1210086			1281010
8228	08/27/2024	1210086	BELT MICRO V BELT 6 RIB 0500 ALT 1308mm LONG		1281010
8228	08/27/2024	1210086	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696		1281010
8228	08/27/2024	1210086	SCREW IDLER PULLEY MTG MERC BENZ 0500LE	Bus B/D stud rd near stud park s/c borken main belt Idler bolt. left from w/s 8.45am back 9.50am used b/d van. still try to remove the broken bolt c/o While completing a A / B service found oil leaking from a union just off to the O/S of the engine removed floor hatch and tighten this union up steam cleaned extensively around the engine bay till spotless. Took for long road test and checked no more power steering leaks all dry on all lines. Fit back floor hatch.	1281010
8228	08/27/2024	1210086	Fault#:39304 - Ops Entered - Fault - Breakdown Belts Pulleys		1281010
8228	08/22/2024	1209205	Mechanic entered - Fluid Leaks Rear of bus Power steering li		1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068	OIL ENGINE ALL FLEET PLUS E900 15W-40		1280060
8228	08/22/2024	1209068			1280060
8228	08/22/2024	1209068	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1280060
8228	08/22/2024	1209068	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1280060
8228	08/22/2024	1209068	OIL SAMPLE TEST KIT	CARRY OUT B SERVICE AS PER CHECK LIST Carried out A / B service as per checklist reported / repaired any found defects.	1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068	Consumables		1280060
8228	08/22/2024	1209068			1280060
8228	08/22/2024	1209068			1280060
8228	08/19/2024	1208424	Consumables		1280060
8228	08/19/2024	1208424			1279568
8228	08/19/2024	1208424	'Power steering oil low' warning light on		1279568
8228	08/13/2024	1207250	Drv entered - Engine Belts_Loose Noisy Missing		1278740
8228	08/12/2024	1206075	FILTER POWER STEER SCANIA ALL MODELS	Fitted new Power steering pump.steam cleaned road tested ok. cleaned the oil spill on the work area. Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370100 Receiving #:392010 Date :2024-08-09 Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370100 Receiving #:392010 Date :2024-08-09 turned steering wheel side to side while idling steering stiff done the same thing but reved to 10rpm and steering feels smooth ordered new pump at 8/7/24 6:55AM VEHICLE SAFETY INSPECTION completed as per check list. Assisted Guri with safety inspection as per checklist. Tensioned all wheel nuts with Guri TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Lochi completed by galssprotech 11/7/2024 Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G365249 Receiving #:390202 Date :2024-07-16 assist Mehdi to re-place demister fan. then went road test and checked it started heating it went till 38celsius and the did Pti with Mehdi and find reverse buzzer faulty find broken cable and re-paired it and check ok.Complete. replaced demister fan assembly reassmblled everythings road tested topped up collant and find all works ok.then did PTI with Feda and find reverse buzzer faulty.re-paired it and checked ok.Complete. DONE Tested found fault was at demister motor Ranjith have given the job too Manny CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST completed as per check list	1278688
8228	08/12/2024	1206075			1278688
8228	08/09/2024	1206075	PUMP POWER STEERING MERCEDES		1278688
8228	08/09/2024	1206075	CORE POWER STEERING PUMP		1278688
8228	08/08/2024	1206075	Drv entered - Steering Excessive Play		1278498
8228	07/19/2024	1201953			1275312
8228	07/19/2024	1201953			1275312
8228	07/19/2024	1201953			1275312
8228	07/16/2024	1201252	Replace Anti Graffiti Film Audit No.1071 Stage 3		1274716
8228	07/16/2024	1201252	REPLACE ANTI GRAFFITI FILM. A		1274716
8228	07/15/2024	1199933		CARRY OUT A SERVICE AS PER CHECK LIST Completed same time as B service as per checklist.	1274556
8228	07/15/2024	1199933			1274556
8228	07/15/2024	1200872	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC		1274556
8228	07/11/2024	1199933	Drv entered - A/C Heating Demister Not Heating		1274556
8228	07/02/2024	1197650			1273241
8228	07/02/2024	1197650	OIL DIFFERENTIAL SYNGEAR 75W-140 VALVOLINE		1273241
8228	06/18/2024	1194919	FILTER DRYER AIR COND THERMO KING 2750300 DML305R		1270792
8228	06/18/2024	1194919	OIL AC COMPRESSOR		1270792
8228	06/18/2024	1194919			1270792
8228	06/18/2024	1194919			1270792
8228	06/01/2024	1186679		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list checked and find the plug for B+ which gives signal to dash was not connected.find cables are corroded too.re-built loom and connected and checked ok.Complete.	1268465
8228	06/01/2024	1186679	Consumables		1268465
8228	05/26/2024	1173876	FABRICATE AND FIT FUSE HOSE		1267599
8228	05/23/2024	1189872	ANNUAL SAFETY INSPECTION		1266707
8228	05/22/2024	1189872			1266685
8228	05/22/2024	1189872			1266685
8228	05/22/2024	1189872			1266685
8228	05/22/2024	1189872			1266685
8228	05/22/2024	1189974	Mechanic entered - Air System Air_Leak Rear		1266685
8228	05/22/2024	1189974	O-RING KIT LARGE VOSS A6739970145		1266685
8228	05/21/2024	1189706	Drv entered - Steering Steering Wheel FaultySteering wheel	Checked power steering fluid and condition which was all good still red oil right level power steering pump is silent makes no unusal noise checked front of steering parts all good. Road tested bus drives like all Mercedes steering is heavier than Volvo or Scania. Assisted Matt Removed gearbox floor hatch checkd fluid level which was good removed metal plate over retarder switch and found it was turned off switch retarder back on to postion 2 off accelerator retarding. Steam cleaned gearbox road tested bus retarder working as normal now. Fit floor hatch back. Fit metal plate for retarder swi Assisted Matt Steam cleaned all the fuel off the engine found fuel leaking from the fuel line leading into cylinder unit injector 1 tighten up this fitting as it was loose. Took the bus for a good road test bus did not leak fuel on the road test. Fit coolant hose to brass gearbox coolant hose from engine to gearbox roadtested sealing well. Removed and replace LED lamp fitted used parts. Test ok.	1266490
8228	05/21/2024	1189706			1266490
8228	05/21/2024	1189708	Drv entered - Brakes Foot_Brakes PullingBrake retarder is n		1266490
8228	05/17/2024	1189016	Mechanic entered - Fluid Leaks Rear of bus Fuel leak rear		1266260
8228	05/17/2024	1189050	Mechanic entered - Fluid Leaks Rear of bus Coolan leak geabo		1266260
8228	05/17/2024	1189114	PTI Tablet Entered -Elec and Light - left back clearance lig		1266260
8228	05/17/2024	1189114	Consumables		1266260
8228	05/17/2024	1189070	Body (None)Carry out final inspection for RSI		1266260
8228	05/17/2024	1189070	Consumables		1266260
8228	05/07/2024	1186838	Mechanic entered - Engine Belts_Loose Noisy Missing A/C and		1264768
8228	05/07/2024	1173876		Completed done good roadtest checked operation power ok. No fault showing on dash. Bus can be use. checked and find old battery.re-placed it ok.Complete.	1264768
8228	05/07/2024	1186679	Mechanic entered - Warning Lights Batteries		1264768
8228	05/07/2024	1186679	BATTERY 1450CCA POS ON RHS EMFN200R		1264768
8228	05/07/2024	1186778	LED STRIP LIGHT HARNESS		1264768
8228	05/07/2024	1186778	Mechanic entered - Elec and Light Interior Lights Saloon lig		1264768
8228	05/07/2024	1186779	Mechanic entered - Elec and Light Other Faulty RPD.		1264768
8228	05/07/2024	1186778	Consumables		1264768
8228	05/07/2024	1186779	Consumables		1264768
8228	05/07/2024	1186679	Consumables		1264768
8228	05/07/2024	1186780	Mechanic entered - CCTV Hard Drive RE-format hard drive. (un		1264768
8228	05/07/2024	1186833	Mechanic entered - Body Other RSI steam clean.	carried out CCTV B service as per list and format hard drive.Complete.	1264768
8228	05/07/2024	1186835	Mechanic entered - Body Other Front o/s wheel rubber and arc		1264768
8228	05/07/2024	1186835	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1264768
8228	05/07/2024	1186835	WHEEL ARCH BRUSH 2.5M LENGTH 12065		1264768
8228	05/07/2024	1186836	Mechanic entered - Body Rear_Door Operation Faulty Adjust sp		1264768
8228	05/07/2024	1186893	Mechanic entered - Body Other Under chassi have rusted part		1264768
8228	05/07/2024	1186893	UNDERBODY SHUTZ BLACK L250 AEROSOL 500ML		1264768
8228	05/07/2024	1186835	Consumables		1264768
8228	05/07/2024	1186893	Consumables		1264768
8228	05/07/2024	1186833	Consumables		1264768
8228	05/07/2024	1186837	O-RING KIT LARGE VOSS A6739970145	Adjusted checked operation ok. Painted rusted part.	1264768
8228	05/07/2024	1186837	VALVE CIRCUIT PROTECTION MERC BENZ 0500LE		1264768
8228	05/07/2024	1186837	Mechanic entered - Air System Air_Leak Rear		1264768
			Removed and replace circuit protection valve and air line fittings o ring seal. Build up air test ok.		1264768

8228	05/07/2024	1186863	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	complate fire safety inspection as per checklist	1264768
8228	05/06/2024	1186526	VEHICLE SAFETY INSPECTION	Completed VSI.	1264768
8228	05/06/2024	1186526	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	Completed VSI. Tensioned wheel nuts w/ Satheesh.	1264768
8228	05/06/2024	1186526	Assisted		1264768
8228	05/06/2024	1186526	Assisted		1264768
8228	05/06/2024	1186527	PRE ANNUAL SAFETY INSPECTION	CHECK PASI completed and tensioned wheel nuts w/ Satheesh.	1264768
8228	05/06/2024	1186527	CARRY OUT CCTV - B SERVICE	AS PER CHECK LIST Completed.	1264768
8228	05/06/2024	1186515	CARRY OUT A SERVICE	AS PER CHECK LIST Completed	1264768
8228	05/06/2024	1186515	Consumables		1264768
8228	05/06/2024	1186515	Consumables		1264768
8228	05/06/2024	1186515	Consumables		1264768
8228	05/04/2024	1173876		Fitted new muffler and top oil and coolant. Top up all fluid and coolant check all fluid level ok. Steam cleaned.	1264768
8228	05/03/2024	1173876		Fitted new dip stick Re fit coolant transmission pipe Re fit turbo hose and intake pipe Re fit all clamps secured Re fit wiring and sensor for intake pipe plus breather hose . Re fit alternator bracket and alternator assembly re fit wirings and secured Adjusted alternator belt. Re fit coolant pipe and hoses Re fit hydraulic fan dri	1264768
8228	05/02/2024	1173876	REPAIR EXHAUST FLEXI SECTION	Creditor #:GB-DAA001 DAALDER EXHAUSTS P/O #:G363843 Receiving #:384940 Date :2024-05-02	1264768
8228	05/02/2024	1173876		Cleaned and fitted new sump gasket Re fit sump assembly tensioned all bolts according to specs. (35 nm.). Removed and replace alternator bracket bushing fitted two new bushing. Temporary repair coolant pipe weld with bronze rod damaged part Note: Coolant pipe being ordered coming in 4 weeks time as per advise b	1264768
8228	05/02/2024	1173876		assist to fit sump in.	1264768
8228	05/01/2024	1173876	Service	Assisted Rene	1264768
8228	05/01/2024	1173876		Re fit fuel lines fuel filter housing air filter housing secured wiring secured coolant hoses and re fit accessories. Secured brether hoses. Carry/over.	1264768
8228	05/01/2024	1173876	MUFFLER MERC BENZ 0500LE E3 A6	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G363830 Receiving #:384841 Date :2024-05-01	1264768
8228	04/29/2024	1173876	TUBE DIPSTICK MERC BENZ 0500LE	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G363649 Receiving #:384624 Date :2024-04-29	1264768
8228	04/29/2024	1173876	GASKET OIL SUMP 457942 MERC BE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G363642 Receiving #:384603 Date :2024-04-29	1264768
8228	04/29/2024	1173876	BUSH ALTERNATOR MTG 12/25/37 MM MERC BENZ 0500LE A0009921210		1264768
8228	04/29/2024	1173876	FILTER AIR MERC BENZ 0500LE E3 - E5 A0040941704		1264768
8228	04/26/2024	1173876	SILICONE SEALER GREY VOLVO 30B0700		1264768
8228	04/26/2024	1173876		Re fit fuel lines. fitted new banjo washers. Removed ECU tester and fitted 8228 ECU and re fit wirings and banjo bolts and washers. Re fit unit pumps wirings and secured covers. Re fit fuel hi pressure lines. Re fit intake manifold and fitted new manifold gasket and tensioned all bolts according to specs (25 nm.). Job to cont	1264768
8228	04/24/2024	1173876		Re fit all unit pump and fitted new unit pump number one cylinder. Tensioned unit pump bolts according to specs. (60 -->10) Re fit fuel line pipe and banjo bolts. Carry/over job to continue.	1264768
8228	04/22/2024	1173876	SEAL RING 457942 MERC BENZ 050	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30	1264768
8228	04/22/2024	1173876	GASKET INLET MANIFOLD 457942 M	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30	1264768
8228	04/22/2024	1173876	SEAL RING 457942 MERC BENZ 050	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30	1264768
8228	04/22/2024	1173876	SEAL RING 457942 MERC BENZ 050	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30	1264768
8228	04/22/2024	1173876	UNIT INJECTOR PUMP 457942 MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30 1 B/O	1264768
8228	04/22/2024	1173876	SEAL RING 457942 MERC BENZ 050	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G360996 Receiving #:384688 Date :2024-04-30 1 B/O	1264768
8228	03/20/2024	1173876		Cleaned parts need to be cleaned. Carry/over. List parts need.	1264768
8228	03/20/2024	1173876		Assisted Rene	1264768
8228	03/18/2024	1173876	O RING INJECTOR 457954 MERC BE	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G361011RET Receiving #:381949 Date :2024-03-19 RETURNED FOR CREDIT	1264768
8228	03/18/2024	1173876	INJECTOR 457942 MERC BENZ 0500	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G361011RET Receiving #:381949 Date :2024-03-19	1264768
8228	03/14/2024	1173876		Removed belts alternator assembly drain oil and removed sump assembly. Job to continue carry/over.	1264768
8228	03/14/2024	1173876	O RING INJECTOR TUBE 457942 ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G360993RET Receiving #:381765 Date :2024-03-15 RETURNED FOR CREDIT	1264768
8228	03/14/2024	1173876			1264768
8228	03/13/2024	1173876	O RING INJECTOR TUBE 457942 ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G360993 Receiving #:381618 Date :2024-03-13	1264768
8228	03/13/2024	1173876	INJECTOR 457942 MERC BENZ 0500	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G361011 Receiving #:381617 Date :2024-03-13	1264768
8228	03/13/2024	1173876	O RING INJECTOR 457954 MERC BE	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G361011 Receiving #:381617 Date :2024-03-13	1264768
8228	03/07/2024	1173876		Removed intake manifold to get access removing unit pump. Removed 456 unit pump.	1264768
8228	03/06/2024	1173876		Cleaned engine Removed air filter housing assembly removed intake pipes Drain coolant Removed transmission hoses and pipe Removed unit pump wirings Removed fuel high pressure lines. Removed number 2 and 3 unit pump. Clean up work area. To continue carry/over.	1264768
8228	03/06/2024	1174862		PASS	1264768
8228	03/05/2024	1173876			1264768
8228	03/04/2024	1173876	FILTER FUEL/WATER SEPARATOR MERC 0500LE >E5 A0004771302		1264768
8228	03/04/2024	1173876		RE FIT ecu assembly and fuel lines Wirings rectify fault. Unit pump number 1 (INJECTOR FAULT). Removed fuel lines and filters Fuel line block with dirt. Removed injector number 1 found out injector assembly damaged. To continue carry/over. Assisted by Nick removing injector.	1264768
8228	03/04/2024	1173876	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151		1264768
8228	03/01/2024	1173453	REPLACE ANTI GRAFITTI FILM L1	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G360386 Receiving #:380894 Date :2024-03-05	1264768
8228	03/01/2024	1173876	Ops Entered - Fault - Engine Low Power - Route: 900v - Jack	Rectify fault check events showing on dash. Erase all fault and test active fault INS 3010 3040. MR 9044 and AGN 5521. Most of active fault pointing on CAN BUS fault Data communication with control unit MRengine control.Control unit MR engine control has failed. Removed ECU found out coroded full of dirt corotion an	1264768
8228	02/29/2024	1173453	Vandalism REPLACE ANTI GRAFITTI FILM L1 L2 L4	DONE BY GLASSPROTECH 29/02/2024 PO# G360386	1264768
8228	02/14/2024	1169661	PTI Tablet Entered -Elec and Light - Exterior Lights right h	Replaced globe.	1261900
8228	02/14/2024	1169661	GLOBE 24V 70W H1		1261900
8228	02/14/2024	1169661	Consumables		1261900
8228	02/07/2024	1167888	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	Completed	1260646
8228	02/06/2024	1166089		Install radiator and intercooler and all removal parts. filled coolant road tested rechecked. ok. Carried out PTI. Cleaned work area.	1260281
8228	02/05/2024	1166089		Cleaned radiator and Intercooler Welded broken fan angle drive motor bracket. install radiator to fan bracket fan cover. and fan motor. C/O.	1260281
8228	02/01/2024	1166089	FAN ANGLE DRIVE ASSY MERC 0500	Creditor #:GB-CBM001 CBM COMPANY P/O #:G358675 Receiving #:378491 Date :2024-02-02	1260281
8228	02/01/2024	1166089		Still try to remov broken bolt. C/O	1260281
8228	02/01/2024	1166089		Assisted.	1260281
8228	02/01/2024	1166089		assisted indi	1260281
8228	01/31/2024	1166089		Cooling fan bracket crack Drain coolantRemoved Intercooler and radiator. C/O.	1260281
8228	01/30/2024	1166089	Ops Entered - Fault - Air System Air_Leak Rear - Route: 900	Refit axle on O/S/R tensioned all bolts to 420nm.	1260281
8228	01/30/2024	1166089	Ops Entered - Fault - Air System Air_Leak Rear - Route: 900	Driver reported noise from engine found radiator fan drive had broken from whear it mounts arranged tow Replaced broken air fitting on N/S/R tank removed axle.	1260281
8228	01/29/2024	1166089	TOW BUS OAKLEIGH TO DANDENONG	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G358560 Receiving #:378440 Date :2024-02-01	1260281
8228	01/22/2024	1164871	REPLACE ANTI GRAFITTI FILM R1	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G358076 Receiving #:377833 Date :2024-01-23	1259529
8228	01/22/2024	1164871	Vandalism. REPLACE ANTI GRAFITTI FILM. R1	Completed by Glass Protect	1259273
8228	01/20/2024	1164585		VEHICLE SAFETY INSPECTION Completed	1259273
8228	01/20/2024	1164585		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Guri	1259273
8228	01/20/2024	1164614	Mechanic entered - Elec and Light Exterior Lights F/O/S bott	Replaced light assembly.	1259273
8228	01/20/2024	1164614	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1259273
8228	01/20/2024	1164614	Consumables		1259273
8228	01/20/2024	1164613	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1259273
8228	01/20/2024	1164613	Mechanic entered - Air System Air_Leak Doors Rear door switc		1259273
8228	01/20/2024	1164613	BUTTON CLIPPARD DOOR VALVE 11916-2		1259273
8228	01/04/2024	1161252	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	COMPLETED	1257686
8228	12/28/2023	1160080	Consumables		1257173
8228	12/28/2023	1160080	PTI Tablet Entered -Elec and Light - Exterior Lights. Front	replaced os front park light globe	1257173
8228	12/21/2023	1159413	CCTV FIT X5 DVR	fitted and comissioned	1257173
8228	12/19/2023	1158992		Replaced radiator cap.	1256693
8228	12/19/2023	1158992	CAP RADIATOR 70KPA MERC 0500LE A0005014615		1256693
8228	12/19/2023	1158992	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: - T		1256693
8228	12/18/2023	1158734	Consumables		1256336
8228	12/18/2023	1158734	PTI Tablet Entered -Elec and Light - Exterior LightsRIGHT H		1256336
8228	12/15/2023	1157068		Replaced globe.	1256295
8228	12/15/2023	1157068	SIGHT GLASS COOLANT MERC 0500LE	Drained coolant and replace sight glass. Topped up coolant and check leaks ok.	1256295
8228	12/08/2023	1157068	PTI Tablet Entered -Fluid Leaks - Rear of bus coolant leak		1255174
8228	12/07/2023	1156755	Consumables	No coolant leak need replace header tank sight glass.	1255030
8228	12/07/2023	1156755	Ops Entered - Fault - Elec and Light Indicators Not Working	checked and find 2x globe blown on driver's front and side indicator. re-placed globes and checked them ok. Complete.	1255030
8228	12/04/2023	1155804	Water leaking through 3 different places between front and r	Had ben on top of the work ladder with the drivers spray gun using loads of water on the roof and around the A/C pod no water getting inside. Took the bus for road test with A/C on to build up water run off put bus on pit and had no water running off the A/C. Found the drain lines were blocked used an air gun blower to	1254311
8228	12/04/2023	1155804		Assisted with using gun on roof and attempting to cause leaks. cleaned out drain lines as best as possible	1254311
8228	11/24/2023	1150727	LATCH PANEL QUAD	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G354988 Receiving #:374274 Date :2023-11-24	1253558
8228	11/24/2023	1150727	Consumables		1253558

8228	11/23/2023	1153802	PTI Tablet Entered -	wornly entered defect.	1253106
8228	11/23/2023	1153802	PTI Tablet Entered -	wrongly entered defect.	1253106
8228	11/23/2023	1150727		Replaced lock.	1253106
8228	11/20/2023	1153294	PTI Tablet Entered -coolant leak	Top up coolant drive tested and checked coolant leaks ok.	1252686
8228	11/17/2023	1152771		Fitted Axle and Tensioned to spec. Replaced the broken hose topped up coolant and Road tested ok.	1252686
8228	11/17/2023	1152771	HOSE ELBOW RADIATOR MERC BENZ 0500LE A0015010882		1252686
8228	11/16/2023	1152771	Fault#:38969 - Ops Entered - Fault - Breakdown Oil Leak -	Andrew Dyson attendented break down and found not oil leaking leaking coolant from top of the engine elbo hose. called tow truck to tow the bus	1252686
8228	11/16/2023	1152771	Tow from Wellington/Stud Rd to	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G354887 Receiving #:374171 Date :2023-11-23	1253394
8228	11/14/2023	1152018		complete cctv service as per check list	1251525
8228	11/14/2023	1152018		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete cctv service as per check list	1251525
8228	11/09/2023	1151111		replaced hammer	1250418
8228	11/09/2023	1151111	HAMMER EMERGENCY C/W BRACKET 2	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G354075 Receiving #:373223 Date :2023-11-09	1250806
8228	11/09/2023	1151111	Consumables		1250806
8228	11/08/2023	1150728		replaced the shock	1250418
8228	11/08/2023	1151110	Mechanic entered - Engine Other coolant leaking at rear next		1250418
8228	11/08/2023	1151110		repaired with new hose	1250418
8228	11/08/2023	1150972		replaced the gasket steam cleaned road tested ok	1250418
8228	11/08/2023	1150972	Mechanic entered - Engine Other coolant leaking around water		1250418
8228	11/08/2023	1150975	Mechanic entered - Engine Other coolant leaking from transmi		1250418
8228	11/08/2023	1150975	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G		1250418
8228	11/08/2023	1150727	LATCH PANEL QUAD		1250418
8228	11/08/2023	1151109		n/s/f over head grab handle replaced.	1250418
8228	11/08/2023	1151111	Mechanic entered - Body Other n/s/f emergency hammer cracked		1250418
8228	11/08/2023	1151109	PLASTIC TRIANGLE HANDSTRAP GREY		1250418
8228	11/08/2023	1151109	Mechanic entered - Body Other n/s/f one grab handle broken		1250418
8228	11/08/2023	1150727	LATCH PANEL QUAD	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G353972 Receiving #:373243 Date :2023-11-09	1250806
8228	11/08/2023	1151109	Consumables		1250418
8228	11/06/2023	1150683		VEHICLE SAFETY INSPECTION Started Safety inspection was taken over by Sisil and Guri	1250418
8228	11/06/2023	1150683		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1250418
8228	11/06/2023	1150683		incorrect log on	1250418
8228	11/06/2023	1150683		Assisted Sisil with safety inspection and tensioned wheel nuts.	1250418
8228	11/06/2023	1150683		completed Safety inspection and tensioned wheel nuts with Guri.	1250418
8228	11/06/2023	1150728	Mechanic entered - Suspension Other n/s/r shocker leaking		1250418
8228	11/06/2023	1150728	SHOCK ABSORBER RR MERC BENZ 05	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G353924 Receiving #:373040 Date :2023-11-06	1250642
8228	11/06/2023	1150707	Consumables		1250418
8228	11/06/2023	1150707	Mechanic entered - Elec and Light Exterior Lights N/F park u	replaced the light	1250418
8228	11/06/2023	1150707	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1250418
8228	11/06/2023	1150727	Mechanic entered - Body Other rear door top modesty panel lo		1250418
8228	11/06/2023	1150727		Part ordered	1250418
8228	11/06/2023	1150722	Mechanic entered - Body Other n/s/r passanger seat handle co	fixed the seat handle	1250418
8228	11/06/2023	1150722	Consumables		1250418
8228	11/01/2023	1150019	Body L/H rear reflector amber missing	Fitted	1249925
8228	11/01/2023	1150019	REFLECTOR AMBER HELLA 94 X 44MM		1249925
8228	11/01/2023	1150019	Consumables		1249925
8228	11/01/2023	1149994	Consumables		1249925
8228	11/01/2023	1149994		CARRY OUT A SERVICE AS PER CHECK LIST Complete	1249925
8228	11/01/2023	1149994		carried out A service as per check list	1249925
8228	11/01/2023	1149994	Consumables		1249925
8228	11/01/2023	1149994	Consumables		1249925
8228	11/01/2023	1149994	Consumables		1249925
8228	10/31/2023	1149710	Consumables		1249490
8228	10/31/2023	1149625	Consumables		1249490
8228	10/31/2023	1149625	Workshop Tablet Entered -Elec and Light - Two Way Radioplea	relocater the two way radio	1249490
8228	10/31/2023	1149710	Saloon speaker not working through Consat	Some one has connected two amplifier together. Volgren fixed	1249490
8228	10/25/2023	1148673	Consumables		1248774
8228	10/25/2023	1148673	PTI Tablet Entered -Elec and Light - Exterior Lights left-ha	Replaced light assembly.	1248774
8228	10/18/2023	1147128	Consumables		1247468
8228	10/18/2023	1147128	PTI Tablet Entered -Elec and Light left-hand front park li	removed globe and replaced with new to no faults	1247468
8228	10/05/2023	1144594	Mechanic entered - Suspension Other suspension valve air lin	removed the air line and fitted 2x new oring kit refitted the air line checked for leak no leak found	1245384
8228	10/05/2023	1144594	O-RING KIT LARGE VOSS A6739970145		1245384
8228	10/02/2023	1143622		helping for Bruce to find the laud noise source this bus finali we are identyficate the Consat system passanger audio amplyfier noisy	1244812
8228	10/02/2023	1143622	Driver Tablet Entered -A/C Heating - Noisy when AC onhigh	Commission tested A/C noise was not comong from A/C there is a Amplifer behind driver causing the issue Ranjith set up repair time	1244812
8228	09/27/2023	1143113		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list and found pressure limiting valve leaking r/r pressure limiting valve rene had changed pipes on 18 of january 2023.	1244349
8228	09/27/2023	1143113	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1244349
8228	09/27/2023	1143113	AIR DRYER ASSY MERC 0500LE A0004302915		1244349
8228	09/27/2023	1143113	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1244349
8228	09/27/2023	1143113	VALVE OVERFLOW MERC BENZ 0500LE		1244349
8228	09/21/2023	1142003	Ops Entered - Fault - Engine Noisy or Rattling - Route: -	inspected bus inside and out for any rattling or unusual noises could not hear rattles or unusual noises. complete	1243520
8228	09/18/2023	1141155	Drv entered - A/C Heating Noisy	locate and repair refrigerant leak at crossover right side	1243196
8228	09/18/2023	1141155	AIR CON REFRIDGERANT		1243196
8228	09/18/2023	1142003	SmartBus Decal	Creditor #:EA-LAB010 LABEL CONCEPTS P/O #:EA350958 Receiving #:370242 Date :2023-09-27	1244030
8228	09/16/2023	1141208	Only book bus to bodt shop	Completed by east cost and refer w/o 1140618 Acc # 55397	1243196
8228	09/16/2023	1141208	Only book bus to bodt shop	Assisting	1243196
8228	09/16/2023	1140618	DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL		1243196
8228	09/16/2023	1140618	D/S LOWER ORANGE STRIPES - SMART BUS		1243196
8228	09/16/2023	1140618	REFLECTOR AMBER HELLA 94 X 44MM		1243196
8228	09/16/2023	1140618	D/S LOWER BLACK STRIPES - SMART BUS		1243196
8228	09/16/2023	1140618		fit up panels stickers	1243196
8228	09/15/2023	1140618	SHEET ALUMIN 2400x1200x2mm		1243196
8228	09/15/2023	1140618		made 2 panels	1243196
8228	09/15/2023	1140618		prep and paint 2 panels	1243196
8228	09/15/2023	1140618	DBC-4	Creditor #:EA-BOD001 BODYSHOP PAINT SUPPLIES P/O #:EA350949 Receiving #:369541 Date :2023-09-18	1243256
8228	09/14/2023	1140618		making panels	1243196
8228	09/09/2023	1139733		Assisted	1242112
8228	09/09/2023	1139733		VEHICLE SAFETY INSPECTION Completed with Ben.	1242112
8228	09/09/2023	1139740	Mechanic entered - Fluid Leaks Front of bus Heater demister	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ben.	1242112
8228	09/09/2023	1139740	VALVE HEATER DEMISTER MERC 0500LE DHV4008 37V3305 HV4008	Removed and replace heater demister valve. Top up coolant test ok. Steam cleaned front of bus with coolant.	1242112
8228	09/09/2023	1139738	Mechanic entered - Brakes Other Front off side brake booster		1242112
8228	09/05/2023	1138578	Consumables	Checked found out brake booster clamp bolt loose Retightened clamp test ok no leak.	1241593
8228	09/05/2023	1138578		chcked busminder logging in ok. cleaned chargeing point and secured cable. Complete.	1241593
8228	09/05/2023	1138578	Ops Entered - Fault - BusMinder Unable To Log In - Route: 9	checked bus minder cleaned charge connections. bus minder logging in and charging correctly tested ok	1241593
8228	09/04/2023	1138174	Body Mirrors ExteriorMirror and assembly detached from B	N/S mirror arm base bolt broken and mirror arm bent. replaced broken bolts and repaired.	1241018
8228	08/31/2023	1137768	PTI Tablet Entered -Engine - Warning Light. coolant viewin	Checked coolant level ok.	1240879

8228	08/22/2023	1134994	Consumables			1238702
8228	08/22/2023	1134994	Loud Siren / Alarm undable to drive	check for loud noise it's come thru radio secure alternator wires and radio wires sound off. bus serviceble		1238702
8228	08/18/2023	1137376		CARRY OUT FIRE EXTINGUISHER TEST & TAG completed by ATS.		1238702
8228	08/18/2023	1137376		Assisting		1238702
8228	08/17/2023	1134150	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	Done by Refuelers		1238132
8228	07/31/2023	1130139	OIL SAMPLE TEST KIT			1234865
8228	07/31/2023	1130139		completed as per check list and tensioned the wheel nuts with Abraham		1234865
8228	07/31/2023	1130139	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709			1234865
8228	07/31/2023	1130139		CARRY OUT C SERVICE AS PER CHECK LIST Completed		1234865
8228	07/31/2023	1130139	FILTER AIR MERC BENZ 0500LE E3 - E5 A0040941704			1234865
8228	07/31/2023	1130139	BREATHER OIL MIST MERC BENZ 0500LE A5410100163			1234865
8228	07/31/2023	1130139	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN			1234865
8228	07/31/2023	1130139	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)			1234865
8228	07/31/2023	1130139	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151			1234865
8228	07/31/2023	1130139	OIL FAN DRIVE MERC BENZ 0500LE E3 to E5			1234865
8228	07/31/2023	1130139	FILTER FUEL/WATER SEPARATOR MERC 0500LE >E5 A0004771302			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST Completed		1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed		1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/31/2023	1130139	Consumables			1234865
8228	07/25/2023	1128948		VEHICLE SAFETY INSPECTION Completed VSI.		1233866
8228	07/25/2023	1128948		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts w/ Haysun.		1233866
8228	07/25/2023	1128952	Mechanic entered - Steering Other Rectify steering fluid lea	rectified fault found union leaking tighten the union joint		1233866
8228	07/25/2023	1128961	Ops Entered - Fault - Elec and Light Two Way Radio - Route:	Checked communication w/ operations OK.		1233866
8228	07/25/2023	1128961	Consumables			1233866
8228	07/21/2023	1128269	Ops Entered - Fault - Warning Lights Engine - Route: 900v -	Checked no warning light on dash. Drive tested and checked ok.		1233076
8228	07/19/2023	1127476	Warning Lights Engine	check fault codes clean fuel regulator clear fault codes bus ok		1232341
8228	07/17/2023	1126920	Accident # 55486 MIRROR	Job completed uner work order 1125504		1232057
8228	07/10/2023	1125472	MyKi 4G antenna need install	Completedby Amtek		1230882
8228	07/10/2023	1125472	Consumables			1230882
8228	07/10/2023	1125504	Mechanic entered - Accident MIRROR front left mirror broken	Removed broken side mirror arm assembly. Fitted side mirror arm coming from Bus 585. Fitted with Nick.		1230882
8228	07/10/2023	1125504	Mechanic entered - Accident MIRROR front left mirror broken	Assisting		1230882
8228	07/07/2023	1124810	Workshop Tablet Entered -Elec and Light - Interior Lights ar	checked bus and found driver had left the ticket light on which was shining directly on the driver turned off light and cabin is now no longer bright.		1230793
8228	07/07/2023	1124810	Consumables			1230793
8228	07/07/2023	1125049	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	Completed		1230793
8228	07/01/2023	1123553		CARRY OUT A/C - A SERVICE AS PER CHECK LIST service as per Ist		1229737
8228	06/30/2023	1123515	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	Completed by Volgren		1229737
8228	06/16/2023	1120426	STRUT GAS STAY 600Nm 540mm LONG	PARTS NOT IN STOCK		1227786
8228	06/14/2023	1120426	Mechanic entered - Body Rear_Door Operation Faulty rear latc	Checked engine door strut gas stay missng. Fitted two new strut gas stay.		1227374
8228	06/14/2023	1120426	STRUT GAS STAY 600Nm 540mm LONG			1227374
8228	05/24/2023	1116543		VEHICLE SAFETY INSPECTION		1224644
8228	05/24/2023	1116543		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed.		1224644
8228	05/24/2023	1116543	ANNUAL SAFTEY INSPECTION	ANNUAL SAFETY INSPECTION SERIAL #RSI053396. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1224644
8228	05/24/2023	1116573	Brakes R/H rear brake booster leaks on hand brake line cone	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G343732 Receiving #:361402 Date :2023-05-25		1224737
8228	05/24/2023	1116573	O-RING KIT LARGE VOSS(A6739970145)	FIT NEW SEALING KIT		1224644
8228	05/22/2023	1115913	Workshop Tablet Entered -Steering - Shakes/ Wobbles	carried out road testing bus carried out checking for any shakes or wobbles at all speeds up to 80kmph none at all checked condition of front tyres allgood.		1224172
8228	05/22/2023	1115046		secured with screw		1224172
8228	05/22/2023	1116122	INVERTER 24V 15-36W (KIRG)			1224172
8228	05/22/2023	1116122	Body (None)Final inspection for RSI	completed. fitted new invertor for saloon lights.		1224172
8228	05/22/2023	1116122		completed		1224172
8228	05/22/2023	1115046	Consumables			1224172
8228	05/22/2023	1116122	Consumables			1224172
8228	05/18/2023	1115574		Tensioned wheel nuts w/ Seujong pos.12.		1224037
8228	05/18/2023	1115574		Assisted Abraham		1224037
8228	05/17/2023	1115260	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Removed and replace wiper blade. Replace off side wiper blade.		1223681
8228	05/17/2023	1115260	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM			1223681
8228	05/17/2023	1114324		Removed and replace sway bar link rod off side with Abraham.		1223681
8228	05/17/2023	1114324		Assisted Rene.		1223681
8228	05/17/2023	1114326		Removed and replace lower torque rod with Abraham and tensioned according to specs.		1223681
8228	05/17/2023	1114325	Mechanic entered - Suspension Other Front upper torque rod b	Replaced		1223681
8228	05/17/2023	1114325	Mechanic entered - Suspension Other Front upper torque rod b	Assisted		1223681
8228	05/17/2023	1114326		Assisted Rene.		1223681
8228	05/17/2023	1115259	Mechanic entered - Engine Other Engine and under carriage ne	Steam clean bus.		1223681
8228	05/17/2023	1115133	Mechanic entered - CCTV Other Camera base damaged and door p	carried out making a new lip from sheet metal due to latch not hooking on fitted all good latch now hooking and check over cctv console base all good		1223681
8228	05/17/2023	1115047	Mechanic entered - Body Other Drivers behind panel need to s	secured panel behind driver with new screws		1223681
8228	05/17/2023	1115054	Mechanic entered - Body Other Near side front stauction pole	secured n/s stauction pole due to nuts being loose		1223681
8228	05/17/2023	1115046	Mechanic entered - Body Other Front passenger door over head			1223681
8228	05/17/2023	1115060	Mechanic entered - Body Other Drivers seat belt frayed.	removed seat belt and replaced with spare seat belt from spare driver seat in store		1223681
8228	05/17/2023	1115212	STONEGUARD BLACK AEROSOL 500ML			1223681
8228	05/17/2023	1115212	Mechanic entered - Body Other Chassi rusted need to paint.	sanded down rust sprayed stone gaurd all good		1223681
8228	05/17/2023	1115045	Mechanic entered - Body Other Passenger dis able seat (fold	secured disable seats		1223681
8228	05/17/2023	1115148	Mechanic entered - Body Other Drivers console panel vinyl to	cut out torn vinly got new vinly from east coast patch up cut out area		1223681
8228	05/17/2023	1115257	Mechanic entered - Body Other Front wheel arch rubber and br	Removed and replace off side front and near side front wheel arch rubber and brush. Fitted new wheel arch brush and rubber.		1223681
8228	05/17/2023	1115257	WHEEL ARCH BRUSH 12065			1223681
8228	05/17/2023	1115257	RUBBER WHEEL ARCH 41294			1223681
8228	05/17/2023	1115045	Consumables			1223681
8228	05/17/2023	1115047	Consumables			1223681
8228	05/17/2023	1115054	Consumables			1223681
8228	05/17/2023	1115060	Consumables			1223681
8228	05/17/2023	1115148	Consumables			1223681
8228	05/17/2023	1115212	Consumables			1223681
8228	05/17/2023	1115257	Consumables			1223681
8228	05/17/2023	1115220	Mechanic entered - Air System Air_Leak Rear leaking air from	replaced fitting seals built up area checked for leaks no leaks all good		1223681
8228	05/17/2023	1115220	O-RING KIT LARGE VOSS(A6739970145)			1223681
8228	05/16/2023	1114326	TORQUE ROD NSF LWR MERC BENZ O	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G343077 Receiving #:360715 Date :2023-05-16		1223681

8228	05/16/2023	1114326	TORQUE ROD OSF LWR MERC BENZ O	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G343077 Receiving #:360715 Date :2023-05-16	1223681
8228	05/16/2023	1114326	SCREW FRT LWR TORQUE ROD MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114326	NUT M16 X 1.5 RR ENGINE MOUNT	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114325	TORQUE ROD FRT UPPER LH MERC B	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114325	TORQUE ROD FRT UPPER RH MERC B	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114325	BOLT FRT UPPER TORQUE ROD MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114325	NUT RR LWR TORQUE ROD MERC BEN	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114325	BOLT RR LWR TORQUE ROD MERC BE	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/16/2023	1114326	SCREW FRT LWR TORQUE ROD MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G343085 Receiving #:360788 Date :2023-05-17	1224035
8228	05/15/2023	1114325	BOLT RR LWR TORQUE ROD MERC BENZ 0500LE		1223584
8228	05/15/2023	1114324	LINK SWAY BAR OSF MERC BENZ 05	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G343077 Receiving #:360614 Date :2023-05-15	1223681
8228	05/15/2023	1114677	Mechanic entered - Fluid Leaks Rear of bus Steering pump pip	Checked any leaks from steering system ok.	1223584
8228	05/12/2023	1114297		PRE ANNUAL SAFETY INSPECTION CHECK Completed check list.	1223546
8228	05/12/2023	1114297		Done.	1223546
8228	05/12/2023	1114316	Mechanic entered - Wipers and Washers Other Near side wiper	Removed wiper washer jet assembly Fitted new wiper washer hose and jet assembly.	1223546
8228	05/12/2023	1114316	WIPER WASHER HOSE+JET ASSY		1223546
8228	05/12/2023	1114324	Mechanic entered - Suspension Noisy Front off side sway bar		1223546
8228	05/12/2023	1114325	Mechanic entered - Suspension Other Front upper torque rod b		1223546
8228	05/12/2023	1114326	Mechanic entered - Suspension Other Front lower torque rod b		1223546
8228	05/12/2023	1114315	Mechanic entered - Body Other Near side rear air tank door p		1223546
8228	05/12/2023	1114315	STRUT GAS STAY 250Nm 520mm long		1223546
8228	05/12/2023	1114315	Consumables		1223546
8228	05/05/2023	1112620		Assisted Matt. Drained fluid replaced filter and refilled fluid	1222282
8228	05/05/2023	1112620	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1222282
8228	05/05/2023	1112620		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Carried out transmission service road tested after checked fluids all good.	1222282
8228	05/05/2023	1112620	OIL ZF GEARBOX SYNTHETIC ECOFLUID A PLUS		1222282
8228	05/03/2023	1112257	PTI Tablet Entered -Elec and Light - Exterior Lights left ha		1222112
8228	05/03/2023	1112257	Consumables		1222112
8228	04/18/2023	1109440	GLOBE 24V 70W H1		1220266
8228	04/18/2023	1109440	Elec and Light Exterior LightsFront Headlight not workin	checked and find out ront head light and 2x saloon not working. re-place interior lights and checked headlight and find out globe blown out. re-placed globe and checked it working ok. Complete.	1220266
8228	04/18/2023	1109440	Consumables		1220266
8228	04/17/2023	1109119		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist and repaire alternator connection	1220265
8228	04/17/2023	1109119		assisted Csaba to do fire safety and find out broken wire on alternator re-paired it and complete fire safety as per Check list. Complete.	1220265
8228	04/13/2023	1108574	Workshop Tablet Entered -very bright inside the cabin Elec a		1219916
8228	04/13/2023	1108574		checked bus and found cabin lights switched on turned off lights and no longer bright	1219916
8228	04/13/2023	1108574	Consumables		1219916
8228	04/12/2023	1108451	Workshop Tablet Entered -Elec and Light - Exterior Lights ri		1219565
8228	04/12/2023	1108451	GLOBE 24V 70W H1		1219565
8228	04/12/2023	1108452	Workshop Tablet Entered -headlight not working right side		1219565
8228	04/12/2023	1108451	Consumables	DVR entered twice.	1219565
8228	04/12/2023	1108452	Consumables		1219565
8228	04/11/2023	1091883		change back the ECU from 8230 and tested it working good	1219549
8228	04/01/2023	1091883	Mechanic entered - Engine Low Power	Bus 8228 running with bus 8230 ECU. Reason bus 8230 had a probel enging staling intermitten	1219549
8228	03/17/2023	1101348	Consumables		1219549
8228	03/17/2023	1101348		replaced guaged needs to be driven and tested	1219549
8228	03/17/2023	1103766		CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS	1219549
8228	03/16/2023	1103500	Service	Assisted.	1219549
8228	03/16/2023	1103500		VEHICLE SAFETY INSPECTION Completed	1219549
8228	03/16/2023	1103500		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Kuma	1219549
8228	03/10/2023	1101348	REPAIR GEARBOX TEMPERATURE GAU	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G339198 Receiving #:356376 Date :2023-03-10	1219549
8228	03/07/2023	1100667	Consumables		1219549
8228	03/07/2023	1101348	Mechanic entered - Dash Guages Not Working Temp gauge fitted	***Parts order form in 7/3/2023***	1219549
8228	03/07/2023	1100667	Elec and Light engine hatch micro switch u/s.	Replaced engine hatch micro switch.	1219549
8228	03/03/2023	1100667	SWITCH R/RIGHT ENGINE HATCH MERC 0500LE A0065450814		1219549
8228	03/02/2023	1100667	Elec and Light engine hatch micro switch u/s.	parts on order.	1219549
8228	02/08/2023	1091883	Mechanic entered - Engine Low Power	scaned for fault codes with stuart showed codes regarding ecu wrote down all codes unplugged ecu and plugged in tested ecu rescanned only showing fault codes regarding dash removed dash and plugged in 8229 dash working fine dash for 8228 menu selected button not working unplugged test ecu and plugged in 8228 €	1219549
8228	02/08/2023	1091883	Mechanic entered - Engine Low Power	ranb diagnostic tool to find fault codes. swapped Engine ECU with spare. all codes cleared from system. identified ECU fitted is for EURO 5 models. vehicle requires EURO 3 programed ECU.	1219549
8228	02/02/2023	1091641	HOSE P/STEERING RES - PUMP MERC BENZ 0500LE	PART NOT IN STOCK	1219549
8228	01/27/2023	1092602	Body coat hanger missing.	Replaced coat hanger.	1219431
8228	01/27/2023	1092602	Consumables		1219431
8228	01/24/2023	1090867	CLEAN AIR SYSTEM PIPES	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G336133 Receiving #:353527 Date :2023-01-30	1219549
8228	01/24/2023	1092602	COAT HOOK DRIVERS WAS0004	BOOKING PARTS OUT	1219431
8228	01/23/2023	1092602	Body coat hanger missing.	parts on order.	1219431
8228	01/18/2023	1090867	Fault#:38560 - Ops Entered - Fault - Breakdown Air System Fa	Completed top-up coolant and steering oil. Steam cleaned engine roadtested check air build up operation ok.	1219431
8228	01/18/2023	1091883	Mechanic entered - Engine Low Power	Check for fault Fault showing on dash MR 5909 adblue related bus don't have adblue. and INS 1125. Roadtest engine low power Check ECU found out ECU is coroaded and it has dirt inside. Removed and cleaned Refit wiring and erase fault code roadtest still low power. Carry/over.	1219431
8228	01/18/2023	1091856	Consumables		1219431
8228	01/18/2023	1091856		CARRY OUT A SERVICE AS PER CHECK LIST Completed check list. Done wheel nut tension with Abraham.	1219431
8228	01/18/2023	1091856	Consumables		1219431
8228	01/18/2023	1091856	Consumables		1219431
8228	01/18/2023	1091856	Consumables		1219431
8228	01/17/2023	1091641	Mechanic entered - Steering Other Steering pump hose need re	Removed hose fitted new.	1219431
8228	01/17/2023	1091641	HOSE P/STEERING RES - PUMP MERC BENZ 0500LE		1219431
8228	01/17/2023	1090867	WASHER P/STRG PIPE VOLVO B7RLE		1219431
8228	01/17/2023	1090867	Fault#:38560 - Ops Entered - Fault - Breakdown Air System Fa	Fitted new air compressor hose and adaptor Fitted new clean air line pipes and air dryer. Secured pipes. Fitted steering pump o ring and re fit steering pump Fitted new air compressor assembly and gasket. Fitted new air compressor coolant pipe hose and banjo bolts and washers. 5Re fit steering pipes and air compressor	1219431
8228	01/16/2023	1090867	AIR COMPRESSOR VOITH MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G335717 Receiving #:352815 Date :2023-01-16	1219431
8228	01/13/2023	1090867	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)		1219431
8228	01/13/2023	1090867	Fault#:38560 - Ops Entered - Fault - Breakdown Air System Fa	Drain coolant removed air compressor coolant pipe Removed air line pipes Removed air compressor assembly and steering pump. Removed air dryer condenser drain valve check valve and air line pipes. Removed and replace rear air bag control valve air line o ring kits. Removed air dryer air line hose and fittings found out	1219431
8228	01/13/2023	1090867	WASHER VOITH COMP COOL PIPE MERC 0500LE		1219431
8228	01/13/2023	1090867	GASKET AIR COMPRESSOR MT MERC BENZ 0500LE 49A9446		1219431
8228	01/13/2023	1090867	O RING P/STRG PUMP MERC BENZ 0500LE A0159974845		1219431
8228	01/13/2023	1090867	PIPE COOLANT VOITH AIR COMP MERC 0500LE		1219431
8228	01/13/2023	1090867	UNION BANJO VOITH COMP COOLING PIPE MERC 0500LE		1219431
8228	01/13/2023	1090867	NUT VOSS 232 22mm MERC BENZ 0500LE 49G4527WABCO		1219431
8228	01/13/2023	1090867	ELBOW COUPLING 90 DEGREES MERC BENZ 0500LE		1219431
8228	01/13/2023	1090867	FILTER AIR DRY MAN A91 MERC 0500LE OH1830 3090288		1219431
8228	01/13/2023	1090867	HOSE COMP - UNLOADER MERC BENZ 0500 A0014292135 A0014292735		1219431
8228	01/13/2023	1090867	COUPLING AIR HOSE - COMP MERC BENZ 0500LE A0089970889		1219431
8228	01/13/2023	1090867	VALVE AIR FILTER CHECK 22mm CYCLONE		1219431
8228	01/13/2023	1090867	O-RING KIT LARGE VOSS(A6739970145)		1219431
8228	01/12/2023	1090867	Fault#:38560 - Ops Entered - Fault - Breakdown Air System F	Attened to B/Down found faulty air system call tow truck waitting for tow truk 2.30 hr	1219431
8228	01/12/2023	1090867	Fault#:38560 - Ops Entered - Fault - Breakdown Air System F	Assisting	1219431
8228	01/12/2023	1090867	DIRECT PURCHASE - TOWING	GB-EAG001 EAGLE TOWING G336252 RECV 353362	1219431
8228	12/28/2022	1088394		Tension wheel nuts position 1 and 2 with Satheesh.	1216644

8228	12/28/2022	1088394		Assisted Rene.	1216644
8228	12/23/2022	1088068	Consumables		1216636
8228	12/23/2022	1088068	Mechanic entered - Wheels and Tyres Worn Pos.2 worn.	Fitted new orig tyres pos.12 and tensioned wheel nuts w/ Satheesh.	1216636
8228	12/23/2022	1088068	TYRE 295/80R22.5 NEW		1216636
8228	12/23/2022	1087870	Mechanic entered - Engine Other Rectify squeaking noise.	Found out alternator bracket bolts loose and alt. pulley rubbing on chassis head bolt. Re-tightened alternatorbracket bolts and adjusted belt.	1216636
8228	12/23/2022	1087869	Mechanic entered - Brakes Other Front brake rotors needs rep	Replacement of front break rptors completed. Passed break test road tested check break operation Ok . Checked temperature OK . No break warning light dash Checked bearing play OK tention wheel nuts with Stheesh	1216636
8228	12/22/2022	1087869	Mechanic entered - Brakes Other Front brake rotors needs rep	Fitted new rotor front n/s. CARRY/OVER	1216636
8228	12/22/2022	1087869	ROTOR FRONT & REAR MERC BENZ 0500LE A9424230112		1216636
8228	12/22/2022	1087869	BOLT FRT BRAKE DISC MERC 0500LE A910105014019		1216636
8228	12/22/2022	1087869	BRAKE PAD SET SCANIA MERC BENZ 0500LE		1216636
8228	12/22/2022	1087477	Mechanic entered - Air System Other Rectify airleak. (rear b	Replaced airline oring-kits.	1216636
8228	12/20/2022	1087447		VEHICLE SAFETY INSPECTION	1216451
8228	12/20/2022	1087447		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1216451
8228	12/20/2022	1087447		Completed VSI and tensioned wheel nuts w/ Nick.	1216451
8228	12/20/2022	1087477	O-RING KIT LARGE VOSS(A6739970145)		1216451
8228	12/20/2022	1087477	Mechanic entered - Air System Other Rectify airleak. (rear b	Started replacing airline oring kits in rear brake modulator valve. carry/over.	1216451
8228	12/16/2022	1084845	Drv entered - Wipers and Washers Wipers Loose	Secuere wipers.	1215885
8228	11/29/2022	1083714	Workshop Tablet Entered -Warning Lights - Engine	assisted	1213414
8228	11/29/2022	1083714	Workshop Tablet Entered -Warning Lights - Engine	run Actia check fault codes clean Engine ECU plug and injector unit pump wire conector fitted same as road tested bus ok.	1213414
8228	11/29/2022	1083715	Workshop Tablet Entered -Warning Lights - Engine malfunction	removed ecu connector and blew with air gun and checked if any pins were damaged and checked if there were fault codes no codes showed up	1213414
8228	11/29/2022	1083715	Workshop Tablet Entered -Warning Lights - Engine malfunction	check ok.	1213414
8228	11/29/2022	1083671	Mechanic entered - Body Other rear floor hatch bolt broken	removed rear floor hatch bolt was broken before hand sent bus to east coast to get new hook weld on new hook welded on renistalled floor hatch all good	1213414
8228	11/29/2022	1083671	FLOOR HATCH SCREWS 13405 + 30628		1213414
8228	11/29/2022	1083725	BODYSHOP - WELD LUG ON FLOOR HATCH - INTERIOR		1213414
8228	11/29/2022	1083725	Consumables		1213414
8228	11/15/2022	1081020		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Service Complete as per Check list. Complete.	1210966
8228	11/04/2022	1079153	Drv entered - Elec and Light AM-FM Radio	re-placed radio and checked it workingok. Complete.	1209736
8228	11/04/2022	1079153	RADIO 12/24V 3' LCD MULTIMEDIA RECEIVER		1209736
8228	11/04/2022	1079153	Consumables		1209736
8228	10/19/2022	1076463		Tension wheel nuts position 5 and 6 with Kuma.	1207594
8228	10/19/2022	1076463		Assisted Rene.	1207594
8228	10/19/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys	check and repaire the connections	1207594
8228	10/19/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys	asiist Csaba to checke the bus and the engine start was working did check for power and when checked the diagram find out connection for ECU unit then did continuity test and find then clean the ECU unit and checked started working again. bad connection makes it not working so it is working ok now. Complete.	1207594
8228	10/18/2022	1076191		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts w/ Rene.	1207594
8228	10/18/2022	1076191		VEHICLE SAFETY INSPECTION Completed VSI.	1207594
8228	10/18/2022	1076205	Mechanic entered - Wheels and Tyres Worn Pos.6 worn	Fitted new orig. tyres pos.56 and tensioned wheel nuts w/ Rene.	1207594
8228	10/18/2022	1076205	TYRE 295/80R22.5 NEW		1207594
8228	10/18/2022	1076205	Consumables		1207594
8228	10/18/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys		1207594
8228	10/18/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys		1207594
8228	10/18/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys		1207594
8228	10/18/2022	1075872	BELT MICRO V SERPENT 9 RIB 2120mm LNG		1207594
8228	10/18/2022	1075872	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1207594
8228	10/18/2022	1076056	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	Removed	1207594
8228	10/17/2022	1075872	Fault#:38480 - Ops Entered - Fault - Breakdown Belts Pulleys	Bus B/D princes Hy after Akia boken belt tempery repaired driver drive the bus to depot. left from W/S 15.30 back 17.00. used B/D Van	1207594
8228	10/13/2022	1075158	Fault#:38476 - Ops Entered - Fault - Breakdown Overheating/	As above	1207214
8228	10/13/2022	1075158	Ops Entered - Fault - Warning Lights Engine - Route: 900v -	Bus B/D Huntingvale station lost water pump Idler pully . used cabletise repaired temperrly drive drive the bus to depot. Left from W/S 8.15am back 9.50am used B/D van replaced the belt and puly road tested ok	1207214
8228	10/13/2022	1075158	BELT MICRO V SERPENT 9 RIB 2120mm LNG		1207214
8228	10/13/2022	1075158	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1207214
8228	10/13/2022	1075158	SCREW IDLER PULLEY MTG MERC BENZ 0500LE		1207214
8228	09/28/2022	1071780	PTI Tablet Entered -Elec and Light - Exterior Lights Front	check and replaced park light globe	1204961
8228	09/28/2022	1071780	Consumables		1204961
8228	09/26/2022	1071440		Re-tensioned wheel nuts w/ Roshan pos.3.4	1204202
8228	09/26/2022	1071440		assisted with abraham.	1204202
8228	09/24/2022	1071136	Mechanic entered - Wheels and Tyres Other P.o 3-4 tyre worn	P.O 3-4 tyre worn. Removed and fitted 2 new tyres wheels tension with Kuma	1204202
8228	09/24/2022	1071136	TYRE 295/80R22.5 NEW		1204202
8228	09/24/2022	1071136	Consumables		1204202
8228	09/24/2022	1071152	Mechanic entered - Air System Air_Leak Rear	replaced air line seals.	1204202
8228	09/24/2022	1071152	O-RING KIT SMALL VOSS(A0309971748)		1204202
8228	09/24/2022	1071152	O-RING KIT LARGE VOSS(A6739970145)		1204202
8228	09/24/2022	1071111		CARRY OUT A SERVICE AS PER CHECK LIST	1204202
8228	09/24/2022	1071111		completed.	1204202
8228	09/24/2022	1071111	Consumables		1204202
8228	09/24/2022	1071111	Consumables		1204202
8228	09/24/2022	1071111	Consumables		1204202
8228	09/24/2022	1071111	Consumables		1204202
8228	09/01/2022	1067276	Elec and Light Exterior LightsHeadlights not working	Replaced globe.	1201165
8228	09/01/2022	1067276	GLOBE 24V 70W H1		1201165
8228	09/01/2022	1067276	Consumables		1201165
8228	08/31/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	found damage wire near main wire harnes y joine replaced wire.secure all wire harnes road tested bus ok.	1201158
8228	08/31/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Repair and replace all removed wiring in bus from continuity testing whilst looking for broken wire. Complete.	1201158
8228	08/30/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	check door inter lock wire harnes c/o	1201158
8228	08/25/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	try to find damage 4232 wire	1201158
8228	08/25/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Started to locate broken wire 4232 unfasten some of the wiring in the electrical centre to get better access to test wiring. Needed to probe wiring at several places along the chassis to narrow down location broken wire is between the underneath of driver's platform and infront of the rear axle waiting for hoist to be availa	1201158
8228	08/24/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Wire 4232 finally traced to pressuere switch on N/S not O/S as previously informed. Conducted test of switch operation and continuity of earth wire to chassis all good. Performed continuity test of 4232 wire from switch to plug x202.0 at electrical center wire broken between these two points. C/O	1201158
8228	08/24/2022	1065544		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1201158
8228	08/24/2022	1065544		Completed by ATS	1201158
8228	08/23/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Discovered that bus is intermittently losing the handbrake signal from the chassis side of electrics on wire number 4232.	1201158
8228	08/22/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Connect lat top to RPD unit and check inputs outputs.C/O.	1201158
8228	08/12/2022	1060924	O-RING KIT LARGE VOSS(A6739970145)		1201158
8228	08/12/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	replaced front brake propotional value and fixed air leake now without RPD door brakes working need to check RPD system swap with other bus rpd unit still same c/o	1201158
8228	08/09/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b		1201158
8228	08/09/2022	1060924		removed front brake proportional value c/o	1201158
8228	08/05/2022	1060924	SWITCH PARK BRAKE 6.7 BAR MERC BENZ 0500LE 50G3111		1201158
8228	08/05/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	replaced park brake switch and check air system need to fix air leaks and order parts c/o	1201158
8228	08/05/2022	1060924	VALVE PROPORTION AIR/ ELE MERC	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G326454 Receiving #:342871 Date :2022-08-08	1201158
8228	08/03/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	check door brake n/w swap RPD unit with other o500 still same c/o	1201158
8228	08/03/2022	1060924	Ops Entered - Fault - Brakes Park_Brake Not Holding - door b	Print out wiring diagram for bus stop brake and park brake circuit check RPD connections.	1201158
8228	07/25/2022	1059174		VEHICLE SAFETY INSPECTION Completed check list.	1199782
8228	07/25/2022	1059174		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done Assisted by Abraham for wheel nut tension.	1199782
8228	07/20/2022	1058178	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1199053
8228	07/20/2022	1058178	DRYER AIR ASSY MERC 0500LE(A0004302915)		1199053
8228	07/20/2022	1058178	VOSS NUT 232 16MM MERC BENZ 0500LE A0009975334		1199053
8228	07/20/2022	1058178	AIR DRYER FITTING ELBOW 16MM MERC BENZ 0500LE		1199053

8228 07/20/2022 1058178 PLUG 12MM X 1.0MM		1199053
8228 07/20/2022 1058178		1199053
8228 07/20/2022 1058178 VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air system service completed. Air pipes didnt need removing as they didnt have build up inside and werent blocked Washed area after work completed	1199053
8228 07/20/2022 1058178 SILENCER AIR DRYER MERC BENZ 0500LE		1199053
8228 07/18/2022 1057886 PTI Tablet Entered -REAR NUMDER PLATE LIGHT IS DAMAGEDElec a	REplaced LED light.	1198942
8228 07/18/2022 1057886 LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1198942
8228 07/18/2022 1057886 Consumables		1198942
8228 07/06/2022 1055651	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list	1197409
8228 07/06/2022 1055651 OIL AC COMPRESSOR		1197409
8228 07/06/2022 1055651 FILTER DRYER AIR COND THERMO KING		1197409
8228 07/06/2022 1055651 FAN CONDENSOR A/C CITI-RT		1197409
8228 07/06/2022 1055651	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced right out side condenser fan motor service as per list	1197409
8228 06/30/2022 1054784 Consumables		1196443
8228 06/30/2022 1054784 Tablet Entered - front ns park light out	replaced globe.	1196443
8228 05/30/2022 1048234 ANNUAL BUS INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G322099 Receiving #:338193 Date :2022-05-30	1191575
8228 05/25/2022 1048234 EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER		1191216
8228 05/25/2022 1048234	VEHICLE SAFETY INSPECTION	1191216
8228 05/25/2022 1048234	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1191216
8228 05/25/2022 1048234	ANNUAL SAFETY INSPECTION SERIAL #RSI043426- WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 Complete RSI	1191216
8228 05/25/2022 1048234	Assisting	1191216
8228 05/24/2022 1047968 Mechanic entered - Suspension Noisy suspention valve Leaking	Installed new valve and checked ok.	1191116
8228 05/24/2022 1047968 VALVE ECAS MERC BENZ 0500LE ->	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G320216 Receiving #:337728 Date :2022-05-24	1191116
8228 05/24/2022 1047968 Mechanic entered - Suspension Noisy suspention valve Leaking	replaced the valve	1191116
8228 05/24/2022 1047964 Carry out final inspection for RSI	completed and repaired one seat	1191116
8228 05/24/2022 1048054 Mechanic entered - Body Wheel Chair Ramp Not aligned proper	repair wheelchair ramp	1191116
8228 05/24/2022 1047964 Carry out final inspection for RSI	completed and Tesioned wheel nuts with Sisil.	1191116
8228 05/21/2022 1047285 Mechanic entered - Body Other O/s 3rd Reflector Missing.	fitted new one 19/05/2022	1190745
8228 05/20/2022 1047285 Mechanic entered - Body Other Driver fan mounting loose.	replaced with steel plate also changed the fan	1190745
8228 05/20/2022 1047285 24V DRIVERS FAN (USE FASCO ONLY)		1190745
8228 05/20/2022 1047285 Body Water Leaks Roof	repaired with cylon	1190745
8228 05/20/2022 1047285 Mechanic entered - Body Water Leaks Roof	holl in top of the windscreen repaired with cylon	1190745
8228 05/20/2022 1047285 Mechanic entered - Body Other Mirror Arms rusted.	painted	1190745
8228 05/20/2022 1047291 Mechanic entered - Air System Air_Leak Front	Emerjuncy exit switch valve leak replaced valve	1190745
8228 05/19/2022 1047019 Mechanic entered - Gearbox Driveline Other coolant leaks thr		1190745
8228 05/19/2022 1047019 VALVE BALL 1/2 HEATER 20MM		1190745
8228 05/19/2022 1047019 Service	Changed thermostate 2 seal Heater tap near transmission. the work hours are mistakenly written 8 hours it is just 3 hours	1190745
8228 05/19/2022 1047285 Body Water Leaks Roof	As below	1190745
8228 05/19/2022 1047285 Mechanic entered - Body Other Wind screen Blinds mount broke	repaired with new screw	1190745
8228 05/19/2022 1047287 Mechanic entered - Body Other Rust in the front of the chasi	cleaned and painted	1190745
8228 05/19/2022 1047286 Mechanic entered - Body Other steam clean the bus	completed	1190745
8228 05/19/2022 1047285 Mechanic entered - Body Wheel Chair Ramp Not aligned properl	Reff defect 928179	1190745
8228 05/19/2022 1047285 REFLECTOR AMBER HELLA 94x44mm		1190745
8228 05/19/2022 1047291 Mechanic entered - Air System Air_Leak Front		1190745
8228 05/19/2022 1047291 VALVE BOTTOM DOOR SWITCH REG/GREEN		1190745
8228 05/18/2022 1047019 Mechanic entered - Gearbox Driveline Other coolant leaks thr		1190745
8228 05/18/2022 1047019 Mechanic entered - Body Other Front Door Sensitive Edge rubb	fitted back the rubber	1190745
8228 05/13/2022 1046026	PRE ANNUAL SAFETY INSPECTION CHECK completed	1190419
8228 05/13/2022 1046026	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1190419
8228 05/13/2022 1046026	Assisted to complete the Inspection.	1190419
8228 05/13/2022 1046046 Mechanic entered - Engine Other No. 6 rocker cover oil leak.	fitted new Cover and gasket.	1190419
8228 05/13/2022 1046046 COVER ROCKER MERC BENZ 0500LE A4570100330		1190419
8228 05/13/2022 1046212 Tablet Entered - Brakes handbrake know part is missing	replaced new park brake valve.	1190419
8228 05/13/2022 1046212 VALVE PARK BRAKE MERC BENZ 0500LE A0034307581		1190419
8228 05/12/2022 1045927 Tablet Entered - Brakes handbrake know part is missing	defect entered twice.	1190062
8228 05/09/2022 1045079	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed Tune up as per checklist.	1189500
8228 05/09/2022 1045128 PUMP WASHER 24 VOLT		1189500
8228 05/09/2022 1045128 WIPER BLADE ASSY 1000mm N102(TRP1000)		1189500
8228 05/09/2022 1045128 Mechanic entered - Wipers and Washers Washers Not Working &		1189500
8228 05/09/2022 1045158 Air System Air_Leak Rear	Replaced o/s rear of rear air bag. Replaced 2X air fittings kit.	1189500
8228 05/09/2022 1045158 O-RING KIT LARGE VOSS(A6739970145)		1189500
8228 05/09/2022 1045158 AIRBAG FRONT/RR MERC 0405 0500LE SCANIA VOLVO		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022 1045078 Consumables		1189500
8228 05/09/2022		

8228	02/22/2022	1030765	GLOBE 24V 70W H1		1178630
8228	02/22/2022	1030765	Consumables		1178630
8228	02/21/2022	1030353		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1178341
8228	02/21/2022	1030353		Completed by ATS	1178341
8228	02/04/2022	1026785		VEHICLE SAFETY INSPECTION Assisted Abraham with Safety inspection as per checklist.	1176160
8228	02/04/2022	1026785		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1176160
8228	02/04/2022	1026785		Completed VSI and tensioned wheel nuts w/ Nick.	1176160
8228	02/04/2022	1026788	Mechanic entered - Suspension Other n/s rear of rear airbag	Fitted new airbag n/s rear of rear.	1176160
8228	02/04/2022	1026788	AIRBAG FRONT/RR MERC 0405 0500LE VOLVO B10BLE RR		1176160
8228	02/04/2022	1026802	Mechanic entered - Body Other Foot brake padal rubber pad wo	Fitted new pedal pad.	1176160
8228	02/04/2022	1026802	PAD BRAKE PEDAL RUBBER FLAT MERC 500LE(A110291018201)		1176160
8228	02/04/2022	1026787	Mechanic entered - Air System Air_Leak Rear Airtank drain va	Fitted new o-ring repair kit in fittings and new air tank drain valves.	1176160
8228	02/04/2022	1026787	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 49G7901		1176160
8228	02/04/2022	1026787	O-RING KIT LARGE VOSS(A6739970145)		1176160
8228	02/01/2022	1025954		Retensioned all wheel nuts on pos 3/4 and 5/6 all rear with Ben	1175598
8228	02/01/2022	1025954		tensioned wheelnuts with Matt.	1175598
8228	01/31/2022	1025424	Mechanic entered - Wheels and Tyres Other over heated rear w	Checkec rear brake pads18mm Brake chamber replaced in 08/11/2021 Readjusted rear brakeit was tighth park brake brake off very hard to sping wheel. road teste 20 km after check temp front 28C/29C Rear 48C/54C. brake tested pass. Removed wheel and check caliper self adjuesment okCheaked Brake booster Door br	1175480
8228	01/31/2022	1025424	Consumables		1175480
8228	01/20/2022	1023863		assisted	1174045
8228	01/20/2022	1023863		Re-tensioned wheel nutsbw/ Abraham pos.12	1174045
8228	01/19/2022	1023561	Mechanic entered - Wheels and Tyres Other wheel arch missing	fitted New wheel Arch.	1173918
8228	01/19/2022	1023561	WHEEL ARCH BRUSH 12065		1173918
8228	01/19/2022	1023561	RUBBER WHEEL ARCH 41294		1173918
8228	01/19/2022	1023561	Consumables		1173918
8228	01/19/2022	1023393	Mechanic entered - Suspension Other O/S Front Air bag Leakin	Replaced the front Air bags and checked for leaks.	1173918
8228	01/19/2022	1023393	Mechanic entered - Suspension Other O/S Front Air bag Leakin	replaced The air bag with Sathees	1173918
8228	01/19/2022	1023301	Mechanic entered - Brakes Other rear brake pads worn.	Replaced Rear rotors Adjust wheel bearings and torqued all nuts to specifications.	1173918
8228	01/19/2022	1023301	Mechanic entered - Brakes Other rear brake pads worn.	Fitted back Brake boosters new pads tensioned wheel nut with Shathees also road test done by Sathees	1173918
8228	01/19/2022	1023301	Mechanic entered - Brakes Other rear brake pads worn.		1173918
8228	01/19/2022	1023301	Mechanic entered - Brakes Other rear brake pads worn.		1173918
8228	01/18/2022	1023393	AIRBAG FRONT/RR MERC 0405 0500LE VOLVO B10BLE RR		1173918
8228	01/18/2022	1023393	Mechanic entered - Suspension Other O/S Front Air bag Leakin	As below	1173918
8228	01/18/2022	1023301	Mechanic entered - Brakes Other rear brake discs worn 36mm.	Road and brake tested ok.	1173918
8228	01/18/2022	1023301	Mechanic entered - Brakes Other rear brake pads worn.	Fitted back brake booster and pads.Tentioned wheel nuts with sisil.	1173918
8228	01/18/2022	1023301	LOCK WASHER RR HUB NUT MERC BENZ 0500LE E6		1173918
8228	01/18/2022	1023301	BOLT REAR DISC TORX HD MERC BENZ 0500LE A9429902804		1173918
8228	01/18/2022	1023301	BRAKE PAD SET SCANIA MERC BENZ 0500LE		1173918
8228	01/18/2022	1023301	Mechanic entered - Brakes Other rear brake discs worn 36mm.	removed rear hub fitted back with new rooters c/o	1173918
8228	01/18/2022	1023301	ROTOR FRONT & REAR MERC BENZ 0500LE A9424230112		1173918
8228	01/14/2022	1022742		CARRY OUT A SERVICE AS PER CHECK LIST completed.	1173918
8228	01/14/2022	1022742	Consumables		1173918
8228	01/14/2022	1022742	Consumables		1173918
8228	01/14/2022	1022742	Consumables		1173918
8228	01/14/2022	1022742	Consumables		1173918
8228	01/05/2022	1020842	Warning Lights - Dash fault code is INS 1125	Removed dash fascia. Cleaned function buttons with contact cleaner to enable operation. Changed display from German to English and cleared fault codes. Complete.	1172885
8228	01/05/2022	1020842	Consumables		1172885
8228	01/04/2022	1020842	Warning Lights - Dash fault code is INS 1125	Bus not at depot. It appears that code will not clear due to damaged button in dash. Tomorrow we will try to swap dash with a similar bus to clear fault code. Carry over.	1172678
8228	12/30/2021	1020224	Tablet Entered - Elec and Light - AM-FM Radio not working	checked and fixed radio power switch radio working	1172247
8228	12/30/2021	1020224	Consumables		1172247
8228	12/20/2021	1018465	Mechanic entered - Elec and Light Exterior Lights rear numbe	replaced both broken no. plate lights.	1171425
8228	12/20/2021	1018465	LED FRONT POSITION MARKER LIGHT		1171425
8228	12/20/2021	1018465	Consumables		1171425
8228	12/20/2021	1018849	Mechanic entered - Body - (nsf) wheel arch brush damaged	replaced.	1171425
8228	12/20/2021	1018849	WHEEL ARCH BRUSH 12065		1171425
8228	12/20/2021	1018849	Consumables		1171425
8228	11/30/2021	1013807	Mechanic entered - Body - Fuel cap not closing	job completed by others.	1168903
8228	11/30/2021	1013807	Consumables		1168903
8228	11/29/2021	1013807	Mechanic entered - Body - Fuel cap not closing	removed fuel cap for inspection by ranjith.	1168805
8228	11/25/2021	1013807	Mechanic entered - Body - Fuel cap not closing	checked. lugs on cap worn. needs replacing. parts request form submitted.	1168128
8228	11/23/2021	1013306		VEHICLE SAFETY INSPECTION	1168088
8228	11/23/2021	1013306		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1168088
8228	11/23/2021	1013306		Assisting	1168088
8228	11/23/2021	1013306	REFLECTOR AMBER HELLA 94x44mm		1168088
8228	11/23/2021	1013508	Mechanic entered - Elec and Light - Exterior Lights rear num	refit light.	1168088
8228	11/23/2021	1013508	Consumables		1168088
8228	11/23/2021	1013354	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE	Complete	1168088
8228	11/23/2021	1013354	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE	Assisting	1168088
8228	11/16/2021	1011969	Mechanic entered - Wheels and Tyres - Oil on rim of tyre	checked & found excessive oil from wheel nuts on the rim clean rims.	1166875
8228	11/16/2021	1011969	Consumables		1166875
8228	11/16/2021	1011783		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST CCTV service complete.	1166875
8228	11/15/2021	1011695	Mechanic entered - Elec and Light - Exterior Lights front n/	Replaced globe.	1166586
8228	11/15/2021	1011694	Mechanic entered - Elec and Light - Exterior Lights front n/	Replaced globe.	1166586
8228	11/15/2021	1011694	Consumables		1166586
8228	11/15/2021	1011695	Consumables		1166586
8228	11/10/2021	1010680	Mechanic entered - Body - Fuel cap not closing	Adjust the lock pin.	1165864
8228	11/10/2021	1010680	Consumables		1165864
8228	11/09/2021	1008300	Engine - Check all coolant hoses and replace if required	replaced 5 coolent hoses steam cleaned road tested ok	1165730
8228	11/09/2021	1008300	Engine - Check all coolant hoses and replace if required	replaced remaining coolant hoses steam cleaned and road tested all okay	1165730
8228	11/09/2021	1008300	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G		1165730
8228	11/09/2021	1008300	HOSE COOLANT TAPERED 60/70 MERC BENZ 0500LE		1165730
8228	11/09/2021	1008300	HOSE ELBOW RADIATOR TAPERED MERC BENZ 0500LE A0008321794 (G)		1165730
8228	11/09/2021	1010118	BOOSTER BRAKE LHR MERC BENZ 0500LE E6	Jess replaced O/R brake booster and tested brake road tested ok	1165730
8228	11/09/2021	1010118	Mechanic entered - Brakes - N/R brake booster faulty		1165730
8228	11/09/2021	1010118	BOOSTER BRAKE RHR MERC BENZ 0500LE E6		1165730
8228	11/09/2021	1010118	Mechanic entered - Brakes Other N/R brake booster faulty	replaced o/r brake booster brake tested and road tested all ok	1165730
8228	11/08/2021	1008300	Engine - Check all coolant hoses and replace if required	drain replaced tranmission coolent hose more ordered	1165730
8228	11/08/2021	1008300	Engine - Check all coolant hoses and replace if required	drained coolant and started replacing hoses as required	1165730
8228	11/08/2021	1008300	HOSE RADIATOR UPPER /LOWER MER	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G310380 Receiving #:325526 Date :2021-11-09	1165730
8228	11/08/2021	1008300	HOSE ELBOW RADIATOR MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G310380 Receiving #:325526 Date :2021-11-09	1165730
8228	11/08/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff	fitted new diff to the bus	1165730
8228	11/08/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff	replaced diff sealed with silicon. put boosters back and topped up diff oil	1165730
8228	11/08/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff		1165730
8228	11/08/2021	1008299	SILICONE SEALER GREY VOLVO 30B0700		1165730
8228	11/08/2021	1008299	DIFF PLUG		1165730

8228	11/08/2021	1010118	Mechanic entered - Brakes - N/R brake booster faulty	replaced N/R brake booster c/o	1165730
8228	11/05/2021	1008299	REPAIR /OVERHAUL DIFFERENTIAL	Creditor #:-GB-BAY002 BAYSWATER DIFF SERVICE PTY LTD P/O #:-G309956 Receiving #:325279 Date :2021-11-05	1165730
8228	10/28/2021	1008197	Mechanic entered - Engine - One of the wire loom connector	Fixed	1165730
8228	10/28/2021	1008281	Fluid Leaks Repaire fuel leak on fuel tank hose	Repaired	1165730
8228	10/28/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff	removed the Diff	1165730
8228	10/28/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff	Diff removed	1165730
8228	10/28/2021	1008299	Mechanic entered - Gearbox Driveline Noisy Diff	removed driveshaft and diff with tayla and sibil	1165730
8228	10/28/2021	1008081	Brakes Foot_Brakes Leaking Air.	Removed and fitted new proportioning valve Checked for leaks okay	1165730
8228	10/28/2021	1008081	Brakes Foot_Brakes Leaking Air.	Assist Tayla	1165730
8228	10/28/2021	1008081	VALVE PROPORTIONING AIR/ ELE MERC BENZ 0500LE 50G1405WABCO		1165730
8228	10/27/2021	1008080	Brakes Foot_Brakes Leaking Air	defect entered twice.	1165730
8228	10/27/2021	1008081	Brakes Foot_Brakes Leaking Air.	checked & found proportional relay valveparts on order.	1165730
8228	10/22/2021	1007199	Mechanic entered - Elec and Light Exterior Lights rear numbe	missing screws Replaced with New screws and mounted Back.Checked Lights working fine.	1164844
8228	10/22/2021	1007199	Consumables		1164844
8228	09/11/2021	998881		VEHICLE SAFETY INSPECTION `Carry out Safety inspection as per check list.replaced front door steppedge insert (yellow) 1mDriver compartment Butterfly vent.	1159262
8228	09/11/2021	998881		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1159262
8228	09/11/2021	998881	BUTTERFLY AIR VENT 300516		1159262
8228	09/11/2021	998881	EDGE STEP EDGE INSERT YELLOW 40MM P/M 2B10378SER		1159262
8228	09/09/2021	998520	Consumables		1159115
8228	09/09/2021	998520	Consumables		1159115
8228	09/09/2021	998520	Consumables		1159115
8228	09/09/2021	998520	Consumables		1159115
8228	09/09/2021	998520	Consumables		1159115
8228	09/09/2021	998520		CARRY OUT A SERVICE AS PER CHECK LIST completed a service as per check list repaired coolant leak rear side of engine..	1159115
8228	09/03/2021	996974	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.	1158067
8228	09/03/2021	996974	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.	1158067
8228	08/27/2021	995375		Tensioned wheel nuts pos 5 and 6.	1156632
8228	08/27/2021	995375		Assisted	1156632
8228	08/26/2021	995030	Mechanic entered - Wheels and Tyres Worn Tyre #6 wornout.	Removed and replace Fitted two new recap. Position 5 return to rack. Tensioned wheel nuts Assisted by Satheesh.	1156416
8228	08/26/2021	995030	TYRE 295/80R22.5 RECAP		1156416
8228	08/26/2021	995030	Consumables		1156416
8228	08/10/2021	990708	CLEAN AIR SYSTEM PIPES	Creditor #:-GB-HMG001 HM GEM ENGINES P/O #:-G304489 Receiving #:319121 Date :2021-08-13	1154211
8228	08/09/2021	990708		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST carried out air system overhaul as per check list. no leaks.	1153646
8228	08/09/2021	990708	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1153646
8228	08/09/2021	990708	AIR DRYER ASSY MERC BENZ 0500LE(A0004302915)		1153646
8228	08/09/2021	990708	VALVE DRAIN CONDENSOR MERCEDES 0500LE(A0054327401)		1153646
8228	08/09/2021	990708		Assiest.	1153646
8228	08/05/2021	990208	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Assisted Satheesh.	1153122
8228	08/05/2021	990208		Assisting Diff service completed. Drained old oil and filled with 15 litres of Synthetic FM 75W-140.	1153122
8228	08/05/2021	990208	OIL DIFFERENTIAL OIL SYNTHETIC FM 75W-140 (3083208)		1153122
8228	08/03/2021	989726	Replaced by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1152843
8228	07/27/2021	988081	Ops Entered - Body - Front Door Operation Faulty	checked and fixed door switch power wire conector bus ok.	1151533
8228	07/27/2021	988081	Consumables		1151533
8228	07/22/2021	987365		VEHICLE SAFETY INSPECTION Completed	1151131
8228	07/22/2021	987365		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Abraham.	1151131
8228	07/22/2021	987371	Mechanic entered - Elec and Light Interior Lights 1X flouro	R/R inveter and flouro tube.	1151131
8228	07/22/2021	987371	INVERTER 24V 15-36W (KIRG)		1151131
8228	07/22/2021	987371	Consumables		1151131
8228	07/19/2021	986298		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1150133
8228	06/07/2021	978798	*NO PARTS IN STORE*- Mechanic entered - Body - Disable stop	Removed and replaced disabled stopbell switch.	1144448
8228	06/07/2021	978798	BELL PUSH FOR WHEEL CHAIR PASS (40792)		1144448
8228	06/07/2021	978798	Consumables		1144448
8228	06/07/2021	978793	Mechanic entered - Air System Air_Leak Rear Air leak in fiti	Peplaced airline fittings o-ring kit.	1144448
8228	06/07/2021	978793	KIT O-RING SMALL VOSS (A0309971748)		1144448
8228	06/07/2021	978793	Mechanic entered - Air System Air_Leak Rear Air leak in fiti		1144448
8228	06/07/2021	978773	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)		1144448
8228	06/07/2021	978773	FILTER FUEL MERCEDES (A5410900151)		1144448
8228	06/07/2021	978773	FILTER OIL FILTER MERCEDES A0001801709		1144448
8228	06/07/2021	978773	FILTER OIL FILTER MERCEDES A0001801709		1144448
8228	06/07/2021	978773	OIL ANALYSIS KIT DETECTA AZ-DET25 3350-601 23448457		1144448
8228	06/07/2021	978773	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)		1144448
8228	06/07/2021	978773	OIL FAN DRIVE OIL MERC BENZ 0500LE		1144448
8228	06/07/2021	978773	FILTER STEERING FILTER (153468) (0153468)(349619)		1144448
8228	06/07/2021	978773	OIL ENGINE MOBIL DELVAC MODERN 15W-40		1144448
8228	06/07/2021	978773	FILTER AIR FILTER MERC BENZ 0500LE A0040941704		1144448
8228	06/07/2021	978773		CARRY OUT C SERVICE AS PER CHECK LIST Completed C service and tensioned all wheel nuts w/ Satheesh.	1144448
8228	06/07/2021	978773			1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST Completed B service.	1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed A service.	1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	06/07/2021	978773	Consumables		1144448
8228	05/28/2021	976547	CARRY OUT ANNUAL INSPECTION	Creditor #:-GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:-G299721 Receiving #:313738 Date :2021-05-31	1143170
8228	05/28/2021	977010	Low power. Re-starting engine helps for short period of tim	Drove bus up and down eastlink shifting well although its very loud whining in 3rd 4th and 5th gears 6th isn't too bad. Checked gearbox fluid good condition and right level No drive line issues backlash normal. Gets to 100 in normal amount of time for a bus with over 1M kms on it.	1142538
8228	05/28/2021	977072	Low power. Re-starting engine helps for short period of tim	Ref W/O 977010 same job defect.	1142538
8228	05/28/2021	974718	repair rust as required	Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:-G299979 Receiving #:313914 Date :2021-06-02	1143461
8228	05/26/2021	976547	Service	VEHICLE SAFETY INSPECTION completed	1142424
8228	05/26/2021	976547	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1142424
8228	05/26/2021	976547		ANNUAL SAFETY INSPECTION SERIAL #PASS RSI 037930 26/05/2021 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1142424
8228	05/26/2021	976547	Service	Assisting Steem cleaned around fuel tank	1142424
8228	05/26/2021	976638	Mechanic entered - Engine Other Radiator bottom mount bolt m	Checked radiator mounts the lower one closes to the air dryer is a sleeve style bush there shouldn't be a bolt through it.	1142424
8228	05/26/2021	976636	Mechanic entered - Fluid Leaks Middle of bus Fuel tank fuel	Steam cleaned all of fuel tanks took for road test and returned to depot found fuel cap had not been locked on and leaked fuel all over the tanks again steam cleaned again made sure fuel cap was locked on and road test return to depot no more fuel over tanks all dry.	1142424
8228	05/26/2021	976639	Mechanic entered - Engine Other Coolent hose rubbing cheshis	Moved mounting bracket over now small gap between chassis and coolant hose.	1142424
8228	05/24/2021	976095	Mechanic entered - Body Other One reflector missing N/S	Fitted new amber reflector to N/S	1142061
8228	05/24/2021	976095	REFLECTOR AMBER HELLA 94x44mm		1142061

8228	05/24/2021	974718	Mechanic entered - Body Other Rust under wheelchair area	sand back rust sprayed body detna on effected areas lowered from hoist and steam cleaned engine bay and other areas required under bus	1142061
8228	05/24/2021	974718	STONEGUARD BLACK L253 1L (SG)		1142061
8228	05/24/2021	974718	Mechanic entered - Body Other Rust under wheelchair area	Cleaned off rust areas around rear door and painted / body sprayed. Creditor #:GB-DAA001 DAALDER EXHAUSTS P/O #:G299107 Receiving #:312816 Date :2021-05-18 Collected from daddler exhaust repaired exhuast flex pipe fitted the new pipe back to the bus. Checked for leaks none found. with matt looked over work from yesturday noticed some rust that needed to be removed still needs to be cleaned and painted a Sanded back areas under front wheelchair ramp and rear door added anti rust treatment to the surface rust cleaned and sprayed body detna on affected areas. The rear door area had holes in it will have to go to the bodyshop to be replaced. Removed exhaust pipe assembly from muffler put part in hot wash to clean exhaust off paint marked exactly where the two point between the flexy need to meet up drove down to daddler exhaust for them to replace the flexy. Assisting Removed old burnt out switch globes fitted new L.E.D ones all dash lights working now.	1142061
8228	05/18/2021	974650	REPAIR EXHAUST FLEXI SECTION		1142061
8228	05/18/2021	974650	Mechanic entered - Engine Other Exhaust flex cracked	Removed broken door hinge and fitted brand new one door swinging straight now. grinded back rust after raising bus onto hoist inspected rest of bus for rust and grinded that back to. applied ubs protecft plous schwarz to all areas grinded. to be completed in morning	1141947
8228	05/18/2021	974718	Mechanic entered - Body Other Rust under wheelchair area		1141947
8228	05/18/2021	974718	Mechanic entered - Body Other Rust under wheelchair area	CARRY OUT A SERVICE AS PER CHECK LIST Completed A service as per checklist reported / repaired any foud defects.	1141947
8228	05/17/2021	974650	Mechanic entered - Engine Other Exhaust flex cracked		1141947
8228	05/17/2021	974650	Mechanic entered - Engine Other Exhaust flex cracked	VEHICLE SAFETY INSPECTION Carried out Safety inspection as per checklist reported / repaired any found defects. TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Jess. CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed CCTV service PRE ANNUAL SAFETY INSPECTION CHECK Completed RSI checks as per checklist with Jess reported / repaired any found defects. Lifted up front alxe and put body on stands removed old sway bar link on N/S/F. Fitted new balljoint style sway bar lik with split pin nuts too N/S/F.	1141947
8228	05/17/2021	974589	Mechanic entered - Dash Dash_Lights Not Working x4 switch li		1141947
8228	05/17/2021	974589	Consumables	Removed floorhatch above gearbox Tighten up hose clamps for gearbox cooler tighten up hose clamps for radiator hoses. Took bus for road test no more coolant leaks from these hoses. Removed floor hatches and steam cleaned engine and gearbox for RSI cleaned under axles as well. fitted back radiator road tested ok Ecu hs been rewired and fitted back to engine radiator fan and radiator have been fitted radiator mountings fitted. intercooler secured to radiator. hydualic fan shaft fitted back to motor Intercooler pipes fitted and secured Fitted intercooler covers. Fillexd with coolant Started engine checked for leaks All okay Engine was!	1141947
8228	05/17/2021	974592	Mechanic entered - Body Other Drivers door 1 hinge broken		1141947
8228	05/17/2021	974718	Mechanic entered - Body Other Rust under wheelchair area	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G297756 Receiving #:311181 Date :2021-04-28 Deassembled fan assembly Washed fan radiator intercooler and bracket. reassembled fan assembly fitted new fan drive motor.. Ready to be put back. Ecu plug detachtd from ecu. Plug needs to be rewired. removed the radeator replaced fandrive Creditor #:GB-CAR020 CARDINIA P/O #:G297799 Receiving #:311325 Date :2021-04-29 checked for the defect Grahm found radiator fan clutch faulty start to remove the radiator c/o Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G297745 Receiving #:311161 Date :2021-04-27 Checked by Graham found radiator fan clutch faulty secured bus for safety. draied coolant removed side panels of intercooler. removed intercooler pipes. Removed radiator and fan together. C/O CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection complete. replaced globe.	1141947
8228	05/17/2021	974592	HINGE DRIVERS DOOR S/S 60mmX60mm (12205)(802505)		1141947
8228	05/17/2021	974587		Fitted Completed by refuellers as per email completed Removed old sway bar link on O/S/F used balljoint pullers. Fitted new sway bar link and paint marked after tightening. assisted Mattwith replacing the n/s/f sway bar link Used number 2 button for D Button and drew Letter D on it. assisted Matt in changing the 2 button to a d button replaced n/s/r wheel arch lock mech with Matt	1141947
8228	05/17/2021	974587			1141947
8228	05/17/2021	974587	Consumables	Assisted Jess with Replacing lock mech for N/S/R wheel arch. Panel now holding. Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G294450 Receiving #:307726 Date :2021-03-05 completed. VEHICLE SAFETY INSPECTION Safety completed as per checklist TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel tension to OEM spec	1141947
8228	05/17/2021	974587	Consumables		1141947
8228	05/17/2021	974587	Consumables	completed. fitted new buzzer.	1141947
8228	05/17/2021	974587	Consumables		1141947
8228	05/14/2021	974291		Fitted new reverse buzzer. tested okay Fitted new reverse buzzer. tested okay	1141947
8228	05/14/2021	974291			1141947
8228	05/14/2021	974293		drained left hand rear air tank reolced seal and refit the seal. tested for leaks	1141947
8228	05/14/2021	974334	Mechanic entered - Suspension Other N/S/F sway bar link bush		1141947
8228	05/14/2021	974334	LINK SWAY BAR NSF MERC BENZ 0500LE A6283201089	Fitted by Refuellers	1141947
8228	05/14/2021	974389	Mechanic entered - Fluid Leaks Rear of bus Coolant leaks fro		1141947
8228	05/14/2021	974390	Mechanic entered - Engine Other Steam clean for Rsi	carried out changing radiator fan and radiator and draining angle drive oil and replacing topped up coolant and road tested to ensure no leaks.	1141947
8228	04/30/2021	970636	Elec and Light check and repair fault in break system		1141947
8228	04/30/2021	970636	Elec and Light - Check and repair fault in break system	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G292553 Receiving #:305475 Date :2021-02-08 Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G292553 Receiving #:305475 Date :2021-02-08 discus with the driver towed bus to depot. (radiator fan broken) Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G292524 Receiving #:306204 Date :2021-02-17 PICK UP FROM MONASH UNI CARRY OUT FIRE EXTINGUISHER TEST & TAG	1141947
8228	04/30/2021	970636	Elec and Light - Check and repair fault in break system		1141947
8228	04/30/2021	970636	Consumables	Removed and replaced led signal lamp assy. rear o/s. Completed	1141947
8228	04/28/2021	970636	ANGLE DRIVE FAN MERC BENZ 050		1141947
8228	04/28/2021	970636	Elec and Light - Check and repair fault in break system	R/R door switch and checked the operation of the door ok.	1141947
8228	04/28/2021	970636	Elec and Light check and repair fault in break system		1141947
8228	04/28/2021	970636	FIND ELECTRICAL FAULT	Completed by Refuellers Fit back	1141947
8228	04/27/2021	970636	Elec and Light check and repair fault in break system		1141947
8228	04/27/2021	970636	ECU PIN / BUSH HOUSING MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G290602 Receiving #:303287 Date :2021-01-05	1141947
8228	04/27/2021	970636	Elec and Light - Check and repair fault in break system		1141947
8228	04/23/2021	970000		Replace dif oil seal	1141947
8228	04/23/2021	970000			1141947
8228	04/08/2021	966944	Mechanic entered - Elec and Light - Exterior Lights o/s head		1141947
8228	04/08/2021	966944	GLOBE 24V 70W H1		1141947
8228	04/08/2021	966944	Consumables		1141947
8228	03/30/2021	964819	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL		1141947
8228	03/24/2021	963307	Place new poster over the top attach hangers to hand rails		1141947
8228	03/22/2021	962285	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI		1141947
8228	03/05/2021	958801	Mechanic entered - Suspension - R/H/F sway barlink u/s		1141947
8228	03/05/2021	958801	Mechanic entered - Suspension - R/H/F sway barlink u/s		1141947
8228	03/05/2021	958801	Mechanic entered - Body - D button missing on gear selector		1141947
8228	03/05/2021	958801	Mechanic entered - Body - D button missing on gear selector		1141947
8228	03/05/2021	958820	Mechanic entered - Body - NSR wheel arch lock broken		1141947
8228	03/05/2021	958820	STEEL CLAW CATCHES (38014)		1141947
8228	03/05/2021	958820	Mechanic entered - Body - NSR wheel arch lock broken		1141947
8228	03/04/2021	958801	LINK SWAY BAR OSF MERC BENZ		1141947
8228	03/03/2021	958350			1141947
8228	03/03/2021	958350			1141947
8228	03/03/2021	958350			1141947
8228	03/03/2021	958350	FILTER AIR FILTER MERCEDES BENZ (C27-1170)		1141947
8228	03/03/2021	958350			1141947
8228	03/03/2021	958354	Mechanic entered - Elec and Light - Reverse buzzer not worki		1141947
8228	03/03/2021	958354	BUZZER REVERSING 24V 102DB NR72602		1141947
8228	03/03/2021	958354	Mechanic entered - Elec and Light - Reverse buzzer not worki		1141947
8228	03/03/2021	958354	Mechanic entered - Elec and Light - Reverse buzzer not worki		1141947
8228	03/03/2021	958354	Consumables		1141947
8228	03/03/2021	958356	Mechanic entered - Air System Other air leak from left hand		1141947
8228	03/03/2021	958356	KIT O-RING LARGE VOSS (A6739970145)		1141947
8228	02/16/2021	954660	Leave old poster in and fit you must wear a maskover the		1141947
8228	02/09/2021	951532	OIL FAN ANGLE DRIVE MERC 0500LE E6		1141947
8228	02/09/2021	951532	Engine - Radiator fan broken.		1141947
8228	02/09/2021	951532	COOLANT PRE-MIX 50/50 EXTENDED LONG LIFE CALTEX		1141947
8228	02/09/2021	952313	Consumables		1141947
8228	02/09/2021	952313	Consumables		1141947
8228	02/09/2021	952313	Consumables		1141947
8228	02/09/2021	952313	Consumables		1141947
8228	02/06/2021	951532	RADIATOR MERC BENZ 0500LE A0		1141947
8228	02/06/2021	951532	FAN BLADE 750MM DIA MERC BENZ		1141947
8228	02/04/2021	951311	Ops Entered - Fault - Breakdown - Route: 900 - Monash Uni		1141947
8228	02/04/2021	951311	DIRECT PURCHASE - TOWING		1141947
8228	02/04/2021	951025	Replaced by ATS		1141947
8228	01/19/2021	948029	Consumables		1141947
8228	01/19/2021	948029	LAMP LED AMBER 177 X 100		1141947
8228	01/19/2021	948029	RHS lower indicator not working		1141947
8228	01/14/2021	946822	Removed N/S/F window COVID-19 & MYKI decals and reposition		1141947
8228	01/13/2021	946694	Consumables		1141947
8228	01/13/2021	946694	Drv entered - Body Front_Door Operation Faulty		1141947
8228	01/13/2021	946694	SWITCH DR CONTACT (NORMALLY OPEN) (M22-K10)		1141947
8228	01/12/2021	946380	Please fit A3 poster over COVID-19 poster and hangers to be		1141947
8228	01/06/2021	944471	Mechanic entered - Engine - Exhaust leak from flex.		1141947
8228	01/06/2021	944471	Mechanic entered - Engine - Exhaust leak from flex.		1141947
8228	01/05/2021	944471	SEAL DIFF PINION MERC BENZ 0		1141947
8228	01/05/2021	944471	NUT DIFF PINION MERC BENZ 0500LE 49F0011		1141947
8228	01/05/2021	944471	Mechanic entered - Gearbox Driveline - Oil leak from dif		1141947

8228	01/05/2021	944471	Mechanic entered - Gearbox Driveline - Oil leak from dif	Replace dif oil seal	1123573
8228	01/05/2021	944471	REPAIR EXHAUST FLEXI SECTION	Creditor #:-GB-DAA001 DAALDER EXHAUSTS P/O #:-G290600 Receiving #:-303391 Date :2021-01-06	1123573
8228	01/05/2021	944471	Mechanic entered - Engine - Exhaust leak from flex.	REMOVE exhaust pipe and send to repaire C/O job	1123573
8228	01/05/2021	944471	Mechanic entered - Engine - Exhaust leak from flex.	REMOVE exhaust pipe and send to repaire C/O job	1123573
8228	12/23/2020	943119			1122120
8228	12/23/2020	943119			1122120
8228	12/23/2020	943119	BELL PUSH FOR WHEEL CHAIR PASS (40792)		1122120
8228	12/23/2020	943119			1122120
8228	12/08/2020	940150	Mechanic entered - Fluid Leaks Middle of bus fuel cup not	completed.	1119725
8228	12/03/2020	931746	Ops Entered - Gearbox Driveline - Rough Gear Change - Route	Adjust diesel tank cap lock.	1119118
8228	12/03/2020	939150		Tom (KNOX) Rebuilt g/box	1119118
8228	12/03/2020	939150	*BUS AT KNOX*- PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS N	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete	1119118
8228	12/03/2020	939191		Complete.	1119118
8228	12/02/2020	933816	Gearbox Driveline	reinstalled gearbox in the bus. had issues with reinstalling the cross member but eventually had all crossmembet bolts and trans mount bolts in and secured. all torque converter bolts have been connected and torqued to spec by tom. coolant lines. air lines sensors intercooler lines all connected back up with a few new hc	1119118
8228	11/30/2020	931746	REPAIR / OVERHAUL 4149 004 013	Creditor #:-GB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:-G287539 Receiving #:-301182 Date :2020-11-30 SERIAL CODE 00060413	1119118
8228	11/26/2020	936776	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed	1119118
8228	11/17/2020	933816	Gearbox Driveline	removed transmission.	1119118
8228	11/17/2020	933816	Gearbox Driveline	Assisting removed crossmember under transmission removed transmission with the table. washed gearbox clean removed all bolts off gearbox prepped all bolts for reinstallation. had to drain coolant beforen hand	1119118
8228	11/16/2020	933308	Remove old poster and fit you must wear a face mask when t	Replaced by Refuellers	1119118
8228	11/12/2020	931587	Mechanic entered - Body	fit plastic base to disabled seat. fit seat to frame and secure to wall.	1119118
8228	11/12/2020	931587	SEAT BASE PLASTIC SUPERSLIM BLACK DISABLED SEAT		1119118
8228	11/12/2020	931587	Consumables		1119118
8228	11/11/2020	931587	REPAIR DISABLED SEAT BASE	Creditor #:-GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-G287226 Receiving #:-299754 Date :2020-11-11	1119118
8228	11/11/2020	931587	REPAIR DISABLED SEAT BACK	Creditor #:-GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-G287226 Receiving #:-299754 Date :2020-11-11	1119118
8228	11/11/2020	931587	Mechanic entered - Body	drill out and tap mounting points for disabled seat plate mount - existing ones thread stripped.	1119118
8228	11/09/2020	931746	Ops Entered - Gearbox Driveline - Rough Gear Change - Route	checked costor pluge no oilin there road tested gears 2345 rough change	1119118
8228	11/09/2020	931587	Mechanic entered - Body	remove disabled seat for repair.	1119118
8228	11/04/2020	930458	Mechanic entered - Body - Pax. plastic seat shell broken	replaced.	1117555
8228	11/04/2020	930458	KIELGREY CENTRA SEAT SHELL		1117555
8228	11/04/2020	930458	Consumables		1118397
8228	10/30/2020	929921	Fit new Myki Decals & refit COVID-19 decals new position fo	completed.	1117181
8228	10/21/2020	927941	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1115630
8228	10/21/2020	927941	Mechanic entered - Elec and Light Exterior Lights revers	(note:broken plate number light not reverse light) R/R LED light.	1115630
8228	10/21/2020	927941	Consumables		1115920
8228	10/19/2020	927361	Mechanic entered - Elec and Light Exterior Lights rear numbe	R/r LED number plate light.	1115055
8228	10/19/2020	927361	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1115055
8228	10/19/2020	927361	Consumables		1115343
8228	10/14/2020	926403	Mechanic entered - Elec and Light Exterior Lights N/S Fr Lwr	R/R globe.	1114201
8228	10/14/2020	926403	Consumables		1114488
8228	10/12/2020	925645	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Fitted new wiper blades. tested okay	1114085
8228	10/12/2020	925645	WIPER REFILL 1000mm MULTI FIT		1114085
8228	10/12/2020	925607		CARRY OUT A SERVICE AS PER CHECK LIST A Service completed Faults entered and fixed.	1114085
8228	10/12/2020	925607		assist Tayla with A service..	1114085
8228	10/12/2020	925607		assist Tayla with A service..	1114085
8228	10/12/2020	925607	Consumables		1114093
8228	10/12/2020	925607	Consumables		1114093
8228	10/12/2020	925607	Consumables		1114093
8228	10/12/2020	925607	Consumables		1114093
8228	10/06/2020	923539	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1113140
8228	10/06/2020	923539	WIPER ARM TRICO CONVEN NS		1113140
8228	10/06/2020	923539	WIPER ARM O/S		1113140
8228	10/05/2020	923539	Ops Entered - Wipers and Washers - Wipers Not Working - Rou	check and fixed wiper cam assy adjusted link rods road tested wipers ok.	1113140
8228	10/05/2020	923974	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	Completed	1113140
8228	10/03/2020	923539	Ops Entered - Wipers and Washers - Wipers Not Working - Rou	check wiper need to adjust wiper links c/o	1113140
8228	10/02/2020	923539	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1113140
8228	10/02/2020	923539	Ops Entered - Wipers and Washers - Wipers Not Working - Rou	Reassemble wiper arm.C/O	1113140
8228	10/01/2020	923539	WIPER ARM TRICO CONVEN NS	Creditor #:-GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:-G284726 Receiving #:-297236 Date :2020-10-02	1113140
8228	10/01/2020	923539	WIPER ARM O/S	Creditor #:-GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:-G284726 Receiving #:-297236 Date :2020-10-02	1113140
8228	09/29/2020	922937	Mechanic entered - Elec and Light Exterior Lights l/h side l	R/r headlight globe.	1112931
8228	09/29/2020	922937	GLOBE 24V 70W H1		1112931
8228	09/29/2020	922937	Consumables		1113140
8228	09/28/2020	922486		completed.	1112920
8228	09/28/2020	922486		VEHICLE SAFETY INSPECTION Safety completed as per checklist Faults entered in tims and fix Wheels torqured to OEM spec with Alan	1112920
8228	09/28/2020	922486		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheels torqured to OEM spec with Alan	1112920
8228	09/28/2020	922528	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1112920
8228	09/28/2020	922611	Mechanic entered - Elec and Light Other gear selector D bu	fit new button.	1112920
8228	09/28/2020	922528	Mechanic entered - Elec and Light Other number plate light u	fit new number plate light unit.	1112920
8228	09/28/2020	922528	Consumables		1112920
8228	09/28/2020	922611	Consumables		1112931
8228	09/28/2020	922591	Mechanic entered - Body Other secure l/h folding seat frame	Secured L/H folding seat frame	1112920
8228	09/28/2020	922612	Mechanic entered - Body Other refit seat back rest seat at	Fixed seat backing and resucurted it	1112920
8228	09/28/2020	922599	Mechanic entered - Body Other r/h/r seat grab handle damaged	fitted new seat handle grabs	1112920
8228	09/28/2020	922599	PASS SEAT HANDGRIP CENTRA MK 2		1112920
8228	09/28/2020	922597	Mechanic entered - Body Other secure r/h folding seat frame.	Secured R/H folding seat frame	1112920
8228	09/28/2020	922609	Mechanic entered - Body Other elctrical panel gasstays not w	replaced	1112920
8228	09/28/2020	922609	STRUT GAS STAY 500Nm 330mm LONG		1112920
8228	09/28/2020	922603	Mechanic entered - Air System Other air leak from air tank u	fit new seal kit to pipe.	1112920
8228	09/28/2020	922603	KIT O-RING LARGE VOSS (A6739970145)		1112920
8228	09/08/2020	918783	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1109315
8228	09/08/2020	918783	VOSS NUT 232 16MM MERC BENZ 0500LE A0009975334		1109315
8228	09/08/2020	918783		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1109315
8228	09/08/2020	918783		completed as per check list..	1109315
8228	09/08/2020	918783	KIT O-RING LARGE VOSS (A6739970145)		1109315
8228	09/08/2020	918783	KIT O-RING SMALL VOSS (A0309971748)		1109315
8228	09/08/2020	918783	AIR DRYER ASSY MERC BENZ 0500LE A0004302915		1109315
8228	09/08/2020	918783	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1109315
8228	09/04/2020	918263	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1108996
8228	09/04/2020	918263	Mechanic entered - Air System Air_Leak Rear	Air tank drain valves leaking. Removed and fitted new drain valves.	1108996
8228	08/24/2020	915590	Mechanic entered - Engine Other Park in line 1	Checked Engine bay.Tyressuspension ok Couldn't fine any fault. Road tested ok. It waspark in line one no created any job.	1106488
8228	08/07/2020	912177		VEHICLE SAFETY INSPECTION Completed safety + faults.	1103420
8228	08/07/2020	912177		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1103420
8228	08/07/2020	912177	WHEEL ARCH BRUSH 12065		1103420
8228	08/07/2020	912177	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1103420
8228	08/07/2020	912177	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1103420

8228	08/07/2020	912260	VALVE CIRCUIT PROTECTION MERC BENZ 0500LE			1103420
8228	08/07/2020	912260	Mechanic entered - Air System Air_Leak Rear 4 way valve need	replaced the valve		1103420
8228	08/06/2020	913231	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		1103420
8228	08/03/2020	910303	ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR			1102338
8228	07/31/2020	910303	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1102308
8228	07/31/2020	910303		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Completed.		1102308
8228	07/31/2020	910214	Remove old A3 Poster and fit with You can no longer top up	Completed by Refuellers		1102308
8228	07/21/2020	907833		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		1099940
8228	07/21/2020	907833	FILTER DRYER AIR COND THERMO KING			1099940
8228	07/21/2020	907833		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list		1099940
8228	07/15/2020	906800	FILTER OIL FILTER MERCEDES A0001801709			1099397
8228	07/15/2020	906800	OIL ENGINE DELO 400 MGX SAE 15W-40 (Min)			1099397
8228	07/15/2020	906800	OIL ANALYSIS KIT DETECTA AZ-DET25 3350-601 23448457			1099397
8228	07/15/2020	906800	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)			1099397
8228	07/15/2020	906800		CARRY OUT B SERVICE AS PER CHECK LIST carried out a and b service as per check list and tensioned all wheel nuts with ryan and road tested to ensure no oil leaks.		1099397
8228	07/15/2020	906800	Consumables			1099398
8228	07/15/2020	906800	Consumables			1099398
8228	07/15/2020	906800	Consumables			1099398
8228	07/15/2020	906800	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		1099397
8228	07/15/2020	906800	Consumables			1099398
8228	07/15/2020	906800	Consumables			1099398
8228	07/15/2020	906800	Consumables			1099398
8228	07/07/2020	905058	Ops Entered - Fault - Air System Air_Leak Interior - under d	carried out replacing full new drivers seat.		1097789
8228	07/07/2020	905058	SEAT SEAT ASSY ISRI A6008 AIR LUMBAR CHANGE OVER			1097789
8228	07/03/2020	904616	Ops Entered - Fault - Air System Air_Leak Front - Route: 90	Repair and secured air hose.		1097555
8228	06/24/2020	902776	Mechanic entered - Elec and Light Exterior Lights	Locate and repair fault in indicator circuit		1095885
8228	06/24/2020	902776	Consumables			1096422
8228	06/23/2020	902492	Mechanic entered - Elec and Light Exterior Lights os side in	take off cover and found it didnt have contact ith earth so made contact and globe working done.		1095885
8228	06/23/2020	902492	Consumables			1096170
8228	06/12/2020	900002	Drv entered - BusMinder No Power			1093643
8228	06/12/2020	900002	Ops Entered - Fault - BusMinder No Power - Route: 900 - Mo	replaced bus minder unit old unit no BMNO1205 new unit no BMNO5031		1093643
8228	06/12/2020	900002	Consumables			1094268
8228	06/11/2020	900282				1093643
8228	06/11/2020	900282		Retention all wheel nuts with Sadid.		1093643
8228	06/11/2020	900002	Drv entered - BusMinder No Power	check and fixed power but need to replac device		1093643
8228	06/10/2020	897480	BRAKE BOOSTER RHR MERC BENZ 0500LE E6			1093643
8228	06/10/2020	897480	Mechanic entered - Air leak on hand brake quick realise valv	leak from Rear brake boosters replaced borth tensioned wheel nut with Haysun. also tested the brake and road tested ok		1093643
8228	06/10/2020	897480	BRAKE BOOSTER LHR MERC BENZ 0500LE E6			1093643
8228	06/10/2020	899766	Fit A3 Poster in poster frame and fit decals as requested in	completed.		1093643
8228	06/09/2020	897480	BEARING KING PIN MERC BENZ 0500LE			1093643
8228	06/09/2020	897480	Mechanic entered - Air leak on hand brake quick realise valv	looking fot defect leaking from valve or brake boosters		1093643
8228	06/05/2020	897480	Mechanic entered - Front King pins worn	replaced king pin 4 needle beyaring 1 roller beyaring tensioned wheel nut with Haysun (09/06/2020)		1093643
8228	06/05/2020	897480	BEARING KING PIN MERC BENZ 0	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276929 Receiving #:288566 Date :2020-06-05		1093643
8228	06/05/2020	897480	SEAL RING KINGPIN MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276929 Receiving #:288566 Date :2020-06-05		1093643
8228	06/05/2020	897480	Engine oil leakk on oil filter hoses	replaced 2 hoses and filter houseing		1093643
8228	06/05/2020	897480	Mechanic entered - Air leak on hand brake quick realise val			1093643
8228	06/04/2020	897480	Mechanic entered - Suspension Other Front King pins worn	work with Sisil to fix king pin		1093643
8228	06/04/2020	897480	Mechanic entered - Front King pins worn	fixing king pin		1093643
8228	06/04/2020	897480	PIPE OIL FILTER TO BLOCK 0500LE			1093643
8228	06/04/2020	898541	Up load new desto file	Updated		1093643
8228	06/04/2020	897480	Mechanic entered - Air leak on hand brake quick realise valv			1093643
8228	06/04/2020	898517	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	Completed by ECTB		1093643
8228	06/03/2020	897480	SEAL RING KINGPIN MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276663 Receiving #:288327 Date :2020-06-03		1093643
8228	06/03/2020	897480	SPACER WASHER 2.20MM KINGPI	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276663 Receiving #:288327 Date :2020-06-03		1093643
8228	06/03/2020	897480	LOCK RING KINGPIN MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276663 Receiving #:288326 Date :2020-06-03		1093643
8228	06/03/2020	897480	SEAL RING KINGPIN MERC BENZ	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G276663 Receiving #:288327 Date :2020-06-03		1093643
8228	06/03/2020	897480	HOSE OIL FILT HSG - OIL COOLER M/ BENZ 0500LE A4571801620			1093643
8228	06/03/2020	897480	HOSE OIL FILT HSG - OIL COOLER M/ BENZ 0500LE A4571801720			1093643
8228	06/03/2020	897480	OIL FILTER HOUSING MERC BENZ 0500LE			1093643
8228	06/02/2020	897480	Mechanic entered - Suspension Other Front King pins worn	check and order parts		1093643
8228	06/01/2020	897480	KING PIN KIT LH MERC BENZ 050	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G276531 Receiving #:288078 Date :2020-06-01 NSF KIT 0500LE		1093643
8228	05/28/2020	896856	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G276262 Receiving #:287914 Date :2020-05-29		1093643
8228	05/27/2020	896856		VEHICLE SAFETY INSPECTION		1093643
8228	05/27/2020	896856		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1093643
8228	05/27/2020	896856		ANNUAL SAFETY INSPECTION - RWC 026222 - PASSED - 27/05/2020WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1093643
8228	05/27/2020	896856		Assisting RSI completed with Neven		1093643
8228	05/25/2020	896420	Mechanic entered - Elec and Light Interior Lights interior I	replaced led light		1093169
8228	05/25/2020	896420	LIGHT INTERIOR LED ORION			1093169
8228	05/25/2020	896420	Consumables			1093279
8228	05/25/2020	896385	Carry out final check for RSI	final rsi check complete checked over any defects found fixed		1093169
8228	05/25/2020	896385	Carry out final check for RSI	completed		1093169
8228	05/21/2020	895930	Mechanic entered - Elec and Light Exterior Lights o/s headli	Fitted new low beam bulb o/s.		1092691
8228	05/21/2020	895930	GLOBE 24V 70W H1			1092691
8228	05/21/2020	895930	Consumables			1092861
8228	05/20/2020	893643	Rear door rollers and bushes n	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G275385 Receiving #:287134 Date :2020-05-20 replace as required		1092321
8228	05/19/2020	894858	DIRECT PURCHASE - VANDALISM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G275536 Receiving #:287122 Date :2020-05-20 CLEAN AS REWQUIRED		1092321
8228	05/18/2020	894858	Vandalism - Paint chips on the front pole and poles by the	Completed by ECTB		1092218
8228	05/15/2020	894691		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST wash bus did inspection.		1092218
8228	05/14/2020	893555	Mechanic entered - Rear door rubber need to fix	FIXED		1091854
8228	05/14/2020	893556	Mechanic entered - Behind the driver seat board aluminium fr	FITTED		1091854
8228	05/14/2020	893594	Mechanic entered - Body Passenger Seat Torn 3 passenger seat	fitted 3 new passenger seat base		1091854
8228	05/14/2020	893556	Mechanic entered - Behind the driver seat board aluminium fr	Haysun fitted new one		1091854
8228	05/14/2020	893555	Mechanic entered - Rear door rubber need to fix	Haysun done		1091854
8228	05/13/2020	892332	ALTERNATOR 24V 140AMP MERC 0500LE	PART ISSUED TO GLENN BY RANJITH		1091832
8228	05/13/2020	893643	Reardoor rollers and bushes need to replace	Completed by Glen @ ECTB		1091832
8228	05/13/2020	893643	Reardoor rollers and bushes need to replace	Assisting		1091832
8228	05/12/2020	893561	Mechanic entered - Drag link balljoint rubber broken			1091832
8228	05/12/2020	893561	Mechanic entered - Drag link balljoint rubber broken	replaced the draglink		1091832
8228	05/12/2020	893603	Mechanic entered - Body Passenger Seat Torn 3 passenger seat			1091832
8228	05/12/2020	893560	Mechanic entered - Engine door back heat foam missing			1091832
8228	05/12/2020	893560	SOUND INSULATION 2.4M X 1.3M X 28MM P/M	replaced		1091832
8228	05/12/2020	893603	Mechanic entered - Body Passenger Seat Torn 3 passenger seat	fitted new		1091832
8228	05/12/2020	893560	Mechanic entered - Engine door back heat foam missing			1091832

8228	05/12/2020	893929	Mechanic entered - Steam clean the bus	cleaned	1091832
8228	05/12/2020	893643	ANGLE NOSING BIFOLD DR	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	KIT SENSITIVE EDGE KIT SMC	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	PIVOT SHAFT KIT 607324	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	DOOR PIVOT PIN KIT	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	GUIDE ROLLER ASSY	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	GUIDE ROLLER TRACK	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/12/2020	893643	BRACKET NOSING BIFOLD DR	Creditor #:-GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:-G275158 Receiving #:-286748 Date :2020-05-13	1091832
8228	05/11/2020	893515		PRE ANNUAL SAFETY INSPECTION CHECK completed	1091832
8228	05/11/2020	893515		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1091832
8228	05/11/2020	893561	NUT DRAG LINK BALL JOINT MER	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G275102 Receiving #:-286534 Date :2020-05-11	1091832
8228	05/11/2020	893561	DRAGLINK ASSY MERC BENZ 0500L	Creditor #:-GB-DAI001 DAIMLER TRUCKS LAVERTON P/O #:-G275120 Receiving #:-286539 Date :2020-05-11	1091832
8228	05/11/2020	893557	Mechanic entered - Indicators Not Working N/S		1091832
8228	05/11/2020	893562	Mechanic entered - Elec and Light Indicators Not Working n/s		1091832
8228	05/11/2020	893557	Mechanic entered - Indicators Not Working N/S	broken wire repaired	1091832
8228	05/11/2020	893562	Mechanic entered - Elec and Light Indicators Not Working n/s	repaired	1091832
8228	05/11/2020	893557	Consumables		1091832
8228	05/11/2020	893562	Consumables		1091832
8228	05/11/2020	893602	Mechanic entered - Body Other front wheel arch need to chang	replaced both wheel arch brush and rubber	1091832
8228	05/11/2020	893554	PASS SEAT HANDGRIP CENTRA MK 2		1091832
8228	05/11/2020	893558	Mechanic entered - Rear door top plastick cover broken		1091832
8228	05/11/2020	893554	Mechanic entered - Passenger Seat Belt Handdle cut	Haysun replaced	1091832
8228	05/11/2020	893558	Mechanic entered - Rear door top plastick cover broken	replaced rear door cover and fitted light and buttons in	1091832
8228	05/11/2020	893554	Mechanic entered - Passenger Seat Belt Handdle cut	fitted new handle	1091832
8228	05/11/2020	893558	FIRTREE CLIP SIDE PILLAR L/GREY		1091832
8228	05/11/2020	893558	Mechanic entered - Rear door top plastick cover broken	replaced	1091832
8228	05/11/2020	893558	COVER REAR DOOR ROOF CONTROL	Creditor #:-GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:-G275118 Receiving #:-286555 Date :2020-05-11	1091832
8228	05/11/2020	893602	WHEEL ARCH RUBBER		1091832
8228	05/11/2020	893602	WHEEL ARCH BRUSH 12065		1091832
8228	05/11/2020	893594	REPAIR DBLE SEAT BASE	Creditor #:-GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-G275147 Receiving #:-286577 Date :2020-05-12	1091832
8228	05/11/2020	893594	REPAIR SINGLE SEAT BASE	Creditor #:-GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-G275147 Receiving #:-286577 Date :2020-05-12	1091832
8228	05/11/2020	893559	Mechanic entered - Air Leak Rear 6 way valve air line fittin		1091832
8228	05/11/2020	893559	Mechanic entered - Air Leak Rear 6 way valve air line fittin	replaced 6 oring kit	1091832
8228	05/11/2020	893559	KIT O-RING LARGE VOSS (A6739970145)		1091832
8228	05/07/2020	892332	Ops Entered - Breakdown Not St		1091600
8228	05/06/2020	892332	Fault#:-37558 - Ops Entered - Breakdown Not Starting - Rout	Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:-G274814 Receiving #:-286347 Date :2020-05-08 BUS NOT STARTING	1091201
8228	05/04/2020	892077	Mechanic entered - Suspension Other refit driveshaft	Repaired by Glenn @ ECTB	1091201
8228	05/04/2020	891275	KIT O-RING LARGE VOSS (A6739970145)	refitted n/s driveshaft Torqued hub bolts to spec with Alan	1091201
8228	05/04/2020	891275	KIT O-RING SMALL VOSS (A0309971748)		1091201
8228	05/04/2020	890806	Mechanic entered - Air System Air_Leak Rear Air leak from f	Job continue by Abraham and Nick last 1/05/2020.	1091201
8228	05/02/2020	892332	Fault#:-37558 - Ops Entered - Breakdown Not Starting - Rout	Wont start wont get into gears doors n/w. Power cuts off when ignition turned to starting position. Managed to start but no gears. Removed axle arrange tow electrical panel close to road. Check solenoids beside batteries	1091201
8228	05/01/2020	892332	PICK UP FROM WELLINGTON ROAD A	Creditor #:-GB-EAG001 EAGLE TOWING & SALVAGE P/O #:-G274656 Receiving #:-286495 Date :2020-05-11	1091832
8228	05/01/2020	890797	Mechanic entered - Fluid Leaks Rear of bus Air compressor co	Fitted aircompressor coolant hose.	1090940
8228	05/01/2020	890797	Mechanic entered - Fluid Leaks Rear of bus Air compressor co	Assisted Abraham drive tested and checked coolant leaks ok.	1090940
8228	05/01/2020	890806	Mechanic entered - Air System Air_Leak Rear Air leak from fi	c/o	1090940
8228	05/01/2020	891275	Mechanic entered - Air System Air_Leak Rear Relay valve and	Fitted new relay valve and replaced airline fittings repair kit.	1090940
8228	05/01/2020	890806	VALVE RELAY MERC BENZ 0500LE	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G274381 Receiving #:-285848 Date :2020-05-01	1090940
8228	04/30/2020	890806	VALVE PROPORTIONING AIR/ ELE MERC BENZ 0500LE 50G1405WABC		1090940
8228	04/29/2020	890797	Mechanic entered - Fluid Leaks Rear of bus Air compressor co	Start fitted new coolant pipe Pipe a bit short cannot fit to air compressor fitting. Remove fitting while removing fitting to tight accidentally snapped fittings need new fitting. Check store no parts available report to Kumar order fitting. Carry/over.	1090940
8228	04/29/2020	890806	VALVE PROPORTIONING AIR/ ELE	Creditor #:-GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:-G274151 Receiving #:-285584 Date :2020-04-29	1090940
8228	04/29/2020	891275	KIT O-RING SMALL VOSS (A0309971748)		1090940
8228	04/29/2020	891275	KIT O-RING LARGE VOSS (A6739970145)		1090940
8228	04/29/2020	891275	Mechanic entered - Air System Air_Leak Rear Relay valve and	Remove back up valve and relay valve. Fitted new relay valve and replace oring air line fittings. Back up valve provide by Lee different from old one need parts order. Carry/over.	1090940
8228	04/28/2020	890797	PIPE COOLANT AIR COMPRESSOR MERC BENZ 0500LE		1090940
8228	04/28/2020	890806	KIT O-RING SMALL VOSS (A0309971748)		1090940
8228	04/28/2020	890806	VALVE RELAY VALVE RR MERC BE	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G274152 Receiving #:-285469 Date :2020-04-28	1090940
8228	04/27/2020	890787		Assisted Rene	1090940
8228	04/27/2020	890787		VEHICLE SAFETY INSPECTION Completed .	1090940
8228	04/27/2020	890787		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Dpone with Abraham.	1090940
8228	04/27/2020	890787		Assisted Rene.	1090940
8228	04/27/2020	890797	Mechanic entered - Fluid Leaks Rear of bus Air compressor co	Drain coolant and remove air compressor coolant pipe. Check at store no available parts.	1090940
8228	04/27/2020	890803	Mechanic entered - Brakes Other Brake pedal rubber worn.	Remove and replace.	1090940
8228	04/27/2020	890803	PAD BRAKE PEDAL RUBBER MERC BENZ 500LE A1072910182		1090940
8228	04/27/2020	890806	Mechanic entered - Air System Air_Leak Rear Air leak from fi	Remove air line fittings o-ring kit.	1090940
8228	04/24/2020	890468	Mechanic entered - Elec and Light Exterior Lights Front clea	secure connections n/s os side clearance indicator light	1090350
8228	04/24/2020	890468	Consumables		1090658
8228	04/23/2020	890235	Ops Entered - Fault - Wipers and Washers Wipers Not Working	Secured wiper arm and replaced wiper blade assembly.	1090068
8228	04/23/2020	890235	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1090068
8228	04/20/2020	889454		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Completed tune-up service as per checklist	1089572
8228	04/20/2020	889454	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221		1089572
8228	04/20/2020	889487	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1089572
8228	04/20/2020	889487	Mechanic entered - Elec and Light Exterior Lights number pla	fitted new plate number lamp rear n/s and secure wire	1089572
8228	04/20/2020	889487	Consumables		1089708
8228	04/20/2020	889476	Mechanic entered - Air System Other air leak from the air ta	Fitted new air tank fittings repair kit	1089572
8228	04/20/2020	889476	KIT O-RING LARGE VOSS (A6739970145)		1089572
8228	04/16/2020	884989	REPLACE ANTI GRAFITTI FILM	Creditor #:-GB-GLA010 GLASSPROTECH MELBOURNE P/O #:-G272182 Receiving #:-284597 Date :2020-04-17 REPLACE R1	1089176
8228	04/02/2020	885837	Ops Entered - Fault - Warning Lights Coolant - Route: 900 -	r/r heater hose & long drive testok.	1086670
8228	04/02/2020	885837	HOSE SILICONE 3 PLY 3/4 ID (PER CM)		1086670
8228	03/30/2020	884453	Wheels and Tyres - Need front wheel alignment (out side wo	Aligned by Big Wheel	1086190
8228	03/30/2020	884453	Consumables		1086207
8228	03/30/2020	884453	Consumables		1086207
8228	03/30/2020	884989	Vandalism - Graffiti etched on the rear and off-side back s	Replaced by Glassprotech	1086190
8228	03/28/2020	884453	CARRY OUT WHEEL ALIGNMENT	Creditor #:-GB-BIG010 BIG WHEELS TRUCK ALIGNMENT P/O #:-G272048 Receiving #:-283228 Date :2020-03-30	1086190
8228	03/27/2020	884453	Wheels and Tyres - Need front wheel alignment (out side wo	Sent to Big Wheel	1086190
8228	03/25/2020	883834	Tape off front Seats of All Route and Rail Buses with spec	Done	1085823
8228	03/20/2020	882033		Retensioned wheel nuts position 1 and 2 with Kuma.	1084679
8228	03/19/2020	881575	Mechanic entered - Wheels and Tyres Worn Position 2 tyre wor	Remove position 1 and 2 tyre Fitted two(2) new tyre. Position 1 return to rack. Tensionm wheel nuts Assisted by Abraham.	1084613
8228	03/19/2020	881575	TYRE 295/80R22.5 NEW		1084613
8228	03/19/2020	881575	Consumables	Completed by Refuellers	1084679
8228	03/19/2020	881575	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed check list.	1084679
8228	03/19/2020	881815	Remove old poster and fit Reduce Your Risk of Coronavirus		1084613
8228	03/19/2020	881572			1084613
8228	03/19/2020	881572	Consumables		1084679

8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/19/2020	881572	Consumables			1084679
8228	03/10/2020	879347	Mechanic entered - Body Other fuel caps not closing	straightened bent latch on cap. checked for closing and security - o.k.		1082584
8228	03/03/2020	878187	Engine - Steam clean under body	done stem cleaned		1081816
8228	03/03/2020	877480	Mechanic entered - Elec and Light Other 4 saloon lights out	replaced all 4 interior lights		1081816
8228	03/03/2020	877480	LIGHT INTERIOR LED ORION			1081816
8228	03/03/2020	878186	Elec and Light - Dash switch globes out	repaired dash globes		1081816
8228	03/03/2020	877480	Consumables			1081906
8228	03/03/2020	878186	Consumables			1081906
8228	03/03/2020	878186	Consumables			1081906
8228	03/03/2020	877480	Consumables			1081906
8228	03/03/2020	878184	Body - Rear emer sticker missing	replaced sticker		1081816
8228	03/03/2020	878176	Body - Drivers heater knob missing	replaced knob		1081816
8228	03/03/2020	878185	Body - Seat instruction decal missing	replaced decal		1081816
8228	03/03/2020	878176	KNOB HEATER CONTROL (AURORA)			1081816
8228	03/03/2020	878188	Body - NS disable floor vinyl peeling	repaired vynal		1081816
8228	03/03/2020	878188	FIRTREE CLIP SIDE PILLAR L/GREY			1081816
8228	03/01/2020	877680	REPAIR DBLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G270001 Receiving #:281314 Date :2020-03-04		1081906
8228	02/28/2020	877443		VEHICLE SAFETY INSPECTION completed as per sheet and tension wheel nuts with Tayla		1081317
8228	02/28/2020	877443		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1081317
8228	02/28/2020	877480	LIGHT INTERIOR LED ORION			1081317
8228	02/28/2020	877480	FIRTREE CLIP SIDE PILLAR L/GREY			1081317
8228	02/28/2020	877480	Consumables			1081317
8228	02/28/2020	877680	Mechanic entered - Body Passenger Seat Torn	replaced		1081317
8228	02/26/2020	877110		Retensioned wheel nuts position 3 and 4 with Nick.		1080746
8228	02/26/2020	877110		Retensioned wheel nuts position 3 and 4 with Sadid.		1080746
8228	02/25/2020	876795	Wheels and Tyres Replace t front tyra	changed pos 34 tyres tensioned wheel nut with Jesun		1080490
8228	02/25/2020	876795	TYRE 295/80R22.5 NEW			1080490
8228	02/25/2020	876795	Wheels and Tyres Replace t front tyra	assisted sisil to change pos 34 tyres and tension wheel nuts		1080490
8228	02/25/2020	876795	Consumables			1080746
8228	02/13/2020	876578	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		1078023
8228	01/28/2020	869753	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446			1074973
8228	01/28/2020	869753	Mechanic entered - Body Drivers Seat Belt buckle broken.	replaced.		1074973
8228	01/08/2020	865722	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	Completed		1071670
8228	01/07/2020	865587				1071670
8228	01/07/2020	865587		VEHICLE SAFETY INSPECTION Completed check list.		1071670
8228	01/07/2020	865587		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done Assisted by Abraham for wheel nut tension only.		1071670
8228	01/06/2020	865164	Ops Entered - Fault - BusMinder Unable To Log In - Route:	Sent email to Ron to rectify		1071228
8228	01/06/2020	865164	Ops Entered - Fault - BusMinder Unable To Log In - Route:	Sent email to Ron to rectify		1071228
8228	01/06/2020	865164	Consumables			1071670
8228	01/04/2020	865005	INDICATOR LED FRONT TURN LOW FLOOR SQUARE (32983)			1070809
8228	01/04/2020	865005	Mechanic entered - Elec and Light Exterior Lights (osf) top	replaced.		1070809
8228	01/04/2020	865005	Consumables			1071228
8228	01/02/2020	864523	Mechanic entered - Fluid Leaks Other CHECK FUEL LEAKS	CHECKED FUEL LEAKS OKCLEANED ENGINEROAD TESTED OK		1070660
8228	12/31/2019	864550	Fault#:37203 - Ops Entered - Fault - Breakdown Oil Leak -	Attended by Oakleigh. Found No3 injector pipe loose. Tighten up pipe and clean the spillage. Wash the engine at the depot		1070660
8228	12/30/2019	864286		Tension wheel nuts tyre pos 5 and 6 with Abraham.		1070402
8228	12/30/2019	864286		Assisted.		1070402
8228	12/27/2019	863943	TYRE 295/80R22.5 NEW			1069651
8228	12/27/2019	863943	Ops Entered - Fault - Wheels and Tyres Damaged - Route: -	Replaced tyre position 5 and tensioned all wheel nuts with Zubair		1069651
8228	12/27/2019	863943	Consumables			1070402
8228	12/23/2019	863549		CARRY OUT A SERVICE AS PER CHECK LIST A service completed and tensioned wheel nuts w/ Sadid		1069497
8228	12/23/2019	863549		Assisted.		1069497
8228	12/23/2019	863549	Consumables			1069651
8228	12/23/2019	863549	Consumables			1069651
8228	12/23/2019	863549	Consumables			1069651
8228	12/16/2019	862127	Done in Sept			1068030
8228	12/11/2019	861370	A/C belt need replace			1067311
8228	12/11/2019	861370	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG			1067311
8228	12/11/2019	861370	Consumables			1067532
8228	12/11/2019	861370	Ops Entered - Fault - Fuel - Route: 900 - Stud Park Shoppin	Drive tested and checked fuel leaks found leaks from fuel line to fuel filter. Replaced copper washers drive tested and checked ok.		1067311
8228	12/09/2019	860777	Mechanic entered - Fluid Leaks Middle of bus fuel cap	ADJUSTED.		1066698
8228	12/05/2019	859622	NUT BRASS BATTERY TERMINAL NEGATIVE (-) MA14HDN			1066300
8228	12/05/2019	859622	NUT BRASS BATTERY TERMINAL NEGATIVE (-) MA14HDN			1066300
8228	12/05/2019	859622	Drv entered - Elec and Light Flat Batteries	Load tested the battires on not so good but before replaced cleaned out compartment as really dirty.Removed batterys.Cleaned and spray painted securing bar also fitted different polarity batties dur eto positive to close to touching chasis.Also put conduuit on positive and also replaced all terminals.		1066300
8228	12/05/2019	859622	BATTERY1000CCAPOS ON RHS EMFN200R			1066300
8228	12/05/2019	859622	Consumables			1066300
8228	12/03/2019	858819	A3 Poster Frame Adhesive Decal Campaign please remove old	Completed by ECTB		1065777
8228	11/29/2019	858057	KIT O-RING LARGE VOSS (A6739970145)			1065220
8228	11/29/2019	858057				1065220
8228	11/29/2019	858057	AIR DRYER ASSY MERC BENZ 0500LE A0004302915			1065220
8228	11/29/2019	858057	KIT O-RING SMALL VOSS (A0309971748)			1065220
8228	11/29/2019	858057		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Checked air line condition from compressor to air dryer Ok.		1065220
8228	11/29/2019	858057	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE			1065220
8228	11/13/2019	853969	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833			1061847
8228	11/13/2019	853969	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG			1061847
8228	11/13/2019	853969	Mechanic entered - Fluid Leaks Other Fuel leak under fuel ta	road test clean fuel tank. road tested . checked ok.		1061847
8228	11/13/2019	853969	Mechanic entered - Engine Other Water pump leaking	fit new water pump. new drive belt new adjuster pulley.		1061847
8228	11/12/2019	853969	Mechanic entered - Fluid Leaks Other Fuel leak side of the e	secure injector and leakoff pipes.		1061847
8228	11/12/2019	853969	WATER PUMP MERC BENZ 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G262205 Receiving #:272136 Date :2019-11-12		1061847
8228	11/12/2019	853969	Mechanic entered - Body Other Steam wash engine and top of t	clean engine and gear box.		1061847
8228	11/12/2019	853969	Mechanic entered - Body Other Both front mudflap missing	fit new mud flaps.		1061847
8228	11/12/2019	853969	MUDFLAP 605MM X 330MM			1061847
8228	11/12/2019	853969	Mechanic entered - Air System Other Air leak on top of accum	reseal air pipes.		1061847
8228	11/12/2019	853969	KIT O-RING SMALL VOSS (A0309971748)			1061847
8228	11/12/2019	853969	KIT O-RING SMALL VOSS (A0309971748)			1061847
8228	11/11/2019	853727		VEHICLE SAFETY INSPECTION Safety Inspection completed and tensioned all wheel nuts		1061847
8228	11/11/2019	853727		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1061847
8228	11/11/2019	853727		VEHICLE SAFETY INSPECTION Safety Inspection completed and tensioned all wheel nuts		1061847

[illegible]

[illegible]

8228	03/13/2019	803154	GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596FWLED		1027613
8228	03/13/2019	803157	EDGE SENSITIVE EDGE DOOR SWITCH DW40		1027613
8228	03/12/2019	802981			1027330
8228	03/12/2019	802981		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tentioned all wheel nuts with Tayla	1027330
8228	03/12/2019	802981		VEHICLE SAFETY INSPECTION Carried out safety as per check list with Tayla and Oliver.	1027330
8228	03/12/2019	803160	Mechanic entered - Steering Excessive Play Grease both Kingp	Greased both kingpins took up the play.	1027330
8228	03/12/2019	803038	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG		1027330
8228	03/12/2019	803038	Mechanic entered - A/C Heating Belt Loose or _Missing A/C bel		1027330
8228	03/12/2019	803155	Mechanic entered - Engine Other Wash engine and gear box		1027330
8228	03/12/2019	803156	Consumables	Removed floor hatch and washed engine and gearbox	1027613
8228	03/12/2019	803156	Mechanic entered - Elec and Light Interior Lights One light	Replaced globe	1027330
8228	03/12/2019	803154	Mechanic entered - Dash Dash_Lights Not Working Ramp request	Replaced globe now working	1027330
8228	03/12/2019	803157	Mechanic entered - Body Rear_Door Operation Faulty Adjust re	Adjusted edges but still no good replaced adjuster units and still no good elias helped set up right now working	1027330
8228	03/12/2019	803153	Mechanic entered - Body Passenger Seat Torn Bolt missing on	Fitted missing bolt on rear seats	1027330
8228	02/28/2019	800862	Consumables		1025907
8228	02/28/2019	800862	Mechanic entered - Elec and Light Exterior Lights LH Parker	R/R LH front Parker light globe	1025320
8228	02/28/2019	800862	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)		1025320
8228	02/20/2019	799172	Consumables		1024468
8228	02/20/2019	799172	Mechanic entered - Body Other driver's cab door hinges loose	replaced missing screws. adjusted and tightened hinges.	1023933
8228	02/15/2019	798281		Retentioned pos 5/6 with Indika	1023436
8228	02/14/2019	797925	Consumables		1023436
8228	02/14/2019	797925	Mechanic entered - Wheels and Tyres Worn pos 56	Sadid changed pos 56 tyres (run out from stor) tensioned wheel nut with sisil	1023367
8228	02/14/2019	797977	HOSE COOLANT BOTTOM OF HEADTANK 0500LE		1023367
8228	02/14/2019	797977	Mechanic entered - Fluid Leaks Rear of bus coolant leaking.	completed changed header tank road tested allgood.	1023367
8228	02/14/2019	797977	TANK COOLANT HEADER MERC 040	Creditor # :GB-MUL001 MULTISPARES LTD P/O #:G241184 Receiving #:249410 Date :2019-02-14	1023367
8228	02/14/2019	797914	Consumables		1023436
8228	02/14/2019	797914	Consumables		1023436
8228	02/14/2019	797914	Consumables		1023436
8228	02/14/2019	797914	Consumables		1023367
8228	02/14/2019	797914		CARRY OUT A SERVICE AS PER CHECK LIST	1023367
8228	02/06/2019	796110	Bunch of tagging at rear of bus. Windows x 4. Back of chair	CARRY OUT A SERVICE AS PER CHECK LIST	1021626
8228	02/04/2019	795334	WIPER WASHER HOSE+JET ASSY	graffiti cleaned (victor)	1020620
8228	02/04/2019	795334	Drv entered - Wipers and Washers Washers Not Working		1020620
8228	02/01/2019	794916	Consumables		1021246
8228	02/01/2019	794916	Mechanic entered - Elec and Light Exterior Lights headlights	check and fixed hi beam conector bus ok.	1020620
8228	02/01/2019	798971	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1021246
8228	01/29/2019	794141	Tablet Entered - Front doors not closing	check air system fixed 4 way value road tested bus ok.	1020264
8228	01/23/2019	793269	Consumables		1019452
8228	01/23/2019	793269	Drv entered - BusMinder Damaged	checked found bus minder not damaged or already replaced.Checked if charging and charging ok.checked stand and stand ok.	1019383
8228	01/22/2019	792824	Consumables		1019383
8228	01/22/2019	792824	Ops Entered - Fault - BusMinder Unable To Log In - Route:	sent email to Ron to rectify	1019383
8228	01/21/2019	792484	Drv entered - A/C Heating Not Heating	Tested heating run unit up to 25c and retruned too set point check demisters tested ok	1018840
8228	01/21/2019	792485	Please remove old 2018 fare decals and fit new 2019 fare dec	Replaced	1018840
8228	01/18/2019	790553	REPAIR SEAT BASES	Creditor # :GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G238643 Receiving #:247111 Date :2019-01-18	1018840
8228	01/11/2019	790553	CAP END CAP CENTRA SEAT END CAP		1017426
8228	01/11/2019	790553	GLOBE 24V 10W SINGLE CONTACT		1017426
8228	01/11/2019	790553		Helped with safety and repairs	1017426
8228	01/11/2019	790553		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts with mark	1017426
8228	01/11/2019	790553		completed Safety <> R/R bus stop globes <> replaced 3 x base cushion <> removed graffiti from rear of bus <> replaced missing yellow strips at rear of bus <> replaced miss black seat cap <> Replaced rhs no plate light	1017426
8228	01/11/2019	790553	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1017426
8228	01/11/2019	790654	Consumables		1018040
8228	01/11/2019	790654	Drv entered - BusMinder Unable To Log In	send emailed to Ron to fix on 11/01/19	1017426
8228	01/11/2019	790654	Ops Entered - Fault - BusMinder Unable To Log In - Route:	send emailed to Ron to fix on 11/01/19	1017426
8228	01/11/2019	790654	Ops Entered - Fault - BusMinder Unable To Log In - Route:	send emailed to Ron to fix on 11/01/19	1017426
8228	01/04/2019	789278	Drv entered - A/C Heating Not Cooling	Commission tested found unloader was not on stem locked back into positin and un unit unit drop to 23c with door open replaced return air filter medium	1016778
8228	01/02/2019	788883	Vandalism - Removed graffiti from front of bus	removed	1016527
8228	12/29/2018	788350	Consumables		1016127
8228	12/29/2018	788350	LED INT LIGHT ORION		1015651
8228	12/29/2018	788350	Mechanic entered - Elec and Light Interior Lights	replaced faulty saloon light.	1015651
8228	12/04/2018	783797	SWITCH DR CONTACT (NORMALLY OPEN) (M22-K10)		1011197
8228	12/04/2018	783797	EDGE SENSITIVE EDGE DOOR SWITCH DW40		1011197
8228	12/04/2018	783797	Mechanic entered - Body Rear_Door Operation Faulty	Rear doors not working.Replaced valves at back and door switch for rear.	1011197
8228	11/26/2018	781680	Consumables		1009962
8228	11/26/2018	781846	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	Replaced under w/order 781680	1009301
8228	11/26/2018	781680	LAMP STOP/TAIL LED HELLA		1009301
8228	11/26/2018	781680	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	replaced rns top park/brake light assy	1009301
8228	11/26/2018	781846	Consumables		1009962
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1008571
8228	11/19/2018	780242	FILTER OIL FILTER MERCEDES A0001801709		1008571
8228	11/19/2018	780242	OIL ENGINE OIL MINERAL 15W-40 DELO 400 LE (LU18)(3361808)		1008571
8228	11/19/2018	780242		CARRY OUT B SERVICE AS PER CHECK LIST	1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/19/2018	780242	Consumables		1008571
8228	11/12/2018	778961		CARRY OUT A SERVICE AS PER CHECK LIST	1007420
8228	11/12/2018	778961		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done.	1007420
8228	11/12/2018	778990	Mechanic entered - Body Other Rear passenger door keep on op	VEHICLE SAFETY INSPECTION Completed.	1007420
8228	11/10/2018	778642		Check for fault found rear door bush worn remove and replace and door have gap not sealing adjust door. re check for operation works ok.	1007420
8228	11/09/2018	778433	Consumables	re-tensioned all drive wheel nuts with dulkith.	1007948
8228	11/09/2018	778433	Mechanic entered - Wheels and Tyres Worn tyres3 and 5 (worn)	changed tyres 3 and 5 (worn). put tyre 4 to pos. 5. new tyres at pos. 3 and 4. all drive wheel nuts tensioned with ryan.	1007420
8228	11/09/2018	778433	TYRE 295/80R22.5 NEW		1007420
8228	11/07/2018	777952	SILENCER DOOR VALVE SILENCER		1006797
8228	11/07/2018	777952	Drv entered - Body Rear_Door Operation Faulty	check rear passanger doors and replaced control value bus ok.	1006797
8228	11/07/2018	777952	VALVE 5 PORT PILOT		1006797

8228	11/02/2018	768269	CLEAN GRAFFITI INSIDE	Creditor #:'GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:'G233581 Receiving #:'241415 Date :2018-11-07	1007312
8228	11/01/2018	775944	REPLACE ANTI GRAFFITI FILM	Creditor #:'GB-GLA010 GLASSPROTECH MELBOURNE P/O #:'G232941 Receiving #:'241424 Date :2018-11-07 L12 R12	1007312
8228	10/29/2018	776307	SEAL O-RING DISCHARGE VIBRASORBER SCREW TYPE		1005267
8228	10/29/2018	776307	NITROGEN DRY D SIZE		1005267
8228	10/29/2018	776307	PULLEY ADJUSTER IDLER PULLEY MERCEDES 0500 (A000501833)		1005267
8228	10/29/2018	776307	AIR CON REFRIDGERANT		1005267
8228	10/29/2018	776307	Mechanic entered - A/C Heating Not Cooling	Tested fond the muffler has failed and back idler noisye Replaced failed oring remove muffler and replaced section off pipe replaced back idler noisye bearing pressure tested and vac system charge and tested with electromic refrigerant leak detector tested ok	1005267
8228	10/29/2018	775992	SILENCER AIR DRYER MERC 0500LE		1005267
8228	10/29/2018	775992	Mechanic entered - Brakes Foot_Brakes Leaking Air		1005267
8228	10/29/2018	776305		replace air drier and exhaust muffler	1005267
8228	10/29/2018	776305		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Check drier and oil both tested ok none in stock	1005267
8228	10/29/2018	776305		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1005267
8228	10/26/2018	775944	Vandalism - Replace Anti graffiti Film - L12 R12	REPLACED BY GLASSPROTECH	1005047
8228	10/26/2018	775985	Breakdown#:'35713 - Ops Entered - Breakdown - Breakdown Brake	bus B/down faulty air system fixed temperaly and drive to depot need to fixed air leak	1005047
8228	10/26/2018	775992	Mechanic entered - Brakes Foot_Brakes Leaking Air		1005047
8228	10/26/2018	775992	KIT O-RING SMALL VOSS (A0309971748)		1005047
8228	10/26/2018	775992	KIT O-RING LARGE VOSS (A6739970145)		1005047
8228	10/26/2018	775992	SEAL RING A/DRYER		1005047
8228	10/26/2018	775992	AIR DRYER ASSY A0004302915		1005047
8228	10/23/2018	775312	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)		1004673
8228	10/23/2018	775312	KIT O-RING LARGE VOSS (A6739970145)		1004673
8228	10/23/2018	775312	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1004673
8228	10/23/2018	775312		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Carry out Air system service	1004673
8228	10/19/2018	774508	Mechanic entered - Vandalism Other rear side windows badly	Cleaned by Fleet Support	1003614
8228	10/02/2018	770060	Consumables		1000026
8228	10/02/2018	770060	Mechanic entered - Elec and Light Indicators Not Working	changed blown globe (nsf) side indicator.	999040
8228	10/02/2018	770060	GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT		999040
8228	10/01/2018	769725	Consumables		999857
8228	10/01/2018	769725	GLOBE 24V 70W H1		999040
8228	10/01/2018	769725	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	changed blown globe (ns) low beam headlight.	999040
8228	10/01/2018	769725	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers	999040
8228	09/27/2018	768269	DIRECT PURCHASE - VANDALISM	Creditor #:'GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:'G230687 Receiving #:'238486 Date :2018-10-01 Removed grafitti & paint rear of seats & panels	999040
8228	09/21/2018	768371		Assisting	997959
8228	09/21/2018	768371		Tensioned all tyres.	997959
8228	09/21/2018	767704		wrong bookback	997959
8228	09/21/2018	768269	Vandalism Vandalism/ Graffiti Interior rear window drive	Graffiti clean by East coast	997959
8228	09/21/2018	768269	Vandalism - clean back seats a/c ducts windows side wall	As above	997959
8228	09/20/2018	767704		VEHICLE SAFETY INSPECTION	997959
8228	09/20/2018	767704		VEHICLE SAFETY INSPECTION	997959
8228	09/20/2018	767704		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	997959
8228	09/20/2018	767752	Vandalism (None) External Rear Emergency Exit Sticker t	Checked has been replaced	997959
8228	09/20/2018	767704	Brakes - Remove tyres and check brakes	Assisted & retensioned	997959
8228	09/20/2018	767704	Brakes - Remove tyres and check brakes	Removed and checked put tyres back and retensioned	997959
8228	09/20/2018	767744	KIT O-RING LARGE VOSS (A6739970145)		997959
8228	09/20/2018	767744	Air System leaks	Replace plastic pipe conection kit	997959
8228	09/19/2018	767521	SPRING RECLINE D/SEAT		997959
8228	09/19/2018	767521	Ops Entered - Fault - Body Drivers Seat Controls - Route: 9	Check and found spring broken replaced spring	997959
8228	09/13/2018	766144	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	995633
8228	08/31/2018	763180	Consumables		993019
8228	08/31/2018	763180	Consumables		993019
8228	08/31/2018	763180	Consumables		993019
8228	08/31/2018	763180	Consumables		993019
8228	08/31/2018	763180	Consumables		993019
8228	08/27/2018	762115	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	CARRY OUT A SERVICE AS PER CHECK LIST	992406
8228	08/14/2018	759162		Completed.	991690
8228	08/14/2018	759162	Gasket Rocker Cover Mercedes 0500	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Carried out tune up as per check list washed oil off engine and road test bus. No leaks.	989760
8228	08/08/2018	758068	RADIATOR CAP 70KPA - BEHR A0005014615		989760
8228	08/08/2018	758068	INSPECTION HOLE GASKET		988540
8228	08/08/2018	758068	Engine - Engine sump leak	Rectify oil leak found leaking oil at inspection hole of compressor. Remove and replace gasket. Leaking oil at oil filter housing sender Remove and replace oil sender o-ring. Refit sender and topped-up oil Steam clean engine and roadtest do a good roadtest and re check for oil leak found after roadtest leaking oil at steering	988540
8228	08/08/2018	758068	Fluid Leaks - Coolant leak top of engine	Rectify coolant leak found heater hose leaking coolant Remove hose. Fitted new hose and re position hose and secured. Topped-up coolant found radiator cap rubber worn. Replace radiator cap. Steam clean Engine and roadtest check for heater operation ok. Re check for leak and coolant level all ok.	988540
8228	08/07/2018	757575		VEHICLE SAFETY INSPECTION	987885
8228	08/07/2018	757575		VEHICLE SAFETY INSPECTION	987885
8228	08/07/2018	757575		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	987885
8228	08/01/2018	754194	DIRECT PURCHASE - VANDALISM	Creditor #:'GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:'G225129 Receiving #:'233752 Date :2018-08-06 CLEAN VANDALISM AS REQUIRED	987885
8228	08/01/2018	756445	Body rear door rubber seal coming lose	re-inserted both front and rear doors rubber seal back into tracks.	986935
8228	08/01/2018	756445	Body rear door rubber seal coming lose	fixed.	986935
8228	07/31/2018	756171	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Checked by Refuellers and this job has been done	986935
8228	07/26/2018	755147	REMOVE OLD POSTER AND REPLACE WITH BUS TIMES ARE CHANGING	Replaced by refuellers	986455
8228	07/21/2018	754194	Vandalism Vandalism/ Graffiti Interior back of rear seats	Cleaned by ECTB	985332
8228	07/09/2018	751093	FUSE BLADE 10 AMP (NR52810)		983000
8228	07/09/2018	751093	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	complete	983000
8228	06/22/2018	747316	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	REPLACED	979870
8228	06/20/2018	746657	DIRECT PURCHASE - VANDALISM	Creditor #:'GB-GLA010 GLASSPROTECH MELBOURNE P/O #:'G222693 Receiving #:'230252 Date :2018-06-22 REPLACED L12R12	979870
8228	06/20/2018	746657	Vandalism - Replace anti graffiti film - L12 R12	Replaced 14/06/18	979517
8228	06/18/2018	745391	DIRECT PURCHASE - VANDALISM	Creditor #:'GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:'G222231 Receiving #:'230058 Date :2018-06-20 CLEAN	979291
8228	06/14/2018	744672	DIRECT PURCHASE - BUS INSPECTI	Creditor #:'GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:'G221942 Receiving #:'230349 Date :2018-06-25 RSI	980086
8228	06/14/2018	745391	Vandalism - Clean graffiti as required	CLEANED BY ECTB 26/05/18	978655
8228	06/14/2018	745429	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	completed.	978655
8228	06/13/2018	744672		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	977250
8228	06/13/2018	744672		VEHICLE SAFETY INSPECTION	977250
8228	06/13/2018	744672	GLOBE 24V 10W SINGLE CONTACT		977250
8228	06/13/2018	744672		ANNUAL SAFETY INSPECTION SERIAL - RWC 016891 - PASSED - 13/06/18WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	977250
8228	06/13/2018	745092	Consumables		978655
8228	06/13/2018	745092	Consumables		978655
8228	06/13/2018	745092	Consumables		978655
8228	06/13/2018	745092	Consumables		978655
8228	06/13/2018	745092		CARRY OUT A SERVICE AS PER CHECK LIST	977250
8228	06/06/2018	742766	Fluid Leaks - Coolant leak coolant hoses from header tank	Tightened hose clamp	976200
8228	06/06/2018	742766	Body - few pax seats torn & damaged	Jordan fitted 05/06/2018	976200
8228	06/05/2018	743560	GLOBE 24V 70W H1		976200
8228	06/05/2018	743560	Consumables		976629
8228	06/05/2018	743560	Mechanic entered - Elec and Light Exterior Lights RHS Front	Removed and Replaced N/S Headlight globe.	976200
8228	06/05/2018	742766	SINGLE SEAT BASE		976200
8228	06/05/2018	742766	CENTRA CUSHION CLIP RH		976200

8228	06/05/2018	742766	CENTRA CUSHION CLIP LH		976200
8228	06/04/2018	742766	Engine - Steamclean the bus	completed	976200
8228	06/04/2018	742766	REPAIR DISABLED SEATS	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G221362 Receiving #:229011 Date :2018-06-05	976629
8228	06/04/2018	742766	DOUBLE SEAT BASE RETRIMMED	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G221362 Receiving #:229011 Date :2018-06-05	976629
8228	06/04/2018	742766	SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G221362 Receiving #:229011 Date :2018-06-05	976629
8228	06/04/2018	742766	Air System - Air leak next to air dryer	replaced 12 air line fitting oring kit	976200
8228	06/04/2018	742766	KIT O-RING LARGE VOSS (A6739970145)		976200
8228	06/01/2018	742708		PRE ANNUAL SAFETY INSPECTION CHECK completed	976200
8228	06/01/2018	742708		PRE ANNUAL SAFETY INSPECTION CHECK completed	976200
8228	06/01/2018	742708	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		976200
8228	06/01/2018	742766	Body - few pax seats torn & damaged	20 seats sent for repair	976200
8228	06/01/2018	742766	Body - Secure side panel	completed	976200
8228	06/01/2018	742766	Body - Replace 2 x disability decals	replaced borth	976200
8228	06/01/2018	742766	Body - Secure N/R b/bar	completed	976200
8228	06/01/2018	742766	Body - 2 x seat handles damaged	replaced borth	976200
8228	06/01/2018	742766	CENTRA CUSHION CLIP LH		976200
8228	06/01/2018	742766	PASS SEAT HANDGRIP CENTRA MK 2 (310254)		976200
8228	06/01/2018	742766	Body - Rear door rubber came out	fitted back	976200
8228	06/01/2018	742766	KIT O-RING LARGE VOSS (A6739970145)		976200
8228	06/01/2018	742766	KIT O-RING LARGE VOSS (A6739970145)		976200
8228	06/01/2018	742766	KIT O-RING LARGE VOSS (A6739970145)		976200
8228	05/22/2018	740252		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST fire safety inspection complete	976200
8228	05/22/2018	740158	KIT SWITCH OVERRIDE RPD		973925
8228	05/21/2018	740130		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	973925
8228	05/21/2018	740130		VEHICLE SAFETY INSPECTION	973925
8228	05/21/2018	740130			973925
8228	05/21/2018	740158	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INST	Wired bus Programed node and did the check sheet all ok.	973925
8228	05/19/2018	739743		re tensioned wheel nuts with sisil.	973925
8228	05/19/2018	739740	Vandalism Vandalism/ Graffiti Interior bright orange graf	completed.	973925
8228	05/18/2018	739518	TYRE 295/80R22.5 NEW		973925
8228	05/18/2018	739518	Wheels and Tyres - Pos 2 tyre needs replacing	changed tyres 1 (rack) and 2 (worn). 295's fitted. all steer wheel nuts tensioned with dulkith.	973925
8228	05/18/2018	739518	Consumables		974900
8228	05/18/2018	739956	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed	973925
8228	04/30/2018	735655		CARRY OUT FIRE EXTINGUISHER TEST & TAG	969674
8228	04/30/2018	735655		COMPLETED ON 15/02/18	969674
8228	04/10/2018	732062		VEHICLE SAFETY INSPECTION	965502
8228	04/10/2018	732062		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	965502
8228	04/10/2018	732062		VEHICLE SAFETY INSPECTION	965502
8228	04/09/2018	731650	Accident#:46890 - Ops Entered - Accident - Bus is hit by 3r	Job has been completed	965246
8228	03/24/2018	728997	Body Fuel Cap Doesn't lock	fuel cap fixed fri. 23/3/18. operation checked today. opens and closes(locks) o.k.	963260
8228	03/23/2018	728850	Mechanic entered - Body Other Fuel locking cap broken	removed panel. removed spot welds from bottom attachment pin. removed cap. cleaned. securing latch re-welded to cap. cap re-assembled and fitted to tank. operation checked -o.k. panel re-attached and secured. dulkith assisting.	963260
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	FILTER AIR FILTER MERCEDES BENZ 0500LE (E491L)		963260
8228	03/23/2018	728749	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)		963260
8228	03/23/2018	728749	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		963260
8228	03/23/2018	728749		CARRY OUT C SERVICE AS PER CHECK LIST completed.	963260
8228	03/23/2018	728749	OIL FAN DRIVE OIL MERCEDES 0500LE		963260
8228	03/23/2018	728749	FILTER P/STEER SCANIA VOLVO M/BENZ (E10H02) 0153468_1585618		963260
8228	03/23/2018	728749	FILTER FUEL FILTER MERCEDES 0500LE		963260
8228	03/23/2018	728749	FILTER FUEL FILTER MERCEDES 0500LE		963260
8228	03/23/2018	728749	OIL ENGINE OIL MINERAL 15W/40 DELO 400 (LU18) (3361808)		963260
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/23/2018	728749	Consumables		963492
8228	03/22/2018	728640	Fluid Leaks Rear of buspuddle of coolant of bus	CARRY OUT A SERVICE AS PER CHECK LIST	963260
8228	03/19/2018	727715	Consumables	road tested clean enginesecure coolant hosesroad tested ok.	963260
8228	03/19/2018	727714	Consumables		962732
8228	03/19/2018	727715	Mechanic entered - Elec and Light Exterior Lights RHS Headli	refer to preivous order	962553
8228	03/19/2018	727714	GLOBE 24V 70W H1		962553
8228	03/19/2018	727714	Mechanic entered - Elec and Light Exterior Lights head light	removed replaced globe	962553
8228	03/15/2018	727001	Drv entered - Body Drivers Seat Controls	check and adjusted driver seat back rest lock	961493
8228	03/15/2018	727001	Mechanic entered - Body Other Fuel cap no longer locking shu	check and fixed fuel cap	961493
8228	03/13/2018	726437	Breakdown#:34628 - Ops Entered - Breakdown - Breakdown Overh	bus B/down on Welington rd fixed temperaly and drive to depot releplaced all heter hoses topup coolant road test bus ok.	960678
8228	03/07/2018	725403	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		959686
8228	03/07/2018	725403	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		959686
8228	03/07/2018	725403	KIT CYCLONE CONDENSER VALVE KIT		959686
8228	03/07/2018	725403	HALDEX COIL BASE OIL SEPERATOR (49G0031)		959686
8228	03/07/2018	725403	KIT DRAIN VALVE KIT BOTTOM		959686
8228	03/07/2018	725403	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		959686
8228	03/07/2018	725403			959686
8228	03/07/2018	725403		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed with Mark.	959686
8228	03/07/2018	725403	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		959686
8228	03/07/2018	725403	KIT HALDEX COIL KIT MERCEDES 0500LE (49G0027)		959686
8228	03/07/2018	725403	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		959686
8228	02/27/2018	723220	Consumables		958179
8228	02/27/2018	722663	Consumables		958179
8228	02/27/2018	723220	Ops Entered - Fault - Elec and Light Exterior Lights - Head	checked and ok.	957512
8228	02/27/2018	722663	GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		957512
8228	02/27/2018	722663	Mechanic entered - Elec and Light Exterior Lights	repleaced ns park light globe.	957512
8228	02/27/2018	722321	GLOBE 24V 70W H1		957512
8228	02/27/2018	722942	Please remove any old poster and fit new ones multi choice	Fitted by Refuellers	957512
8228	02/27/2018	722830	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	Replaced decal	957512

8228	02/26/2018	722321	Elec and Light Hight beam U/S	Replace globe	957512
8228	02/16/2018	720236	Consumables		955793
8228	02/16/2018	720236	GLOBE 24V 10W SINGLE CONTACT		955360
8228	02/16/2018	720234	SEAT FOAM CUSHION PAN DRIVERS SEAT ISRI A6008BASE		955360
8228	02/15/2018	720223		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS VEHICLE SAFETY INSPECTION R/R globe. R/R drivers seat cushion.	955360
8228	02/15/2018	720223			955360
8228	02/15/2018	720223			955360
8228	02/15/2018	720236	Mechanic entered - Elec and Light Interior Lights Passenger		955360
8228	02/15/2018	720234	Mechanic entered - Body Other Drivers seat cushion U/S	replaced.	952868
8228	02/08/2018	718212	SINGLE SEAT BACK REST		952868
8228	02/08/2018	718212	Mechanic entered - Body Passenger Seat Torn		952558
8228	02/05/2018	717488	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		952558
8228	02/05/2018	717488		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	952787
8228	02/05/2018	717511	Consumables		952558
8228	02/05/2018	717511	Elec and Light - c/room bay engine light faulty		952558
8228	02/05/2018	717512	CCTV only recording from one camera Video Loss light on.		953254
8228	02/01/2018	715303	REPLACE ANTI GRAFFITI FILM	Creditor #:-GB-GLA010 GLASSPROTECH MELBOURNE P/O #:-G212236 Receiving #:-220494 Date :2018-02-08 Repaired by ECTB Replaced By Glassprotech	950173
8228	01/25/2018	715509	Rectify Vandalism damage reported by refuelers		949792
8228	01/24/2018	715303	Vandalism - Replace Anti Graffiti Film - L123 R123		950173
8228	01/24/2018	714707	Consumables		950173
8228	01/24/2018	714706	Consumables	Creditor #:-GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:-G211971 Receiving #:-219411 Date :2018-01-25 Repaired by Whitehorse Repaired by Whitehorse	950173
8228	01/24/2018	714706	CHECK AND REPAIR WARNING BUZZ		949792
8228	01/24/2018	714707	Ops Entered - Fault - Elec and Light Warning Light On Dash -		949792
8228	01/24/2018	714706	Ops Entered - Fault - Elec and Light Warning Light On Dash -		950173
8228	01/24/2018	714707	Consumables	found buzzer to be on all the time only thing on dash is fault code (INS 1125) power steering inplusable. also changed air presure sender switch still buzzing send to whitehorse	949792
8228	01/24/2018	714706	Consumables		949792
8228	01/22/2018	714707	Ops Entered - Fault - Elec and Light Warning Light On Dash -		949792
8228	01/22/2018	714707	SWITCH LOW AIR 0500LE (A0045455514)		948645
8228	01/22/2018	714706	LOW WATER PROBE 500LE	CARRY OUT A SERVICE AS PER CHECK LIST completed and tensioned wheel nuts with phil	948645
8228	01/12/2018	713292	Consumables		948645
8228	01/12/2018	713292	Consumables		948645
8228	01/12/2018	713292	Consumables		948645
8228	01/12/2018	713292	Consumables	Fitted	947934
8228	01/12/2018	713292	Consumables		947329
8228	01/12/2018	713292	Consumables		947329
8228	01/12/2018	713292	Consumables		946709
8228	01/08/2018	712359	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	replaced missing emerg. exit pull cover (centre door) and secured loose access panel above.	946709
8228	01/04/2018	711334	Consumables		945442
8228	01/04/2018	711334	Consumables		945442
8228	01/04/2018	711334	EMERGENCY EXIT BUTTON PULL COVER (16906)		942374
8228	01/04/2018	711334	Body - Centre door exit flap cover missing	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS VEHICLE SAFETY INSPECTION	942292
8228	12/28/2017	710418			942292
8228	12/28/2017	710418			942292
8228	12/28/2017	710418			939658
8228	12/15/2017	708397	Consumables	changed blown globe (nsf) bottom park light. found that drivers camera was disconnected from thoreb unit plugged and tightened and now working fine	935829
8228	12/15/2017	708397	GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		935829
8228	12/15/2017	708397	GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		935469
8228	12/15/2017	708397	Elec and Light - LH park light out		935469
8228	12/07/2017	706531	CCTV CCTV not recording driver camera not recording.	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done VEHICLE SAFETY INSPECTION Completed Remove and repair stitch rip part. check warning light and adjusted wheel chair ramp check park brake air presure road test bus ok. bus B/D on North rd air pressure flaxi hose burst waitng for parts repleaced hose drive to depot.	935276
8228	11/17/2017	702476	VALVE 5 PORT PILOT		935276
8228	11/17/2017	702476	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou		934498
8228	11/15/2017	701979	SENSOR LEVELLING VALVE ECAS M BENZ 0500LE A0015420018		934286
8228	11/15/2017	701979	Drv entered - Suspension Hard	REMOVED added coolant - low.	934286
8228	11/15/2017	701979	Drv entered - Suspension Leaning		934286
8228	11/14/2017	701573			933665
8228	11/14/2017	701573			933665
8228	11/14/2017	701588	Mechanic entered - Body Passenger Seat Torn Rear pasenger se	changed blown globe (os) low beam headlight. CARRY OUT A/C - A SERVICE AS PER CHECK LIST Check for fault found sensor o-ring worn damage remove and replace. steam clean roadtest re check for leak ok no leak.	933550
8228	11/10/2017	700728	Ops Entered - Fault - Air System Air Not Building_Up - Rout		933550
8228	11/08/2017	700116	Ops Entered - Fault - Air System Air Not Building_Up - Rou		933550
8228	11/08/2017	700116	HOSE COMPRESSOR TO UNLOADER MERCEDES (A0014292135)		933550
8228	11/08/2017	700116	COUPLING AIR HOSE COMPRESSOR MERCEDES 0500 (50G4501)	CARRY OUT A SERVICE AS PER CHECK LIST Complete Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:-G205157 Receiving #:-213109 Date :2017-10-30 completed by East coast REPLACED BY REFUELLERS	933102
8228	11/08/2017	700163	Please remove the 2 x Do Not Enter decals at the exterior		929807
8228	11/06/2017	699841	Mechanic entered - Fluid Leaks Other		929807
8228	11/06/2017	699839	Consumables		929807
8228	11/06/2017	699839	GLOBE 24V 70W H1	fitted indicator stalk fiottwed new emergency light fitted indicator stalk fitted rear seat Did the Audit replaced. CARRY OUT FIRE EXTINGUISHER TEST & TAG Done	929779
8228	11/06/2017	699839	Elec and Light Exterior Lights Front Right Hand Headlight		929779
8228	11/02/2017	699356			929779
8228	11/01/2017	698976	Mechanic entered - Engine Other Oil sensor leaking.		929779
8228	11/01/2017	698973	Consumables	829807	929779
8228	11/01/2017	698973	Consumables		929779
8228	11/01/2017	698973	Consumables		929779
8228	11/01/2017	698973	Consumables		929779
8228	11/01/2017	698973	Consumables	929340	929779
8228	11/01/2017	698973	Consumables		929340
8228	11/01/2017	698973	Consumables		927665
8228	11/01/2017	698973	Consumables		926832
8228	10/27/2017	695299	CLEAN GRAFFITI INSIDE	926832	
8228	10/18/2017	695299	Vandalism Vandalism/ Graffiti Interior rear roof		
8228	10/17/2017	694940	Remove old poster and fit new A3 Posters and hangers		
8228	10/16/2017	694357	Consumables		
8228	10/16/2017	694357	Consumables	929779	
8228	10/16/2017	694357	ARM INDICATOR ARM MERCEDES 0500LE (50V4710)		
8228	10/16/2017	694357	LED FRONT POSITION MARKER LIGHT		
8228	10/16/2017	694357	Ops Entered - Fault - Elec and Light Indicators Not Working		
8228	10/16/2017	694357	Elec and Light - Rear door exit light dull	929340	
8228	10/16/2017	694357	Mechanic entered - Elec and Light Indicators Not Working ind		
8228	10/16/2017	694357	Body - Seat base cushion rear row ripped		
8228	10/12/2017	693792	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT		
8228	10/06/2017	692033	Body rear yellow grip on step is missing	926832	
8228	10/04/2017	691070			
8228	10/04/2017	691070			
8228	10/04/2017	691070			

8228	09/26/2017	689681	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		925033
8228	09/26/2017	689681	BUTTON CLIPPARD DOOR VALVE 49Z4811		925033
8228	09/26/2017	689681	Ops Entered - Fault - Passenger Doors - Route: 900 - Monash	found air leaking through to open valve so not shuttin and opening correctlty.Removed open and close valves and replaced with new ones.Tested 10 times and working ok.	925033
8228	09/26/2017	689868	Remove old A3 Posters with Seniors Festival please leave	Replaced by Fleet Support	925033
8228	09/25/2017	689261		Tensioned all rear tyres.	925033
8228	09/25/2017	689261		Assisting	925033
8228	09/25/2017	688478	FILTER AIR FILTER MERCEDES BENZ 0500LE (E491L)		925033
8228	09/25/2017	688750	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	i cleaned graffiti in side this bus	925033
8228	09/25/2017	688750	CCTV - Drivers camera n/w	found fault re attached camera and working fine	925033
8228	09/25/2017	689246	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	Fitted rear decals.	925033
8228	09/25/2017	689246	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		925033
8228	09/25/2017	689260	Body - Rear door top panel lock missing		925033
8228	09/23/2017	688478		Secured hatch	925033
8228	09/23/2017	688478		assisted ryan. completed.	925033
8228	09/23/2017	688504	REFILL WIPER REFILL TO SUIT TX800 / TX900	VEHICLE SAFETY INSPECTION Safety Inspection Completed with Mark	925033
8228	09/23/2017	688504	Mechanic entered - Wipers and Washers Other Wiper Blades Wor	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	925033
8228	09/23/2017	688504	Consumables		925033
8228	09/23/2017	688504	SINGLE SEAT BASE		925285
8228	09/23/2017	688504	REFLECTOR AMBER 94 X 44mm		925033
8228	09/23/2017	688504	TYRE 295/80R22.5 NEW		925033
8228	09/23/2017	688504	Mechanic entered - Wheels and Tyres Other All rear tyres nee	changed all drive tyres with ryan. 3 and 6 (worn); 4 and 5 (rack). all drive wheel nuts tensioned with ryan. replaced both worn wiper refills.	925033
8228	09/23/2017	688504	PLASTIC TRIANGLE HANDSTRAP GREY		925033
8228	09/23/2017	688504	Mechanic entered - Body Other 3 Side Reflector Missing	replaced missing reflectors.	925033
8228	09/23/2017	688504	Mechanic entered - Body Passenger Seat Torn	replaced damaged pax. seat base cushions.	925033
8228	09/23/2017	688504	Mechanic entered - Body Other 1 Hand Rail/Grab Handle Missin	replaced.	925033
8228	09/17/2017	686987	Mechanic entered - Vandalism Vandalism/ Graffiti Interior gr	i cleaned in side and out side this bus	922732
8228	09/08/2017	685321	Drv entered - A/C Heating Not Heating	Repaired the boost pump earth tested ok	920357
8228	08/30/2017	681868	DIRECT PURCHASE - VANDALISM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201034A Receiving #:209157 Date :2017-09-05 COMPLETE GRAFITTI WORK	919807
8228	08/30/2017	681868	DIRECT PURCHASE - VANDALISM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201034R Receiving #:209155 Date :2017-09-05 COMPLETE GRAFITTI WORK	919807
8228	08/30/2017	681868	Complete grafititi work	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201034 Receiving #:208845 Date :2017-09-01	918860
8228	08/30/2017	679185	CCTV CCTV not recording there is no camera in driver area	re plugged drivers camera in the back of the unit. now workijng	913686
8228	08/26/2017	681868	Vandalism Vandalism/ Graffiti Interior Graffiti on floor	Completed EASTCOAST	918196
8228	08/26/2017	681868	Ops Entered - Fault - Vandalism Vandalism/ Graffiti Interio	Completed EASTCOAST	918196
8228	08/23/2017	681867	SINGLE SEAT BASE		918196
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126			918196
8228	08/23/2017	682126	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)	CARRY OUT B SERVICE AS PER CHECK LIST	918196
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126	Consumables		918343
8228	08/23/2017	682126			918196
8228	08/22/2017	681868	Body - Driver door hinge loose & worn	CARRY OUT A SERVICE AS PER CHECK LIST completed	918196
8228	08/22/2017	681867	Body - Various pax seat worn	Checked ok.	918196
8228	08/17/2017	680736	Accident	R/R 2 passenger bottom seat cushion.	918196
8228	08/17/2017	680736	Accident	Completed on W/O 674830	916828
8228	08/17/2017	680736	Accident	Completed on W/O 674830	916828
8228	08/17/2017	680736	Accident	Completed on W/O 674830	916828
8228	08/17/2017	680736	Accident	Completed on W/O 674830	916828
8228	08/14/2017	674347	CLEAN AIR SYSTEM PIPES	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G199845 Receiving #:207231 Date :2017-08-14	915891
8228	08/11/2017	679187	REPAIR DISABLED SEAT	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G200082 Receiving #:207249 Date :2017-08-14	915891
8228	08/11/2017	679714	Body - NS seats at disable spot showing metal	remove and replaced.	913686
8228	08/10/2017	679455		VEHICLE SAFETY INSPECTION completed.	915670
8228	08/10/2017	679455		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed.	915670
8228	08/10/2017	679455		VEHICLE SAFETY INSPECTION completed.	915670
8228	08/10/2017	679187	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		913686
8228	08/10/2017	679187	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		913686
8228	08/10/2017	679187	OVERFLOW VALVE 0500LE		913686
8228	08/10/2017	679187	SEAL RING A/DRYER		913686
8228	08/10/2017	679187	SILENCER AIR DRYER		913686
8228	08/10/2017	679187	AIR DRYER MERCEDES 0500 (49G8505WABCO)		913686
8228	08/10/2017	679187	Mechanic entered - Suspension Other replace over flow valve	replaced.	913686
8228	08/10/2017	679186	Engine replace fuel pipe.	replaced	913686
8228	08/10/2017	679186	CONDENSOR DRAIN VALVE 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G199979 Receiving #:206997 Date :2017-08-10	915670
8228	08/10/2017	674347	Fitted new air dryer & water seperator	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	913686
8228	08/09/2017	679186	Engine replace fuel pipe.	c/o	913686
8228	08/09/2017	674347	WASHER POWER STEER PUMP B10M		913686
8228	08/04/2017	674347	AIR COMPRESSOR COOLANT PIPE 0500		913686
8228	08/03/2017	677910	Please remove old posters and fit new one along with hangers	Done by refuellers	913686
8228	08/03/2017	674347	COMPRESSOR PIPE UNION		913686
8228	08/01/2017	674347	SILENCER 0500	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G199389 Receiving #:206369 Date :2017-08-02	915670
8228	08/01/2017	674347	Service		913686
8228	07/31/2017	674347	AIR LINE 0500 EURO 3		913686
8228	07/31/2017	674347	SEAL O-RING POWER STEERING PUMP MERCEDES 0500LE		913686
8228	07/31/2017	674347	GASKET COMPRESSOR 0500LE (A4571304815)		913686
8228	07/31/2017	674347		fitted air compressor remove all comores air lines. c/o.	913686
8228	07/25/2017	674830	Supply and apply Smartbus deca	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G198415 Receiving #:205759 Date :2017-07-26	915670
8228	07/25/2017	674347		remove air dryer water seperater and air compressor c/o.	915670
8228	07/21/2017	674830	DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL		914195
8228	07/21/2017	674347	AIR COMPRESSOR VOITH 0500LE		915670
8228	07/20/2017	675209	Breakdown#:33577 - Ops Entered - Breakdown - Breakdown Road	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G198520 Receiving #:206169 Date :2017-07-31	914195
8228	07/20/2017	674830	SUPPLIES BODY SHOP SUPPLIES	After hours call out to tow bus from Caulfield to Dandenong	914195
8228	07/20/2017	674830	PAINT SUPPLIES		914195
8228	07/19/2017	674830	Accident damage - N/S/F to R - Acc # DAN 45735. *THIRD PART	Assisting	914195
8228	07/19/2017	674830	Accident damage - N/S/F to R - Acc # DAN 45735. *THIRD PARTY	painted etch primer primer smart silver and clear coats unmasked and realeased the bus for mechanical service c/o	914195
8228	07/19/2017	674830	Accident damage - N/S/F to R - Acc # DAN 45735. *THIRD PART	Assisting	914195
8228	07/19/2017	674830	Accident damage - N/S/F to R - Acc # DAN 45735. *THIRD PART	repaired accident damage ready for painting	914195
8228	07/19/2017	674830	SHEET FLAT ALUMINIUM 2MM x 1200MM x 2400MM		914195
8228	07/17/2017	674479	Body (None) Yellow grip missing on rear step.	Replaced	913686

8228	07/17/2017	674359	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	913686
8228	07/17/2017	674359	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	913686
8228	07/12/2017	675209	DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G198373 Receiving #:205281 Date :2017-07-20 CAULFIELD TO DANDENONG	914196
8228	06/30/2017	671011	Consumables		909495
8228	06/30/2017	671011	LIGHT BRAKE LIGHT LED		909106
8228	06/30/2017	671011	Mechanic entered - Elec and Light Exterior Lights N/S top st	re-wired and fitted new stop/tail light. Tested and working ok.	909106
8228	06/28/2017	670717	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	UPDATED	908329
8228	06/26/2017	669928	Ops Entered - Fault - Brakes Park_Brake Not Releasing - Rou	check and fixed park brake fault road test bus serviceble.	907028
8228	06/24/2017	668074		Tensioned wheel nuts position 345 and 6 with Dulkith	907028
8228	06/22/2017	669220	Remove old Green 2016/17 registration Label and/ or Blue EF	Replaced	907028
8228	06/20/2017	667188		ANNUAL SAFETY INSPECTION - RWC 013141 - PASSED - 20/06/17	907028
8228	06/20/2017	667555	DIRECT PURCHASE - VANDALISM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G195792 Receiving #:203074 Date :2017-06-21 REPLACE L124R124 MODESTY	907146
8228	06/20/2017	667484	Consumables		907146
8228	06/20/2017	667484	Mechanic entered - Elec and Light Other mounting rack for wi	fit new mounting rack and attached wiring. p.t.i'd fuelled and parked bus.	907028
8228	06/19/2017	668075		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	907028
8228	06/19/2017	668075		VEHICLE SAFETY INSPECTION Safety Inspection completed and tensioned all wheel nuts with Alex	907028
8228	06/19/2017	667484	Mechanic entered - Elec and Light Other mounting rack for wi	removed bracing from bus and began to measure new and cut holes for bolts. had to secured wiring temporari;ly for rsi. carry over.	907028
8228	06/19/2017	667828	Air System - Air leak above transmission	Replaced retarder valve air hose o-rings	907028
8228	06/19/2017	667828	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		907028
8228	06/16/2017	667828	REAR BRAKE CALIPER LH 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G195872 Receiving #:202779 Date :2017-06-16	907028
8228	06/16/2017	667828	Brakes - Test rear NS brake low decal failed on balance	Removed and fit rear tyres to change brake pads and N/S/R callipertensioned all wheel nuts with Alex	907028
8228	06/16/2017	667828	SET DISC PAD SET SCANIA / MERCEDES 0500		907028
8228	06/15/2017	667188	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G195678 Receiving #:202946 Date :2017-06-20	907028
8228	06/15/2017	667555	Vandalism - Replace/Fit Anti Graffiti Film - L124 R124	REPLACED	907028
8228	06/15/2017	667484	CABLE TRAY 230MM	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G195763 Receiving #:202826 Date :2017-06-19	907028
8228	06/15/2017	667484	Mechanic entered - Elec and Light Other mounting rack for wi	ordered new mounting rack. awaiting parts.	907028
8228	06/15/2017	667480		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST fire safety complete	907028
8228	06/14/2017	667188		ANNUAL SAFETY INSPECTION - DN 013141 - FAILED - 14/06/17	907028
8228	06/09/2017	666612	Drv entered - Air System Air_Leak Front	Check OK	905981
8228	06/07/2017	666334		Assisting	905680
8228	06/07/2017	666334		Tensioned pos 1 tyre.	905680
8228	06/06/2017	665672	Engine - S/wash engine and under the bus	Steam washed under vehicle and engine	905680
8228	06/06/2017	665672	Mechanic entered - Fluid Leaks Rear of bus Oil leak around o	Removed oil pressure switch and replace o-ringroad test and check for leak	905680
8228	06/06/2017	665672	Consumables		905680
8228	06/06/2017	665672	Mechanic entered - Elec and Light Other	re-connected electrical wires to (nsf) and rear emergency exit hammers. (both not connected).	905680
8228	06/06/2017	665672	CCTV - CCTV/camera n/w	repaired	905680
8228	06/06/2017	665672	REFLECTOR RED 94x44mm (84052)		905680
8228	06/06/2017	665672	PLASTIC TRIANGLE HANDSTRAP GREY		905680
8228	06/06/2017	665672	Mechanic entered - Body Other	replaced frayed pax grab handles (front).	905680
8228	06/06/2017	665672	WHEEL ARCH BRUSH 2.5MTR 12065		905680
8228	06/06/2017	665672	Body - 3 x end caps missing	Replaced 3 end caps	905680
8228	06/06/2017	665672	Body - Both front wheel arch brushes need replacing	Replaced both front wheel arc brushes	905680
8228	06/05/2017	665672	Suspension - Need to check airbags	Check all iar bagsall ok	905680
8228	06/05/2017	665672	A/C Heating - heater hose rubbing on air hose on top of g/bo	Secured heater hose	905680
8228	06/05/2017	665672	Elec and Light - rear emer hammer n/w	Done by Mark	905680
8228	06/05/2017	665672	CAP END CAP CENTRA SEAT END CAP		905680
8228	06/05/2017	665672	Body - Side apnel bolts loose	Secured side panel bolts	905680
8228	06/05/2017	665672	SWITCH LOW AIR 0500LE (A0045455514)		905680
8228	06/05/2017	665672	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		905680
8228	06/05/2017	665672	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		905680
8228	06/05/2017	665672	Air System - Air leaking around water seperator	Replaced air line o-ring kit	905680
8228	06/05/2017	665672	Air System - Air tank drain valve damaged/leaking	Replaced drain valve	905680
8228	06/05/2017	665672	VALVE MANUAL DRAIN VALVE		905680
8228	06/02/2017	665309	FILTER AIR FILTER MERCEDES BENZ 0500LE (E491L)		905680
8228	06/02/2017	665309		PRE ANNUAL SAFETY INSPECTION CHECK Pre Annual Safety inspection Completed	905680
8228	06/02/2017	665378	Mechanic entered - Wipers and Washers Wipers Loose	Adjust Wiper arm	905680
8228	06/02/2017	665376	Consumables		905680
8228	06/02/2017	665376	Mechanic entered - Elec and Light Interior Lights 1 Bus Stop	Replaced 1 Globe	905680
8228	06/02/2017	665374	Mechanic entered - Brakes Other Check N/S/F brake Calliper a	Removed and Fit N/S/F tyre to measure Brake Rotor and check Callipertensioned all wheel nuts with Mark	905680
8228	05/23/2017	662819	Ops Entered - Fault - Wipers and Washers Wipers Not Working	check OK	902774
8228	05/23/2017	663007	Consumables		903412
8228	05/23/2017	663007	Fit A3 Poster/Hangers	Fitted	902774
8228	05/17/2017	661957	Consumables		902272
8228	05/17/2017	661957	Consumables		902272
8228	05/17/2017	661957	Consumables		902272
8228	05/17/2017	661957	Consumables		902272
8228	05/17/2017	661957	AMBER REFLECTOR		901884
8228	05/17/2017	661957		CARRY OUT A SERVICE AS PER CHECK LIST	901884
8228	05/08/2017	659940	CCTV (None) VLOSS red	found that two cameas unplugged from unit. attatched them and working	899515
8228	05/08/2017	659940	Body (None) RHS from the last 7th seat panel missing sc	fitted christmas tree plug to fenders	899515
8228	05/08/2017	659940	Body (None) RHS above the middle CCTV panel missing scr	as above	899515
8228	05/08/2017	659940	FIRTREE CLIP SIDE PILLAR		899515
8228	05/08/2017	659998	BROOM HEAD (07890234)		899515
8228	05/08/2017	659998	BROOM HANDLE (8232715)		899515
8228	05/08/2017	659998	Body (None) - Missing Broom	Supply broom as requested	899515
8228	05/06/2017	659794	FITTING REDUCER ISRI SEAT		899515
8228	05/06/2017	659794	Air leak from driver seat also lagege plate noisy	Repair lagege plate and fixed air leak from driver seat	899515
8228	05/05/2017	659533	Consumables		899950
8228	05/05/2017	659533	Mechanic entered - Elec and Light Exterior Lights N/S/F park	Replaced parklight globe	899515
8228	05/05/2017	659533	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)		899515
8228	04/28/2017	657962	VALVE OVERFLOW VALVE MERCEDES 0500LE		897504
8228	04/28/2017	657962	SEAL RING A/DRYER		897504
8228	04/28/2017	657962	VALVE 4 WAY CIRCUIT PROTECTION VALVE		897504
8228	04/27/2017	658195	CCTV - Drivers camera n/w	reconnected camera connections at rear of cctv unit. working ok.	897504
8228	04/27/2017	657962	VALVE SAFETY BLOW OFF 1.3MP 30G0308		897504
8228	04/27/2017	657962	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		897504
8228	04/27/2017	657962	Air System - Air compressor blowing up oil	Overhaul the air dryerR/R 6 way and overflow valve.Steam clean engine road test - ok.	897504
8228	04/27/2017	657962	HOSE COMPRESSOR TO UNLOADER MERCEDES (A0014292135)		897504
8228	04/27/2017	657962	COUPLING AIR HOSE COMPRESSOR MERCEDES 0500 (50G4501)		897504
8228	04/26/2017	657962	Air System - Air compressor blowing up oil	Drained coolant. R/R air compressor. Removed air pipe line and checked for blocking ok. R/R 1 flexible hose. Filled coolant and check found air leaking @ air dryer. Removed air dyer. C/F	897504
8228	04/26/2017	657962	AIR COMPRESSOR 0500 EURO 3	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G192282 Receiving #:199035 Date :2017-04-26	897504
8228	04/26/2017	657962	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		897504
8228	04/26/2017	657962	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		897504

8228	04/26/2017	657962 SEAL O-RING POWER STEERING PUMP MERCEDES 0500LE			897504
8228	04/26/2017	657962 GASKET COMPRESSOR 0500LE (A4571304815)			897504
8228	04/21/2017	657444	Complete with Nick		896851
8228	04/21/2017	657444	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		896851
8228	04/21/2017	657444	VEHICLE SAFETY INSPECTION		896851
8228	04/20/2017	657043 Body - DRIVER DOOR NOT LOCKING	check ok.		896177
8228	04/17/2017	656468 Consumables			895830
8228	04/17/2017	656468 GLOBE 24V 70W H1			895033
8228	04/17/2017	656468 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	changed blown globe (os) low beam headlight.		895033
8228	04/12/2017	656061 Consumables			895033
8228	04/12/2017	656061 LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			894713
8228	04/12/2017	656061 Mechanic entered - Elec and Light Exterior Lights	replaced smashed (nsr) clearance light.		894713
8228	04/05/2017	654877 Body - Refit door leak rubbers	refitted door seals job completed		892953
8228	03/22/2017	652212	completed		889261
8228	03/22/2017	652212	completed		889261
8228	03/22/2017	652355 Vandalism Vandalism/ Graffiti Interior Graffiti at Rear	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Carried out tune up and road test bus to check for leaks. no leaks.		886514
8228	03/22/2017	650487 CCTV CCTV not recording Driver view camera not recording	REF TO DEFECT # 629372		886514
8228	03/22/2017	652211	drivers camera was disconnected. plugged it in and it started working		886514
8228	03/22/2017	652211 Consumables	completed		889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables			889302
8228	03/22/2017	652211 Consumables	completed		886514
8228	03/22/2017	652211	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A-service with sisil and zubair.		886514
8228	03/14/2017	650518 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)			886514
8228	03/14/2017	650487 ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)			886514
8228	03/14/2017	650487 Drv entered - Wipers and Washers Wipers Not_Clearing Screen	changed os wipper blade assy		886514
8228	03/11/2017	650518			886514
8228	03/11/2017	650518	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		886514
8228	03/11/2017	650518	VEHICLE SAFETY INSPECTION		886514
8228	03/11/2017	650518 Consumables			886723
8228	03/11/2017	650518 Consumables			886723
8228	03/11/2017	650518 Elec and Light - Front park light out	Replaced N/S/F park light globe Vehicle Safety Inspection Completed and tensioned all wheel nuts with Kumar		886514
8228	03/10/2017	650487 TEMPERATURE SENDER- MERC 0500			886514
8228	03/10/2017	650487 THERMOSTAT 83 DEGREE (A004203837501) (51.06402.0063)			886514
8228	03/10/2017	650487 Engine - Rectify engine overheating.	Steam cleaned intercooler/radiator. Drive tested engine still overheating. Rectify fault check engine block 110 degrees and radiator 95 degrees. Drained coolant and replaced engine temp sender key. Drive tested engine overheated at full throttle. Drained coolant and removed and checked thermostet found faulty therm		885144
8228	03/06/2017	649349 KIT DRAIN VALVE KIT BOTTOM			885144
8228	03/06/2017	649349 FILTER AIR FILTER CHECK VALVE 22mm CYCLONE			885144
8228	03/06/2017	649349 KIT HALDEX CONDENSER KIT TOP (CYCLONE)			885144
8228	03/06/2017	649349 KIT CYCLONE CONDENSER VALVE KIT			885144
8228	03/06/2017	649349 KIT HALDEX COIL KIT MERCEDES 0500LE (49G0027)			885144
8228	03/06/2017	649349 HALDEX COIL BASE OIL SEPERATOR (49G0031)			885144
8228	03/06/2017	649349 SEAL 4 WAY PROTECTION VALVE BARREL SEAL MERCEDES 0500LE			885144
8228	03/06/2017	647943 SEAL 4 WAY PROTECTION VALVE BARREL SEAL MERCEDES 0500LE			885144
8228	03/06/2017	649349 Air System 6way valve leaking and noair coming in dors syste	Assisted Alan to fit new seals		885144
8228	03/06/2017	649349 Air System 6way valve leaking and noair coming in dors syste	fit new valve seals to 6way valveoverhaul water seperator.		885144
8228	03/06/2017	649306 LABEL DURESS BUTTON 8x25mm RED/BLACK			885144
8228	03/06/2017	649306 LABEL RADIO 8x25mm WHITE/BLACK			885144
8228	03/06/2017	649306 LABEL KNEEL 8x25mm WHITE/BLACK			885144
8228	03/06/2017	649306 LABEL LOWER/RAISE 8x25mm WHITE/BLACK			885144
8228	03/06/2017	649306 LABEL PARK BRAKE 8x25mm WHITE/BLACK			885144
8228	03/06/2017	649306 LABEL HAZARDS 8x25mm WHITE/BLACK			8851

8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072		CARRY OUT B SERVICE AS PER CHECK LIST		872974
8228	01/06/2017	637072		CARRY OUT B SERVICE AS PER CHECK LIST		872974
8228	01/06/2017	637072		CARRY OUT B SERVICE AS PER CHECK LIST		872974
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072		CARRY OUT A SERVICE AS PER CHECK LIST		872974
8228	01/06/2017	637072		CARRY OUT A SERVICE AS PER CHECK LIST		872974
8228	01/06/2017	637072	Consumables			873323
8228	01/06/2017	637072	Consumables			873323
8228	01/05/2017	637189	Fit New 2107 Large and Small Fares Small Concessionand AO	Replaced		873323
8228	01/01/2017	607062	Consumables			872242
8228	01/01/2017	607062	CARRY OUT ROLLAWAY SYSTEM	Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G178986 Receiving #:192126 Date :2017-01-23		877610
8228	12/31/2016	636075	Body (None):drivers sun visor is loose needs to be tighten	re-secured front sun blind.		870232
8228	12/31/2016	636075	Consumables			872023
8228	12/29/2016	635996	PULLEY ADJUSTER IDLER PULLEY MERCEDES 0500 (A0005501833)			870232
8228	12/29/2016	635996	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG			870232
8228	12/29/2016	635996	Mechanic entered - A/C Heating Other	removed broken bolt in idler changed idler with belt and adjusted a/c compresure.road test bus okl		870232
8228	12/28/2016	635399	SINGLE SEAT BASE			870232
8228	12/28/2016	635399	Mechanic entered - Body Passenger Seat Torn	replaced damaged / worn pax. seat base cushions.		870232
8228	12/28/2016	635399	Consumables			871700
8228	12/26/2016	635324	Warning Lights (None) / Warning 'INS 1125' is showing on d	check and and clear fault codes bus serviceble.		870232
8228	12/26/2016	635324	Consumables			870666
8228	12/14/2016	633285	LIGHT BRAKE LIGHT LED			867810
8228	12/14/2016	633285	Mechanic entered - Elec and Light Exterior Lights O/S/R/B br	replaced		867810
8228	12/14/2016	633285	Consumables			868523
8228	12/08/2016	632247		VEHICLE SAFETY INSPECTION completed		865878
8228	12/08/2016	632247		VEHICLE SAFETY INSPECTION completed		865878
8228	12/08/2016	632247		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Ryan		865878
8228	12/08/2016	632329	FIRTREE CLIP SIDE PILLAR			865878
8228	12/08/2016	632329	LED FRONT POSITION MARKER LIGHT			865878
8228	12/08/2016	632329	Elec and Light - Exit light NSF n/w	Fitted new Exit light		865878
8228	12/08/2016	632329	Elec and Light (None): hammer was removed by passenger l	fitted emergency hammer holder		865878
8228	12/08/2016	632329	Elec and Light - Saloon light fluro n/w	fitted new saloon fluro		865878
8228	12/08/2016	632329	EMERGENCY HAMMER HOLDER WITH SENSOR			865878
8228	12/08/2016	632329	Consumables			866758
8228	12/08/2016	632329	CCTV - Driver CCTV camera u/s	found cctv not secured proply.Removed and made a plate then fitted cctv to it and secures driver camera lead		865878
8228	12/08/2016	632329	PLASTIC TRIANGLE HANDSTRAP GREY			865878
8228	12/08/2016	632329	Body - Overhead grab handle x 4 missing	fitted 4 new hand grabs		865878
8228	12/08/2016	632329	Body - Wheel chair ramp brake u/s	checked wheel chair ramp break and ok.		865878
8228	12/08/2016	632329	Consumables			866758
8228	12/08/2016	632248		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed		865878
8228	12/08/2016	632248	SILENCER AIR DRYER			865878
8228	12/08/2016	632248	KIT DRAIN VALVE KIT BOTTOM			865878
8228	12/08/2016	632248	KIT CYCLONE CONDENSER VALVE KIT			865878
8228	12/08/2016	632248	KIT HALDEX CONDENSER KIT TOP (CYCLONE)			865878
8228	12/08/2016	632248	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)			865878
8228	12/08/2016	632248	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER			865878
8228	12/08/2016	632248	HALDEX COIL BASE OIL SEPERATOR (49G0031)			865878
8228	12/08/2016	632248		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed		865878
8228	12/01/2016	623581	AIR CONDITIONING REPAIR	Creditor #:GB-SOU015 SOUTHERN STATES GROUP P/O #:G180538 Receiving #:189518 Date :2016-12-09 X430 Conversion by Southern States Thermo King		866758
8228	11/30/2016	630662	Body Rear_Door Operation Faulty: clip on rear door is loos	check and fixed sensetive edge clip		864061
8228	11/22/2016	629055	Mechanic entered - Suspension Other levaling control valve l	replaced the valve		862740
8228	11/22/2016	629055	ECAS LEVELLING VALVE CONTROL S	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G181936 Receiving #:188114 Date :2016-11-22		862740
8228	11/22/2016	629055	Body - Heater hose worn near turbo	replaced the hose and steam cleaned		862740
8228	11/22/2016	629055	AIR COMPRESSOR HOSE	Creditor #:GB-HEM001 HEMA'S HOSE SERVICES P/O #:G181991 Receiving #:188129 Date :2016-11-22		862760
8228	11/22/2016	629055	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			862740
8228	11/22/2016	629055	Air System - Replace 6 way valve air line fitting	replaced 3 line fitting and road tested ok		862740
8228	11/21/2016	627014	Vandalism - Replace O/S/R x 3	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G181083 Receiving #:187978 Date :2016-11-21		862740
8228	11/21/2016	629055	Air System - Air hose worn at engine bay	secured it's ok		862740
8228	11/18/2016	629016	Body FRONT WINDSCREEN FROSTING LOWER BOTTOM/ REAR TINT NEED	Completed refer W/O 627014		862740
8228	11/17/2016	626260	MOTOR EVAPORATOR FAN MOTOR			862410
8228	11/15/2016	627839	Mechanic entered - Body Other	replaced expired fire extinguisher.		861664
8228	11/11/2016	627141	A/C Heating - evap fan motors left bank down	Remove and replaced all evap fan motor assemblies tested ok		860389
8228	11/10/2016	627014	Vandalism - Replace O/S/R x 3 N/S/R x 3 windows including f			860389
8228	11/09/2016	626743	Check and readjust camaras angle	checked all angles. fitted a rear door camera so now well be able to see the rear door. all good to go.		860389
8228	11/07/2016	626260		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		860148
8228	11/07/2016	626260		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		860148
8228	11/03/2016	623581	A/C Heating - Compressor has failed unit needs a upgrade	A/C modification completed by Thermo king		859378
8228	11/03/2016	625532	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced by Fleet Support		859378
8228	10/17/2016	621680	Accident	painted a/c cover		858024
8228	10/17/2016	621680	UNREPORTED damage - Air con pod.	Decals		858024
8228	10/17/2016	621680	UNREPORTED damage - Air con pod.	Repairs and assembly		858024
8228	10/17/2016	621680	BODY SHOP SUPPLIES			858024
8228	10/17/2016	621680	PAINT SUPPLIES			858024
8228	10/14/2016	622026	Drv entered - A/C Heating Not Heating	Tested found that the compressor has failed unit needs a upgrade		858024
8228	10/14/2016	621680	UNREPORTED damage - Air con pod.	Painted repair		858024
8228	10/14/2016	621680	UNREPORTED damage - Air con pod.	Repairs		858024
8228	10/14/2016	622084	Consumables			858024
8228	10/14/2016	622084	Consumables			858024
8228	10/14/2016	622084	Consumables			858024
8228	10/14/2016	622084	Consumables			858024
8228	10/14/2016	622084	Consumables			858024
8228	10/13/2016	621680	UNREPORTED damage - Air con pod.	CARRY OUT A SERVICE AS PER CHECK LIST		858024
8228	10/04/2016	619925		Started repairs to air con pod		858024
8228	10/04/2016	619925		VEHICLE SAFETY INSPECTION		855844
8228	10/04/2016	619925				855844
8228	10/04/2016	619908	Consumables	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		856043

8228	10/04/2016	619908	GLOBE 24V 70W H1 HIGH BEAM			855844
8228	10/04/2016	619908	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	fitted HL globe. now working.		855844
8228	10/04/2016	619873	Air System - Air leaking	check and fixed air leak.		855844
8228	10/01/2016	606644	Consumables			855295
8228	10/01/2016	606644	CARRY OUT CCTV UPGRADE			859378
8228	09/27/2016	618630	Consumables			855002
8228	09/27/2016	618630	DECAL CUSTOMER ENQUIRY			855002
8228	09/26/2016	618630	Body - Replace 1300 decal			855002
8228	09/06/2016	614255				848909
8228	09/03/2016	613941	Service	re-tensioned nuts on wheels 5 and 6 with dulkith.		848909
8228	09/03/2016	613941	Service	Assit with Sisil		848909
8228	09/02/2016	613746	Consumables	Retentioned pos 1 and 2		849213
8228	09/02/2016	613746	Wheels and Tyres - Tyre pos 2 worn & tyre 5 low pressure	removed wheels 5 and 6. tightened loose valve stem - leaking. inflated both to specs. refitted wheels. nuts tensioned with ranjith. changed tyres 1 (rack) and 2 (worn). all steer nuts tensioned with sisil.		848909
8228	09/02/2016	613746	TYRE 11R22.5N NEW			848909
8228	09/01/2016	607971	Supply and apply Smartbus decal			848909
8228	08/31/2016	613243	Accident - Decal application from Accident W/O 607971			848868
8228	08/30/2016	612899		Safety Inspection Completed		845481
8228	08/30/2016	612899	TRIANGLE SAFETY DOUBLE SIDED 3 BOX			845481
8228	08/30/2016	612899		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		845481
8228	08/30/2016	612899		VEHICLE SAFETY INSPECTION		845481
8228	08/29/2016	609856	Consumables			848436
8228	08/29/2016	609856	Elec and Light Rectify Park brake light n/w.	found broken wires supervised Pascal fixing the wires		845481
8228	08/29/2016	609856	Elec and Light Rectify Park brake light n/w.	Repaired broken wires		845481
8228	08/23/2016	607971	PAINT SUPPLIES			847514
8228	08/23/2016	607971	BODY SHOP SUPPLIES			847514
8228	08/19/2016	610775		re-tensioned all drive wheel nuts.		845481
8228	08/18/2016	610450	Consumables			846745
8228	08/18/2016	610450	TYRE 11R22.5N NEW			845481
8228	08/17/2016	610450	Wheels and Tyres - Tyre 6 needs replacing	replaced tyres position 5 and 6 tensioned.		845481
8228	08/17/2016	610450	Ops Entered - Fault - Passenger Doors - Route: 900 - Wellin	checked the relay and ok found connection for door brake request not goodso fitted new terminal.Checked and ok		845481
8228	08/17/2016	610450	Read door brake Not Holding	checked the relay and ok found connection for door brake request not goodso fitted new terminal.Checked and ok		845481
8228	08/15/2016	609876	Consumables			846185
8228	08/15/2016	609856	Drv entered - Elec and Light AM-FM Radio	Fitted new antenna		845481
8228	08/15/2016	609856	Drv entered - Elec and Light AM-FM Radio	fitted new antena		845481
8228	08/15/2016	609856	AM/FM ANTENNA			845481
8228	08/15/2016	609876	fit diode to rollaway system	fitted diode to roll away system		845481
8228	08/12/2016	607971	DECAL EMERGENCY EXIT PRESS BUTTON UNDER BUMPER			845481
8228	08/12/2016	607971	RED REFLECTOR 94X44MM 84052			845481
8228	08/12/2016	607971	Accident - Minor damage on RH corner	Unmasked and reassembled		845481
8228	08/12/2016	607971	Accident - Minor damage on RH corner	Secured front bar rear rego plate & washed bus		845481
8228	08/11/2016	607971	Accident - Minor damage on RH corner	painted etch primer primer 2pac silver and 2pac clear coates on ns os lower panels (x 1 each side) and rear bumper bar painted primer and 2pac bumper orange on front bumper bar c/o		845481
8228	08/11/2016	607971	UNREPORTED - Repair acc damage	Cont prep work to rear bar remove n/s panel repair refit prep work front bar mask up bus ready for paint work		845481
8228	08/10/2016	607971	Accident - Minor damage on RH corner	Repaired acc dam c/o		845481
8228	08/10/2016	607971	Accident - Minor damage on RH corner	Secure rear bar & prep work		845481
8228	08/10/2016	607971	Accident - Minor damage on RH corner	General repairs c/o		845481
8228	08/10/2016	607971	2MM X 1200MM X 2400MM FLAT ALUMINIUM			845481
8228	08/04/2016	607971	ROOF INTAKE POD VENT			843617
8228	08/03/2016	607971	ROOF INTAKE POD VENT			843400
8228	08/03/2016	607971	Accident - Minor damage on RH corner			843400
8228	07/29/2016	607062	Consumables			842513
8228	07/29/2016	607062	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	fitted rollaway prevention device		842433
8228	07/28/2016	606644	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	as above		842433
8228	07/28/2016	606664	Consumables			842433
8228	07/28/2016	606664	Consumables			842433
8228	07/28/2016	606664	Consumables			842433
8228	07/28/2016	606664	Consumables			842433
8228	07/28/2016	606664				842433
8228	07/25/2016	606010	Ops Entered - Fault - Comm Equip - Route: 900 - Stud Park	CARRY OUT A SERVICE AS PER CHECK LIST		841465
8228	07/22/2016	605378	Drv entered - Passenger Doors	Repaired by AA radio		840236
8228	07/19/2016	604566	Drv entered - Wipers and Washers Wipers Loose	adjusted passanger doors bus ok.		840005
8228	07/15/2016	604145	Consumables	adjusted wipper link bus ok.		840005
8228	07/15/2016	604144	Consumables			840005
8228	07/15/2016	604145	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	already been fixed.		839438
8228	07/15/2016	604144	GLOBE 24V 70W H1			839438
8228	07/15/2016	604144	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)			839438
8228	07/15/2016	604144	Drv entered - Elec and Light Exterior Lights	changed blown globes (os) low beam headlight and (osf) bottom park light.		839438
8228	07/13/2016	603691	RUBBER CLUTCH PEDAL RUBBER 16-240			838746
8228	07/13/2016	603691	Mechanic entered - Brakes Other			838746
8228	07/11/2016	602956	HARDENER DELFLEET GRAFFITI RESISTANT PER LITRE	replaced worn brake pedal rubber.		838018
8228	07/11/2016	602956	CLEANER GRAFFITI REMOVER AMERASE PER LITRE			838018
8228	07/11/2016	602956	ANTI GRAFFITI PAINT DARK GREY			838018
8228	07/11/2016	602956	ANTI GRAFFITI PAINT LIGHT GREY			838018
8228	07/11/2016	602891	EMERGENCY EXIT BUTTON PULL COVER			838018
8228	07/09/2016	604761	Vandalism Vandalism/ Graffiti Interior	ref to w/o 602956		840005
8228	07/09/2016	602956	Vandalism Vandalism/ Graffiti Exterior: back of bus...also			838018
8228	07/09/2016	602956	Vandalism Vandalism/ Graffiti Exterior: back of bus...also	Grafftit cleaned whole bus		838018
8228	07/08/2016	602879				838018
8228	07/08/2016	602879		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		838018
8228	07/08/2016	602879		VEHICLE SAFETY INSPECTION		838018
8228	07/08/2016	602891	Consumables			838431
8228	07/08/2016	602891	Elec and Light - NSF exit light n/w	checked ok		838018
8228	07/08/2016	602891	Body - Emer exit flap at front door broken	replaced flap		838018
8228	07/08/2016	602891	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			838018
8228	07/08/2016	602891	Mechanic entered - Air System Other Air line for check valve	Remove and replace air line o-ring kit. check ok.		838018
8228	07/05/2016	602225	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	fleet support		837329
8228	06/21/2016	599113	Mechanic entered - Fluid Leaks Other	added coolant - low.		833783
8228	06/17/2016	597704	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G170226 Receiving #:176334 Date :2016-06-21		833783
8228	06/17/2016	598590	Consumables			833174
8228	06/17/2016	598590	Elec and Light Flat Batteries: ELECTRICAL FAULT	removed alternator and replaced with spare alt. had to re solder connection at slip ring. working ok.		833026
8228	06/17/2016	598590	Body Passenger Seat REAR YELLOW STRIP MISSING	Completed		833026
8228	06/16/2016	598280	Breakdown#:32628 - Ops Entered - Breakdown - Breakdown Road			833026
8228	06/16/2016	598280	Breakdown#:32628 - Ops Entered - Breakdown - Breakdown Road	Take van jump start bus 8228 and return to depot 10.00 pm.Stud rd rowville Alt fault with bus.Bus u/s with Rene.		833026

8228	06/16/2016	598057	Air System	Air_Leak	Rear Air dryer leaking air.	Repaired air leak	833026
8228	06/16/2016	598057	FITTING JOINER	12MM			833026
8228	06/16/2016	598057	KIT AIR LINE FITTING	VOSS 22MM (50Z0114)			833026
8228	06/15/2016	597704			ANNUAL SAFETY INSPECTION - RWC 006950 - PASSED - 15/06/16		832593
8228	06/14/2016	597423	Please remove any old poster and fit new A3 poster and add		done by fleet support		832593
8228	06/09/2016	592941	Body	Rear_Door	Operation Faulty: DRIVER STATES THE DOOR IS	checked rear door making slight noise but not obstructing or petruding.	828554
8228	06/02/2016	595222	Gearbox Driveline	REQUIRES	STEAM CLEAN.		830115
8228	06/02/2016	595222	Gearbox Driveline	REQUIRES	STEAM CLEAN.	ASSITED SISIL	830115
8228	06/02/2016	595223	DECAL EMERGENCY EXIT	600MMx80MM			830115
8228	06/02/2016	595223	DECAL WHEELCHAIR ACCESS RAMP	LOAD RATED 300 KG			830115
8228	06/02/2016	595223	Mechanic entered - Body	Other	giveway decal wheelchair ramp	replaced decals as mentioned	830115
8228	06/02/2016	595223	Body	Rear seat	yellow strip missing.	put new yellow strip	830115
8228	06/02/2016	595223	Body	Rear seat	yellow strip missing.		830115
8228	06/02/2016	595223	DECAL GIVE WAY	240MM X 225MM			830115
8228	06/02/2016	595223	Air System	Air leak around air dryer	(SHOULD BE BUS 8228)	ALEX replaced 4 oring kit	830115
8228	06/02/2016	595223	Air System	Air leak around air dryer	(SHOULD BE BUS 8228)	replaced 5 o ring kits for circuit protection valve	830115
8228	06/01/2016	595188			PRE ANNUAL SAFETY INSPECTION CHECK completed		830115
8228	06/01/2016	595222	Gearbox Driveline	REQUIRES	STEAM CLEAN.	STEAM CLEANED THE BUS	830115
8228	06/01/2016	595223	Body	Rear seat	yellow strip missing.		830115
8228	06/01/2016	595223	KIT AIR LINE FITTING	VOSS 22MM	50Z0114		830115
8228	06/01/2016	595223	Air System	Air leak around air dryer	(SHOULD BE BUS 8228)		830115
8228	05/28/2016	592941	Consumables				829392
8228	05/28/2016	592941	Elec and Light - NSF	exit light	flickering	Check found connection loose secured test works ok.	829266
8228	05/28/2016	592941	Elec and Light - Interior	fluro light	n/w	Check for fault check power for inverter found inverter faulty. remove and replace inverter and flouro tube test operation works ok.	829266
8228	05/27/2016	594294	PERFORM CAMPAIGN	04/16	DRIVERS WALLETS AND MAP POCKET INSTA	Originally fitted	829266
8228	05/23/2016	592941	CONTACT BLOCK	DOOR PUSH SWITCH (M22-K10)			828742
8228	05/21/2016	592970	Mechanic entered - Body	Front_Door	Operation Faulty front d	Rectified and replaced front door switch - ok	828554
8228	05/20/2016	592941	DOOR VALVE	SILENCER			828554
8228	05/20/2016	592941	VALVE CLIPPARD	DOOR OPEN/CLOSE (11916-2)	BUTTON		828554
8228	05/19/2016	592701	Ops Entered - Fault - Passenger	Doors - Route: 900 - Stud P		job completed	828389
8228	05/19/2016	592701	Ops Entered - Fault - Passenger	Doors - Route: 900 - Stud P		job completed	828389
8228	05/19/2016	592701	Ops Entered - Fault - Body	Drivers Seat Controls - Route: 9		removed old seat and replaced with new job completed	828389
8228	05/18/2016	592701	SEAT ASSY	ISRI A6008	AIR LUMB	Creditor #-:GB-RP RP AUTO UPHOLSTERY PTY LTD P/O #-:G167821 Receiving #-:174337 Date :2016-05-20	828554
8228	05/17/2016	592200	Ops Entered - Breakdown - Breakdown	Road Defect	Affects Ser	out 400pm in 600pm chadston s/center. fault bbrke holding. when i go half way the driver manage to bus move.	828202
8228	05/17/2016	592198	Air System	Air Not	Building_Up	Checked wheel chair ramp operation as per Tims description - ok.	828202
8228	05/16/2016	591854	AIRBAG	FRONT AND REAR 0405/0500	REAR/ B10M/B7R REAR		828131
8228	05/13/2016	591650					827825
8228	05/13/2016	591650			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		827825
8228	05/13/2016	591650			VEHICLE SAFETY INSPECTION		827825
8228	05/13/2016	591854	Suspension - replace	front OS	airbag	Replaced	827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827825
8228	05/13/2016	591649	ENGINE OIL	BREATHER KIT 0500LE (EAS500M05)			827825
8228	05/13/2016	591649	OIL FILTER	1725+0500LE E161H01D28			827825
8228	05/13/2016	591649			CARRY OUT B SERVICE AS PER CHECK LIST		827825
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827908
8228	05/13/2016	591649	Consumables				827825
8228	05/11/2016	590989	Body	Front_Door	Operation FaultyDRIVERS CABIN DOOR NOT O	CARRY OUT A SERVICE AS PER CHECK LIST	827567
8228	04/15/2016	586529	AIR DRYER	MERCEDES 0500 (49G8505W)		fixed driver cabin door lock bus ok.	821063
8228	04/15/2016	586529	AIR LINE FITTING	KIT VOSS 0500LE	AIR DRYER SMALL 50Z0115		821063
8228	04/14/2016	586529	HALDEX CONDENSER	KIT TOP(CYCLONE)			820558
8228	04/14/2016	586529	CYCLONE CONDENSER	VALVE KIT			820558
8228	04/14/2016	586529	DRAIN VALVE	KIT BOTTOM			820558
8228	04/14/2016	586529	HALDEX COIL	KIT 0500LE 49G0027	HALDEX		820558
8228	04/14/2016	586529	PURGE VALVE	KIT FOR WABCO 49G712W	AIR DRYER		820558
8228	04/14/2016	586529	KIT AIR LINE FITTING	VOSS 22MM	50Z0114		820558
8228	04/14/2016	586529	CHECK VALVE	22MM CYCLONE	AIR FILTER		820558
8228	04/14/2016	586529	FILTER DRYER	SCANIA/VOLVO (1375997)(49G8704W)			820558
8228	04/14/2016	586529			rebuilt cyclone seperator		820558
8228	04/14/2016	586529			CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST		820558
8228	04/04/2016	584203	SEAT BELT	LEFT HAND (A60LH)			818934
8228	04/02/2016	584203	Drv entered - Comm	Equip		Checked two way radio OK	818934
8228	04/02/2016	584203	Drv entered - Body	Windows	Front	Checked windows no fault found	818934
8228	04/02/2016	584203	Body (None)	driver	vseat cushion worn.	Checked cushin has been replaced	818934
8228	04/02/2016	584203	Drv entered - Body	Drivers	Seat Belt	Replaced	818934
8228	03/29/2016	583107	MOUNT RUBBER	EXHAUST VOLVO (6850149-3)(30T0001)			817283
8228	03/26/2016	583148				re-tensioned nuts on wheels 3; 4; 5 and 6.	817283
8228	03/24/2016	583037					817283
8228	03/24/2016	583037				TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	817283
8228	03/24/2016	583037				VEHICLE SAFETY INSPECTION	817283
8228	03/24/2016	583106	Consumables				817605
8228	03/24/2016	583106	Wheels and Tyres	Worn	replace pos 5 Tyre.	R&R pos. 5 tyre fitted r/o tyre and retensioned wheel nuts with nick.	817283
8228	03/24/2016	583106	Wheels and Tyres	Worn	replace pos 5 Tyre.	replaced.	817283
8228	03/24/2016	583107	Engine	replace	muffler cushion.	replaced.	817283
8228	03/16/2016	581420	Consumables				815450
8228	03/16/2016	581420	GLOBE	H1 24V 70W	HLC2470		815072
8228	03/16/2016	581420	Elec and Light	head light	l/h out	changed blown globe (ns) low beam headlight.	815072
8228	03/08/2016	580196	Body - Faulty	drivers	seat & unable to adjust	check driver seat adjuster it's ok bus serviceble.	813562
8228	02/26/2016	578479	Consumables				811369
8228	02/26/2016	578479	Consumables				811369
8228	02/26/2016	578479	Consumables				811369
8228	02/26/2016	578479	Consumables				811369
8228	02/26/2016	578479					811369
8228	02/26/2016	578479				CARRY OUT A SERVICE AS PER CHECK LIST	811369
8228	02/17/2016	576454	Consumables				808845
8228	02/17/2016	576454	Drv entered - Elec and Light	AM-FM	Radio	removed old broken raido and wired in new one.Secured radio.	808821
8228	02/17/2016	576454	RADIO	AM/FM 12-24VOLT (AV8141)			808821

8228	02/12/2016	575763	Consumables			807684
8228	02/12/2016	575763	Elec and Light - Ins fault 1125 orange symbol	check fault codes fault check switch n/w bus serviceble.		807522
8228	02/09/2016	574811		re-tensioned nuts on wheels 3 and 4.		807093
8228	02/08/2016	574722		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		807093
8228	02/08/2016	574722		VEHICLE SAFETY INSPECTION		807093
8228	02/08/2016	574722		VEHICLE SAFETY INSPECTION		807093
8228	02/08/2016	574655	Consumables			807093
8228	02/08/2016	574655	TYRE NEW 11R22.5N			807093
8228	02/08/2016	574655	Wheels and Tyres - Tyre 3 worn	changed tyres 3 (worn) and 4 (rack). nuts tensioned with pascal.		807093
8228	02/05/2016	574360	CCTV (None) Audio Recordings Not Working.	Assisted Elias		806719
8228	02/05/2016	574360	CCTV (None) Audio Recordings Not Working.	found audio plug from drivers camera not connected.Connected waited for control to check footage audio working now but no to good so replaced old camera with spare(still new) from machine shop.put all back together and all ok.		806719
8228	02/05/2016	574366	25mm BLACK NO 7			806719
8228	02/05/2016	574366	25mm BLACK NO 8			806719
8228	02/05/2016	574366	Body decal			806719
8228	02/04/2016	573989	SEAT BELT BUCKLE TWIN WIRE GREY			806071
8228	02/04/2016	573989	Mechanic entered - Body Drivers Seat Belt			806071
8228	02/04/2016	573988	CLUTCH PEDAL RUBBER 16-240			806071
8228	02/04/2016	573988	Mechanic entered - Body Other	replaced worn brake pedal rubber.		806071
8228	02/03/2016	573896	Mechanic entered - Steering Other	added power steering fluid - low.		806071
8228	02/03/2016	573895	Mechanic entered - Fluid Leaks Other	added coolant - low.		806071
8228	02/03/2016	573892	Consumables			806071
8228	02/03/2016	573892	GLOBE WEDGE INSTRUMENT 24V 5W 17197			806071
8228	02/03/2016	573892	GLOBE H1 24V 70W HLC2470			806071
8228	02/03/2016	573892	Mechanic entered - Elec and Light Exterior Lights	changed blown globes (os) low beam headlight and both front bottom park lights.		806071
8228	01/21/2016	571438	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01			802421
8228	01/21/2016	571438		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed and road tested		802421
8228	01/21/2016	571439	Mechanic entered - Engine Other oil leak tapet cover	replaced crack cover and steam cleaned		802421
8228	01/21/2016	571439	MERC RADIATOR MOUNT BUSHING			802421
8228	01/21/2016	571439	Engine Radiator mount cracked	replaced		802421
8228	01/21/2016	571439	ROCKER COVER	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G160932 Receiving #:166601 Date :2016-01-21		802790
8228	01/21/2016	571792	The Campaign requires all Bus destinations systems to be in	16 X 140 N/A N/A		802790
8228	01/19/2016	570958	DECAL PTV METRO MYKI DECAL LARGE 450x330mm			802421
8228	01/19/2016	570958	Campaign 23_15 A3 Poster Change			802421
8228	01/15/2016	570314	Engine Cracked # 5 rocker cover leaking oil.	Checked has been replaced		801768
8228	12/31/2015	567717	Consumables			798890
8228	12/31/2015	567717	Elec and LightExit door U/S	adjust rear passanger door.		797933
8228	12/31/2015	567717	Ops Entered - Fault - Comm Equip - Route: 900 - Caulfield S	check ok.		797933
8228	12/23/2015	566832				796946
8228	12/23/2015	566832		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		796946
8228	12/23/2015	566832		VEHICLE SAFETY INSPECTION		796946
8228	12/23/2015	566779		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		796946
8228	12/23/2015	566779	DOUBLED UP	VEHICLE SAFETY INSPECTION		796946
8228	12/21/2015	566038	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	Applied supplied decal		796252
8228	12/18/2015	565770	Consumables			796252
8228	12/18/2015	565770	Consumables			796252
8228	12/18/2015	565770	Consumables			796252
8228	12/18/2015	565770	Consumables			796252
8228	12/18/2015	565770	Consumables	completed with phil		796252
8228	12/18/2015	565770	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		796252
8228	12/10/2015	564114	Air System leaks	fixed air leak from driver seat and near air drayer.		794184
8228	12/09/2015	563934	Air System Air losing from driver seat	fixed air leak from driver seat.		794184
8228	12/08/2015	563743	Body / R/H SIDE FRONT DAMAGED PANEL	No report		794184
8228	12/01/2015	562289	DECAL MAKE YOUR MARK			793079
8228	12/01/2015	562289	Camapign 20/15 Audit & Update of Safety Decals.Requires a			793079
8228	11/20/2015	559986	Remove Old Poster and Fit new All Night Public Transport Po			791682
8228	11/17/2015	559331		completed		791317
8228	11/16/2015	559070	Engine Replace rocker cover gasket	CARRY OUT A/C - A SERVICE AS PER CHECK LIST		791317
8228	11/09/2015	557716	Service	Replaced		789874
8228	11/09/2015	557716	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST		789874
8228	11/06/2015	557302	Body (None) / Windscreen washer needs to be fill with wa	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST		788819
8228	11/01/2015	559070	ROCKER COVER	checked. already been done.		791317
8228	10/27/2015	555589		Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G157431 Receiving #:163780 Date :2015-11-16		787360
8228	10/27/2015	555589		Safety Inspection Completed		787360
8228	10/27/2015	555589		CLEAN A/C FILTERS		787360
8228	10/27/2015	555589		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		787360
8228	10/27/2015	555589		VEHICLE SAFETY INSPECTION		787290
8228	10/26/2015	555449		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		787290
8228	10/26/2015	555449		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		787290
8228	10/26/2015	555449	ROCKER COVER GASKET 0500LE			785754
8228	10/20/2015	554154	Mechanic entered - Fluid Leaks Other			710837
8228	10/16/2015	553821	PLATE CLAMPING SIDE PANEL			710837
8228	10/16/2015	553821	GAS STAY 350NM X 600MM			710837
8228	10/16/2015	553821	KIT AIR LINE FITTING VOSS 22MM 50Z0114			710837
8228	10/16/2015	553821	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)			710837
8228	10/16/2015	553821	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER			710837
8228	10/16/2015	553821	DRAIN VALVE KIT BOTTOM			710837
8228	10/16/2015	553821	HALDEX COIL BASE OIL SEPERATOR (49G0031)			710837
8228	10/16/2015	553821	CYCLONE CONDENSER VALVE KIT			710837
8228	10/16/2015	553821	Check air system won't build air pressure	tow the bus to work shopekit airdryer and air sepatetorfixed burst air line road tested ok		710837
8228	10/15/2015	553821	DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G157155 Receiving #:162838 Date :2015-10-22 TOW FROM CAULFIELD STATION TO DANDENONG		786216
8228	10/09/2015	551508	Consumables			784151
8228	10/09/2015	551508	GLOBE H1 24V 70W			783562
8228	10/09/2015	551508	GLOBE 24V 75/70W H4			783562
8228	10/09/2015	551508	Service	Replace both lights and checked ranjith		783562
8228	10/08/2015	551508	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500			783562
8228	10/07/2015	551508	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	checked. both low beam headlights are too dull. need to replace both inserts. reflective coating and lens u/s.		783191
8228	10/05/2015	550644	Consumables			783191
8228	10/05/2015	550644	Consumables			783191
8228	10/05/2015	550644	Consumables			782767
8228	10/05/2015	550644	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)			782767
8228	10/05/2015	550644	OIL FILTER 1725+0500LE			782767
8228	10/05/2015	550644	FUEL FILTER 0500LE			782767
8228	10/05/2015	550644	FUEL FILTER MERC 0500LE			782767
8228	10/05/2015	550644	AIR FILTER MERC 0500LE E491L			782767

8228	10/01/2015	550527	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fitted	782125
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644		CARRY OUT C SERVICE AS PER CHECK LIST	782125
8228	10/01/2015	550644		CARRY OUT B SERVICE AS PER CHECK LIST	782125
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644	Consumables		782553
8228	10/01/2015	550644		CARRY OUT A SERVICE AS PER CHECK LIST	782125
8228	09/28/2015	549592	Replace A3 poster with Victorian Seniors Festival Poster	Replaced by refuellers	782061
8228	09/21/2015	548219	Ops Entered - Fault - Comm Equip - Route: 900 - Chadstone	CHECKED WITH CONTROL ROOM AND WORKING OK	779894
8228	09/19/2015	547882	Consumables		779545
8228	09/19/2015	547882	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	light working fine	778735
8228	09/16/2015	547368	CCTV - Cameras n/w	checked and found hdd was not in locked position. if hdd is not locked in unit will not power up and record. bus also has one 'dummy' camera.	778518
8228	09/16/2015	547368	Body - Door sensitive edge n/w	adjusted sensitive edge. working ok.	778518
8228	09/10/2015	546363		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done w/ nick & neven	777424
8228	09/10/2015	546363		VEHICLE SAFETY INSPECTION Completed	777424
8228	09/10/2015	546363		VEHICLE SAFETY INSPECTION	777424
8228	09/10/2015	546363		CLEAN A/C FILTERS	777424
8228	09/10/2015	546553	Consumables		777431
8228	09/10/2015	546553	Complete task as instructed in Fleet Campaign 09/15	Checked OK	777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)		777424
8228	09/10/2015	546362	OIL FILTER 1725+0500LE		777424
8228	09/10/2015	546362		CARRY OUT B SERVICE AS PER CHECK LIST Completed	777424
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362	Consumables		777431
8228	09/10/2015	546362		CARRY OUT A SERVICE AS PER CHECK LIST	777424
8228	09/07/2015	545124	DOOR VALVE SILENCER		775930
8228	09/07/2015	545124	Body Rear_Door Operation Faulty	adjust front and rear passanger doors fitted silenser for door value.	775930
8228	09/04/2015	545126	KIT AIR LINE FITTING VOSS 22MM 50Z0114		775930
8228	09/03/2015	545126	Air System Air_Leak Rear from the air dryer	Fitted new o -ring kit to the air line.	775930
8228	09/03/2015	545124	N/A for 0500 yet	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	775930
8228	08/19/2015	542011	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	Completed	772442
8228	08/14/2015	541205	HEATER-DEMISTER VALVE TAP MERC 0500 (DHV4008)		771171
8228	08/14/2015	541205	Ops Entered - Fault - Fluid Leaks Front of bus - Route: 90	Replacedemister coolant tap road tested	771171
8228	07/29/2015	537941	Complete Campaign 6/15 A3 Marketing Poster Change	Replaced	767031
8228	07/27/2015	537420	WIPER REFILL SUIT TX800+TX900		766805
8228	07/27/2015	537420	Consumables		767031
8228	07/27/2015	537420	GLOBE 24V 21W SINGLE CONTACT		766805
8228	07/27/2015	537419	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		766805
8228	07/24/2015	537410		VEHICLE SAFETY INSPECTION	766805
8228	07/24/2015	537410		CLEAN A/C FILTERS	766805
8228	07/24/2015	537410		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	766805
8228	07/24/2015	537410		VEHICLE SAFETY INSPECTION	766805
8228	07/24/2015	537420	Wipers and Washers Wipers Not_Clearing Screen	R,R inserts	766805
8228	07/24/2015	537419	Air System Leaking air at accumulator valve	R/R o - ring	766805
8228	07/24/2015	537411	Consumables		766805
8228	07/24/2015	537411	Consumables		766805
8228	07/24/2015	537411	Consumables		766805
8228	07/24/2015	537411		CARRY OUT A SERVICE AS PER CHECK LIST	766805
8228	07/21/2015	536715	CCTV (None) Cameras 1 3 and 4 not working	found camera unit door open and cameras disconnected re connected and secured with tape.found unit not to be powered checked wiring and traced issue to a blown fuse.replaced fuse but kepted blowing found that data logger runs on same circuit and dodgy wiring there was causing the short.repaired the wiring and	766023
8228	07/14/2015	535628	Consumables		764327
8228	07/14/2015	535628	GLOBE WEDGE INSTRUMENT 24V 5W		763553
8228	07/14/2015	535628	Mechanic entered - Elec and Light Exterior Lights	changed blown globe (nsf) bottom park light.	763553
8228	07/10/2015	535170	JET WASHER		762928
8228	07/10/2015	535170	PUMP WIPER-WASHER 24 VOLT 80826		762928
8228	07/10/2015	535170	Mechanic entered - Wipers and Washers Washers Not Working	removed both wiper blades. removed both old washer jets - damaged. fitted new washer jets. replaced washer motor u/s. tested - o.k.	762928
8228	07/03/2015	533968	Driver cabin door latch broken	fixed driver door lock.	761456
8228	06/30/2015	533436	Mechanic entered - Body Other	re-inserted rubber edge strips on both halves of centre door - come out of door frames.	760756
8228	06/25/2015	532813	NO 8 WHITE 25MM		760341
8228	06/25/2015	532813	NO 7 WHITE 25MM		760341
8228	06/25/2015	532813	EMERGENCY PROCEDURE DECAL		760341
8228	06/25/2015	532813	DECAL MAX SAFE CARRY WHITE ON CLEAR		760341
8228	06/25/2015	532813	DECAL VIDEO AND AUDIO SURVEILLANCE		760341
8228	06/25/2015	532813	Audit Route buses for correct Decals and positions. Replace		760341
8228	06/22/2015	531409	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G152636 Receiving #:157760 Date :2015-06-29	760756
8228	06/19/2015	531851	Vandalism - interior graffiti	rolled on paint over graffiti	758396
8228	06/17/2015	531556		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	758396
8228	06/17/2015	531556		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	758396
8228	06/17/2015	531556		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	758396
8228	06/17/2015	531556		VEHICLE SAFETY INSPECTION	758396
8228	06/17/2015	531556		CLEAN A/C FILTERS	758396
8228	06/17/2015	531409		ANNUAL SAFETY INSPECTION - RWC 003814 - PASSED 17/06/15	758396
8228	06/17/2015	531532	Consumables		758723
8228	06/17/2015	531529	Consumables		758723
8228	06/17/2015	531532	LED FRONT POSITION MARKER LIGHT		758396
8228	06/17/2015	531532	Mechanic entered - Elec and Light Interior Lights	replaced front door and (osf) 'led' exit lights - n/w.	758396
8228	06/17/2015	531529	GLOBE H1 24V 70W		758396
8228	06/17/2015	531529	Mechanic entered - Elec and Light Exterior Lights	changed blown globe (os) low beam headlight.	758396
8228	06/11/2015	530398		Check Alt Brush Pack.	757470
8228	06/11/2015	530398		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals done.	757470
8228	06/11/2015	530398		Inspect radiator and charge air cooler for dirt - clean done. done	757470
8228	06/11/2015	530413	REAR SHOCKER 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G152434 Receiving #:156963 Date :2015-06-11	757545
8228	06/11/2015	530413	Suspension rear lower toque rod buses need replace	replaced.	757470
8228	06/11/2015	530413	Mechanic entered - Suspension Other replace o/s/r shockers.	done.	757470

8228	06/11/2015	530413	Engine - Steamclean bus	cleaned	757470
8228	06/11/2015	530413	REPAIR DOUBLE SEAT BASES	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G152452 Receiving #:157013 Date :2015-06-12	757545
8228	06/10/2015	530398		Overhaul air seperator	757470
8228	06/10/2015	530398		Replace angle drive oil	757470
8228	06/10/2015	530398		Test coolant level - top up if required to equate to 37C frost protection	757470
8228	06/10/2015	530398		Replace power steering filter and check level (Replace oil if required)	757470
8228	06/10/2015	530398	FUEL FILTER MERC 0500LE		757470
8228	06/10/2015	530398	FUEL FILTER 0500LE		757470
8228	06/10/2015	530398	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		757470
8228	06/10/2015	530398	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-O-153468		757470
8228	06/10/2015	530398		PRE ANNUAL SAFETY INSPECTION CHECK	757470
8228	06/10/2015	530398		PRE ANNUAL SAFETY INSPECTION CHECK	757470
8228	06/10/2015	530398	HALDEX COIL KIT 0500LE 49G0027HALDEX		757470
8228	06/10/2015	530398	CYCLONE CONDENSER VALVE KIT		757470
8228	06/10/2015	530398		Check oil level in transmission - top up if required	757470
8228	06/10/2015	530398		Check and clean cartridge in dry type air cleaner	757470
8228	06/10/2015	530398		Replace pre and main fuel filters	757470
8228	06/10/2015	530398		Replace air dryer cansiter clean silence and drain reservoir	757470
8228	06/10/2015	530413	TORQUE ROD BUSH	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G152434 Receiving #:156931 Date :2015-06-10	757545
8228	06/10/2015	530413	REAR SHOCKER 0500LE		757470
8228	06/10/2015	530413	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		757470
8228	06/10/2015	530432	Suspension replace rea shockers	R/R n/s/r shockers	757470
8228	06/10/2015	530413	Vandalism N/ S rear bags need replace	R/R air bags	757470
8228	06/10/2015	530413	Suspension rear lower toque rod buses need replace	Removed torque rod to fit bushes but the bushes failed to fit.Re- fit old bushes and fitted back to the bus.	757470
8228	06/09/2015	530142	MAX SAFE CARRY--Black on Clear(TWMSCCPBC)		757357
8228	06/09/2015	530142	25mm BLACK NO 8		757357
8228	06/09/2015	530142	25mm BLACK NO 7		757357
8228	06/09/2015	530142	Audit Route buses for correct Decals and positions. Replace		757357
8228	06/08/2015	529949	Consumables		757357
8228	06/08/2015	529949	GLOBE 24V 21W SINGLE CONTACT		756684
8228	06/08/2015	529949	Mechanic entered - Elec and Light Exterior Lights	changed blown globe - (osf) side indicator.	756684
8228	06/04/2015	529634	Consumables		756684
8228	06/04/2015	529634	Mechanic entered - Elec and Light Other	secured and repaired wiring at alternatorac compressorboost pump and power steering pump	756453
8228	06/04/2015	529584		FIRE SAFETY INSPECTION AS PER CHECK LIST did the inspection	756453
8228	06/02/2015	529144	Mechanic entered - Steering Other	added power steering fluid - low.	756007
8228	06/02/2015	529142	Mechanic entered - Fluid Leaks Other	added coolant - low.	756007
8228	05/18/2015	526496	Mechanic entered - Body Other	tightened loose coolant door latch.	752852
8228	05/18/2015	526496	Ops Entered - Fault - Air System Air_Leak Interior - Route:	repaired air leak from driver seat.	752852
8228	05/18/2015	526496	FITTING STRAIGHT JOINER 6MM 11060600		752852
8228	05/18/2015	526496	Ops Entered - Fault - Air System Air_Leak Interior - Route:	repaired air leak from driver seat.	752852
8228	05/12/2015	523520	WHEEL NUT SQUIRREL		752509
8228	05/12/2015	523520	Fluid Leaks - Radiator cracked leaking coolant	Road testfill up coolant and steam wash engine to check coolant leak	752509
8228	05/12/2015	523520	Engine replace water pump	Completed	752509
8228	05/12/2015	523520		fixed door brackets	752509
8228	05/12/2015	523520	FITTING STRAIGHT JOINER 4MM	fixed door brackets	752509
8228	05/12/2015	523520	PADDLE LATCH DRIVER COMPARTMENT DOOR	fixed door brackets	752509
8228	05/12/2015	523520	AIR LINE FITTING KIT 0500LE AIR DRYER SMALL 50Z0115		752509
8228	05/12/2015	525716	Consumables		752527
8228	05/12/2015	525716	Consumables		752527
8228	05/12/2015	525716	Consumables	A Service A Service Completed	752509
8228	05/12/2015	525716		Clean A/C filter	752509
8228	05/12/2015	525716		Grease AC Compressor Clutch Bearing	752509
8228	05/12/2015	525716		Tension Wheel Nuts To OEM Specification	752509
8228	05/12/2015	525716		Fit all hoses and secure all brackets	752509
8228	05/11/2015	523520	Fluid Leaks - Radiator cracked leaking coolant		752509
8228	05/11/2015	523520	WATER PUMP WITH GASKETS MERCEDES BENZ 0500LE	fitted all back	752509
8228	05/07/2015	523520	Fluid Leaks - Radiator cracked leaking coolant	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G151109 Receiving #:154990 Date :2015-05-07	752509
8228	05/07/2015	523520	COOLANT HOSE	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G151109 Receiving #:154990 Date :2015-05-07	752509
8228	05/07/2015	523520	RADIATOR TOP HOSE	c/o	752509
8228	05/06/2015	523520	Fluid Leaks - Radiator cracked leaking coolant	Creditor #:GB-DAN013 DANDENONG RADIATOR SERVICE P/L P/O #:G150758 Receiving #:154788 Date :2015-05-05	752509
8228	05/04/2015	523520	REPAIR RADIATOR	c/o Fit radiator and coolant hoses	752509
8228	05/01/2015	523520	Fluid Leaks radiator leak	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G150755 Receiving #:154673 Date :2015-05-01	752509
8228	05/01/2015	523520	FAN BLADE 750MM	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G150755 Receiving #:154557 Date :2015-04-30	752509
8228	04/30/2015	523520	OIL SEAL 80 X 50 X 10	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G150813 Receiving #:154495 Date :2015-04-29	752509
8228	04/29/2015	523520	BLEEDER SCREW	Creditor #:GB-THO005 THOREB AUSTRALIA PTY LTD P/O #:G149217 Receiving #:154648 Date :2015-05-01	752509
8228	04/27/2015	514696	CCTV UPGRADE	topup coolant check leak need to check radiator. bus serviceble.	751003
8228	04/21/2015	522224	Ops Entered - Fault - Eng Cool - Route: 900 - Stud Park S/C	Tension Wheel Nuts	750413
8228	04/16/2015	521707		Perform & Complete PTSV Bus Safety Inspection	750413
8228	04/16/2015	521707			748980
8228	04/10/2015	520672	Consumables		739980
8228	04/10/2015	520672	Update destination Files and Check display	Updated desto files.	739980
8228	04/09/2015	514696	Security CCTV System Faulty - hasnt Recorded since 10/02/2	Fitted wi-fi unit by mobitec and install by volgrean	739980
8228	04/08/2015	520062		Perform & Complete PTSV Bus Safety Inspection Safety Inspection Completed	739980
8228	04/08/2015	520062		Tension Wheel Nuts	739980
8228	04/08/2015	520062		Perform & Complete PTSV Bus Safety Inspection Safety Inspection Completed	739980
8228	04/08/2015	520125	Air System - Front proportional valve leaking	changed the vlave and road tested	739980
8228	04/08/2015	520125	FRONT RELAY PROPORTIONAL VALVE 0500LE		739980
8228	04/08/2015	520063	Consumables		748778
8228	04/08/2015	520063	Consumables		748778
8228	04/08/2015	520063	AIR FILTER MERC 0500LE E491L		739980
8228	04/08/2015	520063		Clean A/C filter	739980
8228	04/08/2015	520063		Grease AC Compressor Clutch Bearing	739980
8228	04/08/2015	520063		Tension Wheel Nuts To OEM Specification	739980
8228	04/08/2015	520063		A Service A Service Completed	739980
8228	04/02/2015	519563	Consumables		747675
8228	04/02/2015	519563	GLOBE WEDGE INSTRUMENT 24V 5W		746952
8228	04/02/2015	519563	Elec and Light - NSF bottom park light working	changed blown globe.	746952
8228	04/01/2015	519364	Replace See Something Say Something Poster	n/a	739980
8228	03/31/2015	518881		re-tensioned nuts on wheels 5 and 6.	746231
8228	03/30/2015	518482	TYRE NEW 11R22.5N		746231
8228	03/28/2015	518482	Whls & Tyres pos5 need replacing	Replaced tyre position 5 & 6	744971
8228	03/26/2015	517990	Drv entered - Passenger Doors Require Adjusted	adjust rear passanger door.	743920

8228	03/26/2015	517989	Mechanic entered - Eng Cool Coolant Low	added coolant.	743920
8228	03/24/2015	517555	Mechanic entered - Eng Cool Coolant Low	added coolant.	743920
8228	03/19/2015	516725	Consumables		743408
8228	03/19/2015	516725	NARVA 24V REVERSING BUZZER		742923
8228	03/19/2015	516725	Mechanic entered - Elec & Light Reverse Lights	replaced reverse buzzer - u/s.	742923
8228	03/19/2015	516725	Mechanic entered - Eng Cool Coolant Low	added coolant and steam cleaned around radiator tank re: possible leak.	742923
8228	03/18/2015	516725	Whls & Tyres pos 5 - 6 need replacing		742923
8228	03/17/2015	516537	Mechanic entered - Eng Cool Coolant Low	added coolant.	742426
8228	03/05/2015	514732	Consumables		740078
8228	03/05/2015	514731	Consumables		740078
8228	03/05/2015	514732	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		739980
8228	03/05/2015	514732	Mechanic entered - Elec & Light Park Lights	replaced smashed (osr) clearance light.	739980
8228	03/05/2015	514731	GLOBE 24V 2W 2663		739980
8228	03/05/2015	514731	Mechanic entered - Elec & Light Guages	changed blown globe.	739980
8228	03/05/2015	514729	Mechanic entered - Eng Cool Coolant Low	added coolant.	739980
8228	03/05/2015	514696	Security CCTV System Faulty - hasnt Recorded since 10/02/2	checked hard drive on computer cannot re format to check and not recording properly replacement unit to be ordered.	739980
8228	03/05/2015	514696	Security CCTV - Camera u/s - unit was open and hard drive no	secured hardrive	739980
8228	02/24/2015	513154	LED NO PLATE+EXIT LIGHT		738048
8228	02/24/2015	513154			738048
8228	02/24/2015	513154		Tension Wheel Nuts	738048
8228	02/24/2015	513154		Perform & Complete PTVS Bus Safety Inspection	738048
8228	02/19/2015	512143	Consumables		736848
8228	02/19/2015	512143	Amber Warning Light Code: INS 1125	check fault code check engine heater ok bus serviceble clear fault code.	736463
8228	02/17/2015	511763	Mechanic entered - Eng Cool Coolant Low	added coolant.	736076
8228	02/09/2015	510467	Consumables		734897
8228	02/09/2015	510467	BATTERY 12V 200AMP 1100CCA + LHS		734249
8228	02/09/2015	510467	Elec & Light Battery Flat	changed batterys	734249
8228	02/03/2015	509501		re-tensioned nuts on wheels 1; 2; 3; 4; 5 and 6.	733512
8228	02/03/2015	509499		re-tensioned nuts on wheels 1; 2; 3; 4; 5 and 6.	733512
8228	02/02/2015	509322	TYRE NEW 11R22.5N		733512
8228	01/30/2015	509322	Whls & Tyres - Replace tyres 34	Replaced and tensioned w/nuts	733512
8228	01/30/2015	509067	Consumables		733512
8228	01/30/2015	509067	Ops Entered - Fault - Body & Acc Drivers Seat Back Rest - R	job completed	733082
8228	01/30/2015	509117	Brakes Smoking / Smell / Dense white smoke and strong sm	N/S/R brake booster leek and smell changed n/r brake booster and road tested tension n/r wheel nut with Alex.	733082
8228	01/30/2015	509117	BRAKE BOOSTER REAR O/S MB0500LE 50G2547K		733082
8228	01/29/2015	508701	Consumables		733082
8228	01/29/2015	508701	GLOBE 24V 21W SINGLE CONTACT		733082
8228	01/28/2015	508867	Consumables		733082
8228	01/28/2015	508701	Mechanic entered - Elec & Light Battery Flat	jump started.	732860
8228	01/28/2015	508867	Elec & Light - Replace globes	Replaced reverse & parklight globes	733082
8228	01/28/2015	508700	RAD CAP MERC BENZ SIGHT GLASS SIDE		732860
8228	01/28/2015	508700	Mechanic entered - Eng Cool Coolant Low	replaced radiator cap - seals u/s. and added coolant.	732860
8228	01/28/2015	508475	COOLANT HOSE 60/50MM	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G147774 Receiving #:149898 Date :2015-01-28	732860
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508754	OIL ENGINE DELO 400LE 15W40 (LU18)		732860
8228	01/28/2015	508754	AIR FILTER MERC 0500LE E491L		732860
8228	01/28/2015	508754	OIL FILTER 1725+0500LE		732860
8228	01/28/2015	508754		Grease AC Compressor Clutch Bearing	732860
8228	01/28/2015	508754		D-Service & Bus Safety Inspection	732860
8228	01/28/2015	508754		Tension Wheel Nuts to Spec	732860
8228	01/28/2015	508754		A Service & Bus Safety Inspection	732860
8228	01/28/2015	508786	Consumables		733082
8228	01/28/2015	508786	Consumables		733082
8228	01/28/2015	508786	Consumables		733082
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508754	Consumables		733082
8228	01/28/2015	508786		A Service	732860
8228	01/28/2015	508786		Clean A/C filter	732860
8228	01/28/2015	508786		Grease AC Compressor Clutch Bearing	732860
8228	01/28/2015	508786		Tension Wheel Nuts To OEM Specification	732860
8228	01/28/2015	508754		A Service	732860
8228	01/28/2015	508754		Clean A/C filter	732860
8228	01/28/2015	508754		Grease AC Compressor Clutch Bearing	732860
8228	01/28/2015	508754		Tension Wheel Nuts To OEM Specification	732860
8228	01/27/2015	508475	HOSE ENG TO G/BOX COOLER MERC 0500LE		732860
8228	01/27/2015	508475	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		732860
8228	01/27/2015	508475	Eng Cool Leaking coolant	changed tran.coolent pipe and hose	732860
8228	01/17/2015	507237	Consumables		730661
8228	01/17/2015	507237	Mechanic entered - Elec & Light Battery Flat	Jumpstart	730321
8228	01/16/2015	507094		re-tensioned nuts on wheels 1; 2; 3; 4; 5 and 6.	730321
8228	01/16/2015	507056		Completed	730321
8228	01/16/2015	507056		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	730321
8228	01/16/2015	507056	HALDEX COIL KIT 0500LE 49G0027HALDEX	Coil Kit	730321
8228	01/16/2015	507056	DRAIN VALVE KIT BOTTOM	Valve Kit	730321
8228	01/16/2015	507056	HALDEX COIL BASE OIL SEPERATOR	Base	730321
8228	01/16/2015	507056	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	730321
8228	01/16/2015	507056		Re-kit Air Cyclone Separator	730321
8228	01/14/2015	506261	Ops Entered - Breakdown - Breakdown Road Defect Unaffected		729733
8228	01/14/2015	506261	Mechanic entered - Brakes Locking	complete the job tensioned wheel nut with Alex and road tested.	729733
8228	01/13/2015	506261	REAR BRAKE CALIPER RH 0500LE	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G147332 Receiving #:149366 Date :2015-01-13	729733
8228	01/13/2015	506261	Mechanic entered - Brakes Locking	finished o/s .start n/s hub fit	729733
8228	01/13/2015	506261	REAR HUB NUT LOCK WASHER		729733
8228	01/13/2015	506261	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		729733
8228	01/12/2015	506261	Mechanic entered - Brakes Locking	strip o/r brake and hub	729733
8228	01/12/2015	506261	DISC PAD SET SCANIA MB0500		729733
8228	01/12/2015	506261	BRAKE BOOSTER REAR N/S MB0500LE 50G2546K		729733
8228	01/07/2015	505441	Consumables		729451
8228	01/07/2015	505441	L/H ANTIBURST LOCK		729259
8228	01/07/2015	505441	Ops Entered - Fault - Body & Acc Interior - Route: 900 - St	driver comp door lock replaced & adjusted .	729259

8228	01/06/2015	505307	Suspension - NSF airbag leaking	Remove old air bag and replace with new one	728913
8228	01/06/2015	505307	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		728913
8228	01/06/2015	505204	Mechanic entered - Eng Cool Coolant Low	added coolant.	728913
8228	01/06/2015	505212	Consumables		729259
8228	01/06/2015	505212	Body & Acc (None) / Driver Security door will not stay shu	checked. operating fine. serviceable.	728913
8228	01/05/2015	504949	Consumables		728913
8228	01/05/2015	504949	Mechanic entered - Elec & Light Battery Flat	jump started.	728913
8228	01/02/2015	504767	Eng Cool - Coolant leaking around radiator	Washed and road tested - ok	728001
8228	01/02/2015	504766	Eng Cool High Temperature	Steam cleaned radiator (very dirty) and road tested - ok.	728001
8228	01/02/2015	504921	Consumables		728490
8228	01/02/2015	504921	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	Completed	728490
8228	12/30/2014	504032	WIPER REFILL SUIT TX800+TX900		727648
8228	12/30/2014	504031	MUFFLER MOUNT 0500LE 50T0010		727648
8228	12/29/2014	503995		Safety Inspection Completed steam washed coolant leak and top up coolant	727631
8228	12/29/2014	503995		Tension Wheel Nuts	727631
8228	12/29/2014	503995			727631
8228	12/29/2014	504032	Mechanic entered - Wipers & Washers Rubber Adrift	fit new wiper rubber.	727631
8228	12/29/2014	504031	Mechanic entered - Exhaust Broken Mount	fit new muffler mount.	727631
8228	12/23/2014	503408	Consumables		0
8228	12/23/2014	503408	SEAT ASSY ISRI 6008 MECH LUMBAR		726883
8228	12/22/2014	503408	Ops Entered - Fault - Body & Acc Drivers Seat Back Rest - R	replaced driver seat with seat out of stores and sent damaged seat away for repair	726703
8228	12/18/2014	502862	Consumables		0
8228	12/18/2014	502862	L/H ANTIBURST LOCK		726149
8228	12/18/2014	502862	HINGE DRIVERS COMPARTMENT		726149
8228	12/18/2014	502862	PADDLE LATCH DRIVER COMPARTMENT DOOR		726149
8228	12/18/2014	502862	SIDE BIN LOCK PINS		726149
8228	12/17/2014	502862	Body & Acc - Repair drivers door lock	Repaired lock and hinges	726149
8228	12/16/2014	502315	Mechanic entered - Wipers & Washers Washers Not Working	filled 'mt' wiper washer bottle.	725566
8228	12/16/2014	502347	A/C BELT 0500 BENZ		725566
8228	12/16/2014	502347	Mechanic entered - Engine Other	adjust a/c compresure change main belt road test bus ok.	725566
8228	12/13/2014	502146	A3 Poster Change	Fitted	725361
8228	12/12/2014	501812	Consumables		0
8228	12/12/2014	501812	Ops Entered - Fault - Body & Acc Drivers Seat Back Rest - R	job completed	724584
8228	12/12/2014	501812	Ops Entered - Fault - Body & Acc Drivers Seat Controls - Ro	job completed	724584
8228	12/08/2014	500584		re-tensioned nuts on wheels 1 and 2.	723055
8228	12/04/2014	499966	TYRE NEW 11R22.5N		722721
8228	12/03/2014	499966	Mechanic entered - Whls & Tyres Damaged	changed tyres 1 (sidewall damage) and 2 (worn). nuts tensioned with ranjith and ryan.	721929
8228	12/03/2014	499835	A/C BELT 0500 BENZ		721929
8228	12/03/2014	499835	Ops Entered - Fault - Engine W'rrning Light - Route: 900 - C	change a/c belt2 idler pullyes try to adjust a/c compressure inside mounting bolt damage adjust belt road test bus ok.need remove a/c compressure to fixed mounting bolt.	721929
8228	12/02/2014	499694	Steering - Steering wheel u/s	R/r steering wheelalighned steering wheel and checked - ok.	721929
8228	12/01/2014	499694	STEERING WHEEL 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G146073 Receiving #:148077 Date :2014-12-02	722380
8228	12/01/2014	499368	Consumables		0
8228	12/01/2014	499368	Mechanic entered - Elec & Light Battery Flat	jump started.	721929
8228	11/26/2014	498743	Consumables		0
8228	11/26/2014	498743	Mechanic entered - Body & Acc Other	re-fit sections of anti slip strip fallen out and replace missing section - rear of bus.	721194
8228	11/25/2014	498445	Consumables		0
8228	11/25/2014	498445	Complete AM/FM radio saloon speaker modification	did the radio campaing	720739
8228	11/21/2014	497983	Consumables		0
8228	11/21/2014	497983	Elec & Light Alternator noise	remove and replaced alternator	720090
8228	11/18/2014	497116	Consumables		0
8228	11/18/2014	497116	CLEAR FRONT INDICATOR WRAP-AROUND		717984
8228	11/18/2014	497116	Mechanic entered - Elec & Light Park Lights	change nsf corner indecater/park light assy.	717984
8228	11/17/2014	496256	Consumables		0
8228	11/17/2014	496256	Consumables		0
8228	11/17/2014	496256	Consumables		0
8228	11/17/2014	496256	Consumables		0
8228	11/17/2014	496256	COMPRESSOR OIL AIR CON		717984
8228	11/17/2014	496256	FILTER DRIER THERMO KING		717984
8228	11/12/2014	496267		Tension Wheel Nuts	717984
8228	11/12/2014	496267		Perform & Complete PTSV Bus Safety Inspection	717984
8228	11/12/2014	496267		Tension Wheel Nuts	717984
8228	11/12/2014	496267		Perform & Complete PTSV Bus Safety Inspection	717984
8228	11/12/2014	496256	Service	A Service	717984
8228	11/12/2014	496256		Clean A/C filter	717984
8228	11/12/2014	496256		A Service	717984
8228	11/12/2014	496256		Grease AC Compressor Clutch Bearing	717984
8228	11/12/2014	496256		Tension Wheel Nuts To OEM Specification	717984
8228	11/11/2014	495818		Replace compressor oil	717830
8228	11/11/2014	495818		B Service	717830
8228	11/11/2014	495818		Replace filter drier	717830
8228	11/11/2014	495818		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	717830
8228	11/11/2014	495818		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	717830
8228	11/11/2014	495818		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	717830
8228	11/11/2014	495818		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	717830
8228	11/11/2014	495818		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	717830
8228	11/11/2014	495818		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	717830
8228	11/11/2014	495818		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	717830
8228	11/11/2014	495818		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	717830
8228	11/11/2014	495818		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	717830
8228	11/11/2014	495818		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	717830
8228	11/11/2014	495818		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	717830
8228	10/29/2014	493816	Consumables		0
8228	10/29/2014	493816	Remove Legacy Poster and replace with See Something Say So	N/A	714739
8228	10/28/2014	493336	Consumables		0
8228	10/28/2014	493336	Elec & Light - Replace NSR bottom indicator	replaced	714187
8228	10/21/2014	492112		Tension Wheel Nuts Done with Nick	712867
8228	10/21/2014	492112		Perform & Complete PTSV Bus Safety Inspection Complete with Nick	712867
8228	10/07/2014	489578	Consumables		0
8228	10/07/2014	489578	Elec & Light Indicators - Front N/S bottom indicator not w	replaced (nsf) bottom park/indicator lamp - melted.	709047
8228	10/07/2014	489578	WEDGE GLOBE INSTRUMENT 24V 5W		709047
8228	10/07/2014	489578	GLOBE 24V 21W SINGLE CONTACT		709047
8228	10/07/2014	489578	CLEAR FRONT INDICATOR WRAP-AROUND		709047
8228	10/07/2014	489593	Mechanic entered - Eng Cool Coolant Low	added coolant.	709047

[illegible]

8228	07/21/2014	474910	ANNUAL INSPECTION	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G141377 Receiving #:143383 Date :2014-07-23	695560
8228	07/21/2014	475511	Mechanic entered - Body & Acc Destination Blind	Replaced driver blind	695244
8228	07/21/2014	475511	DRIVERS BLIND 1800MM WIDE (23317)		695244
8228	07/20/2014	474910	Annual Licence	- RWC 006477 - PASSED 20/07/14	695244
8228	07/20/2014	475511	Elec & Light - Replace both top park lights	Replaced	695244
8228	07/20/2014	475511	LED FRONT PARK LAMP WHITE		695244
8228	07/18/2014	475259	Mechanic entered - Steering Other	added power steering fluid - low.	695443
8228	07/18/2014	475282	Removed & replaced air cyclone seperator	Re-kit Air Cyclone Separator	695443
8228	07/18/2014	475282	Inspected air pipe for blockage ok	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	695443
8228	07/18/2014	475282	HALDEX COIL KIT 0500LE	Coil Kit	695443
8228	07/18/2014	475282	DRAIN VALVE KIT BOTTOM	Valve Kit	695443
8228	07/18/2014	475282	HALDEX COIL BASE OIL SEPERATOR	Base	695443
8228	07/18/2014	475282	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	695443
8228	07/17/2014	475056	Ops Entered - Fault - Steering Shimmy - Route: 900 - Oaklei	reseal power steering pump pipesbleed systemroad tested ok.	695244
8228	07/17/2014	475061	Elec & Light - Reverse buzzer n/w	checked could not fault	695244
8228	07/17/2014	475056	Ops Entered - Fault - Brakes Pull Right - Route: 900 - Stud	road tested ok.	695244
8228	07/10/2014	473558	Mechanic entered - Steering Other	added power steering fluid - low.	694040
8228	07/07/2014	472701	Mechanic entered - Elec & Light Battery Flat	Jumpstart	693207
8228	07/07/2014	472842	Mechanic entered - Eng Cool High Temperature	found coolant temp sensor to be u/s removed and replaced and test drove all ok.	693207
8228	07/07/2014	472842	TEMPERATURE SENDER- MERC 0500		693207
8228	07/07/2014	472738	Ops Entered - Fault - Security CCTV System Faulty - Route:	found 1 cameras graffitied cleand and tested all ok and checked playback all ok.	693207
8228	07/05/2014	472667	Mechanic entered - Elec & Light Battery Flat	jumpstart	693207
8228	07/04/2014	472413	MANUAL DRAIN VALVE		693207
8228	07/03/2014	472413	Ops Entered - Fault - Air System Low Air Pressure - Route:	Located air leak at rear air tank.R/R new air tank valve.re-checked - ok.	693207
8228	07/02/2014	472073	Mechanic entered - Steering Other	added power steering fluid - low.	692945
8228	07/02/2014	471889	Mechanic entered - Elec & Light Battery Flat	Jumpstart	692945
8228	07/01/2014	471821	Steering replace power steering filterlock	fit new power steering filter lock.	692945
8228	07/01/2014	471821	POWER STRG LATCH (FILTER)	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G140658 Receiving #:142598 Date :2014-07-01	692945
8228	07/01/2014	471821	POWER STEERING FILTER VOLVO		692945
8228	06/30/2014	471526	32MM LOOSE WHEEL NUT INDICATOR		692945
8228	06/30/2014	471526	Fit Wheel Nut Pointers to all wheel nuts on the front axle	Replaced	692945
8228	06/30/2014	471537	Body & Acc - Front door step tread trim panel broken	replaced with new job completed	692945
8228	06/30/2014	471527	NUT HAND RAIL CLAMP (280010)		692945
8228	06/27/2014	471207			692945
8228	06/27/2014	471207		Change Diff Oil	692945
8228	06/27/2014	471207	Service	Change Diff Oil	692945
8228	06/27/2014	471207		R.S.I. inspection	692945
8228	06/27/2014	471207		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	692945
8228	06/27/2014	471207		Inspect radiator and charge air cooler for dirt - clean	692945
8228	06/27/2014	471207		Check oil level in transmission - top up if required	692945
8228	06/27/2014	471207		Check and clean cartridge in dry type air cleaner	692945
8228	06/27/2014	471207		Replace pre and main fuel filters	692945
8228	06/27/2014	471207		Replace air dryer cansiter clean silence and drain reservoir	692945
8228	06/27/2014	471207		Replace angle drive oil	692945
8228	06/27/2014	471207		Test coolant level - top up if required to equate to 37C frost proctection	692945
8228	06/27/2014	471207		Replace power steering filter and check level (Replace oil if required)	692945
8228	06/27/2014	471207	Service	R.S.I. inspection	692945
8228	06/27/2014	471207		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	692945
8228	06/27/2014	471207		Inspect radiator and charge air cooler for dirt - clean	692945
8228	06/27/2014	471207		Check oil level in transmission - top up if required	692945
8228	06/27/2014	471207		Check and clean cartridge in dry type air cleaner	692945
8228	06/27/2014	471207		Replace pre and main fuel filters	692945
8228	06/27/2014	471207		Replace air dryer cansiter clean silence and drain reservoir	692945
8228	06/27/2014	471207		Replace angle drive oil	692945
8228	06/27/2014	471207		Test coolant level - top up if required to equate to 37C frost proctection	692945
8228	06/27/2014	471207		Replace power steering filter and check level (Replace oil if required)	692945
8228	06/27/2014	471207	FUEL FILTER MERC 0500LE		692945
8228	06/27/2014	471207	FUEL FILTER 0500LE		692945
8228	06/27/2014	471207	AIR DRYER CANISTER VOLVO+ NL202		692945
8228	06/27/2014	471207	POWER STEERING FILTER VOLVO		692945
8228	06/27/2014	471527	Engine - Secure air pipe on top of engine	Secured	692945
8228	06/27/2014	471527	Fuel - Fuel leak from fuel pipe at coolant tank	Replaced pipe	692945
8228	06/27/2014	471537	Body & Acc - Front door step tread trim panel broken	Removed ramp c/o	692945
8228	06/27/2014	471527	Air System - Air leak at air tanks	Repaired	692945
8228	06/11/2014	468032	Mechanic entered - Elec & Light Battery Flat	jumpstart	689125
8228	06/10/2014	467963		Tension Wheel Nuts to Spec	689125
8228	06/10/2014	467963		Replace Engine Oil Breather Kit	689125
8228	06/10/2014	467963		Grease AC Compressor Clutch Bearing	689125
8228	06/10/2014	467963	OIL FILTER 1725+0500LE		689125
8228	06/10/2014	467963	ENGINE OIL DELO 400LE 15W40 (LU18)		689125
8228	06/10/2014	467963		Tension Wheel Nuts to Spec	689125
8228	06/10/2014	467963		A Service & Bus Safety Inspection	689125
8228	06/10/2014	467963		D-Service & Bus Safety Inspection	689125
8228	06/10/2014	467963	ENGINE OIL BREATHER KIT 0500LE (EASS00M05)		689125
8228	06/10/2014	467963	AIR FILTER MERC 0500LE		689125
8228	06/10/2014	467963		A Service	689125
8228	06/10/2014	467963		Clean A/C filter	689125
8228	06/10/2014	467963		Grease AC Compressor Clutch Bearing	689125
8228	06/10/2014	467963		Tension Wheel Nuts To OEM Specification	689125
8228	06/02/2014	466263	SEAT CATCH		687206
8228	06/02/2014	466263	GAS STAY 450N 710MM EXT LENGTH		687206
8228	05/30/2014	466255	ROCKER COVER GASKET 0500LE	Rocker Cover Gasket	687078
8228	05/30/2014	466255	Adjust Tappets	Adjusted Tappets - Washed engineroad tested and checked for leaks - ok.	687078
8228	05/30/2014	466182			687078
8228	05/30/2014	466182		Tension Wheel Nuts	687078
8228	05/30/2014	466182	Elec & Light N/S/F parklight n/w	Perform & Complete PTSV Bus Safety Inspection	687078
8228	05/30/2014	466182	WEDGE GLOBE INSTRUMENT 24V 5W	R/R globe	687078
8228	05/30/2014	466263	Body & Acc Gas Struts u/s		687078
8228	05/30/2014	466263	Body & Acc Gas Struts u/s	Replaced back seat catches & hooks & secired old catches	687078
8228	05/30/2014	466182	SEAT BELT LEFT HAND	R/R struts	687078
8228	05/30/2014	466182	Mechanic entered - Body & Acc Drivers Seat Belt		687078
8228	05/26/2014	465096	Check CCTV and date update	R/R D/seat belt - ok	687078
8228	05/26/2014	465098	DISC PAD SET SCANIA MB0500	checked cctv found time and date not correct reset time and date found camera 1 not working checked and found loose connection reconnected all ok	685849

8228	05/26/2014	465098	Ops Entered - Fault - Brakes ABS On - Route: 900 - Brandon	change rear brake pads road test bus ok.	685849
8228	05/26/2014	465132	Mechanic entered - Brakes Brake Linings Worn	assisted dulkith in removing wheels 3;4;5 and 6 for brake pad change. wheels re-fitted and all drive wheel nuts tensioned with dulkith.	685849
8228	05/14/2014	462895	GLOBE H1 24V 70W		683286
8228	05/13/2014	462895	Elec & Light - Replace headlight globe	Replaced fuelled & parked	683286
8228	05/12/2014	462514	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	replaced	682958
8228	05/05/2014	460618	REPAIR POS 6 TYRE PUNTURE 11R2	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G138363 Receiving #:140286 Date :2014-05-07	681754
8228	05/05/2014	460908	Elec & Light Park Lights not working	replaced parker globe	680206
8228	05/02/2014	460618	Whls & Tyres repair pos 6 tyre punture	Repaired	680206
8228	05/01/2014	460504	Whls & Tyres Replace Pos 6 tyre	replaced	680206
8228	04/30/2014	461043	Elec & Light - Bus wont start	Jump started	680206
8228	04/16/2014	458291	L.E.D SIDE MARKER PEREI RED/AMBER		678404
8228	04/16/2014	458291	Mechanic entered - Elec & Light Park Lights	replaced smashed clearance light (nsr).	678404
8228	04/14/2014	457866	Mechanic entered - Elec & Light Battery Flat	Jumpstart	677737
8228	04/12/2014	457681	Whls & Tyres - Tyre 3 low tread	checked ok	677737
8228	04/11/2014	457654		Perform & Complete PTSV Bus Safety Inspection	677737
8228	04/11/2014	457654		Perform & Complete PTSV Bus Safety Inspection	677737
8228	04/11/2014	457654		Tension Wheel Nuts	677737
8228	04/11/2014	457682	Suspension - Replace OSF sway bar link rod	Replaced O/S/F sway bar link	677737
8228	04/11/2014	457682	Suspension Noisy	Removed sway bar bush clamps and lubricated	677737
8228	04/11/2014	457682	Drv entered - Suspension Noisy	Rectified sway bar bushes noisy	677737
8228	04/11/2014	457682	Engine - Engine oil leak from sump gasket	Checked ok.	677737
8228	04/11/2014	457682	Body & Acc - LHF seat cushion torn	Secured seat cushion	677737
8228	04/10/2014	457027	WORN - POS 34 - 11 R22.5 - NE	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G137571 Receiving #:139578 Date :2014-04-15 REPLACE WITH NEW	678024
8228	04/09/2014	457016	Mechanic entered - Whls & Tyres Worn	changed tyres 3 and 4. wheel nuts tensioned.	677026
8228	04/09/2014	457027	Whls & Tyres - Replace tyre pos 34 - worn	Replaced	677026
8228	04/09/2014	457018	Mechanic entered - Steering Other	added power steering fluid.	677026
8228	04/09/2014	457110	Mechanic entered - Eng Cool Leaking	change heater hose from engine to boste pump top up coolant road test bus ok.	677026
8228	04/03/2014	455891	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	Completed	675227
8228	04/02/2014	455435	Mechanic entered - Eng Cool Coolant Low	added coolant.	675227
8228	03/24/2014	453985	Elec & Light Dash Light park brake light does not ulimina	Checked OK	673516
8228	03/24/2014	453985	Perform Campaign 1_14 School Bus Light Globe Check Check	N/A	673516
8228	03/24/2014	454041	Fit Myki decals as requiredFit Recruitment decal as requi	Replaced decals	673516
8228	03/24/2014	453985	Body & Acc - Rear floor missing yellow safety strips	Checked OK	673516
8228	03/24/2014	453859		A Service	673516
8228	03/24/2014	453859		A Service	673516
8228	03/24/2014	453859		Clean A/C filter	673516
8228	03/24/2014	453859		Grease AC Compressor Clutch Bearing	673516
8228	03/24/2014	453859		Tension Wheel Nuts To OEM Specification	673516
8228	03/06/2014	451447	Elec & Light - Replace LED saloon light	ELIAS - Replaced LED and Fluro	670034
8228	03/06/2014	411176	FLURO TUBE 24V 18W 24'		669880
8228	03/06/2014	411176	FIRTREE CLIP		669880
8228	03/06/2014	450883	Service	Replace Differential oil	669880
8228	03/06/2014	450883		diff lude already done early this year	669880
8228	03/05/2014	411176	LED INTERIOR ROOF LIGHT		669712
8228	03/04/2014	450420	Service	Arranged repair and peperwork etc.	669559
8228	03/04/2014	450420	BRAZILLIAN MIRROR RH		669559
8228	03/04/2014	450420	Accident damage - Acc # DAN 68747 - mirror only.	Replaced broken mirror.	669559
8228	02/28/2014	449980		Tension Wheel Nuts	669184
8228	02/28/2014	449980		Perform & Complete PTSV Bus Safety Inspection	669184
8228	02/21/2014	448786	RADIATOR HOSE UPPER 0500LE		667729
8228	02/21/2014	448786	Eng Cool radiator hose leaking	draine coolant change radiator upper hose near engine topup coolant road test bus ok.	667729
8228	02/14/2014	447418	WORN - POS 3 - 11 R22.5 - NEW	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G135193 Receiving #:136851 Date :2014-02-17 REPLACE WITH NEW	666776
8228	02/14/2014	447425	Whls & Tyres - Tyre 3 low tread		666493
8228	02/14/2014	447425	Mechanic entered - Whls & Tyres Worn	changed tyre 3. dirty wheel washed. wheel nuts tensioned.	666493
8228	02/14/2014	447418	Whls & Tyres - Replace tyre pos 3 - worn	Replaced	666492
8228	02/14/2014	447424	DOWN LIGHT LED		666492
8228	02/14/2014	447424	Mechanic entered - Elec & Light Interior Lights	replaced front door step light (u/s).	666492
8228	01/20/2014	441453	Replace A./C compresor	Creditor #:GB-SOU015 SOUTHERN STATES GROUP P/O #:G133784 Receiving #:136114 Date :2014-01-30	663216
8228	01/20/2014	443975	Mechanic entered - Eng Cool Coolant Low	added coolant.	660521
8228	01/18/2014	443845	HALDEX COIL KIT 0500LE	Coil Kit	660521
8228	01/18/2014	443845	DRAIN VALVE KIT BOTTOM	Valve Kit	660521
8228	01/18/2014	443845	HALDEX COIL BASE OIL SEPERATOR	Base	660521
8228	01/18/2014	443845	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	660521
8228	01/18/2014	443845		Re-kit Air Cyclone Separator	660521
8228	01/15/2014	443448		Perform & Complete PTSV Bus Safety Inspection	660271
8228	01/15/2014	443448		Tension Wheel Nuts	660271
8228	01/15/2014	443448		Perform & Complete PTSV Bus Safety Inspection	660271
8228	01/14/2014	441453	C-O THERMOKING SCREW COMPRESSOR		660017
8228	01/08/2014	441453	A/C BELT 0500 BENZ		658409
8228	01/02/2014	441708	Seat wont lock in position	ref to w/o 432163	658409
8228	12/31/2013	441453	Ops Entered - Fault - Air Cond Air Conditioner - Route: 90	Compressor OUT 10327B7604 IN K042ZC0038	658409
8228	12/31/2013	441453	Air Cond Air Conditioner / AC Light On	ac not working check wire fuse all ok low pressure need to check pressure	658409
8228	12/31/2013	441453	Air Cond Air Conditioner	ac not working check wire fuse all ok low pressure need to check pressure	658409
8228	12/31/2013	441453	Mechanic entered - Air Cond Other	ac not working check wire fuse all ok low pressure needto check pressure	658409
8228	12/24/2013	440912	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	removed	658409
8228	12/17/2013	439918	Brakes - Brakes wearing uneven NSR inner brake pad 5mm OSR	Checked has been replaced with new brake pads	658409
8228	12/12/2013	438991	Carry out campaign as per Fleet re-branding Procedure.	N/A	658409
8228	11/26/2013	436550	Perform Campaign as per Instructions Ensure that appropri	Completed.	658409
8228	11/26/2013	436614		complete	658409
8228	11/26/2013	436614		A Service	658409
8228	11/26/2013	436614		Clean A/C filter	658409
8228	11/26/2013	436614		Grease AC Compressor Clutch Bearing	658409
8228	11/26/2013	436614		Tension Wheel Nuts To OEM Specification	658409
8228	11/22/2013	436027	WEAR SENSOR		657915
8228	11/22/2013	436027	Ops Entered - Fault - Elec & Light Dash Light - Route: 900	check brake fault code then change RNS brake wear senser wire clear fault code road test bus ok.	657915
8228	11/22/2013	436027	Mechanic entered - Eng Cool Coolant Low	added coolant.	657915
8228	11/21/2013	435871	Mechanic entered - No Defect Recorded	Road Test With Damon	657760
8228	11/21/2013	435326	Brakes - Foot brake valve leak	Replace compressore	657760
8228	11/20/2013	435412	Air System change air compressor and clean air pipes com/ to	tightened power steering pump fittings and all fittings on compressor. removed air pipe off air dryer and checked if blocked could not fault. replaced air dryer filter. replaced saftey valve on compressor. topped up coolant and power streeting oil	657760
8228	11/20/2013	435412	VALVE SAFETY BLOW OFF 1.3MP		657760
8228	11/20/2013	435412	AIR DRYER FILTER C/W COALESCING		657760
8228	11/19/2013	435412	Air System change air compressor and clean air pipes com/ to		657760
8228	11/19/2013	435412	COMPRESSOR O RING 0500LE		657760

8228	11/19/2013	435412	GASKET SUIT 0500LE COMPRESSOR A4571304815		657760
8228	11/18/2013	435326	Brakes - Foot brake valve leak		657760
8228	11/18/2013	435412	AIR COMPRESSOR 0500 EURO 3	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G131971 Receiving #:133416 Date :2013-11-18	657760
8228	11/18/2013	435412	Air System change air compressor and clean air pipes com/ t		657760
8228	11/18/2013	435412	Air System change air compressor and clean air pipes com/ to		657760
8228	11/18/2013	435360	ACCUMULATOR RETARDER VALVE		657760
8228	11/18/2013	435360	Air System - Transmission accumalator air leak		657760
8228	11/08/2013	434352	Fit New Myki Decal as Per PTV fitting instructions	fit new air switch. Fit New Myki Decal as Per PTV fitting instructions	657760
8228	10/28/2013	432163	SPRING RECLINE D/SEAT		656664
8228	10/25/2013	432163	Body & Acc REPAIR DRIVER SEAT	Fixed	656664
8228	10/24/2013	431946	AIR COMPRESSOR COOLANT PIPE 0500		655594
8228	10/24/2013	431946	Eng Cool - Air compressor coolant pipe leak	change air compressour cooling pipe and unione steam clean road test check leak bus ok.	655594
8228	10/22/2013	431660	Body & Acc - Remove rear decals	Removed & polished	655594
8228	10/22/2013	428907	BY LAW PICKUP/SET DOWN DECAL		655594
8228	10/21/2013	431181	GLOBE H1 24V 70W		655594
8228	10/21/2013	431946	COMPRESSOR PIPE UNION	Creditor #;GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G130924 Receiving #:132838 Date :2013-10-31	657760
8228	10/21/2013	431181	BRAKE+ CLUTCH PEDAL PAD 0500LE		655594
8228	10/19/2013	430675	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign		655594
8228	10/18/2013	431019			655594
8228	10/18/2013	431019			655594
8228	10/18/2013	431019			655594
8228	10/18/2013	431181	Elec & Light - Change OS h/light globe	Replaced	655594
8228	10/18/2013	430978	Comm Equip CT camera U/S	fixed CCTV problem	655594
8228	10/18/2013	431181	Brakes - Replace brake pedal rubber	Replaced	655594
8228	10/17/2013	430728	Mechanic entered - Eng Cool Coolant Low	top up coolant	655594
8228	10/15/2013	430197	Diff & HubsReplace diff oil	Replace diff oil	655481
8228	10/11/2013	429734	Mechanic entered - Eng Cool Coolant Low	added coolant.	654490
8228	10/10/2013	429554	Ops Entered - Fault - Air Cond Cooling Fault Light - Route:	topup coolantt	654490
8228	10/10/2013	429597	Ops Entered - Fault - Passenger Doors Leaking Air - Route:	Assist Alan to change rear door switch	654490
8228	10/10/2013	429597	Ops Entered - Fault - Passenger Doors Leaking Air - Route:	fit new door switches.adjust doors.	654490
8228	10/10/2013	429589	Mechanic entered - Passenger Doors Other Faulty Switch	ref to w/o 429597	654490
8228	10/09/2013	429328	Mechanic entered - Eng Cool Coolant Low	added coolant.	654376
8228	10/07/2013	428907	NO SMOKING DECAL		653983
8228	10/07/2013	428907	CCTV SURVEILLANCE DECAL		653983
8228	10/07/2013	428907	CUSTOMER ENQUIRY DECAL		653983
8228	10/07/2013	428907	PLEASE ASSIST DRIVER DECAL		653983
8228	10/07/2013	428907	PASSENGERS REQUIRED BY LAW DECAL		653983
8228	10/07/2013	428907	DRIVERS NO DEFECT CHECKLIST DECAL		653983
8228	10/07/2013	428907	WARNING MAXIMUM HEIGHT DECAL		653983
8228	10/07/2013	428907	EMERGENCY PROCEDURE DECAL		653983
8228	10/07/2013	428907	LICENSED TO CARRY DECAL		653983
8228	10/02/2013	428907	Perform sticker audit on vehicles ensuring that correct sti	Secured	653534
8228	10/02/2013	428064	Body & Acc check driwer seat	topup coolant and check leak bus ok.	653534
8228	10/01/2013	427819	Mechanic entered - Eng Cool Coolant Low	added coolant.	652275
8228	09/25/2013	427082	Mechanic entered - Eng Cool Coolant Low	added coolant.	650717
8228	09/20/2013	426267	Mechanic entered - Eng Cool Coolant Low	added coolant.	650717
8228	09/19/2013	426111	Mechanic entered - Eng Cool Coolant Low	added coolant.	649857
8228	09/16/2013	425496	Mechanic entered - Eng Cool Coolant Low	road tested & fuelled vehicle.	648628
8228	09/11/2013	424755	Mechanic entered - Eng Cool Coolant Low	add coolant.	648628
8228	09/11/2013	424753	Ops Entered - Fault - Eng Cool Coolant Low - Route: 900 - B		648180
8228	09/09/2013	423187	SIDEWALL DAMAGE	Creditor #;GB-BEA001 BEAUREPAIRES P/O #:G128984 Receiving #:130623 Date :2013-09-09 SCRAPPED	647079
8228	09/09/2013	424330	Mechanic entered - Eng Cool Coolant Low	added coolant.	647079
8228	09/08/2013	424065	Brake Interlock Re-Install to be performed as per Campaign	Completed	647079
8228	09/07/2013	423465	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed	647079
8228	09/02/2013	423187	Whls & Tyress - Sidewall damage	Scrapped	647079
8228	09/02/2013	423076	Organise Mbenz Recall SM949 to be performed by Whitehorse T	completed	646768
8228	08/30/2013	422835		Safety Inpection Completed	646768
8228	08/30/2013	422835		Tension Wheel Nuts	646768
8228	08/30/2013	422835		Perform & Complete PTSV Bus Safety Inspection safty done	646768
8228	08/30/2013	422885	Elec & Light - Dash lights n/w	check ok	646768
8228	08/30/2013	422885	Elec & Light - Replace centre door step light fault code on	Cleared code light OK	646768
8228	08/30/2013	422885	BUTTERFLY AIR VENT		646768
8228	08/29/2013	422763	Eng Cool - Add coolant	Added	646768
8228	08/26/2013	421972	Mechanic entered - Eng Cool Radiator Cap	replaced coolant cap	645803
8228	08/26/2013	421972	RAD CAP MERC BENZ SIGHT GLASS SIDE		645803
8228	08/19/2013	416802	ANNUAL INSPECTION	Creditor #;GB-ROA001 Road Safety Inspections P/O #:G128240 Receiving #:129902 Date :2013-08-22	645803
8228	08/18/2013	416802	Annual Licence		641219
8228	08/14/2013	420011	Suspension - Offside rear front airbag slightly leaking		644274
8228	08/14/2013	420011	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		644274
8228	08/14/2013	420011	Suspension - Offside rear front airbag slightly leaking		644274
8228	08/14/2013	420080	Engine Leaking oil or some other fluid.	secure coolant pipe.top of engine. road tested ok.	644274
8228	08/13/2013	419394	SEAT BELT LEFT HAND		644274
8228	08/13/2013	419394	Drv entered - Body & Acc Drivers Seat Belt	replaced with new	644274
8228	08/13/2013	417556	Body & Acc - LHS 1st seat cushion torn	removed old made new cushion and fitted to bus	644274
8228	08/13/2013	417556	Body & Acc - Drivers seat backrest faulty	completed	644274
8228	08/13/2013	417556	Body & Acc - Wheel chair ramp - clean	completed	644274
8228	08/13/2013	419384	COMPRESSOR OIL AIR CON		644274
8228	08/13/2013	419384	FILTER DRIER THERMO KING		644274
8228	08/13/2013	419384	AIR CON REFRIDGERANT		644274
8228	08/13/2013	419384	O RING AIR CON		644274
8228	08/09/2013	417556	Vandalism - Clean graffiti - floor seats & side walls	Cleaned	644273
8228	08/09/2013	419394	Drv entered - Body & Acc Drivers Seat Belt		644273
8228	08/09/2013	419394	Drv entered - Body & Acc Drivers Seat Belt		644273
8228	08/09/2013	417556	Body & Acc - LHS 1st seat cushion torn	Servicable	644273
8228	08/09/2013	417556	Body & Acc - paint rear b/bar	Polish	644273
8228	08/09/2013	417556	Body & Acc - Replace driver seat decal	Replaced	644273
8228	08/09/2013	417556	Body & Acc - paint rear b/bar	Polish	644273
8228	08/09/2013	417556	Body & Acc - Polish exterior panels/headers & touch up pain	Polish	644273
8228	08/09/2013	417556	Body & Acc - Clean air condition filter secure vents	Cleaned	644273
8228	08/09/2013	417556	Body & Acc - replace/secure seat cushions - OS 1	Secured	644273
8228	08/09/2013	417556	Body & Acc - Drivers seat - replace cushion	Replaced - 438433	644273
8228	08/09/2013	417556	Body & Acc - Wheel chair ramp - clean		644273
8228	08/09/2013	417556	Body & Acc - Clean back seat - rubbish	Cleaned	644273

8228	08/09/2013	417556	Body & Acc - Drivers seat bottom fabric torn	Replaced	644273
8228	08/09/2013	417556	Body & Acc - secure all lower skirt panels	Secured	644273
8228	08/09/2013	417556	Body & Acc - Paint till stand	Paint	644273
8228	08/09/2013	417556	Body & Acc - replace fleet number on dash - in yellow	Replace	644273
8228	08/09/2013	417556	Body & Acc - Paint exterior mirrors and arms	Paint	644273
8228	08/09/2013	419384		C Service	644273
8228	08/09/2013	419384		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	644273
8228	08/09/2013	419384	Replace all unloader O rings and discharge. Service valve O	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	644273
8228	08/09/2013	419384		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	644273
8228	08/09/2013	419384		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	644273
8228	08/09/2013	419384		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	644273
8228	08/09/2013	419384		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	644273
8228	08/09/2013	419384		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	644273
8228	08/09/2013	419384		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	644273
8228	08/09/2013	419384		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	644273
8228	08/09/2013	419384		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	644273
8228	08/09/2013	419384		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	644273
8228	08/08/2013	418955	Body & Acc - Paint wheels	alloy wheels	643883
8228	08/07/2013	419125	Eng Cool - Add coolant	Added	643996
8228	08/07/2013	418952		Replace Engine Oil Breather Kit	643883
8228	08/07/2013	418952		Grease AC Compressor Clutch Bearing	643883
8228	08/07/2013	418952	ENGINE OIL DELO 400LE 15W40		643883
8228	08/07/2013	418952		Tension Wheel Nuts to Spec	643883
8228	08/07/2013	418952		A Service & Bus Safety Inspection	643883
8228	08/07/2013	418952		D-Service & Bus Safety Inspection	643883
8228	08/07/2013	418952	ENGINE OIL BREATHER KIT 0500LE		643883
8228	08/07/2013	418952	OIL FILTER 1725+0500LE		643883
8228	08/07/2013	418952	AIR FILTER MERC 0500LE		643883
8228	08/07/2013	418952	Fuelled & parked bus	A Service	643883
8228	08/07/2013	418952		A Service	643883
8228	08/07/2013	418952		Grease AC Compressor Clutch Bearing	643883
8228	08/07/2013	418952		Tension Wheel Nuts To OEM Specification	643883
8228	08/07/2013	418952		Clean A/C filter	643883
8228	08/06/2013	418490	FLAT - POS 3 - 11 R22.5 - NEW	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G127874 Receiving #:129245 Date :2013-08-07 REPAIR OR REPLACE WITH NEW	643883
8228	08/06/2013	418964	Eng Cool - Check for coolant leak	Remove floor & checked for leak leak around compressor topped up coolant	643883
8228	08/05/2013	418490	Whls & Tyres - Replace tyre pos 3 - flat	Replaced	642986
8228	07/31/2013	417801	15AMP BLADE FUSE		641683
8228	07/30/2013	417853	Eng Cool - Add coolant	Added	641683
8228	07/30/2013	417556	FREIGHT	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G127463 Receiving #:128849 Date :2013-07-30	641683
8228	07/30/2013	417556	bar	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G127463 Receiving #:128849 Date :2013-07-30	641683
8228	07/30/2013	417556	bush tophat	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G127463 Receiving #:128849 Date :2013-07-30	641683
8228	07/30/2013	417556	bush	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G127463 Receiving #:128849 Date :2013-07-30 8228	641683
8228	07/30/2013	417556	Body & Acc - Drivers seat backrest faulty		641683
8228	07/29/2013	417005	WORN - POS 56 - 11 R22.5 - NE	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G127542 Receiving #:128837 Date :2013-07-30 REPLACE WITH NEW	641219
8228	07/29/2013	417801	Elec & Light - Bus wont start	Jump started	641219
8228	07/26/2013	417005	Whls & Tyres - Replace tyre pos 56 - worn	Replaced	641219
8228	07/26/2013	417095	SWAY BAR DROP ARM REAR 0500LE		641219
8228	07/26/2013	417276	Engine - Steamclean bus	Cleaned	641219
8228	07/26/2013	417276	Body & Acc - Drivers seat back rest needs repair	Repaired	641219
8228	07/25/2013	416542	Assist Alan	RSI Inspection	641219
8228	07/25/2013	416542		Replace angle drive oil	641219
8228	07/25/2013	417071	Annaul Body Inspection	Inspected	641219
8228	07/25/2013	417095	Whls & Tyres - Both RHR tyres worn	replaced	641219
8228	07/25/2013	417095	Suspension - RHR sway bar link worn	Replaced	641219
8228	07/25/2013	417095	Eng Cool - Coolant leak from LH side of engine	repaired	641219
8228	07/25/2013	416904	PARK BRAKE VALVE 0500LE		641219
8228	07/24/2013	416542		RSI Inspection	641219
8228	07/24/2013	416542		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	641219
8228	07/24/2013	416542		Check oil level in transmission - top up if required	641219
8228	07/24/2013	416542		Check and clean cartridge in dry type air cleaner	641219
8228	07/24/2013	416542		Replace pre and main fuel filters	641219
8228	07/24/2013	416542		Replace air dryer cansiter clean silence and drain reservoir	641219
8228	07/24/2013	416542		Test coolant level - top up if required to equate to 37C frost protection	641219
8228	07/24/2013	416542		Inspect radiator and charge air cooler for dirt - clean	641219
8228	07/24/2013	416542	FUEL FILTER 0500LE		641219
8228	07/24/2013	416542	AIR DRYER MERCEDES 0500		641219
8228	07/24/2013	416542	FUEL FILTER MERC 0500LE		641219
8228	07/24/2013	416542	POWER STEERING FILTER VOLVO		641219
8228	07/24/2013	416542		Replace power steering filter and check level (Replace oil if required)	641219
8228	07/24/2013	416608	AMBER REFLECTOR		641219
8228	07/24/2013	416842	Eng Cool - Add coolant	Added	641219
8228	07/24/2013	416904	Brakes - Replace park brake valve	Replaced	641219
8228	07/24/2013	416541	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		641219
8228	07/24/2013	416541	HALDEX COIL BASE OIL SEPERATOR	Base	641219
8228	07/24/2013	416541		Re-kit Air Cyclone Separator	641219
8228	07/24/2013	416541	HALDEX COIL KIT 0500LE	Coil Kit	641219
8228	07/24/2013	416541	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	641219
8228	07/24/2013	416541	DRAIN VALVE KIT BOTTOM	Valve Kit	641219
8228	07/23/2013	416608	Elec & Light - Replace missing NSF amber reflector	Replaced	641219
8228	07/23/2013	416626	Eng Cool - Add coolant	Added	641219
8228	07/23/2013	416358	CLUTCH PEDAL RUBBER 16-240		640721
8228	07/22/2013	416479	Cool & AC Sys. Leak	Repaired leaking heater hose	640721
8228	07/22/2013	416375	Eng Cool - Add coolant	Added	640721
8228	07/22/2013	416358	Brakes - Replace brake pedal rubber	Replaced	640721
8228	07/16/2013	415588	Wipers & Washers - Wipers sticking	Adjusted	639007
8228	07/16/2013	415281	VALVEBOTTOM DOOR SWITCH+REG/GREEN		638660
8228	07/16/2013	415281	0500 COOLANT LOW LEVEL SENDER		638660
8228	07/15/2013	415098		Perform & Complete PTVS Bus Safety Inspection	637865
8228	07/15/2013	415098		Tension Wheel Nuts	637865
8228	07/15/2013	415281	Drv entered - Heat & Demist Other	repaired wiring on boost pump fuel & parked	638660
8228	07/15/2013	415281	Drv entered - Heat & Demist Other	Checked boost pump wire broken at connector 1	638660
8228	07/15/2013	414995	Drv entered - Other	??????	637865
8228	07/15/2013	415281	Ops Entered - Fault - Elec & Light W'rning Light - Route:	Fault code for 5443 rectified	638660

8228	07/15/2013	415281	Eng Cool - cOOLANT LEVEL SENSOR FAULTY	rEPLACED FILLED COOLANT cleared f/code emer exit valve changed	638660
8228	07/15/2013	415281	Eng Cool Leaking	Checked OK	638660
8228	07/15/2013	415281	Eng Cool Leaking	S/wash top up coolant checked coolant leak & r/tested	638660
8228	07/05/2013	413600	SIDEWALL DAMAGE	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G126646 Receiving #:127935 Date :2013-07-09 SCRAPPED	636805
8228	07/05/2013	413600	Whls & Tyres - Sidewall damage	Scrapped	635799
8228	07/04/2013	413687	Wipers & Washers - Wipers are sticking	Adjusted & tightened	635799
8228	07/02/2013	412679	WORN - POS 34 - 11 R22.5 - NE	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G126428 Receiving #:127741 Date :2013-07-05 REPLACE WITH NEW	635799
8228	07/01/2013	412679	Whls & Tyres - Replace tyre pos 34 - worn	Replaced	634264
8228	07/01/2013	411176	FIRTREE CLIP		634264
8228	06/28/2013	412455	Whls & Tyres - Replace tyres 34	Replaced	633841
8228	06/28/2013	412455	SWAY BAR LINK ROD LEFT		633841
8228	06/28/2013	412455	Suspension - Front sway bar link worn	Replaced (with wayne)	633841
8228	06/28/2013	411176	Elec & Light - Replace interior LED lights	Replaced	630205
8228	06/28/2013	412456		A Service	633833
8228	06/28/2013	412456		Clean A/C filter	633833
8228	06/28/2013	412456		Grease AC Compressor Clutch Bearing	633833
8228	06/28/2013	412456		Tension Wheel Nuts To OEM Specification	633833
8228	06/20/2013	411176	LED INTERIOR ROOF LIGHT	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G125955 Receiving #:126945 Date :2013-06-20	630205
8228	06/19/2013	410978	Adjust rear door sensors	Adjusted	630205
8228	06/19/2013	410978	Elec & Light - alt bushes worn	Removed and fitted new bushes	630205
8228	06/18/2013	410668		Perform & Complete PTSV Bus Safety Inspection	630205
8228	06/18/2013	410668		Tension Wheel Nuts	630205
8228	06/18/2013	410668	COVER BUS STOPPING SIGN		630205
8228	06/18/2013	410668		Perform & Complete PTSV Bus Safety Inspection	630205
8228	06/18/2013	410619	Eng Cool - Coolant leak	Tulla replaced hose and clamps 11/06/13	630205
8228	06/12/2013	409991	Ops Entered - Fault - Engine Leaking - Route: 902 - Greens	Check for leaks no obvious leak found	628605
8228	06/12/2013	409991	Body & Acc Drivers Seat Back Rest Spring broken	Temp repair drivers seat back rest	628605
8228	05/24/2013	407295	Eng Cool - Add coolant	Added	622308
8228	05/21/2013	406189	COOLANT PIPE	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G124582 Receiving #:125260 Date :2013-05-21	621809
8228	05/21/2013	406189	EXHAUST BRAKE SOLENOID 0500		621809
8228	05/20/2013	406189	A/C BELT 0500 BENZ		621117
8228	05/20/2013	406189	Air Cond - Replace a/c belt	Replaced	621117
8228	05/20/2013	406189	Gearbox - G/box coolant hose leaking	Water pipe topped up coolant s/cleaned	621117
8228	05/20/2013	406189	HOSE ENG TO G/BOX COOLER MERC 0500LE		621117
8228	05/20/2013	406189	Gearbox - G/box coolant hose leaking	Replaced hose	621117
8228	05/20/2013	406189	Elec & Light - Battery bracket broken	Fabricated new bracket & secured batteries	621117
8228	05/20/2013	406189	Brakes - Front Discs Worn	Replaced front rotors pads	621117
8228	05/20/2013	406189	DISC PAD SET SCANIA MB0500		621117
8228	05/20/2013	406189	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		621117
8228	05/20/2013	406189	Brakes - Front Discs Worn	Fitted new front discs & pads	621117
8228	05/20/2013	406189	EXHAUST BRAKE SOLENOID 0500		621117
8228	05/20/2013	406189	Air System - Air leak near air dryer	Fitted new exhaust brake air solenoid valve	621117
8228	05/17/2013	406040		Perform & Complete PTSV Bus Safety Inspection	621117
8228	05/17/2013	406040		Tension Wheel Nuts	621117
8228	05/17/2013	406040		Perform & Complete PTSV Bus Safety Inspection	621117
8228	05/17/2013	406229	Elec & Light - cable on battery broken	Changed terminal	621117
8228	05/10/2013	394434	Suspension - Replace OSR stabilizer link arm ball joint	Checked OK	598341
8228	05/01/2013	403466	SENSITIVE EDGE DOOR SWITCH		616457
8228	04/30/2013	403466	Elec & Light - Replace sensitive edge switch	Replaced	616457
8228	04/29/2013	403256	Passenger Doors - Adjust rear door sensors	Adjusted	616426
8228	04/29/2013	403291	Gearbox - Replace g/box accumalator solenoide	Replaced	616426
8228	04/29/2013	403252	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Audited	616426
8228	04/29/2013	402880	SOLENOID VALVE ZFAUTO	Creditor #:MUL001 MULTISPARES LTD P/O #:G123470 Receiving #:124236 Date :2013-04-29	616242
8228	04/29/2013	402880		A Service	616242
8228	04/29/2013	402880		Clean A/C filter	616242
8228	04/29/2013	402880		A Service	616242
8228	04/29/2013	402880		Grease AC Compressor Clutch Bearing	616242
8228	04/29/2013	402880		Tension Wheel Nuts To OEM Specification	616242
8228	04/27/2013	403089	Air System - check for air leak	R/tested OK	615824
8228	04/18/2013	401926	Engine - Add hydraulic oil	Added	613546
8228	04/18/2013	401767	FIRE EXTINGUISHER 2.5KG		613288
8228	04/17/2013	401596		Perform & Complete PTSV Bus Safety Inspection	612678
8228	04/17/2013	401596		Tension Wheel Nuts	612678
8228	04/17/2013	401596		Perform & Complete PTSV Bus Safety Inspection	612678
8228	04/17/2013	401767	Body & Acc - Replace fire extinguisher	Replaced	613288
8228	04/16/2013	401390	LED SIDE INDICATOR LAMP amber		612678
8228	04/15/2013	401390	Elec & Light - Replace LED clearance light	Replaced	612678
8228	03/19/2013	396811	RAD CAP MERC BENZ SIGHT GLASS SIDE		605572
8228	03/14/2013	396811	HOSE ENG TO G/BOX COOLER MERC 0500LE		604040
8228	03/14/2013	397133	Eng Cool low	Top up and road tested OK	604249
8228	03/13/2013	396747		Perform & Complete PTSV Bus Safety Inspection	603529
8228	03/13/2013	396747		Tension Wheel Nuts	603529
8228	03/13/2013	396747		Perform & Complete PTSV Bus Safety Inspection	603529
8228	03/13/2013	396546	GLOBE HIGH BEAM 24V70W H1		603529
8228	03/13/2013	396811	Eng Cool g.box cooling pipe leaks	Replaced pipe and hose	603529
8228	03/13/2013	396811	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		603529
8228	03/13/2013	396811	Eng Cool g.box cooling pipe leaks	Replaced pipe and hose assist Subu	603529
8228	03/13/2013	396742		Bus Safety Inspection	603529
8228	03/13/2013	396742	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	603529
8228	03/13/2013	396742	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	603529
8228	03/13/2013	396742		Service T - Replace Transmission Oil & Filter	603529
8228	03/08/2013	396546	Elec & Light head light out	Replace globe	602686
8228	03/01/2013	395231	Elec & Light - RH side indicator n/w	Replaced by Tulla 25/02/13	599690
8228	03/01/2013	395238	Eng Cool - Water leak	Tulla replaced header tank topped up coolant no signs of leaking	599690
8228	02/27/2013	394638	SNAP ON SILENCER A/DRYER		598815
8228	02/26/2013	394434	Complete Campaign 16/12 as required	Alloy wheels	598341
8228	02/26/2013	394434	Eng Cool - Coolant leak from g/box cooling line	Repaired	598341
8228	02/26/2013	394638	Air System - Air leak near air dryer pipe	Repaired air leak	598341
8228	02/26/2013	394638	FITTING JOINER 8MM		598341
8228	02/26/2013	394638	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		598341
8228	02/26/2013	394637	ENGINE OIL DELO 400LE 15W40		598341
8228	02/26/2013	394637	AIR FILTER MERC 0500LE		598341
8228	02/26/2013	394637		Grease AC Compressor Clutch Bearing	598341

8228	02/26/2013	394637	Tension Wheel Nuts to Spec	598341
8228	02/26/2013	394637	A Service & Bus Safety Inspection	598341
8228	02/26/2013	394637	Replace Engine Oil Breather Kit	598341
8228	02/26/2013	394637	ENGINE OIL BREATHER KIT 0500LE	598341
8228	02/26/2013	394637	OIL FILTER 1725+0500LE	598341
8228	02/26/2013	394637	D-Service & Bus Safety Inspection	598341
8228	02/26/2013	394560	Coil Kit	598341
8228	02/26/2013	394560	Re-kit Air Cyclone Separator	598341
8228	02/26/2013	394560	Valve Kit	598341
8228	02/26/2013	394560	Base	598341
8228	02/26/2013	394560	Condenser Valve Kit.	598341
8228	02/26/2013	394560	Re-kit Air Cyclone Separator	598341
8228	02/26/2013	394637	A Service	598341
8228	02/26/2013	394637	Clean A/C filter	598341
8228	02/26/2013	394637	Grease AC Compressor Clutch Bearing	598341
8228	02/26/2013	394637	Tension Wheel Nuts To OEM Specification	598341
8228	02/25/2013	394434	Creditor #:MUL001 MULTISPARES LTD P/O #:G120768 Receiving #:121486 Date :2013-02-25	598341
8228	02/25/2013	394434	Creditor #:MUL001 MULTISPARES LTD P/O #:G120768 Receiving #:121486 Date :2013-02-25	598341
8228	02/12/2013	392717	Perform & Complete PTVS Bus Safety Inspection	594187
8228	02/12/2013	392717	Tension Wheel Nuts	594187
8228	02/12/2013	392717	Perform & Complete PTVS Bus Safety Inspection	594187
8228	02/11/2013	389947	Creditor #:BEA001 BEAUREPAIRES P/O #:G119340 Receiving #:120823 Date :2013-02-11 SCRAP TYRE	594187
8228	02/11/2013	389929	Creditor #:BEA001 BEAUREPAIRES P/O #:G119340 Receiving #:120823 Date :2013-02-11 SCRAP TYRE	594187
8228	02/05/2013	390572	Creditor #:BEA001 BEAUREPAIRES P/O #:G119492 Receiving #:120566 Date :2013-02-05 REPLACE WITH NEW	591700
8228	01/30/2013	390538		589928
8228	01/29/2013	390835	Whls & Tyres - Replace tyres 56	589928
8228	01/29/2013	390572	Whls & Tyres - Replace tyre pos 56 - worn	589160
8228	01/29/2013	390538	Eng Cool - Add coolant	589928
8228	01/29/2013	390538	Body & Acc drivers compartment door has a broken latch.	589928
8228	01/22/2013	389929	Whls & Tyres - side wall damage	587562
8228	01/22/2013	389947	Whls & Tyres - side wall damage	587562
8228	01/21/2013	389627	L.E.D SIDE MARKER PEREI RED/AMBER	586811
8228	01/19/2013	389509	ROCKER COVER GASKET 0500LE	586811
8228	01/19/2013	389509		586811
8228	01/19/2013	389712	Eng Cool - Clean radiator	586811
8228	01/18/2013	389607	Air Cond - Clean a/c filters	587095
8228	01/18/2013	389627	Elec & Light - Replace NSR LED clearance light	587095
8228	01/18/2013	389627	Eng Cool - Add coolant	587095
8228	01/17/2013	389168	GLOBE H1 24V 70W	586418
8228	01/17/2013	389335	Eng Cool - Add hydraulic oil	586811
8228	01/16/2013	389168	Elec & Light - Replace OS headlight	586418
8228	01/10/2013	388255		585219
8228	01/10/2013	388255	Tension Wheel Nuts	585219
8228	01/10/2013	388255	Perform & Complete PTVS Bus Safety Inspection	585219
8228	01/10/2013	388250	Eng Cool - Add coolant	585219
8228	01/07/2013	387728	Whls & Tyres - NSF tyre damage	584556
8228	01/07/2013	387745	Eng Cool - Clean radiator	584556
8228	01/07/2013	387711	Eng Cool - Add coolant	584556
8228	01/07/2013	387645	Clean A/C filter	584546
8228	01/07/2013	387645	A Service	584546
8228	01/07/2013	387645	Tension Wheel Nuts To OEM Specification	584546
8228	01/07/2013	387645	A Service	584546
8228	01/07/2013	387645	Grease AC Compressor Clutch Bearing	584546
8228	12/18/2012	385476	checked ok - 18/12/12	577979
8228	12/18/2012	385568	added	578211
8228	12/18/2012	385258		577979
8228	12/17/2012	370822	Eng Cool - Radiator fan needs replacing	547105
8228	12/17/2012	385258	Body & Acc Passanger hand pole braket missing	577940
8228	12/12/2012	384265	SIDEWALL - POS 1 - 11 R22.5 -	576740
8228	12/12/2012	384684	Body & Acc - Replace mirror	576403
8228	12/11/2012	384692	Eng Cool - Add coolant	576403
8228	12/10/2012	384546	Wipers & Washers - Replace OS wiper jet	575951
8228	12/10/2012	384265	Whls & Tyres - Replace tyre pos 1 - sidewall	575627
8228	12/09/2012	384495	Whls & Tyres - Replace tyre NSF	575627
8228	12/06/2012	383972		574898
8228	12/06/2012	383972	Tension Wheel Nuts	574898
8228	12/06/2012	383972	Perform & Complete PTVS Bus Safety Inspection	574898
8228	12/06/2012	384086	Eng Cool - Add coolant	574898
8228	12/04/2012	383783	Body & Acc - Secure loose mirror	574898
8228	12/03/2012	383592	Body & Acc - Replace rear damaged seat	573728
8228	11/30/2012	383066	RAD CAP MERC BENZ SIGHT GLASS SIDE	571998
8228	11/29/2012	383066	Eng Cool - Replace radiator cap	571998
8228	11/28/2012	382959	Eng Cool - Add coolant	571592
8228	11/27/2012	382756	Eng Cool - Add coolant	571311
8228	11/16/2012	381293	Air Cond - Clean a/c filters	567690
8228	11/15/2012	380647	WORN - POS 34 - 11 R22.5 - NE	567408
8228	11/15/2012	381027	Air System - Air leak	567408
8228	11/14/2012	380519	Gearbox - Transmission cooling pipe leaking	567231
8228	11/14/2012	380519	A6345011726 WATER PIPE	567231
8228	11/14/2012	380951	BATTERY 12V 190 AMP 1000CCA (+ on right side)	567231
8228	11/13/2012	380942	Whls & Tyres - Replace 34 tyres	567134
8228	11/13/2012	380647	Whls & Tyres - Replace tyre pos 34 - worn	567133
8228	11/13/2012	380951	Elec & Light - Replace batteries	567134
8228	11/13/2012	380204	COMPRESSOR OIL AIR CON	567133
8228	11/13/2012	380204	FILTER DRIER THERMO KING	567133
8228	11/13/2012	380204	AIR CON REFRIDGERANT	567133
8228	11/13/2012	380204	Service valve cap	567133
8228	11/12/2012	380519	Air Cond - AC blower fan noisy	567124
8228	11/12/2012	380519	Gearbox - Transmission cooling pipe leaking	567124
8228	11/12/2012	380519	Elec & Light - Fuel gauge defective full but shows 1/2 tank	567124
8228	11/12/2012	380519	Comm Equip Not Opertating. On wrong channel needs to be on	567124
8228	11/10/2012	380549	Elec & Light - Bus wont start	567124
8228	11/09/2012	380293	Tension Wheel Nuts	566263

8228	11/09/2012	380293	Perform & Complete PTSV Bus Safety Inspection	566263
8228	11/09/2012	380204	B Service	566263
8228	11/09/2012	380204	Replace filter drier	566263
8228	11/09/2012	380204	Replace compressor oil	566263
8228	11/09/2012	380204	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	566263
8228	11/09/2012	380204	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	566263
8228	11/09/2012	380204	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	566263
8228	11/09/2012	380204	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	566263
8228	11/09/2012	380204	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	566263
8228	11/09/2012	380204	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	566263
8228	11/09/2012	380204	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	566263
8228	11/09/2012	380204	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	566263
8228	11/09/2012	380204	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	566263
8228	11/09/2012	380204	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	566263
8228	11/09/2012	380204	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	566263
8228	11/09/2012	380292	A Service	566263
8228	11/09/2012	380292	Clean A/C filter	566263
8228	11/09/2012	380292	Grease AC Compressor Clutch Bearing	566263
8228	11/09/2012	380292	Tension Wheel Nuts To OEM Specification	566263
8228	11/08/2012	380128	BLADE WIPER 1MTR	566263
8228	11/08/2012	380074	Elec & Light - Bus wont start	566263
8228	11/08/2012	379858	Eng Cool cooling tank cap missing	566263
8228	11/07/2012	380128	Wipers & Washers - Replace os w/screen wiper blade	566715
8228	11/07/2012	379723	GLOBE INST 24V 2W	566263
8228	11/07/2012	379858	RADIATOR CAP	566715
8228	11/03/2012	379843	Eng Cool - Add coolant	565807
8228	11/03/2012	379531	Cannot change to channel 3. Stuck on channel 1	565069
8228	11/02/2012	379723	Elec & Light - Replace dash light	565354
8228	10/31/2012	379241	Eng Cool - Add coolant	564614
8228	10/27/2012	377971	Security - Test and repair security camera system	561445
8228	10/24/2012	378097	LED FRONT POSITION MARKER LIGHT	561445
8228	10/24/2012	377283	Security - Test and repair security camera system	561445
8228	10/23/2012	378097	Elec & Light - Replace both No plate LEDS	562523
8228	10/23/2012	377971	Direct Purchase - ELECTRICAL	562523
8228	10/22/2012	377845	Elec & Light - Bus wont start	562133
8228	10/22/2012	377871	Eng Cool - Add coolant	562133
8228	10/19/2012	377493	CIRCUIT PROTECTION VALVE	561744
8228	10/19/2012	377493	Air System - Replace 6way protection valve	561625
8228	10/15/2012	376840	Eng Cool - Add coolant	560669
8228	10/11/2012	375949	CYCLONE PACK (SEPARATOR) MERC COMPLETE UNIT	558602
8228	10/10/2012	375947	Perform & Complete PTSV Bus Safety Inspection	558546
8228	10/10/2012	375947	Tension Wheel Nuts	558546
8228	10/10/2012	375947	Perform & Complete PTSV Bus Safety Inspection	558546
8228	10/10/2012	376011	Repair / replace air hose as s	558546
8228	10/10/2012	376011	Air System Leaking - air dryer hose leaking	558546
8228	10/10/2012	375949	Re-kit Air Cyclone Separator	558546
8228	10/10/2012	375949	Valve Kit	558546
8228	10/10/2012	375949	Coil Kit	558546
8228	10/10/2012	375949	Condenser Valve Kit.	558546
8228	10/10/2012	375949	Re-kit Air Cyclone Separator	558546
8228	10/10/2012	375949	Base	558546
8228	09/23/2012	373746	Jump started	551996
8228	09/21/2012	373486	Replace Engine Oil Breather Kit	551879
8228	09/21/2012	373486	ENGINE OIL BREATHER KIT 0500LE	551879
8228	09/21/2012	373486	AIR FILTER MERC 0500LE	551879
8228	09/21/2012	373486	OIL FILTER 1725+0500LE	551879
8228	09/21/2012	373486	ENGINE OIL DELO 400LE 15W40	551879
8228	09/21/2012	373486	Tension Wheel Nuts to Spec	551879
8228	09/21/2012	373486	A Service & Bus Safety Inspection	551879
8228	09/21/2012	373486	D-Service & Bus Safety Inspection	551879
8228	09/21/2012	373486	A Service	551879
8228	09/21/2012	373486	Grease AC Compressor Clutch Bearing	551879
8228	09/21/2012	373486	Tension Wheel Nuts To OEM Specification	551879
8228	09/21/2012	373486	Clean A/C filter	551879
8228	09/20/2012	369008	ROAD SAFETY INSPECTIONS	551450
8228	09/20/2012	373077	REPLACE 8MM SAFETY FILM TO DRI	551450
8228	09/19/2012	373077	Body & Acc - Replace 8mm safety filmm to drivers window	550977
8228	09/18/2012	372995	Comm Equip - Two way radio marked Spare Smart Bus but doe	550599
8228	09/18/2012	372995	Comm Equip Controls: Cannot get two way radio on to Chann	550599
8228	09/17/2012	372873	Elec & Light - bus wont start	550599
8228	09/16/2012	369008	Annual Licence	544446
8228	09/16/2012	372751	Elec & Light - bus wont start	544446
8228	09/16/2012	372756	Body & Acc - Replace fire extinguisher	544446
8228	09/15/2012	372540	Ops Entered - Fault - Comm Equip Poor Reception - Route: 9	549878
8228	09/15/2012	372540	Ops Entered - Fault - Brakes Park Brake Light On - Route:	549878
8228	09/13/2012	372399	Elec & Light - SECURE LOOSE DOOR CONTROL PUSH BUTTONS	549878
8228	09/12/2012	372076	done at RSI - 16/09/2012	549179
8228	09/12/2012	372076	Perform & Complete PTSV Bus Safety Inspection	549179
8228	09/12/2012	372076	Tension Wheel Nuts	549179
8228	09/05/2012	371382	Jump started	547638
8228	09/04/2012	371200	Inspected	547222
8228	09/04/2012	371147	Investigation/Inspection - Check bus over sitting out front	547222
8228	09/03/2012	370823	POWER STEERING FILTER VOLVO	547105
8228	09/03/2012	370823	AIR DRYER CANISTER VOLVO+ NL202	547105
8228	09/03/2012	370823	FUEL FILTER 0500LE	547105
8228	09/03/2012	370823	FUEL FILTER MERC 0500LE	547105
8228	09/03/2012	370823	Replace power steering filter and check level (Replace oil if required)	547105
8228	09/03/2012	370823	Test coolant level - top up if required to equate to 37C frost protection	547105
8228	09/03/2012	370823	Replace angle drive oil	547105
8228	09/03/2012	370823	Replace air dryer cansiter clean silence and drain reservoir	547105
8228	09/03/2012	370823	Replace pre and main fuel filters	547105
8228	09/03/2012	370823	Check and clean cartridge in dry type air cleaner	547105

8228	09/03/2012	370823	Check oil level in transmission - top up if required	547105
8228	09/03/2012	370823	Inspect radiator and charge air cooler for dirt - clean	547105
8228	09/03/2012	370823	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	547105
8228	09/03/2012	370823	Replace final drive oil	547105
8228	09/03/2012	370823	Rear Axle Lube	547105
8228	09/03/2012	370962	Added	547105
8228	09/03/2012	370822	Imported Service History	547105
8228	09/03/2012	370822	Eng Cool - Radiator fan needs replacing	547105
8228	09/03/2012	0	Imported Service History	547105
8228	09/01/2012	370855	Investigation/Inspection - Check out bus sitting out front	547105
8228	08/27/2012	369951	Elec & Light - Bus wont start	545345
8228	08/27/2012	369948	Eng Cool - Add coolant	545345
8228	08/07/2012	366797	WORN - POS 56 - 11 R22.5 - NE	539979
8228	08/06/2012	366784	Perform & Complete PTVS Bus Safety Inspection	539868
8228	08/06/2012	366784	Tension Wheel Nuts	539868
8228	08/06/2012	366784	Perform & Complete PTVS Bus Safety Inspection	539868
8228	08/06/2012	366797	Replaced	539868
8228	08/06/2012	366818	replace 5 & 6	539868
8228	08/05/2012	366902	Jump started	539868
8228	07/30/2012	366100	Jump started	537723
8228	07/30/2012	365900	Tension Wheel Nuts To OEM Specification	537499
8228	07/30/2012	365900	Grease AC Compressor Clutch Bearing	537499
8228	07/30/2012	365900	Clean A/C filter	537499
8228	07/30/2012	365900	A Service	537499
8228	07/30/2012	365900	A Service	537499
8228	07/30/2012	365900	Perform & Complete PTVS Bus Safety Inspection	537499
8228	07/06/2012	362584	Tension Wheel Nuts	530158
8228	07/06/2012	362584		530158
8228	07/06/2012	362584	CRANK DRIVE BELT 0500LE MERC	530158
8228	07/06/2012	362795	Elec & Light - Reverse beeper n/w	531497
8228	07/01/2012	361821	Elec & Light - Bus wont start	528774
8228	06/29/2012	361591	GLOBE INDICATOR 24V-18W SINGLE CONTACT	528308
8228	06/28/2012	361591	Elec & Light - Replace NS indicator globe	528308
8228	06/28/2012	352479	Repalce decals	528308
8228	06/27/2012	361207	A/C BELT 0500 BENZ	527673
8228	06/27/2012	361207	BELT BOTTOM ALTERNATOR MERC 0500LE	527673
8228	06/27/2012	352584	Direct Purchase - BODYWORK	527853
8228	06/26/2012	361207	Engine - Replace belts	527673
8228	06/26/2012	360713	BOOSTER- A634420021801	527673
8228	06/25/2012	360683	Body & Acc - Fit Give way decal	527161
8228	06/25/2012	360713	Brakes - When idling air pressure gauges are in green - ok	527161
8228	06/25/2012	360713	Brakes - When idling air pressure gauges are in green - ok	527161
8228	06/23/2012	360855	Drv entered - Comm Equip Not Receiving	527161
8228	06/22/2012	360713	Brakes - When idling air pressure gauges are in green - ok	527161
8228	06/08/2012	356394	MODULATION VALVE 0500le	524306
8228	06/08/2012	356394	wear sensor	524306
8228	06/06/2012	353560	AMBER REFLECTOR SIDE MOUNT	523115
8228	06/05/2012	356394	TOW FROM OAKLEIGH STN TO GBS	522175
8228	06/04/2012	357716	REFLECTOR RED	522175
8228	06/04/2012	357961	Body & Acc - refit w/arch brush	522175
8228	06/01/2012	357440		521650
8228	06/01/2012	357440		521650
8228	06/01/2012	357723	Engine - Steamclean bus	521729
8228	06/01/2012	357716	Elec & Light - Replace LH rear reflector	521729
8228	06/01/2012	357718	Eng Cool - Radiator fan bearing need to check next service	521729
8228	06/01/2012	357718	Comm Equip - 2way radio n/w	521729
8228	06/01/2012	357718	Body & Acc - fire extinguisher - security (Checked on 23/02	521729
8228	06/01/2012	357437		521650
8228	06/01/2012	357437		521650
8228	06/01/2012	357437		521650
8228	05/31/2012	357541	Elec & Light - Brakes	521650
8228	05/31/2012	356974	Brakes Replace rear brake rottors and pads	521650
8228	05/31/2012	356974	BRAKE CALIPER TAPPET KIT 0500[A0004204982)	521650
8228	05/31/2012	356974	Brakes Replace rear brake rottors and pads	521650
8228	05/31/2012	356974	DISC PAD SET SCANIA MB0500	521643
8228	05/30/2012	356974	DISC PAD SET SCANIA MB0500	521650
8228	05/30/2012	356974	Brakes Replace rear brake rottors and pads	521650
8228	05/30/2012	356974	Brakes Replace rear brake rottors and pads	521650
8228	05/30/2012	356974	Brakes Replace rear brake rottors and pads	521650
8228	05/30/2012	356394	a9403501035 hub seal kit	521650
8228	05/29/2012	356974	Brakes Replace rear brake rottors and pads	521643
8228	05/29/2012	356974	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500	521643
8228	05/29/2012	356939	Brakes Replace rear rottors and pads	521643
8228	05/29/2012	356974	Brakes Replace rear brake rottors and pads	521643
8228	05/25/2012	356394	Brakes Holding On	521643
8228	05/25/2012	356394	Brakes Holding On	521643
8228	05/15/2012	355081	Elec & Light Secured O/S indicator lense	518840
8228	05/14/2012	354433	BALD - New - 11.00R 22.5 alloy	518462
8228	05/14/2012	354631	Air System Low Air Pressure	517792
8228	05/11/2012	354433	Whls & Tyres - Bald pos 2	517792
8228	05/10/2012	354480	Whls & Tyres Replace O/S/front tyre	517792
8228	05/07/2012	353607		515177
8228	05/07/2012	353607	CYCLONE CONDENSER VALVE KIT	515177
8228	05/07/2012	353607	HALDEX COIL BASE OIL SEPERATOR	515177
8228	05/06/2012	353826	Elec & Light O/S/F indicator U/S	516391
8228	05/06/2012	352584	Ventura decals to be supplied fitted to SmartBus	515177
8228	05/03/2012	352479	Accident - Repair NS rear skirt panel NS no 7 panel paint	515177
8228	05/03/2012	352479	Accident Damaged # 35185 R/R : o/s. lower body panels No3	515177
8228	05/03/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	515177
8228	05/03/2012	352479	Accident Damaged # 35185 R/R : o/s. lower body panels No3	515177
8228	05/02/2012	353560	Accident Damaged # 35148 R/R. o/s/r. clearance light ~ I.e.	515177
8228	05/02/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	515177

8228	05/02/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	Assisted	515177
8228	05/01/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	Painted panels front OS & NS headlight surrounds centre	515177
8228	05/01/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	Assembled front bar headlight surrounds centre panel make NS No 6 fuel panel	515177
8228	04/30/2012	352928	Vandalism - Clean graffiti - floor seats & side walls (Ch	Cleaned as best as possible	515177
8228	04/30/2012	352928	Body & Acc - Paint exterior mirrors and arms (Checked on 2	Painted	515177
8228	04/30/2012	352928	Body & Acc - Replace Do Not Overtake decal - NSR corner b/b	Replaced with new	515177
8228	04/30/2012	352928	Body & Acc - replace emergency exit decals with safety hamm	Replaced with new	515177
8228	04/30/2012	352928	Body & Acc - Replace Licensed to carry (No) seat (No) adult	Replaced rear inside	515177
8228	04/30/2012	352928	Body & Acc - Replace interior decals - no Smoking (Checked	Replaced with new	515177
8228	04/30/2012	352928	Body & Acc - Polish front bumper bar (Checked on 23/02/12	Removed & painted	515177
8228	04/30/2012	352470	Air System loosing air	Removed air dryer cleaned inside & rekitted	515177
8228	04/30/2012	352470	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		515177
8228	04/30/2012	352470	AIR DRYER CANISTER VOLVO+ NL202		515177
8228	04/30/2012	352470	Air System loosing air	Checked and found air leak from air dryer	515177
8228	04/30/2012	352479	Ops Entered - Accident - Other Vehicle Failed to Give Way -	Painted front bar	515177
8228	04/20/2012	351321		Perform & Complete PTSV Bus Safety Inspection	513484
8228	04/20/2012	351321		Perform & Complete PTSV Bus Safety Inspection	513484
8228	04/20/2012	351321		Tension Wheel Nuts	513484
8228	04/20/2012	351551	Eng Cool - Coolant leak	Tightened hoses	513635
8228	04/17/2012	350784	Body & Acc - Interior panel over front door is loose	Replaced all missing screws from overhead panel at front door	512649
8228	04/13/2012	349808	SIDEWALL - POS 1 - 11R 22.5 -	Creditor #:BEA001 BEAUREPAIRES P/O #:G106617 Receiving #:107135 Date :2012-04-13 REPLACE WITH NEW	510684
8228	04/12/2012	350101	A/CON PULLEY BELT B55 17X1470MM B7RLE		510240
8228	04/12/2012	350101	L.E.D SIDE MARKER PEREI RED/AMBER		510240
8228	04/11/2012	350100	Whls & Tyres - Replace tyre 1	Replaced & tensioned w/nuts	510240
8228	04/11/2012	349808	Whls & Tyres - Replace tyre pos 1 - sidewall	Replaced	510077
8228	04/11/2012	350101	Elec & Light - Replace OS clearance light globe	Replaced	510240
8228	03/30/2012	348862	Breakdown - Springvale Rd - OUT 11.00 am BACK 12.30 pm - Ai	Van 619. Temp repair & returned to depot adjusted air dryer changed air line O ring kit r/tested bus OK	507237
8228	03/27/2012	347753	Direct Purchase - MECHANICAL		506272
8228	03/27/2012	347886	A/C BELT 0500 BENZ		506272
8228	03/27/2012	348317	Eng Cool - Add coolant	Added	506452
8228	03/24/2012	347753		Perform & Complete PTSV Bus Safety Inspection	505254
8228	03/24/2012	347753		Tension Wheel Nuts	505254
8228	03/24/2012	347886	Engine - Replace rear main belt	Replaced	505254
8228	03/24/2012	347754		D-Service & Bus Safety Inspection	505254
8228	03/24/2012	347754		A Service & Bus Safety Inspection	505254
8228	03/24/2012	347754		Tension Wheel Nuts to Spec	505254
8228	03/24/2012	347754	ENGINE OIL DELO 400LE 15W40		505254
8228	03/24/2012	347754	OIL FILTER 1725+0500LE		505254
8228	03/24/2012	347754	AIR FILTER MERC 0500LE		505254
8228	03/24/2012	347754		Grease AC Compressor Clutch Bearing	505254
8228	03/24/2012	347754	ENGINE OIL BREATHER KIT 0500LE		505254
8228	03/24/2012	347754		Replace Engine Oil Breather Kit	505254
8228	03/24/2012	347754		Tension Wheel Nuts To OEM Specification	505254
8228	03/24/2012	347754		Grease AC Compressor Clutch Bearing	505254
8228	03/24/2012	347754		Clean A/C filter	505254
8228	03/24/2012	347754		A Service	505254
8228	03/23/2012	347370	BALD - New 11.00R 22.5 alloy -	Creditor #:BEA001 BEAUREPAIRES P/O #:G105874 Receiving #:106424 Date :2012-03-23 Replace with new tyre	505254
8228	03/22/2012	347370	Whls & Tyres - Replace tyre pos 34 - bald	Replaced	505022
8228	03/21/2012	347498	Whls & Tyres - Replace NS rear tyres	Replaced	505022
8228	03/21/2012	346563	Random Vehicle Audit	Inspected	502607
8228	03/21/2012	346564		Service T - Replace Transmission Oil & Filter	502607
8228	03/21/2012	346564		Bus Safety Inspection	502607
8228	03/17/2012	346564	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	502607
8228	03/17/2012	346564	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	502607
8228	03/02/2012	344799	Elec & Light - Replace side indicator	Replaced & cleaned a/c filters	499295
8228	02/29/2012	344252	Eng Cool - Add coolant	Added	497370
8228	02/28/2012	343720	radiator hose	Creditor #:MUL001 MULTISPARES LTD P/O #:G104810 Receiving #:105382 Date :2012-02-28	497152
8228	02/28/2012	344099	Eng Cool - Check for leaks	Topped up checked for leaks	497370
8228	02/27/2012	343877	Elec & Light - Replace LH headlight globe	Replaced topped up coolant bus OK	497152
8228	02/27/2012	343720	Eng Cool Leaking - top coolant hose broken	Replaced damaged coolant hose	497152
8228	02/27/2012	343720	HOSE ENG TO G/BOX COOLER MERC 0500LE		497152
8228	02/27/2012	343720	Brakes - Check brakes	Tightened brake booster rod s/cleaned r/tested checked coolant leak OK topped up coolant fuelled & parked	497152
8228	02/23/2012	343126		Perform & Complete PTSV Bus Safety Inspection	496772
8228	02/23/2012	343126		Tension Wheel Nuts	496772
8228	02/23/2012	343126		Perform & Complete PTSV Bus Safety Inspection	496772
8228	02/22/2012	343201	Eng Cool - Radiator hose leaking	Replaced by Tullamarine 13/02/12 = \$158.74 inc gst	496772
8228	02/21/2012	342994	Air Cond - Clean a/c filter	Cleaned	496449
8228	02/21/2012	342836		Service schedule changed	495996
8228	02/14/2012	341987	Eng Cool - Low coolant warning on dash	Checked OK	494391
8228	02/10/2012	341223	GLOBE HIGH BEAM 24V70W H1		493747
8228	02/09/2012	341223	Elec & Light - Replace headlight globe	Replaced	493747
8228	02/08/2012	341059	Air Cond - Clean a/c filters	Cleaned	493302
8228	02/08/2012	340930		Tension Wheel Nuts To OEM Specification	493155
8228	02/08/2012	340930		Grease AC Compressor Clutch Bearing	493155
8228	02/08/2012	340930		Clean A/C filter	493155
8228	02/08/2012	340930		A Service	493155
8228	02/08/2012	340930		A Service	493155
8228	01/23/2012	338829	Body & Acc - secure/replace rear seat brackets	secured by trim shop	487576
8228	01/16/2012	337605		Adjust Tappets	485618
8228	01/16/2012	337605	ROCKER COVER GASKET 0500LE	Rocker Cover Gasket	485618
8228	01/16/2012	337605	S/clean engine & radiator	Adjust Tappets	485618
8228	01/16/2012	337698	Body & Acc - Replace seat cushions rear (Also reported by T	Replaced	485619
8228	01/05/2012	335931	Brakes - Front brake pads 6mm	Ass Subu with torquing w/nuts	482617
8228	01/05/2012	335931	DISC PADS SCANIA L94+0500 MERC		482617
8228	01/05/2012	335931	Brakes - Front brake pads 6mm	Front both side brake pads changed wheels fitted & nuts tensioned	482617
8228	01/05/2012	333793	CHECK REAR BRAKE MODULATOR	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G102134 Receiving #:103372 Date :2012-01-05	483032
8228	12/30/2011	335620	Investigation/Inspection	R/tested	482041
8228	12/29/2011	335441	Brakes - Check for OS rear brake bind	Found OS rear booster leak replaced booster	481864
8228	12/29/2011	335249	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		481864
8228	12/28/2011	335249	Brakes - Rear brake relay valve leak when park brake on	Fit seals to 4way valve	481864
8228	12/21/2011	333793	N/S/R Brake Booster 0500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:G101923 Receiving #:102914 Date :2011-12-21 8228	481321
8228	12/19/2011	333793	Brakes - Rear wheels locking on	Removed EDS modulator inlet pipe sprayed contact cleaner fitted back still air leak	481321
8228	12/16/2011	333793	AIR FITTING	Creditor #:ENZ001 Enzed Dandenong P/O #:G101944 Receiving #:102776 Date :2011-12-16 8228	481321

8228	12/15/2011	333793	Brakes - Rear wheels locking on	Removed both side rear wheels checked and found NS rear booster leak	replaced. Remove booster air line OS rear checked and found air coming from park brake air line c/o EDS modulator air leak	481321
8228	12/15/2011	333793	O/S/R Brake Booster 0500LE			481321
8228	12/15/2011	333793	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE			481321
8228	12/15/2011	333793	Air System - Repair air fitting			481321
8228	12/14/2011	333192	POS 5-6 11R NEW			481321
8228	12/14/2011	333793	Brakes - Rear wheels locking on	Creditor #:BEA001 BEAUREPAIRES P/O #:G101687 Receiving #:102562 Date :2011-12-14		481321
8228	12/14/2011	333793	Brakes - Rear wheels locking on	Checked and found rear brake relay valve leak remove relay valve		481321
8228	12/14/2011	333793	Brakes - Rear wheels locking on	Found modulator air leak brake air system faults - send to WhiteHorse - 20/12/2011		481321
8228	12/12/2011	332955	BRAKE+ CLUTCH PEDAL PAD 0500LE	Overhaul rear relay valve		480316
8228	12/12/2011	332955	GLOBE S/CONTACT 24V-10W			480316
8228	12/12/2011	332955	DISC PADS SCANIA L94+0500 MERC			480316
8228	12/12/2011	332955	WIPER REFILL SUIT TX800+TX900			480316
8228	12/12/2011	333192	Whls & Tyres Worn tyre pos 5-6			480316
8228	12/10/2011	332955				479870
8228	12/10/2011	332955		Perform & Complete PTSV Bus Safety Inspection		479870
8228	12/10/2011	332955		Perform & Complete PTSV Bus Safety Inspection		479870
8228	12/10/2011	333290	Wipers & Washers - Replace wiper refills	Tension Wheel Nuts		479870
8228	12/10/2011	333286	Whls & Tyres - Replace tyre pos 56	Replaced		480316
8228	12/10/2011	333286	Whls & Tyres - Replace tyre pos 56	Replaced		480316
8228	12/10/2011	333286	Suspension - NSR rear airbag cracked	Replaced		480316
8228	12/10/2011	333286	Elec & Light - Replace bus stopping globe	Checked OK		480316
8228	12/10/2011	333286	Brakes - Replace brake pedal	Replaced		480316
8228	12/10/2011	333286	Brakes - Replace rear brake pads	Replaced		480316
8228	12/10/2011	333286	Brakes - Replace rear brake pads	Replaced with Dulkith		480316
8228	12/10/2011	333286	Air System - Big noise when vacuum relief (air releif valve	Replaced		480316
8228	12/06/2011	331911	CYCLONE PACK (SEPARATOR) MERC COMPLETE UNIT	Remove air dryer exhaust silencer from 8229 and fixed 8228		480316
8228	12/06/2011	331911	HALDEX CONDENSER KIT TOP(CYCLONE)			478923
8228	12/06/2011	331912	AIR FILTER MERC 0500LE			478923
8228	12/02/2011	331911		Re-kit Air Cyclone Separator		477563
8228	12/02/2011	331912		A Service		477563
8228	12/02/2011	331912		Tension Wheel Nuts To OEM Specification		477563
8228	12/02/2011	331912		Grease AC Compressor Clutch Bearing		477563
8228	12/02/2011	331912		Clean A/C filter		477563
8228	12/02/2011	331912		A Service		477563
8228	11/21/2011	330179	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)			474428
8228	11/21/2011	330179	HALDEX CONDENSER KIT TOP(CYCLONE)			474428
8228	11/21/2011	330179	HALDEX COIL BASE OIL SEPERATOR			474428
8228	11/21/2011	330179	DRAIN VALVE KIT BOTTOM			474428
8228	11/21/2011	330179	HALDEX COIL KIT 0500LE			474428
8228	11/18/2011	330179	Air System - Rebuild ACS	Rebuilt		474428
8228	11/16/2011	329809	Vandalism - Clean graffiti from inside bus	Cleaned		473571
8228	11/16/2011	329809	Air Cond - Clean a/c filters	Cleaned		473571
8228	11/14/2011	328732	CAMPAIGN - Install retro - reflector tape on rear engine ha	Installed by Attitude Signs		471044
8228	11/04/2011	328066	Eng Cool - Add coolant	Added		469738
8228	10/20/2011	323705	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G98954 Receiving #:100214 Date :2011-10-20		464646
8228	10/20/2011	325575	Eng Cool - Add coolant	Added		464646
8228	10/16/2011	323705	Annual Licence	RWC - 804047 - Passed		462120
8228	10/14/2011	324902	Brakes - Check fault code BS 5443	Deleted fault code and checked rear brake pad OK		463495
8228	10/13/2011	324421	GLOBE INDICATOR 24V-18W SINGLE CONTACT			462906
8228	10/13/2011	324421	CLEAR FRONT INDICATOR WRAP-AROUND			462906
8228	10/12/2011	324059	Wipers & Washers - Wipers just stopped working	Checked out wipers unable to fault		462506
8228	10/12/2011	324421	Elec & Light - Replace indicator lens & globe	Replaced		462906
8228	10/12/2011	324322	CAMPAIGN - Fit covers on retarder switchs in electrical cen	Fitted		462906
8228	10/05/2011	323139	Pre Road Safety Check			460836
8228	10/05/2011	323139		Tension Wheel Nuts		460836
8228	10/05/2011	323139		Perform & Complete PTSV Bus Safety Inspection		460836
8228	10/05/2011	323286	Elec & Light - S/clean battery	Cleaned		460984
8228	10/05/2011	323140	ENGINE OIL BREATHER KIT 0500LE			460836
8228	10/05/2011	323140	AIR FILTER MERC 0500LE			460836
8228	10/05/2011	323140	OIL FILTER 1725+0500LE			460836
8228	10/05/2011	323140	ENGINE OIL DELO 400LE 15W40			460836
8228	10/05/2011	323140		D-Service & Bus Safety Inspection		460836
8228	10/05/2011	323140		A Service & Bus Safety Inspection		460836
8228	10/05/2011	323140		Replace Engine Oil Breather Kit		460836
8228	10/05/2011	323140		Grease AC Compressor Clutch Bearing		460836
8228	10/05/2011	323140		Tension Wheel Nuts to Spec		460836
8228	10/05/2011	323140		A Service		460836
8228	10/05/2011	323140		Clean A/C filter		460836
8228	10/05/2011	323140		Grease AC Compressor Clutch Bearing		460836
8228	10/05/2011	323140		Tension Wheel Nuts To OEM Specification		460836
8228	09/27/2011	321634		Replace final drive oil		458240
8228	09/27/2011	321634		Inspect radiator and charge air cooler for dirt - clean		458240
8228	09/27/2011	321634		Replace pre and main fuel filters		458240
8228	09/27/2011	321634		Replace air dryer cansiter clean silence and drain reservoir		458240
8228	09/27/2011	321634		Replace angle drive oil		458240
8228	09/27/2011	321634		Test coolant level - top up if required to equate to 37C frost protection		458240
8228	09/27/2011	321634		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.		458240
8228	09/27/2011	321634		Replace power steering filter and check level (Replace oil if required)		458240
8228	09/27/2011	321634		Check and clean cartridge in dry tyre air cleaner		458240
8228	09/27/2011	321634		Check oil level in transmission - top up if required		458240
8228	09/27/2011	321634		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals		458240
8228	09/27/2011	321635	Annual Body Inspection	Inspected		458240
8228	09/27/2011	321635	15LTR RUBBISH BINS			458240
8228	09/24/2011	321402				457889
8228	09/24/2011	321402		Tension Wheel Nuts		457889
8228	09/19/2011	318153	FILTER DRIER THERMO KING	Perform & Complete PTSV Bus Safety Inspection		454800
8228	09/13/2011	319567	Brakes ABS On - check MIL BS 5443	R/tested		453678
8228	09/13/2011	319567	Brakes ABS On - check MIL BS 5443	Checked brake pads & r/tested		453678
8228	09/06/2011	303472	scrap	Creditor #:BEA001 BEAUREPAIRES P/O #:G97433 Receiving #:98355 Date :2011-09-06		451804
8228	09/06/2011	318542	Passenger Doors - Check doors	Checked OK		452071
8228	09/05/2011	318153		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;		451528
8228	09/05/2011	318153		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		451528
8228	09/05/2011	318153		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		451528

8228	09/05/2011	318153	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	451528
8228	09/05/2011	318153	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	451528
8228	09/05/2011	318153	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	451528
8228	09/05/2011	318153	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	451528
8228	09/05/2011	318153	ADJUSTER IDLER PULLEY	451528
8228	09/05/2011	318153	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	451528
8228	09/05/2011	318153	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	451528
8228	09/05/2011	318153	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	451528
8228	09/05/2011	318153	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	451528
8228	08/30/2011	317497	Body & Acc - Repair NS front luggage rack	450071
8228	08/30/2011	317497	Body & Acc - Replace exit only decal on rear doors	450071
8228	08/30/2011	317497	Body & Acc - Pole broken up back of bus	450071
8228	08/29/2011	316996	Eng Cool - Add coolant	449857
8228	08/29/2011	316700	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE	449857
8228	08/29/2011	316621	REPAIR REAR WINDOW	449857
8228	08/26/2011	316700	Brakes - Rear brake relay valve leaking	449445
8228	08/26/2011	316621	Accident #33860# O/S rear window smashed	449445
8228	08/19/2011	313448	DOWN LIGHT	447037
8228	08/18/2011	314507	POS 1 11R NEW FLAT	446759
8228	08/18/2011	303510	Replace Grenda decals x 4	446759
8228	08/18/2011	315219	A Service	446759
8228	08/18/2011	315219	Clean A/C filter	446759
8228	08/18/2011	315219	Grease AC Compressor Clutch Bearing	446759
8228	08/18/2011	315219	Tension Wheel Nuts To OEM Specification	446759
8228	08/18/2011	315219	A Service	446759
8228	08/17/2011	314007	Completed alt rebuild had to extract broken screw from alt	
8228	08/17/2011	314007	BOSCH REGULATOR 0500LE ALT	446435
8228	08/17/2011	314007	BEARING ALT MAN 16-240+0500LE	446435
8228	08/16/2011	314007	Cont alt rebuild c/o	
8228	08/16/2011	314884	Whls & Tyres - Replace pos 1 tyre	446435
8228	08/16/2011	314507	fix puncture pos 1	445899
8228	08/16/2011	314115	2 WAY RADIO NOT WORKING - CHEC	445899
8228	08/16/2011	314115	2 way radio not transmitting	445899
8228	08/15/2011	314007	Cont alt rebuild c/o	
8228	08/15/2011	314650	Air Cond - Clean a/c filters	445899
8228	08/12/2011	314007	Began alt rebuild c/o	
8228	08/11/2011	314115	Comm Equip - 2way u/s	445530
8228	08/09/2011	313448	Replace down light on drivers locker with swivel down ligh	444625
8228	08/09/2011	313396	WEDGE GLOBE INSTRUMENT 24V 3W	444625
8228	08/09/2011	313396	CLEAR FRONT INDICATOR WRAP-AROUND	444625
8228	08/09/2011	313661	Brakes - Airleak at handbrake when released	444625
8228	08/08/2011	313396	Elec & Light - Replace globes	444625
8228	08/08/2011	313149	GLOBE INDICATOR 24V-18W SINGLE CONTACT	444288
8228	08/05/2011	313149	Elec & Light - Replace globe	443612
8228	08/05/2011	312941	BRAZILLIAN MIRROR L/H	443612
8228	08/04/2011	312941	Body & Acc - Replace NS mirror	443514
8228	08/04/2011	312941	Air System - Check for air leak	443514
8228	08/04/2011	312941	Air System - Check for air leak	443514
8228	08/04/2011	308614	overflow air bag valve	443363
8228	08/01/2011	312262	AX - NSR tyre oil leak from hub	442831
8228	07/20/2011	310448	Tension Wheel Nuts	439266
8228	07/20/2011	310448	Perform & Complete PTSV Bus Safety Inspection	439266
8228	07/11/2011	308614	BR - Warning light with code BS 85443	435569
8228	07/11/2011	308614	Proportional valve leaking - front	435569
8228	07/08/2011	308941	Air Cond - Clean a/c filters	435865
8228	07/07/2011	308614	Elec & Light W'ring Light - Warning light on dash	435569
8228	07/07/2011	308614	A0054297644 PROPORTION VALVE	435865
8228	07/06/2011	308047	GLOBE HIGH BEAM 24V70W H1	435036
8228	07/03/2011	308047	Replace OSF headlight globe	434644
8228	06/30/2011	307653	Clean a/c filters	433612
8228	06/24/2011	306094	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE	430938
8228	06/24/2011	306094	AS - Air leak from front of bus	430938
8228	06/21/2011	306154	GLOBE HIGH BEAM 24V70W H1	430938
8228	06/21/2011	306154	Headlight n/w	430938
8228	06/21/2011	306141	GLOBE HIGH BEAM 24V70W H1	430938
8228	06/20/2011	306141	Replace NS front headlight globe	430938
8228	06/20/2011	306094	AS - Air leak from front of bus	430938
8228	06/20/2011	305806	AIR FILTER MERC 0500LE	430777
8228	06/20/2011	305806	Tension Wheel Nuts To OEM Specification	430777
8228	06/20/2011	305806	A Service	430777
8228	06/20/2011	305806	A Service	430777
8228	06/20/2011	305806	Clean A/C filter	430777
8228	06/20/2011	305806	Grease AC Compressor Clutch Bearing	430777
8228	06/14/2011	304832	CYCLONE PACK (SEPARATOR) MERC COMPLETE UNIT	428067
8228	06/11/2011	304831	Perform & Complete PTSV Bus Safety Inspection	428067
8228	06/11/2011	304831	Tension wheel nuts	428067
8228	06/11/2011	304949	Pin hole coolant leak from transmtion cooler pipe	428343
8228	06/11/2011	304832	Repaired	428067
8228	06/08/2011	303472	Re-kit Air Cyclone Separator	427476
8228	06/08/2011	297714	Creditor #:BEA001 BEAUREPAIRES P/O #:G93313 Receiving #:94541 Date :2011-06-08	415249
8228	06/08/2011	297714	BELT BOTTOM ALTERNATOR MERC 0500LE	415249
8228	06/08/2011	297714	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE	415249
8228	06/08/2011	297714	EL - Remove and discontinue use of top alternator	415249
8228	06/08/2011	297714	EL - Battery bridge cable u/s	415249
8228	06/08/2011	297714	A0011526710 SOLENOID S/MOTOR	415249
8228	06/08/2011	297714	BR - BS light on dash - amber	415249
8228	06/07/2011	297714	EL - Remove and discontinue use of top alternator	415249
8228	06/07/2011	297714	EL - Remove and discontinue use of top alternator	415249
8228	06/06/2011	297714	EL - Fuel gauge was on 1/4 when it had only done 200 ks	415249
8228	06/06/2011	297714	FU - Fuel gauge faulty	415249
8228	06/03/2011	303768	Clean a/c filters	427476
8228	06/03/2011	297714	EL - Fuel gauge was on 1/4 when it had only done 200 ks	415249
8228	06/02/2011	303472	fix flat tyre pos 2	427476
8228	06/02/2011	297714	FU - Fuel gauge faulty	415249
			Began removing sender cut floor hole bigger c/o	

8228	06/02/2011	303510	Replace Grendas decals x 4	Replaced	427476
8228	06/01/2011	303501	Breakdown - Wellington Rd - OUT 3.40 pm BACK 5.00 pm - OS f	C/O bus 8264. Assisted to change tyre	427476
8228	06/01/2011	303501	Breakdown - Wellington Rd - OUT 3.40 pm BACK 5.00 pm - OS f	C/O bus 8264. Changed tyre returned and tesnioned w/nuts fuelled & parked	427476
8228	05/26/2011	301871	POS 4-5 11R NEW	Creditor #::BEA001 BEAUREPAIRES P/O #:K92812 Receiving #:93819 Date :2011-05-26	425605
8228	05/23/2011	301871	Replace tyre pos 45 - low tread	Replaced	424807
8228	05/20/2011	301869	Replace OSR tyres	Replaced	424807
8228	05/19/2011	301451	Add coolant	Added	424207
8228	05/14/2011	300606	NS side marker broken	PTI - DYSONS - 25/2/11 - Replaced	422393
8228	05/11/2011	299306	11R NEW FLAT	Creditor #::BEA001 BEAUREPAIRES P/O #:G91936 Receiving #:93162 Date :2011-05-11	421701
8228	05/09/2011	299916	Adjust doors	Adjusted	421246
8228	05/05/2011	299306	fix flat tyre pos 1	fixed	420174
8228	05/05/2011	299431	Replace tyre Nm. 1	Replaced	420174
8228	04/29/2011	297714	HYA6345420317 FUEL SENDER	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G91275 Receiving #:92651 Date :2011-04-29 8228	417861
8228	04/29/2011	296301	50A9115W COMPRESSOR WARRANTY	Creditor #::MUL001 MULTISPARES LTD P/O #:G90448 Receiving #:92585 Date :2011-04-29 8228	417861
8228	04/20/2011	298102	Bus makes noise	Road check no noise found	416079
8228	04/18/2011	297802	Wiper jets U/S	Cleaned	415559
8228	04/18/2011	297802	Fit door strep	Fit new strap	415559
8228	04/18/2011	297802	Readjust rear door	Adjusted	415559
8228	04/18/2011	297801	Random Vehicle Audit		415559
8228	04/18/2011	297713		Replace engine oil breather kit	415249
8228	04/18/2011	297713	ENGINE OIL BREATHER KIT 0500LE		415249
8228	04/18/2011	297713		Grease AC Compressor Clutch Bearing	415249
8228	04/18/2011	297713	AIR FILTER MERC 0500LE		415249
8228	04/18/2011	297713	OIL FILTER 1725+0500LE		415249
8228	04/18/2011	297713		Tension Wheel Nuts to Spec	415249
8228	04/18/2011	297713		A Service & Bus Safety Inspection	415249
8228	04/18/2011	297713		D-Service & Bus Safety Inspection	415249
8228	04/18/2011	297713	ENGINE OIL DELO 400LE 15W40		415249
8228	04/18/2011	297713		Grease AC Compressor Clutch Bearing	415249
8228	04/18/2011	297713		Clean A/C filter	415249
8228	04/18/2011	297713		Tension Wheel Nuts To OEM Specification	415249
8228	04/18/2011	297713		A Service & Bus Safety Inspection	415249
8228	04/10/2011	296782	Add coolant	Added	413604
8228	04/06/2011	295185	POS 3-4 11R NEW	Creditor #::BEA001 BEAUREPAIRES P/O #:G90338 Receiving #:91639 Date :2011-04-06	412461
8228	04/06/2011	296301	FILTER REGULATOR DOOR RAM		412461
8228	04/06/2011	296301	AIR - repair air leak at front of bus	Replaced front bumper door button	412461
8228	04/06/2011	296144	FITTING MERCEDES COMPRESSOR		412461
8228	04/05/2011	295423	VALVE SAFETY BLOW OFF 1.3MP		412461
8228	04/05/2011	296144	COOL - Coolant in air tanks	Fitted new air compressor steam clean road tested.	412461
8228	04/05/2011	296143	COOL - Coolant in air tanks	Ref to w/order 296144	412461
8228	03/31/2011	295588	AIR REGULATOR		412461
8228	03/31/2011	295588	GAUGE MIST SEPARATOR		412461
8228	03/31/2011	295588	AIR - front door outside button airleak	Replaced door regulator	412461
8228	03/30/2011	295423	COOL - Coolant in air tanks	Removed air compressor and replace gaskets	412461
8228	03/29/2011	295185	replace worn tyre pos 3-4	replace worn tyre pos 3-4	412461
8228	03/29/2011	295059	AXL - Left rear wheel hub oil leaking	Replaced hub seal completed	412461
8228	03/29/2011	295059	AXL - Left rear wheel hub oil leaking	Assist Sisil with hub seal & fitting tyres	412461
8228	03/29/2011	295059	AXL - Left rear wheel hub oil leaking	Assist Sisil with hub seal	412461
8228	03/28/2011	295059	REAR HUB SEAL KIT 0500LE		412461
8228	03/28/2011	295059	AXL - Left rear wheel hub oil leaking	Assist Sisil with hub seal	412461
8228	03/28/2011	295059	AXL - Left rear wheel hub oil leaking	Strip the part	412461
8228	03/21/2011	293945		A Service & Bus Safety Inspection	412252
8228	03/21/2011	293945		A Service & Bus Safety Inspection	412252
8228	03/21/2011	293945		Clean A/C filter	412252
8228	03/21/2011	293945		Grease AC Compressor Clutch Bearing	412252
8228	03/21/2011	293945		Tension Wheel Nuts To OEM Specification	412252
8228	03/13/2011	293377	Add coolant	Added	411070
8228	02/24/2011	291192	Clean a/c filters	Cleaned	405709
8228	02/18/2011	290253	Drv entered - Air Cond Other	Checked OK	403891
8228	02/18/2011	290253	BR - Next time brake pads get changed need to replace discs	Checked all brakes is new pads have been fitted	403891
8228	02/18/2011	290253	BR - warning light orange - BS 5443	Cleared all codes	403891
8228	02/18/2011	290253	BR - BS 5443	same job	403891
8228	02/18/2011	290253	AIR - Air leak rear right wheel	Checked no leaks	403891
8228	02/17/2011	288617	POS 1-2 11R NEW	Creditor #::BEA001 BEAUREPAIRES P/O #:G88226 Receiving #:89679 Date :2011-02-17	403567
8228	02/12/2011	289561	Air line cracked	Put in joiner	402079
8228	02/12/2011	289331		Bus Safety Inspection	401579
8228	02/12/2011	289331	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	401579
8228	02/12/2011	289331	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	401579
8228	02/12/2011	289331		Service T - Replace Transmission Oil & Filter	401579
8228	02/12/2011	289331		Service T - Replace Transmission Oil & Filter	401579
8228	02/10/2011	289053	AC - AC switch is missing & a/c is on all the time	checked ok	401200
8228	02/10/2011	289147	Add coolant	Added	401200
8228	02/09/2011	288862	SENSITIVE EDGE DOOR SWITCH		400501
8228	02/08/2011	288861	WHL - NSR tyres only 4 & 5 mm	Replaced n s r tyres	400501
8228	02/08/2011	288617	replace worn tyre pos 1-2	replace worn tyre pos 1-2	400501
8228	02/08/2011	288862	PD - replace front door sensitive edge	Replaced	400501
8228	02/08/2011	288860	PD - Door switch below bumper leaking air	Repaired	400501
8228	02/08/2011	288905	ELE - Air con switch broken off	Changed a/c switch and checked ok	400501
8228	02/08/2011	288862	BODY - replace nsf mud flap	Replaced	400501
8228	02/08/2011	288565		A Service & Bus Safety Inspection	400109
8228	02/08/2011	288565	Service	A Service & Bus Safety Inspection	400109
8228	02/08/2011	288565		Clean A/C filter	400109
8228	02/08/2011	288565		Grease AC Compressor Clutch Bearing	400109
8228	02/08/2011	288565		Tension Wheel Nuts To OEM Specification	400109
8228	02/04/2011	277000	replace decals	Creditor #::ATT001 ATTITUDE SIGNS P/O #:G85592 Receiving #:89236 Date :2011-02-04 8228	398811
8228	02/01/2011	287381	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		397833
8228	02/01/2011	287381	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE		397833
8228	01/28/2011	287381	BR - Code on dash BS 5443	Removed relay & 6 way valves rekittd and fitted back	397389
8228	01/25/2011	287022	Clean a/c filters	Cleaned	396558
8228	01/18/2011	286114	Park brake light staying on	Checked unable to fault r/tested OK	395193
8228	01/17/2011	285986	Breakdown - Monash University - OUT 7.30 pm BACK 8.30 pm -	C/O bus 8380. Returned & cleared brake fault BS 5443 fault did not return cleaned elec connections on pressure switches on rear boosters	394608
8228	01/11/2011	285127	Not building up air	Att by Dysons 24/12/10.Found air dryer leaking \$50.63 exc GST	392481
8228	01/11/2011	285127	Not building up air	Att by Dysons 21/12/10. Checked air system for correct air pressure \$81.26 exc GST	392481

8228	01/11/2011	285121	Air wont build up	Att by Dysons on 30/11/10. Repaired air system fittings OK \$101.26 exc GST	392481
8228	01/05/2011	283755	CLEAR EXIT ONLY DOOR STICKER		388472
8228	01/04/2011	280878	AIR LEAK AT REAR RELAY VALVE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G86067 Receiving #:87857 Date :2011-01-04	389747
8228	12/31/2010	283755	Replace exit only decal	Replaced	388472
8228	12/31/2010	283755	Ops Entered - Fault - Air System - Route: 902 - Wood St Re	Repaired air system air dryer replaced emerg hammer tightened belts	388472
8228	12/31/2010	283755	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		388472
8228	12/31/2010	283755	AIR DRYER CANISTER VOLVO+ NL202		388472
8228	12/31/2010	283755	AIR LINE FITTING KIT 0500LE AIR DRYER		388472
8228	12/31/2010	283755	WATER SEPERATOR SCANIA+VOLVO		388472
8228	12/31/2010	283755	Ops Entered - Fault - Air System - Route: 902 - Wood St Re	Fixed air dryer adjusted pressure adjusted alt belts & r/tested	388472
8228	12/30/2010	283755	AIR - ACS unit leaking	rekit water seperator remove air dryer	388472
8228	12/30/2010	283755	AIR - ACS unit leaking	Rekit air dryer & air water seperator	388472
8228	12/30/2010	283683	SINGLE WABCO AIR DRYER KIT 0500LE		388472
8228	12/29/2010	283683	Breakdown - Wantirna Rd Ringwood - OUT 2.00 pm BACK 3.40 pm	C/O bus 8621. Temp repair and returned (need to overhaul air dryer)	388472
8228	12/27/2010	283469	Adjust front door	Adjusted door air dryer r/tested fuelled & parked	388472
8228	12/14/2010	280878	BRK - air leak at rear relay valve	Repaired by W/horse	387325
8228	12/13/2010	280878	rear n/s booster A634420021801	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G85879 Receiving #:87140 Date :2010-12-13 8228	387325
8228	12/10/2010	280878	BRK - MIL coming on	Changed RHR brake chamber relay valve checked both brake chambers repaired brake shutter valve overhauled relay valve BS fault 7392 AGN fault 5521 faults are active still air leak in system with handbrake on and rear door open	387325
8228	12/06/2010	280878	BRK - MIL coming on	Found relay valve leaking replaced then found booster faulty	387325
8228	11/29/2010	279787	WEDGE GLOBE INSTRUMENT 24V 3W		385078
8228	11/29/2010	279862	Add coolant	Added	385871
8228	11/26/2010	279787	Replace globe	Replaced	385078
8228	11/26/2010	279365	AIR - air dryer leak	Replaced bottom air dryer kit	385078
8228	11/26/2010	279366		Clean A/C filter	385078
8228	11/26/2010	279366		Grease AC Compressor Clutch Bearing	385078
8228	11/26/2010	279366		Tension Wheel Nuts To OEM Specification	385078
8228	11/26/2010	279366		A Service & Bus Safety Inspection	385078
8228	11/24/2010	277156	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G84561 Receiving #:86224 Date :2010-11-24	385078
8228	11/23/2010	277040	O RING OIL LINE COMP 0500LE		385078
8228	11/23/2010	277040	SHIM GASKET SUIT 0500LE COMPRESSOR A4571304815		385078
8228	11/22/2010	277040	BELT BOTTOM ALTERNATOR MERC 0500LE		384629
8228	11/22/2010	277040	A/C BELT 0500 BENZ		384629
8228	11/19/2010	277040	AC - A/C belt cracked	Replaced	384629
8228	11/19/2010	277040	EN - In engine bay X member that holds coolant tank is loos	Tightened	384629
8228	11/19/2010	277040	ENG - Engine sump oil leak (Checked on 14/04/1003/06/1008	Repaired leak between comp & engi	384629
8228	11/19/2010	277040	COOL - Cooling system leak at OSR of vehicle	Repaired	384629
8228	11/19/2010	277040	BOD - Key is missing for the compartment where triangle is	Fitted	384629
8228	11/19/2010	277040	SUB - Polish windscreen - Sub/con - Knights - n/s rear wind	Polished by Knights	384629
8228	11/19/2010	277040	Suspect compressor headgasket	Replaced compressor s/cleaned & r/tested	384629
8228	11/19/2010	277040	AIR - Constant air leak at unloader above diff	Replaced overflow valve diaphragm	384629
8228	11/19/2010	277040	Suspect compressor headgasket	Replaced compressor	384629
8228	11/17/2010	277040	EN - Steamclean the bus	done	384629
8228	11/16/2010	277000	RED REFLECTOR 94X44MM		384629
8228	11/15/2010	277000	BOD - Step edges replace/fit inserts at rear of the bus	replaced	384629
8228	11/15/2010	277000	BOD - Replace wheel arch rubber NS 1 & OS 1 front and secur	Replaced	384629
8228	11/15/2010	277000	BOD - Paint rear bumper bar	same as a/d	384629
8228	11/15/2010	277000	UNREPORTED - Accident Damage # 32132 - Replace OS panels 8	Paint clear coat only to OSR corner bar & middle section	384629
8228	11/15/2010	277000	UNREPORTED - Accident Damage # 32132 - Replace OS panels 8	Remounted centre & corner bumper bar	384629
8228	11/15/2010	277000	Accident Damaged #31580 R/R. n/s. lower body panels No3	Painted rear bar	384629
8228	11/14/2010	277156	inspect for rsi -	DN - 129318 passed	384629
8228	11/12/2010	277000	BOD - Replace clow catches - OS 89	Replaced OS 8 only	384629
8228	11/12/2010	277000	BOD - Adjust front doors	Adjusted	384629
8228	11/12/2010	277000	BOD - Polish exterior panels/headers & touch up paint work	Polished & touched up	384629
8228	11/12/2010	277000	BOD - Replace air supply decal	NA	384629
8228	11/12/2010	277000	BOD - Clean battery box	Cleaned	384629
8228	11/12/2010	277000	BOD - Adjust rear doors	Adjusted	384629
8228	11/12/2010	277000	BOD - Replace skit panel hinge rubber OS 89 & NS 67	checked OK	384629
8228	11/12/2010	277000	BOD - Replace side reflectors - NS OS	been done	384629
8228	11/12/2010	277040	911-553-200-0 COMP	Creditor #:MUL001 MULTISPARES LTD P/O #:G84624 Receiving #:85823 Date :2010-11-12	384629
8228	11/12/2010	277000	UNREPORTED - Accident Damage # 32132 - Replace OS panels 8	Replaced OS only refitted panels & reflectors	384629
8228	11/12/2010	277000	BUMPER BOLT SPECIAL		384629
8228	11/12/2010	277000	PLASTIC WASHER		384629
8228	11/12/2010	277000	SCREW TORX 8 X 15MM SIDE PANEL		384629
8228	11/12/2010	277000	RED REFLECTOR 94X44MM		384629
8228	11/11/2010	277000	F/GLASS REAR N/S BUMPER CORNER		384629
8228	11/11/2010	277000	2MM X 1200MM X 2400MM FLAT ALUMINIUM		384629
8228	11/11/2010	277000	CENTRA SEAT END CAPS		384629
8228	11/11/2010	277000	SEAT CATCH		384629
8228	11/11/2010	277000	Accident Damaged #31580 R/R. n/s. lower body panels No3	ADAM - Prep ready for paint	384629
8228	11/11/2010	277000	AMBER REFLECTOR SIDE MOUNT	Prep work ready for 2pak primer	384629
8228	11/11/2010	277000	Accident Damaged # 32131 R/R. n/s.lower panel reflectors n	Painted	384629
8228	11/10/2010	277000	Prep & paint door handle	Painted 2pak	384629
8228	11/10/2010	277000	BOD - Secure seat frames 1 OS 11 OS No 1 NS secure rear b	ADAM - Secured	384629
8228	11/10/2010	277000	BOD - Replace emergency exit push button under panel	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Replace interior decals - priority seating	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Clean air condition filter secure vents	Cleaned	384629
8228	11/10/2010	277000	BOD - Replace Licensed to carry (No) seat (No) adult passen	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Replace fleet numbers front & rear	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Replace seat NS 3 & 6 endcaps	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Secure ticket machine stand	ADAM - Secured	384629
8228	11/10/2010	277000	BOD - Replace front door seals	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Repair hand grips NS 89	ADAM - Repaired	384629
8228	11/10/2010	277000	BOD - Secure demister ducts	ADAM - Secured	384629
8228	11/10/2010	277000	BOD - Replace skit panel hinge rubber OS 89 & NS 67	Removed & repaired	384629
8228	11/10/2010	277000	BOD - paint exterior mirrors and arms	Painted	384629
8228	11/10/2010	277000	BOD - Replace fleet number on dash - in yellow	ADAM - Checked OK	384629
8228	11/10/2010	277000	BOD - Replace exit only on rear doors	ADAM - Replaced	384629
8228	11/10/2010	277000	BOD - Wheel chair ramp - clean	Cleaned	384629
8228	11/10/2010	277000	BOD - Remove Grendas name address & weight - OSF No 1 panel	ADAM - Removed	384629
8228	11/10/2010	277000	BOD - Secure all lower skit panels	ADAM - Secured	384629
8228	11/10/2010	277000	BOD - Clean graffiti - floor seats & side walls	Cleaned	384629
8228	11/10/2010	277000	BOD - Paint till stand	Painted	384629
8228	11/10/2010	277284	BROOM HANDLE (8232715)		384629

8228	11/10/2010	277284	BROOM HEAD (09803211)			384629
8228	11/09/2010	277040	Steamclean bus	Cleaned		384629
8228	11/09/2010	277040	Suspect compressor headgasket	Checked air leak		384629
8228	11/08/2010	277284	Replace broom	Replaced		384629
8228	11/07/2010	277040	Suspect compressor headgasket	Put off road due to head gasket cleaned graffiti		384629
8228	11/05/2010	276873	Replace NS rear clearance lamp screws	Replaced		383693
8228	11/05/2010	276871	Breakdown - Knox Shops - OUT 10.45 am BACK 11.45 am - Coola	C/O bus 8296. Added coolant		383693
8228	11/03/2010	276513	Add coolant	Added		382642
8228	10/28/2010	275233	POS 5 11R NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G83855 Receiving #:85295 Date :2010-10-28		381743
8228	10/27/2010	275082	WATER SEPERATOR SCANIA+VOLVO			381299
8228	10/25/2010	275337	BRAZILLIAN MIRROR L/H	Creditor #::PSS001 PARTS SUPPLY SOLUTIONS P/O #:G83349 Receiving #:85036 Date :2010-10-25		379052
8228	10/25/2010	275337	Service			379052
8228	10/25/2010	275233	replace worn tyre pos 5-6	replace worn tyre pos 5-6		379052
8228	10/22/2010	275082		Inspect radiator and charge air cooler for dirt - clean		378790
8228	10/22/2010	275082		Replace final drive oil		378790
8228	10/22/2010	275082		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals		378790
8228	10/22/2010	275082		Inspect radiator and charge air cooler for dirt - clean		378790
8228	10/22/2010	275082		Check oil level in transmission - top up if required		378790
8228	10/22/2010	275082		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks		378790
8228	10/22/2010	275082		Check and clean cartridge in dry tyre air cleaner		378790
8228	10/22/2010	275082		Replace pre and main fuel filters		378790
8228	10/22/2010	275082		Replace air dryer cansiter clean silence and drain reservoir		378790
8228	10/22/2010	275082		Replace angle drive oil		378790
8228	10/22/2010	275082		Test coolant level - top up if required to equate to 37C frost protection		378790
8228	10/22/2010	275082		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.		378790
8228	10/22/2010	275082		Replace power steering filter and check level (Replace oil if required)		378790
8228	10/22/2010	275082	FUEL FILTER MERC 0500LE			378790
8228	10/22/2010	275082	FUEL FILTER 0500LE			378790
8228	10/22/2010	275082	AIR DRYER CANISTER VOLVO+ NL202			378790
8228	10/22/2010	275082	POWER STEER FILTER B10M			378790
8228	10/22/2010	274989	ANN - annual body inspection	Inspected		378790
8228	10/22/2010	275216	Change OSR both tyres	Changed		378790
8228	10/22/2010	275216	EN - Oil sitting on top of the engine	S/cleaned top & bottom of engine		378790
8228	10/22/2010	275237	Replace hinge rubber of rear panel OS	Replaced		378790
8228	10/22/2010	275237	Replace hinge rubber of rear panel OS	Replaced		378790
8228	10/22/2010	275199	BOD - Fire extinguisher expired	Replaced		378790
8228	10/12/2010	273686	GEAR - gearbox at the back makes a lot of noise	Checked ok		377809
8228	10/12/2010	273686	GB - G/box at the back makes a big noise	Road tested all these buses 6th gear noisy its normal		377809
8228	10/12/2010	272246	CHECK VALVE 22MM CYCLONE AIR FILTER			377809
8228	10/11/2010	272996	VOLVO THERMOSTAT 81 DEGREES			377031
8228	10/09/2010	273307	Add coolant	Added		377618
8228	10/08/2010	272996	THERMOSTAT ORING 0405+0500LE MERC			377031
8228	10/08/2010	272996	THERMOSTAT 71 DEG 0405+0500LE BENZ			377031
8228	10/08/2010	272996	Building pressure in engine cooling system	same as		377031
8228	10/08/2010	272996	Air pumping to coolant system need to check air compressor	Fit new thermostats topped up coolant & r/tested OK		377031
8228	10/07/2010	272996	Air pumping to coolant system need to check air compressor	Checked overheating found thermostat not opening drained coolant & removed thermostats		377031
8228	10/07/2010	272246	CYCLONE PACK (SEPARATOR) MERC	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G82892 Receiving #:84355 Date :2010-10-07		377031
8228	10/06/2010	272957	Check coolant leak	Changed header tank cap pumping air to coolant system need to check air compressor		377031
8228	10/06/2010	272957	BOD - Check back hatch struts	Changed struts		377031
8228	10/06/2010	272957	BOD - Need new engine compartment door struts	same as		377031
8228	10/05/2010	272593	SNAP ON SILENCER A/DRYER			376520
8228	10/05/2010	272246	Replaced air dryer & water seperator & checked valve	Re kit the air dryer and water seperator that were pulled off this bus.		376476
8228	10/05/2010	272246	WATER SEPERATOR SCANIA+VOLVO			376476
8228	10/05/2010	272246	HALDEX CONDENSER KIT TOP			376476
8228	10/05/2010	272246	AIR DRIER KIT MERCEDES 0500LE			376476
8228	10/05/2010	272246	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)			376476
8228	10/05/2010	272246	AIR LINE FITTING KIT 0500LE AIR DRYER			376476
8228	10/05/2010	272246	AIR DRYER UNLOADER KIT			376476
8228	10/04/2010	272593	Check air system	Changed air dryer 4 way valve seal O ring also adjust air dryer overflow valve & r/tested		376520
8228	10/04/2010	272246	Replaced air dryer & water seperator & checked valve	Re-kit Air Cyclone Separator		376476
8228	09/30/2010	272115	Add coolant	Added		376222
8228	09/30/2010	272115	Add coolant	Added		376222
8228	09/22/2010	271101	Clean a/c filter	Cleaned		373875
8228	09/15/2010	270207	Drv entered - Vandalism Graffiti	Cleaned		372161
8228	09/08/2010	269219	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL			369906
8228	09/08/2010	269219		A Service & Bus Safety Inspection		369906
8228	09/08/2010	269219		D-Service & Bus Safety Inspection		369906
8228	09/08/2010	269219		Tension Wheel Nuts to Spec		369906
8228	09/08/2010	269219				369906
8228	09/08/2010	269219		Grease AC Compressor Clutch Bearing		369906
8228	09/08/2010	269219				369906
8228	09/08/2010	269219		Replace engine oil breather kit		369906
8228	09/08/2010	269219		A Service & Bus Safety Inspection		369906
8228	09/08/2010	269219		Tension Wheel Nuts To OEM Specification		369906
8228	09/08/2010	269219		Grease AC Compressor Clutch Bearing		369906
8228	09/08/2010	269219		Clean A/C filter		369906
8228	09/02/2010	268535	Take bus to port melbourne	Left 7.00 am Back 2.30 pm		368306
8228	09/01/2010	268361	AIR S - make air connection	completed		368306
8228	09/01/2010	268361	AIR S - make air connection	make a air connection with one way valve to give air from w/shop		368306
8228	08/31/2010	268022	WHEEL NUT SQUIRREL			368306
8228	08/31/2010	268063	12V 200AMP 1100CCA			368306
8228	08/31/2010	268063	WING NUT BATTERY TERMINAL NEG (BRASS)			368306
8228	08/31/2010	268063	Replace batteries	Replaced batteries		368306
8228	08/31/2010	268063	WING NUT BRASS BATTERY TERMINAL POSITIVE			368306
8228	08/31/2010	268022	DISC PADS SCANIA L94+0500 MERC			368306
8228	08/30/2010	268022	Remove & fit rear tyres	Removed & fitted		368306
8228	08/30/2010	268022	Check rear brake pads	Removed rear wheel & checked brake pads brake pdas cooked replaced pads & torqued w/nuts		368306
8228	08/26/2010	267370	DIP STICK MERCEDES 0500LE			367903
8228	08/25/2010	267370	EN - Need to replace dip stick	Replaced		367903
8228	08/23/2010	267001	Bus wont start	Jump started		367146
8228	08/23/2010	267001	Bus wont start	Jump started		367146
8228	08/18/2010	265931	COMPRESSOR OIL AIR CON			365983

8228	08/18/2010	265931	FILTER DRIER THERMO KING	D Service	365983
8228	08/14/2010	265931		Replace filter drier	365105
8228	08/14/2010	265931		Replace compressor oil	365105
8228	08/14/2010	265931		Check & replace electric motor brushes	365105
8228	08/14/2010	265931		Check boost pump condition	365105
8228	08/14/2010	265931		C Service	365105
8228	08/14/2010	265931		Replace compressor oil	365105
8228	08/14/2010	265931		Replace filter drier	365105
8228	08/14/2010	265931		B Service	365105
8228	08/14/2010	265931		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	365105
8228	08/14/2010	265931		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	365105
8228	08/14/2010	265931		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	365105
8228	08/14/2010	265931		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	365105
8228	08/14/2010	265931		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	365105
8228	08/14/2010	265931		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	365105
8228	08/14/2010	265931	Replaced broken compressor mount bolts X 2	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	365105
8228	08/14/2010	265931		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	365105
8228	08/14/2010	265931		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	365105
8228	08/14/2010	265931		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	365105
8228	08/14/2010	265931		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	365105
8228	08/13/2010	265759	Add coolant	Added	364826
8228	08/05/2010	264647	SUS - O/R/R air bag leak (Checked 03/06/10 servicable HKS)	Replaced airbag	362459
8228	08/05/2010	264647	Ops Entered - Fault - Fuel - Route: - Change over from Sh	Checked OK	362459
8228	07/30/2010	264175	Floor dirty drink spill	Mopped floor	360891
8228	07/29/2010	263926	Clean graffiti	Cleaned	360441
8228	07/29/2010	263926	C a/c pipe hose clamp loose	Secure on intake manifold side	360441
8228	07/27/2010	263680	Clean a/c filter	Cleaned	359977
8228	07/27/2010	263680	Clean engine	S/cleaned	359977
8228	07/26/2010	263503	Door fault - getting stuck	Repaired by Dysons 26/07/10	358687
8228	07/21/2010	262583	Air dryer leaking	Attended by Dysons. Replaced air dryer . Total cost \$932.40	358136
8228	07/19/2010	262490	Clean graffiti	Cleaned	357331
8228	07/15/2010	262092	PD - Drv entered - Passenger Doors Require Adjusted	Refit door rubber	356558
8228	07/15/2010	262092	N/S/R acc dam	Temp repair to NS panel	356558
8228	07/09/2010	261354	Air leaking from front of bus	Checked for air leak found air line fitting snapped off remove fitting from 8235 & fit to bus	354856
8228	07/07/2010	264650	Replace both front tyres	Replaced by Dysons \$30.47	362459
8228	07/04/2010	264649	Bus wont start	Jump started by Dysons \$40.63	362459
8228	06/21/2010	259002	ELE - jump start bus	jump started	349557
8228	06/21/2010	259002	ELE - jump start bus	jump started	349557
8228	06/18/2010	257464	POS 1 11R NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G78274 Receiving #:79970 Date :2010-06-18 R	349195
8228	06/17/2010	258166	CLIPPARD VALVE DOOR OPEN/CLOSE		349081
8228	06/16/2010	258166	CALIPER SHEAR ADAPTOR		349081
8228	06/16/2010	258166	Drv entered - Brakes Shuddering	Checked end play found was NSF 0.10mm and OSF 0.10mm so I adjusted until both were 0.02mm and checked for play the play was still excessive so I checked end play again and it was within spec I hit the hub with plastic hammer to find I got a further 2.40mm from the OSF and a further 0.10mm from the NSF I readjusted	349081
8228	06/16/2010	258166	Drv entered - Brakes Shuddering	Repaired by Mercedes Benz. Reprogram g/box ECU	349081
8228	06/11/2010	258165	BREAK - Breakdown Wellington Rd Mulgrave. No Brakes. Out	c/o bus 8385 at 8:05pm. Returned to depot. Sometimes brake light indicator on dash on. Try to find the fault code.	349081
8228	06/11/2010	258166	Drv entered - Brakes Shuddering	Try to find fault code? c/o	349081
8228	06/09/2010	257022	POS 2 11R NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G78185 Receiving #:79725 Date :2010-06-09	348319
8228	06/08/2010	257464	replace worn tyre pos 1	replace worn tyre pos 1	347988
8228	06/08/2010	257566	Change tyre No 1	Changed	347988
8228	06/08/2010	257566	Change tyre No 1	Changed	347988
8228	06/07/2010	257014	0500 COOLANT LOW LEVEL SENDER	Creditor #:MUL001 MULTISPARES LTD P/O #:G78173 Receiving #:79592 Date :2010-06-07	347591
8228	06/07/2010	252553	AIR CONDITIONING REPAIR comp I	Creditor #:CEL001 22 CELSIUS P/O #:G76966 Receiving #:79582 Date :2010-06-07	347591
8228	06/04/2010	257022	replace worn tyre pos 2	replace worn tyre pos 2	346792
8228	06/03/2010	257014	Change tyre # 2	Changed	346613
8228	06/03/2010	257093	Drv entered - Vandalism Graffiti	Cleaned	346613
8228	06/03/2010	256960	Random vehikle audit	Inspected at service	346613
8228	06/03/2010	257093	Drv entered - Gearbox Harsh Thumping	Checked OK	346613
8228	06/03/2010	257014	Change coolant sensor	Changed sensor	346613
8228	06/03/2010	257014	Change coolant sensor	Assist Allan to change sensor	346613
8228	06/03/2010	257014	Change coolant sensor	R/tested to check for warning light	346613
8228	06/03/2010	256978	BR - Brake light on dash comes intermittently	R/tested for brake lights OK	346613
8228	06/03/2010	256939		A Service & Bus Safety Inspection	346613
8228	06/03/2010	256939		A Service & Bus Safety Inspection	346613
8228	06/03/2010	256939		Tension Wheel Nuts To OEM Specification	346613
8228	06/03/2010	256939		Grease AC Compressor Clutch Bearing	346613
8228	06/03/2010	256939		Clean A/C filter	346613
8228	06/02/2010	256854	COOL - Drv entered - Eng Cool Coolant Low	Removed low coolant level sensor wire connection cleaned up put back r/tested OK	346613
8228	06/02/2010	256853	Breakdown - Springvale Station - OUT 3.30 pm BACK 4.30 pm -	C/O bus 8239. Met bus Low Coolant alarm was on returned (removed and cleaned sensor wire connection replaced checked OK)	346613
8228	06/02/2010	256795	SNAP ON SILENCER A/DRYER		346613
8228	06/01/2010	256795	Check air dryer	Replaced silencer	346613
8228	05/28/2010	256213	ELE - coolant warning alarm going off yet temp was ok	check warning light is ok	346613
8228	05/28/2010	256213	BODY - front door latch loose	checked front door latch is ok	346613
8228	05/26/2010	255967	ELE - fit indicator switch	fitted	346613
8228	05/21/2010	252955	POS 3 11R NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G77053 Receiving #:79078 Date :2010-05-21	346613
8228	05/19/2010	255019	ENG C - coolant light on	checked coolant low. fill coolant road test.	345988
8228	05/18/2010	254843	BREAK - Breakdown Clow St. Out 9pm in 9:30pm. Coolant fa	c/o bus 239. Coolant fault.	345623
8228	05/17/2010	254586	ELE - install e tag	installed	345224
8228	05/12/2010	254146	Drv entered - Vandalism Floor Trim	Repaired	344488
8228	05/05/2010	262154	Replace air dryer		342418
8228	05/04/2010	252955	REPLACE WORN TYRES POS 3-4	Replaced	342001
8228	05/03/2010	252561	Replace both lh side tyres rear	Replaced	341925
8228	05/03/2010	252561	Drv entered - Gearbox Harsh Thumping	Checked OK	341925
8228	05/03/2010	252561	Replace lh top indicator assembly	Replaced	341925
8228	05/03/2010	252561	BR - Check rear brakes	R/tested brakes OK fuelled & parked	341925
8228	05/03/2010	252561	BR - Check rear brakes	Removed both rear side brake pads adjusted checked rotor thicknessmeasured new pads fitted. Brakes adjusted.	341925
8228	05/03/2010	252561	DISC PADS SCANIA L94+0500 MERC		341925
8228	05/01/2010	252553	Drv entered - Air Cond Air Conditioner	Repaired by 22 celsius	341925
8228	04/30/2010	252553	AC - A/C compressor leak		341925
8228	04/29/2010	252560	Breakdown - Stud Park Shopping Centre - OUT 6.00 pm BACK 7.	C/O bus 8387. Returned to depot. (Removed n/s/r tyres & checked brake pads both sides pads are worn unevenly. Replaced)	341679
8228	04/29/2010	252561	BR - Check rear brakes	Assist Siri to check brake pads replaced tyre & parked	341679
8228	04/29/2010	252561	BR - Check rear brakes	Removed n/s/r tyres & checked the brake pads rear both side brake pads are worn unevenly	341679
8228	04/21/2010	251519	Add coolant	Added	339769
8228	04/21/2010	251552	HALDEX COIL BASE OIL SEPARATOR		339769

8228	04/21/2010	251552	WATER SEPERATOR SCANIA+VOLVO			339769
8228	04/21/2010	251552	Drv entered - Brakes Shuddering	R/tested but did not find any fault		339769
8228	04/21/2010	251552	Air leak somewhere	Overhauled seperator		339769
8228	04/19/2010	251286	Clean a/c filter	Cleaned		338926
8228	04/15/2010	250966	Clean a/c filter	Cleaned		337200
8228	04/14/2010	250830	Remove graffiti	Removed		337200
8228	04/14/2010	250836	COMM - radio stuck on channel 1	Checked that is normal		337200
8228	04/14/2010	250830	Replace pass seat rear	Replaced		337200
8228	04/14/2010	250684		Clean A/C filter		337200
8228	04/14/2010	250684		Grease AC Compressor Clutch Bearing		337200
8228	04/14/2010	250684		Tension Wheel Nuts To OEM Specification		337200
8228	04/14/2010	250684		A Service & Bus Safety Inspection		337200
8228	04/13/2010	250712	Replace dash globe	Checked OK		336777
8228	04/08/2010	250013	Clean a/c filter	Cleaned		334766
8228	04/07/2010	249868	GLOBE HIGH BEAM 24V70W H1			334486
8228	04/07/2010	249868	R/H headlamp n/w	Replaced globe		334486
8228	04/06/2010	249769	Bus wont start	Jump started		334038
8228	03/26/2010	248878	Clean a/c filter	Cleaned		332067
8228	03/22/2010	248301	ALTERNATOR SPECIAL BOLT			330653
8228	03/22/2010	248301	ENG - Top alternator mount bolt broken	Assist mech to fix alt bracket		330653
8228	03/22/2010	248301	ENG - Top alternator mount bolt broken	Welded broken parts		330653
8228	03/22/2010	248301	ENG - Top alternator mount bolt broken	Removed alternator & 3 broken bolts from alt bracket drill hole refit bracket and alternator		330653
8228	03/11/2010	247121	32MM LOOSE WHEEL NUT INDICATOR			326883
8228	03/11/2010	247259	Clean radiator	S/cleaned		326883
8228	03/11/2010	247217	Add coolant	Added		326883
8228	03/11/2010	247121		Clean A/C filter		326883
8228	03/11/2010	247121		Grease AC Compressor Clutch Bearing		326883
8228	03/11/2010	247121		A Service & Bus Safety Inspection		326883
8228	03/11/2010	247121		Tension Wheel Nuts To OEM Specification		326883
8228	03/11/2010	247121		A Service & Bus Safety Inspection		326883
8228	03/09/2010	246492	H/D - Drivers fan bearing defective	repaired road test check for leak and over heating		326148
8228	03/09/2010	246492	H/D - Drivers fan bearing defective	checked ok		326148
8228	03/09/2010	246492	H/D - Drivers fan bearing defective	Checked OK		326148
8228	03/08/2010	246492	H/D - Drivers fan bearing defective	Checked fan working on both sides		326148
8228	03/08/2010	246891	Air leak	Checked for air leak OK		326148
8228	03/05/2010	246677	Remove graffiti	Removed		324926
8228	03/04/2010	246492	COOLANT PIPE RAD-PUMP	Creditor #.:WHT001 WHITEHORSE TRUCKS P/O #.:G74718 Receiving #:76830 Date :2010-03-04 228		326148
8228	03/03/2010	246492	E/C Replace upper radiator pipe			326148
8228	03/02/2010	246282	Clean a/c filter	Cleaned		323726
8228	03/01/2010	360683	Install Give way decals	Creditor #.:ATT001 ATTITUDE SIGNS P/O #.:G109958 Receiving #:110892 Date :2012-07-04		529516
8228	02/23/2010	239145	solenoid valve	Creditor #.:WHT001 WHITEHORSE TRUCKS P/O #.:G72811 Receiving #:76487 Date :2010-02-23		321658
8228	02/18/2010	244265	POS 5-6 11R225 NEW	Creditor #.:BEA001 BEAUREPAIRES P/O #.:G74774 Receiving #:76387 Date :2010-02-18		319886
8228	02/16/2010	246492	Clean a/c filter	Cleaned		319256
8228	02/16/2010	244661	Replace headlight globe	Replaced		319256
8228	02/16/2010	244661	GLOBE HIGH BEAM 24V70W H1			319256
8228	02/16/2010	244661	The park light is n/w on front l/s			319256
8228	02/15/2010	244765	15LTR RUBBISH BINS	Checked OK		319256
8228	02/15/2010	244765	Replace bin			318857
8228	02/12/2010	244265	Replace tyre pos 56 - worn	Given to driver		317937
8228	02/11/2010	244308	Change tyres o/s/r	Replaced		317937
8228	02/11/2010	244125		Changed		317937
8228	02/11/2010	244125		Tension Wheel Nuts to Spec		317937
8228	02/11/2010	244125		A Service & Bus Safety Inspection		317937
8228	02/11/2010	244125		D-Service & Bus Safety Inspection		317937
8228	02/11/2010	244125		Replace engine oil breather kit		317937
8228	02/11/2010	244125	OIL FILTER 1725+0500LE			317937
8228	02/11/2010	244125	ENGINE OIL BREATHER KIT 0500LE			317937
8228	02/11/2010	244125		Grease AC Compressor Clutch Bearing		317937
8228	02/11/2010	244125	AIR FILTER MERC 0500LE			317937
8228	02/11/2010	244125	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL			317937
8228	02/11/2010	244125		Grease AC Compressor Clutch Bearing		317937
8228	02/11/2010	244125		Tension Wheel Nuts To OEM Specification		317937
8228	02/11/2010	244125		A Service & Bus Safety Inspection		317937
8228	02/11/2010	244125		Clean A/C filter		317937
8228	02/10/2010	241786	A0044297644 REAR RELAY VALVE	Creditor #.:WHT001 WHITEHORSE TRUCKS P/O #.:G74542 Receiving #:76141 Date :2010-02-10		317604
8228	02/10/2010	241786	49G1513W repair kit for relay	Creditor #.:MUL001 MULTISPARES LTD P/O #.:G74602 Receiving #:76107 Date :2010-02-10		317604
8228	02/09/2010	243884	Clean a/c filter	Cleaned		317159
8228	02/08/2010	241786	Rear relay valve leaking air - near diff	Replaced		317159
8228	02/05/2010	243370	A/C broken			315988
8228	02/05/2010	243370	A/C compressor oil leak	Tested found discharge O ring failed replaced O ring tested OK		315988
8228	02/04/2010	241786	Rear relay valve leaking air - near diff	Removed & refitted rear brake relay valve - wrong parts		316283
8228	02/04/2010	241786	Rear relay valve leaking air - near diff	wrong parts		311905
8228	01/27/2010	241786	brake relay valve	Creditor #.:WHT001 WHITEHORSE TRUCKS P/O #.:G74213 Receiving #:75765 Date :2010-01-27		313526
8228	01/25/2010	242188	Clean a/c filter	Cleaned		312635
8228	01/20/2010	241793	Dash light n/w	checked ok.		311905
8228	01/20/2010	241793	Dash light n/w	Replaced		311905
8228	01/20/2010	241793	No broom	Replaced		311905
8228	01/20/2010	241793	BROOM HEAD (09803211)			311905
8228	01/20/2010	241793	BROOM HANDLE (8232715)			311905
8228	01/20/2010	241793	checked ok.	Replaced		311905
8228	01/19/2010	241601	Clean a/c filter	Cleaned		311456
8228	01/19/2010	241627	INDICATOR LAMP SUIT B12BLE			311456
8228	01/19/2010	241627	GLOBE INDICATOR 24V-18W SINGLE CONTACT			311456
8228	01/19/2010	241627	Left side front indicator is broken	Changed indicator light & globe		311456
8228	01/19/2010	241646	Ops Entered - Fault - Fuel - Route: 901 - Dandenong Station	Checked fuel & fuel gauge		311456
8228	01/14/2010	241247	Add coolant	Added		310197
8228	01/13/2010	237878	POS 3 11R225 NEW	Creditor #.:BEA001 BEAUREPAIRES P/O #.:G72955 Receiving #:75401 Date :2010-01-13		309793
8228	01/12/2010	240964	Add coolant	Added		309408
8228	01/11/2010	240785	clean a/c filters	clean filters		309217
8228	01/11/2010	240877	Clean radiator	S/cleaned		309217
8228	01/11/2010	240775		Tension Wheel Nuts To OEM Specification		309217
8228	01/11/2010	240775		A Service & Bus Safety Inspection		309408
8228	01/11/2010	240775		Clean A/C filter		309217
8228	01/11/2010	240775		Grease AC Compressor Clutch Bearing		309217

8228	01/11/2010	240775	A Service & Bus Safety Inspection	309217
8228	01/05/2010	240102	Road tested but unable to find fault also checked brake pads its ok. not able to find books or cd to find function above brakes.	307965
8228	01/04/2010	240102	Road test checking for brake problems check front and rear pads - check computer for faults O/s/f brakes locking up u/s	307800
8228	01/02/2010	239972	replaced drivers side wiper and adjust all. Also refers to 78196.	307412
8228	01/02/2010	239973	checked a/c ok.	307412
8228	12/31/2009	239824	Added	307011
8228	12/31/2009	239824	Replaced	307412
8228	12/31/2009	239824	LED CLEARANCE LIGHT (RED AMBER)	307412
8228	12/31/2009	239824	Replaced	307011
8228	12/31/2009	239824	Replaced	307011
8228	12/31/2009	239824	Refixed	307011
8228	12/31/2009	239824	Refixed	307011
8228	12/31/2009	239824	fixed rear top window glass beading.	307412
8228	12/28/2009	239566	Checked g/box oil OK r/tested NO fault found	306152
8228	12/21/2009	235003	Creditor #:ROA001 Road Safety Inspections P/O #:G72073 Receiving #:74848 Date :2009-12-21	303973
8228	12/21/2009	239145		303973
8228	12/21/2009	239145	Creditor #:MUL001 MULTISPARES LTD P/O #:G73398 Receiving #:74856 Date :2009-12-21 228	303973
8228	12/21/2009	239145	Checked and found relay valve leaking removed rekittd and fitted back r/tested topped up g/box oil	303973
8228	12/18/2009	238959	Cleaned	303191
8228	12/16/2009	238715	Added	302745
8228	12/10/2009	238257	Repaired w/screen washer hose o/s & n/s	300483
8228	12/10/2009	238257	Repaired	300483
8228	12/10/2009	238093	ZF Transmission Filter	300203
8228	12/10/2009	238093	Bus Safety Inspection	300203
8228	12/10/2009	238093	ZF Ecofluid A Plus Synthetic Transmission Oil	300203
8228	12/10/2009	238093	Service T - Replace Transmission Oil & Filter	300203
8228	12/10/2009	238093	Grease AC Compressor Clutch Bearing	300203
8228	12/10/2009	238093	Tension Wheel Nuts To OEM Specification	300203
8228	12/10/2009	238093	A Service & Bus Safety Inspection	300203
8228	12/10/2009	238093	Clean A/C filter	300203
8228	12/08/2009	237878	Replaced	299823
8228	12/08/2009	237910	Changed	299823
8228	12/08/2009	237910	Replaced 34 tyres and torqued w/nuts	299823
8228	12/02/2009	237307	Cleaned	297387
8228	12/01/2009	235736	Creditor #:BEA001 BEAUREPAIRES P/O #:G72346 Receiving #:74268 Date :2009-12-01	296694
8228	11/21/2009	236306	Cleaned graffiti from seats walls floor & windows	294360
8228	11/18/2009	235736		293418
8228	11/18/2009	236039	Replaced & torqued w/nuts	293555
8228	11/18/2009	236039	Replaced	293555
8228	11/18/2009	236039	Replaced	293418
8228	11/18/2009	236084	A/C BELT 0500 BENZ	293555
8228	11/18/2009	236084	Breakdown - Frankston Dandenong Rd - OUT 9.00 am BACK 10.00	293418
8228	11/15/2009	235003	BC 139449	291016
8228	11/11/2009	235170	Checked OK	291016
8228	11/11/2009	235170	Cleaned	291016
8228	11/11/2009	235170	Cleaned	291016
8228	11/11/2009	235142	Cleaned	291016
8228	11/11/2009	235170	BRAKE+ CLUTCH PEDAL PAD 0500LE	291136
8228	11/11/2009	235170	Brake pedal pad worn	291016
8228	11/11/2009	235070		291136
8228	11/11/2009	235070	A Service & Bus Safety Inspection	291016
8228	11/11/2009	235070	A Service & Bus Safety Inspection	291016
8228	11/11/2009	235070	Tension Wheel Nuts To OEM Specification	291016
8228	11/11/2009	235070	Grease AC Compressor Clutch Bearing	291016
8228	11/11/2009	235070	Clean A/C filter	291016
8228	11/09/2009	234240	Creditor #:ASS001 ASSOCIATED TOWING P/O #:G71860 Receiving #:73552 Date :2009-11-09	290287
8228	11/05/2009	234523		289264
8228	11/05/2009	234523	Rekittd	288884
8228	11/02/2009	234243	Checked door override switch on turned off OK	287989
8228	11/02/2009	234240	Stripped and serviced air dryer	288603
8228	10/31/2009	234156		287989
8228	10/31/2009	234156	Removed clutch assembly & pressure tested found shaft seal had failed replaced seal etc pressure tested again all OK. VAC system found unit would not pull under 2000 micron traced back discharge service valve O ring replaced O ring pressure tested & vac tested again all OK charge system & commission tested OK	287989
8228	10/31/2009	234156	Defect # 788127788978802	287989
8228	10/31/2009	234156		287989
8228	10/30/2009	233397	Cleaned	287177
8228	10/27/2009	233538		287230
8228	10/27/2009	233538	Replaced	287187
8228	10/26/2009	232920	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	287167
8228	10/26/2009	232920	Inspect radiator and charge air cooler for dirt - clean	287167
8228	10/26/2009	232920	Test coolant level - top up if required to equate to 37C frost protection	287167
8228	10/26/2009	232920	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	287167
8228	10/26/2009	233353	checked ok	287177
8228	10/26/2009	233352	checked ok.	287177
8228	10/26/2009	233668	unmask fleet numbers	287177
8228	10/26/2009	232920		287187
8228	10/23/2009	233220	L/H LOWER SEAT LUMBAR BUTTONS	287177
8228	10/23/2009	233220	Polished	287177
8228	10/23/2009	233220	Checked OK	287177
8228	10/23/2009	233220	Touched up	287177
8228	10/23/2009	233220	Button only OK	287177
8228	10/23/2009	233220	Repaired top header & N/S/R corner & painted	287177
8228	10/23/2009	233220	Polished	287177
8228	10/22/2009	233042	Cleaned	287177
8228	10/22/2009	233042	Polished	287177
8228	10/22/2009	233042		287177
8228	10/22/2009	233042	Secured	287177
8228	10/22/2009	233042	Repaired 3	287177
8228	10/22/2009	233042	Painted	287177
8228	10/22/2009	233042	Replaced	287177
8228	10/22/2009	233042	Painted	287177
8228	10/22/2009	233042	Replaced	287177
8228	10/22/2009	233042	Replaced	287177
8228	10/22/2009	233042	Cleaned	287177

8228	10/22/2009	233042	Replace emergency exit decals with safety hammers	Checked all OK	287177
8228	10/21/2009	232920		R.S.I inspection of bus	287177
8228	10/21/2009	232920		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NMTORQUE AFTER ENG HAS COOLED FOR 30 MIN.	287177
8228	10/21/2009	232920		Replace final drive oil	287167
8228	10/21/2009	232920		Check oil level in transmission - top up if required	287167
8228	10/21/2009	232920		Check and clean cartridge in dry tyre air cleaner	287167
8228	10/21/2009	232920		Replace pre and main fuel filters	287167
8228	10/21/2009	232920		Replace air dryer cansiter clean silence and drain reservoir	287167
8228	10/21/2009	232920		Replace angle drive oil	287167
8228	10/21/2009	232920		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NMTORQUE AFTER ENG HAS COOLED FOR 30 MIN.	287167
8228	10/21/2009	232920		Replace power steering filter and check level (Replace oil if required)	287167
8228	10/21/2009	232920	FUEL FILTER MERC 0500LE		287167
8228	10/21/2009	232920	FUEL FILTER 0500LE		287167
8228	10/21/2009	232920	AIR DRYER CANISTER VOLVO+ NL202		287167
8228	10/21/2009	232920	POWER STEER FILTER B10M		287167
8228	10/21/2009	232920		Replace final drive oil	287177
8228	10/21/2009	232855	Annual body check	inspected	287167
8228	10/21/2009	233135	clean graffitti	cleaned graffitti	287167
8228	10/21/2009	232920	O RING B12BLE INTERCOOLER		287177
8228	10/15/2009	232211	clean a/c filter	cleaned a/c filter	284777
8228	10/12/2009	231657	A/C BELT 0500 BENZ		284044
8228	10/12/2009	231657	change main belt	changed main belt	283812
8228	10/12/2009	231738	Cracks in main belt	Replaced	283812
8228	10/06/2009	231257		Clean A/C filter	282387
8228	10/06/2009	231257		Grease AC Compressor Clutch Bearing	282387
8228	10/06/2009	231257		Tension Wheel Nuts To OEM Specification	282387
8228	10/06/2009	231257	Service	service completed.	282554
8228	10/06/2009	231257	Service	adjusted top alternator belt	282554
8228	10/06/2009	231257	Service	A Service & Bus Safety Inspection. completed.	282387
8228	09/30/2009	230722	Add coolant	Added	280141
8228	09/25/2009	220091	SUPPLY AND FIT DECALS	Creditor #.:ATT001 ATTITUDE SIGNS P/O #:G68033 Receiving #:72393 Date :2009-09-25	278530
8228	09/22/2009	229313	TOW BUS TO DEPOT	Creditor #.:ASS001 ASSOCIATED TOWING P/O #:G70537 Receiving #:72300 Date :2009-09-22	277465
8228	09/17/2009	229403	Air drayer air leak	Rekit complete air dryer & r/tested	275325
8228	09/16/2009	229403	Air drayer air leak	Replaced air dryer kit but still leaking air need to remove again	275325
8228	09/16/2009	229403	SINGLE AIR DRYER KIT 0500LE		275325
8228	09/15/2009	229313	Breakdown - Oakleigh Station - OUT 9.30 pm BACK 1.30 am - W	Used van 619. Couldn't fix towed bus back to depot (OVERHAULED AIR DRYER)	275325
8228	09/09/2009	228556	OIL FILTER 1725+0500LE		273215
8228	09/09/2009	228556	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		273215
8228	09/09/2009	228556		Tension Wheel Nuts to Spec	273215
8228	09/09/2009	228556		A Service & Bus Safety Inspection	273215
8228	09/09/2009	228556		D-Service & Bus Safety Inspection	273215
8228	09/09/2009	228556		Grease AC Compressor Clutch Bearing	273215
8228	09/09/2009	228556	AIR FILTER MERC 0500LE		273215
8228	09/09/2009	228556		A Service & Bus Safety Inspection	273215
8228	09/09/2009	228556		Grease AC Compressor Clutch Bearing	273215
8228	09/09/2009	228556		Tension Wheel Nuts To OEM Specification	273215
8228	09/09/2009	228556		Clean A/C filter	273215
8228	09/02/2009	227967	L/H mirror very loose	Secured mirror	270685
8228	09/02/2009	227967	L/H mirror very loose	Secured mirror	270685
8228	08/27/2009	227407	Add coolant	Added	268704
8228	08/26/2009	227182		C Service	267984
8228	08/26/2009	227182		Replace filter drier	267984
8228	08/26/2009	227182		Replace compressor oil	267984
8228	08/26/2009	227182		B Service	267984
8228	08/26/2009	227182	Pressure tested compressor and leak check with electronic &	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	267984
8228	08/26/2009	227182		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	267984
8228	08/26/2009	227182		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	267984
8228	08/26/2009	227182		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	267984
8228	08/26/2009	227182		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	267984
8228	08/26/2009	227182		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	267984
8228	08/26/2009	227182		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	267984
8228	08/26/2009	227182		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	267984
8228	08/26/2009	227182		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	267984
8228	08/26/2009	227182		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	267984
8228	08/26/2009	227182		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	267984
8228	08/25/2009	227134	Add coolant	Added	267984
8228	08/14/2009	226126	Add coolant	Added	264381
8228	08/14/2009	226042		A Service & Bus Safety Inspection	263986
8228	08/14/2009	226042		A Service & Bus Safety Inspection	264381
8228	08/14/2009	226042		Clean A/C filter	263986
8228	08/14/2009	226042		Grease AC Compressor Clutch Bearing	263986
8228	08/14/2009	226042		Tension Wheel Nuts To OEM Specification	263986
8228	08/10/2009	225697	check amber light on dash	Checked no fault found road tested	262942
8228	08/09/2009	225638	BRAZILLIAN MIRROR L/H		262942
8228	08/09/2009	225638	L/H mirror brake	Mirror has changed	262571
8228	08/08/2009	225466	Ops Entered - Fault - Fuel - Route: 901 - Kirkham Rd Relie	Check fuel system no fault found	261996
8228	08/04/2009	223403	POS 5 11R225 NEW	Creditor #.:BEA001 BEAUREPAIRES P/O #:G68772 Receiving #:70843 Date :2009-08-04	261317
8228	07/27/2009	224252	INSTRUMENT GLOBE 24V3W		258947
8228	07/27/2009	224252	Replace R/H/S front park light	Replaced	258621
8228	07/24/2009	224173	No rubbish bin	Replaced bin	257649
8228	07/20/2009	223403	Replace tyre pos 5 - bald	Replaced	255517
8228	07/17/2009	223409	Change tyre # 5	Changed	255517
8228	07/17/2009	223409	Change tyre # 5	Changed	255517
8228	07/17/2009	223338		Tension Wheel Nuts To OEM Specification	255517
8228	07/17/2009	223338		Clean A/C filter	255517
8228	07/17/2009	223338		Grease AC Compressor Clutch Bearing	255517
8228	07/17/2009	223338		A Service & Bus Safety Inspection	255517
8228	07/17/2009	223338		A Service & Bus Safety Inspection	255517
8228	06/25/2009	221266	GLOBE HIGH BEAM 24V70W H1		248909
8228	06/25/2009	221266	Ops Entered - Fault - Elec & Light - Route: 900 - Stud Park	Replaced headlight globe	248909
8228	06/25/2009	221266	No R/H headlight	Creditor #.:SMA001 SMART ALUMINIUM P/O #:G67763 Receiving #:69657 Date :2009-06-23	248909
8228	06/23/2009	220091	40X40X6CM ANGLE X1 LEN	Creditor #.:SMA001 SMART ALUMINIUM P/O #:G67746 Receiving #:69520 Date :2009-06-18	248662
8228	06/18/2009	220091	3MM X 1200MM X 2400MM FLAT ALU		246685

8228	06/17/2009	220091	Left side back panel over tyre (panel in the bus)		246640
8228	06/17/2009	220091	R/R panels No4 & No5 repair damaged areas & prepare & repai	Repairs and paintwork completed	246640
8228	06/17/2009	220091	Accident Damaged # 21110 R/R.rear door aperture rubbern/s	Repairs and paintwork completed	246640
8228	06/16/2009	220091	AMBER REFLECTOR SIDE MOUNT		246640
8228	06/16/2009	220091	GAS STAY 270x500 400NM		246640
8228	06/16/2009	220091	R/R panels No4 & No5 repair damaged areas & prepare & repai	Paintwork done	246640
8228	06/16/2009	220091	Accident Damaged # 21110 R/R.rear door aperture rubbern/s	Paintwork done	246640
8228	06/16/2009	220091	STEEL CLAW CATCHES		246640
8228	06/15/2009	220091	Accident Damaged # 21110 R/R.rear door aperture rubbern/s	Fabricated panels	246640
8228	06/12/2009	220091	Accident Damaged # 21110 R/R.rear door aperture rubbern/s	Fabricated panels	246640
8228	06/12/2009	220091	R/R panels No4 & No5 repair damaged areas & prepare & repai	Fabricated panels	246640
8228	06/05/2009	219577	Driver heater still n/w please fix	Replaced broken heater vent	245941
8228	06/05/2009	219669	Repair air leak on top of g/box	Repaired	246281
8228	06/05/2009	219669	Repair air leak on top of g/box	Repaired	245941
8228	06/05/2009	219553		Clean A/C filter	245941
8228	06/05/2009	219553		Grease AC Compressor Clutch Bearing	245941
8228	06/05/2009	219553		A Service & Bus Safety Inspection	246281
8228	06/05/2009	219553		Tension Wheel Nuts To OEM Specification	245941
8228	06/05/2009	219553		A Service & Bus Safety Inspection	245941
8228	06/01/2009	219088	INSTRUMENT GLOBE 24V3W		244375
8228	06/01/2009	219088	Replace front L/H park light	Replaced	244375
8228	05/19/2009	217825	Add oil	Added	239943
8228	05/18/2009	217772	Door wont close	Repair door sensitive egrs switch and adjust	239744
8228	05/16/2009	217702	EMERGENCY EXIT BUTTON PULL COVER		239366
8228	05/16/2009	217702	SENSITIVE EDGE DOOR SWITCH		239366
8228	05/16/2009	217702	Battery needs s/clean	Cleaned	239366
8228	05/15/2009	216996	POS 3 11R225 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G66735 Receiving #:68628 Date :2009-05-15	239106
8228	05/15/2009	216836	POS 6 11R225 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G66704 Receiving #:68627 Date :2009-05-15	239106
8228	05/15/2009	217687	Repair air leak next to air dryer	Repaired leak	239366
8228	05/15/2009	217687	Repair air leak next to air dryer	Repaired leak	239106
8228	05/14/2009	217448	Add oil	Added	238725
8228	05/11/2009	216996	Replace tyre pos 3 - flat spot	Replaced	237511
8228	05/11/2009	217043	Rear doors need adjusting	Adjusted rear door	237511
8228	05/09/2009	217035	Change N/S rear tyres	Changed	237134
8228	05/08/2009	216836	Replace tyre pos 6 - bald	Replaced	236594
8228	05/08/2009	217022	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		237134
8228	05/08/2009	217022	DISC PADS SCANIA L94+0500 MERC		237134
8228	05/08/2009	217022	Low brake light coming on	Fit front disc pads & torqued w/nuts	236876
8228	05/08/2009	217022	Air leak behind air dryer canister at regulator valve	Found bad air leak at 6way valve overhauled & r/tested	236876
8228	05/07/2009	216851	Replace wiper blades	Replaced	236594
8228	05/07/2009	216851	Change O/S/R outer tyre	Changed	236876
8228	05/07/2009	216851	Change O/S/R outer tyre	Changed	236594
8228	05/07/2009	216771	Random vehicle Audit	Completed at service	236594
8228	05/07/2009	216770		A Service & Bus Safety Inspection	236876
8228	05/07/2009	216770	WIPER REFILL SUIT TX800+TX900		236594
8228	05/07/2009	216770		Clean A/C filter	236594
8228	05/07/2009	216770		Grease AC Compressor Clutch Bearing	236594
8228	05/07/2009	216770		Tension Wheel Nuts To OEM Specification	236594
8228	05/07/2009	216770		A Service & Bus Safety Inspection	236594
8228	05/01/2009	216251	Adjust rear door sensor	Adjusted	234199
8228	04/23/2009	215461	R/H/S headlight blown	Replaced globe	231709
8228	04/20/2009	214976	Add coolant	Added	230543
8228	04/16/2009	214690	Rear door wont close	Found sensor faulty	229735
8228	04/08/2009	214080	OIL FILTER 1725+0500LE		227873
8228	04/08/2009	214080	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		227873
8228	04/08/2009	214080		Tension Wheel Nuts to Spec	227873
8228	04/08/2009	214080		A Service	227873
8228	04/08/2009	214080		D-Service	227873
8228	04/08/2009	214080	R/tested	D-Service	228185
8228	04/08/2009	214080		Grease AC Compressor Clutch Bearing	227873
8228	04/08/2009	214080	AIR FILTER MERC 0500LE		227873
8228	04/08/2009	214080		Clean A/C filter	227873
8228	04/08/2009	214080		Grease AC Compressor Clutch Bearing	227873
8228	04/08/2009	214080		Tension Wheel Nuts To OEM Specification	227873
8228	04/08/2009	214080		A Service	227873
8228	04/07/2009	213992	Add oil	Added	227592
8228	04/07/2009	213992	Add coolant	Added	227592
8228	04/06/2009	213267	POS 4-5 11R REAR NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G65610 Receiving #:67521 Date :2009-04-06	227211
8228	04/01/2009	213267	32MM LOOSE WHEEL NUT INDICATOR		225545
8228	04/01/2009	213267	Replace tyre pos 45 - irregular wearing	Replaced	225545
8228	04/01/2009	213450	Front wheels feel like they are square	Removed front wheels (12) & fit on rear (56) fit new tyres to front torqued all w/nuts	225545
8228	04/01/2009	213353	Replace tyres	Replaced	225545
8228	03/27/2009	212839	RELAY HOIST 24V 30-40AMP		224680
8228	03/27/2009	212841	Drv entered - Elec & Light Cab Light	Replaced globe	224328
8228	03/27/2009	212839	Drivers down light out - need light for ticket selling at n	Checked OK	224328
8228	03/27/2009	212839	Interior light over drivers head not lighting	Checked OK	224328
8228	03/27/2009	212839	Drivers down light out - need light for ticket selling at n	Checked OK	224328
8228	03/27/2009	212829	Drivers door light n/w	Checked wiring and air lines	224328
8228	03/25/2009	212626	Add coolant	Added	223597
8228	03/24/2009	211752	POS 3	Creditor #:BEA001 BEAUREPAIRES P/O #:G65213 Receiving #:67171 Date :2009-03-24	223150
8228	03/18/2009	211752	Replace tyre pos 3 - flat	Replaced	221003
8228	03/17/2009	211720	Flat tyre L/H side		220608
8228	03/17/2009	211720	Ops Entered - Whls & Tyres	Changed tyre & steam wash	220608
8228	03/17/2009	211720	Ops Entered - Fault - Whls & Tyres - Route: 901 - Kirkham		220608
8228	03/16/2009	211416	Pretrip inspection	Wrong bus has been Booked for trip inspection	220157
8228	03/16/2009	211590	INDICATOR LAMP SUIT B12BLE		220608
8228	03/16/2009	211590	Replace indicator cover front L/H/S	Replaced	220157
8228	03/13/2009	211526	Rear top L/H side roof A/C dust damaged	Replaced damaged air intake on N/S rear roof of bus replaced new out of store (needs painting)	219488
8228	03/13/2009	211526	Accident damage no 18957 - Replace air intake roof pod rep	As above	219488
8228	03/12/2009	211419	Recall fuel line upgrade SM730	Completed by W/horse	219488
8228	03/11/2009	210961		A Service	219488
8228	03/11/2009	210961		A Service	219201
8228	03/11/2009	210961		Grease AC Compressor Clutch Bearing	219201

8228	03/11/2009	210961	Tension Wheel Nuts To OEM Specification	219201
8228	03/11/2009	210961		219201
8228	03/09/2009	210909	Fit screws	218367
8228	03/05/2009	210579	Changed	217039
8228	03/05/2009	210567	Added	217039
8228	02/20/2009	209357	Added	213056
8228	02/16/2009	206939	Checked tyre Ok to run	206357
8228	02/16/2009	206939	Replaced alt belt	206357
8228	02/16/2009	206939	Repair connections	211659
8228	02/13/2009	206939		206357
8228	02/13/2009	206939	Found 3amp fuse blown traced back to unloader No 2. Repair wiring & plug run commission test	204924
8228	02/10/2009	208489	Checked found wires off - connected	210054
8228	02/10/2009	208453	Removed	210054
8228	02/10/2009	208316	A Service	209648
8228	02/10/2009	208316	Grease AC Compressor Clutch Bearing	209648
8228	02/10/2009	208316	Tension Wheel Nuts To OEM Specification	209648
8228	02/10/2009	208316	A Service	209648
8228	02/08/2009	206939	Cleaned a/c filter	209242
8228	02/05/2009	207974	Added	208312
8228	02/04/2009	176941	Creditor #::BEA001 BEAUREPAIRES P/O #:G59687 Receiving #:65701 Date :2009-02-04	208312
8228	02/01/2009	220091	Creditor #::ATT001 ATTITUDE SIGNS P/O #:G67601 Receiving #:70000 Date :2009-07-06	252111
8228	01/30/2009	206939	Checked a/c light stays on	206357
8228	01/29/2009	206939	Added	206076
8228	01/21/2009	206674	Reset side panel retarder switch	204165
8228	01/19/2009	206514	Refilled	203352
8228	01/09/2009	205730		200320
8228	01/09/2009	205730	Replaced	200320
8228	01/09/2009	205717	Added	200320
8228	01/08/2009	205595	Added	200320
8228	01/08/2009	205690	Checked OK	200320
8228	01/08/2009	205697	Replaced	200320
8228	01/08/2009	205611	ZF Ecofluid A Plus Synthetic Transmission Oil	200320
8228	01/08/2009	205611	Service T - Replace Transmission Oil & Filter	200320
8228	01/08/2009	205611	ZF Transmission Filter	200320
8228	01/08/2009	205611	Tension Wheel Nuts To OEM Specification	200320
8228	01/08/2009	205611	A Service	200320
8228	01/08/2009	205611	Grease AC Compressor Clutch Bearing	200320
8228	01/06/2009	204612	Creditor #::BEA001 BEAUREPAIRES P/O #:G63008 Receiving #:64946 Date :2009-01-06	199468
8228	12/29/2008	204612	Replaced	195883
8228	12/29/2008	204283	Creditor #::REB001 CIM CONCEPTS P/O #:G62904 Receiving #:64797 Date :2008-12-29 228	197485
8228	12/26/2008	204644	Replaced	196382
8228	12/24/2008	204267	Commission tested unit OK replaced noisy idler	194827
8228	12/22/2008	204267	Charge system with refrigerant and leak check found condensor fan relay had failed causing pressure releif valve to give replace relay tested up	194827
8228	12/22/2008	204385	Refilled	195224
8228	12/19/2008	204258		194827
8228	12/19/2008	204258	Checked OK	194827
8228	12/19/2008	204283	Replaced 2way with spare sent old one for repair	194827
8228	12/19/2008	204267		195091
8228	12/19/2008	204267		195091
8228	12/19/2008	204267		195091
8228	12/19/2008	204267		195091
8228	12/05/2008	203017	Creditor #::BEA001 BEAUREPAIRES P/O #:G62425 Receiving #:64288 Date :2008-12-05	190063
8228	12/05/2008	203211	Sensor faulty adjusted	190063
8228	12/04/2008	203017	Replaced	189691
8228	12/04/2008	202982	Adjusted rear door sensors	189691
8228	12/04/2008	202982		189691
8228	12/04/2008	202982	Replaced	189691
8228	12/04/2008	202982	R/tested brakes OK changed pos 5 tyre	189691
8228	12/04/2008	202911	MEC A Service	189691
8228	12/04/2008	202911	A Service	189691
8228	12/04/2008	202911	Tension Wheel Nuts To OEM Specification	189691
8228	12/01/2008	201141	Creditor #::ROA001 Road Safety Inspections P/O #:G61861 Receiving #:64067 Date :2008-12-01	188774
8228	11/24/2008	201908	Drilled broken bolt in alternator plate fit 3 new bolts & adjusted alternator belt	186252
8228	11/24/2008	202026	Repaired engine hatch microswitch	186252
8228	11/23/2008	201908	Removed alternator and 1 bolt another on left side	186180
8228	11/18/2008	200410	Replaced coolant pipe	184601
8228	11/18/2008	200410	Replaced coolant pipe	182597
8228	11/17/2008	201409	Adjusted rear door sensor	183944
8228	11/17/2008	201407	Replaced broken bolt	183944
8228	11/17/2008	200410		183944
8228	11/16/2008	201141	PASSED INSP. BC115076	183586
8228	11/11/2008	200410	Complited	182597
8228	11/11/2008	200772		182914
8228	11/11/2008	200771	Completed	182914
8228	11/11/2008	200770		182914
8228	11/11/2008	200768	Painted	182914
8228	11/11/2008	200762	Secured and painted	182914
8228	11/11/2008	200761	Cleaned	182914
8228	11/11/2008	200760	Secured	182914
8228	11/11/2008	200760		182915
8228	11/10/2008	200410	Repaired	182597
8228	11/10/2008	200410		182597
8228	11/10/2008	200533	Ordered parts	182597
8228	11/10/2008	200532	Clean A/C filters and vents	182597
8228	11/10/2008	200532	Secured and repairs rear door	182597
8228	11/10/2008	200531	Paint wheels	182597
8228	11/10/2008	200529	Secured all lower skit panels	182597
8228	11/10/2008	200410	Replaced brake pedal rubber	182597
8228	11/10/2008	200410		182597
8228	11/10/2008	200410	Replaced	182597
8228	11/10/2008	200410	Replaced	182597
8228	11/06/2008	200189	Put gauges on A/C r/tested A/C working 22 to 24 stayed att 22 most of the time	181579
8228	11/06/2008	200097		181388
8228	11/06/2008	200097		181388

8228	11/06/2008	200097	RYAN	A Service	181388
8228	11/06/2008	200097		D-Service	181388
8228	11/06/2008	200097	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		181388
8228	11/06/2008	200097		Tension Wheel Nuts to Spec	181388
8228	11/06/2008	200097		A Service	181388
8228	11/06/2008	200097		Tension Wheel Nuts To OEM Specification	181388
8228	10/29/2008	181690		Inspect radiator and charge air cooler for dirt - clean	177461
8228	10/29/2008	182143	Annual body check	Completed	179138
8228	10/27/2008	181690	WATER SEPERATOR SCANIA+VOLVO		178671
8228	10/27/2008	181690		R.S.I Inspection	177461
8228	10/27/2008	181690		Check oil level in transmission - top up if required	177461
8228	10/27/2008	181690		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	177461
8228	10/27/2008	181690		Check and clean cartridge in dry tyre air cleaner	177461
8228	10/27/2008	181690		Replace pre and main fuel filters	177461
8228	10/27/2008	181690		Replace air dryer cansiter clean silence and drain reservoir	177461
8228	10/27/2008	181690		Test coolant level - top up if required to equate to 37C frost protection	177461
8228	10/27/2008	181690		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	177461
8228	10/27/2008	181690		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	177461
8228	10/27/2008	181690		Replace power steering filter and check level (Replace oil if required)	177461
8228	10/27/2008	181690	FUEL FILTER MERC 0500LE		177461
8228	10/27/2008	181690	FUEL FILTER 0500LE		177461
8228	10/27/2008	181690	AIR DRYER CANISTER VOLVO+ NL202		177461
8228	10/27/2008	181690	POWER STEER FILTER B10M		177461
8228	10/27/2008	181690	WIPER REFILL SUIT TX800+TX900		178671
8228	10/27/2008	181690		Replace final drive oil	177461
8228	10/27/2008	181690		Replace angle drive oil	177461
8228	10/27/2008	181868	Replace wiper blade	Replaced O/S wiper blade	178671
8228	10/13/2008	180487	Refill coolant	Refilled	173512
8228	10/10/2008	180320	Bus wont start	Jump started	172750
8228	10/07/2008	180065	Remove graffiti	Removed graffiti	171691
8228	10/07/2008	180065	Replace passenger seat rear N/S	Replaced	171691
8228	10/07/2008	179976		Tension Wheel Nuts To OEM Specification	171691
8228	10/07/2008	179976		A Service	171691
8228	10/07/2008	179976		A Service	171691
8228	09/12/2008	177995	1180X782 REAR SIDE GLASS	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G59883 Receiving #:61844 Date :2008-09-12 228	164653
8228	09/12/2008	177995	FIT REAR N/S SIODE GLASS	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G59933 Receiving #:61825 Date :2008-09-12	164653
8228	09/11/2008	177995	Replace n/s.side windowsupplied by Volgren.		164300
8228	09/01/2008	176941	Replace tyre pos 56 - bald	Replaced	162026
8228	08/29/2008	176948	Change front tyres & O/S rear	DULKITH-Changed	162026
8228	08/29/2008	176948	Change front tyres & O/S rear	Changed	162026
8228	08/29/2008	176863		Tension Wheel Nuts To OEM Specification	162026
8228	08/29/2008	176863		A Service	162026
8228	08/29/2008	176863	DULKITH	A Service	162026
8228	08/29/2008	176863		A Service	162026
8228	08/22/2008	176249	Replace park light	Replaced	160382
8228	08/22/2008	176249	GLOBE FESTOON 24V5W		160019
8228	08/22/2008	176249	GLOBE HIGH BEAM		160019
8228	08/22/2008	176249	Replace headlight globe	Replaced	160019
8228	08/22/2008	176249	Replace park light	Replaced	160019
8228	08/21/2008	175769	Direct Purchase - BODYWORK	Creditor #:TIN002 TINT FX P/O #:G59289 Receiving #:61253 Date :2008-08-21 Tint front windscreen and front doors	159617
8228	08/16/2008	175729	Inspect for driveline warranty - Due on 1/8/08	Completed	158137
8228	08/16/2008	175769	Tint windscreen & front door glasses.	Completed by Tint FX	158336
8228	08/15/2008	175639	SAMP BLADE FUSE		158137
8228	08/15/2008	175639		B Service	157732
8228	08/15/2008	175639		Replace filter drier	157732
8228	08/15/2008	175639		Replace compressor oil	157732
8228	08/15/2008	175639	Service as per list: Replace mod valve kit trace short in F	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	157732
8228	08/15/2008	175639		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	157732
8228	08/15/2008	175639		CONDENSOR AREA: Clean condensor coils; check boltscamps for tension	157732
8228	08/15/2008	175639		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	157732
8228	08/15/2008	175639		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltscamps & fittings; clean condensate drains; clean drip tray	157732
8228	08/15/2008	175639		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	157732
8228	08/15/2008	175639		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	157732
8228	08/15/2008	175639		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	157732
8228	08/15/2008	175639		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	157732
8228	08/15/2008	175639		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	157732
8228	08/15/2008	175639		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	157732
8228	08/15/2008	175639		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	157732
8228	08/14/2008	175639	COMPRESSOR OIL AIR CON		158137
8228	08/14/2008	175639	ASCO WATER VALVE KIT		158137
8228	08/14/2008	175639	FILTER DRIER THERMO KING		158137
8228	07/30/2008	174284	Remove broken bolts from alternator mounting platerefit &	Repaired & replaced top alternator belt	153667
8228	07/30/2008	174284	Remove broken bolts from alternator mounting platerefit &	Remove alt & mounting plate	153667
8228	07/30/2008	174284	Remove r/seat graffiti	Removed	153667
8228	07/30/2008	174231		A Service	153263
8228	07/30/2008	174231		Tension Wheel Nuts To OEM Specification	153263
8228	07/30/2008	174231		A Service	153263
8228	07/02/2008	172012		A Service	144541
8228	07/02/2008	172012		Tension Wheel Nuts To OEM Specification	144541
8228	07/02/2008	172012		A Service	144541
8228	07/01/2008	169451	POS 5	Creditor #:BEA001 BEAUREPAIRES P/O #:G56742 Receiving #:50858 Date :2008-07-01	144541
8228	06/25/2008	171595	Replace side light	Replaced	142804
8228	06/25/2008	171571	Fit N/S rear LED clearance lens	Replaced	142804
8228	06/25/2008	171571	LED CLEARANCE LIGHT (RED AMBER)		143205
8228	06/17/2008	170784	Air leak above rear door	fixed broken hose	140569
8228	06/17/2008	170784	Drv entered - Air System Leaking	fixed	140569
8228	06/13/2008	170565	Losing air through back door	Checked rear door for air leak	139757
8228	06/04/2008	150962	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G49736 Receiving #:50088 Date :2008-06-04 Water pump leaking	137400
8228	06/04/2008	141885	Direct Purchase - ELECTRICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G45155 Receiving #:50084 Date :2008-06-04 Fault codes comes BS 6241	137400
8228	06/04/2008	136247	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G41261 Receiving #:50108 Date :2008-06-04 Park brake warning comes on while driving	137400
8228	05/30/2008	169451	Replace tyre pos 5 - bald		135731
8228	05/30/2008	169451	Replace tyre pos 5 - bald		135731
8228	05/30/2008	169451	Replace tyre pos 5 - bald		135731

8228	05/30/2008	169194	OIL DIPSTICK	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G56506 Receiving #:49883 Date :2008-05-30 228	135731
8228	05/29/2008	169431	Replace O/S/R inner tyre	Replaced	135731
8228	05/29/2008	169431	Replace O/S/R inner tyre	Replaced	135544
8228	05/29/2008	169339	AIR FILTER MERC 0500LE		135544
8228	05/29/2008	169339	OIL FILTER 1725+0500LE		135544
8228	05/29/2008	169339	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		135544
8228	05/29/2008	169339		Tension Wheel Nuts to Spec	135544
8228	05/29/2008	169339		A Service	135544
8228	05/29/2008	169339		D-Service	135544
8228	05/29/2008	169339		Tension Wheel Nuts To OEM Specification	135544
8228	05/29/2008	169339		A Service	135544
8228	05/28/2008	169194	Annual random audit	Completed	135544
8228	05/28/2008	169194	Annual random audit	Completed	135224
8228	05/28/2008	169294	Dipstick is broken refueller cant check oil level	Fitted new dipstick checked oil level OK fuelled & parked	135224
8228	05/22/2008	167248	POS 5	Creditor #::BEA001 BEAUREPAIRES P/O #:G55338 Receiving #:49655 Date :2008-05-22 NEW	133523
8228	05/06/2008	167248	Replace tyre pos 5 - bald & flat	Replaced	127989
8228	05/06/2008	167248	Replace tyre pos 5 - bald & flat		127989
8228	05/06/2008	167296	Replace O/S/rear outer tyre	Replaced	127989
8228	05/06/2008	167296	Replace O/S/rear outer tyre	Replaced	127989
8228	05/06/2008	167207	AIR FILTER MERC 0500LE		127989
8228	05/06/2008	167207		A Service	127989
8228	05/06/2008	167207		Tension Wheel Nuts To OEM Specification	127585
8228	05/06/2008	167207		A Service	127585
8228	04/29/2008	166579	Replace lower alternator pulley and belt to suit 6PK	Replaced by Whitehorse	126867
8228	04/28/2008	165945	Water leak from b/box cool pipe (hole)	Replaced pipe	126867
8228	04/28/2008	165945	Water leak from b/box cool pipe (hole)	Replaced pipe	124428
8228	04/28/2008	166635	Replace halogen globe	Replaced by ABDUL	126651
8228	04/28/2008	166635	HALOGEN GLOBE 24V20W		126867
8228	04/22/2008	165945	Roadtest	Tested	125220
8228	04/22/2008	165945	Water leak from b/box cool pipe (hole)	Ordered parts	124428
8228	04/22/2008	165945	A6345002072 COOLANT PIPE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G54898 Receiving #:48850 Date :2008-04-22	124773
8228	04/21/2008	165945	No o/s. headlight.	Checked OK	124428
8228	04/19/2008	165881	Low oil coolant light on red light	Checked OK	124428
8228	04/16/2008	164012	POS 4	Checked OK	122992
8228	04/04/2008	164555	BALL JOINT FOR FUEL LINKAGES	Creditor #::BEA001 BEAUREPAIRES P/O #:G54184 Receiving #:48686 Date :2008-04-16 NEW	119539
8228	04/04/2008	164555	Repairs to wiper linkages.	replaced linkages	119539
8228	04/04/2008	164555	Service	repaired kneeling linkages & ball joints	119539
8228	04/01/2008	164255		Tension Wheel Nuts To OEM Specification	118582
8228	04/01/2008	164255	Service	A Service	118582
8228	03/28/2008	164012	Replaced tyre pos. 4 Fat spots	rep. tyre pos. 4	116963
8228	03/27/2008	163965	Vibration and tyre or wheel thump in front end	Replaced N/S/R tyres	116711
8228	03/17/2008	163302	GLOBE HIGH BEAM		113979
8228	03/17/2008	163302	Replace head lamp globe	Rep. globe	113683
8228	03/12/2008	163029	Smart bus console NO power	Replaced alternator belt	112268
8228	03/04/2008	162426	Top of boost pump leaking coolant	Checked boost pump OK	111266
8228	03/04/2008	162426	Top of boost pump leaking coolant	Checked boost pump unable to find coolant leaking	111266
8228	03/04/2008	162426	Seat very bouncy and not good tension	Checked seat adjusted working OK	111266
8228	03/04/2008	162426	Seat very bouncy and not good tension	Checked seat adjusted working OK	111266
8228	02/27/2008	162066	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		110632
8228	02/27/2008	162066	Breakdown - Monash University - OUT 9.30 am BACK 11.00 am -	C/O bus 229. Replaced top alt belt on site	110578
8228	02/21/2008	161665	No broom to clean the bus	Checked OK	108596
8228	02/21/2008	161597	Service	A Service	108596
8228	02/21/2008	161597		Tension Wheel Nuts To OEM Specification	108596
8228	02/21/2008	161597	Service	A Service	108596
8228	02/18/2008	161276	A/C BELT 0500 BENZ		108066
8228	02/18/2008	161276	Replaced water pump belt.	rep. water pump belt	107786
8228	02/11/2008	160806	Adjust rear door sensors	Adjusted	105755
8228	01/23/2008	159334	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	100008
8228	01/23/2008	159334	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	100008
8228	01/23/2008	159334	Service	Service T - Replace Transmission Oil & Filter	100008
8228	01/23/2008	159334		Tension Wheel Nuts To OEM Specification	100008
8228	01/23/2008	159334	Service	A Service	100008
8228	01/21/2008	159099	WEDGE GLOBE INSTRUMENT 24V 3W		99476
8228	01/21/2008	159099	Replaced globe	Rep. globe	99476
8228	01/02/2008	157686	MERC ALTERNATOR BELT TOP 0500LE		94753
8228	01/02/2008	157686	Fit alternator belt	Fitted	94753
8228	01/02/2008	157686	Replace broken wire in alternator	Replaced wire	94573
8228	01/02/2008	157623	Breakdown - Caulfield Station - OUT 7.30 am BACK 8.45 am -	C/O bus 238. Checked no fault found returned to depot	94573
8228	12/30/2007	157463	Replace top alternator belt	Replace top alternator belt	94171
8228	12/29/2007	157456	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		94171
8228	12/29/2007	157456	Breakdown - Battery light on - Oakleigh Station - Dep 11.00	C/o bus Return to depot	94171
8228	12/17/2007	156602	CLEANED AIR FILTER MERC 0500LE		91885
8228	12/17/2007	156602	Replace air cleaner	rep. air filter	91885
8228	12/14/2007	156503	Coolant leak at boost pump	REP. GASKET REFITTED O/K.	91626
8228	12/14/2007	156421	Rear brakes low	CHECKED REAR BRAKES ARE SERVICABLE	91626
8228	12/13/2007	156455	Low coolant level	checked o/k.	91626
8228	12/12/2007	156353	Low coolant light on and low on coolant	Found boost pump leaking drain seal fitting	91433
8228	12/08/2007	146424	SERVICE VALVE GASKETBOCK+ BITZER COMP		90809
8228	12/06/2007	155748	OIL FILTER 1725+0500LE		90307
8228	12/06/2007	155748		Tension Wheel Nuts to Spec	90307
8228	12/06/2007	155748		A Service	90307
8228	12/06/2007	155748		D-Service	90307
8228	12/06/2007	155748		Tension Wheel Nuts To OEM Specification	90307
8228	12/06/2007	155748		A Service	90307
8228	11/27/2007	153996	Annual Inspections	Creditor #::ROA001 Road Safety Inspections P/O #:G50685 Receiving #:45181 Date :2007-11-27	88092
8228	11/26/2007	154994	Battery light on code : FR1125	Checked OK	87594
8228	11/18/2007	153996	Annual Inspection - BC 108554	Passed	86054
8228	11/14/2007	154025	Adjust wiper jetson o/s.	Adjusted	86054
8228	11/14/2007	154025	WEDGE GLOBE INSTRUMENT 24V 3W		86190
8228	11/14/2007	154025	Steam clean all chassis	S/cleaned	86105
8228	11/14/2007	154025	Steam clean & check shockers.	cleaned	86105
8228	11/13/2007	153932	Secure clean adjust front & rear doors		86054
8228	11/13/2007	153932	Polish exterior panels/headers & touch up paint work	Polished	86054

8228	11/13/2007	153932	Polish exterior panels/headers & touch up paint work	Polished	86054
8228	11/13/2007	153932	Paint wheels	OK	86054
8228	11/13/2007	153932	Secure all lower skit panels	Secured	86054
8228	11/13/2007	153932	Polish and touch up front bumper bar	Polished	86054
8228	11/13/2007	153932	Secure paint exterior mirrors and arms		86054
8228	11/13/2007	153932	Clean graffiti - seats side walls in rear section	Cleaned	86054
8228	11/13/2007	153932	Clean air condition filter secure vents	Cleaned	86054
8228	11/13/2007	153932	Wheel chair ramp - operation and clean	Cleaned	86054
8228	11/13/2007	153932	Paint till stand	Painted	86054
8228	11/13/2007	153932	Repair N/S panel No 3 prepare and paint as required. Decal	Repaired panels & touch up paintwork	86054
8228	11/13/2007	153932	No 2 panel paint damage N/Side		86054
8228	11/09/2007	153661		Replace final drive oil	85629
8228	11/09/2007	153661		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	85629
8228	11/09/2007	153661		Inspect radiator and charge air cooler for dirt - clean	85629
8228	11/09/2007	153661		Check oil level in transmission - top up if required	85629
8228	11/09/2007	153661		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	85629
8228	11/09/2007	153661		Check and clean cartridge in dry tyre air cleaner	85629
8228	11/09/2007	153661		Replace pre and main fuel filters	85629
8228	11/09/2007	153661		Replace air dryer cansiter clean silence and drain reservoir	85629
8228	11/09/2007	153661		Replace angle drive oil	85629
8228	11/09/2007	153661		Test coolant level - top up if required to equate to 37C frost proctection	85629
8228	11/09/2007	153661		Adjust engine valve clearnaces	85629
8228	11/09/2007	153661		Replace power steering filter and check level (Replace oil if required)	85629
8228	11/09/2007	153661	FUEL FILTER MERC 0500LE		85629
8228	11/09/2007	153661	FUEL FILTER 0500LE		85629
8228	11/09/2007	153661	AIR DRYER CANISTER MAN NL202+VOLVO		85629
8228	11/09/2007	153661	POWER STEER FILTER B10M		85629
8228	11/01/2007	153221	Ops Entered - Air Cond	Replace boost pump by Southern States under warranty	85082
8228	11/01/2007	153221	Ops Entered - Air Cond	Found unit failed due to blown boost pump fuse. Unit cutting out intermittently had a quick look cant find fault still under TK warranty NOTE boost pump fuse has been replaced 3 times	85082
8228	11/01/2007	153240	Breakdown - Stud park shopping centre - OUT 3.30 pm BACK 4.	C/O bus 10. Returned to depot for repairs	85082
8228	10/29/2007	152890	Annual body check	Completed	84546
8228	10/24/2007	151759	BALD	Creditor #:BEA001 BEAUREPAIRES P/O #:G49948 Receiving #:44468 Date :2007-10-24 Pos 3	83621
8228	10/24/2007	152522	MOVE SCREEN	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #:G50188 Receiving #:44512 Date :2007-10-24	83621
8228	10/24/2007	152522	Move driverscreen		83621
8228	10/22/2007	152219	32MM LOOSE WHEEL NUT INDICATOR		83007
8228	10/22/2007	152219		A Service	82742
8228	10/22/2007	152219		Tension Wheel Nuts To OEM Specification	82742
8228	10/22/2007	152219		A Service	82742
8228	10/15/2007	151759	Replaced tyre pos.3 - flat	rep. tyre pos. 3 flat	81799
8228	10/13/2007	151732	rep. tyre pos.3	rep. tyre pos. 3	81534
8228	10/11/2007	151635	BRIDGESTONE R192 11.225 TYRE		81534
8228	10/11/2007	151635	Replace 2 tyres	Replaced	81259
8228	10/09/2007	151375	R/H front light not working	Checked lights - no fault found	80730
8228	10/04/2007	150962	Water pump leaking.	Repaired by Whitehorse	80447
8228	10/01/2007	150652	BUTTERFLY AIR VENT		80171
8228	09/30/2007	150652	Drivers heater duct for feet missing.	Fitted butterfly vent.	80171
8228	09/04/2007	148725	Front brake light out	Replaced N/S/F park light globe	75183
8228	09/03/2007	148490	FAN BELT A/C ARTIC		74917
8228	09/01/2007	148492	No reverse buzzer	checked all o/k.	74917
8228	09/01/2007	148490	Alt fan belt cracked	REPLACED ALTERNATOR BELT	74917
8228	08/31/2007	148085	FUEL LEAKS AT FILTER -PIPE	Creditor #::WHT001 WHITEHORSE TRUCKS P/O #:G48492 Receiving #:43292 Date :2007-08-31	74498
8228	08/30/2007	147417	POS 5	Creditor #::BEA001 BEAUREPAIRES P/O #:G48092 Receiving #:43241 Date :2007-08-30	74140
8228	08/29/2007	148211	BRIDGESTONE R192 11.225 TYRE		74004
8228	08/29/2007	148211	Change front tyres	Changed	74004
8228	08/28/2007	148085	Fuel leaks at filter - Pipe	Repaired by Whitehorse	74004
8228	08/27/2007	147976		A Service	74004
8228	08/27/2007	147976		Tension Wheel Nuts To OEM Specification	74004
8228	08/27/2007	147976		A Service	74004
8228	08/21/2007	147417	TYRE POS 5 FLAT	Replaced	72174
8228	08/18/2007	147283	Replaced tyre pos. 5 -flat	Replaced tyre pos. 5	71910
8228	08/09/2007	146636	Adjust air gap and calabrate sensor.	Adjusted air gap and calibrated coil sensor.	70463
8228	08/09/2007	146424	FILTER DRIER THERMO KING		70510
8228	08/09/2007	146424		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	70042
8228	08/09/2007	146424		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	70042
8228	08/09/2007	146424		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	70042
8228	08/09/2007	146424		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	70042
8228	08/09/2007	146424		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	70042
8228	08/09/2007	146424		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	70042
8228	08/09/2007	146424		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	70042
8228	08/09/2007	146424		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	70042
8228	08/09/2007	146424		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	70042
8228	08/09/2007	146424		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	70042
8228	08/09/2007	146424		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	70042
8228	07/13/2007	144337	Service	A Service	64629
8228	07/13/2007	144337	Service	A Service	64629
8228	07/13/2007	144337	Service	A Service	64629
8228	07/13/2007	144337		Tension Wheel Nuts To OEM Specification	64629
8228	06/27/2007	143199	Graffiti on seats & floor in rear of bus.	Cleaned graffiti	60962
8228	06/27/2007	143204	Replace O/S headlight globe	Replaced	60775
8228	06/27/2007	143204	GLOBE HIGH BEAM		60962
8228	06/21/2007	142688	GLOBE HIGH BEAM		58959
8228	06/21/2007	142688	Replace N/S headlight globe	Replaced	58959
8228	06/12/2007	141885	Fault code comes up BS 6241	Repaired by Whitehorse	56013
8228	06/08/2007	141817	Breakdown - Warning code came on Monash Uni. Clayton. Left	C/O. BUS & RETURNED TO DEPOT WARNING CODE ACTIVE *BS 6241	56013
8228	06/05/2007	141479		A Service	55229
8228	06/05/2007	141479		Tension Wheel Nuts To OEM Specification	55229
8228	06/05/2007	141479		A Service	55229
8228	05/22/2007	140384	Air conditioner is not working.	Repaired by Whitehorse	51051
8228	05/03/2007	138852		D-Service	45058
8228	05/03/2007	138852	FAN BELT A/C ARTIC		45475
8228	05/03/2007	138852	AIR FILTER MERC 0500LE		45058
8228	05/03/2007	138852	OIL FILTER 1725+0500LE		45058
8228	05/03/2007	138852	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		45058

8228	05/03/2007	138852	Tension Wheel Nuts to Spec	45058
8228	05/03/2007	138852	A Service	45058
8228	05/03/2007	138852	Tension Wheel Nuts To OEM Specification	45058
8228	05/03/2007	138852	D Service	45058
8228	04/07/2007	137124	Replace top alternator bolts x3 realign belt and tension	39387
8228	04/07/2007	137124	Engine belts worn	39387
8228	04/05/2007	137214	Replace belt	39088
8228	04/05/2007	137214	A/C BELT 0500 BENZ	39387
8228	03/27/2007	136247	Park brake warning light comes on while driving - sometimes	38441
8228	03/26/2007	136251	Breakdown - Cnr Wellington rd & Wanda St - OUT 6.30 pm BACK	38201
8228	03/23/2007	136064	Secure gutter mould	38192
8228	03/23/2007	135962	AIR FILTER MERC 0500LE	38192
8228	03/23/2007	135962	Tension Wheel Nuts To OEM Specification	38192
8228	03/23/2007	135962	A Service	38192
8228	03/14/2007	135221	Graffiti on back seats last row	35653
8228	03/02/2007	134229	SWITCH-SOLENOID STARTER	33019
8228	03/02/2007	134229	Needs emergency exit button fitting.	33019
8228	03/02/2007	134229	Needs emergency exit button fitting.	33019
8228	02/20/2007	133440	A/C BELT 0500 BENZ	30890
8228	02/20/2007	133440	Breakdown - Wellington & Jells Rds - OUT 7.20 am BACK 8.45	30890
8228	02/13/2007	132918	A/C not working	28695
8228	02/13/2007	132918	A/C blowing hot air	28695
8228	02/13/2007	132918	A/C BELT 0500 BENZ	28695
8228	02/12/2007	132808	Annual random audit	28695
8228	02/12/2007	132808	Annual random audit	28695
8228	02/12/2007	132806	A Service	28695
8228	02/12/2007	132806	A Service	28695
8228	02/12/2007	132806	Tension Wheel Nuts To OEM Specification	28695
8228	02/07/2007	132409	Bottom alt belt loose	27696
8228	02/07/2007	132409	CRANK-IDLE BELT M.A.N. 13X1405MM	27696
8228	01/31/2007	131931	Check A/C	26950
8228	01/31/2007	131949	Clean drivers camera	26950
8228	01/12/2007	130683	Rear door air leaks. Occasionally (P) Warning light comes on	21181
8228	01/08/2007	130357	Lights on speedo on all the time	20489
8228	01/08/2007	130357	Check dash fault	20489
8228	01/05/2007	130151	Replace N/S/R marker lamp	19814
8228	01/05/2007	130151	PLASTIC DEMISTER OUTLETS	19814
8228	01/05/2007	130196	Replaced clearance light lens.	19814
8228	01/05/2007	130133	rep. lens	19814
8228	01/05/2007	130133	A Service	19814
8228	01/05/2007	130133	Tension Wheel Nuts To OEM Specification	19814
8228	01/05/2007	130133	A Service	19814
8228	12/21/2006	129362	Breakdown - Oakleigh Station - OUT 6.00 pm BACK 7.00 pm - A	16204
8228	11/30/2006	127596	Water hammer check and replace elbows as requiredfit insu	10763
8228	11/28/2006	127317	TOP ALTERNATOR BELT MERC 0500L	10644
8228	11/27/2006	127317	32MM LOOSE WHEEL NUT INDICATOR	10414
8228	11/27/2006	127317	Replace wheel nut indicators	10414
8228	11/27/2006	127317	Drv entered - Passenger Doors Not Operating	10414
8228	11/27/2006	127317	Drv entered - Passenger Doors Not Operating	10414
8228	11/27/2006	127317	Replace top alternator belt	10414
8228	11/27/2006	127302	A Service	10414
8228	11/27/2006	127302	A Service	10414
8228	11/27/2006	127302	Tension Wheel Nuts To OEM Specification	10414
8228	11/23/2006	127084	Rear door will not shut	9052
8228	11/22/2006	126235	ROAD SAFETY INSPECTIONS	8790
8228	11/19/2006	126235	Annual Inspection - BC 097996	7432
8228	11/16/2006	126411	Steamclean all bus	7736
8228	11/16/2006	126411	Drv entered - Elec & Light Park Lights	7736
8228	11/16/2006	126411	Modify till pin	7736
8228	11/13/2006	126015	Checked OK	6806
8228	11/13/2006	126015	Change pre and main fuel filter	6806
8228	11/13/2006	126015	Check power steering oil level	6806
8228	11/13/2006	126015	Check & clean filter cartridge in dry-type air cleaner	6806
8228	11/13/2006	126015	Remove disassemble & clean cyclone separator (apply water repellant grease to electrical connections) check drainage function for leaks	6806
8228	11/13/2006	126015	Check oil level in transmission & top-up if required	6806
8228	11/13/2006	126015	Inspect radiator & charge-air cooler for dirt - clean if required	6806
8228	11/13/2006	126015	Electrical - BATTERIES: check fluid level (leave air gap when topping up) CABLES: check cable connections are firm with good contact on ALL battery terminals	6806
8228	11/13/2006	126015	Inspect bus as per sheet	6806
8228	11/13/2006	126015	Adjust Engine Valve Clearance	6806
8228	11/13/2006	126015	Top-up coolant level (must equate to -37C frost protection)	6806
8228	11/13/2006	126015	Change oil in fan angle drive	6806
8228	11/13/2006	126015	Change air drier cannister; clean silencer & drain air reservoir	6806
8228	11/13/2006	126101	Annual body check	7432
8228	11/13/2006	126222	DO NOT OVERTAKE TURNING DECAL	7432
8228	11/13/2006	126222	GIVE WAY SIGN (SMALL)	7432
8228	11/13/2006	126222	fitted all regulation & safety decals as required.	7432
8228	10/31/2006	125190	Warranty Service - 5000 kms	5188
8228	10/24/2006	124552	New Registration - DN 099526	2719
8228	10/20/2006	124359	Drivers fan doesn't work	1707
8228	10/19/2006	124259	No broom	1445
8228	10/19/2006	124259	BROOM HANDLE (8232715)	1445
8228	10/19/2006	124259	BROOM HEAD (09803211)	1445
8228	10/13/2006	123864	removed spares etc. from bus & fitted till pin.	455
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	100
8228	08/14/2006	0	Imported Service History	100
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	0
8228	08/14/2006	0	Imported Service History	100