

Veh#	Date	W/O#	Description	Notes	Odometer
870	09/14/2026	1369725		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612739
870	09/05/2026	1367310		COMPLETED BY ATS 12/8/26	612739
870	08/03/2026	1358908	Decommission Bus for Auction	removed livery and driver area devices inc etag and plates.	612739
870	07/06/2026	1351383	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O413473 Receiving #:440570 Date :2026-07-06	612739
870	07/01/2026	1351383		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612739
870	07/01/2026	1351383		VEHICLE SAFETY INSPECTION	612739
870	07/01/2026	1351383		ANNUAL SAFETY INSPECTION SERIAL # ____RSI 077119 PASS ____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	612739
870	06/26/2026	1350679	Consumables		612739
870	06/26/2026	1350678	Consumables		612739
870	06/26/2026	1350679	Consumables		612739
870	06/26/2026	1350678	Consumables		612739
870	06/26/2026	1350679	DECAL MAX SAFE CARRY BLACK ON WHITE		612739
870	06/26/2026	1350679	Mechanic entered - Body Other Interior max capacity sticker	Removed and replaced sticker with new black font white background.	612739
870	06/26/2026	1350678	2ND PRE ASI CHECK	Completed pre ASI second check.	612739
870	06/23/2026	1349700		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	612739
870	06/11/2026	1347001		PRE ANNUAL SAFETY INSPECTION CHECK	612739
870	06/11/2026	1347051	Consumables		612739
870	06/11/2026	1347051	Mechanic entered - Elec and Light Interior Lights driver tic	replaced globe in ticket light checked for function ok	612739
870	06/11/2026	1347174	Mechanic entered - Air System Other o/s rear air bag air l	seured with using piece of hose	612739
870	06/04/2026	1345595		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612739
870	06/04/2026	1345595		VEHICLE SAFETY INSPECTION Carried out Safety inspection.	612739
870	06/04/2026	1345692	Consumables		612739
870	06/04/2026	1345692	Mechanic entered - Elec and Light Next Stop Button O/S Rear	removed pax bell found loose teminal to switch refitted terminal checked for operation ok refitted bell to staunchion pole. ok.	612739
870	06/04/2026	1345692	Consumables		612739
870	06/04/2026	1345692	Consumables		612739
870	06/04/2026	1345692	Mechanic entered - Body Other 2x emergency Hammers Missing.	fitted 2x new emergency hammers 1 to front of bus 1 to rear removed roof panels and recrimped wires behind panel fitted hammers into holders and resecured roof panels ok.	612739
870	06/04/2026	1345692	Mechanic entered - Body Other 1x N/S Disabled seat base plas	drilled into plastic and sttel of seat base added screw checked for security ok.	612739
870	06/04/2026	1345692	EMERGENCY HAMMER KIT W/WIRE		612739
870	03/14/2026	1327255		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612393
870	03/14/2026	1327255		VEHICLE SAFETY INSPECTION	612393
870	03/14/2026	1327294	Consumables		612393
870	03/14/2026	1327294	Mechanic entered - Elec and Light Next Stop Button N/S Pax B	replaced broken next stop button with new item from stock.	612393
870	03/14/2026	1327294	SWITCH STOP YELLOW (62628)(50V2242) 340085		612393
870	03/14/2026	1327294	Mechanic entered - Elec and Light Next Stop Button 1x Pax Be	resecured loose pax bell.	612393
870	03/14/2026	1327294	Mechanic entered - Body Other Disabled Seat Top Pins N/S	Re Seated disabled seat top pins.	612393
870	03/14/2026	1327294	Mechanic entered - Body Other O/S Roof Trim Missing Screws.	fitted new screws from stock.	612393
870	03/14/2026	1327294	Mechanic entered - Body Other O/S Pillar Trim Missing Screws	replaced with new screws from stock.	612393
870	03/14/2026	1327294	Mechanic entered - Body Other 1x Seat Base Bracket loose in	tightened loose floor bracket bolt for seat.	612393
870	03/14/2026	1327294	HOOK DRIVERS COAT WAS0004		612393
870	03/14/2026	1327294	Mechanic entered - Body Other Drivers Vest Hook Not Fitted.	fitted new drivers vest hook with item from stock.	612393
870	02/26/2026	1323435		COMPLETED BY ATS 15/2/26	612393
870	02/03/2026	1318112	Consumables		612393
870	02/03/2026	1318112	Mechanic entered - Elec and Light Flat Batteries	Jump sarted bus. Let sit for 30 minutes	612393
870	01/09/2026	1313365		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Carried out as pe check list	612393
870	12/30/2025	1311560		assisted	612393
870	12/30/2025	1311560		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612393
870	12/30/2025	1311560		VEHICLE SAFETY INSPECTION carry out safety inspection.	612393
870	12/30/2025	1311621	Consumables		612393
870	12/30/2025	1311621	Mechanic entered - Elec and Light Interior Lights spedo guag	fit new globe to spedo guage backlight checked for function ok.	612393
870	12/30/2025	1311621	Mechanic entered - Elec and Light Interior Lights O/S middle	fit new fluorescent globe to O/S middle saloon light checked for function ok.	612393
870	12/30/2025	1311621	Mechanic entered - Elec and Light Exterior Lights O/S revers	fit new globe to O/S reverse light checekd for function ok.	612393
870	12/30/2025	1311627	Consumables		612393
870	12/30/2025	1311627	RAIL >>> SEAT ROUND END CAP MISSING 11	FIT 11 SECOND HAND END CAPS.	612393
870	10/14/2025	1296531	Campaign 2025 Remove intercooler / wash radiator	Removed intercooler pressured radiator and intercooler. Fitted intercooler and secured all bolts.	612393
870	10/03/2025	1294101		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612393
870	10/03/2025	1294101		VEHICLE SAFETY INSPECTION	612393
870	10/03/2025	1294186	FILTER AIR OUTER SCANIA K94IB L94UAB K124IB E218L		612393
870	10/03/2025	1294186	Mechanic entered - Engine Other air filter needs replacing	removed old air filter and replaced it with a new one from stock.	612393
870	10/03/2025	1294193	Consumables		612393
870	10/03/2025	1294186	Consumables		612393
870	10/03/2025	1294193	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok.	612393
870	10/03/2025	1294186	Mechanic entered - Elec and Light Other n/s/r reverse light	replaced with a new globe from parts store.	612393
870	10/03/2025	1294193	Mechanic entered - Body Other n/s disability seat loose.	repaired ok	612393
870	10/03/2025	1294193	Mechanic entered - Body Other n/s disability seat loose.	repaired n/s disability seat ok.	612393
870	10/03/2025	1294193	Mechanic entered - Body Other n/s/f side bumper bolt loose.	tightened n/s/f side bumper bolts ok.	612393
870	10/03/2025	1294193	Mechanic entered - Body Other front door top bolts loose.	tightened front door top bolts ok.	612393
870	10/03/2025	1294193	Mechanic entered - Body Other n/s/r top rain molding off.	repaired n/s/r top rain molding ok.	612393
870	10/03/2025	1294186	Mechanic entered - Body Other panel behind the drivers seat	removed old rivet and replaced with the right size rivet. all secured now.	612393
870	10/03/2025	1294235	Vehicle Mechanical Audit	Completed bus audit document # 000098	612393
870	10/03/2025	1294186	Mechanic entered - Body Other o/s exterior emergency exit de	removed old sticker and making sure surface was clean before the new sticker went on grabbed a new one from stock and applied it to the bus.	612393
870	09/25/2025	1292703	Consumables		612393
870	09/25/2025	1292703	Mechanic entered - Elec and Light Flat Batteries Battery fla	Jump started ok.	612393
870	09/01/2025	1286244	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O394166 Receiving #:418808 Date :2025-09-02 24 MONTH SERVICE	612231
870	08/28/2025	1286313		COMPLETED BY ATS	612079
870	08/28/2025	1286244		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - PO:O394166 - CARRIED OUT BY JIMMY FROM COLD DRIVE	612079
870	08/28/2025	1286244		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - PO:O394166 - CARRIED OUT BY JIMMY FROM COLD DRIVE	612079
870	07/28/2025	1277080	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:K391533 Receiving #:416133 Date :2025-07-29	612079
870	07/18/2025	1277080		VEHICLE SAFETY INSPECTION - Assisting	612027
870	07/18/2025	1277080		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS - Assisting	612027
870	07/18/2025	1277080		ANNUAL SAFETY INSPECTION SERIAL #RSI 071867 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 - Assisting	612027
870	06/17/2025	1270576		PRE ANNUAL SAFETY INSPECTION CHECK	612027
870	06/17/2025	1270576		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	612027
870	06/16/2025	1270576		VEHICLE SAFETY INSPECTION	612027
870	06/16/2025	1270576		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	612027
870	06/16/2025	1270626	Mechanic entered - Body Other	replaced reflectrors and floor hook	612027
870	06/16/2025	1270626	HANDLE WHEELCHAIR RAMP 62x48		612027
870	06/16/2025	1270626	REFLECTOR AMBER 94 X 44MM(QTY OF 2)		612027
870	06/06/2025	1268961		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carry out fire safety inspection.	612027
870	05/21/2025	1265407	A/C Heating Belt Loose or_Missing	fitted two a/c belts.	610225
870	05/21/2025	1265407	BELT V-BELT COGGED TRI-POWER 17x2110mm		610225
870	05/21/2025	1265407	BELT V-BELT COGGED TRI-POWER 17x2110mm		610225
870	05/16/2025	1264763	Mechanic entered - Elec and Light Flat Batteries both batter	removed old batteries replaced with new items from stock checked for function ok.	610024

870	05/16/2025	1264763	BATTERY EXSN94SCMF 1350AAC EMFN150L		610024
870	05/16/2025	1264763	Consumables		610024
870	04/22/2025	1259731	Elec and Light (None) bus starts once the master switch i	removefit new ignition switch.	610024
870	04/22/2025	1259731	SWITCH IGNITION SCANIA L94 UAB		610024
870	03/20/2025	1253532		VEHICLE SAFETY INSPECTION carry out safety inspection.	610024
870	03/20/2025	1253532		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorque all wheel nuts.	610024
870	03/20/2025	1253616	Mechanic entered - Body Front_Door Operation Faulty Front do	Adjusted safety edge switches.	610024
870	03/20/2025	1253616	Mechanic entered - Body Other Inside mirror loose.	Secured.	610024
870	03/20/2025	1253616	Mechanic entered - Body Other 1x N/S disable seat not stayin	Tightened pivot bolts	610024
870	03/20/2025	1253616	Consumables		610024
870	03/14/2025	1252512	Mechanic entered - Elec and Light Exterior Lights N/S/R mark	Removed and replaced marker light assy fit new connectors	609763
870	03/14/2025	1252512	LAMP LED SIDE MARKER RED/AMBER		609763
870	03/14/2025	1252512	Consumables		609763
870	03/03/2025	1246784		fitting window rubber window and mirror	609616
870	03/03/2025	1246784	SAUSAGE WHITE BOSTIK		609616
870	03/03/2025	1246784	DECAL VENTURA ROUTE LARGE 850MM X 250MM		609616
870	03/03/2025	1246784		fit window fit sticker clean bus inside	609616
870	03/01/2025	1246784	WHEEL ARCH RUBBER BACKING P/LENGTH		609616
870	03/01/2025	1246784	REFLECTOR RED 94MM X 4MM NR84052BL		609616
870	03/01/2025	1246784	REFLECTOR AMBER 94mm X 44MM (84051)		609616
870	03/01/2025	1246784		do sealer fit wheel arch still working on window	609616
870	02/28/2025	1246784		perp maskup and paint and wheels	609616
870	02/28/2025	1246784	PAINT ENAMEL GLOSS WHITE 4LT		609616
870	02/28/2025	1246784	HARDENER DEBEER FAST 2.5L(F3255)		609616
870	02/27/2025	1246784		put bus into boothpolished blend out areas sanded and putty work.	609616
870	02/21/2025	1246784	FLOCKED EXTRUSION 13W X 11.5H	Creditor #:EA-ALP001 ALP OZ AUTO MOULDS PTY LTD P/O #:EA382314 Receiving #:405134 Date :2025-02-21	609616
870	02/20/2025	1246784		cut old sika and clean sika and cut new panel and resika and remove wheel arch rubber and inset	609616
870	02/20/2025	1246784	Accident # 58074 NEARSIDE-Middle. Liability Pending	Assisting	609616
870	02/20/2025	1246784	SAUSAGE WHITE BOSTIK		609616
870	02/20/2025	1246784		repair drivers window	609616
870	02/20/2025	1246784	stainless steel part for windo	Creditor #:EA-BUNNINGS BUNNINGS P/O #:EA382193 Receiving #:405132 Date :2025-02-21	609616
870	02/20/2025	1246696		completed by ATS 20-2-25	609616
870	02/12/2025	1244493	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	CAMPAIGN DOES NOT APPLY TO RAIL BUSES	609616
870	02/07/2025	1243427	diff pinion seal leaking	Checked and found slight leak from diff bearing retainer tight all the bolts on retainer wash checked diff oil level road tested and checked for leaks found okay	609616
870	02/03/2025	1242348		TRANSMISSION CHECK AS PER CHECK LIST	609616
870	01/09/2025	1237756		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	609616
870	12/30/2024	1235910		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	609616
870	12/30/2024	1235910		VEHICLE SAFETY INSPECTION	609616
870	12/30/2024	1235926	Engine oil dipstick u/s	R/R engine oil dipstick	609616
870	12/30/2024	1235926	DIPSTICK ENGINE OIL 753MM SCANIA L94 40A8200		609616
870	12/30/2024	1235997	PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801 1535068		609616
870	12/30/2024	1235997	Mechanic entered - Engine Other Smooth engine bet idler bear	Removed and replaced engine belt idler. Fitted engine belt all ok.	609616
870	12/30/2024	1235997	Mechanic entered - Body Other D button not lighting up.	Fitted new globe now working.	609616
870	12/09/2024	1232257	A/C not cooling	rectified by Dave Cold Drive on 07/12/2024 poO377582	609616
870	12/07/2024	1232257	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O377582 Receiving #:401000 Date :2024-12-19 check and rectify ac nw	609616
870	11/11/2024	1225794		carried out fitting and adjusting 2 new ac belts missing. ran bus and check all good.	608122
870	11/11/2024	1225794	BELT V-BELT COGGED A/CON T	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G375699 Receiving #:398131 Date :2024-11-11	608122
870	11/11/2024	1225794	Consumables		608122
870	11/08/2024	1225794	FILLER CAP		608122
870	11/08/2024	1225794	OIL FILLER TUBE SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G375676 Receiving #:398027 Date :2024-11-08	608122
870	11/07/2024	1225794		Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G375676 Receiving #:398027 Date :2024-11-08	608122
870	11/07/2024	1225794		oil spout is missing.ordered them at 10:30 am on 7/11/2024 and find a stocked good deep stick put in and checked ok then clean engine bay and waiting for parts.C/O.	608122
870	11/07/2024	1225794	BELT MICRO V SERPENTINE BELT 8		608122
870	11/07/2024	1225794	BELT V-BELT COGGED A/CON T	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G375675 Receiving #:397965 Date :2024-11-07	608122
870	11/07/2024	1225794	Mechanic entered - Warning Lights Batteries bus not moving.	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G375675 Receiving #:397965 Date :2024-11-07	608122
870	10/29/2024	1223759	PERFORM CAMPAIGN 15/24 PRE SUMMER PREVENTATIVE MAINTENANCE	checked bus and find have battery lights on when checked find out A/C belt is missing and alternator belt is broken and worn too.find the engine il deep stick is missing	608101
870	10/14/2024	1220720	Consumables	remove intercooler and pressure wash radiator for debris. Refitted intercooler	608101
870	10/14/2024	1220720	FARE STICKERS TO BE REMOVED FROM INSIDE		608101
870	10/02/2024	1217834	Mechanic entered - Warning Lights Coolant light on.	removed stickers	607558
870	10/01/2024	1217387		fit good second hand low water probe. no warning light on dash	607558
870	10/01/2024	1217387		VEHICLE SAFETY INSPECTION Carried out safety inspection	607558
870	10/01/2024	1217584	Mechanic entered - Engine Other Belt Tensioner U/S	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	607558
870	10/01/2024	1217584	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002	replaced U/S Tensioner with new item from stock.	607558
870	10/01/2024	1217451	Mechanic entered - Dash Other School Light Switch Label Miss		607558
870	10/01/2024	1217451	Consumables	fitted new label to switch from stock.	607558
870	10/01/2024	1217451	Mechanic entered - Body Other O/S/R Hatch Catch Claw Missing		607558
870	10/01/2024	1217451	CATCH CLAW PLASMA ENGINE HATCH DOOR 2132-001-2	fitted new hatch catch claw from stock.	607558
870	10/01/2024	1217584	Mechanic entered - Air System Air_Leak Rear 4 way valve cir		607558
870	10/01/2024	1217584	VALVE CIRCUIT PROTECTION 4WAY SCANIA 1431049 1381883	removed 4 way valve replaced with new item from stock aired up bus checked for leaks ok.	607558
870	10/01/2024	1217387	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH		607558
870	09/16/2024	1212161	COMPLETE A-SERVICE	complete	607558
870	09/03/2024	1212161		Creditor #:MT-22CELS 22 CELSIUS P/O #:M371741 Receiving #:395009 Date :2024-09-20	607558
870	08/08/2024	1206159		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Completed by 22 Celsius	607558
870	07/22/2024	1202491	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	CARRY OUT FIRE EXTINGUISHER TEST & TAG	607192
870	07/22/2024	1202491	Consumables	Retensioned all front wheel nuts to 650nm.	607192
870	07/15/2024	1200935	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC	COMPLETE	606960
870	07/11/2024	1199878		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	606960
870	07/11/2024	1199878		VEHICLE SAFETY INSPECTION	606960
870	07/11/2024	1199878		ANNUAL SAFETY INSPECTION SERIAL # __RSI 065367 PASS __WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	606960
870	07/01/2024	1199878	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O368244 Receiving #:390176 Date :2024-07-16	607192
870	06/28/2024	1197183	TYRE 295/80R22.5 NEW		606960
870	06/28/2024	1197183	Mechanic entered - Wheels and Tyres Other both front tyres t	removed both front tyres and replaced both front tyres ok.	606960
870	06/28/2024	1197183	Consumables		606960
870	06/28/2024	1197181	LENS CLEAR TO SUIT 2043		606960
870	06/28/2024	1197181	Mechanic entered - Elec and Light Other reverse light lens c	replaced reverse light lens ok.	606960
870	06/28/2024	1197181	Consumables		606960
870	06/28/2024	1197181	Mechanic entered - Body Other both middle seat all loose.	repaired all middle seat ok.	606960
870	06/28/2024	1197181	STONEGUARD PLUS SZ L253 1000ML		606960
870	06/28/2024	1197181	Mechanic entered - Body Other driver seat back panel very lo	replaced driver seat back panel ok.	606960
870	06/28/2024	1197181	Mechanic entered - Body Other bus inside o/s rear top panel	replaced o/s/r top panel screws ok.	606960
870	06/28/2024	1197181	Mechanic entered - Body Other under front painting.	painting under front ok.	606960
870	06/28/2024	1197181	Mechanic entered - Body Other both rear seat top roll cut.	repaired both rear seat top roll ok.	606960
870	06/28/2024	1197181	Mechanic entered - Body Other n/s/r and o/s/middle glass loo	repaired n/s/r and o/s/middle lass ok.	606960

870	06/18/2024	1195015	VEHICLE SAFETY INSPECTION	606474
870	06/18/2024	1195015	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	606474
870	06/18/2024	1195015	PRE ANNUAL SAFETY INSPECTION CHECK	606474
870	06/18/2024	1195015	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	606474
870	06/18/2024	1195152	AIRBAG FRONT SCANIA K310UB E5 40Y2248 40Y2223	606474
870	06/18/2024	1195152	Mechanic entered - Suspension Other N/S/F air bag leaking.	606474
870	06/18/2024	1195152	Mechanic entered - Suspension Other Rear sway bar D rubber b	606474
870	06/18/2024	1195152	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)	606474
870	06/18/2024	1195152	Mechanic entered - Fluid Leaks Rear of bus Transmission outp	606474
870	06/18/2024	1195152	Mechanic entered - Fluid Leaks Other Diff oil seal leaking.	606474
870	06/18/2024	1195152	SEAL DIFF PINION SCANIA R660 1502385	606474
870	06/18/2024	1195152	NUT DIFF PINION SCANIA R660 1525988	606474
870	06/18/2024	1195152	SEAL REAR TRANSMISSION SR 4 SCANIA Zf 0734 319 052 01	606474
870	06/18/2024	1195152	Mechanic entered - Elec and Light Next Stop Button O/S first	606474
870	06/18/2024	1195152	Mechanic entered - Elec and Light Other Speedo head globes u	606474
870	06/18/2024	1195152	Mechanic entered - Elec and Light Other All switch globes u/	606474
870	06/18/2024	1195152	SWITCH STOP YELLOW (62628)(50V2242)	606474
870	06/18/2024	1195152	Consumables	606474
870	06/07/2024	1193157	Mechanic entered - Engine Other engine sump gasket oil leaks	606474
870	06/07/2024	1193157	GASKET SPINNER FILTER HOUSING (1116355)	606474
870	06/07/2024	1193157	GASKET SUMP DSC9 SCANIA L94 551450 1412666 1382398	606474
870	06/07/2024	1193157	O-RING LARGE UPPER SPINNER FILTER SCANIA	606474
870	06/07/2024	1193157	O-RING LOWER SPINNER FILTER SCANIA L94 K124	606474
870	06/07/2024	1193157	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS	606474
870	05/31/2024	1191713	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out as per check list	606474
870	05/20/2024	1125882	REFLECTOR AMBER SMALL 70x28mm	605378
870	05/20/2024	1125882	REFLECTOR RED NARVA 70x28mm (NR84037BL)	605378
870	05/20/2024	1125882	Consumables	605378
870	05/15/2024	1188349	PTI Tablet Entered -Elec and Light - Exterior Lights os head	604595
870	05/15/2024	1188349	GLOBE 24V H4 75/70W HALOGEN	604595
870	05/06/2024	1186237	PTI Tablet Entered -Elec and Light - Exterior Lights front n	603433
870	05/02/2024	1185838	Elec and Light Exterior Lights - Front bottom L/H indicato	603316
870	05/02/2024	1185838	Consumables	603316
870	03/22/2024	1178200	VEHICLE SAFETY INSPECTION Carried out Safety Inspection as per checklist.	602450
870	03/22/2024	1178200	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	602450
870	03/22/2024	1178200	Checked bus minder bus minder charging and working fine.	602450
870	03/22/2024	1178270	Mechanic entered - Elec and Light Exterior Lights Reverse li	602450
870	03/22/2024	1178270	Mechanic entered - Elec and Light Exterior Lights N/S/F top	602450
870	03/22/2024	1178270	Mechanic entered - Elec and Light Exterior Lights Step light	602450
870	03/22/2024	1178270	Mechanic entered - Elec and Light Interior Lights Drivers st	602450
870	03/22/2024	1178270	Consumables	602450
870	03/22/2024	1178200	Consumables	602450
870	03/22/2024	1178270	HANDLE HEIGHT & RAKE ORANGE	602450
870	03/22/2024	1178270	Mechanic entered - Body Other Drivers seat height adjuster h	602450
870	02/28/2024	1172704	Removed and fitted new handle.	601931
870	02/22/2024	1171627	complete	601790
870	02/22/2024	1171627	Driver Tablet install	601790
870	02/20/2024	1170948	installed bus minder tablet and cradle wired up power . checked operation and charging all ok	601790
870	02/20/2024	1170948	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	601385
870	01/08/2024	1162230	complete	601385
870	01/04/2024	1161235	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	601385
870	12/28/2023	1160187	COMPLETED	601385
870	12/28/2023	1160187	VEHICLE SAFETY INSPECTION Complete	601385
870	12/28/2023	1160187	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	601385
870	12/28/2023	1160187	Assisting	600933
870	11/06/2023	1150804	Driver entered to wrong bus	600597
870	10/25/2023	1148376	no fault found	600597
870	10/25/2023	1148376	Driver Tablet Entered -Body - Rear_Door Operation Faultyst	600096
870	10/13/2023	1146045	Consumables	600096
870	10/13/2023	1146045	Mechanic entered - Body Other Water leak inside bus.	599803
870	10/06/2023	1144389	INDICATOR CHECK LINK WHEEL NUT LOCK 33mm	599803
870	10/05/2023	1144389	consumable item.	599803
870	10/05/2023	1144389	VEHICLE SAFETY INSPECTION carried out safety as per check list	599803
870	10/05/2023	1144389	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	599803
870	10/05/2023	1144389	Assisting	599803
870	10/05/2023	1144389	INDICATOR CHECK LINK WHEEL NUT LOCK 33mm	599803
870	10/05/2023	1144444	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081	599803
870	10/05/2023	1144444	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081	599803
870	10/05/2023	1144444	Mechanic entered - Suspension Noisy front sway bar d bushes	599803
870	10/05/2023	1144433	Mechanic entered - Engine Other Compressor leaking from plug	599803
870	10/05/2023	1144433	PLUG COVER / BLANKING RR AIR COMPRESSOR SCANIA L94	599803
870	10/04/2023	1144245	Mechanic entered - BusMinder Missing Fit bus minder back int	599770
870	10/04/2023	1144245	USB 5V 3A DUAL CONVERTER MODULE BUS MINDER	599770
870	09/06/2023	1138823	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	598432
870	09/06/2023	1138823	Assisting	598432
870	09/06/2023	1138823	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR350346 Receiving #:369146 Date :2023-09-12 CARRY OUT A/C B SERVICE	599094
870	09/06/2023	1138823	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	598432
870	09/04/2023	1138191	REMOVE AND REPLACE STARTER MOTOR. (SECONDHAND UNIT)	598342
870	09/04/2023	1138365	Carried out campaign 05/23 - Position of no smoking no vaping decals	598342
870	09/01/2023	1137788	secure mirror	598101
870	08/29/2023	1136915	Completed by ATS 11.08.2023	597881
870	08/25/2023	1133423	correcting stock found in cycle count	597638
870	08/25/2023	1133423	correcting stock found in cycle count	597638
870	08/17/2023	1133423	NON-STOCK	596855
870	08/16/2023	1133423	LED AMBER HOZ	596559
870	08/15/2023	1133423	Ops Entered - Fault - indicator not working	596559
870	08/14/2023	1131732	BELT SEAT R/H ISRI(A6008)	596280
870	08/14/2023	1131732	Consumables	596280
870	08/10/2023	1132223	Workshop Tablet Entered -Elec and Light - Exterior Lights ne	596010
870	08/10/2023	1132223	GLOBE 24V 75/70W H4	596010
870	08/08/2023	1131732	Workshop Tablet Entered -Body - Drivers Seat Belt stalk cove	595773
870	08/08/2023	1131732	BELT SEAT R/H ISRI(A6008)	595773
870	07/19/2023	1127701	PERFORM CAMPAIGN 02/23 - Positioning of 2023 PTV Decals	594342
870	07/14/2023	1125829	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:CR346796 Receiving #:365082 Date :2023-07-18	594230
870	07/12/2023	1125829	VEHICLE SAFETY INSPECTION	593553
870	07/12/2023	1125829	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	593553
870	07/12/2023	1125829	ANNUAL SAFETY INSPECTION SERIAL #RSI 055516 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	593553

870	07/12/2023	1125829		Assisting	593553
870	07/12/2023	1125882	Mechanic entered - Elec and Light Other Reflector missing	R&R Reflector	593553
870	07/12/2023	1125882	REFLECTOR RED NARVA 70x28mm (NR84037BL)		593553
870	07/12/2023	1125882	REFLECTOR AMBER 94mm X 44MM (84051)		593553
870	07/12/2023	1126079	REGULATOR CHARGE MERC 0500LE SCANIA L94		593553
870	07/12/2023	1126079	Mechanic entered - Elec and Light Other Charge regulator fau	Removed and replaced charge regulator	593553
870	06/28/2023	1123029	Replace Anti Graffiti Film - R1 R3 R3A	Completed by GlassProtech 07.06.2023	593008
870	06/28/2023	1122982	Workshop Tablet Entered -Elec and Light - Hazard Lights	REPLACED GLOBE	593008
870	06/27/2023	1122779	Mechanic entered - Gearbox Driveline Other Output seal leaki	Replaced Seal	592947
870	06/27/2023	1122779	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734 319 052 01		592947
870	06/27/2023	1122779	LOCK PLATE - OUTPUT FLANGE 1250-304-353		592947
870	06/27/2023	1122757		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B Service	592947
870	06/27/2023	1122757		Assisting	592947
870	06/27/2023	1122757	FILTER FUEL SCANIA L94(1372444)		592947
870	06/27/2023	1122757	FILTER OIL SCANIA K93 L94 1117285 2059778		592947
870	06/27/2023	1122757	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		592947
870	06/27/2023	1122757	O-RING SPINNER FILTER SCANIA L94		592947
870	06/27/2023	1122757	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		592947
870	06/27/2023	1122757	OIL SAMPLE KIT AMPOL		592947
870	06/27/2023	1122757	Consumables		592947
870	06/27/2023	1122757	Consumables		592947
870	06/27/2023	1122757	Consumables		592947
870	06/22/2023	1121379	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #.:CR345326 Receiving #.:363445 Date :2023-06-27 CARRY OUT FIRE SAFETY INSPECTION	592947
870	06/21/2023	1123029	Replace Anti Graffiti Film - R	Creditor #.:VB-GLA010 GLASSPROTECH MELBOURNE P/O #.:CR345328 Receiving #.:363797 Date :2023-06-29	593068
870	06/21/2023	1119656	AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02	only 2 air bags used.	592541
870	06/21/2023	1121712	PTI Tablet Entered -Elec and Light - Indicators Not Working	R&R O/S/F side globe with new	592541
870	06/20/2023	1121379		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	592409
870	06/20/2023	1121379		Assisting	592409
870	06/09/2023	1119601		VEHICLE SAFETY INSPECTION	591663
870	06/09/2023	1119601		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	591663
870	06/09/2023	1119601		PRE ANNUAL SAFETY INSPECTION CHECK	591663
870	06/09/2023	1119601		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	591663
870	06/09/2023	1119656	Mechanic entered - Suspension Noisy Front D bushes worn		591663
870	06/09/2023	1119656	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		591663
870	06/09/2023	1119656	AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02		591663
870	05/29/2023	1117310	BATTERY 1030CCA POSITIVE ON LEFT H/S		590631
870	05/29/2023	1117310	Elec and Light Flat Batteries	batteries too low voltage (3volts) to jumpstart. Fit 2x new batteries and check charge	590631
870	05/29/2023	1117310	Consumables		590631
870	05/03/2023	1112100	VALVE SOLENOID ACCUMULATOR ZF(49D5802ZF)		588517
870	05/03/2023	1112100	Mechanic entered - Elec and Light Warning Light On Dash Bus	Replace alt reg and g/box accmulator soildniod	588517
870	05/03/2023	1112100	Consumables		588517
870	05/01/2023	1112100	REGULATOR ALTERNATOR BOSCH 140	Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #.:CR342167 Receiving #:359796 Date :2023-05-03 for 870	588517
870	04/27/2023	1110951	Workshop Tablet Entered -Elec and Light - Indicators Not Wor	REMOVE AND REPLACE NSF INDICATOR GLOBE	588016
870	03/23/2023	1104982	Ops Entered - Fault - Elec and Light Warning Light On Dash -	ADJUST ENGINE HATCH SWITCH	586274
870	03/23/2023	1104982	Consumables		586274
870	03/21/2023	1104244	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S	RETORQUE NSR WHEELNUTS TO SPEC	586033
870	03/21/2023	1104244	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S	Assisting	586033
870	03/21/2023	1104244	Consumables		586033
870	03/20/2023	1103612	TYRE 295/80R22.5 RECAP		586033
870	03/20/2023	1103612	Consumables		586033
870	03/17/2023	1103317	CHIN GUARD GREY SEAT TOP 870MM		585930
870	03/17/2023	1103317	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		585930
870	03/17/2023	1103317		VEHICLE SAFETY INSPECTION	585930
870	03/17/2023	1103317		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	585930
870	03/17/2023	1103317	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		585930
870	03/17/2023	1103612	Mechanic entered - Wheels and Tyres Worn N/S/R NEED REPLACIN		585930
870	03/16/2023	1103474	Consumables	REPLACED N/S/REAR TYRES	585930
870	03/16/2023	1103474	Mechanic entered - Elec and Light Next Stop Button REPLACED		585930
870	03/16/2023	1103474	SWITCH STOP YELLOW BUTTON (20485)		585930
870	03/16/2023	1103474	SWITCH STOP YELLOW BUTTON (20485)		585930
870	03/16/2023	1103474	SWITCH STOP RED/GREY		585930
870	03/16/2023	1103474	SWITCH STOP RED/GREY		585930
870	03/16/2023	1103474	SWITCH STOP RED/GREY		585930
870	02/27/2023	1099595		Completed by ATS 17.02.2023	584585
870	02/16/2023	1096785	Anti Graffiti Film R2	Creditor #.:VB-GLA010 GLASSPROTECH MELBOURNE P/O #.:CR337544 Receiving #:355350 Date :2023-02-24	584466
870	02/14/2023	1096785	Anti Graffiti Film R2	Completed by GlassProtech	583457
870	02/02/2023	1094228	Ops Entered - Fault - Wiper come on as turning corners	checked wipers for operation checked wipers whilst steering left and right could not fault. road test to double check. could not fault during road test	582444
870	02/02/2023	1094230	Consumables		582444
870	02/02/2023	1094230	Ops Entered - Fault - Elec and Light AM-FM Radio -driver spe	turned radio on found speaker not working removed speaker and found loose connection. secured plug refit speaker. drivers speaker working okay.	582444
870	01/13/2023	1091006	Ops Entered - Fault - Elec and Light Warning Light On Dash	road tested replaced wiper stalk.	582032
870	01/13/2023	1091006	SWITCH WIPER/WASHER SCANIA L94UAB 1424970		582032
870	01/04/2023	1089161		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST secured camera plugs	582019
870	12/23/2022	1087765		VEHICLE SAFETY INSPECTION carried safty as per check list repolaced front and rear d bushes fixed all other defects.	581793
870	12/23/2022	1087765		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	581793
870	12/22/2022	1087765			581894
870	12/22/2022	1087765	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)		581894
870	12/22/2022	1087765	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		581894
870	12/22/2022	1087765	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)		581894
870	12/22/2022	1087765	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		581894
870	12/08/2022	1085405	Mechanic entered - A/C Heating Belt Loose or_Missing	Replace a/c belts	580895
870	12/08/2022	1085405	BELT V COGGED TRI-POWER 17x2135mm		580895
870	12/06/2022	1084985		TRANSMISSION CHECK AS PER CHECK LIST	580815
870	11/14/2022	1080682	Consumables		578869
870	11/14/2022	1080682	Consumables		578869
870	11/14/2022	1080682	OSF PARK LIGHT N/W	REPLACE GLOBE	578869
870	10/15/2022	1075594	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	Carried out campaign 10/22	576790
870	10/10/2022	1074358	Workshop Tablet Entered -Engine - Noisy or Rattling	check over engine & road test. could not fault at time of test	576335
870	10/10/2022	1074360	Workshop Tablet Entered -Warning Lights - Engine	connect scan tool. could find any engine fault codes.all ok	576335
870	10/10/2022	1074359	Workshop Tablet Entered -Elec and Light - Next Stop Button	found stop bell switch turned off. turned on switch & test buzzer. test all ok	576335
870	10/10/2022	1074359	Consumables		576335
870	10/04/2022	1072767	TIE ROD ASSY SCANIA L94/K230/N310(2146105)(2584182)		575795
870	10/04/2022	1072767		Assisting	575795
870	10/04/2022	1072767		VEHICLE SAFETY INSPECTION	575795

870	10/04/2022	1072767		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Replace tie rod		575795
870	10/04/2022	1072864	Mechanic entered - Suspension Noisy front d bushes worn	Remove and replace front sway bar d rubbers		575795
870	10/04/2022	1072864	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081			575795
870	09/29/2022	1072131	Mechanic entered - Elec and Light Exterior Lights	Replaced headlight insert		575795
870	09/29/2022	1072131	HEADLIGHT INSET 178MM HI/LO			575795
870	09/29/2022	1072131	Consumables			575795
870	09/20/2022	1070662	Drv entered - Body Water Leaks Roof	RESEAL AS REQUIRED		575616
870	09/20/2022	1070662	Consumables			575616
870	09/16/2022	1069285	Drv entered - Suspension Hard	Bus raised removed broken 4-way valve transferred fittings to new valve with teflon tape. Fitted new valve to bus air built up + valve checked for leaks		575515
870	09/15/2022	1069285	Drv entered - Suspension Hard	Removed leaking protection valve marked and removed all fittings from protection valve cleaned fittings applied teflon tape + fit to new protection valve. Installed new valve to bus fitting cracked on new valve when tightening. Bus started + air built up air leaking from crack in fitting. New protection valve ordered.		575410
870	09/15/2022	1069285	40G2802WABCO -4 way	Creditor #:IB-MUL001 MULTISPARES LTD P/O #:-V329191 Receiving #:345986 Date :2022-09-20 870		575724
870	09/13/2022	1069285	circit protection valve 40G280	Creditor #:IB-MUL001 MULTISPARES LTD P/O #:-V328991 Receiving #:345588 Date :2022-09-14		575307
870	09/13/2022	1069285	Drv entered - Suspension Hard	Lifted bus with hoist supported with chassis stands. Inspected suspension no air leaks from bags. Air dumping from air bag controller under front of bus. Air leaking from 4-way protection valve at rear of bus. Removed + replaced air bag controller. Cleaned all fittings + assembled with teflon sealant tape. Checked for opera		575197
870	09/12/2022	1069285	Drv entered - Suspension Hard	Driven bus suspension appears to ride normally. Dash buttons for suspension control aren't functioning properly. Air suspension resets when doors close and bus begins driving. Air coming from under the front of the bus when suspension controls not working properly.		574950
870	09/09/2022	1068774	Ops Entered - Fault - Suspension Hard - Route: S2580 - Monb	reset suspension to normal ride height. Test operation. Ok. Road test Ok.		574950
870	09/09/2022	1068839		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service carried out by cold drive		574950
870	09/09/2022	1068839		Assisting		574950
870	09/09/2022	1068839	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-CR328794 Receiving #:345776 Date :2022-09-16 Carry out a/c a service		575515
870	09/06/2022	1067892	Mechanic entered - Suspension Hard front suspension raises w	Looked at front end and test drive bus. Will not fault see how it goes. Check out on pit seems ok.		574624
870	08/27/2022	1066242	Consumables			573858
870	08/27/2022	1066242	Mechanic entered - Body Other no rubbish bin in bus	fit rubbish bin to bus		573858
870	08/23/2022	1065199		Completed by ATS 16.08.2022		573364
870	08/23/2022	1064912	Consumables			573364
870	08/23/2022	1064912	Consumables			573364
870	08/23/2022	1064912	FILTER AIR DRYER SCANIA VOLVO(1393551)(20546795)(20424148)			573364
870	08/23/2022	1064912	OIL SAMPLE KIT AMPOL			573364
870	08/23/2022	1064912	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			573364
870	08/23/2022	1064912	O-RING SPINNER FILTER SCANIA L94			573364
870	08/23/2022	1064912		CARRY OUT C SERVICE AS PER CHECK LIST complete B + C SERVICE as per checklist		573364
870	08/23/2022	1064912				573364
870	08/23/2022	1064912	FILTER OIL SCANIA K93 L94(1117285)(2059778)			573364
870	08/23/2022	1064912	FILTER FUEL SCANIA L94(1372444)			573364
870	08/23/2022	1064912	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			573364
870	08/23/2022	1064912	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)			573364
870	08/23/2022	1064912	FILTER HYD COOLING FAN SCANIA SR3 4(1354074)			573364
870	08/23/2022	1064912	FILTER AIR OUTER SCANIA SR 3 & 4(395773)(AF25066)			573364
870	08/23/2022	1064912	FILTER FUEL CHASSIS SCANIA L94 UB(1393640)(PSD470/1)			573364
870	08/23/2022	1064912	PAPER SPINNER FILTER OIL INSERT SCANIA L94			573364
870	08/23/2022	1064912	Consumables			573364
870	08/23/2022	1064912	Consumables			573364
870	08/23/2022	1064912		CARRY OUT B SERVICE AS PER CHECK LIST		573364
870	08/22/2022	1064884	Drv entered - Warning Lights Engine	check fault codes. found pressed accel & brake pedal code. clear codes test all ok		572596
870	08/15/2022	1063159	Drv entered - Vandalism Vandalism/ Graffiti Interior	Paint over graffiti		572596
870	08/15/2022	1063159	Drv entered - Vandalism Vandalism/ Graffiti Interior	Assisting		571506
870	08/01/2022	1060477	Mechanic entered - Elec and Light Exterior Lights	replace indicator globe. test ok		571626
870	08/01/2022	1060011	DIRECT PURCHASE - GLASS - 8888	Creditor #:-VB-OBR001 O'BRIENS GLASS INDUSTRIES P/O #:-CR325968 Receiving #:342506 Date :2022-08-02 REMOVE AND REPLACE OS SIDE WINDOW GLASS		571626
870	08/01/2022	1060011	Consumables			571626
870	07/29/2022	1060011	Consumables			571335</

870	04/04/2022	1038765	Consumables			564265
870	03/29/2022	1037748	Drv entered - Warning Lights Engine	Check fault. No light at time of test. Check oil and coolant all ok		563901
870	03/22/2022	1036327		VEHICLE SAFETY INSPECTION		563180
870	03/22/2022	1036327		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		563180
870	03/22/2022	1036327		Assisting Assist in carrying out VSI on vehicle		563180
870	03/22/2022	1036327	Service	VEHICLE SAFETY INSPECTION. finish VSI		563180
870	03/22/2022	1036438	Ops Entered - Fault - Wipers and Washers Wipers Not Working	Re Filled washer bottle all working now		563180
870	03/22/2022	1036386	Consumables			563180
870	03/22/2022	1036386	Mechanic entered - Elec and Light Exterior Lights Front indi	Replaced front indicator lens		563180
870	03/22/2022	1036386	LENS AMBER ROUND (85945)			563180
870	02/24/2022	1031599	Mechanic entered - A/C Heating Belt Loose or_Missing	replace 2x A/C belts		561401
870	02/24/2022	1031599	BELT V-BELT COGGED TRI-POWER 17x2135mm			561401
870	02/24/2022	1031599	BELT V-BELT COGGED TRI-POWER 17x2135mm			561401
870	02/24/2022	1031375	Ops Entered - Fault - Elec and Light Warning Light On Dash	Check for fault with wipers coming on with indicators unable to fault		561401
870	02/23/2022	1031135		CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed By ATS Fire		561289
870	02/17/2022	1029654	Tablet Entered - Wipers activating each time steering wheel	checked bus for fault and can't get it to fault - OK		560868
870	02/01/2022	1011989	BRAKE DRUM	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR310995 Receiving #:332312 Date :2022-02-28		561624
870	01/25/2022	1024363	Service	replace sensor with good secondhand. clear faults. test all ok		559262
870	01/25/2022	1024363	Consumables			559262
870	01/24/2022	1024363	Drv entered - Elec and Light Warning Light On Dash	connect scan tool. found charge air sensor fault. ordered parts		559092
870	01/21/2022	1024173	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	Campaign Complete		559092
870	01/13/2022	1018637	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315	STOCK CORRECTION		558491
870	01/13/2022	1018637	Consumables			558491
870	01/10/2022	1021686		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		558226
870	12/31/2021	1020535	Drv entered - Warning Lights Engine	checked fault codes to many to pin point issue cleared codes and need to check again		558010
870	12/30/2021	1020153		VEHICLE SAFETY INSPECTION		558010
870	12/30/2021	1020153		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		558010
870	12/30/2021	1020232	BUSH FRONT SWAY BAR SCANIA K230UB 40mm(1919010)			558010
870	12/30/2021	1020232	Mechanic entered - Suspension Other front swaybar bushes wor	removed and replaced front swaybar bushes		558010
870	12/23/2021	1019580	Drv entered - Warning Lights Engine	check and delete fault codes test o.k		557572
870	12/17/2021	1018637	Ops Entered - Fault - Elec and Light Flat Batteries - Route	R&R charge reg with new check charging - OK		556904
870	12/17/2021	1018637	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315			556904
870	12/17/2021	1018637	Consumables			556904
870	12/01/2021	1011989	Service	CARRY OUT ROADTEST BRAKESTEST AND RECORD BRAKE TEMPS.		555681
870	11/22/2021	1011989	DIRECT PURCHASE - BRAKES	Creditor #:\VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:CR311192 Receiving #:326417 Date :2021-11-23 RELINE SCANIA FRONT BRAKE SHOES		554786
870	11/19/2021	1012810	Mechanic entered - A/C Heating Belt Loose or_Missing Belts t	A/C Belts replaced and re-fitted		554541
870	11/19/2021	1012810	BELT V-BELT COGGED TRI-POWER 17x2135mm			554541
870	11/19/2021	1012814	Mechanic entered - Engine Other ECU Faulty			554541
870	11/19/2021	1012814	Scania L94 ECU			554541
870	11/19/2021	1012805	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE			554541
870	11/18/2021	1012338	Mechanic entered - Wheels and Tyres Wheel Nut Retension Fro	Retorque steer wheelnuts to spec		554402
870	11/18/2021	1012338	Consumables			554402
870	11/17/2021	1011989	Brakes Foot_Brakes Pulling- wobble on steering	Removed and replaced front drums and shoes.		554402
870	11/16/2021	1011989	Brakes Foot_Brakes Pulling- wobble on steering	road test found brake shudder from front brakes		554344
870	11/15/2021	1011691	Drv entered - Warning Lights Engine	check & test wiring test all ok. change diode & will test. replace engine ECU all ok		554344
870	11/12/2021	1011006	Mechanic entered - Wheels and Tyres Wheel Nut Retension BOT	RETORQUE STEER WHEELNUTS TO SPEC		554168
870	11/12/2021	1011006	Mechanic entered - Wheels and Tyres Wheel Nut Retension BOT	Assisting		554168
870	11/12/2021	1011006	Consumables			554168
870	11/11/2021	1010944	Drv entered - Warning Lights Engine	check fault codes found codes 22161211. clear fault codes & road test. no fault at time of test		554168
870	11/10/2021	1010656	When braking the Steering Pulling to the right -	road test after new tyres all ok		554011
870	11/10/2021	1010656	When braking the Steering Pulling to the right -	check over steering components. all ok. road test suspect faulty tyre.replace steer wheels		554011
870	11/10/2021	1010656	TYRE 295/80R22.5 NEW			554011
870	11/10/2021	1010656	TYRE 295/80R22.5 NEW			554011
870	11/04/2021	1009461	Drv entered - Elec and Light Exterior Lights	replace head light globe		553598
870	11/04/2021	1009461	GLOBE 24V 75/70W H4			553598
870	10/27/2021	1007954	Drv entered - Warning Lights Engine	reset test o.k		553062
870	10/21/2021	1006739	Mechanic entered - Elec and Light Flat Batteries	jump started vehicle all functions working correctly		552377
870	10/21/2021	1006740	Mechanic entered - Elec and Light Other	jump start book back (jump started at 6:30)		552377
870	10/21/2021	1003955	PART NOT FIT FOR PURPOSE			552377
870	10/19/2021	1003955	BUZZER WARNING 12V - 24V 90 DECIBELS(HL6022)			552188
870	10/19/2021	1006213		CARRY OUT B SERVICE AS PER CHECK LIST		552188
870	10/19/2021	1006213	OIL SAMPLE KIT AMPOL			552188
870	10/19/2021	1006213	FILTER OIL SCANIA S4 & K			552188
870	10/19/2021	1006213	FILTER FUEL FILTER SCANIA SR4 (1372444)			552188
870	10/19/2021	1006213	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			552188
870	10/19/2021	1006213	PAPER SPINNER FILTER OIL INSERT SCANIA L94			552188
870	10/19/2021	1006213	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701			552188
870	10/19/2021	1006213	O-RING LARGE SPINNER FILTER SCANIA 40A7703			552188
870	10/19/2021	1006213	Consumables			552188
870	10/19/2021	1006213	Consumables			552188
870	10/14/2021	1003955	WARNING BUZZER	Creditor #:\VB-MUL002 MULTISPARES CROYDON P/O #:CR308443 Receiving #:323738 Date :2021-10-14 BUS 870		551873
870	10/13/2021	1003972	PIVOT WIPER SINGLE SWF 86.5MM	Creditor #:\VB-AGM001 AGMAT AGENCIES P/O #:CR308793 Receiving #:323668 Date :2021-10-13		551817
870	10/11/2021	1003972	Wipers and Washers Wipers Noisy wiper linkage worn	removed and replaced wiper pivot.		551658
870	10/11/2021	1003972	Wipers and Washers Wipers Noisy wiper linkage worn	assisted in wiper pivot replacement		551658
870	10/08/2021	1003972	a634320038901 RIDE HEIGHT LINK	Creditor #:\VB-DAIQ02 DAIMLER TRUCKS SOMERTON P/O #:CR308498 Receiving #:323437 Date :2021-10-11		551658
870	10/08/2021	1004297	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	RETORQUE NSR WHEELNUTS TO SPEC		551410
870	10/08/2021	1004297	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	Assisting		551410
870	10/08/2021	1004297	Consumables			551410
870	10/06/2021	1003749		VEHICLE SAFETY INSPECTION		551272
870	10/06/2021	1003749		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		551272
870	10/06/2021	1003749	PUMP WATER SCANIA L94 UAB(1510	Creditor #:\VB-MUL002 MULTISPARES CROYDON P/O #:CR308409 Receiving #:323239 Date :2021-10-07		551410
870	10/06/2021	1003972	Wipers and Washers Wipers Noisy wiper linkage worn			551272
870	10/06/2021	1003930	Mechanic entered - Wheels and Tyres Worn n/s rear inner tyre	removed and replaced n/s rear tyres		551272
870	10/06/2021	1003930	TYRE 295/80R22.5 RECAP			551272
870	10/06/2021	1003930	Consumables			551272
870	10/06/2021	1003860	Mechanic entered - Suspension Other front swaybar bushes wor	removed and replaced front swaybar bushes		551272
870	10/06/2021	1003905	Mechanic entered - Suspension Other o/s rear airbags leaking	replace both O/S/R air bags		551272
870	10/06/2021	1003905	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290			551272
870	10/06/2021	1003905	Mechanic entered - Suspension Other o/s rear airbags leaking	removed and replaced o/s rear airbags		551272
870	10/06/2021	1003860	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			551272
870	10/06/2021	1003799	BELT MICRO V SERPENT 8 RIB 2135mm LNG(1389048)			551272
870	10/06/2021	1003799	Mechanic entered - Engine Belts_Loose Noisy Missing engine b	removed and replaced engine belt and tensioner pulley		551272
870	10/06/2021	1003799	TENSIONER BELT SCANIA SR4(1859654)(1503113)			551272

870	10/06/2021	1003955	Mechanic entered - Elec and Light Other door over ride buzze	Remove and replace buzzer	551272
870	10/06/2021	1003949	Mechanic entered - Body Other 2x passenger stop buttons brok	replac e2x bus stop buttons	551272
870	10/06/2021	1003949	Yellow/Red Stop Switch		551272
870	10/06/2021	1003950	Mechanic entered - Body Other wrong emergency exit sticker	replace N/S/R emergancy exit sticker	551272
870	10/06/2021	1003950	DECAL EMERGENCY EXIT RED GLOW IN DARK 320MM X 45MM		551272
870	10/06/2021	1003949	Consumables		551272
870	10/06/2021	1003950	Consumables		551272
870	10/06/2021	1003858	Mechanic entered - Air System Air_Leak Rear rear middle air	removed and replaced drain valve	551272
870	10/06/2021	1003858	VALVE MANUAL DRAIN 22MM VOLVO B7RLE{1081328-5}(1581425-4)		551272
870	10/04/2021	1003238	Ops Entered - Fault - BusMinder Unable To Log In - Route:	reset busminder	551098
870	10/01/2021	998020	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-CR306629 Receiving #:324320 Date :2021-10-22 CARRY OUT A/C B SERVICE	552614
870	09/28/2021	1002029		TRANSMISSION CHECK AS PER CHECK LIST	551097
870	09/08/2021	998020		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	549835
870	09/08/2021	998020		Assisting	549835
870	09/08/2021	998020		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	549835
870	09/03/2021	997051	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	Campaign Completed	549471
870	09/01/2021	996354	Ops Entered - Fault - Elec and Light AM-FM Radio - Route:	secured wire	549143
870	08/30/2021	995884	Ops Entered - Fault - Elec and Light Warning Light On Dash	checked fault codes. found code 16 &22. cleared fault codes. recheck all ok	548855
870	08/30/2021	995884	Consumables		548855
870	08/27/2021	995146	Drv entered - Elec and Light Next Stop Button	Checked all n/s stop button ok. checked fuse and wiring. Fault found n/s stop button wire came out from plug. Reconnected plug and checked stop button works okay.	548755
870	08/27/2021	995146	Consumables		548755
870	08/26/2021	994907	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	needs more diagnosing all of the n/s left next stop buzzers n/w (except disable) BUS BEING REPAIRED KNOX DEPOT 26/8 REFER DEFECT 889528	548600
870	08/26/2021	994907	Consumables		548600
870	08/25/2021	994499	Ops Entered - Fault - BusMinder Unable To Log In - Route:	reset busminder	548249
870	08/25/2021	994499	Consumables		548249
870	08/24/2021	994369		CARRY OUT FIRE EXTINGUISHER TEST & TAG	548249
870	08/24/2021	994369		Assisting - Completed by ATS	548249
870	08/24/2021	994369		Completed by ATS	548249
870	08/13/2021	992068	Drv entered - Elec and Light AM-FM Radio	reset am-fm radio and set radio stations	547191
870	08/13/2021	992069	Drv entered - Elec and Light Next Stop Button	fit ns passenger stop button	547191
870	08/13/2021	992069	SWITCH STOP RED/GREY		547191
870	08/13/2021	992068	Consumables		547191
870	08/13/2021	992069	Consumables		547191
870	07/22/2021	987312	Drv entered - Elec and Light Reverse Buzzer	checked reverse bus operation buzzer is working correctly also checked buzzer itself connections are secure and is mounted securley looks fairly new could not fault	547191
870	07/22/2021	987312	Consumables		547191
870	07/20/2021	986839	Mechanic entered -	wrong bus entered	544430
870	07/15/2021	985684	Drv entered - Elec and Light AM-FM Radio	Checked radio working correctly	543308
870	07/15/2021	985684	Consumables		543308
870	07/14/2021	985424		VEHICLE SAFETY INSPECTION	543308
870	07/14/2021	985424		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	543308
870	07/14/2021	985424		ANNUAL SAFETY INSPECTION SERIAL #L501597_____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	543308
870	07/14/2021	985424		Assisting	543308
870	07/14/2021	985424	DIRECT PURCHASE - BUS INSPECTI	Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-CR302742 Receiving #:316992 Date :2021-07-16	544231
870	07/14/2021	985648	Mechanic entered - Body Other NS Mirror fallen off	Fitted new mirror head	543308
870	07/14/2021	985648	MIRROR L/H 380mm SHORT (UES1411E)		543308
870	07/12/2021	984861	REPLACE PASSENGER STOP REQUEST BUTTON	REPLACED PASSENGER STOP REQUEST BUTTON ASSEMBLY	543308
870	07/12/2021	984861	Yellow/Red Stop Switch		543308
870	07/12/2021	984861	Consumables		543308
870	07/01/2021	967501	DIRECT PURCHASE - CHASSIS	Creditor #:-VB-ENG001 600 ENGINEERING P/O #:-CR296728 Receiving #:316231 Date :2021-07-05 repair leaking fuel tank	542737
870	06/28/2021	973440	DIRECT PURCHASE ACCIDENT	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-CR298680 Receiving #:316032 Date :2021-06-30 CARRY OUT ACCIDENT REPAIRS #52042	542423
870	06/24/2021	981794	ELECTRICAL REPAIRS AS PER FIRE SAFETY W/O 541592	fitted new battery holder bolt made clearance at battery bracket broken and exposed wiring in main and beside drivers elect panel fixed secured harness that had broken p-clamp all clear	541592
870	06/24/2021	981752		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed FSI defects found: battery holder needs new securing bolt battery bracket close to terminals broken wiring at main elect pannel exposed connection at elect panel beside driver p-clamp broken holding up harness n/s/r near fuel tank time booked fixing issi	541592
870	06/23/2021	981664	Ops Entered - Fault - Body Front_Door Operation Faulty - loo	checked door and no fault. need better discription	541592
870	06/18/2021	980694		PRE ANNUAL SAFETY INSPECTION CHECK	541038
870	06/18/2021	980694		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	541038
870	06/18/2021	980694	DIRECT PURCHASE - CHASSIS	Creditor #:-VB-BAYBOL BAYSWATER BOLTS P/O #:-CR301239 Receiving #:315345 Date :2021-06-23 SUPPLY 4X BOLTS AND NUTS AS PER SAMPLE	541592
870	06/18/2021	980851	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		541038
870	06/18/2021	980851	TORQUE ROD FRT UPPER SCANIA K230UB 1438475 2055289		541038
870	06/18/2021	980851	TORQUE ROD FRT UPPER SCANIA K230UB 1438475 2055289		541038
870	06/18/2021	980851	Mechanic entered - Suspension Other Both front upper torque	R&R both upper torque rods with new and R&R front d rubbers with new	541038
870	06/18/2021	980851	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		541038
870	06/18/2021	980736	Mechanic entered - Engine Other X1 engine idler worn and bel	R&R both with new	541038
870	06/18/2021	980736	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		541038
870	06/18/2021	980736	PULLEY IDLER SCANIA (1514087)		541038
870	06/08/2021	978920	Drv entered - Body Drivers Seat twisted	Fitted up new seat with new belt reel and previous buckle.	540277
870	06/08/2021	978920	SEAT DRIVER NEW 6008 ISRI		540277
870	06/08/2021	978920	BELT SEAT BELT LAP O/S		540277
870	06/07/2021	975685	VALVE FOOT VALVE SCANIA SR3 &	Creditor #:-VB-MUL002 MULTISPARES CROYDON P/O #:-CR300531 Receiving #:314358 Date :2021-06-07	540156
870	06/01/2021	967478	Direct Purchase - BODYWORK	Creditor #:-VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:-CR296716 Receiving #:314689 Date :2021-06-11 Reseal 2 x side windows	540409
870	05/28/2021	977044	Ops Entered - Fault - Warning Lights Engine - Route: 672 -	CLEAR CODES ROADTEST CHECKED O.K	539342
870	05/25/2021	976331	Drv entered - Body Drivers Seat Leaning	CHECKED DRIVERS SEAT CHECKED O.K	538915
870	05/24/2021	976071	Steering Shakes/ Wobbles under braking at times and when	CHECKED AND ROADTEST BUS DID NOT FAULT RETURN TO WORKSHOP CHECKED ALL STEERING SUSPENSIONBRAKE UNDERCARRIAGE COMPONENTS ALL CHECKED O.K	538744
870	05/21/2021	975685	Ops Entered - Fault - Brakes Park_Brake Not Releasing - Ro	REMOVE AND REPLACE BRAKE FOOT VALVE.CARRY OUT BRAKE TEST AND CHECK TEMPS	538657
870	05/21/2021	975685	VALVE FOOT VALVE SCANIA SR3 & SR4 0469052 571136		538657
870	05/21/2021	975630	Accident #52042 - N/S/ Rear Bumper. Unreported Accident	REPAIRED ECOAST DANDENONG	538657
870	05/21/2021	975629	Accident #52042 - N/S/ Rear Bumper. Unreported Accident	Duplictae work order 973440	538657
870	05/20/2021	975497	Body drivers seat belt	adjust & tighten seat belt	538316
870	05/11/2021	973440	Accident - NEAR SIDE REAR #52042	REPAIRED EASTCOAST DANDENONG	538316
870	05/11/2021	973440	Accident - NEAR SIDE REAR #52042	Assisting	538316
870	05/06/2021	972533	PERFORM CAMPAIGN 12/21 ROUTE BUS DESTINATION FILE UPDATE	completed upload	538316
870	05/04/2021	972135	driver states twoway radio will not work	CHECKED TWO-WAY RADIO WORKING O.K	538119
870	05/04/2021	972135	Consumables		538119
870	04/27/2021	970570	Drv entered - Elec and Light AM-FM Radio	RESET RADIO AND SET STATIONS	536942
870	04/26/2021	970462	Drv entered - Warning Lights Engine	reset test o.k	536942
870	04/26/2021	970551	Drv entered - Warning Lights Engine	had 3 fault codes. 12. 16 & 22. clear fault codes. rechecked after a day no faults.	536942
870	04/26/2021	967501	Direct Purchase - BODYWORK	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-CR297441 Receiving #:311918 Date :2021-05-05 REMOVE AND REPLACE BODY TO CHASSIS MOUNT AT OS FUEL TANK AREA	538316
870	04/26/2021	970463	Drv entered - Elec and Light AM-FM Radio	checked o.k	536942
870	04/22/2021	967501	Service	REMOVE AND REFIT REPAIRED FUEL TANK. BODY TO CHASSIS MOUNT RERPAIRED BY MICK VALKRANOFF	536657
870	04/16/2021	968558	Ops Entered - Fault - Elec and Light - 2 way radio not wor	TURN ON TWO WAY RADIO TEST O.K	535867
870	04/13/2021	967475	BOLT COMPRESSOR GEAR		535693
870	04/13/2021	967475	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1871043 1376911	remove compressor change fittings and gear over to new	535693
870	04/13/2021	967475	Mechanic entered - Air System Other Water in air tanks and b	Fit air compressor and check over	535693
870	04/13/2021	967475	Mechanic entered - Air System Other Water in air tanks and b		535693

870	04/12/2021	967257	VEHICLE SAFETY INSPECTION	535442
870	04/12/2021	967257	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete VSI and repairs	535442
870	04/12/2021	967481	fit new wiper blades	535442
870	04/12/2021	967481	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	535442
870	04/12/2021	967481	WIPER REFILL 1000mm MULTI FIT (TRP1000)	535442
870	04/12/2021	967351	R&R front D rubbers with new	535442
870	04/12/2021	967351	Mechanic entered - Suspension Other Front D rubbers worn	535442
870	04/12/2021	967351	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM	535442
870	04/12/2021	967295	R&R pully with new	535442
870	04/12/2021	967295	Mechanic entered - Engine Other X1 engine idler pully worn	535442
870	04/12/2021	967295	PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801	535442
870	04/12/2021	967501	changed coolant level sensor with new	535442
870	04/12/2021	967404	Elec and Light Warning Light On Dash low coolant light on	535442
870	04/12/2021	967404	SENDER LOW COOLANT LEVEL SCA	535622
870	04/12/2021	967478	Creditor #:-VB-MUL002 MULTISPARES CROYDON P/O #:-CR296685 Receiving #:310071 Date :2021-04-12	535442
870	04/12/2021	967478	Body Windows Side. O/s windows 3 and 4 bneed reseal	535442
870	04/12/2021	967478	Repairs carried out by alpha glass	535442
870	04/12/2021	967478	Consumables	535442
870	04/12/2021	967475	Mechanic entered - Air System Other Water in air tanks and b	535442
870	04/12/2021	967475	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)	535442
870	04/12/2021	967475	AIR COMPRESSOR RR DRIVE	535693
870	04/06/2021	966300	Creditor #:-VB-MUL002 MULTISPARES CROYDON P/O #:-CR296727 Receiving #:310242 Date :2021-04-14	535442
870	04/04/2021	966028	could not fault at time of test. all working ok	535442
870	04/04/2021	966028	Drv entered - Elec and Light Next Stop Button	535442
870	04/04/2021	966028	replace stop button	535442
870	04/04/2021	966028	SWITCH STOP RED/GREY	535442
870	03/30/2021	965161	Campaign Complete	535127
870	03/30/2021	965162	Campaign Complete	535127
870	03/30/2021	965162	Place new poster over the top attach hangers to hand rails	534993
870	03/29/2021	964704	refer W/O 964705	534993
870	03/29/2021	964705	R&R Drive belt with new.	534993
870	03/29/2021	964705	Mechanic entered - Engine Noisy or Rattling	534993
870	03/29/2021	964705	Mechanic entered - Engine Noisy or Rattling	534993
870	03/29/2021	964705	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048	534993
870	03/23/2021	962814	R&R with new	534339
870	03/23/2021	962814	Mechanic entered - Body Other O/S next stop button broken	534339
870	03/23/2021	962814	SWITCH STOP RED/GREY	534028
870	03/19/2021	961940	Campaign Completed	532957
870	03/10/2021	959616	replace stop button with secondhand	532957
870	03/10/2021	959616	Ops Entered - Fault - Elec and Light - buzzer staying on	532957
870	03/10/2021	959616	Consumables	532265
870	03/02/2021	957993	removed v-stay bolt in diff housing fit pulling half bolt and puller bolt tighten by hand until stopped then tightened with impact gun. v-stay came loose. removed chassis buch bolts. removed v-stay. fit new v-stay and tensioned all bolts to factory specs.	532265
870	03/02/2021	957993	Suspension (None) V rod worn	532265
870	03/01/2021	957774	fitted new air filter indicator	532265
870	03/01/2021	957774	Mechanic entered - Engine Other engine air filter indicator	532265
870	03/01/2021	957774	INDICATOR AIR FILTER SCANIA L94UAB (1358837)	532265
870	03/01/2021	946849	Creditor #:-VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:-CR291172 Receiving #:307926 Date :2021-03-10 RESEAL OSF No1 SIDE WINDOW GLASS	532957
870	03/01/2021	946849	DIRECT PURCHASE GLASS	532265
870	03/01/2021	957762	CARRY OUT B SERVICE AS PER CHECK LIST carry out B service as per checklist	532265
870	03/01/2021	957762	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281	532265
870	03/01/2021	957762	FILTER FUEL FILTER SCANIA SR4 (1372444)	532265
870	03/01/2021	957762	FILTER OIL SCANIA S4 & K	532265
870	03/01/2021	957762	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050	532265
870	03/01/2021	957762	Consumables	532265
870	03/01/2021	957762	Consumables	532265
870	03/01/2021	957762	Consumables	532265
870	02/17/2021	946198	replace speaker cover	531058
870	02/17/2021	955009	Campaign Completed	531058
870	02/16/2021	954297	Completed By ATS	530928
870	02/16/2021	954297	CARRY OUT FIRE EXTINGUISHER TEST & TAG	530928
870	02/11/2021	952770	Consumables	530585
870	02/11/2021	952770	Retention wheel nuts	530261
870	02/11/2021	952770	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSF	530261
870	02/11/2021	952770	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSF	530261
870	02/10/2021	952573	Assisting	530261
870	02/09/2021	952366	Campaign Completed	530261
870	02/09/2021	952366	Consumables	530083
870	02/09/2021	952366	Mechanic entered - Wheels and Tyres Worn NSF tyre worn to tr	530083
870	02/09/2021	952366	Mechanic entered - Wheels and Tyres Worn NSF tyre worn to tr	530083
870	02/09/2021	952365	Mechanic entered - Air System Warning Light On Driver compla	530083
870	02/01/2021	946198	Checked air system for leaks and target pressure. Took for extended test drive and could not replicate any fault.	529359
870	02/01/2021	946198	Body (None) O/S/R speaker cover damaged	529359
870	02/01/2021	946017	refer W/O 955009	529359
870	02/01/2021	946017	Mechanic entered - Body Other OSR saloon speaker grille dama	529002
870	01/28/2021	949695	Consumables	528837
870	01/28/2021	949695	Ops Entered - Fault - Elec and Light Horn - Route: - Arri	528410
870	01/22/2021	948801	Consumables	528410
870	01/22/2021	948801	drivers speaker seems to be working at time of test head unit is old and not working at its best could do with a new one soon	528410
870	01/22/2021	948801	Ops Entered - Fault - Elec and Light AM-FM Radio - Route:	528216
870	01/14/2021	946849	Consumables	528104
870	01/14/2021	946849	Body Windows Side O/S/F #1 window need reseal	528104
870	01/14/2021	946849	Body Windows Side O/S/F #1 window need reseal	527983
870	01/13/2021	946448	A/C Heating Not Cooling	527983
870	01/13/2021	946448	SOLENOID 24V CONT SILVER CONTACT ST88 ACX3306	527983
870	01/13/2021	946256	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	527983
870	01/13/2021	946470	Campaign Completed	527983
870	01/12/2021	945923	VEHICLE SAFETY INSPECTION COMPLETE AS PER W/O	527983
870	01/12/2021	945923	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS COMPLETE AS PER W/O	527983
870	12/31/2020	944009	refer W/O 944009	526696
870	12/31/2020	944009	Knocking noise when braking. Coolant light came on.	526696
870	12/31/2020	944008	check coolant level all ok. check fault codes none found. replace front swaybar D bushes. road test all ok	526696
870	12/31/2020	944008	Knocking noise when braking. Coolant light came on.	526696
870	12/31/2020	944008	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM	526696
870	12/31/2020	944008	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM	526696
870	12/01/2020	938685	check A/C adjust temp 18deg run bus inside temp came down to 18deg.readjust to 21.5deg. could not fault at time of test	524508
870	12/01/2020	938685	Check air con in cooling mode	524508
870	12/01/2020	938685	Ops Entered - Fault - A/C Heating Not Cooling - Route: 689	524508
870	11/30/2020	936349	Creditor #:-VB-MUL002 MULTISPARES CROYDON P/O #:-CR288382 Receiving #:301374 Date :2020-12-02	524688
870	11/30/2020	938354	INDICATOR AIR FILTER SCANIA	524328
870	11/30/2020	938354	Ops Entered - Fault - Body Front_Door Operation Faulty - ala	524328
870	11/30/2020	938354	Consumables	523793
870	11/30/2020	938110	Campaign Completed	523793
870	11/30/2020	938110	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	523793
870	11/25/2020	936349	SERVICE MOISTURE EJECTOR	523793
870	11/25/2020	936349	KIT CYCLONE CONDENSOR VALVE KIT LOWER SECTION	523793
870	11/25/2020	936349	Consumables	523793
870	11/25/2020	936349	FILTER AIR FILTER (395773) AF25066	523793
870	11/25/2020	936349	FILTER AIR FILTER INNER SCANIA SR3 SR4 397813	523793
870	11/23/2020	933136	non-stock item. correcting negative stock.	523653
870	11/23/2020	933136	SWITCH HAZARD 4 SERIES 1327015	523793
870	11/23/2020	933136	Consumables	523793
870	11/20/2020	935390	Campaign Completed	523475
870	11/20/2020	935508	Campaign Completed	523475
870	11/20/2020	935508	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	522700
870	11/13/2020	933136	replace hazard switch	522700
870	11/13/2020	933136	Mechanic entered - Elec and Light Exterior Lights hazard swi	522700
870	11/13/2020	933136	SWITCH HAZARD 4 SERIES 1327015	522700
870	11/09/2020	931804	all stickers fitted	522136
870	11/09/2020	931804	Fit new Myki Decals & refit COVID-19 decals new position f	521829
870	11/05/2020	930788	TRANSMISSION CHECK AS PER CHECK LIST	520555
870	10/20/2020	927538	Trans cooler line leak. Driver complained of 'soft' brakes. Replaced cooler hose and adjusted slack adjusters. Test drove and brake tested. Temps okay.	520555

870	10/15/2020	926713	Body	N/S/F & O/S/F/windows need resael	repaired by Alpha Glass	920213
870	10/15/2020	926714	Consumables			920213
870	10/14/2020	926297			VEHICLE SAFETY INSPECTION complete	920213
870	10/14/2020	926297			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	920213
870	10/14/2020	926350	Mechanic entered -	Suspension Other Front and rear swaybar D	R/R front and rear swaybar D bushes	920213
870	10/14/2020	926350	BUSH SWAY BAR D/AXLE	SCANIA K124IB 40Y3450		920213
870	10/14/2020	926350	BUSH FRT SWAY BAR	SCANIA K230UB 0469081 1919010 40MM		920213
870	10/14/2020	926324	BELT MICRO V SERPENTINE	BELT 8 RIB 2135mm LONG (1389048)		920213
870	10/14/2020	926324	Mechanic entered -	Engine Belts_Loose Noisy Missing Accessor		920213
870	10/06/2020	924402	PERFORM CAMPAIGN	20/20 VEHICLE TOLLWAY ETAG FITMENT		920213
870	10/01/2020	918858	HOSE BEND			519426
870	10/01/2020	920540	HOSE G/BOX	COOLING SCANIA L9	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR283339 Receiving #:298064 Date :2020-10-15	520213
870	09/28/2020	922644	Vandalism/	Vandalism/ Graffiti Interior needs paint	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR283873 Receiving #:298063 Date :2020-10-15	520213
870	09/25/2020	920312	AIR CONDITIONING	REPAIR	Painted over Graffiti	519301
870	09/17/2020	920540	Ops Entered -	Fault - Warning Lights Temperature - Route:	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR283789 Receiving #:297224 Date :2020-10-02 CARRY OUT A/C A SERVICE	519301
870	09/17/2020	920540	CAP EXPANSION	TANK 0.75BAR SCANIA K93 L113 1403954	REMOVE AND REPLACE TRANSMISSION COOLER COOLANT HOSE. FILL WITH COOLANT ROADTEST O.K.FIT NEW HEADER TANK CAP	518816
870	09/16/2020	915980	DIRECT PURCHASE	ACCIDENT		518816
870	09/16/2020	920312			Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR282345 Receiving #:296161 Date :2020-09-17 CARRY OUT ACCIDENT DAMAGE #50738	519027
870	09/16/2020	920312			CARRY OUT A/C - A SERVICE AS PER CHECK LIST (COLDRIVE)	518816
870	09/08/2020	918865	Mechanic entered -	Engine Noisy or Rattling Boost leak at in	Assisting	518816
870	09/08/2020	918865	Mechanic entered -	Engine Noisy or Rattling Boost leak at in	Fitted new O-Ring to intercooler hose	518140
870	09/08/2020	918858	Fluid Leaks	Rear of bus. bottom radiator hose leaking coo	Assist DP fitting new O-Ring to hose	518140
870	09/08/2020	918858	Fluid Leaks	Rear of bus. bottom radiator hose leaking cool	Fitted new coolant hose and filled with coolant	518140
870	09/03/2020	917950	Mechanic entered -	Elec and Light Other Battery light on das	Assist DP fitting new coolant hose and filled bus with coolant.	517784
870	09/03/2020	917950	CHARGE REGULATOR	VOLTAGE	Inspect fault. Found alternator reg u/s. Remove and replace charge reg	517784
870	09/03/2020	917950	Consumables			517897
870	09/01/2020	915980	Accident #50980 -	N/S Panel Srtatched. DAF	repaired at east coast truck & bus	517784
870	09/01/2020	915980	Accident #50980 -	N/S Panel Srtatched. DAF	Assisting	517784
870	08/21/2020	915475	Accident #50737 -	damage to o/s/r bumper corner. TPAF	completed	517538
870	08/20/2020	903691	SOLENOID VALVE	SCANIA (REAR)	incorrect PN booked to WO correcting neg stock	517424
870	08/20/2020	886125	LAMP HEADLAMP	MK3 VOLVO B10M	incorrect qty booked to work order. correcting neg stock	517424
870	08/20/2020	886125	Consumables			517538
870	08/17/2020	914153			Completed	516918
870	08/17/2020	914153			CARRY OUT FIRE EXTINGUISHER TEST & TAG	516918
870	08/06/2020	908007	REPLACE ANTI	GRAFFITI FILM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:CR279938 Receiving #:293434 Date :2020-08-11	516425
870	08/06/2020	911559	Remove old A3	Poster and fit with You can no longer top up	Completed	515974
870	08/01/2020	903425	DIRECT PURCHASE	GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:CR278346 Receiving #:293928 Date :2020-08-18 REMOVE AND REPLACE OSR SIDE WINDOW	517116
870	07/30/2020	904972	SPRING		booked to work order in error. correcting stock levels	515407
870	07/30/2020	904972	HOSE		booked to work order in error. correcting stock levels	515407
870	07/24/2020	904972	GASKET INJ	PUMP GEAR COVER L	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR278966 Receiving #:292231 Date :2020-07-24	514863
870	07/24/2020	904972	DIAPHRAM	K280	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR278966 Receiving #:292231 Date :2020-07-24	514863
870	07/24/2020	904972	SPRING		Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR278966 Receiving #:292231 Date :2020-07-24	514863
870	07/24/2020	904972	HOSE		Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR278966 Receiving #:292231 Date :2020-07-24	514863
870	07/21/2020	908007	Vandalism: Replace	Anti Graffiti Film - L1 L2 R2	Compleetd by glassprotect	514319
870	07/15/2020	906779			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	513637
870	07/15/2020	906779			VEHICLE SAFETY INSPECTION	513637
870	07/15/2020	906779			Assisting	513637
870	07/15/2020	906779			ANNUAL SAFETY INSPECTION SERIAL #K921633 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	513637
870	07/15/2020	906779	DIRECT PURCHASE -	BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR279450 Receiving #:291333 Date :2020-07-15	513904
870	07/08/2020	904858	VALVE EXTENSION-130mm	Metal type		512919
870	07/08/2020	904858	Consumables			513113
870	07/08/2020	904858	Consumables			513113
870	07/08/2020	904858	Consumables			513113
870	07/08/2020	904858	Consumables			513113
870	07/07/2020	904858				512563
870	07/06/2020	904972	BELT MICRO V SERPENTINE	BELT 8 RIB 2135mm LONG (1389048)		512563
870	07/06/2020	904972	Fluid Leaks	Rear of bus. engine oil leak		512563
870	07/06/2020	904972	Fluid Leaks	Rear of bus. engine oil leak		512563
870	07/06/2020	904858			R/R air breather diaphragm and plate	512563
870	07/06/2020	904858	FILTER ZF TRANS	ECOMAT (1193281-1)/4139 298 038 01)	assit mick to complete b service	512563
870	07/06/2020	904858	KIT O-RING OIL SPINNER	FILTER SCANIA ABOVE ENG #6203050		512563
870	07/06/2020	904858	Oil Filter	SCANIA S4 & K		512563
870	07/06/2020	904858	FILTER FUEL	FILTER SCANIA SR4 (1372444)		512563
870	07/06/2020	904858	TENSIONER	SR4 FLATBACK BELT 1859654 knx 1503113		512563
870	07/06/2020	904858				512563
870	07/06/2020	904858	OIL ANALYSIS KIT	DETECTA AZ-DET25 3350-601 23448457		512563
870	07/03/2020	904574	Body	Drivers window latch missing	Carry out b service as per work order	512349
870	07/01/2020	903250	Direct Purchase -	MECHANICAL	secured rear drivers window slider	513113
870	07/01/2020	903250	CONSUMABLE -	DELIVERY CHARGE	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277RET Receiving #:290971 Date :2020-07-09 SEAT CHIN GUARDS 1170MM	513113
870	07/01/2020	903250	CHIN GUARD	GREY SEAT TOP 1170M	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277RET Receiving #:290971 Date :2020-07-09	513113
870	07/01/2020	903250	CONSUMABLE -	DELIVERY CHARGE	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277A Receiving #:290979 Date :2020-07-09	513113
870	06/30/2020	903691	REPLACE FRONT	SUSPENSION SOLENOID VALVE	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277A Receiving #:290979 Date :2020-07-09	511699
870	06/30/2020	903691	REPLACE FRONT	SUSPENSION SOLENOID VALVE		511699
870	06/30/2020	903691	SOLENOID VALVE	SCANIA (REAR)		511699
870	06/30/2020	903691	REPLACE FRONT	SUSPENSION SOLENOID VALVE	diagnose front suspention solenoid valve as faulty R & R with new unit and fixed issue	511699
870	06/30/2020	903691	VALVE FRT	LVL CNTRL VALVE VO	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR278437 Receiving #:290346 Date :2020-06-30	511916
870	06/30/2020	903250	Body	(None) seat roll top damaged	R&R with new	511699
870	06/30/2020	903691	Body	Drivers Seat Leaning and not straight		511699
870	06/30/2020	903691	Body	Drivers Seat Leaning and not straight	checked over seat and found no issues	511699
870	06/26/2020	903425	Body	Windows Side O/S window cracked	Assisting	511557
870	06/26/2020	903425	Body	Windows Side O/S window cracked		511557
870	06/26/2020	903250	Direct Purchase -	MECHANICAL	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277 Receiving #:290370 Date :2020-06-30 SEAT CHIN GUARDS 1170MM	511916
870	06/26/2020	903250	FREIGHT	CHARGE	Creditor #:VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:CR278277 Receiving #:290370 Date :2020-06-30	511916
870	06/25/2020	903063	Mechanic entered -	Suspension Soft rear sway bar mount bushes	removed and replaced bushes. bent sway bar retainers to suit new bush.	511496
870	06/25/2020	903063	BUSH RR SWAY BAR	(50MM I/D) SCANIA K93CRB 228483		511496
870	06/25/2020	903102	Mechanic entered -	Suspension Soft front sway bar mount bush	replaced front sway bar bushes	511496
870	06/25/2020	903102	BUSH FRT SWAY BAR	SCANIA K230UB 0469081 1919010 40MM		511496
870	06/25/2020	903239	Mechanic entered -	Engine Other air dryer u/s	replaced air dryer and associated fitting to new unit. wash area.	511496
870	06/25/2020	903111	Mechanic entered -	Elec and Light Reverse Buzzer n/w	replaced buzzer	511496
870	06/25/2020	903111	BUZZER	REVERSING 24V 102DB NR72602		511496
870	06/25/2020	903111	Consumables			511557
870	06/25/2020	903053	Mechanic entered -	Body Other o/s/r hatch latch u/s	removed and replaced damaged latch	511496
870	06/25/2020	903053	CATCH CLAW	PLASMA ENGINE HATCH DOOR		511496

[illegible]

870	02/10/2020	873214	ELBOW FITTING FRT AIRBAG SCANIA L94UAB		499603
870	02/10/2020	873214	AIRBAG O/S/F SCANIA K230UB (2024284)		499603
870	02/10/2020	873214	FITTING		499603
870	02/10/2020	873166		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	499603
870	02/04/2020	871497	RECTIFY AIR LEAK FROM AIR DRYER - MOISTURE INJECTOR FLEXIBL	REMOVE AND REPLACE AIR HOSE TEST O.K	498716
870	02/04/2020	871497	DIRECT PURCHASE - BRAKES	Creditor #.:VB-PIR001 PIRTEK BAYSWATER P/O #.:CR267978 Receiving #:278729 Date :2020-02-04 SUPPLY AIR HOSE AS PER SAMPLE	499038
870	02/01/2020	870981	Wheels and Tyres Wheel Nut Retension both front	retension both front wheels	498716
870	02/01/2020	870981	Consumables		498844
870	02/01/2020	871006	Ops Entered - Fault - A/C Heating Not Cooling - Route: 688	check a/c all working. no driver boost function in bus	498716
870	02/01/2020	868441	replace N/S rear cracked windo	Creditor #.:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #.:CR266980 Receiving #:280994 Date :2020-03-02	500938
870	02/01/2020	868441	Consumables		498844
870	02/01/2020	868441	Consumables		498844
870	01/31/2020	870705	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	Completed Campagin	498716
870	01/30/2020	870372	Body Windows Side. N/S 2nd rear window is cracked	has already been fixed by alpha glass	498570
870	01/30/2020	870372	Consumables		498716
870	01/30/2020	870354	Mechanic entered - Brakes Foot_Brakes Noisy pulling to righ		498570
870	01/30/2020	870354	Mechanic entered - Brakes Foot_Brakes Noisy pulling to righ	road & brake test	498570
870	01/30/2020	870354	Mechanic entered - Brakes Foot_Brakes Noisy pulling to righ	replace front brake drums	498570
870	01/30/2020	870354	DRUM BRAKE DRUM REAR L94UB	Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #.:CR267602 Receiving #:278478 Date :2020-01-31 40f3317 brake drums	498716
870	01/20/2020	868441	Body Windows Side N/S/R window cracked	window replaced by Alpha glass	497541
870	01/20/2020	868441	Consumables		497695
870	01/09/2020	866108	A/C Heating not blowing in drivers cab	CHECK A/C VENT TEMP CHECKED O.K	496453
870	01/08/2020	865635	Mechanic entered - Wheels and Tyres Wheel Nut Retension STE	RETORQUE STEER WHEELNUTS TO SPEC	496102
870	01/08/2020	865635	Mechanic entered - Wheels and Tyres Wheel Nut Retension STE	Assisting	496102
870	01/08/2020	865635	Consumables		496453
870	01/06/2020	863949	Service	Replace nsf- osf brake slack adjuster Carry out roadtest/braketest checktemps o.k	495978
870	01/06/2020	863949	DIRECT PURCHASE - BRAKES	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:CR265878 Receiving #:276355 Date :2020-01-06 2026123 - supply brake slack adjuster wera indicator/washer	495978
870	01/01/2020	854157	Direct Purchase - BODYWORK	Creditor #.:VB-RP RP AUTO UPHOLSTERY PTY LTD P/O #.:CR262414 Receiving #:277351 Date :2020-01-20 RETRIM LONG SEAT BASE	497541
870	01/01/2020	854157	Consumables		495978
870	12/31/2019	863949	SLACK ADJUSTER FRONT OFF SID	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:CR265604 Receiving #:276314 Date :2020-01-03 OVERNIGHT EX ADELAIDE	495978
870	12/30/2019	864219	Mechanic entered - Wheels and Tyres Wheel Nut Retension	Inspected linings on steer axle. Both wheels were pulled off	495978
870	12/30/2019	864219	Consumables		495978
870	12/30/2019	863949	SLACK ADJUSTER N/S/F L94	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:CR265604 Receiving #:276010 Date :2019-12-30 EX CAMPBELLFIELD	495978
870	12/27/2019	863962	CCTV (None) service	done by Bwere	495978
870	12/27/2019	863962	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #.:CR265593 Receiving #:276088 Date :2019-12-31 service	495978
870	12/27/2019	863949	Mechanic entered - Brakes Foot_Brakes Pulling pulling to o/s	check and adjust brakes remove and replace n/s/f top torque rod	495978
870	12/27/2019	863949	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)		495978
870	12/27/2019	863956	Campaign (None) service	wrong job	495978
870	12/12/2019	857713	DIRECT PURCHASE ACCIDENT	Creditor #.:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #.:CR263602 Receiving #:274861 Date :2019-12-12 CARRY OUT ACCIDENT REPAIRS AS PER No 49965	494741
870	12/11/2019	861372	A3 Poster Frame Adhesive Decal Campaign please remove old	done	494658
870	11/28/2019	857713	Accident #49965 - couple of mid panel n/s - DAF	REPAIRED AT EASTCOAST	494658
870	11/28/2019	857713	Accident #49965 - couple of mid panel n/s - DAF	Assisting	494658
870	11/27/2019	857241	Ops Entered - Fault - Body Windowsdriver Side - why has th	temp window original unit being made	494356
870	11/25/2019	856719	Drv entered - Body Windows Side	this bus drivers window has a temporary repair. Alpha Glass are coming back to fix	494114
870	11/14/2019	854328	DIRECT PURCHASE - ENGINE	Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #.:CR262392 Receiving #:272551 Date :2019-11-15 SUPPLY SUMP GASKET	493535
870	11/14/2019	854439	DIRECT PURCHASE GLASS	Creditor #.:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #.:CR262411 Receiving #:272843 Date :2019-11-20 replace drivers window	493885
870	11/13/2019	854131		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	493377
870	11/13/2019	854131		VEHICLE SAFETY INSPECTION. refer W/O 854131	493377
870	11/13/2019	854328	Fluid Leaks Rear of bus. engine oil leak	REMOVE AND REPLACE SUMP AND FIT NEW SUMP GASKET	493377
870	11/13/2019	854439	Body Windows Front. drivers window broken		493377
870	11/13/2019	854328	Body Windows Side. drivers lower window needs reseal		493377
870	11/12/2019	854132		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	493377
870	11/12/2019	854132		VEHICLE SAFETY INSPECTION & repairs	493377
870	11/12/2019	854132		VEHICLE SAFETY INSPECTION & repairs	493377
870	11/12/2019	854154	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		493377
870	11/12/2019	854154	Mechanic entered - Steering Excessive Play	replace front sway bar D bushes	493377
870	11/12/2019	854154	Mechanic entered - Steering Excessive Play	replace front sway bar D bushes	493377
870	11/12/2019	854157		wrong bus	493377
870	11/08/2019	853311	Mechanic entered - Wheels and Tyres Wheel Nut Retension OSR	Assisting	492929
870	11/08/2019	853311	Mechanic entered - Wheels and Tyres Wheel Nut Retension OSR	RETORQUE OSR WHEELNUTS TO SPEC	492929
870	11/08/2019	853311	Consumables		493264
870	11/06/2019	852980	Mechanic entered - Wheels and Tyres Worn POS 5 and 6 tyres w	Replaced POS 6 with runout to match POS 5 approx 50% tread tensioned wheel nuts	492814
870	11/06/2019	852980	Consumables		492929
870	11/06/2019	852651	FILTER FUEL FILTER SCANIA SR4 (1372444)		492814
870	11/06/2019	852651	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		492814
870	11/06/2019	852651	Oil Filter SCANIA S4 & K		492814
870	11/06/2019	852651	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		492814
870	11/06/2019	852651		CARRY OUT B SERVICE AS PER CHECK LIST	492814
870	11/06/2019	852651	Consumables		492929
870	11/06/2019	852651	Consumables		492929
870	11/06/2019	852651	Consumables		492929
870	11/06/2019	852651	Consumables		492929
870	10/29/2019	851123	Drv entered - Warning Lights Engine	RESET CHECKED O.K	492199
870	10/29/2019	851226	Consumables		492303
870	10/29/2019	851226	Ops Entered - Fault - Elec and Light IndicatorsTurn on when	REPAIRED WIRING	492199
870	10/24/2019	850145		TRANSMISSION CHECK AS PER CHECK LIST	492021
870	10/22/2019	849596	Drv entered - Warning Lights Engine	check & clear fault codes. no warning lights on dash at time of test	491543
870	10/22/2019	849691	Consumables		491744
870	10/22/2019	849691	Ops Entered - Fault - Elec and Light Horn - Route: - Arriv	repair wiring to horn	491543
870	10/16/2019	848294	DIRECT PURCHASE - ENGINE	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:CR260231 Receiving #:270260 Date :2019-10-18 supply 1539692 gasket	491184
870	10/16/2019	848294	DIRECT PURCHASE - ENGINE	Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #.:CR260229 Receiving #:270258 Date :2019-10-18 supply rear main seal	491184
870	10/16/2019	848294	Fluid Leaks Rear of bus	remove gbox remove bell housing replace bell housing gasket and rear main seal replace accumulator piston refit all parts	490969
870	10/16/2019	848294	Fluid Leaks Rear of bus	asist Mick to remove trans rear cover and replace re main seal. put new bell housing gasket on and put trans back in fill with fluids wash and road test all good	490969
870	10/16/2019	848294	Fluid Leaks Rear of bus		490969
870	10/08/2019	846803	TYRE 295/80R22.5 NEW		490004
870	10/08/2019	846803	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 6	adjustall brakes. replace both front tyres 1x new 1x near new	490004
870	09/30/2019	845079	Engine (None) flush cooling system	Flushed cooling system re filled with red coolant.	489225
870	09/30/2019	845080	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866		489225
870	09/30/2019	845080	Mechanic entered - Brakes Park_Brake Not Releasing	Fitted new park brake valve	489225
870	09/24/2019	844231	DIRECT PURCHASE - ENGINE	Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #.:CR258714 Receiving #:268277 Date :2019-09-25 rear main oil seal	489020
870	09/24/2019	844231	Fluid Leaks Rear of bus. engine oil leak	Found oil leak at bellhousing-block Removed driveshaft trans and starter R/R rear bellhousing gasket and rear main seal Refitted trans driveshaft and starter motor filled with coolant oil checked for leaks Test drove Rechecked for leaks - okay.	489020
870	09/24/2019	844231	Fluid Leaks Rear of bus. engine oil leak	remove gearbox replace bellhousing gasket and remain seal	489020
870	09/24/2019	844231	Fluid Leaks Rear of bus. engine oil leak		489020

870	09/20/2019	843578	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR258502 Receiving #:268172 Date :2019-09-24 CARRY OUT A/C B SERVICE	489020
870	09/20/2019	843578		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	488774
870	09/20/2019	843578		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	488774
870	09/19/2019	843351	Ops Entered - Fault - Warning Lights Engine - Route: 664 -	checked no fault found	488391
870	09/05/2019	840388	Consumables		487294
870	09/05/2019	840388	Body Windows Front drivers windows not working	lube window	486996
870	08/30/2019	839155		CARRY OUT FIRE EXTINGUISHER TEST & TAG	486523
870	08/30/2019	839155		Completed	486523
870	08/19/2019	835086	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:CR255367 Receiving #:265529 Date :2019-08-26 CARRY OUT FIRE SAFETY INSPECTION	485996
870	08/15/2019	835487		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	484850
870	08/15/2019	835487		VEHICLE SAFETY INSPECTION	484850
870	08/15/2019	835487	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR255551 Receiving #:264809 Date :2019-08-16 CARRY OUT ANNUAL INSPECTION	484957
870	08/15/2019	835487		ANNUAL SAFETY INSPECTION SERIAL #K199286 _____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	484850
870	08/13/2019	835199	Consumables		486661
870	08/13/2019	835199	Ops Entered - Fault - Elec and Light Next Stop Button - Ro	found button turned off. turned button on & test all ok	484634
870	08/13/2019	835086		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	484634
870	08/07/2019	833992	Consumables		486661
870	08/07/2019	833992	Drv entered - Elec and Light Next Stop Button	found buzzer button turned off. turned button on and test all ok	484088
870	08/07/2019	834033	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWED01 BWERE ELECTRICS PTY LTD P/O #:CR254957 Receiving #:264227 Date :2019-08-09 video loss repair	484372
870	08/07/2019	834033	CCTV (None) service	done by bwere	484088
870	08/06/2019	833763	Consumables		486661
870	08/06/2019	833763	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		483897
870	08/06/2019	833763	Mechanic entered - Elec and Light Exterior Lights number pla	replace number plate light & repair wiring	483897
870	08/03/2019	833132		PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre annual inspection and listed defects found	483573
870	08/01/2019	832427	Fault#:36776 - Ops Entered - Fault - Breakdown Not Starting	jump started b/down van	483327
870	07/31/2019	832343	Vandalism: Replace Anti Graffiti Film - R2A	Completed By Glass Protect	483327
870	07/31/2019	832384	Consumables		483424
870	07/31/2019	832384	CABLE BATTERY BRIDGE SHORT	test batteries found to be faulty. replace batteries & repair hold down rplace x over cable	483327
870	07/31/2019	832384	BATTERY 800CCA (EMFN150L) (N150L)	test batteries found to be faulty. replace batteries & repair hold down rplace x over cable	483327
870	07/31/2019	832384	Elec and Light Flat Batteries	test batteries found to be faulty. replace batteries & repair hold down rplace x over cable	483327
870	07/15/2019	828899	Consumables		482722
870	07/15/2019	828899	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	replace stop bell button	481058
870	07/04/2019	826781	Consumables		480205
870	07/04/2019	826781	Mechanic entered - Elec and Light Flat Batteries	Jump started bus.	480114
870	07/02/2019	826336	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:CR252372 Receiving #:261296 Date :2019-07-09 Bus 870: 6 Monthy Service	480534
870	07/02/2019	826336	CCTVSIX MONTH SERVICE		479969
870	06/17/2019	823232	Consumables		478285
870	06/17/2019	823232	Mechanic entered - Warning Lights Batteries flat batteries	jump started all ok	478013
870	06/15/2019	821262	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		478013
870	06/15/2019	821262	RECTIFY TRANS FLUID LEAK AS REQUIRED	REMOVE AND REPLACE TRANSMISSION SUMPGASKETFILTER FILL WITH OIL ROADTEST CHECKED O.K	478013
870	06/06/2019	821184	BELT TENSIONER		477169
870	06/06/2019	821184	BALL BEARING		477169
870	06/05/2019	821184		finsiied washed and completed all ok	477168
870	06/05/2019	821184		VEHICLE SAFETY INSPECTION	476972
870	06/05/2019	821184		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	476972
870	06/05/2019	821184	DIRECT PURCHASE - STEERING	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249736 Receiving #:258333 Date :2019-06-05 SUPPLY DRAGLINK ASSEMBLY	477168
870	06/05/2019	821262	RECTIFY TRANS FLUID LEAK AS REQUIRED	CHECKED SUMP U/S ORDERED PARTS	476972
870	06/05/2019	821262	DIRECT PURCHASE - TRANSMISSION	Creditor #:VB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:CR249752 Receiving #:258439 Date :2019-06-05 SUPPLY SUMP GASKET AND WASHERS	477168
870	06/05/2019	821299	Mechanic entered - Engine Noisy or Rattling engine fan ider	replace fan idler bearing	476972
870	06/05/2019	821299	Consumables		477169
870	06/05/2019	821262	Consumables		477169
870	06/05/2019	821262	ISRI SEAT AIR SUSPENSION AIR LUMBER RECO		476972
870	06/05/2019	821299	Mechanic entered - Body Other front mudflap mount bent	straighten and secure	476972
870	06/05/2019	821299	Mechanic entered - Body Wheel Chair Ramp anti slip strip in	secure and reglue anti slip strip	476972
870	06/05/2019	821262	Mechanic entered - Body Drivers Seat Leaning Seat back rest	replace drivers seat	476972
870	05/29/2019	819855	Accident #48923-Damage to NS rear of bus Scrape marks and		476347
870	05/29/2019	819855	DIRECT PURCHASE ACCIDENT #4892	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR249214 Receiving #:257799 Date :2019-05-30 Damage to NS rear of bus Scrape marks and scuffs	476450
870	05/28/2019	819577	Gearbox Driveline (None) retarder N/W	adjust potentiometer in footvalve roadtest check o.k	476236
870	05/27/2019	819423	Consumables		476236
870	05/27/2019	819423	Ops Entered - Fault - BusMinder No Power - Route: - Arriv	Checked out Bus minder. found fault and Repair.	476025
870	05/22/2019	818533	Consumables		475755
870	05/22/2019	818533	Drivers seat is leaning and uncomfortable	CHECKED DRIVERS SEAT CONDITION O.K	475552
870	05/13/2019	816354	FIT GLASS PROTECH		474927
870	05/08/2019	816354	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:CR247886 Receiving #:256293 Date :2019-05-14 L4	474927
870	05/07/2019	814994	Please remove all old poster and fit MYKI has gone mobil	done	474570
870	05/03/2019	814122	Consumables		474465
870	05/03/2019	814122	Wheels and Tyres Vibration the whole bus is vibrating.	road test could not fine a vibration. found lose saloon panels & rattels. tighten & secure saloon pannels.	474331
870	05/01/2019	813060	25.1.19 - BWERE - Rectify not connect to 3G		473747
870	05/01/2019	803335	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR243224 Receiving #:256140 Date :2019-05-10 CARRY OUT ACCIDENT REPAIRS AS PER ACCIDENT #47737	474927
870	04/24/2019	811796	Consumables		473221
870	04/24/2019	811796	Drv entered - Elec and Light Indicators Not Working	refitted new 2 globes in o /s/f /t all checked all ok also checked and wiped down desto and blew out surrounds	473215
870	04/24/2019	811783	Right hand indicator is out.Left hand rear wheel arsh anti	refitted brush secured all ok	473215
870	04/24/2019	811816		Assisting on C service and test drive and wash.	473215
870	04/24/2019	811816	Consumables		473221
870	04/24/2019	811816	Consumables		473221
870	04/24/2019	811816	Oil Filter SC S4 & K		473215
870	04/24/2019	811816	FILTER FUEL FILTER SCANIA SR4 (1372444)		473215
870	04/24/2019	811816	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		473215
870	04/24/2019	811816	FILTER FUEL FILTER SCANIA SR4 (1393640)		473215
870	04/24/2019	811816	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		473215
870	04/24/2019	811816	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		473215
870	04/24/2019	811816	O-RING KIT OIL SPINNER FILTER SCANIA UP TO ENG #6203049		473215
870	04/24/2019	811816		CARRY OUT C SERVICE AS PER CHECK LIST	473215
870	04/24/2019	811816	Consumables		473221
870	04/24/2019	811816	Consumables		473221
870	04/24/2019	811816		CARRY OUT B SERVICE AS PER CHECK LIST	473215
870	04/12/2019	810053	Consumables		472193
870	04/12/2019	810053	Ops Entered - Fault - BusMinder No Power - Route: - Arriv	turn on ticket machine switch	472032
870	04/10/2019	809398	Consumables		471856
870	04/10/2019	809398	Wheels and Tyres Wheel Nut Retension. both front wheels.	Assisting	471572
870	04/10/2019	809398	Wheels and Tyres Wheel Nut Retension. both front wheels.	retorque steer wheels	471572
870	04/08/2019	808794	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:CR245240 Receiving #:253541 Date :2019-04-09 fit new brake linings and radius grind	471572
870	04/08/2019	808794	Brakes Vibration	Assisting	471542

870	04/08/2019	808794	Brakes Vibration	Remove front wheel assembly fit new drums and brake linings braketest /roadtest	471542
870	04/05/2019	808571	DIRECT PURCHASE - STEERING	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR245177 Receiving #:253401 Date :2019-04-05 SUPPLY STEERING WHEEL 1545452	471387
870	04/05/2019	808571	HORN PAD SC L94 (40M1310)		471387
870	04/05/2019	808571	Ops Entered - Fault - Brakes Foot_Brakes Leaking Air - jus	Adjust govenor valve.Check and adjust all brakes. Carry out braketest and roadtest checked o.k.. Remove and replace steering wheel and horn pad.	471387
870	04/02/2019	807904	Consumables		470937
870	04/02/2019	807904	INDICATOR SIDE INDICATOR R/H		470742
870	04/02/2019	807904	Elec and Light Flat Batteries. O/S indicator broken	replace broken indicator assy	470742
870	04/01/2019	813060	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:CR246731 Receiving #:255071 Date :2019-05-01 25.1.19 Rectify not connect to 3G	473945
870	04/01/2019	796907	SEAT BASE DOUBLE SEAT BASE	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:CR240864 Receiving #:253035 Date :2019-04-03 RETRIM SEAT BAS E AS REQUIRED	470937
870	03/25/2019	805786	Consumables		469860
870	03/25/2019	805786	Wheels and Tyres Wheel Nut Retension. N/S/R 469616 km	Assisting	469624
870	03/25/2019	805786	Wheels and Tyres Wheel Nut Retension. N/S/R 469616 km	TORQUE NSR WHEELNUTS	469624
870	03/19/2019	803335	Accident#:47737 - Ops Entered - Accident - Bus Hitting Obje	repair eastcoast Dandenong	469624
870	03/14/2019	803191	Consumables		469624
870	03/14/2019	803191	TYRE 295/80R22.5 RECAP	Creditor #:IB-TYR002 TYRES4U P/O #:V243273 Receiving #:252167 Date :2019-03-22 scania steel	469624
870	03/12/2019	803046		Finish off safety.	469537
870	03/12/2019	803046	FILTER AIR FILTER (395773) AF25066		469537
870	03/12/2019	803046			469537
870	03/12/2019	803046	INDICATOR SIDE INDICATOR R/H		469537
870	03/12/2019	803046		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	469537
870	03/12/2019	803046		VEHICLE SAFETY INSPECTION	469537
870	03/12/2019	803191	Wheels and Tyres Flat or Leaking	Remove and replace split tyre on N/S/R/I	469537
870	03/12/2019	803046	STEERING WHEEL SCANIA	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR243119 Receiving #:251384 Date :2019-03-13	469624
870	03/01/2019	807285		CARRY OUT FIRE EXTINGUISHER TEST & TAG	469261
870	02/28/2019	800892	GEAR SELECTOR BUTTONS STIFF	LUBRICATE GEAR SHIFT QUADRANT	469130
870	02/28/2019	800891	Consumables		469189
870	02/28/2019	800891	BusMinder No Power	TURN ON POWER SWITCH	469130
870	02/11/2019	796907	Consumables		468128
870	02/11/2019	796907	OSR SEAT DAMAGED	remove seat sent for retrim refit seat	468059
870	02/07/2019	796184	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	COMPLETED	467496
870	02/01/2019	785675	Consumables		467293
870	02/01/2019	785675	TYRE 295/80R22.5 NEW	Creditor #:VB-TYR002 TYRES4U P/O #:CR236817 Receiving #:249388 Date :2019-02-14 steel scania	468300
870	01/17/2019	791893	Please remove old 2018 fare decals and fit new 2019 fare de	COMPLETE	466661
870	01/03/2019	788941	FIT GLASS PROTECH		465165
870	12/31/2018	788941	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:CR237981 Receiving #:246152 Date :2019-01-08 L3A R2 R2A R3 R3A R4 - 5.12.18	466045
870	12/21/2018	787431	CCTV SERVICE		464927
870	12/19/2018	786881	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 Commercial Brake & Clutch P/O #:CR237307 Receiving #:245360 Date :2018-12-20 raduis grind front brake drums and linings	464877
870	12/19/2018	786881	Ops Entered - Fault - Wheels and Tyres Vibration -Wheel wob	Remove steer wheels send drum -hub wheel for radius grindingfit new brake shoes roadtest brake test check temps o.k	464877
870	12/17/2018	786122	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)		464625
870	12/17/2018	786122	BUSH SWAY BAR		464625
870	12/17/2018	786122			464625
870	12/14/2018	785969		Assisting	464625
870	12/14/2018	785969	RETORQUE NSF WHEEL NUTS	RETORQUE NSF WHEELNUTS	464625
870	12/14/2018	786122		Assisting	464625
870	12/14/2018	786122		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	464625
870	12/14/2018	786122		VEHICLE SAFETY INSPECTION	464625
870	12/13/2018	785675	Wheels and Tyres nsf worn	Remove and replace nsf tyre torque to spec David Cowan-Cvennix	464625
870	12/07/2018	787431	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:CR237607 Receiving #:245826 Date :2019-01-03 SERVICE CCTV	465165
870	11/02/2018	777271		TRANSMISSION CHECK AS PER CHECK LIST	461619
870	10/30/2018	776600	Elec and Light Exterior Lights N/S headlight out	Replaced globe	461436
870	10/12/2018	772951	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR231743 Receiving #:240184 Date :2018-10-22 Carry out a/c a service	460626
870	10/12/2018	772951		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	460073
870	10/07/2018	771493	Consumables		459560
870	10/07/2018	771493	passenger door front not working	traced and found alternator reg u/s . R&R reg checked operation of passenger doors all okay	459163
870	10/07/2018	771493	REGULATOR BOSCH 140AMP 1197311315 (VR3014G)		459163
870	10/04/2018	770775	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	COMPLETE	459163
870	10/01/2018	761577	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:CR227905 Receiving #:240870 Date :2018-10-30 Carry out fire safety inspection	461436
870	09/20/2018	767898		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	458940
870	09/20/2018	767898		VEHICLE SAFETY INSPECTION	458940
870	09/20/2018	767898	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR230054 Receiving #:237664 Date :2018-09-20	458940
870	09/20/2018	767898	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)		458940
870	09/20/2018	767898	AIRBAG O/S/F SCANIA K230UB (2024284)		458940
870	09/20/2018	767898		ANNUAL SAFETY INSPECTION SERIAL #J453154_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	458940
870	08/30/2018	762922	LINK SWAYBAR SCANIA K230 1766014 20486 01		457403
870	08/30/2018	762922		Assisting	457403
870	08/30/2018	762922		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	457403
870	08/30/2018	762922		VEHICLE SAFETY INSPECTION complete	457403
870	08/30/2018	762922	Service	PRE ANNUAL SAFETY INSPECTION CHECK complete	457403
870	08/30/2018	762973	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR228367 Receiving #:235925 Date :2018-08-31 supply engine belt pulley 40N0904	457589
870	08/30/2018	762973	Engine engine pulley u/s	Fit new pulley ok	457403
870	08/28/2018	762308		CARRY OUT FIRE EXTINGUISHER TEST & TAG	457171
870	08/28/2018	762250	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	carried out	457171
870	08/24/2018	761577		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	456845
870	08/20/2018	760360	LAMP LED SIDE MARKER RED/AMBER		456832
870	08/20/2018	760360	REFLECTOR AMBER 94mm X 44MM (84051)		456832
870	08/20/2018	760360	fit new nsr side clearance light and reflector	fitted nsr side mark lamp and reflector	456832
870	08/10/2018	758585	Elec and Light AM-FM Radio	rewire radio and repair wiring test o.k	455893
870	08/01/2018	753316	Consumables		455255
870	08/01/2018	753316	TYRE 295/80R22.5 RECAP	Creditor #:VB-TYR002 TYRES4U P/O #:CR224865 Receiving #:235219 Date :2018-08-22 scania steel	456840
870	08/01/2018	756355	Drv entered - Body Drivers Seat Belt	Adjusted angle of seat belt reel and checked operation ok at this time	455020
870	07/25/2018	754833	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Checked ok	454651
870	07/23/2018	754109	Drv entered - Elec and Light Exterior Lights		454092
870	07/23/2018	754109	Drv entered - Elec and Light Exterior Lights	Replaced o/s/f park light globe and n/s/f indicator globe	454092
870	07/23/2018	754109	Consumables		454553
870	07/23/2018	754109	Consumables		454553
870	07/23/2018	754109	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		454092
870	07/23/2018	754109	FILTER FUEL FILTER SCANIA SR4 (1372444)		454092
870	07/23/2018	754109	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		454092
870	07/23/2018	754109	Oil Filter SC S4 & K		454092
870	07/23/2018	754109		CARRY OUT B SERVICE AS PER CHECK LIST	454092
870	07/23/2018	754109			454092
870	07/20/2018	753689		Assisting	454092
870	07/20/2018	753689	torques nsr wheelnuts	torqued to spec	454092

870	07/19/2018	753316	Wheels and Tyres - Tyre 3 worn	replace nsr tyres torque nuts to spec	454092
870	07/19/2018	753316	Replace nsr tyres	replace nsr tyres and torque wheel nuts to spec	454092
870	07/09/2018	749524	Engine Belts_Loose Noisy Missing	repleced 2 newa/c beltes	452574
870	06/26/2018	748124	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	COMPLETED	451032
870	06/21/2018	746970	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	COMPLETE	450727
870	06/14/2018	745397	Consumables		450230
870	06/14/2018	745397	Ops Entered - Fault - Elec and Light Next Stop Button - Ne	check and un jam button test o.k	450157
870	06/08/2018	744230	Body PASSENGER SEAT BASE HAS DETACHED. KEEPS COMING OFF.	secure passenger seat o/s	449710
870	06/06/2018	743581		Assisting	449555
870	06/06/2018	743581		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	449555
870	06/06/2018	743581		VEHICLE SAFETY INSPECTION	449555
870	06/01/2018	749524	BELT V-BELT COGGED TRI-POWE	Creditor #:#GB-RPW001 R.P. WALLIS WHOLESale P/O #:#G223515 Receiving #:#230936 Date :2018-07-02	451750
870	05/25/2018	741298	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	Complete	448784
870	05/11/2018	737826	assist		447750
870	05/11/2018	737889	Service		447750
870	05/11/2018	737889	KIT SWITCH OVERRIDE RPD		447750
870	05/11/2018	737811	KIT SWITCH OVERRIDE RPD		447750
870	05/11/2018	737811	BUZZER VDO 24V		447750
870	05/10/2018	737826	RECTIFY COOLANT LEAK AT HEATER BOOST PUMP	Remove and replace heater boost pump as required	447707
870	05/10/2018	737826	PUMP BOOST 24V		447707
870	05/10/2018	737889	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	fitted decal	447707
870	05/10/2018	737811	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	Carry out as per campaign. Remove and replace warning buzzer @ instrument cluster	447707
870	05/01/2018	729744	DIRECT PURCHASE - MECHANICAL G	Creditor #:#VB-MUL002 MULTISPARES CROYDON P/O #:#CR216764A Receiving #:#228029 Date :2018-05-23	448625
870	04/23/2018	734530	HOSE HEATER SILICON 3 PLY 3/8 ID [price per cm]		446159
870	04/23/2018	734530	Fluid Leaks coolant leak at header tank		446159
870	03/28/2018	729744	Ops Entered - Fault - Throttle - Route: - Take Service Bu	Replace broken T fitting and silicone hose as required check for leaks ok	444741
870	03/28/2018	729744	DIRECT PURCHASE - MECHANICAL G		444765
870	03/28/2018	729744	Service	Creditor #:#VB-MUL001 MULTISPARES LTD P/O #:#CR216764 Receiving #:#224045 Date :2018-03-29 supply throttle potentiometer	444741
870	03/27/2018	729472	DIRECT PURCHASE - MECHANICAL G	Drive to Croydon depot. check accelerator potentiometer and wiring- ok. Check for feedback on wiring to ECU. Found fault. fit diode. check and no more fault.	444741
870	03/27/2018	729472	Air System Air_Leak Rear	Creditor #:#VB-MUL001 MULTISPARES LTD P/O #:#CR216678 Receiving #:#223954 Date :2018-03-27 supply fluid separator assembly / 40G0006HALDEX	444482
870	03/27/2018	729383	Consumables	replace fluid separator/oil collector test o.k	444765
870	03/27/2018	729383	Consumables		444765
870	03/27/2018	729383	Consumables		444765
870	03/27/2018	729383	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		444482
870	03/27/2018	729383		CARRY OUT A SERVICE AS PER CHECK LIST	444482
870	03/26/2018	729125	BELT V-BELT COGGED TRI-POWER 17x2135mm		444482
870	03/26/2018	729125	Engine-compressor beltes	fit new a/c beltes	444482
870	03/13/2018	726248	BELT V-BELT COGGED TRI-POWER 17x2135mm		443577
870	03/13/2018	726248		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	443577
870	03/13/2018	726248		VEHICLE SAFETY INSPECTION	443577
870	03/09/2018	725785	Fluid Leaks-small coolant leak	Checked and tightened as required hose clamps around header tank washed and checked for leaks ok	443577
870	03/01/2018	712593	DIRECT PURCHASE - MECHANICAL G	Creditor #:#VB-COM100 Commercial Brake & Clutch P/O #:#K211156 Receiving #:#223471 Date :2018-03-21 Reline front & rear brakes	444323
870	02/20/2018	712092	Body-metal bar under motor rh side hanging down	removed engine cover guide	442169
870	01/30/2018	716064	A/C Heating Belt Loose or_Missing	fit new a/c beltes	440648
870	01/30/2018	716064	BELT V-BELT COGGED TRI-POWER 17x2135mm		440648
870	01/19/2018	714427	Wheels and Tyres- wheel indicator front o/s	fit new osf wheel nut indicator	440039
870	01/16/2018	713869	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	COMPLETE	440039
870	01/15/2018	713435	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	Assisting	440039
870	01/15/2018	713435	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	torqued all wheel nuts	440039
870	01/15/2018	713435	INDICATOR CHECK LINK WHEEL NUT LOCK 33mm		440039
870	01/15/2018	713561	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)		440039
870	01/15/2018	713561	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)		440039
870	01/15/2018	713561	Remove and replace front and rear sway bar D rubbers	REPLACED FRONT AND REAR SWAY BAR D RUBBERS AS REQUIRED	440039
870	01/15/2018	713561	remove and replace osf upper torque rod assembly	REPLACED OSF UPPER TORQUE ROD ASSEMBLY	440039
870	01/12/2018	712593	O-RING BRAKE SHOE PIVOT (1338019)		440039
870	01/12/2018	712593	LOCK RING BRAKE SHOE PIN 0804782		440039
870	01/11/2018	712593	BRAKE DRUM	Creditor #:#VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:#K211155 Receiving #:#218381 Date :2018-01-12	440209
870	01/11/2018	712593	carry out front and rear brake reline	New drums and re-lined shoes arrived finished cleaning up hubs. Assembled all parts adjusted brakes tensioned wheel nuts and road tested.	440039
870	01/10/2018	712593	carry out front and rear brake reline	Raised bus and removed all wheels drums and brake shoes parts ordered and shoes sent away.	440039
870	12/19/2017	709091	Mechanic entered - Vandalism Vandalism/ Graffiti Interior re	removed grafity	440039
870	12/15/2017	708364		Assisting	440039
870	12/15/2017	708364		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	440039
870	12/15/2017	708364		VEHICLE SAFETY INSPECTION	440039
870	12/12/2017	707554	Remove old poster and fit new A3 Posters and hangers	completed	439846
870	12/05/2017	706033	BELT V-BELT COGGED TRI-POWER 17x2135mm		439198
870	12/05/2017	706033	A/C Heating Belt Loose or_Missing	replace a/c beltes	439198
870	11/24/2017	703929	Engine-compressor belt not on properly	refit a/c belt test a/c o.k	438637
870	11/15/2017	701861	Ops Entered - Fault - Brakes occasionally grab really badly	grease vehicle check all brakes for condition and operation road test and brake test vehicle Fr.7o deg Rr. 90 deg	438020
870	11/08/2017	700159	Please remove the 2 x Do Not Enter decals at the exterior	COMPLETED	437535
870	10/31/2017	698508	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	completed	436787
870	10/27/2017	697583	Wheels and Tyres Flat or Leaking	Checked all tyre pressures ok	436376
870	10/18/2017	695215	DIRECT PURCHASE - ELECTRICAL	Creditor #:#VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:#CR205120 Receiving #:#212156 Date :2017-10-18 CARRY OUT CCTV CHECK	435672
870	10/18/2017	695215	CCTV CHECK		435672
870	10/03/2017	689562	DIRECT PURCHASE - MECHANICAL G	Creditor #:#VB-ENG001 600 ENGINEERING P/O #:#CR203649 Receiving #:#211110 Date :2017-10-04 REPAIR AND STRENGTHEN FUEL TANK BRACKETS AS REQUIRED	434975
870	10/03/2017	689562	FUEL TANK J BRACKETS U/S	refit j brackets and fuel tank checked o.k	434540
870	10/01/2017	688606	AIR CONDITIONING REPAIR	Creditor #:#VB-COL004 COLD DRIVE PTY LTD P/O #:#CR203469 Receiving #:#213339 Date :2017-11-01 carry out a/c b service	436924
870	09/28/2017	690301		CARRY OUT FIRE EXTINGUISHER TEST & TAG	434540
870	09/27/2017	689562	FUEL TANK J BRACKETS U/S	remove fuel tank and brackets as required send j brackets for repair	434540
870	09/26/2017	689489	Consumables		434975
870	09/26/2017	689489	Consumables		434975
870	09/26/2017	689489	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		434540
870	09/26/2017	689489			434540
870	09/26/2017	689489		CARRY OUT B SERVICE AS PER CHECK LIST	434540
870	09/26/2017	689489	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		434540
870	09/26/2017	689489	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		434540
870	09/26/2017	689489	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		434540
870	09/26/2017	689489	Consumables		434975
870	09/26/2017	689489	Consumables		434975
870	09/26/2017	689489		CARRY OUT A SERVICE AS PER CHECK LIST	434540
870	09/25/2017	688648	Remove old A3 Posters with Seniors Festival please leave	completed	434540
870	09/25/2017	688606	BELT V-BELT COGGED TRI-POWER 17x2135mm		434540
870	09/25/2017	688606		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	434540
870	09/25/2017	688606		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	434540

870	09/21/2017	688051	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	434423
870	09/21/2017	688051	VEHICLE SAFETY INSPECTION	434423
870	09/21/2017	688051	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR203261 Receiving #:210554 Date :2017-09-25	434920
870	09/21/2017	688051	ANNUAL SAFETY INSPECTION SERIAL #1493177	434423
870	09/21/2017	688131	PRE ANNUAL SAFETY INSPECTION CHECK	434423
870	09/15/2017	686822	No rear door	433897
870	08/28/2017	682879	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:CR201365 Receiving #:208725 Date :2017-08-31 REPLACE VANDALISED OS-NS WINDOW GLASS AS REQUIRED	432697
870	08/28/2017	682879		432498
870	08/22/2017	681671	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:CR200870 Receiving #:208723 Date :2017-08-31 Carry out fire safety inspection	432697
870	08/22/2017	681671	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	432038
870	08/22/2017	681760	carried out	432038
870	08/18/2017	680962	TRANSMISSION CHECK AS PER CHECK LIST	432038
870	08/18/2017	680962		432038
870	08/18/2017	680962	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:CR200627 Receiving #:208231 Date :2017-08-25 40Y2222	432498
870	08/18/2017	680962		432038
870	08/18/2017	680962	Fit new n/s/r/r airbag ok	432038
870	08/18/2017	680962		432038
870	07/19/2017	674876	Replaced blown headlight globe.	430138
870	07/19/2017	674876	Replaced wiper blade.	430138
870	07/19/2017	674876		430138
870	07/19/2017	674965	ok	430221
870	07/19/2017	674965	ok	430138
870	07/19/2017	674964		430138
870	07/18/2017	674555		430170
870	07/18/2017	674555	Replaced missing lens.	430138
870	07/18/2017	674555		430138
870	07/13/2017	673586		429742
870	07/13/2017	673586		429324
870	07/13/2017	673586		429324
870	07/13/2017	673586	replaced front o/s side indicator.	429324
870	07/13/2017	673586	complete	429324
870	07/02/2017	671374		428386
870	07/02/2017	671374	checked selector gear switchcleaned selector gear switch checked ok	427893
870	06/27/2017	670131		427714
870	06/27/2017	670131	replace engine thermostat roadtest checked o.k	427714
870	06/26/2017	669934		427646
870	06/26/2017	669934	fit new ns-os wiper refills	427646
870	06/22/2017	668304	Creditor #:VB-TYR002 TYRES4U P/O #:CR196237 Receiving #:203237 Date :2017-06-23	427260
870	06/21/2017	668457		426991
870	06/21/2017	668457		426991
870	06/21/2017	668457		426991
870	06/20/2017	668304		426991
870	06/19/2017	667267		426480
870	06/16/2017	667267		426480
870	06/16/2017	667267		426480
870	06/15/2017	667267		426480
870	06/14/2017	667267	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	426480
870	06/14/2017	667267	VEHICLE SAFETY INSPECTION	426480
870	05/24/2017	663130		424691
870	05/24/2017	663130		424691
870	05/24/2017	663130	CARRY OUT A SERVICE AS PER CHECK LIST	424600
870	05/16/2017	661657		424039
870	05/16/2017	661657	Completed	423893
870	05/15/2017	661096	SERVICE MOISTURE EJECTOR	423720
870	05/15/2017	661096	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	423720
870	05/15/2017	661096		423720
870	04/20/2017	657163		422165
870	04/20/2017	657163		422066
870	04/20/2017	657163	replace nsf upper globe	422066
870	03/20/2017	651646	repair seat	417936
870	03/20/2017	651646	repair frame	417936
870	03/20/2017	651646	secure panel	417936
870	03/20/2017	651646	repair seat	417936
870	03/20/2017	651646	label switches	417936
870	03/17/2017	651351	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	417936
870	03/17/2017	651351	VEHICLE SAFETY INSPECTION	417936
870	03/17/2017	651351		417936
870	03/01/2017	628745	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR181826AB Receiving #:194869 Date :2017-02-28	416505
870	03/01/2017	628745	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR181826AREV Receiving #:194868 Date :2017-02-28	416505
870	02/27/2017	647849	Completed Campaign	416505
870	02/27/2017	647760	Checked passenger buzzers. Working ok.	416505
870	02/23/2017	628745	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR181826A Receiving #:194635 Date :2017-02-23	416446
870	02/23/2017	628745		416505
870	02/22/2017	646691	Completed Campaign	416307
870	02/20/2017	646033		415722
870	02/20/2017	646033	Replaced broken clearance light	415722
870	02/17/2017	645457		416187
870	02/17/2017	645457	Retensioned front wheels.	415722
870	02/16/2017	645114		416067
870	02/16/2017	645114	Replaced front tyres.	415722
870	02/15/2017	644832	Performed Audit	415722
870	02/08/2017	643518	Fit new decals	415228
870	02/02/2017	642459		414884
870	02/02/2017	642459		414884
870	02/02/2017	642459		414816
870	02/02/2017	642459	CARRY OUT B SERVICE AS PER CHECK LIST	414816
870	02/02/2017	642459		414816
870	02/02/2017	642459		414816
870	02/02/2017	642459		414816
870	02/02/2017	642459		414816
870	02/02/2017	642459		414884
870	02/02/2017	642459		414884
870	02/02/2017	642459	CARRY OUT A SERVICE AS PER CHECK LIST	414816
870	01/30/2017	641603	Replaced posters	413430

870	01/23/2017	640235	SCANIA LEVEL VALVE L94UAB 40Y2	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #.:CR185956 Receiving #.:192459 Date :2017-01-30	413430
870	01/23/2017	640235	Suspension (None)-constantly just raising and lowering m	Checked air bags ok. Cleaned leveling sensor out and still faulting. Ordered replacement sensor. & fitted sensor.	412102
870	01/04/2017	636437	BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010		407999
870	01/04/2017	636437	Mechanic entered - Suspension Noisy swaybar front rubbers w	Replace O/S/F sway bar rubber N/S/F needs replacing nill stock ordered	407999
870	01/04/2017	636437	Mechanic entered - Suspension Noisy Torque rod bushes front	Checked all bushes OK at this time	407999
870	01/04/2017	636437	Consumables		407999
870	01/04/2017	636437	DECAL SAFETY TRIANGLE RED		407999
870	01/04/2017	636437	Mechanic entered - Dash Dash_Lights Not Working and not la	Replaced globes	407999
870	01/04/2017	636437	Mechanic entered - Dash Dash_Lights Not Working	Replaced globes	407999
870	01/04/2017	636437	Mechanic entered - Body Other internal mirrors loose	Secured mirror	407999
870	01/04/2017	636437	Mechanic entered - Body Passenger Seat Torn 2nd and 6th o/s	Repaired passenger seats	407999
870	01/04/2017	636437	Mechanic entered - Body Windows Side 2nd o/s loose loose in	Book in for window reseal	407999
870	01/04/2017	636437	Mechanic entered - Body Other triangle decals missing	Fitted decal	407999
870	12/22/2016	634860	Mechanic entered - Wipers and Washers Washers Not Working	top up washer bottle test o.k	407999
870	12/20/2016	634316		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	407999
870	12/20/2016	634316		VEHICLE SAFETY INSPECTION	407999
870	12/13/2016	633140	SWITCH- STOP-YELLOW		407999
870	12/13/2016	633140	passenger stop button n/w	remove and replace pasasenger stop button	407999
870	11/18/2016	628745	Consumables		407999
870	11/18/2016	628745	Body Drivers Seat Belt	secure drivers seat belt reel	405973
870	11/10/2016	627025	CCTV (None)RETRO FIT CCTV SYSTEM WITH ANALOGUE CAMERAS		405709
870	11/10/2016	627040	CCTV (None)CHECK CCTV SYSTEM AND FIT SIM CARD BY BEN WE		405024
870	11/01/2016	627025	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS P/O #.:CR181095 Receiving #.:187361 Date :2016-11-11 RETRO FIT CCTV SYSTEM WITH ANALOGUE CAMERAS	405709
870	11/01/2016	627040	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS P/O #.:CR181105 Receiving #.:187357 Date :2016-11-11 CHECK CCTV SYSTEM AND FIT SIM CARD	405709
870	10/28/2016	624727	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced	404362
870	10/06/2016	620237	LAMP LED TURN		402993
870	10/06/2016	620237	O/S/R/T indicator n/w	Replaced indicator	402993
870	09/26/2016	618194	Consumables		402881
870	09/26/2016	618194	A3 Poster Change please remove old poster and fit Vitorian	Replaced A3 Poster	402771
870	09/23/2016	615553	Consumables		402771
870	09/23/2016	615553	Consumables		402771
870	09/23/2016	615553	Direct Purchase - BODYWORK	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR176919 Receiving #.:184060 Date :2016-09-26 repair body to chassis mount at fuel tank area	402771
870	09/22/2016	617006		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	402616
870	09/22/2016	617006		VEHICLE SAFETY INSPECTION	402616
870	09/22/2016	617006	ROAD WORTHY INSPECTION	Creditor #.:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #.:CR177482 Receiving #.:184206 Date :2016-09-27	402881
870	09/22/2016	617006		ANNUAL SAFETY INSPECTION SERIAL #H737989	402616
870	09/21/2016	616393	Direct Purchase - MECHANICAL	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR177253 Receiving #.:184197 Date :2016-09-27 Carry out rollaway campaign 8/16	402881
870	09/19/2016	616568	AIR CONDITIONING REPAIR	Creditor #.:VB-COLO04 COLD DRIVE PTY LTD P/O #.:CR177298 Receiving #.:184210 Date :2016-09-27 CARRY OUT A/C -A SERVICE	402881
870	09/19/2016	616568		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	402616
870	09/16/2016	616393	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)		402616
870	09/14/2016	615553	VALVE SOLENOID ACCUMULATOR ZF (0501 316 527 01 49D2909)		402432
870	09/13/2016	615553		TRANSMISSION CHECK AS PER CHECK LIST	402432
870	09/13/2016	615553		CARRY OUT A SERVICE AS PER CHECK LIST	402432
870	08/26/2016	612355	Elec and Light Next Stop Button-door buzzer keeps going o	repair passenger stop button	401653
870	08/18/2016	610570	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)		400919
870	08/18/2016	610570		PRE ANNUAL SAFETY INSPECTION CHECK	400919
870	08/18/2016	610570	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		400919
870	08/17/2016	610303	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-CAR008 CARDINIA P/O #.:CR174935 Receiving #.:181019 Date :2016-08-18 Carry out fire safety inspection	401051
870	08/17/2016	610303		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	400919
870	08/09/2016	608780	Accident#:42883 - Ops Entered - Accident - - NEAR SIDE MID		400919
870	08/01/2016	607214	Ops Entered - Fault - Heat & Demist-climate control not wor	reset a/ controller tested o.k	400471
870	08/01/2016	607227	SENDER WATER LEVEL SR3		400471
870	08/01/2016	607227	replaced low coolant sensor	replaced low coolant sensor	400471
870	07/28/2016	606525	Consumables		400471
870	07/28/2016	606495	Consumables	Completed	400313
870	07/28/2016	606525	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	Completed	400313
870	07/28/2016	606495	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA		396568
870	06/30/2016	599332	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706		396436
870	06/30/2016	598866	1MT MULTI FIT WIPER REFILL		396436
870	06/30/2016	600945	CCTV UPDATE		397156
870	06/28/2016	599690	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-THOREB THOREB AUSTRALIA P/O #.:CR170848 Receiving #.:177452 Date :2016-06-30 CCTV UPGRADE KIT	396568
870	06/23/2016	599690	CCTV Upgrade		396568
870	06/22/2016	599332		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	396568
870	06/22/2016	599332		VEHICLE SAFETY INSPECTION	396568
870	06/20/2016	598866	fit new wiper inserts	fitted new os-ns wiper inserts	396436
870	06/20/2016	598866	1MT MULTI FIT WIPER REFILL		396436
870	06/09/2016	600945	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-THOREB THOREB AUSTRALIA P/O #.:CR169839 Receiving #.:177440 Date :2016-06-30 CCTV KIT PART #KIT-VENTURA-V2	397156
870	06/04/2016	599825	Please remove any old poster and fit new A3 poster and add	complete	392244
870	06/02/2016	595356	Ops Entered - Fault - Elec and Light Next Stop Button - Fro	checked all passenger stop buttons working correctly	395458
870	06/01/2016	582895	Direct Purchase - TYRES	Creditor #.:VB-TYR002 TYRES4U P/O #.:CR164933 Receiving #.:176978 Date :2016-06-27 DISPOSAL	396849
870	06/01/2016	582895	Direct Purchase - TYRES	Creditor #.:VB-TYR002 TYRES4U P/O #.:CR164933 Receiving #.:176978 Date :2016-06-27 remove and replace recap tyres x2	396849
870	05/02/2016	589263	Body Drivers Seat Belt	adjusted seat belt angle	393228
870	04/28/2016	588444	Consumables		393228
870	04/28/2016	588444	Consumables		393228
870	04/28/2016	588444	Checklink Wheel Nut 33mm		393166
870	04/27/2016	588444		Completed A and B service.	393015
870	04/27/2016	588444	FILTER FUEL SCANIA SR4(H17WK04)		393015
870	04/27/2016	588444	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01		393015
870	04/27/2016	588444	O-RING LARGE SPINNER FILTER SCANIA (40A7703)		393015
870	04/27/2016	588444	O-RING SPINNER FILTER SCANIA (40A7701)UP TO ENG#6203049		393015
870	04/27/2016	588444	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		393015
870	04/27/2016	588444		CARRY OUT B SERVICE AS PER CHECK LIST	393015
870	04/27/2016	588444	Consumables		393166
870	04/27/2016	588444	Consumables		393166
870	04/27/2016	588444		CARRY OUT A SERVICE AS PER CHECK LIST	393015
870	04/19/2016	587309	Consumables		392767
870	04/19/2016	587309	Consumables		392767
870	04/19/2016	587309		CARRY OUT A SERVICE AS PER CHECK LIST	392767
870	03/30/2016	583445	Service	Retensioned wheel nuts	392195
870	03/24/2016	582895		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	392048
870	03/24/2016	582895		VEHICLE SAFETY INSPECTION	392048
870	01/28/2016	572878	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	completed	388828
870	12/24/2015	566909	L.E.D SIDE MARKER RED/AMBER		387753

870	12/24/2015	566909	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	387753
870	12/24/2015	566909	VEHICLE SAFETY INSPECTION	387753
870	12/22/2015	566454	complete	387753
870	12/22/2015	566440	complete	387753
870	12/01/2015	562293	Replaced rear hutch struts	386976
870	11/20/2015	560053		386651
870	11/20/2015	560016		386651
870	11/20/2015	560053	complete	386495
870	11/20/2015	560016	complete	386495
870	11/06/2015	547380		385777
870	11/01/2015	537887		385585
870	11/01/2015	537887		384863
870	11/01/2015	537887		384863
870	11/01/2015	537887	Repaired by alpha glass (warranty	384863
870	10/12/2015	552647	checked a/c tensioned a/c belts tested o.k	384373
870	10/08/2015	552207	completed	384274
870	10/08/2015	552232	completed	384274
870	10/01/2015	547380	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P.L. P/O #:CR155910 Receiving #:162006 Date :2015-10-08 Carry out annual inspection	384202
870	09/30/2015	549855	fitted	383941
870	09/30/2015	549841	fitted	383941
870	09/29/2015	547497	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR155929REV Receiving #:161751 Date :2015-09-30	383941
870	09/29/2015	547497	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR156428 Receiving #:161754 Date :2015-09-30	383941
870	09/29/2015	547497	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR155929 Receiving #:161701 Date :2015-09-29 Carry out a/c b service added compressor oil as required	383941
870	09/28/2015	537887	fit c/o drivers seat	383852
870	09/28/2015	537887	fit c/o drivers seat	383852
870	09/25/2015	548956	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	383852
870	09/25/2015	548956	VEHICLE SAFETY INSPECTION-Carried out 16/9 w/o 547217 383739kms	383852
870	09/24/2015	504912	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR147247 Receiving #:149880 Date :2015-09-24	383852
870	09/23/2015	548621	COMPLETED CAMPAIGN	381107
870	09/18/2015	547380	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR155757 Receiving #:161277 Date :2015-09-18 MM	383852
870	09/18/2015	547380	Creditor #:VB-BUR001 BURSON AUTOMOTIVE PTY LTD P/O #:CR155934 Receiving #:161292 Date :2015-09-18 supply 2 1058 headlight inserts	383767
870	09/17/2015	547380		383652
870	09/17/2015	547380	ANNUAL SAFETY INSPECTION (RWC #) H046013	383652
870	09/17/2015	547497	CHECK BOOST PUMP OPERATION	383652
870	09/17/2015	547497	CHECK & REPLACE ELECTRIC MOTOR BRUSHES WHERE APPLICABLE	383652
870	09/17/2015	547497	REPLACE A/C COMPRESSOR OIL	383652
870	09/17/2015	547497	REPLACE A/C FILTER/DRIER	383652
870	09/17/2015	547497	CARRY OUT B SERVICE	383652
870	09/17/2015	547497	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	383652
870	09/17/2015	547497	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	383652
870	09/17/2015	547497	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	383652
870	09/17/2015	547497	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	383652
870	09/17/2015	547497	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	383652
870	09/17/2015	547497	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	383652
870	09/17/2015	547497	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	383652
870	09/17/2015	547497	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	383652
870	09/17/2015	547497	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	383652
870	09/17/2015	547497	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	383652
870	09/17/2015	547497	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	383652
870	09/16/2015	547217	PRE ANNUAL SAFETY INSPECTION CHECK	383652
870	09/07/2015	544222	Creditor #:VB-JDC001 JDC ENGINEERING PTY LTD P/O #:CR155334 Receiving #:160853 Date :2015-09-07 Repair transmission sump as required	383190
870	09/04/2015	544222	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR155206 Receiving #:160840 Date :2015-09-04 4149 231 012 01	383262
870	09/04/2015	544222	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR155206 Receiving #:160840 Date :2015-09-04	383262
870	09/04/2015	544222	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:CR155206 Receiving #:160840 Date :2015-09-04 BUS 870	383262
870	09/01/2015	528956	Creditor #:VB-ALPO03 ALPHA BUS GLASS PTY LTD P/O #:CR152114 Receiving #:161173 Date :2015-09-15 Replace drivers slider window glass	383652
870	08/31/2015	544222		382919
870	08/31/2015	544222	Remove transmission sump send for repair refit sump fill as required	382919
870	08/31/2015	544222		382949
870	08/31/2015	544222		382949
870	08/31/2015	544222		382919
870	08/31/2015	544222		382919
870	08/27/2015	541937	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR154958 Receiving #:160512 Date :2015-08-27 Carry out fire safety inspection	382755
870	08/20/2015	541937	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	382181
870	08/19/2015	541738	fitted	382181
870	08/06/2015	539511	checked bus starts o.k charge rate 27.5volts	381107
870	08/03/2015	538803	complete	381414
870	07/02/2015	533301	Remove and replace nsf tyre (secondhand unit fitted)	380140
870	06/30/2015	533301		380140
870	06/30/2015	533301		380140
870	06/30/2015	533301	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	380140
870	06/01/2015	528956	VEHICLE SAFETY INSPECTION	378969
870	05/14/2015	526090		377970
870	05/14/2015	526090	Replaced N/S headlight	377970
870	05/01/2015	516645	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR148872 Receiving #:152425 Date :2015-05-21	378468
870	05/01/2015	516645	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR148872 Receiving #:152425 Date :2015-05-21	378468
870	05/01/2015	516645	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR148872 Receiving #:152425 Date :2015-05-21	378468
870	04/20/2015	522065	completed	376556
870	04/08/2015	519912		376248
870	04/08/2015	519912		376248
870	04/08/2015	519912		376248
870	04/08/2015	519912		376248
870	04/08/2015	519912	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	376248
870	04/08/2015	519912	VEHICLE SAFETY INSPECTION	376248
870	03/31/2015	519116	carried out	376248
870	03/26/2015	517830	changeover a/c compressor fitted by colddrive	376156
870	03/25/2015	517830	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:CR149863 Receiving #:153290 Date :2015-04-02 Remove and replace a/c compressor	376248
870	03/25/2015	517830		376156
870	03/25/2015	517830		376156
870	03/19/2015	516645		375644
870	03/18/2015	516645		375644
870	03/12/2015	514055	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:CR148961 Receiving #:152291 Date :2015-03-16 Remove and replace full rear pty decal (graffiti)	375644
870	03/02/2015	514055	Cleaned graffiti	375175
870	02/10/2015	510664	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:CR148251 Receiving #:150692 Date :2015-02-11 CARRY OUT A/C A SERVICE	374064

870	02/10/2015	510664	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	373960
870	02/10/2015	510664	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	373960
870	02/10/2015	510664	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	373960
870	02/10/2015	510664	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	373960
870	02/10/2015	510664	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	373960
870	02/10/2015	510664	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	373960
870	02/10/2015	510664	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	373960
870	02/10/2015	510664	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	373960
870	02/10/2015	510664	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	373960
870	02/10/2015	510664	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	373960
870	02/10/2015	510664	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	373960
870	02/01/2015	507584 Consumables		373522
870	02/01/2015	507584 Consumables		373522
870	02/01/2015	507584		373288
870	01/20/2015	0 Imported Service History	SERVICE CARRIED OUT ON 21/1/15@373380KMS.	373288
870	01/20/2015	507584 Consumables	Imported Service History	373288
870	01/20/2015	507584 FILTER AIR DRYER SCANIA SR4 (1393551)(49G8709HALDEX)		373288
870	01/20/2015	507584 FILTER FUEL SCANIA L94UAB (H7090WK30)	Filter Air Dryer	373288
870	01/20/2015	507584 HYDRAULIC TORQUE FLUID 414	Raycor filter	373288
870	01/20/2015	507584 FILTER HYD COOLING FAN SCANIA SR3 (E90HD149)	Hydraulic oil	373288
870	01/20/2015	507584 FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468	Hydraulic filter	373288
870	01/20/2015	507584 RPM BORATE EP LUBE 220 80/90 (LU6)	Power steering filter	373288
870	01/20/2015	507584	diff oil	373288
870	01/20/2015	507584 Consumables	Service as per check list	373288
870	01/20/2015	507584 O-RING KIT OIL SPINNER FILTER SCANIA		373288
870	01/20/2015	507584 FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	Kit . filter Cent	373288
870	01/20/2015	507584 HYDRAULIC TORQUE FLUID 414	Filter Oil	373288
870	01/20/2015	507584 FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)	Torque fluid	373288
870	01/20/2015	507584 FILTER FUEL SCANIA SR4(H17WK04)	Filter ZF Trans	373288
870	01/20/2015	507584 OIL ENGINE DELO 400LE 15W40 (LU18)	Fuel Filter	373288
870	01/20/2015	507584	Engine Oil	373288
870	01/20/2015	507584	Tension ALL Wheel Nuts to OEM Specs	373288
870	01/20/2015	507584 Consumables	A - Service & Bus Safety Inspection	373288
870	01/20/2015	507584		373288
870	01/20/2015	507584	Tension ALL Wheel Nuts to OEM Specs	373288
870	01/20/2015	507584	A - Service & Bus Safety Inspection	373288
870	01/09/2015	504912 O RING 11MM ID	Tension ALL Wheel Nuts to OEM Specs	373288
870	01/09/2015	504912 COMPRESSOR K SR with rear driv	A - Service & Bus Safety Inspection	373288
870	01/09/2015	504912 Hand pump	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 SEAL RING	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 O RING COMPRESSOR	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 SCREW	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 Washer	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 BRACKET	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 ORing	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 O RING COMPRESSOR MOUNT SCANIA	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/09/2015	504912 COVER	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146979 Receiving #.:149279 Date :2015-01-09	373288
870	01/05/2015	504912	Perform Safety Inspection as per checklist DONE	373288
870	01/05/2015	504905	Perform Safety Inspection as per checklist	373288
870	12/12/2014	501707 A3 Poster Change	fitted	373006
870	11/28/2014	499217 Direct Purchase - BODYWORK	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR146075 Receiving #.:147993 Date :2014-12-01 Supply and fit wheel arch rubbers and brushes	372525
870	11/28/2014	499217 Supplya nd fit wheel arch rubbers and brushes		372418
870	11/18/2014	496422 AIR FILTER SCANIA L94UB(395773}		371807
870	11/17/2014	496422 Ops Entered - Fault - Engine Lacking Power - Route: 690 - C	Refit intercooler	371807
870	11/17/2014	496422 Service	Refit radiator shourd and lower engine cover.Roadtest o.k.	371807
870	11/17/2014	496422 Ops Entered - Fault - Engine Lacking Power - Route: 690 - C	Refit turbo	371807
870	11/17/2014	496422 DIRECT PURCHASE - MECHANICAL G	Creditor #.:VB-FTGRAD Ferntree Gully Radiators P/O #.:CR145554 Receiving #.:147478 Date :2014-11-17 Clean intercooler as required	371807
870	11/14/2014	496422 Ops Entered - Fault - Engine Lacking Power - Route: 690 - C	Cleaned all parts for reassembly.	371807
870	11/13/2014	496422 DIRECT PURCHASE - MECHANICAL G	Creditor #.:VB-EAGTOW Eagle Towing & Salvage P/O #.:CR145528 Receiving #.:147497 Date :2014-11-18 Tow bus from Aquinas College to Croydon workshop	371807
870	11/13/2014	496422 Ops Entered - Fault - Engine Lacking Power - Route: 690 -	Remove turbo and intercooler	371807
870	10/30/2014	493850 Remove Legacy Poster and replace with See Something Say So	fitted	371011
870	10/08/2014	490018 rectify water from a/c drain tube leaking binto osf wheel a	Repair a/c drain tube	370531
870	10/01/2014	488495 Complete AM/FM radio saloon speaker modification	DONE	370322
870	09/30/2014	488495	Perform Safety Inspection as per checklist	370322
870	09/30/2014	487734 Direct Purchase - BODYWORK	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR143966 Receiving #.:145984 Date :2014-10-02 Replace os rear frame upright (near fuel tank)	370363
870	09/30/2014	488495	A - Service & Bus Safety Inspection	370322
870	09/26/2014	487734 GLOBE 24V 75/70W H4		370322
870	09/25/2014	487734		370322
870	09/25/2014	487734 ROAD WORTHY INSPECTION	Creditor #.:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #.:CR143902 Receiving #.:145786 Date :2014-09-25	370322
870	09/25/2014	487734	Assist fleetcheck	370322
870	09/16/2014	485898 No power up hill 25-30kmh up tourist Rd. Has a whistle nois	Checked bus found turbo boost clamp off clean hose-pipe. Retension clamp test o.k	369848
870	09/04/2014	483936 Remove old decal and fit new Authorised Officers Decal DO N	fitted decal	369330
870	09/02/2014	483362	Inspect vehicle as per RSI Checklist	369255
870	09/02/2014	483362 test		369255
870	09/02/2014	483362 test		369255
870	09/02/2014	0 Imported Service History	Imported Service History	369255
870	08/19/2014	480683 Remove old A3 poster & replace with Legacy or Penalty Fares	fit poster	368401
870	08/18/2014	479678 REGULATOR VOLTAGE 0405NH		368401
870	08/13/2014	479678 Ops Entered - Fault - Engine Won't Start - Route: 690 - AI	Checked bus found alternator regulator faulty.Removed and replace alternator regulator tested o.k.	368158
870	08/01/2014	463436 Direct Purchase - BODYWORK	Creditor #.:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #.:CR141882 Receiving #.:143868 Date :2014-08-07 Remove and replace disabled floor tiles as required	367878
870	07/23/2014	475980 Water leak in middle of bus inside-Air Con?	UNBLOCKED DRAIN PIPE	367066
870	07/23/2014	475980 Water leak in middle of bus inside-Air Con?		367066
870	07/08/2014	454263 Perform Campaign 1_14 School Bus Light Globe Check Check w		366632
870	07/08/2014	472980 Perform Campaign 1_14 School Bus Light Globe Check Check		366632
870	07/04/2014	472310	DONE DONE	366632
870	07/04/2014	472310	Perform Safety Inspection as per checklist	366632
870	07/04/2014	472310	Inspect vehicle as per RSI Checklist	366632
870	07/04/2014	472310 Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	DONE	366632
870	07/04/2014	472310 Fit Tyre Valve Extensions To All Inner Rear Axle Wheels		366632
870	07/04/2014	454263 Perform Campaign 1_14 School Bus Light Globe Check Check w		366632
870	07/04/2014	472310	Tension ALL Wheel Nuts to OEM Specs	366632
870	07/04/2014	472310	A - Service & Bus Safety Inspection	366632

870	07/04/2014	472310	O RING FILTER KIT K93	Kit . filter Cent	366632
870	07/04/2014	472310	FILTER OIL K124 / L94UAB (H200W20)2059778	Filter Oil	366632
870	07/04/2014	472310	HYDRAULIC TORQUE FLUID 414	Torque fluid	366632
870	07/04/2014	472310	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	366632
870	07/04/2014	472310	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	366632
870	07/04/2014	472310	ENGINE OIL DELO 400LE 15W40 (LU18)	Engine Oil	366632
870	07/04/2014	472310		Tension ALL Wheel Nuts to OEM Specs	366632
870	07/04/2014	472310		A - Service & Bus Safety Inspection	366632
870	06/27/2014	463436	GLOBE 24V 75/70W H4		366632
870	06/20/2014	469892	Fit Wheel Nut Pointers to all wheel nuts on the front axle	fitted	366265
870	06/17/2014	463436	Ops Entered - Fault - Elec & Light Headlights - Route: 690	FITTED NEW HEADLIGHT GLOBE.N.S.	366000
870	06/06/2014	463436	Direct Purchase - MECHANICAL	Creditor #:\VB-CUS001 CUSTOM CARE P/O #:CR138953 Receiving #:141871 Date :2014-06-13 SUPPLY 2 DISABLED FLOOR TILES	365858
870	06/02/2014	466514	Ops Entered - Fault - Elec & Light Bell Button - Front pass		365262
870	05/19/2014	463436	replace disabled floor tiles as required	carried out by knox b/shop	364400
870	05/09/2014	461880	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	fit poster	363805
870	04/29/2014	459871			363208
870	04/29/2014	459871		A - Service & Bus Safety Inspection DONE	363208
870	04/29/2014	459871		Tension ALL Wheel Nuts to OEM Specs DONE	363208
870	04/23/2014	457236	Central Electrical Panel	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:C136941 Receiving #:139723 Date :2014-04-23	363135
870	04/16/2014	458549	Fit Myki decals as requiredFit Recruitment decal as requi		362895
870	04/10/2014	457236			362889
870	04/10/2014	457236	Remove and replace central electric fuse/relay panel		362889
870	04/10/2014	457236	Remove and replace central electric fuse/relay panel	replaced electric central fuse/relay unit	362889
870	04/09/2014	456927			362889
870	04/09/2014	456927			362889
870	04/09/2014	456927		Perform Safety Inspection as per checklist	362889
870	04/04/2014	456255	Ops Entered - Breakdown - Breakdown Change Over Request - R	repaired wiring to rear engine hatch switch	362808
870	04/04/2014	456255	Ops Entered - Breakdown - Breakdown Change Over Request - R		362808
870	04/02/2014	455442	Ops Entered - Fault - Engine Won't Start - Route: - Take S	Checked bus no fault found	362727
870	04/01/2014	454263	Ops Entered - Fault - Engine Won't Start - Route: - Take S	CHECKED BUS STARTED O.K NO FAULT FOUND	362727
870	04/01/2014	455348	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	fitted poster	362727
870	03/26/2014	454254	Remove and replace a/c solenoid as required	FITTED NEW SOLONOID.	362450
870	03/26/2014	454263	Perform Campaign 1_14 School Bus Light Globe Check Check w		362450
870	03/25/2014	454028	Air Cond n/w	check bus a/c electrics extensively found solenoid under front bumper faulty.Carried out temp repair.New solenoid ordered	362384
870	08/27/2013	0	Imported Service History	Imported Service History	345043
870	08/27/2013	0	Imported Service History	Imported Service History	345043
870	02/01/2013	0	Imported Service History	Imported Service History	320998
870	02/20/2012	0	Imported Service History	Imported Service History	277636
870	02/20/2012	0	Imported Service History	Imported Service History	277626
870	12/19/2011	0	Imported Service History	Imported Service History	0
870	12/19/2011	0	Imported Service History	Imported Service History	0
870	09/05/2011	0	Imported Service History	Imported Service History	255800
870	09/23/2006	0	Imported Service History	Imported Service History	40000