

Veh#	Date	W/O#	Description	Notes	Odometer
877	09/05/2026	1367309		COMPLETED BY ATS 12/8/26	311567
877	09/04/2026	1364012	Vandalism-Graffiti Audit # 133	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O417316 Receiving #:445450 Date :2026-09-04 877 - Oakleigh	311567
877	08/29/2026	1364012	Vandalism-Graffiti Audit # 1339 Glassprotect - Aug 2026	Assisting	311567
877	08/07/2026	1360012		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	311567
877	08/07/2026	1360012		VEHICLE SAFETY INSPECTION bus ihas been prepared to be sold. about to go to the auction.	311567
877	07/30/2026	1358142	Decommission Bus for Auction	removed etag internal and external ventura livery with heat gun fitted plates with screws	311567
877	07/30/2026	1358142	Decommission Bus for Auction	removed cctv consat two way and busminder	311567
877	06/04/2026	1345601		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorque all wheel nuts.	311567
877	06/04/2026	1345601		VEHICLE SAFETY INSPECTION carry out safety inspection.	311567
877	06/04/2026	1345682	Consumables		311567
877	06/04/2026	1345682	Consumables		311567
877	06/04/2026	1345682	BELT SEAT R/H ISRI(A6008)		311567
877	06/04/2026	1345682	Mechanic entered - Body Drivers Seat Belt frayed.	fit new seat belt.	311567
877	03/16/2026	1326359	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O406162 Receiving #:432165 Date :2026-03-16	311567
877	03/11/2026	1326359		VEHICLE SAFETY INSPECTION	311436
877	03/11/2026	1326359		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	311436
877	03/11/2026	1326359		ANNUAL SAFETY INSPECTION SERIAL # ____ RSI 076523 PASS __ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	311436
877	03/11/2026	1326400	Consumables		311436
877	03/11/2026	1326400	Mechanic entered - Elec and Light Other header light damage.	removed header light and replaced n/s/header light ok. repaired parker light wires ok.	311436
877	03/11/2026	1326400	HEADLIGHT INSET 178MM HI/LO		311436
877	03/11/2026	1326430	Mechanic entered - Body Other n/s/r glass loose.	CHECKED GLASS FOR SECURITY . COULD NOT FAULT - BUS PASSED ASI INSPECTION SAME DAY	311436
877	03/11/2026	1326430	Mechanic entered - Body Other steering under shaft rubber d	SECURED BOOT - BUS PASSED ASI INSPECTION SAME DAY	311436
877	03/10/2026	1326005	Mechanic entered - A/C Heating Other a/c mount damage.	removed a/c mount and replaced a/c mount ok.	311436
877	03/10/2026	1326005	MOUNT A/C COMPRESSOR LARGE DENSO		311436
877	03/10/2026	1326005	Consumables		311436
877	03/10/2026	1326005	Mechanic entered - Elec and Light Other step light wsitch co	replaced step light switch cover ok.	311436
877	03/10/2026	1326005	Mechanic entered - Elec and Light Other saloon light switch	replaced saloon light switch cover ok.	311436
877	03/10/2026	1326005	SWITCH HAZARD LIGHTS SCANIA L94 1327015		311436
877	03/10/2026	1326005	Mechanic entered - Elec and Light Other switch hazard damage	replaced switch hazard ok.	311436
877	03/10/2026	1326005	Mechanic entered - Body Other n/s/r emergency exit decal dam	replaced n/s/r emergency exit decal ok.	311436
877	03/10/2026	1326005	Mechanic entered - Body Other n/s and o/s reflector damage.	replaced n/s and o/s reflector ok.	311436
877	03/10/2026	1326005	Mechanic entered - Body Other n/s/r smoking decal missing.	replaced n/s/r smoking decal ok.	311436
877	03/10/2026	1326005	Mechanic entered - Body Other n/s/f stunchion pole top bolt	replaced n/s/f staunchion pole top bolt ok.	311436
877	03/10/2026	1326005	Mechanic entered - Body Other both disability seat loose.	repaired both disability seat ok.	311436
877	03/10/2026	1325979	2ND PRE RSI CHECK UP	COMPLETE	311436
877	02/26/2026	1323453		COMPLETED BY ATS 15/2/26	311291
877	02/25/2026	1322927		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out as per check list	311291
877	02/23/2026	1322407	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O405279 Receiving #:430659 Date :2026-02-24 6MM X 4MM PUSH IN JOINER	311291
877	02/23/2026	1322407		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	311291
877	02/23/2026	1322407		VEHICLE SAFETY INSPECTION	311291
877	02/23/2026	1322406		PRE ANNUAL SAFETY INSPECTION CHECK	311291
877	02/23/2026	1322454	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Fit a tee joiner and clean nozzles	311291
877	02/23/2026	1322454	Mechanic entered - Engine Other Dip stick frayed	Replaced dip stick	311291
877	02/23/2026	1322454	SEAL DIFF PINION SCANIA R660 1502385		311291
877	02/23/2026	1322454	Mechanic entered - Fluid Leaks Rear of bus Diff pinion seal	Removed driveline diff end removed U bracket removed diff flange nut removed cleaned flange assemble back new seal fit flange nut driveline and bracket checked diff oil	311291
877	02/23/2026	1322454	Mechanic entered - Fluid Leaks Front of bus Demister control	Removed and replaced leaking valve with new hose and clamps	311291
877	02/23/2026	1322454	Consumables		311291
877	02/23/2026	1322454	HEATER DEMISTER VALVE TAP MERC 0500 DHV4008 37V3305 230016		311291
877	02/23/2026	1322454	DIPSTICK ENGINE OIL 753MM SCANIA L94 40A8200		311291
877	02/23/2026	1322454	BUTTON GEAR SHIFT D VERTICAL SERIES 4(50E0401ZF)		311291
877	02/23/2026	1322454	TEE PIECE 5MM		311291
877	02/23/2026	1322454	UNION ASSY SCANIA (L94UB) (K310UB)		311291
877	02/23/2026	1322454	Mechanic entered - Driver Tablet Not Charging	Removed tablet battery from 345 bus minder fit to tablet charge and fit to bus	311291
877	02/23/2026	1322454	Mechanic entered - Dash Other D Selector button broken	Removed and replaced broken button	311291
877	02/23/2026	1322454		Drill and fit screws to panel	311291
877	02/23/2026	1322454	Mechanic entered - Air System Air_Leak Rear Signal line to a	Removed and replaced signal line fitting with tubing got reducer joiner from Enzed fit to bus and checked for leaks all okay	311291
877	02/10/2026	1319615	Consumables		311291
877	02/10/2026	1319615	Mechanic entered - Elec and Light Other	jump started	311291
877	02/10/2026	1319612		CARRY OUT A/C - B SERVICE AS PER CHECK LIST PO- O404377 - CARRIED OUT BY JIMMY FROM COLD DRIVE	311291
877	02/10/2026	1319612	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O404377 Receiving #:430496 Date :2026-02-23 24 MONTH SERVICE	311291
877	02/10/2026	1319612		CARRY OUT A/C - A SERVICE AS PER CHECK LIST PO- O404377 - CARRIED OUT BY JIMMY FROM COLD DRIVE	311291
877	02/10/2026	1319612		CARRY OUT A/C - A SERVICE AS PER CHECK LIST PO- O404377 - CARRIED OUT BY JIMMY FROM COLD DRIVE	311291
877	02/07/2026	1319104	>>>RAIL BUS <<<N/S/R 2nd to rear window need reseal.	SECURED WITH SIKAFLEX	311291
877	02/03/2026	1318114	Consumables		311291
877	02/03/2026	1318114	Mechanic entered - Elec and Light Flat Batteries		311291
877	01/27/2026	1316535	Consumables	Jump sarted bus. Let sit for 30 minutes	311291
877	01/27/2026	1316535	Mechanic entered - Body Other Graffiti on side of bus	Removed graffiti with acetone	311291
877	12/04/2025	1307287		Assisting	311274
877	12/04/2025	1307287		Assisting	311274
877	12/04/2025	1307287		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Carried out safety inspection as per checklist. Tensioned all wheel nuts to 650nm.	311274
877	12/04/2025	1307286		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	311274
877	12/04/2025	1307286		VEHICLE SAFETY INSPECTION	311274
877	12/04/2025	1307378	WASHER BOTTLE SLT 24V		311274
877	12/04/2025	1307378	Mechanic entered - Wipers and Washers Washers Not Working wa	Removed and replaced washer bottle and washer motor with new. Checked now working.	311274
877	12/04/2025	1307378	Consumables		311274
877	12/04/2025	1307378	Mechanic entered - Elec and Light Flat Batteries	Jump started bus. Charged batteries while performing safety inspection and repairs. Road tested bus and load tested batteries all ok.	311274
877	12/04/2025	1307378	Mechanic entered - Elec and Light Other RPM dash lights n/w	Removed and replaced 4x broken dash light globes with new. Checked dash all ok.	311274
877	12/04/2025	1307378	Consumables		311274
877	12/04/2025	1307378	Mechanic entered - Body Other Rear door modesty panel pole t	Secured modesty panel bracket and fitted new bolt.	311274
877	11/11/2025	1302242	Consumables		311030
877	11/11/2025	1302242	CHECK OVER BUS 877	COMPLETED	311030
877	11/10/2025	1301844	Mechanic entered - Elec and Light Flat Batteries	Jump started ok.	311030
877	10/02/2025	1293878	Consumables		311030
877	10/02/2025	1293878	Mechanic entered - Elec and Light Interior Lights School lig	Removed switch panel removed globe replace with new ok.	311030
877	09/22/2025	1291266	GLASS RESEAL	Creditor #:VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:O395538 Receiving #:420258 Date :2025-09-23 RESEAL OS GLASS X 2 AS REQUIRED	311030
877	09/18/2025	1291244	Consumables		311030
877	09/18/2025	1291244	OSR RETORQUE REQUIRED - TAKE FOR ROAD TEST	retension complete	311030
877	09/18/2025	1291266	OSF 2ND AND 3RD GLASS TO RESEAL	PO:O395538 - CARRIED OUT ONLINE BOOKING WITH OBRIANS - AWAITING REPAIR DATE	311030
877	09/16/2025	1290552		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	311030
877	09/10/2025	1289501		VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.	311030
877	09/10/2025	1289501		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts.	311030
877	09/10/2025	1289501		Assisting	311030

[illegible]

877	09/19/2024	1202493	1377924	Rotational Speed Senso	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O372680 Receiving #:394879 Date :2024-09-19	303831
877	09/19/2024	1202493	1361118	Cable Flat Terminal	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O372680 Receiving #:394879 Date :2024-09-19	303831
877	09/18/2024	1202493	GASKET	ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		303831
877	09/17/2024	1202493	Consumables			303831
877	09/17/2024	1202493	SENSOR	ABS NSR SCANIA L94 K320 40G0009 49V6301		303831
877	09/17/2024	1202493	SENSOR	ABS L/H/R REAR 1892066		303831
877	09/01/2024	1176705	Consumables			303831
877	09/01/2024	1176705	PRESSURE	SENSOR	Creditor #:VB-BEA100 BEARING LOGISTICS P/O #:O371960 Receiving #:393966 Date :2024-09-06	303831
877	08/29/2024	1210755			CARRY OUT FIRE EXTINGUISHER TEST & TAG drivers fire extinguisher not tagged. Removed and fit new one in place.	303645
877	07/23/2024	1202701	jump	start bus	jump started	303115
877	07/23/2024	1202701	Consumables			303115
877	07/23/2024	1202653	Accident	REAR damage - PTI sheet on 25/03/2024	inspected bus no damage to be found	303115
877	07/22/2024	1202493	Mechanic	entered - Wheels and Tyres Wheel Nut Retension O/S/	Retensioned O/S/R wheel nuts to 650nm.	303115
877	07/22/2024	1202493	Consumables			303115
877	07/15/2024	1200932	PERFORM	CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC	COMPLETE	303115
877	07/01/2024	1197374	SLACK	ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		303115
877	07/01/2024	1197374			VEHICLE SAFETY INSPECTION	303115
877	07/01/2024	1197374	OSR	SLACK ADJUSTOR U/S	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS RETORQUE ALL WHEEL NUTS.	303115
877	07/01/2024	1197374	WIPER	JET BLOCKED	REPLACED OSR SLACK ADJUSTOR	303115
877	07/01/2024	1197374	NSRR	BOTTOM SHOCKER BOLT LOOSE	UNBLOCKED . CHECKED OPERATION ALL OK	303115
877	07/01/2024	1197374	NSF	BOTTOM BLINKER NOT WORKING	TIGHTEND	303115
877	07/01/2024	1197468	Mechanic	entered - Wheels and Tyres Worn P5 tyre tread low.	R/R GLOBE . CHECKED OPERATION ALL OK	303115
877	07/01/2024	1197468	Consumables		change P5 tyer.RUNOUT.	303115
877	06/19/2024	1195221	Mechanic	entered - Elec and Light Other doors not working	checked and found no ground to the door switches thru RPD module. reset RPD and checked the doors started working.	303115
877	06/19/2024	1195221	Consumables			302318
877	06/15/2024	1194617	Mechanic	entered - Engine Other eng hatch switch not functio	checked and found hatch inhibitor switch loose and tied up. secured switch and checked functioning ok. secured rev buzzer.	302318
877	06/12/2024	1193998	JUMP	START BUS	Jump started bus and left bus running for 2hrs. bus needed jump starting as hasnt been used for rail in a few weeks . charge rate 27.6 volts	302318
877	06/12/2024	1193998	Consumables			302318
877	06/01/2024	1182858	DIRECT	PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O363074 Receiving #:388137 Date :2024-06-14 rectify desto not working as required	302318
877	06/01/2024	1182858	Consumables			302318
877	06/01/2024	1176385	1865747	Slack Adjuster	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O361185-RET Receiving #:387755 Date :2024-06-07 Incorrect Item	302318
877	05/24/2024	1190268			TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.	301770
877	05/09/2024	1184035	OIL	ENGINE ALL FLEET PLUS E900 15W-40		299450
877	05/01/2024	1176385	SLACK	ADJUSTER AUTO NSR SCANIA	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O361185-1 Receiving #:386198 Date :2024-05-20	301153
877	04/23/2024	1184065	Mechanic	entered - Gearbox Driveline Other trans drain plug	Replaced trans drain plug with new.	296926
877	04/23/2024	1184065	DRAIN	PLUG M22 X 1.5 ECOMAT ZF 49A4000		296926
877	04/23/2024	1184035	Consumables			299450
877	04/23/2024	1184035	Consumables			299450
877	04/23/2024	1184035	OIL	ENGINE ALL FLEET PLUS E900 15W-40		296926
877	04/23/2024	1184035	OIL	ATF STEERING DEX-3 VALVOLINE		296926
877	04/23/2024	1184035	O-RING	LOWER SPINNER FILTER SCANIA L94 K124		296926
877	04/23/2024	1184035	O-RING	LARGE UPPER SPINNER FILTER SCANIA		296926
877	04/23/2024	1184035			CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order all ok	296926
877	04/23/2024	1184035	PAPER	SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		296926
877	04/23/2024	1184035	FILTER	ZF ECOMAT GEARBOX 4139-298-038 3098081		296926
877	04/23/2024	1184035	FILTER	FUEL SCANIA VARIOUS MODELS		296926
877	04/23/2024	1184035	OIL	SAMPLE TEST KIT		296926
877	04/23/2024	1184035	FILTER	OIL SCANIA VARIOUS MODELS		296926
877	04/17/2024	1182858	desto	not working	PO:O363074 - desto repaired by Ryan from Lonsdale	296229
877	04/17/2024	1182858	Consumables			296229
877	04/16/2024	1180972	DIRECT	PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O362513 Receiving #:384140 Date :2024-04-18	296339
877	04/12/2024	1181728	brakes	feel like their dragging on take off	road test could not fault.	295607
877	04/09/2024	1180972			VEHICLE SAFETY INSPECTION	295374
877	04/09/2024	1180972			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	295374
877	04/09/2024	1180972			ANNUAL SAFETY INSPECTION SERIAL # ____ RSI 049125 PASS ____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	295374
877	04/09/2024	1181003	Driver	Tablet Entered -Engine - Low Powerpick-up too slow	road tested bus . could not fault lacking power	295374
877	04/09/2024	1181003	Driver	Tablet Entered -Body - Drivers Seat LeaningLumbar d	adjusted weight mechsism on drivers seat . checked operation all ok	295374
877	04/09/2024	1181003	Consumables			295374
877	04/09/2024	1181003	Consumables			295374
877	04/06/2024	1180612	Ops	Entered - Fault - Consat Push-to-talk COMMs - Route: 7	double entry the same door fault	295147
877	04/06/2024	1180612	Consumables			295147
877	04/06/2024	1180612	Front	doors wont close unless door override is used.	ADJUSTED front door pressure and road tested - no fault occurred	295147
877	04/06/2024	1180612	Consumables			295147
877	04/02/2024	1179729	Ops	Entered - Fault - Body Front_Door Operation Faulty - R	multiple entry	294780
877	04/02/2024	1179729	Body	Front_Door Operation Faulty	multiple entry	294780
877	04/02/2024	1179729	Front	doors open when bus in motion.	Checked bus road tested and checked door operation could not fault bus.	294780
877	04/02/2024	1179729	Consumables			294780
877	04/02/2024	1179729	Consumables			294780
877	03/28/2024	1179201			CARRY OUT A/C - B SERVICE AS PER CHECK LIST carried out by cold drive poO362001	294483
877	03/28/2024	1179201			CARRY OUT A/C - A SERVICE AS PER CHECK LIST	294483
877	03/26/2024	1178848	Mechanic	entered - Elec and Light Exterior Lights N/S/F bott	Replaced N/S/F bottom park light with new. Checked front lights all ok.	294256
877	03/26/2024	1178848	Consumables			294256
877	03/23/2024	1178380	Mechanic	entered - Elec and Light Exterior Lights N/S headli	Replaced N/S headlight globe. Checked lights all ok.	293630
877	03/23/2024	1178380	GLOBE	24V H4 75/70W HALOGEN		293630
877	03/23/2024	1178380	Consumables			293630
877	03/20/2024	1176705			checked and found the pressor sensor not operating. checked the pressure and adjusted. sensitivity started working. checked door brakes and all ok.	293218
877	03/19/2024	1177404			PRE ANNUAL SAFETY INSPECTION CHECK	293218
877	03/19/2024	1177404			CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	293218
877	03/19/2024	1177450	Mechanic	entered - Suspension Other Both front and rear sway	Removed and fitted new sway bar bushes for front and rear.	293218
877	03/19/2024	1177450	BUSH	SWAY BAR D/AXLE 47MM SCANIA K124IB 1880751		293218
877	03/19/2024	1177450	BUSH	FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		293218
877	03/19/2024	1177450	HEADLIGHT	INSET 178MM HI/LO		293218
877	03/19/2024	1177450	GLOBE	24V H4 75/70W HALOGEN		293218
877	03/19/2024	1177450	Mechanic	entered - Elec and Light Exterior Lights O/S Head l	Removed and replaced low beam insert and globes	293218
877	03/19/2024	1177450	Mechanic	entered - Elec and Light Interior Lights Next stop	Removed and fitted new dash light globe	293218
877	03/19/2024	1177404	Mechanic	entered - Elec and Light Other dash R.P.M light no	Replaced speedo head globe	293218
877	03/19/2024	1177450	Consumables			293218
877	03/19/2024	1177404	Consumables			293218
877	03/19/2024	1176385			Fit back new n/s/r slack adjuster adjusted brakes	293218
877	03/19/2024	1176265			Fitted new slack adjuster adjusted brakes	293218
877	03/18/2024	1176385	SLACK	ADJUSTER OSR MAN ADJ SCA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O361337 Receiving #:382232 Date :2024-03-22	293630

877	03/16/2024	1176898	Vandalism	Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	293218
877	03/15/2024	1176812	intercooler remove / wash radiator	Removed intercooler washed intercooler and radiator. Fitted intercooler in position and tightened all bolts and screws.	293218	
877	03/15/2024	1176705	Mechanic entered - Body	Other front door sensitive not work	293218	
877	03/15/2024	1176385	1865747	Slack Adjuster	293630	
877	03/14/2024	1176238			293218	
877	03/14/2024	1176238			293218	
877	03/14/2024	1176265	Mechanic entered - Suspension	Other n/s/f bottom shock rubbe	293218	
877	03/14/2024	1176265	BUSH SHOCK	ABSORBER SCANIA	293218	
877	03/14/2024	1176265	FILTER AIR OUTER	SCANIA K94IB L94UAB K124IB	293218	
877	03/14/2024	1176265	Mechanic entered - Engine	Other engine air filter 2years.	293218	
877	03/14/2024	1176290	Driver Tablet Entered -Elec and Light - Next Stop Button	checked operation of all passenger bell buttons . could not fault	293218	
877	03/14/2024	1176265	Mechanic entered - Elec and Light	Other rear step light not	293218	
877	03/14/2024	1176265	Mechanic entered - Elec and Light	Other buzzer reversing not	293218	
877	03/14/2024	1176265	Consumables		293218	
877	03/14/2024	1176290	Consumables		293218	
877	03/14/2024	1176265	Mechanic entered - Body	Other n/s/f staunchion pole bolt mis	293218	
877	03/14/2024	1176265	BRAKE BOOSTER	REAR RH SCANIA L94	293218	
877	03/14/2024	1176265	SLACK ADJUSTER	AUTO OSR D/AXLE SCANIA SERIES 4 2009820	293218	
877	03/14/2024	1176385	NSR slack adjustor	R/R	293218	
877	03/14/2024	1176265	Mechanic entered - Brakes	Other o/s/r brake booster air leak	293218	
877	03/14/2024	1176265	Mechanic entered - Brakes	Other n/s/r brake slack adjust not	293218	
877	03/14/2024	1176265	PERFORM CAMPAIGN	01/24 REMOVAL OF OLD NO SMOKING DECALS	293218	
877	03/05/2024	1174299	Driver Tablet Entered -Engine - Low Power	road tested bus . could not fault	291435	
877	03/05/2024	1174299	interior mirror broken	replaced interior mirror ok.	291435	
877	03/05/2024	1174299	MIRROR INTERIOR	RECTANGULAR SMALL	291435	
877	03/02/2024	1174000	Ops Entered - Fault - CCTV Server Connection -	Route: 703 -	291435	
877	03/01/2024	1173645	Driver Tablet Entered -Engine - Low Power	checked the camera status adjust few settings the unit looks like conected I will be report it for the streamax	291435	
877	03/01/2024	1179201	AIR CONDITIONING REPAIR	long road testcould not fault lacking power	291435	
877	02/29/2024	1173335		Creditor #:-VB-COLO04 COLD DRIVE PTY LTD P/O #:O362001 Receiving #:383121 Date :2024-03-31 carry out AC B service as required	294780	
877	02/17/2024	1170273	Busminder not tracking	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST CARRIED OUT AS PER CHECK LIST	291435	
877	02/17/2024	1170273	USB SV 3A DUAL CONVERTER	MODULE BUS MINDER	289647	
877	02/17/2024	1170273	Ops Entered - Fault - Driver Tablet Unable To Log In -	Route	289647	
877	02/17/2024	1170273	BUSMINDER CABLE	USB A TO C TYPE 5V3A	289647	
877	02/17/2024	1170321	Mechanic entered - Elec and Light	Interior Lights dash indic	289647	
877	02/14/2024	1169421	Workshop Tablet Entered -Engine - Low Power	checked road tested could not falt.	288966	
877	02/12/2024	1169002	Mechanic entered - Elec and Light	Exterior Lights Head light	288721	
877	02/12/2024	1169002	GLOBE 24V H4 75/70W	HALOGEN	288721	
877	02/12/2024	1169004	Mechanic entered - Elec and Light	Exterior Lights Park ligh	288721	
877	02/08/2024	1167943	Mechanic entered - Wheels and Tyres	Wheel Nut Retension N/S/	287777	
877	02/08/2024	1167943	Consumables	retorque n/s/f wheel nuts.	287777	
877	02/06/2024	1167644	AIRBAG FRONT	SCANIA K310UB E5 40Y2248 40Y2223	287587	
877	02/06/2024	1167644	Ops Entered - Fault - Suspension	Hard - Route: 703 - Monash	287587	
877	02/01/2024	1164626	DIRECT PURCHASE - VANDALISM		287115	
877	01/20/2024	1164578	Mechanic entered - Wheels and Tyres	Wheel Nut Retension N/S/	284810	
877	01/20/2024	1164578	Consumables		284810	
877	01/20/2024	1164602	Vandalism	Vandalism/ Graffiti Interior	284810	
877	01/20/2024	1164626	GRAFFITI AUDIT # 1013	15/1/24	284810	
877	01/20/2024	1164544	Mechanic entered - Body	Other Pillar cracked behind fuel tan	284810	
877	01/20/2024	1164544	Consumables		284810	
877	01/19/2024	1164340			284810	
877	01/19/2024	1164340			284810	
877	01/19/2024	1164411	TYRE 295/80R22.5	RECAP	284810	
877	01/19/2024	1164411	Mechanic entered - Wheels and Tyres	Worn N/S/R/O tyre U/S -	284810	
877	01/19/2024	1164411	Consumables		284810	
877	01/19/2024	1164430	Mechanic entered - Suspension	Other N/S/F Sway Bar link U/S	284810	
877	01/19/2024	1164430	LINK FRT SWAY BAR	L94 K360 1766014 0463245 2048601	284810	
877	01/19/2024	1164430	Mechanic entered - Body	Other 1x no smoking/vaping Decal mis	284810	
877	01/19/2024	1164430	Mechanic entered - Body	Other 1x disabled seat bottom plasti	284810	
877	01/19/2024	1164430	Mechanic entered - Body	Other disabled seat top pins not sea	284810	
877	01/19/2024	1164430	Mechanic entered - Body	Other Rear Seat Backing N/S	284810	
877	01/19/2024	1164430	Consumables		284810	
877	01/16/2024	1163676	Driver Tablet Entered -A/C Heating -	Noisydrivers fan not	284582	
877	01/12/2024	1163078	Mechanic entered - Engine	Other engine no power.	283840	
877	01/06/2024	1161944	PERFORM CAMPAIGN	10/23 POSITIONING OF 2024 PTV FARES	282826	
877	01/02/2024	1160666	Ops Entered - Fault - Body	Rear_Door Operation Faulty - Rou	281901	
877	01/02/2024	1160646	OSR buff - LDM confirmed	2-1-24	281901	
877	01/02/2024	1160666	Consumables		281901	
877	01/02/2024	1160646	Consumables		281901	
877	12/28/2023	1159894	DIRECT PURCHASE - GLASS		282559	
877	12/28/2023	1159894	Consumables		282559	
877	12/27/2023	1159894	PTI Tablet Entered -Body - Rear_Door	Operation Faulty door	281901	
877	12/27/2023	1159894	PTI Tablet Entered -Body - Windows	Side rear door glass is	281901	
877	11/28/2023	1151972	DECAL PTV D - PASS	REAR	277229	
877	11/28/2023	1151972	DECAL PTV G - DRIVER	REAR	277229	
877	11/28/2023	1151972	DECAL PTV D - PASS	REAR	277229	
877	11/28/2023	1151972	DECAL PTV G - DRIVER	REAR	277229	
877	11/27/2023	1154472	Mechanic entered - Wheels and Tyres	Wheel Nut Retension o/s/	277229	
877	11/27/2023	1154472	Consumables		277229	
877	11/24/2023	1154215	engine side cover under	compressor leaking	277229	
877	11/24/2023	1151972	DECAL PTV D - PASS	REAR	277229	
877	11/24/2023	1151972	DECAL PTV N - PASS	REAR CORNER	277229	
877	11/24/2023	1151972	REFLECTOR AMBER	HELLA 94 X 44MM	277229	
877	11/24/2023	1151972	SIKA 5221	CARTRIDGE	277229	
877	11/20/2023	1151972	DECAL PTV D - PASS	REAR	278771	
877	11/20/2023	1153148			277229	
877	11/17/2023	1151972			277229	
877	11/16/2023	1151972			277229	
877	11/15/2023	1151972			277229	
877	11/14/2023	1151972	Accident rear damage #	56074	277229	
877	11/09/2023	1151193			277229	
877	11/09/2023	1151193			277229	
877	11/09/2023	1151344	Mechanic entered - Suspension	Other n/s/r/r and o/s/r/r and	277229	
877	11/09/2023	1151344	AIRBAG REAR	SCANIA K280UB K310 16mm FITTING 6714 NP02	277229	

877	11/09/2023	1151344	HARNESS WEAR SENSOR SCANIA FRONT L94		2772229
877	11/09/2023	1151344	CONNECTOR ELBOW-MALE SWIVEL 12MM x 16MM		2772229
877	11/09/2023	1151226	Mechanic entered - Fluid Leaks Other trans coolant hose leak	tightened trans coolant hose clamp ok.	2772229
877	11/09/2023	1151226	Mechanic entered - Elec and Light Other pax switch crack.	replaced o/s/r pax switch.	2772229
877	11/09/2023	1151226	SWITCH STOP YELLOW (62628)(50V2242)		2772229
877	11/09/2023	1151226	Consumables		2772229
877	11/09/2023	1151226	Mechanic entered - Body Other front door top panel screws mi	replaced front door top panel screws ok.	2772229
877	11/09/2023	1151226	Mechanic entered - Body Other n/s/f staunchion pole loose an	repaired n/s/r staunchion pole and replaced n/s/f staunchion pole top bolt ok.	2772229
877	11/09/2023	1151226	Mechanic entered - Body Other both middle all seat loose.	repaired both all middle seat ok.	2772229
877	11/09/2023	1151226	Mechanic entered - Body Other n/s/r modesty panel loose.	repaired n/s/r modesty panel ok.	2772229
877	11/09/2023	1151226	Mechanic entered - Body Other bus inside o/s/f top panel scr	replaced o/s/f top panel screws.	2772229
877	11/04/2023	1150677	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	276813
877	11/02/2023	1150276	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866		276566
877	11/02/2023	1150276	Mechanic entered - Brakes Park_Brake Not Holding Park brak v	Removed park brake valve and fitted new one. Road tested and checked if any leak all ok.	276566
877	11/02/2023	1150137		CARRY OUT B SERVICE AS PER CHECK LIST	276566
877	11/02/2023	1150137	FILTER OIL SCANIA K93 L94 1117285 2059778		276566
877	11/02/2023	1150137	FILTER FUEL SCANIA L94 (1372444)		276566
877	11/02/2023	1150137	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		276566
877	11/02/2023	1150137	OIL SAMPLE TEST KIT		276566
877	11/02/2023	1150137	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		276566
877	11/02/2023	1150137	O-RING SPINNER FILTER SCANIA L94		276566
877	11/02/2023	1150137	PAPER SPINNER FILTER OIL INSERT SCANIA L94		276566
877	11/02/2023	1150137	Consumables		276566
877	11/02/2023	1150137	Consumables		276566
877	10/17/2023	1146885	Consumables		274002
877	10/17/2023	1146885	Mechanic entered - Elec and Light Exterior Lights O/S/F top	Replaced O/S/F top park light globe. Checked front lights all ok.	274002
877	10/14/2023	1146275	Consumables		273518
877	10/14/2023	1146275	PTI Tablet Entered -Elec and Light - Exterior Lights os fron	fit globe.	273518
877	10/09/2023	1144951	Consumables		272759
877	10/09/2023	1145192	Consumables		272759
877	10/09/2023	1144951	Driver Tablet Entered -Elec and Light - Next Stop Buttonsom	checked and found next stop buzzer comes on with light on dash for all pax switches. hammer warning on at times. removed hammer and insulated internal wires ok.	272759
877	10/09/2023	1145192	Mechanic entered - Elec and Light Exterior Lights N/S/F top	Removed and replaced festoon globe	272759
877	10/04/2023	1144047		complete	271715
877	10/03/2023	1143744	Consumables		271715
877	10/03/2023	1143744	emergency hammer requires securing at rear of salloon	replaced n/s/r hammer and hammer holder ok.	271715
877	10/03/2023	1143744	EMERGENCY HAMMER KIT W/WIRE		271715
877	10/03/2023	1143744	EMERGENCY HAMMER BRACKET WITH SENSOR		271715
877	10/03/2023	1143734		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	271715
877	09/18/2023	1141084		VEHICLE SAFETY INSPECTION	269496
877	09/18/2023	1141084		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	269496
877	09/18/2023	1141120	Mechanic entered - Wipers and Washers Other o/s wiper blade	replaced o/s wiper blade ok.	269496
877	09/18/2023	1141120	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM		269496
877	09/18/2023	1141120	Mechanic entered - Steering Other steering wheel loose.	repaired steering wheel ok.	269496
877	09/18/2023	1141120	Mechanic entered - Elec and Light Other 2 way not working.	repaired 2 way wires ok.	269496
877	09/18/2023	1141120	Mechanic entered - Elec and Light Other n/s/f indicator lens	replaced n/s/f indicator light lens ok.	269496
877	09/18/2023	1141120	LENS AMBER ROUND (85945)		269496
877	09/18/2023	1141120	Consumables		269496
877	09/18/2023	1141120	Mechanic entered - Body Other both middle seat top pins off.	put in both middle seat top pins ok.	269496
877	09/18/2023	1141120	Mechanic entered - Body Other driver seat back modesty panel	repaired driver seat back modesty panel ok.	269496
877	09/18/2023	1141120	Mechanic entered - Body Other wheel chair ramp pin off.	put in wheel chair ramp pin ok.	269496
877	09/18/2023	1141120	Mechanic entered - Body Other n/s/middle seat loose.	repaired n/s/middle seat ok.	269496
877	09/08/2023	1139436	PERFORM CAMPAIGN 06/23 REPLACE ETAG	replaced e-tag	268387
877	09/01/2023	1137821	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	carried out campaign	267042
877	08/30/2023	1137044	Consumables		266539
877	08/30/2023	1137044	PTI Tablet Entered -Front parklight out	replaced n/s/f top parklight globe ok.	266539
877	08/30/2023	1137044	PTI Tablet Entered -Elec and Light - Exterior Lights os fron	replaced o/s front top parklight globe ok.	266539
877	08/29/2023	1135806	Consumables		266539
877	08/29/2023	1135806	Driver side window blind is too short and not wide enough t	removed the old one and fitted 1230X600 mm blind	266539
877	08/28/2023	1135806	DRIVERS BLIND 1200MM X 600MM D	Creditor #:/VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:/O349674 Receiving #:368002 Date :2023-08-28	266539
877	08/25/2023	1135806	Driver side window blind is too short and not wide enough t	need to order new blind	266104
877	08/21/2023	1134832	Consumables		265527
877	08/21/2023	1134832	Mechanic entered - Elec and Light Other busminder tab bracke	fabricated two ally plates and mounted to dash and secured tab ok	265527
877	08/05/2023	1131381	Consumables		262250
877	08/05/2023	1131381	PTI Tablet Entered -Body - Windows Front bus washed	completed by fleet support	262250
877	07/28/2023	1129685		VEHICLE SAFETY INSPECTION	261417
877	07/28/2023	1129685		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	261417
877	07/28/2023	1129706	AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02		261417
877	07/28/2023	1129706	Mechanic entered - Suspension Other N/S/R front air bag leak	Removed and replaced N/S/R front air bag. Checked for air leaks from air fitting all ok.	261417
877	07/28/2023	1129706	Consumables		261417
877	07/28/2023	1129706	Mechanic entered - Elec and Light Other Rear licence plate l	Replaced rear licence plate light assembly. Checked light all ok.	261417
877	07/28/2023	1129706	Mechanic entered - Elec and Light Interior Lights Driver's r	Replaced driver's light globe. Checked light all ok.	261417
877	07/28/2023	1129706	Mechanic entered - Elec and Light Interior Lights O/S 2nd sa	Replaced saloon light fluro. Checked saloon lights all working.	261417
877	07/28/2023	1129706	LAMP LED NUMBER PLATE EXIT LIGHT 250120 27771		261417
877	07/28/2023	1129706	Consumables		261417
877	07/28/2023	1129706	ASSEMBLY RETRIMMED BASE 6008		261417
877	07/28/2023	1129706	Mechanic entered - Body Other Few hinge pins for disabled se	Refitted pins. Checked seat rest for play all ok.	261417
877	07/28/2023	1129706	Mechanic entered - Body Other N/S last stop switch loose.	Resecured stop switch. Checked switch all working.	261417
877	07/28/2023	1129706	Mechanic entered - Body Other Drivers seat cushion lacks pad	Removed and replaced driver's seat cushion. Checked for play all secured.	261417
877	07/22/2023	1128347	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	260176
877	07/14/2023	1126563	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	complete	258776
877	07/12/2023	1125976		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order all ok	258339
877	07/12/2023	1125976		Assisting Assisted with B service as per work order.	258339
877	07/12/2023	1125976	FILTER FUEL SCANIA L94 (1372444)		258339
877	07/12/2023	1125976	FILTER OIL SCANIA K93 L94 1117285 2059778		258339
877	07/12/2023	1125976	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		258339
877	07/12/2023	1125976	PAPER SPINNER FILTER OIL INSERT SCANIA L94		258339
877	07/12/2023	1125976	O-RING SPINNER FILTER SCANIA L94		258339
877	07/12/2023	1125976	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		258339
877	07/12/2023	1125976	OIL SAMPLE KIT AMPOL		258339
877	07/12/2023	1125976	DRAIN PLUG M22 X 1.5 ECOMAT ZF 49A4000		258339
877	07/12/2023	1125976	Consumables		258339
877	07/12/2023	1125976	Consumables		258339
877	06/29/2023	1123340	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe and park light globe.	256188

877	06/29/2023	1123340	GLOBE 24V H4 75/70W HALOGEN			256188
877	06/29/2023	1123340	Consumables			256188
877	06/26/2023	1122570	GLOBE 24V H4 75/70W HALOGEN			254847
877	06/26/2023	1122570	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe.		254847
877	06/26/2023	1122570	Consumables			254847
877	06/26/2023	1122353	PTI Tablet Entered -Body - Body Damagepetrol lid broken	to order fuel tank filler cap.		254847
877	06/26/2023	1122353		Removed one second hand from Moorabbin depot and fit to the bus		254847
877	06/21/2023	1121126	PTI Tablet Entered -desto Interior panel broken	fit hinges to desto hatchfit hatch to bus.		254192
877	06/21/2023	1121126	POSITION HINGE			254192
877	06/19/2023	1121126	PTI Tablet Entered -desto Interior panel broken	all 3 hinges brokenorder newrefit desto hatchmake fit temp brackets.		253893
877	06/14/2023	1120255	Mechanic entered - CCTV System Noisy	foramtted hard drive and corrected camera settings all functions operating correctly		252908
877	06/14/2023	1120255	HARD DRIVE HDD 1TB CCTV(111-1TBSSDD)			252908
877	06/13/2023	1120007	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	completed by consat installers - garys team		252908
877	06/08/2023	1119357		VEHICLE SAFETY INSPECTION		252713
877	06/08/2023	1119357		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		252713
877	06/08/2023	1119415	Mechanic entered - Elec and Light Reverse Buzzer Reverse Ala	located reverse alarm found power wire to be broken trimmed wire re crimped new terminals checked for operation ok.		252713
877	06/08/2023	1119415	Consumables			252713
877	06/08/2023	1119441	CCTV CCTV not recording since April 2023	fitted new DVR wired and mounted. took the bus to Knox to get programmed. username admin and pw admin too. cctv recording all good.		252713
877	06/08/2023	1119441	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-STR001 STREAMAX AUSTRALIA P/O #:O344720 Receiving #:362461 Date :2023-06-09 supply CCTV DVR as required		252908
877	06/08/2023	1119415	Mechanic entered - Body Other Front Modesty Panel Handle Loo	drilled out loose rivetsre rivetted handle checked for movement ok.		252713
877	06/08/2023	1119415	Mechanic entered - Body Other Disabled Seat Top Pins N/S	re seated disabled seat top pins		252713
877	06/08/2023	1119415	Mechanic entered - Body Other O/S/R Seat Base N/S	not secured bolts in position no washers on bolts to hold base down removed bolts lifted base added bolts with washers retightened checked for seat base movement ok.		252713
877	06/08/2023	1119443	Mechanic entered - Body Other Rear Inside step safety strip	cleaned strip channel taped either side so as to not get glue overspray coated inside of channel and underside of strip with glue allowed cure time fitted strip into channel pushed into position then pressed in with mallet ok.		252713
877	06/08/2023	1119466	Mechanic entered - Body Other Front Roof Hatch cover - Front	fitted spare part from moorabbin.		252713
877	05/13/2023	1114341	PTI Tablet Entered -Engine - Warning Light engine not starti	trace found engine isolate switch wire loosereconnect wireok.		247827
877	05/12/2023	1114149	PTI Tablet Entered -Fluid Leaks - Rear of bus low coolant l	checked coolant level could not fault		247827
877	05/09/2023	1083872	Service - 3rd Accident	Job completed. Refer to W/O# 1111195		247087
877	05/08/2023	1112969	PTI Tablet Entered -Engine - Warning Light coolant level low	road tested coolant okcheck tested coolant pressure engine bottom coolant hose crack and drain coolant and replaced coolant hose and put in coolant after road sested all ok and check again coolant all ok.		246833
877	05/08/2023	1112969	HOSE HEADER TANK 483182			246833
877	05/05/2023	1111195		Fit new osr marker light and repaired wiring.		246833
877	05/05/2023	1086049	Accident # 54290 - o/s/r corner damage to go to bodyshop - L	Retrieved the bus to replace the rear bar and found that it was a wrong bar and released the bus on request. job could not be able to finish		246833
877	05/05/2023	1111195	LAMP LED SIDE MARKER RED/AMBER			246833
877	05/04/2023	1111195	REFLECTOR RED 70MM X 31MM			246833
877	05/04/2023	1111195	DECAL DO NOT OVERTAKE 100MM X 300MM			246833
877	05/04/2023	1111195				246833
877	05/04/2023	1111195		fittup o/s/r corner ptv decals (used offcuts) needs new clearance light. also welded up seat frames base for kumar buses 1428 and 1313		246833
877	05/03/2023	1111195				246833
877	05/03/2023	1111195		prep and repair and paint prep and paint wheels		246833
877	05/03/2023	1111195	HARDENER DEBEER FAST 2.5L(F3255)			246833
877	05/03/2023	1111195	PAINT ENAMEL GLOSS WHITE 4LT			246833
877	05/01/2023	1111195		removed decals secured and fibreglassed rear bar bracket on repaired both bars and primed welded up rear bar bracket		246833
877	05/01/2023	1111195	FILLER CAMS FINE			246833
877	05/01/2023	1083872	TPAF MOBILE - R/2022/54290/MR - REAR BUMPER AND O/S - DECAL	perp for paint		246833
877	04/28/2023	1111195	Repairn Rear bar and O/S/R bar - Accident # 54290			246833
877	04/28/2023	1111195		stripped down bus fibreglassed rear o/s bar fiberfilled		246833
877	04/22/2023	1110316	PTI Tablet Entered -Fluid Leaks - Rear of bus low coolant le	top up coolant.		246461
877	04/20/2023	1109926		test has been done on Feb 2023		246461
877	04/19/2023	1109521	PTI Tablet Entered -Engine - Warning Light low coolant level	put in coolant after check coolant not leaks ok.		245705
877	04/15/2023	1108934	PTI Tablet Entered -Engine - Warning Light low coolant 2 day	check coolant leaksnillong road testcould not fault.		245171
877	04/13/2023	1108043	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O340954 Receiving #:358650 Date :2023-04-14 carry out ASI as required		245171
877	04/11/2023	1108043		VEHICLE SAFETY INSPECTION		244717
877	04/11/2023	1108043		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		244717
877	04/11/2023	1108043		ANNUAL SAFETY INSPECTION SERIAL # RSI 056832 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 PO O340954		244717
877	04/11/2023	1108057		PRE ANNUAL SAFETY INSPECTION CHECK done by satya on 18-03-2023		244717
877	04/11/2023	1108057		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		244717
877	04/11/2023	1108045	Mechanic entered - Elec and Light Other number light not wor	repaired number place wires ok.		244717
877	04/11/2023	1108045	Mechanic entered - Body Other under middle rust.	repaired under middle rust all ok.		244717
877	04/11/2023	1108045	Consumables			244717
877	03/27/2023	1105553	Mechanic entered - Engine Will Not Start in Neutral starter	checked and found starter faulty. ring gear is ok. replaced starter motor and checked ok		242243
877	03/27/2023	1105553	STARTER MOTOR SCANIA L94 (0571420)(IM038)			242243
877	03/27/2023	1105508		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list		242243
877	03/25/2023	1105445	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	Retensioned all front wheel nuts.		242243
877	03/25/2023	1105445	Consumables			242243
877	03/25/2023	1105452	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti		242243
877	03/25/2023	1105420	Mechanic entered - Suspension Other Front sway bar bushes wo	Removed and fitted new front sway bar bushes.		242243
877	03/25/2023	1105420	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081			242243
877	03/25/2023	1105420	Mechanic entered - Elec and Light Interior Lights 2x saloon	Removed and fitted 2 new fluoro tubes and an inverter.		242243
877	03/25/2023	1105420	INVERTER 24 VOLT 36 WATT MAN			242243
877	03/25/2023	1105396	2nd PRE ASI check	Carried out PRE RSI second check.		242243
877	03/25/2023	1105396	Consumables			242243
877	03/24/2023	1105256		TRANSMISSION CHECK AS PER CHECK LIST carried out as per check list		242243
877	03/24/2023	1105255	remove intercooler / wash radiator	removed intercooler and wash both radiator and cooler. fitted back ok		242243
877	03/24/2023	1104728		traced D/B relay input and output circuits. found relay is on all the time. RPD turned relay on. checked RPD inputs. found both door close are ok but ALT sig failed. traced and found ALT circuit CB partially popped. replaced CB and wiggle tested. road tested too. no fault recurring.		242243
877	03/24/2023	1104937	DIRECT PURCHASE - GLASS	Creditor #:VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:O339986 Receiving #:357289 Date :2023-03-27 reseal 3rd glass front the front on o/s of bus		242603
877	03/24/2023	1104937	Consumables			242603
877	03/23/2023	1104937	Mechanic entered - Body Other o/s/middle galss very loose.	O339986 - O'Brians booked online - waiting for booking phone call from o brians - completed by obrians		242243
877	03/23/2023	1104980	Mechanic entered - Body Other Pillar behind fuel tank cracke	brought bus into workshop located crack on body pillar behind fuel tank set bus up on high lifts disconnected battery raised bus up removed fuel tank cleaned area removed reinforcement that was already added fabricated 2 pieces of angle iron to fit repair properly		242243
877	03/23/2023	1104980	Consumables			242243
877	03/22/2023	1104580		VEHICLE SAFETY INSPECTION		242243
877	03/22/2023	1104580		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		242243
877	03/22/2023	1104614	Mechanic entered - Wheels and Tyres Other both front tyres u	removed both tyres and replaced both front tyres all ok.		242243
877	03/22/2023	1104614	TYRE 295/80R22.5 NEW			242243
877	03/22/2023	1104614	Consumables			242243
877	03/22/2023	1104603	Mechanic entered - Suspension Other Rear sway bar worn	checked rear D rubber could not fault ok.		242243
877	03/22/2023	1104613	Mechanic entered - Engine Other engine belt tensioner noisy	replaced engine belt tensioner ok.		242243
877	03/22/2023	1104613	TENSIONER ALT BELT SCANIA N310UA 2197005 1859657			242243
877	03/22/2023	1104728	Elec and Light (None) door brakes on all the time	checked door brake related circuits and RPD; needs further diagnostics.		242243
877	03/22/2023	1104613	Mechanic entered - Body Other o/s/r member pillar bolts loos	tightened o/s/r member pillar bolts ok.		242243
877	03/22/2023	1104613	Mechanic entered - Body Other o/s/middle seat loose.	replaced o/s/middle seat ok.		242243
877	03/22/2023	1104613	Mechanic entered - Body Other front door modesty panel very	repaired front modesty panel ok.		242243
877	03/22/2023	1104613	Consumables			242243
877	03/18/2023	1103849		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		241738
877	03/18/2023	1103849		PRE ANNUAL SAFETY INSPECTION CHECK Completed pre annual inspection		241738

877	03/18/2023	1103884	reverse buzzer u/s	Replaced buzzer with new one	241738
877	03/18/2023	1103884	rust under body	Cleaned rust and painted under body	241738
877	03/18/2023	1103884	Mechanic entered - Body Other N/S/R rain gutter coming off	Drill and fit screws	241738
877	03/18/2023	1103884	BUZZER REVERSING 24V 102DB(NR72602)		241738
877	03/18/2023	1103884	hinge pins loose	Fit back hinge pins	241738
877	03/18/2023	1103884	body rivots missing	Drill out broken rivets and fit new rivets	241738
877	03/18/2023	1103884	Consumables		241738
877	03/18/2023	1103884	Mechanic entered - Air System Air_Leak Rear Two test port fi	Replaced both the fittings with new one	241738
877	03/03/2023	1100815		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O338787 carried out by Ben from cold drive	239698
877	03/03/2023	1100815	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O338787 Receiving #:356616 Date :2023-03-15 carry out 12 month a/c service as required	241263
877	03/01/2023	1100144	Drv entered - A/C Heating Not Cooling	traced and found earth wire to a/c compressor open circuit . repaired and secured earth wire . checked operation of a/c - all ok	239318
877	03/01/2023	1100107	Drv entered - Elec and Light Exterior Lights	n/s headlight n/wfit globe.	239318
877	03/01/2023	1100107	GLOBE 24V H4 75/70W HALOGEN		239318
877	02/21/2023	1098327	Mechanic entered - Body Other n/s/r seat very loose.	Removed rear seat frame completely and welded broken brackets re-fitted seat frame and re-fitted seat capsules x 03 and secured seat frame job completed	238233
877	02/20/2023	1097953	Consumables		237758
877	02/20/2023	1097953	Consumables		237758
877	02/20/2023	1097953	Consumables		237758
877	02/20/2023	1097953		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order all check ok	237758
877	02/20/2023	1097953	PAPER SPINNER FILTER OIL INSERT SCANIA L94		237758
877	02/20/2023	1097953	O-RING SPINNER FILTER SCANIA L94		237758
877	02/20/2023	1097953	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		237758
877	02/20/2023	1097953	OIL SAMPLE KIT AMPOL		237758
877	02/20/2023	1097953	FILTER OIL SCANIA K93 L94 1117285 2059778		237758
877	02/20/2023	1097953	FILTER FUEL SCANIA L94(1372444)		237758
877	02/18/2023	1097801	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	refer to work order 1097799	237758
877	02/18/2023	1097799	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	checked condition of a/c belt and clutch operation - ok road tested bus . could not fault a/c	237758
877	02/18/2023	1097799	passenger bell sometimes don't sound	checked operation of each pax bell button . alarm sounded every time . work ok	237758
877	02/18/2023	1097799	Engine Low Power	road tested bus for lacking power . could not fault	237758
877	02/18/2023	1097799	Driver Tablet Entered -Body - Rear_Door Operation Faulty	lubricated and adjusted rear passenger door . also checked operation of rear door on road test - all ok	237758
877	02/17/2023	1097602	ac doesn't cool the hot temperature properly	checked aircon clutch is on;took for a drive and found temp maintained at 20C	237758
877	02/09/2023	1095713	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	checked a/c belt - ok . checked a/c setting - 21 C . road tested bus . could not fault	236717
877	01/30/2023	1093382		VEHICLE SAFETY INSPECTION	1234975
877	01/30/2023	1093382		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1234975
877	01/30/2023	1093423	Mechanic entered - Engine Other engine belt idler bearing no	replaced engine belt idler bearing ok.	1234975
877	01/30/2023	1093423	PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087		1234975
877	01/30/2023	1093423	Consumables		1234975
877	01/30/2023	1093423	Mechanic entered - Elec and Light Other reversing buzzer not	repaired reversing buzzer wires ok.	1234975
877	01/30/2023	1093423	Mechanic entered - Body Other n/s/f under rust.	repaired n/s/f under rust ok.	1234975
877	01/30/2023	1093423	Mechanic entered - Body Other both middle seat loose.	repaired both middle seat ok.	1234975
877	01/30/2023	1093423	Mechanic entered - Body Other n/s/f step stripe missing.	repaired n/s/f step stripe ok.	1234975
877	01/30/2023	1093423	Mechanic entered - Body Other o/s/r bumper bolt loose.	tightened o/s/r bumper bolt ok.	1234975
877	01/30/2023	1093423	Consumables		1234975
877	01/28/2023	1093351	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	1234975
877	01/18/2023	1091675	Mechanic entered - A/C Heating Other a/c not working and che	checked operation of a/c . could not fault 18 C	123622
877	01/01/2023	1083872	- Part:R75EX-035 wheel arch ex	Creditor #:EA-CUS100 CUSTOM BUS AUSTRALIA P/O #:EA334716 Receiving #:352344 Date :2023-01-06	1232179
877	12/09/2022	1083872	DECAL PTV O - DRIVER REAR CORNER		1228122
877	12/06/2022	1085118	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S	carried out retorque as required	1227663
877	12/06/2022	1085118	Consumables		1227663
877	12/03/2022	1084566		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1227338
877	12/03/2022	1084566		VEHICLE SAFETY INSPECTION	1227338
877	12/03/2022	1084567	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retension done	1227338
877	12/03/2022	1084581	Mechanic entered - Wheels and Tyres Other O/S/R TYRES U/S BE	removed O/S/R TYRES replaced O/S/R TYRES OK.	1227338
877	12/03/2022	1084581	TYRE 295/80R22.5 RECAP		1227338
877	12/03/2022	1084567	Consumables		1227338
877	12/03/2022	1084581	Consumables		1227338
877	12/03/2022	1084588	Mechanic entered - Steering Other POWER STEERING WHEEL LOOSE	Adjusted POWER STEERING WHEEL OK.	1227338
877	12/03/2022	1084588	Mechanic entered - A/C Heating Other A/C BELT LOOSE.	Adjusted A/C BELT OK.	1227338
877	12/03/2022	1084596	Mechanic entered - Elec and Light Other doors nw after SHO f	checked and found two wires loose at RPD module. no proper terminals available; temporarily fixed terminals tested ok	1227338
877	12/03/2022	1084588	Mechanic entered - Elec and Light Other DASH SWITCH LIGHT NO	replaced DASH SWITCH GLOBE OK.	1227338
877	12/03/2022	1084588	Consumables		1227338
877	12/03/2022	1084596	Consumables		1227338
877	12/03/2022	1084588	Mechanic entered - Body Other BOTH MIDDLE SEAT TOP PINS OFF.	PUT IN MIDDLE SEAT TOP PINS OK.	1227338
877	12/03/2022	1084588	Consumables		1227338
877	12/03/2022	1084568	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s	removed O/S/R BRAKE SLACK ADJUST replaced O/S/R BRAKE SLACK ADJUST OK.	1227338
877	12/03/2022	1084568	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		1227338
877	12/01/2022	1084297	Mechanic entered - Wheels and Tyres Worn Pos 3 tyre worn	Removed and replaced worn pos 3 tyre and match pos 4 with new retreads	1226792
877	12/01/2022	1084297	TYRE 295/80R22.5 RECAP		1226792
877	12/01/2022	1084297	Consumables		1226792
877	12/01/2022	1083872	CONSUMABLE - DELIVERY CHARGE	Creditor #:EA-CUS100 CUSTOM BUS AUSTRALIA P/O #:EA333437 Receiving #:350799 Date :2022-12-07	1228122
877	12/01/2022	1083872	FG0730 REAR EXT LOWER CORNER	Creditor #:EA-CUS100 CUSTOM BUS AUSTRALIA P/O #:EA333437 Receiving #:350799 Date :2022-12-07	1228122
877	12/01/2022	1083872	FG1098 REAR BUMPER	Creditor #:EA-CUS100 CUSTOM BUS AUSTRALIA P/O #:EA333437 Receiving #:350799 Date :2022-12-07	1228122
877	11/11/2022	1080520	The CCTV does not load for us to view the footage.	checked all cameras working fine. removed HD and checked with OPS all good. no faults	1224116
877	11/09/2022	1080045	Mechanic entered - Body Other O/S/R bumper loose and reflect	Drilled 2 holes on O/S/R bumper and fitted 2x nut and bolts. Checked security all ok. Fitted new O/S/R red reflector. needs to go to bodyshop for correct repair	1223840
877	11/09/2022	1080045	REFLECTOR RED 94mm X 44mm		1223840
877	11/09/2022	1080045	Consumables		1223840
877	11/09/2022	1080045	Consumables		1223840
877	11/03/2022	1078869	one of the rear stop buttons does not activate buzzer only	replaced n/s/r pax switcho/s/middle pax switch all ok. after check all working ok. DASH BUZZER ALL WORKING OK.	1222971
877	11/03/2022	1078869	YELLOW/RED STOP SWITCH (20485)		1222971
877	11/03/2022	1078869	Consumables		1222971
877	10/28/2022	1078253	Consumables		1222658
877	10/28/2022	1078253	O/S Window requires Re Seal - 3rd window from front.	re-sealed three windows of os job completed	1222658
877	10/28/2022	1078165		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1222658
877	10/17/2022	1075808		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1220768
877	10/17/2022	1075808		SERVICE MOISTURE EJECTOR	1220768
877	10/17/2022	1075808	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1220768
877	10/13/2022	1075110	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	carried out campaign	1220066
877	10/10/2022	1074232	Mechanic entered - Body Other 1X crack in O/S/R Chassis Conn	assited chris	1219790
877	10/10/2022	1074232	Mechanic entered - Body Other 1X crack in O/S/R Chassis Conn	removed fuel tank and O/S/R Panel grinded channels into cracks ran beads through channels making multiple passes grinded welds painted refitted O/S/R Panel and associated wiring refitted fuel tank refitted fuel lines and wiring. refitted bumper bar.	1219790
877	10/10/2022	1074232	Consumables		1219790
877	10/06/2022	1073388		VEHICLE SAFETY INSPECTION	1219422
877	10/06/2022	1073388		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1219422
877	10/06/2022	1073586	Consumables		1219422
877	10/06/2022	1073586	Mechanic entered - Elec and Light Interior Lights Front Insi	removed light cover replaced blown fluoro checked for operation ok refitted cover.	1219422

877	10/06/2022	1073586	Mechanic entered - Dash Other Busminder Bracket cracking das	removed busminder and bracket removed cluster to allow access drilled 3 holes in dash fabricated steel piece for support fitted bracket holder and steel behind dash used new bolts and nyloc nut tightened and refitted busminder to bracket checked for movement ok refitted cluster.	1219422
877	10/06/2022	1073586	Consumables		1219422
877	10/06/2022	1073586	Mechanic entered - Body Other Front modesty panel loose.	drilled out loose rivets at base rivetted base of panel checked for movement ok.	1219422
877	10/06/2022	1073586	Consumables		1219422
877	10/06/2022	1073398	O-RING SPINNER FILTER SCANIA L94		1219422
877	10/06/2022	1073398	FILTER OIL SCANIA K93 L94 1117285 2059778		1219422
877	10/06/2022	1073398	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1219422
877	10/06/2022	1073398	OIL SAMPLE KIT AMPOL		1219422
877	10/06/2022	1073398	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1219422
877	10/06/2022	1073398	FILTER FUEL SCANIA L94(1372444)		1219422
877	10/06/2022	1073398	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1219422
877	10/06/2022	1073398	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)		1219422
877	10/06/2022	1073398	FILTER HYD COOLING FAN SCANIA SR3 4(1354074)		1219422
877	10/06/2022	1073398	FILTER WATER SCANIA SR3/SR4 0342988		1219422
877	10/06/2022	1073398	FILTER FUEL CHASSIS SCANIA L94 UB(1393640)(PSD470/1)		1219422
877	10/06/2022	1073398	FILTER AIR DRY MAN A91 MERC 0500LE OH1830 3090288		1219422
877	10/06/2022	1073398		CARRY OUT C SERVICE AS PER CHECK LIST CARRY OUT SERV AS PER WORK ORDER ALL CHECK OK	1219422
877	10/06/2022	1073398	318535 Latch Hook	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O330223 Receiving #-346826 Date :2022-10-06	1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219510
877	10/06/2022	1073398	Consumables		1219422
877	10/06/2022	1073398	Consumables		1219422
877	10/06/2022	1073398		CARRY OUT B SERVICE AS PER CHECK LIST CARRY OUT SERV AS PER WORK ORDER ALL CHECK OK	1219422
877	10/06/2022	1073398	Consumables		1219422
877	10/06/2022	1073398	Consumables		1219422
877	10/06/2022	1073398	Consumables		1219422
877	10/06/2022	1073398	Consumables		1219422
877	09/29/2022	1072079	Ops Entered - Fault - A/C Heating Not Heating - Route: 703	O329830 - repaired by cold drive cammy	1218663
877	09/29/2022	1072079	AIR CONDITIONING REPAIR	Creditor #-VB-COL004 COLD DRIVE PTY LTD P/O #-O329830 Receiving #-346655 Date :2022-10-04 rectify heaters not working as required	1219191
877	09/16/2022	1070329	V rod bushing crack.	Removed and fitted new V rod assembly.	1217177
877	09/16/2022	1070329	ASSEMBLY V STAY ASSEMBLY SCANIA L94UAB		1217177
877	09/15/2022	1069908	Consumables		1216868
877	09/15/2022	1069908	Mechanic entered - Elec and Light Other o/s head light crack	replaced o/s head light ok.	1216868
877	09/15/2022	1069908	HEADLIGHT INSET 178MM HI/LO		1216868
877	09/15/2022	1069908	Mechanic entered - Elec and Light Other battery terminal cra	replaced battery terminal ok.	1216868
877	09/15/2022	1069908	Mechanic entered - Elec and Light Other n/s/middle pax switc	replaced n/s/middle pax switch ok.	1216868
877	09/15/2022	1069908	YELLOW/RED STOP SWITCH (20485)		1216868
877	09/15/2022	1069908	Consumables		1216868
877	09/15/2022	1069908	Consumables		1216868
877	09/15/2022	1069908	Mechanic entered - Body Other o/s/r engine member bolt loose	tightened o/s/r engine member bolt ok.	1216868
877	09/15/2022	1069908	Mechanic entered - Body Other both middle seat top pins off.	put in both middle seat top pins ok.	1216868
877	09/15/2022	1069908	SEAT BACK SINGLE CEN CVR CA		1216868
877	09/15/2022	1069908	Mechanic entered - Body Other n/s/f modesty panel loose.	replaced n/s/f modesty panel ok.	1216868
877	09/15/2022	1069908	Mechanic entered - Body Other n/s/r seat back base missing.	replaced n/s/r seat back basebottom seat base clip ok.	1216868
877	09/15/2022	1069908	CENTRA CUSHION CLIP LH		1216868
877	09/15/2022	1069908	CENTRA CUSHION CLIP RH		1216868
877	09/15/2022	1069908	Consumables		1216868
877	09/15/2022	1069842	Consumables		1216868
877	09/15/2022	1069842	Consumables		1216868
877	09/15/2022	1069842		CARRY OUT B SERVICE AS PER CHECK LIST	1216868
877	09/15/2022	1069842	FILTER OIL SCANIA K93 L94(1117285)(2059778)		1216868
877	09/15/2022	1069842	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1216868
877	09/15/2022	1069842	O-RING SPINNER FILTER SCANIA L94		1216868
877	09/15/2022	1069842	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1216868
877	09/15/2022	1069842	OIL SAMPLE KIT AMPOL		1216868
877	09/15/2022	1069842	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1216868
877	09/15/2022	1069842	FILTER FUEL SCANIA L94(1372444)		1216868
877	09/15/2022	1069842	Consumables		1216868
877	09/15/2022	1069842	Consumables		1216868
877	09/15/2022	1069842	Consumables		1216868
877	09/01/2022	1062407	Accident#53911 OFFSIDE - Front indicator broken	fit new blinker unit.	1214684
877	09/01/2022	1066613	Accident # 53911 - o/s/f damage	bus sent to bodyshop for 3rd party accident repairs .	1214684
877	09/01/2022	1066671	TPAF - O/S/F CORNER PREPARE AND PAINT - REPLACE HINGE VINYL	mop inside put on wheel nut spotters	1214684
877	08/31/2022	1066671	TPAF - O/S/F CORNER PREPARE AND PAINT - REPLACE HINGE VINYL	prep and painted o/s/f corner fit new piano hinge vinyl to o/s/f panel polish o/s/f painted wheels.	1214684
877	08/30/2022	1066552		TRANSMISSION CHECK AS PER CHECK LIST	1214684
877	08/30/2022	1066671	TPAF - O/S/F CORNER PREPARE AND PAINT - REPLACE HINGE VINYL	prep and painted o/s/f corner fit new piano hinge vinyl to o/s/f panel polish o/s/f painted wheels.	1214684
877	08/29/2022	1066443		complete	1214684
877	08/27/2022	1066286	Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	1214184
877	08/24/2022	1065582	Consumables		1213939
877	08/24/2022	1065582	Consumables		1213939
877	08/24/2022	1065582	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Retensioned O/S/R wheel nuts.	1213939
877	08/23/2022	1065124	SLACK ADJUSTER AUTO-REAR N/SIDE SERIES 4(2009819)		1213918
877	08/23/2022	1065124		Tried ajusting both rear brakes found n/s/r slack adjuster jamming removed and replaced n/s/r slack adjuster adjusted both rear brakes road tested found okay - Job done -Sadid	1213918
877	08/23/2022	1065124	Brakes Foot_Brakes Noisy rear low	commercial brakes Removed o/s/r wheels and drums found brake lining ok fit drum and wheels back	1213918
877	08/23/2022	1065124	Brakes Foot_Brakes Noisy rear low	Assisting	1213918
877	08/18/2022	1064355	Consumables		1213219
877	08/18/2022	1064355	Consumables		1213219
877	08/18/2022	1064355	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe.	1213219
877	08/10/2022	1062407	INDICATOR LIGHT SIDE R/H		1211919
877	08/08/2022	1061717		VEHICLE SAFETY INSPECTION	1211144
877	08/08/2022	1061717		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1211144
877	08/08/2022	1061747	Mechanic entered - Suspension Other both rear D rubber u/s	removed both rear D rubberreplaced both rear D rubber ok.	1211144
877	08/08/2022	1061747	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)		1211144
877	08/08/2022	1061747	Mechanic entered - Steering Other steering wheel loose.	Adjusted power steering wheel ok.	1211144
877	08/08/2022	1061747	Mechanic entered - Body Other n/s/fn/s/r modesty panel all	repaired n/s/fn/s/r modesty panel all ok.	1211144
877	08/08/2022	1061747	Mechanic entered - Body Other n/so/s/middle seat top pins o	put in n/so/s middle seat top pins ok.	1211144
877	08/08/2022	1061747	Mechanic entered - Body Other n/s/r staunchion pole loose.	repaired n/s/r staunchion pole ok.	1211144
877	08/08/2022	1061747	Consumables		1211144
877	08/08/2022	1061747	Consumables		1211144

877	08/03/2022	1060762	Mechanic entered - Body Other wiper fast speed n/w.	could not fault.	
877	08/03/2022	1060762	Consumables		
877	08/03/2022	1060762	Consumables		
877	08/02/2022	1060745	Mechanic entered - Fluid Leaks Rear of bus Hydraulic tank sw	Top up hydraulic oil	
877	07/22/2022	1058551	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O325471 Receiving #:341788 Date :2022-07-25 glass film audit 721 - stage 4	
877	07/21/2022	1058551	Vandalism Vandalism/ Graffiti Interior	O325471 - carried out by glass protech	
877	07/19/2022	1058006	Ops Entered - Fault - A/C Heating Demister Not Heating - R	PO#: O325295 cold drive BEN	
877	07/19/2022	1058006	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O325295 Receiving #:341703 Date :2022-07-22 carry out AC-B service as required	
877	07/07/2022	1055973	LAMP LED STOP/TAIL		
877	07/07/2022	1055973	Mechanic entered - Elec and Light Exterior Lights N/S/R uppe	Removed and fitted new LED lamp.	
877	07/07/2022	1055973	Consumables		
877	07/07/2022	1055973	Consumables		
877	07/04/2022	1055057	Mechanic entered - Elec and Light Other cant select gears.	could not fault.	
877	07/04/2022	1055057	Consumables		
877	07/04/2022	1055057	Consumables		
877	07/02/2022	1055168	Vandalism Vandalism/ Graffiti Interior	carried out vandalisem painting as required	
877	07/01/2022	1040022	TPAF Accident#: 53117 - Prep and paint Middle centre bumper		
877	06/29/2022	1054328	hard to select gears	lube selectorok.	
877	06/29/2022	1040022	Service - Accident		
877	06/27/2022	1053793	BELT MICRO V SERPENT 8 RIB 2135mm LNG(1389048)		
877	06/27/2022	1053793	Mechanic entered - Engine Other engine belt u/s.	replaced engine belt after engine belt offbecause removed bus number is 1194 engine idler bearing put in bus number is 877 after check all ok. bus number is 877 removed engine idler bearing put back bus number is1194 ok.	
877	06/24/2022	1053741	Mechanic entered - Engine Belts_Loose Noisy Missing WORN	Replaced main engine belt and tensioner	
877	06/24/2022	1053741	TENSIONER BELT SCANIA SR4(1859654)(1503113)		
877	06/24/2022	1053741	BELT MICRO V SERPENT 8 RIB 2135mm LNG(1389048)		
877	06/22/2022	1053301	Mechanic entered - Elec and Light Indicators Not Working O/S	Replaced globe	
877	06/22/2022	1053301	Consumables		
877	06/22/2022	1053301	Consumables		
877	06/20/2022	1052621		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
877	06/20/2022	1052621		VEHICLE SAFETY INSPECTION	
877	06/20/2022	1052638	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok.	
877	06/20/2022	1052638	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		
877	06/20/2022	1052638	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok	
877	06/20/2022	1052638	LAMP HEADLAMP MK3 SCANIA L94 K230		
877	06/20/2022	1052638	Mechanic entered - Elec and Light Other n/s head light u/s.	replaced n/s head light ok.	
877	06/20/2022	1052638	Consumables		
877	06/20/2022	1052638	Consumables		
877	06/20/2022	1052638	Mechanic entered - Body Other middle seat top pins off.	put in middle seat top pins ok.	
877	06/20/2022	1052638	Consumables		
877	06/20/2022	1052638	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s	removed o/s/r brake slack adjust replaced o/s/r brake slack adjust ok.	
877	06/20/2022	1052638	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		
877	05/20/2022	1047426	Mechanic entered - Elec and Light Other pax switches broken	removed old switches and replaced with new one all tested ok	
877	05/20/2022	1047426	YELLOW/RED STOP SWITCH (20485)		
877	05/20/2022	1047426	Consumables		
877	05/20/2022	1047426	Consumables		
877	05/20/2022	1047426	Mechanic entered - Body Other fromt stauchion pole loose	removed and re rivetted front stauchion pole all checked ok	
877	05/20/2022	1047426	Consumables		
877	05/20/2022	1047354	O-RING SPINNER FILTER SCANIA L94		
877	05/20/2022	1047354	PAPER SPINNER FILTER OIL INSERT SCANIA L94		
877	05/20/2022	1047354		CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order all check ok	
877	05/20/2022	1047354	FILTER OIL SCANIA K93 L94 1117285 2059778		
877	05/20/2022	1047354	OIL SAMPLE KIT AMPOL		
877	05/20/2022	1047354	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		
877	05/20/2022	1047354	FILTER FUEL SCANIA L94 1372444		
877	05/20/2022	1047354	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		
877	05/20/2022	1047354	Consumables		
877	05/20/2022	1047354	Consumables		
877	05/20/2022	1047354	Consumables		
877	05/20/2022	1047354	Consumables		
877	05/20/2022	1047354	Consumables		
877	05/16/2022	1044396	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O320899 Receiving #:337232 Date :2022-05-16 carry out ASI as required	
877	05/05/2022	1044396		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
877	05/05/2022	1044396		VEHICLE SAFETY INSPECTION	
877	05/05/2022	1044396		ANNUAL SAFETY INSPECTION SERIAL #RSI O39769 PO O320899 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	
877	04/28/2022	1042882	Mechanic entered - Wheels and Tyres Wheel Nut Retension Both	Retorqued both front tyres to 650nm.	
877	04/28/2022	1042882	Consumables		
877	04/28/2022	1042882	Consumables		
877	04/27/2022	1042500		VEHICLE SAFETY INSPECTION	
877	04/27/2022	1042500		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
877	04/27/2022	1042575	Mechanic entered - Wipers and Washers Other O/S wiper not cl	Fitted new insert.	
877	04/27/2022	1042575	WIPER REFILL 1000mm MULTI FIT (TRP1000)		
877	04/27/2022	1042571	Mechanic entered - Wheels and Tyres Other Swap front wheels	Swapped front wheels around for sidewall wear	
877	04/27/2022	1042571	Consumables		
877	04/27/2022	1042571	Consumables		
877	04/27/2022	1042500	BATTERY 1030CCA POS ON LHS(EMFN150L)		
877	04/27/2022	1042500	Mechanic entered - Elec and Light Other Batteries needs rep	Removed and fitted new batteries. Cleaned terminals.	
877	04/27/2022	1042500	Consumables		
877	04/27/2022	1042500	Consumables		
877	04/27/2022	1042572	Mechanic entered - Air System Other Front door outside emerg	Fitted new button.	
877	04/27/2022	1042572	SWITCH EMERGENCY PUSH BUTTON RED HINO FD240 55CXXX0282		
877	04/27/2022	1042500	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	Removed stickers.	
877	04/21/2022	1041589	Mechanic entered - Elec and Light Exterior Lights O/S/F lowe	Fited new park light globe.	
877	04/21/2022	1041589	Consumables		
877	04/21/2022	1041589	Consumables		
877	04/20/2022	1041279		PRE ANNUAL SAFETY INSPECTION CHECK	
877	04/20/2022	1041279		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	
877	04/20/2022	1041115	Mechanic entered - Elec and Light Flat Batteries rebooked fo	tested batteries ok	
877	04/20/2022	1041115	Consumables		
877	04/20/2022	1041115	Consumables		
877	04/19/2022	1040871	Mechanic entered - Elec and Light Flat Batteries	jump started and rebooked for battery test	
877	04/19/2022	1040871	Consumables		
877	04/19/2022	1040871	Consumables		
877	04/04/2022	1038690	Mechanic entered - Elec and Light Flat Batteries	JUMP STARTMASTER AND SALOON LIGHTS LEFT ON.	
877	04/04/2022	1038690	Consumables		

877	04/04/2022	1038690	Consumables			1191234
877	04/02/2022	1038801	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required		1191517
877	04/01/2022	1035065	AIR CONDITIONING REPAIR	Creditor #:\VB-COLO04 COLD DRIVE PTY LTD P/O #:\O317800 Receiving #:\335531 Date :2022-04-21 carry out 24 month service as required		1193305
877	03/30/2022	1038044	Consumables			1191026
877	03/30/2022	1038044	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced headlight and park light globe checked all ok.		1191026
877	03/30/2022	1038044	GLOBE 24V H4 75/70W HALOGEN			1191026
877	03/30/2022	1038044	Consumables			1191026
877	03/30/2022	1038045	Consumables			1191026
877	03/30/2022	1038045	Mechanic entered - Body Other Wires covering desto panel.	Opened desto panel and moved wires behind desto. Checked operation all ok.		1191026
877	03/30/2022	1038045	Consumables			1191026
877	03/26/2022	1037324				1190457
877	03/23/2022	1036590	A/C Heating Air Conditioning evap motors us	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list		1189891
877	03/23/2022	1036590	MOUNT A/C COMPRESSOR LARGE DENSO	done by cold drive cammy po 0318273		1189891
877	03/22/2022	1036590	AIR CONDITIONING REPAIR			1190770
877	03/16/2022	1035315	Mechanic entered - Elec and Light Other alarm on	Creditor #:\VB-COLO04 COLD DRIVE PTY LTD P/O #:\O318273 Receiving #:\333947 Date :2022-03-28 replace evap motors		1189704
877	03/16/2022	1035315	EMERGENCY HAMMER KIT W/WIRE	replaced rear emg hammer and checked ok		1189704
877	03/16/2022	1035315	EMERGENCY HAMMER BRACKET WITH SENSOR			1189704
877	03/16/2022	1035315	Consumables			1189704
877	03/16/2022	1035315	Consumables			1189704
877	03/15/2022	1035065	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	- O317800 carried out by cammy cold drive		1188697
877	03/15/2022	1035065		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O317800 carried out by cammy cold drive		1188697
877	03/15/2022	1035065		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O317800 carried out by cammy cold drive		1188697
877	03/09/2022	1034053	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE	complete		1188083
877	02/25/2022	1031856		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1186110
877	02/25/2022	1031856		complete		1186110
877	02/24/2022	1031405	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	complete		1184652
877	02/23/2022	1030795	Consumables			1184652
877	02/23/2022	1030795	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s/	retorque n/s/r wheel nuts.		1184652
877	02/23/2022	1030795	Consumables			1184652
877	02/22/2022	1030624		TRANSMISSION CHECK AS PER CHECK LIST		1184652
877	02/22/2022	1030450		VEHICLE SAFETY INSPECTION		1184652
877	02/22/2022	1030450		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1184652
877	02/22/2022	1030520	Consumables			1184652
877	02/22/2022	1030520	Mechanic entered - Wheels and Tyres Other n/s/r tyres u/s.	removed n/s/r tyres replaced n/s/r tyres ok.		1184652
877	02/22/2022	1030520	TYRE 295/80R22.5 RECAP			1184652
877	02/22/2022	1030520	Consumables			1184652
877	02/22/2022	1030513	Mechanic entered - Suspension Other both front D rubber u/	removed both front D rubber replaced both front D rubber ok.		1184652
877	02/22/2022	1030513	BUSH FRONT SWAY BAR SCANIA K230UB 40mm(1919010)			1184652
877	02/22/2022	1030513	Mechanic entered - Fluid Leaks Other engine fan motor pipe f	removed fuel cooler hosetightened engine fan motor pipe fittingput in fuel cooler hosetightened fuel cooler hose clamp ok.		1184652
877	02/22/2022	1030513	Consumables			1184652
877	02/22/2022	1030513	Mechanic entered - Body Other both middle seat top pins off.	put in both middle seat top pins ok.		1184652
877	02/22/2022	1030513	Mechanic entered - Body Other both middle seat loose.	repaired both middle seat ok.		1184652
877	02/22/2022	1030513	Consumables			1184652
877	02/21/2022	1030007	Consumables			1184652
877	02/21/2022	1030007	Mechanic entered - Elec and Light Other O/S/R TOP INDICATOR	replaced INDICATOR LIGHT OK.		1184652
877	02/21/2022	1030007	LAMP INDICATOR LED			1184652
877	02/21/2022	1030007	Consumables			1184652
877	02/07/2022	1027256	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	A/C compressor earth wire not connected. Wire broken from earth terminal. Stripped wire removed earth terminal crimped new terminal and refitted wire. Let the bus run on idle to check A/C. All ok.		1182530
877	02/07/2022	1027256	Drv entered - A/C Heating Not Cooling	Double entery by driver.		1182530
877	01/24/2022	1021758	Direct Purchase - BODYWORK	Creditor #:\VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:\O313923 Receiving #:\330153 Date :2022-01-27 mobile mick to resecure rear passenger seat as required		1180131
877	01/24/2022	1021758	Consumables			1180131
877	01/22/2022	1024285	Mechanic entered - Elec and Light Other n/s/f park light not	replaced n/s/f park light globe ok.		1179174
877	01/22/2022	1024285	Mechanic entered - Elec and Light Other n/s/r reversing ligh	replaced n/s/r reversing light globe ok.		1179174
877	01/22/2022	1024285	Mechanic entered - Elec and Light Other dash R.P.M light not	replaced dash R.P.M light globe ok.		1179174
877	01/22/2022	1024285	Mechanic entered - Elec and Light Other n/s/r saloon light n	repaired n/s/r saloon light wires ok.		1179174
877	01/22/2022	1024285	Consumables			1179174
877	01/22/2022	1024285	Consumables			1179174
877	01/22/2022	1024285	Mechanic entered - Body Other driver seat back top panel loo	replaced driver seat back top panel screws ok.		1179174
877	01/22/2022	1024285	Mechanic entered - Body Other driver seat belt buckle u/s.	replaced driver seat belt buckle ok.		1179174
877	01/22/2022	1024285	SEAT BELT BUCKLE			1179174
877	01/22/2022	1024285	Consumables			1179174
877	01/22/2022	1024233	OIL SAMPLE KIT AMPOL			1179174
877	01/22/2022	1024233		CARRY OUT B SERVICE AS PER CHECK LIST		1179174
877	01/22/2022	1024233	PAPER SPINNER FILTER OIL INSERT SCANIA L94			1179174
877	01/22/2022	1024233	O-RING LARGE SPINNER FILTER SCANIA 40A7703			1179174
877	01/22/2022	1024233	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701			1179174
877	01/22/2022	1024233	FILTER OIL SCANIA S4 & K			1179174
877	01/22/2022	1024233	FILTER FUEL SCANIA SR4(1372444)			1179174
877	01/22/2022	1024233	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			1179174
877	01/22/2022	1024233	Consumables			1179174
877	01/22/2022	1024233	Consumables			1179174
877	01/22/2022	1024233	Consumables			1179174
877	01/22/2022	1024233	Consumables			1179174
877	01/22/2022	1024233	Consumables			1179174
877	01/18/2022	1023422	Mechanic entered - Suspension Other front sway barD rubb	repaired on w/o 1021447		1178520
877	01/08/2022	1021758	Mechanic entered - Body Other n/s/r all seat loosebody sho			1176746
877	01/07/2022	1021321		VEHICLE SAFETY INSPECTION		1176746
877	01/07/2022	1021321		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1176746
877	01/07/2022	1021447	front sway bar u/s	replace front sway bar .		1176746
877	01/07/2022	1021447	Mechanic entered - Suspension Other front sway bar u/sorde			1176746
877	01/07/2022	1021447	489789 Torsion Bar			1177478
877	01/07/2022	1021438	Mechanic entered - Steering Other steering wheel loose.	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:\O313876 Receiving #:\329391 Date :2022-01-13		1176746
877	01/07/2022	1021438	Mechanic entered - Fluid Leaks Other trans top heater hose c	ADJUSTED STEERING WHEEL OK.		1176746
877	01/07/2022	1021438	Mechanic entered - Elec and Light Other driver seat switch b	tightened trans top heater hose clamp ok.		1176746
877	01/07/2022	1021438	Consumables	removed bus number is 570 driver seat switchput back 877 ok.		1176746
877	01/07/2022	1021438	Consumables			1176746
877	01/07/2022	1021438	Mechanic entered - Body Other n/s/f modesty panel loose.	repaired N/S/F MODESTY PANEL OK.		1176746
877	01/07/2022	1021438	Mechanic entered - Body Other middle seat top pins off.	put in both middle seat top pins ok.		1176746
877	01/07/2022	1021438	Mechanic entered - Body Other o/s/r seat back base off.	repaired o/s/r seat back base ok.		1176746
877	01/07/2022	1021438	Mechanic entered - Body Other driver back seat adjust handle	removed bus number is 570 driver back seat adjust handleput back bus number is 877 ok.		1176746
877	01/07/2022	1021438	Consumables			1176746
877	12/20/2021	1018730	Mechanic entered - Elec and Light Other o/s/f top park light	replaced o/s/f top park light globe ok.		1172771

877	12/20/2021	1018730	Consumables																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															</
-----	------------	---------	-------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

877	09/01/2021	993496		cleaned trans inner housing cleaned flywheel gear all cleaned sump gasket from to the engine block gasket replaced engine oil spinner kits cleaned engine sump check engine ok. cleaned bell housing gasket to engine block gasket ok.	1151612
877	09/01/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	engine spinner housing gasket off trans wires cover broken repaired trans wires cover ok. replaced sump pluge washer put in engine belt replaced ait comperssor coolant hose cleaned all boltsnuts	1151612
877	09/01/2021	993496	HOSE G/BOX COOLING 160 DEG 1 7/8 X 2 1/4 1451072 461674	cleaned	1151612
877	09/01/2021	993496	HOSE G/BOX COOLING SCANIA L94 0485995	cleaned	1151612
877	09/01/2021	993496		replaced engine sump gasket replaced engine oil dipstick filler tube put in engine top coolant hose checked engine ok.	1151612
877	09/01/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	replaced bell housing gasketretorqued bell housing bolts 90Nm replaced rear crank sealretorqued flywheel bolts 180Nm put in flywheelengine speed sensor maked engine stand ok.	1151612
877	09/01/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	put in engine sumptightened all sump bolts 25Nm engine timing cover to engine sump oil pipetightened oil pipe fitting ok. retorqued sump pluge 80Nm tightened spinner housing nutstightened spinner oil pipe fitting tightened bell housing top fuel pipe bracket bolts ok.	1151612
877	09/01/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	put in engine start motortightened engine start motor nutsput in atart motor wires put in engine start motor key wirestightened start motor key wires screw ok.	1151612
877	09/01/2021	993496		put in transmissiontightened transmission housing all nuts tightened torque convert boltspu	1151612
877	09/01/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	put in trans engine mount both brackettightened both trans engine mount bracket bolts trans all put back wireshose trans all wires clampstightened fuel pipe clamp replaced trans coolant hose x3tightened trans coolant pipe bracket bolts put in coolantengine oil ok	1151612
877	09/01/2021	993496		put in driver shafttightened driver shaft bolts tightened driver clamp road tested all okcheck engine oilcoolant all ok.temp is 80 ok	1151612
877	08/26/2021	993496	SEAL RR CRANKSHAFT DC9 03B01	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O305538 Receiving #:320699 Date :2021-09-02	1151908
877	08/26/2021	993496	GASKET FLYWHEEL HSG SCANIA L	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O305538 Receiving #:320699 Date :2021-09-02	1151908
877	08/25/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	turbo from to the oil return line cylinder block put in pipetightened pipe clamp put in air comperssor return pipe tightened hose clamp put in bottom coolsnt hose ok.	1151612
877	08/24/2021	993496	HOSE TO TOP COMPRESSOR L94UB(205118)		1151612
877	08/24/2021	993496		cleaned engine oil cooler gasket removed water pump replaced water pump replaced engine oil cooler gasket kits put in engine oil coolertightened oil cooler all bolts replaced put in oil cooler from air comperssor hose tightened air comperssor hose clamp.	1151612
877	08/24/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	removed engine bottom coolant hose removed engine oil cooler hose removed engine cooler oil pipe removed oil cooler from air comperssor pipehose removed oil cooler	1151612
877	08/24/2021	970905	GASKET OIL COOLER SCANIA L94 UAB 40A2629		1151612
877	08/24/2021	970905	GASKET OIL COOLER SCANIA L94 UAB 40A2628		1151612
877	08/24/2021	970905	GASKET OIL COOLER SCANIA L94 UAB 40A2627		1151612
877	08/24/2021	970905	Consumables		1151612
877	08/23/2021	993496	HOSE TRANSMISSION COOLING HOSE		1151612
877	08/23/2021	993496	GASKET SPINNER FILTER HOUSING (1116355)		1151612
877	08/23/2021	993496	GASKET SUMP SCANIA L94(551450)(1412666)		1151612
877	08/23/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	removed ENGINE SPEEDO FLYWHEEL SENSOR. removed START MOTOR removed engine spinner case removed engine sump removed bell housing	1151612
877	08/23/2021	970905	STRUT GAS STAY 250Nm 430mm LONG		1151612
877	08/20/2021	993362	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	RETORQUED BOTH FRONT WHEEL NUTS OK.	1151612
877	08/20/2021	993362	Consumables		1151612
877	08/20/2021	993496	Mechanic entered - Fluid Leaks Other just engine oil leaks.	removed trans wires removed transmission driver shaft removed driver shaft clamp removed transmission bracket bolts removed all transmission bolts drain coolant removed trans all coolant hose removed transmission removed flywheel.	1151612
877	08/20/2021	993496		removed battery wire.	1151612
877	08/20/2021	993573		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1151612
877	08/20/2021	993573		complete	1151612
877	08/19/2021	993015		VEHICLE SAFETY INSPECTION	1151612
877	08/19/2021	993015		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1151612
877	08/19/2021	993090	Mechanic entered - Wheels and Tyres Other both front tyres u	removed both front tyres replaced both front tyres ok.	1151612
877	08/19/2021	993090	TYRE 295/80R22.5 NEW		1151612
877	08/19/2021	993090	Consumables		1151612
877	08/19/2021	993090	Mechanic entered - Suspension Other both rear D rubber u/s	removed both rear D rubber replaced both rear D rubber ok.	1151612
877	08/19/2021	993090	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok.	1151612
877	08/19/2021	993090	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		1151612
877	08/19/2021	993090	Mechanic entered - Body Other both middle seat loose.	repaired both middle seat ok.	1151612
877	08/19/2021	993090	Mechanic entered - Body Other both middle seat top pins off.	put in both middle seat top pins ok.	1151612
877	08/19/2021	993090	Mechanic entered - Body Other driver door loose.	repaired driver door ok.	1151612
877	08/19/2021	993090	Consumables		1151612
877	08/16/2021	992392	Mechanic entered - Body Rear_Door Operation Faulty Rear Doo	O304945 - repaired by ash from benware - part that was replaced was supplied by oakleigh workshop	1150921
877	08/16/2021	992392	Consumables		1151908
877	08/13/2021	992392	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O304945 Receiving #:320025 Date :2021-08-25 rectify rear passenger door sensive edge not working	1151908
877	08/05/2021	990092	Brakes (None) not sensitive - PTI	Checked brakes found linings to be ok adjusted all 4 wheels found O/S/R Slack adjuster not tightening properly replaced slack adjuster and adjusted brakes Roadtested and brake tested ok	1149103
877	08/05/2021	990092	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		1149103
877	07/30/2021	988941	Drv entered - Brakes Foot_Brakes Pulling	adjust all brakesroad and brake testok.	1147987
877	07/29/2021	988835	Mechanic entered - Body Drivers Seat Belt buckle tight again	Removed buckle and fit longer bolt with spacer	1147987
877	07/29/2021	988835	Consumables		1147987
877	07/27/2021	988012	GLOBE 24V H4 75/70W HALOGEN		1147397
877	07/27/2021	988012	Mechanic entered - Elec and Light Other o/s/f bottom park li	replaced o/s/f bottom park light globe ok replaced n/s head light globe ok.	1147397
877	07/27/2021	988012	Consumables		1147397
877	07/15/2021	984482	Vandalism/ Graffiti Interior G	Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O302474 Receiving #:317482 Date :2021-07-22 bus 877 Completed 5/7/21	1146687
877	07/08/2021	984482	Vandalism/ Graffiti Interior Graffiti film Audit 509	O302474 - completed by glass protect	1143166
877	07/08/2021	984279	VALVE FOOT SCANIA SR3 & SR4 (0469052) (571136)		1143166
877	07/08/2021	984279	Ops Entered - Fault - Brakes Foot_Brakes Leaking Air - Rout	removed U/S Foot brake Valve fitted block offs to new Foot Brake Valve fitted assembly checked for leaks Roadtested.	1143166
877	07/08/2021	984279	Ops Entered - Fault - Brakes Foot_Brakes Leaking Air - Rout	drilled a hole on foot valve to adjust retarder severity	1143166
877	07/08/2021	984279	Ops Entered - Fault - Brakes Foot_Brakes Leaking Air - Rout	adjusted all brake liningsbrake tested okcheck air leaksfoot brake air leaks. front n/s brake linings is 40%o/s 30% both rear 20%	1143166
877	07/07/2021	984055	Mechanic entered - Body Other dash is very loose	repaired dash all ok	1143166
877	07/07/2021	984055	Consumables		1143166
877	07/05/2021	983523		VEHICLE SAFETY INSPECTION Carried out safety inspection	1143166
877	07/05/2021	983523		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1143166
877	07/05/2021	983606	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	replaced wiper blades checked ok	1143166
877	07/05/2021	983606	WIPER REFILL 1000mm MULTI FIT (TRP1000)		1143166
877	07/05/2021	983606	Mechanic entered - Engine Other Belt Tensioner U/S	Replaced Belt Tensioner	1143166
877	07/05/2021	983606	BELT TENSIONER SCANIA N310UA 2197005 1859657		1143166
877	07/05/2021	983606	Mechanic entered - Engine Other Idler Pulley U/S	replaced idler pulley	1143166
877	07/05/2021	983606	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		1143166
877	07/05/2021	983606	Mechanic entered - Dash Dash_Lights Not Working Speedo Light	removed speedo replaced 2 x blown globes checked ok refitted speedo.	1143166
877	07/05/2021	983606	Consumables		1143166
877	07/05/2021	983646	Mechanic entered - Body Other n/s/r passenger side windows	checked window leak . could not fault . maybe incorrect window has been listed	1143166
877	07/05/2021	983606	Mechanic entered - Body Other N/S/F Myki Bracket Loose	drilled out loose rivets re rivetted bracket checked for movement all ok	1143166
877	07/05/2021	983606	Mechanic entered - Body Other N/S/F Modesty Panel Loose	rivets missing at bottom of modesty panel re rivetted bracket checked for movement all ok	1143166
877	07/05/2021	983606	Consumables		1143166
877	07/05/2021	983646	Consumables		1143166
877	07/05/2021	983606	Mechanic entered - Air System Air_Leak Rear O/S/R/F Air Bag	removed inner wheel arch guard checked fitting found fitting to be loose tightened fitting aired up bus and checked for leaks all ok	1143166
877	07/02/2021	983239	Wheels and Tyres - o/s/r retorqued required	retorqued o/s/r wheel nuts.	1143166
877	07/02/2021	983239	Consumables		1143166
877	07/01/2021	983159	pos 6 tyre tread low	replaced pos 6 tyre with 2nd hand run out tyre . tensioned wheels nuts all okay	1143166
877	07/01/2021	983159	Consumables		1143166
877	07/01/2021	983158	Suspension - o/s/r front air bag u/s	replaced n/s/r front air bag	1143166
877	07/01/2021	983158	Ops Entered - Fault - Air System Air Not Building_Up - Rou	double entry	1143166
877	07/01/2021	983158	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		1143166
877	06/26/2021	982188	reverse buzzer needs securing	resecurd reverse buzzer. checked operation . all okay	1141819
877	06/26/2021	982188	Consumables		1141819
877	06/09/2021	978758	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O300553 Receiving #:314646 Date :2021-06-10 rectify odometer not working as required	1139765
877	06/09/2021	978758	Consumables		1139765
877	06/08/2021	978758	Dash - odometer not working	brought back from Lonsdale	1139106
877	06/07/2021	978758	Dash - odometer not working	O300553 - bus sent to lonsdale for odometer not working	1139106
877	06/05/2021	978654	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	1139106

877	06/04/2021	978405	Mechanic entered - Vandalism Vandalism/ Graffiti Interior ba	clean graffiti all check ok	1139106
877	06/04/2021	978405	Mechanic entered - A/C Heating Other compressor pulley cove	retighten loose screw all check ok	1139106
877	06/04/2021	978405	Mechanic entered - Elec and Light Other o/s/r reflector crac	fitted reflector all check ok	1139106
877	06/04/2021	978405	REFLECTOR AMBER 94mm X 44MM (84051)		1139106
877	06/04/2021	978405	Mechanic entered - Elec and Light Indicators Not Working sta	fitted stalk allo check ok	1139106
877	06/04/2021	978405	SWITCH INDICATOR SCANIA L94 1402448		1139106
877	06/04/2021	978405	YELLOW/RED STOP SWITCH (20485)		1139106
877	06/04/2021	978405	Mechanic entered - Elec and Light Next Stop Button o/s/r	supply new switch all check ok	1139106
877	06/04/2021	978405	Consumables		1139106
877	06/04/2021	978405	Mechanic entered - Body Other n/s/r side hatch panel loose	resecure panel with rivet all check ok	1139106
877	06/04/2021	978405	Mechanic entered - Body Other front modesty panel mising riv	fitted rivet all check ok	1139106
877	06/04/2021	978405	Consumables		1139106
877	06/04/2021	978332		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order all check ok	1139106
877	06/04/2021	978332	FILTER OIL SCANIA S4 & K		1139106
877	06/04/2021	978332	SPINNER FILTER KIT ALL SCANIA		1139106
877	06/04/2021	978332	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1139106
877	06/04/2021	978332	OIL SAMPLE KIT CALTEX		1139106
877	06/04/2021	978332	FILTER FUEL FILTER SCANIA SR4 (1372444)		1139106
877	06/04/2021	978332	Consumables		1139106
877	06/04/2021	978332	Consumables		1139106
877	05/06/2021	972504	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorque all rear wheel nuts.	1133860
877	05/06/2021	972504	Consumables		1133860
877	05/05/2021	972265		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1133860
877	05/05/2021	972265		VEHICLE SAFETY INSPECTION	1133860
877	05/05/2021	972265		ANNUAL SAFETY INSPECTION SERIAL # ____L 390186 GREEN SHEET ____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 CARRIED OUT BY FLEET CHECK 0298292	1133860
877	05/05/2021	972265	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O298292 Receiving #:312004 Date :2021-05-06 CARRY OUT ASI AS REQUIRED	1134102
877	05/05/2021	972362	Suspension - rear front air bags cracked x 2	removed both n/s/r/fo/s/r/f air bags x2 replaced both n/s/r/fo/s/r/f air bags ok road tested all ok	1133860
877	05/05/2021	972362	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		1133860
877	04/29/2021	971401	Mechanic entered - Suspension Soft O/S/F AIR BAG LEAKING	Replaced leaking air bag with new one	1133447
877	04/29/2021	971401	AIRBAG FRT 14MM SCANIA K230UB 1726239 2809671		1133447
877	04/29/2021	971208	Mechanic entered - Elec and Light Other o/s/middle pax switc	replaced o/s/middle pax switch ok	1133447
877	04/29/2021	971208	SWITCH- STOP-YELLOW (62628)		1133447
877	04/29/2021	971208	Mechanic entered - Elec and Light Other driver seat top ligh	replaced driver seat top light lens ok	1133447
877	04/29/2021	971208	CLEAR LENS		1133447
877	04/29/2021	971208	Consumables		1133447
877	04/29/2021	970905	Mechanic entered - Body Other both middle seat bracket bolts	repaired both middle seattightened both middle seat bracket all bolts ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other rear modesty panel loose	repaired rear modesty panel ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other rear door very loose	repaired rear door ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other n/s/f bus inside panel screws	replaced n/s/f bus inside panel screws ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other n/s/f staunchion pole screws m	replaced n/s/f staunchion pole screws	1133447
877	04/29/2021	971208	Mechanic entered - Body Other driver seat back modesty panel	replaced driver seat back modesty panel ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other o/s/r staunchion pole bolt mis	repaired o/s/r staunchion pole nut replaced o/s/r staunchion pole bolt ok	1133447
877	04/29/2021	971208	Mechanic entered - Body Other front modesty panel loose	repaired front modesty panel ok	1133447
877	04/28/2021	970904		PRE ANNUAL SAFETY INSPECTION CHECK	1133447
877	04/28/2021	970904		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1133447
877	04/28/2021	970974	Emergency hammer taken and holder broken.	checked bus for emergency hammers and holders. could not fault any missing	1133447
877	04/28/2021	970905	Mechanic entered - Suspension Other rear both D rubber u/s	removed rear D rubber replaced both rear D rubber ok	1133447
877	04/28/2021	970905	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1133447
877	04/28/2021	970905	Mechanic entered - Steering Other n/s tie rod bolt loose	tightened n/s tie rod bolt ok	1133447
877	04/28/2021	970905	Mechanic entered - Fluid Leaks Other coolant leaks from ther	removed thermostat housingNikki replaced thermostattightened thermostat housing bracket bolts tightened thermostat housing hose clamps ok after check all ok	1133447
877	04/28/2021	970905	THERMOSTAT 75/79 DEG DOUBLE SCANIA L94UAB 1745449		1133447
877	04/21/2021	969345	Mechanic entered - Elec and Light Other pax buzzer n/wblink	fit new blinker stalkcould not fault pax buzzer or switches.	1132128
877	04/21/2021	969345	SWITCH INDICATOR SCANIA L94 1402448		1132128
877	04/21/2021	969345	Consumables		1132128
877	04/16/2021	968433	Mechanic entered - Body Drivers Seat Belt seat belt anchor b	fit new seatbelt anchor.	1131013
877	04/16/2021	968433	SEAT BELT BUCKLE		1131013
877	04/12/2021	967258	Mechanic entered - Air System Air_Leak Rear	shuttle valve air line leak at comprepair air lineok.	1129892
877	04/06/2021	966068	Mechanic entered - Elec and Light Other re-bookbattery test	load testcheck charge rateok.	1128942
877	04/06/2021	966068	Consumables		1128942
877	04/03/2021	966003	Mechanic entered - Elec and Light Flat Batteries	jump started; re-booked for battery check	1128942
877	04/03/2021	966003	Consumables		1128942
877	04/03/2021	966015		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per checklist	1128942
877	04/01/2021	965096	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O296126 Receiving #:309833 Date :2021-04-08 12 month a/c service	1129892
877	03/31/2021	965042	Drv entered - A/C Heating Not Cooling	replaced solenoid and tested aircon ok	1128850
877	03/30/2021	965042	a/c soleniod u/s - 24063-08BX	checked and found relay/solenoid internal fault. ordered the solenoid	1128759
877	03/30/2021	965042	24063-08BX Solenoid	Creditor #:VB-ASHDOW ASHDOWN INGRAM P/O #:O296108 Receiving #:309558 Date :2021-04-06	1129290
877	03/30/2021	965042	Consumables		1129290
877	03/30/2021	965096		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O296126	1128759
877	03/26/2021	963482	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		1127970
877	03/26/2021	963482	BELT MICRO V SERPENTINE BELT 8 RIB 2465MM LONG 1800534		1127970
877	03/26/2021	963482	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048		1127970
877	03/26/2021	963881	Place new poster over the top attach hangers to hand rails	complete	1127970
877	03/26/2021	964103	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	complete	1127970
877	03/25/2021	963482	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	removed timming cover & fixed cover & road testok.	1127970
877	03/25/2021	963482	BELT MICRO V SERPENTINE BELT 8 RIB 2465MM LONG 1800534		1127970
877	03/25/2021	963483	Mechanic entered - Engine Other idler bearing need replace	replace idler bearing check ok	1127970
877	03/25/2021	963483	PULLEY IDLER SCANIA (1514087)		1127970
877	03/22/2021	962403	Ops Entered - Fault - A/C Heating - Route: 703 - Bentleigh	traced and found wiring fault . repaired plug to back of a/c controller . checked operation all okay	1127178
877	03/20/2021	962175		VEHICLE SAFETY INSPECTION Completed inspection	1127178
877	03/20/2021	962175		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1127178
877	03/20/2021	962189	Mechanic entered - Suspension Other N/S/R rear air bag leaki	Replaced air bag	1127178
877	03/20/2021	962189	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		1127178
877	03/20/2021	962189	Mechanic entered - BusMinder Other Magnetic stand u/s	Fitted magnet from a scrap bus	1127178
877	03/20/2021	962189	Mechanic entered - Elec and Light Exterior Lights Rear door	Cleaned both the lens and sealed them	1127178
877	03/20/2021	962189	Mechanic entered - Elec and Light Interior Lights Rear door	Fitted newled light assy	1127178
877	03/20/2021	962189	Consumables		1127178
877	03/20/2021	962189	Mechanic entered - Body Other Few disable seat hinge pins co	Fit pins back	1127178
877	03/20/2021	962189	Mechanic entered - Body Drivers Seat Controls One lumbar swi	Fitted new button	1127178
877	03/20/2021	962189	Consumables		1127178
877	03/20/2021	962189	Mechanic entered - Brakes Other O/S/F and N/S/R slack adjust	Replaced both the slack adjusters	1127178
877	03/20/2021	962189	SLACK ADJUSTER FRONT OUTER SIDE (1789567)		1127178
877	03/20/2021	962189	SLACK ADJUSTERAUTO-REAR N/SIDE (2009819) SERIES 4		1127178
877	03/20/2021	962189	L/H LOWER SEAT LUMBAR BUTTONS		1127178

877	03/20/2021	962189	LAMP STEP LIGHT ROUND 24V		1127178
877	03/20/2021	962189	SLACK ADJUSTER FRONT OUTER SIDE (1789567)		1127178
877	03/20/2021	962189	SLACK ADJUSTER FRONT OUTER SIDE (1789567)		1127178
877	03/18/2021	961409		TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.	1126668
877	03/16/2021	960891	Mechanic entered - Fluid Leaks Rear of bus leaking engine o	Checked OK	1126403
877	03/12/2021	960288	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	complete	1125359
877	03/05/2021	958772	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque n/s/r wheel nuts.	1124140
877	03/05/2021	958772	Consumables		1124140
877	03/02/2021	958179	Mechanic entered - Wheels and Tyres Worn Pos 3 and 4 worn	Replaced both the tyres with new retreads	1123669
877	03/02/2021	958179	TYRE 295/80R22.5 RECAP		1123669
877	03/02/2021	958179	Consumables		1123669
877	02/24/2021	950514	Consumables		1122735
877	02/24/2021	950514	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O292265 Receiving #:307111 Date :2021-02-26 check and supply quote for pax seat loose from body mount	1122966
877	02/23/2021	956225		SERVICE MOISTURE EJECTOR	1122042
877	02/23/2021	956225	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1122042
877	02/20/2021	955732	Leave old poster in and fit you must wear a maskover the	complete	1122042
877	02/15/2021	953772		complete	1121166
877	02/15/2021	953772		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1121166
877	02/11/2021	952790	Consumables		1120920
877	02/11/2021	952790	Mechanic entered - Elec and Light Other re-book for battery	Tested batteries ok	1120125
877	02/10/2021	952468	Consumables		1120730
877	02/10/2021	952415	Consumables		1120730
877	02/10/2021	952415	Mechanic entered - Elec and Light Other won't start	jump started ok	1120125
877	02/10/2021	952468	Mechanic entered - Elec and Light Other engine hatch switch	repaired engine hatch switch ok	1120125
877	02/02/2021	950514	Body (None) rear pax seat to the body loose	dropped off at body shop PO#: O292265	1120125
877	02/01/2021	950044	Consumables		1120415
877	02/01/2021	950044	Consumables		1120415
877	02/01/2021	950044		CARRY OUT C SERVICE AS PER CHECK LIST carried out c service	1120125
877	02/01/2021	950044	FILTER AIR FILTER (395773) AF25066		1120125
877	02/01/2021	950044	FILTER FUEL FILTER SCANIA SR4 (1393640)		1120125
877	02/01/2021	950044	Oil Filter SCANIA S4 & k		1120125
877	02/01/2021	950044	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1120125
877	02/01/2021	950044	OIL SAMPLE KIT CALTEX		1120125
877	02/01/2021	950044	FILTER HYD COOLING FAN SCANIA L94UAB 1354074		1120125
877	02/01/2021	950044	FILTER FUEL FILTER SCANIA SR4 (1372444)		1120125
877	02/01/2021	950044	FILTER STEERING FILTER (153468) (0153468)(349619)		1120125
877	02/01/2021	950044	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1120125
877	02/01/2021	950044	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		1120125
877	02/01/2021	950044	Consumables		1120415
877	02/01/2021	950044	Consumables		1120415
877	02/01/2021	950044		CARRY OUT B SERVICE AS PER CHECK LIST carried out b service	1120125
877	01/27/2021	949101	Consumables		1119840
877	01/27/2021	949101	Consumables		1119840
877	01/27/2021	949101	Ops Entered - Fault - Elec and Light Hazzard switch broken-	fit new hazard switch.	1119484
877	01/27/2021	949101	SWITCH HAZARD 4 SERIES 1327015		1119484
877	01/22/2021	948689	Removed N/S/F window COVID-19 & MYKI decals and reposition	complete	1118863
877	01/20/2021	948126	Consumables		1118674
877	01/20/2021	948126	Consumables		1118674
877	01/20/2021	948126	Mechanic entered - Elec and Light Exterior Lights front ste	checked lens condition . could not fault	1118445
877	01/19/2021	947810	Please fit A3 poster over COVID-19 poster and hangers to be	complete	1118212
877	01/18/2021	947564	Consumables		1118212
877	01/18/2021	947564	Consumables		1118212
877	01/18/2021	947564	Mechanic entered - Elec and Light Exterior Lights N/S head l	Replaced globe	1117738
877	01/16/2021	947230	Consumables		1117893
877	01/16/2021	947230	Consumables		1117893
877	01/16/2021	947230	Mechanic entered - Elec and Light Exterior Lights n/s headli	could not fault.	1117738
877	01/14/2021	946706		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1117212
877	01/14/2021	946706		VEHICLE SAFETY INSPECTION done.	1117212
877	01/14/2021	946908	Mechanic entered - Elec and Light Interior Lights front driv	r/r lensOk.	1117212
877	01/14/2021	946908	Consumables		1117738
877	01/14/2021	946908	Consumables		1117738
877	01/14/2021	946908	Mechanic entered - Elec and Light Interior Lights rear emerg	r/r lightok.	1117212
877	01/14/2021	946908	Consumables		1117738
877	01/14/2021	946908	Consumables		1117738
877	01/14/2021	946908	Mechanic entered - Body Other loose a/c duct panel.	fixed a/c duct panelok.	1117212
877	01/14/2021	946908	Mechanic entered - Body Other battery carrier not secure.	fixed battery carrierok.	1117212
877	01/14/2021	946908	Mechanic entered - Body Other cut rear pax seat back handle.	fixed pax seat back handleok.	1117212
877	01/14/2021	946908	LIGHT EMERGENCY EXIT WITH HAMMER CUSTOM		1117212
877	01/14/2021	946708	FILTER FUEL FILTER SCANIA SR4 (1372444)		1117212
877	01/14/2021	946708	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1117212
877	01/14/2021	946708	Oil Filter SCANIA S4 & K		1117212
877	01/14/2021	946708	Consumables		1117738
877	01/14/2021	946708	Consumables		1117738
877	01/14/2021	946708	Consumables		1117738
877	01/14/2021	946708	Consumables		1117738
877	01/14/2021	946708		CARRY OUT B SERVICE AS PER CHECK LIST carry out servas per work order check ok	1117212
877	01/14/2021	946708	OIL SAMPLE KIT CALTEX		1117212
877	01/14/2021	946708	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1117212
877	01/11/2021	945877	Consumables		1117212
877	01/11/2021	945877	Consumables		1117212
877	01/11/2021	945877	Mechanic entered - Elec and Light Exterior Lights O/S/F top	Remove and fit new screws	1116984
877	01/08/2021	945189	Mechanic entered - Fluid Leaks Other check coolant leaks	checked coolant hose all okput in coolant 6ltroad tested after check coolant okno leakstemp is 80 ok	1116594
877	01/06/2021	944652	HOSE G/BOX COOLING SCANIA L94 0485995		1116028
877	01/06/2021	944652	Mechanic entered - Fluid Leaks Rear of bus Coolant Leak Hol	Removed old Hose replaced hose and hose clamps refilled with coolant roadtested ok rechecked and topped up coolant.	1116028
877	01/01/2021	943529	Consumables		1115800
877	01/01/2021	943529	Consumables		1115800
877	01/01/2021	943529	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O290395 Receiving #:303475 Date :2021-01-07 replace osr window glass as cracked	1116594
877	12/29/2020	943529	Drv entered - Body Windows Rear	PO#: O290395 alpha glass	1115234
877	12/29/2020	943529	Consumables		1115234
877	12/10/2020	940665	Mechanic entered - Wipers and Washers Wipers Not Working	Reset node for wipers checked operation all okay	1112904
877	12/10/2020	940550	Mechanic entered - A/C Heating Other a/c belts u/s N/S INDI	checked operation of indicators and hazards . could not fault	1112904
877	12/09/2020	940170	Mechanic entered - Body Other cctv hatch cover not secure.	secure hatch cover.	1112724
877	12/09/2020	940170	Consumables		1112904

877	12/07/2020	939863	Mechanic entered - Elec and Light Exterior Lights N/S/F top	Replaced globe	1112456
877	12/07/2020	939863	Consumables		1112724
877	11/28/2020	937821	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	complete	1111014
877	11/25/2020	936436	o/s/f park light not working	R&R globe	1110500
877	11/25/2020	936436	Consumables		1110746
877	11/18/2020	934636	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	complete	1109408
877	11/18/2020	934361	Remove old poster and fit you must wear a face mask when t	complete	1109408
877	11/16/2020	933552	o/s headlight not working	R&R globe . checked operation all okay	1109069
877	11/16/2020	933552	Consumables		1109194
877	11/14/2020	933414	Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	1109069
877	11/07/2020	931418		VEHICLE SAFETY INSPECTION done.	1107962
877	11/07/2020	931418		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1107962
877	11/07/2020	931446	Mechanic entered - Suspension Other rear sway bar D rubber u	r/r sway bar D rubbersok.	1107962
877	11/07/2020	931446	Mechanic entered - Elec and Light Exterior Lights o/s/f top	r/r globe & lensok.	1107962
877	11/07/2020	931446	Elec and Light OSF TOP PARK LIGHT NW	r/r globeok.	1107962
877	11/07/2020	931446	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1107962
877	11/07/2020	931446	LENS TO SUIT 2063 LAMP 85765		1107962
877	11/07/2020	931446	Consumables		1108250
877	11/07/2020	931446	Mechanic entered - Body Other missing outter reflectors.	fitted new reflectorsok.	1107962
877	11/07/2020	931446	Mechanic entered - Body Other noisy from front modesty panel	fixed modesty panelok.	1107962
877	11/07/2020	931446	Mechanic entered - Body Other loose pax seat base bolts.	tighten boltsok.	1107962
877	11/07/2020	931446	Consumables		1108250
877	11/07/2020	931420		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST CARRIED OUT AS PER CHECK LIST	1107962
877	10/30/2020	929904	Fit new Myki Decals & refit COVID-19 decals new position f	complete	1106995
877	10/16/2020	926841	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	fit etag	1104864
877	10/15/2020	926615	Mechanic entered - A/C Heating Other inlet air filter grille	removed the filter carrier; removed all riverts and secured. washed filter and fitted back. tested ok.	1104864
877	09/28/2020	922623		complete	1102409
877	09/28/2020	922623		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1102409
877	09/09/2020	917707	Direct Purchase - BODYWORK	Creditor #-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #-O283002 Receiving #-295698 Date :2020-09-10 mick to carry out repair to passenger grab bar as required	1100087
877	09/09/2020	917707	Consumables		1100087
877	09/03/2020	917846	V STAY ASSEMBLY SCANIA L94UAB		1099175
877	09/03/2020	917846	Mechanic entered - Suspension Other V rod bush u/s.	r/r rear V rodok.	1099175
877	09/02/2020	917707	Mechanic entered - Body Other missing rear stauchion pole s	O283002 - repaired by mick	1099175
877	08/29/2020	916907		VEHICLE SAFETY INSPECTION done.	1098247
877	08/29/2020	916907		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1098247
877	08/29/2020	916935	PUMP. FUEL PRIMER VOLVO B10BLE 3826073 A0000908850		1098247
877	08/29/2020	916935	Mechanic entered - Suspension Other leaking air from n/s/r/r	fixed air bag fitok.	1098247
877	08/29/2020	916935	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	fixed coolant hoseok.	1098247
877	08/29/2020	916935	Mechanic entered - Fluid Leaks Rear of bus leaking fuel from	r/r fuel priming pumpok.	1098247
877	08/29/2020	916935	Mechanic entered - Body Other noisy from front modesty panel	fixed modesty panelok.	1098247
877	08/29/2020	916935	Mechanic entered - Body Other front sun blind not secure.	fixed sun blindok.	1098247
877	08/29/2020	916935	Consumables		1098247
877	08/29/2020	916935	Mechanic entered - Air System Air_Leak Rear leaking air from	fixed air hoseok.	1098247
877	08/27/2020	916559	Mechanic entered - Engine Other Air Filter U/S	Replaced Air Filter with new from stock ok	1098247
877	08/27/2020	916540		CARRY OUT B SERVICE AS PER CHECK LIST carried out B service ok	1098247
877	08/27/2020	916540	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1098247
877	08/27/2020	916540	OIL SAMPLE KIT CALTEX		1098247
877	08/27/2020	916540	FILTER FUEL FILTER SCANIA SR4 (1372444)		1098247
877	08/27/2020	916540	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1098247
877	08/27/2020	916540	Oil Filter SCANIA S4 & K		1098247
877	08/27/2020	916540	FILTER AIR FILTER (395773) AF25066		1098247
877	08/27/2020	916540	Consumables		1098435
877	08/27/2020	916540	Consumables		1098435
877	08/25/2020	915866		load tested both batterys . both batterys passed the load test . checked charge rate . 27.7 volts . could not fault	1097524
877	08/24/2020	915580	Elec and Light won't start flat batteries	jump started and rebook for battery check	1097524
877	08/24/2020	915580	Consumables		1098019
877	08/19/2020	914795	Mechanic entered - Elec and Light Other Battery Check Book	Carried out battery load test Checked batteryall ok	1096397
877	08/19/2020	914795	Consumables		1097280
877	08/18/2020	914511		TRANSMISSION CHECK AS PER CHECK LIST	1096397
877	08/11/2020	913086	Remove old A3 Poster and fit with You can no longer top up	carried out by fleet support	1095392
877	08/10/2020	912372	Mechanic entered - Elec and Light Flat Batteries wont start.	jump startok.	1095174
877	08/10/2020	912372	Consumables		1095392
877	07/29/2020	909729	Ops Entered - Fault - Wipers and Washers Wipers Not Working	checked operation of wipers .could not fault	1093589
877	07/28/2020	909268	Drv entered - Brakes Foot_Brakes Noisy	road test and brake test for noisy brakescould not fault.	1093125
877	07/22/2020	908384	Mechanic entered - Elec and Light Exterior Lights O/S revers	Fit back with new screws	1092421
877	07/22/2020	908384	Consumables		1092664
877	07/21/2020	907818	Mechanic entered - Elec and Light Flat Batteries battery che	load testcheck charge rateok.	1091897
877	07/21/2020	907818	Consumables		1092421
877	07/20/2020	907602	Mechanic entered - Elec and Light Flat Batteries	jump started bus	1091897
877	07/20/2020	907602	Consumables		1092231
877	07/06/2020	904736	Consumables		1090704
877	07/06/2020	904736	Mechanic entered - Elec and Light Other BLINKERS CANCELING .	COULD NOT FAULT.	1090222
877	06/30/2020	903637		VEHICLE SAFETY INSPECTION Carried out safety inspection ok	1089463
877	06/30/2020	903637		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1089463
877	06/30/2020	903705	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	Replaced rear sway bar 'D' bushes	1089463
877	06/30/2020	903705	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1089463
877	06/30/2020	903705	Mechanic entered - Elec and Light Other 1x Battery U/S Fail	replaced battery - failed after charging	1089463
877	06/30/2020	903705	BATTERY 1030CCA POS ON LHS EMFN150L		1089463
877	06/30/2020	903705	Consumables		1089768
877	06/30/2020	903705	Mechanic entered - Body Other N/S/R Seat Base Torn	Removed seat base and replaced with fresh base from body shop ok	1089463
877	06/30/2020	903705	Mechanic entered - Body Other Front Modesty Panel Loose	Drilled out old rivets and re rivetted panel and checked ok	1089463
877	06/30/2020	903705	Mechanic entered - Body Other Rear Roof Stauchion Support I	tightened support ok	1089463
877	06/30/2020	903705	Mechanic entered - Body Other Disabled seat pins out	re seated pins ok	1089463
877	06/30/2020	903705	Mechanic entered - Body Other Rear Modesty Panel loose	Re drilled holes at bottom and added self tapping screws to bottom and side surround ok	1089463
877	06/30/2020	903705	Consumables		1089768
877	06/30/2020	903705	Mechanic entered - Air System Air_Leak Doors Air Leak From F	Door Control Valve also leaking Replaced both valves and checked ok	1089463
877	06/30/2020	903705	VALVE DOOR VALVE		1089463
877	06/30/2020	903705	FESTO DOOR CONTROL VALVE (173125)		1089463
877	06/30/2020	903705	Mechanic entered - Air System Air_Leak Doors Door Control Va	replaced Control Valve ok	1089463
877	06/13/2020	900718	Drv entered - BusMinder Damaged	resecured bus minder handset	1086475
877	06/13/2020	900718	Consumables		1086701
877	06/10/2020	899914	n/s side indicator not working	R&R globe . checked operation all okay	1086059
877	06/10/2020	899914	Consumables		1086247

877	06/03/2020	898456	Mechanic entered - Elec and Light Other O/S/F upper park lig	replaced globe as required	1084897
877	06/03/2020	898456	Consumables		1085140
877	05/12/2020	894016	Mechanic entered - Elec and Light Other O/S headlight N/W	replaced globe as required	1080645
877	05/12/2020	894016	Consumables		1080869
877	05/11/2020	893694	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S	carried out retorque as required	1080403
877	05/11/2020	893694	Consumables		1080645
877	05/07/2020	892836		VEHICLE SAFETY INSPECTION	1079565
877	05/07/2020	892836		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1079565
877	05/07/2020	892836		ANNUAL SAFETY INSPECTION SERIAL#K669198 WORKSHOP SUPERVISOR/MANAGER NOTE:REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO0.25 done by FLEET CHECKPOO274886	1079565
877	05/07/2020	892836	DIRECT PURCHASE - BUS INSPECTI	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O274886 Receiving #:286796 Date :2020-05-14	1081133
877	05/07/2020	892983	Mechanic entered - Suspension Other both rear sway bar bushi	removed both rear sway bar bushing replaced both rear sway bushing x8 ok	1079565
877	05/07/2020	892983	BUSH RR SWAY BAR D AXLE SCANIA L94UAB 2156626 1477867		1079565
877	05/07/2020	892982	Mechanic entered - Steering Excessive Play Tie Rod U/S	Adjusted and replaced Tie Rod	1079565
877	05/07/2020	892982	TIE ROD ASSY SCANIA L94/K230/N310 1897333 2146105		1079565
877	05/07/2020	891898	Mechanic entered - Engine Other ENGINE SUMP PLUGE BROKEN AND	ok	1079565
877	05/06/2020	891898	GASKET SUMP SCANIA L94 40A3	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O274810 Receiving #:286431 Date :2020-05-08	1079977
877	05/06/2020	891898	GASKET SPINNER FILTER HOUSING (1116355)		1079565
877	05/06/2020	891898	Gasket Oil Spinner SR 3 (1392196)		1079565
877	05/06/2020	892807	Mechanic entered - Engine Other REPLACED ENGINE SUMP	CLEANED ENGINE SUMP GASKET AND replaced ENGINE SUMP TIGHTENED ALL OIL PIPE OK replaced SUMP ALL GAKKET OK TIGHTENED SUMP PLURE TIGHTENED SUMP BOLTS OK road test R.P.M 1500 engine oil gauge 6 bar ok engine low 3 bar oksump is oil no leaks ok	1079565
877	05/05/2020	891898	DIRECT PURCHASE - ENGINE	Creditor #:\VB-HMG001 HM GEM ENGINES P/O #:O274578 Receiving #:286423 Date :2020-05-08 check and rectify eng oil sump drain plug nut to the sump as required	1079977
877	05/04/2020	891898	Mechanic entered - Engine Other ENGINE SUMP PLUGE BROKEN AN	sent to HM and GEM PO#: O274578	1079565
877	05/03/2020	891898		Drained engine oil out and removed sump for repair cleaned in hot wash	1079565
877	05/02/2020	891835		VEHICLE SAFETY INSPECTION	1079565
877	05/02/2020	891835		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1079565
877	05/02/2020	891861	Mechanic entered - Wipers and Washers Other wiper washer tan	replaced second hand wiper wash tank by hamid	1079565
877	05/02/2020	891898		check and found e/oil leaks from sump gasket also drain nut loose no oil leak though. needs repairing thises oil leaks	1079565
877	05/02/2020	891861	Mechanic entered - Elec and Light Other o/s/r saloon light	replaced saloon light tube hamid	1079565
877	05/02/2020	891861	Consumables		1079757
877	05/02/2020	891861	Mechanic entered - Body Other n/s/f staunchion pole loose	repaired n/s/f staunchion pole ok	1079565
877	05/02/2020	891861	Mechanic entered - Body Other o/s/r member pillar bolt loose	tightened o/s/r member pillar bolt ok	1079565
877	05/02/2020	891861	Mechanic entered - Body Other driver back modesty panel bolt	repaired driver back modesty panel ok	1079565
877	05/02/2020	891861	Consumables		1079757
877	04/30/2020	891325	FILTER FUEL FILTER SCANIA SR4 (1372444)		1079165
877	04/30/2020	891325	Oil Filter SCANIA S4 & K		1079165
877	04/30/2020	891325	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1079165
877	04/30/2020	891325		CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order check tested ok	1079165
877	04/30/2020	891325	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1079165
877	04/30/2020	891325	Consumables		1079565
877	04/28/2020	890842	Mechanic entered - Elec and Light Other N/S INDICATOR NOT WO	checked N/S ALL INDICATOR WORKING OK	1078485
877	04/28/2020	890842	Consumables		1079165
877	04/25/2020	890610	Vandalism interior graffiti	cleaned and painted over graffiti	1078485
877	04/22/2020	889788	Mechanic entered - Suspension Other front D rubber u/s	replaced both front D rubber ok	1078140
877	04/22/2020	889788	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1078140
877	04/22/2020	889788	Mechanic entered - Suspension Other rear D rubber u/s	replaced both rear D rubber ok	1078140
877	04/22/2020	889788	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		1078140
877	04/22/2020	889170	Mechanic entered - Body Other o/s mirror bracket bolt broken	repaired o/s/mirror ok	1078140
877	04/22/2020	889170	Consumables		1078293
877	04/22/2020	889835		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	1078140
877	04/21/2020	889494	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retensioned N/S/F Wheel	1077218
877	04/21/2020	889494	Consumables		1078140
877	04/20/2020	889253	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorqued o/s/r wheel nuts ok	1077218
877	04/20/2020	889253	Consumables		1077855
877	04/20/2020	888978	DIRECT PURCHASE - VANDALISM	Creditor #:\VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O273435 Receiving #:284816 Date :2020-04-20 GRAFFITI WINDOW FILM STAGE 3	1077565
877	04/20/2020	889273	Mechanic entered - Suspension Other n/s/f top torque rod u/s	job done by Chris	1077218
877	04/20/2020	889273	TORQUE ROD FRT UPPER SCANIA K230UB 1438475 2055289		1077218
877	04/20/2020	889273	Mechanic entered - Suspension Other N/S/F Upper Torque rod U	Replaced N/S/F Upper Torque Rod ok	1077218
877	04/18/2020	889167		PRE ANNUAL SAFETY INSPECTION CHECK	1077218
877	04/18/2020	889167		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1077218
877	04/18/2020	889170	TYRE 295/80R22.5 RECAP		1077218
877	04/18/2020	889170	Mechanic entered - Wheels and Tyres Other o/s/r tyres u/s	replaced o/s/r tyres u/s x2	1077218
877	04/18/2020	889170	Consumables		1077565
877	04/18/2020	889170	Mechanic entered - Engine Other engine belt tensioner u/s	replaced engine belt tensioner ok	1077218
877	04/18/2020	889170	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		1077218
877	04/18/2020	889170	Mechanic entered - Elec and Light Other dash fuel and air ga	replaced dash fuel and air gauge light globe ok	1077218
877	04/18/2020	889170	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok	1077218
877	04/18/2020	889170	Mechanic entered - Elec and Light Other n/s head light crack	replaced n/s head light ok	1077218
877	04/18/2020	889170	LAMP HEADLAMP MK3 VOLVO B10M		1077218
877	04/18/2020	889170	Consumables		1077565
877	04/18/2020	889170	Mechanic entered - Body Other n/s/f staunchion pole loose	repaired n/s/f staunchion pole ok	1077218
877	04/18/2020	889170	Mechanic entered - Body Other n/s/middle seat loose	repaired n/s/middle seat ok	1077218
877	04/17/2020	888978	Vandalism Vandalism/ Graffiti Interior	COMPLETED	1077218
877	04/14/2020	887802	Mechanic entered - Elec and Light Flat Batteries	jump start.	1076671
877	04/14/2020	887802	Consumables		1077135
877	04/09/2020	887495	A4 notification to be printed off in colour laminated and	carried out campaign as required	1076671
877	03/30/2020	884875	Mechanic entered - Elec and Light Flat Batteries	Jump Started Bus	1074508
877	03/30/2020	884875	Consumables		1075022
877	03/28/2020	884950	Vandalism interior graffiti	cleaned and painted over interior graffiti	1074508
877	03/24/2020	883259	Remove old poster and fit Reduce Your Risk of Coronavirus	carried out campaign as required	1073865
877	03/24/2020	883352	Tape off front Seats of All Route and Rail Buses with spec	carried out campaign as required	1073865
877	03/20/2020	881989	Accident # 49763 - NEAR SIDE FRONT Unreported damage	COMPLETED	1072552
877	03/17/2020	880931	MOUNT A/C COMPRESSOR LARGE DENSO		1072065
877	03/17/2020	880931	MOUNT A/C COMPRESSOR SMALL DENSO		1072065
877	03/17/2020	880931		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O271209	1072065
877	03/17/2020	880931	AIR CONDITIONING REPAIR	Creditor #:\VB-COLO04 COLD DRIVE PTY LTD P/O #:O271209 Receiving #:282967 Date :2020-03-26 24 month a/c service	1074262
877	03/17/2020	880931		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O271209	1072065
877	03/06/2020	879133	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retensioned O/S front ok	1070799
877	03/06/2020	879133	Consumables		1070866
877	03/06/2020	878543	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	remove fit new A/C main solinoid.	1070799
877	03/05/2020	878543	24063-08BX Battery Solenoid	Creditor #:\VB-ASHDOW ASHDOWN INGRAM P/O #:O270475 Receiving #:281457 Date :2020-03-06	1070799
877	03/04/2020	878509		VEHICLE SAFETY INSPECTION	1070799
877	03/04/2020	878509		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1070799
877	03/04/2020	878509	Wipers and Washers high speed nw	Wiper working on two speed	1070799
877	03/04/2020	878543	Mechanic entered - Wheels and Tyres Worn Pos 2 tyre worn	Replaced tyre with new one	1070799

877	03/04/2020	878543	TYRE 295/80R22.5 NEW			1070799
877	03/04/2020	878543	Consumables			1070799
877	03/04/2020	878543	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	diagnosed and found ac battery solenoid us.		1070799
877	03/04/2020	878543	Mechanic entered - Elec and Light Next Stop Button Broken ne	Replaced broken switch		1070799
877	03/04/2020	878543	SWITCH- STOP-YELLOW (62628)			1070799
877	03/04/2020	878543	Mechanic entered - Elec and Light Interior Lights One fluro	Replaced fluro and globe		1070799
877	03/04/2020	878543	Consumables			1070799
877	03/04/2020	878543	Mechanic entered - Body Other No smoking decal at rear vanda	Fitted new decal		1070799
877	03/04/2020	878509	Has a couple of loose panels screws halfway along the right	Fitted new screws		1070799
877	03/04/2020	878509	loose screws in panels near priority seating	tightened screws		1070799
877	03/04/2020	878543	Consumables			1070799
877	03/04/2020	878509	Consumables			1070799
877	03/02/2020	877862	Mechanic entered - Body Other high speed wiper n/wloose scr	secure wiper wiring plug to wiper motorsecure screws to seats.		1069690
877	03/02/2020	877862	Consumables			1070768
877	02/28/2020	877551		complete		1069690
877	02/28/2020	877551		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1069690
877	02/26/2020	877101	Mechanic entered - Elec and Light Other drivers cctv camera	added screws to resecure camera		1069160
877	02/26/2020	877101	Consumables			1069424
877	02/19/2020	875078	Mechanic entered - Steering Steering Wheel Faulty sticky -	R&R steering wheel with new		1068213
877	02/19/2020	875078	40M1303OE Steering Wheel	Creditor #:-VB-MUL004 MULTISPARES OAKLEIGH P/O #:-O269187 Receiving #:-280224 Date :2020-02-21		1068442
877	02/18/2020	874900		TRANSMISSION CHECK AS PER CHECK LIST		1067810
877	02/18/2020	874894	PUMP WATER BOOST MOTOR			1067810
877	02/18/2020	874894	Mechanic entered - A/C Heating Other boost pump leaking.	fit new boost pumpok.		1067810
877	02/13/2020	874106	Mechanic entered - Elec and Light Other N/S front park light	replaced globe ok		1067128
877	02/13/2020	874106	Consumables			1067354
877	02/07/2020	872683	Ops Entered - Fault - Passenger Doors - Route: 703b - Centr	checked rear door operation was ok		1066198
877	02/07/2020	872683	Consumables			1066407
877	02/06/2020	872371	Mechanic entered - Elec and Light Other N/S headlight N/W	replaced globe ok		1065988
877	02/06/2020	872371	Consumables			1066198
877	01/23/2020	869329	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	carried out campaign as required		1063743
877	01/10/2020	866487	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension		1061584
877	01/10/2020	866487	Consumables			1061693
877	01/10/2020	866175	DIRECT PURCHASE GLASS	Creditor #:-VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:-O266279 Receiving #:-277430 Date :2020-01-20 replace cracked n/s mid flat lam x 1 as required		1063325
877	01/10/2020	866175	Consumables			1061693
877	01/09/2020	866146		VEHICLE SAFETY INSPECTION		1061584
877	01/09/2020	866146		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed safety		1061584
877	01/09/2020	866146	Mechanic entered - Wipers and Washers Washers Not Working	Clean up jets		1061584
877	01/09/2020	866146	Mechanic entered - Wheels and Tyres Worn Pos 5 tyre worn	Replaced worn pos 5 tyre with a runout tyre		1061584
877	01/09/2020	866146	Consumables			1061584
877	01/09/2020	866146	Mechanic entered - Body Other Rear modesty panel loose	Drill and fit screw		1061584
877	01/09/2020	866175	n/s mid glass cracked badly	O266279 - replaced by alpha glass		1061584
877	01/09/2020	866146	Ops Entered - Fault - Body Windows Front - Route: 703b - M	checked operation of sun blind . could not fault		1061584
877	01/09/2020	866146	Consumables			1061584
877	01/09/2020	866146	SLACK ADJUSTER AUTO-REAR O/SIDE (2009820) SERIES 4			1061584
877	01/09/2020	866146	Mechanic entered - Brakes Other O/S/R slack adjuster u/s	Replaced slack adjuster		1061584
877	01/08/2020	865887	Mechanic entered - Elec and Light Other O/S upper parker lig	fitted globe		1061321
877	01/08/2020	865887	Consumables			1061584
877	01/03/2020	864886	Mechanic entered - Body Other Disabled seat top pins not sea	Re Seated Pins ok		1060246
877	01/03/2020	864886	Mechanic entered - Body Other Front Modesty Panel Loose at B	Drilled rivets and re rivetted panel ok		1060246
877	01/03/2020	864886	Consumables			1060349
877	01/03/2020	864785		CARRY OUT B SERVICE AS PER CHECK LIST Carried Out B Service ok		1060246
877	01/03/2020	864785	FILTER FUEL FILTER SCANIA SR4 (1372444)			1060246
877	01/03/2020	864785	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1060246
877	01/03/2020	864785	Oil Filter SCANIA S4 & K			1060246
877	01/03/2020	864785	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1060246
877	01/03/2020	864785	Consumables			1060349
877	01/03/2020	864785	Consumables			1060349
877	01/03/2020	864785	Consumables			1060349
877	12/24/2019	863778	Mechanic entered - Air System Other air leaking from driver'	replaced air fitting under driver's seat		1059121
877	12/19/2019	862861	A/C n/w	checked operation of a/c. could not fault		1058347
877	12/19/2019	862868	Body - drivers side sun blind u/s	R&R sunblind		1058347
877	12/19/2019	862868	BLIND SUN BLIND1000W x 500H			1058347
877	12/19/2019	862868	Consumables			1058347
877	12/17/2019	862261	Mechanic entered - Elec and Light Other o/s/f park light not	replaced o/s/f park globe		1057536
877	12/17/2019	862292	Mechanic entered - Elec and Light Other	repaired on work order - 862261		1057536
877	12/17/2019	862261	Consumables			1058195
877	12/17/2019	862292	Consumables			1058195
877	12/17/2019	862481	Mechanic entered - Body Other N/S mirror arm bent	Straighten mirror arm and adjusted		1057536
877	12/17/2019	862481	Consumables			1058195
877	12/14/2019	861889	Drv entered - BusMinder Unable To Log In	found bus minder handset was turned off . turned on . checked operation all okay		1057536
877	12/14/2019	861889	Consumables			1057799
877	12/07/2019	860153	A3 Poster Frame Adhesive Decal Campaign please remove old	complete		1056330
877	12/06/2019	859874		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1056330
877	12/06/2019	859874		completed		1056330
877	11/29/2019	857948	Mechanic entered - Body Other PDI inspection	carry out inspection check ok		1054997
877	11/29/2019	857948	Consumables			1055128
877	11/28/2019	854072	DIRECT PURCHASE ACCIDENT	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-O262291 Receiving #:-273780 Date :2019-11-29 accident damage at nsr cnr and frt top and bottom cnr Acc#49763		1054997
877	11/18/2019	855260		instructed to close of cctv services as per instruction from fleet		1054997
877	11/18/2019	855260		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		1054997
877	11/12/2019	854072	Accident#49763 - unreported nsr and frt top cnr damage	sent to b/shop PO O262291		1054997
877	10/24/2019	849990		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1051816
877	10/24/2019	849990		VEHICLE SAFETY INSPECTION		1051816
877	10/24/2019	849990	assisted			1051816
877	10/24/2019	850056	Mechanic entered - Suspension Other both front D rubber u/	replaced d rubber ok		1051816
877	10/24/2019	850056	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1051816
877	10/24/2019	850056	Mechanic entered - Fluid Leaks Other oil cooler leaks	tightened oil cooler bolts ok		1051816
877	10/24/2019	850056	Consumables			1052184
877	10/24/2019	850056	LENS CLEAR			1051816
877	10/24/2019	850056	Mechanic entered - Elec and Light Other inside cabin lens u/	replaced cabin light lens ok		1051816
877	10/24/2019	850056	Consumables			1052184
877	10/24/2019	850056	Mechanic entered - Body Other middle seat top pins out	put in middle seat top pins ok		1051816
877	10/24/2019	850056	Mechanic entered - Body Other n/s/r hammer decal missing	replaced n/s/r hammer decal ok		1051816
877	10/24/2019	850056	Mechanic entered - Body Other passenger seat clip u/s	replaced seat clip ok		1051816

877	10/24/2019	850056	Mechanic entered - Body Other seat bracket bolt loose	retight bracket ok	1051816
877	10/24/2019	850056	CENTRA CUSHION CLIP RH		1051816
877	10/15/2019	848215	Mechanic entered - Wipers and Washers Wipers Not Working	Checked wipers all ok and working	1050172
877	10/07/2019	845477	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	BROUGHT TGHE BUS BACK - PTI	1048719
877	10/02/2019	845477	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	dropped off the bus at Volgren PO#: O259195	1048719
877	10/01/2019	845251	Consumables		1048719
877	10/01/2019	845130	Consumables		1048719
877	10/01/2019	845251	Elec and Light - desto nw	fitted a recondition desto controller as there was no display. programmed desto files tested ok	1048283
877	10/01/2019	845130	Mechanic entered - Elec and Light Indicators Not Working o/s	fit globe.	1048283
877	10/01/2019	843492	Hose Coolant	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O258505 Receiving #:268874 Date :2019-10-03	1048719
877	09/21/2019	843492	air compressor u/s	Road tested checked all ok	1047268
877	09/20/2019	843492	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1871043 1376911		1047268
877	09/20/2019	843492	SEAL O-RING COMPRESSOR MOUNT SCANIA L94 (323790)		1047268
877	09/20/2019	843492	HOSE		1047268
877	09/20/2019	843492	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		1047268
877	09/20/2019	843492	air compressor u/s	Replaced air compressor with new one replaced coolant hoses Replaced air drier filter	1047268
877	09/20/2019	843492	AIR COMPRESSOR - WITH REAR COV	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #.:O258465 Receiving #:267907 Date :2019-09-20	1047268
877	09/20/2019	843492	BOLT COMPRESSOR GEAR		1047268
877	09/16/2019	842579	DIPSTICK P/STEER ZF		1046763
877	09/16/2019	842579	HEADER TANK FILLER CAP 1403954		1046763
877	09/16/2019	842579	Fault#:36895 - Ops Entered - Fault - Breakdown Not Starting	Attended breakdown top up coolant start brought to depot Replaced power steering fluid as coolant went in due to missing dipstick replaced header tank cap Checked hydraulic fan oil level ok wash and road test	1046763
877	09/14/2019	842339	Consumables		1046603
877	09/14/2019	842339	Drv entered - Body Front_Door Operation Faulty	no faults found	1046579
877	09/09/2019	841188	Consumables		1045662
877	09/09/2019	841187	Consumables		1045662
877	09/09/2019	841186	Consumables		1045662
877	09/09/2019	841188	BLIND SUN BLIND1000W x 500H		1045406
877	09/09/2019	841188	Ops Entered - Fault - Body Drivers Seat Belt - Route: - A	Drill holes and mount new side blind	1045406
877	09/09/2019	841187	Ops Entered - Fault - Body Windows Side Driver blind missi	double entry	1045406
877	09/09/2019	841186	drivers side sunblind missing	double entry	1045406
877	08/24/2019	837521		Completed retension	1042593
877	08/24/2019	837521		VEHICLE SAFETY INSPECTION Completed safety	1042593
877	08/24/2019	837554	Consumables		1042816
877	08/24/2019	837554	Mechanic entered - Elec and Light Other One saloon light an	Replaced fluoro and globe	1042593
877	08/24/2019	837554	Consumables		1042816
877	08/24/2019	837554	CAP END CAP CENTRA SEAT END CAP		1042593
877	08/24/2019	837554	Mechanic entered - Body Other ONE SEAT END CAP CRACKED	Replaced end cap	1042593
877	08/24/2019	837554	Mechanic entered - Body Drivers Seat Leaning Due to lack of	Replaced seat cushion	1042593
877	08/17/2019	836849	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting	1041621
877	08/16/2019	835751	Consumables		1041621
877	08/16/2019	835751	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorque all front wheel nuts.	1041136
877	08/14/2019	835328	JOINER PLASTIC 5MM X 5MM W/SCREEN		1040877
877	08/14/2019	835328	Mechanic entered - Wipers and Washers Washers Not Working O/	Added joiner so Jet Works	1040877
877	08/14/2019	835348	Consumables		1041136
877	08/14/2019	835348	TYRE 295/80R22.5 RECAP		1040877
877	08/14/2019	835348	Mechanic entered - Wheels and Tyres Other N/S/F Tyre Changed	to Match	1040877
877	08/14/2019	835348	Mechanic entered - Wheels and Tyres Worn O/S/F Tyre U/S 3mm	Replaced With New Tyre	1040877
877	08/14/2019	835348	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		1040877
877	08/14/2019	835348	Mechanic entered - Suspension Other both front bottom shock	replaced both front old shock rubber ok	1040877
877	08/14/2019	835348	Mechanic entered - Suspension Other both front D rubber u/	replaced both front D rubber ok x2	1040877
877	08/14/2019	835348	TIE ROD ASSY SCANIA L94/K230/N310 1897333		1040877
877	08/14/2019	835348	Mechanic entered - Steering Other Tie Rod U/S	Replaced and Adjusted Tie rod	1040877
877	08/14/2019	835309	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		1040877
877	08/14/2019	835309	PULLEY IDLER SCANIA (1514087)		1040877
877	08/14/2019	835309	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		1040877
877	08/14/2019	835309	Mechanic entered - Engine Other Belt Tensioner U/S	Replaced Tensioner	1040877
877	08/14/2019	835309	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1040877
877	08/14/2019	835309	Mechanic entered - Engine Other Drive Belt U/S	Replaced Drive Belt	1040877
877	08/14/2019	835309	Mechanic entered - Engine Other Idler Pulley (Smooth) U/S	Replaced Pulley	1040877
877	08/14/2019	835309	Mechanic entered - Engine Other Idler Pulley (Ribbed) U/S	Replaced Pulley	1040877
877	08/14/2019	835348	Consumables		1041136
877	08/14/2019	835348	Mechanic entered - Elec and Light Exterior Lights O/S/F Scho	Replaced Globe Ok	1040877
877	08/14/2019	835309	Consumables		1041136
877	08/14/2019	835309	Mechanic entered - Body Other N/S/R Centre Staunchion Pole L	Re drilled hole and new screws used to tighten pole	1040877
877	08/14/2019	835309	Mechanic entered - Body Other Disabled Seats top Pins out	Re-seated Pins for seat	1040877
877	08/14/2019	835215	Consumables		1041136
877	08/14/2019	835215	Consumables		1041136
877	08/14/2019	835215	Consumables		1040877
877	08/14/2019	835215	Oil Filter SCANIA S4 & K	CARRY OUT B SERVICE AS PER CHECK LIST Carried Out B Service	1040877
877	08/14/2019	835215	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1040877
877	08/14/2019	835215	FILTER FUEL FILTER SCANIA SR4 (1372444)		1040877
877	08/14/2019	835215	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1040877
877	08/08/2019	834290	Vandalism - glass protect to replace glass film x 1	O255030 - glass protect	1039895
877	08/01/2019	832671	Consumables		1038799
877	08/01/2019	832671	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension	1038602
877	08/01/2019	834290	DIRECT PURCHASE - VANDALISM	Creditor #.:VB-GLA010 GLASSPROTECH MELBOURNE P/O #.:O255030 Receiving #:264441 Date :2019-08-12 replace glass film x 1	1040623
877	07/31/2019	832395	Consumables		1038602
877	07/31/2019	832395	TYRE 295/80R22.5 NEW		1038450
877	07/31/2019	832395	Mechanic entered - Wheels and Tyres Damaged Pos 1 tyre sidew	Replaced tyre with new one and brake tested	1038450
877	07/30/2019	832098	Consumables		1038450
877	07/30/2019	832098	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension	1038221
877	07/30/2019	831899	Consumables		1038450
877	07/30/2019	832100	Consumables		1038450
877	07/30/2019	832100	Mechanic entered - Elec and Light Exterior Lights O/S/F bott	Replaced globe	1038221
877	07/30/2019	831899	o/s headlight not working	R&R globe	1038221
877	07/27/2019	831439		TRANSMISSION CHECK AS PER CHECK LIST Completed checks	1037224
877	07/27/2019	831439	Consumables		1038221
877	07/27/2019	831439	TYRE 295/80R22.5 RECAP		1037224
877	07/27/2019	831439	Mechanic entered - Wheels and Tyres Worn POS 3 and 4 worn	Replaced worn out tyres with new retreads	1037224
877	07/27/2019	831439	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)		1037224
877	07/27/2019	831439	Mechanic entered - Suspension Other N/S/R rear air bag leaki	Replaced leaking air bag	1037224
877	07/23/2019	830406	Consumables		1037224

877	07/23/2019	830406	Ops Entered - Fault - Elec and Light Warning Light On Dash -	road testcould not fault dash warning light.	1036298
877	07/22/2019	830128	Consumables		1037008
877	07/22/2019	830127	Consumables		1037008
877	07/22/2019	830128	Mechanic entered - Elec and Light Other alternator regulator	replaced alternator regulator ok	1036298
877	07/22/2019	830128	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315		1036298
877	07/22/2019	830127	Mechanic entered - Elec and Light Other battery jump	jumped battery	1036298
877	07/20/2019	830086	Consumables		1036815
877	07/20/2019	830086	o/s front top park light not working	R&R globe . checked operatrion all okay	1036298
877	07/15/2019	828904	Consumables		1035560
877	07/15/2019	828904	Mechanic entered - Elec and Light Indicators Not Working N/S	Replaced globe and fix contact	1035332
877	07/07/2019	827149	Consumables		1034122
877	07/07/2019	827149	Mechanic entered - Body Drivers Seat Controls Lumber switch	Fitted new cover and seat end caps	1033803
877	07/07/2019	827149	Mechanic entered - Body Other Front myki mount pole loose	Drill and fit new rivets fit screws to modesty panel	1033803
877	07/07/2019	827149	Mechanic entered - Body Other Drivers door hinge loose ca	Fit hinge pin back and drill and fit screws to both hinges Cut rivet aluminium strip over the carpet	1033803
877	07/07/2019	827149	Mechanic entered - Body Other Drivers seat cushion lacks pad	Replaced seat base	1033803
877	07/07/2019	827149	R/H UPPER SEAT LUMBAR BUTTONS		1033803
877	07/07/2019	827149	CAP END CAP CENTRA SEAT END CAP		1033803
877	07/06/2019	827140		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1033803
877	07/06/2019	827140		VEHICLE SAFETY INSPECTION	1033803
877	07/05/2019	826908	CCTV - johnny to carry out 6 month service as required	O252152 - carried out by johnny	1033803
877	07/04/2019	826908	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O252152 Receiving #:261621 Date :2019-07-12 johnny to carry out 6 month cctv service	1034902
877	06/29/2019	825836	Consumables		1033118
877	06/29/2019	825835	Consumables		1033118
877	06/29/2019	825836	Consumables		1033118
877	06/29/2019	825835	Consumables		1033118
877	06/29/2019	825836	Drv entered - BusMinder Damaged - needs flat bracket/holder	checked bracket and phone . could not fault	1032854
877	06/29/2019	825835	Drv entered - BusMinder Unable To Log In	checked bracket and phone . could not fault	1032854
877	06/14/2019	822866	Consumables		1030273
877	06/14/2019	822866	Consumables		1030273
877	06/14/2019	822866	Mechanic entered - Elec and Light Indicators Not Working o/s	fit globe.	1029783
877	06/11/2019	822263	Consumables		1029501
877	06/11/2019	822263	Consumables		1029501
877	06/11/2019	822263	Mechanic entered - Body Other Drivers side blinds came off	Fitted screw and nut for end bracket	1029058
877	05/23/2019	818648	Consumables		1025988
877	05/23/2019	818648	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSF	retorqie n/s/f wheel nuts.	1025441
877	05/23/2019	818648	Consumables		1025988
877	05/20/2019	817786		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1024865
877	05/20/2019	817786		VEHICLE SAFETY INSPECTION	1024865
877	05/20/2019	817786	DIRECT PURCHASE - BUS INSPECTI	Creditor #.:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O248377 Receiving #:257297 Date :2019-05-23	1025723
877	05/20/2019	817786		ANNUAL SAFETY INSPECTION SERIAL # ____J814814 GREEN_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1024865
877	05/20/2019	817964	Mechanic entered - Suspension Leaning frt too low	nsf sus rod slided back causing wrong height adjust. repositioned the rod clamp and secured the rod	1024865
877	05/20/2019	817963	Consumables		1025247
877	05/20/2019	817963	Consumables		1025247
877	05/20/2019	817963	Mechanic entered - Body Other FIRE extinguisher out of date	replaced the extinguisher supplied with bracket	1024865
877	05/18/2019	817696	CENTRA CUSHION CLIP LH		1024865
877	05/18/2019	817696	CENTRA CUSHION CLIP RH		1024865
877	05/18/2019	817696	SINGLE SEAT BASE		1024865
877	05/18/2019	817696	Mechanic entered - Vandalism Other Passenger seat cushion be	Replaced saeat cushion and clips	1024865
877	05/18/2019	817696	Consumables		1025092
877	05/18/2019	817696	Consumables		1025092
877	05/18/2019	817696	SWITCH- STOP-YELLOW (20485)		1024865
877	05/18/2019	817696	Mechanic entered - Elec and Light Next Stop Button broken	Replaced next stop button	1024865
877	05/15/2019	816950	Consumables		1024636
877	05/15/2019	816950	Consumables		1024636
877	05/15/2019	816950	Drv entered - BusMinder Damaged	double entry	1024372
877	05/13/2019	816515	Consumables		1024129
877	05/13/2019	816515	Consumables		1024129
877	05/13/2019	816515	Knob Control (372621 0372621)		1023972
877	05/13/2019	816515	Mechanic entered - Elec and Light Other light control switch	r/r switch knobok.	1023972
877	05/12/2019	815292	Please remove all old poster and fit MYKI has gone mobil	fleet support completed this campaign	1023224
877	05/10/2019	816109	Consumables		1023631
877	05/10/2019	816109	Consumables		1023631
877	05/10/2019	816109	Wheel Nut Retension Retension n/s/r wheels	wheel nut retensionok.	1023224
877	05/09/2019	815744		SERVICE MOISTURE EJECTOR	1023224
877	05/09/2019	815744		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST done.	1023224
877	05/09/2019	815583	Consumables		1023436
877	05/09/2019	815583	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O247580 Receiving #:256802 Date :2019-05-20 alpha to replace n/s/r glass as required x 1	1025092
877	05/09/2019	815583	Consumables		1023436
877	05/09/2019	815583	n/s rear glass smashed	PO#: O247580 - replaced by alpha glass	1023224
877	05/08/2019	815544	Consumables		1023436
877	05/08/2019	815544	Consumables		1023436
877	05/08/2019	815544	Mechanic entered - Wheels and Tyres Flat or Leaking POS 3 ty	Replaced pos 3 tyre with a runout tyre	1023224
877	05/04/2019	812812		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1022299
877	05/04/2019	812812		completed	1022299
877	05/01/2019	813148		PRE ANNUAL SAFETY INSPECTION CHECK	1022299
877	05/01/2019	813148	Consumables		1022299
877	05/01/2019	813148	Consumables		1022299
877	05/01/2019	813148	Drv entered - Body Drivers Seat Cover		1022299
877	05/01/2019	813225	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O246767 Receiving #:255367 Date :2019-05-03 carry out AC-A service as required	1022568
877	05/01/2019	813225		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - done by cold drive on 30/04/2019 PO#: O246767	1022299
877	04/30/2019	812678	Consumables		1022299
877	04/30/2019	812678	indicators not staying on and next stop buzzer nw	CHECKED BLINKS AND PAX STOPSCOULD NOT FAULT.	1022299
877	04/26/2019	812089	Consumables		1021935
877	04/26/2019	812089	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s	double entry	1021821
877	04/26/2019	812089	Wheels and Tyres Wheel Nut Retension osf	retensioned osf	1021821
877	04/23/2019	811500		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1020454
877	04/23/2019	811500		VEHICLE SAFETY INSPECTION	1020454
877	04/23/2019	811654	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)		1020454
877	04/23/2019	811654	Mechanic entered - Suspension Other o/s/f torque rod bushing	o/s/f torque rod u/s replaced o/s/f torque rod ok	1020454
877	04/23/2019	811654	BELT V-BELT COGGED TRI-POWER 17x2110mm		1020454
877	04/23/2019	811654	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1020454
877	04/23/2019	811654	Mechanic entered - A/C Heating Other front heat hose clamp c	tightened front heat hose clamps ok	1020454
877	04/23/2019	811654	Mechanic entered - A/C Heating Other a/c belt u/s	replaced a/c belts x2	1020454

877	04/23/2019	811501	Mechanic entered - A/C Heating Other a/c belt u/s			1020454
877	04/23/2019	811501	Mechanic entered - A/C Heating Other a/c belt u/s			1020454
877	04/23/2019	811654	Mechanic entered - Gearbox Driveline Other accum cylinder so	tightened accum cylinder solenoid retarder		1020454
877	04/23/2019	811654	Mechanic entered - Engine Other engine belt u/s	replaced engine belt ok		1020454
877	04/23/2019	811599	BELT TENSIONER			1020454
877	04/23/2019	811599	Mechanic entered - Engine Other Belt Tensioner Worn	Replaced Belt Tensioner		1020454
877	04/23/2019	811599	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)			1020454
877	04/23/2019	811599	Mechanic entered - Engine Other Idler Pulley Worn	Replaced Idler Pulley		1020454
877	04/23/2019	811501	Mechanic entered - Engine Other engine belt u/s			1020454
877	04/23/2019	811654	Consumables			1021439
877	04/23/2019	811654	Mechanic entered - Elec and Light Other dash fuel gauge ligh	replaced dash fuel gauge globe ok		1020454
877	04/23/2019	811654	Mechanic entered - Elec and Light Other dash air gauge light	replaced dash air gauge globe oki		1020454
877	04/23/2019	811654	Consumables			1021439
877	04/23/2019	811654	Mechanic entered - Body Other n/s/r seat back base broken	repaired n/s/r seat back base		1020454
877	04/23/2019	811654	Mechanic entered - Body Other driver door loose	repaired driver door ok		1020454
877	04/23/2019	811654	Mechanic entered - Body Other middle seat top pin out	put in middle seat top pins ok		1020454
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501	FILTER AIR FILTER (395773) AF25066			1020454
877	04/23/2019	811501	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)			1020454
877	04/23/2019	811501	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)			1020454
877	04/23/2019	811501	FILTER HYD COOLING FAN SCANIA L94UAB 1354074			1020454
877	04/23/2019	811501	FILTER FUEL FILTER SCANIA SR4 (1393640)			1020454
877	04/23/2019	811501	FILTER FUEL FILTER SCANIA SR4 (1372444)			1020454
877	04/23/2019	811501	Oil Filter SC S4 & K			1020454
877	04/23/2019	811501	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1020454
877	04/23/2019	811501	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1020454
877	04/23/2019	811501		CARRY OUT C SERVICE AS PER CHECK LIST		1020454
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501	Consumables			1021439
877	04/23/2019	811501		CARRY OUT B SERVICE AS PER CHECK LIST		1020454
877	04/20/2019	811424		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST - carried out fire safe as per check list		1020454
877	04/10/2019	809627	Consumables			1019245
877	04/10/2019	809627	REAR POSITION STOP LAMP LED (DESIGNLINE)			1019016
877	04/10/2019	809627	Mechanic entered - Elec and Light Exterior Lights o/s/r top	r/r park lightok.		1019016
877	03/18/2019	804192	Consumables			1014761
877	03/18/2019	804192	Mechanic entered - Elec and Light Other battery jump	jumped battery		1014493
877	03/15/2019	801718	Mechanic entered - Fluid Leaks Rear of bus coolant leak fro	removed radiator . sent away for repairs . auto cooling found radiator u.s . auto cooling supplied new radiator . replaced thermostat hydraulic oil lines replaced x 1 diesel fuel cooler hoses replaced x 2 . installed new radiator . cleaned inter cooler . installed inter cooler . filled with coolant filled with hydraulic fan oil . washe		1014493
877	03/13/2019	801718	THERMOSTAT 75/79 DEG - DOUBLE (40A3513)			1014493
877	03/13/2019	801718	Mechanic entered - Fluid Leaks Rear of bus leaking coolant.			1014493
877	03/13/2019	801718	SEAL THERMOSTAT SEAL SCANIA 1755952			1014493
877	03/12/2019	801718	DIRECT PURCHASE - ENGINE	Creditor #:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:O243068 Receiving #:251695 Date :2019-03-18 radiator u/s . auto cooling to supply new radiator		1014498
877	03/08/2019	801718	DIRECT PURCHASE - ENGINE	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O243039 Receiving #:252047 Date :2019-03-21 supply and make hydraulic oil hose as required		1015247
877	03/05/2019	801763	Mechanic entered - Fluid Leaks Other header tank low.	top up coolantroad testcould not fault leaks.		1013892
877	03/04/2019	801718	Mechanic entered - Fluid Leaks Rear of bus leaking coolant.	leaking coolant from radiator.		1013892
877	02/21/2019	799656	Mechanic entered - Elec and Light Exterior Lights	Replaced n/s headlight and park light globe		1012255
877	02/20/2019	799248	Vandalism glass film replaced x 5	film replaced by glass protect on p/o - O241586		1011714
877	02/19/2019	798709		VEHICLE SAFETY INSPECTION		1011714
877	02/19/2019	798709		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1011714
877	02/19/2019	798782	Consumables			1011976
877	02/19/2019	798782	Mechanic entered - Wheels and Tyres Other both rear tyres a	replaced both rear tyres air valve ok		1011714
877	02/19/2019	798782	Mechanic entered - Wheels and Tyres Other both rear tyres a	replaced both tyres air valve ok		1011714
877	02/19/2019	799248	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O241586 Receiving #:250026 Date :2019-02-22 X 5 FILM		1012481
877	02/19/2019	798782	INDICATOR STALK SCANIA SERIES 4 (1402448)			1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other indicator switch u/s	replaced indicator switch ok		1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other n/s/r school light n	replaced n/s/r school light ok		1011714
877	02/19/2019	798782	SCHOOL LIGHT ASSY PANEL MOUNT			1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other front n/s pax stop	repaired n/s/f pax stop bell switch wires ok		1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other n/s/r school light n	replaced n/s/r school light ok		1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other front n/s pax stop	repaired n/s/f pax stop bell switch ok		1011714
877	02/19/2019	798782	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok		1011714
877	02/19/2019	798782	Consumables			1011976
877	02/19/2019	798782	Mechanic entered - Body Other n/s/f seat base cut	repaired n/s/f seat base ok		1011714
877	02/19/2019	798782	Mechanic entered - Body Other front door top cover off	replaced front door top cover		1011714
877	02/19/2019	798782	EDGE STEP EDGE YELLOW 43mm			1011714
877	02/19/2019	798782	Mechanic entered - Body Other n/s/f step edge missing	replaced n/s/f step edge ok		1011714
877	02/19/2019	798782	Mechanic entered - Body Other front door top cover off	replaced front door top cover screws ok		1011714
877	02/19/2019	798782	Mechanic entered - Body Other driver back modesty panel loos	repaired driver back modesty panel ok		1011714
877	02/19/2019	798782	Mechanic entered - Body Other middle seat top pins out	put in middle seat top pins ok		1011714
877	02/19/2019	798782	Mechanic entered - Body Other n/s/f staunchion pole bolts mi	replaced n/s/f staunchion pole bolts ok		1011714
877	02/19/2019	798782	Mechanic entered - Brakes Other o/s/r brak booster u/s			1011714
877	02/19/2019	798782	BRAKE BOOSTER REAR OUTER SIDE SCANIA L94			1011714
877	02/19/2019	798782	Mechanic entered - Brakes Other o/s/r brak booster u/s	replaced o/s/r brake booster ok		1011714
877	02/13/2019	797471	Mechanic entered - Elec and Light Indicators Not Working on	fit globe.		1010411
877	02/13/2019	797470	Mechanic entered - Elec and Light Other desto not working	could not fault.		1010411
877	02/09/2019	796763	Consumables			1010184
877	02/09/2019	796763	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	no faults found		1009905
877	02/04/2019	795513	Drv entered - A/C Heating Not Cooling	checked operation of a/c . adjusted controls . checked operation all okay		1008976
877	02/01/2019	794853		TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.		1008578
877	01/22/2019	792764	Consumables			1007504
877	01/22/2019	792763	Consumables			1007504
877	01/22/2019	792764	Mechanic entered - Wheels and Tyres Wheel Nut Retension bot	double entry - job carried out on work order - 792763		1007139
877	01/22/2019	792763	Mechanic entered - Wheels and Tyres Wheel Nut Retension rea	carried out retorque as required		1007139
877	01/21/2019	792609	Consumables			1007375
877	01/21/2019	792609	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok		1007139
877	01/21/2019	792609	INVERTER 24 Volt 36 Watt MAN			1007139
877	01/21/2019	792609	Mechanic entered - Elec and Light Other n/s middle saloon li	replaced n/s middle saloon light inveterok		1007139
877	01/21/2019	792609	Mechanic entered - Body Other wheel chair ramp broken	repaired wheel chair ramp ok		1007139
877	01/21/2019	792568	Please remove old 2018 fare decals and fit new 2019 fare de	carried out campaign as required		1007139
877	01/21/2019	792461	Consumables			1007375
877	01/21/2019	792461	Consumables			1007375

877	01/21/2019	792461	FILTER FUEL FILTER SCANIA SR4 (1372444)		1007139
877	01/21/2019	792461	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1007139
877	01/21/2019	792461	Oil Filter SC S4 & K		1007139
877	01/21/2019	792461	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1007139
877	01/21/2019	792461		CARRY OUT B SERVICE AS PER CHECK LIST	1007139
877	01/08/2019	789861	Consumables		1005557
877	01/08/2019	789861	Elec and Light - desto nw reported by geoff	checked could not fault	1004860
877	01/06/2019	789525	Mechanic entered - Body Front_Door Operation Faulty rear do	adjusted rear passenger door . checked door brake operation and sensrive edge . all working okay . checked with lou	1004860
877	01/01/2019	783143	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O235816 Receiving #:247432 Date :2019-01-22 repair passenger grab handle requiring securing to the roof as required	1007375
877	01/01/2019	786456	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O237153 Receiving #:247657 Date :2019-01-24 replace smashed n/s/r glass as required	1007748
877	12/18/2018	786564	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	retorque o/s/r wheel nuts.	1002056
877	12/18/2018	786564	Consumables		1002683
877	12/17/2018	786299		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1002056
877	12/17/2018	786299		VEHICLE SAFETY INSPECTION	1002056
877	12/17/2018	786359	Consumables		1002531
877	12/17/2018	786359	TYRE 295/80R22.5 RECAP		1002056
877	12/17/2018	786359	TYRE 295/80R22.5 RECAP		1002056
877	12/17/2018	786359	Mechanic entered - Wheels and Tyres Worn	Replaced o/s/r/i and o/s/r/o tyre at 1'002'523Km's	1002056
877	12/17/2018	786378	Consumables		1002531
877	12/17/2018	786359	Consumables		1002531
877	12/17/2018	786359	Mechanic entered - Elec and Light Other dash air gauge light	replaced dash air gauge light globe ok	1002056
877	12/17/2018	786359	Mechanic entered - Elec and Light Other n/s head light u/s	R&R both high beams o/s n/s - satya	1002056
877	12/17/2018	786359	Mechanic entered - Elec and Light Other o/s head light u/s	checked okay	1002056
877	12/17/2018	786359	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok	1002056
877	12/17/2018	786378	Mechanic entered - Elec and Light Exterior Lights Headlamps	part has been ordered	1002056
877	12/17/2018	786359	Consumables		1002531
877	12/17/2018	786359	Consumables		1002531
877	12/17/2018	786359	HL1053 Head Lamp Insert	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O237123 Receiving #:245133 Date :2018-12-19	1002531
877	12/17/2018	786359	Mechanic entered - Body Other middle staunchion pole bolt lo	tightened middle staunchion pole bolts ok	1002056
877	12/17/2018	786359	Mechanic entered - Body Other rear smoking decal u/s	replaced rear smoking decal ok	1002056
877	12/17/2018	786359	Mechanic entered - Body Other o/s/f staunchion pole bolt mis	replaced o/s/f staunchion pole bolts ok	1002056
877	12/17/2018	786359	Mechanic entered - Body Other middle seat loose	tightened middle seat bolts ok	1002056
877	12/17/2018	786456	Accident - n/s/r glass smashed	replaced by alpha glass - O237153	1002056
877	12/13/2018	785896	Accident#:46969 - Ops Entered - Accident - Bus hits 3rd Par	Completed by ECTB. Bus sent on 26/7/2018.	1001793
877	12/03/2018	783567	Consumables		999782
877	12/03/2018	783567	INDICATOR STALK SCANIA SERIES 4 (1402448)		999538
877	12/03/2018	783567	indicator stalk u/s	R&R indicator stalk checked operation all okay	999538
877	12/03/2018	783568	Consumables		999782
877	12/03/2018	783568	Consumables		999782
877	12/03/2018	783568	internal mirror loose	tightend and adjusted internal drivers mirror	999538
877	12/01/2018	783143	Consumables		998948
877	12/01/2018	783143	Consumables		998948
877	12/01/2018	779959	Consumables		998948
877	12/01/2018	779959	Consumables		998948
877	12/01/2018	783143	Mechanic entered - Body Other damaged o/s/f body.Overhead	repaired by mick - O235816	998685
877	12/01/2018	779959	Body - o/s/r side hatch struts u/s	R&R gas struts x 2	998685
877	12/01/2018	785896	DIRECT PURCHASE ACCIDENT #4696	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O236948 Receiving #:245330 Date :2018-12-20	1002947
877	11/29/2018	782618	CCTV carry out 6 month service - bewere johnny	carried out by johnny from bewere - O235611	998196
877	11/26/2018	779959	Consumables		997991
877	11/26/2018	779959	K500-18-500nm Gas Struts	Creditor #:VB-MCN001 MCNAUGHTANS P/O #:O235245 Receiving #:243029 Date :2018-11-26	997728
877	11/19/2018	780315	Consumables		996655
877	11/19/2018	780315	Body - drivers blind not working	repaired drivers side sun blind . checked operation all okay	996655
877	11/16/2018	779994	Consumables		996243
877	11/16/2018	779994	Mechanic entered - Elec and Light Other ns fluro nw	replaced fluro ok	996090
877	11/16/2018	779994	Consumables		996243
877	11/16/2018	779994	Mechanic entered - Body Other driver's modesty loose	secured ok	996090
877	11/16/2018	779994	Mechanic entered - Body Other driver's door top hinge loose	secured ok	996090
877	11/16/2018	779994	Mechanic entered - Body Other NS BIN LUGGAGE LOOSE	secured ok	996090
877	11/01/2018	767285	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O229866 Receiving #:243368 Date :2018-11-29 replace glass film as required	998469
877	11/01/2018	782618	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWED01 BWERE ELECTRICS PTY LTD P/O #:O235611 Receiving #:243487 Date :2018-11-29	998469
877	11/01/2018	783143	Consumables		993596
877	11/01/2018	783143	DIRECT PURCHASE - BODYWORK	Creditor #:VB-BUNNINGS BUNNINGS KNOX P/O #:O235815 Receiving #:243699 Date :2018-12-03 purchase self drilling screws as required	999538
877	10/29/2018	776330	Consumables		993046
877	10/29/2018	776330	Consumables		993046
877	10/29/2018	776330	Mechanic entered - Body Drivers Seat Controls seat backrest	reposition seat to seat base box.	992623
877	10/27/2018	776130		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	992623
877	10/27/2018	776130		VEHICLE SAFETY INSPECTION	992623
877	10/27/2018	776130	Consumables		992978
877	10/27/2018	776130	Consumables		992978
877	10/27/2018	776149	Consumables		992978
877	10/27/2018	776149	Consumables		992978
877	10/27/2018	776130	Ops Entered - Fault - Body Passenger Seat Torn - Route: -		992623
877	10/27/2018	776149	PLASTIC YELLOW KNOB		992623
877	10/27/2018	776149	Mechanic entered - Body Drivers Seat Controls	fitted missing knobs for drivers seat	992623
877	10/26/2018	775788	Consumables		992978
877	10/26/2018	775788	o/s front top park light lens has come off	extract dislodged lensrefit to lightrefit lighttok.	992623
877	10/17/2018	763604	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		991179
877	10/10/2018	772250	Consumables		990029
877	10/10/2018	772250	Mechanic entered - Elec and Light Exterior Lights o/s/top fr	fit globe.	989592
877	10/10/2018	772348	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	carried out campaign as required	989592
877	10/09/2018	771828	Consumables		989877
877	10/09/2018	771828	Mechanic entered - Elec and Light Exterior Lights o/s/f/t pa	fit globe.	989592
877	10/09/2018	771819	Consumables		989877
877	10/09/2018	771819	Consumables		989877
877	10/09/2018	771819	Ops Entered - Fault - Body Drivers Seat Controls - Route: 7	free up sizer liftnow ok.	989592
877	10/05/2018	771236	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	carried out campaign as required	989188
877	09/26/2018	769233		CARRY OUT FIRE EXTINGUISHER TEST & TAG	987858
877	09/26/2018	769233		closed off as completed as per instruction from paul bell	987858
877	09/18/2018	767285	Vandalism glass protect to replace 3 x glass film as requir	glass protect p/o - O229866	985316
877	09/17/2018	766945	Consumables		986171
877	09/17/2018	766945	n/sf blinker not working	repositioned globe. checked operation all okay	985316
877	09/13/2018	766342	Campaign 07/17 WIFI CCTV UPGRADE.Cordinate upgrade of	6months service wi-fi and defects done by Johnny	984793
877	09/12/2018	766562	CCTV - 6months service and wi-fi connection issues	Johnny carried out cctv 6months service and fixed wi-fi connection issues	984793

877	09/12/2018	760287	Consumables			984793
877	09/12/2018	760287	Consumables			984793
877	09/12/2018	760287	O-RING KIT OIL SPINNER FILTER SCANIA UP TO ENG #6203049			984793
877	09/08/2018	763604	Mechanic entered - Suspension Other rear D rubber u/s	replaced rear D rubber ok		984263
877	09/08/2018	763604	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)			984263
877	09/08/2018	763604	Mechanic entered - Engine Other engine fan pump oil leaks	replaced engine fan pump motor ok		984263
877	09/06/2018	760320	BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)			984023
877	09/06/2018	760320	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)			984023
877	09/04/2018	763604	Mechanic entered - Gearbox Driveline Other traNSMISSION seal	replaced transmission rear seal okl		983276
877	09/04/2018	760370		put in fuel coolertightened fuel cooler bracket bolttightened fuel cooler hose clamps put in intercooler tightened intercooler pipe clamp tightened intercooler bracket boltsput in coolantput in engine fan oil ok		983276
877	09/04/2018	760370	hydraulic fan motor leaking	put in engine fan motor pipeclamptightened engine fan motor pipes put in radiator coolant hosetightened radiator coolant hose clamps put in intercooler pipehose put in engine fan motor coolertightened engine fan cooler bracket bolttightened fan cooler pipe		983276
877	09/04/2018	763604	Mechanic entered - Engine Other engine fan pump oil leaks	replaced engine fan motor ok		983276
877	09/03/2018	763562		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		983276
877	09/03/2018	763562		VEHICLE SAFETY INSPECTION		983276
877	09/03/2018	763604	WASHER SEALING SC SUMP (1356776)			983276
877	09/03/2018	763604	Mechanic entered - Gearbox Driveline Other diff top pluge oi	replaced diff top pluge washer ok		983276
877	09/03/2018	763604	Mechanic entered - Engine Other engine fan pump oil leaks	replacedengine fan motor ok		983276
877	09/03/2018	763604	Oil Filter SC S4 & K			983276
877	09/03/2018	760370	hydraulic fan motor leaking	removed radiator removed hydraulic fan motor cleaned all part puit in radiatortightened radiator bracket bolts		983276
877	09/03/2018	763604	Mechanic entered - Engine Other engine oil filter leaks	replaced engine oil filter ok		983276
877	09/03/2018	763604	Consumables			983876
877	09/03/2018	763604	Mechanic entered - Elec and Light Other dash R.P.M gauge lig	replaced dash R.P.M gauge light globe ok		983276
877	09/03/2018	763604	Mechanic entered - Elec and Light Other fax switch loose	tightened n/s/f fax switch screws ok		983276
877	09/03/2018	763604	Consumables			983876
877	09/03/2018	763604	Mechanic entered - Body Other o/sn/s inside top panel screw	tightened o/sn/s top panel screws ok		983276
877	09/03/2018	763604	Mechanic entered - Body Other n/s middle seat cover off	repaired n/s middle seat clover ok		983276
877	09/01/2018	763143	Consumables			983694
877	09/01/2018	763143	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O228454 Receiving #:236381 Date :2018-09-05 rectify dtent springs not working in drivers seat slide adjustment as required		983983
877	08/31/2018	763189	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			983276
877	08/31/2018	763189	BELT TENSIONER			983276
877	08/31/2018	763189	Mechanic entered - Engine Belts_Loose Noisy Missing belt tor	Replaced eng belt and tensioner; road tested ok		983276
877	08/31/2018	763143	Consumables			983694
877	08/31/2018	763143	Mechanic entered - Body Drivers Seat Controls base loose	drivers seat base was removed from bus 877 and sent away for repair . the drivers seat from bus 791 which was VOR at the time was installed into bus 791. 877 was repaired on O228454 and installed back into bus 791 checked operation all okay		983276
877	08/31/2018	763143	Mechanic entered - Body Drivers Seat Controls base loose	swaped seat from 791 and sent defected seataway		983276
877	08/27/2018	761881	Breakdown#:35441 - Ops Entered - Breakdown - Breakdown Warni	bus had a broken alt belt. organized Moorabbin brekdown and the belt was replaced onsite. inspected at workshop and put back on service. (friday arvo)		982497
877	08/24/2018	761695	Consumables			982497
877	08/24/2018	761695	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			982497
877	08/24/2018	761695	Elec and Light - warning lights on dash	attended to the breakdown at Monash Uni. checked and found alt belt come off. replaced belt from Oakleigh stock. checked all good		982497
877	08/24/2018	761707	Mechanic entered - Breakdown Other main belt broken	okleigh bus go oakleigh pick up belt and repit in monash uni bus stand put back to service go back to oakleigh and hand over other belt come to moorabbin transit		982497
877	08/22/2018	761179	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	fitted DC 5V outlet socket and wired up		982405
877	08/21/2018	760370	40N1600 Fan Motor Assy	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O227490 Receiving #:235140 Date :2018-08-22		982405
877	08/20/2018	760320	Mechanic entered - Wipers and Washers Other wiper washer not	repaired o/s wiper washer ok		981574
877	08/20/2018	760320	BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)			981574
877	08/20/2018	760320	Mechanic entered - Suspension Other front both D rubber u/	replaced front both D rubber ok		981574
877	08/20/2018	760320	Mechanic entered - Gearbox Driveline Other diff pluge u/s	replaced diff pluge ok		981574
877	08/20/2018	760320	PLUG MAGNETIC (2165310)			981574
877	08/20/2018	760320	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)			981574
877	08/20/2018	760320	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok		981574
877	08/20/2018	760320	Mechanic entered - Engine Other engine belt tensioner u/s	replaced engine belt tensioner ok		981574
877	08/20/2018	760320	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113			981574
877	08/20/2018	760320	Consumables			982179
877	08/20/2018	760320	SCHOOL LIGHT ASSY PANEL MOUNT			981574
877	08/20/2018	760320	Mechanic entered - Elec and Light Other o/s/r school light u	repaired school light wires replaced school light ok		981574
877	08/20/2018	760514	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	carried out campaign as required		981574
877	08/20/2018	760287	Consumables			982179
877	08/20/2018	760287	Consumables			982179
877	08/20/2018	760287	Consumables			982179
877	08/20/2018	760287	FILTER FUEL FILTER SCANIA SR4 (1372444)			981574
877	08/20/2018	760287	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			981574
877	08/20/2018	760287	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			981574
877	08/20/2018	760287	Oil Filter SC S4 & K			981574
877	08/20/2018	760287		CARRY OUT B SERVICE AS PER CHECK LIST		981574
877	08/15/2018	759487	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	carried out campaign as required		981087
877	08/14/2018	748652	Consumables			981087
877	08/14/2018	748652	Body - drivers blind is broken	ordered		980619
877	08/03/2018	756973		TRANSMISSION CHECK AS PER CHECK LIST		978970
877	08/01/2018	756343	Ops Entered - Fault - Suspension Kneel/ Raise - Route: - A	road test to confirm fault. fit new front leveling block. all ok		978505
877	08/01/2018	756343	SOLENOID VALVE (REAR) 481830			978505
877	08/01/2018	756343	VALVE FRT LEVELLING CNTRL VALVE VOLVO B10BLE 9957009			978505
877	08/01/2018	748652	CONSUMABLE - DELIVERY CHARGE	Creditor #:VB-CUS001 CUSTOM CARE P/O #:O223855 Receiving #:235879 Date :2018-08-30		983276
877	08/01/2018	748652	Driver's Blind -1100x600	Creditor #:VB-CUS001 CUSTOM CARE P/O #:O223855 Receiving #:235879 Date :2018-08-30		983276
877	08/01/2018	760370	Consumables			978970
877	08/01/2018	760370	Consumables			978970
877	08/01/2018	760370	Consumables			978970
877	08/01/2018	760370	SEAL REARTRANSMISSION SR 4 SC	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O228606 Receiving #:236119 Date :2018-09-03		983694
877	07/30/2018	755702	Mechanic entered - Body Other drivers blind falling off	secure blind.		977775
877	07/30/2018	755702	Consumables			978505
877	07/28/2018	755594	LENS ROUND NARVA (2.9800.09)			977775
877	07/28/2018	755594	Mechanic entered - Elec and Light Indicators Not Working	replaced indicator lense		977775
877	07/28/2018	755594	Consumables			978036
877	07/25/2018	754665	Mechanic entered - Suspension Kneel/ Raise stuck on kneel.	road test for speed signal to activateand self level to kick innow ok.		977138
877	07/23/2018	746859	Consumables			977138
877	07/23/2018	746859	BUCKLE SEAT BELT TWIN WIRE GREY (SOB2123GY) (340446)			976916
877	07/21/2018	748652	Consumables			976767
877	07/21/2018	748652	Ops Entered - Fault - Body Windows Side - Route: - Dep Mo	double entry		976525
877	07/21/2018	748652	Body - drivers blind is broken	FIT NEW DRIVERS SUN BLIND.		976525
877	07/21/2018	748652	Drv entered - Body Windows Side	assisted cdf		976525
877	07/19/2018	753418	Mechanic entered - Elec and Light Other RPD dash switch dis	done by BW electrics on 19/07/2018 not requested for a PO		976372
877	07/19/2018	753418	Consumables			976525
877	07/18/2018	753045	Mechanic entered - Suspension Other rears stuck on raise.	release air rear bagsroad testok.		976058
877	07/17/2018	752959	Mechanic entered - Body Other back hatch open itself.	r/r back hatch shock absoberok.		976058
877	07/17/2018	752959	STRUT GAS STAY 600Nm 540mm LONG			976058
877	07/17/2018	752959	Consumables			976058

877	07/14/2018	752778	Vandalism - clean and paint interior graffiti as required	cleaned and painted interior graffiti as required	975780
877	07/13/2018	752140	Breakdown # 35154 - Air System Fault	no fault as checked on 21/07/2018 during the sun blind job	975373
877	07/13/2018	752091	Mechanic entered - Elec and Light Exterior Lights n/s/f bott	fit globe.	975373
877	07/13/2018	752091	Consumables		975780
877	07/06/2018	750692	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	retorqued wheels as required to oem spec	973770
877	07/06/2018	750692	Consumables		974254
877	07/05/2018	750449	WIPER REFILL 1000mm MULTI FIT		973770
877	07/05/2018	750449	Mechanic entered - Wipers and Washers Other both wiper rubbe	replaced both wiper rubber ok	973770
877	07/05/2018	749775	2117367 End Yolk	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O223737 Receiving #:231210 Date :2018-07-06	974103
877	07/05/2018	750426	Mechanic entered - Body Drivers Seat Controls lumbar support	reconnected air hoses and tested all ok	973770
877	07/05/2018	750426	Consumables		974103
877	07/05/2018	750050	Consumables		974103
877	07/05/2018	750050	Mechanic entered - Body Front_Door Operation Faulty front do	adjustyed rebound pressues all ok	973770
877	07/05/2018	750050	Mechanic entered - Body Front_Door Operation Faulty front do	adjusted rebound pressures and tested all ok	973770
877	07/05/2018	750421	Mechanic entered - Brakes Other brakes wound off when towed	wound brake boosters back on and adjusted. road and brake tested all ok	973770
877	07/04/2018	750078	Consumables		973962
877	07/04/2018	750078	TYRE 295/80R22.5 NEW		973770
877	07/04/2018	750078	o/s/f tire u.s	replaced o/s/f tyreretorqued o/s/f wheel nuts ok	973770
877	07/04/2018	750145	AIRBAG REAR SCANIA K310		973770
877	07/04/2018	750145	Suspension - o/s/r/r air bag	replaced o/s/r/r air bag ok	973770
877	07/04/2018	750145	FITTING ELBOW UNION		973770
877	07/04/2018	750085	MOUNT A/C COMPRESSOR LARGE DENSO		973770
877	07/04/2018	750085	a/c mounts u/s	replaced a/c mount x2	973770
877	07/04/2018	749604	diff pinion seal leaking	replaced diff yoke replaced diff seal ok	973770
877	07/04/2018	749775	192032 Door Sensor Digital Dis	Creditor #:VB-FES010 FESTO PTY LTD P/O #:O223741 Receiving #:231209 Date :2018-07-06	974103
877	07/04/2018	749775	Mechanic entered - Engine Other not building air		973770
877	07/04/2018	749784	Consumables		973962
877	07/04/2018	750050	Mechanic entered - Body Front_Door Operation Faulty front do	started diagnosis and repair on front doors	973770
877	07/04/2018	750050	FESTO DOOR VALVE MINI TYPE		973770
877	07/04/2018	749784	Body - drivers seat back no air supply	fit new air dryer assembly and conected all hoses	973770
877	07/03/2018	749775	Mechanic entered - Engine Other not building air	remove faulty receiver drierregulator unit. fit new air dryer assembly and conected all hoses	973770
877	07/03/2018	749784	air dryer u/s	completed on work order - 749775	973770
877	07/02/2018	749518		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	973770
877	07/02/2018	749518		VEHICLE SAFETY INSPECTION	973770
877	07/02/2018	749504	Consumables		973962
877	07/02/2018	749504	TYRE 295/80R22.5 RECAP		973770
877	07/02/2018	749504	Mechanic entered - Wheels and Tyres Other n/s/r tyre u/s	replaced n/s/r tyres ok	973770
877	07/02/2018	749518	Consumables		973962
877	07/02/2018	749518	Ops Entered - Fault - Wheels and Tyres Flat or Leaking - R	replaced with runout tyre . tensioned wheel nuts all okay	973770
877	07/02/2018	752140	DIRECT PURCHASE - TOWING	Creditor #:VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:O224403 Receiving #:231905 Date :2018-07-16 after hours tow from Clayton Road to Oakleigh Depot	975780
877	07/02/2018	749504	FILTER AIR FILTER (395773) AF25066		973770
877	07/02/2018	749504	Mechanic entered - Engine Other engine air filter u/s	replaced engine air filter ok	973770
877	07/02/2018	749504	Consumables		973962
877	07/02/2018	749504	REVERSE ALARM 12-24v 72608		973770
877	07/02/2018	749504	BATTERY 800CCAPOS ON LHS		973770
877	07/02/2018	749504	LAMP HEADLAMP MK3 VOLVO B10M		973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Interior Lights dash rpm l	r/r globesok.	973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Interior Lights dash switc	r/r globesok.	973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Reverse Buzzer reverse buz	r/r reverse buzzerok.	973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Other both head light u/s	r/r head lightok.	973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Other n/s/f step light not	replaced step light ok	973770
877	07/02/2018	749504	Mechanic entered - Elec and Light Other battery u/s	replaced battery x2 ok	973770
877	07/02/2018	749504	STOP TAIL LIGHT ASSEMBLY		973770
877	07/02/2018	749504	Consumables		973962
877	07/02/2018	749504	Mechanic entered - Body Other rear modesty panel loose.	fixed modesty panelok.	973770
877	07/02/2018	749518	Consumables		973962
877	07/02/2018	749518	Ops Entered - Fault - Body Drivers Seat Cover - Route: -		973770
877	07/02/2018	749504	Mechanic entered - Air System Other front air leaks	repaired front air hose fitting ok	973770
877	07/02/2018	749518	Consumables		973962
877	07/02/2018	749518	Consumables		973962
877	07/02/2018	749518	Consumables		973962
877	07/02/2018	749518		CARRY OUT A SERVICE AS PER CHECK LIST	973770
877	06/28/2018	748926	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	carried out campaign as required	973507
877	06/22/2018	747479	Body - seat belt not working	untwisted seat belt checked all okay	972523
877	06/22/2018	747479	Consumables		972750
877	06/22/2018	747479	Consumables		972750
877	06/21/2018	746859	Consumables		972523
877	06/21/2018	746859	Consumables		972523
877	06/21/2018	746859	Ops Entered - Fault - Body Drivers Seat Belt - Route: 703b	fit new buckle	972053
877	06/21/2018	746999	Ops Entered - Fault - Body Drivers Seat Belt - Route: 703b	adjusted drivers seat checked operation all okay	972053
877	06/21/2018	746999	Consumables		972523
877	06/21/2018	746999	Consumables		972523
877	06/13/2018	744979	Consumables		970718
877	06/13/2018	744979	Ops Entered - Fault - Wheels and Tyres Flat or Leaking - Ro	pumped tire up to proper pressure	970232
877	05/24/2018	741042	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	carried out campaign as required	966232
877	05/21/2018	740047		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	965686
877	05/21/2018	740047		VEHICLE SAFETY INSPECTION	965686
877	05/21/2018	740047	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O220414 Receiving #:227956 Date :2018-05-23 annual inspections	965988
877	05/21/2018	740047		ANNUAL SAFETY INSPECTION SERIAL # _____serial J 124706_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	965686
877	05/21/2018	739790	Consumables		965797
877	05/21/2018	739790	Mechanic entered - Elec and Light Other battery jump	jumped battery ok	965686
877	05/21/2018	739605	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INST	completed installing program using the laptop	965686
877	05/18/2018	739605	KIT SWITCH OVERRIDE RPD		965686
877	05/18/2018	739605	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INST	installed RPD kit; node needs to be programmed. laptop nw	965686
877	05/16/2018	738930	Breakdown#:34912 - Ops Entered - Breakdown - Breakdown Air S	built up air and checked for leaks. could not fault	964764
877	05/16/2018	738930	Breakdown#:34912 - Ops Entered - Breakdown - Breakdown Air S	built up air and checked for leaks. could not fault	964764
877	05/01/2018	731450	DECAL NO SMOKING 130x130mm		962713
877	04/30/2018	735492	Mechanic entered - Brakes Other n/s/f brake slack adjust u/s	replaced n/s/f brake slack adjust okdrain air tank road tested okbrake tested ok adjusted all beake lininngs	962265
877	04/30/2018	735492	SLACK ADJUSTER FRONT NEAR SIDE (1789568)		962265
877	04/30/2018	735549		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	962265
877	04/28/2018	735373		PRE ANNUAL SAFETY INSPECTION CHECK done.	962265
877	04/28/2018	735450	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	make & fitted patch & gasketok.	962265
877	04/28/2018	735450	Consumables		962474

877	04/28/2018	735450	Mechanic entered - Body Other pax seat braket bolts loose.	tighten boltsok.	962265
877	04/28/2018	735424	Mechanic entered - Brakes Other uneven worn brakes 35%-52%	this is impossible to say on this bus as no dash reading. could have been a wrong bus number entered	962265
877	04/28/2018	735373	Consumables		962474
877	04/28/2018	735373		done	962265
877	04/28/2018	735373	Consumables		962474
877	04/28/2018	735373		CARRY OUT A SERVICE AS PER CHECK LIST	962265
877	04/08/2018	731507	Consumables		958204
877	04/08/2018	731507	Mechanic entered - Wheels and Tyres Wheel Nut Retension off	carried out retorque as required	957998
877	04/07/2018	731385		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	957998
877	04/07/2018	731385		VEHICLE SAFETY INSPECTION safety completed	957998
877	04/07/2018	731452	Mechanic entered - Wipers and Washers Washers Not Working	repaird wiper washers unblocked tubes filled water	957998
877	04/07/2018	731447	Consumables		958204
877	04/07/2018	731447	TYRE 295/80R22.5 RECAP		957998
877	04/07/2018	731447	Mechanic entered - Wheels and Tyres Worn	replaced osi tyre tenstioned wheel nuts	957998
877	04/07/2018	731450	DECAL NO SMOKING 130x130mm		957998
877	04/07/2018	731450	Mechanic entered - Vandalism Other	replaced no smoking decal	957998
877	04/07/2018	731451	Consumables		958204
877	04/07/2018	731451	Mechanic entered - Elec and Light Exterior Lights	replaced door step light globe	957998
877	04/07/2018	731449	Consumables		958204
877	04/07/2018	731448	Consumables		958204
877	04/07/2018	731449	Mechanic entered - Body Other seats	affixed priortity seating seats fitted pins	957998
877	04/07/2018	731448	Mechanic entered - Body Other modesty	repair modesty panel secure	957998
877	03/27/2018	729405	Consumables		956148
877	03/27/2018	729405	Mechanic entered - Elec and Light Exterior Lights n/s/t park	replaced globe	955639
877	03/27/2018	729405	Mechanic entered - Elec and Light Exterior Lights n/s/t park	replaced globe	955639
877	03/24/2018	729010	Consumables		955547
877	03/24/2018	729010	Mechanic entered - Elec and Light Exterior Lights n/s/f par	R&R globe . checked operation all okay	955315
877	03/19/2018	727530	Consumables		954828
877	03/19/2018	727530	Mechanic entered - Body Other rear door mirror broken	fit second hand mirror. all ok	953991
877	03/17/2018	727441	AIR CONDITIONING REPAIR	Creditor #:\VB-COL004 COLD DRIVE PTY LTD P/O #:O216022 Receiving #:\223841 Date :2018-03-27 carry out AC-B service as required REPLACE DRYER REPLACE COMPRESSOR OIL REGAS	955905
877	03/17/2018	727441		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - done by cold drive on 17/03/2018 PO O216022	953991
877	03/17/2018	727441		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	953991
877	03/14/2018	726725	CCTV not recording	cctv system was completely replaced with new gen3 system by johnnry from bewere on 13-3-18	953745
877	03/14/2018	726725	Ops Entered - Fault - CCTV System Noisy - Route: 703 - Cen	double entry	953745
877	03/10/2018	726152	Consumables		953639
877	03/10/2018	726152	Mechanic entered - Wheels and Tyres Wheel Nut Retension NEA	retensioned nsr wheel nuts as per specs	953206
877	03/10/2018	726172	Consumables		953639
877	03/10/2018	726172	LIGHT SIDE INDICATOR L/H		953206
877	03/10/2018	726172	Body-osf cnr damaged indicater smashed	removed osf cnr panel. replaced head light (not booked as per lan) and indicator.	953206
877	03/09/2018	725858	Consumables		953467
877	03/09/2018	725858	Mechanic entered - Wheels and Tyres Flat or Leaking n/s/rea	job completed on work order - 725698	953206
877	03/08/2018	725698	Consumables		953206
877	03/08/2018	725698	Mechanic entered - Wheels and Tyres Flat or Leaking	replace nsr inner tyre replace ns rear inner tyre with a good runout tenstioned wheel nuts	952835
877	03/08/2018	725521	FESTO DOOR CONTROL VALVE (173125)		952835
877	03/08/2018	725521	Breakdown#:\34600 - Ops Entered - Breakdown - Breakdown Passe	fit new door valve. testyed operation of the door all ok	952835
877	03/06/2018	723301	Consumables		952835
877	03/06/2018	723301	Mechanic entered - Body Rear_Door Operation Faulty rear door	replaced rear door rebound valve by Ben Were	952170
877	03/05/2018	724556	Consumables		952673
877	03/05/2018	724207	Consumables		952673
877	03/05/2018	724556	Elec and Light Next Stop Button button behind back door	repaired on work order 724207	952170
877	03/05/2018	724207	Mechanic entered - Elec and Light Next Stop Button pax bell	fit new pax bell. tested operation.all ok	952170
877	03/05/2018	724207	SWITCH- STOP-YELLOW		952170
877	03/05/2018	724504	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	carried out campaign as required	952170
877	03/03/2018	724391	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelsiem painting as required	952407
877	03/01/2018	723301	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-FES010 FESTO PTY LTD P/O #:O214867 Receiving #:\222169 Date :2018-03-02 supply a door rebound valvePN2250	952170
877	02/28/2018	723301	Mechanic entered - Body Rear_Door Operation Faulty rear door	repair wiring at door switch. PO#:\ O214867 FESTO REBOUND VALVE	952049
877	02/28/2018	723301	Consumables		952049
877	02/16/2018	720286		TRANSMISSION CHECK AS PER CHECK LIST trans check as per checklist.	950174
877	02/13/2018	719614	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	carried out campaign as required	949684
877	02/12/2018	719254		CARRY OUT FIRE EXTINGUISHER TEST & TAG	949190
877	02/12/2018	719235		CARRY OUT FIRE EXTINGUISHER TEST & TAG	949190
877	02/12/2018	719254		inspection carried out by ATS fire services - O213090	949190
877	02/12/2018	719235		inspection carried out by ATS fire services - O213090	949190
877	02/10/2018	718791	Consumables		949415
877	02/10/2018	718791	Consumables		949415
877	02/10/2018	718791		CARRY OUT A SERVICE AS PER CHECK LIST completed A service as per checklist. road and brake tested all ok	949190
877	02/10/2018	718791	Consumables		949415
877	02/06/2018	717620	Consumables		948721
877	02/06/2018	717620	Mechanic entered - Elec and Light Other n/s/f indicator ligh	replaced n./s/f indicator light ok	948022
877	02/06/2018	717620	LIGHT SIDE INDICATOR L/H		948022
877	02/04/2018	717200	Consumables		948250
877	02/04/2018	717200	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	Assisting	948022
877	02/04/2018	717200	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	RETENSIONED NSR WHEEL NUTS AS PER SPECS	948022
877	02/03/2018	717145	Service	ASSISTED AJW	948022
877	02/03/2018	717145		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	948022
877	02/03/2018	717145		VEHICLE SAFETY INSPECTION completed saftety inspection as per checklist. wheel nuts torqued to OEM spec road and brake tested all ok	948022
877	02/03/2018	717148	Consumables		948250
877	02/03/2018	717147	Consumables		948250
877	02/03/2018	717148	WHEEL NUT SCANIA L94 (2285273)		948022
877	02/03/2018	717148	Mechanic entered - Wheels and Tyres Other n/s/r wheel nuts c	replaced wheel nuts. torqued wheels to OEM spec.	948022
877	02/03/2018	717147	TYRE 295/80R22.5 RECAP		948022
877	02/03/2018	717147	Mechanic entered - Wheels and Tyres Worn n/s/r tires worn	replaced both n.s.r tires with recaps. torqued wheel nuts to OEM spec.	948022
877	02/03/2018	717149	Consumables		948250
877	02/03/2018	717149	LAMP FLUORESCENT TUBE 18W		948022
877	02/03/2018	717149	Mechanic entered - Elec and Light Interior Lights saloon lig	fit new fluoro. tested operation. all ok	948022
877	01/09/2018	712516	indicaotor not working	R&R globe	944245
877	12/05/2017	706048		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	938577
877	12/05/2017	706048		VEHICLE SAFETY INSPECTION safet completed	938577
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		938577
877	12/05/2017	706048	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		938577

877	12/05/2017	706048	FILTER FUEL FILTER SCANIA SR4 (H17WK11) (H17WK05)		938577
877	12/05/2017	706048		CARRY OUT B SERVICE AS PER CHECK LIST b service completed	938577
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048	Consumables		938916
877	12/05/2017	706048		CARRY OUT A SERVICE AS PER CHECK LIST a service completed	938577
877	12/02/2017	705573	Consumables		938670
877	12/02/2017	705573	Mechanic entered - Elec and Light Exterior Lights n/s/t fro	R&R globe	938577
877	12/01/2017	705384	Consumables		938670
877	12/01/2017	705384	Elec and Light Two Way Radio - Not Transmitting	2-way reset at repeator by cim	938577
877	11/18/2017	702590	BOTH NSR AIR BAG LEAKING	checked all air bags on bus . all new . could not fault	936594
877	11/11/2017	700979	Consumables		935810
877	11/11/2017	700979	Elec and Light N/S top front park light N/W.	no faults with nsf top parker ut os frt bottom indicator nw. replaced festoon	935378
877	11/08/2017	700144	Consumables		935378
877	11/08/2017	700144	Ops Entered - Fault - Body Drivers Seat Belt - Route: - A	adjusted seat belt angle . checked operation of seat belt all ok	934529
877	11/04/2017	695688	ROLLER		934529
877	11/01/2017	690497	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O203792 Receiving #:215214 Date :2017-11-28 replaced n/s/r glass as required	938140
877	10/31/2017	698339	Breakdown#:33941 - Ops Entered - Breakdown - Breakdown Road	adjusted seat belt . checked operation all ok	933278
877	10/31/2017	698339	VALVE DOOR VALVE		933278
877	10/31/2017	698339	Air System air leak can be heard when inside bus.	R&R front door air regulator	933278
877	10/30/2017	698162	Consumables		933948
877	10/30/2017	698162	Mechanic entered - Body Other driver seat belt not working	fixed driver seat belt ok	933278
877	10/30/2017	697971	Remove old poster and fit new A3 Posters and hangers	carried out campaign as required	933278
877	10/29/2017	697206	Please remove the 2 x Do Not Enter decals at the exterior	carried out campaign as required	933278
877	10/28/2017	697807	Breakdown#:33933 - Ops Entered - Breakdown - Breakdown Road	r/r globeok.	933488
877	10/28/2017	697807	Drv entered - Elec and Light Next Stop Button	DONE	933488
877	10/28/2017	697807	Consumables		933678
877	10/28/2017	697807	DISABLE SEAT BACK COME OFF	fixed for pax seatok.	933488
877	10/23/2017	696347	Mechanic entered - A/C Heating Not Cooling	reset battery and a/c . road tested all ok	932584
877	10/19/2017	695688	Ops Entered - Fault - Eng Cool - Route: 703b - Centre Rd o	IDLER SEIZED AND ALT BELT BROKEN. REPLACED IDLER ROLLER ANDALT BELT. FILLED COOLANT. ROAD TEST OK. AJW ASSISTED	932075
877	10/19/2017	695688	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		932075
877	10/19/2017	695688	ROLLER		932075
877	10/19/2017	695688	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	CARRIED OUT CAMPAIGN	932075
877	10/05/2017	691807		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	929533
877	10/05/2017	691807		VEHICLE SAFETY INSPECTION completed safety inspection as per checklist. wheel nuts torqued to OEM spec. road and brake tested all ok	929533
877	10/05/2017	691905	Mechanic entered - Steering Excessive Play sway bar link bal	removed worn sway bar links. fit new links and road tested. ok	929533
877	10/05/2017	691905	LINK SWAYBAR SCANIA K230 1766014 20486 01		929533
877	10/05/2017	691908	Mechanic entered - Elec and Light Exterior Lights front step		929533
877	10/05/2017	691908	LENS AMBER TO SUIT 2149	rplaced blown globe and fit new lens. tersted operation. all ok	929533
877	10/05/2017	691807	Consumables		929908
877	10/05/2017	691807	Consumables		929908
877	10/05/2017	691807	Consumables		929908
877	10/05/2017	691807		CARRY OUT A SERVICE AS PER CHECK LIST	929533
877	10/02/2017	690917	Wheels and Tyres - o/s/r retorque	carried out retorque as required	928414
877	10/01/2017	689638	Remove old A3 Posters with Seniors Festival please leave	carried out campaign as required	928414
877	09/30/2017	690737	Mechanic entered - Wheels and Tyres Flat or Leaking	replace os rear outter tyre flate . tenstioned all wheels	928884
877	09/30/2017	690737	TYRE 295/80R22.5 RECAP		928884
877	09/30/2017	690736	Mechanic entered - Suspension Soft	replaces ns front airbag	928884
877	09/30/2017	690736	AIRBAG O/S/F SCANIA K230UB (2024284)		928884
877	09/30/2017	690727	Mechanic entered - Engine Other engine idler bearing u/s	replaced engine idler bearing ok	928884
877	09/30/2017	690727	SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		928884
877	09/30/2017	690642	Consumables		929057
877	09/30/2017	690642	Elec and Light Exterior Lights O/S headlight N/W.	replaced o/s/f head light globe ok	928884
877	09/30/2017	690642	Consumables		929057
877	09/30/2017	690642	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		928884
877	09/30/2017	690642	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	replaced rear door decal ok	928884
877	09/28/2017	690497	n/s/r glass smashed	O203792- glass replaced by alpha	928884
877	09/28/2017	679902	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O200241 Receiving #:211098 Date :2017-10-04 carry out accident repairs as rqd acc#45133 acc#44022	929272
877	09/24/2017	688641	Engine - over heating	tighted hose clamp and topped up coolant . road tested all ok	928110
877	09/14/2017	686454	Breakdown#:33753 - Ops Entered - Breakdown - Breakdown Road	rear door bottom bearing u/sremove doorchange bearingrefit dooroperating ok.	926463
877	09/14/2017	686454	BEARING (FYH)		926463
877	09/12/2017	686053	Consumables		926463
877	09/12/2017	686053	Mechanic entered - Body Drivers Seat Belt not working	adjusted the angle ok	926236
877	09/09/2017	684094	Consumables		926009
877	09/09/2017	684094	AIRBAG O/S/F SCANIA K230UB (2024284)		925745
877	09/09/2017	684094	AIRBAG FRONT SCANIA K230 (40Y2223)		925745
877	09/07/2017	685106	Consumables		925745
877	09/07/2017	685106	Elec and Light - o.s.f top park light not working	R&R globe	924725
877	09/04/2017	684216	Breakdown#:33721 - Ops Entered - Breakdown - Breakdown Road	completed on work order - 684094	924725
877	09/02/2017	684094	osf air bag leaking air(refullers reported)	replaced frt os air bag and tested ok	924237
877	09/02/2017	684094	AIRBAG FRONT SCANIA K230 (40Y2223)		924237
877	09/02/2017	684094	Body pax seat back come off	repaired ns disable seat back	924237
877	08/30/2017	683378	Consumables		924237
877	08/30/2017	683378	Dash needs a globe on the speedometer. cant see at night	R&R speedo globe . checked operation all ok	923801
877	08/26/2017	682670	Engine bus rolls when you move your foot from brake to accel	road tested and brake tested bus . all ok	923188
877	08/25/2017	682670	Engine bus rolls when you move your foot from brake to accel	road tested ok foot from brake to accelarator bus no move ok found n/s/f brake slack adjust u/s . R&R slack adjustor	923188
877	08/25/2017	682670	SLACK ADJUSTER FRONT NEAR SIDE (1789568)		923188
877	08/25/2017	682686	Mechanic entered - Brakes Other n/s/f slack adjuster u/s.	r/r slack adjuster. need brake tester & road test.	923188
877	08/22/2017	681627	Consumables		922929
877	08/22/2017	681627	Body - rear door convex mirror is loose	tightend mirror	922040
877	08/16/2017	603778	Consumables		921813
877	08/16/2017	603778	MAP POCKETS COACH SEATS S606175		921137
877	08/15/2017	680109	Mechanic entered - Engine Other won't start	jump started	921137
877	08/15/2017	679683	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O200140 Receiving #:208698 Date :2017-08-31 rectify cctv not working as required	924028
877	08/15/2017	680269	Accident - OFF SIDE REAR - Unreported damage	Completed at Panel shop	921137
877	08/15/2017	680268	Accident 44022 - NEAR SIDE REAR	Completed at panel shop	921137
877	08/14/2017	679991	Consumables		921305
877	08/14/2017	679991	frt door nw	fitted frt door ext emg switch wires as they were not connected	921137
877	08/14/2017	679902	Accident Acc# 45133	back here on 14/08/2017	921137
877	08/14/2017	679902	Accident#:44022 - Ops Entered - Accident - ZzVehicle Hit St	done at Knox/Dandy PO#: O200241	921137
877	08/14/2017	679949	Please remove old posters and fit new one along with hangers	campaign has been done	921137
877	08/14/2017	674237	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)		921137
877	08/14/2017	674237	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		921137

877	08/11/2017	679683	lonsdale to rectify cctv not working as required	O200140 - lonsdale	921137
877	08/07/2017	678513		TRANSMISSION CHECK AS PER CHECK LIST	921137
877	08/03/2017	677770	Consumables		921137
877	08/03/2017	677770	Elec and Light no light in the front door where the step is	fit new fluro.	920571
877	08/03/2017	677770	Consumables		921137
877	08/03/2017	677770	Body pax bell at the back doesnt ring when they press it it	could not fault pax buttons.	920571
877	08/03/2017	677770	LAMP FLUORESCENT TUBE 18W		920571
877	08/01/2017	677270	Consumables		920928
877	08/01/2017	677267	Consumables		920928
877	08/01/2017	677270	Mechanic entered - Elec and Light Exterior Lights n/s/f/t pa	fit globe.	920571
877	08/01/2017	677267	Elec and Light NEAR SIDE PARK LIGHT DOESNT WORK	fit globe.	920571
877	07/28/2017	676699		Assisting completed safety inspecton as per checklist. wheels torqued to OEM spec. road and brake tested all ok	920301
877	07/28/2017	676699		VEHICLE SAFETY INSPECTION	920301
877	07/28/2017	676699		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	920301
877	07/28/2017	676699	NUT WHEEL NUT (40F2600) (174	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:-O199037 Receiving #:205982 Date :2017-07-28	920301
877	07/28/2017	676775	TYRE 295/80R22.5 RECAP		920301
877	07/28/2017	676775	Mechanic entered - Wheels and Tyres Worn o/s/r tires worn	replaced worn tires with recaps. torqued wheel nuts to OEM spec. all ok	920301
877	07/28/2017	638928	TORQUE ROD BUSH SCANIA SR4 K230 1435944 23845 01		920301
877	07/18/2017	674237	Consumables		918652
877	07/18/2017	674237	Consumables		918652
877	07/18/2017	674237	washer sealing SC sump	Creditor #:-VB-MUL001 MULTISPARES LTD P/O #:-O198073 Receiving #:205101 Date :2017-07-19	918385
877	07/18/2017	674237	Consumables		918652
877	07/17/2017	674237		SERVICE MOISTURE EJECTOR	917577
877	07/17/2017	674237		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST engine tune-up serviceok.	917577
877	07/17/2017	674237	FILTER AIR DRYER SCANIA SR4 (1393551) (49G8709HALDEX)		917577
877	07/17/2017	674237		CARRY OUT C SERVICE AS PER CHECK LIST completed ABC service as per checklist. road and brake tested all ok	917577
877	07/17/2017	674237	FILTER FUEL FILTER SCANIA SR4 (H17WK11) (H17WK05)		917577
877	07/17/2017	674237	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		917577
877	07/17/2017	674237	FILTER HYDRAULIC COOLING FAN SCANIA SR3 (E90HD149)		917577
877	07/17/2017	674237	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)		917577
877	07/17/2017	674237	FILTER FUEL FILTER SCANIA SR4 (1393640)		917577
877	07/17/2017	674237	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		917577
877	07/17/2017	674237	Consumables		918385
877	07/17/2017	674237	Consumables		918385
877	07/17/2017	674237		CARRY OUT B SERVICE AS PER CHECK LIST	917577
877	07/17/2017	674237	Consumables		918385
877	07/17/2017	674237	Consumables		918385
877	07/17/2017	674237		CARRY OUT A SERVICE AS PER CHECK LIST	917577
877	07/17/2017	674237	Consumables		918385
877	07/17/2017	674237	Consumables		918385
877	07/14/2017	673687	Consumables		918033
877	07/14/2017	673687	Mechanic entered - Elec and Light Exterior Lights o/s/f indi	fit globe.	917577
877	07/11/2017	649840	FILTER AIR DRYER SCANIA K230 (1774598) (2081360)		917087
877	07/08/2017	672628	Consumables		916650
877	07/08/2017	672628	Drv entered - Body Drivers Seat Controls	weight adjustment reset. and crimped air line for driver controls fixed.	916650
877	07/04/2017	671268	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	carried out campaign by paul bell	915549
877	06/23/2017	669554	Consumables		914373
877	06/23/2017	669554	Mechanic entered - Body Other rear hatch switch needs to be	adjusted rear engine hatch switch checked operation all ok	913955
877	06/22/2017	669301	Consumables		914162
877	06/22/2017	669301	Remove old Green 2016/17 registration Label and/ or Blue EF	Complete	913955
877	06/14/2017	667233	Consumables		912613
877	06/14/2017	667233	FRONT NS INDICATOR N/W	R&R globe	912404
877	06/04/2017	664345	Consumables		911354
877	06/04/2017	664345	Fit A3 Poster/Hangers	carried out campaign as required	910263
877	06/03/2017	665545	Engine doesn't always start after being shut down then af	started and stopped engine several times . could not fault	910263
877	06/02/2017	665389	Wheels and Tyres - carry out front retorque as required	carried out retorque as required	910263
877	06/01/2017	664943		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	910263
877	06/01/2017	664943		VEHICLE SAFETY INSPECTION	910263
877	06/01/2017	664991	wheel nuts u/s x 10	R&R wheels nuts	910263
877	06/01/2017	663362	WHEEL CLEANING	Creditor #:-VB-TYR002 TYRES4U P/O #:-O195053 Receiving #:202034 Date :2017-06-02	911000
877	06/01/2017	663362	DISPOSAL	Creditor #:-VB-TYR002 TYRES4U P/O #:-O195053 Receiving #:202034 Date :2017-06-02	911000
877	06/01/2017	663362	BALANCE	Creditor #:-VB-TYR002 TYRES4U P/O #:-O195053 Receiving #:202034 Date :2017-06-02	911000
877	06/01/2017	663362	TYRE 295/80R22.5 NEW		910263
877	06/01/2017	663362	Mechanic entered - Wheels and Tyres Vibration	both front tires worn. fit new tires wheel nuts torqued to OEM spec. retorquedbooked.	910263
877	06/01/2017	663362	WHEEL NUT SCANIA L94		910263
877	06/01/2017	663362	VALVE EXTENSION-130mm Metal type		910263
877	06/01/2017	663362	Mechanic entered - Wheels and Tyres Other rear both tyres ai	replaced rear both tyres air valve ok	910263
877	06/01/2017	664991	Mechanic entered - Gearbox Driveline Other diff seal u/s	replaced diff seal ok	910263
877	06/01/2017	664991	Consumables		911000
877	06/01/2017	664991	Mechanic entered - Body Other rear modesty loose	fixed rear modesty ok	910263
877	06/01/2017	664943	Consumables		911000
877	06/01/2017	664943	Consumables		911000
877	06/01/2017	664943	Consumables		911000
877	05/31/2017	664728	Mechanic entered - Engine Other NOT STARTING AT KEY.	CARRY OUT A SERVICE AS PER CHECK LIST	910263
877	05/27/2017	663847	CLEAN UP EXTERNAL GRAFFITI OVERNIGHT AS REQUIRED	ADJUST ENGINE HATCH SWITCH.	910263
877	05/25/2017	663362	Mechanic entered - Wheels and Tyres Vibration	CLEANED UP EXTERNAL GRAFFITI OVERNIGHT AS REQUIRED	909935
877	05/23/2017	662903	DIRECT PURCHASE - BUS INSPECTI	road testrebookalignment and balance.	909478
877	05/23/2017	662903		Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-O194255 Receiving #:201135 Date :2017-05-24	909478
877	05/23/2017	662903		ANNUAL SAFETY INSPECTION SERIAL # 264139	909270
877	05/23/2017	662903		PRE ANNUAL SAFETY INSPECTION CHECK	909270
877	05/23/2017	662903	Drv entered - Steering Shakes/ Wobbles		909270
877	05/23/2017	662903	Consumables		909478
877	05/23/2017	662903	Mechanic entered - Elec and Light Exterior Lights Park light	R&R High low beam 178mm insert. All ok.	909270
877	05/23/2017	662903	Mechanic entered - Elec and Light Exterior Lights	Head beam globe not working. R&R head beam globe.	909270
877	05/23/2017	662903	LAMP HEADLAMP MK3 VOLVO B10M		909270
877	05/18/2017	662108	Consumables		908813
877	05/18/2017	662108	Mechanic entered - Body Other driver's rear door view mirror	secured mirror and adjusted	908359
877	05/13/2017	661029		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	907430
877	05/12/2017	660858	Consumables		907850
877	05/12/2017	660858	Mechanic entered - Elec and Light Exterior Lights n/s headl	replaced globe	907430
877	05/06/2017	659810	Consumables		906973
877	05/06/2017	659810	Body PAX BELL NOT WORKING	turned on passenger bell on dash checked operation . could not fault	906512
877	05/01/2017	641527	Consumables		905809

877	05/01/2017	641527	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS P/O #:O193235 Receiving #:200126 Date :2017-05-10 RECTIFY REAR DOORS NOT CLOSING	902721
877	04/28/2017	658240	Consumables		905579
877	04/28/2017	658240	Mechanic entered - Elec and Light Indicators Not Working n/s	reposition globe in holder.	905143
877	04/27/2017	638928	DIRECT PURCHASE - MECHANICAL GENERAL		905143
877	04/21/2017	654148	Consumables		904389
877	04/21/2017	654148	Consumables		904389
877	04/21/2017	654148	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)		904124
877	04/21/2017	654148	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		904124
877	04/10/2017	655646	GLOBE 24V 21W SINGLE CONTACT (HLR2421)		902786
877	04/10/2017	655646	Body indicator not working passenger side of the bus	r/r globe n/s/f indicator	902786
877	04/07/2017	655302	A/C Heating -air con not working	O191268	902432
877	04/07/2017	655302	A/C Heating -air con not working	O191268	902432
877	04/07/2017	655302	A/C Heating -air con not working in the bus	O191268	902432
877	04/07/2017	655302		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O191268	902432
877	04/04/2017	655302	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O191268 Receiving #:198348 Date :2017-04-12 carry out 12 month a.c service as required	903170
877	04/01/2017	654148		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	901317
877	04/01/2017	654148		VEHICLE SAFETY INSPECTION done tension wheel nuts road/brake test oki	901317
877	04/01/2017	654202	Mechanic entered - Engine Other n/s/f engine mount nfg need	R&R both front engine mounts	901317
877	04/01/2017	654148	FILTER FUEL FILTER SCANIA SR4 (H17WK04)		901317
877	04/01/2017	654148	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		901317
877	04/01/2017	654148	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		901317
877	04/01/2017	654148		CARRY OUT B SERVICE AS PER CHECK LIST done	901317
877	04/01/2017	654148	Consumables		901713
877	04/01/2017	654148	Consumables		901713
877	04/01/2017	654148		CARRY OUT A SERVICE AS PER CHECK LIST done	901317
877	03/08/2017	649840	Ops Entered - Fault - Air System Air_Leak Doors - Route: 7	traced and found front door main air reg u/s . R&R main door reg. also replaced air dryer filter. checked building of air up on bus . and checked for air leaks . all ok	897880
877	03/08/2017	649840	FILTER AIR DRYER SCANIA K230 (1774598) (2081360)		897880
877	03/01/2017	638928	1427426 REAR SEAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O186575 Receiving #:196264 Date :2017-03-17	899213
877	03/01/2017	638928	812515 BOLT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O186575 Receiving #:196264 Date :2017-03-17	899213
877	03/01/2017	638928	13855563 WASHER	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O186575 Receiving #:196264 Date :2017-03-17	899213
877	03/01/2017	638928	812612 BRACKET	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O186575 Receiving #:196264 Date :2017-03-17	899213
877	02/28/2017	648181	Consumables		897181
877	02/28/2017	648181	GLOBE 24V 75/70W H4		896292
877	02/28/2017	648181	Elec and Light no front headlights	REPLACED GLOBE ALSO RESET CURCUIT BREAKER FOR HEAD LIGHTS	896292
877	02/26/2017	647164	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	Campaign completed.	896292
877	02/25/2017	647085	Please remove any old poster and fit either Good News for T	Campaign completed.	896292
877	02/23/2017	638911	EDGE STEP EDGE YELLOW 43mm		896366
877	02/20/2017	646276	Consumables		896015
877	02/20/2017	646276	Mechanic entered - Elec and Light Exterior Lights n/s/r clea	r/r led clearance lightok.	895481
877	02/20/2017	646276	L.E.D CLEARANCE LAMP		895481
877	02/18/2017	645963	DRIVER'S SUNBLIND US AND REPLACE AS RQD(PARTS SUPPLIED)	REMOVED OH CONSOLE AND MODIFIED THE LENGTH OF SUNBLIND TO SUIT TO THE EXISTING SCREW HOLES. REPLACED AND CHECKED OK	895481
877	02/17/2017	645494	Body - door brakes are locked on	checked operation of door brakes . could not fault . working for both fron and rear door. road tested all ok	895481
877	02/16/2017	638928	BUSH TORQUE ROD BUSH SCANIA / MERCEDES (1517403) (2520801)		895481
877	02/15/2017	638928	BUSH TORQUE ROD BUSH SCANIA / MERCEDES (1517403) (2520801)		895481
877	02/13/2017	644243	Consumables		895255
877	02/13/2017	644243	door brakes not working - beware to have a look at roll awa	front door repaired by benware for roll away campaign - ben has not asked for a order number	894790
877	02/10/2017	638928	BUSH TORQUE ROD BUSH SCANIA / MERCEDES (1517403) (2520801)		894790
877	02/09/2017	643750	retension osr wheel nuts	retensioned osr and both frt wheel nuts as per specs	892208
877	02/08/2017	638928	TORQUE ROD BUSH SCANIA SR4 K230 1435944 23845 01		892208
877	02/07/2017	638928	Suspension - front upper torque rod bushes u.s	r/r upper torque rod bushes both sides tension wheel nuts ok	892208

877	01/14/2017	638928	Mechanic entered - Elec and Light Other reverse alarm u/s	replaced reverse alarm ok	892208
877	01/14/2017	638911	LAMP 1.2W SWF SWITCH LED (17040) (E-596WLED) (47706)		892208
877	01/14/2017	638911	SWITCH HAZARD 4 SERIES 1327015		892208
877	01/14/2017	638911	Mechanic entered - Elec and Light Other hazard switch u/s	replaced hazard switch ok	892208
877	01/14/2017	638911	Mechanic entered - Elec and Light Other o/s/f top park light	tightened o/s/f top park light bracket bolts	892208
877	01/14/2017	638911	Mechanic entered - Elec and Light Other dash switch globe u/	replaced dash switch globe ok	892208
877	01/14/2017	638911	EDGE STEP EDGE YELLOW 43mm		892435
877	01/14/2017	638911	Consumables		892208
877	01/14/2017	638911	Mechanic entered - Body Other step edge u/s	replaced step edge ok	892208
877	01/14/2017	638911	Mechanic entered - Body Other staunchion poles bolt missing	replaced staunchion poles boltstightened staunchion bolts ok	892208
877	01/14/2017	638890	Consumables		892435
877	01/14/2017	638890	Consumables		892435
877	01/14/2017	638890	Consumables		892435
877	01/14/2017	638890			892208
877	01/09/2017	589599	AIRBAG REAR SCANIA K230 / K270 (2024287)		888199
877	01/08/2017	636775	Fit New 2107 Large and Small Fares Small Concessionand AO	campaign complete. Campaign complete.	888199
877	01/06/2017	636091	TYRE 295/80R22.5 RECAP		890655
877	01/06/2017	636091	DISPOSAL	Creditor #:VB-TYR002 TYRES4U P/O #:O184708 Receiving #:190961 Date :2017-01-06	890655
877	01/06/2017	636091	29580R22.5R TYRE	Creditor #:VB-TYR002 TYRES4U P/O #:O184708 Receiving #:190961 Date :2017-01-06	890655
877	01/06/2017	637146	Consumables		890906
877	01/06/2017	637146	Mechanic entered - Elec and Light Next Stop Button middle b	adjusted contacts in passenger pax bell button checked operation ok	888199
877	01/05/2017	636700	Consumables		890655
877	01/05/2017	636700	Body -CORDS HANGING DOWN IN FRONT OF THE DESTO	repositioned wire from infront of desto . all ok	888199
877	01/05/2017	636775	DECAL AUTHORISED OFFICER		888199
877	01/05/2017	636775	DECAL 2017 PTV DECAL CONCESSION CARD TYPE 300x150mm		888199
877	01/05/2017	636775	DECAL 2017 PTV METRO MYKI DECAL SMALL 300x150mm		888199
877	01/03/2017	636396	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	888199
877	01/02/2017	636114	Wheels and Tyres - carry out n/s/r tire as required	carried out retorque to n/s/r as required	888199
877	01/01/2017	630965	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS P/O #:O182728 Receiving #:192697 Date :2017-01-31 rectify bus loosing throttle as required	894765
877	12/31/2016	636091	VALVE EXTENSION-130mm Metal type		888199
877	12/31/2016	636091	TYRE 295/80R22.5 RECAP		888199
877	12/31/2016	636091	Wheels and Tyres - o/s/r tires u/s		888199
877	12/31/2016	636091	Wheels and Tyres - o/s/r tires u/s	replaced tires on o/s/r tensioned wheel nuts	888199
877	12/29/2016	635603	Mechanic entered - Elec and Light Exterior Lights n/s/f cor	repaired contact for globe . checked operation all ok	888199
877	12/19/2016	634166	Vandalism Vandalism/ Graffiti Interior	carried out interior painting as required - saturday	888199
877	12/15/2016	633722	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	887678
877	12/14/2016	633522	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	887468
877	12/08/2016	632220	Consumables		886535
877	12/08/2016	632220	Mechanic entered - Body Rear_Door Operation Faulty not clos	adjusted rear door snestive edge. and door closure postion . checked operation of door . working ok	886078
877	12/05/2016	631615	Vandalism Vandalism/ Graffiti Interior	carried out interior painting as required	885509
877	12/01/2016	616109	heater demistor adjustor cable and heater tap assembly u/s		874429
877	12/01/2016	630965	Mechanic entered - Breakdown Road Defect Affects Service no	O182728 -bus repaired by ben from bwere . diode had blown in a diode pack in the fuse panel	885380
877	12/01/2016	630965	DIRECT PURCHASE - TOWING	Creditor #:VB-EAGTOW Eagle Towing & Salvage P/O #:O182902 Receiving #:189409 Date :2016-12-08 tow bus back to oakleigh depot as required	886307
877	11/30/2016	630742	CAMERA INTERNAL 2.1mm LENS		885139
877	11/30/2016	630742	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	carried out campaign as required	885139
877	11/29/2016	630694	Breakdown - Cnr Wellington & Blackburn Rds - No acceleratio	Attended by regional b/down Phil Ling - found bus had no acceleration called tow truck no repairs were carried out (waited for tow truck)	885139
877	11/28/2016	630398	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	884886
877	11/23/2016	629470	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O182091 Receiving #:188817 Date :2016-11-30 replace all rear glass and film as required	885139
877	11/23/2016	629470	Vandalism - all rear glass and film to be replaced	all rear glass and film to be replaced by alpha on order - O182091	882922
877	11/17/2016	628230		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	882922
877	11/17/2016	628230		VEHICLE SAFETY INSPECTION A/B service done safety inspection wheel tension road test & brake done ok	882922
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	O-RING SPINNER FILTER SCANIA (1769798)		882922
877	11/17/2016	628230	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)		882922
877	11/17/2016	628230	FILTER FUEL FILTER SCANIA SR4 (H17WK04)		882922
877	11/17/2016	628230	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		882922
877	11/17/2016	628230	O-RING LARGE SPINNER FILTER SCANIA (1769799)		882922
877	11/17/2016	628230		CARRY OUT B SERVICE AS PER CHECK LIST	882922
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		883268
877	11/17/2016	628230	Consumables		882922
877	11/17/2016	628230	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	882922
877	11/17/2016	628230		CARRY OUT A SERVICE AS PER CHECK LIST	882922
877	11/14/2016	627695	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	882258
877	11/12/2016	627391	Body -weld broken on rear modest	prep modest panel weld paint ok	882258
877	10/29/2016	624864	Drv entered - Wipers and Washers Washers Not Working	filled the bottle	879787
877	10/28/2016	624578	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced	879787
877	10/20/2016	622911	Campaign 14/16 Destination signs Setting and loadig Files.	carried out campaign as required	878446
877	10/08/2016	620740	Elec and Light -3-4 bell switches not working on the bus	traced and found pax bell button u/s . replaced pax bell button. checked operation . working ok	876695
877	10/08/2016	620740	Consumables		877056
877	10/08/2016	620740	Body -PAX BELL NOT WORKING		876695
877	10/08/2016	620740	SWITCH- STOP-YELLOW		876695
877	10/07/2016	620497	Consumables		877056
877	10/07/2016	620497	Wheels and Tyres - carry out retorque to n/s/f as required	carried out retorque to n/s/f as required	876695
877	10/06/2016	620099	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O178591 Receiving #:185498 Date :2016-10-14 carry out roller away campaign as required - mariano	877638
877	10/05/2016	620099	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	carried out roll away campaign as required mariano from knox - O178591	876695
877	10/03/2016	619541	Vandalism Vandalism/ Graffiti Interior	painted over interior vandelisem	874429
877	10/03/2016	581079	OIL DIPSTI		874429
877	10/03/2016	581079	SCANIA DIP STICK L94UAB		874429
877	09/21/2016	617353	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	875171
877	09/19/2016	616802	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	carry out retorque on o/s/r as required	874715
877	09/10/2016	615264	Wheels and Tyres - carry out o/s/r retorque as required	Creditor #:VB-TYR002 TYRES4U P/O #:O176718 Receiving #:183117 Date :2016-09-13	873706
877	09/09/2016	614810	295/80R22.5 BANDAG BITUMEN RET	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tenstioned	873706
877	09/08/2016	614810		VEHICLE SAFETY INSPECTION safety completed	873529
877	09/08/2016	614810	Mechanic entered - Wheels and Tyres Worn	removed os rear tyre replaced and re fitted then torqued test driven ok	873529
877	09/08/2016	614810	TYRE 295/80R22.5 RECAP		873529
877	09/08/2016	614810	Consumables		873706
877	09/08/2016	614810	Consumables		873706
877	09/08/2016	614810		CARRY OUT A SERVICE AS PER CHECK LIST a service completed	873529
877	08/31/2016	613392	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	872186

877	08/30/2016	613123	Consumables			872412
877	08/30/2016	613123	Please remove old poster and fit new Legacy poster	Replaced Poster		872186
877	08/29/2016	612825	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		871958
877	08/24/2016	611640	Consumables			871581
877	08/24/2016	611640	GLOBE 24V 75/70W H4			871115
877	08/24/2016	611640	Elec and Light Exterior Lights one headlight out	fit globe.		871115
877	08/16/2016	610059	Consumables			870209
877	08/16/2016	610059	GLOBE 24V 21W SINGLE CONTACT (HLR2421)			869790
877	08/16/2016	610059	Elec and Light Interior Lights - Driver Cabin light N/W	replaced globe		869790
877	08/16/2016	610059	Elec and Light Exterior Lights - Step light N/W	replaced globe		869790
877	08/16/2016	610059	GLOBE 24V 5W BAYONET (17181)			869790
877	08/12/2016	609583	Brakes are spongy	checked brakes adjusted brakes - ok . road tested and brake tested bus . could not fault spondgy brakes		869254
877	08/12/2016	609583	Air System- climate control error message	checked operation of climate control . could not fault the climate control system		869254
877	08/11/2016	609511	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		869254
877	08/11/2016	609346	Spongy Brakes	adjusted brake checked brakes . road tested and brake tested . all ok		869254
877	08/09/2016	608894	Mechanic entered - Brakes Park_Brake Not Releasing properly	REMOVED OLD HAND BRAKE VALVE AND FIT NEW one checked operation. working ok . road tested and brake tested . all ok		869026
877	08/09/2016	608894	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O174327 Receiving #:180373 Date :2016-08-09 961 723 021 0 Hand Brake Valve		869254
877	08/01/2016	604497	Vandalism Vandalism/ Graffiti Interior			864944
877	08/01/2016	601145	FILTER AIR DRYER SCANIA SR4 (1393551)(20546795)			863758
877	07/22/2016	605386	GLOBE 24V 4W SINGLE CONTACT [BOX 10]			864944
877	07/22/2016	605386	Mechanic entered - Elec and Light Exterior Lights o/s front	replaced globe		864944
877	07/21/2016	605157	GLOBE 24V 75/70W H4			864944
877	07/21/2016	605157	Elec and Light- headlight out	replaced globe		864944
877	07/18/2016	604498	Vandalism Vandalism/ Graffiti Interior	carried out interior vandel painting		864944
877	07/17/2016	603152	Consumables			865904
877	07/17/2016	603152	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	carried out campaign as required		864944
877	07/16/2016	603778	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	carried out campaign as required		865411
877	07/16/2016	603778	Consumables			865904
877	07/15/2016	604164	Door Buzzer N/W	turn on pax buzzer switch checked operation ok		865411
877	07/15/2016	604206	Consumables			865904
877	07/15/2016	604206	DECAL PARK BRAKE/ NO WINDOW ACCESS			865411
877	07/15/2016	604206	Mechanic entered - Body Other fit decals as needed	FITTED DECAL		865411
877	07/14/2016	604066	Consumables			865904
877	07/14/2016	604066	DECAL NO SMOKING			865411
877	07/14/2016	604066	fit no smoking decal	fitted no smoking decal		865411
877	07/13/2016	603892	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		865411
877	07/13/2016	603558	Mechanic entered - Vandalism Vandalism/ Graffiti Interior L	Graffiti removed.		865411
877	07/13/2016	603778	MAP POCKETS COACH SEATS S606175			865411
877	07/11/2016	603275	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		864944
877	07/09/2016	601528	Air System - 4 way protection valve u/s	replaced 4WAY PROTECTION VALVEROAD TESTED OKAIR GAUGE OK		864944
877	07/06/2016	601528	Direct Purchase - MECHANICAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O171734 Receiving #:177943 Date :2016-07-06 supply 4-way protection valve as required		864152
877	07/04/2016	601443		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		863758
877	07/04/2016	601443		VEHICLE SAFETY INSPECTION		863758
877	07/04/2016	601528	Air System - 4 way protection valve u/s	WOP		863758
877	07/01/2016	601145	Wheels and Tyres - rear tires low	checked the osr tyres; 5mm remaining; (also inspected by LDM)		863758
877	07/01/2016	601145	Mechanic entered - Wheels and Tyres Worn n/s rear tire trea	checked nsr tyres; 6mm remaining. (also inspected by LDM)		863758
877	07/01/2016	601145	AIR DRYER VALVE BLOCK (BLACK)(35clf0155)			863758
877	07/01/2016	601145	Mechanic entered - Air System Air Not Building_Up air gauge	checked and found slow to build up and gauge 1 still at 6bars. checked the gauge senders and swapped them. system 1 pressure is low. found a leak due to a cracked reg valve block. replaced air dryer and valve block. started building up quickly and still the gauge 1 is low. measured the air pressure at the 4-way valve. sup		863758
877	06/28/2016	600502		CARRY OUT B SERVICE AS PER CHECK LIST		862934
877	06/28/2016	600502	Consumables			863758
877	06/28/2016	600502	Consumables			863758
877	06/28/2016	600502	Consumables			863758
877	06/28/2016	600502	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			862934
877	06/28/2016	600502	FILTER FUEL SCANIA SR4(H17WK04)			862934
877	06/28/2016	600502	FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1			862934
877	06/28/2016	600502	O-RING LARGE SPINNER FILTER SCANIA (1769799)			862934
877	06/28/2016	600502	O-RING SPINNER FILTER SCANIA (1769798)			862934
877	06/28/2016	600502		CARRY OUT A SERVICE AS PER CHECK LIST		862934
877	06/28/2016	600502	Consumables			863758
877	06/28/2016	600502	Consumables			863758
877	06/28/2016	600502	Consumables			863758
877	06/25/2016	600122		TRANSMISSION CHECK AS PER CHECK LIST TRANS CHECK COMPLETED		862934
877	06/25/2016	600122	Air System - WHEN YOU PUT THE PARK BRAKE ON IT ITS LOOSING	CHECKED AIR SYSTEMS FOR LEAKS NO FAULTS FOUND		862934
877	06/24/2016	599920	GLOBE 24V 21W SINGLE CONTACT (HLR2421)			862934
877	06/24/2016	599920	Mechanic entered - Elec and Light Exterior Lights O/S FRONT	replaced globe		862934
877	06/21/2016	599192	Breakdown#:32638 - Ops Entered - Breakdown - Breakdown Road	double entry		862084
877	06/21/2016	599192	Rear external lights nw and also rear saloon light nw	replaced fuse to rear node re powered node . checked operation all rear lights outside bus all working ok		862084
877	06/19/2016	598143	Please remove any old poster and fit new A3 poster and add	fleet support carried out campaign as required		862084
877	06/18/2016	598650	GLOBE DASH			862287
877	06/18/2016	598650	Dash - front bell stop lights up on dash but bell does not	fit globe to dash blinker working ok		862287
877	06/18/2016	598650	Dash - INDICATORS NOT WORKING ON DASH	double entry		862287
877	06/01/2016	566667	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O159931 Receiving #:175658 Date :2016-06-08 paint interior of bus over graffeti as required		860359
877	06/01/2016	568681	Consumables			859715
877	06/01/2016	568681	Consumables			859715
877	06/01/2016	568681	Consumables			859715
877	06/01/2016	568681	Direct Purchase - TYRES	Creditor #:VB-TYR002 TYRES4U P/O #:O160456A Receiving #:177200 Date :2016-06-29 BALANCE		863640
877	06/01/2016	568681	Direct Purchase - TYRES	Creditor #:VB-TYR002 TYRES4U P/O #:O160456A Receiving #:177200 Date :2016-06-29 295/80R22.5 DCOIN		863640
877	05/27/2016	594234	ROAD WORTHY INSPECTION	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O169078 Receiving #:175202 Date :2016-06-01 carry out RSI as required		859448
877	05/27/2016	594234		ANNUAL SAFETY INSPECTION carried out by FLEET CHECK ON 27/05/2016 po O 169078 SERIAL H500800		854380
877	05/27/2016	594234		PRE ANNUAL SAFETY INSPECTION CHECK		854380
877	05/27/2016	594218	Consumables			858882
877	05/27/2016	594218	DECAL BREAK GLASS IN EMERGENCY ROCK 120MM SQ RED/CLEAR			854380
877	05/27/2016	594218	DECAL EMERGENCY EXIT			854380
877	05/27/2016	594218	Mechanic entered - Body Other EMG EXIT DECALS MISSING	FITTED DECALS		854380
877	05/27/2016	589534	FILTER AIR OUTER SCANIA SR3 SR4 395773 0395773 E218L			854380
877	05/26/2016	571958	Consumables			858753
877	05/26/2016	571958	Retrimmed Base Assy 6008			840622
877	05/25/2016	589192	GLOBE WEDGE 24V 1.2W HLW241.2 47706 SWFLED E-596FWLED			854380
877	05/25/2016	589192	GLOBE 24V 4W S/C			854380
877	05/24/2016	593459	SWITCH- STOP-YELLOW			858121
877	05/24/2016	593459	Breakdown#:32582 - Ops Entered - Breakdown - Breakdown Road	replaced abroken pax switch.		858121
877	05/17/2016	592116	Suspension NSR front air bag leaking	Replace NSR rear air bag as found to also be leaking.		856954
877	05/17/2016	592113	Suspension NSR front air bag leaking	Replace NSR front air bag as required		856954

877	05/16/2016	589599	REAR AIR BAG (DRIVE AXLE) SCAN	Creditor # :VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O168129 Receiving #:174150 Date :2016-05-18	857082
877	05/14/2016	589599	AIRBAG REAR SCANIA K230 / K270 2024287		856579
877	05/09/2016	590493	jump start bus as required	jump start bus	855403
877	05/06/2016	590367	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	NEW GRAFFITI CLEANED	855403
877	05/05/2016	589961	Consumables		855403
877	05/05/2016	589961	Body - engine hatch gas strut u/s	replaced u/s engine hatch strut	854949
877	05/05/2016	589961	GAS STAY 575MM X 600NM		854949
877	05/03/2016	589534		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	854380
877	05/03/2016	589534		VEHICLE SAFETY INSPECTION	854380
877	05/03/2016	589599	n/s/r/f airbag u/s	replaced air bag	854380
877	05/03/2016	589665	CLEAR LENS		854380
877	05/03/2016	589665	GLOBE 24V 10W S/C		854380
877	05/03/2016	589665	Mechanic entered - Elec and Light Exterior Lights frt door s	replaced globe	854380
877	05/03/2016	589665	Mechanic entered - Elec and Light Exterior Lights Rear door	replaced lens	854380
877	05/03/2016	589534	FILTER AIR OUTER SCANIA SR3 SR4 395773 0395773 E218L		854380
877	05/03/2016	589534		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	854380
877	04/30/2016	589192	GLOBE 24V 4W S/C		854380
877	04/30/2016	589192	Mechanic entered - Elec and Light Exterior Lights N/S PARK	this was done by CDF on 23/04/2016	854380
877	04/22/2016	587420	GLOBE 24V 75/70W H4 48892		853269
877	04/22/2016	587420	Mechanic entered - Elec and Light Exterior Lights N/S HEADLI	FIT GLOBE.	853269
877	04/20/2016	587420	Passenger stop button keeps going off.	COULD NOT FAULT.	852951
877	04/18/2016	583354	Direct Purchase - MECHANICAL	Creditor # :VB-AIR001 AIR ANYWHERE P/O #:O165211 Receiving #:172293 Date :2016-04-20 balance the wheels and fix the alignment as rqd	853042
877	04/14/2016	586443	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	Checked all pax stop switches if any of them sicking. all good. road tested to see if a wiring getting grounded. no faults found.	851814
877	04/13/2016	586121	Dash-buzzers not working - first one at entrance door + on	reconnect wire to pax buzzer - checked operation ok	851814
877	04/10/2016	584752	Mechanic entered - Vandalism Vandalism/ Graffiti Interior L	painted interior of bus over graffiti	850674
877	04/09/2016	585477	The pax bell by the raer passenger door gets stuck.	repaired wires checked operation ok	850674
877	04/08/2016	585236	Mechanic entered - Elec and Light Exterior Lights front n/s	replaced globe checked operation ok	850674
877	04/08/2016	585236	GLOBE 24V 21W SINGLE CONTACT HLR2421		850674
877	04/08/2016	585236	Mechanic entered - Body Other door buzzer not working	checked operation of passenger door buzzer could not fault	850674
877	04/02/2016	584215	SWITCH- STOP-YELLOW		850232
877	04/02/2016	584215	Elec and LightThe last two buttons/buzzers up the back of	Replaced one pax switch and repaired the other at the very back of the bus. tested ok	850232
877	03/31/2016	583354	Engine - when bus gets to 60kmh per hour the bus starts sha	air anywhere carried out this job po O165211/ road tested ok	850092
877	03/30/2016	583354	Engine - when bus gets to 60kmh per hour the bus starts sha	removed front breaks and re fitted	850092
877	03/30/2016	583354	Direct Purchase - MECHANICAL	Creditor # :VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:O165048 Receiving #:170779 Date :2016-03-30 radius grind brakes and machine drums as required	850092
877	03/29/2016	583354	Engine - when bus gets to 60kmh per hour the bus starts sha	brakes machined by trade brake on order - O165048 wheels balanced and wheel alignment	849582
877	03/29/2016	583353	Mechanic entered - Body Other bonnet hatch not secure	secured engine hatch	849582
877	03/29/2016	583352	Body - engine hatch wont close properly	secured engine hatch	849582
877	03/29/2016	583353	Consumables		849964
877	03/29/2016	583352	Consumables		849964
877	03/22/2016	582648	Mechanic entered - Engine Other BATTERY JUMP.	STARTED ENGINE OK	849471
877	03/22/2016	581739	GAS STAY 575MM X 600NM	Creditor # :VB-MCN001 MCNAUGHTANS P/O #:O164670 Receiving #:171195 Date :2016-04-06	850674
877	03/22/2016	581739	Consumables		849582
877	03/17/2016	581739	Body - engine hatch gas struts u/s	replaced gas struts	848683
877	03/17/2016	581831		CARRY OUT A/C - B SERVICE AS PER CHECK LIST O164453 carried out by cold drive cammelious	848683
877	03/17/2016	581831		CARRY OUT A/C - A SERVICE AS PER CHECK LIST O164453 carried out by cold drive cammelious	848683
877	03/15/2016	581831	AIR CONDITIONING REPAIR	Creditor # :VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O164453 Receiving #:170187 Date :2016-03-21 carry out a/c-b service as required - cammelious	849242
877	03/11/2016	581079	SCANIA DIP STICK L94UAB		848426
877	03/11/2016	581079	Engine dipstick is u/s	replaced eng oil dipstick	848426
877	03/11/2016	581076		CARRY OUT A SERVICE AS PER CHECK LIST	848426
877	03/11/2016	581076	Consumables		848632
877	03/11/2016	581076	Consumables		848632
877	03/11/2016	581076	Consumables		848632

877	01/07/2016	568681	Consumables		838126
877	01/07/2016	568681	Consumables		838126
877	01/07/2016	568681		CARRY OUT A SERVICE AS PER CHECK LIST	837763
877	01/03/2016	567509	Consumables		837311
877	01/03/2016	567509	Consumables		837311
877	01/03/2016	567509	Campaign 23_15 A3 Poster Change	carried out campaign as required	836658
877	12/23/2015	566667	Vandalism Vandalism/ Graffiti Interior	carried out at knox full a on order - o159931	836658
877	12/23/2015	566667	Vandalism Vandalism/ Graffiti Interior	carried out at knox full a on order - o159931	836658
877	12/23/2015	566664	carry out rebrand as required	rebrand and repairs carried out by knox bodyshop on order - O159923	836658
877	12/11/2015	564421	Consumables		836658
877	12/11/2015	564421	Consumables		836658
877	12/11/2015	564421	Body N/S drivers mirror needs adjusting. No Vision.	adjusted drivers mirror	836658
877	12/03/2015	560939	Consumables		835629
877	12/03/2015	560939	Consumables		835629
877	12/03/2015	560939	Blind Drivers side 1230 wide 6	Creditor #:VB-CUS001 CUSTOM CARE P/O #:O158975 Receiving #:164939 Date :2015-12-09 Drivers blind	836336
877	12/01/2015	560939	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O158552 Receiving #:165513 Date :2015-12-22 reseal side glass x 1 as required	836658
877	11/30/2015	560939	Consumables		834919
877	11/30/2015	560939	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O158544 Receiving #:164438 Date :2015-12-02 carry out complete drivers seat overhaul as required	834919
877	11/30/2015	560939	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O158544 Receiving #:164436 Date :2015-12-02 carry out complete drivers seat overhaul as required	834919
877	11/25/2015	560933	Engine dip stick missing.	refitted original dipstick topped up engine oil 3 litres	833764
877	11/25/2015	560939	Mechanic entered - Body Drivers Seat Controls driver's seat	removed and replaced new driver seat assy. checked adjustments and control botton ops - ok.	833764
877	11/25/2015	560939	Mechanic entered - Body Windows Rear nsr (above the rear wh	glass resealed by alpha glass on order - O158552	833764
877	11/25/2015	560939	Mechanic entered - Body Drivers Seat Controls driver's seat	drivers seat overhauled by auto trimmers on order number - O158544	833764
877	11/25/2015	560939	Mechanic entered - Body Other driver's sunblind us		833764
877	11/23/2015	560414	Consumables		833764
877	11/23/2015	560384	Consumables		833764
877	11/23/2015	560414	Remove Old Poster and Fit new All Night Public Transport Po	carried out campaign as required	833231
877	11/23/2015	560384	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	carried out campaign as required	833231
877	11/20/2015	560112		TRANSMISSION CHECK AS PER CHECK LIST	833231
877	11/20/2015	560112		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	833231
877	11/20/2015	560112		VEHICLE SAFETY INSPECTION	833231
877	11/20/2015	560219	Mechanic entered - Wipers and Washers Washers Not Working	cleaned the nozzles and filled the washer bottle	833231
877	11/20/2015	560217	GLOBE 24V 21W SINGLE CONTACT HLR2421		833231
877	11/20/2015	560217	Mechanic entered - Elec and Light Exterior Lights nsf bottom	fitted festoon	833231
877	11/20/2015	560218	Mechanic entered - Elec and Light Interior Lights driver's l	fitted globe	833231
877	11/18/2015	559592	Consumables		833231
877	11/18/2015	559592	Body Drivers Seat Controls - Weight control Knob broken	pin has come off. fitted a new pin and adjusted the weight	832835
877	11/07/2015	557489	Consumables		831165
877	11/07/2015	557489	rear fleet number us	replaced REAR FLEET NUMBER.OK	830938
877	11/07/2015	557489	DECAL #8 125MM BLACK		830938
877	11/07/2015	557489	DECAL #7 125MM BLACK		830938
877	10/31/2015	556500	Consumables		830203
877	10/31/2015	556500	Checklink Wheel Nut 33mm		829996
877	10/31/2015	556500	Mechanic entered - Wheels and Tyres Other rear wheel nuts li	replaced wheel nut links.	829996
877	10/31/2015	556500	BUSH REAR SWAY BAR K94 SCANIA		829996
877	10/31/2015	556500	Mechanic entered - Suspension Noisy rear sway bar 'D' rubber	removed and refit new rear sway bar 'D' rubber bush.	829996
877	10/31/2015	556498	Consumables		830203
877	10/31/2015	556498	Consumables		830203
877	10/31/2015	556498	Consumables		830203
877	10/31/2015	556498	Consumables		830203
877	10/31/2015	556498		A SERVICE AS PER CHECK LIST	829996
877	10/25/2015	554716	Complete task as instructed in Fleet Campaign 09/15	carried out campaign as required	828364
877	10/04/2015	550051	Replace A3 poster with Victorian Seniors Festival Poster	carry out campaign as required	824195
877	10/01/2015	550457	A/C n/w	checked operation of a/c . cannot fault . air con aont work is the bus is under 22 C we have not had a day over 22 for weeks	824195
877	09/25/2015	548935		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS - carried out by damon from moorabin	823953
877	09/25/2015	548935		VEHICLE SAFETY INSPECTION - carried out by damon from moorabin	823953
877	09/25/2015	549134	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Completed 25/09/15	823953
877	09/22/2015	548166	GLOBE 24V/21W FESTOON		822811
877	09/22/2015	548166	Elec and Light - o/s/f indicator n/w	replaced globe	822811
877	09/22/2015	548166	n/s/f parker n/w	replaced globe	822811
877	09/13/2015	546511	Audit Route buses for correct Decals and positions. Replace	carried out campaign as required	820512
877	09/05/2015	544389	GLOBE FESTOON 24V 5W LONG		818997
877	09/05/2015	544389	n/s/f top park light n/w	r/r globeok.	818997
877	09/05/2015	544389	KIT SLACK ADJUSTER REPAIR		818997
877	09/05/2015	544389	o/s/r slack adjustor u/s	r/r slack adjuster & drive testok.	818997
877	09/03/2015	544389	TUBES FLUORESCENT 18W		818145
877	09/03/2015	544389	REFLECTOR- RED SM		818145
877	09/03/2015	544389	IDLER PULLEY SCANIA ARTIC(No Groove Plastic)		818145
877	09/03/2015	544389	Engine idler pully	r/r idle pully.	818145
877	09/03/2015	544380	diff u/s	fitted diffok.	818145
877	09/03/2015	544389	door step light n/w	r/r fluro tubeok.	818145
877	09/03/2015	544389	n/s/r top water rail u/s	fixed for water rail.	818145
877	09/03/2015	544389	n/s/r reflector n/w	fit new deflectorok.	818145
877	09/02/2015	544380	Direct Purchase - MECHANICAL	Creditor #:VB-BAY002 BAYSWATER DIFF SERVICE PTY LTD P/O #:O155338 Receiving #:160880 Date :2015-09-07 overhaul diff as required	818997
877	09/01/2015	544380	diff u/s	removed diff & clean its.	818145
877	08/31/2015	544250			818145
877	08/31/2015	544250		SERVICE MOISTURE EJECTOR	818145
877	08/31/2015	544250		CARRY OUT VALVE ADJUSTMENT TURBO CHECK & INTERCOOLER/RADIATOR CLEAN AS PER CHECK LIST	818145
877	08/31/2015	544389	o/s/f tyre worn	r/r tyreok.	818145
877	08/31/2015	544380	diff u/s	diff rebuilt at bayswater diffs on order - O155338 remove diff	818145
877	08/31/2015	544250	Consumables		818992
877	08/31/2015	544250	Consumables		818992
877	08/31/2015	544250	O-RING LARGE SPINNER FILTER SCANIA (1769799)		818145
877	08/31/2015	544250	O-RING SPINNER FILTER SCANIA (1769798)		818145
877	08/31/2015	544250	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)		818145
877	08/31/2015	544250	FILTER HYD COOLING FAN SCANIA SR3 (1354074)		818145
877	08/31/2015	544250	FILTER FUEL SCANIA L94UAB (H7090WK30)		818145
877	08/31/2015	544250	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		818145
877	08/31/2015	544250	FILTER FUEL SCANIA SR4(H17WK04)		818145
877	08/31/2015	544250		C SERVICE AS PER CHECK LIST	818145
877	08/31/2015	544250	FILTER AIR DRYER SCANIA SR4 (20546795)(49G8709HALDEX)		818145
877	08/31/2015	544250	Consumables		818992
877	08/31/2015	544250	Consumables		818992
877	08/31/2015	544250		B SERVICE AS PER CHECK LIST	818145

877	08/31/2015	544250	Consumables			818992
877	08/31/2015	544250	Consumables			818992
877	08/31/2015	544250		A SERVICE AS PER CHECK LIST		818145
877	08/28/2015	543969	carry out n/s/r and n/s/f retorque as required	carried out retorque as required		818145
877	08/27/2015	543755	NS Outter tyre worn	double entry		818145
877	08/27/2015	543755	TYRE RECAP 295/80R22.5			818145
877	08/27/2015	543755	TYRE NEW 295/80R22.5			818145
877	08/27/2015	543755	Mechanic entered - Wheels and Tyres Damaged NSF and NSR tyre	Replaced NSF and OSR tyres; tensioned wheel nuts as per specs		818145
877	08/22/2015	542930	Consumables			817592
877	08/22/2015	542930	Body - driver seat base cushion padding flat can feel seat	FITTED SEAT BASE		817156
877	08/22/2015	542930	Retrimmed Base Assy 6008			817156
877	08/19/2015	542099	Attend breakdown at Blackburn Stn.	Travel to Blackburn Stn and jump start bus return to depot.		816749
877	08/19/2015	541924	BATTERY 800CCA EMFN150			816749
877	08/19/2015	541924	Mechanic entered - Engine Other won't start	Replaced one battery as found load test failed. also checked charging at 27.5V.		816749
877	08/09/2015	539572	Consumables			814516
877	08/09/2015	539572	Complete Campaign 6/15 A3 Marketing Poster Change	carried out campaign as required		813938
877	08/08/2015	540038	Back pax bell sticks	free up pax bell switch checked operition ok		814390
877	08/06/2015	539547	front door wont close	adjust door ram speed checked operation ok		813938
877	08/04/2015	539128		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		813712
877	08/04/2015	539128		VEHICLE SAFETY INSPECTION		813712
877	08/04/2015	539128	Consumables			813938
877	08/04/2015	539128	Consumables			813938
877	08/04/2015	539128	GLOBE 24V 75/70W H4			813712
877	08/04/2015	539128		B SERVICE AS PER CHECK LIST		813712
877	08/04/2015	539128	GLOBE FESTOON 24V 5W LONG			813712
877	08/04/2015	539128	ROLLER			813712
877	08/04/2015	539128	Consumables			813938
877	08/04/2015	539128	Consumables			813938
877	08/04/2015	539128		A SERVICE AS PER CHECK LIST		813712
877	08/01/2015	535737	WIPER LINKAGE EYE PIVOT RH THR	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01		813460
877	08/01/2015	535737	WIPER MOTOR. CUSTOM COACH CB 6	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01		813460
877	07/18/2015	535737	Wipers Not working	wiper linakge pivots u/s removed from VOR bus 1183 installed onto the bus checked operation of wipers . checked ok		809756
877	07/16/2015	535961	Engine wont start	jump start bus		808774
877	07/15/2015	535737	Wipers NW	traced wiring found wiper motor u/s . removed wiper motor from 1183 and fit to bus 887. new wiper motor will be installed in bus 1183 .		808774
877	07/15/2015	535820	Engine wont start	replaced u/s battery		808774
877	07/15/2015	535820	BATTERY 800CCA EMFN150			808774
877	07/14/2015	535513	Engine wont start	jump start bus		808774
877	07/13/2015	535318	Mechanic entered - Engine Other battery jump.	started battery jump.		808774
877	07/10/2015	535195	Mechanic entered - Engine Low Power won't start	jump start.		808774
877	07/07/2015	534599	Mechanic entered - Engine Low Power won't start	jump start.		807161
877	07/07/2015	533934	YELLOW 43mm STEP EDGE			807161
877	07/06/2015	533934	Mechanic entered - Engine Other battery jump.	started battery jump.		807161
877	07/06/2015	533934	GLOBE 24V 2W 2663			807161
877	07/06/2015	533934	Mechanic entered - Elec and Light Next Stop Button ns pax st	checked next stop; could not find a fault with either side.		807161
877	07/06/2015	533934	Fuel Guage NW	checked and found fuel gauge working. could not find any fault.		807161
877	07/06/2015	533934	Breakdown After1/2hr layover bus wouldn't start breakdown			807161
877	07/04/2015	533934	Mechanic entered - Engine Other BATTERY JUMP.	STARTED BATTERY JUMP.		807161
877	07/04/2015	533934	Fuel Guage NW			807161
877	07/03/2015	533980	Engine wont start	jump start bus		807161
877	07/02/2015	533934	Mechanic entered - Elec and Light Next Stop Button ns pax st	checked and found os pax working but ns nw at times. checked wiring; could not locate a fault. need further check.		807161
877	06/30/2015	533395	Engine wont start	jump start bus		805748
877	06/23/2015	532323	Mechanic entered - Engine Other chack coolant leaks.	check coolant leakstightened radiator top hose clampsroad tested okput in coolant.		803913
877	06/22/2015	532095		TRANSMISSION CHECK AS PER CHECK LIST		803913
877	06/22/2015	532271	Breakdown-Overheating.	Attended site.Found top radiator hose broken from radiator.Reffited with 2 clamps filled up with coolant.Followed to oakleigh depot		803913
877	06/19/2015	531963	Mechanic entered - Engine Other	JUMP STARTED		803913
877	06/19/2015	531848	Body Front_Door Operation Faulty - Front door rattles. Rat	secure panels at front door.		803913
877	06/15/2015	530981	GLOBE 24V 75/70W H4			803286
877	06/15/2015	530981	Elec and Light - rectify headlight n/w as required	replaced headlight globe checked operation		803286
877	06/08/2015	529939	Elec and Light - Flat Battery	JUMP START.		801866
877	05/29/2015	528611	Service	ANNUAL SAFETY INSPECTION (RWC #)G680244 Performed by fleet check O152016		799734
877	05/29/2015	528611	ROAD WORTHY INSPECTION	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O152016 Receiving #:156626 Date :2015-06-03 carry out bic inspection as required		801059
877	05/29/2015	528646	Consumables			800362
877	05/29/2015	528608	Consumables			800362
877	05/29/2015	528646	Wheels and Tyres - full retorque	re-torque o/s/r wheel nuts. refit links.		798967
877	05/29/2015	528608	TYRE RECAP 295/80R22.5			798967
877	05/29/2015	528608	Mechanic entered - Wheels and Tyres Worn	replaced O/S/R TYRES.		798967
877	05/29/2015	527726	Suspension - n/s/r/r shocker u/s	replaced n/s/r shock absorber.		798967
877	05/28/2015	527726	SHOCKER	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:156304 Date :2015-05-28		799734
877	05/27/2015	528611		PRE ANNUAL SAFETY INSPECTION CHECK		799734
877	05/25/2015	527674		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		798967
877	05/25/2015	527674		VEHICLE SAFETY INSPECTION		798967
877	04/24/2015	522923	GLOBE 24V 21W SINGLE CONTACT			792446
877	04/24/2015	522923	LIGHT SIDE INDICATOR L/H			792446
877	04/24/2015	522923	OS indicator lence broken and some of the passenger bell so	replaced blinker assembly checked all pax switches could not fault		792446
877	04/20/2015	522084	Dash (None) - when customers press the stop button to get	replaced globe W/O 522008		790742
877	04/20/2015	522008	DASH GLOBES			790742
877	04/20/2015	522008	Dash (None) - when customers press the stop button to get	replaced 'next stop' light on dash. checked all bottons and dash light for operation - ok.		790742
877	04/17/2015	521652	retension rear wheel nuts	retensioned rear wheel nuts Re-torqued offside and near side rear tyres to the right Spec.		790742
877	04/17/2015	521652	Elec and Light Indicators Not Working O/S side indicator	Replaced globe.		790742
877	04/17/2015	521652	GLOBE 24V 21W SINGLE CONTACT			790742
877	04/17/2015	521652	Body - Driver seat needs replacing no adjustment no cushi	Could not find fault.		790742
877	04/14/2015	521094		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		790381
877	04/14/2015	521094		VEHICLE SAFETY INSPECTION		790381
877	04/14/2015	521154	Wheels and Tyres - n/s/r tyres u/s	replaced n/s/r inner tyre. refit valve extension. refit wheel nuts link. torque wheel nuts.		790381
877	04/14/2015	521154	next stop pax bell n/w	refit pax 'next stop' botton. replaced terminals. checked for operation - ok.		790381
877	04/14/2015	521154	SWITCH- STOP-YELLOW			790381
877	04/14/2015	521154	LAMP LED TURN			790381
877	04/14/2015	521154	TYRE RECAP 295/80R22.5			790381
877	04/14/2015	521154	FESTOON 24V 10W 7550			790381
877	04/14/2015	521154	o/s/r bottom indicator n/w	replaced indicator lens assy. replaced terminals.		790381
877	04/14/2015	521154	n/s top parklight n/w	replaced n/s top park light and indicator globes. refit top panel and desto hatch.		790381
877	04/14/2015	521094	Consumables			790460
877	04/14/2015	521094	Consumables			790460

877	04/14/2015	521094	Consumables			790460
877	04/14/2015	521094		A SERVICE AS PER CHECK LIST		790381
877	04/01/2015	503548	supply fittings	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O146863-A Receiving #:154506 Date :2015-04-29 supply fittings connector male 6mm + 4mm connector male 3/16		793191
877	03/29/2015	518273	Replace See Something Say Something Poster	complete audit as required		786306
877	03/18/2015	516692	carry out a/c-a service as required	Cold drive carried out a/c-a service on order - O149476		783652
877	03/17/2015	516692	Direct Purchase - MECHANICAL	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O149476 Receiving #:152816 Date :2015-03-25 carry out a/c-a service as required		786306
877	03/10/2015	515285	Body & Acc Drivers Seat Cushion - Driver Seat is Worn. Dri	checked drivers seat base and switch control operation. could not fault.		782940
877	03/03/2015	514192	retension nsr wheel nuts	retensioned nsr wheel nuts		781138
877	02/27/2015	513706	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG			780590
877	02/27/2015	513706	TYRE RECAP 295/80R22.5			780590
877	02/27/2015	513706	nsr tyre us	replaced REAR N/S TYRES.		780590
877	02/27/2015	513706	nsr seat bolt loose	tightened n/s/r seat bolts.		780590
877	02/27/2015	513706	nsr window glass trim us	fixed rear n/s window glass trim.		780590
877	02/27/2015	513706	ns frt pax hand rail bracket bolt mising	replaced fax hand rail bracket bolts.		780590
877	02/27/2015	513706	ns mirror bolt loose	tightened n/s mirror bracket bolts.		780590
877	02/20/2015	512451		VEHICLE SAFETY INSPECTION		779700
877	02/20/2015	512451		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		779700
877	02/19/2015	512171	Air Cond (None)Bus roof A/C Ventilation grill vibrates a	SECURED HATCH.		779190
877	02/12/2015	511083	Elec & Light Horn not working	TRACE WIRINGREMOVE STEERING WHEEL FOUND CONTACT FOR STEERING COLUM STUCK REPOSITION CONTACT HORN OK.		777700
877	02/05/2015	510088	drivers seat base u/s	replaced drivers seat base .		776617
877	02/03/2015	509336	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O147981 Receiving #:151688 Date :2015-03-03 rectify cctv not recording as required		781417
877	02/02/2015	509336	Security CCTV System Faulty - CCTV hasn't recorded since	cctv repaired by lonsdale on order number - 0147981		775363
877	01/30/2015	504373	ROLLER	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147244 Receiving #:150075 Date :2015-01-30		775363
877	01/30/2015	504373	DRAG LINK SCANIA 40L2227ZF	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147244 Receiving #:150075 Date :2015-01-30		775363
877	01/30/2015	504373	SR4 BELT TENSIONER	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147244 Receiving #:150075 Date :2015-01-30 1859654		775363
877	01/30/2015	488618	Hose trans cooling	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147244 Receiving #:150075 Date :2015-01-30		775363
877	01/27/2015		0 Imported Service History	Imported Service History		774877
877	01/27/2015	508487	SINGLE SEAT BASE			774877
877	01/27/2015	508487	GLOBE 24V 10W S/C			774877
877	01/27/2015	508487	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706			774877
877	01/27/2015	508487	dash switch light n/w	r/r globe.		774877
877	01/27/2015	508487	rear step light n/w	r/r globeok.		774877
877	01/27/2015	508417	Mechanic entered - Body & Acc Passenger Seat Cushion	r/r pax seat cushionok.		774877
877	01/27/2015	508487	rear pax seat base has play in it	removed pax shell & fixed for seat braketok.		774877
877	01/27/2015	508487	rear door step edge	fitted new edgeok.		774877
877	01/27/2015	508417	Consumables			774877
877	01/27/2015	508417	Consumables			774877
877	01/27/2015	508417	O-RING KIT OIL SPINNER FILTER SCANIA	Kit . filter Cent		774877
877	01/27/2015	508417	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	Filter Oil		774877
877	01/27/2015	508417	FILTER FUEL SCANIA SR4(H17WK04)	Fuel Filter		774877
877	01/27/2015	508417	OIL ENGINE DELO 400LE 15W40 (LU18)	Engine Oil		774877
877	01/27/2015	508417		Tension ALL Wheel Nuts to OEM Specs		774877
877	01/27/2015	508417		A - Service & Bus Safety Inspection		774877
877	01/27/2015	508417	HYDRAULIC TORQUE FLUID 414	Torque fluid		774877
877	01/27/2015	508417	FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)	Filter ZF Trans		774877
877	01/27/2015	508417	Consumables			774877
877	01/27/2015	508417	Consumables			774877
877	01/27/2015	508417		Tension ALL Wheel Nuts to OEM Specs		774877
877	01/27/2015	508417		A - Service & Bus Safety Inspection		774877
877	01/13/2015	506361	Body & Acc Drivers Seat Cushion seat base cushion not hor	FIT NEW DRIVERS SEAT BASE.		772548
877	01/03/2015	504373	Mechanic entered - Steering Other	removed steering drak link replaced steering drak link.		770366
877	01/03/2015	504373	Mechanic entered - Engine Other	replaced engine belt tentioner.		770366
877	01/03/2015	504373	Mechanic entered - Engine Other	replaced engine belt ilder bearing.		770366
877	01/02/2015	504647	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	completed during service		770366
877	12/31/2014	504373		Perform Safety Inspection as per checklist		769861
877	12/31/2014	504373	Mechanic entered - Whls & Tyres Puncture	replaced rear o/s old tyre.		769861
877	12/31/2014	504373	AIR SPRING (SP0003A)			769861
877	12/31/2014	504373	Mechanic entered - Suspension Leaking	replaced rear o/s/f air bag.		769861
877	12/31/2014	504373	Mechanic entered - Suspension Leaking	removed and refit o/s rear-front airbag. secured air line hose and joiner.		769861
877	12/31/2014	504373	Mechanic entered - Engine Other	replaced engine belt tentioner bearing.		769861
877	12/31/2014	504373	Mechanic entered - Eng Cool Leaking	tightened coolant hose clamp.		769861
877	12/31/2014	504373	Mechanic entered - Security CCTV Check System	fixed cctv wiresreplaced fuse.		769861
877	12/31/2014	504373	Mechanic entered - Brakes Losing Air	fixed rear o/sbrake booster union.		769861
877	12/24/2014	503661	Air System Leaking air line to drivers seat has blown of	fit new hose to drivers seat checked operation of drivers seat ok		767226
877	12/23/2014	503548	Air System - blown air bag??	fittings for drivers seat supplied by enzed on order O146863 - repaired air line to drivers seat checked operation of drivers seat - ok		767226
877	12/15/2014	502083	A3 Poster Change	Fit by Fleet Support Staff		765663
877	12/12/2014	503548	supply air fittings for driver	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O146863 Receiving #:149209 Date :2015-01-07		771155
877	12/06/2014	500561	Drv entered - Breakdown Mech Defect Affects Service	could not fault bus		764347
877	12/02/2014	499753	air valve block leaking	replaced air dryer valve block. secured air line hose and connectors.		763753
877	12/02/2014	499753	Inverter 24v 36W MAN			763753
877	12/02/2014	499753	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706			763753
877	12/02/2014	499753	AIR DRYER VALVE BLOCK (BLACK)(35clf0155)			763753
877	12/02/2014	499753	dash light n/w	replaced globes		763753
877	12/02/2014	499753	FLUORESCENT TUBES 18W			763753
877	12/02/2014	499753	Globe 24V 5W D/C			763753
877	12/02/2014	499753	DASH GLOBES			763753
877	12/02/2014	499753	saloon light n/w	replaced floro tube. replaced inverter and terminals.		763753
877	12/02/2014	499753	front step light n/w	replaced globe. replaced dash light globes. replaced dash switch globes.		763753
877	12/02/2014	499691	Consumables			0
877	12/02/2014	499691	Consumables			0
877	12/02/2014	499691	Consumables			0
877	12/02/2014	499691		A - Service & Bus Safety Inspection		763753
877	12/02/2014	499691		Tension ALL Wheel Nuts to OEM Specs		763753
877	12/01/2014	496784	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUTO05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O145603 Receiving #:148107 Date :2014-12-03 repair driver's seat base as required		763845
877	11/18/2014	497209	Remove Legacy Poster and replace with See Something Say So	Replaced poster as required		760350
877	11/15/2014	496784	Body & Acc Drivers Seat Cushion seat's base cushion not	replaced driver's seat base PO O145603		759355
877	11/14/2014	485463	ROLLER	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O145158 Receiving #:147430 Date :2014-11-14		759355
877	11/10/2014	495451		Perform Safety Inspection as per checklist		758557
877	11/10/2014	495505	dash indicator light nw	replaced dash globe		758557
877	11/10/2014	495505	AIR DRYER VALVE BLOCK (BLACK)(35clf0155)			758557
877	11/10/2014	495505	GLOBE&HOLDER GREY 1.2W			758557
877	11/10/2014	495451	Body & Acc Interior water leaking from sun blind onto das	squirted water and found frt rh pillar leaking. re-sealed tested ok.		758557
877	11/10/2014	495505	Air System leaking	replaced air dryer valve black		758557

877	11/06/2014	494871	GLOBE FESTOON 24V 18W	replaced festoon	758006
877	11/06/2014	494871	nsf bottom indicator nw		758006
877	11/01/2014	494212	Heat & Demist Demisters Cold also climate control does no	opened the heater tap. road tested ac and	756950
877	11/01/2014	494212	Body & Acc Drivers Seat Belt - Drivers Seat belt not retr	repositioned the seat belt and tightened	756950
877	10/27/2014	492819	Air Cond Air Conditioner - Stays On 11.5 C	run a/c could not fault	756128
877	10/27/2014	492819	Heat & Demist not working	double entry	756128
877	10/27/2014	492819	Heat & Demist Heater Cold Blows Cold Air	secured heater tap cable road test to operating temp still cold . rebook for u/s boost pump	756128
877	10/27/2014	492819	Front n/s buzzer n/w	double entry	756128
877	10/27/2014	492819	Elec & Light Bell Button - Front N/S Buzzer Not Working.	fit new pax switch	756128
877	10/23/2014	492452	Wheel nut retention - front axle both sides retorque	carried out wheel nut retention as required	755082
877	10/20/2014	491785	Complete AM/FM radio saloon speaker modification	carried out speaker disconnect campaign as required	755082
877	10/20/2014	491737	Elec & LightPax bell gets stuck every time when used	repaired wiring to front pax button checked operation ok	755082
877	10/17/2014	491615	Whls & Tyres - n/s/f tyre u.s	replaced front tyres. torque wheel nuts. refit wheel nuts pointers.	754522
877	10/17/2014	491615	AIR DRYER VALVE BLOCK (BLACK)		754522
877	10/17/2014	491615	Suspension- front D rubbers u/s	replaced front 'D' rubbers.	754522
877	10/17/2014	491555	Heat & Demist Not Working		754522
877	10/17/2014	491615	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706		754522
877	10/17/2014	491615	GLOBE&HOLDER GREY 1.2W		754522
877	10/17/2014	491615	STABILIZER BAR BUSH FRONT L94UAB		754522
877	10/17/2014	491615	dash switch lights n/w	replaced globes	754522
877	10/17/2014	491615	dash lights n/w	replaced dash lights globe.	754522
877	10/17/2014	491555	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O144697 Receiving #:146837 Date :2014-10-28	756410
877	10/17/2014	491555	Body & Acc Drivers Seat Cushion seat's base not horizonta	removed and refit drivers seat base. sent out for repair.	754522
877	10/17/2014	491615	Air System - control valve leaking	removed and replaced unloader valve. secured air lines. checked for air leak.	754522
877	10/17/2014	491555	Consumables		0
877	10/17/2014	491555	Consumables		0
877	10/17/2014	491555	FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)		754522
877	10/17/2014	491555	COOLANT PREMIX NF48 (use L830)		754522
877	10/17/2014	491555	GREASE ENERGREASE LC2-T		754522
877	10/17/2014	491555	OIL AUTO TRANS ATF H/DUTY		754522
877	10/17/2014	491555	OILBP MULTIFLEET /Ltr		754522
877	10/17/2014	491555	O-RING		754522
877	10/17/2014	491555	O-RING		754522
877	10/17/2014	491555	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		754522
877	10/17/2014	491555	ZF GEARBOX FILTER		754522
877	10/17/2014	491555		Tension ALL Wheel Nuts to OEM Specs	754522
877	10/17/2014	491555		A - Service & Bus Safety Inspection	754522
877	10/17/2014	491555	Consumables		0
877	10/17/2014	491555	Consumables		0
877	10/17/2014	491555		Tension ALL Wheel Nuts to OEM Specs	754522
877	10/17/2014	491555		A - Service & Bus Safety Inspection	754522
877	10/09/2014	490161	Eng Cool Coolant Low - This bus required two liters of coo	topped up coolant replaced radiator cap with second hand unit . road tested ok	752979
877	10/08/2014	489278	THERMOSTAT SCANIA K230	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O144095 Receiving #:146144 Date :2014-10-08	752979
877	10/08/2014	489278	THERMOSTAT SEAL	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O144095 Receiving #:146144 Date :2014-10-08	752979
877	10/08/2014	489894	Eng Cool - Header Tank/leaking Coolant.	top up coolant .	752697
877	10/06/2014	489278	Eng Coolant getting less and over heating at times	drain coolant and remove thermostat . check found one port blocked . WOP . fit new thermostat refill coolant steam clean radiator road test OK .	752348
877	10/06/2014	489278	COOLANT PREMIX NF48		752348
877	10/04/2014	489278	Eng Coolant getting less and over heating at times	check over heating check coolant hose ok check air comperssor ok checked coolant prssure ok removed coolant found thermostat order thermostat.	752348
877	10/04/2014	489278	Eng Coolant getting less and over heating at times	took for a drive checked for leaks.	752348
877	10/04/2014	489278	Eng Cool Coolant Lowheader tank was almost empty needs	rectify coolant leak found on heater hose.	752348
877	10/03/2014	489195	Remove old decal and fit new Authorised Officers Decal DO N	Completed as required	752348
877	10/01/2014	488618	COOLANT PREMIX NF48		751839
877	10/01/2014	488618	TRIDON HOSE CLAMP 12MM 50-70		751839
877	10/01/2014	488618	Engine over heated	removed bus 1183 engine coolant hose installed bus 877 engine coolant hose. replaced coolant hose clampscoolant.	751839

877	08/15/2014	480148	Body & Acc Drivers Seat Cushion - Driver seat base cushion	replaced driver's seat cushion from one of the decommissioned bus.		742313
877	08/14/2014	478035	FREIGHT	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14 FREIGHT IN F/BRAKE VALVE 40G0105	VOR	742595
877	08/14/2014	478035	VALVE FOOTBRAKE WITH RETARDE	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14		742595
877	08/09/2014	479139	Body & Acc Security Door above drivers head needs to be c	secured driver's over head locker		741263
877	08/07/2014	478670	SWITCH- STOP-YELLOW			740717
877	08/07/2014	478670	Elec & Light Bell Button - second from the rear off side	fit new pax switch .		740717
877	08/05/2014	478035	Breakdown- rectify door brakes coming on as required	traced and found footbrake valve u/s . r/r footbrake valve . road and brake tested ok		739872
877	08/04/2014	478035	Sub-contracted - MECHANICAL	Creditor #:-VB-EAGTOW Eagle Towing & Salvage P/O #:O141988 Receiving #:144251 Date :2014-08-14 Road tolls		742313
877	08/04/2014	478035	Sub-contracted - MECHANICAL	Creditor #:-VB-EAGTOW Eagle Towing & Salvage P/O #:O141988 Receiving #:144251 Date :2014-08-14 Tow Vehicle as required		742313
877	08/04/2014	478035	Breakdown- rectify door brakes coming on as required	refit axle jacked up bus		739872
877	07/29/2014	476290	V-CLAMP	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O141648 Receiving #:143591 Date :2014-07-29		739327
877	07/29/2014	476290	O -RING	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O141648 Receiving #:143591 Date :2014-07-29		739327
877	07/29/2014	476290	CONSUMABLE DELIVERY CHARGE	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O141648 Receiving #:143591 Date :2014-07-29 Freight for 0368030 + 1445398 Sc Dandy to Oak		739327
877	07/26/2014	474043	P.B.R.VALVE (0570866)P/Br SR4	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141235 Receiving #:143520 Date :2014-07-26		738718
877	07/24/2014	476233		Perform Safety Inspection as per checklist finished safety inspection		738250
877	07/24/2014	476290	Engine idle pulley us	r/r belt tentioner & idle pullyok.		738250
877	07/24/2014	476290	ROLLER			738250
877	07/24/2014	476290	PULLEY IDLER SCANIA			738250
877	07/24/2014	476290	intake pipe o-ring and clamp us	r/r o-ring & clampok.		738250
877	07/24/2014	476290	Belt tensioner K			738250
877	07/24/2014	476233		Tension ALL Wheel Nuts to OEM Specs checked for wheel nutok.		738250
877	07/24/2014	476233		A - Service & Bus Safety Inspection finished a-service		738250
877	07/24/2014	476233	Consumables			0
877	07/24/2014	476233	Consumables			0
877	07/24/2014	476233	Consumables			0
877	07/24/2014	476233	Consumables			0
877	07/21/2014	475408	Elec & LightSpeedo light on the dash n/w	replaced speedo ill/globes		736604
877	07/21/2014	475408	GLOBE&HOLDER GREY 1.2W			736604
877	07/14/2014	473991	Retrimmed Base Assy 6008			735723
877	07/14/2014	471483	COOLANT PREMIX NF48	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O140695 Receiving #:143024 Date :2014-07-14		735950
877	07/14/2014	471483	HOSE BEND	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O140695 Receiving #:143024 Date :2014-07-14 0481886		735950
877	07/14/2014	474043	Brakes Locking	checked for air leak won't build up. found unloader valve blocked. also hand brake valve leaking. replaced h/brk valve and air dryer unloader valve. road/brakes tested.		735723
877	07/14/2014	474043	Brakes Locking	found foot valve u/s .		735723
877	07/14/2014	474043	P.B.R.VALVE (0570866)P/Br SR4			735723
877	07/14/2014	474043	AIR DRYER VALVE BLOCK (BLACK)			735723
877	07/12/2014	473991	Body & Acc Drivers Seat Cushion padding leans to the left	replaced driver's seat base		735723
877	07/02/2014	471933	Eng Cool Leaking no coolant in header tank	top up coolant checked for leaks ok		733086
877	07/01/2014	460471	Repair A/C as required	Creditor #:-VB-COLO04 COLD DRIVE AIR CONDITIONING P/O #:O139796 Receiving #:143423 Date :2014-07-24		738011
877	07/01/2014	471483	Sub-contracted - MECHANICAL	Creditor #:-VB-EAGTOW Eagle Towing & Salvage P/O #:O141130 Receiving #:143000 Date :2014-07-11 tow the bus from centre rd to oakleigh depot		735723
877	06/30/2014	471483	Fit Wheel Nut Pointers to all wheel nuts on the front axle	installed wheel nut pointers		732716
877	06/30/2014	471483	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	installed wheel extensions		732716
877	06/30/2014	471483	Ops Entered - Breakdown - Breakdown Change Over Request -	Cooling System .locate split hose and replace top up coolant .		732716
877	06/27/2014	469712	STOP/TAI LAMP	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	467395	ASSORTED TERMINALS	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	467395	PUMP BOOST 24V	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	467395	AIR DRYER VALVE BLOCK (BLACK)	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	467395	GLOBE 24V/21W FESTOON	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	467395	GLOBE 24V SCHOOL LAMP	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	470384	GAS STAY 600N- 501 MM (40059)	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	470384	Potentiometer- retard switch	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	GREASE ENERGREASE LC2-T	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	OIL AUTO TRANS ATF H/DUTY	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	OILBP MULTIFLEET /ltr	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	O-RING	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	O-RING	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	FILTER ZF TRANS	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	FILTER	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	FILTER ELE L94 & EARLY K230	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27		732716
877	06/27/2014	468761	OIL FILTER	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O140073 Receiving #:142465 Date :2014-06-27 H200W20		732716
877	06/24/2014	470384	Body & AccRear hatch does not stay open	r/r rear hatch strut barsok. r/r n/s/r indicator lightok.		732229
877	06/24/2014	470384	BrakesRetrarter not working	checked and found foot valver potentiometer u/s. removed air lines to the foot valve and pulled the whole valve out. dismantled the valve replaced retarder potentiometer. fitted valve and air lines. adjusted switch road brakes tested ok.		732229
877	06/24/2014	470384	Brakes are spongy and grabbing	road tested found retarder n/w . footbrake valve poteniometer n/w . needs to be replaced		732229
877	06/23/2014	470080	Elec & LightFront n/s stop button hanging loose	resecured pax button		731446
877	06/20/2014	469712	Elec & Lightrn/s tail light n/w	R/R new LED stop light .		731446
877	06/20/2014	469713	Brakes are grabbing	adj brakes road and brake test ok .		731446
877	06/16/2014	465340	1MT MULTI FIT WIPER REFILL	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	465340	SINGLE SEAT BASE	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	465340	GLOBE WEDGE 24V 1.2W	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	465340	PULLEY IDLER SCANIA	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	467395	o.s.r.o tyre u/s	replaced o/s/r inner and outter tyres. checked and torque wheel nuts. refit wheel nuts yellow guide.		730430
877	06/16/2014	467395	Engine coolant leak from boost pump	replaced boost pump		730430
877	06/16/2014	467770	GLOBE 24V 75/70W H4	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	467395	front indicators u/s	replaced osf top indicator festoon		730430
877	06/16/2014	467395	Perform Campaign 1_14 School Bus Light Globe Check Check w	removed all school lights and replaced globes with 35W. fitted both frt lights.		730430
877	06/16/2014	465612	FLUSH HINGE R/H	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	465612	BUSH REAR SWAY BAR K94 SCANIA	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	465612	BUSH	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16		730896
877	06/16/2014	467395	Brakes - no retarder	road test and brake test. retarder n/w andslight wheel vibration when brake is applied. retarder switch ordered		730430
877	06/16/2014	467395	Brakes VERY NOISY			730430
877	06/16/2014	467395	Air System leaking air from unloader valve			730430
877	06/16/2014	468761		replaced unloader		730430
877	06/16/2014	468761		Tension ALL Wheel Nuts to OEM Specs		730430
877	06/16/2014	468761		A - Service & Bus Safety Inspection		730430
877	06/16/2014	468761		Tension ALL Wheel Nuts to OEM Specs		730430
877	06/16/2014	468761		A - Service & Bus Safety Inspection		730430
877	06/14/2014	467395	Brakes - no retarder	diagnosed and found foot valve potentio meter us need to replace		730430
877	06/10/2014	467770	n/s headlight n/w	fit new globe		728722
877	06/06/2014	467395	Perform Campaign 1_14 School Bus Light Globe Check Check	replaced all globes.		729043
877	06/05/2014	467307	replace smashed rear door glas	Creditor #:-VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O139799 Receiving #:141688 Date :2014-06-10		729739
877	06/05/2014	467307	Passenger Doors - Rear passenger door glass broken.	glass replaced by alpha glass		728722
877	06/05/2014	467310	Perform Campaign 1_14 School Bus Light Globe Check Check			728722
877	06/05/2014	467310	Security CCTV System Faulty - CCTV hasnt' recorded since	checked and found cctv unit pwr fuse blown replaced fuse checked recording ok.		728722
877	06/04/2014	466788	phil to carry out body work bi	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139679 Receiving #:141684 Date :2014-06-10		729739
877	06/03/2014	466788	Carry out bic repairs as required - phil in b-shop			728334

877	05/30/2014	465612	v-rod bushes us	r/r v rod bush. fitted v-rod & tighten boltsok.	727803
877	05/30/2014	465612	sway bar and D rubber bushes us	refit V rod and rubber bush. refit V rod. removed sway bar link and D rubbers(assist JHL)	727803
877	05/30/2014	465612	sway bar and D rubber bushes us	removed s-way bar bushes & linkages. fi fitted sway bar & replace d-rubbersok.	727803
877	05/28/2014	465612	os mirror bracket loose	removed mirror & made bolt tradefitted mirror & checked againok. found drivers sun blind u/sfixed sun blindok.	727464
877	05/28/2014	465612	pax pole bracket us	fixed pax poleok.	727464
877	05/28/2014	465612	rear pax seat loose	removed rear pax seat & tighten seat braket boltsok.	727464
877	05/27/2014	465428			727434
877	05/27/2014	465428			727434
877	05/27/2014	465380	ROAD WORTHY INSPECTION	Perform Safety Inspection as per checklist	727434
877	05/27/2014	465380		Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O139374 Receiving #:141189 Date :2014-05-28	727434
877	05/27/2014	465380			727434
877	05/27/2014	465380		Inspect vehicle as per RSI Checklist	727434
877	05/27/2014	465340		Inspect vehicle as per RSI Checklist replacedrear n/s in tyre.ok	727434
877	05/27/2014	465340		SERIAL F 807879	727434
877	05/27/2014		0 Imported Service History	Imported Service History	727434
877	05/27/2014	465427			727434
877	05/27/2014	465427		wheel tention	727434
877	05/27/2014	465427		A - Service & Bus Safety Inspection a service & safety inspection. r/r wiper rubbers. r/r rear seat cushion. r/r engine bearing.	727434
877	05/23/2014	462711	INDICATOR STALK SCANIA SERIES	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O138652 Receiving #:141012 Date :2014-05-23	726681
877	05/23/2014	464343	DRIVERS FAN 24V	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O138652 Receiving #:141012 Date :2014-05-23	726681
877	05/23/2014	464792	Brakes need adjusting when applied the brakes pull suddenl	adj brakes road and brake test ok .	726541
877	05/21/2014	464343	Body & Acc - driver's fan loose and noisy	remove wire in new fan .	726211
877	05/18/2014	462846	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	carried out A3 replacement as required	724089
877	05/15/2014	463060	Elec & Light Headlights O/S Headlight out	replaced globe checked operation ok	724089
877	05/14/2014	462711	Elec & LightThe R/H indicator have to hold with the hand	removed and fit new indicator stalk	724089
877	05/09/2014	459554	GLOBE 24V 75/70W H4	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	723408
877	05/01/2014	460471	Air Cond Air Conditioner n/w	a/c condensor fan motor brushes replaced by coldrive on tims order number	721689
877	05/01/2014	460413	Elec & Light Indicators do not cancel when making a right	make and fit new cancell striker plate .	721689
877	05/01/2014	460413	Ops Entered - Fault - Body & Acc Water Leak - Route: 703 -	road test to operating temp could not fault coolant leak .	721689
877	04/26/2014	459554	Elec & Light Headlights n/s not working	fit new globe	720353
877	04/15/2014	458026		Perform Safety Inspection as per checklist	718407
877	04/15/2014	458088	Air Cond pip bracket bolts missing	fixed a/c braket.ok	718407
877	04/15/2014	458088	Air Cond pip bracket bolts missing	removed bracket. secured pipe.	718407
877	04/15/2014	458088	Engine belt u.s	r/r engine belt.ok	718407
877	04/15/2014	458088	Engine belt u.s	removed & refit a/c belts. checked belt tension.	718407
877	04/15/2014	458088	air filter u/s	replaced air filter. secured filter housing bracket.	718407
877	04/15/2014	458088	dash switch light n/w	replaced wedge x 2	718407
877	04/15/2014	458088	drivers light n/w	replaced globe. replaced terminal in inverter.	718407
877	04/15/2014	458088	reverse light broken lens	replaced lens x 2. change globe.	718407
877	04/15/2014	458088	dash lights n/w	replaced dash globes x 2	718407
877	04/15/2014	458088	Mechanic entered - Security CCTV System Faulty check and rec	replaced blade fuse x 2. checked & connect removed terminal on camera #2	718407
877	04/15/2014	458088	drivers modesty panel u/s	fixed modesty panel.ok	718407
877	04/15/2014	458088	drivers modesty panel u/s	secured screws on top drivers carrier panel.	718407
877	04/15/2014	458088	missing decals	refit decals	718407
877	04/15/2014	458026			718407
877	04/15/2014	458026	OIL AUTO TRANS ATF H/DUTY	Filter Air Dryer	718407
877	04/15/2014	458026	FILTER	Raycor filter	718407
877	04/15/2014	458026	VANELLUS ECO 10W/40 FOR MAN	Hydraulic oil	718407
877	04/15/2014	458026	FILTER OIL/CONT HYD FAN	Hydraulic filter	718407
877	04/15/2014	458026	P/STEER FILTER 0153468	Power steering filter	718407
877	04/15/2014	458026	BP DIFF OIL HYPGEAR 85W140 EP (205LTS)	diff oil	718407
877	04/15/2014	458026		Service as per check list	718407
877	04/15/2014	458026		Tension ALL Wheel Nuts to OEM Specs	718407
877	04/15/2014	458026		A - Service & Bus Safety Inspection	718407
877	04/13/2014	456520	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	carried out campaign as required	715284
877	04/06/2014	455525	Fit Myki decals as requiredFit Recruitment decal as requi	carried out campaign as required	715284
877	04/02/2014	455444	Brakes Noisy also rear pax button sticks on	unstick rear pax switch rebooked noisy brakes for 3-4-14 checked operation of pax switch ok	715284
877	04/01/2014	449432	BOLT HX HD 8X50	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	450599	GLOBE 24V 75/70W H4	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	453604	INDICATOR STALK SCANIA SERIES	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	452432	O RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	452432	LOCK RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	OIL FILTER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	AIR CON.BELT TRI POWER S/4	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	Wheel steering RECO L94	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	S/T SCR C/S PHL 7982 ZN 3.5X25	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	CONT TUBE 12 - 16	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	GAS STAY 960N (41200)	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	AIR SPRING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	FILTER FUEL K124 / LU94A (14	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	FILTER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	O-RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	O-RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	04/01/2014	451404	FILTER ZF TRANS	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	718407
877	03/22/2014	453604	Elec & Light Indicators will not cancel after making right	made and fitted a new striker plate and replaced blinker stalk.	712537
877	03/18/2014	452432	Brakes Noisy and not very effective with full load.	installed front brakes linings & replaced front bothside brakes durms. ok	712169
877	03/18/2014	452432	Brakes Noisy and not very effective with full load.	installed rear brakes linings & replaced rear bothside brakes durms. ok	712169
877	03/18/2014	452432	Brakes Noisy and not very effective with full load.		712169
877	03/18/2014	452432	Brakes Noisy and not very effective with full load.	assisted SHO to fit the brakes fitted rear wheels.	712169
877	03/18/2014	452432	Brakes Noisy and not very effective with full load.		712169
877	03/17/2014	452432	Brakes Noisy and not very effective with full load.		712169
877	03/11/2014	451496		Perform Safety Inspection as per checklist	710379
877	03/11/2014	451404		cut out a hole in floor access to airbag fitted a plate on floor. ok	710379
877	03/11/2014	451404		replaced hornpad kit & hornpad. ok replaced airline fitting on airbag. ok	710379
877	03/11/2014	451404		replaced hatch strut. ok	710379
877	03/11/2014	451404		replaced rear n/s/f air bag. ok	710379
877	03/11/2014	451404		replaced A/C belts. ok	710379
877	03/11/2014	451404		replaced steering wheel. ok	710379
877	03/11/2014	451404		Tension ALL Wheel Nuts to OEM Specs	710379
877	03/11/2014	451404		A - Service & Bus Safety Inspection	710379
877	03/11/2014	451404			710379
877	03/11/2014	451404		Tension ALL Wheel Nuts to OEM Specs	710379
877	03/11/2014	451404		A - Service & Bus Safety Inspection	710379
877	03/11/2014	451404		replaced headlight globe	709654

877	02/26/2014	449432		Adjust Tappets adjusted tappets & road tasted ok.	707949
877	02/20/2014	448475	Engine	Stalling or loosing power does not accelerate prop	706702
877	02/20/2014	448472	Body & Acc	Drivers Seat Mount weight suspension spring ad	706702
877	02/19/2014	448069	Elec & Light	AM/FM radio n/w	706702
877	07/10/2013		0	Imported Service History	660277
877	05/30/2013		0	Imported Service History	651655
877	04/04/2013		0	Imported Service History	640283
877	10/08/2012		0	Imported Service History	604492
877	10/08/2012		0	Imported Service History	604492
877	10/08/2012		0	Imported Service History	604492
877	08/16/2012		0	Imported Service History	0
877	08/16/2012		0	Imported Service History	0
877	01/21/2012		0	Imported Service History	549709
877	07/10/2008		0	Imported Service History	289894
877	07/01/2008		0	Imported Service History	290000
877	06/19/2008		0	Imported Service History	284894
877	05/29/2008		0	Imported Service History	279894
877	05/07/2008		0	Imported Service History	274894
877	04/16/2008		0	Imported Service History	269894
877	03/26/2008		0	Imported Service History	264894
877	03/05/2008		0	Imported Service History	259894
877	02/12/2008		0	Imported Service History	254894
877	01/22/2008		0	Imported Service History	249894
877	01/01/2008		0	Imported Service History	244894
877	12/10/2007		0	Imported Service History	239894
877	12/01/2007		0	Imported Service History	0
877	11/19/2007		0	Imported Service History	234894
877	10/29/2007		0	Imported Service History	229894
877	10/08/2007		0	Imported Service History	224894
877	09/16/2007		0	Imported Service History	219894
877	08/26/2007		0	Imported Service History	214894
877	08/05/2007		0	Imported Service History	209894
877	07/15/2007		0	Imported Service History	204894
877	06/23/2007		0	Imported Service History	199894
877	06/02/2007		0	Imported Service History	194894