

Veh#	Date	W/O#	Description	Notes	Odometer
878	09/14/2026	1369718		CARRY OUT A/C - A SERVICE AS PER CHECK LIST bus is subject to selling; services have been stopped as instructed by Sue	1338693
878	09/05/2026	1367308		COMPLETED BY ATS 12/8/26	1338693
878	08/05/2026	1359553		VEHICLE SAFETY INSPECTION - BUS IS DUE FOR SALE; PREPARED AND READY TO GO TO AUCTION YARD	1338693
878	08/05/2026	1359553		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1338693
878	07/30/2026	1358144	Decommission Bus for Auction	removed cctv consat two way and busminder	1338693
878	07/30/2026	1358144	Decommission Bus for Auction	removed etag internal and external ventura livery with heat gun fitted plates with screws	1338693
878	06/01/2026	1339194	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O409910 Receiving #:438001 Date :2026-06-01 CARRY OUT ASI AS REQUIRED	1338693
878	05/15/2026	1341109	OSR RETORQUE REQUIRED	Assisting	1338693
878	05/15/2026	1341109	OSR RETORQUE REQUIRED	CARRIED OUT RETORQUE AS REQUIRED	1338693
878	05/15/2026	1341109	Consumables		1338693
878	05/14/2026	1340856	REMOVE FRONT AND REAR PLATES. DISPOSE OF OLD PLATES . INSTAL	Jump start bus in the yard brought up drill out rivets and removed old rego plates fit new rego plates with rivets cut and dispose old rego plate park bus in the yard	1338693
878	05/14/2026	1340856	Consumables		1338693
878	05/08/2026	1339387		VEHICLE SAFETY INSPECTION	1338693
878	05/08/2026	1339387		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1338693
878	05/08/2026	1339495	Consumables		1338693
878	05/08/2026	1339495	Mechanic entered - Wheels and Tyres Other o/s/r inner tyre a	removed o/s/r outer tyre and repaired o/s/r/inner tyre air valve and retorqued o/s/r wheel nuts ok.	1338693
878	05/08/2026	1339531	Consumables		1338693
878	05/08/2026	1339531	Mechanic entered - Elec and Light Other dash fuel gauge ligh	replaced dash fuel gauge light globe ok.	1338693
878	05/08/2026	1339531	Consumables		1338693
878	05/08/2026	1339531	Mechanic entered - Body Other front sun blind not working.	repaired front sun blind ok.	1338693
878	05/08/2026	1339531	Mechanic entered - Body Other radiator bottom bracket bolt l	tightened radiator bottom bracket bolt ok.	1338693
878	05/07/2026	1339194		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1338693
878	05/07/2026	1339194		VEHICLE SAFETY INSPECTION	1338693
878	05/07/2026	1339194		ANNUAL SAFETY INSPECTION SERIAL #RSI 077863 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1338693
878	05/04/2026	1338462	Consumables		1338693
878	05/04/2026	1338462	CARRY OUT 2ND PRE ASI CHECK AS REQUIRED	COMPLETE	1338693
878	04/25/2026	1336520		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carrid out fire safe as per check list	1338107
878	04/22/2026	1335626	PTI Tablet Entered -Body - OTHER. brakes not releasing	build full airroad testbrakes releasingcould not fault.	1337104
878	04/22/2026	1335626	Consumables		1337104
878	04/21/2026	1335299		PRE ANNUAL SAFETY INSPECTION CHECK	1337104
878	04/21/2026	1335299			1337104
878	04/21/2026	1335380	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM		1337104
878	04/21/2026	1335380	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	replaced worn wiper blades with new items from stock checked for clearing screen ok.	1337104
878	04/21/2026	1335380	Mechanic entered - Engine Other Header Tank Mounts Loose	tightened loose header tank mounts	1337104
878	04/21/2026	1335380	BATTERY EXSN94SCMF 1450AAC EMFN150L		1337104
878	04/21/2026	1335380	Mechanic entered - Elec and Light Flat Batteries 1 x Battery	Removed U/S Battery Replaced with new item from stock.	1337104
878	04/21/2026	1335380	Consumables		1337104
878	04/21/2026	1335380	Mechanic entered - Body Other N/S/R seat base torn	removed torn seat base replaced with new item from stock ok.	1337104
878	04/21/2026	1335380	HANDLE HEIGHT & RAKE ORANGE		1337104
878	04/21/2026	1335380	Mechanic entered - Body Drivers Seat Controls Driver Seat Ra	fitted new seat adjuster cover from stock.	1337104
878	04/21/2026	1335380	SEAT CUSH SINGLE CEN CVR CI		1337104
878	04/21/2026	1335380	Mechanic entered - Body Other N/S/R back seat base torn	removed torn seat base fit new seat base from stock ok.	1337104
878	04/21/2026	1335380	Consumables		1337104
878	04/18/2026	1334857	Mechanic entered - Air System Air_Leak Doors From front door	Found split hose for door valve removed and replaced hose with new one	1337103
878	04/17/2026	1334857	Mechanic entered - Elec and Light Flat Batteries	Jump start bus in the yard for charter department	1337103
878	04/17/2026	1334857	Consumables		1337103
878	03/06/2026	1325438	Consumables		1336755
878	03/06/2026	1325438	LIGHT INDICATOR SIDE L/H		1336755
878	03/06/2026	1325438	PTI Tablet Entered -Elec and Light - Indicators Not Working	Removed n/s/f side indicator light assy found broken terminal replaced with new one tested working okay	1336755
878	02/26/2026	1323436		COMPLETED BY ATS 15/2/26	1336755
878	02/12/2026	1320078		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1336755
878	02/12/2026	1320078		VEHICLE SAFETY INSPECTION	1336755
878	02/12/2026	1320078			1336755
878	02/12/2026	1320097	AIRBAG FRONT SCANIA K310UB 2809671		1336755
878	02/12/2026	1320097	Mechanic entered - Suspension Other OSF air bag U/S	Lifted bus. Placed jack stands under body. Removed panel inside bus above airbag. Removed top pins and air line on air bag. Turned wheels full lock right. Removed bottom pins from airbag. Removed airbag. Fit new airbag and pins. Used thread tape to ensure no air leaks from fitting. Started bus sprayed soapy water on a	1336755
878	02/12/2026	1320097	Mechanic entered - Body Other blind not working.	repaired blind ok.	1336755
878	02/12/2026	1320097	Mechanic entered - Body Other driver seat side switch cap mi	replaced driver seat side old switch cap ok.	1336755
878	02/12/2026	1320097	Mechanic entered - Body Other NSF luggage rack cushion loose	Fit screw to secure. OK.	1336755
878	02/12/2026	1320097	SLACK ADJUSTER AUTO-REAR N/SIDE SERIES 4(2009819)		1336755
878	02/12/2026	1320097	Mechanic entered - Brakes Other n/s/r brake slack adjuster n	removed n/s/r brake slack adjuster and replaced n/s/r brake slack adjuster ok.	1336755
878	02/03/2026	1318109	Consumables		1336755
878	02/03/2026	1318109	Mechanic entered - Elec and Light Flat Batteries		1336755
878	11/24/2025	1304791		Jump sarted bus. Let sit for 30 minutes	1336755
878	11/20/2025	1304092		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1336755
878	11/20/2025	1304092		VEHICLE SAFETY INSPECTION carry out safety inspection.	1336755
878	11/20/2025	1304194	Mechanic entered - Wipers and Washers Other N/S wiper hits b	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorqued all wheel nuts.	1336755
878	11/20/2025	1304194	Mechanic entered - Dash Dash_Lights Not Working spedometer g	repositioned and secured wiper arm checked for clearance ok.	1336755
878	11/20/2025	1304194	Mechanic entered - Elec and Light Interior Lights driver ove	fit new globe to speedometer guage checked for function ok.	1336755
878	11/20/2025	1304194	Mechanic entered - Elec and Light Interior Lights O/S/R salo	fit new globe checked for function ok.	1336755
878	11/20/2025	1304194	Mechanic entered - Dash Dash_Lights Not Working tachometer g	fit new fluorescent globe checked for function ok.	1336755
878	11/20/2025	1304194	Consumables	fit new globe to tachometer guage checked for function ok.	1336755
878	11/20/2025	1304194	Mechanic entered - Body Other vinyl floor lifting up		1336755
878	11/20/2025	1304194	Mechanic entered - Body Other O/S disabled seat not secure i	secured lifted section of vinyl with screws ok.	1336755
878	11/11/2025	1302241	Consumables	tightened pivot bolt checked for security ok.	1336755
878	11/11/2025	1302241	CHECK OVER BUS 878		1336282
878	11/10/2025	1301842	Mechanic entered - Elec and Light Flat Batteries	COMPLETED	1336282
878	10/15/2025	1296736	Consumables	Jump started ok.	1336282
878	10/15/2025	1296736	Mechanic entered - Elec and Light Flat Batteries		1336282
878	09/04/2025	1288249	RAIL >>>FUEL TANK LEAKING DIESEL	Jump started batteries let idle for 30 minues OK.	1335344
878	08/28/2025	1286267		PARKED BUS ON PIT . CHECKED FUEL TANK FOR LEAKS . COULD NOT FAULT . PARKED BUS IN GRAVEL AREA . HANDED KEYS TO OPERATIONS . RELEASED BUS IN TIMS	1334565
878	08/27/2025	1285952		COMPLETED BY ATS	1334565
878	08/27/2025	1285952		Assisting	1334565
878	08/27/2025	1285952		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to 650nm.	1334565
878	08/27/2025	1285952		VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.	1334565
878	08/27/2025	1286122	Mechanic entered - Suspension Other N/S/R/F + O/S/R/F shock	Replaced N/S/R/F and O/S/R/F shock absorbers with new.	1334565
878	08/27/2025	1286122	SHOCK ABSORBER REAR SCANIA L94/K124 300 025 1478317		1334565
878	08/27/2025	1285952	OIL SAMPLE TEST KIT		1334565
878	08/27/2025	1285952	OIL SAMPLE TO BE TAKEN AT NEXT SERVICE OR SAFETY INSPECTION	Collected oil sample and filled up all paperwork.	1334565
878	08/11/2025	1281826	AIR CONDITIONING REPAIR	Creditor #:VB-COLO04 COLD DRIVE PTY LTD P/O #:O393022 Receiving #:418101 Date :2025-08-22 24 MONTH SERVICE	1334565
878	08/11/2025	1281826		CARRY OUT A/C - B SERVICE AS PER CHECK LIST PO:O393022 - CARRIED OUT BY BEN FROM COLD DRIVE	1334565
878	08/11/2025	1281826		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1334565
878	08/11/2025	1281826		CARRY OUT A/C - A SERVICE AS PER CHECK LIST PO:O393022 - CARRIED OUT BY BEN FROM COLD DRIVE	1334565
878	08/01/2025	1277532	GRAFFITI FILM AUDIT #1232	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O391667 Receiving #:416572 Date :2025-08-01 OAKLEIGH	1334565

878	07/28/2025	1278864	Consumables	STARTED BUS . CHECKED CHARGE RATE ON DASH . 27.5 VOLTS. LOAD TESTED BATTERYS . COULD NOT FAULT	1374565
878	07/28/2025	1278864	BATTS TO BE REPLACED	DUPLICATED IN ERROR REFER WO# 1110789	1334565
878	07/21/2025	1277531	GRAFFITI FILM AUDIT #1232	REFER PO O391667	1334565
878	07/21/2025	1277532	GRAFFITI FILM AUDIT #1232	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O388478 Receiving #:413041 Date :2025-06-17	1334565
878	06/17/2025	1267734	DIRECT PURCHASE - BUS INSPECTI	VEHICLE SAFETY INSPECTION	1334565
878	06/02/2025	1267734		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1334565
878	06/02/2025	1267734		ANNUAL SAFETY INSPECTION SERIAL #____RSI 071569 PASS____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1334565
878	05/28/2025	1266989	Body (None) carry out 2nd PRE-ASI	checked he bus over and found no issues	1334306
878	05/28/2025	1266989	Consumables		1334306
878	05/28/2025	1266989	Consumables		1334306
878	05/13/2025	1263849		VEHICLE SAFETY INSPECTION carry out safety inspection.	1333528
878	05/13/2025	1263849		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorque all wheel nurs	1333528
878	05/13/2025	1263847	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	retorque o/s/r wheel nuts.	1333528
878	05/13/2025	1263847	Consumables		1333528
878	05/09/2025	1263338	Mechanic entered - Wheels and Tyres Worn O/S/R inner tyre lo	removed O/S/R tyres put inner tyre to disposal replaced inner tyre with runout put tyres back on bus tensioned wheel nuts to OEM spec ok.	1333528
878	05/09/2025	1263338	Consumables		1333528
878	05/09/2025	1263278	SHOCK ABSORBER REAR SCANIA L94/K124 300 025 1478317		1333528
878	05/09/2025	1263278	Mechanic entered - Suspension Other o/s/f shock bottom rubbe	removed O/S/F shock absorber bottom rubbers replaced with new items from stock checked ok.	1333528
878	05/09/2025	1263278	BUSH SHOCK ABSORBER SCANIA		1333528
878	05/09/2025	1263278	Mechanic entered - Suspension Other n/s/r/r shock oil leaks.	removed leak shocker fitted with new shocker	1333528
878	05/09/2025	1263326	Mechanic entered - Elec and Light Other n/s/f top park light	remove old globe fitted with new globe now working	1333528
878	05/09/2025	1263326	Mechanic entered - Elec and Light Other n/s/f bottom park li	removed old globe fitted with new globe now working	1333528
878	05/09/2025	1263326	Consumables		1333528
878	05/09/2025	1263278	Mechanic entered - Body Other front door bottom rubber off.	inserted rubber back into door ok.	1333528
878	05/09/2025	1263278	Mechanic entered - Body Other o/s/f bus inside top panel scr	replaced missing screws with new items from stock ok.	1333528
878	05/09/2025	1263326	Mechanic entered - Body Other o/s and n/s disability seat lo	repaired n/s disability seat 3 and removed disability o/s and n/s 2seat after repaired o/s and n/s disability seat 2 ok./	1333528
878	05/09/2025	1263278	Consumables		1333528
878	05/09/2025	1263278	Consumables		1333528
878	05/09/2025	1263326	Consumables		1333528
878	05/09/2025	1263326	Consumables		1333528
878	05/08/2025	1263059		PRE ANNUAL SAFETY INSPECTION CHECK	1333528
878	05/08/2025	1263059		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1333528
878	05/05/2025	1262216		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	1333528
878	03/14/2025	1248932	THROTTLE PEDAL BOX U/S - AWAITING DIRECTION FROM BEN WILLIS	parts ordered	1333102
878	03/14/2025	1248932	Consumables		1333102
878	03/13/2025	1248932	Service	adjusted throttle link rod to run between 0% to 100%. road/brake tested all good.	1333102
878	03/12/2025	1248932	THROTTLE PEDAL BOX U/S - AWAITING DIRECTION FROM BEN WILLIS	fitted throttle pedal box and foot valve. fitted foot valve and connected air lines.	1333102
878	03/08/2025	1248932	ACCELERATOR PEDAL SCANIA K124I	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O383210 Receiving #:406186 Date :2025-03-11	1333102
878	03/08/2025	1248932	LINK ROD	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O383210 Receiving #:406186 Date :2025-03-11	1333102
878	03/07/2025	1248932	THROTTLE PEDAL BOX U/S - AWAITING DIRECTION FROM BEN WILLIS	removed air lines to foot valve drilled thru rusted throttle box monting bolts and took the pedal assy out.	1333102
878	02/21/2025	1246579	OIL GEAR HP 85W-140 VALVOLINE		1331803
878	02/21/2025	1246579	Consumables		1331803
878	02/21/2025	1246579	Consumables		1331803
878	02/20/2025	1246579		TRANSMISSION CHECK AS PER CHECK LIST Carried out transmission service as per checklist.	1331803
878	02/20/2025	1246579		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist.	1331803
878	02/20/2025	1246579		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts.	1331803
878	02/20/2025	1246579		Assisted.	1331803
878	02/20/2025	1246874	Mechanic entered - Elec and Light Interior Lights N/S/F salo	Replaced N/S/F saloon light fluro with new. Checked now working.	1331803
878	02/20/2025	1246874	Consumables		1331803
878	02/20/2025	1246697		completed by ATS 20-2-25	1331803
878	02/20/2025	1246579	FILTER OIL SCANIA VARIOUS MODELS		1331803
878	02/20/2025	1246579	OIL SAMPLE TEST KIT		1331803
878	02/20/2025	1246579	FILTER FUEL SCANIA VARIOUS MODELS H17WK04		1331803
878	02/20/2025	1246579	FILTER FUEL/WATER SEPARATOR K270IB K310IB E4		1331803
878	02/20/2025	1246579	FILTER POWER STEER SCANIA ALL MODELS 153468		1331803
878	02/20/2025	1246579	FILTER AIR DRYER SCANIA K124IB L94IB L94UAB		1331803
878	02/20/2025	1246579	FILTER AIR OUTER SCANIA K94IB L94UAB K124IB E218L		1331803
878	02/20/2025	1246579	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)		1331803
878	02/20/2025	1246579	FILTER HYD COOLING FAN SCANIA SR3 4 1354074		1331803
878	02/20/2025	1246579	O-RING LOWER SPINNER FILTER SCANIA L94 K124		1331803
878	02/20/2025	1246579	O-RING LARGE UPPER SPINNER FILTER SCANIA		1331803
878	02/20/2025	1246579	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		1331803
878	02/20/2025	1246579		CARRY OUT C SERVICE AS PER CHECK LIST Carried out C service as per checklist.	1331803
878	02/20/2025	1246579	WASHER DIFF PLUG 36MM SCANIA ALL MODELS 49Z1019		1331803
878	02/20/2025	1246579		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist.	1331803
878	02/20/2025	1246579	OIL ENGINE ALL FLEET PLUS E900 15W-40		1331803
878	02/20/2025	1246579	OIL ATF STEERING DEX-3 VALVOLINE		1331803
878	02/20/2025	1246579	Consumables		1331803
878	02/20/2025	1246579	Consumables		1331803
878	02/13/2025	1244671	Ops Entered - Fault - Gearbox Driveline Temperature High -	put in engine fan oil and check coolant ok and radiator washer and road tested ok.	1330858
878	02/13/2025	1244782	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	Removed old decal and fit new campaign decal	1330858
878	01/25/2025	1240731	AIR CONDITIONING REPAIR	Creditor #:VB-COLO004 COLD DRIVE PTY LTD P/O #:O380441 Receiving #:403664 Date :2025-01-31 SHAFT SEAL LEAKING	1328928
878	01/24/2025	1240731	Mechanic entered - A/C Heating Other A/C compressor shaft s	PO:O380441 SHAFT SEAL REPLACED BY DAVE FROM COLD DRIVE	1327966
878	01/16/2025	1239181	Mechanic entered - Body Other A/C filter screen loose.	A/C filter budget lock not secured. Secured lock with screw. Locked A/C filter screen. All ok.	1326538
878	01/16/2025	1239181	Consumables		1326538
878	01/07/2025	1237307	Mechanic entered - Body Other n/s/r wheel arch rubber not se	secured wheel arch rubber with screw	1324714
878	01/07/2025	1237307	Consumables		1324714
878	01/04/2025	1236773	Wheel Nut Retension n/s/r	retorque n/s/r wheel nuts.	1324221
878	01/04/2025	1236773	Consumables		1324221
878	12/31/2024	1236057		VEHICLE SAFETY INSPECTION	1324023
878	12/31/2024	1236057		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1324023
878	12/31/2024	1236108	Mechanic entered - Wheels and Tyres Other change n/s/r outer	replaced n/s/r outer tyre with run out.	1324023
878	12/31/2024	1236108	Consumables		1324023
878	12/31/2024	1236067	Mechanic entered - Engine Other engine belt idler bearing no	removed engine belt idler bearing and replaced engine belt idler bearing ok.	1324023
878	12/31/2024	1236067	PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087		1324023
878	12/31/2024	1236067	Mechanic entered - Elec and Light Exterior Lights N/S top pa	Replaced globed all ok.	1324023
878	12/31/2024	1236067	Mechanic entered - Elec and Light Other n/s/f indicator not	replaced n/s/f indicator globe ok.	1324023
878	12/31/2024	1236067	Mechanic entered - Elec and Light Other dash switch light al	replaced dash switch globe ok.	1324023
878	12/31/2024	1236067	Mechanic entered - Body Other N/S & O/S middle seat loose.	Secured both loose middle seats.	1324023
878	12/31/2024	1236067	Mechanic entered - Body Other rear door top cover screws mis	replaced rear door top cover screws ok.	1324023
878	12/31/2024	1236067	Mechanic entered - Body Other rear bumper bolt loose.	tightened rear bumper bolts ok.	1324023
878	12/31/2024	1236067	Mechanic entered - Brakes Other o/s/r brake slack adjust not	removed o/s/r brake slack adjust and replaced o/s/r brake slack adjust ok.	1324023

878	12/31/2024	1236067	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820			1324023
878	12/30/2024	1235993	DISABLED STICKER AT FRONT OF BUS MISSING	Fitted new disability decal on front of bus.		1324023
878	12/30/2024	1235993	PASSENGER DOOR BUTTONS NEED LABELS	Fitted new labels on passenger door.		1324023
878	12/30/2024	1235993	DECAL WHEELCHAIR			1324023
878	12/16/2024	1233874	replace front door front leaf with door from scrap bus 868			1322252
878	12/13/2024	1232603	DIRECT PURCHASE - GLASS	DISREGUARD DEFECT		1322252
878	12/10/2024	1232603	Vandalism Vandalism/ Graffiti Interior Passenger broke t	Creditor #:VB-OBR001 O'BRIENS GLASS INDUSTRIES P/O #:O377735 Receiving #:400684 Date :2024-12-16 REPLACE FRONT DOOR FRONT LEAF GLASS AS REQUIRED		1322252
878	12/10/2024	1232608	Ops Entered - Fault - Body Windows Front - Route: 703 - Lu	PO#: O377735		1322252
878	12/02/2024	1230720	Mechanic entered - Elec and Light Other rear step light not	attended the breakdown and brought the bus back to depot		1320465
878	11/27/2024	1229794		replaced rear step light globe ok.		1319930
878	11/19/2024	1228184	Body Front_Door Operation Faulty	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list		1318712
878	11/19/2024	1228184	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	double entry		1318712
878	11/19/2024	1228184	SWITCH DOOR SWITCH GREEN 22mm 4 Pin	checked and found front door losing air pressure at times. checked solenoids and found ok. traced and found outside emg switch faulty. replaced and checked door operation ok.		1318712
878	11/19/2024	1228184	Consumables			1318712
878	11/16/2024	1227661	Driver Tablet Entered -Brakes - Foot_Brakes Noisy	Checked front brake linings and drums clean slack adjuster and cam adjusted brakes road tested found retarder working brakes okay		1318263
878	10/30/2024	1224284		VEHICLE SAFETY INSPECTION		1315841
878	10/30/2024	1224284		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1315841
878	10/30/2024	1224355	Mechanic entered - Engine Other Air filter dirty	Replaced filter		1315841
878	10/30/2024	1224355	FILTER AIR OUTER SCANIA K94IB L94UAB K124IB E218L			1315841
878	10/30/2024	1224355	Mechanic entered - Dash Other Few switch globes u/s	Replaced globes		1315841
878	10/30/2024	1224355	Mechanic entered - Elec and Light Interior Lights Drivers re	Removed and replaced globe		1315841
878	10/30/2024	1224355	Mechanic entered - Elec and Light Two Way Radio n/w	Fixed loose connector for the wiring to the radio		1315841
878	10/30/2024	1224284	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	complete		1315841
878	10/30/2024	1224284	PERFORM CAMPAIGN 15/24 PRE SUMMER PREVENTATIVE MAINTENANCE	complete		1315841
878	10/14/2024	1220607	Workshop Tablet Entered -Elec and Light - Next Stop Button	check all stop buttonscould not fault.		1313160
878	10/11/2024	1220514	Mechanic entered - Elec and Light Exterior Lights N/S headli	Removed and fitted new headlight globe.		1313160
878	10/11/2024	1220514	GLOBE 24V H4 75/70W HALOGEN			1311158
878	10/01/2024	1215257	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O372657 Receiving #:395554 Date :2024-10-01 24 month service		1310361
878	09/24/2024	1216395	PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087			1310361
878	09/24/2024	1216395	Fault#:39338 - Ops Entered - Fault - Breakdown Belts Pulley	attended breakdown . found plastic ribbed idler pully seized . replaced idler pully . checked condition of engine belt and other rollers. all ok		1309363
878	09/19/2024	1215600	Mechanic entered - Engine Other Engine oil dip stick broken.	Removed and fitted new engine oil dip stick.		1309363
878	09/19/2024	1215600	DIPSTICK ENGINE OIL 753MM SCANIA L94 40A8200			1309363
878	09/19/2024	1215578	Consumables			1309363
878	09/19/2024	1215578	Consumables			1309363
878	09/19/2024	1215578	OIL ATF STEERING DEX-3 VALVOLINE			1309363
878	09/19/2024	1215578		Assisting		1309363
878	09/19/2024	1215578		CARRY OUT B SERVICE AS PER CHECK LIST Carried out Bservice as per checklist.		1309363
878	09/19/2024	1215578	OIL ENGINE ALL FLEET PLUS E900 15W-40			1309363
878	09/19/2024	1215578	O-RING LOWER SPINNER FILTER SCANIA L94 K124			1309363
878	09/19/2024	1215578	FILTER FUEL SCANIA VARIOUS MODELS H17WK04			1309363
878	09/19/2024	1215578	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)			1309363
878	09/19/2024	1215578	FILTER OIL SCANIA VARIOUS MODELS			1309363
878	09/19/2024	1215578	OIL SAMPLE TEST KIT			1309363
878	09/19/2024	1215578	O-RING LARGE UPPER SPINNER FILTER SCANIA			1309363
878	09/19/2024	1215578	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS			1309363
878	09/18/2024	1215257		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - PO:O372657 : carried out by ben from cold drive		1309363
878	09/18/2024	1215257		Assisting		1309363
878	09/18/2024	1215257		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - PO:O372657 : carried out by ben from cold drive		1309363
878	09/17/2024	1214996	Mechanic entered - Fluid Leaks Rear of bus Fuel Tank Wet at	checked fuel tank . could not fault		1309363
878	09/13/2024	1214365		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Carried out Tune Up service as per checklist.		1309363
878	09/13/2024	1214365		SERVICE MOISTURE EJECTOR		1309363
878	09/13/2024	1214365	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921			1308902
878	09/10/2024	1213740	Consumables			1308902
878	09/10/2024	1213740	Mechanic entered - Body Other Passenger seat behind rear doo	Fit back seat base with new nuts		1308632
878	09/09/2024	1213458	Consumables			1308632
878	09/09/2024	1213458	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe and parklight globe.		1308632
878	09/09/2024	1213458	GLOBE 24V H4 75/70W HALOGEN			1308632
878	09/01/2024	1198713	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O367954 Receiving #:394456 Date :2024-09-13 FABRICATE AND SUPPLY HYDRAULIC HOSE X 1 AS PER SAMPLE		1309603
878	09/01/2024	1176703	Consumables			1308450
878	09/01/2024	1176703	PRESSURE SENSOR	Creditor #:VB-BEA100 BEARING LOGISTICS P/O #:O371960 Receiving #:393966 Date :2024-09-06		1307591
878	08/31/2024	1211595		VEHICLE SAFETY INSPECTION Carried out safety inspection.		1307591
878	08/31/2024	1211595		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1307591
878	08/31/2024	1211604	Mechanic entered - Suspension Other O/S/R Sway Bar 'D' Rubbe	removed 1x worn sway bar 'D' Rubber replaced with new item from stock.		1307591
878	08/31/2024	1211604	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)			1307591
878	08/31/2024	1211604	Consumables			1307591
878	08/31/2024	1211641	Consumables			1307591
878	08/31/2024	1211641	Headlight is out	checked headlights both working.		1307591
878	08/31/2024	1211604	Mechanic entered - Elec and Light Exterior Lights O/S/F Uppe	opened desto panel removed indicator and park light bracket removed lens replaced blown globe checked for operation refitted lens and refitted light bracket and desto panel.		1307591
878	08/31/2024	1211604	Mechanic entered - Elec and Light Exterior Lights N/S/R Step	removed broken lens replaced with new item from stock.		1307591
878	08/31/2024	1211604	LENS REVERSE / CLEARANCE LIGHT CLEAR			1307591
878	08/31/2024	1211604	Mechanic entered - Elec and Light Flat Batteries 2X Batterie	replaced 2x batteries with new items from stock.		1307591
878	08/31/2024	1211604	BATTERY EXSN94SCMF 1350AAC EMFN150L			1307591
878	08/31/2024	1211604	Mechanic entered - Elec and Light Two Way Radio 2 way radio	added 1x missing screw drilled out mounting panel and fibreglass on otherside added another screw checked for movement ok.		1307591
878	08/31/2024	1211604	Consumables			1307591
878	08/31/2024	1211604	Consumables			1307591
878	08/31/2024	1211640	Consumables			1307591
878	08/31/2024	1211640	Consumables			1307591
878	08/31/2024	1211640	FIRE EXT CHECK	checked fire extinguisher in date and charged.		1307591
878	08/31/2024	1211604	Mechanic entered - Body Other O/S/F Passenger seat backing n	removed seat base pushed seat backing back into position on retaining hooks refitted base.		1307487
878	08/29/2024	1203563	Consumables			1307487
878	08/29/2024	1203563	Consumables			1307487
878	08/29/2024	1203563	Consumables			1307487
878	08/29/2024	1203563	Consumables			1307487
878	08/29/2024	1203563	Consumables	Sprayed body stoneward an secure wires at fronts		1307487
878	08/15/2024	1203563	WHITE PAINT PEN MILWAUKEE			1307487
878	08/15/2024	1203563	SAUSAGE BLACK BOSTIK			1307487
878	08/05/2024	1205319	Consumables			1307487
878	08/05/2024	1205319	Consumables			1307487
878	08/05/2024	1205319	Floor Rotten in 2 spots - N/S/R Behind wheel arch N/S/F B	repaired at bodyshop 5-8-24		1307487
878	08/01/2024	1203563	Mechanic entered - Body Other floor rotten	remove rotttern floor replaced wood in floor		1307487
878	07/26/2024	1203563	Mechanic entered - Body Other floor rotten	remove rotttern floor		1307487
878	07/26/2024	1203563	Consumables			1307487
878	07/26/2024	1203563	Consumables			1307487

878	07/23/2024	1202548	spondgy floor near inside floor saloon hatch																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											</
-----	------------	---------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

878	04/26/2024	1184583	PULLEY IDLER SCANIA(1413875)		1296145
878	04/26/2024	1184535	COOLING HOSE SCANIA L94UB & K230UB E3 0486819		1296145
878	04/26/2024	1184535	Service	water pump bottom hose rubbed with oil sender loom and leaking when the eng is hot. drained coolant and replaced hose. filled coolant and repaired oil sender wiring.	1296145
878	04/26/2024	1184535	Consumables		1296145
878	04/26/2024	1184535	Drv entered - Elec and Light Next Stop Button	checked all pax stop buttons; working ok	1296145
878	04/26/2024	1184535		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	1296145
878	04/18/2024	1183000	Mechanic entered - Elec and Light Other dash R.P.M light not	replaced R.P.M light globe ok.	1294940
878	04/18/2024	1183000	Consumables		1294940
878	04/15/2024	1182065	PTI Tablet Entered -Elec and Light - Exterior Lights ns from	removed desto cover inside removed parker and indicator assembly refitted lens with new screws refitted assembly and desto cover.	1294523
878	04/15/2024	1182065	Consumables		1294523
878	04/04/2024	1180290	Driver Tablet Entered -Elec and Light - Next Stop Button at	Checked all next stop button. Checked stop switch next to driver's seat multiple times. All working. Checked driver's next stop warning on dash and constat all working.	1292964
878	04/04/2024	1180291	Mechanic entered - Elec and Light Indicators Not Working N/S	Replaced N/S/F bottom indicator globe with new.	1292964
878	04/04/2024	1180290	Consumables		1292964
878	04/04/2024	1180291	Consumables		1292964
878	03/25/2024	1178631	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	Found A/C was not turned on. Left bus running for 20mins with A/C and boost fan on high. Checked all ok.	1291666
878	03/18/2024	1176991	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	complete	1290438
878	03/13/2024	1175774	OIL ATF STEERING DEX-3 VALVOLINE		1289949
878	03/13/2024	1175774	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXAMATIC)		1289949
878	03/13/2024	1175774	OIL ENGINE ALL FLEET PLUS E900 15W-40		1289949
878	03/13/2024	1175774	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		1289949
878	03/13/2024	1175774	Consumables		1289949
878	03/13/2024	1175774	Consumables		1289949
878	03/12/2024	1175571		VEHICLE SAFETY INSPECTION	1289930
878	03/12/2024	1175571		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1289930
878	03/12/2024	1175676	Mechanic entered - Fluid Leaks Other trans solenoid valve co	replaced trans solenoid valve cover oring ok.	1289930
878	03/12/2024	1175676	Mechanic entered - Elec and Light Other n/s reverse light no	replaced n/s reverse light lens and globe ok.	1289930
878	03/12/2024	1175676	LENS CLEAR TO SUIT 2043		1289930
878	03/12/2024	1175676	Consumables		1289930
878	03/12/2024	1175676	Mechanic entered - Body Other n/s/middle seat o/s/middle sea	repaired o/s and n/s seat ok.	1289930
878	03/12/2024	1175676	Mechanic entered - Body Other o/s/r staunchion pole loose.	repaired o/s/r staunchion pole ok.	1289930
878	03/12/2024	1175676	Mechanic entered - Body Other n/s/r and o/s/r side bumper bl	repaired n/s/r and o/s/r side bumper ok.	1289930
878	03/12/2024	1175676	Mechanic entered - Body Other o/s/f inside top panel screws	repaired o/s/f inside top panel ok.	1289930
878	03/12/2024	1175676	Mechanic entered - Brakes Other n/s/r brake slack adjust not	removed n/s/r brake slack adjust and replaced n/s/r brake slack adjust ok.	1289930
878	03/12/2024	1175676	SLACK ADJUSTER AUTO-REAR N/SIDE SERIES 4(2009819)		1289930
878	03/12/2024	1175774		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist.	1289930
878	03/12/2024	1175774	OIL ENGINE ALL FLEET PLUS E900 15W-40		1289930
878	03/12/2024	1175774	OIL ATF STEERING DEX-3 VALVOLINE		1289930
878	03/12/2024	1175774	OIL SAMPLE TEST KIT		1289930
878	03/12/2024	1175774	FILTER OIL SCANIA VARIOUS MODELS		1289930
878	03/12/2024	1175774	O-RING LOWER SPINNER FILTER SCANIA L94 K124		1289930
878	03/12/2024	1175774	O-RING LARGE UPPER SPINNER FILTER SCANIA		1289930
878	03/12/2024	1175774	FILTER FUEL SCANIA L94 1372444		1289930
878	03/12/2024	1175774	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081		1289930
878	03/12/2024	1175774	PLUG SUMP DRAIN SCANIA 3 SERIES 1433641 1423608		1289930
878	03/12/2024	1175774	WASHER SUMP DRAIN PLUG SCANIA		1289930
878	03/12/2024	1175774		Assisting	1289930
878	03/02/2024	1174001	Ops Entered - Fault - CCTV Server Connection - Route: 703 -	checked the camera status adjust few settings the unit looks like conected I will be report it for the streamax	1288314
878	03/01/2024	1163128	DIRECT PURCHASE - STEERING	Creditor #:VB-HYD001 HYDROSTEER PTY LTD P/O #:O357517 Receiving #:381901 Date :2024-03-18 rectify oil leak at steering box as required	1290830
878	02/26/2024	1172316	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	1287352
878	02/22/2024	1171605	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	PO: O359928 - repaired by Jimmy from cold drive	1286897
878	02/22/2024	1171605	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	double entry	1286897
878	02/22/2024	1171605	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O359928 Receiving #:380678 Date :2024-02-29 rectify a/c not working as required	1288314
878	02/21/2024	1171228		removed the fitting at the back of air compressor.	1286897
878	02/21/2024	1171228	Driver Tablet Entered -Air System - Warning Light On	tested and found air leaking from shuttle valve tube at air compressor. fitted a heat proof air tube; leak stopped. to be monitored.	1286897
878	02/21/2024	1171228		road tested and found the air pressure stayed at green areas on both air gauges.	1286897
878	02/16/2024	1170178	Ops Entered - Fault - Air System Air_Leak Doors - Route: 70	Checked for air leaks found air compressor signal line leaking replaced nylon tubing fit new brass joiner to leaking air line along the chassis Replaced leaking accumulator solenoid valve with new one Road tested for an hour works okay	1286318
878	02/16/2024	1170178	VALVE SOLENOID G/BOX ACCUMMULATOR ZF 0501 318 457		1286318
878	02/15/2024	1169754	Drv entered - Brakes Foot_Brakes Leaking Air	CHECKED for any air leak/loss. road/brakes tested ok. air pressures on both gauges remain and maintained within green areas.	1285826
878	02/08/2024	1164627	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O357998-1 Receiving #:379692 Date :2024-02-16 Graffiti Audit # 1013 stage 2 Film replacement 8/2/24	1286318
878	02/08/2024	1168249	Mechanic entered - Elec and Light Exterior Lights O/S/F bott	Replaced O/S/F bottom park light globe. Checked all ok.	1284856
878	02/03/2024	1167092	Workshop Tablet Entered -Steering - Steering Wheel Faulty	CHECKED AND COULD NOT FAULT WO1167035	1283957
878	02/03/2024	1167092	Workshop Tablet Entered -Steering - Steering Wheel Faulty	CHECKED AND COULD NOT FAULT WO1167035	1283957
878	02/03/2024	1167035	Workshop Tablet Entered -Steering - Steering Wheel Faulty	COULD NOT FAULT STEERING WHEELNEW.	1283957
878	02/03/2024	1167036	Workshop Tablet Entered -Engine - Low Power	ROAD TESTCOULD NOT FAULT.	1283957
878	01/29/2024	1165943	Mechanic entered - Air System Air_Leak Rear	Air leak from signal line fitting on air compressor. Removed hose shortened about 1cm and refitted line. Checked for leak all okay.	1283063
878	01/25/2024	1165417	Driver Tablet Entered -Air System - Air_Leak Interior when	road testcould not fault .	1282605
878	01/20/2024	1164627	GRAFFITI AUDIT # 1013 15/1/24		1281869
878	01/20/2024	1164546	Workshop Tablet Entered -Steering - Steering Wheel Faulty	new steering wheel fittedcould not fault.	1281869
878	01/12/2024	1163128	Mechanic entered - Steering Other Steering Box Weeping	removed steering box and cradle from bus. sent to hydrosteer for oil leak repair refitted steering box and bracket refilled with oil bled system roadtested bus ok.	1281531
878	01/10/2024	1162574		VEHICLE SAFETY INSPECTION	1281008
878	01/10/2024	1162574		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1281008
878	01/10/2024	1162702	Mechanic entered - Body Other No Smoking/vaping decal missin	replaced missing decal with new item from stock.	1281008
878	01/10/2024	1162702	Mechanic entered - Body Other Disabled seat top pins not sea	reseated disabled seat top pins.	1281008
878	01/10/2024	1162702	Consumables		1281008
878	01/06/2024	1161945	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	campaign complete	1280516
878	12/29/2023	1160439	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe.	1279356
878	12/29/2023	1160439	GLOBE 24V H4 75/70W HALOGEN		1279356
878	12/29/2023	1160439	Consumables		1279356
878	12/28/2023	1160098	Consumables		1279356
878	12/28/2023	1160098	Mechanic entered - Elec and Light Indicators Not Working o/s	fit globe. checked operation all ok	1279356
878	12/27/2023	1159978	CCTV FIT X5 DVR	fitted an comissioned DVR	1277447
878	12/14/2023	1158075	Consumables		1277447
878	12/14/2023	1158075	Body (None) disable seat upper pin out	fitted a pin ok	1274200
878	11/25/2023	1154357		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1273780
878	11/22/2023	1153668	Mechanic entered - Body Other o/s/r pillar crack.	removed corner body panel located crack grinded into crack welded crack on all 3 sides grinded back on sides with access added plate steel over top of where crack is welded 2x plates on front and rear of pillar allowed to cool painted section allowed to dry refitted corner panel.	1273780
878	11/21/2023	1153508	body deadner required	Sprayed body deadner as required	1273780
878	11/21/2023	1153508	STONEGUARD PLUS SZ L253 1000ML		1273515
878	11/20/2023	1153162		complete	1272549
878	11/15/2023	1152170		VEHICLE SAFETY INSPECTION	1272549
878	11/15/2023	1152170		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1272549
878	11/15/2023	1152228	Mechanic entered - Suspension Other n/s/r/r air bag leaks.	removed n/s/r/r air bag and replaced n/s/r/r air bag ok.	1272549
878	11/15/2023	1152228	AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02		1272549
878	11/15/2023	1152228	Mechanic entered - Body Other n/s/f and n/s/r hammer light s	replaced n/s/f and n/s/r hammer light screws ok.	1272549

878	11/15/2023	1152228	Mechanic entered - Body Other both middle all seat loose.	repaired n/s ans o/s all middle seat.	1272549
878	11/15/2023	1152228	Mechanic entered - Body Other n/s/r marker light loose.	tightened n/s/r marker light screws ok.	1272549
878	11/15/2023	1152228	Mechanic entered - Body Other rear modesty panel loose.	repaired rear modesty panel ok.	1272549
878	11/15/2023	1152228	Mechanic entered - Body Other o/s and n/s front bus inside t	replaced o/s and n/s front bus inside top panel screws ok.	1272549
878	11/14/2023	1151935		check transmission and list check.	1272549
878	11/02/2023	1150298	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced H4 globe and also park light globe	1271204
878	11/02/2023	1150298	GLOBE 24V H4 75/70W HALOGEN		1271204
878	11/02/2023	1150298	Consumables		1271204
878	10/25/2023	1148489	Fault#:38941 - Ops Entered - Fault - Breakdown Air System F	found leaking fitting from air dryer . carried out temp repair . followed bus back to depot for further repair.	1269529
878	10/25/2023	1148468	leak at air dryer	replaced plastic fitting with a brass one and changed safety valve in the dryer. fitted fittings supplied by ENZED tread sealed and tested no leak. ok	1269529
878	10/25/2023	1148468	VALVE SAFETY 14.3 BAR SCANIA (1111195)		1269529
878	10/25/2023	1148468	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O353209 Receiving #:372208 Date :2023-10-25 12 mm brass joiner x 5	1269700
878	10/25/2023	1148464	Consumables		1269529
878	10/25/2023	1148464	Consumables		1269529
878	10/25/2023	1148464			1269529
878	10/25/2023	1148464	O-RING LARGE SPINNER FILTER SCANIA L94 & K230	CARRY OUT B SERVICE AS PER CHECK LIST Carried B service as per checklist washed and road tested all ok.	1269529
878	10/25/2023	1148464	O-RING SPINNER FILTER SCANIA L94		1269529
878	10/25/2023	1148464	OIL SAMPLE TEST KIT		1269529
878	10/25/2023	1148464	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1269529
878	10/25/2023	1148464	FILTER FUEL SCANIA L94 (1372444)		1269529
878	10/25/2023	1148464	FILTER OIL SCANIA K93 L94 1117285 2059778		1269529
878	10/25/2023	1148464	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1269529
878	10/25/2023	1148464	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 4021000 1439814		1269529
878	10/23/2023	1148028	Mechanic entered - Air System Air_Leak Rear Air dryer hose l	Removed damaged portion of the air dryer hose and fitted joiner. Secured air lines and wires.	1269265
878	10/04/2023	1144217	PERFORM CAMPAIGN 07/23 REPOSITION ETAG	fitted e-tag	1266511
878	09/30/2023	1143411	Fault#:38884 - Ops Entered - Fault - Breakdown Air System F	traced and found air dryer filter O ring leaking . patched up air leak to get the bus back to the depot .	1265970
878	09/22/2023	1142166	Workshop Tablet Entered -A/C Heating - Not Cooling	O351399 - repairs carried out by cold drive - waiting on parts - simon to advise fan motors replaced by dave on 26-09-2023	1265392
878	09/22/2023	1142166	AIR CONDITIONING REPAIR	Creditor #.:VB-COLO04 COLD DRIVE PTY LTD P/O #:O351399 Receiving #:370460 Date :2023-10-02 rectify a/c not working as required	1266105
878	09/20/2023	1141590	Ventura Oakleigh anti-graffiti	Creditor #.:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O351197 Receiving #:369944 Date :2023-09-21 18/9/23	1265142
878	09/19/2023	1141590	Vandalism - film replacement from audit 955		1264861
878	09/18/2023	1141193		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1264305
878	09/18/2023	1141193		VEHICLE SAFETY INSPECTION	1264305
878	09/18/2023	1141241	Mechanic entered - Wipers and Washers Washers Not Working	Repaired leaking hose top up water and tested found working	1264305
878	09/18/2023	1141241	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		1264305
878	09/18/2023	1141241	PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		1264305
878	09/18/2023	1141241	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113		1264305
878	09/18/2023	1141241	Mechanic entered - Body Other Rear first step yellow strip	Fitted new yellow strip	1264305
878	09/18/2023	1141241	Mechanic entered - Body Other N/S 1st disable seat is loose	Fit back hinge pin and tight bolts	1264305
878	09/18/2023	1141241	Mechanic entered - Brakes Other O/S/R slack adjuster locked	Removed and replaced slack adjuster adjusted both rear brakes	1264305
878	09/18/2023	1141241	air leak to compressor signal line	Removed fitting got new fitting from enzed fit back with new hose tested okay	1264305
878	09/18/2023	1141241	DIRECT PURCHASE - MECHANICAL G	Creditor #.:VB-ENZED ENZED MOORABBIN P/O #:O351070 Receiving #:370107 Date :2023-09-25 supply air line fitting as required	1265392
878	09/16/2023	1141059	Drv entered - Brakes Park_Brake Leaking Air	replaced air comperssor hose and hose fitting oring ok.	1264305
878	09/14/2023	1140535	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	road tested could not falt ok.	1264305
878	09/01/2023	1137822	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	carried out campaign	1262029
878	08/28/2023	1136598	Consumables		1261204
878	08/28/2023	1136598	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	Retensioned both rear wheel nuts to 650nm.	1261204
878	08/26/2023	1136260	Vandalism Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI	1261204
878	08/25/2023	1135799	Consumables		1261204
878	08/25/2023	1135799	PTI Tablet Entered -Wheels and Tyres - Worn tyre 4	replaced both rear tyres and tensioned wheel nuts.	1261204
878	08/25/2023	1135799	TYRE 295/80R22.5 RECAP		1261204
878	08/25/2023	1135799		assisted CDF	1261204
878	08/25/2023	1135798	Driver Tablet Entered -Air System - Air Not Building_UpAir	adjusted air dryer reg and built up to green . checked operation of air system regen all ok	1261204
878	08/25/2023	1135862	Air System - air dryer R/R		1261204
878	08/25/2023	1135862	AIR DRYER ASSY SCANIA 1743859	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O349605 Receiving #:367902 Date :2023-08-25	1261204
878	08/25/2023	1135862	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1376911		1261204
878	08/25/2023	1135862	BOLT COMPRESSOR DRIVE GEAR SCANIA L94 1437486		1261204
878	08/25/2023	1135862	O-RING SEAL COMPRESS MOUNT MERC SCANIA L94 323790 B7R 975610		1261204
878	08/25/2023	1135862	AIR COMPRESSOR - WITH REAR COVER PLATE		1261204
878	08/25/2023	1135862		Removed and replaced air dryer and air compressor. Transfered fittings to new unit. Tensioned tightened compressor gear bolt to 90nm+60deg. 1x coolant hose u/s. Replaced coolant hose. Checked for any leaks. Road tested by Sadid. Checked air gauge while road testing. all ok.	1261204
878	08/25/2023	1135862	COOLING HOSE SCANIA L94UB & K230UB E3 0486819		1261204
878	08/23/2023	1135471	Ops Entered - Fault - Air System Air Not Building_Up - Rout	Removed and fitted new air dryer filter. Removed and fitted new compressor signal line and fitting. Drained air tanks for oil/water. Road tested and checked for air building up operation. All okay.	1261033
878	08/23/2023	1135471	FILTER AIR DRYER SCANIA VOLVO 1393551 20546795 20424148		1261033
878	08/23/2023	1135471	UNION ASSY SCANIA (L94UB) (K310UB)		1261033
878	08/21/2023	1134852	Fault#:38831 - Ops Entered - Fault - Breakdown Not Starting	breakdown was cancelled . driver had bus in drive	1260622
878	08/04/2023	1131228	Consumables		1257796
878	08/04/2023	1131228	PTI Tablet Entered -Body - Windows Front bus washed	completed by fleet support	1257796
878	08/02/2023	1127231		replaced rear sway bar clamp x 2 with U bolts.	1257142
878	08/01/2023	1127231	0468205 Clamp	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O347403 Receiving #:366232 Date :2023-08-03	1257796
878	08/01/2023	1130228	Consumables		1257142
878	08/01/2023	1130228	saloon rear step edge to be secured	repaired wheel chair ramp ok.	1257142
878	07/25/2023	1128859		VEHICLE SAFETY INSPECTION carried out safety check. all ok	1256398
878	07/25/2023	1128859		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retension wheel nut to spec	1256398
878	07/25/2023	1127231	0815124 Bolt	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O347403 Receiving #:365611 Date :2023-07-27	1256728
878	07/25/2023	1127231	0470932 U Bolt	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O347403 Receiving #:365611 Date :2023-07-27	1256728
878	07/25/2023	1128945	Consumables		1256398
878	07/25/2023	1128945	WASHER NOZZLE		1256398
878	07/25/2023	1128945	Mechanic entered - Body Other front modesty panel loose.	secured	1256398
878	07/25/2023	1128945	Mechanic entered - Body Other front n/s washer jett not work	replaced washer nozzle. checked all ok	1256398
878	07/18/2023	1127231	Suspension (None) rear sway bar U-bolt missing	parts ordered	1254991
878	07/18/2023	1118109	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)		1254991
878	07/18/2023	1118109	BUSH SWAY BAR LINK REAR AXLE SCANIA L94UAB 2156626 1477867	removed rear sway bar and replaced rear sway bar bushings and replaced rear D rubber and replaced rear sway bar and welding sway bar rubber clamp ok.	1254991
878	07/18/2023	1118109		road tested could not fault ok.	1254464
878	07/14/2023	1126442	Drv entered - Brakes Foot_Brakes Noisy	complete	1254464
878	07/14/2023	1126540	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	Checked for air leak found signal line to the air compressor had a split cut hose and fit new joiner and road tested found okay	1254164
878	07/12/2023	1126116	Ops Entered - Fault - Air System Air Not Building_Up - Rout	Double entry by drivers	1254164
878	07/12/2023	1126116	Driver Tablet Entered -Air System - Warning Light On	Another entry by different driver	1254164
878	07/12/2023	1126116	Workshop Tablet Entered -Air System - WSining Light On Air	Creditor #.:VB-COLO04 COLD DRIVE PTY LTD P/O #:O346759 Receiving #:365131 Date :2023-07-19 12 month service	1255259
878	07/11/2023	1125656	AIR CONDITIONING REPAIR	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - carried out by ben from cold drive O346759	1253963
878	07/11/2023	1125656		Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O344288 Receiving #:364803 Date :2023-07-14	1254416
878	07/01/2023	1118109	SWAY BAR REAR SCANIA	repaired n/s/middle pax switch wires ok.	1251953
878	06/30/2023	1123365	Driver Tablet Entered -Elec and Light - Next Stop Button		1251953
878	06/30/2023	1123365	Consumables		1251953
878	06/30/2023	1123364	Driver Tablet Entered -Air System - Warning Light On	road tested not warning on ok.	1251953

878	06/23/2023	1122110	Workshop Tablet Entered -A/C Heating - Not Heating	checked operation of heaters and demistors. could not fault . all blowing hot	
878	06/23/2023	1122155	OIL SAMPLE KIT AMPOL		
878	06/23/2023	1122155	O-RING SPINNER FILTER SCANIA L94		
878	06/23/2023	1122155		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist.	
878	06/23/2023	1122155	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		
878	06/23/2023	1122155	FILTER OIL SCANIA K93 L94 1117285 2059778		
878	06/23/2023	1122155	FILTER FUEL SCANIA L94(1372444)		
878	06/23/2023	1122155	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		
878	06/23/2023	1122155	PAPER SPINNER FILTER OIL INSERT SCANIA L94		
878	06/23/2023	1122155	Consumables		
878	06/15/2023	1120652	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	Checked king pins greased them checked brake slack adjusters found okay adjusted front brakes and road tested found okay tested in the yard with supervisor Lindsay all okay	
878	06/13/2023	1118647	STEERING WHEEL SCANIA 1545452	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O344473-RET Receiving #:362561 Date :2023-06-14 Item Incorrect	
878	06/13/2023	1120008	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	completed by consat installers - garys team	
878	06/09/2023	1118605	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O344437 Receiving #:362463 Date :2023-06-09 carry out ASI inspection as required	
878	06/08/2023	1118647	WHEEL STEERING WHEEL NEW SC	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O344650 Receiving #:362382 Date :2023-06-08	
878	06/08/2023	1118647	SWITCH INDICATOR STALK SCANIA L94 1402448		
878	06/08/2023	1118647		Replaced the indicator stalk as self cancelling not working.	
878	06/08/2023	1118647		Removed steering wheel and replaced with new steering wheel. Road tested by kapila checked everything all ok.	
878	06/06/2023	1118845	beeping noise coming from dash	found paper had ran out of drivers myki machine . driver to install new paper	
878	06/06/2023	1118845	Consumables		
878	06/05/2023	1118605		VEHICLE SAFETY INSPECTION	
878	06/05/2023	1118605		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
878	06/05/2023	1118605		ANNUAL SAFETY INSPECTION SERIAL # _____RSI 046993 PASS _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	
878	06/05/2023	1118610	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S	carried out retorque as required	
878	06/05/2023	1118610	Consumables		
878	06/05/2023	1118630	Mechanic entered - Elec and Light Other school light switch	replaced wedge ok	
878	06/05/2023	1118630	Consumables		
878	06/05/2023	1118647	STEERING WHEEL SCANIA 1545452	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O344473 Receiving #:362165 Date :2023-06-05	
878	06/05/2023	1118647	steering wheel requires replament	Removed steering wheel and replaced with new steering wheel. Road tested by kapila checked everything all ok.	
878	06/03/2023	1118490	Mechanic entered - Wheels and Tyres Worn O/S/F Tyre U/S - 2m	removed worn tyre replaced with new tyre from stock.	
878	06/03/2023	1118490	TYRE 295/80R22.5 NEW		
878	06/03/2023	1118490	Consumables		
878	06/03/2023	1118486	Mechanic entered - Elec and Light Next Stop Button 2x Pax Sw	removed cracked pax switches replaced with new items from stock checked for operation ok.	
878	06/03/2023	1118486	SWITCH STOP YELLOW BUTTON (20485)		
878	06/03/2023	1118486	Consumables		
878	06/03/2023	1118483	2nd PRE ASI check	Carried out 2nd Pre ASI Check	
878	06/03/2023	1118486	Mechanic entered - Body Other Disabled seat top pins not sea	seated disabled seat top pins	
878	06/03/2023	1118486	Mechanic entered - Body Other Rear No Smoking Decal Missing	applied new decal from stock.	
878	06/03/2023	1118486	Mechanic entered - Brakes Other O/S/R Slack Adjuster U/S	removed worn slack adjuster replaced with new item from stock fittefd and adjusted ok.	
878	06/03/2023	1118486	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		
878	06/03/2023	1118486	Mechanic entered - Air System Air_Leak Rear Compressor air I	removed air line from compressor trimmed end refitted checked for leak ok.	
878	06/01/2023	1118109	Suspension Other Rear sway bar worn	ordered	
878	05/30/2023	1117691		PRE ANNUAL SAFETY INSPECTION CHECK Carried out PRE ASI inspection as per checklist.	
878	05/30/2023	1117691		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	
878	05/30/2023	1117770	Mechanic entered - Suspension Other Front sway bar bushes wo	Removed and fitted new front sway bar bushes.	
878	05/30/2023	1117770	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		
878	05/30/2023	1117770	Mechanic entered - Elec and Light Interior Lights 1x dash li	Removed and fitted new dash globe.	
878	05/30/2023	1117770	Consumables		
878	05/25/2023	1116720	Mechanic entered - Wheels and Tyres Other N/S/R/OUTER TYRE W	removed N/S/R/OUTER TYRE AND replaced N/S/R/OUTER RUNOUT TYRE OK.	
878	05/25/2023	1116887	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retensioned N/S/R wheel nuts to 650nm.	
878	05/25/2023	1116720	Consumables		
878	05/25/2023	1116887	Consumables		
878	05/25/2023	1116691		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	
878	05/16/2023	1114958	PTI Tablet Entered -offside headlight	Defect entered twice.	
878	05/16/2023	1114958	PTI Tablet Entered -offside headlight	Removed and fitted new headlight globe.	
878	05/16/2023	1114958	GLOBE 24V H4 75/70W HALOGEN		
878	05/16/2023	1114958	Consumables		
878	05/06/2023	1112872		TRANSMISSION CHECK AS PER CHECK LIST CARRY OUT TRANS CHECK.	
878	04/28/2023	1111188		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
878	04/28/2023	1111188		VEHICLE SAFETY INSPECTION	
878	04/20/2023	1109927		test has been done on Feb 2023	
878	04/14/2023	1108730	PTI Tablet Entered -Body - Windows Front wiper blades need	this was done by Satya wo1108173	
878	04/14/2023	1108730	Consumables		
878	04/11/2023	1108173	Workshop Tablet Entered -Wipers and Washers - Wipers Not_Cle	Replaced n/s wiper blade	
878	04/11/2023	1108173	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM		
878	03/24/2023	1105306	remove intercooler / wash radiator	carry out removal all check ok	
878	03/07/2023	1100783	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O338798 Receiving #:356239 Date :2023-03-08 machine drums and radius grind brake linings as required - replace linings if they need to be changed	
878	03/06/2023	1100783		Refitted slack adjusters. Fitted new brake shoes. Refitted wheel and hub assembly. Tightened up hub and adjusted brakes. Road tested brake tested and check brake temperatures. All okay.	
878	03/04/2023	1101269	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	
878	03/03/2023	1100783	Mechanic entered - Suspension Other Front airbags losing ai	checked by LDM . deemed found serviceable . could not find any leaks in suspension system	
878	03/03/2023	1100783	Mechanic entered - Steering Shakes/ Wobbles Steering wheel	checked and found front brakes vibration	
878	03/03/2023	1100783	Mechanic entered - Steering Shakes/ Wobbles Steering wheel	Removed front wheel shoes and hubs to send away for machining. Removed slack adjusters and checked S cam bushes. Bushes okay.	
878	03/03/2023	1100783	send brake away for radius grind and machine	commercial brake and clutch - O338798	
878	03/03/2023	1100783	Mechanic entered - Steering Shakes/ Wobbles Steering wheel	Assited Sadid with removing front wheels shoes and hub. Loaded front wheels and hub to courier van.	
878	03/01/2023	1100358	Consumables		
878	03/01/2023	1100358	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	Completed retension	
878	02/28/2023	1099882		VEHICLE SAFETY INSPECTION Carried out Safety inspection as per checklist.	
878	02/28/2023	1099882		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
878	02/28/2023	1099912	Consumables		
878	02/28/2023	1099912	Mechanic entered - Wheels and Tyres Other Front tyres need t	Rotated front tyres.	
878	02/28/2023	1099912	Mechanic entered - Steering Excessive Play Tie rod ball join	Removed and fitted new tie rod assembly.	
878	02/28/2023	1099912	TIE ROD ASSY SCANIA L94/K230/N310/K310 2146105		
878	02/28/2023	1099912	Mechanic entered - Fluid Leaks Rear of bus Header tank crack	Removed and fitted new header tank.	
878	02/28/2023	1099912	EXPANSION TANK SIDE FILL COMP ASSY SCANIA 1731694 1896287		
878	02/28/2023	1099912	Consumables		
878	02/28/2023	1099912	Mechanic entered - Elec and Light Exterior Lights O/S/F lowe	Removed and fitted new park light globe.	
878	02/27/2023	1099409	Workshop Tablet Entered -Air System - Warning Light On loos	completed on work order 1099296	
878	02/25/2023	1099296	Workshop Tablet Entered -Air System - Warning Light On	repair leaking comp shuttle valve air line and replace missing engine oil filler cap.	
878	02/25/2023	1099296	CAP OIL FILLER SCANIA L94UAB 1544036 1385367		
878	02/17/2023	1097636	Ops Entered - Fault - Air System Warning Light On - Route:	Brought bus on pit checked for air leaks. Found no air leaks. Drained air in system and checked air build up time. Air is building up fine. Took for good road test and drove around the yard as well. Could not get bus to fault.	
878	02/15/2023	1096993	Engine (None) take an eng oil sample at 10000km interval	Took engine oil sample.	
878	02/15/2023	1096993	Consumables		
878	02/15/2023	1096993	Consumables		

878	02/15/2023	1096993	Consumables		1231860
878	02/15/2023	1096993	FILTER OIL SCANIA K93 L94 1117285 2059778		1231860
878	02/15/2023	1096993	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1231860
878	02/15/2023	1096993	FILTER AIR OUTER SCANIA SR 3 & 4(395773)(AF25066)		1231860
878	02/15/2023	1096993		CARRY OUT C SERVICE AS PER CHECK LIST Carried out C service as per checklist.	1231860
878	02/15/2023	1096993	FILTER FUEL SCANIA L94(1372444)		1231860
878	02/15/2023	1096993	FILTER FUEL CHASSIS SCANIA L94 UB(1393640)(PSD470/1)		1231860
878	02/15/2023	1096993	FILTER HYD COOLING FAN SCANIA SR3 4(1354074)		1231860
878	02/15/2023	1096993	O-RING SPINNER FILTER SCANIA L94		1231860
878	02/15/2023	1096993	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1231860
878	02/15/2023	1096993	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1231860
878	02/15/2023	1096993	OIL SAMPLE KIT AMPOL		1231860
878	02/15/2023	1096993	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)		1231860
878	02/15/2023	1096993	FILTER AIR DRYER SCANIA VOLVO(1393551)(20546795)(20424148)		1231860
878	02/15/2023	1096993	Consumables		1231860
878	02/15/2023	1096993	Consumables		1231860
878	02/15/2023	1096993	Consumables		1231860
878	02/15/2023	1096993		CARRY OUT B SERVICE AS PER CHECK LIST CarrieD out B service as per checklist.	1231860
878	01/27/2023	1093155	Consumables		1228581
878	01/27/2023	1093155	Ops Entered - Fault - BusMinder Unable To Log In - Route:	could not fault	1228581
878	01/27/2023	1093152	Consumables		1228581
878	01/27/2023	1093152	Ops Entered - Fault - Body Mirrors Interior - Route: 703 -	checked mirrors ext and int no faults	1228581
878	01/27/2023	1093151	Workshop Tablet Entered -Brakes - Warning Light On	no warning light on - road / brakes tested ok	1228581
878	01/21/2023	1092336	Driver Tablet Entered -Air System - Air Not Building_UpAir	checked operation of air system building up . 90 seconds to full pressure. checked of leak through suspension system and brake system . could not fault	1227917
878	01/21/2023	1092336	Driver Tablet Entered -Air System - Air Not Building_UpAir	double entry	1227917
878	01/16/2023	1091261	pillar behind fuel tank cracked and osr corner crack	Removed Fuel Tank Removed O/S/R Side Panel pulled steel back into position welded cracked areas and painted. Removed Fuel Tank marked fuel lines removed tank hanger and tank hanger bracket grinded back cracks filled cracks with weld cut steel plates to size grinded back welds added plates over weakened section c	1227218
878	01/16/2023	1091261	Consumables		1227218
878	01/13/2023	1090863	Consumables		1227218
878	01/13/2023	1090863		CARRY OUT B SERVICE AS PER CHECK LIST	1227218
878	01/13/2023	1090863	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1227218
878	01/13/2023	1090863	FILTER FUEL SCANIA L94(1372444)		1227218
878	01/13/2023	1090863	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1227218
878	01/13/2023	1090863	FILTER OIL SCANIA K93 L94 1117285 2059778		1227218
878	01/13/2023	1090863	O-RING SPINNER FILTER SCANIA L94		1227218
878	01/13/2023	1090863	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1227218
878	01/13/2023	1090863	OIL SAMPLE KIT AMPOL		1227218
878	12/31/2022	1088785	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	1225173
878	12/29/2022	1088470		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST CARRIED OUT AS PER CHECK LIST	1225173
878	12/22/2022	1087723	Consumables		1225173
878	12/22/2022	1087723	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	adjust air pressure to secondary regulatorok.	1225173
878	12/22/2022	1087723	Ops Entered - Fault - Air System Air Not Building_Up - Rout	could not fault.	1225173
878	12/20/2022	1087371	Consumables		1225173
878	12/20/2022	1087371	Mechanic entered - Body Other o/s/f air hose hit from torqu	secured brake hose with cable tie	1225173
878	12/19/2022	1087082		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1224919
878	12/19/2022	1087082		VEHICLE SAFETY INSPECTION	1224919
878	12/19/2022	1087119	Mechanic entered - Steering Other power steering wheel loose	repaired power steering wheel ok.	1224919
878	12/19/2022	1087119	Mechanic entered - Engine Other engine belt tensioner u/s be	replaced engine belt tensioner ok.	1224919
878	12/19/2022	1087119	TENSIONER ALT BELT SCANIA N310UA 2197005 1859657		1224919
878	12/19/2022	1087119	Consumables		1224919
878	12/19/2022	1087119	LENS TO SUIT 2063 LAMP 85765		1224919
878	12/19/2022	1087119	Mechanic entered - Elec and Light Other N/S/F TOP PARK LIGHT	replaced n/s/f top park light lens ok.	1224919
878	12/19/2022	1087119	Consumables		1224919
878	12/19/2022	1087119	Mechanic entered - Body Other n/s and o/s middle seat top pi	put in n/s and o/s middle seat top pins ok.	1224919
878	12/19/2022	1087119	Mechanic entered - Body Other n/s/f staunchion pole loose.	tightened n/s/f staunchion pole bolt ok.	1224919
878	12/19/2022	1087119	Mechanic entered - Body Other n/s/f bottom rust.	repaired n/s/f bottom rust all ok.	1224919
878	12/19/2022	1087119	Mechanic entered - Body Other rear door top bolt loose.	tightened rear door top bolt ok.	1224919
878	12/17/2022	1087002	Consumables		1224919
878	12/17/2022	1087173	Consumables		1224919
878	12/17/2022	1087002	Mechanic entered - Body Rear_Door Operation Faulty not clasi	adjust loose top guide roller.	1224919
878	12/17/2022	1087173	Driver Tablet Entered -Body - Rear_Door Operation Faulty bo	REPAIRED ON W/O 1087002	1224919
878	12/10/2022	1085855	front passneger door fault	adjusted front passenger door . checked operation all ok	1223959
878	12/10/2022	1085855	Consumables		1223959
878	12/03/2022	1084594	Mechanic entered - Elec and Light Other rpm nw	checked and found w terminal wire disconnected. repaired and checked ok	1222737
878	12/03/2022	1084594	Consumables		1222737
878	12/03/2022	1084582	Mechanic entered - Brakes Other SPUNGY.	ADJUST ALL BRAKESROAD AND BRAKE TESTOK.	1222737
878	12/03/2022	1084582	Mechanic entered - Brakes Other SPUNGY.	CRAIG TESTED AND FOUND RETARDER NW. DIAG AND FOUND out of adjustment and return circuit from foot valve interrupted (open/close) fixed the circuit issue adjusted and road tested. ok	1222737
878	11/26/2022	1082166	Apply print film	completed 10/11/22	1220582
878	11/23/2022	1082489	One of the seats up in the rear section of the bus facing t	double entry	1220848
878	11/23/2022	1082489	Consumables		1220848
878	11/23/2022	1082489	Consumables		1220848
878	11/22/2022	1082166	Apply print film L3		1221570
878	11/22/2022	1082489	Mechanic entered - Body Other Passenger seat base and back r	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O332890-1 Receiving #:349992 Date :2022-11-25	1220848
878	11/03/2022	1079054	Consumables	Refitted back rest and seat base.	1217491
878	11/03/2022	1079054	Mechanic entered - Elec and Light Exterior Lights N/S headli	Removed and fitted new headlight globe.	1217491
878	10/31/2022	1078472	Consumables		1217180
878	10/31/2022	1078472	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315		1217180
878	10/31/2022	1078472	Mechanic entered - Elec and Light Other not charging	remove altinatorregulatorcheck slip ringsokfit new regcharging ok.	1217180
878	10/31/2022	1078472	Consumables		1217180
878	10/31/2022	1078457	Consumables		1217247
878	10/31/2022	1078457	N/S/R Window Cracked - 2nd behind rear door.	O331628 - glass replaced x 1 - obrian	1217180
878	10/31/2022	1078457	888885 BUY IN SIDE GLASS BUS A	Creditor #:VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:O331628 Receiving #:348478 Date :2022-11-02 replaced cracked glass x 1 n/s mid	1217247
878	10/29/2022	1078448	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	1217180
878	10/28/2022	1078062		VEHICLE SAFETY INSPECTION	1216922
878	10/28/2022	1078062		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS lumber seat controls missing replaced with new	1216922
878	10/28/2022	1078062	L/H LOWER SEAT LUMBAR BUTTONS		1216922
878	10/28/2022	1078062	L/H UPPER SEAT LUMBAR BUTTONS		1216922
878	10/28/2022	1078167	Mechanic entered - Body Other Pillar Behind Fuel Tank Cracke	entered new defect in TIMS 951318 - to be rebooked	1216922
878	10/28/2022	1078167	Mechanic entered - Body Other N/S/F Modesty Panel Loose	tightened loose panel checked for movement ok.	1216922
878	10/28/2022	1078167	Consumables		1216922
878	10/28/2022	1078167	Mechanic entered - Air System Air_Leak Rear Air Leak From co	removed line from connector trimmed end re inserted into connector checked for leaks ok.	1216922
878	10/13/2022	1075111	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	carried out campaign	1214389
878	10/10/2022	1074080		TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.	1213811
878	10/04/2022	1073079	Consumables		1213112

878	10/04/2022	1073079	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe.	1213112
878	10/04/2022	1073079	Consumables		1213112
878	09/27/2022	1071651	Mechanic entered - Suspension Other Found rear sway bar D bu	Replaced both the bushes	1212160
878	09/27/2022	1071651	BUSH SWAY BAR D/AXLE 47MM SCANIA K1241B 1880751		1212160
878	09/27/2022	1071614	Mechanic entered - Fluid Leaks Rear of bus Torque converter	Checked and found repairs completed	1212160
878	09/27/2022	1071614	Mechanic entered - Fluid Leaks Rear of bus Engine side cove	Checked for oil leaks cleaned tight up bolts road tested found okay	1212160
878	09/20/2022	1069863	Consumables		1211768
878	09/20/2022	1069863	Mechanic entered - Body Front_Door Operation Faulty NOT CLOS	WIRE IN REED SWITCH ADJUST DOOR SPEEDSROAD TESTOK.	1211768
878	09/20/2022	1069863	Consumables		1211768
878	09/17/2022	1070015	Apply Print Film	Audit 761 completed on the 8/9/22	1211768
878	09/16/2022	1070015	Apply Print Film L2 L2 R2	Creditor #-VB-GLA010 GLASSPROTECH MELBOURNE P/O #-O329194 Receiving #-345879 Date :2022-09-19	1211768
878	09/16/2022	1069863	Mechanic entered - Body Front_Door Operation Faulty NOT CLOS	refit pivot sharftsdoorsrams and adjust doors.	1211768
878	09/15/2022	1069863	SME-8-K-LED-24 PROXIMITY SWITCH		1211768
878	09/15/2022	1069863	Mechanic entered - Body Front_Door Operation Faulty NOT CLOS	repair and weld shelf plate.	1211768
878	09/03/2022	1064767	Mechanic entered - Suspension Other front sway bar u/s40mm.	removed front sway bar removed front both D rubber replaced front sway barboth D rubber ok.	1209792
878	09/03/2022	1064767	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081		1209792
878	09/01/2022	1067067	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1209499
878	09/01/2022	1067067		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST - complete	1209499
878	09/01/2022	1067067		SERVICE MOISTURE EJECTOR	1209499
878	08/30/2022	1064767	SWAY (ANTI ROLL) BAR FRT SCA	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O327476 Receiving #-344476 Date :2022-08-30	1209256
878	08/29/2022	1066451		complete	1209029
878	08/24/2022	1065484		VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list.	1208547
878	08/24/2022	1065484		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1208547
878	08/24/2022	1065508	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Removed and fitted new N/S wiper blade insert.	1208547
878	08/24/2022	1065508	WIPER REFILL 1000mm MULTI FIT (TRP1000)		1208547
878	08/23/2022	1064905	Consumables		1207847
878	08/23/2022	1064905	Consumables		1207847
878	08/23/2022	1064905	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	retorque o/s/r wheel nuts.	1207847
878	08/22/2022	1064871	Consumables		1207847
878	08/22/2022	1064871	Consumables		1207847
878	08/22/2022	1064871	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	Retensioned O/S/R wheel nuts	1207847
878	08/20/2022	1064595	Consumables		1207847
878	08/20/2022	1064595	Consumables		1207847
878	08/20/2022	1064595	TYRE 295/80R22.5 RECAP		1207847
878	08/20/2022	1064595	Mechanic entered - Wheels and Tyres Other o/s/r tyres u/s.	removed o/s/r tyres replaced o/s/r tyres ok.	1207847
878	08/20/2022	1064586	Mechanic entered - Engine Other engine air filter u/s.	replaced engine air filter ok.	1207847
878	08/20/2022	1064586	FILTER AIR OUTER SCANIA SR 3 & 4(395773)(AF25066)		1207847
878	08/20/2022	1064586	Consumables		1207847
878	08/20/2022	1064586	Consumables		1207847
878	08/20/2022	1064586	Mechanic entered - Body Other n/s/f staunchion pole loose.	repaired n/s/f staunchion pole ok.	1207847
878	08/20/2022	1064586	Mechanic entered - Body Other rear smoking decal missing.	replaced rear smoking decal ok.	1207847
878	08/20/2022	1064586	Mechanic entered - Body Other o/s/middle seat top pins off.	put in o/s/middle seat top pins ok.	1207847
878	08/20/2022	1064583	Consumables		1207847
878	08/20/2022	1064583	Consumables		1207847
878	08/20/2022	1064583	Consumables		1207847
878	08/20/2022	1064583	Consumables		1207847
878	08/20/2022	1064583	PAPER SPINNER FILTER OIL INSERT SCANIA L94	CARRY OUT B SERVICE AS PER CHECK LIST	1207847
878	08/20/2022	1064583	O-RING SPINNER FILTER SCANIA L94		1207847
878	08/20/2022	1064583	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1207847
878	08/20/2022	1064583	FILTER OIL SCANIA K93 L94(1117285)(2059778)		1207847
878	08/20/2022	1064583	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		1207847
878	08/20/2022	1064583	FILTER FUEL SCANIA L94(1372444)		1207847
878	08/20/2022	1064583	OIL SAMPLE KIT AMPOL		1207847
878	08/20/2022	1064583	Consumables		1207847
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	drain coolant and engine oil removed engine spinner case removed engine sump removed driver shaft	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	removed engine start motor removed transmission coolant hosecoolant pipes removed all transmission wiresremoved both transmission engine mount bracket removed trans top fuel hose bracket bolts removed all trans toeque converter bolts removed trans to beel housing all nuts. removed transmission.	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	removed flywheel gear removed flywheel sensoe removed bell housingclenaed bell housing gaskethot washer cleaned bell housingcleaned flywheel replaced bell housing gasket replaced rear crank seal retorqued bell housing boltsretorqued flywheel bolts cleaned transmossion.	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	put in start motortightened start motor nutsput in start motor wires ok.	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	maked engine bottom holding bracket engine sump gasket all offcylinder to sump gasket all off put in sump gasketspinner gasket ok.	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	put in engine sumpretoequed engine all sump bolts removed dipstick plastic flexible replaced dipstick plastic flexible removed spinner all kitsreplaced spinner all kits ok replaced engine sump pluge replaced put in spinner casetightened spinner case all bolts	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	put in transmissiontightened transmission to bell housing nuts put in transmission all wiresput in engine mount brackettightened engine mount bracket all bolts	1206656
878	08/12/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	replaced trans coolant hose put in transmission top coolant pitehosetightened trans coolant pipe bracket boltstightened coolant hose clamps ok put in driver shafttightened driver shaft bolts tightened torque converter all boltscheck coolantengine oilengine fan oilpower steering oil ok. replaced engine belt idler bearing o	1206656
878	08/02/2022	1060510	Drv entered - A/C Heating Demister Not Heating	road testbring to operating tempcould not fault.	1204758
878	07/23/2022	1058837	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension	1203257
878	07/23/2022	1058837	Consumables		1203257
878	07/23/2022	1058837	Consumables		1203257
878	07/23/2022	1058880	Body (None) rear door air leaking	fit new air regulator to rear door.	1203257
878	07/23/2022	1058880	VALVE FESTO DOOR MINI TYPE(159625 ¼")		1203257
878	07/23/2022	1058880	Consumables		1203257
878	07/23/2022	1058880	Consumables		1203257
878	07/22/2022	1058837	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete		1203257
878	07/21/2022	1058624	Mechanic entered - Wheels and Tyres Damaged Pos 3 tyre side	Replaced pos3 tyre with side wall damage match pos4 with new retread	1202989
878	07/21/2022	1058624	TYRE 295/80R22.5 RECAP		1202989
878	07/21/2022	1058624	Consumables		1202989
878	07/21/2022	1058624	Consumables		1202989
878	07/13/2022	1056684	AIR FITTING AND HOSE RECTIFICA	Creditor #-VB-ENZED ENZED MOORABBIN P/O #-O324911 Receiving #-341480 Date :2022-07-20	1202761
878	07/12/2022	1056684	Ops Entered - Fault - Air System Air Not Building_Up - Rou	ENZED PO#: O324911 Checked and found signal line for air compressor comes off called in enzed and made air line with fittings and tested found okay	1201181
878	07/11/2022	1055108	DIRECT PURCHASE - BUS INSPECTI	Creditor #-VB-ROA002 ROAD SAFETY INSPECTIONS P/O #-O324382 Receiving #-340971 Date :2022-07-12	1201181
878	07/11/2022	1056407	Wipers and Washers Wipers Not Working	Assisting checked and found low speed had pwr once the master on; checked the stalk but stops pwr once node disconnected. suspected node; drove to moorabbin and removed an F-Node from 884. fitted and checked wipers ok. fitted arms and adjusted ok	1201143
878	07/11/2022	1056397	a/c gas leak pipe behind compressor	checked for a/c gas leak on pipe. could not fault . it was condensation from discharged outlet pipe . which is normal	1201143
878	07/09/2022	1056407	Wipers and Washers Wipers Not Working	wipers doors and demisters nw; found fuse 43 blowbn. replaced fuse and adjusted wipers as they run past the pillar. after could not stop wipers as wiper works as soon as the master switch is on. swapped motor still the same.	1201143
878	07/09/2022	1056300	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	1201143
878	07/06/2022	1055767	Mechanic entered - Air System Air_Leak Rear Single line for	Replaced fitting	1200934
878	07/06/2022	1055767	UNION ASSY SCANIA		1200934
878	07/05/2022	1055509	Mechanic entered - Wipers and Washers Wipers Loose n/s	Adjusted the wiper arm	1199877
878	07/05/2022	1055509	Mechanic entered - Body Other Rubbish bin lid under the bus	Drill broken rivets off and fit new rivets to lid and hinge	1199877
878	07/05/2022	1055509	Consumables		1199877
878	07/05/2022	1055509	Consumables		1199877
878	07/05/2022	1055509	Mechanic entered - Air System Air_Leak Interior Above rear d	Found valve on rear door leaking replaced festo door control valve	1199877
878	07/05/2022	1055509	FESTO DOOR CONTROL VALVE (173125)		1199877
878	07/04/2022	1055108		VEHICLE SAFETY INSPECTION	1199877
878	07/04/2022	1055108		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1199877

878	07/04/2022	1055108	ANNUAL SAFETY INSPECTION SERIAL # __RSI 040130 - PASS__ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1199877
878	07/04/2022	1055108	PRE ANNUAL SAFETY INSPECTION CHECK	1199877
878	07/04/2022	1055108	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1199877
878	07/01/2022	1054867	AIR CONDITIONING REPAIR	1201181
878	07/01/2022	1054867	Creditor # :VB-COL004 COLD DRIVE PTY LTD P/O #:O324312 Receiving #:340964 Date :2022-07-12 carry out 24 month as required	1199877
878	07/01/2022	1054867	CARRY OUT A/C - B SERVICE AS PER CHECK LIST - PO#: O324312 cold drive cammy	1199877
878	06/29/2022	1054482	Consumables	1199877
878	06/29/2022	1054482	Mechanic entered - Wheels and Tyres Wheel Nut Retension Ret	1199877
878	06/29/2022	1054482	Consumables	1199877
878	06/29/2022	1046297	TRANSMISSION ECOT ZF REBUILD	1199877
878	06/29/2022	1053293	Mechanic entered - Fluid Leaks Rear of bus Engine oil leak	1199877
878	06/29/2022	1054494	Consumables	1199877
878	06/29/2022	1054494	Mechanic entered - Elec and Light Interior Lights Drivers li	1199877
878	06/29/2022	1054494	Consumables	1199877
878	06/29/2022	1053293	Mechanic entered - Air System Air_Leak Rear From air compres	1199877
878	06/29/2022	1053293	LOCK WASHER RR HUB SCANIA K230UB 273023	1199877
878	06/29/2022	1053293	SLACK ADJUSTER AUTO-REAR N/SIDE SERIES 4(2009819)	1199877
878	06/29/2022	1053293	SEAL REAR AXLE CAP SCANIA(1765061)(120310)	1199877
878	06/29/2022	1053293	Mechanic entered - Air System Air_Leak Rear From air compres	1199877
878	06/24/2022	1053293	2025393 S-Cam - N/S/R	1200465
878	06/22/2022	1053278	Mechanic entered - Vandalism Other Graffiti on N/S/R exterior	1199877
878	06/22/2022	1046401	Mechanic entered - Fluid Leaks Other injector pump cover gas	1199877
878	06/22/2022	1046400	Mechanic entered - Engine Other injector pump gear cover oil	1199877
878	06/22/2022	1046400	Mechanic entered - Engine Other injector pump gear cover oil	1199877
878	06/22/2022	1046400	Mechanic entered - Engine Other injector pump gear cover oil	1199877
878	06/22/2022	1046400	Mechanic entered - Engine Other injector pump gear cover oil	1199877
878	06/22/2022	1046401	Mechanic entered - Fluid Leaks Other injector pump cover gas	1199877
878	06/22/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	1199877
878	06/22/2022	1053278	Mechanic entered - Body Other 3x rear panel screw missing.	1199877
878	06/22/2022	1053278	Consumables	1199877
878	06/22/2022	1053293	Mechanic entered - Brakes Other Could not adjust brakes n/s/	1199877
878	06/22/2022	1053293	Mechanic entered - Air System Air_Leak Rear From air compres	1199877
878	06/22/2022	1053250		1199877
878	06/21/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	1199877
878	06/09/2022	1046400	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG	1199877
878	06/09/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	1199877
878	06/03/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	1199877
878	06/02/2022	1046297	DIRECT PURCHASE - ELCTRICAL	1200465
878	06/02/2022	1046297	Mechanic entered - Engine Other bell housing gasket oil leak	1199877
878	06/02/2022	1046297	ZF INVOICE PROCESSED IN ERROR	1200465
878	06/02/2022	1046297	DIRECT PURCHASE - ELECTRICAL	1200465
878	06/01/2022	1033084	DIRECT PURCHASE - ELECTRICAL	1200465
878	06/01/2022	1033084	Consumables	1200465
878	06/01/2022	1033084	Consumables	1200465
878	05/30/2022	1046297	HOSE G/BOX COOLING SCANIA L94 0485995	1199877
878	05/30/2022	1046297	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940	1199877
878	05/26/2022	1047318	Gearbox Driveline Front seal leaking oil	1199877
878	05/26/2022	1046297	PAPER SPINNER FILTER OIL INSERT SCANIA L94	1199877
878	05/26/2022	1046297	O-RING SPINNER FILTER SCANIA L94	1199877
878	05/26/2022	1046297	O-RING LARGE SPINNER FILTER SCANIA L94 & K230	1199877
878	05/25/2022	1047318	GASKET SUMP ECOMAT 2	1199877
878	05/25/2022	1047318	GASKET OUTPUT COVER ZF	1199877
878	05/25/2022	1047318	Gearbox Driveline Front seal leaking oil	1199877
878	05/23/2022	1047318	Gearbox Driveline Front seal leaking oil	1199877
878	05/23/2022	1046400	PUMP FUEL PRIMER SCANIA L94 3826073 A0000908850	1199877
878	05/20/2022	1047318	Gearbox Driveline Front seal leaking oil	1199877
878	05/19/2022	1047318	Gearbox Driveline Front seal leaking oil	1199877
878	05/19/2022	1047318	KIT REPAIR ECOMAT FRONT COVER	1199877
878	05/19/2022	1046400	COOLING HOSE (0290864)	1199877
878	05/17/2022	1046297	HOSE RADIATOR LWR DC901 SCANIA L94 1872597 461737	1199877
878	05/17/2022	1046297	HOSE G/BOX COOLING 160 DEG 1 7/8 X 2 1/4 1451072 461674	1199877
878	05/17/2022	1046297	GASKET SUMP DSC9 SCANIA L94 551450 1412666 1382398	1199877
878	05/17/2022	1046297	GASKET SUMP DSC9 SCANIA L94 551450 1412666 1382398	1199877
878	05/16/2022	1046297	GASKET FLYWHEEL HSG SCANIA L94	1200465
878	05/16/2022	1046297	SEAL RR CRANK DS1174 SCANIA L1	1200465
878	05/16/2022	1046297	GASKET INJ PUMP GEAR COVER L	1200465
878	05/14/2022	1046307	Mechanic entered - Vandalism Vandalism/ Graffiti Interior R	1199877
878	05/13/2022	1045972		1199877
878	05/13/2022	1045972		1199877
878	05/13/2022	1046075	Mechanic entered - Dash Other Bus Minder Not secured mount	1199877
878	05/13/2022	1046075	Consumables	1199877
878	05/13/2022	1046075	Consumables	1199877
878	05/13/2022	1046075	Mechanic entered - Body Other N/S/F Modesty Panel Loose	1199877
878	05/13/2022	1046075	Consumables	1199877
878	05/10/2022	1045404	Consumables	1199367
878	05/10/2022	1045404	Mechanic entered - Elec and Light Exterior Lights N/S/F top	1199367
878	05/10/2022	1045404	Consumables	1199367
878	05/09/2022	1044866		1199233
878	05/09/2022	1044866		1199233
878	05/09/2022	1044932	Consumables	1199233
878	05/09/2022	1044932	Mechanic entered - Elec and Light Next Stop Button n/s/r	1199233
878	05/09/2022	1044932	Mechanic entered - Elec and Light Next Stop Button n/s/r	1199233
878	05/09/2022	1044932	SWITCH STOP YELLOW (62628)(50V2242)	1199233
878	05/09/2022	1044932	Consumables	1199233
878	05/09/2022	1044932	Mechanic entered - Body Other o/s/f indicator loose	1199233
878	05/09/2022	1044932	Mechanic entered - Body Other step strip rubber missing	1199233
878	05/09/2022	1044932	Mechanic entered - Body Other rear stauchion pole loose	1199233
878	05/09/2022	1044932	Mechanic entered - Body Other a/c filter bracket loose	1199233
878	05/09/2022	1044932	Consumables	1199233
878	05/09/2022	1044932	Mechanic entered - Air System Air_Leak Front leaking from ta	1199233
878	05/09/2022	1044932	VALVE MANUAL DRAIN 22MM VOLVO B7RLE(1081328-5)(1581425-4)	1199233

878	05/06/2022	1044698	Consumables			1199233
878	05/06/2022	1044698	Mechanic entered - Elec and Light Other o/s/r saloon light n	all saloon lights workingcould not fault.		1199233
878	05/06/2022	1044698	Consumables			1199233
878	05/05/2022	1044426	Bus was raised and wont lower	repair front broken levelling valve torque rod clampchange leaking levelling valve blockroad testok.		1199233
878	05/05/2022	1044426	VALVE FRT LVL CNTRL VALVE VOLVO B7 SCANIA L94			1199233
878	04/30/2022	1043502	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	complete		1198493
878	04/23/2022	1041885	Mechanic entered - Air System Air_Leak Rear	checked and found air leaking from junction connector at the osr under the ac comp; removed and fixed leaking. checked for further leak; could not locate any		1197422
878	04/23/2022	1041883		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list		1197422
878	04/21/2022	1041600	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Removed and fitted new wiper blade inserts.		1197194
878	04/21/2022	1041600	WIPER REFILL 1000mm MULTI FIT (TRP1000)			1197194
878	04/12/2022	1040190	Mechanic entered - Elec and Light Exterior Lights N/S/F/T PA	fit globe		1195146
878	04/12/2022	1040190	Consumables			1195146
878	04/12/2022	1040190	Consumables			1195146
878	04/04/2022	1038868	VALVE CIRCUIT PROTECTION SCANIA 1431049			1193654
878	04/04/2022	1038868	Mechanic entered - Air System Air Not Building_Up Intermitte	Removed and fitted new circuit protection valve. Checked for air leaks and air building up. No leaks and air builds up fine. Road tested and brake tested with Satya. Air building up as it should.		1193654
878	03/26/2022	1037328	Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI		1192530
878	03/25/2022	1037080		VEHICLE SAFETY INSPECTION		1192530
878	03/25/2022	1037080		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1192530
878	03/25/2022	1037184	Consumables			1192530
878	03/25/2022	1037184	Mechanic entered - Elec and Light Other rear pax switch	removed switch and was just not properly connected refitted all checked ok		1192530
878	03/25/2022	1037184	Mechanic entered - Elec and Light Interior Lights O/S/R Salo	removed cover and blown fluoro replaced with new globe from stock checked for operation ok.		1192530
878	03/25/2022	1037184	Consumables			1192530
878	03/25/2022	1037184	Consumables			1192530
878	03/25/2022	1037184	Mechanic entered - Body Other front and rearn modesty panel	removed old rivet and replaced with new rivets also made bracket to support better all checked ok		1192530
878	03/25/2022	1037184	Consumables			1192530
878	03/25/2022	1036980	PRESSURE SENSOR			1192530
878	03/24/2022	1036900	Consumables			1192530
878	03/24/2022	1036900	Mechanic entered - Body Other Floor Flex - Rear of bus behi	checked condition of saloon floor . could not fault		1192530
878	03/24/2022	1036900	Consumables			1192530
878	03/24/2022	1036980	Ops Entered - Fault - Air System Air_Leak Rear - Route: 703	Removed and replaced air compressor air drier and oil seperator top up coolant and road test found okay		1192530
878	03/24/2022	1036980	AIR COMPRESSOR - WITH REAR COVER PLATE			1192530
878	03/24/2022	1036980	AIR DRYER ASSY SCANIA 1743859 0470200			1192530
878	03/24/2022	1036980	O-RING SEAL COMPRESSOR MOUNT SCANIA L94 MERC(323790)			1192530
878	03/24/2022	1036980	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1871043 1376911			1192530
878	03/24/2022	1036980	BOLT COMPRESSOR GEAR SCANIA			1192530
878	03/24/2022	1036980	Ops Entered - Fault - Air System Air_Leak Rear - Route: 703	Assisting with the job		1192530
878	03/24/2022	1036980	Ops Entered - Fault - Air System Air_Leak Rear - Route: 703	Assisting		1192530
878	03/24/2022	1036980	Ops Entered - Fault - Air System Air_Leak Rear - Route: 703	checked door system and suspect rear door rebound sensor faulty - alled BW electrics. recommended servicing air system components due to suspected air building up and contamination issues. BW replaced door sensor. PO O318468		1192530
878	03/24/2022	1036980	OIL COLLECTOR AIR DRIER SCANIA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O318452 Receiving #:333864 Date :2022-03-25		1192530
878	03/19/2022	1036004	Ops Entered - Fault - Brakes Warning Light On - Route: 703	road tested . checked air system . could not fault		1192072
878	03/16/2022	1035377	Ops Entered - Fault - Wipers and Washers Wipers Not Working	completed on w/o - 1035354		1191831
878	03/16/2022	1035354	Mechanic entered - Wipers and Washers Wipers Not Working int	change the wiper motor used but good coondition one checked operation all ok		1191831
878	03/11/2022	1034841	Mechanic entered - Wipers and Washers Wipers Not Working Wip	checked connections relays fuses restart the node system		1191299
878	03/09/2022	944167	Body Windows Front NS peep and windshield crack	complete		1190701
878	03/09/2022	944167	Consumables			1190701
878	03/09/2022	944167	Consumables			1190701
878	03/07/2022	1033698	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	repaired earth wire to compressor plate . checked operation all ok		1190136
878	03/07/2022	1033562	Mechanic entered - Elec and Light Other battery jump.	checked battery 9v5vjumped battery.		1190136
878	03/07/2022	1033562	Consumables			1190136
878	03/07/2022	1033562	Consumables			1190136
878	03/03/2022	1033084	Mechanic entered - Elec and Light Warning Light On Dash rea	checked and rectified by BW electrics PO#: O317232		1190136
878	03/03/2022	1033084	PRESSURE SENSOR			1190136
878	03/03/2022	1033084	Consumables			1190136
878	03/01/2022	1012943	Mechanic entered - Accident - OFF SIDE FRONT Front indicator	Replaced indicator and reflector. Cleaned scratches with acetone.		1190136
878	03/01/2022	1012943	Service - Accident	fit new headlight sourround mould to o/s/f . repaired front bumper mounts . bog sand and paint parts of front bumper . all ok		1190136
878	02/25/2022	1031893	Ops Entered - Fault - Air System Air_Leak Rear - Route: 703	no air leakadjust drier unit regulator.road testok.		1190136
878	02/25/2022	1031835		complete		1190136
878	02/25/2022	1031835		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1190136
878	02/24/2022	1012943	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O316695 Receiving #:332258 Date :2022-02-28 mobile mick to carry out repairs to o/s/f of bus as required - headlight surround		1190136
878	02/24/2022	1031406	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	complete		1189625
878	02/18/2022	1029705	Consumables			1188498
878	02/18/2022	1029705	Mechanic entered - Elec and Light Indicators Not Working das	fit globe.		1188498
878	02/18/2022	1029705	Consumables			1188498
878	02/17/2022	1029511	Consumables			1188498
878	02/17/2022	1029511	SWITCH OIL PRESSURE SCANIA (1881260)			1188498
878	02/17/2022	1029511	Mechanic entered - Elec and Light Warning Light On Dash oil	Check and change warning light globe repait oil pressure wire change the oil pressure sender		1188498
878	02/17/2022	1029511	Consumables			1188498
878	02/17/2022	1029455	Consumables			1188498
878	02/17/2022	1029455	Consumables			1188498
878	02/17/2022	1029455	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			1188498
878	02/17/2022	1029455	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814			1188498
878	02/17/2022	1029455	O-RING SPINNER FILTER SCANIA L94			1188498
878	02/17/2022	1029455		CARRY OUT B SERVICE AS PER CHECK LIST		1188498
878	02/17/2022	1029455	FILTER OIL SCANIA S4 & K			1188498
878	02/17/2022	1029455	FILTER FUEL SCANIA SR4(1372444)			1188498
878	02/17/2022	1029455	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			1188498
878	02/17/2022	1029455	PAPER SPINNER FILTER OIL INSERT SCANIA L94			1188498
878	02/17/2022	1029455	OIL SAMPLE KIT AMPOL			1188498
878	02/17/2022	1029455	Consumables			1188498
878	02/17/2022	1029455	Consumables			1188498
878	02/17/2022	1029455	Consumables			1188498
878	02/09/2022	1027909	Consumables			1187261
878	02/09/2022	1027909	Mechanic entered - Elec and Light Exterior Lights N/S/F top	Fitted new globe.		1187261
878	02/09/2022	1027909	Consumables			1187261
878	02/01/2022	1025933	Mechanic entered - Wheels and Tyres Wheel Nut Retension Both	Retensioned both front wheel nuts.		1185751
878	02/01/2022	1025933	Consumables			1185751
878	02/01/2022	1025933	Consumables			1185751
878	02/01/2022	1007389	1865748 Slack Adjuster	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O309591-RET Receiving #:332015 Date :2022-02-23 Incorrect Slack Adjuster		1189869
878	02/01/2022	1007389	Restock Fee	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O309591-1 Receiving #:332021 Date :2022-02-23		1189869
878	01/31/2022	1025594	Mechanic entered - Elec and Light Next Stop Button 2 nex sto	replaced passenger stop buttons x 2		1185337
878	01/31/2022	1025594	YELLOW/RED STOP SWITCH (20485)			1185337
878	01/31/2022	1025594	Consumables			1185337
878	01/31/2022	1025594	Consumables			1185337

878	01/31/2022	1024904	PLUG HUB COVER FORT SCANIA 4 SERIES 1549063	Assisted Satya.	1185337
878	01/31/2022	1024904	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	Creditor #:VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:O315180 Receiving #:330511 Date :2022-02-01 Check and machine drums & linings	1185337
878	01/31/2022	1024904	Direct Purchase - MECHANICAL	Drums and shoes arrived from Machining. Fitted brake shoes and drums. Adjusted brakes and torqued the wheels. Road tested brake tested and checked brake temperature all ok.	1185717
878	01/31/2022	1024904	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	Assisted Satya	1185337
878	01/31/2022	1024904	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	VEHICLE SAFETY INSPECTION	1185337
878	01/28/2022	1025297		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1185337
878	01/28/2022	1025297		removed both front tyres replaced both front tyres ok.	1185337
878	01/27/2022	1024930	Mechanic entered - Wheels and Tyres Other both front tyres u		1185337
878	01/27/2022	1024930	TYRE 295/80R22.5 NEW		1185337
878	01/27/2022	1024930	Consumables		1185337
878	01/27/2022	1024930	Consumables		1185337
878	01/27/2022	1024904	AIRBAG FRONT 14mm SCANIA K310UB E5(2809671)(2024289)		1185337
878	01/27/2022	1024904	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	road teste not brake bus going turn left. checked n/s/f tyre lowdamagen/s/e air bag air leaks removed n/s/f air bag replaced n/s/e air bagadjusted adjusted tie rod oktoein toeout all ok.	1185337
878	01/22/2022	1024245	Mechanic entered - Brakes Other pulling left.	adjust brakesroad and brake testok.	1184790
878	01/20/2022	1014543		TRANSMISSION CHECK AS PER CHECK LIST	1184560
878	01/14/2022	1021354	HORN 24V1 Incorrectly Booked out		1183433
878	01/14/2022	1021354	HORN ELECTRIC DISC 24V(ACX5118)		1183433
878	01/14/2022	1021354	Consumables		1183433
878	01/14/2022	1021354	Consumables		1183433
878	01/14/2022	1022738	Mechanic entered - Body Front_Door Operation Faulty n/w.	trace found top exitbutton wires fallen offrefit wiresok.	1183433
878	01/14/2022	1022738	Consumables		1183433
878	01/10/2022	1021270	Mechanic entered - Elec and Light Other rear door not workin	double entry	1182646
878	01/10/2022	1021270	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O313934 Receiving #:330297 Date :2022-01-28 rectify rear passenger door not working as required	1185717
878	01/10/2022	1021270	Consumables		1185717
878	01/10/2022	1021270	Consumables		1185717
878	01/07/2022	1021354	Mechanic entered - Elec and Light Horn n/w.	fit new horn.	1182646
878	01/07/2022	1021354	HORN 24V		1182646
878	01/07/2022	1021358	Elec and Light Horn LOOSE CONNECTION - PTI SHEET	DONE BY CDF WO1021354	1182646
878	01/07/2022	1021358	Consumables		1182646
878	01/07/2022	1021358	Consumables		1182646
878	01/06/2022	1021270	Mechanic entered - Elec and Light Other rear door not workin	O313934 - rear passenger door repaired by ben were	1182646
878	01/06/2022	1021270	SME-8-K-LED-24 PROXIMITY SWIT	Creditor #:VB-FES010 FESTO PTY LTD P/O #:O313812 Receiving #:329185 Date :2022-01-07	1182721
878	12/31/2021	1020491	Mechanic entered - Body Front_Door Operation Faulty n/w.	found external door button switch contacts rustyclean contactsdoor ok.	1181935
878	12/31/2021	1020538	Ops Entered - Fault - Body Front_Door Operation Faulty - R	repaired on work order - 1020491	1181935
878	12/31/2021	1020491	Consumables		1181935
878	12/31/2021	1020538	Consumables		1181935
878	12/24/2021	996527	Ops Entered - Fault - Passenger Doors - Route: 703 - Luntar	check operation front doorscould not fault.	1181248
878	12/24/2021	996527	Consumables		1181248
878	12/20/2021	1018746	Mechanic entered - Body Other o/s headlight cover loose.	secure cover.	1180115
878	12/20/2021	1018746	Consumables		1180115
878	12/16/2021	1018258		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1179654
878	12/10/2021	1017170	Mechanic entered - Air System Other air pressure drops.	air leaks niladjust main regulatorroad testok.	1178301
878	12/09/2021	1017120	Elec and Light Exterior Lights os upper park light nw	checked operation of all lights with lindsay . all external lights . could not fault	1178301
878	12/09/2021	1017120	Consumables		1178301
878	12/09/2021	1017078	Mechanic entered - Brakes Other O/S/R S cam u/s		1178301
878	12/04/2021	1015901		VEHICLE SAFETY INSPECTION	1007389 1177161
878	12/04/2021	1015901		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1177161
878	12/04/2021	1015902	AIRBAG FRONT 14mm SCANIA K310UB E5(2809671)(2024289)		1177161
878	12/04/2021	1015902	Mechanic entered - Suspension Other o/s/f air bag u/s.	removed o/s/f air bag replaced o/s/f air bag ok.	1177161
878	12/04/2021	1015903	Mechanic entered - Elec and Light Other o/sn/s middle pax s	replaced o/s/sn/s middle pax switch ok.	1177161
878	12/04/2021	1015903	YELLOW/RED STOP SWITCH (20485)		1177161
878	12/04/2021	1015903	horn not working return at 18.30pm tonight to depot	checked and found loose connection at horn plug	11771

878	10/22/2021	1007136	Consumables			1169351
878	10/22/2021	1007136	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701			1169351
878	10/22/2021	1007136	PAPER SPINNER FILTER OIL INSERT SCANIA L94			1169351
878	10/22/2021	1007136		CARRY OUT B SERVICE AS PER CHECK LIST		1169351
878	10/22/2021	1007135		CARRY OUT B SERVICE AS PER CHECK LIST done and parts booked on wo1007136		1169351
878	10/22/2021	1007136	FILTER OIL SCANIA S4 & K			1169351
878	10/22/2021	1007136	OIL SAMPLE KIT AMPOL			1169351
878	10/22/2021	1007136	FILTER FUEL FILTER SCANIA SR4 (1372444)			1169351
878	10/22/2021	1007136	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			1169351
878	10/22/2021	1007136	O-RING LARGE SPINNER FILTER SCANIA 40A7703			1169351
878	10/22/2021	1007136	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814			1169351
878	10/22/2021	1007135	Consumables			1169351
878	10/22/2021	1007135	Consumables			1169351
878	10/22/2021	1007135	Consumables			1169351
878	10/22/2021	1007136	Consumables			1169351
878	10/22/2021	1007136	Consumables			1169351
878	10/22/2021	1007136	Consumables			1169351
878	10/22/2021	1007136	Consumables			1169351
878	10/13/2021	1005370	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced N/S Headlight and park light globes. Checked all working.		1167185
878	10/13/2021	1005370	Consumables			1167185
878	09/27/2021	1001750	Consumables			1163878
878	09/27/2021	1001750	Mechanic entered - Elec and Light Flat Batteries	jump started bus		1163878
878	09/25/2021	1001643	Mechanic entered - Engine Belts_Loose Noisy Missing split.	fit new alt belt.		1163878
878	09/25/2021	1001643	BELT MICRO V SERPENT 8 RIB 2135mm LNG(1389048)			1163878
878	09/23/2021	1001632	Consumables			1163878
878	09/23/2021	1001632	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced globe		1163878
878	09/13/2021	999242	Mechanic entered - A/C Heating Belt Loose or_Missing	Both belts missing fitted new a/c belts		1161185
878	09/13/2021	999242	BELT V-BELT COGGED TRI-POWER 17x2135mm			1161185
878	09/13/2021	999242	Mechanic entered - Engine Belts_Loose Noisy Missing			1161185
878	09/13/2021	999242	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940	Found engine belt ribs missing replaced belt plain idler pulley and belt tensioner		1161185
878	09/13/2021	999242	BELT TENSIONER SCANIA SR4 1859654 1503113			1161185
878	09/13/2021	999242	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG(1389048)			1161185
878	09/11/2021	998871	Consumables			1161185
878	09/11/2021	998871	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque n/s/f wheel nuts.		1161185
878	09/09/2021	998309		VEHICLE SAFETY INSPECTION		1161185
878	09/09/2021	998309		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1161185
878	09/09/2021	998374	Mechanic entered - Engine Other ENGINE BELT U/S.	replaced engine belt.		1161185
878	09/09/2021	998374	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG(1389048)			1161185
878	09/09/2021	998374	Consumables			1161185
878	09/09/2021	998374	Mechanic entered - Body Other o/s/f staunchion pole loose.	repaired o/s/f staunchion pole ok. replaced pax switch		1161185
878	09/09/2021	998374	Mechanic entered - Body Other both middle seat top pins off.	put in both middle seat top pins ok.		1161185
878	09/09/2021	998374	Mechanic entered - Air System Other air dryer bottom valve a	repaired air dryer bottom valve ok.		1161185
878	09/09/2021	998374	YELLOW/RED STOP SWITCH (20485)			1161185
878	09/07/2021	997807	Mechanic entered - Suspension Other noise under bus.	found n/s/f wheel bearing u/sremove hub and strip.		1161148
878	09/07/2021	997807	BEARING WHEEL BEARING FRONT SERIES 4			1161148
878	09/07/2021	997807	Mechanic entered - Suspension Other noise under bus.	Replaced n/s/f wheel bearing assemble back centralise wheel and tension wheel nuts adjusted both front brakes and road test with brake test checked temperature n/s/f 23deg and o/s/f 21 deg		1161148
878	09/04/2021	997270	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	complete		1160630
878	09/02/2021	996527	Consumables			1160418
878	09/02/2021	996527	SWITCH DOOR CONTACT (NORMALLY OPEN)			1160418
878	09/02/2021	996527	Ops Entered - Fault - Passenger Doors - Route: 703 - Luntar	Checked and found the rear door close switch faulty. replaced ok. road tested ok		1160418
878	08/20/2021	993627		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1157951
878	08/20/2021	993627		complete		1157951
878	08/20/2021	993504	BELT V-BELT COGGED TRI-POWER 17x2135mm			1157951
878	08/20/2021	993504		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O305321 - completed by cold drive cammy		1157951
878	08/20/2021	993504	MOUNT A/C COMPRESSOR LARGE DENSO			1157951
878	08/20/2021	993504	AIR CONDITIONING REPAIR	Creditor #:/VB-COL004 COLD DRIVE PTY LTD P/O #:O305321 Receiving #:320252 Date :2021-08-27 carry out 12 month service as required		1159250
878	08/12/2021	991548	Mechanic entered - Elec and Light Other faulty master switch	check operation of switchcould not fault.		1155933
878	08/12/2021	991548	Consumables			1155933
878	08/11/2021	991509	Mechanic entered - Dash Switches Not Working Master switch w	Replaced with a good second hand one		1155933
878	08/11/2021	991509	Consumables			1155933
878	08/03/2021	989372	Mechanic entered - A/C Heating Other a/c belt u/s.	check a/c beit after a/c belt hit from to the a/c bracket cut a/c bracket ok replaced a/c belt all okroad tested all ok.		1154294
878	08/03/2021	989372	BELT V-BELT HI-POWER 17x2160mm			1154294
878	08/03/2021	989372	Mechanic entered - Engine Other engine belt u/s.	replaced engine belt ok.		1154294
878	08/03/2021	989372	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG(1389048)			1154294
878	08/03/2021	989372	Mechanic entered - Elec and Light Other o/s/f indicator ligh	removed o/s indicator light replaced indicator light ok.		1154294
878	08/03/2021	989372	INDICATOR SIDE INDICATOR R/H			1154294
878	08/03/2021	989372	Consumables			1154294
878	08/02/2021	989150	Mechanic entered - Elec and Light Flat Batteries Jump Starte	Jump Started		1154294
878	08/02/2021	989150	Consumables			1154294
878	07/28/2021	988302		VEHICLE SAFETY INSPECTION		1153754
878	07/28/2021	988302		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1153754
878	07/28/2021	988320	Mechanic entered - Wheels and Tyres Other n/s/r tyres u/s	removed n/s/r tyres replaced n/s/r tyres okretorqued n/s/r wheel nuts.ok.		1153754
878	07/28/2021	988320	TYRE 295/80R22.5 RECAP			1153754
878	07/28/2021	988544	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s/	Completed retension		1153754
878	07/28/2021	988320	Consumables			1153754
878	07/28/2021	988544	Consumables			1153754
878	07/28/2021	988320	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1153754
878	07/28/2021	988320	Mechanic entered - Suspension Other BOTH FRONT d RUBBER U/	removed both front D rubber replaced both front D rubber. ok		1153754
878	07/28/2021	988320	Mechanic entered - Engine Other engine belt u/s.	replaced engine belt		1153754
878	07/28/2021	988320	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG(1389048)			1153754
878	07/28/2021	988355	Mechanic entered - Elec and Light Next Stop Button	replaced broken pax switch		1153754
878	07/28/2021	988355	SWITCH- STOP-YELLOW (62628)			1153754
878	07/28/2021	988355	Consumables			1153754
878	07/28/2021	988320	Mechanic entered - Brakes Other n/s/r brake slack adjust kit	removed n/s/r brake slack adjust replaced n/s/r brake slack adjust kits ok.		1153754
878	07/28/2021	988320	KIT REPAIR KIT SLACK ADJUSTER (1350817)			1153754
878	07/26/2021	987706	Mechanic entered - Elec and Light Exterior Lights n/s/f/t pa	fit globe.		1153200
878	07/26/2021	987927	front top park light not working	repaired on work order - 987706		1153200
878	07/26/2021	987706	Consumables			1153200
878	07/26/2021	987927	Consumables			1153200
878	07/21/2021	987117	Mechanic entered - Elec and Light Indicators Not Working N/S	Replaced globe		1152689
878	07/21/2021	987117	Consumables			1152689
878	07/15/2021	984483	Vandalism/ Graffiti Interior G	Creditor #:/VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O302474 Receiving #:317482 Date :2021-07-22 bus 878 Completed 5/7/21		1152956
878	07/12/2021	984930	Mechanic entered - Engine Other Air Filter U/S	replaced U/S Air Filter replaced with new item from stock.		1150727
878	07/12/2021	984930	AIR FILTER OUTER SCANIA SR 3 & 4 395773 AF25066			1150727

878	07/12/2021	984930	Mechanic entered - Engine Other Drive Belt U/S	loosened and removed A/C Belts Removed drive belt and removed split part of belt from around crank pulley Put new belt on and re adjusted A/C Checked ok	1150727
878	07/12/2021	984930	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048		1150727
878	07/12/2021	984856		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B Service	1150727
878	07/12/2021	984856	SPINNER FILTER KIT ALL SCANIA		1150727
878	07/12/2021	984856	FILTER FUEL FILTER SCANIA SR4 (1372444)		1150727
878	07/12/2021	984856	FILTER OIL SCANIA S4 & K		1150727
878	07/12/2021	984856	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1150727
878	07/12/2021	984856	OIL SAMPLE KIT CALTEX		1150727
878	07/12/2021	984856	Consumables		1150727
878	07/08/2021	984483	Vandalism/ Graffiti Interior Graffiti film Audit 509	O302474 - completed by glass protect	1150519
878	07/01/2021	982962	Mechanic entered - A/C Heating Other demister not working	road tested demister not working after check rear heater valve okcheck demister valve after demister valve open after demister working ok	1148492
878	06/17/2021	980400		TRANSMISSION CHECK AS PER CHECK LIST	1146420
878	06/12/2021	979776	Ops Entered - Fault - Body Front_Door Operation Faulty - R	front door opening whilst trying to close . reduce air pressure at main air regulator . adjusted exhaust port to slow down closing pressure. checked operation all okay	1145811
878	06/12/2021	979776	Consumables		1145811
878	06/10/2021	979456	Body Front_Door Operation Faulty	front door not closing. this waw intermittent. no signal from door switch. removed the switch and found close switch terminal loose. secured and road tested ok.	1145578
878	06/10/2021	979456	Consumables		1145578
878	06/03/2021	978102		VEHICLE SAFETY INSPECTION	1143731
878	06/03/2021	978102		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1143731
878	06/03/2021	978102	DIRECT PURCHASE - BUS INSPECTI	ANNUAL SAFETY INSPECTION SERIAL #___L 453821 GREEN SHEET ____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1143731
878	05/26/2021	976587	Mechanic entered - Body Front_Door Operation Faulty n/w.	Creditor #-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #-O300270 Receiving #-314651 Date :2021-06-10	1145578
878	05/26/2021	976587	Consumables	reconnect wire to front door external exit button.	1142374
878	05/20/2021	975273	Mechanic entered - Engine Other engine oil cap missing		1140605
878	05/20/2021	975273	CAP OIL FILLER SCANIA L94UAB 1544036 1385367	replaced oil capcleaned rear bumperengine hatch ok oil ok	1140605
878	05/14/2021	974216	Mechanic entered - Suspension Other V rod u/s	removed V rodNikkiShannon doing put in V rod tightened VROD front bolts Nikkisahnnon doing put in rear V rod bushing training NIKKishannon how is V rod senter all ok.	1140605
878	05/14/2021	974216	BOLT V STAY ASSY CENTRE BUSH SCANIA L94		1140605
878	05/14/2021	974216	V STAY ASSEMBLY SCANIA L94UAB		1140605
878	05/14/2021	974393	Mechanic entered - Suspension Other V-Rod Worn	completed by sho on w/o 974216	1140605
878	05/14/2021	974227	Mechanic entered - Body Other n/s/r window strip off	repaired n/s/r window strip ok	1140605
878	05/14/2021	974365	Mechanic entered - Body Other fuel tank clemp move	repaired fuel tank clamo ok	1140605
878	05/14/2021	974227	Consumables		1140605
878	05/14/2021	974365	Consumables		1140605
878	05/13/2021	973958		PRE ANNUAL SAFETY INSPECTION CHECK	1140605
878	05/13/2021	973958		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1140605
878	05/13/2021	974039	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		1140605
878	05/13/2021	974060	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	Replaced rear Sway Bar 'D' Rubbers	1140605
878	05/13/2021	974060	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1140605
878	05/13/2021	974039	Mechanic entered - Suspension Other both front D rubber u/	removed both front D rubber replaced both front D rubber ok	1140605
878	05/13/2021	974039	Mechanic entered - Suspension Other both front D rubber u/		1140605
878	05/13/2021	974039	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok	1140605
878	05/13/2021	974039	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		1140605
878	05/13/2021	974039	Mechanic entered - Elec and Light Other n/s head light u/s	replaced n/s head light ok	1140605
878	05/13/2021	974039	LAMP HEADLAMP MK3 VOLVO B10M		1140605
878	05/13/2021	974039	Consumables		1140605
878	05/13/2021	974039	Mechanic entered - Body Other o/s/r seat base loose	repaired o/s/r seat base ok	1140605
878	05/13/2021	974039	Mechanic entered - Body Other both middle seat all loose	repaired both middle seat ok	1140605
878	05/13/2021	974039	Mechanic entered - Body Other n/s/f seat bracket bolt loose	tightened n/s/f seat bracket bolt ok	1140605
878	05/13/2021	974039	Mechanic entered - Body Other n/s/f staunchion pole bolt mis	replaced n/s/f staunchion pole bolt ok	1140605
878	05/13/2021	974039	Consumables		1140605
878	05/13/2021	974039	Mechanic entered - Brakes Other o/s/f brake slack adjust u/s	removed o/s/f brake slack adjust replaced o/s/f brake slack adjust ok	1140605
878	05/13/2021	974039	SLACK ADJUSTER FRONT OUTER SIDE (1789567)		1140605
878	05/12/2021	973653	Mechanic entered - Wheels and Tyres Flat or Leaking N/S/R/O	removed flat tyre and replaced with runout tyre from stock	1140605
878	05/12/2021	973806	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retensioned all wheel nuts	1140605
878	05/12/2021	973806	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retensioned all wheel nuts	1140605
878	05/12/2021	973259	TYRE 275/70R22.5 RECAP	Incorrect Tyres booked out	1140605
878	05/12/2021	973259	TYRE 295/80R22.5 RECAP	Incorrect Tyres booked out	1140605
878	05/12/2021	973653	Consumables		1140605
878	05/12/2021	973806	Consumables		1140605
878	05/12/2021	973802	Mechanic entered - Body Other n/s/r hub nut missing.	fitted NSR hub cap nuts and studs ok	1140605
878	05/12/2021	973802	Consumables		1140605
878	05/12/2021	973259	Brakes Foot_Brakes Noisy - closed wo968217 to enable bus a	fitted drum linings & wheelsok. r/r o/s/r tyres.	1140605
878	05/12/2021	973259	Mechanic entered - Brakes Other rear slack adjuster u/s.	done.	1140605
878	05/12/2021	973259	TYRE 275/70R22.5 RECAP		1140605
878	05/12/2021	973259	KIT REPAIR KIT SLACK ADJUSTER (1350817)	road tested and checked retarder working ok.	1140605
878	05/12/2021	973802	Mechanic entered - Brakes Other retarter n/w.	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O298648 Receiving #-312409 Date :2021-05-12	1140833
878	05/11/2021	973259	LOCK NUT	r/r slack adjuster kitsok.	1140605
878	05/11/2021	973259	Mechanic entered - Brakes Other rear slack adjuster u/s.	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O298648 Receiving #-312409 Date :2021-05-12	1140833
878	05/11/2021	973259	STUD	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O298648 Receiving #-312409 Date :2021-05-12	1140833
878	05/10/2021	973259	Mechanic entered - Brakes Other rear slack adjuster u/s.	removed rear slack adjusters.	1140605
878	05/10/2021	973259	Brakes Foot_Brakes Noisy - closed wo968217 to enable bus	removed front & rear tyres drums & linings.	1140605
878	05/10/2021	973259	DIRECT PURCHASE - BRAKES	Creditor #-VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #-O298632 Receiving #-312493 Date :2021-05-13 replace linings and machine drums as required please call 0447 597 651 for quote before repair	1140833
878	05/08/2021	973054		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	1140605
878	05/07/2021	972884	Elec and Light Exterior Lights nsf parkers nw refer wo 971	TRACERPAIR BROKEN SUPPLY WIRE TO LIGHT.	1140605
878	05/07/2021	972884	Consumables		1140605
878	05/03/2021	971703	Mechanic entered - Elec and Light Exterior Lights O/S HEADLI	FIT GLOBES	1139513
878	05/03/2021	971705	Mechanic entered - Elec and Light Exterior Lights N/S FRONT	NO POWER TO LIGHTWIRING TO BE CHECKED. closed wo to enable bus allocation opened new defect in TIMS 873340	1139513
878	05/03/2021	971703	Consumables		1139513
878	05/03/2021	971705	Consumables		1139513
878	04/21/2021	969350		VEHICLE SAFETY INSPECTION Carried out safety inspection	1137729
878	04/21/2021	969350		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1137729
878	04/21/2021	969425	STRUT GAS STAY 500Nm 500mm LONG		1137729
878	04/21/2021	969425	Mechanic entered - Body Other N/S Radiator Hatch Struts Leak	removed leaking struts changed mounts and replaced with new struts from stock	1137729
878	04/15/2021	968217	Drv entered - Brakes Foot_Brakes Noisy	washed drums; road tested found noisywhenhot. needs re-booking. closed wo to enable bus allocation opened new defect in TIMS 873335	1136659
878	03/31/2021	965314	Mechanic entered - Elec and Light Indicators Not Working das	fit globe.	1134232
878	03/31/2021	965314	Consumables		1134232
878	03/27/2021	964277	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	carried out campaign	1133511
878	03/26/2021	963884	Place new poster over the top attach hangers to hand rails	complete	1133511
878	03/16/2021	960895	Mechanic entered - Fluid Leaks Other engine rear bellhousin	Checked OK	1131654
878	03/15/2021	960402	Mechanic entered - Body Other n/s/r upper body damagedeen b	rerivet n/s/r gutter rail.	1130994
878	03/15/2021	960402	Consumables		1130994
878	03/12/2021	960272	Mechanic entered - Gearbox Driveline Other select gear switc	r/r gear select switchok.	1130994
878	03/12/2021	960272	Mechanic entered - Engine Other belt idle pully u/s.	r/r idle pullyok.	1130994

878	03/12/2021	960272	Mechanic entered - Fluid Leaks Rear of bus suspect rear main	carry out under carriage wash recomend further inspection @ nxt service or safety which ever comes 1st	1130994
878	03/12/2021	960272	Button Shift N HORIZONTAL SERIES 3		1130994
878	03/12/2021	960272	Mechanic entered - Elec and Light Interior Lights n/s/r salo		1130994
878	03/12/2021	960272	Mechanic entered - Elec and Light Other rear step light lens		1130994
878	03/12/2021	960272	LENS CLEAR TO SUIT 1406		1130994
878	03/12/2021	960272	Mechanic entered - Elec and Light Other battery postive cabl	remove terminal clean all terminal cut back damage wire refit terminal tighten all check ok	1130994
878	03/12/2021	960272	EMERGENCY HAMMER COMPLETE WITH CRADLE 274-0044		1130994
878	03/12/2021	960272	PULLEY IDLER SCANIA (1514087)		1130994
878	03/12/2021	960272	Consumables		1130994
878	03/12/2021	960272	Mechanic entered - Body Other missing o/s/f modesty panel sc		1130994
878	03/12/2021	960272	Mechanic entered - Body Other emergency hammar u/s.	drilling & fitted new boltsok. r/r emergency hammarok.	1130994
878	03/12/2021	960272	Consumables		1130994
878	03/12/2021	960221	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI		1130994
878	03/12/2021	960068			1130994
878	03/12/2021	960068	FILTER HYD COOLING FAN SCANIA L94UAB 1354074		1130994
878	03/12/2021	960068	FILTER OIL SCANIA S4 & K	CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order check ok	1130994
878	03/12/2021	960068	FILTER FUEL FILTER SCANIA SR4 (1372444)		1130994
878	03/12/2021	960068	FILTER FUEL FILTER SCANIA SR4 (1372444)		1130994
878	03/12/2021	960068	SPINNER FILTER KIT ALL SCANIA		1130994
878	03/12/2021	960068	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1130994
878	03/12/2021	960068	FILTER STEERING FILTER (153468) (0153468)(349619)		1130994
878	03/12/2021	960068	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		1130994
878	03/12/2021	960068	Consumables		1130994
878	03/12/2021	960068	Consumables		1130994
878	03/12/2021	960068			1130994
878	03/12/2021	960068	Consumables		1130994
878	03/12/2021	960068	Consumables		1130994
878	03/05/2021	958855	Mechanic entered - Body Other a/c roof vent loose.		1130994
878	03/05/2021	958855	Consumables		1130232
878	02/20/2021	955733	Leave old poster in and fit you must wear a maskover the		1130232
878	02/19/2021	955427		complete VEHICLE SAFETY INSPECTION Carried out safety inspection TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS replaced Rear Sway Bar 'D' Bushes	1127716
878	02/19/2021	955427			1127716
878	02/19/2021	955514	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes		1127716
878	02/19/2021	955514	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1127716
878	02/19/2021	955514	Mechanic entered - Suspension Other O/S/R/R + N/S/R/R AirBag		1127716
878	02/19/2021	955514	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290	replaced O/S/R/R+N/S/R/R air bags checked ok	1127716
878	02/19/2021	955648	Consumables		1127716
878	02/19/2021	955648	Mechanic entered - Body Other N/S Mirror Loose		1127983
878	02/19/2021	955427	Drv entered - Brakes Foot_Brakes Noisy		1127716
878	02/15/2021	953776			1127716
878	02/15/2021	953776		tightened Mirror arm ok WASHED OUT ALL BRAKE DUST FROM DRUMS ROAD TESTED . COULD NOT FAULT NOISEY BREAKS complete CARRY OUT FIRE EXTINGUISHER TEST & TAG	1127073
878	02/15/2021	953480	Consumables		1127073
878	02/15/2021	953480	Consumables		1127342
878	02/15/2021	953480	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1127342
878	02/15/2021	953480	OIL SAMPLE KIT CALTEX		1127073
878	02/15/2021	953480		CARRY OUT B SERVICE AS PER CHECK LIST carried out B service	1127073
878	02/15/2021	953480	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1127073
878	02/15/2021	953480	Oil Filter SCANIA S4 & K		1127073
878	02/15/2021	953480	FILTER FUEL FILTER SCANIA SR4 (1372444)		1127073
878	02/12/2021	953265	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703		1127073
878	02/12/2021	953265	AIR CONDITIONING REPAIR	O293071 - repaired by cold drive - cammy Creditor #:#VB-COLO04 COLD DRIVE PTY LTD P/O #:#O293071 Receiving #:#306427 Date :2021-02-18 rectify a/c not working as required cleaned and painted over int graffiti removed bus number 1179 front door air hosefittingput back bus number is 878 ok CLOSE ROOF HATCHESRUN A/C 1 HOURCOULD NOT FAULT. complete complete closeboth roof hatchesroad testengine power okac cooling ok.	1127716
878	01/30/2021	950142	Vandalism Vandalism/ Graffiti Interior		1127716
878	01/25/2021	948892	Mechanic entered - Air System Other front door air leaks		1124576
878	01/22/2021	948591	Mechanic entered - A/C Heating Not Cooling		1122873
878	01/22/2021	948691	Removed N/S/F window COVID-19 & MYKI decals and reposition		1122873
878	01/19/2021	947798	Please fit A3 poster over COVID-19 poster and hangers to be		1122873
878	01/12/2021	945955	Mechanic entered - Engine Low Power and A/C not cooling .		1122405
878	01/06/2021	944876	Consumables		1121467
878	01/06/2021	944876	Consumables		1120464
878	01/06/2021	944876	Mechanic entered - Elec and Light Exterior Lights N/S Headli		1120464
878	01/04/2021	944339	Consumables		1120277
878	01/04/2021	944339	Consumables		1120051
878	01/04/2021	944339	Mechanic entered - Wheels and Tyres Wheel Nut Retension Ret		1120051
878	01/04/2021	944129	Consumables		1119864
878	01/04/2021	944344	Consumables		1120051
878	01/04/2021	944344	Consumables		1120051
878	01/04/2021	944129	Consumables		1120051
878	01/04/2021	944129	Elec and Light Flat Batteries		1120051
878	01/04/2021	944344	Mechanic entered - Elec and Light Flat Batteries book back	Jump started left all lights on for 20 mins and demistors , load tested batts . both batts holding above 12.5 volts. charging at 27.0 volts . could not fault chcked and found no faults aircon ok fit new slack adjusters.refit hubsand wheels.adjust brakesroad and brake testok. Creditor #:#VB-MUL004 MULTISPARES OAKLEIGH P/O #:#O290284 Receiving #:#303083 Date :2020-12-29 Creditor #:#VB-MUL004 MULTISPARES OAKLEIGH P/O #:#O290284 Receiving #:#302967 Date :2020-12-23 Creditor #:#VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:#O290232 Receiving #:#303029 Date :2020-12-24 machine/fit new linings and drums as required Checked king pins brake linnings all okay adjusted all brakes road test found o/s pulling replaced o/s/f wheel and remove both front brakes for maching	1119864
878	12/31/2020	943909	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703		1119864
878	12/31/2020	943909	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703		1119608
878	12/31/2020	942897	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7		1119608
878	12/29/2020	942897	BRAKE S CAM LHF SCANIA L94 (1		1119608
878	12/29/2020	942897	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route: 7	fitted s-cam bushes linings and slack adjusters. fitted wheels. road braketested ok.	1119608
878	12/29/2020	942897	SLACK ADJUSTER FRONT NEAR SIDE (1789568)		1119608
878	12/29/2020	942897	BRAKE S CAM RHF SCANIA L94		1119608
878	12/29/2020	942897	40g3802 Bush		1119608
878	12/23/2020	942897	SEAL BRAKE		1119608
878	12/23/2020	942897	DIRECT PURCHASE - BRAKES	Assisted by -JK FIT NEW FUEL FILTERCHANGH 2 RELAYSLONG ROAD TESTOK.	1119608
878	12/22/2020	942897	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route:		1119172
878	12/22/2020	942897	TYRE 295/80R22.5 NEW		1119172
878	12/22/2020	942897			1119172
878	12/21/2020	942509	Mechanic entered - Engine Other CUTS OUT.		1119172
878	12/21/2020	942509	FILTER FUEL FILTER SCANIA SR4 (1372444)	breakdown van attended breakdown CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list supply new rubber refit part check ok	1119172
878	12/21/2020	942509	RELAY 5 PIN CHANGE OVER 24V 10/20 AMP 68052		1119172
878	12/21/2020	942549	Ops Entered - Fault - Breakdown - Route: 703 - Kmart Black		1118400
878	12/19/2020	942391			1118400
878	12/15/2020	941270	Mechanic entered - Suspension Other Rear Sway Bar Link Bushe		1118400
878	12/15/2020	941270	BUSH RR SWAY BAR D AXLE SCANIA L94UAB 2156626 1477867	changed next stop button check ok	1118400
878	12/15/2020	941270	SWITCH INDICATOR SCANIA L94 1402448		1118400
878	12/15/2020	941270	Mechanic entered - Elec and Light Next Stop Button yellow st		1118400
878	12/15/2020	941270	SWITCH- STOP-YELLOW (62628)		1118400
878	12/15/2020	941270	Mechanic entered - Elec and Light Other rear emergency hatch		1118400

878	12/15/2020	941270	Mechanic entered - Elec and Light Other rear emergency door	supply new switch refit check tested ok	1118400
878	12/15/2020	941270	SWITCH EMERGENCY PUSH BUTTON RED HINO FD240 55CXX0282		1118400
878	12/15/2020	941270	Mechanic entered - Elec and Light Other indicator stalk not	supply new part carry out r/r check ok	1118400
878	12/15/2020	941270	Consumables		1118681
878	12/15/2020	941270	Mechanic entered - Body Other n/s/r passanger seat backing l	resecure seat backing check ok	1118400
878	12/15/2020	941270	Mechanic entered - Body Other passanger rear door grab handl	resecure grab handle check ok	1118400
878	12/15/2020	941270	Mechanic entered - Body Other front door grab handle had scr	remove grab handle refit new screw refit handle/ painted check ok	1118400
878	12/15/2020	941270	Mechanic entered - Body Other middle floor hatch was open an	retighten the lock and tab of hatch check ok	1118400
878	12/15/2020	941270	Consumables		1118681
878	12/14/2020	940998		VEHICLE SAFETY INSPECTION Carried out Safety Inspection ok	1118400
878	12/14/2020	940998		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1118400
878	12/14/2020	941059	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1118400
878	12/14/2020	941059	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	replaced Rear Sway Bar 'D' Rubbers checked ok	1118400
878	12/14/2020	941059	Mechanic entered - Elec and Light Interior Lights 1 x emerge	replaced emergency exit light with part on shelf already booked for bus. ok	1118400
878	12/14/2020	941059	Consumables		1118680
878	12/14/2020	941059	Mechanic entered - Body Other Rear No Smoking Decal missing	applied new decal from stock	1118400
878	12/14/2020	941059	Consumables		1118680
878	12/14/2020	941059	Mechanic entered - Air System Other n/s/r/r air bag need to	replaced Air Bag and checked ok	1118400
878	12/14/2020	941059	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		1118400
878	12/14/2020	941059	Mechanic entered - Air System Air_Leak Doors Air Leak Above	opened hatch found i airline to be leaking removed line and replaced with new hose re adjusted valve and checked for door opening and air leaks ok	1118400
878	12/09/2020	940346	Mechanic entered - Elec and Light Horn n/w	Replaced horn with new one	1118094
878	12/09/2020	940346	ELECTRIC DISC HORN 24V(ACX5118)		1118094
878	12/09/2020	940346	Consumables		1118094
878	12/05/2020	939544		TRANSMISSION CHECK AS PER CHECK LIST carry outtrans check.	1117184
878	12/05/2020	939835	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	1117184
878	12/04/2020	939434	Mechanic entered - Engine Other engine belt u/s	replaced engine belt ok	1117184
878	12/04/2020	939434	Mechanic entered - Engine Other engine belt tensioner u/s	replaced engine belt tensioner ok	1117184
878	12/04/2020	939434	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		1117184
878	12/04/2020	939434	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1117184
878	12/04/2020	939434	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok	1117184
878	12/04/2020	939434		re fittedaxlr and axle cap 1 stud for axle cap broken will require rebooking for replacement however bus is ok to go out again	1117184
878	12/04/2020	939448	FILLER CAP OIL (40A2806)		1117184
878	12/04/2020	939434	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		1117184
878	12/04/2020	939448	Mechanic entered - Engine Other engine oil cap pipe cut	removed 869 engine oil cap pipeput back 878 ok	1117184
878	12/04/2020	939448	OIL TUBE SCANIA L94UAB		1117184
878	12/04/2020	939448	STRAP (FOR FILLER CAP-1544036)		1117184
878	12/04/2020	939448	DIPSTICK ENGINE OIL SCANIA L94UAB 1515996 1479736		1117184
878	12/04/2020	939533	Mechanic entered - Elec and Light Exterior Lights N/S/F top	Replaced globe	1117184
878	12/04/2020	939533	Consumables		1117619
878	12/04/2020	939448	Mechanic entered - Body Other maked hone bracket ok	maked hone bracket ok	1117184
878	12/04/2020	939448	Consumables		1117619
878	12/04/2020	939400	Ops Entered - Fault - Breakdown - Route: 703 - Bentleigh S	O289037 - bus towed to oakleigh	1117184
878	12/04/2020	939400	DIRECT PURCHASE - TOWING	Creditor #:VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:O289037 Receiving #:302205 Date :2020-12-14 tow bus back to oakleigh . engine idler seized	1118666
878	12/01/2020	938403	Mechanic entered - A/C Heating Not Cooling	run a/c for 1hourcould not fault.	1116472
878	11/28/2020	937828	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	complete	1116138
878	11/18/2020	934635	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	complete	1114372
878	11/18/2020	934362	Remove old poster and fit you must wear a face mask when t	complete	1114372
878	11/14/2020	933415	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	1113902
878	11/09/2020	931519	Mechanic entered - Breakdown Not Starting flat battery	carry out jump start check ok	1112785
878	11/02/2020	930246	Ops Entered - Fault - CCTV Warning Light On - Route: - Ar	checked by Ashley BW electrics no faults found PO#: O286699	1111857
878	10/31/2020	930095	Fit new Myki Decals & refit COVID-19 decals new position f	complete	1111857
878	10/30/2020	929727		load tested batteries ok	1111857
878	10/26/2020	928383	Elec and Light flat batteries	jump started and re-book	1110880
878	10/26/2020	928383	Consumables		1111349
878	10/20/2020	925390	FITTING ELBOW		1110163
878	10/20/2020	927418	Mechanic entered - Elec and Light Flat Batteries	Jump Started Bus ok	1110163
878	10/20/2020	927418	Consumables		1110654
878	10/19/2020	927195		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST done.	1110163
878	10/19/2020	927195		SERVICE MOISTURE EJECTOR	1110163
878	10/14/2020	925390	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		1109692
878	10/14/2020	925694	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O285505 Receiving #:298037 Date :2020-10-15 replaced cracked o/s peep glass as required # 51255	1109936
878	10/13/2020	925911	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	fit etag	1109398
878	10/12/2020	925694	Mechanic entered - Accident Other bus was involved in accide	replaced side mirror assembly and side indicator straightened front corner bumper also. bus still requires corner glass to be replaced before returning to service	1109398
878	10/12/2020	925694	MIRROR R/H 380mm SHORT (UES1411D)		1109398
878	10/12/2020	925694	LIGHT SIDE INDICATOR L/H		1109398
878	10/10/2020	925388		VEHICLE SAFETY INSPECTION	1109398
878	10/10/2020	925388		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1109398
878	10/10/2020	925390	Mechanic entered - Suspension Other rear sway bar bush x 2 u	Removed U/S 'D' Rubbers replaced with new rubbers from stock.	1109398
878	10/01/2020	923282	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		1108107
878	10/01/2020	923282	Mechanic entered - Suspension Other front D-rubber u/s	supply new bushes carry out remove of old part refitted new bushes check ok	1108107
878	10/01/2020	923282	Mechanic entered - Fluid Leaks Rear of bus	carry out under carrige wash recommend inspect next service	1108107
878	10/01/2020	923210		CARRY OUT B SERVICE AS PER CHECK LIST carry out ser as per work order check tested ok	1108107
878	10/01/2020	923210	FILTER FUEL FILTER SCANIA SR4 (1372444)		1108107
878	10/01/2020	923210	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1108107
878	10/01/2020	923210	Oil Filter SCANIA S4 & K		1108107
878	10/01/2020	923210	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		1108107
878	10/01/2020	923210	OIL SAMPLE KIT CALTEX		1108107
878	10/01/2020	923210	Consumables		1108334
878	10/01/2020	923210	Consumables		1108334
878	09/28/2020	922629		complete	1107694
878	09/28/2020	922629		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1107694
878	09/25/2020	922267	Mechanic entered - Body Other rear step grip-strip loose	re glued down strip all ok	1107453
878	09/25/2020	922267	Consumables		1107694
878	08/22/2020	913841	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O281716 Receiving #:294378 Date :2020-08-24 Window Film Audit 418 completed 3/8/20 oakleigh	1101975
878	08/14/2020	913841	Vandalism Vandalism/ Graffiti Interior window film	Completed 3/8/20 refer email PB 13/8/20	1101252
878	08/11/2020	913087	Remove old A3 Poster and fit with You can no longer top up	carried out by fleet support	1100826
878	08/06/2020	911378		VEHICLE SAFETY INSPECTION Carried out safety inspection ok	1100157
878	08/06/2020	911378		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1100157
878	08/06/2020	911432	Mechanic entered - Wheels and Tyres Worn N/S/R/O Tyre 2mm re	Replaced both N/S/R Tyres outer tyre 2mm inner tyre 5mm changed to match.	1100157
878	08/06/2020	911432	TYRE 295/80R22.5 RECAP		1100157
878	08/06/2020	911432	Mechanic entered - Wheels and Tyres Worn N/S/F Tyre 3mm	Replaced N/S/F Tyre with New steer ok	1100157
878	08/06/2020	911432	TYRE 295/80R22.5 NEW		1100157
878	08/06/2020	912000	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Completed retension	1100157

878	08/06/2020	912000	Consumables			1100509
878	08/06/2020	911432	Consumables			1100509
878	08/06/2020	911432	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1100157
878	08/06/2020	911432	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483			1100157
878	08/06/2020	911432	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	Replaced Rear Sway Bar 'D' Bushes ok		1100157
878	08/06/2020	911432	Mechanic entered - Suspension Other Front Sway Bar 'D' Bushe	Replaced Front Sway bar 'D' Bushes ok		1100157
878	08/06/2020	911432	Mechanic entered - Body Other N/S Safety Tape Missing	replaced safety tape on N/S Front seat ok		1100157
878	08/06/2020	911432	Mechanic entered - Body Other Heater Hose Under Bus Retaini	No Retaining Brackets in stock Used cable ties to hold pipe in position in conjunction with other brackets along length of bus check next service or safety		1100157
878	08/06/2020	911432	Consumables			1100509
878	07/06/2020	904980	Mechanic entered - Elec and Light Other O/S headlight and pa	replaced both globes as required		1094777
878	07/06/2020	904980	Consumables			1095005
878	07/06/2020	904842	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O278857 Receiving #:291193 Date :2020-07-13 carry out 24 month service as required		1095776
878	07/06/2020	904842		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O278857		1094777
878	07/06/2020	904842		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O278857 - ajith		1094777
878	06/23/2020	895788	Direct Purchase - BODYWORK	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-O275888 Receiving #:289954 Date :2020-06-25 check and supply quote for int and ext body repairs and tidy up		1093105
878	06/23/2020	895788	Consumables			1092875
878	06/11/2020	900060		VEHICLE SAFETY INSPECTION - driver Rodney took the bus to seaford		1091022
878	06/11/2020	900060		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1091022
878	06/11/2020	900060		ANNUAL SAFETY INSPECTION SERIAL #K668704WORKSHOPSUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETYINSPECTIONLINE TIME ON THE W/O TO 0.25 done at seaford PO#: O277216		1091022
878	06/11/2020	900060	DIRECT PURCHASE - BUS INSPECTI	Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-O277216 Receiving #:289024 Date :2020-06-15 carry out asi as required at seaford		1091356
878	06/11/2020	900132	Mechanic entered - Engine Other won't start - flat batteries	load tested batteries after an overnight charge; both failed - replaced bothbatteries and checked charging 28.5v secured bin tray		1091022
878	06/11/2020	900132	BATTERY 12V 800CC			1091022
878	06/11/2020	900132	BATTERY 12V 800CC			1091022
878	06/10/2020	900141	Elec and Light - won't start	jump started in the morning and afternoon again. removed and chaged batteries. to be load tested		1091022
878	06/10/2020	900141	Consumables			1091022
878	06/10/2020	899842		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safety ins as per check list		1091022
878	06/09/2020	899256		PRE ANNUAL SAFETY INSPECTION CHECK done.		1090973
878	06/09/2020	899256		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1090973
878	06/09/2020	899421	Mechanic entered - A/C Heating Other a/c mount u/s.	r/r a/c mountsok.		1090973
878	06/09/2020	895788	Body - check and supply a quote for interior and exterior b	sent to body shop PO#: O275888		1090973
878	06/09/2020	899421	Consumables			1091022
878	06/09/2020	899421	Mechanic entered - Body Other missing screws for o/s/f cover	fixed panelok.		1090973
878	06/09/2020	899421	Mechanic entered - Body Other drivers door not secure.	make door stoperok.		1090973
878	06/09/2020	899421	Mechanic entered - Body Other noisy from inner top panel.	fixed panelok.		1090973
878	06/09/2020	899421	Mechanic entered - Body Other missing screws for n/s/r inner	fixed panelok.		1090973
878	06/09/2020	899421	MOUNT A/C COMPRESSOR SMALL DENSO			1090973
878	06/09/2020	899421	MOUNT A/C COMPRESSOR LARGE DENSO			1090973
878	06/09/2020	899421	Mechanic entered - Air System Air_Leak Rear leaking air from	fixed air hoseok.		1090973
878	06/09/2020	899414	Fit A3 Poster in poster frame and fit decals as requested i	carried out campaign as required		1090973
878	05/22/2020	843511	emergency exit light u/s - LED style			1090973
878	05/22/2020	843511	Consumables			1090973
878	05/19/2020	895085		VEHICLE SAFETY INSPECTION Carried out Safety inspection		1090585
878	05/19/2020	895085		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1090585
878	05/19/2020	895316	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	carried out re torque as required		1090585
878	05/19/2020	895316	Consumables			1090705
878	05/19/2020	895143	Mechanic entered - Suspension Other front/rear sway bar bush	Removed And replaced front and rear sway bar 'D' Bushes		1090585
878	05/19/2020	895143	LINK FRT SWAY BAR SCANIA L94 1766014 0463245 20486 01			1090585
878	05/19/2020	895143	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1090585
878	05/19/2020	843511	Mechanic entered - Elec and Light Exterior Lights N/S Revers	replaced N/S Reverse globe and checked ok		1090585
878	05/19/2020	895143	Mechanic entered - Brakes Other N/S/F Brake Booster Leaking	Removed Leaking Booster Disassembled booster replaced diaphragm reassembled and refitted to bus checked for air leaks ok		1090585
878	05/19/2020	895143	DIAPHRAGM TYPE 20 DEEP SCANIA 1303474			1090585
878	05/19/2020	895143	Mechanic entered - Brakes Other N/S/F Brake Booster Leaking	assisting		1090585
878	05/09/2020	893359	Mechanic entered - Engine Other Air Filter U/S	Replaced Air Filter		1088976
878	05/09/2020	893359	FILTER AIR FILTER (395773) AF25066			1088976
878	05/09/2020	893398	Mechanic entered - Elec and Light Interior Lights N/S/R Salo	replaced saloon light Fluro ok		1088976
878	05/09/2020	893398	Consumables			1089256
878	05/09/2020	893358		CARRY OUT B SERVICE AS PER CHECK LIST		1088976
878	05/09/2020	893358	Oil Filter SCANIA S4 & K			1088976
878	05/09/2020	893358	FILTER FUEL FILTER SCANIA SR4 (1372444)			1088976
878	05/09/2020	893358	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1088976
878	05/09/2020	893358	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1088976
878	05/09/2020	893358	Consumables			1089256
878	05/09/2020	893358	Consumables			1089256
878	05/02/2020	891889		TRANSMISSION CHECK AS PER CHECK LIST		1087400
878	05/01/2020	843511	LIGHT EMERGENCY EXIT WITH HA	Creditor #:-VB-CUS001 CUSTOM BUS CARE PTY LTD P/O #:-O258490-1 Receiving #:287892 Date :2020-05-28 (INVOICE 055355)		1090973
878	04/30/2020	891501	Mechanic entered - A/C Heating Other heater n/w.	r/r heater motorok.		1087286
878	04/30/2020	891501	PUMP WATER BOOST MOTOR			1087286
878	04/27/2020	890534	Direct Purchase - BODYWORK	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-O274023 Receiving #:285686 Date :2020-04-30 check and rectify rear door bottom plate		1087286
878	04/27/2020	890534	Consumables			1086800
878	04/25/2020	890534	Body rear door bottom us	done by Glenn PO#: O274023		1086420
878	04/23/2020	890178	Mechanic entered - Elec and Light Interior Lights rear emer	ordered on w/o - 843511		1086177
878	04/23/2020	890178	Consumables			1086420
878	04/22/2020	889842		PRE ANNUAL SAFETY INSPECTION CHECK done.		1086163
878	04/22/2020	889842		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1086163
878	04/22/2020	889950	Mechanic entered - Engine Belts_Loose Noisy Missing noisy fr	r/r pullysok.		1086163
878	04/22/2020	889950	Mechanic entered - Elec and Light Other n/s/f park light n/w	r/r globeok.		1086163
878	04/22/2020	889950	Consumables			1086177
878	04/22/2020	889950	Mechanic entered - Body Other noisy from n/s/r modesty panel	fixed modesty panelok.		1086163
878	04/22/2020	889950	Mechanic entered - Body Other pax luggage racks not secure.	fixed luggage racksok.		1086163
878	04/22/2020	889950	Mechanic entered - Body Other missing rear rubber strip.	fitted new rubber stripok.		1086163
878	04/22/2020	889950	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940			1086163
878	04/22/2020	889950	PULLEY IDLER SCANIA (1514087)			1086163
878	04/22/2020	889950	EDGE STEP EDGE INSERT YELLOW 40mm (2B10378SER)			1086163
878	04/22/2020	889950	Consumables			1086177
878	04/22/2020	889837		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LISTcarried out fire safe as per check list		1086163
878	04/21/2020	889699	Mechanic entered - Elec and Light Other N/S headlight not wo	replaced globe as required		1085901
878	04/21/2020	889697	Ops Entered - Fault - Dash Dash_Lights Not Working - Route:	replaced globes as required		1085901
878	04/21/2020	889697	Mechanic entered - Elec and Light Other speedo lights not wo	replaced globes as per defect no: 817392		1085901
878	04/21/2020	889699	Consumables			1086163
878	04/21/2020	889697	Consumables			1086163
878	04/20/2020	889198	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-O273490 Receiving #:284822 Date :2020-04-20 rectify air leak at front door as required		1085635
878	04/20/2020	889198	Consumables			1085901
878	04/18/2020	889169	Ops Entered - Fault - Elec and Light Interior Lights - Rout	could not fault.		1085460

878	04/18/2020	889169	Consumables			1085635
878	04/18/2020	889198	rectify air leak at front door as required	repaired by glen - O273490		1085460
878	04/17/2020	889065	Fault#:37533 - Ops Entered - Fault - Breakdown Overheating/	breakdown carried out by sungho . patched up coolant hose that was leaking . bought bus back to the depot for further repair by jordan		1085460
878	04/17/2020	889078	Mechanic entered - Fluid Leaks Other vehicle leaking coolant	found leaking hose from transmission replaced and tested ok		1085460
878	04/17/2020	889078	COOLANT HOSE (485995)			1085460
878	04/09/2020	886975	Direct Purchase - MECHANICAL	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O272958 Receiving #:284641 Date :2020-04-17 check and rectify frt door as required		1085460
878	04/09/2020	886975	Consumables			1084483
878	04/09/2020	887509	A4 notification to be printed off in colour laminated and	carried out campaign as required		1084225
878	04/08/2020	886975	Body frt door nw properly air leak	fixed by Glenn PO#: O272958		1084052
878	04/08/2020	887092	Drivers door impedes drivers seat controls	checked operation of drivers seat controls . could not fault		1084052
878	04/08/2020	887092	Consumables			1084225
878	04/08/2020	887091	Drv entered - Brakes Foot_Brakes Noisy	completed on w/o - 884992		1084052
878	04/06/2020	875162	WATER PUMP SCANIA L94UAB (40A4394)			1083791
878	04/06/2020	875162	WATER PUMP SCANIA L94 UAB 1510490 0570961			1083791
878	03/31/2020	884992	Mechanic entered - Brakes Other front brakes noisy.	fit brake linings and wheels.		1082830
878	03/31/2020	884992	Mechanic entered - Brakes Other front brakes noisy.	Fitted new hub washer and nut both sides adjusted brakes and road tested		1082830
878	03/30/2020	884992	Mechanic entered - Brakes Other front brakes noisy.	remove wheels and hubslinings for machining. PO#: O272197		1082830
878	03/30/2020	884992	WASHER WHEEL HUB LOCK FRONT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O272229 Receiving #:283703 Date :2020-04-02		1083323
878	03/30/2020	884992	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O272197 Receiving #:283704 Date :2020-04-02 REPAIR FRT BRAKES AS REQUIRED		1083323
878	03/30/2020	884992	HUB LOCK NUT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O272229 Receiving #:283703 Date :2020-04-02		1083323
878	03/30/2020	884992	Consumables			1083071
878	03/30/2020	884992	Consumables			1083071
878	03/30/2020	884992	Consumables			1083071
878	03/28/2020	884949	Vandalism interior graffiti	cleaned and painted over interior graffiti		1082830
878	03/24/2020	883561	Mechanic entered - Body Other N/S mirror arm loose due to hi	Tighten arm bolts and adjust mirror		1082136
878	03/24/2020	883561	Consumables			1082378
878	03/24/2020	883348	Tape off front Seats of All Route and Rail Buses with spec	carried out campaign as required		1082136
878	03/19/2020	881341		VEHICLE SAFETY INSPECTION carried out safety inspection		1081376
878	03/19/2020	881341		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1081376
878	03/19/2020	881417	Vandalism passenger seats cut	replaced all cut seats with re trimmed seats		1081376
878	03/19/2020	881417	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUTO05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O271378 Receiving #:282317 Date :2020-03-19 x 2 skins and x 6 seat bases		1081603
878	03/19/2020	881417	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	Replaced rear sway bar 'D' Bushes		1081376
878	03/19/2020	881417	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483			1081376
878	03/19/2020	881417	Mechanic entered - Elec and Light Interior Lights Speedo Lig	replaced Speedo globes ok		1081376
878	03/19/2020	881417	Mechanic entered - Elec and Light Interior Lights 3x Saloon	replaced 3x saloon fluors ok		1081376
878	03/19/2020	881417	Consumables			1081603
878	03/19/2020	881417	Mechanic entered - Body Other Rear Step inside bus missing s	Cut safety strip to size and shape and glued into position ok		1081376
878	03/19/2020	881417	Consumables			1081603
878	03/13/2020	880392	Mechanic entered - Elec and Light Other horn not working	replaced horn with one from 869		1080649
878	03/13/2020	880392	Consumables			1080911
878	02/28/2020	877586		complete		1077996
878	02/28/2020	877586		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1077996
878	02/18/2020	875162	Mechanic entered - Fluid Leaks Rear of bus coolant leak	Checked for coolant leak and found water pump leaking drain coolant and replaced water pump top up coolant wash and road test Repl;aced header tank too		1076178
878	02/18/2020	875162	WATER PUMP SCANIA L94UAB (40A4394)			1076178
878	02/18/2020	875162	EXPANSION TANK C/FILL 1731694/1896287			1076178
878	02/14/2020	874278	Mechanic entered - A/C Heating Belt Loose or_Missing loose.	tighten a/c belts.		1075732
878	02/10/2020	872856	Mechanic entered - Elec and Light Flat Batteries	JUMP START.		1074524
878	02/10/2020	872856	Consumables			1075007
878	02/03/2020	871381	SWITCH DOOR CONTACT (NORMALLY OPEN)			1073663
878	02/03/2020	871381	Mechanic entered - Body Front_Door Operation Faulty Wont clo	Checked front door wont close removed and changed switch		1073663
878	02/03/2020	871381	Consumables			1073815
878	01/30/2020	870321	Mechanic entered - Elec and Light Indicators Not Working das	fit globe.		1073063
878	01/30/2020	869804	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O267493 Receiving #:278350 Date :2020-01-30 rectify air leak at front door as required - glen		1073137
878	01/30/2020	869804	Consumables			1073401
878	01/30/2020	870321	Consumables			1073401
878	01/29/2020	869804	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:O267494 Receiving #:278404 Date :2020-01-31 purchase x 2 door regulators . valve fittings and 1 filter as required		1073401
878	01/27/2020	869804	Elec and Light door brakes nw and air leaking at front	repaired by glen - O267493		1073063
878	01/23/2020	869328	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	carried out campaign as required		1072485
878	01/22/2020	868929		VEHICLE SAFETY INSPECTION Carried out Safety Inspection		1072485
878	01/22/2020	868929		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1072485
878	01/22/2020	868929		Assisting		1072485
878	01/22/2020	868980	Mechanic entered - Fluid Leaks Rear of bus Coolant Leak From	Adjusted hose clamp on hose And refilled header tank		1072485
878	01/22/2020	868980	Mechanic entered - Dash Dash_Lights Not Working	Removed cluster and checked dash lights Poor Earth connection Cleaned globe holes and globe contacts ok		1072485
878	01/22/2020	868980	Mechanic entered - Elec and Light Exterior Lights Centre Roo	Loose Connection Adjusted connection ok		1072485
878	01/22/2020	868980	Consumables			1072485
878	01/22/2020	868980	Mechanic entered - Body Other Centre Modesty Panel Loose	Drilled modesty panel and added screws ok		1072485
878	01/22/2020	868980	Mechanic entered - Body Other N/S/R Pax Switch missing screw	Replaced screw and tightened pax switch ok		1072485
878	01/22/2020	868980	Consumables			1072485
878	01/11/2020	866490	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1069953
878	01/11/2020	866490		CARRY OUT B SERVICE AS PER CHECK LIST Carried Out B Service and Trans Service ok		1069953
878	01/11/2020	866490	FILTER FUEL FILTER SCANIA SR4 (1372444)			1069953
878	01/11/2020	866490	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1069953
878	01/11/2020	866490	Oil Filter SCANIA S4 & K			1069953
878	01/11/2020	866490	Consumables			1070220
878	01/11/2020	866490	Consumables			1070220
878	01/11/2020	866490	Consumables			1070220
878	01/06/2020	865352	Mechanic entered - Elec and Light Exterior Lights O/SF head	Replaced both the globes		1068684
878	01/06/2020	865352	Consumables			1069237
878	12/07/2019	860155	A3 Poster Frame Adhesive Decal Campaign please remove old	complete		1064302
878	12/06/2019	859817		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1064302
878	12/06/2019	859817		completed		1064302
878	12/03/2019	858646	Mechanic entered - Suspension Other both front top torque r	R&R front upper torque rod bushes		1063818
878	12/03/2019	858646	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)			1063818
878	12/03/2019	858646	Mechanic entered - Engine Other front o/s engine mount crack	R&R engine mount		1063818
878	12/03/2019	858646	MOUNT ENGINE SCANIA 1475868			1063818
878	12/02/2019	858375	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S	carried out retorque as required		1063576
878	12/02/2019	858375	Consumables			1063818
878	11/28/2019	857523		VEHICLE SAFETY INSPECTION		1063149
878	11/28/2019	857523		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1063149
878	11/28/2019	857618	Mechanic entered - Wheels and Tyres Other OFFSIDE REAR TYRE	replaced O/S/R TYRESX2		1063149
878	11/28/2019	857618	TYRE 295/80R22.5 RECAP			1063149
878	11/28/2019	857618	Consumables			1063385
878	11/28/2019	857655	Mechanic entered - Elec and Light Other DASH R.P.M light not	replaced dash R.P.M light globe ok		1063149

878	11/28/2019	857655	Mechanic entered - Elec and Light Other INDICATOR SWITCH U/S	replaced indicator switch ok	1063149
878	11/28/2019	857655	INDICATOR STALK SCANIA SERIES 4 (1402448)		1063149
878	11/28/2019	857655	Mechanic entered - Elec and Light Other front step light not	replaced front step light globe ok	1063149
878	11/28/2019	857655	Consumables		1063385
878	11/28/2019	857655	Mechanic entered - Body Other rear staunchion pole loose	repaired rear staunchion pole ok	1063149
878	11/28/2019	857655	Mechanic entered - Body Other n/s/r outer hammer decal missi	replaced n/s/r outer hammer decal ok	1063149
878	11/28/2019	857655	Mechanic entered - Body Other rear door handle loose	tightened rear door handle ok	1063149
878	11/28/2019	857655	Mechanic entered - Body Other bus inside o/s top panel loose	repaired bus inside o/s top panel loose	1063149
878	11/28/2019	857655	Consumables		1063385
878	11/25/2019	856924	Mechanic entered - Body Drivers Seat Leaning Back rest not s	Fixed up the backrest locking mechanism	1062679
878	11/25/2019	856924	Consumables		1062905
878	11/18/2019	855254		instructed to close of cctv services as per instruction from fleet	1060865
878	11/18/2019	855254		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1060865
878	11/11/2019	853871	Mechanic entered - A/C Heating Belt Loose or_Missing	Adjusted a/c beltsas they were squeeking	1059890
878	11/04/2019	852621	Mechanic entered - Air System Other Air leak from drivers se	Removed seat cushion cut hose and fit back to joiner	1059243
878	11/01/2019	851900	BELT V-BELT COGGED TRI-POWER 17x2110mm		1058732
878	11/01/2019	851900	Mechanic entered - A/C Heating Belt Loose or_Missing	fit 2 new belts.	1058732
878	10/29/2019	851032		TRANSMISSION CHECK AS PER CHECK LIST	1058410
878	10/29/2019	851032		carried out trans check	1058410
878	10/16/2019	848382	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	sent to volgren PO 00260310	1057188
878	10/15/2019	841549	Consumables		1057188
878	10/15/2019	841549	Direct Purchase - BODYWORK	Creditor #:VB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:O258488 Receiving #:270176 Date :2019-10-17 rectify drivers seat lumber support not working	1057188
878	10/11/2019	847425	Consumables		1056818
878	10/11/2019	847425	Mechanic entered - Body Front_Door Operation Faulty NOT OPEN	RECONNECT WIRE TO DOOR SWITCH.	1056467
878	10/10/2019	847269	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWEE001 BWERE ELECTRICS PTY LTD P/O #:O259842 Receiving #:271129 Date :2019-10-28 carry out cctv 6-monthe service as required	1058145
878	10/10/2019	847269	CCTV 6months service	done by BW electrics - Johnny PO 0259842	1056467
878	10/09/2019	847122	Consumables		1056467
878	10/09/2019	847122	front door fault	traced and found top pivot bolt loose . tightend and adjusted . checked operation of front and rear door brakes . working all okay	1056241
878	10/03/2019	845619	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		1055069
878	10/03/2019	845619	Mechanic entered - Suspension Other both front D rubber u/	Replaced Sway Bar 'D' Rubbers	1055069
878	09/24/2019	843533	PIVOT SINGLE (SWF 83) OUT BOAR	Creditor #:VB-AGM001 AGMAT AGENCIES P/O #:O258492 Receiving #:268163 Date :2019-09-24	1054182
878	09/23/2019	843952	Mechanic entered - Engine Other flat batteries	Jump started bus . checked charge rate all okay	1053550
878	09/21/2019	843692	Mechanic entered - Wipers and Washers Other n/s wiper pivot	replaced wiper pivot ok	1053550
878	09/20/2019	843533	MOUNT A/C COMPRESSOR LARGE DENSO		1053550
878	09/20/2019	843533	Mechanic entered - A/C Heating Other A/C Compressor Front Mo	Replaced A/C Mount X2	1053550
878	09/20/2019	843191	Consumables		1053736
878	09/20/2019	843191	Mechanic entered - Elec and Light Other o/s/f indicator line	repaired o/s/f indicator lines ok	1053550
878	09/20/2019	843191	Mechanic entered - Elec and Light Other n/s head light u/s	replaced n/s head light ok	1053550
878	09/20/2019	843191	LAMP HEADLAMP MK3 VOLVO B10M		1053550
878	09/20/2019	843191	Consumables		1053736
878	09/20/2019	843191	Mechanic entered - Body Other n/s/r hmmer decal missing	replaced n/s/r hammer decal ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other n/s/f inside bottom panel loos	tightened n/s/f inside bottom ponel bolts ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other middle seat base cut	repaired middle seat base ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other rear smoking decal missing	replaced rear smoking decal ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other rear modesty panel loose	repaired rear modesty panel ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other driver seat belt buckle missin	replaced driver seat belt buckle ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other n/s/f staunchion pole loose	repaired n/s/f staunchion pole ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other air dryer bracket bolt broken	welding from to the air dryer bracket ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other both front wheel arch rubber m	replaced both front wheel arch rubber ok	1053550
878	09/20/2019	843191	Mechanic entered - Body Other driver buckle seat belt u/s	ok	1053550
878	09/19/2019	843155		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1053550
878	09/19/2019	843155		VEHICLE SAFETY INSPECTION	1053550
878	09/19/2019	843191	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		1053550
878	09/18/2019	841549	Consumables		1053681
878	09/18/2019	843116	Consumables		1053681
878	09/18/2019	843116	Ops Entered - Fault - Body Drivers Seat Leaning - Route: -	Adjusted the lock and fitted a rubber stopper	1053550
878	09/18/2019	841549	Mechanic entered - Body Drivers Seat Controls Lumber adjustm	Replaced complete seat assy as joiners were leaking and keeps coming off	1053550
878	09/16/2019	841549	Consumables		1053309
878	09/16/2019	841549	SWITCH- STOP-YELLOW (62628)		1052684
878	09/16/2019	841549	Mechanic entered - Elec and Light Next Stop Button Button da	Replaced damage next stop switch behind rear door	1052684
878	09/12/2019	841549	PLUG MAGNETIC (2165310)		1052684
878	09/12/2019	841549	MOUNT EXHAUST RUBBER VOLVO (6850149-3) (6850149)		1052684
878	09/11/2019	841549	Mechanic entered - Fluid Leaks Rear of bus Engine Minor Oil	order bell housing gasketrear crank sealrear cam shaft cover gasket please	1052275
878	09/11/2019	841780	Consumables		1052684
878	09/11/2019	841780	Mechanic entered - Body Other Drivers seat squeeking and a	Lubricate seat base bushes and pedal bushes	1052275
878	09/04/2019	840237	Mechanic entered - Air System Air_Leak Interior Air leak fro	Repaired air hose under drivers seat	1051406
878	09/04/2019	840224	Accident #46486 - Minor Dent and paint Damage near the fron	CLOSED OFF BY MICHAEL RUSSEL . NO DAMAGE	1051406
878	09/04/2019	840223	Accident # 47018 - 3 rd party - Dent near front door and n	CLOSED OFF BY MICHAEL RUSSEL . NO DAMAGE	1051406
878	08/31/2019	837697	Mechanic entered - Air System Air_Leak Rear Compressor Relie	replaced relief valve	1050690
878	08/28/2019	837697	40G0304 A/C Relief Valve	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O256495 Receiving #:265954 Date :2019-08-29	1050465
878	08/26/2019	837831	BUSH SHOCK ABSORBER		1049651
878	08/26/2019	837831	Mechanic entered - Suspension Other Front Lower Shock Rubber		1049651
878	08/26/2019	837697	Mechanic entered - Suspension Other Rear Sway Bar 'D' Bushes	Replaced Rear Sway Bar 'D' Bushes	1049651
878	08/26/2019	837697	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		1049651
878	08/26/2019	837831	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Tightened Hose clamp Monitor	1049651
878	08/26/2019	837831	Consumables		1049977
878	08/26/2019	837831	Mechanic entered - Elec and Light Interior Lights Speedo Das	Replaced Dash Light	1049651
878	08/26/2019	837831	LIGHT SIDE INDICATOR L/H		1049651
878	08/26/2019	837831	Mechanic entered - Elec and Light Exterior Lights O/S/F Indi	replaced O/S/F Indicator assembly	1049651
878	08/26/2019	837831	Consumables		1049977
878	08/26/2019	837697	Consumables		1049977
878	08/26/2019	837831	Mechanic entered - Body Other O/S/F side Mirror Loose	Tightened Mirror	1049651
878	08/26/2019	837697	Mechanic entered - Body Other Drivers Seat Air Leak	Leaking From Joiner Replaced Joiner ok	1049651
878	08/26/2019	837697	Mechanic entered - Body Other O/S Disabled seat top pins out	Re seasted Top Pins	1049651
878	08/26/2019	837697	SLACK ADJUSTERAUTO-REAR N/SIDE (2009819) SERIES 4		1049651
878	08/26/2019	837697	Mechanic entered - Brakes Other N/S/R Slack Adjuster U/S	Replaced N/S/R Slack Adjuster and adjusted	1049651
878	08/26/2019	837697	SAFETY VALVE 14.3 bar		1049651
878	08/26/2019	837697	compressor safety valve u/s	double entry	1049651
878	08/26/2019	837606	Consumables		1049977
878	08/26/2019	837606	Consumables		1049977
878	08/26/2019	837606	Consumables		1049977
878	08/26/2019	837606	Oil Filter SCANIA S4 & K		1049651
878	08/26/2019	837606	FILTER FUEL FILTER SCANIA SR4 (1372444)		1049651

878	08/26/2019	837606	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1049651
878	08/26/2019	837606		CARRY OUT B SERVICE AS PER CHECK LIST	Carried Out B Service	1049651
878	08/26/2019	837606	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1049651
878	08/20/2019	836413	Consumables			1049213
878	08/20/2019	836413	REAR POSITION STOP LAMP LED (DESIGNLINE)			1048904
878	08/20/2019	836413	Mechanic entered - Elec and Light Exterior Lights N/S/R/T PA	WIRE IN NEW LED LIGHT.		1048904
878	08/17/2019	836844	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting		1048420
878	08/17/2019	836018	Engine belt u/s	Replaced main engine belt and tensioner		1048420
878	08/17/2019	836018	BELT TENSIONER SCANIA N310UA 2197005 1859657			1048420
878	08/17/2019	836018	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG			1048420
878	08/14/2019	835449	Consumables			1048228
878	08/14/2019	835449	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension nsr		1047963
878	08/13/2019	835186	Consumables			1047963
878	08/13/2019	835186	TYRE 295/80R22.5 RECAP			1047719
878	08/13/2019	835186	Mechanic entered - Wheels and Tyres Worn Pos 3 and pos 4 ty	Replaced both worn tyres with new retreads		1047719
878	08/09/2019	834402	Consumables			1047491
878	08/09/2019	834402	Body - DRIVER SEAT LOOSING AIR - BY REFUELLERS	could not fault.		1047016
878	08/05/2019	833322	Mechanic entered - Air System Other Drivers Seat Blown air l	Cut line added in air line joiner and tested ok		1046385
878	07/25/2019	830928	DIRECT PURCHASE GLASS	Creditor #:-VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:-O253800 Receiving #:263114 Date :2019-07-30 alpha glass to replaced o/s peep glass as required		1045351
878	07/24/2019	830928	MIRROR L/H 380mm SHORT (UES1411E)			1044746
878	07/24/2019	830928	LIGHT SIDE INDICATOR L/H			1044746
878	07/24/2019	830928	Service	replaced smashed mirror and replaced o/s indicator		1044746
878	07/24/2019	830928	Accident # 49319 - 3rd party at fault - o/s/f damage	o/s peep glass replaced by alpha - O253800		1044746
878	07/23/2019	830479	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O253599 Receiving #:263539 Date :2019-08-01 carry out AC-A service as required - quote if required		1045869
878	07/23/2019	830479		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - done by Cold Drive PO#:-O253599 shaft seal and pulley bearing done too		1044746
878	07/22/2019	830266		VEHICLE SAFETY INSPECTION done.		1044250
878	07/22/2019	830266		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1044250
878	07/22/2019	830266	Consumables			1044746
878	07/22/2019	830266	Wheels and Tyres - n/s/r inner tyre u.s	could not fault.		1044250
878	07/22/2019	830346	Mechanic entered - Suspension Other n/s/f air bag u/s.	r/r air bagok.		1044250
878	07/22/2019	830346	Mechanic entered - Engine Other engine belt pulls u/s.	r/r pullysok.		1044250
878	07/22/2019	830346	Consumables			1044746
878	07/22/2019	830346	AIRBAG O/S/F SCANIA K230UB (2024284)			1044250
878	07/22/2019	830346	PULLEY IDLER SCANIA (1514087)			1044250
878	07/22/2019	830346	SWITCH- STOP-YELLOW (62628)			1044250
878	07/22/2019	830346	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)			1044250
878	07/22/2019	830346	Mechanic entered - Elec and Light Next Stop Button pax stop	r/r stop bell switchok.		1044250
878	07/22/2019	830346	Mechanic entered - Elec and Light Exterior Lights rear door	r/r globeok.		1044250
878	07/18/2019	829169	Consumables			1044005
878	07/18/2019	829169	MiscParts	Creditor #:-VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-O253121 Receiving #:262390 Date :2019-07-22		1044005
878	07/18/2019	829169	Direct Purchase - BODYWORK	Creditor #:-VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-O253121 Receiving #:262390 Date :2019-07-22 refoam drivers seat base x 1 as required		1044005
878	07/17/2019	829489	Consumables			1043759
878	07/17/2019	829489	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced h4 globe		1043493
878	07/17/2019	829489	Consumables			1043759
878	07/17/2019	829489	Mechanic entered - Body Other O/S/F passenger seat smells of	Removed seat cushion fitted one from 879 and wash the smelling cushions		1043493
878	07/16/2019	829012		Creditor #:-VB-ENZED ENZED MOORABBIN P/O #:-O253039 Receiving #:262920 Date :2019-07-26 enzed to make main compressor line as per sample		1044746
878	07/16/2019	829012	DIRECT PURCHASE - TOWING	Creditor #:-VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:-O252989 Receiving #:262914 Date :2019-07-26 tow bus back to oakleigh for fault of loosing air b/d number - # 36732		1044746
878	07/16/2019	829012	Fault#:36732 - Ops Entered - Fault - Breakdown Air System F	put axle back in . traced and found main air compressor pipe olive and pipe leaking bad . enzed jaimie came and made a new air hose . he installed the air hose . checked operation of building up or air . all okay		1043449
878	07/16/2019	829012	Consumables			1043493
878	07/16/2019	829012	Mechanic entered - Body Front_Door Operation Faulty	Checked for door brake switch as bus was towed in today switch on and off and works ok		1043449
878	07/16/2019	829169	Mechanic entered - Body Drivers Seat Cover Smelling of piss	Replaced seat cushion		1043449
878	07/08/2019	827405	Consumables			1042055
878	07/08/2019	827405	battery master not working	lubricated battery master . checked operation 15 times . all okay		1041827
878	07/02/2019	826299	Consumables			1040866
878	07/02/2019	826299	bus minder stand broken bus minder not charging more then	relocated busminder using a fabricated bracket. checked charging ok		1040711
878	06/06/2019	821682	Fault#:36618 - Ops Entered - Fault - Breakdown Not Starting	As was about to leave the w/shop breakdown was cancelled		1035954
878	05/31/2019	809893		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1034788
878	05/30/2019	820191	Consumables			1034788
878	05/30/2019	820191	Drv entered - BusMinder Damaged	double entry		1034544
878	05/30/2019	820191	Consumables			1034788
878	05/25/2019	818831	Fault#:36567 - Ops Entered - Fault - Breakdown Air System Fa	fitted pipe brackets back fill up coolant repaired leaking pipe fitted axle back wash and brake test		1033712
878	05/25/2019	818831	Mechanic entered - Elec and Light Interior Lights N/S/R flur	Replaced fluro		1033712
878	05/25/2019	818831	Consumables			1033843
878	05/25/2019	818831	Consumables			1033843
878	05/24/2019	818831	Fault#:36567 - Ops Entered - Fault - Breakdown Air System Fa	Drained coolant removed air compressor fitted all fittings and gear to new compressor and fit back connect all hoses and pipes		1033712
878	05/24/2019	818831	BOLT COMPRESSOR GEAR			1033712
878	05/24/2019	818831	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1871043 1376911			1033712
878	05/24/2019	818831	SEAL O-RING COMPRESSOR MOUNT SCANIA L94 (323790)			1033712
878	05/24/2019	818831	AIR COMPRESSOR RR DRIVE			1033712
878	05/23/2019	818831	DIRECT PURCHASE - TOWING	Creditor #:-VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:O248803 Receiving #:257960 Date :2019-05-31 tow bus back to oakleigh not building up air		1034788
878	05/21/2019	809893		VEHICLE SAFETY INSPECTION		1033177
878	05/21/2019	809893		ANNUAL SAFETY INSPECTION SERIAL # _____J_815109_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1033177
878	05/12/2019	815284	Please remove all old poster and fit MYKI has gone mobil	fleet support completed this campaign		1030820
878	05/09/2019	809893	DIRECT PURCHASE - BUS INSPECTI	Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-O247581 Receiving #:256175 Date :2019-05-13		1031640
878	05/09/2019	815647	SPR.BR.CYL R/R L94 N/S/R (35CLE0010)			1030820
878	05/09/2019	815647	Mechanic entered - Brakes Other n/s/r brake booster u/s	replaced n/s/r brake booster ok - brake test was carried out on RSI inspection		1030820
878	05/09/2019	815029	Consumables			1031236
878	05/09/2019	815029	Consumables			1031236
878	05/09/2019	815029	Consumables			1031236
878	05/09/2019	815029	HEADER TANK FILLER CAP 1403954			1030820
878	05/09/2019	815029	RELAY FLASHER SCANIA L94+K124 (1401789)(4DN-007-431-021)			1030820
878	05/09/2019	815029	Consumables			1031236
878	05/09/2019	815029	Consumables			1031236
878	05/09/2019	815029	Consumables			1031236
878	05/08/2019	815349	AIRBAG O/S/F SCANIA K230UB (2024284)			1030820
878	05/08/2019	815349	Mechanic entered - Suspension Other n/s/f air bag u/s	replaced n/s/f air bag ok		1030820
878	05/08/2019	815349	AIRBAG REAR SCANIA K310 (2024290)			1030820
878	05/08/2019	815349	Mechanic entered - Suspension Other o/s/r/r air bag u/s	replaced o/s/r/r air bag ok		1030820
878	05/08/2019	815349	Mechanic entered - Steering Other steering wheel loose	repaired steering wheel ok		1030820
878	05/08/2019	815349	Consumables			1031065
878	05/08/2019	815349	Consumables			1031065
878	05/08/2019	815349	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok		1030820
878	05/08/2019	815349	Mechanic entered - Elec and Light Other n/s/f school light n	replaced school light globe ok		1030820

878	05/08/2019	815349	Consumables			1031065
878	05/08/2019	815349	Consumables			1031065
878	05/08/2019	815349	Mechanic entered - Body Other middle seat top pins out	put in middle seat pins ok		1030820
878	05/08/2019	815349	Mechanic entered - Body Other bus inside top n/so/s screws	tightened bus inside n/so/s top screws ok		1030820
878	05/08/2019	815029		CARRY OUT C SERVICE AS PER CHECK LIST		1030820
878	05/08/2019	815029	Oil Filter SC S4 & K			1030820
878	05/08/2019	815029	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1030820
878	05/08/2019	815029	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1030820
878	05/08/2019	815029	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)			1030820
878	05/08/2019	815029	FILTER FUEL FILTER SCANIA SR4 (1372444)			1030820
878	05/08/2019	815029	FILTER FUEL FILTER SCANIA SR4 (1393640)			1030820
878	05/08/2019	815029	FILTER HYD COOLING FAN SCANIA L94UAB 1354074			1030820
878	05/08/2019	815029	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)			1030820
878	05/08/2019	815029	FILTER AIR FILTER (395773) AF25066			1030820
878	05/08/2019	815029	Consumables			1031065
878	05/08/2019	815029	Consumables			1031065
878	05/08/2019	815029	Consumables			1031065
878	05/08/2019	815029	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST		1030820
878	05/08/2019	815029	Consumables			1031065
878	05/08/2019	815029	Consumables			1031065
878	05/08/2019	815029	Consumables			1031065
878	05/07/2019	814753	Air System Air_Leak Interior from under seat.	done by lee on 03/05/2019 wo814137		1030820
878	05/04/2019	812814		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1029651
878	05/04/2019	812814		completed		1029651
878	05/03/2019	814137	Consumables			1030590
878	05/03/2019	814137	FITTING JOINER BRASS 4-6mm			1030343
878	05/03/2019	814137	Mechanic entered - Body Other leaking air from drivers seat.	fixed drivers seat for air leakok.		1030343
878	05/03/2019	814137	Consumables			1030590
878	04/26/2019	812170	Brakes slack adjuster us	replaced slack adjuster on wo812006.		1029048
878	04/26/2019	812170	SLACK ADJUSTER AUTO-REAR O/SIDE (2009820) SERIES 4			1029048
878	04/26/2019	812006	SLACK ADJUSTER AUTO-REAR O/SIDE (2009820) SERIES 4			1029048
878	04/26/2019	812006	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s	checked frontrear brakefound o/s/r brake slack adjust replaced o/s/r brake slack adjustroad tested ok		1029048
878	04/23/2019	811715		TRANSMISSION CHECK AS PER CHECK LIST Carried out transmission check. ok.		1028726
878	04/22/2019	811491	Consumables			1028726
878	04/22/2019	811491	o/s headlight not working	R&R headlight checked operation all okay		1028045
878	04/21/2019	811451	Consumables			1028576
878	04/21/2019	811451	o/s/r top blinker not working	R&R o/s/r top LED . checked operation all okay		1028045
878	04/18/2019	811180	CCTV 6-months service	done by Johnny on 17/04/2019 PO#: O246165		1028045
878	04/17/2019	811180	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWEO01 BWERE ELECTRICS PTY LTD P/O #:O246165 Receiving #:254644 Date :2019-04-24 carry out cctv serice/repair as required		1029048
878	04/13/2019	810191	Mechanic entered - Steering Shakes/ Wobbles	road testslight shake under brakesok to use.		1026903
878	04/11/2019	809893		carried out pre rsi inspsectron		1026536
878	04/10/2019	809454	DECAL BREAK GLASS IN EMERGENCY HAMMER RED/CLEAR 120mm SQ			1026286
878	04/10/2019	809454	EMERGENCY HAMMER COMPLETE WITH CRADLE 274-0044			1026286
878	04/10/2019	809454	REVERSE ALARM 12-24v 72608			1026286
878	04/10/2019	809454		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1026286
878	04/10/2019	809454		VEHICLE SAFETY INSPECTION		1026286
878	04/10/2019	809454		PRE ANNUAL SAFETY INSPECTION CHECK		1026286
878	04/01/2019	806288	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O244328 Receiving #:253465 Date :2019-04-08		1026286
878	03/29/2019	807117		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list		1024882
878	03/26/2019	806288	Vandalism glass film to be replaced x 8	glass film replaced by glass protect on p/o - o244328		1024149
878	03/24/2019	805775	Consumables			1023921
878	03/24/2019	805775	Mechanic entered - Elec and Light Exterior Lights	Replaced n/s/f top park light globe		1023396
878	03/12/2019	803144	Accident#:47018 - Dent near front door and near side indic	replaced indicator lens with good 2nd hand . removed scuff mark with cutters .		1021657
878	03/02/2019	801306	Consumables			1020518
878	03/02/2019	801306	Mechanic entered - Body Passenger Seat Torn	seat back removedrefit to seat ok.		1020253
878	02/26/2019	800302	LIGHT SIDE INDICATOR L/H			1019294
878	02/26/2019	800302	Mechanic entered - Elec and Light Exterior Lights n/s/f indi	fit new blinker assembly.		1019294
878	02/22/2019	799528	Consumables			1019294
878	02/22/2019	799528	Wheel Nut Retension both frt 1018723km	retorque all front and rear wheel nuts.		1018723
878	02/20/2019	799186	TYRE 295/80R22.5 NEW			1018723
878	02/20/2019	799186	Steering Shakes/ Wobbles			1018723
878	02/20/2019	799186	SLACK ADJUSTER FRONT NEAR SIDE (1789568)	replaced both frt tyres and kept the old in runout stock. tensioned the wheel nuts.		1018723
878	02/20/2019	799186	The front of the bus shuttering under braking	double entry		1018723
878	02/20/2019	799186	Brakes Foot_Brakes Pulling	replaced n/s/f slack adjustor		1018723
878	02/20/2019	799186	retarder not working	turned on switch checked operation all okay		1018723
878	02/20/2019	799186	dash light not globes not working	replaced speedo dash light globe x 2 checked operation all okay		1018723
878	02/14/2019	796706	DIRECT PURCHASE - STEERING	Creditor #:VB-AIR001 AIR ANYWHERE P/O #:O240979 Receiving #:249535 Date :2019-02-18 carry out wheel alignment and balance as required		1018438
878	02/12/2019	796706	Drv entered - Brakes Foot_Brakes Pulling	installed linings drums and hubs . adjusted brakes . road tested and brake tested all okay		1017374
878	02/11/2019	796706	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O240809 Receiving #:249314 Date :2019-02-14 radius grind brakes and machine drums as required		1017964
878	02/09/2019	796706	Drv entered - Steering Pulling	pulling to right when brake.		1017374
878	02/09/2019	796706	Drv entered - Steering Shakes/ Wobbles	steering wobbles at or above 60ks. adjusted all brakes nsf slack adjuster too loose. need attention on frt brakes and slack adjuster		1017374
878	02/09/2019	796709	door brakes stuck on	checked door brakes working ok. not stuck on as road tested		1017374
878	02/09/2019	796089	Consumables			1017532
878	02/09/2019	796089	Mechanic entered - Body Other o/s/r side panel shocker u/s.	straightened the side hatch brackets and replaced struts ok		1017374
878	02/09/2019	796706	Drv entered - Brakes Foot_Brakes Pulling	remove front wheelsbrake linings for machining.		1017374
878	02/09/2019	796706	Drv entered - Brakes Park_Brake Leaking Air	air building up ok. no leak at pb valve.		1017374
878	02/09/2019	796706	Unreported Accident #48404 - NSR corner and window damage.	repaired by alpha glass no charge		1017374
878	02/07/2019	795996	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O240666 Receiving #:248902 Date :2019-02-11 replace smashed side window - n/s/r window		1017532
878	02/07/2019	795996	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O240666 Receiving #:248901 Date :2019-02-11 Install Peep		1017532
878	02/07/2019	796089	K505-10-22-500N Gas Strut	Creditor #:VB-MCN001 MCNAUGHTANS P/O #:O240659 Receiving #:249318 Date :2019-02-14		1017964
878	02/06/2019	796048		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1017374
878	02/06/2019	796048		VEHICLE SAFETY INSPECTION done.		1017374
878	02/06/2019	795996	Vandalism - hit by an object while on drive	glass was replaced by alpha - O240666		1017374
878	02/06/2019	796048	Consumables			1017374
878	02/06/2019	796048	Consumables			1017374
878	02/06/2019	796048	Oil Filter SC S4 & K			1017374
878	02/06/2019	796048	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1017374
878	02/06/2019	796048	FILTER FUEL FILTER SCANIA SR4 (1372444)			1017374
878	02/06/2019	796048		CARRY OUT B SERVICE AS PER CHECK LIST done.		1017374
878	02/06/2019	796048	O-RING LARGE SPINNER FILTER SCANIA (1769799)			1017374
878	02/06/2019	796048	O-RING SPINNER FILTER SCANIA (1769798)			1017374
878	02/04/2019	795515	Drv entered - A/C Heating Demister Not Heating	adjusted a/c belts . checked operation of a/c . could not fault		1016954
878	01/31/2019	794691	Accident#:46804 - Ops Entered - Accident - To Be Advised (a	complete		1016533

878	01/31/2019	794652	Accident#:46357 - Ops Entered - Accident - Bus is hit by 3r	closed off as per instruction from paul bell - complete	1016533
878	01/30/2019	794223	Consumables		1016533
878	01/30/2019	794223	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque all wheel nuts.	1016136
878	01/30/2019	791683	HOSE SILICONE 3 PLY 1 ID (PER CM)		1016136
878	01/30/2019	791683	HOSE SILICONE 3 PLY 16mm 5/8 ID (price per cm)		1016136
878	01/26/2019	793682		Assisted by lou	1016106
878	01/26/2019	793682	Drv entered - Brakes Foot_Brakes Noisy	Fitted all brakes with new drums . Adjusted brakes and road tested	1016106
878	01/25/2019	793664	Consumables		1016106
878	01/25/2019	793664	Ops Entered - Fault - Elec and Light Two Way Radio - Route:	there was no power to 2way. fixed a broken wire and secured the bracket ok	1016106
878	01/25/2019	793682	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O239755 Receiving #:248203 Date :2019-01-31 radius grind and machine brakes as required	1016533
878	01/25/2019	793682	Drv entered - Brakes Foot_Brakes Noisy	removed wheels drums & linings for front & rear. need send to repair shop.	1016106
878	01/19/2019	791683	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	n/s/r top inside heat coolant put in.tightened n/s/r top coolant hose clamp n/s/r top inside hosepipe cover n/s/r top heat coolant hosepipe ties put coolantcheck ok put back n/s/r top inside panelcover ok road tested ok check coolant all ok	1015157
878	01/19/2019	791683	HOSE SILICONE 3 PLY 1 ID (PER CM)		1015157
878	01/18/2019	791683	HOSE SILICONE 3 PLY 16mm 5/8 ID (price per cm)		1015157
878	01/18/2019	791683	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	road tested removed n/s/r inside panelcheck coolant leaks found n/s/r heat coolant pipe crack n/s/r inside top heat coolant pipe cut replaced n/s/r coolant hose replaced heat hose ties ok	1015157
878	01/18/2019	792269	Please remove old 2018 fare decals and fit new 2019 fare de	carried out campaign as required	1015157
878	01/17/2019	791717	Mechanic entered - Fluid Leaks Other low coolant.	top up coolant.	1014681
878	01/16/2019	791683	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	leaking coolant from coolant pipe.	1014681
878	01/14/2019	791129	coolant leak	traced and found hose clamp loose . tightend clamp and topped up coolant	1014453
878	01/14/2019	791158	Consumables		1014453
878	01/14/2019	791158	BATTERY 12V 800CC		1014453
878	01/14/2019	791158	batterys u/ x 2	R&R batterys checked charge rate all okay	1014453
878	01/11/2019	790803	HEADER TANK FILLER CAP 1403954		1014184
878	01/11/2019	790803	Fluid Leaks - Header tank cap U/S	Replaced header tank cap	1014184
878	01/10/2019	790552	Engine header low	topped up coolant . checked for leaks all okay	1014091
878	01/10/2019	790548	check operation of brakes	checked all brakes - 60 % front and rear just all slack adjustors . and adjusted brakes . road tested and brake tested all okay	1014091
878	12/19/2018	786833		SERVICE MOISTURE EJECTOR	1010703
878	12/19/2018	786833		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1010703
878	12/19/2018	786833	GASKET ROCKER COVER SCANIA SR4 DC9 (1425921)		1010703
878	12/19/2018	786920	PULLEY IDLER SCANIA (1514087)		1010703
878	12/19/2018	786920	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		1010703
878	12/19/2018	786920	Mechanic entered - Engine Other alternate pulley broken	replaced old alternate pulley replaced engine belt okengine idler bearing x2	1010703
878	12/19/2018	786920	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG		1010703
878	12/17/2018	786442	BELT V-BELT COGGED TRI-POWER 17x2110mm		1010551
878	12/17/2018	786442	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1010551
878	12/17/2018	786442	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		1010551
878	12/17/2018	786442	Mechanic entered - Engine Belts_Loose Noisy Missing alt belt	replaced alt belt and ac belts . checked the belts running ok.	1010551
878	12/15/2018	786250	IDLER PULLEY (METAL SMOOTH) (1779801)		1009965
878	12/15/2018	786250	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1009965
878	12/15/2018	786250	Engine belt u/s	R&R engine belt and tensioner	1009965
878	12/15/2018	786248	Consumables		1010223
878	12/15/2018	786248	REAR POSITION STOP LAMP LED (DESIGNLINE)		1009965
878	12/15/2018	786248	o/s/r top park light not working	R&R led indicator	1009965
878	12/10/2018	785037	Mechanic entered - Engine Belts_Loose Noisy Missing	Replaced damage engine belt fit back a/c belts	1008935
878	12/10/2018	785037	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1008935
878	12/07/2018	784598	Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 703	adjusted both frt and rear brakes; road/brake tested ok. to rebook	1008450
878	12/05/2018	783859		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.	1007779
878	12/05/2018	783859		VEHICLE SAFETY INSPECTION Carried out vehicle safety inspection as per checklist. ok.	1007779
878	12/05/2018	783984	Mechanic entered - Fluid Leaks Rear of bus	found transmission coolant lines leaking tightened hose clamps drained coolant system replaced coolant with red road tested vehicle checked coolant level. ok.	1007779
878	12/05/2018	783920	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		1007779
878	12/05/2018	783920	Mechanic entered - Engine Other		1007779
878	11/29/2018	782681	Consumables	Serpentine belt split replaced serpentine belt. ok.	1007052
878	11/29/2018	782681	Mechanic entered - Elec and Light Indicators Not Working on	O235651	1006899
878	11/29/2018	782681	Ops Entered - Fault - Elec and Light Indicators Not Working	O235651 - node reloaded .	1006899
878	11/27/2018	782084	Ops Entered - Fault - Wipers and Washers Wipers Not Working	checked operation of wipers . could not fault	1006576
878	11/16/2018	779924	Consumables		1004816
878	11/16/2018	779924	Mechanic entered - Elec and Light Indicators Not Working bl	double entry	1004273
878	11/05/2018	777741	Consumables		1002821
878	11/05/2018	777741	dash indicators not working	repairs carried out by bewere electrics	1002629
878	10/18/2018	774418	Breakdown#:35692 - Ops Entered - Breakdown - Breakdown Air S	Attended breakdown found main air line fitting to moisture ejector end came off remove pipe and temporary fix and brought bus to workshop	999701
878	10/18/2018	774419	Mechanic entered - Air System Air_Leak Rear	Removed air pipe and fix olive fitted back and tested ok	999701
878	10/11/2018	772801			998505
878	10/11/2018	772696		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	998505
878	10/11/2018	772696		VEHICLE SAFETY INSPECTION done.	998505
878	10/11/2018	772814	Mechanic entered - Engine Belts_Loose Noisy Missing alts bel	r/r beltok.	998505
878	10/11/2018	772814	Consumables		998505
878	10/11/2018	772814	Consumables		998505
878	10/11/2018	772814	Mechanic entered - Body Other desto panel hinge u/s.	r/r hingeok.	998505
878	10/11/2018	772814	Mechanic entered - Body Other damaged a/c filter frame.	fixed a/c filter frameok.	998505
878	10/11/2018	772814	Mechanic entered - Body Other damaged pax bagkage.	removed it & fixed bagkageok.	998505
878	10/11/2018	772814	Mechanic entered - Body Other safety triangle u/s.	swap with bus 800ok.	998505
878	10/11/2018	772814	HINGE		998505
878	10/11/2018	772814	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		998505
878	10/07/2018	771492	Consumables		997798
878	10/07/2018	771492	Consumables		997798
878	10/07/2018	771492	Body - n/s front top park light lens coming off	rescured	997538
878	10/05/2018	771232	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	carried out campaign as required	997538
878	10/01/2018	769746	Consumables		996882
878	10/01/2018	769746	Mechanic entered - Elec and Light Other battery jump	jumped battery	996435
878	09/26/2018	736295	BIC Repairs - Serial RSI 016779 - Fluid leak transmission	02/05/2018 - Trans leak checked OK. Oil was from engine oil leak.	996175
878	09/26/2018	736295	Consumables		996435
878	09/26/2018	736295	DECAL BREAK GLASS IN EMERGENCY ROCK 120MM SQ RED/CLEAR		996175
878	09/26/2018	736295	EMERG HAMMER KIT WITH WIRE		996175
878	09/26/2018	736295	BIC repairs - Serial RSI 016779 - Decal & hammer	02/05/2018 - Hammer and emergency exit exterior decal fitted.	996175
878	09/26/2018	769247		CARRY OUT FIRE EXTINGUISHER TEST & TAG	996175
878	09/26/2018	769247		closed off as completed as per instruction from paul bell	996175
878	09/25/2018	768832	Consumables		996175
878	09/25/2018	768832	Body drivers door bottom hinge broken.	fit new hinge.	995801
878	09/25/2018	768832	FLUSH HINGE R/H		995801
878	09/21/2018	768064	Breakdown#:35578 - Ops Entered - Breakdown - Breakdown Brake	replaced park brake supply one way valve ok removed park hand valve. replACED park hand valvbe ok ROAD/BRAKES TESTED	995319
878	09/21/2018	768064	Valve Check		995319
878	09/21/2018	768064	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866 40G2702W		995319
878	09/20/2018	768064	Breakdown#:35578 - Ops Entered - Breakdown - Breakdown Brake	door brakes nw since the park brake light obn all the time. replaced the p/b switch still the same. suspect the one way air control valve.	995319

[illegible]

878	05/18/2018	739482	Mechanic entered - Elec and Light Exterior Lights n/s/f side	fit new globe	972381
878	05/16/2018	738424	KIT SWITCH OVERRIDE RPD		972120
878	05/14/2018	738424	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	installation of RPD dash switch is complete. still need install the programme. TVI not responding, contact one of the Bens please..	971768
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389		CARRY OUT B SERVICE AS PER CHECK LIST completed b service as per checklist. road and brake tested. all ok	971768
878	05/14/2018	738389	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		971768
878	05/14/2018	738389	FILTER FUEL FILTER SCANIA SR4 (H17WK11) (H17WK05)		971768
878	05/14/2018	738389	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		971768
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389	Consumables		971871
878	05/14/2018	738389		CARRY OUT A SERVICE AS PER CHECK LIST	971768
878	05/10/2018	737742	Consumables		971768
878	05/10/2018	737742	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	fit globe	971276
878	05/05/2018	736913	Consumables		970635
878	05/05/2018	736913	Body - drivers seat wont adjust	tightend adjustor on drivers seat . checked operation of drivers seat all okay	970428
878	05/04/2018	735931	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROAA002 ROAD SAFETY INSPECTIONS P/O #:O218955 Receiving #:227148 Date :2018-05-11	971768
878	05/02/2018	736295	bic repairs - Serial RSI 016779 - engine oil leaks	washed and engine and found loose oil feedpipe to injector pump . tightend oil pipe. roadtested all okay	969974
878	05/01/2018	735931		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	969807
878	05/01/2018	735931		VEHICLE SAFETY INSPECTION	969807
878	05/01/2018	735931		ANNUAL SAFETY INSPECTION SERIAL#_____RSI 016779_____WORKSHOPSUPERVISOR/MANAGER NOTE: REDUCE THEVEHICLE SAFETY INSPECTION LINE TIMEON THE W/O TO 0.25	969807
878	05/01/2018	735931		taken the bus and waited at dandenong untill the RSI finished.	969807
878	04/28/2018	735410	Consumables		969576
878	04/28/2018	735410	check the bus before the RSI	checked the tyres suspension oil leaks etc... road brakes tested ok	969478
878	04/26/2018	735205		TRANSMISSION CHECK AS PER CHECK LIST	969021
878	04/23/2018	734383	Consumables		968793
878	04/23/2018	734383	Mechanic entered - Elec and Light Exterior Lights rear door	fit globe	967873
878	04/13/2018	732731	Mechanic entered - Engine Other engine bottom coolant leake	tightened engine bottom hose clamp ok	966614
878	04/13/2018	732731	Consumables		966614
878	04/13/2018	732731	Mechanic entered - Elec and Light Other dash gauge light not	replaced dash gauge light globe ok	966614
878	04/08/2018	731487		Test drive and top up coolant. Checked OK.	965121
878	04/08/2018	731487	Fluid Leaks Rear of bus.	Replaced coolant hose.	965121
878	04/08/2018	731487	HOSE TRANSMISSION COOLING HOSE		965121
878	04/04/2018	730775		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	964457
878	04/04/2018	730775		VEHICLE SAFETY INSPECTION done.	964457
878	04/04/2018	730802	Consumables		964846
878	04/04/2018	730802	Mechanic entered - Wheels and Tyres Other wheel arch rubber	fixed rubberok.	964457
878	04/04/2018	728998	AIRBAG O/S/F SCANIA K230UB (2024284)		964457
878	04/04/2018	728998	AIRBAG FRONT SCANIA K230 (40Y2223)		964457
878	04/04/2018	730802	Consumables		964846
878	04/04/2018	730802	Mechanic entered - Elec and Light Exterior Lights indicator	r/r globesok.	964457
878	04/04/2018	730802	Consumables		964846
878	04/04/2018	730802	Mechanic entered - Body Other stauchion pole bolt missing.	fitted new boltok.	964457
878	04/04/2018	730802	Mechanic entered - Body Other pax seat boltsloose.	tigheten boltsok.	964457
878	04/04/2018	730776		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	964457
878	03/24/2018	729029		PRE ANNUAL SAFETY INSPECTION CHECK	962322
878	03/24/2018	728998	AIRBAG FRONT SCANIA K230 (40Y2223)		962322
878	03/24/2018	728998	Mechanic entered - Suspension Other o/s/f air bag u/s	replaced o/s/f air bag ok	962322
878	03/24/2018	728998	Mechanic entered - Suspension Other o/s/f air bag u/s	replaced o/s/f air bag ok	962322
878	03/24/2018	728998	Mechanic entered - Engine Other coolant tank u/s	removed 1206 put in bus 878 oktightened all hose clamps okput in coolantok	962322
878	03/24/2018	729031	Consumables		962831
878	03/24/2018	729031	Mechanic entered - Elec and Light Other front step light not	repaired front step light wires ok	962322
878	03/24/2018	729031	Mechanic entered - Elec and Light Other front step light not	repaired front step light wires	962322
878	03/24/2018	728998	Consumables		962831
878	03/24/2018	728998	Mechanic entered - Body Other middle seat loose	repaired middle seat ok	962322
878	03/24/2018	728998	Mechanic entered - Body Other rear modesty panel loose		962322
878	03/24/2018	728998	Mechanic entered - Body Other middle seat loose	replaced middle seat ok	962322
878	03/23/2018	728763	Consumables		962757
878	03/23/2018	728763	Mechanic entered - Body Other inside mirror loose	securedd mirror	962322
878	03/21/2018	728187	Consumables		962322
878	03/21/2018	728187	n/s/f blinker not working	R&R indicator . checked operation all okay	962095
878	03/21/2018	728187	INDICATOR SIDE INDICATOR R/H		962095
878	03/17/2018	727406	Mechanic entered - A/C Heating Other adjust a/c belts	Adjusted a/c belt ok	961135
878	03/17/2018	727406	THERMOSTAT SCANIA K230 (1404925)		961135
878	03/17/2018	727406	Mechanic entered - Engine Other thermostat u/s	replaced thermostat ok	961135
878	03/17/2018	727406	Consumables		961643
878	03/17/2018	727406	Mechanic entered - Elec and Light Other speedo light not wor	replaced speedo light globe ok	961135
878	03/17/2018	727406	Mechanic entered - Elec and Light Other fuel gauge light not	replaced fuel gauge light globe	961135
878	03/17/2018	727406	Consumables		961643
878	03/17/2018	727406	Mechanic entered - Body Other rear modesty panel loose	tightened rear modesty panel ok	961135
878	03/17/2018	727370	Consumables		961643
878	03/17/2018	727370	Consumables		961643
878	03/17/2018	727370	Consumables		961643
878	03/17/2018	727370		CARRY OUT A SERVICE AS PER CHECK LIST	961135
878	03/17/2018	727370			960014
878	03/08/2018	725526	Consumables		959333
878	03/08/2018	725526	Mechanic entered - Body Front_Door Operation Faulty front do	adjusted to slow when closing all ok	959333
878	03/07/2018	718927	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)		959333
878	03/07/2018	718927	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)		959333
878	03/05/2018	724494	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	carried out campaign as required	959074
878	02/26/2018	722333	Consumables		957926
878	02/26/2018	722333	Direct Purchase - BODYWORK	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O214560 Receiving #:221774 Date :2018-02-26 replace drivers seat foam as require x 1	957662
878	02/26/2018	722333	Drv entered - Body Drivers Seat Leaning	O214560 - removed drivers seat base and sent away to be refoamed at autotrimmers	957230
878	02/24/2018	722234	Consumables		957662
878	02/24/2018	722234	high beam indicator nw	replaced dash globe	957230
878	02/12/2018	718913		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	954760
878	02/12/2018	718913		VEHICLE SAFETY INSPECTION	954760
878	02/12/2018	718913		Assisting	954760
878	02/12/2018	718927	Mechanic entered - Wipers and Washers Other N/S wiper blade	repaired wiper blade	954760
878	02/12/2018	718927	Mechanic entered - Suspension Other n/s/r/r air bag u/s	replaced n/s/r/r air bag ok	954760
878	02/12/2018	718927	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)		954760
878	02/12/2018	718927	Mechanic entered - Engine Other engine belt u/s	replaced engine belt	954760

878	02/12/2018	718927	BELT TENSIONER			954760
878	02/12/2018	718927	Mechanic entered - Engine Other engine belt tensioner u/s	replaced engine belt tensioner ok		954760
878	02/12/2018	718927	PUMP WATER PUMP SCANIA S4			954760
878	02/12/2018	718927	Mechanic entered - Engine Other water pump u/s	replaced water pump ok		954760
878	02/12/2018	718927	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			954760
878	02/12/2018	718988	Consumables			955397
878	02/12/2018	718927	Consumables			955397
878	02/12/2018	718988	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O213571 Receiving #:220911 Date :2018-02-14 reseal nsr 2nd window as required		955628
878	02/12/2018	718988	Body-nsr window glass rattles-needs resealing	alpha glass PO#: O213571		954760
878	02/12/2018	718927	Mechanic entered - Body Other n/s middle seat loose	repaired n/s middle saet ok		954760
878	02/12/2018	718927	Mechanic entered - Body Other rear modesty panel loose	repaired rear modesty panel ok		954760
878	02/12/2018	718927	Mechanic entered - Body Other Rear door step light N/W	replaced rear door step light globe ok		954760
878	02/12/2018	718927	Mechanic entered - Body Other Sun visor guides sticking	repaired sun visor guides ok		954760
878	02/12/2018	718927	SLACK ADJUSTER AUTO-REAR O/SIDE (2009820) SERIES 4			954760
878	02/12/2018	718927	SLACK ADJUSTER FRONT OUTER SIDE (1789567)			954760
878	02/12/2018	718927	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s	replaced o/s/r brake slack adjust ok		954760
878	02/12/2018	718927	Mechanic entered - Brakes Other o/s/f brake slack adjust u/s	replaced o/s/f brake slack adjust ok		954760
878	02/12/2018	718927	SEAL HUB REAR OUTER SCANIA K124EB			954760
878	02/12/2018	719234		CARRY OUT FIRE EXTINGUISHER TEST & TAG		954760
878	02/12/2018	719251		CARRY OUT FIRE EXTINGUISHER TEST & TAG		954760
878	02/12/2018	719251		inspection carried out by ATS fire services - O213090		954760
878	02/12/2018	719234		inspection carried out by ATS fire services - O213090		954760
878	02/11/2018	718858	Consumables			955249
878	02/11/2018	718858	Ops Entered - Fault - Elec and Light Indicators Not Working	replaced globe ok		954760
878	02/09/2018	718753	Breakdown#:34472 - Ops Entered - Breakdown - Breakdown Misc			954760
878	02/09/2018	718753	Breakdown#:34472 - Ops Entered - Breakdown - Breakdown Misc	Front panel needs locking. Retightened front panel lock holding nuts & secured the panel		954760
878	02/09/2018	718753	Consumables			954958
878	02/09/2018	718753	o/s/f side indicator smashed	R&R o/s/f side indicator		954760
878	02/09/2018	718753	LIGHT SIDE INDICATOR L/H			954760
878	02/09/2018	718757	Consumables			954958
878	02/09/2018	718757	Body - secured roof panel	secured roof panel		954760
878	02/06/2018	717829	HEATER-DEMISTER VALVE TAP MERC 0500 (DHV4008)			954120
878	02/06/2018	717829	Engine - heater tap leaking	R&R front of bus leaking heater tap topped with coolant . road tested all okay		954120
878	01/19/2018	714433	Consumables			951449
878	01/19/2018	714433	Wheels and Tyres - carry out n/s/f retorque as required	carried out retorque as required		951022
878	01/17/2018	714001	Consumables			951022
878	01/17/2018	714001	Mechanic entered - Wheels and Tyres Other n/s/f tyre u/s	replaced n/s/f tyre ok		950675
878	01/17/2018	714001	TYRE 295/80R22.5 NEW			950675
878	01/17/2018	714017	Consumables			951022
878	01/17/2018	714001	Consumables			951022
878	01/17/2018	714017	Mechanic entered - Body Other n/s/f staunchionc bolt missing	replaced n/s/f stunchionc bolt ok		950675
878	01/17/2018	714001	Mechanic entered - Body Other front modestey panel loose	repaired front modestey panel ok		950675
878	01/17/2018	713981	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals			950675
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			950675
878	01/17/2018	713981	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			950675
878	01/17/2018	713981	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			950675
878	01/17/2018	713981	ASSISTED SHO			950675
878	01/17/2018	713981	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			950675
878	01/17/2018	713981		CARRY OUT B SERVICE AS PER CHECK LIST		950675
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981	Consumables			951022
878	01/17/2018	713981		CARRY OUT A SERVICE AS PER CHECK LIST		950675
878	01/06/2018	712029	n/s/b front park light not working	R&R globe . checked operation all ok f		949268
878	12/27/2017	705774	Consumables			948284
878	12/27/2017	705774	SWITCH HAZARD 4 SERIES 1327015			948021
878	12/27/2017	705774	SWITCH HAZARD SWITCH SCANIA L94 (40V3103)			948021
878	12/14/2017	708100		VEHICLE SAFETY INSPECTION		946048
878	12/14/2017	708100		Assisting		946048
878	12/14/2017	708100		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheels tensioned		946048
878	12/14/2017	708100		VEHICLE SAFETY INSPECTION safety completed		946048
878	12/14/2017	708100		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		946048
878	12/14/2017	708230	Mechanic entered - Engine Belts_ Loose Noisy Missing	replace engone belt main belt		946048
878	12/14/2017	708230	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			946048
878	12/14/2017	708229	Consumables			946381
878	12/14/2017	708229	TUBE FLUORESCENT TUBE 12 INCH F10W/33			946048
878	12/14/2017	708229	Mechanic entered - Elec and Light Exterior Lights	replaced front door step light		946048
878	12/04/2017	705774	Mechanic entered - Elec and Light Exterior Lights o/s high	replaced globe		943658
878	12/04/2017	705774	Mechanic entered - Elec and Light Indicators Not Working da	double entry		943658
878	12/04/2017	705774	SWITCH HAZARD SWITCH SCANIA L94 (40V3103)			943658
878	12/04/2017	705774	Consumables			944336
878	12/04/2017	705774	Mechanic entered - Body Other hazard light button not worki	replaced hazard switch		943658
878	12/02/2017	705760	Vandalism Vandalism/ Graffiti Interior	carried out interior painting over vandalisem as required		943658
878	12/01/2017	705382	Consumables			943916
878	12/01/2017	705382	Elec and Light Two Way Radio - Not Transmitting	2-way reset at repeator by cim		943658
878	11/28/2017	690495	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O203789 Receiving #:215215 Date :2017-11-28 replace n/s/r glass as required		942952
878	11/22/2017	703138	PUMP WATER PUMP SCANIA S4			941294
878	11/21/2017	703138	Engine - coolant leaking from engine	R&R water pump . road tested all ok		941294
878	11/21/2017	703210	Mechanic entered - Engine Other engine belt is broken	removed new belt because new belt is brokenput in old belt ok		941294
878	11/21/2017	703069	Mechanic entered - Fluid Leaks Rear of bus coolant leak at r	removed coolant water pump		941294
878	11/21/2017	703069	Mechanic entered - Engine Other a/c belt u/s	replaced a/c belts ok		941294
878	11/21/2017	703069	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			941294
878	11/20/2017	702468	Consumables			941934
878	11/20/2017	702468	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-CIM CIM CONCEPTS PTY LTD P/O #:O207486 Receiving #:214840 Date :2017-11-22 rectify 2-way not working as required		941960
878	11/17/2017	702468	rectify 2-way not working	O207486 - 2-way repaired by cim		941294
878	11/17/2017	702411	Consumables			941732
878	11/17/2017	702411	Consumables			941732
878	11/17/2017	702411	Consumables			941732
878	11/17/2017	702411	Consumables			941732
878	11/17/2017	702411	Consumables			941732
878	11/17/2017	702411	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST a service completed		941294

878	11/15/2017	701895	Consumables			941294
878	11/15/2017	701895	Mechanic entered - Body Other driver's mirror broken	replaced mirror		941106
878	11/15/2017	701895	Mechanic entered - Body Other driver's seat belt stalk us	replaced seat belt stalk		941106
878	11/15/2017	701895	BUCKLE SEAT BELT TWIN WIRE GREY (SOB2123GY) (340446)			941106
878	11/15/2017	701895	MIRROR R/H 380mm SHORT (UES1411D)			941106
878	11/10/2017	700726		TRANSMISSION CHECK AS PER CHECK LIST		940342
878	10/30/2017	697964	Remove old poster and fit new A3 Posters and hangers	carried out campaign as required		938021
878	10/29/2017	697209	Please remove the 2 x Do Not Enter decals at the exterior	carried out campaign as required		938021
878	10/21/2017	683634	Consumables			937215
878	10/21/2017	683634	Consumables			937215
878	10/21/2017	683634	Consumables			937215
878	10/21/2017	683634	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			936851
878	10/20/2017	694173	BEARING ROLLER BEARING			936851
878	10/19/2017	694173	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O205228 Receiving #:212478 Date :2017-10-20 reskin passenger seat back		937009
878	10/19/2017	694173	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O205228 Receiving #:212478 Date :2017-10-20 reskin passenger seat bases		937009
878	10/19/2017	694173	Direct Purchase - BODYWORK	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O205228 Receiving #:212478 Date :2017-10-20 refoam drivers seat base x 1		937009
878	10/19/2017	694173	Service	road/brakes tested ok		936851
878	10/19/2017	695668	Consumables			937009
878	10/19/2017	695668	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	already on		936851
878	10/19/2017	695668	fit the pax seat bases as required	fitted the pax seat bases as required		936851
878	10/19/2017	695668	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE			936851
878	10/19/2017	695668	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT			936851
878	10/18/2017	694173	SEAL REAR HUB OUTER SR 3 & 4 SCANIA 1765061			936851
878	10/18/2017	694173	SEAL HUB REAR OUTER SCANIA K124EB			936851
878	10/18/2017	694173	BEARING ROLLER BEARING			936851
878	10/18/2017	694173	SEAL HUB REAR SCANIA SR4 1740992			936851
878	10/18/2017	694173	40F3321R BRAKE CHAMBER 10	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O205232 Receiving #:212328 Date :2017-10-20		936851
878	10/18/2017	694173	Mechanic entered - Wheels and Tyres Damaged n/s/r wheel & hu	fitted new drum wheels. need to road test & fitting pax seat cushion.		936851
878	10/18/2017	694173	LINING BRAKE LINING ASB FREE 10 INCH SCANIA (FB4918)			936851
878	10/18/2017	683634	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			936851
878	10/17/2017	694173	2378715 BRAKE DRUM	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	2285273 WHEEL NUT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	1368693 WHEEL STUD	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	1340933 LOCK NUT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	1340934 STUD	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	0273024 NUT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	337565 HUB ASSY	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O204957 Receiving #:212116 Date :2017-10-18		936851
878	10/17/2017	694173	0273023 LOCK WASHER	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	0273022 PROTECTION WASHER	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	1461757 SPACER RING	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	1493961 OIL COLLECTOR	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/17/2017	694173	0041181 SLEEVE	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O204927 Receiving #:212121 Date :2017-10-18		936851
878	10/16/2017	694173	Mechanic entered - Wheels and Tyres Damaged n/s/r wheel & hu	removed hub bearing drum & linings.		936591
878	10/14/2017	694134		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		936591
878	10/14/2017	694134		VEHICLE SAFETY INSPECTION		936591
878	10/14/2017	694172	WIPER BLADE VOLGREN TRACK BUS			936591
878	10/14/2017	694172	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE			936591
878	10/14/2017	694172	Mechanic entered - Wipers and Washers Other wiper blades u/s	r/r wiper bladesok.		936591
878	10/14/2017	694173	Mechanic entered - Wheels and Tyres Damaged n/s/r wheel & hu	removed n/s/r wheel drum hub & bearing. need to order for parts.		936591
878	10/14/2017	694172	Consumables			936851
878	10/14/2017	694172	Mechanic entered - Body Other need fitting rear door decalles.	fitted new decallesok.		936591
878	10/14/2017	694172	Mechanic entered - Body Other pax seat cushion u/s. x2	removed pax seat cushion.		936591
878	10/01/2017	689631	Remove old A3 Posters with Seniors Festival please leave	carried out campaign as required		933814
878	09/28/2017	690495	n/s/r glass smashed	O203789 - glass replaced by alpha		934189
878	09/28/2017	688615	Fluid Leaks No Coolant in header tank.	ALL OK.		934189
878	09/28/2017	688615	Engine leaking coolant	replaced radiatortightened radiator bracket all bolts ok put in radiator hosesotightened radiator hoses clamps ok tightened all engine fan pipes ok tightened fule cooler hoses clamps ok		934189
878	09/28/2017	688615		put in intercoolertightened intercooler bracket bolts ok. tightened intercooler pipes clamps ok tightened intercooler cover bolts ok put in coolantengine fan oil ok ROAD TESTED OKCHECK RADIATOR TOP TEMP IS 63RADIATOR BOTTOM TEMP IS 72 OK CHECK COOLANT OKCHECK ENGINE FAN OIL IS OK.		934189
878	09/28/2017	688615	CLAMP HOSE 14-27			934189
878	09/26/2017	688615	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:O203610 Receiving #:210693 Date :2017-09-27 supply new radiator as required		934189
878	09/25/2017	688615	Fluid Leaks No Coolant in header tank.			933814
878	09/25/2017	688615	Engine leaking coolant	CHECKED COOLANT LEAKSROAD TESTED FOUND RADIATOR removed INTERCOOLLERRADIATOR		933814
878	09/25/2017	688615	THERMOSTAT SCANIA K230 (1404925)			933814
878	09/25/2017	688615	Mechanic entered - Engine Other ENGINE THERMOSTAT U/S	replaced ENGINE THERMOSTAT OK		933814
878	09/19/2017	687439	ASSY AIR DRYER ASSY HALDEX			933142
878	09/19/2017	687439	Mechanic entered - Fluid Leaks Rear of bus coolant leak at	tightend hose clamp topped up coolant		933142
878	09/19/2017	687439		Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O203107 Receiving #:210686 Date :2017-09-27 supply air fitting as required		934189
878	09/19/2017	687439	Mechanic entered - Air System Other air gauges showing 0	R&R air dryer and air reg . adjusted . road tested all ok		933142
878	09/18/2017	685370	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O202954 Receiving #:210698 Date :2017-09-27 check and rectify wipers not working at times		934189
878	09/09/2017	683634	GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596WLED			932539
878	09/09/2017	683634	CLAMP HOSE 18-32			932539
878	09/09/2017	683634	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			932539
878	09/09/2017	683634	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			932539
878	09/09/2017	683634	Consumables			933099
878	09/09/2017	683634	Consumables			933099
878	09/08/2017	685370	Wipers and Washers Wipers Not Working	fixed at lonsdale and the bus back in 16/09/2017 O202954(reprogrammed nodes)		932539
878	09/06/2017	684944	Wipers and Washers Wipers Not Working	removed the wiper motor to give part number replaced the wiper motor and re-wired the plug as the terminals loose. wiper operation is not good. lee to continue with tightening the linkage on pivot.		932539
878	09/06/2017	684944	PUMP WATER BOOST MOTOR			932539
878	09/06/2017	684944	403.155 24V WIPER MOTOR	Creditor #:VB-KIRG KIRG IMPORTERS PTY LTD P/O #:O202230 Receiving #:209321 Date :2017-09-06		932539
878	09/06/2017	684805	Fluid Leaks Rear of bus coolant leak.	checked engine for coolant leaks . could not fault		932539
878	09/06/2017	684944	Mechanic entered - Fluid Leaks Rear of bus leaking coolant.	r/r coolant boost pumpok.		932539
878	09/01/2017	683870	Wheels and Tyres - carry out rear retorque as required	carried out rear retorque as require to OEM spec		930579
878	08/31/2017	683724	VALVE EXTENSION-130mm Metal type			930579
878	08/31/2017	683724	Mechanic entered - Wheels and Tyres Other tyres air valve u/	replaced tyres air valve ok		930579
878	08/31/2017	683724	WHEEL NUT SCANIA L94 (2285273)			930579
878	08/31/2017	683724	TYRE 295/80R22.5 RECAP			930579
878	08/31/2017	683724	Mechanic entered - Wheels and Tyres Other all rear tires rep	fitted rear tyres and tensioned the wheel nuts		930579
878	08/31/2017	683634	Drv entered - Brakes Foot_Brakes Noisy	road tested ok brake tested ok		930579
878	08/31/2017	683634	Consumables			931849
878	08/31/2017	683634	Consumables			931849
878	08/31/2017	683634	Consumables			931849
878	08/31/2017	683634	O-RING LARGE SPINNER FILTER SCANIA (1769799)			930579
878	08/31/2017	683634	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)			930579
878	08/31/2017	683634	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			930579

878	08/31/2017	683634	Assisting completed C service as per checklist. orad and brake tested all ok	930579
878	08/31/2017	683634	CARRY OUT C SERVICE AS PER CHECK LIST	930579
878	08/31/2017	683634	O-RING SPINNER FILTER SCANIA (1769798)	930579
878	08/31/2017	683634	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)	930579
878	08/31/2017	683634	FILTER HYDRAULIC COOLING FAN SCANIA SR3 (E90HD149)	930579
878	08/31/2017	683634	FILTER FUEL FILTER SCANIA SR4 (1393640)	930579
878	08/31/2017	683634	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)	930579
878	08/31/2017	683634	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)	930579
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	CARRY OUT B SERVICE AS PER CHECK LIST	930579
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	Consumables	931849
878	08/31/2017	683634	CARRY OUT A SERVICE AS PER CHECK LIST	930579
878	08/30/2017	683380	Consumables	931833
878	08/30/2017	683380	Elec and Light next stop light on dash not coming on.	930579
878	08/30/2017	683380	Dash PASSENGER LIGHT NOT COMING UP ON THE DASH DRIVERS DON	930579
878	08/29/2017	683089	Consumables	931568
878	08/29/2017	683089	Elec and Light NO INDICATORS OR HAZARD LIGHTS WORKING	930579
878	08/29/2017	683089	Mechanic entered - Elec and Light Indicators Not Working on	930579
878	08/28/2017	682887	Wipers and Washers - not working	930579
878	08/26/2017	682740	Brakes DESTO AT THE FRONT BOARD - THE FONT IS TO HIGH AND Y	930579
878	08/22/2017	681617	AIR CONDITIONING REPAIR	932539
878	08/22/2017	681617	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O200853	929637
878	08/14/2017	678330	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)	928702
878	08/14/2017	678330	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)	928702
878	08/14/2017	679950	Please remove old posters and fit new one along with hangers	928702
878	08/07/2017	678673	Ops Entered - Fault - Wipers and Washers Wipers Not Working	927366
878	08/07/2017	678673	Ops Entered - Fault - Wipers and Washers Wipers Not Working	927366
878	08/05/2017	678330	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)	927366
878	08/05/2017	678330	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)	927366
878	08/05/2017	678330	O-RING LARGE SPINNER FILTER SCANIA (1769799)	927366
878	08/05/2017	678330	O-RING SPINNER FILTER SCANIA (1769798)	927366
878	08/05/2017	678330	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)	927366
878	08/05/2017	678330	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	927366
878	08/05/2017	678330	VEHICLE SAFETY INSPECTION	927366
878	08/05/2017	678330	Assisting	927366
878	08/05/2017	678365	Mechanic entered - Engine Other engine belt idle pully u/s	927366
878	08/05/2017	678365	Consumables	927593
878	08/05/2017	678365	Mechanic entered - Elec and Light Interior Lights saloon lig	927366
878	08/05/2017	678365	IDLER PULLEY SCANIA ARTIC (No Groove Plastic)	927366
878	08/05/2017	678365	LAMP FLUORESCENT TUBE 18W	927366
878	08/05/2017	678330	Ops Entered - Fault - Comm Equip - Route: 703b - Centre Rd	927366
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	Body 2 way not working	927366
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	CARRY OUT B SERVICE AS PER CHECK LIST	927366
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	Consumables	927593
878	08/05/2017	678330	CARRY OUT A SERVICE AS PER CHECK LIST	927366
878	07/26/2017	676325	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	925226
878	07/24/2017	675554	Fluid Leaks 20LTR of coolant added (reported by Geoff)	924844
878	07/24/2017	675554	40N05101 TRANS COOLANT HOSE	925068
878	07/22/2017	675554	Ops Entered - Fault - Eng Cool - Route: 703b - Centre Rd o	924844
878	07/21/2017	675398	Drv entered - Wipers and Washers Wipers Loose	924844
878	07/21/2017	675393	Mechanic entered - Wipers and Washers Wipers Not Working	924844
878	07/13/2017	673380	Consumables	923864
878	07/13/2017	673380	Mount A/C Large	923608
878	07/13/2017	673380	Mount A/C Small	923608
878	07/13/2017	673380	Mechanic entered - Body Other a/c mount u/s	923608
878	07/13/2017	673369	ASSY AIR DRYER ASSY HALDEX	923608
878	07/12/2017	673369	Air System leaking at front	923608
878	07/11/2017	673192	Mechanic entered - Steering Other o/s tyre hit drag link.	923268
878	07/11/2017	673158	Consumables	923608
878	07/11/2017	651165	Consumables	923608
878	07/11/2017	673158	Mechanic entered - Elec and Light Other o/s/f top park light	923268
878	07/11/2017	673158	LAMP ROOF CLEAR	923268
878	07/11/2017	651165	LAMP LED SIDE MARKER RED/AMBER	923268
878	07/07/2017	672339	Wheels and Tyres tyres seem to a bit flat they need to be bo	922035
878	07/06/2017	672337	Mechanic entered - Wheels and Tyres Flat or Leaking Driver c	922035
878	07/05/2017	672005	Consumables	922839
878	07/05/2017	671920	Consumables	922839
878	07/05/2017	672005	Body seat recliner not working	922035
878	07/05/2017	671920	Mechanic entered - Body Drivers Seat Controls seat recliner	922035
878	07/02/2017	671378	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	922035
878	06/22/2017	669315	Consumables	920746
878	06/22/2017	669315	Remove old Green 2016/17 registration Label and/ or Blue EF	920557
878	06/08/2017	666391	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	918088
878	06/08/2017	666391	VEHICLE SAFETY INSPECTION	918088
878	06/08/2017	666425	VALVE EXTENSION-130mm Metal type	918088
878	06/08/2017	666425	Mechanic entered - Wheels and Tyres Other rear both tyres ai	918088
878	06/08/2017	666425	VALVE EXTENSION-130mm Metal type	918088
878	06/08/2017	666425	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)	918088
878	06/08/2017	666425	Mechanic entered - Engine Other engine belt u/s	918088
878	06/08/2017	666425	Consumables	918314
878	06/08/2017	666425	LAMP HEADLAMP MK3 VOLVO B10M	918088
878	06/08/2017	666425	Mechanic entered - Elec and Light Other o/s head light insid	918088
878	06/08/2017	666425	LAMP HEADLAMP MK3 VOLVO B10M	918088
878	06/08/2017	666425	replaced engine belt ok	918088
878	06/08/2017	666425	replaced o/s head light ok	918088

878	06/08/2017	666425	Consumables			918314
878	06/08/2017	665566	Consumables			918314
878	06/08/2017	665566	Direct Purchase - BODYWORK	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:\O195326 Receiving #:\203430 Date :2017-06-27 R&R drivers seat base as required		921277
878	06/08/2017	666425	Mechanic entered - Body Other n/s/r coner upper wather stip	fixed n/s/r coner upper wather stip ok		918088
878	06/08/2017	666425	Mechanic entered - Body Other rear modesty panle loose	repaired modesty panle ok		918088
878	06/08/2017	666391	Consumables			918314
878	06/08/2017	666391	Consumables			918314
878	06/08/2017	666391	Consumables			918314
878	06/08/2017	666391	Consumables			918088
878	06/04/2017	664344	Consumables			917655
878	06/04/2017	664344	Fit A3 Poster/Hangers	carried out campaign as required		916556
878	06/03/2017	665566	Drv entered - Body Drivers Seat Leaning	R&R drivers seat base		917426
878	06/03/2017	665566	ASSEMBLY RETRIMMED BASE ASSY 6008			917426
878	05/31/2017	633568	Consumables			917198
878	05/31/2017	633568	Drv entered - Body Drivers Seat Leaning	adjusted drivers seat . checked operation all ok. Completed 04/04/2017		892040
878	05/25/2017	663357	Mechanic entered - Fluid Leaks Rear of bus coolant leak	no leakstop up coolant.		915910
878	05/25/2017	663358	Consumables			916064
878	05/25/2017	663358	Mechanic entered - Elec and Light Exterior Lights n/s revers	fit globe.		915910
878	05/24/2017	663244	Mechanic entered - Fluid Leaks Rear of bus coolant leak	found top radiator fitting was loose. tightened and filled with coolant. road tested and checked for leak. all ok		915910
878	05/22/2017	662590	Mechanic entered - Engine Other FLAT BATTs.	JUMP START.		915415
878	05/19/2017	661769	Mechanic entered - Suspension Kneel/ Raise bus is leaning to	checked and found nsr air bags dumped. no air pumped to the bags from solenoid block. suspected solenoid. also ns leveling valve changes wouldn't make any change on suspension height. replaced both solenoid and leveling valve. road tested and found all good.		915415
878	05/19/2017	661769	LEVEL SENSOR			915415
878	05/19/2017	661769	SOLENOID VALVE (REAR) 481830			915415
878	05/17/2017	661769	803007 WASHER	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O193851 Receiving #:\200623 Date :2017-05-17		915298
878	05/17/2017	661769	293701 BOLT	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O193851 Receiving #:\200623 Date :2017-05-17		915298
878	05/16/2017	661769	Mechanic entered - Suspension Other V-Rod rubber cracked on	Remove bolts on the V-Rod.		915298
878	05/06/2017	659801	Consumables			913577
878	05/06/2017	659801	GLOBE 24V 4W SINGLE CONTACT [BOX 10] (17141)			913517
878	05/06/2017	659801	GLOBE 24V 75/70W H4			913517
878	05/06/2017	659801	Mechanic entered - Elec and Light Exterior Lights o/s headl	replaced globes checked operation all ok		913517
878	05/05/2017	659521	Wheels and Tyres - carry out o/s/f and n/s/r retorque as re	carried out retorque as retorque		913049
878	05/05/2017	658937	Direct Purchase - TYRES	Creditor #:\VB-TYR002 TYRES4U P/O #:\O193057 Receiving #:\199846 Date :2017-05-06 BALANCE		913517
878	05/05/2017	659500	Consumables			913577
878	05/05/2017	659500	Campaign 14/16 Destination signs Setting and loadig Files.	carried out campaign as required		913049
878	05/04/2017	659047		ANNUAL SAFETY INSPECTION SERIAL # i 263938		913049
878	05/04/2017	659047	DIRECT PURCHASE - BUS INSPECTI	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:\O192897 Receiving #:\199788 Date :2017-05-05		913517
878	05/04/2017	659047		PRE ANNUAL SAFETY INSPECTION CHECK		913049
878	05/03/2017	658937	Mechanic entered - Suspension Other worn front & rear Sway	fitted rear Drubberok.		913049
878	05/02/2017	658937	Mechanic entered - Wheels and Tyres Other worn o/s/f & n/s/r	r/r tyresok.		913049
878	05/02/2017	658937	TYRE 295/80R22.5 NEW			913049
878	05/02/2017	658937	TYRE 295/80R22.5 RECAP			913049
878	05/02/2017	658937	Mechanic entered - Suspension Other worn front & rear Sway	r/r front d rubbers. need fit rear d rubbers.		913049
878	05/02/2017	658937	BUSH SWAY BAR FRONT SCANIA SR4 0469081 1919010			913049
878	05/02/2017	658937	BUSH SWAY BAR FRONT SCANIA K SERIES (1880751)			913049
878	05/02/2017	658785	Consumables			913316
878	05/02/2017	658785	Mechanic entered - Elec and Light Exterior Lights n/s/r bott	replaced nsr bottom LED		913049
878	05/02/2017	658785	REAR POSITION STOP LAMP			913049
878	04/24/2017	657604	Consumables			912319
878	04/24/2017	657604	Mechanic entered - Elec and Light Exterior Lights n/s top f	replaced nsf top indicator festoon		911649
878	04/24/2017	657604	GLOBE 24V 18W FESTOON [BOX 10] (7595)			911649
878	04/22/2017	657533	Mechanic entered - Suspension Leaning	ADJUSTED NSR LEVELING VALVE;ROAD TESTED OK		911649
878	04/21/2017	654030	Consumables			911954
878	04/21/2017	654030	Consumables			911954
878	04/21/2017	654030	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			911649
878	04/21/2017	654030	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			911649
878	04/20/2017	657044	Consumables			911649
878	04/20/2017	657044	Elec and Light back off side tail light out	reconnected wire		911269
878	04/13/2017	656228		TRANSMISSION CHECK AS PER CHECK LIST		910817
878	04/03/2017	500366	BUSH TORQUE ROD BUSH SCANIA/MERCEDES (1517403) (2520801)			908842
878	04/01/2017	630218	6500/517 DRIVERS SEAT	Creditor #:\VB-ISR001 ISRI SEATS SUNSHINE P/O #:\O182370 Receiving #:\198099 Date :2017-04-10		910341
878	04/01/2017	630218	A60-RH SEAT BELT	Creditor #:\VB-ISR001 ISRI SEATS SUNSHINE P/O #:\O182370 Receiving #:\198099 Date :2017-04-10		910341
878	04/01/2017	654162	Brakes RETARDER NOT WORKING PROPERLY	switch was turned off; turned back on road tested and checked retarder working good.		908842
878	03/31/2017	654030		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		908842
878	03/31/2017	654030		VEHICLE SAFETY INSPECTION safety inspection tension wheel nuts & road testok.		908842
878	03/31/2017	654030	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	r/r wiper rubbersok.		908842
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Mechanic entered - Body Drivers Seat Cover driver seat ripp			908842
878	03/31/2017	654030	AIRBAG FRONT SCANIA K310			908842
878	03/31/2017	654030	WIPER REFILL 1000mm MULTI FIT			908842
878	03/31/2017	654030	Mechanic entered - Air System Air_Leak Front leaking air fro	r/r front air bagsok.		908842
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			908842
878	03/31/2017	654030	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			908842
878	03/31/2017	654030	FILTER FUEL FILTER SCANIA SR4 (H17WK04)			908842
878	03/31/2017	654030	O-RING SPINNER FILTER SCANIA (1769798)			908842
878	03/31/2017	654030	O-RING LARGE SPINNER FILTER SCANIA (1769799)			908842
878	03/31/2017	654030		CARRY OUT B SERVICE AS PER CHECK LIST done.		908842
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030	Consumables			909115
878	03/31/2017	654030		CARRY OUT A SERVICE AS PER CHECK LIST		908842
878	03/23/2017	652554		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list.		907408
878	03/21/2017	651932	Mechanic entered - Fluid Leaks Rear of bus coolant leak fro	checked and found header tank over full . drained coolant to correct level . road tested all ok		907089
878	03/16/2017	651165	LAMP LED SIDE MARKER RED/AMBER			906622
878	03/16/2017	651165	Elec and Light - globe holder u/s	replaced side marker light . checked operation all ok		906622
878	03/11/2017	650510	Consumables			906147
878	03/11/2017	650510	Body door wont open as door brakes are stuck on	checked operation of front and rear passengers doors . checked operation of sensitive edge . all ok		905488
878	03/09/2017	650103	GLOBE 24V 4W SINGLE CONTACT [BOX 10] (17141)			905488
878	03/09/2017	650103	Elec and Light - n/s/f bottom parker not working	replaced globe		905488

878	03/06/2017	649192	EXPANSION TANK C/FILL 40N0805	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:-O188871 Receiving #:-195392 Date :2017-03-06	905209
878	03/04/2017	649192	Engine -coolant leak	COOLANT LEAKING FROM HEADER TANK. TEMPORARILY FITTED ONE FROM 880. FILLED COOLANT; STEAM CLEANED ROAD TESTED OK.	905000
878	03/01/2017	648144	HOSE (49N-001)		903699
878	02/28/2017	648144	Engine coolant leak	tightend hose clamp and also replaced transmission coolant hose on o/s of bus	903699
878	02/26/2017	647165	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	Campaign completed.	903699
878	02/25/2017	647087	Please remove any old poster and fit either Good News for T	Campaign completed.	903699
878	02/17/2017	645514	Body front door not closing properly when you are on a hill.	adjusted door pressures . checked operation all ok	902700
878	02/10/2017	644090		SERVICE MOISTURE EJECTOR done	902009
878	02/10/2017	644090		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST engine tune-up & shot road testok.	902009
878	02/10/2017	644091	retension rear wheel nuts	retensioned rear wheel nuts as per specs	902009
878	02/10/2017	643606	DRUM BRAKE DRUM	Creditor #:-VB-MUL001 MULTISPARES LTD P/O #:-O187210 Receiving #:-193567 Date :2017-02-10	902009
878	02/09/2017	643606	TYRE 295/80R22.5 RECAP		901738
878	02/08/2017	643606	LINING BRAKE LINING ASB FREE 10 INCH SCANIA (FB4918)		901738
878	02/08/2017	643606	INDICATOR WHEEL NUT POINTER 33mm		901738
878	02/08/2017	643606	Brakes - rear brakes a low		901738
878	02/06/2017	642798	Consumables	r/r linings drums & o/s/r/o tyre. tension wheel nuts & road testok.	901471
878	02/06/2017	642798	n.s headlight n.w	checked operation of n/s headlamp found to be not working . found power plug to be disconnected . reconnected plug . checked operation of headlamp found to be working ok	900760
878	01/30/2017	641352		completed saftey inspection and A service as per check list. found rear brakes to be low. road tested brake tested wheels torqued to spec. all ok	899034
878	01/28/2017	641339		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	899034
878	01/28/2017	641339		VEHICLE SAFETY INSPECTION	899034
878	01/28/2017	641352		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	899034
878	01/28/2017	641352		VEHICLE SAFETY INSPECTION	899034
878	01/28/2017	641352	Consumables		899731
878	01/28/2017	641352	Speedo light is not working		899034
878	01/28/2017	641352	Consumables		899731
878	01/28/2017	641352	Consumables		899731
878	01/28/2017	641352	Consumables		899731
878	01/28/2017	641352		CARRY OUT A SERVICE AS PER CHECK LIST	899034
878	01/27/2017	476349	DIAPHRAGM TYPE 24 DEEP DISH BRAKE BOOSTER		899034
878	01/17/2017	639254	Mechanic entered - Fluid Leaks Rear of bus coolant leaking	bleed cooling system. road tested for 1 hour . rechecked cooling system all ok	897378
878	01/10/2017	637850	Mechanic entered - Fluid Leaks Rear of bus coolant coolant	tighted hose clamp at header tank . pressure tested cooling system . checked compressor for pressurizing cooling system . could not fault . road tested all ok	890615
878	01/09/2017	637584	Engine - coolant leak	traced and found . coolant header tank over full. drained coolant and tightend hose clamp for coolant header tank . road tested and checked ok	890615
878	01/08/2017	636777	Fit New 2107 Large and Small Fares Small Concessionand AO	campaign complete.	890615
878	01/05/2017	636777	DECAL 2017 PTV DECAL CONCESSION CARD TYPE 300x150mm		890615
878	01/05/2017	636777	DECAL 2017 PTV METRO MYKI DECAL SMALL 300x150mm		890615
878	01/05/2017	636777	DECAL AUTHORISED OFFICER		890615
878	01/04/2017	636442	Consumables	replaced globe	895181
878	01/04/2017	636442	GLOBE 24V 75/70W H4	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O184626 Receiving #:-191462 Date :2017-01-13 carry out 24 month service as required	890615
878	01/04/2017	636442	Elec and Light - o/s headlight not working	24 month service carried out on a/c- O184626	894660
878	01/03/2017	636183	AIR CONDITIONING REPAIR		896154
878	01/03/2017	636183	Mechanic entered - A/C Heating Not Cooling	carried out interior painting as required - saturday	890615
878	01/01/2017	632266	Consumables	fit new transmission soleniod . road tested bus and checked operation of retarder working ok	890615
878	01/01/2017	632266	DIRECT PURCHASE GLASS		890615
878	12/19/2016	634164	Vandalism Vandalism/ Graffiti Interior	replaced globe checked operation of head light . working ok	892735
878	12/17/2016	631608	transmission retarder solenoid valve u/s		892471
878	12/17/2016	633947	GLOBE 24V 75/70W H4	double entry drivers seat has already been ordered on 15-12-16	891773
878	12/17/2016	633947	Elec and Light NS Head light N/W	new graffiti cleaned	892735
878	12/16/2016	633845	Consumables	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O183205 Receiving #:-190000 Date :2016-12-19 REPLACED LEAKING DISCHARGE HOSE. REFILLED COMPRESSOR OIL	891220
878	12/16/2016	633845	The lever foor the tilt of the drivers seat is jamming on t	O183205 a/c repaired by cold drive - cammelious	891277
878	12/13/2016	633268	Mechanic entered - Vandalism Vandalism/ Graffiti Interior		891220
878	12/08/2016	632264	AIR CONDITIONING REPAIR	O183207 - windscreen replaced by alpha - due to scratched windscreen from wipers	890615
878	12/08/2016	632264	Drv entered - Cool & AC Sys	r/r ac mounts	890615
878	12/08/2016	632266	Consumables	check retarder valve found leaking part on order	890615
878	12/08/2016	632266	windscreen u/s	r/r belt idler pully	890615
878	12/05/2016	631643	Mechanic entered - A/C Heating Other ac mounts us	hydraulic hose to be repaired	890615
878	12/05/2016	631643	Mechanic entered - Gearbox Driveline Other retarder valve le	fix school light wiring	890615
878	12/05/2016	631643	Mechanic entered - Engine Other belt idler pully us	r/r reverse buzzer	890615
878	12/05/2016	631643	Mechanic entered - Fluid Leaks Rear of bus hydraulic hose le	r/r interier light	890993
878	12/05/2016	631643	Mechanic entered - Elec and Light Exterior Lights school lig		890993
878	12/05/2016	631643	Mechanic entered - Elec and Light Reverse Buzzer reverse buz		890615
878	12/05/2016	631643	Mechanic entered - Elec and Light Interior Lights n/s/t ligh		890615
878	12/05/2016	631544	Consumables		890615
878	12/05/2016	631544	Consumables		890615
878	12/05/2016	631544	Consumables		890615
878	12/05/2016	631544	Consumables		890615
878	12/05/2016	631544	Filter ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)		890615
878	12/05/2016	631544	Filter FUEL Filter SCANIA SR4 (H17WK04)		890615
878	12/05/2016	631544	Filter OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		890615
878	12/05/2016	631544		AB servicetension wheel nuts & road testok.	890615
878	12/05/2016	631544	REVERSE ALARM 12-24v 72608		890615
878	12/05/2016	631544	Mount A/C Large		890615
878	12/05/2016	631544	IDLER PULLEY SCANIA ARTIC (No Groove Plastic)		890615
878	12/05/2016	631544		CARRY OUT B SERVICE AS PER CHECK LIST a&b service complete defects tension wheel nuts brake test road test ok	890615
878	12/05/2016	631544	Consumables		890993
878	12/05/2016	631544	Consumables		890993
878	12/05/2016	631544	Consumables		890993
878	12/05/2016	631544		CARRY OUT A SERVICE AS PER CHECK LIST	890615
878	12/02/2016	631199	FAN DRIVERS FAN 24 Volt		890615
878	12/02/2016	631199	GLOBE 24V 21W SINGLE CONTACT (HLR2421)		890615
878	12/02/2016	631199		VEHICLE SAFETY INSPECTION a service complete safety inspection complete tension wheel nuts road test brake test ok	890615
878	12/02/2016	631199		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	890822
878	12/02/2016	631199	Consumables		890822
878	12/02/2016	631199	Consumables		890822
878	12/02/2016	631199	Consumables		890615
878	11/28/2016	630218	driver's seat us	CARRY OUT A SERVICE AS PER CHECK LIST R/R drivers fan wire in ok	889702
878	11/28/2016	630290	Mechanic entered - Body Other MIDDLE SEAT REMOVING	1196 removed DRIVER SEATPUT BACK 878.OK new seat to go to 1196	889702
878	11/25/2016	630050	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	removed MIDDLE SEATWELDING FROM TO THE SEAT BRACKET OK	888389
878	11/22/2016	629148	GLOBE 24V 4W SINGLE CONTACT [BOX 10]	new graffiti cleaned	888389
878	11/22/2016	629148	Mechanic entered - Elec and Light Exterior Lights N/S FRONT	replaced globe	888389
878	11/21/2016	629107	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	NEW GRAFFITI CLEANED	887048
878	11/09/2016	626690	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	waiting to have round 3 wifi carried out	885591
878	10/29/2016	622453	Consumables		885215
878	10/29/2016	622453	Body -indicator stalk not working properly	REPLACED STEERING WHEEL AND ROAD TESTED FOR INDICATORS OK	

878	10/28/2016	624577	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced	885215
878	10/21/2016	623157	Consumables		884571
878	10/21/2016	623157	Body -drivers seat loose	tightend drivers seat base checked all operation of the seat . working ok	884118
878	10/20/2016	619275	Consumables		884343
878	10/20/2016	619275	Direct Purchase - BODYWORK		884118
878	10/19/2016	622668	Engine - coolant leak	Creditor #:\VB-ECOAST EASTCOAST TRUCK & BUS P/O #:\O178309 Receiving #:\186015 Date :2016-10-20 rectify drive window glass coming out of the frame as required	882960
878	10/19/2016	622453	WHEEL STEERING WHEEL NEW SC	tightened all hose clamps to header tank	884343
878	10/18/2016	622453	Body -indicator stalk not working properly	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O179733 Receiving #:\186122 Date :2016-10-24	882960
878	10/18/2016	622453	INDICATOR STALK SCANIA SERIES 4 1402448	replaced u/s indicator stalk . need to order a new steering wheel which has been ordered	882960
878	10/17/2016	622165	Vandalism Vandalism/ Graffiti Interior		882960
878	10/13/2016	621766	Consumables	carried out interior vandelisem painting inside bus	883162
878	10/13/2016	621735	Consumables		883162
878	10/13/2016	621766	Disable seats are not folding up or staying up		882960
878	10/13/2016	621735	Body - disabled seats do not lift up	checked operation of disabled seats . could not fault	882960
878	10/07/2016	620422	INDICATOR STALK SCANIA SERIES 4 1402448	pulled apart and checked all seat compoenauts . could not fault any leaky gas struts.	881850
878	10/06/2016	620422	Elec and Light -left hand indicator will not switch off		881850
878	10/05/2016	619977		r/r indicator stork & test ok	881850
878	10/05/2016	619860	DIRECT PURCHASE - ELECTRICAL	TRANSMISSION CHECK AS PER CHECK LIST trans check completed	881850
878	10/05/2016	602729	Consumables	Creditor #:\VB-ECOAST EASTCOAST TRUCK & BUS P/O #:\O178490 Receiving #:\184870 Date :2016-10-06 carry out rollaway campaign at knox as required - mariano	882000
878	10/05/2016	602729	Consumables		882000
878	10/05/2016	602729	Consumables		882000
878	10/05/2016	602729	FILTER FUEL FILTER SCANIA L94UAB (H7090WK30)		881850
878	10/05/2016	602729	FILTER FUEL FILTER SCANIA SR4 (1393640)		881850
878	10/04/2016	619860	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	roll away provention campaign carried out on order -O178490 at knox - mariano carried this out when bus was at bodyshop for drivers window repair.	881850
878	09/29/2016	619275	Consumables		881850
878	09/29/2016	619275	Drivers window frame has come off	repaired carried out for drivers window at knox bodyshop on order - O178309	881850
878	09/27/2016	618508	Consumables		881850
878	09/27/2016	618508	Flouro		881286
878	09/27/2016	618508	Mechanic entered - Elec and Light Interior Lights no driver	replaced globe checked operation . working ok	881286
878	09/26/2016	617885		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS - service complete	881286
878	09/26/2016	617885		VEHICLE SAFETY INSPECTION - service complete	881286
878	09/26/2016	618104	carry out n/s/r retorque as required	carried out retorque as required on n/s/r wheels nut as required	881286
878	09/26/2016	617885	Consumables		881623
878	09/26/2016	617885	Consumables		881623
878	09/26/2016	617885		CARRY OUT A SERVICE AS PER CHECK LIST - service complete	881286
878	09/24/2016	617928	TYRE 295/80R22.5 RECAP		881286
878	09/24/2016	617928	Mechanic entered - Wheels and Tyres Worn	removed off side rear inner tyre replaced with new re tread and torqued all wheels	881286
878	09/19/2016	616506	EXPANSION TANK C/FILL 40N0805	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O177349 Receiving #:\184005 Date :2016-09-26 EXPASION TANK	881490
878	09/17/2016	616506	Mechanic entered - Fluid Leaks Rear of bus pin hole coolant	filled up coolant road tested and found header tank leaking. needs replaced replaced header tank filled coolant test drove vehicle and re checked levels all ok	880586
878	09/15/2016	616108	Mechanic entered - Brakes Other brakes feel spongy	checked linings for condition all ok 80 % front and 70 % rear . adjusted all brake and checked condition of slack adjustors . road tested brake tested and checked operation of retarder . all operation is ok	879156
878	09/14/2016	615876	Consumables		880299
878	09/14/2016	615876	Mechanic entered - Elec and Light Exterior Lights O/S FRONT	secured the indicator	879156
878	09/07/2016	613912	NR TYRE DISPOSAL	Creditor #:\VB-TYR002 TYRES4U P/O #:\O176396 Receiving #:\182722 Date :2016-09-08	878930
878	09/07/2016	613912	Balance Steer Tyres	Creditor #:\VB-TYR002 TYRES4U P/O #:\O176396 Receiving #:\182722 Date :2016-09-08	878930
878	09/07/2016	613912	295/80R22.5 DOUBLE COIN R660	Creditor #:\VB-TYR002 TYRES4U P/O #:\O176396 Receiving #:\182722 Date :2016-09-08	878930
878	09/07/2016	614481	RETENSION NSF WHEEL NUTS	carried out retorque as required n/s/f	878552
878	09/03/2016	613912	TYRE 295/80R22.5 NEW		877695
878	09/03/2016	613912	Mechanic entered - Wheels and Tyres Worn N/S/F SIDE WALL DA	FITTED NSF TYRE AND TENSIONED THE WHEEL NUTS	877695
878	09/01/2016	613507	Vandalism Vandalism/ Graffiti Interior	Graffiti removed.	877695
878	09/01/2016	612014	Direct Purchase - MECHANICAL	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O175633 Receiving #:\184349 Date :2016-09-28 483182 COOLANT HOSE	881850
878	08/31/2016	613393	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	877493
878	08/30/2016	613122	Consumables		877695
878	08/30/2016	613122	Please remove old poster and fit new Legacy poster	Replace Poster	877493
878	08/27/2016	612517	Mechanic entered - Fluid Leaks Rear of bus coolant leak	tightend nuts for theirmostat housing road tested . checked coolant . all ok	877016
878	08/25/2016	612014	Engine - coolant leak	removed coolant hose and ordered	876691
878	08/25/2016	612014	Engine - coolant leak	replaced coolant hose & fill coolant. ok.	876691
878	08/23/2016	604870	Direct Purchase - MECHANICAL	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:\O175342 Receiving #:\181980 Date :2016-08-30 repair fault with engine cylinder number 5 as required	877493
878	08/17/2016	610385	Consumables		875721
878	08/17/2016	610385	PERFORM CAMPAIGN 04/16 DRIVERS WALLETs AND MAP POCKET INSTA	Campaign completed.	875495
878	08/11/2016	609341	Wheels and Tyres - carry out n/s/r retorque	carried out retorque as required	874601
878	08/10/2016	609214	TYRE 295/80R22.5 RECAP		874601
878	08/10/2016	609214	Wheels and Tyres - rear tires worn	FIT NEW N/S/R/O TIRE AND TORQUED TO 650NM	874601
878	08/09/2016	608891	Consumables		874601
878	08/09/2016	608891	GLOBE 24V 75/70W H4		874299
878	08/09/2016	608891	NS Headlight low beam n/w	replaced globe	874299
878	08/01/2016	604870	Engine - noisy	repaired at scania . cylinder 5 and cylinder 1 required new head valves . and also fuel stop solenoid was replaced	871861
878	08/01/2016	602805	Consumables		873677
878	08/01/2016	602805	Direct Purchase - BODYWORK	Creditor #:\VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:\O172190 Receiving #:\181976 Date :2016-08-30 11750 GAS STRUT	877493
878	07/17/2016	603173	Consumables		873031
878	07/17/2016	603173	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	carried out campaign as required	871861
878	07/14/2016	603928	Elec and Light - o/s head light globe u/s	replaced globe	872617
878	07/14/2016	603928	GLOBE 24V 75/70W H4		872617
878	07/14/2016	602805	Consumables		873031
878	07/14/2016	602805	osr hatch struts us	replaced gas struts	872617
878	07/11/2016	603276	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	871861
878	07/09/2016	602930	GLOBE & HOLDER 1.2W GREY (966327-9) [BOX 10]		871861
878	07/09/2016	602930	dash gauge lights nw	replaced cluster illumination light globes x 4	871861
878	07/09/2016	602922	Mechanic entered - Elec and Light Exterior Lights n/s front	replaced nsf side indicator assy	871861
878	07/09/2016	602922	INDICATOR SIDE INDICATOR R/H		871861
878	07/08/2016	602729		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	871861
878	07/08/2016	602729		VEHICLE SAFETY INSPECTION	871861
878	07/08/2016	602805	osr hatch struts us	parts ordered	871861
878	07/08/2016	602729	Consumables		872389
878	07/08/2016	602729	Consumables		872389
878	07/08/2016	602729	Consumables		872389
878	07/08/2016	602729	Consumables		872389
878	07/08/2016	602729	Filter ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1		871861
878	07/08/2016	602729	O-RING LARGE SPINNER FILTER SCANIA (1769799)		871861
878	07/08/2016	602729	O-RING SPINNER FILTER SCANIA (1769798)		871861
878	07/08/2016	602729	FILTER SCANIA SR4 FUEL 1393640		871861
878	07/08/2016	602729	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		871861
878	07/08/2016	602729		CARRY OUT B SERVICE AS PER CHECK LIST	871861
878	07/08/2016	602729	Consumables		872389
878	07/08/2016	602729	FILTER FUEL SCANIA SR4(H17WK04)		871861

878	07/08/2016	602729	Consumables			872389
878	07/08/2016	602729	Consumables			872389
878	07/08/2016	602729	Consumables			872389
878	07/08/2016	602729	Consumables			872389
878	07/08/2016	602729		CARRY OUT A SERVICE AS PER CHECK LIST		871861
878	07/06/2016	602375	Consumables			872015
878	07/06/2016	602375	Body - vomit on seat	replaced pax seat base		871861
878	07/06/2016	602375	CENTRA CUSHION CLIP RH			871861
878	07/06/2016	602375	CENTRA CUSHION CLIP LH			871861
878	07/06/2016	602375	ALN CAP SCR 4 x 16			871861
878	07/06/2016	602375	SINGLE SEAT BASE			871861
878	07/01/2016	600503	AIR CONDITIONING REPAIR	Creditor #;VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O171158 Receiving #:177874 Date :2016-07-06 carry out AC-B service as required		871303
878	06/28/2016	600503		CARRIED OUT A/C - B SERVICE AS PER CHECK LIST BY COLD DRIVE ON 28/06/2016 PO#: O171158		870325
878	06/28/2016	600566	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	A/C - A and B DONE ON 28/06/2016 BY COLD DRIVE WO 600503.		870325
878	06/19/2016	598190	Please remove any old poster and fit new A3 poster and add	fleet support carried out campaign as required		869024
878	06/16/2016	598305	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	NEW GRAFFITI CLEANED		869024
878	06/11/2016	597193	Wipers n/w	disconnected wiper motor plug and reconnected; started working. could be the wiper motor. need to keep eye out		867759
878	06/07/2016	596137	Mechanic entered - Vandalism Vandalism/ Graffiti Interior L	painted interior of bus over graffiti		866702
878	05/30/2016	594712	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti damage cleaned		865763
878	05/26/2016	549898	KIT BUSH V BAR SCANIA			823415
878	05/12/2016	591236		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		862192
878	05/12/2016	591236		VEHICLE SAFETY INSPECTION safety completed		862192
878	05/12/2016	591236	Consumables			862570
878	05/12/2016	591236	Consumables			862570
878	05/12/2016	591236	Consumables			862570
878	05/12/2016	591236	Consumables			862570
878	05/12/2016	591236	Consumables			862570
878	05/12/2016	591236		CARRY OUT A SERVICE AS PER CHECK LIST service completed		862192
878	05/01/2016	584982	BRAKE DRUM	Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O165656 Receiving #:174871 Date :2016-05-27		865042
878	05/01/2016	584982	WHEEL BEARING	Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O165656 Receiving #:174871 Date :2016-05-27		865042
878	04/30/2016	589193	TUBES FLUORESCENT 18W			860432
878	04/30/2016	589193	Mechanic entered - Elec and Light Interior Lights REAR SALO	DONE BY CDF ON 23/04/2016		860432
878	04/15/2016	586806	Check brake pads or retarder - driver has to step hard on t	checked the brake linings; frt 70 rears 40. road/brakes tested; well		858466
878	04/14/2016	586500	ANNUAL SAFETY INSPECTION SERIAL #	RSI carried out by Fleet check po O166095		858338
878	04/14/2016	586500	ROAD WORTHY INSPECTION	Creditor #;VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O166095 Receiving #:172321 Date :2016-04-20 carry out bic inspection as required		859010
878	04/14/2016	586500	PRE ANNUAL SAFETY INSPECTION CHECK			858338
878	04/14/2016	586466	Mechanic entered - Engine Other engine top coolant hose clam	tightened engine top coolant hose clamp ok		858338
878	04/14/2016	586466	GLOBE 24V SCHOOL LAMP			858338
878	04/14/2016	586466	Mechanic entered - Elec and Light Other school light not wor	replaced SCHOOL LIGHT GLOBE.		858338
878	04/12/2016	585844	carry out front retorque as required	carried out retorque as required		857187
878	04/10/2016	584748	Mechanic entered - Vandalism Vandalism/ Graffiti Interior I	painted interior of bus over graffiti		857187
878	04/08/2016	585316	Breakdown#:32482 - Ops Entered - Breakdown - Breakdown Road	repaired carried out on work order - 584982		857187
878	04/08/2016	584982	Direct Purchase - MECHANICAL	Creditor #;VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:O165717 Receiving #:171609 Date :2016-04-13 radius grind and machine brakes as required		857831
878	04/08/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	replaced FRONT BOTH BRAKE DURMS X2 INSTALLED FRONT BOTH HUBSTIGHTENED FRONT BOTH TORQUE HUBS NUTS 1000nM TIGHTENED FRONT BOTH WHEEL NUTS 600Nm ADJUSTED FRONT BRAKE LININGS ROAD TESTED OK		857187
878	04/07/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	brakes radius grind and machine drums as required		857187
878	04/07/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	removed front both brake durms removed hubs bearingcleaned all parts. replaced front both hubs bearing x2		857187
878	04/07/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	ordered front brake drums x 2 and wheels bearings x 2 through scania - LDM		857187
878	04/06/2016	584838	LAMP LED TURN			857187
878	04/06/2016	584838	n/s/r top indicator not working	remove rewire and fit new LED blinker assembly		857187
878	04/06/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	removed front both brake liningsdurms front both hubs bearing x2 u/sfront both brake durms x2 order please		857187
878	04/06/2016	584982	Mechanic entered - Brakes Foot_Brakes Pulling Brakes pulling	Carry out road test with driver. check over brakes on pit. carry out brake adjustment on the pit. Carry out road test. vehicle still pulling. bring back onto pit and check adjustmnet slackers are ok and not de adjusting. Check over and suspect issue with brake linnings advise regrind.		857187
878	03/12/2016	579451	air leak at air valve near diff	replaced quick release valve located at diff		854322
878	03/10/2016	579451	air spring	Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O163598RET Receiving #:170518 Date :2016-03-23		855844
878	03/10/2016	579451	air elbow	Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O163598RET Receiving #:170518 Date :2016-03-23		855844
878	03/04/2016	579451	Direct Purchase - MECHANICAL	Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O163598 Receiving #:169590 Date :2016-03-09 supply relay valve x 1 and air bags x 2		853795
878	03/03/2016	579356		TRANSMISSION CHECK AS PER CHECK LIST transmission checked ok		852630
878	03/03/2016	579356		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheels tensioned		852630
878	03/03/2016	579356		VEHICLE SAFETY INSPECTION safety completed		852630
878	03/03/2016	579356	A/C Heating - air con not working	checked a/c comp clutch is on and blowers ok. road tested amb tmp 26C air inlet at roof filter 26 at start and dropped down to 17C during road test. ac outlet tmp 15C		852630
878	03/03/2016	579356	A/C N/W	double entry		852630
878	03/03/2016	579451	air leak at air valve near diff	2 air bags and relay valve ordered through scania on order - O163598		852630
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356	FILTER FUEL VOLVO B7/ B12 (20450423)			852630
878	03/03/2016	579356	O-RING LARGE SPINNER FILTER SCANIA (1769799)			852630
878	03/03/2016	579356		CARRY OUT B SERVICE AS PER CHECK LIST b service completed		852630
878	03/03/2016	579356	O-RING SPINNER FILTER SCANIA (1769798)			852630
878	03/03/2016	579356	FILTER FUEL SCANIA SR4(H17WK04)			852630
878	03/03/2016	579356	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			852630
878	03/03/2016	579356	FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1			852630
878	03/03/2016	579356				852630
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356	Consumables			852902
878	03/03/2016	579356		CARRY OUT A SERVICE AS PER CHECK LIST a service completed		852630
878	03/01/2016	573554	SLACK ADJUSTER	Creditor #;VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O160845 Receiving #:168978 Date :2016-03-01		852404
878	02/20/2016	576693	The Campaign requires all Bus destinations systems to be in	campaign completed		850605
878	02/08/2016	574562	Engine - possibly faulty injector - blowing smoke - sounds r	ROAD TESTCOULD NOT FAULT.		847677
878	02/04/2016	574162	FRT DOOR AIR LEAKING	REPAIRED THE FRT DOOR AIR LEAK BY REPLACING AIR FITTING		847677
878	02/02/2016	573554	Mechanic entered - Brakes Other BRAKES SPUNGY.	fitted osr slack adjuster and road tested ok		846828
878	02/02/2016	573554	Brakes - brakes needs adjusting - sometimes gearbox does not	ADJUST BRAKESFOUND O/S/R SLACK ADJUSTER U/SREMOVEORDER NEW.		846828
878	02/01/2016	549898	washer sealing SC sump	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O157309 Receiving #:163197 Date :2015-10-30		837415
878	02/01/2016	549898	MAGNETIC PLUG	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O157309 Receiving #:163197 Date :2015-10-30		837415
878	01/31/2016	572725	Consumables			847398
878	01/31/2016	572725	Consumables			847398
878	01/31/2016	572630	Consumables			847398
878	01/31/2016	572630	Consumables			847398
878	01/31/2016	572725	Camapign 20/15 Audit & Update of Safety Decals.Requires a	carried out campaign as required		846828
878	01/31/2016	572630	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	carried out campaign as required		846828
878	01/11/2016	569279	Engine - overheating	checked the temperature; was @ 90C. Cleaned the radiator with soap and steam. road tested for 40mins;tmp stays @ 80C.		844538
878	01/05/2016	568218	STOP & TAIL LED COMPLETE			842721
878	01/05/2016	568218	rear park light out	replaced u/s stop/tail LED light checked operation of all lights all ok		842721

878	01/03/2016	567489	Consumables			843589
878	01/03/2016	567489	Consumables			843589
878	01/03/2016	567489	Campaign 23_15 A3 Poster Change	carried out campaign as required		842721
878	12/24/2015	566941	Consumables			843110
878	12/24/2015	566941	Wheels and Tyres - carry out rear retorque as required	carried out retorque as required		842721
878	12/19/2015	565834	OIL DIPSTI			842089
878	12/19/2015	565834	Engine - dipstick u.s	replaced dipstick		842089
878	12/17/2015	565409		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		841746
878	12/17/2015	565409		VEHICLE SAFETY INSPECTION		841746
878	12/17/2015	565489	Consumables			842089
878	12/17/2015	565489	TYRE RECAP 295/80R22.5			841746
878	12/17/2015	565489	Mechanic entered - Wheels and Tyres Worn	replaced both os rear tyres		841746
878	12/17/2015	565492	Mechanic entered - Elec and Light Other	fixed brake light connection		841746
878	12/17/2015	565490	Mechanic entered - Elec and Light Exterior Lights	cleaned headlight		841746
878	12/17/2015	565491	Consumables			842089
878	12/17/2015	565491	Consumables			842089
878	12/17/2015	565491	Mechanic entered - Body Passenger Seat Torn	tightened seats		841746
878	12/17/2015	565409	Consumables			842089
878	12/17/2015	565409	Consumables			842089
878	12/17/2015	565409	Consumables			842089
878	12/17/2015	565409		CARRY OUT A SERVICE AS PER CHECK LIST		841746
878	12/03/2015	562875	Consumables			839723
878	12/03/2015	562875	Consumables			839723
878	12/03/2015	562875	Body Drivers Seat Controls driver seat lower support is b	operate all seat controlscould not fault.		839192
878	12/01/2015	555858	DIRECT PURCHASE GLASS	Creditor #;VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O157503 Receiving #:165518 Date :2015-12-22 replace nsr window glasses as required		842240
878	11/27/2015	561454	DIRECT PURCHASE - VANDALISM	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O158614 Receiving #:164442 Date :2015-12-02 paint interior of bus over graffeti as required		839192
878	11/27/2015	561451	Direct Purchase - BODYWORK	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O158610 Receiving #:164443 Date :2015-12-02 repair accident damage to bus as required by knox bodyshop - for accident number # 41968		839192
878	11/26/2015	561454	Vandalism Vandalism/ Graffiti Interior	carried out by knox bodyshop on order - O158614		838218
878	11/26/2015	561451	supply purchuse order to know bodyshop for damage	repaired at knox bodyshop under work order - O158610		838218
878	11/24/2015	560863	AIR CONDITIONING REPAIR	Creditor #;VB-COLO04 COLD DRIVE AIR CONDITIONING P/O #:O158516 Receiving #:164428 Date :2015-12-02 REPLACED ALL 8 BLOWER MOTORS AS REQUIRED		838763
878	11/24/2015	560863	A/C BLOWERS NW	JOB WAS DONE BY COLD DRIVE ON 24/11/2015 PO O158516		837639
878	11/24/2015	560669	Mechanic entered - Elec and Light Exterior Lights o/s headli	secure plug to globe.		837639
878	11/23/2015	560417	Consumables			837865
878	11/23/2015	560417	Remove Old Poster and Fit new All Night Public Transport Po	carried out campaign as required		837639
878	11/01/2015	555858	Ops Entered - Accident - Bus Hit Stationary Object - Route	bus was repaired at knox bodyshop		837412
878	10/25/2015	554732	Complete task as instructed in Fleet Campaign 09/15	carried out campaign as required		836108
878	10/21/2015	545780	A/C N/W	double entry for same dvr		836108
878	10/20/2015	545780	AIR CONDITIONING REPAIR	Creditor #;VB-COLO04 COLD DRIVE AIR CONDITIONING P/O #:O157190 Receiving #:163068 Date :2015-10-28 rectify a/c not working as required		837412
878	10/20/2015	554331	GLOBE STOP/TAIL O/SET 24V 21W			836108
878	10/20/2015	554331	Mechanic entered - Elec and Light Exterior Lights O/S HEADLI	FIT GLOBE.		836108
878	10/15/2015	553382	Offside low beam inop.	checked operation of low beam headlights could not fault		835319
878	10/10/2015	552587	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	carried out campaign as required		823422
878	10/09/2015	549898	diff seal leaking	replaced diff pinion nuttightened driver shaft bolts.		823422
878	10/09/2015	549898	MIRROR-INT 195MM X143MM	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O156470 Receiving #:162073 Date :2015-10-09 MM		834791
878	10/09/2015	540331	Direct Purchase - MECHANICAL	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O156470 Receiving #:162073 Date :2015-10-09 Festo Inv 4202023128		834791
878	10/09/2015	549898	PINION NUT SCANIA R660 DIFF			823422
878	10/09/2015	549898	SEAL PINION DIFF S/3	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O156470 Receiving #:162073 Date :2015-10-09 MM		834791
878	10/09/2015	549898	KIT BUSH V BAR SCANIA	Creditor #;VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O156470 Receiving #:162073 Date :2015-10-09 MM		834791
878	10/09/2015	549898	BUFFING DISC 50MM			823422
878	10/09/2015	549898	FIBRE DISC			823422
878	10/09/2015	549898	Body - fuel tank bracket cracked	REMOVED WIRESWELDING FUEL TANK FRAMEPUT BACK WIRES.		823422
878	10/08/2015	551911	Vandalism Vandalism/ Graffiti Interior	repainted interior of bus		823422
878	10/08/2015	549898	diff seal leaking	REMOVED DRIVER SHAFT replaced DIFF OIL SEAL DIFF PINION NUT ORDER. NOW removed DIFF OINION NUT.		823422
878	10/08/2015	549898	THERMOSTAT L94 K230 40A3502			823422
878	10/08/2015	549898	SEAL THERMOSTAT HOUSING K230 L94			823422
878	10/08/2015	549898	Engine - thermostat housing leaking	replaced THERMOSTATGASKET.		823422
878	10/07/2015	549898	Suspension - V rod taper bush u/s	checked condition of V rod . it is road worthy and with		829696
878	10/07/2015	545780	Drv entered - AC Heating Not Cooling	a/c repairs on order number - O157190 by cold drive for installtion of new a/c condensor fan motors		829696
878	10/04/2015	550052	Replace A3 poster with Victorian Seniors Festival Poster	carry out campaign as required		829696
878	09/29/2015	549492		checked the interior cctv and lights.		832707
878	09/29/2015	549492		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		832707
878	09/29/2015	549492		VEHICLE SAFETY INSPECTION		832707
878	09/29/2015	540678	GLOBE 24V 21W SINGLE CONTACT HLR2421			823422
878	09/29/2015	540678	Mechanic entered - Elec and Light Other reverse light globe	replaced reverse light globe.		823422
878	09/29/2015	540678	SWITCH- STOP-YELLOW			823422
878	09/29/2015	540678	Mechanic entered - Elec and Light Other rear pax bell switch	replaced rear pax bell switch.		823422
878	09/29/2015	549492	Mechanic entered - Elec and Light Other 2way nw	checked and found voltage reducer faulty. fitted a 2nd hand inverter removed from bus 882(CCTV upgraded)		832707
878	09/29/2015	549492	Consumables			832914
878	09/29/2015	549492	Consumables			832914
878	09/29/2015	549492	FILTER FUEL SCANIA L94UAB (H7090WK30)			832707
878	09/29/2015	549492	FILTER AIR DRYER SCANIA SR4 (1393551)(49G8709HALDEX)			832707
878	09/29/2015	549492	FILTER HYD COOLING FAN SCANIA SR3 (E90HD149)			832707
878	09/29/2015	549492	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-O-153468			832707
878	09/29/2015	549492	FILTER AIR OUTER SCANIA SR3 SR4 395773 0395773 E218L			832707
878	09/29/2015	549492	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)			832707
878	09/29/2015	549492	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			832707
878	09/29/2015	549492	O-RING LARGE SPINNER FILTER SCANIA (1769799)			832707
878	09/29/2015	549492	O-RING SPINNER FILTER SCANIA (1769798)			832707
878	09/29/2015	549492	FILTER FUEL SCANIA SR4(H17WK04)			832707
878	09/29/2015	549492		C SERVICE AS PER CHECK LIST		832707
878	09/29/2015	549492	Consumables			832914
878	09/29/2015	549492	Consumables			832914
878	09/29/2015	549492		B SERVICE AS PER CHECK LIST		832707
878	09/29/2015	549492	Consumables			832914
878	09/29/2015	549492	Consumables			832914
878	09/25/2015	549135	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	A SERVICE AS PER CHECK LIST		832707
878	09/22/2015	548164	Elec and Light Indicators Not Working N/S bottom front i	Completed 25/09/15		832505
878	09/15/2015	547015	RELAY 24V/20AMP	replaced globe		831972
878	09/15/2015	547015	Brakes - door brakes do not come on when you open the doors	traced and found relay for door brakes u/s . replaced relay . checked operation of door brakes now working		830478
878	09/02/2015	544775	Switch door green 22mm 4 pin			830478
878	09/02/2015	544775	passenger doors n/w	traced and found front door emergency exit switch fault removed n/s/f corner of bus. replaced switch and refit new switch reassembled bus checked operation of doors		823422
878	09/02/2015	544929	Breakdown- Doors not closing stuck at intersection.	Attended breakdown site setup traffic mang.Reset system doors still not operating.Accessed elec panel and disabled door inerlock system.causing major traffic jam.follwed bak to depot.		823422

[illegible]

878 03/25/2015	517857 Suspension - o/s/f torque rod bush top u/s	replaced o/s/f torque rod bushings x2	801074
878 03/25/2015	517857 PULLEY IDLER SCANIA		801074
878 03/25/2015	517857 Engine belt idler u/s	replaced ENGINE BELT IDLER.	801074
878 03/25/2015	517857 battery tray u/s	welded a plate to stop battery sliding out to the master solenoid.	801074
878 03/25/2015	517857 GLOBE FESTOON 24V 5W		801074
878 03/25/2015	517857 both front park lights n/w		801074
878 03/25/2015	517857 BATTERY 12V 800CC		801074
878 03/25/2015	517857 batterys u/s x 2		801074
878 03/25/2015	517857 battery tray u/s		801074
878 03/25/2015	517857 o/s/f park light n/w		801074
878 03/25/2015	517857 o/s/r corner structure requires welding		801074
878 03/25/2015	517857 n/s/f jumper seat cover loose		801074
878 03/25/2015	517857 Air System - o/s/f brake hose needs securing		801074
878 03/25/2015	517771	ANNUAL BUS FIRE SAFETY INSPECTION	801074
878 03/25/2015	517771 FILTER AIR OUTER SCANIA SR3 SR4 (395773)(0395773)		801074
878 03/25/2015	517771		801074
878 03/25/2015	517771 FILTER FUEL SCANIA L94UAB (H7090WK30)		801074
878 03/25/2015	517771 FILTER FUEL SCANIA SR4(H17WK04)		801074
878 03/25/2015	517771 FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)		801074
878 03/25/2015	517771		801074
878 03/25/2015	517771 O-RING LARGE SPINNER FILTER SCANIA (1769799)	B SERVICE AS PER CHECK LIST	801074
878 03/25/2015	517771 O-RING LARGE SPINNER FILTER SCANIA (1769799)		801074
878 03/25/2015	517771 FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		801074
878 03/25/2015	517771 Consumables		801378
878 03/25/2015	517771 Consumables		801378
878 03/25/2015	517771	A SERVICE AS PER CHECK LIST	801074
878 03/25/2015	517771 Consumables		801378
878 03/25/2015	517771 Consumables		801378
878 03/20/2015	517141 Security CCTV System Faulty - HAS NOT BEEN RECORDING SINC	new cctv system was fitted at Volgren on 20-3-15 - was told by Sean Banfeild that all the new systems were carried out on the one order number provided by paul bevan to Volgren .	800222
878 03/14/2015	514655 Mechanic entered - Body & Acc Other bin lid hanging off bus.	repair hinge and revirt bin lid to hinge	798956
878 03/05/2015	514655 Mechanic entered - Body & Acc Other bin lid hanging off bus.	try to secure lid could not remove lid .	796842
878 03/02/2015	514000 carry out a/c-a service as required	a/c-a service carried out by cold drive on - O148928	796524
878 02/23/2015	512656 Passenger Doors front door not closing properly	adjusted air pressures . checked operation ok	794752
878 02/19/2015	512247 Ticket Equip Not PrintingKeeps feeding printer jam cann	to be fixed by myki	794690
878 02/19/2015	512247 Lift error light came on yellow light switched off power	ROAD TESTED NOT FAULT.OKCHECKED SUSPENSIONDASH LIGHT.OK	794690
878 02/19/2015	512247 FESTOON 24V 10W 7550		794690
878 02/19/2015	512247 Clearance light out Top O/S	replaced TOP CLEARANCE LIGHT GLOBE.	794690
878 02/11/2015	510703 Hose trans cooling	Creditor #-VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #-O147946 Receiving #:150753 Date :2015-02-11	793058
878 02/10/2015	510703 COOLANT PREMIX NF48 (use L830)		792670
878 02/10/2015	510703 HEADER TANK FILLER CAP 1403954		792670
878 02/10/2015	510703 Eng Cool LeakingBreakdown van attendedHole in hose con	road tested. ok	792670
878 02/10/2015	510703 Eng Cool LeakingBreakdown van attendedHole in hose co	REMOVED OLD HOSE AND REFFITTED WITH NEW ONE AND TOPPED UP COOLENT ROAD TESTED THE BUS OK..	792670
878 02/04/2015	0 Imported Service History	Imported Service History	791225
878 02/04/2015	509758	Perform Safety Inspection as per checklist	791225
878 02/04/2015	509800 Suspension - both front air bag u/s	replaced front n/s o/s air bag.	791225
878 02/04/2015	509800 Suspension - front D rubbers u/s	replaced front 'D' rubbers.	791225
878 02/04/2015	509800 Suspension - both front air bag u/s	replaced air hose joiner air fittings. replaced airbags. secured elect hatch and lauggage carrier hatch.	791225
878 02/04/2015	509800 FRONT AIRBAG 35CMG0250HD SP0002A		791225
878 02/04/2015	509800 BUSH SWAY BAR FRONT K230		791225
878 02/04/2015	509800 'GIVE WAY' DECAL 240MM X 225MM		791225
878 02/04/2015	509800 LAMP ROOF CLEAR		791225
878 02/04/2015	509800 GLOBE 24V 10W S/C		791225
878 02/04/2015	509800 GLOBE FESTOON 24V 18W		791225
878 02/04/2015	509800 Engine belt roller u/s	replaced engine belt roller. secured serpentine belt and checked for operation - ok.	791225
878 02/04/2015	509800 ROLLER		791225
878 02/04/2015	509800 front top emergency exit light n/w	replaced globe. replaced wiring terminals.	791225
878 02/04/2015	509800 dash light n/w	replaced dash light globes. secured dash panel.	791225
878 02/04/2015	509800 o/s/f park light n/w	replaced n/s and o/s park lights and indicator lights.	791225
878 02/04/2015	509758 COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	carried out audit as required	791225
878 02/04/2015	509800 missing decals	replaced decal.	791225
878 02/04/2015	509758 Consumables		791662
878 02/04/2015	509758 Consumables		791662
878 02/04/2015	509758 USE ONLY PART # L816 GREASE LIPLX HD2 (LU5)		791225
878 02/04/2015	509758 COOLANT PREMIX NF48 (use L830)		791225
878 02/04/2015	509758 USE ONLY PART # L807 BP MULTIFLEET /Ltr		791225
878 02/04/2015	509758	Tension ALL Wheel Nuts to OEM Specs	791225
878 02/04/2015	509758	A - Service & Bus Safety Inspection	791225
878 01/27/2015	508401 Passenger Doors - Doors releases air and open randomly.	checked frt and rear doors reed switches wiring and plugs. road testedcould not locate any fault	789147
878 01/27/2015	508401 Air System - front door leaking air as required	checked frt and rear doors reed switches wiring and plugs. road testedcould not locate any fault	789147
878 01/23/2015	508125 Ops Entered - Fault - Engine Stalling - Bus at depot now	CHECK FOR FUEL LEAKS NIL ROAD TEST COULD NOT FAULT.	789147
878 01/19/2015	507381 CENTRA CUSHION CLIP LH		788550
878 01/19/2015	507381 CENTRA CUSHION CLIP RH		788550
878 01/19/2015	507381 Rear eight seats are damaged	replaced 9 seat bases and cleaned graffiti.	788550
878 01/08/2015	500671 Direct Purchase - BODYWORK	Creditor #-VB-ECOAST EASTCOAST TRUCK & BUS P/O #-O146327 Receiving #-:149333 Date :2015-01-12 Carry out repairs on drivers cabin door as required	787079
878 12/29/2014	503912 Elec & Light - hazard light switch is missing	fit hazard switch from 880 .	782958
878 12/16/2014	502367 USE ONLY PART # L816 GREASE LIPLX HD2 (LU5)		780800
878 12/16/2014	502367 COOLANT PREMIX NF48 (use L830)		780800
878 12/16/2014	502367 USE ONLY PART NUMBER L814 TEXAMATIC 1888		780800
878 12/16/2014	502367 USE ONLY PART # L807 BP MULTIFLEET /Ltr		780800
878 12/16/2014	502367 O-RING LARGE SPINNER FILTER SCANIA (1769799)		780800
878 12/16/2014	502367 O-RING SPINNER FILTER SCANIA (1769798)		780800
878 12/16/2014	502367 FILTER ZF TRANS ECOMAT(4139 298 038 01)(E39HD119)		780800
878 12/16/2014	502367 FILTER FUEL SCANIA SR4(H17WK04)		780800
878 12/16/2014	502367 FILTER FUEL SCANIA L94UAB (H7090WK30)		780800
878 12/16/2014	502367 FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		780800
878 12/16/2014	502367	Perform Safety Inspection as per checklist	780800
878 12/16/2014	502480 Engine - coolant leak	tighten clemp	780800
878 12/16/2014	502480 Engine - coolant leak	rectify coolant leak. tight coolant hose clamps. secured hoses with cable ties.	780800
878 12/16/2014	502480 missing drivers door	replaced drivers door drilling hingex2 bolts x8	780800
878 12/16/2014	502480 FLUSH HINGE R/H		780800
878 12/16/2014	502480 SINGLE SEAT BASE		780800
878 12/16/2014	502480 pax seat cusion u/s x 2	replaced pax seat cushionx2	780800
878 12/16/2014	502480 missing drivers door	assit MYD on fitting and alignment on driver's door.	780800

878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367	HYDRAULIC TORQUE FLUID 414	Torque fluid		780800
878	12/16/2014	502367	FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)	Filter ZF Trans		780800
878	12/16/2014	502367	FILTER FUEL SCANIA SR4(H17WK04)	Fuel Filter		780800
878	12/16/2014	502367	O-RING KIT OIL SPINNER FILTER SCANIA	Kit . filter Cent		780800
878	12/16/2014	502367	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	Filter Oil		780800
878	12/16/2014	502367	ENGINE OIL DELO 400LE 15W40 (LU18)	Engine Oil		780800
878	12/16/2014	502367		Tension ALL Wheel Nuts to OEM Specs		780800
878	12/16/2014	502367		A - Service & Bus Safety Inspection		780800
878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367	Consumables			0
878	12/16/2014	502367				780800
878	12/16/2014	502367		Tension ALL Wheel Nuts to OEM Specs		780800
878	12/16/2014	502367		A - Service & Bus Safety Inspection		780800
878	12/15/2014	502084	A3 Poster Change	Fit by Fleet Support Staff		780800
878	12/13/2014	501968	Passenger Doors closing slow driver cabin door missing	could not fault pax doors pax buzzer n/w replaced packs button wop for drivers door		780800
878	12/12/2014	500366	BUSH TORQUE ROD SCANIA/MERC	Creditor # :VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O # :O146060 Receiving #:148482 Date :2014-12-12		780800
878	12/09/2014	500366	trans accumulator cylinder leaking	replaced trans accumulator cylinder piston.		780169
878	12/08/2014	500366	BUSH TORQUE ROD SCANIA/MERC			779628
878	12/08/2014	500366	Suspension - top front torque rod bushes u/s	removed front n/s top toque rod bushings. replaced front n/s top toque rod bushings.		779628
878	12/08/2014	500671	drivers cabin door requires repairs	drivers cabin door repaired at knox bodyshop on order number - O146327		779628
878	12/06/2014	500559	Wheel nut retention - o/s/r	carried out wheel nut retention on o/s/r		779628
878	12/05/2014	500366	Whls & Tyres - o/s/r tyres u/s	replaced tyres		779628
878	12/05/2014	500366	Suspension - n/s/f air bag u/s	replaced rear n/s/f air bag.		779628
878	12/05/2014	500366		fixed front o/s park light wires.		779628
878	12/05/2014	500366	Engine oil leak from oil switch	fixed engine oil switch.		779628
878	12/05/2014	500366	rear emergency hammer globe u.s	fixed hammer light wire.		779628
878	12/05/2014	498406	Body & AccCabin Door hinge is broken	installed drivers cabin door		777575
878	12/05/2014	500319	Consumables			0
878	12/05/2014	500319	Consumables			0
878	12/05/2014	500319	Consumables			0
878	12/05/2014	500319		Tension ALL Wheel Nuts to OEM Specs		779628
878	12/05/2014	500319		A - Service & Bus Safety Inspection		779628
878	11/25/2014	498406	Body & AccCabin Door hinge is broken	remove door drill out hinges door u/s order new door WOP .		777575
878	11/18/2014	497194	Remove Legacy Poster and replace with See Something Say So	Replaced poster as required		775993
878	11/17/2014	496821	Whls & Tyres Soft o/s outer low air	checked all tyres air pressure rear 90psi each and frt 110psi could not fault		775444
878	11/10/2014	495448	Mechanic entered - Engine Won't Start flat batts .	jump start .		774104
878	11/01/2014	492529	Mount A/C Large	Creditor # :VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O # :O144715 Receiving #:147057 Date :2014-10-31		772616
878	11/01/2014	492529	REAR GEARBOX SEAL ZF 4HP500	Creditor # :VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O # :O144715 Receiving #:147057 Date :2014-10-31		772616
878	10/29/2014	493507	SR4 BELT TENSIONER			772043
878	10/29/2014	493507	BELT			772043
878	10/29/2014	493507	SCANIA DRIVE BELT L94 EARLY			772043
878	10/29/2014	493507	Air Cond Belt Replacement - A/C Belt missing.	Alligned a/c compressor replaced belt tensioner belt and a/c belts.		772043
878	10/25/2014	492529	transmission seal leaking	replaced transmission oil seal.		770513
878	10/24/2014	492529	FLUORESCENT TUBES 18W			770513
878	10/24/2014	492529	GLOBE 24V SW			770513
878	10/24/2014	492529	SCANIA DRIVE BELT L94 EARLY			770513
878	10/24/2014	492529	DRIVERS FAN 24V			770513
878	10/23/2014	491916		Perform Safety Inspection as per checklist		770513
878	10/23/2014	492529	Wiper blades u/s	replaced wiper rubbers		770513
878	10/23/2014	492529	Engine belt u.s	replaced eng belt		770513
878	10/23/2014	492529	a/c mount u/s x 2	replaced ac mount		770513
878	10/23/2014	492529	rear door outside light n/w	replaced rear door outside light globe		770513
878	10/23/2014	492529	front door light n/w	replaced frt door roof light fluro		770513
878	10/23/2014	492529	o/s/f jumper seat cover u/s	removed the cover and riverted the cover to the bottomn frame		770513
878	10/23/2014	492529	a/c filter frame u/s	removed the ac inlet air filter and secured the holding frame		770513
878	10/23/2014	491916	Consumables			0
878	10/23/2014	491916	Consumables			0
878	10/23/2014	491916		A - Service & Bus Safety Inspection		770513
878	10/23/2014	491916		Tension ALL Wheel Nuts to OEM Specs		770513
878	10/23/2014	491916		A - Service & Bus Safety Inspection		770513
878	10/23/2014	491916		Tension ALL Wheel Nuts to OEM Specs		770513
878	10/23/2014	491916		A - Service & Bus Safety Inspection		770513
878	10/23/2014	491916		Tension ALL Wheel Nuts to OEM Specs		770513
878	10/20/2014	491916	Elec & Light no driver personal fan n/w			769972
878	10/16/2014	490676	EMERGENCY HAMMER COMPL			769906
878	10/16/2014	490676	Hammer removed	refit o/s/r emergency hammer and base holder. fit with metal wire cable to secure. refit elect. connection.		769906
878	10/13/2014	490676	GLOBE 24V 75/70W H4			769856
878	10/13/2014	490676	Mechanic entered - Elec & Light Headlights N/S HEADLIGHT N/W	FIT GLOBE .		769856
878	10/13/2014	490676	Hammer removed	DISCONNECT HAMMER SWITCH HAMMER TO BE REPLACED .		769856
878	10/08/2014	489696	Complete AM/FM radio saloon speaker modification	carried out speaker campaign modification as required		768988
878	10/03/2014	489210	Remove old decal and fit new Authorised Officers Decal DO N	Completed as required		767388
878	09/18/2014	486364	Body & Acc - Drivers cabin door not closing - opens when go	repositioned drivers door into correct postion		763030
878	09/17/2014	483979	rear sway rubbers bushes u/s	removed & replaced rear sway d lubbers		763030
878	09/06/2014	484382	Wheel nut retention	retensioned wheel nuts		761178
878	09/05/2014	483979	SCHOOL LIGHT ASSY PANEL MOUNT			761178
878	09/05/2014	483979	SIDE INDICATOR R/H			761178
878	09/04/2014	483823		Perform Safety Inspection as per checklist		761178
878	09/04/2014	483979	n/s/r/o tyre u/s	replaced tires x 2 . tension wheel nuts		761178
878	09/04/2014	483979	n/s/f school light n/w	replaced school light assembly		761178
878	09/04/2014	483979	n/s/f bottom indicator n/w	replaced globe		761178
878	09/04/2014	483956	SCHOOL LIGHT ASSY PANEL MOUNT			761178
878	09/04/2014	483956	n/s/f/t school light n/w	replaced school light assy		761178
878	09/04/2014	483956	n/s/f bottom indicator n/w	removed the old light repaired wiring and fitted new light assy		761178
878	09/04/2014	483956	SIDE INDICATOR R/H			761178
878	09/04/2014	483823	HYDRAULIC TORQUE FLUID 414	Torque fluid		761178
878	09/04/2014	483823	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		761178
878	09/04/2014	483823	O RING FILTER KIT K93	Kit . filter Cent		761178
878	09/04/2014	483823	FILTER OIL K124 / L94UAB (H200W20)2059778	Filter Oil		761178
878	09/04/2014	483823	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		761178
878	09/04/2014	483823	ENGINE OIL DELO 400LE 15W40 (LU18)	Engine Oil		761178

878	09/04/2014	483823	Tension ALL Wheel Nuts to OEM Specs	761178
878	09/04/2014	483823	A - Service & Bus Safety Inspection	761178
878	09/04/2014	483823	Tension ALL Wheel Nuts to OEM Specs	761178
878	09/04/2014	483823	A - Service & Bus Safety Inspection	761178
878	09/02/2014	483433	Remove old A3 poster & replace with Legacy or Penalty Fares	760894
878	08/30/2014	483049	Bus rolls back in gear	760250
878	08/18/2014	480320	GLOBE 24V 21W SINGLE CONTACT	756941
878	08/18/2014	480320	SIDE INDICATOR R/H	756941
878	08/18/2014	480320	Accident Front OS blinker gone and panel damage	756941
878	08/15/2014	480064	GLOBE FESTOON 24V 18W	756941
878	08/15/2014	480064	Elec & Light Indicators front bottom n/s indicator n/w	756941
878	08/04/2014	477962	Lamp SWF Switch LED	754043
878	08/04/2014	477962	Elec & Light - the following switches need new globes; Hazar	754043
878	08/04/2014	477962	Body & Acc - driver cabin door will not close properly due t	754043
878	08/04/2014	477962	Body & Acc - Off side driver cabin sunblind frame needs tigh	754043
878	07/30/2014	476349	nsr frt air bag leaking	753558
878	07/30/2014	477080	Mechanic entered - Air System Leaking	753558
878	07/29/2014	476349	Valve Solenoid Accumulator	753558
878	07/29/2014	476349	O RING VALVE TO RESERVOIR 7M	753558
878	07/29/2014	476349	AIR SPRING	753558
878	07/29/2014	476349	DIAPHRAGM DEEP DISH	753558
878	07/29/2014	476349	AIR SPRING (SP0003A)	753558
878	07/29/2014	476349	nsr brake diaphragm us	753558
878	07/26/2014	475650	Perform Safety Inspection as per checklist	752379
878	07/25/2014	476349	REFLECTOR	753081
878	07/25/2014	476349	SINGLE SEAT BASE	753081
878	07/25/2014	476349	GLOBE 24V 10W S/C	753081
878	07/25/2014	476349	rear door step light	753081
878	07/25/2014	476349	reflectors missing	753081
878	07/25/2014	476349	pax seat cushion us	753081
878	07/25/2014	476349	Air leaking from accumulator	753081
878	07/21/2014	475650	Fit Wheel Nut Pointers to all wheel nuts on the front axle	752379
878	07/21/2014	475650	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	752379
878	07/21/2014	475650	Perform Campaign 1_14 School Bus Light Globe Check Check	752379
878	07/21/2014	475650	Tension ALL Wheel Nuts to OEM Specs	752379
878	07/21/2014	475650	A - Service & Bus Safety Inspection	752379
878	07/21/2014	475650	Consumables	0
878	07/21/2014	475650	Consumables	0
878	07/21/2014	475650	Consumables	0
878	07/21/2014	475650	Consumables	0
878	07/14/2014	472267	CONSUMABLE DELIVERY CHARGE	751044
878	07/14/2014	472267	INSTRUMENT CLUSTER	751044
878	07/14/2014	471234	COMPRESSOR K SR with rear driv	751044
878	07/14/2014	471234	O RING COMPRESSOR MOUNT SCANIA	751044
878	07/14/2014	471234	COOLANT PREMIX NF48	751044
878	07/14/2014	471234	THERMOSTAT SCANIA K230	751044
878	07/14/2014	471234	O RING 11MM ID	751044
878	07/14/2014	471234	YELLOW 43mm STEP EDGE	751044
878	07/14/2014	471234	O RING MET 17.0X2.5	751044
878	07/14/2014	471234	WASHER DOWDY 14mm	751044
878	07/14/2014	471234	SWITCH- STOP-YELLOW	751044
878	07/09/2014	473230	Mechanic entered - Equip loose inside mirror .	749709
878	07/04/2014	472277	osr shocker bottom bracket us indicator on dash n/w when LH	748519
878	07/04/2014	472277	GLOBE 24V 21W SINGLE CONTACT	748519
878	07/04/2014	472267	rectify dash clustor u/s as tempreture gauge does not work	748519
878	07/03/2014	472277	osr shocker bottom bracket us indicator on dash n/w when LH	748519
878	07/03/2014	472289	saloon lighttt u/s	748519
878	07/03/2014	472289	dash globes n/w	748519
878	07/03/2014	472267	rectify dash clustor u/s as tempreture gauge does not work	748519
878	07/03/2014	472179	Eng Cool Coolant Low	748519
878	07/03/2014	472333	Comm Equip - cctv harddrive u/s	748519
878	07/03/2014	472289	fire extiniusher out of date	748519
878	07/03/2014	472289	hand brake valve u.s	748519
878	07/01/2014	472333	SMALL PARTS	753081
878	07/01/2014	472333	HARD DRIVE SHELL	753081
878	07/01/2014	472333	TRANSCAM 3	753081
878	07/01/2014	472333	CC-TV	753081
878	06/28/2014	471234	Fuel Leaking	747778
878	06/27/2014	457642	CONSUMABLE DELIVERY CHARGE	748068
878	06/27/2014	457642	HOSE	748068
878	06/27/2014	470349	ALTERNATOR	748068
878	06/27/2014	469285	GLOBE 24V 21W SINGLE CONTACT	748068
878	06/27/2014	471234	Fuel Leaking	747778
878	06/27/2014	471234	Fuel Leaking	747778
878	06/24/2014	470349	rectify battery light on as required	747095
878	06/24/2014	470349	rectify battery light on as required	747095
878	06/18/2014	469285	o/s/f indicator n/w	745327
878	06/16/2014	465821	OIL AUTO TRANS ATF H/DUTY	745327
878	06/16/2014	465821	FILTER ZF TRANS	745327
878	06/16/2014	465821	OIL FILTER	745327
878	06/16/2014	465821	OILBP MULTIFLEET /ltr	745327
878	06/16/2014	465821	FILTER ELE L94 & EARLY K230	745327
878	06/16/2014	465821	FILTER	745327
878	06/16/2014	465821	O-RING	745327
878	06/16/2014	465821	O-RING	745327
878	06/16/2014	467216	ALT REGULATOR	745327
878	06/16/2014	465798	GLOBE 24V 75/70W H4	745327
878	06/16/2014	465798	GLOBE 24V 4W S/C	745327
878	06/16/2014	467728	CUSHION PAN (DRIVERS SEAT)-(ct	745327
878	06/16/2014	465906	SWITCH- STOP-YELLOW	745327
878	06/16/2014	465906	ST SCR PHD PHL 7981 ZN 4.2X16	745327
878	06/16/2014	465906	DECAL PARK BRAKE/ NO WINDOW A	745327
878	06/16/2014	465906	Hand pump	745327

878	06/16/2014	465906	Mount Engine Scania	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16	745327
878	06/10/2014	467727	Elec & Light - Hazards driver cabin light & demister need	replaced globes	743263
878	06/10/2014	467728	Body & Acc Drivers Seat Cushion - driver seat base cushio	replaced drivers seat base	743263
878	06/05/2014	467216	Wipers & Washers Wipers Not Working	wipers started working good after alt reg replaced.	742788
878	06/05/2014	467216	Elec & Light Stop lights and Battery light on dash.	diagnosed and found alt reg us removed alt reg found a broken brush. replaced reg jump started and checked chg 29.5V. wipers working ok.	742788
878	05/30/2014	465821			741309
878	05/29/2014	465821		Perform Safety Inspection as per checklist	741309
878	05/29/2014	465798	Gearbox bus rolls back when in gear	bus rolls back in gear. needs to be diagnosed for nbs	741309
878	05/29/2014	465906	front engine mount u/s	replaced front n/s engine mount x1ok	741309
878	05/29/2014	465798	Mechanic entered - Elec & Light Headlights ns head lamp and	replaced h/l globe and repaired a broken wire to park light.	741309
878	05/29/2014	465906	Fuel hand primer u/s	replaced fuel hand pump.ok	741309
878	05/29/2014	465906	pax stop button x3 u/s	replaced pax stop button.ok fixed pax stop button. x2	741309
878	05/29/2014	465906	park brake decal u/s	replaced park brake decal.ok	741309
878	05/29/2014	465821		Tension ALL Wheel Nuts to OEM Specs	741309
878	05/29/2014	465821		A - Service & Bus Safety Inspection	741309
878	05/29/2014	465821			741309
878	05/29/2014	465821			741309
878	05/29/2014	465821			741309
878	05/29/2014	465821			741309
878	05/18/2014	462851	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	A - Service & Bus Safety Inspection	741309
878	05/09/2014	459315	GLOBE 24V 75/70W H4	Tension ALL Wheel Nuts to OEM Specs	737918
878	04/26/2014	459555	Air System Losing Air sort of dumping air and makes a lou	carried out A3 replacement as required	736924
878	04/24/2014	459315	n/s headlight globe n/w	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	733076
878	04/22/2014	457718	SOLENOID VALVE (REAR)	overhaul safty valve for air system and adjusted main air regulator for air system - checked operation ok	733076
878	04/22/2014	457642	NO SMOKING DECAL	fit new globe	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO WINDOW A	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	743991
878	04/22/2014	457642	DECAL PARK BRAKE/ NO		

878	02/24/2014	449005	safety inspection all done	720668
878	02/24/2014	449005	secured the seat belt buckle mirror & checked security camera.	720668
878	02/24/2014	449005	serviced all done	720668
878	02/24/2014	449005	A - Service & Bus Safety Inspection	720668
878	02/24/2014	449005	Tension ALL Wheel Nuts to OEM Specs	720668
878	02/24/2014	449005	A - Service & Bus Safety Inspection	720668
878	02/22/2014	448876	Mechanic entered - Elec & Light Battery Flat	720668
878	02/21/2014	448752	Suspension Hard Riding high	720668
878	02/21/2014	448752	Suspension Hard Riding high	720668
878	08/15/2013	0	Imported Service History	680486
878	08/15/2013	0	Imported Service History	680486
878	12/03/2012	0	Imported Service History	630856
878	09/28/2012	0	Imported Service History	617437
878	09/28/2012	0	Imported Service History	617437
878	06/19/2012	0	Imported Service History	0
878	06/19/2012	0	Imported Service History	0
878	05/23/2012	0	Imported Service History	598706
878	07/10/2008	0	Imported Service History	308597
878	07/01/2008	0	Imported Service History	305000
878	06/18/2008	0	Imported Service History	303597
878	05/27/2008	0	Imported Service History	298597
878	05/05/2008	0	Imported Service History	293597
878	04/12/2008	0	Imported Service History	288597
878	03/21/2008	0	Imported Service History	283597
878	02/28/2008	0	Imported Service History	278597
878	02/06/2008	0	Imported Service History	273597
878	01/15/2008	0	Imported Service History	268597
878	12/23/2007	0	Imported Service History	263597
878	12/01/2007	0	Imported Service History	258597
878	12/01/2007	0	Imported Service History	0
878	11/09/2007	0	Imported Service History	253597
878	10/18/2007	0	Imported Service History	248597
878	09/25/2007	0	Imported Service History	243597
878	09/03/2007	0	Imported Service History	238597
878	08/12/2007	0	Imported Service History	233597
878	07/21/2007	0	Imported Service History	228597
878	06/29/2007	0	Imported Service History	223597
878	06/06/2007	0	Imported Service History	218597
878	05/15/2007	0	Imported Service History	213597