

Veh#	Date	W/O#	Description	Notes	Odometer
879	09/14/2026	1369719		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST bus is subject to selling; services have been stopped as instructed by Sue	1076407
879	09/05/2026	1367305		COMPLETED BY ATS 12/8/26	1076407
879	09/04/2026	1364014	Vandalism-Graffiti Audit # 133	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O417316 Receiving #:445450 Date :2026-09-04 879 - Oakleigh	1076407
879	08/29/2026	1364014	Vandalism-Graffiti Audit # 1339 Glassprotect - Aug 2026	Assisting	1076407
879	08/07/2026	1360014		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1076407
879	08/07/2026	1360014		VEHICLE SAFETY INSPECTION bus has been prepared to be sold; waiting to go to the auction yard in Gelong	1076407
879	07/31/2026	1357946	Decommission Bus for Auction	removed DVR CONSAT BUSMINDER ETC	1076407
879	07/29/2026	1357946	Decommission Bus for Auction	Removed front side and interior Ventura decals and accreditation sticker.	1076407
879	07/29/2026	1357946	Decommission Bus for Auction	Removed e-tag and placed close to dash. Removed number plate rivets and fitted screws. Assisted with removing Ventura decals	1076407
879	07/01/2026	1351418	STRUT GAS STAY 150Nm 525mm LONG		1076407
879	07/01/2026	1351418	RADIATOR PANEL WONT FULLY OPEN		1076407
879	06/12/2026	1344367	DIRECT PURCHASE - VANDALISM	repaired n/s/r radiator panel and removed n/s/r hatch strut and replaced n/s/r radiator hatch strut ok.	1076407
879	06/12/2026	1344367	Consumables	Creditor #:VB-NAT002 NATIONAL WINDSCREENS P/O #:O411456 Receiving #:439121 Date :2026-06-16 chip repair x 1 glass reseal x 1 glass reseal x 1	1076407
879	06/12/2026	1344367	Consumables		1076407
879	06/03/2026	1345376	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O411761 Receiving #:438878 Date :2026-06-12 Carry out A/C A and B service as required	1076407
879	06/03/2026	1345376	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	CARRIED OUT BY COLD DRIVE- DARREN - P/O O411761	1076407
879	06/03/2026	1345376	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	CARRIED OUT BY COLD DRIVE- DARREN - P/O O411761	1076407
879	05/29/2026	1344367	REAR PASSNEGER DOOR GLASS CRACKED - TO CONFIRM	O411456 - CARRIED OUT BY NATIONAL WINDSCREENS	1076407
879	05/29/2026	1344367	NSR LAST WINDOW CRACKED	O411456 - CARRIED OUT BY NATIONAL WINDSCREENS	1076407
879	05/29/2026	1344367	OSR 2ND AND OSF 1ST GLASS REQUIRE RESEAL	O411456 - CARRIED OUT BY NATIONAL WINDSCREENS	1076407
879	05/29/2026	1344367	Consumables		1076407
879	05/27/2026	1343754		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1076407
879	05/27/2026	1343754		VEHICLE SAFETY INSPECTION	1076407
879	05/27/2026	1343890	WASHER DIFF PLUG 36MM SCANIA ALL MODELS		1076407
879	05/27/2026	1343890	Mechanic entered - Gearbox Driveline Other dif filler plug o	Removed and replaced dif filler plug o-ring with new. Checked dif oil level all ok.	1076407
879	05/27/2026	1343890	O-RING ZF OUTPUT SENSOR COVER		1076407
879	05/27/2026	1343890	Mechanic entered - Fluid Leaks Rear of bus Transmission sens	Removed and replaced transmission sensor cover o-ring with new. Checked transmission oil level. Washed area.	1076407
879	05/27/2026	1343890	LIGHT EMERGENCY EXIT WITH HAMMER CUSTOM		1076407
879	05/27/2026	1343890	Mechanic entered - Elec and Light Interior Lights N/S/R emer	Removed and replaced N/S/R emergency exit light with new.	1076407
879	05/27/2026	1343890	Mechanic entered - Elec and Light Exterior Lights O/S/F bott	Removed and replaced O/S/F bottom park light globe with new. Checked all working.	1076407
879	05/27/2026	1343890	Consumables		1076407
879	05/27/2026	1343890	BUTTON L/H LOWER SEAT LUMBAR		1076407
879	05/27/2026	1343890	Mechanic entered - Body Drivers Seat Controls Driver's seat	Fitted new lumbar button.	1076407
879	05/27/2026	1343890	Consumables		1076407
879	05/25/2026	1343197	Consumables		1076407
879	05/25/2026	1343197	Mechanic entered - Elec and Light Flat Batteries	jump started	1076407
879	04/23/2026	1335876	Service	road tested ok	1076180
879	04/22/2026	1337941	Breakdown Overheating/Cooling SystemBreakdown attended	went to the b/d site; found alt belt broken due to seized roller. fitted one from b/d van with a belt. top up coolant and advised to go to depot.	1076180
879	04/22/2026	1335876	PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		1075408
879	04/22/2026	1335876	BELT V-BELT COGGED TRI-POWER 17x2110mm		1075408
879	04/22/2026	1335876	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048		1075408
879	04/22/2026	1335876	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002		1075408
879	04/22/2026	1335876	Engine Belts_Loose Noisy MissingIDLER PULLEY WORN	Removed the belt fitted by breakdown mechanic replaced plain idler pulley and tensioner as the groove pulley was replaced fit new belt fit new A/C belt and adjusted belts	1075408
879	04/22/2026	1335637	PTI Tablet Entered -Body - OTHER. air leak rear of bus	could not fault.	1075408
879	04/22/2026	1335637	Consumables		1075408
879	04/22/2026	1335638	PTI Tablet Entered -Brakes - OTHER	Adjusted brake and road tested all ok.	1075408
879	03/26/2026	1330405	Body OTHER check complete vehicle	Completed vehicle check.	1075408
879	03/26/2026	1330376	Mechanic entered - Body Other Coolant expansion tank bracket	Found 2x bolts missing on one corner. Fitted new bolts.	1075408
879	03/26/2026	1330376	Mechanic entered - Body Other Minor paint transfer on N/S/F	Removed scuff marks with acetone.	1075408
879	03/26/2026	1330376	DECAL ACCREDITATION CROY KNOX OAK & RAIL		1075408
879	03/26/2026	1330376	STRUT GAS STAY 500Nm 540mm LONG		1075408
879	03/26/2026	1330376	Mechanic entered - Body Other Engine hatch gas struts U/S	Removed and fitte new gas struts.	1075408
879	03/26/2026	1330376	Mechanic entered - Body Other Accreditation decal peeling of	Removed and fitted new accreditation decal.	1075408
879	03/26/2026	1330376	DECAL BREAK GLASS IN EMERGENCY HAMMER RED/CLEAR 120mm SQ		1075408
879	03/26/2026	1330376	Mechanic entered - Body Other O/S/F emergency hammer (break	Removed and fitted new emergency hammer decal.	1075408
879	02/27/2026	1323874		COMPLETED BY ATS 22/2/26	1074748
879	02/25/2026	1321936	DIRECT PURCHASE - BUS INSPECTI	Creditor #:MT-ROASAF ROAD SAFETY INSPECTIONS P/O #:M405132 Receiving #:431174 Date :2026-02-27	1074758
879	02/25/2026	1323083	Mechanic entered - Air System Air_Leak Front	trace the air leak and found out leaking from driver seat replaced driver seat air line and secure it	1074748
879	02/20/2026	1321936		VEHICLE SAFETY INSPECTION	1074748
879	02/20/2026	1321936		ANNUAL SAFETY INSPECTION SERIAL # RSI 073404 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1074748
879	02/14/2026	1320651	RSI STEAM CLEAN	rsi steam clean done.	1074748
879	02/13/2026	1319869	Consumables		1074758
879	02/13/2026	1319869	VALVE SOLENOID ACCUMULATOR ZF 0501-316-527		1074748
879	02/12/2026	1319869	RSI REPAIRS	replacd park brake relay valve. replaced test port. replaced transmission accumulator. rsi finals completed.	1074748
879	02/11/2026	1319869	RELAY VALVE	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M404469 Receiving #:430198 Date :2026-02-17	1074758
879	02/11/2026	1319869	COCK DRAIN SCANIA	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M404469 Receiving #:430198 Date :2026-02-17	1074758
879	02/11/2026	1319869	TEST NIPPLE 16MM SCANIA 30G450	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M404469 Receiving #:430198 Date :2026-02-17	1074758
879	01/28/2026	1316742		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1074748
879	01/28/2026	1316742		PRE ANNUAL SAFETY INSPECTION CHECK Carried out service as per checklist.	1074748
879	01/27/2026	1316415		remove front head light os front and bumper etc repair big air leak	1074748
879	01/27/2026	1316415		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	1074748
879	01/27/2026	1316415		VEHICLE SAFETY INSPECTION done	1074748
879	11/05/2025	1300818		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.	1074748
879	11/05/2025	1300818		VEHICLE SAFETY INSPECTION Carried out vehicle safety inspection as per checklist. ok.	1074748
879	10/09/2025	1295400		CARRY OUT FIRE EXTINGUISHER TEST & TAG - Completed in August 25	1074748
879	08/13/2025	1282508	Both Kingpins have play	greased kingpins. checked no movement. all ok	1074748
879	08/13/2025	1282508	Gearbox oil cooler leaking	overtime minor leak from gearbox oil cooler. wash and check.	1074748
879	08/13/2025	1282508	Consumables		1074748
879	08/13/2025	1282508	Consumables		1074748
879	08/13/2025	1282508	Driver side blind not going up	drivers side blind is broken. need to replace with new one.	1074748
879	08/05/2025	1280755		VEHICLE SAFETY INSPECTION safety all done	1074748
879	08/05/2025	1280755		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1074748
879	05/30/2025	1267417	VALVE FESTO DOOR MINI TYPE(159625 ¼")		1074748
879	05/30/2025	1267417	Fault#:39624 - Ops Entered - Fault - Breakdown Air System Fa	checeked over and found door air leaks replaced 4 pressure regs and found all ok now all under bus is all ok no leaks on brakes etc and brake tested all ok	1074748
879	05/30/2025	1267417	VALVE FESTO DOOR MINI TYPE(159625 ¼")		1074748
879	05/28/2025	1266975	Mechanic entered - Wipers and Washers Wipers Not Working	check wipers. found plug at motor has loose terminals. tightened retest all ok	1074748
879	05/28/2025	1266975	MOTOR WIPER DESIGNLINE		1074748
879	05/28/2025	1266848		found and fixed coolant leak :) with monal	1074748
879	05/28/2025	1266848	PTI Tablet Entered -Engine - Warning Light coolant Leaking	Coolant leak from g/box area.	1074748
879	05/28/2025	1266848	HOSE G/BOX COOLING SCANIA L94 0485995		1074748
879	05/28/2025	1266848		topped up coolant diagnosed for leak found leak from gearbox trans cooler replaced topped up coolant and roadtested all ok	1074748
879	05/28/2025	1267023	Mechanic entered - Body Other	entered in wrong	1074748

879	05/28/2025	1267023	Consumables			1074748
879	05/12/2025	1263622		VEHICLE SAFETY INSPECTION		1073896
879	05/12/2025	1263622		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1073896
879	05/12/2025	1263663	Mechanic entered - Fluid Leaks Other trans rear soleniod cov	removed trans soleniod rear cover and old trans removed trans soleniod rear cover and put back bus 879 ok.		1073896
879	05/12/2025	1263663	Mechanic entered - Body Other driver sun blind not working.	repaired driver sun blind ok.		1073896
879	05/12/2025	1263663	Mechanic entered - Body Other O/S disabled seats loose	bent out disabled seat back brackets on loose seats checked for movement ok.		1073896
879	05/12/2025	1263663	Mechanic entered - Body Other drivers seat back modesty pane	tightened screws in modesty panel checked for movement ok.		1073896
879	05/12/2025	1263663	Mechanic entered - Body Other rear no smoking/vaping decal m	replaced missing no smoking/vaping decal ok.		1073896
879	05/12/2025	1263663	Consumables			1073896
879	05/12/2025	1263663	Consumables			1073896
879	05/05/2025	1262237	Mechanic entered - Elec and Light Flat Batteries			1073896
879	05/05/2025	1262237	Consumables			1073896
879	05/01/2025	1249120	DIRECT PURCHASE - ELECTRICAL			1074758
879	05/01/2025	1249120	Consumables			1074758
879	04/01/2025	1249120	REAR PASSENGER DOOR SENS EDGE NOT WORKING - TO GO TO LONSDA			1073896
879	03/27/2025	1255142	Consumables			1073896
879	03/27/2025	1255142	Mechanic entered - Elec and Light Flat Batteries jump stared			1073896
879	03/20/2025	1253641	AIR CONDITIONING REPAIR			1073896
879	03/20/2025	1253641		jump started bus		1073896
879	03/18/2025	1253066	Fault#:39560 - Ops Entered - Fault - Breakdown Air System F	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O384056 Receiving #:407633 Date :2025-03-28 12 MONTH SERVICE		1073896
879	03/13/2025	1252173	Fault#:39552 - Ops Entered - Fault - Breakdown Air System F	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - PO:O384056 - CARRIED OUT BY BEN FROM COLD DRIVE		1073896
879	03/13/2025	1252174	Ops Entered - Fault - Air System Air Not Building_Up - Rou	attended breakdown -air leak and bus wont move checked for air leaks . could not fault air leaks on bus . air gauges at normal operating pressure. suspect intermittant fault from air dryer or brake booster . followed bus back to oakleigh depot .		1073367
879	03/13/2025	1252213	Mechanic entered - Air System Air Not Building_Up Slow in bu	ATTENDED BREAKDOWN . COULD HEAR A BEEPING SOUND FROM THE BUS WHEN I ATTENDED THE BREAKDOWN. BEEPING SOUND STOPPED SUDDENLY . COULD NOT FAULT AIR SYSTEM NOT BUILDING .AIR SYSTEM WAS ON 10 BAR WHEN I GOT TO THE BUS . I RELEASED THE HAND BRAKE AND BUS WAS ABLE TO MOVE . FC		1073367
879	03/13/2025	1252213	FILTER AIR DRYER SCANIA K124IB L94IB L94UAB	REFER TO WORK ORDER 1252173		1073367
879	03/11/2025	1251407	FRONT PASSENGER DOOR NOT WORKING	Checked and replaced air drier filter check for air pressure build up found okay took for road test 45 mins all okay		1072653
879	03/11/2025	1251407	DIRECT PURCHASE - ELECTRICAL			1073896
879	03/11/2025	1251407	Consumables	PO#: O383353 - repaired by Ryan from Lonsdale		1073896
879	03/07/2025	1250783	SEAL REAR TRANS OUPUT SHAFT SCANIA SR 4 ZF 0734 319 052 01	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O383353 Receiving #:407658 Date :2025-03-28 RECTIFY FRONT PASSENGER DOOR NOT WORKING		1072653
879	03/07/2025	1250783	trans rear seal oil leak			1072653
879	03/06/2025	1250421	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	brought bus onto pit removed tailshaft hanger removed tailshaft removed pinion locking plate used puller to remove pinion washed pinion in turbowash removed leaking seal cleaned area applied rubber grease to seal fitted new seal refitted clean pinion made sure pinion seated in correct position refitted pinion lock refit		1072653
879	03/06/2025	1250421	Consumables	lube top guide roller and chanel. checked operation of front passenger door . all ok		1072653
879	03/04/2025	1249120	REAR PASSENGER DOOR SENSITIVE EDGE NOT WORKING - LONSDALE			1072626
879	03/04/2025	1249120	Consumables			1072626
879	03/01/2025	1248221	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O382562 Receiving #:405786 Date :2025-03-04		1072626
879	02/26/2025	1248221		VEHICLE SAFETY INSPECTION		1072626
879	02/26/2025	1248221		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1072626
879	02/26/2025	1248249	CENTRE FRONT SWAY BAR	ANNUAL SAFETY INSPECTION SERIAL # ____RSI 063923 PASS____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1072626
879	02/26/2025	1248248	NSF EMERGENCY EXIT BUTTON STICKER FADED	Loosened D shackles and bush bracket moved sway bar to N/S slightly to centre sway bar ok.		1072626
879	02/25/2025	1248085	Mechanic entered - Suspension Other Sway bar bush u/s	removed Faded decal applied new decal from stock.		1072626
879	02/25/2025	1248085	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081	Replaced front sway bar bushes with new.		1072626
879	02/21/2025	1246902	Mechanic entered - Elec and Light Other fuel gauge n/w.			1072626
879	02/21/2025	1246902	Consumables			1071536
879	02/20/2025	1246698				1071536
879	02/17/2025	1245705	Mechanic entered - Fluid Leaks Other trans main seal oil le	checked operation of fuel gauge . could not fault		1071044
879	02/13/2025	1244670				1070529
879	02/13/2025	1244768	Mechanic entered - Elec and Light Other o/s/f top parking li	completed by ATS 20-2-25		1070529
879	02/13/2025	1244742	PTI Tablet Entered -Elec and Light - Exterior Lights OS TOP	REPAIR TO BE CARRIED OUT ON DEFECT 1084165		1070529
879	02/13/2025	1244768	Consumables	PRE ANNUAL SAFETY INSPECTION CHECK		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other n/s/r seat back cover loose	fitted with new globe now working all good		1070529
879	02/13/2025	1244768	Mechanic entered - Body Passenger Seat Torn	ok		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other n/s/ middel seat not secured	fitted with new screwsnow secured		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other bus inside rear mirror loose.	fitted with screws now secuerd		1070529
879	02/13/2025	1244768	STONEGUARD PLUS SZ L253 1000ML	fitted with rivets now secured		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other o/s/f bus inside top panel scr	replaced bus inside rear mirror ok.		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other front door rubber off.			1070529
879	02/13/2025	1244768	Mechanic entered - Body Other driver seat back modesty panel	replaced o/s/f bus inside top panel screws ok.		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other o/s/r seat bracket bolt loose.	repaired front door rubber ok.		1070529
879	02/13/2025	1244768	Mechanic entered - Body Other under front rust.	replaced driver seat back modesty panel bolt ok.		1070529
879	02/13/2025	1244742	STRUT GAS STAY LIFT UP SEAT	tightened o/s/r seat bracket bolt ok.		1070529
879	02/13/2025	1244742	Mechanic entered - Brakes Other n/s/r brake booster diaphrag	painting under front ok.		1070529
879	02/13/2025	1244742	DIAPHRAGM TYPE 24 DEEP DISH BRAKE BOOSTER BP24D			1070529
879	02/13/2025	1244768	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	ok removed n/s/r brake booster and replaced n/s/r brake booster diaphargm ok.		1070529
879	02/07/2025	1243279	BATTERY EXSN94SCMF 1350AAC EMFN150L			1069914
879	02/07/2025	1243279	Mechanic entered - Elec and Light Flat Batteries Battery pos	completed		1069914
879	02/07/2025	1243279	Consumables	removed batteries and placed on charge fitted new batteries with lower posts secured in cradle and secured cradle to bus ok.		1069914
879	02/07/2025	1243279	Mechanic entered - Body Other o/s/r pillar crack.			1069914
879	02/07/2025	1243185		Removed corner body section located 2x cracks grinded back cracks welded over straight crack with single pass cut section of angle iron welded second section of crack grinded back welded angle iron over initial welded area all around allowed areas to cool painted areas and refitted corner panel.		1069914
879	02/06/2025	1243105	Mechanic entered - Wheels and Tyres Wheel Nut Retension REMO	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST CARRIED OUT AS PER CHECK LIST		1069914
879	02/06/2025	1243105	Consumables	retensioned n/s/r wheel nuts.		1069914
879	02/06/2025	1240456	rear passenger door not operating			1069914
879	02/06/2025	1240456	Consumables	PO:O380399 - rear passenger door repaired at lonsdale		1069914
879	02/06/2025	1240456	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro			1069914
879	02/06/2025	1243105	Mechanic entered - Body Drivers Seat Controls remove 868 sea	double entry		1069914
879	02/06/2025	1240456	DIRECT PURCHASE - ELECTRICAL	replaced seat out of 868 and fitted to 879 all ok now.		1069914
879	01/23/2025	1240282		Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O380399 Receiving #:404111 Date :2025-02-07 RECTIFY REAR PASSENGER DOOR NOT CLOSING AS REQUIRED		1070079
879	01/23/2025	1240282		VEHICLE SAFETY INSPECTION		1069914
879	01/23/2025	1240282		Assisting		1069914
879	01/23/2025	1240373	Mechanic entered - Wheels and Tyres Worn NSR tyre worn x2	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1069914
879	01/23/2025	1240373	TYRE 295/80R22.5 RECAP	Removed and replaced both NSR tyres @1070029KM Torqued to spec		1069914
879	01/23/2025	1240373	Consumables			1069914
879	01/23/2025	1240370	Mechanic entered - Suspension Other o/s/f sway bar link loos			1069914
879	01/23/2025	1240370	LINK FRT SWAY BAR L94 K360 1766014 0463245 2048601			1069914
879	01/23/2025	1240370		Removed and replaced OSF sway bar link		1069914
879	01/23/2025	1240370	Mechanic entered - Elec and Light Other dash r.p.m light not	replaced dash r.p.m light globe ok.		1069914
879	01/23/2025	1240482	STARTER MOTOR SCANIA L94 0571420 IM038			1069914
879	01/23/2025	1240482	starter motor u/s.	Removed and replaced starter motor with new one tested found okay		1069914
879	01/23/2025	1240456	dash indicator light not working.	replaced wedge ok		1069914
879	01/23/2025	1240370	Consumables			1069914
879	01/23/2025	1240482	Consumables			1069914
879	01/23/2025	1240456	Consumables			1069914
879	01/23/2025	1240370	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	FAULT IS AT THE REAR DOOR NOT THE FRONT DOOR - REPAIRED ON DEFECT 1080092		1069914
879	01/23/2025	1240370	Mechanic entered - Body Other wheel chair ramp pin off.	put in wheel ramp pin ok.		1069914

879	01/23/2025	1240370	Mechanic entered - Body Other n/s/middle seat very loose.	repaired n/s/middle all seat ok.	1069914
879	01/23/2025	1240370	Mechanic entered - Body Other driver seat back side panel lo	replaced driver seat back side panel screws ok.	1069914
879	01/23/2025	1240370	Mechanic entered - Body Other rear door top bolt broken.	removed rear door top broken bolt and replaced rear door top bolt ok.	1069914
879	01/23/2025	1240370	Mechanic entered - Body Other bus inside n/s and o/s middle	replaced n/s and o/s middle top panel screws ok.	1069914
879	01/23/2025	1240370	Mechanic entered - Body Other driver seat adjust lever broke	repaired driver seat adjust lever ok.	1069914
879	01/23/2025	1240370	Mechanic entered - Body Other n/s/middle staunchion pole top	removed n/s/middle staunchion pole broken bolt and replaced n/s/middle staunchion pole bolt ok.	1069914
879	01/23/2025	1240370	Consumables		1069914
879	01/15/2025	1238658	Mechanic entered - Elec and Light Other check battery please	checked battery 11.65 and 11.68vt and engine start ok.	1068918
879	01/15/2025	1238658	Consumables		1068918
879	01/14/2025	1238616	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	PO:O379655 clutch coil replaced by ben from cold drive	1068918
879	01/14/2025	1238616	AIR CONDITIONING REPAIR	Creditor #-VB-COLO04 COLD DRIVE PTY LTD P/O #-O379655 Receiving #-402752 Date :2025-01-20 rectify a/c not cooling as required- clutch coil u/s	1069439
879	01/14/2025	1238476	Mechanic entered - Elec and Light Other battery low.	jumped battery ok.	1068918
879	01/14/2025	1238476	Consumables		1068918
879	01/02/2025	1236365	Mechanic entered - A/C Heating Other 1x A/C coolant hose sw	checked hose .could not fault	1068918
879	01/02/2025	1236360	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Replaced coolant hose fitted new. Secured and tightend all clamps. No more leak.	1068918
879	12/23/2024	1235258	Mechanic entered - Elec and Light Flat Batteries	batteries were fully flat and jump started. eng and/or ign/master cannot be turned off. looks a crossed power. traced and found RPD or its plug had a bad connection. rectified a faulty crimped terminal at RPD plug and tested ok.	1068000
879	12/11/2024	1232982	Mechanic entered - Elec and Light Exterior Lights N/S/R bott	Removed and fitted new brake light lamp.	1066080
879	12/11/2024	1232982	LAMP LED STOP/TAIL DESIGNLINE 9-33 VOLT		1066080
879	12/09/2024	1232246	Mechanic entered - Body Passenger Seat Torn O/S/R Seat Base	Removed Torn Seat Base replaced with new item from stock.	1065410
879	12/09/2024	1232246	SEAT CUSH SINGLE CEN CRV CA		1065410
879	12/03/2024	1231287	Mechanic entered - Fluid Leaks Rear of bus Low coolant	Checked bus unable to find any sign of leakage. Topped up coolant and ran bus for 20 minutes. Could not find leak.	1064386
879	12/02/2024	1230039	Mechanic entered - Fluid Leaks Rear of bus Engine side cover	raised bus up removed intake and airbox assembly removed assciated covers removed compressor removed sidecovers inspected and cleaned area awaiting parts. fitted new side cover gaskets refitted side covers replaced compressor oil seal refitted compressor and associated components replaced rocker cover gaskets	1064386
879	12/02/2024	1230039	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1064386
879	12/02/2024	1230039	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1376911		1064386
879	12/01/2024	1230039	GASKET SIDE CVR ENGINE BLOCK D	Creditor #-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #-O376976 Receiving #-400677 Date :2024-12-16	1067094
879	11/22/2024	1228944		CARRY OUT B SERVICE AS PER CHECK LIST Completed B service as per checklist.	1063693
879	11/22/2024	1228944	OIL ENGINE ALL FLEET PLUS E900 15W-40		1063693
879	11/22/2024	1228944	FILTER OIL SCANIA VARIOUS MODELS		1063693
879	11/22/2024	1228944	OIL SAMPLE TEST KIT		1063693
879	11/22/2024	1228944	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)		1063693
879	11/22/2024	1228944	O-RING LOWER SPINNER FILTER SCANIA L94 K124		1063693
879	11/22/2024	1228944	O-RING LARGE UPPER SPINNER FILTER SCANIA		1063693
879	11/22/2024	1228944	OIL ATF STEERING DEX-3 VALVOLINE		1063693
879	11/22/2024	1228944	FILTER FUEL SCANIA VARIOUS MODELS H17WK04		1063693
879	11/22/2024	1228944	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		1063693
879	11/22/2024	1228944	Consumables		1063693
879	11/13/2024	1227102	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	Retensioned O/S/R wheel nuts to 650nm.	1061962
879	11/13/2024	1227102	Consumables		1061962
879	11/12/2024	1226598		VEHICLE SAFETY INSPECTION	1061163
879	11/12/2024	1226598		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1061163
879	11/12/2024	1226662	Mechanic entered - Wipers and Washers Washers Not Working 1x	removed hose to washer jet blew out jet and cleared hose refitted hose and checked for operation ok.	1061163
879	11/12/2024	1226663	Mechanic entered - Wheels and Tyres Worn O/S/R Tyres U/S	removed worn tyres fitted 2x runout tyres from stock.	1061163
879	11/12/2024	1226663	Consumables		1061163
879	11/12/2024	1226662	PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		1061163
879	11/12/2024	1226662	Mechanic entered - Engine Other 1x Idler Pulley U/S	removed worn idler pulley replaced with new item from stock.	1061163
879	11/12/2024	1226662	Mechanic entered - Driver Tablet Other Busminder Not secured	tightened security bolts on busminder mount.	1061163
879	11/12/2024	1226662	Consumables		1061163
879	11/12/2024	1226662	Mechanic entered - Body Other 1x disabled seat not holding u	tightened mounting bolts checked for seat holding in position ok.	1061163
879	11/12/2024	1226662	Mechanic entered - Body Other 1x disabled seat not secured (	tightened loose mounting bolt.	1061163
879	11/12/2024	1226662	Consumables		1061163
879	11/12/2024	1226598	PERFORM CAMPAIGN 15/24 PRE SUMMER PREVENTATIVE MAINTENANCE	carried out rad wash	1061163
879	11/09/2024	1226271	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retensioned nsf wheel nuts as per specs	1061163
879	11/09/2024	1226271	Consumables		1061163
879	11/09/2024	1226268	Vandalism Vandalism/ Graffiti Interior	carried out interior vandalisem painting as required	1061163
879	11/09/2024	1226233	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	COMPLETE	1061163
879	11/08/2024	1226203	TYRE 295/80R22.5 NEW		1061163
879	11/08/2024	1226203	Mechanic entered - Wheels and Tyres Worn P1 tyre worn.	Replaced P1 tyre with new tyre. Checked tyre pressure and tensioned N/S/F tyre to 650nm.	1061163
879	11/08/2024	1226203	Consumables		1061163
879	11/08/2024	1225930	Mechanic entered - Elec and Light Next Stop Button one butto	TRACED AND FOUND PAX BUTTON X 1 NOT WORKING . FIT GOOD 2ND HAND BUTTON. CHECKED OPERATION ALL OK	1061163
879	11/08/2024	1225930	Consumables		1061163
879	10/14/2024	1220854	Consumables		1057627
879	10/14/2024	1220854	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retensioned N/S/R wheel nuts.	1057627
879	10/11/2024	1220513	Consumables		1057396
879	10/11/2024	1220513	Mechanic entered - Wheels and Tyres Worn N/S/R outter tyre w	Removed and fitted run out tyre for position 3. Tensioned all wheel nuts.	1057396
879	10/11/2024	1220513	Mechanic entered - Wheels and Tyres Other Bolt stuck on N/S/	Removed bolt and checked area for air leaks. No air leaks. Checked tyre pressure all ok.	1057396
879	10/04/2024	1218715	Consumables		1056416
879	10/04/2024	1218715	Driver Tablet Entered -Body - Water Leaks bottom of music ra	removed the GPS round antenna and its plate; cleaned and sealed.	1056416
879	09/18/2024	1215385	Driver Tablet Entered -Wipers and Washers - Wipers Not_Clear	Checked washer bottle washer bottle full of water. Cleared washer lines. Checked washers now working.	1054093
879	09/17/2024	1215030	Mechanic entered - Suspension Leaning N/S/R leans after swi	checked the bus for suspension air leaks. no leak from bags. further check confirmed air fitting at the back of fuel tank leaking. hard to see with dirt around. removed all fittings and replaced with hose portions. checked ok	1053870
879	09/13/2024	1214362		VEHICLE SAFETY INSPECTION Completed inspection	1053870
879	09/13/2024	1214362		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1053870
879	09/13/2024	1214523	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820		1053870
879	09/13/2024	1214523	BUSH SWAY BAR D/AXLE 47MM SCANIA K1241B 1880751		1053870
879	09/13/2024	1214523	Mechanic entered - Suspension Other Rear sway bar D bushes w	Replaced both D bushes	1053870
879	09/13/2024	1214523	SLACK ADJUSTER FRONT NEAR SIDE 1789568		1053870
879	09/13/2024	1214523	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1053870
879	09/13/2024	1214362	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734 319 052 01		1053870
879	09/13/2024	1214362	Mechanic entered - Gearbox Driveline Other diff pinion shim	Cleaned and tight the bearing housing bolts	1053870
879	09/13/2024	1214362	Mechanic entered - Gearbox Driveline Other trans seal oil l	Removed and replaced transmission output seal	1053870
879	09/13/2024	1214523	Consumables		1053870
879	09/13/2024	1214523	Mechanic entered - Elec and Light Interior Lights Drivers re	Removed and replaced globe	1053870
879	09/13/2024	1214523	Mechanic entered - Brakes Other O/S/R slack adjuster wont ad	Removed and replaced slack adjuster adjusted rear brakes	1053870
879	09/13/2024	1214523	Mechanic entered - Brakes Other N/S/F slack adjuster weak	Removed and replaced slack adjuster and adjusted both wheel brakes	1053870
879	09/13/2024	1214523	Mechanic entered - Air System Air_Leak Rear Air tank drain v	Replaced drain valve	1053870
879	09/07/2024	1213135		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1053261
879	08/23/2024	1209309		TRANSMISSION CHECK AS PER CHECK LIST carry out trans checkoutput shaft seal weaping.	1050920
879	08/20/2024	1208756	Drv entered - Wipers and Washers Wipers Noisy	N/S wiper blade u/s. Replaced n/s wiper blade with new. Checked all ok.	1050559
879	08/20/2024	1208756	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM		1050559
879	08/20/2024	1208756	Consumables		1050559
879	08/20/2024	1208756	Mechanic entered - Elec and Light Exterior Lights O/S Headli	Removed and replaced headlight globe and park light globe	1050559
879	08/20/2024	1208756	GLOBE 24V H4 75/70W HALOGEN		1050559
879	08/08/2024	1206301	Mechanic entered - Engine Other rocker cover seal oil leaks.	Removed and fitted new rocker cover gaskets. Road tested bus and checked for leaks all okay.	1049140
879	08/08/2024	1206301	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1049140

879	08/07/2024	1205771	CCTV Hard Drive Timing off by 2hrs	adjusted time and dst all good.	1048647
879	07/27/2024	1203619	Driver Touch Screen-gps not keeping up	checked the system sended the status for a server all connection was ok the GPS signal was strong	1047408
879	07/27/2024	1203619	Consumables		1047408
879	07/24/2024	1201411	SENSOR SPEED 4 TERMINAL SCANIA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O369040 Receiving #:390830 Date :2024-07-25	1046876
879	07/24/2024	1201411	Consumables		1046876
879	07/23/2024	1201411	SENSOR SPEED 4 TERMINAL SCANIA L94 1853436		1046329
879	07/17/2024	1201411	Ops Entered - Fault - Dash Speedo Not Working - Route: 703	checked the speedo and odo readng; both are working. there may be an intermittent fault that needs to be further checked.	1045544
879	07/17/2024	1201411		swapped the speed sensor with 886 and road tested; speedo was not playing up. need to put the bus in service to monitor. FITTED THE SENDER TO BUS 886	1045544
879	07/16/2024	1200980	Mechanic entered - Elec and Light Other speedo n/w.	road testcould not fault.	1045544
879	07/16/2024	1200980	Consumables		1045544
879	07/15/2024	1200435	Mechanic entered - Steering Other steering wheel u/s.	removed steering wheel and replaced steering wheel ok.	1045544
879	07/15/2024	1200435	STEERING WHEEL SCANIA L94 40M1303		1045544
879	07/15/2024	1200916	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC		1045544
879	07/13/2024	1200397		COMPLETE	1045544
879	07/13/2024	1200397		VEHICLE SAFETY INSPECTION	1045544
879	07/13/2024	1200398	Mechanic entered - Suspension Other n/s/f air bag leaks.	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1045544
879	07/13/2024	1200451	Kneel/ Raise not working	replaced n/s/f air bag ok.	1045544
879	07/13/2024	1200398	AIRBAG FRONT SCANIA K310UB E5 40Y2248 40Y2223	checked operation of kneel and raise . could not fault	1045544
879	07/13/2024	1200398	FITTING ELBOW 16MM AIRBAG SCANIA L94		1045544
879	07/13/2024	1200435	Mechanic entered - Steering Other steering wheel u/s.	checked and ordered	1045544
879	07/13/2024	1200398	Mechanic entered - Engine Other engine belt idler bearing no	replaced engine belt idler bearing ok.	1045544
879	07/13/2024	1200398	PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087		1045544
879	07/13/2024	1200398	Mechanic entered - Elec and Light Other pax switch 3 crack.	replaced pax switch 3 ok.	1045544
879	07/13/2024	1200398	SWITCH STOP YELLOW (62628)(50V2242)		1045544
879	07/13/2024	1200398	Workshop Tablet Entered -Dash - Speedo Not Working	replaced dash speedo light globe ok.	1045544
879	07/13/2024	1200398	Consumables		1045544
879	07/13/2024	1200398	Mechanic entered - Body Other front modesty panel loose.	repaired front modesty panel ok.	1045544
879	07/13/2024	1200398	Mechanic entered - Body Other bus inside o/s/r and o/s/f top	replaced bus inside o/s/f and o/s/r top panel screws ok.	1045544
879	07/13/2024	1200398	Mechanic entered - Body Other driver seat back modesty panel	repaired driver seat back modesty panel ok.	1045544
879	07/13/2024	1200398	Mechanic entered - Body Other both middle all seat loose.	repaired both middle all seat ok.	1045544
879	07/13/2024	1200398	Consumables		1045544
879	07/13/2024	1200398	Consumables		1045544
879	07/10/2024	1199803	Driver Tablet Entered -Elec and Light - Indicators Not Worki	Removed and fitted new indicator globe.	1045208
879	07/10/2024	1199803	Consumables		1045208
879	07/06/2024	1198907	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over interior graffiti	1044720
879	07/05/2024	1198733	Driver Tablet Entered -Wipers and Washers no water spray	double entry	1044720
879	07/05/2024	1198736	Driver Tablet Entered -Wipers and Washers no water spray	Checked bus found wiper water lines blocked. Unblocked with air pressure and topped up water. Checked wipers operation all okay.	1044720
879	07/04/2024	1198260		carried out ok	1044720
879	06/27/2024	1196984		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist.	1043548
879	06/27/2024	1196984	OIL ENGINE ALL FLEET PLUS E900 15W-40		1043548
879	06/27/2024	1196984	OIL ATF STEERING DEX-3 VALVOLINE		1043548
879	06/27/2024	1196984	OIL SAMPLE TEST KIT		1043548
879	06/27/2024	1196984	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		1043548
879	06/27/2024	1196984	FILTER FUEL SCANIA VARIOUS MODELS H17WK04		1043548
879	06/27/2024	1196984	FILTER OIL SCANIA VARIOUS MODELS		1043548
879	06/27/2024	1196984	O-RING LARGE UPPER SPINNER FILTER SCANIA		1043548
879	06/27/2024	1196984	O-RING LOWER SPINNER FILTER SCANIA L94 K124		1043548
879	06/27/2024	1196984	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)		1043548
879	06/27/2024	1196984	DRAIN PLUG M22 X 1.5 ECOMAT ZF 0636 100 824 01		1043548
879	06/27/2024	1196984	Consumables		1043548
879	06/25/2024	1196537	Driver Tablet Entered -Body - Front_Door Operation Faulty R	adjusted and lubricated front passenger door . checked operation 30 times with nikki controlling the door whilst i was inspecting the door operation . could not fault	1043136
879	06/25/2024	1196538	Driver Tablet Entered -Body - Mirrors Interior LOOSE INTERI	checked all internals mirrors for security . could not fault	1043136
879	06/14/2024	1194307	Water comes in when the door is open	check for roof leakscould not fault.	1041117
879	06/07/2024	1193387	Mechanic entered - Elec and Light Exterior Lights N/S/F bott	Found park light wire severed. Crimped new wire connector and checked globe. Globe still ok. Checked park lights all ok.	1040313
879	06/07/2024	1193387	Consumables		1040313
879	06/05/2024	1192858	Driver Tablet Entered -Wipers and Washers - Washers Not Work	Checked washer motor motor working fine. Washer bottle level is good. Washer nozzle was blocked inside. Removed lines and nozzles and blew it out with air gun. Checked washer operations all okay. Waaher bottle bracket was broken repaired and secured washer bottle bracket.	1039891
879	05/31/2024	1191704	PTI Tablet Entered -Body - Rear_Door Operation Faulty	ADJUST AIR PRESSURE TO RAM.CHECKED OPERATION OF REAR PASSENGER DOOR . OPERATION ALL OK	1038842
879	05/31/2024	1164148	BRAKE CHAMBER TYPE 20 40G2513	Duplicate Issue	1038842
879	05/18/2024	1189135	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Completed retension	1036436
879	05/17/2024	1188890		VEHICLE SAFETY INSPECTION Carried out safety inspection.	1036436
879	05/17/2024	1188890		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1036436
879	05/17/2024	1188937	Mechanic entered - Wipers and Washers Other Washer Bottle No	re secured washer bottle bracket.	1036436
879	05/17/2024	1188937	Mechanic entered - Suspension Other N/S/R Airbags U/S	replaced leaking airbags with new items from stock. aired up bus and checked for leaks bus no longer leaning.	1036436
879	05/17/2024	1188937	AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02		1036436
879	05/17/2024	1188937	TENSIONER ALT BELT SCANIA N310UA 2197005 1859657		1036436
879	05/17/2024	1188937	Mechanic entered - Engine Other Drive Belt U/S	replaced worn drive belt with new item from stock.	1036436
879	05/17/2024	1188937	Mechanic entered - Engine Other idler pulley U/S	replaced worn idler pulley with new item from stock.	1036436
879	05/17/2024	1188937	Mechanic entered - Engine Other Belt Tensioner U/S	replaced worn belt tensioner with new item from stock.	1036436
879	05/17/2024	1188937	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048		1036436
879	05/17/2024	1188937	PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		1036436
879	05/17/2024	1188937	Mechanic entered - Elec and Light Exterior Lights Front Step	replaced blown globe checked for operation ok.	1036436
879	05/17/2024	1189008	Mechanic entered - Body Other 2x disabled seat cushion cover	Removed and replaced seat cover and base with new.	1036436
879	05/17/2024	1188937	Mechanic entered - Body Other O/S/R Hatch Struts U/S	removed worn hatch struts replaced with new items from stock.	1036436
879	05/17/2024	1188937	Mechanic entered - Body Other N/S/R No Vaping/Smoking Decal	fitted new decal from stock.	1036436
879	05/17/2024	1188937	STRUT GAS STAY 500Nm 540mm LONG		1036436
879	05/17/2024	1189008	SUPER SLIM SGL CUSH CVR - RA		1036436
879	05/17/2024	1189008	SUPLERSLIM PLASTIC BASE		1036436
879	05/13/2024	1188031	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	Retensioned all rear wheel nuts to 650nm.	1035711
879	05/10/2024	1187054	ASSEMBLY V STAY DRIVE AXLE SCANIA L94UAB 489986		1035125
879	05/10/2024	1187054	SLACK ADJUSTER AUTO OSR D/AXLE SCANIA SERIES 4 2009820	put in diff oil and put back rear stuaxle and tightened both rear bottom torque rod bolts and tightened rear all shock nuts and replaced rear both all sway bar bushing and tightened sway bar link bolts and put in rear top V rod and tightened V rod all bolts and rear both put in levelling valve rod tightened both rear levelling	1035125
879	05/10/2024	1187054		put in driver shaft and tightened driver shaft all bolts and tightened driver shaft clamp bolts and tightened V rod bolts and road tested after back check o/s/r brake slack adjust very loose and replaced o/s/r brake slack adjust and all brake adjust and road tested and n/s/f brake temp is 45 and o/s/f is 47 and n/s/r is 49 o/s/	1035125
879	05/09/2024	1187054	BUSH RR SWAY BAR D AXLE SCANIA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O364368 Receiving #:385568 Date :2024-05-10	1035221
879	05/09/2024	1187054		put rear all grease and rear both put in stuaxle and tightened all rear Ubolts and removed old axle n/s/r all hub axle cap bolts and put back 879 n/s/r all hub axle bolts and removed old axle o/s/r hub axle cap bolt one and put back 879 o/s/r hub axle bolt and tightened rear both hub axle cap nuts and	1035125
879	05/09/2024	1187054	BOLT V STAY ASSY CENTRE BUSH SCANIA L94		1035125
879	05/09/2024	1187054	BUSH SWAY BAR LINK REAR AXLE SCANIA L94UAB 2156626 1477867		1035125
879	05/08/2024	1187054	WASHER DIFF PLUG 36MM SCANIA ALL MODELS 4921019		1035125
879	05/08/2024	1187054	Ops Entered - Fault - Suspension Noisy - Route: 703 - Lunta	replaced diff bottom pluge washer and removed rear axle on the ground and removed diff and removed rear both stuaxle mount and removed axle shaft.	1035125
879	05/03/2024	1186045	cold drive to replace x 8 evaporator fans	PO:O363978 - completed by Jimmy from Cold Drive	1035125
879	05/02/2024	1185783	Ops Entered - Fault - Suspension Leaning - Route: 703e - Mo	road tested bus pulled in at stops kneeld bus closed door and drove bus is self levelling stopped after driving and inspected if bus was leaning unable to fault.	1035035
879	05/02/2024	1186045	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O363978 Receiving #:385486 Date :2024-05-09 replace evaporator fans x 8 as required	1035125
879	04/26/2024	1184765	Mechanic entered - Elec and Light Exterior Lights N/S headli	Removed and fitted new headlight globe.	1034112
879	04/26/2024	1184765	GLOBE 24V H4 75/70W HALOGEN		1034112

[illegible]

879	12/16/2023	1158446	Mechanic entered - Body Other Rear No Smoking/Vaping Decal M	applied new decal from stock.	1015083
879	12/15/2023	1155117	Consumables		1015083
879	12/15/2023	1155117	TYRE 295/80R22.5 NEW	Removed in Error	1015083
879	12/13/2023	1157941	Consumables		1014594
879	12/13/2023	1157941	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retensioned N/S/R wheel nuts.	1014594
879	12/12/2023	1157662	Consumables		1014366
879	12/12/2023	1157662	Mechanic entered - Wheels and Tyres Worn P3 and P4 tyres wor	Replaced P3 and P4 tyres with new retread tyres. Checked tyre pressures and tensioned N/S/R to 650nm.	1014366
879	12/12/2023	1157662	TYRE 295/80R22.5 RECAP		1014366
879	12/09/2023	1157076	Consumables		1013834
879	12/09/2023	1157076	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	retorque o/s/r wheel nuts.	1013834
879	12/07/2023	1156801	Consumables		1013558
879	12/07/2023	1156801	Mechanic entered - Wheels and Tyres Damaged P6 tyre tread da	Replaced P5 and P6 tyres with new retread tyres. Tensioned O/S/R wheel nuts to 650nm.	1013558
879	12/07/2023	1156801	TYRE 295/80R22.5 RECAP		1013558
879	12/04/2023	1155117	TYRE 295/80R22.5 NEW		1013109
879	12/01/2023	1155349	Consumables		1012010
879	12/01/2023	1155349	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorque all front wheel nuts.	1012010
879	11/30/2023	1155117	PTI Tablet Entered -Wheels and Tyres - Worn tyre 1	NSF tyre side wall worn locked the front wheels replaced NSF and OSF to match tread. tensioned wheel nuts and rebooked for retension.	1012010
879	11/30/2023	1155117	TYRE 295/80R22.5 NEW		1012010
879	11/30/2023	1155328	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	Retensioned all front wheel nuts to 650nm.	1012010
879	11/30/2023	1155328	Consumables		1012010
879	11/30/2023	1155117	Consumables		1013109
879	11/22/2023	1153576		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	1010676
879	11/22/2023	1153576		SERVICE MOISTURE EJECTOR	1010676
879	11/22/2023	1153576	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		1010676
879	11/22/2023	1153740	Workshop Tablet Entered -Dash - left ind light Dash_Lights	refer to work order 1153579	1010676
879	11/22/2023	1153579	PTI Tablet Entered -Elec and Light - Indicators Not Workingf	replaced n/s/f side indictor light globe.	1010676
879	11/22/2023	1153579	Consumables		1010676
879	11/22/2023	1153740	Consumables		1010676
879	11/20/2023	1153163		complete	1010447
879	11/01/2023	1149873	Mechanic entered - Wipers and Washers Other Washer Bottle U	no stock . long wait on parts . drove to moorabbin depot removed washer bottle tank from scrap bus 1192. drove back to oakleigh depot . different tank set between the 2 buses . modified bus 879 to except 2nd hand tank and bracket . installed water res and replaced broken washer water line . all working . parked bus in	1007477
879	10/31/2023	1149706		VEHICLE SAFETY INSPECTION	1007477
879	10/31/2023	1149706		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1007477
879	10/31/2023	1149759	Consumables		1007477
879	10/31/2023	1149759	Mechanic entered - Wheels and Tyres Other Position 3 and pos	Removed position 3 and 6 wheels and switched positions.	1007477
879	10/31/2023	1149759	Mechanic entered - Engine Other Drive belt tensioner pulley	Removed and fitted new tensioner and idler pulley.	1007477
879	10/31/2023	1149759	Mechanic entered - Air System Other 4 way protection valve I	Removed and fitted new 4 way protection valve.	1007477
879	10/31/2023	1149759	PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		1007477
879	10/31/2023	1149759	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113		1007477
879	10/31/2023	1149759	VALVE CIRCUIT PROTECTION 4WAY SCANIA 1431049 1381883		1007477
879	10/26/2023	1148934	Mechanic entered - Body Other Rear emergency exit hammer cab	Fit back steel cable and crimp a sleeve on the cable	1006567
879	10/25/2023	1148676	Consumables		1006381
879	10/25/2023	1148676	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced headlight globe. Checked front lights o/s/f bottom park light n/w. Replaced O/S/F bottom park light globe housing with good spare part. All front lights now working.	1006381
879	10/25/2023	1148676	GLOBE 24V H4 75/70W HALOGEN		1006381
879	10/24/2023	1148047	Consumables		1006128
879	10/24/2023	1148359	Consumables		1006128
879	10/24/2023	1148047	Mechanic entered - Elec and Light Flat Batteries re-book for	check battery Load tester is all 12vt ok. could not falt ok.	1006128
879	10/24/2023	1148359	Ops Entered - Fault - BusMinder No Power - Route: 703 - For	Checked and connected charging cable and cable tie it	1006128
879	10/19/2023	1146841		Moved for paintshop.	1006004
879	10/19/2023	1146841		fittup o/s/f wash bus.	1006004
879	10/19/2023	1146841		perp maskup and paint unask and remove from booth	1006004
879	10/18/2023	1146841		repair o\s front headlight panel and primer and corner panel	1006004
879	10/17/2023	1144286	Consumables		1006004
879	10/17/2023	1144286	DECAL PTV N - PASS REAR CORNER		1006004
879	10/17/2023	1144286	DECAL PTV C - PASS FRONT		1006004
879	10/17/2023	1144286	REFLECTOR AMBER HELLA 94 X 44MM		1006004
879	10/17/2023	1144286		finnish stickers reflectors.fit and check lights	1006004
879	10/17/2023	1146841		remove o\s headlight panel and sand and fibreglass and remove indicator light and repair o\s corner panel	1006004
879	10/16/2023	1144286	REFLECTOR RED 94MM X 4MM NR84052BL		1006004
879	10/16/2023	1144286	Service	clean up of panels prepped for decals applied decals to o/s rear	1006004
879	10/16/2023	1144286		stripped rear light applied rear o/s decal	1006004
879	10/16/2023	1144286	DECAL PTV N - PASS REAR CORNER		1006004
879	10/16/2023	1144286	FOAM TAPE 4MM X 22MM P/M		1006004
879	10/16/2023	1144286	LAMP LED SIDE MARKER RED/AMBER		1006004
879	10/16/2023	1144286		help jump start 3 busses first in the morningfit up stickers	1006004
879	10/13/2023	1144286		perp maskup and paint unmask and remove from booth	1006004
879	10/12/2023	1144286		sanded primer maskup painted white n/s/r top corner maskup and painted wheels.	1006004
879	10/12/2023	1144286		fiting desto hinge on	1006004
879	10/12/2023	1144286		prep for paint work	1006004
879	10/12/2023	1144286		Moved for paintshop	1006004
879	10/11/2023	1144286	decal g	Creditor #:EA-LAB010 LABEL CONCEPTS P/O #:EA352027 Receiving #:371222 Date :2023-10-12	1006004
879	10/10/2023	1144286	R10HI-010 hinges	Creditor #:EA-CUS100 CUSTOM BUS AUSTRALIA P/O #:EA352320 Receiving #:371220 Date :2023-10-12	1006004
879	10/05/2023	1144286		repair front top left corner take decal off o/s rear left and right repair front top corner fibreglas body filer and primer repair top and botom left rear corner and put body filer fited desto unit	1006004
879	10/04/2023	1144286	N/S front desto sign hinge u/s		1006004
879	10/04/2023	1144286	rear of bus decals faded and scratched		1006004
879	10/04/2023	1144286	NSF top corner has a big hole under decal patch up temp re		1006004
879	10/04/2023	1144286	Accident # 55490 - OSF damage- around headlight surround an		1006004
879	10/03/2023	1143876	PERFORM CAMPAIGN 07/23 REPOSITION ETAG	e-tag was in position. replaced with a new tag on 03-10-2023 11am	1006004
879	09/25/2023	1142466	Fluid Leaks Rear of bus	Drained transmission fluid to level replaced dipstick gasket wash and road tested	1004800
879	09/25/2023	1142466	Fluid Leaks Rear of bus	Assisting ATF is found under the trans filler tube area. suspect overfilled . cleaned and road tested. need to monitor.	1004800
879	09/25/2023	1142466	GASKET DIPSTICK ZF (0501 310 134 01)		1004800
879	09/25/2023	1142464	Consumables		1004800
879	09/25/2023	1142464	Elec and Light (None) DOOR BRAKES NW	CHECKED AND FOUND cb6 POPPED IN THE ELECTRIC PANEL. OIL SEPERATOR INTERNALLY SHORTED. PARTS ORDERED	1004800
879	09/25/2023	1142465	CONDENSOR / OIL COLLECTOR AIR	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O351478 Receiving #:370090 Date :2023-09-25	1004800
879	09/25/2023	1142465	Air System Air_Leak Rear OIL SEPERATOR internal short	parts ordered	1004800
879	09/25/2023	1142465	Air System Air_Leak Rear OIL SEPERATOR internal short	Picked up part from multi spares replaced condenser/oil collector and road tested and found door brakes working and circuit breaker not tripping	1004800
879	09/15/2023	1140757		checked and found frt and rear doors nw either. removed the door switch panel and found no GND to the switches thru RPD. removed the battery power and reconnected; started working. tested ok	1003341
879	09/14/2023	1140757	Driver Tablet Entered -Door Brakes doesn't work	Checked and reset RPD still not working needs further checks	1003341
879	09/07/2023	1139353	Consumables		1002064
879	09/07/2023	1139353	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s/	Completed retension	1002064
879	09/05/2023	1138590	Consumables		1001802
879	09/05/2023	1138590	Mechanic entered - Wheels and Tyres Other n/s/r/outer tyre d	removed n/s/r/outer tyre and replaced n/s/r/outer runout tyre ok.	1001802
879	09/05/2023	1138487	DOWDY WASHER 36MM I/D 1356776 2001228		1001802
879	09/05/2023	1138487	Consumables		1001802

879	09/05/2023	1138487	Consumables		1001802
879	09/05/2023	1138487	FILTER AIR DRYER SCANIA VOLVO 1393551 20546795 20424148		1001802
879	09/05/2023	1138487	O-RING SPINNER FILTER SCANIA L94		1001802
879	09/05/2023	1138487	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		1001802
879	09/05/2023	1138487	OIL SAMPLE TEST KIT		1001802
879	09/05/2023	1138487	FILTER AIR OUTER SCANIA SR 3 & 4 395773 AF25066		1001802
879	09/05/2023	1138487	FILTER FUEL SCANIA L94 (1372444)		1001802
879	09/05/2023	1138487	PAPER SPINNER FILTER OIL INSERT SCANIA L94		1001802
879	09/05/2023	1138487		CARRY OUT C SERVICE AS PER CHECK LIST	1001802
879	09/05/2023	1138487		Assisting Assisted SHO with C-B service.	1001802
879	09/05/2023	1138487	FILTER FUEL/WATER SEPARATOR SCANIA L94UB 1393640		1001802
879	09/05/2023	1138487	FILTER OIL SCANIA K93 L94 1117285 2059778		1001802
879	09/05/2023	1138487	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1001802
879	09/05/2023	1138487	FILTER HYD COOLING FAN SCANIA SR3 4 1354074		1001802
879	09/05/2023	1138487	FILTER P/STRG MERC SCANIA VOLVO 0153468 349619		1001802
879	09/05/2023	1138487	Consumables		1001802
879	09/05/2023	1138487	Consumables		1001802
879	09/05/2023	1138487	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814		1001802
879	09/05/2023	1138487		CARRY OUT B SERVICE AS PER CHECK LIST	1001802
879	09/05/2023	1138487		CARRY OUT B SERVICE AS PER CHECK LIST	1001802
879	09/04/2023	1138196		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	1001175
879	08/24/2023	1135508		VEHICLE SAFETY INSPECTION	999621
879	08/24/2023	1135508		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	999621
879	08/24/2023	1135613	Mechanic entered - A/C Heating Other a/c cover screws missin	repaired a/c filter side cover and replaced screws ok.	999621
879	08/24/2023	1135613	Consumables		999621
879	08/24/2023	1135613	DECAL DO NOT OVERTAKE 100MM X 300MM		999621
879	08/24/2023	1135613	Mechanic entered - Body Other rear do not overtake decal dam	replaced rear do not overtake decal ok.	999621
879	08/24/2023	1135613	Mechanic entered - Body Other n/s/middle seat loose.	repaired n/s/middle seat ok.	999621
879	08/24/2023	1135613	Mechanic entered - Body Other driver seat back modesty panel	repaired driver seat back modesty panel ok.	999621
879	08/24/2023	1135613	Mechanic entered - Body Other step middle edge yellow no saf	repaired middle step edge yellow ok.	999621
879	08/24/2023	1135613	Mechanic entered - Body Other driver door loose.	repaired driver door ok.	999621
879	08/24/2023	1135613	Mechanic entered - Brakes Other n/s/r brake slack adjust bra	removed n/s/r brake slack adjust broken bracket bolt and replaced n/s/r brake slack adjust bracket bolt ok.	999621
879	08/24/2023	1135613	Mechanic entered - Air System Other n/s/f and o/s f air hose	repaired o/s/f and n/s/f air hose ok.	999621
879	08/22/2023	1135137	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	complete	999374
879	08/14/2023	1133127	Consumables		998095
879	08/14/2023	1133158	Consumables		998095
879	08/14/2023	1133158	drivers seat belt anchor u/s	R/R seat belt anchor .	998095
879	08/14/2023	1133158	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		998095
879	08/14/2023	1133127	Mechanic entered - Body Passenger Seat Torn disable seat bac	fitted a pin and secured OSF disable seat	998095
879	08/10/2023	1132254	Consumables		997062
879	08/10/2023	1132254	PTI Tablet Entered -Elec and Light - Exterior Lights os fron	repaired o/s/f park light lens ok.	997062
879	08/10/2023	1132244	Consumables		997062
879	08/10/2023	1132244	PTI Tablet Entered -Body - Rear_Door Operation Faulty	removed rear door and repaired rear door ok.	997062
879	08/09/2023	1132030	Consumables		997062
879	08/09/2023	1132030	Ops Entered - Fault - Body Rear_Door Operation Faulty - Ro	checked operation of rear passenger door with am runout driver. could not fault	997062
879	08/04/2023	1131231	Consumables		996243
879	08/04/2023	1131231	PTI Tablet Entered -Body - Windows Front bus washed	completed by fleet support	996243
879	07/28/2023	1129762	Consumables		995190
879	07/28/2023	1129762	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced n/s headlight and n/s/f bottom park light globes. Checked all front lights all ok.	995190
879	07/28/2023	1129762	GLOBE 24V H4 75/70W HALOGEN		995190
879	07/26/2023	1129262	Consumables		994654
879	07/26/2023	1129262	Mechanic entered - Elec and Light Exterior Lights O/S/F bott	Replaced O/S/F bottom park light globe.	994654
879	07/14/2023	1126541	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	complete	992044
879	07/13/2023	1124258	Vandalism Graffiti Interior AU	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O346384 Receiving #:364826 Date :2023-07-14	992044
879	07/11/2023	1125592		TRANSMISSION CHECK AS PER CHECK LIST carried out as per check list	991056
879	07/11/2023	1123734		fitted speedo secured wiring and road tested for about 45mins. speedo and speed limiter all working good.	991056
879	07/10/2023	1123734	SENSOR SPEED 4 TERMINAL SCANIA L94 1853436		991056
879	07/10/2023	1123734		road tested with connect and disconnect speedo and sender plugs. no faults occurred with plugs disconnected. fault could likely be the sender. replaced sender and tested looks ok. need a long test drive before release to the service.	991056
879	07/10/2023	1123734	Consumables		991056
879	07/07/2023	1123734	BATTERY 1450CCA POSITIVE ON LEFT H/S EMFN200L		991056
879	07/07/2023	1123734	Mechanic entered - Gearbox Driveline Other Bus jolting / jum	REPLACED both batteries as they cannot hold the charge.	991056
879	07/07/2023	1123734	Mechanic entered - Gearbox Driveline Other Bus jolting / jum	road tested with a new speed relay still the same.	991056
879	07/05/2023	1124258	Vandalism Graffiti Interior AUDIT# 913 OAK 5/7/23		991056
879	07/05/2023	1123734	Mechanic entered - Gearbox Driveline Other Bus jolting / jum	checked the wiring at OSR corner and os ac vent panel.	991056
879	07/03/2023	1123734	Mechanic entered - Elec and Light Other Speedo inaccurate ne	hooked up SD@ and found speedo fault along with throttle and brake padel. SWAPPED THE SPEEDO didn't fix the issue. needs further checks.	991056
879	07/01/2023	1123552		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	991056
879	07/01/2023	1123552		VEHICLE SAFETY INSPECTION Carried out Safety Inspection as per checklist.	991056
879	07/01/2023	1123575	Mechanic entered - Suspension Other Rear sway bar bushes wor	Removed and fitted new sway bar bushes	991056
879	07/01/2023	1123575	BUSH SWAY BAR D/AXLE 47MM SCANIA K1241B 1880751		991056
879	07/01/2023	1123575	Mechanic entered - Elec and Light Exterior Lights Rear door	Removed and fitted new step light globe.	991056
879	07/01/2023	1123575	Consumables		991056
879	06/13/2023	1120006	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	completed by consat installers - garys team	986919
879	06/07/2023	1118855		checked and found antenna cable plug at radio us. fitted new cable end connector and tested ok.	985911
879	06/07/2023	1118855	Consumables		985911
879	06/06/2023	1118855	2-way radio not working	double entry	985911
879	06/05/2023	1118642	Ops Entered - Fault - Elec and Light Two Way Radio - Route	checked operation of 2-way could not fault	985911
879	06/05/2023	1118642	Consumables		985911
879	05/27/2023	1117192	Ops Entered - Fault - Elec and Light Two Way Radio - Route	checked operation of 2-way with oakleigh operations . loud and clear both ends . could not fault	984328
879	05/27/2023	1117192	Consumables		984328
879	05/20/2023	1115904	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	982919
879	05/19/2023	1114984	Mechanic entered - Body Other REAR DOOR NOT WORKING AND REAR	completed repairs and tested ok	982919
879	05/18/2023	1114984	Mechanic entered - Body Other REAR DOOR NOT WORKING AND REAR	continued the rear door repairs	982919
879	05/17/2023	1114984	Mechanic entered - Body Other REAR DOOR NOT WORKING AND REAR	removed rear door and top parts repair cracked shelf plate and makefit gussets and weld inrefit shelf plate and pivot sharft. FIT DOOR RAMREHANG DOOR AND ADJUSTCHECK OPERATIONOK.	982919
879	05/13/2023	1114336		VEHICLE SAFETY INSPECTION	982919
879	05/13/2023	1114336		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	982919
879	05/13/2023	1114357	Mechanic entered - Steering Other O/S/F TYRE HIT FROM SWAY B	Adjusted N/S/F AXLE STOP BOLT OK.	982919
879	05/13/2023	1114357	SWITCH STOP YELLOW (62628)(50V2242)		982919
879	05/13/2023	1114357	Mechanic entered - Elec and Light Other O/S MIDDLE PAX SWITD	replaced O/S MIDDLE PAX SWITCH OK.	982919
879	05/13/2023	1114357	Consumables		982919
879	05/13/2023	1114357	Mechanic entered - Body Other WHEEL CHAIR RAMP PIN OFF.	PUT IN WHEEL CHAIR RAMP PIN OK.	982919
879	05/13/2023	1114357	Mechanic entered - Body Other O/S MIDDLE SEAT TOP PINS OFF.	PUT IN O/S MIDDLE SEAT TOP PIN OK.	982919
879	05/13/2023	1114357	Mechanic entered - Body Other REAR MODESTY PANEL LOOSE.	repaired REAR MODESTY PANEL OK.	982919
879	05/13/2023	1114357	Mechanic entered - Air System Other AIR COMPRESSOR HOSE AIR	repaired AIR COMPRESSOR HOSE OK.	982919

879	05/12/2023	1114261	Vandalism	Vandalism/ Graffiti Interior FILM REPLACEMENT A	Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O343029 Receiving #:360623 Date :2023-05-15 FILM REPLACEMENT AUDIT # 875 5/5/23 fit globe.	982919
879	05/12/2023	1114261	DIRECT PURCHASE	- VANDALISM		982919
879	05/11/2023	1113784	PTI Tablet Entered	-Elec and Light - Exterior Lights front t		982402
879	05/11/2023	1113784	Consumables			982402
879	05/03/2023	1112038				981235
879	05/03/2023	1112038	OIL SAMPLE KIT AMPOL			981235
879	05/03/2023	1112038	PAPER SPINNER FILTER OIL INSERT SCANIA L94			981235
879	05/03/2023	1112038	O-RING SPINNER FILTER SCANIA L94			981235
879	05/03/2023	1112038	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			981235
879	05/03/2023	1112038	FILTER FUEL SCANIA L94(1372444)			981235
879	05/03/2023	1112038	FILTER OIL SCANIA K93 L94 1117285 2059778		Creditor #:-VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O339420 Receiving #:357039 Date :2023-03-22 replaced rear suspension control solenoid valve. replaced two brass fittings and road tested for two hrs on different road conditions.. kneel/raise auto reset and all working good.	981235
879	05/03/2023	1112038	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			981235
879	05/03/2023	1112038	Consumables			981235
879	05/03/2023	1112038	Consumables			981235
879	05/02/2023	1111948	WIPER REFILL 1000mm MULTI FIT SUIT 8 + 9.5MM			981235
879	05/02/2023	1111948	Mechanic entered	- Wipers and Washers Wipers Not_Clearing Sc		981235
879	05/02/2023	1111948	PTI Tablet Entered	-Body - Windows Front wipers are Noisy		981235
879	04/29/2023	1111440	Vandalism	Vandalism/ Graffiti Interior		981049
879	04/20/2023	1109928				980142
879	03/30/2023	1106577	PTI Tablet Entered	-Elec and Light - Exterior Lights on fron		977127
879	03/29/2023	1106282	remove intercooler / wash radiator		Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O339239 Receiving #:356708 Date :2023-03-17 AUDIT 841 TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS VEHICLE SAFETY INSPECTION ANNUAL SAFETY INSPECTION SERIAL # ____RSI 054834 PASS____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 double entry checked the wiring at osr aircon duct panel osr eng bay and osf pillar. couldn't find any rubbing wires. road tested but no fault occurred. need more info to diagnose. raising front or the rear side etc... 2-way repaired by Frank from CSE cross come at oakleigh on 21-2-23 Found 12 volt inverter for two way faulty removed from old bus 322 fit back and tested found working okay	976900
879	03/29/2023	1106282	Driver Tablet Entered	-BusMinder - Damagedit looks like the		976900
879	03/22/2023	1104695	Mechanic entered	- Body Other Rear Support pillar behind fu		975787
879	03/22/2023	1104695	Consumables			975787
879	03/21/2023	1102917	DIRECT PURCHASE	- BUS INSPECTI		975787
879	03/18/2023	1103455	Vandalism	Vandalism/ Graffiti Interior AUDIT # 841		974759
879	03/17/2023	1103550	Workshop Tablet Entered	-Suspension - Kneel/ Raise tried shu		974759
879	03/17/2023	1103550	VALVE RR LEVELLING CNTRL SCANIA 0481830 VOLVO 3944717			975225
879	03/16/2023	1102287	DIRECT PURCHASE	- VANDALISM		974759
879	03/15/2023	1102917				974759
879	03/15/2023	1102917			Creditor #:-VB-CSE001 CSE CROSSCOM PTY LTD P/O #:O337714 Receiving #:355396 Date :2023-02-27 rectify - 2 way coming on and off as required covered with PTV stickers to prevent water from entering - needs to be repaired CARRY OUT A/C - A SERVICE AS PER CHECK LIST - carried out by Ben from cold drive - O338257 could not fault 2 way or a/c. VEHICLE SAFETY INSPECTION TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	974759
879	03/15/2023	1102899	Driver Tablet Entered	-Suspension - Kneel/ Raise		974759
879	03/15/2023	1102900	Driver Tablet Entered	-Suspension - Kneel/ RaiseWhen the		974759
879	03/15/2023	1097305	Driver Tablet Entered	-Elec and Light - Two Way Radio not w		974759
879	03/14/2023	1102780	Ops Entered	- Fault - Elec and Light Two Way Radio - Route:		974759
879	03/10/2023	1102287	Vandalism	Vandalism/ Graffiti Interior AUDIT 841		974224
879	03/10/2023	1102122	Mechanic entered	- Elec and Light Interior Lights Park light		974224
879	03/09/2023	1102005	Consumables			974224
879	03/09/2023	1102005	Ops Entered	- Fault - Body Front_Door Operation Faulty - R		974224
879	03/08/2023	1101765	Mechanic entered	- Elec and Light Exterior Lights Indicator		973837
879	03/08/2023	1101765	LENS AMBER ROUND (85945)		Creditor #:-VB-COLO04 COLD DRIVE PTY LTD P/O #:O338257 Receiving #:355644 Date :2023-03-01 carry out 12 month service as required	973837
879	03/08/2023	1101765	LENS TO SUIT 2063 LAMP 85765			973837
879	03/08/2023	1101795	Consumables			973837
879	03/08/2023	1101795	2nd PRE ASI check			973837
879	03/08/2023	1101765	Mechanic entered	- Air System Air_Leak Doors Front door pres		973837
879	03/08/2023	1101765	REGULATOR DOOR FILTER PNEU SMC RAM W/GAUGE			973837
879	03/08/2023	1101765	Mechanic entered	- Air System Air_Leak Rear Air leaking from		973837
879	03/08/2023	1101765	TEST NIPPLE 16MM SCANIA 30G4500WABCO			973837
879	03/07/2023	1101360	Workshop Tablet Entered	-Suspension - Kneel/ Raisenot raisi		973837
879	03/04/2023	1100922				973837
879	03/04/2023	1100922			Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O343029 Receiving #:360623 Date :2023-05-15 FILM REPLACEMENT AUDIT # 875 5/5/23 fit globe.	973837
879	03/04/2023	1100924	Mechanic entered	- Suspension Other both front D rubber lo		973837
879	03/04/2023	1100924	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081			973837
879	03/04/2023	1100923	Mechanic entered	- Elec and Light Other o/s head light not w		973837
879	03/04/2023	1100923	GLOBE 24V H4 75/70W HALOGEN			973837
879	03/04/2023	1100950	Consumables			973837
879	03/04/2023	1100951	Consumables			973837
879	03/04/2023	1100952	Consumables			973837
879	03/04/2023	1100953	Consumables			973837
879	03/04/2023	1100950	Mechanic entered	- Body Other FRONT BOTTOM RUST.		973837
879	03/04/2023	1100951	Mechanic entered	- Body Other DRIVER DOOR LOOSE.	Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O339239 Receiving #:356708 Date :2023-03-17 AUDIT 841 TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS VEHICLE SAFETY INSPECTION ANNUAL SAFETY INSPECTION SERIAL # ____RSI 054834 PASS____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 double entry checked the wiring at osr aircon duct panel osr eng bay and osf pillar. couldn't find any rubbing wires. road tested but no fault occurred. need more info to diagnose. raising front or the rear side etc... 2-way repaired by Frank from CSE cross come at oakleigh on 21-2-23 Found 12 volt inverter for two way faulty removed from old bus 322 fit back and tested found working okay	973837
879	03/04/2023	1100952	Mechanic entered	- Body Other BUS INSIDE N/S TOP PANEL SCREW		973837
879	03/04/2023	1100953	Mechanic entered	- Body Other BOTH MIDDLE SEAT ALL LOOSE.		973837
879	03/01/2023	1099099	AIR CONDITIONING REPAIR			973383
879	02/27/2023	1097305	Consumables			972907
879	02/27/2023	1097305	DIRECT PURCHASE	- ELECTRICAL		972907
879	02/24/2023	1099168	Mechanic entered	- Body Other NSF top corner has a big hole		972594
879	02/24/2023	1099099				972594
879	02/15/2023	1096844	Mechanic entered	- A/C Heating Other n/w and 2 way n/w.		970712
879	02/14/2023	1096529				970712
879	02/14/2023	1096529			Creditor #:-VB-CSE001 CSE CROSSCOM PTY LTD P/O #:O337714 Receiving #:355396 Date :2023-02-27 rectify - 2 way coming on and off as required covered with PTV stickers to prevent water from entering - needs to be repaired CARRY OUT A/C - A SERVICE AS PER CHECK LIST - carried out by Ben from cold drive - O338257 could not fault 2 way or a/c. VEHICLE SAFETY INSPECTION TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	970712
879	02/14/2023	1096658	Consumables			970712
879	02/14/2023	1096827	Consumables			970712
879	02/14/2023	1096658	Mechanic entered	- Wheels and Tyres Worn O/S/F and N/S/F Tyr		970712
879	02/14/2023	1096658	TYRE 295/80R22.5 NEW			970712
879	02/14/2023	1096827	Mechanic entered	- Wheels and Tyres Wheel Nut Retension N/S/		970712
879	02/14/2023	1096595	Mechanic entered	- Engine Other Belt Tensioner U/S		970712
879	02/14/2023	1096595	Mechanic entered	- Engine Other idler Pulley U/S		970712
879	02/14/2023	1096595	PULLEY IDLER(SMOOTH PLASTIC)SCANIA 1514086 1428940			970712
879	02/14/2023	1096595	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113			970712
879	02/14/2023	1096691	Consumables		Creditor #:-VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O339420 Receiving #:357039 Date :2023-03-22 replaced rear suspension control solenoid valve. replaced two brass fittings and road tested for two hrs on different road conditions.. kneel/raise auto reset and all working good.	970712
879	02/14/2023	1096692	Consumables			970712
879	02/14/2023	1096691	Mechanic entered	- Elec and Light Two Way Radio cutting off		970712
879	02/14/2023	1096692	Elec and Light	Two Way Radio cutting in and out.		970712
879	02/14/2023	1096595	Mechanic entered	- Body Drivers Seat Controls Drivers seat l		970712
879	02/14/2023	1096595	L/H LOWER SEAT LUMBAR BUTTONS			970712
879	02/11/2023	1096138	Consumables			970712
879	02/11/2023	1096138	BusMinder	No Power charging cable is missing		970712
879	02/10/2023	1095904	Mechanic entered	- BusMinder No Power		970712
879	02/10/2023	1095904	Consumables			970712
879	02/10/2023	1095904	Mechanic entered	- Elec and Light Other Bus minder USB clabe	Creditor #:-VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O339420 Receiving #:357039 Date :2023-03-22 replaced rear suspension control solenoid valve. replaced two brass fittings and road tested for two hrs on different road conditions.. kneel/raise auto reset and all working good.	970712
879	02/10/2023	1095904	USB 5V 3A DUAL CONVERTER MODULE BUS MINDER			970712

879	02/10/2023	1095913		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	970712
879	02/08/2023	1095348	Consumables		970257
879	02/08/2023	1095348	Ops Entered - Fault - Elec and Light Two Way Radio - Route	double entry	970257
879	02/08/2023	1095348	two way not working	traced and found blown fuse to 12 volt invertor . replaced fuse . invertor now working . 2 -way all ok	970257
879	02/08/2023	1095348	Driver Tablet Entered -Elec and Light - Two Way Radiolos	double entry	970257
879	02/04/2023	1094848	Vandalism Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI	969774
879	01/28/2023	1093355	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	968585
879	01/18/2023	1091810	Consumables		967360
879	01/18/2023	1091810	passenger doors not operating	traced and found that RPD node required resetting . reset RPD node . checked operation of both passenger doors . all ok	967360
879	01/16/2023	1091284	Mechanic entered - A/C Heating Other inlet air filter loose	removed the lock side strip as all the rivets were loose. fitted rivets and locks; cleaned and secured the filter. ok	967116
879	12/19/2022	1087253	Consumables		963688
879	12/19/2022	1087253	Mechanic entered - Elec and Light Exterior Lights O/S/F top	Replaced N/S/F top globe. Checked park lights all working.	963688
879	12/15/2022	1085541	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	road tested; doors working fine. rebound door lights all good.	963260
879	12/15/2022	1085541	Consumables		963260
879	12/14/2022	1085541	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	REPLACED AND set up rear door pressure sensor. also changed door switch as 1/10 times no beep when the switch pressed.	963260
879	12/14/2022	1085541	SWITCH DOOR CONTACT (NORMALLY OPEN)		963260
879	12/09/2022	1085541	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	fitted new door rebound sensor from 882 still nw. replaced with a new one. need BW instruction to program the new sensor.	963260
879	12/09/2022	1085541	PRESSURE SENSOR		963260
879	12/09/2022	1085541	CONNECTOR CABLE - FOR 540211 PRESSURE SENSOR		963260
879	12/08/2022	1085557	Mechanic entered - Wheels and Tyres Wheel Nut Retension Bot	carried out retorque as required	963260
879	12/08/2022	1085557	Consumables		963260
879	12/08/2022	1085541	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	bus changed over for rear door not closing. checked and found rebound sensor displaying 2.46bar all the time regardless the door open or closed. suspect door rebound sensor. contacted Ben Were; not answered	963260
879	12/06/2022	1084592	installed new foot brake valve	had to remove foot valve as no access to adjust retarder. fitted back after lining up the screw thru the hole and tested ok.	962899
879	12/06/2022	1085078	N/S/R NUMBER 5 GLASS LOOSE. booked for 7-12-22 alpha LDM	O333851 n/s/r glass x 1 replaced by alpha - will	962899
879	12/06/2022	1085078	N/S/R NUMBER 5 GLASS LOOSE. booked for 7-12-22 alpha LDM	Assisting	962899
879	12/06/2022	1085078	GLASS WINDSCREEN C860 C-MAX BO	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O333851 Receiving #:350977 Date :2022-12-09 replaced n/s/r glass x 1 as required	963260
879	12/06/2022	1085078	Consumables		963260
879	12/05/2022	1080803	COOLANT FILLER PIPE L94	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O332435 Receiving #:350555 Date :2022-12-05	962899
879	12/05/2022	1084592	installed new foot brake valve	R&R footbrake valve . brake test and road test all ok .	962899
879	12/05/2022	1080803	PROJECTA PIECE SCANIA	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O332435 Receiving #:350555 Date :2022-12-05	962899
879	12/05/2022	1080803	SENDER PARK BRAKE SCANIA L94UA	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O332435 Receiving #:350555 Date :2022-12-05	962899
879	12/05/2022	1080803	SWITCH PRESSURE SCANIA L94UAB	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O332435 Receiving #:350555 Date :2022-12-05	962899
879	12/05/2022	1080803	Consumables		962899
879	12/03/2022	1084592	retarder not working	diagnosed and checked foot valve potentiometre faulty.	962899
879	12/03/2022	1084592	VALVE FOOT SCANIA SR3 & SR4 0469052 571136		962899
879	12/02/2022	1084322		VEHICLE SAFETY INSPECTION	962899
879	12/02/2022	1084322		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	962899
879	12/02/2022	1084521	TYRE 295/80R22.5 RECAP		962899
879	12/02/2022	1084521	Mechanic entered - Wheels and Tyres Other REAR TYRES U/S.	P4 and P3 worn 2mm. Uneven wear on P5 tyre. Replaced P3 and P4 tyres with new retread. Checked P6 tyre 14mm tread left. Matched and replaced P5 tyres with new retread.	962899
879	12/02/2022	1084521	Consumables		962899
879	12/02/2022	1084429	AIRBAG REAR 16MM SCANIA K280UB K310 6714 NP02 40Y2222		962899
879	12/02/2022	1084373	BOLT V STAY ASSY CENTRE BUSH SCANIA L94		962899
879	12/02/2022	1084429	Mechanic entered - Suspension Other N/S/R/F AIR BAG U/S BECA	removed N/S/R/F AIR BAG replaced N/S/R/F AIR BAG OK.	962899
879	12/02/2022	1084373	Mechanic entered - Suspension Other V rod bolt u/s because	removed v ROD BOLT replaced V ROD BOLT OK.	962899
879	12/02/2022	1084442	Mechanic entered - Engine Other SPINNER OIL PIPE CLAMP BOLT	replaced SPINNER OIL PIPE CLAMP BOLT OK.	962899
879	12/02/2022	1084442	Mechanic entered - Fluid Leaks Other COOLANT HEAD TANK CAP L	replaced COOLANT HEAD TANK CAP ASSY OK.	962899
879	12/02/2022	1084373	Mechanic entered - Elec and Light Other n/s head light crack	replaced N/S HEAD LIGHT OK.	962899
879	12/02/2022	1084373	HEADLIGHT INSET 178MM HI/LO		962899
879	12/02/2022	1080803	Elec and Light Warning Light On Dash low air pressure war	replaced P/B and low air pressure warning switch.	962899
879	12/02/2022	1080803	Elec and Light Warning Light On Dash low air pressure war	assisted CDF to identify switches	962899
879	12/02/2022	1084373	Consumables		962899
879	12/02/2022	1084442	Mechanic entered - Body Other DRIVER SEAT BACK MODESTY PANEL	repaired DRIVER SEAT BACK MODESTY PANEL OK.	962899
879	12/02/2022	1084442	Mechanic entered - Body Other BUS INSIDE REAR MIRROR VERY LO	repaired BUS INSIDE REAR MIRROR OK.	962899
879	12/02/2022	1084442	Mechanic entered - Body Other DRIVER DOOR VERY LOOSE.	repaired DRIVER DOOR OK.	962899
879	12/02/2022	1084442	Consumables		962899
879	12/02/2022	1084429	DIRECT PURCHASE - BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O333639 Receiving #:350644 Date :2022-12-06 reline rears and supply brake drums if found under sized	963035
879	12/02/2022	1084429	Mechanic entered - Brakes Other BOTH REAR BRAKE LININGS LOW.	removed BOTH REAR BRAKE LININGS DURMS.	962899
879	12/02/2022	1084429	Brakes Park_Brake Not Holding - spongy	removed rear brakes to send away PO#: O333639	962899
879	12/02/2022	1084429	Brakes Park_Brake Not Holding - spongy	Assisting - brakes picked up @ 10.35am	962899
879	12/02/2022	1084416	SLACK ADJUSTER AUTO-REAR N/SIDE SERIES 4(2009819)		962899
879	12/02/2022	1084416	Mechanic entered - Brakes Other N/S/R BRAKE SLACK ADJUST U/S	removed N/S/R BRAKE SLACK ADJUST replaced N/S/R BRAKE SLACK ADJUST OK.	962899
879	12/02/2022	1084429	Mechanic entered - Brakes Other BOTH REAR BRAKE LININGS LOW.	Fitted new brake shoes and drum for O/S/R. Cleaned wheel rims and fitted new retread tyres for O/S/R. Tensioned all wheel nuts.	962899
879	12/02/2022	1084429	Mechanic entered - Brakes Other BOTH REAR BRAKE LININGS LOW.	Assisted with cleaning and fitting brake drums. Adjusted both rear brakes. Retensioned both rear wheel nuts to 650nm.	962899
879	12/02/2022	1084429	Mechanic entered - Brakes Other BOTH REAR BRAKE LININGS LOW.	Assembled new brake lining and drum for o/s/r fit wheel back with one new retread	962899
879	11/24/2022	1082747		TRANSMISSION CHECK AS PER CHECK LIST Carried Out Transmission Check.	961675
879	11/22/2022	1082353	Mechanic entered - Engine Other Idler Pulley U/S	removed worn idler pulley replaced with new item from stock.	960921
879	11/22/2022	1082353	PULLEY IDLER(SMOOTH PLASTIC)SCANIA 1514086 1428940		960921
879	11/22/2022	1082353	Mechanic entered - Engine Other Belt Tensioner U/S	removed worn belt tensioner replaced with new item from stock.	960921
879	11/22/2022	1082353	TENSIONER ALT BELT SCANIA N310UA 2197005 1859657		960921
879	11/22/2022	1082353	Mechanic entered - Body Passenger Seat Torn O/S/R Seat Base	removed torn seat base replaced with new item from stock.	960921
879	11/22/2022	1082353	SEAT CUSH SINGLE CEN CRV CA		960921
879	11/22/2022	1082353	Consumables		960921
879	11/22/2022	1082353	Consumables		960921
879	11/22/2022	1082272	Consumables		960921
879	11/22/2022	1082272	Consumables		960921
879	11/22/2022	1082272	Consumables		960921
879	11/22/2022	1082272	O-RING LARGE SPINNER FILTER SCANIA L94 & K230	CARRY OUT B SERVICE AS PER CHECK LIST	960921
879	11/22/2022	1082272	PAPER SPINNER FILTER OIL INSERT SCANIA L94	Assisting	960921
879	11/22/2022	1082272	O-RING SPINNER FILTER SCANIA L94		960921
879	11/22/2022	1082272	OIL SAMPLE KIT AMPOL		960921
879	11/22/2022	1082272	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814		960921
879	11/22/2022	1082272	FILTER OIL SCANIA K93 L94 1117285 2059778		960921
879	11/22/2022	1082272	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		960921
879	11/22/2022	1082272	FILTER FUEL SCANIA L94(1372444)		960921
879	11/22/2022	1082272	Consumables		960921
879	11/19/2022	1081360	Apply print film	Completed 09/11/22	960921
879	11/18/2022	1081360	Apply print film L1 R1	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O332597 Receiving #:349804 Date :2022-11-23	961675
879	11/14/2022	1080803	Elec and Light Warning Light On Dash low air pressure war	CHECKED low air switch and ordered	960359
879	11/12/2022	1080620	Drv entered - Brakes Foot_Brakes Leaking Air	Checked for air leaks from brake boostersand valves could not find any air leaks	960359
879	11/12/2022	1080620	Drv entered - Brakes Foot_Brakes Leaking Air	Carry out road test and brake test	960359
879	11/10/2022	1080121	low air warning alarm is on	build air pressureroad testcould not fault.	959995

879	11/08/2022	1079851	Mechanic entered - Air System Air Not Building_Up	Drained all air tanks checked for air leaks could not find any road tested found okay	959768
879	11/07/2022	1060226	CAMERA INTERNAL 2.1mm LENS		959566
879	11/05/2022	1079352	Vandalism Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI	959566
879	10/29/2022	1078298	Consumables		958881
879	10/29/2022	1078298	Mechanic entered - Elec and Light Exterior Lights n/s headli	fit globe	958881
879	10/29/2022	1078298	Consumables		958881
879	10/27/2022	1078030	Consumables		958749
879	10/27/2022	1078030	Mechanic entered - Elec and Light Warning Light On Dash Alte	Removed and fitted new alternator regulator. Road tested bus and checked warning light gone.	958749
879	10/27/2022	1078030	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315		958749
879	10/27/2022	1078030	Consumables		958749
879	10/25/2022	1077564	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Replaced swollen sight glass hose with new. Replaced hose clamps. Washed bus. Checked for leaks all ok.	958277
879	10/21/2022	1076952	Consumables		957575
879	10/21/2022	1076952	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Retensioned O/S/R wheel nuts to 650 nm.	957575
879	10/21/2022	1076952	Consumables		957575
879	10/21/2022	1076763	Drv entered - Brakes Foot_Brakes are not functioning takes	completed on defect number 950139	957575
879	10/20/2022	1076702	Consumables		957575
879	10/20/2022	1076702	TYRE 295/80R22.5 RECAP		957575
879	10/20/2022	1076702	Mechanic entered - Wheels and Tyres Worn Pos 6 tyre worn	Replaced with new retread	957575
879	10/20/2022	1076702	Consumables		957575
879	10/20/2022	1076702	Ops Entered - Fault - Brakes Park_Brake Not Holding - Route	Checked for brake linings linings good. Adjusted brakes road tested and brake tested bus. Brakes working normal.	957575
879	10/13/2022	1075112	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	carried out campaign	956121
879	10/11/2022	1074227	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	REPAIR PIVOT SHAFT BOTTOM CARRIEREFIT ALL PARTSADJUST DOORCHECK OPERATIONOK.	956121
879	10/11/2022	1074227	Consumables		956121
879	10/10/2022	1074227	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	found rear leaf pivot shaft base guide pin brokenremove doorrampivot shaft and base plate.	956121
879	10/03/2022	1072669	Engine thermostat requires replacement	Drain coolant remove guards remove thermostat housing replaced thermostat with new one fit back top up coolant wash and road test Fit back guard	955140
879	10/03/2022	1072669	THERMOSTAT 75/79 DEG - DOUBLE SCANIA L94UAB 1745449		955140
879	09/30/2022	1072359		VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list.	954979
879	09/30/2022	1072359		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	954979
879	09/29/2022	1072085	Workshop Tablet Entered -A/C Heating - Not Heating	O329836 - repaired by cold drive cammy - O329836	954966
879	09/29/2022	1072085	AIR CONDITIONING REPAIR	Creditor #:\VB-COL004 COLD DRIVE PTY LTD P/O #:\O329836 Receiving #:\346654 Date :2022-10-04 rectify heaters not working as required	955183
879	09/20/2022	1070659	Mechanic entered - Engine Other head tank cap leaks.	Removed and replaced air compressor fitted new bolt for drive gear torque to specification fit back connect all pipes repair thread for main line fitting Fill up coolant wash and road test	953745
879	09/20/2022	1070659	BOLT COMPRESSOR GEAR SCANIA		953745
879	09/20/2022	1070659	O-RING SEAL COMPRESS MOUNT MERC SCANIA L94 323790 B7R 975610		953745
879	09/20/2022	1070659	O-RING COMPRESSOR 11MM ID SCANIA L94UB(1376911)		953745
879	09/20/2022	1070659	Mechanic entered - Engine Other head tank cap leaks.		953745
879	09/20/2022	1070659	AIR COMPRESSOR - WITH REAR COVER PLATE		953745
879	09/08/2022	1068459	Mechanic entered - Engine Other head tank cap u/s.	replaced head tank cap after road tested ok head tank cap no leaks.	951599
879	09/08/2022	1068459	CAP EXPANSION TANK 0.75BAR SCANIA K93 L94 L113(1403954)		951599
879	09/05/2022	1067638		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	951044
879	08/31/2022	1067009	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Checked and found header tank cap threaded piece damage replaced with good second hand one Wash and road test found okay	950713
879	08/29/2022	1066523	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Replaced leaking header tank cap top up coolant	950259
879	08/29/2022	1066523	CAP EXPANSION TANK 0.75BAR SCANIA K93 L94 L113(1403954)		950259
879	08/29/2022	1066450		complete	950259
879	08/18/2022	1063948	Consumables		948378
879	08/18/2022	1063948	Consumables		948378
879	08/18/2022	1063948	Side glass - cut to size LAM (	Creditor #:\VB-OBRIEN O'BRIEN GLASS INDUSTRIES LTD P/O #:\O327219 Receiving #:\343577 Date :2022-08-18 replace n/s/r cracked glass as required	948378
879	08/17/2022	1064064	Consumables		948287
879	08/17/2022	1064064	Consumables		948287
879	08/17/2022	1063948	n/s/r glass cracked	O327219 - glass replaced by obrian	948287
879	08/17/2022	1064064	Mechanic entered - Body Mirrors Interior Interior mirror loo	Tightened secured and adjusted mirror.	947042
879	08/09/2022	1062210	Mechanic entered - Elec and Light Exterior Lights O/S headli	Removed and fitted new headlight globe.	947042
879	08/09/2022	1062210	Consumables		946920
879	08/09/2022	1062210	Consumables		946920
879	08/08/2022	1061846		VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list.	946920
879	08/08/2022	1061846		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	946920
879	08/08/2022	1061899	BUSH SWAY BAR D/AXLE 47MM SCANIA K124IB 1880751		946920
879	08/08/2022	1061899	Mechanic entered - Suspension Other Rear sway bar bushes wor	Removed and fitted new sway bar bushes.	946920
879	08/08/2022	1061899	Mechanic entered - Body Other No smoking decal missing	Fitted new decals.	946920
879	08/08/2022	1061899	Mechanic entered - Body Other O/S 1st passenger stop button	Fitted new stop button	946920
879	08/08/2022	1061899	SWITCH STOP YELLOW (62628)(50V2242)		946920
879	08/08/2022	1061899	Mechanic entered - Body Other Front blind guides off	Refitted and secured guides.	946920
879	08/08/2022	1061899	Mechanic entered - Body Other Disability seat top top hindg	Refitted and secured hindge.	946920
879	08/08/2022	1061899	Consumables		946920
879	08/08/2022	1061899	Consumables		946920
879	08/01/2022	1060242	Mechanic entered - Fluid Leaks Other coolant overfull.	drain coolantroad tested ok.	945539
879	08/01/2022	1060226	Ops Entered - Fault - CCTV Warning Light On - Route: 703 -	change the cctv camera and cable	945539
879	07/30/2022	1060226	Ops Entered - Fault - CCTV Warning Light On - Route: 703 -	checked and found front blurry; repaired wiring and clkeaned the windshield in and outside. also rear door cam not clear as there were two lights dots appearing but no footages. replaced with digital camera nw. checked wiring and need further check	945539
879	07/22/2022	1058550	DIRECT PURCHASE - VANDALISM	Creditor #:\VB-GLA010 GLASSPROTECH MELBOURNE P/O #:\O325471 Receiving #:\341788 Date :2022-07-25 glass film audit 721 - stage 4	944710
879	07/21/2022	1058550	Vandalism Vandalism/ Graffiti Interior	O325471 - carried out by glass protech	942436
879	07/14/2022	1057319	Mechanic entered - Body Other Interior yellow strip out	Refitted and secured yellow strip	943008
879	07/14/2022	1057319	Consumables		943008
879	07/14/2022	1057319	Consumables		943008
879	07/13/2022	1056994	BELT V-BELT COGGED TRI-POWER 17x2110mm		942798
879	07/13/2022	1056994	Mechanic entered - A/C Heating Belt Loose or_Missing	Removed and fitted new belts. Changed N/S reverse light globe.	942798
879	07/12/2022	1056672	Mechanic entered - A/C Heating Other a/c belt unsecure	removed and resecured belt. road tested and checked ok	942490
879	07/12/2022	1056683	A/C Heating Belt Loose or_Missing	DONE ON WO1056672	942490
879	07/12/2022	1056672	Mechanic entered - Fluid Leaks Rear of bus suspected leak ne	tighten all bolts near suspected leak location road tested and checked no leaks.	942490
879	07/12/2022	1056672	Mechanic entered - Body Other loose power steering resivour	tightened all surrounding and mounting bolt near resvior. all ok	942490
879	07/12/2022	1056672	Consumables		942490
879	07/12/2022	1056672	Consumables		942490
879	07/12/2022	1056527		CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order all check ok	942490
879	07/12/2022	1056527	PAPER SPINNER FILTER OIL INSERT SCANIA L94		942490
879	07/12/2022	1056527	O-RING SPINNER FILTER SCANIA K230		942490
879	07/12/2022	1056527	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		942490
879	07/12/2022	1056527	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		942490
879	07/12/2022	1056527	FILTER FUEL SCANIA L94(1372444)		942490
879	07/12/2022	1056527	FILTER OIL SCANIA K93 L94(1117285)(2059778)		942490
879	07/12/2022	1056527	OIL SAMPLE KIT AMPOL		942490
879	07/12/2022	1056527	Consumables		942490
879	07/12/2022	1056527	Consumables		942490
879	07/12/2022	1056527	Consumables		942490
879	07/12/2022	1056527	Consumables		942490
879	07/12/2022	1056527	Consumables		942490

879	07/12/2022	1056527	Consumables				942490
879	07/01/2022	1054901	Mechanic entered - Body Other Body Support Pillar Behind fue	removed fuel tank located cracks grinded channel into cracks filled with weld making several passes cleaned welds grinded top crack filled channel with weld grinded back welds added 90 degree plate over crack welded plate to support pillar cleaned welds painted refitted tank and fuel lines road tested checked for leaks c			941228
879	07/01/2022	1054901	Consumables				941228
879	07/01/2022	1054901	Consumables				941228
879	06/27/2022	1054010	Mechanic entered - Body Front_Door Operation Faulty	Adjust door closing and opening speed. Road tested and checked door operation. All okay.			940222
879	06/27/2022	1054010	Consumables				940222
879	06/25/2022	1054030	Vandalism Vandalism/ Graffiti Interior	carried out vandelisem painting as required			940222
879	06/22/2022	1052086	Mechanic entered - Suspension Other Front sway Bar U/S	removed worn sway bar replaced with new item tightened checked for correct positioning and replaced split pins road tested ok.			939693
879	06/21/2022	1053002	Mechanic entered - Gearbox Driveline Other Trans Pinion Sea	double entry-job is done			939693
879	06/21/2022	1053002	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734-319-052				939693
879	06/21/2022	1053002	Mechanic entered - Fluid Leaks Other rear trans seal oil le	Removed driveshaft off removed flange with puller replaced seal and fit back flange and driveshaft Wash and road test found okay			939693
879	06/21/2022	1052543	Mechanic entered - Elec and Light AM-FM Radio n/w	repaire the radio connections and change the radio			939693
879	06/21/2022	1052543	RELAY 5 PIN CHANGE OVER 24V 10/20 AMP 68052				939693
879	06/21/2022	1052543	Consumables				939693
879	06/21/2022	1052543	Consumables				939693
879	06/20/2022	1052086	SWAY (ANTI ROLL) BAR FRT SCA	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O323508 Receiving #:339606 Date :2022-06-21			939693
879	06/20/2022	1052543	RADIO 12/24V 3' LCD MULTIMEDIA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O323547 Receiving #:339526 Date :2022-06-20			939693
879	06/18/2022	1052543	Drv entered - Elec and Light AM-FM Radio Missing	radio face missing - ordered			939176
879	06/18/2022	1052544	Mechanic entered - CCTV Other cctv number 2 adjust please.	checked and found all cameras ok. recording and others good. cleaned the lenses and windshield			939176
879	06/16/2022	1052086	Mechanic entered - Suspension Other Front sway Bar U/S	ordered sway bar complete			938577
879	06/15/2022	1051812		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS			938577
879	06/15/2022	1051812		VEHICLE SAFETY INSPECTION			938577
879	06/15/2022	1051905	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)				938577
879	06/15/2022	1051905	Mechanic entered - Suspension Other rear sway bar 'D' Rubber	removed worn 'D' Rubbers replaced with new items from stock checked for play ok.			938577
879	06/15/2022	1051905	Mechanic entered - Fluid Leaks Rear of bus Coolant Leaks	Leaking from hoses from header tank - tightened all hose clamps cleaned area.ok.			938577
879	06/15/2022	1051905	Mechanic entered - Engine Other Belt Tensioner U/S	removed worn belt tensioner replaced with new item from stock.			938577
879	06/15/2022	1051905	Mechanic entered - Engine Other Idler Pulley U/S	removed worn idler pulley replaced with new item from stock.			938577
879	06/15/2022	1051905	TENSIONER ALT BELT SCANIA N310UA 2197005 1859657				938577
879	06/15/2022	1051905	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940				938577
879	06/15/2022	1051905	Mechanic entered - Elec and Light Exterior Lights Rear Step	removed lens replaced blown globe checked for operation all ok refitted lens.			938577
879	06/15/2022	1051905	Mechanic entered - Elec and Light Next Stop Button 1x Pax Sw	removed cracked pax switch replaced with new item checked foroperation ok.			938577
879	06/15/2022	1051905	Mechanic entered - Dash Dash_Lights Not Working 1x dash ligh	removed dash cluster removed blown globe replaced with new globe from stock checked for operation ok.			938577
879	06/15/2022	1051905	Mechanic entered - Elec and Light Interior Lights O/S Saloon	removed cover replaced blown fluro fitted new fluro from stock checked for operation ok refitted cover.			938577
879	06/15/2022	1051905	BELL PUSH STOP BUTTON FLAT (571-0226) (11870)				938577
879	06/15/2022	1051905	Consumables				938577
879	06/15/2022	1051905	Consumables				938577
879	06/15/2022	1051905	Mechanic entered - Body Passenger Seat Torn 1x Torn Seat Bas	removed torn seat base replaced with new item from stock.ok			938577
879	06/15/2022	1051905	SEAT SINGLE CUSH OPITMUS CVR CD				938577
879	06/15/2022	1051905	Mechanic entered - Body Other O/S/F Seat End cap missing	replaced end cap with item from workshop.			938577
879	06/15/2022	1051905	Mechanic entered - Body Other Ramp Pin Not seated	re seated ramp pin.			938577
879	06/15/2022	1051905	Consumables				938577
879	06/11/2022	1051480	Mechanic entered - Elec and Light Other reverse buzzer and l				937886
879	06/11/2022	1051480	Consumables				937886
879	06/11/2022	1051480	Consumables				937886
879	06/10/2022	1051212	LED REAR POSITION STOP(DESIGNLINE)				937886
879	06/10/2022	1051212	Mechanic entered - Elec and Light Exterior Lights n/s/f head	fit globe to headlightfit new light assembly to parker.			937886
879	06/10/2022	1051212	Consumables				937886
879	06/10/2022	1051212	Consumables				937886
879	06/04/2022	1050467	Vandalism Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI			937101
879	06/01/2022	1034895	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290				936358
879	05/30/2022	1048925	Mechanic entered - A/C Heating Demister Not Heating	road testget temp upcould not fault.			935387
879	05/25/2022	1048133	Consumables				934680
879	05/25/2022	1048133	Mechanic entered - Elec and Light Other check reversing buzz	checked reversing buzzerneutral all ok. road tested ok.			934680
879	05/25/2022	1048133	Consumables				934680
879	05/23/2022	1047637	Mechanic entered - Vandalism Vandalism/ Graffiti Exterior gr	cleaned grafiti. all ok			933776
879	05/23/2022	1047643	SENSOR LEVEL FRT SCANIA L94UAB 481829				933776
879	05/23/2022	1047643	VALVE FRT LVL CNTRL VALVE VOLVO B7 SCANIA L94				933776
879	05/23/2022	1047643	Mechanic entered - Suspension Other front Level valve not wo	checked front low raisecheck front air bagscheck air linecheck Level valve removed front Level valve replaced front Level valve ok. removed Levelling cntrl valve replaced Levelling Cntrl valve okroad tested all ok. cleaned coolant sensor ok.			933776
879	05/16/2022	1046284		TRANSMISSION CHECK AS PER CHECK LIST			932598
879	05/16/2022	1046284	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	done			932598
879	05/02/2022	1043364		VEHICLE SAFETY INSPECTION			930971
879	05/02/2022	1043364		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS			930971
879	05/02/2022	1043462	Consumables				930971
879	05/02/2022	1043612	Consumables				930971
879	05/02/2022	1043462	Mechanic entered - Wheels and Tyres Worn N/S/F Tyre U/S - 3m	removed worn tyre replaced with new tyre from stock.			930971
879	05/02/2022	1043462	TYRE 295/80R22.5 NEW				930971
879	05/02/2022	1043612	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Retensioned N/S/F wheel nuts to 650nm.			930971
879	05/02/2022	1043462	Consumables				930971
879	05/02/2022	1043612	Consumables				930971
879	05/02/2022	1043419	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Gr	cleaned with acetone.			930971
879	05/02/2022	1043419	Consumables				930971
879	05/02/2022	1043419	Mechanic entered - Dash Dash_Lights Not Working 2 x Dash Lig	removed cluster fitted 2x new globes checked for operation ok.			930971
879	05/02/2022	1043419	Mechanic entered - Elec and Light Interior Lights drivers li	removed cover lens replaced blown globe checked for operation refitted lens ok.			930971
879	05/02/2022	1043419	Mechanic entered - Dash Other Bus Minder Bracket Loose ripp	removed busminder & Busminder bracket cut sheet metal to sizedrilled out corresponding holes with drill press fitted behing dash plastic fitted bracket to plate tightened with new nuts and bolts refitted busminder bracket and busminder checked for movement ok.			930971
879	05/02/2022	1043419	Mechanic entered - Elec and Light Two Way Radio 2 way radio	added screw into bracket to retain to bus ok.			930971
879	05/02/2022	1043419	Consumables				930971
879	05/02/2022	1043419	Mechanic entered - Body Other Front modesty panel Handle Loo	drilled out loose rivets re rivetted handle ok			930971
879	05/02/2022	1043419	Mechanic entered - Body Windows Rear N/S/R Window Requires R				930971
879	05/02/2022	1043419	Mechanic entered - Body Drivers Seat Controls lumbar control	fitted lumbar cover.			930971
879	05/02/2022	1043419	R/H UPPER SEAT LUMBAR BUTTONS				930971
879	05/02/2022	1043419	Mechanic entered - Body Other N/S/R Sage Catch Missing x1	drilled out rivets fitted new clip checked for locking ok			930971
879	05/02/2022	1043419	CATCH CLAW PLASMA ENGINE HATCH DOOR				930971
879	05/02/2022	1043419	Mechanic entered - Body Other N/S/R Seat Base not retained	lower clips broken removed broken clips fitted new clips from stock refitted base checked ok.			930971
879	05/02/2022	1043419	CENTRA CUSHION CLIP LH				930971
879	05/02/2022	1043419	CENTRA CUSHION CLIP RH				930971
879	05/02/2022	1043419	Mechanic entered - Body Other Ramp Pin Not seated	seated Ramp Pin			930971
879	05/02/2022	1043419	Mechanic entered - Body Other Disabled seat top pins not sea	seated disabled seat top pins.			930971
879	05/02/2022	1043419	Consumables				930971
879	04/30/2022	1043265	Mechanic entered - Elec and Light Exterior Lights N/S/R/T ST	COULD NOT FAULT.			930971
879	04/30/2022	1043265	Consumables				930971
879	04/30/2022	1043265	Consumables				930971
879	04/05/2022	1039148	Mechanic entered - Body Front_Door Operation Faulty not clos	tracerepair wiring to front door external door switch.			926671
879	04/05/2022	1039148	Consumables				926671

879	04/05/2022	1039148	Consumables			926671
879	04/02/2022	1038804	Vandalism/ Graffiti Interior	carried out interior vandeliSEM painting as required		926127
879	04/01/2022	1034081	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O317545 Receiving #:335530 Date :2022-04-21 carry out 24 month service and replaced a/c compressor as required		929360
879	03/31/2022	1038078	Consumables			925538
879	03/31/2022	1038078	Mechanic entered - Body Other doors n/w at times.	foot or park brake on doors okcould not fault.		925538
879	03/31/2022	1038078	Consumables			925538
879	03/22/2022	1036459	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean graffiti all check ok		923429
879	03/22/2022	1036459	Consumables			923429
879	03/22/2022	1036459	Mechanic entered - Elec and Light Exterior Lights	had breakage in wires carry out rewire with new terminal all check ok		923429
879	03/22/2022	1036459	Consumables			923429
879	03/22/2022	1036459	Consumables			923429
879	03/22/2022	1036459	Mechanic entered - Body Other disable tray loose	tighten loose tray all check ok		923429
879	03/22/2022	1036459	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	O-RING LARGE SPINNER FILTER SCANIA L94 & K230	CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order all check ok		923429
879	03/22/2022	1036339	O-RING SPINNER FILTER SCANIA L94			923429
879	03/22/2022	1036339	PAPER SPINNER FILTER OIL INSERT SCANIA L94			923429
879	03/22/2022	1036339	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			923429
879	03/22/2022	1036339	FILTER OIL SCANIA K93 L94 1117285 2059778			923429
879	03/22/2022	1036339	FILTER FUEL SCANIA L94 1372444			923429
879	03/22/2022	1036339	OIL SAMPLE KIT AMPOL			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/22/2022	1036339	Consumables			923429
879	03/18/2022	1035286	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O317870 Receiving #:333517 Date :2022-03-21		923429
879	03/16/2022	1035286		VEHICLE SAFETY INSPECTION		921991
879	03/16/2022	1035286		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		921991
879	03/16/2022	1035286		ANNUAL SAFETY INSPECTION SERIAL # ____RSI 043065 green sheet _____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		921991
879	03/12/2022	1034894		PRE ANNUAL SAFETY INSPECTION CHECK		921991
879	03/12/2022	1034894		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		921991
879	03/12/2022	1034895	Mechanic entered - Suspension Other n/s/r/r air bag u/s.	removed n/s/r/r air bag replaced n/s/r/r air bag ok.		921991
879	03/12/2022	1034895	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290			921991
879	03/12/2022	1034895	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok.		921991
879	03/12/2022	1034895	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940			921991
879	03/12/2022	1034895	Mechanic entered - Elec and Light Other o/s/middle pax switc	replaced o/s middle pax switch ok.		921991
879	03/12/2022	1034895	YELLOW/RED STOP SWITCH (20485)			921991
879	03/12/2022	1034895	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok.		921991
879	03/12/2022	1034895	Consumables			921991
879	03/12/2022	1034895	Consumables			921991
879	03/12/2022	1034895	Mechanic entered - Body Other bus inside rear mirror loose.	tightened bus inside rear mirror bracket screws ok.		921991
879	03/12/2022	1034895	Mechanic entered - Body Other o/s/middle seat top pins off.	put in o/s/middle seat top pins ok.		921991
879	03/12/2022	1034895	Mechanic entered - Body Other o/s/middle reflector u/s.	replaced o/s/middle reflector ok.		921991
879	03/12/2022	1034895	REFLECTOR AMBER 94mm X 44MM (84051)			921991
879	03/12/2022	1034895	Mechanic entered - Body Other n/s/f staunchion pole loose.	replaced n/s/f staunchion pole bolt ok.		921991
879	03/12/2022	1034895	Consumables			921991
879	03/12/2022	1034895	Consumables			921991
879	03/10/2022	1034081	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	cold drive did compressor and then found hose leaking which was the original fault informed to simon when bus sent to knox as the oakleigh ac bay outof service due to concrete works. satya brought the bus back from knox. LDM has completed ac a and b services in tims. entered by kps		921858
879	03/09/2022	1034081	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	a/c compressor replaced by cold drive and 24 month service carried out		921858
879	03/09/2022	1027542	Consumables			922818
879	03/09/2022	1027542	S&F Desto	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O315630 Receiving #:333455 Date :2022-03-18 reseal o/s mid side glass x 1 as required		922818
879	03/09/2022	1027542	Consumables			922818
879	03/09/2022	1034081		CARRY OUT A/C - B SERVICE AS PER CHECK LIST PO#: O317545 - cold drive		921858
879	03/09/2022	1034081		CARRY OUT A/C - A SERVICE AS PER CHECK LIST PO#: O317545 - cold drive		921858
879	02/25/2022	1031833		complete		920119
879	02/25/2022	1031833		CARRY OUT FIRE EXTINGUISHER TEST & TAG		920119
879	02/23/2022	1031114	Consumables			919679
879	02/23/2022	1031114	Ops Entered - Fault - BusMindor No Power - Route: 703 - Kma	checked and repair all wire connections		919679
879	02/23/2022	1031114	Consumables			919679
879	02/23/2022	1031152	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	complete		919679
879	02/21/2022	1030159	Consumables			919479
879	02/21/2022	1030159	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	could not fault door operationpax light comes on when doors closetrace found screw through pax staunchion wiringrepaired wiringok.		919479
879	02/21/2022	1030159	Consumables			919479
879	02/21/2022	1030196		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST done		919479
879	02/21/2022	1030196	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE	rebooked - LDM		919479
879	02/08/2022	1027542	Mechanic entered - Wheels and Tyres Other Needs wheel align			917007
879	02/08/2022	1027542	Consumables			917007
879	02/08/2022	1027542	Consumables			917007
879	02/08/2022	1027524	Consumables			917007
879	02/08/2022	1027524	front passenger is not working correctly	adjust air pressure to front door.		917007
879	02/08/2022	1027524	Consumables			917007
879	02/08/2022	1027542	Consumables			917007
879	02/08/2022	1027542	o/s mid glass requires re-seal x 1 glass	glass resealled by john from alpha - O315630		917007
879	02/07/2022	1026887		VEHICLE SAFETY INSPECTION		916910
879	02/07/2022	1026887		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		916910
879	02/07/2022	1026944	Consumables			916910
879	02/07/2022	1026965	Consumables			916910
879	02/07/2022	1027028	Consumables			916910
879	02/07/2022	1026944	FLUORO COOL WHITE 36W			916910
879	02/07/2022	1026944	SWITCH STOP YELLOW (62628)(50V2242)			916910
879	02/07/2022	1026965	NUT BRASS BATTERY TERMINAL POSITIVE (+) MA14HDP			916910
879	02/07/2022	1026965	Mechanic entered - Elec and Light Other battery terminal is	replaced terminal		916910
879	02/07/2022	1026944	Mechanic entered - Elec and Light Other n/s/r pax switch u/s	replaced n/s/r pax switch ok.		916910
879	02/07/2022	1027028	Mechanic entered - Elec and Light Other CCTV image is not cl	adjust and clean the CCTV lense		916910
879	02/07/2022	1026944	Consumables			916910
879	02/07/2022	1026965	Consumables			916910
879	02/07/2022	1027028	Consumables			916910
879	02/07/2022	1026944	Consumables			916910
879	02/07/2022	1026944	Mechanic entered - Body Other n/s/f step edge missing.	installed new step edge		916910
879	02/07/2022	1026944	Mechanic entered - Body Other o/s/middle seat top pin off.	put in o/s/middle seat top pins ok.		916910
879	02/07/2022	1026944	Mechanic entered - Body Other o/s/middle seat loose.	repaired o/s/middle seat ok.		916910

879	02/07/2022	1026944	Mechanic entered - Body Other n/s/f staunchion pole bolt loo	tightened n/s/fstaunchion pole bolt ok.	916910
879	02/07/2022	1026944	Mechanic entered - Body Other driver seat back modesty panel	repaired driver seat back modesty panel ok.	916910
879	02/07/2022	1026944	Mechanic entered - Body Other wheel chair ramp pin off.	put in wheel chair ramp pin ok.	916910
879	02/07/2022	1026944	Consumables		916910
879	01/31/2022	1025704	Mechanic entered - Elec and Light Next Stop Button O/S/R but		915969
879	01/31/2022	1025704	Consumables		915969
879	01/31/2022	1025704	Consumables		915969
879	01/11/2022	1021925		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	911982
879	01/11/2022	1021925		SERVICE MOISTURE EJECTOR	911982
879	01/11/2022	1021925	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		911982
879	12/22/2021	1019293	Body Front_Door Operation Faulty ref wo 1017527 rebound s	done by BW PO 0313259	908864
879	12/22/2021	1019293	Consumables		909162
879	12/21/2021	1019045		VEHICLE SAFETY INSPECTION	908864
879	12/21/2021	1019045		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	908864
879	12/21/2021	1019080	Mechanic entered - Wipers and Washers Other o/s/wiper washer	repaired o/s wiper washer ok.	908864
879	12/21/2021	1019076	Mechanic entered - Wheels and Tyres Other both rear tyre u/s	removed both rear tyres replaced both rear tyres ok.	908864
879	12/21/2021	1019076	TYRE 295/80R22.5 RECAP		908864
879	12/21/2021	1019210	Mechanic entered - Wheels and Tyres Wheel Nut Retension bot	carried out retorque as required	908864
879	12/21/2021	1019076	Consumables		908864
879	12/21/2021	1019210	Consumables		908864
879	12/21/2021	1019080	Mechanic entered - Elec and Light Other both middle pax stop	replaced both middle pax stop switch ok.	908864
879	12/21/2021	1019080	YELLOW/RED STOP SWITCH (20485)		908864
879	12/21/2021	1019080	Consumables		908864
879	12/18/2021	1018685	Engine MAIN BELT WORN	could not fault.	908370
879	12/18/2021	1018686	Fluid Leaks Rear of bus header tank leaking	header tank splitfit newtop up coolant road testok.	908370
879	12/18/2021	1018686	EXPANSION TANK SIDE FILL COMP ASSY SCANIA 1731694 1896287		908370
879	12/16/2021	1017527	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	refit rams to shelf platerelang doorsadjustroad testok.	908326
879	12/16/2021	1017527	Consumables		908326
879	12/15/2021	1017527	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	REPAIR CRACKED SHELF PLATEWELD AND GUSSETREFIT SHELF PLATE AND PIVOT SHARFTS.	908326
879	12/15/2021	1017527	BEARING (FYH)		908326
879	12/15/2021	1017527	BEARING FOR HOUSING LF205		908326
879	12/15/2021	1017527	HOUSING BRAKET (FOR SB202-01-FYH BEARING)		908326
879	12/15/2021	1017527	HOUSING FOR BEARING AS205-100		908326
879	12/14/2021	1017527	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	in process changing door pivot bearingsremove cracked shelf plate.	908326
879	12/13/2021	1017527	Ops Entered - Fault - Body Front_Door Operation Faulty - R	O312706 for statewide bearing	908078
879	12/13/2021	1017527	BEARING FOR HOUSING LF205	Creditor #.:VB-STA101 STATEWIDE BEARINGS P/O #.:O312706 Receiving #:327885 Date :2021-12-13 supply bearings as required	908326
879	12/13/2021	1017527	HOUSING FOR BEARING AS205-100	Creditor #.:VB-STA101 STATEWIDE BEARINGS P/O #.:O312706 Receiving #:327885 Date :2021-12-13 supply bearings as required	908326
879	12/11/2021	1017558	Vandalism Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI	908078
879	12/09/2021	1016963	Body Front_Door Operation Faulty front door rear leaf sti	checked and found the front door rear leaf not closing as sticky before the full close. removed the ram shaft end and found it's bearing. removed and freed the bearing and teted ok.	908078
879	12/09/2021	1016963	Consumables		908078
879	12/07/2021	1019293	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #.:O313259 Receiving #:328480 Date :2021-12-22 check and rectify rebound sensor too sensitive pre wo ref1017527	909162
879	12/01/2021	1015133	Mechanic entered - Body Front_Door Operation Faulty rear lea	nosing rubber hitting ramp edgeraise nosing rubberok.	907648
879	12/01/2021	1015133	Consumables		907648
879	11/30/2021	1014853	Mechanic entered - Body Front_Door Operation Faulty not clos	adjust air pressure to front door regulatorroad test ok.	907474
879	11/29/2021	1014417	Mechanic entered - Body Front_Door Operation Faulty sticking	lubed guide rollers and tracks.	906572
879	11/19/2021	1012671	Ops Entered - Fault - Dash Speedo Not Working - Route: 703	checked with a different speedo head; suspect sender fit new senderroad test ok.	905184
879	11/19/2021	1012671	SENSOR SPEED 4 TERMINAL SCANIA	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #.:O311200 Receiving #:326185 Date :2021-11-19	905184
879	11/19/2021	1012671	Consumables		905184
879	11/17/2021	1012272		TRANSMISSION CHECK AS PER CHECK LIST	904888
879	11/17/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Wash bus fit hatch back road test and check all oil and coolant level again	904888
879	11/17/2021	1004223	40A5409 Hose Oil Return	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #.:O310965 Receiving #:326032 Date :2021-11-18 879	905069
879	11/17/2021	1004223	40A5406 Gasket Oil Return	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #.:O310965 Receiving #:326033 Date :2021-11-18 879	905069
879	11/16/2021	1004223	FILTER OIL SCANIA S4 & K		904888
879	11/16/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Fit converter bolts fit turbo return pipe connect all coolant hoses clean and fit oil suction pipe fit sump back spinner folter fill oil and coolant . start bus	904888
879	11/16/2021	1004223	PAPER SPINNER FILTER OIL INSERT SCANIA L94		904888
879	11/16/2021	1004223	O-RING LARGE SPINNER FILTER SCANIA 40A7703		904888
879	11/16/2021	1004223	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701		904888
879	11/16/2021	1004223	DIPSTICK ENGINE OIL SCANIA L94UAB 40A8200		904888
879	11/16/2021	1004223	40A5406 Gasket Oil Return		905069
879	11/10/2021	1004223	GASKET OIL COOLER SCANIA L94 UAB 40A2629		904888
879	11/10/2021	1004223	GASKET OIL COOLER SCANIA L94 UAB 40A2627		904888
879	11/10/2021	1004223	GASKET OIL COOLER SCANIA L94 UAB 40A2628		904888
879	11/10/2021	1004223	HOSE TO TOP COMPRESSOR L94UB(205118)		904888
879	11/10/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Cleaned parts fit back oil cooler with new gaskets replaced hose	904888
879	11/09/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	fit new rear main seal fit flywheel and torque to specification Fit gearbox back	904888
879	11/09/2021	1004223	SEAL RR CRANK DS1174 SCANIA L1	Creditor #.:VB-MUL004 MULTISPARES OAKLEIGH P/O #.:O310510 Receiving #:325713 Date :2021-11-11	904888
879	10/27/2021	1004223	381235 Suction ring	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324732 Date :2021-10-28	904888
879	10/27/2021	1004223	Consumables		904888
879	10/25/2021	1004223	GASKET FLYWHEEL HSG SCANIA L94	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324728 Date :2021-10-28	904888
879	10/25/2021	1004223	SEAL RR CRANK DS1174 SCANIA L1	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324728 Date :2021-10-28	904888
879	10/25/2021	1004223	GASKET SUMP SCANIA L94 40A3	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324728 Date :2021-10-28	904888
879	10/25/2021	1004223	GASKET SPINNER HSG MTG SCANIA	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324728 Date :2021-10-28	904888
879	10/25/2021	1004223	1423446 Plastic Plug	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #.:O309181 Receiving #:324728 Date :2021-10-28	904888
879	10/20/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Removed engine oil cooler	904820
879	10/18/2021	1004223	Mechanic entered - Gearbox Driveline Other Trans Pinion Seal	Removed and replaced transmission output seal	904820
879	10/18/2021	1004223	SEAL REAR TRANSMISSION SR 4 SCANIA ZF 0734-319-052		904820
879	10/15/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Removed transmission flywheel bell housing clean parts	904820
879	10/10/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Started removing transmisson	904820
879	10/08/2021	1004433	CCTV (None) front camera 1/3 covered by windshield and rea	fabricate the new extension space holder for the camera	904820
879	10/07/2021	1004223	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	Start removing the bell housing drain oil removed sump remove coolant pipes Started removing transmission	904820
879	10/07/2021	1004167	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		904820
879	10/07/2021	1004167	Mechanic entered - Elec and Light Interior Lights emergency	supply new part fitted new crimp on terminal check and tested ok	904820
879	10/07/2021	1004167	Consumables		904820
879	10/07/2021	1004223	Mechanic entered - Body Other missing exterior panel reflec	could not fault	904820
879	10/07/2021	1004223	Mechanic entered - Body Other missing wheel arch brushes.	booked for mobile mick	904820
879	10/07/2021	1004029		CARRY OUT C SERVICE AS PER CHECK LIST carry out serv as per work order all check ok	904820
879	10/07/2021	1004029	FILTER STEERING FILTER (153468) (0153468)(349619)		904820
879	10/07/2021	1004029	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		904820
879	10/07/2021	1004029	FILTER HYD COOLING FAN SCANIA L94UAB 1354074		904820
879	10/07/2021	1004029	FILTER HYD COOLING FAN SCANIA L94UAB 1354074		904820
879	10/07/2021	1004029	FILTER AIR DRYER SCANIA VOLVO 1393551 20546795 20424148		904820
879	10/07/2021	1004029	FILTER FUEL FILTER SCANIA SR4 (1372444)		904820
879	10/07/2021	1004029	FILTER OIL SCANIA S4 & K		904820

879	10/07/2021	1004029	SAMPLE KIT OIL CALTEX/AMPOL		904820
879	10/07/2021	1004029	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701		904820
879	10/07/2021	1004029	O-RING LARGE SPINNER FILTER SCANIA 40A7703		904820
879	10/07/2021	1004029	PAPER SPINNER FILTER OIL INSERT SCANIA L94		904820
879	10/07/2021	1004029	FILTER WATER SCANIA SR3/SR4 0342988		904820
879	10/07/2021	1004029	Consumables		904820
879	10/07/2021	1004029	Consumables		904820
879	10/07/2021	1004029	Consumables		904820
879	10/07/2021	1004029		CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order all check ok	904820
879	10/07/2021	1004029	Consumables		904820
879	10/07/2021	1004029	Consumables		904820
879	10/07/2021	1004029	Consumables		904820
879	09/29/2021	1002340	Consumables		903726
879	09/29/2021	1002340	Body Front_Door Operation Faulty	checked all ext and int emg switches and found no issues. contacted BW electrics PO#: O307919	903345
879	09/29/2021	1002340	Body Front_Door Operation Faulty	FITTED AND CONNECTED DOOR SWITCHES AFTER ASHLEY FIXED AN ISUE WITH RPD	903345
879	09/29/2021	1002340	DIRECT PURCHASE - ELECTRICAL	Creditor #-VB-BWEO01 BWERE ELECTRICS PTY LTD P/O #-O307919 Receiving #-322788 Date :2021-09-29 check and rectify doors not working as required	903726
879	09/27/2021	1001721		VEHICLE SAFETY INSPECTION Carried out safety inspection	902970
879	09/27/2021	1001721		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	902970
879	09/27/2021	1001791	Mechanic entered - Suspension Other Rear Sway Bar 'D' Rubber	replaced rear sway bar 'D' Rubbers with new items from stock checked ok	902970
879	09/27/2021	1001791	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		902970
879	09/27/2021	1001791	Consumables		902970
879	09/27/2021	1001791	Mechanic entered - Elec and Light Next Stop Button Pax Switc	removed 6x cracked pax switches replaced with new items from stock	902970
879	09/27/2021	1001791	SWITCH STOP YELLOW(62628)		902970
879	09/27/2021	1001791	Mechanic entered - Elec and Light Interior Lights front door	replaced saloon light globe	902970
879	09/27/2021	1001791	Mechanic entered - Elec and Light Reverse Buzzer N/W	checked for power ok found alarm to be not working replaced with new alarm from stock checked for operation ok.	902970
879	09/27/2021	1001791	BUZZER REVERSING 24V 102DB NR72602		902970
879	09/27/2021	1001791	Mechanic entered - Elec and Light Exterior Lights n/s/f uppe	replaced parker light globe tested all ok	902970
879	09/27/2021	1001791	Consumables		902970
879	09/27/2021	1001791	Mechanic entered - Body Drivers Seat Belt Drivers Seat Belt	removed worn buckle replaced with new item from stock	902970
879	09/27/2021	1001791	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		902970
879	09/27/2021	1001791	Mechanic entered - Body Other N/S Disabled seat Not holding	tightened pivot bolts on seat checked ok	902970
879	09/18/2021	1000446	Drv entered - BusMinder No Power	busminder working ok. power is on and charging all good	901540
879	09/18/2021	1000446	Consumables		901540
879	09/15/2021	999651		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	900861
879	09/10/2021	998804	Suspension (None) frt D rubber us	replaced frt D rubbers x 2	900008
879	09/10/2021	998804	Suspension (None) frt D rubber us	Assisting	900008
879	09/10/2021	998804	BUSH SWAY BAR D/AXLE SCANIA K124IB 1880751		900008
879	09/10/2021	998635	Consumables		900008
879	09/10/2021	998635	Consumables		900008
879	09/10/2021	998635	Consumables		900008
879	09/10/2021	998635	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		900008
879	09/10/2021	998635	FILTER OIL SCANIA S4 & K		900008
879	09/10/2021	998635	FILTER FUEL FILTER SCANIA SR4 (1372444)		900008
879	09/10/2021	998635	OIL SAMPLE KIT CALTEX		900008
879	09/10/2021	998635		CARRY OUT B SERVICE AS PER CHECK LIST	900008
879	09/10/2021	998635	SPINNER FILTER OIL INSERT PAPER SCANIA L94		900008
879	09/10/2021	998635	O-RING LARGE SPINNER FILTER SCANIA 40A7703		900008
879	09/10/2021	998635	O-RING SPINNER FILTER SCANIA -> ENG#6203049 40A7701		900008
879	09/03/2021	996818	Consumables		898879
879	09/03/2021	996818	Mechanic entered - Elec and Light Indicators Not Working n/s	fit globe.	898879
879	09/03/2021	996925	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	complete	898879
879	08/20/2021	993630		complete	896207
879	08/20/2021	993630		CARRY OUT FIRE EXTINGUISHER TEST & TAG	896207
879	08/16/2021	992215		VEHICLE SAFETY INSPECTION Carried out Safety inspection	894720
879	08/16/2021	992215		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	894720
879	08/16/2021	992377	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Carried out wheel nut retension to N/S/F	894720
879	08/16/2021	992377	Consumables		894720
879	08/16/2021	992260	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Gr	removed graffiti with acetone ok	894720
879	08/16/2021	992260	Mechanic entered - Engine Other Idler Pulley U/S	Removed worn idler pulley replaced with new item from stock	894720
879	08/16/2021	992260	Mechanic entered - Engine Other Belt Tensioner U/S	Removed worn belt tensioner replaced with new item from stock.	894720
879	08/16/2021	992260	BELT TENSIONER SCANIA N310UA 2197005 1859657		894720
879	08/16/2021	992260	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		894720
879	08/13/2021	992158	Mechanic entered - Wheels and Tyres Worn Pos 1 tyre worn	Replaced tyre with a new one need to send for wheel alignment	894720
879	08/13/2021	992158	TYRE 295/80R22.5 NEW		894720
879	08/13/2021	992158	Consumables		894720
879	08/13/2021	992158	Mechanic entered - Dash Other D selector button broken	Replaced broken D button	894720
879	08/13/2021	992158	BUTTON GEAR SHIFT D VERTICAL SERIES 4		894720
879	08/13/2021	992158	Consumables		894720
879	08/12/2021	991736	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced parklight and headlight globes	894486
879	08/12/2021	991736	Consumables		894486
879	08/07/2021	990581	Mechanic entered - Elec and Light Exterior Lights o/s/r/b pa	fit new LED light.	893309
879	08/07/2021	990581	LAMP LED STOP/TAIL		893309
879	08/07/2021	990581	Consumables		893309
879	07/24/2021	987808	Vandalism Vandalism/ Graffiti Interior	carried out interior vandellisem painting as required	890967
879	07/19/2021	986578	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced h4 globe	889239
879	07/19/2021	986578	Consumables		889239
879	07/19/2021	986289	Mechanic entered - Body Other magnetic phone stand u/s	replaced magnetic phone stand ok.	889239
879	07/19/2021	986289	MAGNETIC PHONE STAND(BUS MINDER)		889239
879	07/19/2021	986289	Consumables		889239
879	07/15/2021	985677	Mechanic entered - Suspension Other both front D rubber u/	removed both front D rubber replaced both front D rubber ok.	888289
879	07/15/2021	985677	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		888289
879	07/15/2021	985868	Mechanic entered - Suspension Other rear sway bar drubber u	completed on w/o -985677	888289
879	07/09/2021	984552	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retorqued n/s/r wheel nuts ok	887736
879	07/09/2021	984552	Consumables		887736
879	07/06/2021	983855		VEHICLE SAFETY INSPECTION done.	887209
879	07/06/2021	983855		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	887209
879	07/06/2021	983989	Mechanic entered - Wheels and Tyres Worn worn n/s/r outter t	r/r tyreok. run out.	887209
879	07/06/2021	983989	Consumables		887209
879	07/06/2021	983989	Mechanic entered - Elec and Light Next Stop Button pax stop	r/r stop buttonok.	887209
879	07/06/2021	983989	Consumables		887209
879	07/06/2021	983989	Mechanic entered - Body Other worn rear pax seat cushion	r/r seat cushionok.	887209
879	07/06/2021	983989	Mechanic entered - Body Other noise from front panel	tighten screwsok.	887209
879	07/06/2021	983989	Mechanic entered - Body Other emergency hatch panel loose	removed & refit panelok.	887209

879	07/06/2021	983989	YELLOW/RED STOP SWITCH (20485)			887209
879	07/06/2021	983989	BRAKE BOOSTER NSR SCANIA 4 SERIES 1446053			887209
879	07/06/2021	983989	Mechanic entered - Body Other noise from rear modesty panel	drilling & rivettingok.		887209
879	07/06/2021	983989	Mechanic entered - Body Other a/c duct panel not secure	removed & repositionok.		887209
879	07/06/2021	983989	Consumables			887209
879	07/06/2021	983989	Mechanic entered - Brakes Other leaking air from n/s/r brake	r/r brake boosterok.		887209
879	06/30/2021	951660	DIAPHRAGM TYPE 24 SHALLOW BRAKE BOOSTER VOLVO B12BLE			885704
879	06/28/2021	981867	LEVEL SENSOR FRT SCANIA L94UAB 481829			885704
879	06/28/2021	981867	Suspension fault - carry out on from breakdown	replaced nsr lev valve.		885704
879	06/28/2021	981867	Suspension fault - carry out on from breakdown	checked pillar wiring for any shortcircuit for nsr lev valve. had cdf tochange levsensor. deleted existing DTCs and road tested. there was no any fault light r DTCs coming in. ok		885704
879	06/26/2021	982369	Vandalism Vandalism/ Graffiti Interior	carried out interior vandalisem painting		885704
879	06/25/2021	981867	Suspension fault - carry out on from breakdown	checked and found front control valve us. also fault light is on due to stuck relay. changed the relay; road tested. suspension still has front solenoid and NSR lev valve faults. need further diagnostics		885704
879	06/25/2021	981867	LEVEL SENSOR FRT SCANIA L94UAB 481829			885704
879	06/25/2021	981867	RELAY 5 PIN CHANGE OVER 24V 10/20 AMP 68052			885704
879	06/24/2021	981867	Suspension fault - carry out on from breakdown	removed frnt lev/control and replaced. also checked the front solenoid block.		885704
879	06/24/2021	981866	Fault#:37938 - Ops Entered - Fault - Breakdown Air System F	breakdown carried out satya he attended the breakdown . the suspension was faulting . satya reset the suspension. then he followed the bus back to the depot . for further repairs		885704
879	06/10/2021	979332	Mechanic entered - Elec and Light Indicators Not Working n/s	fit globe.		882120
879	06/10/2021	979332	Consumables			882120
879	06/09/2021	979207	Mechanic entered - Elec and Light Next Stop Button button br	replace all broken passenger bell refit new bell all ok		882120
879	06/09/2021	979207	YELLOW/RED STOP SWITCH (20485)			882120
879	06/09/2021	979207	Consumables			882120
879	06/09/2021	979207	Mechanic entered - Brakes Other o/s/f slack adjuster nipple	done		882120
879	06/09/2021	979064	OIL SAMPLE KIT CALTEX			882120
879	06/09/2021	979064		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order check ok		882120
879	06/09/2021	979064	SPINNER FILTER KIT ALL SCANIA			882120
879	06/09/2021	979064	FILTER OIL SCANIA S4 & K			882120
879	06/09/2021	979064	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			882120
879	06/09/2021	979064	FILTER FUEL FILTER SCANIA SR4 (1372444)			882120
879	06/09/2021	979064	FILTER AIR FILTER (395773) AF25066			882120
879	06/09/2021	979064	Consumables			882120
879	06/09/2021	979064	Consumables			882120
879	06/03/2021	978210	Ops Entered - Fault - Elec and Light Indicators Not Working	replaced stalk and checked ok		881379
879	06/03/2021	978210	SWITCH INDICATOR SCANIA L94 1402448			881379
879	06/03/2021	978210	Consumables			881379
879	05/27/2021	976925	Mechanic entered - Elec and Light Indicators Not Working N/S	Fitted new light assy		880035
879	05/27/2021	976925	LIGHT SIDE INDICATOR L/H			880035
879	05/27/2021	976925	Consumables			880035
879	05/17/2021	974498		TRANSMISSION CHECK AS PER CHECK LIST		877553
879	05/15/2021	974459		VEHICLE SAFETY INSPECTION		877553
879	05/15/2021	974459		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		877553
879	05/15/2021	974468	Mechanic entered - Suspension Other both front D rubber u/	replaced both front D rubber ok		877553
879	05/15/2021	974468	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			877553
879	05/15/2021	974468	CAP EXPANSION TANK 0.75BAR SCANIA K93 L113 1403954			877553
879	05/15/2021	974468	Mechanic entered - Fluid Leaks Other water pump u/s	replaced water pump		877553
879	05/15/2021	974468	WATER PUMP SCANIA L94 UAB 1510490 0570961			877553
879	05/15/2021	974468	Mechanic entered - Fluid Leaks Other radiator cap broken	replaced coolant head tank cap ok		877553
879	05/15/2021	974468	Mechanic entered - Body Other o/s/r staunchion pole loose	repaired o/s/r staunchion pole		877553
879	05/15/2021	974468	Mechanic entered - Body Other wheel chair ramp pin off	repaired wheel chair ramp pin ok		877553
879	05/15/2021	974468	Mechanic entered - Body Other middle seat top pin off	put in middle seat top pins		877553
879	05/15/2021	974468	Consumables			877553
879	04/26/2021	970536	Mechanic entered - Wheels and Tyres Other O/S/R outer tyre g	Removed screw and checked for leaks found okay		873987
879	04/26/2021	970536	Consumables			873987
879	04/24/2021	970338	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti		873987
879	04/14/2021	951660	BUSH STABILIZER REAR SCANIA (40Y3447)			872084
879	03/27/2021	964276	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	carried out campaign		869231
879	03/26/2021	963885	Place new poster over the top attach hangers to hand rails	complete		869231
879	03/18/2021	961519	Body - rear passenger door step u.s	repaired passenger door step ok		868274
879	03/18/2021	961520	Body - disabled bottom plastic cover cracked	maked disabled bottom plstic cover ok		868274
879	03/18/2021	961519	Consumables			868274
879	03/18/2021	961520	Consumables			868274
879	03/17/2021	961131		VEHICLE SAFETY INSPECTION		868047
879	03/17/2021	961131		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		868047
879	03/17/2021	961131		ANNUAL SAFETY INSPECTION SERIAL #L158166 - GREEN SHEET - WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 ASI done by Fleet Check PO 0295189		868047
879	03/17/2021	961131	DIRECT PURCHASE - BUS INSPECTI	Creditor #:#VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:#0295189 Receiving #:#308522 Date :2021-03-18		868274
879	03/17/2021	961131		PRE ANNUAL SAFETY INSPECTION CHECK		868047
879	03/17/2021	961131		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		868047
879	03/16/2021	960775		VEHICLE SAFETY INSPECTION		867717
879	03/16/2021	960775		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		867717
879	03/16/2021	960871	Mechanic entered - Engine Other Engine belt tensioner and id	Replaced belt tensioner and idle baring		867717
879	03/16/2021	960871	BELT TENSIONER SCANIA N310UA 2197005 1859657			867717
879	03/16/2021	960871	PULLEY IDLER SCANIA (1514087)			867717
879	03/16/2021	960915	Mechanic entered - Elec and Light Interior Lights N/S/R Salo	Replaced N/S/R Saloon fluorescent lamp		867717
879	03/16/2021	960915	Consumables			867717
879	03/16/2021	960910	Mechanic entered - Body Other DRIVER DOOR LOOSE	repaired DRIVER DOOR OK		867717
879	03/16/2021	960910	Mechanic entered - Body Other DRIVER SEAT BACK MODESTY PANEL	repaired DRIVER SEAT BACK MODESTY PANEL OK		867717
879	03/16/2021	960910	Mechanic entered - Body Other REAR MODESTY PANEL LOOSE	repaired REAR MODESTY PANEL OK		867717
879	03/16/2021	960910	Consumables			867717
879	03/11/2021	959673	full retorque required	retorque all wheel nuts.		866649
879	03/11/2021	959673	Consumables			866649
879	03/10/2021	959161	Mechanic entered - Wheels and Tyres Damaged O/S/R/I TYRE HAS	suspect driver has ran over gutter supply new tyre fitted check ok		866649
879	03/10/2021	959161	TYRE 295/80R22.5 RECAP			866649
879	03/10/2021	959161	Consumables			866649
879	03/10/2021	959161	Brakes - front and rear brakes low	remove old brake lining and drum refit new lining and drum check tested ok		866649
879	03/10/2021	959161	O-RING BRAKE SHOE PIVOT (1338019)			866649
879	03/10/2021	959161	LOCK RING BRAKE SHOE PIN SCANIA 0804782			866649
879	03/10/2021	959597	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	complete		866649
879	03/09/2021	959161	Brakes - front and rear brakes low	remove old brake lining and drum refit new lining and drum check tested ok		866649
879	03/09/2021	959161	DIRECT PURCHASE - BRAKES	Creditor #:#VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:#0294676 Receiving #:#308033 Date :2021-03-11 reline front and rear brakes machine drums . replaced drums if required		866994
879	03/06/2021	958982	Brakes sponddy	checked condion of brakes fronts 10 % and rears 40 % . adjusted brakes and road tested . all okay - will rebook in the next week for brake lining replacment.		866649
879	03/01/2021	944169	DIRECT PURCHASE GLASS	Creditor #:#VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:#0290542 Receiving #:#307992 Date :2021-03-11 replace nsf peep and windshield as required		866994
879	03/01/2021	944169	Consumables			866994
879	03/01/2021	950675	AIR CONDITIONING REPAIR	Creditor #:#VB-COL004 COLD DRIVE PTY LTD P/O #:#0292321 Receiving #:#309252 Date :2021-03-29 carry out AC-A service as required		869974
879	02/24/2021	951660	BOLT V STAY ASSY CENTRE BUSH SCANIA L94			865129

[illegible]

879	11/05/2020	930784		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	849025
879	11/05/2020	930848	Mechanic entered - Wheels and Tyres Other both front tyres u	replaced both front tyres ok x2	849025
879	11/05/2020	930848	TYRE 295/80R22.5 NEW		849025
879	11/05/2020	930852	Mechanic entered - Wheels and Tyres Other o/s/r inner tyre u	replaced o/s/r tyre ok	849025
879	11/05/2020	930852	TYRE 295/80R22.5 RECAP		849025
879	11/05/2020	931078	Mechanic entered - Wheels and Tyres Wheel Nut Retension bot	carried out retorque as required	849025
879	11/05/2020	930848	Consumables		849252
879	11/05/2020	930852	Consumables		849252
879	11/05/2020	931078	Consumables		849252
879	11/05/2020	930902	Mechanic entered - Elec and Light Other n/s/r hammer light n	repaired n/s/r hammer light wires ok	849025
879	11/05/2020	930902	Consumables		849252
879	11/05/2020	930902	Mechanic entered - Body Other rear door top loose	repaired rear door top ok	849025
879	11/05/2020	930902	Mechanic entered - Body Other bus inside n/so/s top panel l	repaired bus inside o/sn/s top panel ok	849025
879	11/05/2020	930902	Mechanic entered - Body Other o/s/middle seat top pins off	put in o/s/middle seat top pins ok	849025
879	11/05/2020	930902	Mechanic entered - Body Other rear view mirror loose	repaired rear view mirror ok	849025
879	11/05/2020	930902	Consumables		849252
879	10/30/2020	929681		TRANSMISSION CHECK AS PER CHECK LIST Carried out Trans Check and road test all ok complete	848421
879	10/28/2020	929333	Fit new Myki Decals & refit COVID-19 decals new position f		848191
879	10/26/2020	928604	INDICATOR SIDE INDICATOR R/H		847266
879	10/26/2020	928604	Drv entered - Elec and Light Exterior Lights	Replaced damage o/s/f side indicator assy and replaced headlight globe for n/s	847266
879	10/26/2020	928604	Consumables		847965
879	10/14/2020	926219	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	done	846020
879	10/07/2020	924676	Elec and Light aerial too high reported by refuellers on sa	checked could not fault	845125
879	10/07/2020	924676	Consumables		845375
879	09/29/2020	922845	Mechanic entered - A/C Heating Other a/c vent bracket damage	fabricate new bracket fitted and check ok	844193
879	09/29/2020	922845	Mechanic entered - Elec and Light Other indicator stalk no c	supply new stalk remove part check all wiring tested indicator check ok	844193
879	09/29/2020	922845	INDICATOR STALK SCANIA SERIES 4 (1402448)		844193
879	09/29/2020	922845	Consumables		844433
879	09/29/2020	922845	Mechanic entered - Body Other n/s/r quater panel had loose s	resecure screw check ok	844193
879	09/29/2020	922845	Consumables		844433
879	09/29/2020	922712		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order check ok	844193
879	09/29/2020	922712	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		844193
879	09/29/2020	922712	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		844193
879	09/29/2020	922712	FILTER FUEL FILTER SCANIA SR4 (1372444)		844193
879	09/29/2020	922712	Oil Filter SCANIA S4 & K		844193
879	09/29/2020	922712	OIL SAMPLE KIT CALTEX		844193
879	09/29/2020	922712	Consumables		844433
879	09/28/2020	922630		complete	844193
879	09/28/2020	922630		CARRY OUT FIRE EXTINGUISHER TEST & TAG	844193
879	09/14/2020	919910		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	841550
879	09/10/2020	919394	disabled passenger bell button x 1 not working	replaced button. checked operation of all buttons . all working	841119
879	09/10/2020	919394	SWITCH- STOP-YELLOW (62628)		841119
879	09/10/2020	919394	Consumables		841308
879	09/05/2020	918284	Mechanic entered - Suspension Other N/S/R bump stop cracked	replaced bump stop	840096
879	09/05/2020	918281	Mechanic entered - Body Other O/S/R wires hanging from under	re secured wires with cable ties	840096
879	09/05/2020	918281	Mechanic entered - Body Other front pax seats top hinge pins	knocked pins back in as required	840096
879	09/05/2020	918281	Mechanic entered - Body Other N/S/R modesty panel loose	tightened as necessary	840096
879	09/05/2020	918281	Mechanic entered - Body Other ticket machine loose rattling	added foam tape to underside of ticket machine to remedy issue	840096
879	09/05/2020	918284	Mechanic entered - Body Other N/S/R modesty panel graffiti	cleaned graffiti	840096
879	09/05/2020	918284	BUMP STOP RR AXLE SCANIA L113TRL 0306902		840096
879	09/05/2020	918281	Consumables		840365
879	09/05/2020	918284	Consumables		840365
879	09/04/2020	918269		VEHICLE SAFETY INSPECTION	840096
879	09/04/2020	918269		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	840096
879	09/03/2020	917560	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-BWED01 BWERE ELECTRICS PTY LTD P/O #:-0282907 Receiving #:295465 Date :2020-09-07 CKECK AND RECTIFY THE WIPERS STOP AT TIMES	840365
879	09/02/2020	917560	Wipers and Washers wipers stop at times	WIPERS DONE BY ASHLEY - BW ELECTRICS FITTED AND PROG NEWNODE PO 0282907	839573
879	09/01/2020	917418	CABLE BATTERY BRIDGE SHORT (230MM)		839209
879	09/01/2020	917418	Mechanic entered - Elec and Light Flat Batteries wont start.	r/r batteriesok. old batteries ixfailed one is ok but different size to the replacement.	839209
879	09/01/2020	917418	BATTERY 1100CCA POS ON LHS EMFN200L		839209
879	09/01/2020	917418	Consumables		839573
879	08/30/2020	916948	Mechanic entered - Wipers and Washers Wipers Not Working	Fit plug back on wiper motor	839209
879	08/28/2020	916730	Mechanic entered - Wipers and Washers Washers Not Working	RECONNECT PLUG TO WIPER MOTOR.	839209
879	08/25/2020	916161	Wipers and Washers N/W	Traced and found 1 connector in the plug . that needed replaced . metal tab had broken of . causing terminal to push out when plug is connected . replaced terminal . checked operation all okay	838552
879	08/25/2020	915865		load tested both batts . both passed load test . checked charge rate . 27.8 volts . could not fault	838552
879	08/24/2020	915673	Ops Entered - Fault - Wipers and Washers Wipers Not Working	removed wiper motor and fitted one that chris removed from 1181	838552
879	08/24/2020	915673	Ops Entered - Fault - Wipers and Washers Wipers Not Working	Assisting removed wiper motor from 1181	838552
879	08/24/2020	915573	Mechanic entered - Elec and Light Flat Batteries	jump start.	838552
879	08/24/2020	915573	Consumables		838932
879	08/22/2020	913843	DIRECT PURCHASE - VANDALISM	Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:-0281716 Receiving #:294378 Date :2020-08-24 Window Film Audit 418 completed 3/8/20 oakleigh	838796
879	08/14/2020	913843	Vandalism Vandalism/ Graffiti Interior window film	Completed 3/8/20 refer email PB 13/8/20	837593
879	08/11/2020	913064	Remove old A3 Poster and fit with You can no longer top up	carried out by fleet support	837106
879	07/29/2020	909784	Consumables		835092
879	07/29/2020	909784	indicators n/w	disconnected node . reconnected . checked operation all okay	834828
879	07/20/2020	892111	DIRECT PURCHASE ACCIDENT	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:-0276059 Receiving #:292084 Date :2020-07-23 ACC#50723 CARRY OUT OS FRONT ACCIDENT REPAIRS	833718
879	07/13/2020	906141	Mechanic entered - Elec and Light Exterior Lights Desto Sign	fit globe.	830914
879	07/13/2020	906354	Mechanic entered - Elec and Light Indicators Not Working n/	R&R globe	830914
879	07/13/2020	906141	Consumables		831690
879	07/13/2020	906354	Consumables		831690
879	07/10/2020	905829		VEHICLE SAFETY INSPECTION	830914
879	07/10/2020	905829		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	830914
879	07/10/2020	905891	BELT TENSIONER SCANIA N310UA 2197005 1859657	replaced idler pulley ok	830914
879	07/10/2020	905891	Mechanic entered - Engine Other Idler pulley U/S		830914
879	07/10/2020	905891	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		830914
879	07/10/2020	905891	Mechanic entered - Engine Other Belt Tensioner U/S	replaced belt tensioner ok	830914
879	07/10/2020	905891	Mechanic entered - Elec and Light Exterior Lights N/S/F Park	Replaced N/S/F Parker Globe checked ok	830914
879	07/10/2020	905891	Consumables		831377
879	07/10/2020	905850	Mechanic entered - Body Front_Door Operation Faulty front le	could not fault.	830914
879	07/10/2020	905891	Mechanic entered - Body Other Safety Strip Inside step miss	replaced safety strip cut to size and glued down ok	830914
879	07/10/2020	905891	Mechanic entered - Body Wheel Chair Ramp Disabled Ramp Pin O	Re Seated disabled ramp pin ok	830914
879	07/10/2020	905891	Mechanic entered - Body Other Disabled Seat Bottom cover not	Drilled out rivets repositioned bottom cover to correct spot drilled holes x2 and added teck screws to hold in position	830914
879	07/10/2020	905891	Mechanic entered - Body Other Rear Seat Base Not retained	removed seat base put hooks in right position and reseated seat base ok	830914
879	07/10/2020	905891	Mechanic entered - Body Other Rear Modesty Panel Loose at bo	Drilled out old rivets x3 and replaced with new larger rivets checked modesty panel for rattling ok.	830914
879	07/10/2020	905891	Mechanic entered - Body Other Disabled seat pins out	Reseated disabled seat pins ok	830914

879	07/10/2020	905891	Consumables			831377
879	07/10/2020	905850	Consumables			831377
879	07/06/2020	904974	Mechanic entered - Elec and Light Flat Batteries wont start.	jump startok.		830349
879	07/06/2020	904974	Consumables			830462
879	06/18/2020	901843	Drv entered - Body Drivers Seat Belt	adjusted the angle ok		827351
879	06/18/2020	901843	Drv entered - Body Drivers Seat Belt	double entry		827351
879	06/18/2020	901843	Consumables			827539
879	06/13/2020	900848	Vandalism interior graffiti	cleaned and painted over interior graffiti		826547
879	06/10/2020	899811	Fit A3 Poster in poster frame and fit decals as requested i	carried out campaign as required		826076
879	06/09/2020	899184	Consumables			826076
879	06/09/2020	899184	LAMP FLUORESCENT TUBE 18W			825654
879	06/09/2020	899184	Mechanic entered - Elec and Light Flat Batteries	JUMP START.		825654
879	06/01/2020	897750	Mechanic entered - Engine Other spinner copper bushing missi	supply new cooper bush refit check ok		824985
879	06/01/2020	897750	Mechanic entered - Body Other n/s/r door upper trim was loos	resecure trim check ok		824985
879	06/01/2020	897750	Consumables			824997
879	06/01/2020	897707	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			824985
879	06/01/2020	897707	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			824985
879	06/01/2020	897707		CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order check tested ok		824985
879	06/01/2020	897707	Oil Filter SCANIA S4 & K			824985
879	06/01/2020	897707	FILTER FUEL FILTER SCANIA SR4 (1372444)			824985
879	06/01/2020	897707	Consumables			824997
879	06/01/2020	897707	Consumables			824997
879	05/27/2020	897036	Mechanic entered - Elec and Light Other O/S front upper park	replaced globe as required		824426
879	05/27/2020	897036	Consumables			824470
879	05/25/2020	892111	Accident#50723	done by mick on 23/05/2020 po O276059		823199
879	05/23/2020	896207	Drv entered - Dash Dash_Lights Not Working	fitted 1 x speedo and 3 x cluster globes ok		823199
879	05/23/2020	896207	Consumables			823479
879	05/13/2020	894060		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		821331
879	05/13/2020	894060		VEHICLE SAFETY INSPECTION Carried out Safety Inspection		821331
879	05/13/2020	894160	Drv entered - BusMinder Unable To Log In	fixed the holder put the busminder to charging craddle as the battery was dead due to faulty cable. fitted cable from 1196 ok.		821331
879	05/13/2020	894115	Mechanic entered - Elec and Light Next Stop Button N/S Pax S	Removed switch adjusted terminal contacts tested reassembled ok		821331
879	05/13/2020	894115	Consumables			821770
879	05/13/2020	894160	Consumables			821770
879	05/13/2020	894115	BELT SEATBELT R/HAND ISRI A6008			821331
879	05/13/2020	894115	Mechanic entered - Body Other Rear Modesty Panel Loose at bo	Drilled out loose Rivets Re Rivetted panel and cleaned ok		821331
879	05/13/2020	894115	Mechanic entered - Body Drivers Seat Belt Seat Belt Frayed	Replaced Seat Belt Mechanism adjusted and checked ok		821331
879	05/13/2020	894115	Mechanic entered - Body Other O/S Disabled seat not holding	Tightened side bolts on seat adjusted so seat will hold ok		821331
879	05/13/2020	894115	Consumables			821770
879	05/07/2020	892923	Mechanic entered - Body Drivers Seat Controls LEAKING AIR.			820133
879	05/07/2020	892923	Consumables			820621
879	05/06/2020	892863	Mechanic entered - Body Other drivers seat air leak	found small hole in air supply line. cut hose and added joiner		820133
879	05/06/2020	892863	Consumables			820394
879	05/05/2020	892111	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O274684 Receiving #:286483 Date :2020-05-08 replace windshield as required		820848
879	05/04/2020	892111	Accident#50723 frt bumper and windshield cracked due to im	windshield was done by Alpha Glass PO#: O274684		819858
879	05/01/2020	891822	Mechanic entered - Elec and Light Other O/S front side indic	replaced globe as required		819508
879	05/01/2020	891822	Consumables			819732
879	05/01/2020	891829	Mechanic entered - Body Other N/S front bumper damage	inspected bumper damage beleived to be existing prior		819508
879	05/01/2020	891829	Consumables			819732
879	04/30/2020	891300		TRANSMISSION CHECK AS PER CHECK LIST		818945
879	04/29/2020	891068	Mechanic entered - Steering Other steerine wheel adjust brok	repaired steering wheel ok		818945
879	04/21/2020	889694	Mechanic entered - Elec and Light Other N/S front upper park	re tensioned bolts on light as required		817729
879	04/21/2020	889694	Consumables			817947
879	04/20/2020	888979	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O273435 Receiving #:284816 Date :2020-04-20 GRAFFITI WINDOW FILM STAGE 3		817484
879	04/17/2020	888979	Vandalism Vandalism/ Graffiti Interior	COMPLETED		817261
879	04/14/2020	888025	Mechanic entered - Elec and Light Other won't start	jump started		816662
879	04/14/2020	888025	Consumables			816814
879	04/09/2020	887496	A4 notification to be printed off in colour laminated and	carried out campaign as required		816435
879	04/06/2020	886274	Mechanic entered - Elec and Light Flat Batteries	Jump Started Bus		815185
879	04/06/2020	886274	Consumables			815943
879	03/30/2020	885119	Mechanic entered - Elec and Light Other N/S front upper indi	replaced globe ok		814398
879	03/30/2020	885119	Consumables			814659
879	03/27/2020	884729	Mechanic entered - Elec and Light Other N/S front upper park	replaced globe ok		814176
879	03/27/2020	884729	Consumables			814398
879	03/24/2020	883367	Tape off front Seats of All Route and Rail Buses with spec	carried out campaign as required		813470
879	03/24/2020	883336	Remove old poster and fit Reduce Your Risk of Coronavirus	carried out campaign as required		813470
879	03/23/2020	882646	Mechanic entered - Wipers and Washers Washers Not Working	Checked and fixed up connection at wiper motor		813249
879	03/19/2020	881119	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O271269 Receiving #:282382 Date :2020-03-19		812542
879	03/18/2020	881119		VEHICLE SAFETY INSPECTION		811887
879	03/18/2020	881119		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		811887
879	03/18/2020	881119		ANNUAL SAFETY INSPECTION SERIAL # _____K669306____greensheet_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCETHE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		811887
879	03/18/2020	881311	Ops Entered - Fault - Suspension Soft - Route: 703 - Centre	Checked and tighten clamps for levelling sensor rod		811887
879	03/17/2020	881008	Mechanic entered - Elec and Light Other rear pax bell switch	r/r switchok.		811887
879	03/17/2020	881008	Consumables			812349
879	03/17/2020	881008	Mechanic entered - Body Other worn n/s/r wheel nut pointers.	r/r pointersok.		811887
879	03/17/2020	881008	SWITCH- STOP-YELLOW (62628)			811887
879	03/17/2020	881008	CATCH CLAW PLASMA ENGINE HATCH DOOR			811887
879	03/17/2020	881008	Mechanic entered - Body Other rear side hatch locker u/s.	r/r lockerok.		811887
879	03/17/2020	881008	Mechanic entered - Body Other loose drivers door hinges.	tighten hinge boltsok.		811887
879	03/17/2020	881008	Mechanic entered - Body Other missing interior wiring cover	fixed wiring coverok.		811887
879	03/17/2020	881008	Mechanic entered - Body Other missing luggage racks screws.	fixed luggage racksok.		811887
879	03/17/2020	881008	Consumables			812349
879	03/17/2020	881008	Mechanic entered - Air System Air_Leak Rear leaking air from	fixed air valveok.		811887
879	03/16/2020	880571		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST carry out as per work order check tested ok		811887
879	03/16/2020	880571		SERVICE MOISTURE EJECTOR carry out as per work order check tested ok		811887
879	03/12/2020	879973	Mechanic entered - Suspension Other O/S/F Upper Torque Rod U	replaced O/S/F Upper Torque Rod		811887
879	03/12/2020	879973	TORQUE ROD FRT UPPER SCANIA K230UB 1438475 2055289			811887
879	03/12/2020	879918	LAMP LED TURN			811887
879	03/12/2020	879918	Mechanic entered - Elec and Light Exterior Lights N/S/R Lowe	Replaced N/S/R Lower LED Indicator		811887
879	03/12/2020	879973	Mechanic entered - Elec and Light Interior Lights Dash Light	replaced blown dash globe		811887
879	03/12/2020	879918	Consumables			812110
879	03/12/2020	879973	Consumables			812110
879	03/12/2020	879973	Mechanic entered - Body Other N/S/R Modesty Panel Loose at b	Re Rivetted bottom of modesty panel in position		811887
879	03/12/2020	879973	Consumables			812110

879	03/11/2020	879846	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced globe	811887
879	03/11/2020	879846	Consumables		812110
879	03/04/2020	878610	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced H4 globe	810933
879	03/04/2020	878610	Consumables		811194
879	03/03/2020	878205		PRE ANNUAL SAFETY INSPECTION CHECK	810837
879	03/03/2020	878205		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	810837
879	03/03/2020	878165	TYRE 295/80R22.5 RECAP		810837
879	03/03/2020	878165	Mechanic entered - Wheels and Tyres Other n/s/r tyres u/s	replaced n/s/r tyres x2 ok	810837
879	03/03/2020	878356	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	Completed retension	810837
879	03/03/2020	878165	Consumables		810933
879	03/03/2020	878356	Consumables		810933
879	03/03/2020	878165	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		810837
879	03/03/2020	878165	Mechanic entered - Suspension Other both front D rubber u/	replaced both front D rubber ok	810837
879	03/03/2020	878165	Mechanic entered - A/C Heating Other a/c mount bracket bolt	tightened a/c mount bracket bolts ok	810837
879	03/03/2020	878165	Mechanic entered - Body Other o/s/middle seat top pins off	put in o/s/middle seat top pins ok	810837
879	03/03/2020	878165	Mechanic entered - Body Other front modesty panel loose	repaired front modesty panel ok	810837
879	03/03/2020	878165	Consumables		810933
879	02/28/2020	877602		complete	809820
879	02/28/2020	877602		CARRY OUT FIRE EXTINGUISHER TEST & TAG	809820
879	02/21/2020	875077	Mechanic entered - Steering Steering Wheel Faulty sticky -	R&R steering wheel	808180
879	02/21/2020	875836	INDICATOR STALK SCANIA SERIES 4 (1402448)		808180
879	02/21/2020	875836	indicator stalk broken	R&R indicator stalk . checked operation all okay	808180
879	02/21/2020	875836	Consumables		808666
879	02/19/2020	875077	40M1303OE Steering Wheel	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O269187 Receiving #:280224 Date :2020-02-21	808424
879	02/17/2020	874588		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	807308
879	02/17/2020	874588		CARRY OUT FIRE EXTINGUISHER TEST & TAG	807308
879	02/11/2020	858211	PLATE FRAME CLAMPING VOLGREN		806551
879	02/04/2020	871765	Ops Entered - Fault - Suspension Soft - Route: 703 - Centre	Adjusted front levelling sensor rod in correct position and tighten clamp bolts. Road tested all ok	805116
879	02/04/2020	871489	Oil Filter SCANIA S4 & K		805116
879	02/04/2020	871489	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		805116
879	02/04/2020	871489	FILTER FUEL FILTER SCANIA SR4 (1372444)		805116
879	02/04/2020	871489	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		805116
879	02/04/2020	871489	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		805116
879	02/04/2020	871489		CARRY OUT C SERVICE AS PER CHECK LIST Carried out C Service	805116
879	02/04/2020	871489	FILTER HYD COOLING FAN SCANIA L94UAB 1354074		805116
879	02/04/2020	871489	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)		805116
879	02/04/2020	871489	FILTER AIR FILTER (395773) AF25066		805116
879	02/04/2020	871489	FILTER FUEL FILTER SCANIA SR4 (1393640)		805116
879	02/04/2020	871489	WASHER SEALING SC SUMP (1356776)		805116
879	02/04/2020	871489	PLUG MAGNETIC (2165310)		805116
879	02/04/2020	871489	Consumables		805423
879	02/04/2020	871489	Consumables		805423
879	02/04/2020	871489	Consumables		805423
879	02/04/2020	871489		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B Service	805116
879	02/04/2020	871489	Consumables		805423
879	02/04/2020	871489	Consumables		805423
879	02/04/2020	871489	Consumables		805423
879	02/01/2020	870957	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retorque n/s/fo/s/r wheel nuts.	804493
879	02/01/2020	870957	Consumables		804863
879	02/01/2020	867098	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O266528 Receiving #:280863 Date :2020-02-28 carry out AC - B Service	809820
879	01/31/2020	870593		VEHICLE SAFETY INSPECTION	804493
879	01/31/2020	870593		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	804493
879	01/31/2020	870943	Mechanic entered - Wipers and Washers Wipers Not Working	Checked fuses remove plug from wiper moter and fit terminals on plug	804493
879	01/31/2020	870648	TYRE 295/80R22.5 NEW		804493
879	01/31/2020	870648	Mechanic entered - Wheels and Tyres Other N/S/F FRONT TYRE U	replaced N/S/F TYRE OK	804493
879	01/31/2020	870648	Mechanic entered - Wheels and Tyres Other O/S/R/OUTER TYRE U	replaced O/S/R OUTER TYRE OK	804493
879	01/31/2020	870648	TYRE 295/80R22.5 RECAP		804493
879	01/31/2020	870648	Consumables		804863
879	01/31/2020	870749	Mechanic entered - Elec and Light Other EMERGENCY EXIT LIGHT	replaced EMERGENCY EXIT LIGHT OK	804493
879	01/31/2020	870749	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		804493
879	01/31/2020	870749	Consumables		804863
879	01/31/2020	870749	Mechanic entered - Body Other O/S/MIDDLE SEAT TOP PINS OFF	PUT IN O/S/F MIDDLE SEAT TOP PINS OK	804493
879	01/31/2020	870749	Mechanic entered - Body Other BUS INSIDE O/S/F TOP PANEL SCR	repaired O/S/F BUS INSIDE TOP PANEL OK	804493
879	01/31/2020	870749	Mechanic entered - Body Other WHEEL CHAIR RAMP HINGES OFF	PUT IN WHEEL CHAIR RAMP PIN OK	804493
879	01/31/2020	870749	Mechanic entered - Body Other REAR MODESTY PANEL LOOSE	repaired REAR MODESTY PANEL OK	804493
879	01/31/2020	870749	Consumables		804863
879	01/30/2020	870301	Ops Entered - Fault - BusMinder Unable To Log In - Route: 7	batt u/sswap batt from 882.	804493
879	01/30/2020	870301	Consumables		804799
879	01/23/2020	869382	BusMinder Unable To Log In	traced and found bus minder handset battery u/s . replace batt . checked operation all okay	803605
879	01/23/2020	869382	Consumables		803798
879	01/23/2020	869327	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	carried out campaign as required	803605
879	01/21/2020	868643	Shaft seal leaking - To be booked and completed	replaced shaft seal blower motor and water valve PO#: O267040 by Cold Drive	803287
879	01/20/2020	868475	Mechanic entered - Wipers and Washers Wipers Not Working	Wipers not working Traced loose Plug Reconnected plug and tested wipers ok	802945
879	01/18/2020	797475	Mechanic entered - Elec and Light Flat Batteries	Jump Started Bus ok	802945
879	01/18/2020	797475	Consumables		803136
879	01/14/2020	867098			802945
879	01/14/2020	867098		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - PO#: O266528	802945
879	01/01/2020	853141	DIRECT PURCHASE - ELECTRICAL	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	802945
879	01/01/2020	853141	Consumables	Creditor #:VB-CSE001 CSE CROSSCOM PTY LTD P/O #:O261936 Receiving #:277850 Date :2020-01-23 rectify two way nw as required - carry out repairs on unit only if approved. program two way id from 1196 to 879	803605
879	12/27/2019	863828	Mechanic entered - Wheels and Tyres Wheel Nut Retension Near	retorque n/s/r wheel nuts.	800017
879	12/27/2019	863828	Consumables		799087
879	12/23/2019	863562	Mechanic entered - Wheels and Tyres Flat or Leaking N/S inne	replaced n/s inner tyre with second hand stock	799562
879	12/23/2019	863562	Consumables		798897
879	12/23/2019	863562	Mechanic entered - Suspension Other front airbag height sens	re fastened front airbag height sensor and tested ok	799087
879	12/12/2019	861173	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Completed retension	798897
879	12/12/2019	861173	Consumables		797336
879	12/12/2019	861173	Mechanic entered - Suspension Other rear 'V' ROD TOP BOLT U/	completed	797336
879	12/12/2019	861173	BOLT V-STAY ASSY SCANIA L94		797336
879	12/11/2019	857852	Suspension - diff housing damage	Removed diff disassembled diff and components sent housing away to be repaired refitted components and refitted diff to bus roadtested ok	797260
879	12/11/2019	857852	Suspension - diff housing damage	Removed and disassembled Diff Housing and components sent housing away to be repaired. Refitted all components to housing and refitted to bus road test ok	797260
879	12/11/2019	858211	Mechanic entered - Suspension Other N/S/R and O/S/R lower to	REPLACED TORQUE ROD BUSHES AND REFITTED OK	797260
879	12/10/2019	857852	O-RING BRAKE SHOE PIVOT (1338019)		797260
879	12/10/2019	857852	SEAL RR HUB INNER SCANIA K230UB 1740992		797260

879	12/10/2019	858211	F1001 20 130 Hex Hd Bolt 931 8	Creditor #:\VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263904 Receiving #:274820 Date :2019-12-12	797336
879	12/10/2019	858211	F2101 20 Nyloc Nut	Creditor #:\VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263904 Receiving #:274820 Date :2019-12-12	797336
879	12/10/2019	858211	CONSUMABLE DELIVERY CHARGE	Creditor #:\VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263904 Receiving #:274820 Date :2019-12-12	797336
879	12/09/2019	857852	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-HMG001 HM GEM ENGINES P/O #:O263827 Receiving #:274800 Date :2019-12-12 repair flogged out V rod bush taper hole as required . please ring through with quote repair before proceeding. thanks	797336
879	12/07/2019	860106	A3 Poster Frame Adhesive Decal Campaign please remove old	complete	797260
879	12/03/2019	858211	Mechanic entered - Wheels and Tyres Other Rear Wheel Bearing	FITTED BEARINGS	797260
879	12/03/2019	858211	Consumables		797260
879	12/03/2019	858211	Mechanic entered - Suspension Other Rear Shock Absorbers U/S	fit 4 new rear shocks.	797260
879	12/03/2019	858211	AIRBAG REAR SCANIA K230 / K270 2024287 2024290		797260
879	12/03/2019	858211	Mechanic entered - Suspension Other O/S/R/F Airbag U/S	fit new air bag.	797260
879	12/03/2019	858211	SEAL RR HUB OUTER SCANIA K230UB 1409890		797260
879	12/03/2019	858663	Mechanic entered - Gearbox Driveline Other transmission moun	replaced transmission mount bolt ok	797260
879	12/03/2019	858798	Mechanic entered - Brakes Other rear S cam bushes u/s.	replace all rear S cam bushes and seals.	797260
879	12/02/2019	858211	SEAL RR HUB INNER SCANIA K230UB 1740992		797260
879	12/02/2019	858211	SEAL REAR AXLE CAP SCANIA 1765061 120310		797260
879	12/02/2019	858211	LOCK WASHER RR HUB SCANIA K230UB 273023		797260
879	12/02/2019	858211	BEARING ROLLER BEARING		797260
879	12/02/2019	857852	KIT BUSH V BAR SCANIA		797260
879	12/02/2019	858211	Mechanic entered - Suspension Other Rear Sway bar bushes U/S	FITTED SWAY BAR BUSHES	797260
879	12/02/2019	858211	BUSH RR SWAY BAR D AXLE SCANIA L94UAB 2156626 1477867		797260
879	12/02/2019	858211	SHOCK ABSORBER RR D/AXLE SCANIA K124IB 1478317		797260
879	12/02/2019	858211	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		797260
879	12/02/2019	858211	TORQUE ROD BUSH SCANIA SR4 K230 1435944 23845 01		797260
879	12/02/2019	857852	SEAL BRUSHING RING & RING SE	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O263821 Receiving #:274227 Date :2019-12-05	797260
879	11/25/2019	856716	Mechanic entered - Steering Steering Wheel Faulty adjuster n	secure adjuster.	795862
879	11/23/2019	856594	Mechanic entered - Brakes Other rear S cam bushes u/s.	road testget brakes hotcould not fault.	795862
879	11/23/2019	856600	Drv entered - Brakes Foot_Brakes Noisy	done on wo856594 by cdf	795862
879	11/22/2019	856450	Drv entered - Elec and Light AM-FM Radio	double entry	795862
879	11/22/2019	856450	Consumables		796364
879	11/19/2019	855408		VEHICLE SAFETY INSPECTION	795265
879	11/19/2019	855408		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	795265
879	11/19/2019	855441	Mechanic entered - Wipers and Washers Other wiper rubber u/s	replaced wiper blade x2 ok	795265
879	11/19/2019	855441	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		795265
879	11/19/2019	855441	Mechanic entered - Steering Other STEERING WHEEL LOOSE	repaired steering wheel ok	795265
879	11/19/2019	855441	MOUNT A/C COMPRESSOR LARGE DENSO		795265
879	11/19/2019	855441	Mechanic entered - A/C Heating Other a/c mount u/s	replaced a/c mount ok	795265
879	11/19/2019	855441	Mechanic entered - Elec and Light Other n/s head light u/s	replaced n/s head light ok	795265
879	11/19/2019	855441	LAMP HEADLAMP MK3 VOLVO B10M		795265
879	11/19/2019	855441	Consumables		795670
879	11/19/2019	855441	Mechanic entered - Body Other radiator hatch broken	repaired radiator hatch ok	795265
879	11/19/2019	855441	Mechanic entered - Body Other MIDDLE SEAT TOP PINS OUT	put in middle seat top pins ok	795265
879	11/19/2019	855441	Mechanic entered - Body Other DRIVER SUN BLIND NOT WORKING	repaired driver sun blind ok	795265
879	11/19/2019	855441	Consumables		795670
879	11/12/2019	853933	Mechanic entered - Elec and Light Two Way Radio TO BE FITTED	FIT REPAIRED 2 WAY RADIO.	793845
879	11/12/2019	853933	Consumables		794375
879	11/10/2019	853626	Mechanic entered - Engine Other Cutting off on the way to de	Checked found no fuel leaks took 204 ltrs fuel took for road test founk ok Suspect was low on fuel	793325
879	11/07/2019	853141	Drv entered - Elec and Light Two Way Radio	CDF fitted the same two-way after getting repaired	793073
879	11/07/2019	853141	2-way not working	removed the radio and fitted one from 1196. sent the unit for repairs.	793073
879	11/07/2019	853141	Drv entered - Elec and Light Two Way Radio	PO#: 0261936	793073
879	11/07/2019	853141	Consumables		793325
879	11/04/2019	852577	LIGHT SIDE INDICATOR L/H		793073
879	11/04/2019	852577	Mechanic entered - Elec and Light Indicators Not Working N/S	Replaced damage light with new one	793073
879	11/04/2019	852577	Consumables		793073
879	11/01/2019	850075	DIRECT PURCHASE - ELECTRICAL	Creditor #:\VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O260967 Receiving #:272385 Date :2019-11-14 carry out cctv 6 mnth service	794638
879	11/01/2019	852056		instructed to close off by fleet - ben willis via group e-mail	792833
879	11/01/2019	852056		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	792833
879	10/30/2019	851279	Ops Entered - Fault - Elec and Light Two Way Radio - Route:	refit plug to radio.	792123
879	10/30/2019	851279	Consumables		792592
879	10/28/2019	850872	Advised shaft seal leaking	Creditor #:\VB-COA003 COACHAIR PTY LTD P/O #:O261267 Receiving #:271447 Date :2019-10-31	792592
879	10/28/2019	850872	Mechanic entered - A/C Heating Other A/C compressor shaft s	Shaft seal leaking - Completed by CoachAir.	791797
879	10/28/2019	850871	Shaft seal leaking - Fault - A/C Heating Not Cooling - Rou		791797
879	10/28/2019	850871	Ops Entered - Fault - A/C Heating Not Heating - Route: -	Adviswed by CoachAir - Shaft seal leaking.	791797
879	10/24/2019	850075	CCTV - 6month service	done by johnny bw electrics O260967	791427
879	10/07/2019	846443	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	SENT THE BUS TO VOLGREN PO O259546	790036
879	10/05/2019	845611	Consumables		790036
879	10/05/2019	845611	Drv entered - BusMinder No Power	fitted the one supplied ok	789573
879	10/04/2019	845898		TRANSMISSION CHECK AS PER CHECK LIST Carried out Transmission Check	789573
879	10/04/2019	846012	Consumables		789573
879	10/04/2019	846012	Mechanic entered - Elec and Light Interior Lights O/S/F Salo	Replaced Globe and tested ok	789573
879	10/04/2019	846015	Consumables		789956
879	10/04/2019	846015	Mechanic entered - Body Other O/S/R side hatch strut u/s. Pa	Replaced Gas strut Reinserted clip to hold Hatch closed	789573
879	10/04/2019	846012	Mechanic entered - Air System Air_Leak Rear Air Hose on Rece	Cut Hose at hole and added joiner .ok	789573
879	10/04/2019	845897	Consumables		789956
879	10/04/2019	845897	Consumables		789956
879	10/04/2019	845897	Consumables		789956
879	10/04/2019	845897	Consumables		789956
879	10/04/2019	845897		CARRY OUT B SERVICE AS PER CHECK LIST Carried out 'B' Service	789573
879	10/04/2019	845897	Oil Filter SCANIA S4 & K		789573
879	10/04/2019	845897	FILTER FUEL FILTER SCANIA SR4 (1372444)		789573
879	10/04/2019	845897	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		789573
879	10/04/2019	845897	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		789573
879	10/02/2019	845611	Drv entered - BusMinder No Power	ordered new	789173
879	10/02/2019	845435	Consumables		789573
879	10/02/2019	845435	Mechanic entered - Body Other	N/S/F Parcel shelf loose causing rattle Re Rivetted parcel shelf and checked ok	789173
879	10/02/2019	845610	Drv entered - Brakes Foot_Brakes Leaking Air	checked air full air system for air leaks . could not fault. checked build up time for compressor. 90 seconds at 1500 RPM	789173
879	09/23/2019	843764	Consumables		788201
879	09/23/2019	843764	Mechanic entered - Elec and Light Flat Batteries	Jump Started bus	787806
879	09/23/2019	843797	Consumables		788201
879	09/23/2019	843797	Mechanic entered - Body Front_Door Operation Faulty doors n/	reboot RPD unit.	787806
879	09/20/2019	843661	Fault#:36908 - Ops Entered - Fault - Breakdown Overheating/C	Attended breakdown at blackburn station fit back top radiator hose with two clamps fill up coolant and brought to workshop	787806
879	09/20/2019	837639	Consumables		788013
879	09/20/2019	837639	Mechanic entered - Body Drivers Seat Controls BACKREST BROKE	FIT NEW DRIVERS SEAT. - sent u/s drivers seat away to be repaired / or replaced as per quote	787806
879	09/20/2019	843514	Ops Entered - Fault - Air System Air_Leak Interior - Route	traced and found air leak under drivers seat . reconnected air line . checked operation of drivers seat all okay	787806
879	09/19/2019	843195	Consumables		787806

879	09/19/2019	843195	Mechanic entered - Elec and Light Flat Batteries	Jump Started bus	787679
879	09/14/2019	842340	Engine won't switch off	diagnosed and found park brake signal weak. traced the wiring and found a high resistance at the plug as the light is dull. repaired the wiring tested ok	786928
879	09/12/2019	841703	Consumables		786928
879	09/12/2019	841703	Elec and Light - door brakes nw	finish rewiring door brake loom and secondary looms	786854
879	09/11/2019	841703	Elec and Light - door brakes nw	Assisting - diagnosed door brakes system and found no pwr to solenoid. traced and found broken wires at osr	786854
879	09/11/2019	841703	Elec and Light - door brakes nw	checked the door brakes system - removed the wiring and started repairing	786854
879	09/07/2019	840920		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed safety inspection	786114
879	09/07/2019	840920		VEHICLE SAFETY INSPECTION	786114
879	09/07/2019	841021	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting	786114
879	09/07/2019	840944	Consumables		786398
879	09/07/2019	840944	Lamp Step White LED		786114
879	09/07/2019	840944	Mechanic entered - Elec and Light Interior Lights One saloon	Replaced step light with new one replaced fluro	786114
879	09/07/2019	840944	Consumables		786398
879	09/07/2019	840944	Mechanic entered - Body Other Drivers modesty panel loose	Drill and fit rivets	786114
879	09/05/2019	840634	Consumables		786114
879	09/05/2019	840569	Consumables		786114
879	09/05/2019	840634	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Completed retension	785964
879	09/05/2019	840569	TYRE 295/80R22.5 RECAP		785964
879	09/05/2019	840569	Mechanic entered - Wheels and Tyres Damaged Pos 3 tyre wall	Replaced damage wall pos3 tyre and worn pos 4 tyre with new retreads	785964
879	09/04/2019	840173	Consumables		785964
879	09/04/2019	840173	Ops Entered - Fault - Elec and Light Two Way Radio - Route	traced and found microphone not connected . conntected microphone and carried out radio checked with operations- rod	785772
879	08/23/2019	837338	Consumables		783955
879	08/23/2019	837338	Drv entered - BusMinder Unable To Log In	checked and found log on ok	783955
879	07/30/2019	832101	Consumables		779671
879	07/30/2019	832101	Mechanic entered - Elec and Light Exterior Lights N/S/F bott	Replaced globe	779444
879	07/20/2019	830019	Consumables		777908
879	07/20/2019	830019	Mechanic entered - Body Other bus inside noisy	tightened o/sn/s bus inside top panel screws ok	777680
879	07/19/2019	829511	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:O253221 Receiving #:262583 Date :2019-07-23 repair the fuel tank leaking as required	778408
879	07/19/2019	829511	Mechanic entered - Fluid Leaks Other	Fit back repaired fuel tank fill fuel bleed and start	777680
879	07/18/2019	829511	Mechanic entered - Fluid Leaks Other	assisted Chris to remove the tank - PO#: O253221 for auto cooling	777680
879	07/18/2019	829511	Mechanic entered - Fluid Leaks Other	Fuel Tank Leaking Drained Fuel Tank Removed Fuel Tank And Marked Leak steam washed. need to send away for repairs	777680
879	07/15/2019	828705	assisting		777155
879	07/15/2019	828705		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	777155
879	07/15/2019	828705		VEHICLE SAFETY INSPECTION	777155
879	07/15/2019	828721	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)		777155
879	07/15/2019	828721	Mechanic entered - Suspension Other Front 'D' Rubbers U/S	Replaced Front 'D' Rubbers	777155
879	07/15/2019	828721	Mechanic entered - Engine Other engine oil leaks from oil co	tightened oil cooler all bolts ok	777155
879	07/15/2019	828721	Mechanic entered - Engine Other engine oil leaks from sump	tightened engine sump bolts ok	777155
879	07/15/2019	828721	Mechanic entered - Engine Other engine bottom coolant hose l	tightened engine bottom coolant hose clamp ok	777155
879	07/15/2019	828721	FILTER AIR FILTER (395773) AF25066		777155
879	07/15/2019	828721	Mechanic entered - Engine Other engine air filter u/s	replaced engine air filter ok	777155
879	07/15/2019	828721	Consumables		777408
879	07/15/2019	828721	Mechanic entered - Body Other n/s/f staunchion pole bolts lo	tightened n/s/f staunchion pole bolts ok	777155
879	07/15/2019	828721	Mechanic entered - Body Other n/s/r top corner moulding off	repaired n/s/r top corner moulding	777155
879	07/15/2019	828721	Mechanic entered - Body Other Rear Smoking Decal Missing	replaced no smoking decal	777155
879	07/15/2019	828721	Mechanic entered - Body Other Front Modest Panel Loose	Retained Modesty Panel	777155
879	07/15/2019	828721	Mechanic entered - Body Other Middle Seat Top Pin out	Returned Pin to Position	777155
879	07/11/2019	828138	Consumables		777155
879	07/11/2019	828138	Elec and Light - desto frozen	removed the controller sent away for repairs - fitted back ok PO#: O252649	777145
879	07/08/2019	828138	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O252649 Receiving #:261623 Date :2019-07-12 repair desto controller as required	777155
879	07/03/2019	826402	Consumables		775925
879	07/03/2019	826402	Mechanic entered - Elec and Light Other n/s park light not w	check could not fault ok	775471
879	06/17/2019	823404	Consumables		772989
879	06/17/2019	823404	Mechanic entered - Elec and Light Indicators Not Working O/S	Replaced globe	772935
879	06/17/2019	823404	Consumables		772989
879	06/13/2019	822632	Consumables		771949
879	06/13/2019	822632	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	checked operation of headlights . could not fault	771833
879	06/13/2019	822632	Consumables		771949
879	06/11/2019	822258	Consumables		771715
879	06/11/2019	822049	Consumables		771715
879	06/11/2019	822258	Mechanic entered - Elec and Light Exterior Lights n/s/f head	r/r head light globeok.	771163
879	06/11/2019	822049	Mechanic entered - Elec and Light Other battery jump	jumped battery ok	771163
879	06/11/2019	822258	Consumables		771715
879	06/11/2019	822049	Consumables		771715
879	06/07/2019	821465	1433457 Handle	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O249865 Receiving #:258612 Date :2019-06-07	771444
879	06/06/2019	821465	Ops Entered - Fault - Steering Wanders - Route: 703 - Cent	fitted new steering adjustor . checked operation all okay	770743
879	06/06/2019	821465	Drv entered - Steering Steering Wheel Faulty		770743
879	06/06/2019	821683	Consumables		771163
879	06/06/2019	821683	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced H4 globe	770743
879	06/06/2019	821683	Consumables		771163
879	06/05/2019	820959	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O249680 Receiving #:258547 Date :2019-06-07 mick to repair damaged and misaligned wheel chair ramp as required	770971
879	06/04/2019	820959	EDGE STEP EDGE YELLOW 43mm		770597
879	06/04/2019	821159	Consumables		770743
879	06/04/2019	821159	Mechanic entered - Elec and Light Interior Lights Drivers re	Replaced globe and fluro	770597
879	06/04/2019	821159	Consumables		770743
879	06/04/2019	821159	Consumables		770743
879	06/04/2019	821159	Mechanic entered - Body Drivers Seat Leaning	Replaced seat cushion	770597
879	06/04/2019	821159	CAP END CAP CENTRA SEAT END CAP		770597
879	06/04/2019	821159	Mechanic entered - Body Other Seat end cap missing	Replaced broken end cap	770597
879	06/04/2019	821159	Consumables		770743
879	06/04/2019	821159	Mechanic entered - Air System Air_Leak Rear Leaking from jun	Removed valve and fit plug to port	770597
879	06/04/2019	821091	Consumables		770743
879	06/04/2019	821091	Consumables		770743
879	06/04/2019	821091	Consumables		770743
879	06/04/2019	821091	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		770597
879	06/04/2019	821091	Oil Filter SCANIA S4 & K		770597
879	06/04/2019	821091	FILTER FUEL FILTER SCANIA SR4 (1372444)		770597
879	06/04/2019	821091	FILTER FUEL FILTER SCANIA SR4 (1393640)		770597
879	06/04/2019	821091	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		770597
879	06/04/2019	821091		CARRY OUT B SERVICE AS PER CHECK LIST Completed service	770597
879	06/04/2019	821091	Consumables		770743
879	06/04/2019	821091	Consumables		770743
879	06/04/2019	821091	Consumables		770743

879	06/03/2019	820959	Ops Entered - Fault - Passenger Doors - Route: 703 - Monas	removed wheel chair ramp . realigned . remounted wheel chair ramp . body van mick was sent into the situation to help	770597
879	05/22/2019	818355	assist		768196
879	05/22/2019	818355		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	768196
879	05/22/2019	818355		VEHICLE SAFETY INSPECTION	768196
879	05/22/2019	818448	Mechanic entered - Vandalism Other o/s/r seat base x1clips	replaced o/s/r seat base replaced seat base clip ok	768196
879	05/22/2019	818448	CENTRA CUSHION CLIP RH		768196
879	05/22/2019	818448	CENTRA CUSHION CLIP LH		768196
879	05/22/2019	818448	Mechanic entered - Suspension Other both both lower shock ru	replaced both front lower shock rubber ok	768196
879	05/22/2019	818448	RUB BUFFER		768196
879	05/22/2019	818448	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		768196
879	05/22/2019	818448	Mechanic entered - Suspension Other rear both D rubber u/s	replaced both rear D rubber ok	768196
879	05/22/2019	818448	Mechanic entered - Engine Other belt tensioner u/s	replaced engine belt tensioner ok	768196
879	05/22/2019	818448	Mechanic entered - Engine Other belt idler bearing u/s	replaced engine belt idler bearing ok	768196
879	05/22/2019	818448	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		768196
879	05/22/2019	818448	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		768196
879	05/22/2019	818448	Consumables		768462
879	05/22/2019	818448	Mechanic entered - Elec and Light Other rear step light not	replaced rear step light globe ok	768196
879	05/22/2019	818448	Consumables		768462
879	05/22/2019	818448	Mechanic entered - Elec and Light Other n/s/middle pax switc	FITTED NEW	768196
879	05/22/2019	818448	BELL PUSH STOP BUTTON FLAT (571-0226) (11870)		768196
879	05/22/2019	818448	Consumables		768462
879	05/22/2019	818448	Mechanic entered - Body Other fire extinguisher bracket brok	replaced fire extinguisher bracket ok	768196
879	05/22/2019	818448	Consumables		768462
879	05/22/2019	818448	Mechanic entered - Body Other middle seat top pins out	put in n/s/middle seat top pins ok	768196
879	05/22/2019	818448	EDGE STEP EDGE YELLOW 43mm		768196
879	05/22/2019	818448	Mechanic entered - Body Other rear step edge missing	replaced rear step edge ok	768196
879	05/22/2019	818448	Mechanic entered - Air System Other o/s/f air hose hit from	repaired o/s/f air hose ok	768196
879	05/18/2019	817669	Consumables		767913
879	05/18/2019	817669	Consumables		767913
879	05/18/2019	817669	carry out full retorque as required	carried out retorque as required	767709
879	05/16/2019	816897	LOCK RING BRAKE SHOE PIN 0804782		767709
879	05/16/2019	816897	INDICATOR WHEEL NUT POINTER 33mm		767709
879	05/16/2019	816897	Drv entered - Brakes Foot_Brakes Noisy	removed front and rear brake linings . hubs and drums. sent away for radius grind and machine . reinstalled brakes hubs and wheels . adjusted brakes . tensioned wheels nuts. road tested and brake tested all okay	767709
879	05/15/2019	816897	DIRECT PURCHASE - BRAKES	Creditor #:-VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:0248063 Receiving #:256805 Date :2019-05-20 radius grind and machine brakes as required	767913
879	05/12/2019	815339	Please remove all old poster and fit MYKI has gone mobil	fleet support completed this campaign	766519
879	05/04/2019	812879		CARRY OUT FIRE EXTINGUISHER TEST & TAG	765392
879	05/04/2019	812879		completed	765392
879	05/02/2019	803838	Consumables		765798
879	05/02/2019	803838	Consumables		765798
879	05/02/2019	803838	Mechanic entered - Body Other o/s/r hatch strut missing	replace strut	765534
879	05/01/2019	813032	Consumables		765534
879	05/01/2019	813032	Consumables		765534
879	05/01/2019	813032	1881260 Oil Pressure Sender	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:0246721 Receiving #:255222 Date :2019-05-02	765798
879	05/01/2019	813032	Ops Entered - Fault - Elec and Light Warning Light On Dash -	replaced oil sender road tested ok. readfing 6-7bar and oil light goes out once start	765392
879	05/01/2019	813032	Ops Entered - Fault - Elec and Light Warning Light On Dash	checked and found oil sender faulty - need order	765392
879	04/13/2019	810227	Mechanic entered - Gearbox Driveline Other not selecting gea	switch off busrestartnow ok.	762546
879	04/11/2019	809856	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-BWEO01 BWERE ELECTRICS PTY LTD P/O #:0245698 Receiving #:254370 Date :2019-04-18 carry out cctv service and repair as required	763586
879	04/11/2019	809856	CCTV - service	done by BW - Johnny on 11/04/2019 PO#: 0245698	762393
879	03/27/2019	806544		TRANSMISSION CHECK AS PER CHECK LIST	760126
879	03/27/2019	806544		carried out transmission checked as required	760126
879	03/27/2019	806610	Consumables		760244
879	03/27/2019	806610	Mechanic entered - Body Front_Door Operation Faulty	repaired on work order - 806165	760126
879	03/27/2019	806487	DIRECT PURCHASE ACCIDENT #4871	Creditor #:-VB-EOCAST EASTCOAST TRUCK & BUS SERVICE P/O #:0244376 Receiving #:252974 Date :2019-04-02	760944
879	03/27/2019	806487	Accident # 48716 - Completed by Mobile Mick.	Completed by Mobile Mick 7/3/2019	760126
879	03/26/2019	806165	Consumables		760126
879	03/26/2019	806165	Mechanic entered - Body Front_Door Operation Faulty	trace wiringfound broken wire at door switchrepairnow ok.	760125
879	03/25/2019	806074	Consumables		760125
879	03/25/2019	806074	Mechanic entered - Elec and Light Other front door n/w.	r/r emergency switch & door switch but still n/w. suspect electric system.	759633
879	03/22/2019	805493	Consumables		759475
879	03/22/2019	805493	o/s park light not working	checked operation . could not fault	759215
879	03/21/2019	805128		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	759213
879	03/21/2019	805128		VEHICLE SAFETY INSPECTION	759213
879	03/21/2019	805128	DIRECT PURCHASE - BUS INSPECTI	Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:0243904 Receiving #:252133 Date :2019-03-22	759215
879	03/21/2019	805128		ANNUAL SAFETY INSPECTION SERIAL # _____J815406_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	759213
879	03/18/2019	803838	K500-8-18@500nm Gas strus	Creditor #:-VB-MCN001 MCNAUGHTANS P/O #:0243583 Receiving #:252107 Date :2019-03-22	759215
879	03/18/2019	803838	Consumables		758710
879	03/14/2019	803515		PRE ANNUAL SAFETY INSPECTION CHECK	758156
879	03/14/2019	803611	WIPER REFILL 1000mm MULTI FIT		758156
879	03/14/2019	803611	Mechanic entered - Wipers and Washers Other wiper blade u/s	replaced wiper blade ok	758156
879	03/14/2019	803611	Mechanic entered - Steering Other power steering wheel loose	repaired power steering wheel ok	758156
879	03/14/2019	803611	Mechanic entered - A/C Heating Other a/c filter case screws	repaired a/c filter case ok	758156
879	03/14/2019	803611	Consumables		758270
879	03/14/2019	803611	WIPER REFILL 1000mm MULTI FIT		758156
879	03/14/2019	803611	Mechanic entered - Elec and Light Other n/s/f bottom indicat	replaced n/s/f bottom indicator lens ok	758156
879	03/14/2019	803611	Consumables		758270
879	03/14/2019	803611	Mechanic entered - Body Other o/s bus inside top panel loose	replaced o/s bus inside top panel screws ok	758156
879	03/14/2019	803611	Mechanic entered - Body Other driver back modesty panel loos	repaired driver back modesty panel ok	758156
879	03/14/2019	803611	Mechanic entered - Body Other middle seat top pin out	put in middle seat top pins ok	758156
879	03/14/2019	803611	Mechanic entered - Body Other driver seat back lumbar not wo	repaired driver seat back lumbar hose ok	758156
879	03/14/2019	803611	HANDLE GRAB HANDLE PASSENGER		758156
879	03/14/2019	803611	Mechanic entered - Body Other pax handle grab u/s	replaced pax handle grab ok	758156
879	03/14/2019	803611	OIL COLLECTOR AIR DRIER -SCANIA 40G0006		758156
879	03/14/2019	803611	Mechanic entered - Brakes Other brake condenser drain valve	removed brake condenser drain valve replaced brake condenser drain valve ok	758156
879	03/08/2019	802575	Drv entered - Brakes Foot_Brakes Noisy	ADJUST FRONT BRAKESROAD AND BRAKE TESTOK.	757465
879	03/05/2019	801673	glass film u/s x 4	carried by gkass protect - 0242546	756963
879	03/05/2019	801767	Consumables		757242
879	03/05/2019	801767	Mechanic entered - Elec and Light Exterior Lights o/s/f park	fit globe.	756963
879	03/01/2019	801673	DIRECT PURCHASE - VANDALISM	Creditor #:-VB-GLA010 GLASSPROTECH MELBOURNE P/O #:0242546 Receiving #:250960 Date :2019-03-07 replaced glass film x 4	757465
879	02/27/2019	800667		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	756631
879	02/21/2019	797568	steering adjustor u/s	fitted new steering adjustor . checked operation all okay	755846
879	02/13/2019	797568	Steering adjuster us	ordered parts with scania PO#: 0241085	754158
879	02/13/2019	797568	Direct Purchase - MECHANICAL	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:0241085 Receiving #:249536 Date :2019-02-18 supply steering adjuster as requested	755093
879	02/13/2019	797475	Mechanic entered - Steering Other steering wheel adjuster n/	remove adjuster from bus 1181 and fit .	754158

879	01/31/2019	794597	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	752522
879	01/31/2019	794597	VEHICLE SAFETY INSPECTION	752522
879	01/31/2019	794727		752522
879	01/31/2019	794727	replaced a/c mount ok	752522
879	01/31/2019	794727	replaced driver back modesty panel bolttightened driver back modesty panel bolts ok	752522
879	01/31/2019	794727	repaired rear modesty panel ok	752522
879	01/31/2019	794727	replaced o/s/r panel bolt ok	752522
879	01/31/2019	794727	replaced bus inside top panel screws ok	752522
879	01/31/2019	794727	replaced front step edge ok	752522
879	01/31/2019	794727	tightened middle seat bolts ok	752522
879	01/31/2019	794727		752522
879	01/18/2019	792277	carried out campaign as required	750650
879	01/16/2019	791545		750425
879	01/16/2019	791545		750161
879	01/16/2019	791545	repair panelfit new blinker assembly.	750161
879	01/16/2019	752850	Rec No - 246026	750161
879	01/15/2019	787390		750161
879	01/15/2019	787390	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O237572 Receiving #:246805 Date :2019-01-15 check and rectify desto nw	750146
879	01/11/2019	790821		749920
879	01/11/2019	790821	Retensioned Pos 2 - OSF	749696
879	01/11/2019	790721	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O238680 Receiving #:247213 Date :2019-01-21 carry out ac a service as required	750875
879	01/11/2019	790721	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - done by cold drive cCamillus PO#: O238680	749696
879	01/10/2019	789770	Creditor #:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:O238297 Receiving #:246585 Date :2019-01-11 check and rectify diesel tank leaking	749696
879	01/10/2019	789770	fitted fuel tankok.	749310
879	01/07/2019	789577		749687
879	01/07/2019	789577		749310
879	01/07/2019	789577	replaced o/s/f tyre ok	749310
879	01/07/2019	789770	drain fuel & removed fuel tank. sent to auto cooling PO#: O238297	749310
879	01/07/2019	789624		749687
879	01/07/2019	789577		749687
879	01/07/2019	789624		749310
879	01/07/2019	789624	replaced indicator switch ok	749310
879	01/07/2019	789577	repaired o/s/f park light wires ok	749310
879	01/07/2019	789577	replaced n/s middle saloon light tube ok	749310
879	01/07/2019	789577	repaired front door ok	749310
879	01/07/2019	789540		749687
879	01/07/2019	789540		749687
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	01/07/2019	789540		749310
879	12/21/2018	787390		748046
879	12/21/2018	787390	done by Lonsdale PO#: O237572	747894
879	12/17/2018	786413		747336
879	12/17/2018	786413	reset destination checked operation all okay	747075
879	12/04/2018	783820		745100
879	12/04/2018	783820		745100
879	12/04/2018	783820		744860
879	12/04/2018	783820	R&R seat belt anchor	744860
879	12/03/2018	783559	cleaned vandelisem from inside bus	744248
879	12/03/2018	783536		744860
879	12/03/2018	783536	R&R headlight	744248
879	12/01/2018	781586		744248
879	12/01/2018	781586	Replaced rear sway bar D bushes and link bushes	744248
879	11/29/2018	782597	carried out by johnny from bewere - O235611	743766
879	11/28/2018	781586	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O235413 Receiving #:243308 Date :2018-11-28	743766
879	11/27/2018	782102		743766
879	11/27/2018	782102	reset desto . checked operation all okay	743506
879	11/26/2018	781581		743506
879	11/26/2018	781581		743015
879	11/26/2018	781581		743015
879	11/24/2018	781532		743015
879	11/24/2018	781532		743015
879	11/24/2018	781581		743015
879	11/24/2018	781581	Fitted missing pointer on o/s/f wheel and replaced broken check link on rear wheel	743015
879	11/24/2018	781581		743015
879	11/24/2018	781586	Need to order rear sway bar link bushes and replace the D rubber bushes	743015
879	11/24/2018	781582		743015
879	11/24/2018	781582	Replaced globe and D selector button	743015
879	11/24/2018	781584		743238
879	11/24/2018	781584	Fitted two missing sear end caps drill out old rivets and fit new rivets to the front myki mounting Fit new rivets to bottom panel of rear modesty panel fit aluminium plate to carpet coming off on the side wall off rear door entrance drill and fit screw to padding for o/s luggage bin	743015
879	11/24/2018	781584		743015
879	11/20/2018	780528		742393
879	11/20/2018	780528	could not fault	742005
879	11/15/2018	779844		741585
879	11/15/2018	779844	Found o/s disable next stop switch not working replaced with new one	741361
879	11/15/2018	779844		741361
879	11/13/2018	779008		741135
879	11/13/2018	779008	fit globe.	740742
879	11/01/2018	782597	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O235611 Receiving #:243486 Date :2018-11-29	743989
879	10/16/2018	772772	replaced front brake boosters x 2 brake S cams x 2 and S cambushes. road tested and brake- o/s/f slack adjustor replaced .	736664
879	10/15/2018	772772	fitted s camneed check for slack adjuster.	736664
879	10/15/2018	772772	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O231735 Receiving #:239624 Date :2018-10-15	736664
879	10/12/2018	772772	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O231735 Receiving #:239490 Date :2018-10-12	736664
879	10/12/2018	772772	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O231735 Receiving #:239490 Date :2018-10-12	736664
879	10/12/2018	772772	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O231735 Receiving #:239490 Date :2018-10-12	736664
879	10/12/2018	772772	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O231735 Receiving #:239490 Date :2018-10-12	736664
879	10/11/2018	772772		736664
879	10/05/2018	771233	carried out campaign as required	735765
879	10/02/2018	770097	Assisting - road/brakes tested ok	735220
879	10/02/2018	770097	fitted front brakes and adjusted	735220

879	10/01/2018	769753	DIRECT PURCHASE - BRAKES	Creditor #:\VB-COM100 Commercial Brake & Clutch P/O #:O230725 Receiving #:238551 Date :2018-10-01 radius grind linings and machine drums as required	735220
879	10/01/2018	769753	SLACK ADJUSTER FRONT OUTER SIDE (1789567)		734980
879	10/01/2018	769753	Mechanic entered - Brakes Other o/s/f brake slack adjust u/s	replaced o/s/f brake slack adjust ok	734980
879	10/01/2018	769753	Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 703	removed front both brake liningsbrake durms	734980
879	09/27/2018	769569	Mechanic entered - Gearbox Driveline Other transmission oil	check transmission oil leakscleaned transmission found trans rear cover oring leakstrats oil pipe leaks replaced trans rear COVER ORING removed trans oil pipe clampcleaned pipeclamp ok road tested ok	734980
879	09/26/2018	769065	Consumables		735220
879	09/26/2018	769065	REAR POSITION STOP LAMP LED (DESIGNLINE)		734980
879	09/26/2018	769065	Mechanic entered - Elec and Light Exterior Lights n/s/r bott		734980
879	09/26/2018	769254		rewirefit newlight assembly.	734980
879	09/26/2018	769254		CARRY OUT FIRE EXTINGUISHER TEST & TAG	734980
879	09/22/2018	767235	Engine mounts u/s x2	closed off as completed as per instruction from paul bell	734980
879	09/18/2018	767126		R&R engine mounts x 2	734162
879	09/18/2018	767126		VEHICLE SAFETY INSPECTION	733379
879	09/18/2018	767126		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	733379
879	09/18/2018	767170	Mechanic entered - Wipers and Washers Other wiper rubber u/s	replaced wiper rubber x2 ok	733379
879	09/18/2018	767170	WIPER REFILL 1000mm MULTI FIT		733379
879	09/18/2018	767170	Consumables		733638
879	09/18/2018	767170	Mechanic entered - Wheels and Tyres Other rear tyre air valv	replaced rear both tyre air valve ok	733379
879	09/18/2018	767170	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)		733379
879	09/18/2018	767170	Mechanic entered - Suspension Other front D rubber u/s	replaced front D rubber ok	733379
879	09/18/2018	767170	Mechanic entered - Gearbox Driveline Other trans reor cover	replaced trans rear cover oring ok	733379
879	09/18/2018	767235	MOUNT ENGINE SCANIA 1475868	Creditor #:\VB-MUL004 MULTISPARES OAKLEIGH P/O #:O229857 Receiving #:237542 Date :2018-09-19	733379
879	09/18/2018	767170	Mechanic entered - Engine Other engine belt tensioner u/s	replaced engine belt tensioner ok	733379
879	09/18/2018	767170	Mechanic entered - Engine Other engine belt u/s	replaced engine belt ok	733379
879	09/18/2018	767170	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing ok	733379
879	09/18/2018	767170	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		733379
879	09/18/2018	767170	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		733379
879	09/18/2018	767170	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG		733379
879	09/18/2018	767170	Consumables		733638
879	09/18/2018	767170	Mechanic entered - Elec and Light Other button shift N u/s	replaced button shift N ok	733379
879	09/18/2018	767170	Button Shift N VERTICAL SERIES 4		733379
879	09/18/2018	767170	Consumables		733638
879	09/18/2018	767170	Mechanic entered - Body Other n/s/r seat back rest cover bro	repaired n/s/r seat back cover ok	733379
879	09/18/2018	767170	Mechanic entered - Body Other bus inside o/sn/s screws miss	replaced bus inside o/sn/s screwstightened n/so/s bus inside top screws ok	733379
879	09/18/2018	767170	Mechanic entered - Body Other n/s/r seat bracket bolts loose	tightened n/s/r seat bracket bolts ok	733379
879	09/15/2018	766764	BATTERY POS ON LHS		732860
879	09/15/2018	766764	Engine WON'T START	REPLACED 2 X BATTERIES	732860
879	09/13/2018	766089	Mechanic entered - Engine Other tubor top oil fitting leaks	check ok - wrong bus number disregard	732484
879	09/13/2018	765977	Consumables		732860
879	09/13/2018	765977	Mechanic entered - Elec and Light Flat Batteries to jump sta	jump start bus.	732484
879	09/12/2018	766563	CCTV - 6months service and fixed wi-fi connection issues	Johnny carried out cctv 6months service and fixed wi-fi connection issues	732671
879	08/31/2018	763150	Engine needs jjump start	Jump started bus	730363
879	08/30/2018	763007		TRANSMISSION CHECK AS PER CHECK LIST completed trans check as per checklist. road tested all ok	730363
879	08/30/2018	763012	TYRE 295/80R22.5 RECAP		730447
879	08/30/2018	763083	Consumables		730447
879	08/30/2018	763012	Consumables		730363
879	08/30/2018	763083	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	wheel nuts retensionok.	730363
879	08/30/2018	763012	Mechanic entered - Wheels and Tyres Worn all rear tires worn	replaced all 4 rear tires./ wheel nuts torqued to OEM spec. re torque booked	730363
879	08/30/2018	762714	DIRECT PURCHASE - BRAKES	Creditor #:\VB-COM100 Commercial Brake & Clutch P/O #:O228257 Receiving #:235954 Date :2018-08-31 replaced brake linings and machine drums as required	730447
879	08/30/2018	762714	Service	assisted	730363
879	08/29/2018	762714	Ops Entered - Fault - Brakes Foot_Brakes - Route: 703b - M	removed front and rear brakes sent away for machine refit brakes . road test and brake test . all okay	730363
879	08/27/2018	761894	Mechanic entered - Engine Other not starting	jump started	729869
879	08/22/2018	761036	Mechanic entered - Air System Air_Leak Rear	tracefound rubbed through air line at rear levelling valve blockcut fit joinerok.	729112
879	08/20/2018	760526	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	carried out campaign as required	728619
879	08/17/2018	759936	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	installed DC5V outlet	728619
879	08/17/2018	759935	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	both bus numbers are on	728619
879	08/15/2018	759493	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	carried out campaign as required	728355
879	08/10/2018	758387	Mechanic entered - Engine Other engine oil filter housing	removed engine oil filter housingcleaned all part	727622
879	07/25/2018	754728	Mechanic entered - Elec and Light Other n/s/r saloon light n	repaired n/s/r saloon light wires ok	724628
879	07/25/2018	754728	Mechanic entered - Elec and Light Other n/s/f top park light	repaired n/s/f top park light wires ok	724628
879	07/25/2018	754728	Consumables		724769
879	07/25/2018	754728	Mechanic entered - Body Other n/s mirror loose	tightened n/s mirror bracket bolts ok	724628
879	07/25/2018	754728	Mechanic entered - Body Other driver seat loose	tightened driver seat bolts ok	724628
879	07/25/2018	754728	Mechanic entered - Body Other o/s mirror bolt broken	drill holemade o/s mirror bracket nut ok	724628
879	07/25/2018	754728	Consumables		724769
879	07/25/2018	754636	Consumables		724769
879	07/25/2018	754636		CARRY OUT B SERVICE AS PER CHECK LIST	724628
879	07/25/2018	754636	Oil Filter SC S4 & K		724628
879	07/25/2018	754636	BELT V-BELT COGGED TRUCK & BUS 17x1555mm (11/16x61.1/4)		724628
879	07/25/2018	754636	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		724628
879	07/25/2018	754636	FILTER FUEL FILTER SCANIA SR4 (1372444)		724628
879	07/25/2018	754636	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		724628
879	07/25/2018	754636	Consumables		724769
879	07/25/2018	754636	Consumables		724769
879	07/23/2018	754127		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	723160
879	07/23/2018	754127		VEHICLE SAFETY INSPECTION completed safetyu as per checklist. wheel nuts torqued to OEM spec. road and brake and tested all ok	723160
879	07/23/2018	754169	Consumables		724628
879	07/23/2018	754169	Mechanic entered - Body Other n/s/ mirror loose	tightened mirror and adjusted. all ok	723160
879	07/23/2018	754168	Mechanic entered - Air System Air_Leak Rear	found air leak at reat of bus. tightened fitting all ok	723160
879	07/20/2018	753351	Consumables		723744
879	07/20/2018	753351	IGNITION BARREL WITH KEY L94UB S4		723160
879	07/20/2018	753351	Elec and Light turn ignition key on lights on dash come on	removed the stg covers and had access to the ign barrel. cut the securiti plate around and removed the switch assy. fitted new one and secured. tested all good.	723160
879	07/19/2018	753351	1433457 Handle	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O224909 Receiving #:232392 Date :2018-07-20	723686
879	07/19/2018	753351	Elec and Light turn ignition key on lights on dash come o	attempted to remove the ign switch but the screws jammed.	723160
879	07/19/2018	753351	Consumables		723686
879	07/19/2018	753351	Mechanic entered - Body Rear_Door Operation Faulty rear doo	could not fault; door working ok	723160
879	07/19/2018	752850	DIRECT PURCHASE ACCIDENT	Creditor #:\VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O224714 Receiving #:232568 Date :2018-07-23 carry out accident repair as required Acc#47039 and Acc#:47164	723956
879	07/18/2018	753077	Accident#:47164 - Ops Entered - Accident - Bus Hitting Obje	done at body shop PO O224714	723160
879	07/17/2018	752850	Accident # 47039	damage repairs done at body shop po O224714 acc#43039	723160
879	07/16/2018	752429	Consumables		723160
879	07/16/2018	752429	Mechanic entered - Elec and Light Flat Batteries	jump start	722670
879	07/09/2018	751013	Consumables		721990
879	07/09/2018	751013	Mechanic entered - Elec and Light Flat Batteries	JUMP START.	721727
879	06/23/2018	747612	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	fitted registration label as required	720764

879	06/16/2018	741372	Engine - transmission rear seal leaking	R&R leaking transmission rear seal as required	719289
879	06/13/2018	745053	Consumables		719062
879	06/13/2018	745053	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	sartya replaced globe on night shift rail	717761
879	06/12/2018	744559	Consumables		718910
879	06/12/2018	744559	Mechanic entered - Elec and Light Exterior Lights n/s/top fr	replace ns front desto indicator globe	717761
879	05/28/2018	741372	49D8505 REAR TRANSMISSION SEAL	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O220877 Receiving #:228349 Date :2018-05-28	715518
879	05/25/2018	741162		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	714926
879	05/25/2018	741162		VEHICLE SAFETY INSPECTION	714926
879	05/25/2018	741181	Consumables		715368
879	05/25/2018	741181	Mechanic entered - Wheels and Tyres Other n/s/r tyre air val	replaced n/s/r tyre air valve ok	714926
879	05/25/2018	741181	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine belt idler bearing x2	714926
879	05/25/2018	741181	Mechanic entered - Engine Other engine belt u/s	replaced engine belt ok	714926
879	05/25/2018	741181	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		714926
879	05/25/2018	741181	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG		714926
879	05/25/2018	741181	PULLEY IDLER SCANIA (1514087)		714926
879	05/25/2018	741181	Consumables		715368
879	05/25/2018	741181	Mechanic entered - Elec and Light Other speedo light not wor	replaced speedo light globe ok	714926
879	05/25/2018	741181	Consumables		715368
879	05/25/2018	741181	Mechanic entered - Body Other middle o/s staunchion poles bo	tightened middle o/s staunchion poles bolt ok	714926
879	05/25/2018	741181	Mechanic entered - Body Other middle seat loose	replaced middle seat ok	714926
879	05/25/2018	741181	Mechanic entered - Body Other o/sn/s inside top cover screw	replaced o/sn/s inside top cover screws ok	714926
879	05/25/2018	741163	Consumables		715368
879	05/25/2018	741163	Consumables		715368
879	05/25/2018	741163	Consumables		715368
879	05/25/2018	741163		CARRY OUT A SERVICE AS PER CHECK LIST	714926
879	05/24/2018	741053	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	carried out campaign as required	714926
879	05/21/2018	738643	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INST	completed installing program using the laptop	714249
879	05/18/2018	738694	FILTER AIR FILTER (395773)		713987
879	05/18/2018	738694	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)		713987
879	05/17/2018	739222	Consumables		713987
879	05/17/2018	739222	Mechanic entered - Elec and Light Interior Lights cab light	fit globe.	713553
879	05/16/2018	738643	KIT SWITCH OVERRIDE RPD		713553
879	05/15/2018	738616		SERVICE MOISTURE EJECTOR	712920
879	05/15/2018	738616		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	712920
879	05/15/2018	738694	GASKET ROCKER COVER SCANIA SR4 DC9 (1425921)		712920
879	05/15/2018	738694	Mechanic entered - Engine Other rocker cover gasket u/s	replaced rocker cover gasket ok	712920
879	05/15/2018	738694	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)		712920
879	05/15/2018	738694	Mechanic entered - Engine Other air filter u/s	replaced air filter ok	712920
879	05/15/2018	738643	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	switch and wiring installation done. waiting on interface to program the node.	712920
879	05/12/2018	738188	Consumables		713242
879	05/12/2018	738188	Elec and Light Two Way Radio not transmitting	checked operation of 2-way with oakleigh opps Sen.	712920
879	05/11/2018	737972	Mechanic entered - Suspension Other stuck on raise	road test so speed relay could kick in all ok	712920
879	05/11/2018	738023	Consumables		713242
879	05/11/2018	737971	Consumables		713242
879	05/11/2018	738023	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	R&R globe . checked operation all okay	712920
879	05/11/2018	737971	Mechanic entered - Elec and Light Exterior Lights o/s headli	fit globe	712920
879	05/09/2018	737525	Consumables		712920
879	05/09/2018	737525	Mechanic entered - Body Other drivers cab door loose.	secured hinge	712466
879	04/26/2018	735139	Consumables		710472
879	04/26/2018	735139	Mechanic entered - Body Other number plate u/s.	r/r number plateok.	710207
879	04/11/2018	732135	Consumables		707345
879	04/11/2018	732135	LAMP LED SIDE MARKER RED/AMBER		706361
879	04/11/2018	732135	Elec and Light Exterior Lights N/S rear clearance light m	fit new light and repaired wiring. all ok	706361
879	04/10/2018	732043	Mechanic entered - Steering Steering Wheel Faulty	repaired steering column adjustor	706361
879	04/08/2018	731506	Consumables		706687
879	04/08/2018	731506	Mechanic entered - Wheels and Tyres Wheel Nut Retension n./	carried out retorque as required	706361
879	04/04/2018	730818	Engine - bus wont start	jump started bus . checked starting all okay	705880
879	04/04/2018	730319	Consumables		706098
879	04/04/2018	730319	eng oil light and oil pressure display nw	checked oil pressor fusefound oil pressure fuse after checked okroad tested ok	705880
879	04/03/2018	730507	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	tigheten hose clampok.	705880
879	04/03/2018	730319	eng oil light and oil pressure display nw	fitted new oil sensor but still n/w.swap with other bus still n/w.	705880
879	04/03/2018	730319	eng oil light and oil pressure display nw	removed oil sender	705880
879	03/31/2018	729723	Mechanic entered - Engine Other engine sump plug broken	replaced engine sump gasket replaced spinner gasket put in sumptightened engine sump bolts oktightened oil plugepipes ok put in engine oil ok road tested ok	705880
879	03/29/2018	729723	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-HMG001 HM GEM ENGINES P/O #:O216915 Receiving #:224398 Date :2018-04-04 repair damaged sump thread as required	705880
879	03/29/2018	729794	BELT TENSIONER		705880
879	03/28/2018	729723	1412666 GASKET	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O216795 Receiving #:223993 Date :2018-03-28	705880
879	03/28/2018	729723	1116355 GAKET	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O216795 Receiving #:223993 Date :2018-03-28	705880
879	03/28/2018	729723	1392196 GASKET	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O216795 Receiving #:223993 Date :2018-03-28	705880
879	03/28/2018	729794	Mechanic entered - Engine Other engine belt bearing u/s	engine belt bearing ok	705671
879	03/28/2018	729794	Mechanic entered - Engine Other engine belt tentioner u/s	replaced engine belt tentioner	705671
879	03/28/2018	729723	Mechanic entered - Engine Other engine sump plug broken	removed engine sumpcleaned sump	705880
879	03/28/2018	729794	IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		705671
879	03/28/2018	729794	BELT TENSIONER		705671
879	03/28/2018	729723	PLUG PLUG MAGNETIC K310UB (1433641)		705880
879	03/27/2018	729444		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	705671
879	03/27/2018	729444		VEHICLE SAFETY INSPECTION	705671
879	03/27/2018	729444	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O216664 Receiving #:224057 Date :2018-03-29	705880
879	03/27/2018	729444		ANNUAL SAFETY INSPECTION SERIAL #_____serial 807842_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	705671
879	03/27/2018	729468	Mechanic entered - Suspension Other N/S/F TOQUER ROD U/S	removed n/s/f top torque rod bolt bus number is 1206put in 879tightened n/s/f torque rod bolt ok replaced n/s/f top torque rod ok	705671
879	03/27/2018	729468	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)		705671
879	03/27/2018	729468	Mechanic entered - Steering Other steering wheel loose	steering wheel adjust bolt broken removed steering adjust bolt repaired steering coloum ok replaced steering coloum adjust bolt ok	705671
879	03/27/2018	729468	NUT M16 SCANIA TORQUE ROD	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O216700 Receiving #:224008 Date :2018-03-28	705880
879	03/27/2018	729468	BOLT SCANIA TORQUE ROD M16 x	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O216700 Receiving #:224008 Date :2018-03-28	705880
879	03/27/2018	729468	Consumables		705880
879	03/27/2018	729468	Mechanic entered - Body Other o/s rear emergency decal u/s	replaced n/s/r emergency ok	705671
879	03/27/2018	729468	DECAL CCTV SURVEILLANCE		705671
879	03/27/2018	729468	Mechanic entered - Body Other RAIN GUTTER BROKEN	repaired N/S/R RAIN GUTTER OK	705671
879	03/27/2018	729458		done.	705671
879	03/27/2018	729458		CARRY OUT C SERVICE AS PER CHECK LIST	705671
879	03/27/2018	729458	FILTER HYDRAULIC COOLING FAN SCANIA SR3 (E90HD149)		705671
879	03/27/2018	729458	FILTER FUEL FILTER SCANIA SR4 (1393640)		705671
879	03/27/2018	729458	FILTER AIR DRYER SCANIA SR4 (1393551) (49G8709HALDEX)		705671
879	03/27/2018	729458	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		705671

879	03/27/2018	729458	O-RING SPINNER FILTER SCANIA (1769798)		705671
879	03/27/2018	729458	O-RING LARGE SPINNER FILTER SCANIA (1769799)		705671
879	03/27/2018	729458	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		705671
879	03/27/2018	729458	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		705671
879	03/27/2018	729458	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		705671
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458		CARRY OUT B SERVICE AS PER CHECK LIST	705671
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458		CARRY OUT A SERVICE AS PER CHECK LIST	705671
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/27/2018	729458	Consumables		705880
879	03/23/2018	728803		PRE ANNUAL SAFETY INSPECTION CHECK carried out pre asi as per check list	705427
879	03/23/2018	728947	Consumables		705432
879	03/23/2018	728947	TRIANGLE SAFETY DOUBLE SIDED 3 BOX		705427
879	03/23/2018	728947	Mechanic entered - Body Other safety triangle us	replaced broken triangles	705427
879	03/23/2018	728947	Mechanic entered - Body Other floor vinyl peeled	secured floor	705427
879	03/23/2018	728803		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	705427
879	03/19/2018	727578	Consumables		704844
879	03/19/2018	727578	bus wont start	jump started bus	704375
879	03/07/2018	718708	BUSH KITSSCANIA L94UAB V STAY 40Y33182F 28772 01		702035
879	03/07/2018	718708	KIT BUSH V BAR SCANIA		702035
879	03/06/2018	724689	Consumables		702522
879	03/06/2018	724689	INDICATOR STALK SCANIA SERIES 4 (1402448)		702035
879	03/06/2018	724689	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866 40G2702W		702035
879	03/06/2018	724689	Elec and Light indicator stork has fallen off	R&R indicator stalk	702035
879	03/06/2018	724689	Brakes hand brake wont lock in at times.	R&R hand brake valve	702035
879	03/05/2018	724216	Consumables		702467
879	03/05/2018	724216	Mechanic entered - Elec and Light Flat Batteries jump start	jump start bus	702035
879	03/05/2018	724498	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	carried out campaign as required	702035
879	03/03/2018	724390	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelsiem painting as required	702239
879	03/03/2018	724389	Mechanic entered - Vandalism Other pax seat base x 4 been c	carried out interior vandelsiem painting as required	702239
879	03/01/2018	730319	1881260 OIL PRESSURE SENDER	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O217008 Receiving #:224301 Date :2018-04-04	705880
879	03/01/2018	730319	Consumables		702035
879	02/27/2018	722760		TRANSMISSION CHECK AS PER CHECK LIST	701092
879	02/26/2018	722471	bus wont start	jump started bus	701092
879	02/26/2018	722471	Consumables		701301
879	02/19/2018	720992	Consumables		700272
879	02/19/2018	720992	Mechanic entered - Elec and Light Indicators Not Working	replace indicator lense ns	699693
879	02/19/2018	720992	LIGHT SIDE INDICATOR L/H		699693
879	02/16/2018	720285	Consumables		700065
879	02/16/2018	720285	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s/	retorque n/s/r wheel nuts.	699693
879	02/16/2018	720010	Consumables		700065
879	02/16/2018	720010	SCREW ALLEN CAP M4x16mm		699693
879	02/15/2018	719991		Assisting	699693
879	02/15/2018	719991		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	699693
879	02/15/2018	719991		VEHICLE SAFETY INSPECTION	699693
879	02/15/2018	720010	Mechanic entered - Wipers and Washers Other both wiper rubbe	replaced both wiper rubber ok	699693
879	02/15/2018	720010	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		699693
879	02/15/2018	720010	Mechanic entered - Suspension Other n/s/r bump stop bracket	repaired n/s/r bump stop bracket ok	699693
879	02/15/2018	720010	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O213889 Receiving #:221241 Date :2018-02-16 DOUBLE SEAT BASE	699860
879	02/15/2018	720010	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O213889 Receiving #:221241 Date :2018-02-16 LONG SEAT BASE	699860
879	02/15/2018	720010	DIRECT PURCHASE - VANDALISM	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O213889 Receiving #:221241 Date :2018-02-16 SINGLE SEAT BASE	699860
879	02/15/2018	720010	CENTRA CUSHION CLIP RH		699693
879	02/15/2018	720010	CENTRA CUSHION CLIP LH		699693
879	02/15/2018	720010	CATCH CLAW PLASMA ENGINE HATCH DOOR		699693
879	02/15/2018	720010	Mechanic entered - Body Other o/s driver sun visor loose	repaired driver sun visor ok	699693
879	02/15/2018	720010	Mechanic entered - Body Other n/s/r rain seal loose	repaired n/s/r rain seal ok	699693
879	02/15/2018	720010	Mechanic entered - Body Other seat base cut x3	removed seat bases and sent away PO#: 0213889replaced rear seat bases	699693
879	02/15/2018	720010	Mechanic entered - Body Other n/s/r panel latch loose	replaced n/s/r catch claw ok	699693
879	02/15/2018	720010	Mechanic entered - Body Other front sun visor loose	repaired front sun visor ok	699693
879	02/15/2018	720010	SCREW ALLEN CAP M4x16mm		699693
879	02/15/2018	720010	Mechanic entered - Brakes Other n/s/r brake back plate damag	repaired n/s/r brake lining back plate ok	699693
879	02/15/2018	720010	Mechanic entered - Air System Other air dryer safety valve u	replaced air dryer safety valve ok	699693
879	02/15/2018	720010	Mechanic entered - Air System Other condenser drain valve ai	replaced condenser drain valve ok	699693
879	02/15/2018	720010	SAFETY VALVE 14.3 bar		699693
879	02/15/2018	720010	OIL COLLECTOR AIR DRIER -SCANIA 40G0006		699693
879	02/13/2018	719420	Consumables		699693
879	02/13/2018	719420	Mechanic entered - Body Front_Door Operation Faulty	remove front doorrepair bushingrehang dooralignnoperating ok.	699183
879	02/13/2018	719623	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	carried out campaign as required	699183
879	02/12/2018	719274	Consumables		699442
879	02/12/2018	719274	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S	carried out retorque n/s/r to oem spec	699183
879	02/12/2018	719252		CARRY OUT FIRE EXTINGUISHER TEST & TAG	699183
879	02/12/2018	719237		CARRY OUT FIRE EXTINGUISHER TEST & TAG	699183
879	02/12/2018	719252		inspection carried out by ATS fire services - O213090	699183
879	02/12/2018	719237		inspection carried out by ATS fire services - O213090	699183
879	02/10/2018	718708	Ops Entered - Fault - Suspension Noisy - Route: 703b - Kmar	replaced V ROD BUSHINGS X3 replaced REAR D RUBBER OK removed N/S/R BRAKE DURMPUT OUT BRAKE LINING BACKING PLATE RETORQUED N/S/R WHEEL NUTS OK ROAD TESTED OKBRAKE TESTED OKNO NOISY OK	699007
879	02/10/2018	718708	BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		699007
879	02/10/2018	718708	TORQUE ROD BUSH SCANIA SR4 K230 1435944 23845 01		699007
879	02/10/2018	718708	BUSH KITSSCANIA L94UAB V STAY 40Y33182F 28772 01		699007
879	02/09/2018	718708	LINK SWAYBAR SCANIA K230 1766014 20486 01		699007
879	02/09/2018	718708	Ops Entered - Fault - Suspension Noisy - Route: 703b - Kmar	replaced front shock x1 ok replaced n/s/f sway bar link ok replaced rear top V rod bolt ok	699007
879	02/09/2018	718708	SHOCKER FRONT SERIES 4 (1920824)		699007
879	02/05/2018	717260	Consumables		698346
879	02/05/2018	717260	Mechanic entered - Elec and Light Flat Batteries	jump start	697873
879	01/22/2018	714818	bus needs jump start	Jump started bus .	696213
879	01/16/2018	713692	Mechanic entered - Air System Air_Leak Front	could not fault.	695283
879	01/12/2018	713309	Mechanic entered - Elec and Light Exterior Lights	replace os rear led indicator	695096
879	01/12/2018	713309	LAMP LED TURN		695096

879	01/10/2018	712706	Consumables			694833
879	01/10/2018	712706	Mechanic entered - Body Front_Door Operation Faulty	replaced both front door bottom bearingsnow operating ok.		694661
879	01/10/2018	712706	BEARING (FYH)			694661
879	01/10/2018	712706	BEARING (FYH)			694661
879	12/22/2017	709765	Breakdown#:34256 - Ops Entered - Breakdown - Breakdown Misc	R&R mirror		692379
879	12/22/2017	709765	MIRROR L/H 380mm SHORT (UES1411E)			692379
879	12/13/2017	707877		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		690635
879	12/13/2017	707877		VEHICLE SAFETY INSPECTION		690635
879	12/13/2017	707911	Mechanic entered - Brakes Other o/s/f brake slackl adjust u/	replaced o/s/f brake slack adjust kits ok		690635
879	12/13/2017	707911	KIT REPAIR KIT SLACK ADJUSTER (1350817)			690635
879	12/13/2017	707877	Consumables			690783
879	12/13/2017	707877	Consumables			690783
879	12/13/2017	707877	Consumables			690783
879	12/13/2017	707877				690635
879	12/09/2017	705601	DIRECT PURCHASE - AIR CONDITIO	CARRY OUT A SERVICE AS PER CHECK LIST		690635
879	12/02/2017	705601		Creditor #:-VB-COA003 COACHAIR PTY LTD P/O #:O208653 Receiving #:216470 Date :2017-12-13 CARRY OUT 24 MONTH SERVICE FOR A/C AS REQUIRED		690635
879	12/02/2017	705601		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O208652		688010
879	12/02/2017	705601		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O208652		688010
879	12/01/2017	705383	Consumables			688215
879	12/01/2017	705813	Consumables			688215
879	12/01/2017	705383	Elec and Light Two Way Radio - Not Transmitting	2-way reset at repeator by cim		688010
879	12/01/2017	705813	Elec and Light Flat Batteries	Drive to Middle Brighton and jump start bus need to clean terminals and load test batteries.		688010
879	11/21/2017	703066	Engine - coolant leaking from engine	tightend hose clamp . topped up coolant . road tested all ok		685702
879	11/06/2017	699886	Ops Entered - Fault - Suspension Kneel/ Raise - Route: 703	reset ignition and suspension . checked operation all ok		683885
879	11/01/2017	695423	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			683277
879	10/30/2017	697968	Remove old poster and fit new A3 Posters and hangers	carried out campaign as required		682420
879	10/29/2017	697207	Please remove the 2 x Do Not Enter decals at the exterior	carried out campaign as required		682420
879	10/27/2017	697639	Ops Entered - Fault - Wipers and Washers Washers Not Workin	repaired wiring to wipers . checked operation all ok		682646
879	10/25/2017	696990	Consumables			682420
879	10/25/2017	696990	Body - drivers seat belt is not working	R&R drivers seat belt . checked operation all ok		682381
879	10/23/2017	665793	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)			681501
879	10/23/2017	665793	BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)			681501
879	10/21/2017	663205	SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904			681501
879	10/20/2017	695423	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			681501
879	10/20/2017	695423	AIRBAG O/S/F SCANIA K230UB (2024284)			681501
879	10/20/2017	695423	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)			681501
879	10/19/2017	695577	Mechanic entered - Wipers and Washers Wipers Not Working	reposition wiper drive arm.		681061
879	10/18/2017	695292		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		681061
879	10/18/2017	695292		VEHICLE SAFETY INSPECTION		681061
879	10/18/2017	695346	WIPER REFILL 1000mm MULTI FIT			681061
879	10/18/2017	695346	Mechanic entered - Wipers and Washers Other both wiper rubb	replaced both wiper rubber ok		681061
879	10/18/2017	695423	VALVE EXTENSION-130mm Metal type			681061
879	10/18/2017	695423	Mechanic entered - Wheels and Tyres Other rear both tyres ai	replaced rear both tyres air valve x2		681061
879	10/18/2017	695423	TYRE 295/80R22.5 RECAP			681061
879	10/18/2017	695423	Mechanic entered - Wheels and Tyres Other rear both tyres x4	replaced rear both tyres x4 ok		681061
879	10/18/2017	695423	Mechanic entered - Suspension Other front both air bags x2	replaced front both air bags ok		681061
879	10/18/2017	695423	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)			681061
879	10/18/2017	695423	AIRBAG REAR SCANIA K310			681061
879	10/18/2017	695423	Mechanic entered - Suspension Other n/s/f/r air bags u/s x2	replaced n/s/r/f air bags x2 ok		681061
879	10/18/2017	695423	Mechanic entered - Suspension Other o/s/r/r air bag u/s	replaced o/s/r/r air bag x1 ok		681061
879	10/18/2017	695423	AIRBAG FRONT SCANIA K310			681061
879	10/18/2017	695346	Mechanic entered - Engine Other heat hose clamp loose	tightened heat hose clamp ok		681061
879	10/18/2017	695346	Mechanic entered - Engine Other coolant hose clamp loose	tightened engine bottom coolant hose clamp ok		681061
879	10/18/2017	695346	Mechanic entered - Elec and Light Other pax stop switch u/s	R&R switch replaced pax stop switch ok		681061
879	10/18/2017	695346	SWITCH- STOP-YELLOW			681061
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			681061
879	10/18/2017	695292	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			681061
879	10/18/2017	695292	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			681061
879	10/18/2017	695292	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			681061
879	10/18/2017	695292		CARRY OUT B SERVICE AS PER CHECK LIST		681061
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292	Consumables			681276
879	10/18/2017	695292		CARRY OUT A SERVICE AS PER CHECK LIST		681061
879	10/16/2017	694311	Mechanic entered - Engine Other won't start	jump started		680435
879	10/10/2017	692946	Wheels and Tyres - n/s/f retorque	carried out retorque to OEM spec as required on n/s/f wheel nuts		679618
879	10/10/2017	693068	Consumables			679945
879	10/10/2017	693068	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	carried out campaign as required		679618
879	10/10/2017	693068	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE			679618
879	10/10/2017	693061	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	carried out campaign as required		679618
879	10/07/2017	692651	Vandalism Vandalism/ Graffiti Interior	carried out campaign as required		679618
879	10/06/2017	692216	TYRE 295/80R22.5 NEW			679411
879	10/06/2017	692216	Mechanic entered - Wheels and Tyres Worn N/S/F TYRE LOW TRE	R&R n/s/f tire . tensioned wheel nuts		679411
879	10/02/2017	690922	Consumables			678727
879	10/02/2017	690922	Body BACK PAX BUTTON NOT WORKING	replaced buzzer button . checked operation all ok		677891
879	10/02/2017	690922	SWITCH- STOP-YELLOW			677891
879	10/01/2017	689633	Remove old A3 Posters with Seniors Festival please leave	carried out campaign as required		677891
879	09/20/2017	687687	Consumables			676974
879	09/20/2017	687687	REFLECTOR AMBER (84051)			676518
879	09/20/2017	687687	Body - n/s/r body reflector missing	R&R reflector		676518
879	09/14/2017	673526	DIRECT PURCHASE - BRAKES	Creditor #:-VB-COM100 Commercial Brake & Clutch P/O #:O197852-2 Receiving #:211093 Date :2017-10-04 CHANGE OVER BRAKE SHOES		678727
879	09/14/2017	673526	DIRECT PURCHASE - BRAKES	Creditor #:-VB-COM100 Commercial Brake & Clutch P/O #:O197852-1 Receiving #:211092 Date :2017-10-04 MACHINE @ RADIUS GRIND A REQ		678727
879	09/08/2017	685313	Engine wont start	R&R stater motor . checked starting system all ok		674370
879	09/08/2017	685313	MOTOR STARTER MOTOR SCANIA SR4 (0571420) (40V0200)			674370
879	08/31/2017	683610	Consumables			673405
879	08/31/2017	683610	Mechanic entered - Elec and Light Indicators Not Working o/s	fit globe.		672795
879	08/30/2017	683381	Consumables			673177
879	08/30/2017	683381	Drv entered - Elec and Light Exterior Lights	replace reverse lights globe. checked all operation of lights . all ok		672795
879	08/30/2017	683381	Drv entered - Elec and Light Horn	could not fault horn operation		672795
879	08/25/2017	682553		TRANSMISSION CHECK AS PER CHECK LIST		671867
879	08/22/2017	681794		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheel nuts tenstioned		671384

879	08/22/2017	681794	VEHICLE SAFETY INSPECTION safety completed	671384
879	08/22/2017	681794 Consumables		671661
879	08/22/2017	681794 Consumables		671661
879	08/22/2017	681794 Consumables		671661
879	08/22/2017	681794	CARRY OUT A SERVICE AS PER CHECK LIST a service completed	671384
879	08/18/2017	663205 SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		670783
879	08/14/2017	679860 Engine won't start	jump started	669456
879	08/14/2017	679951 Please remove old posters and fit new one along with hangers	campaign has been done	669456
879	07/19/2017	674930 Accident#:45384 - Ops Entered - Accident - Bus hits 3rd Par	bus was sent to knox on 19/07/2017 po O198279	666956
879	07/18/2017	674379 Mechanic entered - Wheels and Tyres Other n/s/f wheel nuts l	fitted wheel nuts link	666956
879	07/18/2017	674379 Mechanic entered - Wheels and Tyres Other all wheel nuts ret	tightened all wheel nuts retorqued 650nm ok	666956
879	07/18/2017	674379 INDICATOR WHEEL NUT POINTER 33mm		666956
879	07/17/2017	674320 Consumables		667217
879	07/17/2017	674320 head lights nw	replaced globes x 2	666956
879	07/16/2017	674138 Drv entered - Brakes Foot_Brakes Pulling	double entry	666956
879	07/16/2017	674138 Drv entered - Brakes Foot_Brakes Noisy	double entry	666956
879	07/16/2017	673526 Drv entered - Brakes Foot_Brakes Noisy	fit front and rear linings . fit hub drum assembly on front axle . fittedrearwheels and linings . tensioned all wheel nuts. adjusted brakes . roadandbrake tested .all ok	666956
879	07/14/2017	674137 Drv entered - Brakes Foot_Brakes Pulling		666956
879	07/14/2017	674137 Drv entered - Brakes Foot_Brakes Noisy		666956
879	07/14/2017	674137 Drv entered - Brakes Foot_Brakes Pulling		666956
879	07/14/2017	674137 Drv entered - Brakes Foot_Brakes Noisy		666956
879	07/14/2017	673526 Drv entered - Brakes Foot_Brakes Noisy	fitted front linings drums & wheels.	666956
879	07/13/2017	673526 Consumables		666956
879	07/13/2017	673526 Body retarder not working	checked and adjusted retarder on foot valve; road tested ok	666956
879	07/13/2017	673526 Mechanic entered - Brakes Foot_Brakes Noisy	removed front liniongs drum & wheel.	666956
879	07/13/2017	673526 Drv entered - Brakes Foot_Brakes Noisy	REMOVED REAR WHEELS AND BRAKES TO SEND OUT FOR RELINING	666956
879	07/13/2017	673526 Mechanic entered - Brakes Foot_Brakes Noisy	brakes sent to commercial brakes and clutch on 13/07/2017 PO O197852	666956
879	07/11/2017	614970 Consumables		666690
879	07/11/2017	614970 INDICATOR SIDE INDICATOR R/H		666213
879	07/04/2017	671271 PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	carried out campaign by paul bell	664903
879	06/22/2017	669265 Body - back door keep opening automatically	road tested; back door weas not openning by self. still the frt door is playing up at times. bypassed the rear door emg switches to see if there is any of them fails intermittently. also replaced frt door solenoid. road tested and checked the doors operation; ok. need to keep observing.	663543
879	06/22/2017	669265 SOLOINOID VALVE COMPLETE		663543
879	06/22/2017	669317 Remove old Green 2016/17 registration Label and/ or Blue EF	Complete	663666
879	06/22/2017	669317 Consumables		663666
879	06/22/2017	669265 Consumables		663273
879	06/20/2017	667659 Drv entered - Suspension Knee/ Raise	checked operation of suspension . could not fault	663379
879	06/20/2017	667455 Consumables		663273
879	06/20/2017	667455 Mechanic entered - Elec and Light Other throttle cutting off	removed the driver's floor vynal foot valve and the accel pedal with plate. replaced with new part. fitted foot valve vynal and tubes. checked with SD2. Throttle value is moving from 0-100% and arm is also moving from stop to the end stop. road tested ok. need to be observed.	663379
879	06/20/2017	668361 Consumables		663379
879	06/20/2017	667659 Consumables		663273
879	06/20/2017	667659 Body FRONT DOOR GETTING STUCK WHEN OPENING HAVING TO PRESS T	adjusted frt and rear door pressure as the main at 6bar and the door reg at 4bar. tested; doing ok. to be further checed.	663273
879	06/20/2017	667659 Drv entered - Body Front_Door Operation Faulty		663273
879	06/20/2017	667659 Body Front_Door Operation Faulty DOOR NOT ALWAYS OPENING		663273
879	06/20/2017	668361 Body seat has air leak seems like a jose is damaged	checked operation of drivers seat and checked for air leaks .all ok	663273
879	06/19/2017	637830 Consumables		641410
879	06/19/2017	637830 Mechanic entered - Body Other front window shade not working	reconnected and adjusted window shade. checked operation all ok	662842
879	06/16/2017	666649 FILTER AIR FILTER		663273
879	06/16/2017	667547 1742784 THROTTLE PEDAL COMPLET	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O195906 Receiving #:203005 Date :2017-06-20	662842
879	06/16/2017	667779 HOSE TRANSMISSION COOLING HOSE		662842
879	06/16/2017	667779 Mechanic entered - Fluid Leaks Rear of bus coolant	traced and found coolant hose u/s up from trans cooler . R&R hose . filled with coolant . road tested . rechecked for leaks all ok	662842
879	06/16/2017	667779 HOSE TRANSMISSION COOLING HOSE		663173
879	06/16/2017	666649 Consumables		662842
879	06/16/2017	666649 SWITCH HAZARD 4 SERIES 1327015		662842
879	06/15/2017	667547 Engine lacking power	job was done on WO667455	662842
879	06/15/2017	667455 Mechanic entered - Elec and Light Other throttle cutting off	connected sd2 and found code 24 for throttle faults. throttle voltage is sticking at or above 0.47V after pedal released. replaced throttle sensor and checked still the same. suspect linkage bushes. need to remove and check.	662842
879	06/15/2017	667455 SENSOR THROTTLE PEDAL		662842
879	06/15/2017	667659 Body FRONT DOOR GETTING STUCK WHEN OPENING HAVING TO PRESS T	checked the air pressure solenoid park brake and foot brake signals. only frt door needs a couple or more to press switch to open. closing with alarm on. disconnected a white wire from door brake interlock switch; road tested doors working fine. need Ben Were to have a look	664903
879	06/09/2017	666649 FILTER AIR FILTER		664903
879	06/09/2017	666649 FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF2506	checked engine powercheck intercoolerpipehose ok found air filter replaced air filter	662424
879	06/09/2017	666649 Drv entered - Engine Low Power	replaced hazard switch ok	662424
879	06/09/2017	666649 Drv entered - Dash Dash_Lights Not Working	rosd tested ok no foot brake noisy ok	662424
879	06/09/2017	666649 Drv entered - Brakes Foot_Brakes Noisy	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	660841
879	06/05/2017	665703	VEHICLE SAFETY INSPECTION done tension wheel nuts road/brake test ok	660841
879	06/05/2017	665703		660841
879	06/05/2017	665793 BUSH SWAY BAR FRONT SCANIA K SERIES (1880751)		660841
879	06/05/2017	665793 BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)		660841
879	06/05/2017	665793 Mechanic entered - Suspension Other front/rear sway bar bush	r/r front/rear sway bar bushers	661992
879	06/05/2017	665703 Consumables		661992
879	06/05/2017	665703 Consumables		661992
879	06/05/2017	665703 Consumables		660841
879	06/05/2017	665703	CARRY OUT B SERVICE AS PER CHECK LIST done	660841
879	06/05/2017	665703 O-RING SPINNER FILTER SCANIA K230 (40A7718) FROM ENG#6203050		660841
879	06/05/2017	665703 FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		660841
879	06/05/2017	665703 FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		660841
879	06/05/2017	665703 FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)		660841
879	06/05/2017	665703 O-RING SPINNER FILTER SCANIA (1769798)		661992
879	06/05/2017	665703 Consumables		661992
879	06/05/2017	665703 Consumables		661992
879	06/05/2017	665703 Consumables		660841
879	06/05/2017	665703		661916
879	06/04/2017	664367 Consumables	carried out campaign as required	660841
879	06/04/2017	664367 Fit A3 Poster/Hangers	road tested bus could not fault warning light on dash	661589
879	06/03/2017	665567 Drv entered - Warning Lights Engine	replaced cracked fuel tank with a new one. road tested no leak found. all ok	661152
879	05/30/2017	663205 diesel leaks at fuel tank	assisted cdf to replace cracked fuel tank with a new one. road tested no leak found. all ok	661152
879	05/30/2017	663205 diesel leaks at fuel tank	replace old batterys with new. all ok	660841
879	05/30/2017	664567 Mechanic entered - Elec and Light Other batterys not holding		661152
879	05/30/2017	664567 Consumables		660841
879	05/30/2017	664567 BATTERY 12V 800CC		661589
879	05/30/2017	664328 Replaced pipe	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O194817 Receiving #:202040 Date :2017-06-02	660841
879	05/30/2017	664328 Air System Air_Leak Rear	Replaced oil collector and checked ok	660841
879	05/29/2017	663205 300LT FUEL TANK KIT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O194400-CR Receiving #:201524 Date :2017-05-29 INCORRECT ITEM	660841
879	05/29/2017	663205 FUEL TANK KIT	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O194400-1 Receiving #:201525 Date :2017-05-29	660841
879	05/29/2017	663842 OIL COLLECTOR AIR DRIER -SCANIA 40G0006		660636

879 05/27/2017	663842	Mechanic entered - Air System Other Air leaking from oil se	ordered	660636
879 05/26/2017	663205	IDLER PULLEY SCANIA ARTIC (No Groove Plastic)		660636
879 05/26/2017	663205	SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		660636
879 05/26/2017	663205	Mechanic entered - Engine Belts_Loose Noisy Missing Engine i	Check the stocks. R&R engine idler pully.	660636
879 05/26/2017	663205	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		660636
879 05/26/2017	663205	Mechanic entered - Engine Belts_Loose Noisy Missing Engine d	R&R engine drive belt.	660636
879 05/26/2017	663631		Assisting	660636
879 05/26/2017	663631		CARRY OUT A SERVICE AS PER CHECK LIST Carried out service A as per check list. Wheel nut torqued to 650Nm. Washed and road tested. All ok.	660636
879 05/26/2017	663631	Consumables		660943
879 05/26/2017	663631	Consumables		660943
879 05/26/2017	663631	Consumables		660943
879 05/24/2017	663205	FUEL TANK	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O194400 Receiving #:201355 Date :2017-05-26	660636
879 05/24/2017	663205	diesel leaks at fuel tank	tank has been ordered as the tank came in was wrong	660297
879 05/22/2017	662591	Mechanic entered - Engine Other FLAT BATTS.	JUMP START.	659881
879 05/17/2017	662027	Consumables		659711
879 05/17/2017	662027	LAMP FLUORESCENT TUBE 18W		659504
879 05/17/2017	662027	Mechanic entered - Elec and Light Interior Lights step light	found that fluoro tube was blown. replased fluoro and tested operation. all ok	659504
879 05/10/2017	660514	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required	658657
879 05/08/2017	659908	Mechanic entered - Engine Other flat batts.	jump start.	658054
879 04/27/2017	655125	VALVE FOOTBRAKE SR3 & SR4 SC 0469052		656586
879 04/27/2017	655125	VALVE BRAKE L94 (40G0103)		656586
879 04/26/2017	657818	Consumables		656586
879 04/26/2017	657818	Elec and Light -rectify n/s headlamp not working as required		656243
879 04/24/2017	657620	Consumables		656243
879 04/24/2017	657620	Drv entered - Elec and Light Interior Lights	replaced a fluoro	656243
879 04/24/2017	657620	LAMP FLUORESCENT TUBE 18W		656243
879 04/18/2017	656495	Mechanic entered - Engine Other WONT START.	JUMP START.	655093
879 04/12/2017	656105	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O191621 Receiving #:198335 Date :2017-04-12	654794
879 04/12/2017	656105		ANNUAL SAFETY INSPECTION SERIAL # 263831	654794
879 04/12/2017	656105		PRE ANNUAL SAFETY INSPECTION CHECK	654414
879 04/10/2017	655699	Drv entered - Engine Low Power	repair carried out on work order - 655125	653710
879 04/06/2017	655125	VALVE BRAKE L94 (40G0103)		653710
879 04/06/2017	655125	Engine looses power	r/r brake valve.need fit hose & road test.	653710
879 04/06/2017	655125	Engine looses power	checked and suspect foot valve electrical fault. drilled a hole on foot valve and adjusted retarder potentiometer.	652620
879 03/30/2017	653164	Mechanic entered - Gearbox Driveline Other diff pluge u/s	fitted diff plug	652620
879 03/30/2017	653164	Mechanic entered - Elec and Light Other master switch u/s	fitted master switch	652620
879 03/28/2017	653164	Mechanic entered - Engine Other flat batts.	jump start.	652620
879 03/28/2017	653096	0463565 BATTERY MASTER SWITCH	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O190360 Receiving #:197078 Date :2017-03-29	652620
879 03/27/2017	653050	BRAKE BOOSTER REAR OUTER SIDE SCANIA L94 (40G2511W)		652620
879 03/27/2017	653050		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	652620
879 03/27/2017	653164	Mechanic entered - A/C Heating Other a/c err	VEHICLE SAFETY INSPECTION	652620
879 03/27/2017	653117	PLUG MAGNETIC (40F0003)	fixed a/c wires ok	652620
879 03/27/2017	653117	diff plug u/s	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O190354 Receiving #:196907 Date :2017-03-27	652620
879 03/27/2017	653117	2001228 DIFF PLUG WASHER	R&R diff plug	652620
879 03/27/2017	653096	battery master switch u/s - bus wont start	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O190354 Receiving #:196907 Date :2017-03-27	652620
879 03/27/2017	653164	GLOBE & HOLDER 1.2W GREY (966327-9) [BOX 10]	R&R battery master switch checked operation all ok	652620
879 03/27/2017	653164	Mechanic entered - Elec and Light Other speedo light globe n		652620
879 03/27/2017	653164	Mechanic entered - Elec and Light Other rpm light globe not	replaced speedo light globe ok	652620
879 03/27/2017	653164	Consumables	replaced rpm light globe ok	652620
879 03/27/2017	653164	Mechanic entered - Body Other driver sun blind broken	fixed driver sun blind ok	652620
879 03/27/2017	653164	Mechanic entered - Body Other rear modesty panel loose	repaired rear modesty panel ok	652620
879 03/27/2017	653164	Mechanic entered - Brakes Other n/s/r braaqe booster u/s	replaced n/s/r brake booster ok	652620
879 03/20/2017	651797	LABEL STEP LIGHT 8x25mm WHITE/BLACK		650705
879 03/20/2017	651797	LABEL HAZARDS 8x25mm WHITE/BLACK		650705
879 03/20/2017	651797	LABEL HIGH IDLE 8x25mm WHITE/BLACK		650705
879 03/20/2017	651797	SWF SWITCH LABEL MASTER WHITE ON YELLOW 14x14mm		650705
879 03/20/2017	651797	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	carried out campaign as required	650705
879 03/20/2017	651797	LABEL HAZARDS 8x25mm WHITE/BLACK		650705
879 03/20/2017	651797	SWF SWITCH LABEL KNEEL WHITE ON YELLOW 14x14mm		650705
879 03/20/2017	651797	LABEL LOWER/RAISE 8x25mm WHITE/BLACK		650705
879 03/18/2017	651578		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	650705
879 03/16/2017	651114	Consumables		651573
879 03/16/2017	651114	Consumables		651573
879 03/16/2017	651114	Consumables		651573
879 03/16/2017	651114	Consumables		651573
879 03/16/2017	651114	Consumables		650705
879 03/11/2017	650509	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	651197
879 03/11/2017	650509	Body -no am fm radio in bus	repaired wiring to radio checked operation all ok	650705
879 03/01/2017	648419	AIR CONDITIONING REPAIR	Creditor #:VB-COLO04 COLD DRIVE PTY LTD P/O #:O188556 Receiving #:195717 Date :2017-03-09 carry out 12 month service as required	650705
879 02/28/2017	648419	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703		649380
879 02/28/2017	648419		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O188556 - cold drive	649380
879 02/26/2017	647166	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	Campaign completed.	648567
879 02/25/2017	647088	Please remove any old poster and fit either Good News for T	Campaign completed.	648567
879 02/20/2017	646019	Consumables		648363
879 02/20/2017	646019	Mechanic entered - Elec and Light Exterior Lights osf indica	fabricated a plate and secured the light.	647738
879 02/16/2017	645127	Consumables		647738
879 02/16/2017	645127	bus requires new batterys	load tested and checked condition of both batterys . all ok	647402
879 02/13/2017	640328	Suspension - all 3 V rod bushes u/s	reinstalled V rod into bus . road tested ok	646934
879 02/13/2017	644510	Consumables		647177
879 02/13/2017	644510	bus needs jump start	jump started bus . checked operation of starting system . all ok	646934
879 02/11/2017	640328	Suspension - all 3 V rod bushes u/s	oxy acelylene gas useing removed V rod	646934
879 02/01/2017	640328	Suspension - all 3 V rod bushes u/s	ordered	643396
879 02/01/2017	637833	Mechanic entered - Body Other front window shade not working	R&R drivers front sunblind	641410
879 01/24/2017	640537	Wheels and Tyres - carry out o/s/r retorque as required	carried out reotorque as required	643396
879 01/23/2017	640252		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS carried out vehicle safety insepction as required. No faults found. Normal operation.	643396
879 01/23/2017	640252		VEHICLE SAFETY INSPECTION	643396
879 01/23/2017	640252	VALVE EXTENSION-130mm Metal type		643396
879 01/23/2017	640252	TYRE 295/80R22.5 RECAP		643396
879 01/23/2017	640252	Mechanic entered - Wheels and Tyres Worn o/s/r tires worn	replaced worn tires with new recaps. torqued to spec. all ok carried out vehicle satety inspection as required. no fault found. all noromal operation.	643396
879 01/23/2017	640328	40Y3318ZF TORQUE ROD BUSH	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O186027 Receiving #:192334 Date :2017-01-25	643959
879 01/23/2017	640252	PULLEY IDLER SCANIA		643396
879 01/23/2017	640252	Mechanic entered - Engine Other engine idler pully bearing w	removed old pully and replaced with new. all ok	643396

879	01/23/2017	640252	Consumables			643959
879	01/23/2017	640252	REFLECTOR AMBER (84051)			643396
879	01/23/2017	640252	Mechanic entered - Body Other amber reflecter missing	fit new reflecter to replace the missing one		643396
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Mechanic entered - Elec and Light Exterior Lights n/s/f park	r/r globeok.		642652
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Mechanic entered - Body Other side panel hanging down in bus	fixed for panelok.		642652
879	01/17/2017	639290	Mechanic entered - Body Passenger Seat Torn at front	done could not fault.		642652
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290		CARRY OUT B SERVICE AS PER CHECK LIST a b service tension wheel nuts & road testok.		642652
879	01/17/2017	639290		CARRY OUT B SERVICE AS PER CHECK LIST done		642652
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290	Consumables			642941
879	01/17/2017	639290		CARRY OUT A SERVICE AS PER CHECK LIST done		642652
879	01/17/2017	639290		CARRY OUT A SERVICE AS PER CHECK LIST done		642652
879	01/13/2017	638749		TRANSMISSION CHECK AS PER CHECK LIST		641410
879	01/13/2017	637833	Direct Purchase - BODYWORK	Creditor #:-VB-CUS001 CUSTOM CARE P/O #:-O185281 Receiving #:192774 Date :2017-01-31		644840
879	01/12/2017	575893	SEAL REAR HUB OUTER SR 3 & 4 SCANIA 1765061			641410
879	01/11/2017	638228	Consumables			642128
879	01/11/2017	638228	Mechanic entered - Elec and Light Horn is very quiet	replaced horn checked operation ok		641410
879	01/11/2017	638228	Mechanic entered - Elec and Light Warning Light On Dash che	road tested bus . could not fault warning light on dash		641410
879	01/08/2017	636778	Fit New 2107 Large and Small Fares Small Concessionand AO	camapign complete		639642
879	01/05/2017	636778	DECAL AUTHORISED OFFICER			639642
879	01/05/2017	636778	DECAL 2017 PTV DECAL CONCESSION CARD TYPE 300x150mm			639642
879	01/05/2017	636778	DECAL 2017 PTV METRO MYKI DECAL SMALL 300x150mm			639642
879	12/23/2016	635082	GLOBE 24V 75/70W H4			638455
879	12/23/2016	635082	Elec and Light -drivers headlight globe not working	replace globe		638455
879	12/23/2016	582213	Consumables			639642
879	12/23/2016	582213	Consumables			639642
879	12/23/2016	582213	Consumables			639642
879	12/23/2016	582213	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)			638455
879	12/23/2016	582213	FILTER AIR DRYER SCANIA SR4 (1393551) (49G8709HALDEX)			638455
879	12/22/2016	634960	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		638455
879	12/19/2016	634237	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		638455
879	12/14/2016	633526	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		637556
879	12/12/2016	632800	Wheels and Tyres - carry out front retorque as required	carried out front retorque as required		636901
879	12/12/2016	496779	SCANIA DIP STICK L94UAB			636901
879	12/12/2016	496779	DIPSTICK SCANIA			636901
879	12/10/2016	630129	tie rod us	removed tyres replaced tie rodadjusted toe ininstalled tyrestightened toque wheel nuts road tested all ok		636901
879	12/10/2016	630253	Mechanic entered - A/C Heating Other A/C compressor bracket	removed a/c mounts replaced a/c moujts allok		636901
879	12/07/2016	631964	Consumables			636731
879	12/07/2016	631964	Mechanic entered - Body Passenger Seat Torn at front	double entry entered in by fleet support		635905
879	12/05/2016	630129	DIRECT PURCHASE - CHASSIS	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:-O182446 Receiving #:189406 Date :2016-12-08 2082755 NUTS		636731
879	12/05/2016	630129	DIRECT PURCHASE - CHASSIS	Creditor #:-VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:-O182446 Receiving #:189406 Date :2016-12-08 2146105 TIE ROD COMPLETE		636731
879	12/03/2016	631436	Engine -engine light malfunction coming up on the dash	road tested . bus could not fault engine light		635905
879	12/03/2016	631436	Mechanic entered - Elec and Light Exterior Lights n/s front	replaced globe checked operation ok		635905
879	12/01/2016	629908	TYRE 295/80R22.5 NEW			635409
879	12/01/2016	630129	tie rod us	reported by airanywhere ordered parts		634937
879	12/01/2016	630253	Mount A/C Large			634937
879	12/01/2016	630253	Mechanic entered - A/C Heating Other A/C compressor bracket	r/r two large comp mounts & two at rear on order		634937
879	12/01/2016	630253	Mechanic entered - A/C Heating Other A/C compressor bracket	replaced a/c mounts x2		634937
879	11/28/2016	629908	Direct Purchase - TYRES	Creditor #:-VB-TYR002 TYRES4U P/O #:-O182311 Receiving #:188570 Date :2016-11-28 NR - BALANCE STEER TYRES		635165
879	11/28/2016	629908	Direct Purchase - TYRES	Creditor #:-VB-TYR002 TYRES4U P/O #:-O182311 Receiving #:188570 Date :2016-11-28 29580NR22.5N		635165
879	11/28/2016	629948	Direct Purchase - MECHANICAL	Creditor #:-VB-AIR001 AIR ANYWHERE P/O #:-O182300 Receiving #:-188863 Date :2016-12-01 carry out wheel alignment and balance as required		635639
879	11/28/2016	630253	Mount A/C Small	Creditor #:-VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:-O182441 Receiving #:188865 Date :2016-12-01		635639
879	11/28/2016	630199	no battery pwr	CALLED BEN AND GOT FIXED. FITTED NEW CONTROL UNIT		634937
879	11/28/2016	630199	no battery pwr	checked and found CB34 popped. cannot reset and found ROLL AWAY CONTROL DEVICE related fault. need Ben Were to check		634937
879	11/26/2016	630066	Mechanic entered - Wheels and Tyres Wheel Nut Retension reto	retensioned both frt wheels nuts as per specs		634937
879	11/25/2016	629908	Mechanic entered - Wheels and Tyres Worn need frt tyres to b	change both front tyresretorque wheel nuts.		634937
879	11/25/2016	629908	TYRE 295/80R22.5 NEW			634937
879	11/25/2016	629948	Steering - carry out wheel alignment and balance as required	wheel alignment and balance carried out by air anywhere on order - O182300		634937
879	11/22/2016	629258		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		633593
879	11/22/2016	629258		VEHICLE SAFETY INSPECTION safety completed		633593
879	11/15/2016	627748	Consumables			633366
879	11/15/2016	627748	Consumables			633366
879	11/15/2016	627748	Consumables			633366
879	11/15/2016	627748		CARRY OUT A SERVICE AS PER CHECK LIST a service completed		633095
879	11/11/2016	627227	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-BWE001 BWERE ELECTRICS P/O #:-O181176 Receiving #:188826 Date :2016-11-30 carry out wifi round 2 - johnny		635179
879	11/11/2016	627227	Campaign 10/16 WIFI CCTV UPGRADE -Round 2this campiang	wifi round 2 carried out by johnny on order - O181176		633004
879	11/05/2016	625964	A/C Heating air con not working	repaired earth to air con base checked operation of a/c . working ok		632088
879	10/28/2016	624575	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced		631084
879	10/25/2016	623821	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O180085 Receiving #:186756 Date :2016-11-03 rectify a/c not working as required		631593
879	10/25/2016	623821	A/C Heating -demisters not working in the bus	repairs carried out by cold drive O180085		630504
879	10/25/2016	623821	A/C Heating -CLIMATE CONTROL DOES NOT GET ABOVE 11.2	repairs carried out by cold drive O180085		630504
879	10/25/2016	623821	Drv entered - A/C Heating Not Heating	repairs carried out by cold drive O180085		630504
879	10/25/2016	623821	A/C Heating -climate control does not get above 14 degrees	repairs carried out by cold drive O180085		630504
879	10/25/2016	623821	Drv entered - A/C Heating Not Cooling	repairs carried out by cold drive O180085		630504
879	10/20/2016	622973	Campaign 14/16 Destination signs Setting and loadig Files.	carried out campaign as required		630031
879	10/14/2016	620681	Consumables			629412
879	10/14/2016	620681	TYRE 295/80R22.5 RECAP			629130
879	10/13/2016	621692	Consumables			629130
879	10/13/2016	621692	Mechanic entered - Wheels and Tyres Wheel Nut Retension rete	retensioned all wheel nuts as per specs		628866
879	10/13/2016	620681	NR TYRE DISPOSAL	Creditor #:-VB-TYR002 TYRES4U P/O #:-O179010 Receiving #:185387 Date :2016-10-13		629130
879	10/13/2016	620681	295/80R22.5 BANDAG BITUMEN RET	Creditor #:-VB-TYR002 TYRES4U P/O #:-O179010 Receiving #:185387 Date :2016-10-13		629130
879	10/13/2016	621691	Brakes -front near side breaks making alot of noise and heat	checked for retarder; n/w as the switch was turned off. turned the switch on and road tested. rertarder is working good.		628866
879	10/10/2016	620681	DIRECT PURCHASE - BRAKES	Creditor #:-VB-COM100 Commercial Brake & Clutch P/O #:-O179169 Receiving #:185336 Date :2016-10-13 Machine linings and drums		628291
879	10/10/2016	620681	O RING BRAKE SHOE PIVOT 1338019			628291
879	10/10/2016	620681	SNAP RING FRONT+REAR BRAKE SHOE SCANIA 40G7604			628291
879	10/10/2016	620681	Brakes- brakes pulling	r/r drums /brakes ajusted brakes tensioned wheel nuts road test ok		628291
879	10/10/2016	620681	TYRE 295/80R22.5 RECAP			628291

879	10/10/2016	620681	Brakes- brakes pulling	628291
879	10/07/2016	620681	Brakes -noisy brakes and they grab	628291
879	10/07/2016	620681	Brakes- brakes pulling	628291
879	10/06/2016	618750	Direct Purchase - MECHANICAL	628291
879	09/27/2016	618750	Consumables	627339
879	09/27/2016	618750	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	627339
879	09/23/2016	603460	HOSE	626656
879	09/13/2016	605792	receiving #179917	624742
879	09/10/2016	615255		624742
879	09/10/2016	615255		624742
879	09/09/2016	614969	Mechanic entered - Wheels and Tyres Other n/s/f tire has pu	624742
879	09/09/2016	614970	Elec and Light - dash blinker not working and o/s/f indicat	624742
879	09/09/2016	614970	Consumables	625094
879	09/09/2016	614970	GLOBE 24V 21W SINGLE CONTACT (HLR2421)	624742
879	09/09/2016	614970	INDICATOR SIDE INDICATOR R/H	624742
879	09/09/2016	614970	GLOBE DASH	624742
879	09/05/2016	614019	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	623570
879	09/03/2016	613902	Consumables	624251
879	09/03/2016	613902	Consumables	624251
879	09/03/2016	613902	FILTER FUEL SCANIA SR4(H17WK04)	623570
879	09/03/2016	613902	FILTER FUEL FILTER SCANIA L94UAB (H7090WK30)	623570
879	09/03/2016	613902	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	623570
879	09/03/2016	613902	FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1	623570
879	09/03/2016	613902		623570
879	09/03/2016	613902	O-RING LARGE SPINNER FILTER SCANIA (1769799)	623570
879	09/03/2016	613902	O-RING SPINNER FILTER SCANIA (1769798)	623570
879	09/03/2016	613902	Consumables	624251
879	09/03/2016	613902	Consumables	624251
879	09/03/2016	613902		623570
879	09/01/2016	605792	Direct Purchase - MECHANICAL	624965
879	09/01/2016	604485	Consumables	624024
879	09/01/2016	604485	Direct Purchase - BODYWORK	626225
879	08/30/2016	613124	Consumables	623570
879	08/30/2016	613124	Please remove old poster and fit new Legacy poster	623342
879	08/17/2016	610384	Consumables	621313
879	08/17/2016	610384	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	621028
879	08/08/2016	607168	Mechanic entered - Air System Air_Leak Rear n/s/r leak	619875
879	08/05/2016	607168	DECAL NO SMOKING	619684
879	08/05/2016	607168	Mechanic entered - Vandalism Other REAR NO SMOKING STICKER M	619684
879	08/05/2016	608373	SWITCH- STOP-YELLOW	619684
879	08/05/2016	608373	Drv entered - Heat & Demist	619684
879	08/05/2016	608373	Consumables	619875
879	08/05/2016	608373	Drv entered - Elec and Light Next Stop Button	619684
879	08/03/2016	607168	Mechanic entered - Air System Air_Leak Rear n/s/r leak	619200
879	08/02/2016	605792	Direct Purchase - MECHANICAL	620147
879	08/02/2016	605792	Direct Purchase - MECHANICAL	619466
879	08/01/2016	605792	Breakdown#:32697 - Ops Entered - Breakdown - Breakdown Road	618405
879	08/01/2016	607168	Mechanic entered - Air System Air Not Building_Up	619155
879	07/30/2016	605792	Mechanic entered - Air System Air Not Building_Up	619155
879	07/27/2016	605792	Direct Purchase - MECHANICAL	618880
879	07/27/2016	605792	Direct Purchase - MECHANICAL	618880
879	07/27/2016	605792	Direct Purchase - MECHANICAL	618880
879	07/25/2016	605960	Breakdown - Not building air Monash Uni.	618405
879	07/23/2016	605617	AIR DRYER VALVE BLOCK (BLACK)(35clf0155)	618405
879	07/23/2016	605617	FILTER AIR DRYER SCANIA SR4 (1393551)(20546795)	618405
879	07/23/2016	605617	Breakdown#:32696 - Ops Entered - Breakdown - Breakdown Road	618405
879	07/18/2016	604485	Consumables	617329
879	07/18/2016	604485	Mechanic entered - Body Passenger Seat Torn at rear	616468
879	07/17/2016	603150	Consumables	617329
879	07/17/2016	603150	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	616468
879	07/15/2016	604367	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	617329
879	07/12/2016	603460	HOSE	616986
879	07/12/2016	603460	Engine - coolant leak	616986
879	07/12/2016	603307	Consumables	617099
879	07/12/2016	603307	DECAL CUSTOMER ENQUIRY	616986
879	07/12/2016	603307	Replace customer enquiry decal	616986
879	07/06/2016	602322	Consumables	616318
879	07/06/2016	602322	Body-drivers gps console is unplugged	615606
879	07/05/2016	601908	Wipers and Washers -wipers are not working	615606
879	07/01/2016	601224		614752
879	07/01/2016	601224		614752
879	07/01/2016	601224	A/C Heating - climate control not working	614752
879	06/30/2016	600911	Mechanic entered - Body Front_Door Operation Faulty front d	614752
879	06/29/2016	600853	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	614752
879	06/24/2016	600095	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	614374
879	06/23/2016	599602	GLOBE FESTOON 24V 18W	613999
879	06/23/2016	599602	n/s/f top parker not working	613999
879	06/23/2016	599602	Mechanic entered - Elec and Light Exterior Lights n/s top f	613999
879	06/21/2016	599176	GLOBE 24V 4W SINGLE CONTACT	613189
879	06/21/2016	599176	GLOBE 24V 75/70W H4	613189
879	06/21/2016	599176	NS HEAD LIGHT N/WNS TOP FRONT PARK LIGHT NW	613189
879	06/19/2016	598195	Please remove any old poster and fit new A3 poster and add	613189
879	06/16/2016	598306	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	613189
879	06/15/2016	597796		612792
879	06/15/2016	597796	Mechanic entered - A/C Heating Other Damaged Wiring.	612792
879	06/15/2016	597796	Belt tensioner K	612792
879	06/15/2016	597796	Mechanic entered - Engine Belts_Loose Noisy Missing Tensione	612792
879	06/15/2016	597796	Consumables	613189
879	06/15/2016	597796	Consumables	613189
879	06/15/2016	597796	Consumables	613189
879	06/15/2016	597796	Consumables	612792
879	06/15/2016	597796		611390
879	06/01/2016	587086	DIRECT PURCHASE - VANDALISM	611390
879	06/01/2016	587086	Direct Purchase - BODYWORK	611390

			fitted liningsdrumswheels & tension wheel nuts road testok.	
			removed FRONTREAR BRAKE LININGS&DURMS	
			checked brakes noisy	
			Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O178070 Receiving #:184878 Date :2016-10-06 CARRY OUT ROLL OUT CAMPAIGN AS REQUIRED	
			CARRIED OUT BY MARIANO ON ORDER - O178070	
			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	
			VEHICLE SAFETY INSPECTION SAFETY COMPLETED	
			pumped up tire	
			fit dash globe and fit new o/s/f blinker assembly	
			Will be done under round 2 of CCTV upgrades.	

[illegible]

879	02/15/2016	575865	FILTER FUEL SCANIA SR4(H17WK04)		595953
879	02/15/2016	575865	O-RING LARGE SPINNER FILTER SCANIA (1769799)		595953
879	02/15/2016	575865	O-RING SPINNER FILTER SCANIA (1769798)		595953
879	02/15/2016	575865			595953
879	02/13/2016	575865		VEHICLE SAFETY INSPECTION CHECKED BOTTOMTOP	595953
879	02/13/2016	575865		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	595953
879	02/13/2016	575865		CARRY OUT B SERVICE AS PER CHECK LIST	595953
879	02/13/2016	575865	Consumables		596418
879	02/13/2016	575865	Consumables		596418
879	02/13/2016	575865			595953
879	02/12/2016	575645	Engine - when bus goes down into first gear when slowing dow	CARRY OUT A SERVICE AS PER CHECK LIST	595953
879	02/12/2016	575643	Elec and Light - hazards lights do not work they dont work p	CHECK OIL LEVELOKLONG ROAD TESTCOULD NOT FAULT.	595953
879	02/01/2016	514164	Direct Purchase - MECHANICAL	COULD NOT FAULT HAZARD LIGHTS.	595953
879	01/31/2016	572724	Consumables	Creditor #:VB-AIR001 AIR ANYWHERE P/O #:O148988 Receiving #:168527 Date :2016-02-24 Front End Alignment and wheel balance	597495
879	01/31/2016	572724	Consumables		593717
879	01/31/2016	572629	Consumables		593717
879	01/31/2016	572629	Consumables		593717
879	01/31/2016	572724	Camapign 20/15 Audit & Update of Safety Decals.Requires a	carried out campaign as required	593099
879	01/31/2016	572629	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	carried out campaign as required	593099
879	01/29/2016	573126	Consumables		593717
879	01/29/2016	573126	Consumables		593717
879	01/29/2016	573126	Body - HORN NOT WORKING	Horn was touching the body and sounds distorted. repositioned the horn and tested ok.	593099
879	01/20/2016	571157	earth cable has come off a/c compressor	resecured earth cable	591923
879	01/14/2016	569853	GLOBE 24V 21W SINGLE CONTACT HLR2421		591116
879	01/14/2016	569853	saloon lights not working		591116
879	01/03/2016	567501	Consumables	replaced globe	589548
879	01/03/2016	567501	Consumables		589548
879	01/03/2016	567501	Campaign 23_15 A3 Poster Change	carried out campaign as required	588558
879	12/29/2015	567242	GLOBE 24V 75/70W H4 48892		588558
879	12/29/2015	567242	n/s headlight not working	replaced globe	588558
879	12/05/2015	563345	Consumables		585436
879	12/05/2015	563345	re-tension both rear wheel nuts	re-tensioned both rear wheel nuts	585436
879	12/03/2015	563025	Fluid Leaks - leaking coolant	checked inside saloon for roof coolant leaks and also engine coolant leaks . could not faul	585014
879	12/03/2015	563026	Mechanic entered - Air System Air_Leak Rear air leaking fro	checked air system for leaking air . found main compressor pipe needs tighning . tightend . checked for leaks ok	585014
879	12/02/2015	562792		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	585014
879	12/02/2015	562792		VEHICLE SAFETY INSPECTION safety completed	585014
879	12/02/2015	562828	Consumables		585245
879	12/02/2015	562827	Consumables		585245
879	12/02/2015	562828	Mechanic entered - Wheels and Tyres Worn o/s/r tyres - u/s	replaced tyres. torque wheel nuts. replaced links. - double entry	585014
879	12/02/2015	562827	TYRE RECAP 295/80R22.5		585014
879	12/02/2015	562827	Mechanic entered - Wheels and Tyres Flat or Leaking n/s/r in	replaced tyre. refit links. torque wheel nuts.	585014
879	12/02/2015	562829	Mechanic entered - Fluid Leaks Rear of bus coolant leak from	rectify coolant leaking from header tank hoses and boost pump hose clamps.	585014
879	12/02/2015	562574	Consumables		585245
879	12/02/2015	562574	Consumables		585245
879	12/02/2015	562574	Body - near side vision mirror or an angle	adjusted mirror arm bracket	585014
879	12/02/2015	562792	Consumables		585245
879	12/02/2015	562792	Consumables		585245
879	12/02/2015	562792	Consumables		585245
879	12/02/2015	562792			585245
879	11/25/2015	551480	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	CARRY OUT A SERVICE AS PER CHECK LIST a service completed	585014
879	11/25/2015	551480	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	Line added to cancel out Line 50	575774
879	11/25/2015	551480	Consumables	Line added to replace Line 50 with the correct P/N used on the Work Order	575774
879	11/25/2015	551480	Consumables		584435
879	11/25/2015	551480	Consumables		584435
879	11/24/2015	560721	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O158485 Receiving #:164429 Date :2015-12-02 carry out AC-B service as required	585014
879	11/24/2015	560721	CARRY OUT A/C - B SERVICE AS PER CHECK LIS	CARRIED OUT A/C - B SERVICE BY COLD DRIVE ON 24/11/2015 PO O158485	583955
879	11/24/2015	560769	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	AC B DONE BY COLD DRIVE ON 24/11/2015 PO O158485	583955
879	11/23/2015	560412	Remove Old Poster and Fit new All Night Public Transport Po	carried out campaign as required	583672
879	11/23/2015	560412	Consumables		584105
879	11/12/2015	558305	Wheels and Tyres - n/s/r retorque	carried out retorque as required	581322
879	11/12/2015	558305	Consumables		582008
879	11/11/2015	558083	Body - near side rear outer tyre scrub on side wall showing	change tyre. tensioned wheels nuts	581322
879	11/11/2015	558083	Consumables		581776
879	11/07/2015	557479	BATTERY 12V 800CC		580956
879	11/07/2015	557479	Mechanic entered - Elec and Light Other battery u/s.	replaced BATTERYS X2	580956
879	11/06/2015	557380		TRANSMISSION CHECK AS PER CHECK LIST	580956
879	10/27/2015	555627	Elec and Light AM-FM Radio is not working (no Power)	checked operation of am/fm radio . could not fault	579235
879	10/26/2015	555266	Mechanic entered - Engine Other flat batts	jump start.	578420
879	10/25/2015	554679	Complete task as instructed in Fleet Campaign 09/15	carried out campaign as required	578420
879	10/16/2015	553376	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O156971 Receiving #:162611 Date :2015-10-21 over haul drivers seat as required	578420
879	10/15/2015	553376	Body - the driver seat back support must be fixed looks lik	replaced drivers seat . drivers seat was sent away to be overhauled on order number - O156971	576954
879	10/11/2015	551890	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	carried out campaign as required	575774
879	10/11/2015	551882	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	carried out campaign as required	575774
879	10/07/2015	551480	Checklink Wheel Nut 33mm		575774
879	10/07/2015	551480		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	575774
879	10/07/2015	551480		VEHICLE SAFETY INSPECTION	575774
879	10/07/2015	551586	Consumables		575993
879	10/07/2015	551586	TYRE NEW 295/80R22.5		575774
879	10/07/2015	551586	nsf tyre us	fitted tyre	575774
879	10/07/2015	551586	Hand pump		575774
879	10/07/2015	551586	fuel hand pump leaking	fitted hand pump	575774
879	10/07/2015	551586	rear step light globe out	fitted globe	575774
879	10/07/2015	551586	GLOBE 24V 10W S/C		575774
879	10/07/2015	551460	GLOBE 24V 21W SINGLE CONTACT HLR2421		575774
879	10/07/2015	551460	Elec and LightNS Front side indicator not working	fitted a globe	575774
879	10/07/2015	551586	rear brakes hose fitting air leak	tightened rear brake hose fitting.	575774
879	10/07/2015	551586	frt both boosters air leak	tightened front bothside brake booster clamps.	575774
879	10/07/2015	551480	Consumables		575993
879	10/07/2015	551480	Consumables		575993
879	10/07/2015	551480	Consumables		575993
879	10/07/2015	551480	FILTER FUEL SCANIA SR4(H17WK04)		575774
879	10/07/2015	551480	FILTER FUEL SCANIA L94UAB (H7090WK30)		575774
879	10/07/2015	551480	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)		575774
879	10/07/2015	551480	O-RING LARGE SPINNER FILTER SCANIA (1769799)		575774

879	10/07/2015	551480	O-RING SPINNER FILTER SCANIA (1769798)		575774
879	10/07/2015	551480	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		575774
879	10/07/2015	551480		B SERVICE AS PER CHECK LIST	575774
879	10/07/2015	551480	Consumables		575993
879	10/07/2015	551480	Consumables		575993
879	10/07/2015	551480		A SERVICE AS PER CHECK LIST	575774
879	10/07/2015	551480	Consumables		575993
879	10/04/2015	550057	Replace A3 poster with Victorian Seniors Festival Poster	Completed 29/09/15	574354
879	10/04/2015	550056	Replace A3 poster with Victorian Seniors Festival Poster	carry out campaign as required	574354
879	09/25/2015	548980	Body - The back of the drivers seat needs to be fixed. Appe	adjusted mechismisen back rest lock . now working ok	573560
879	09/13/2015	546510	Audit Route buses for correct Decals and positions. Replace	carried out campaign as required	570634
879	08/22/2015	542929	Elec and Light AM-FM Radio not working.	no pwr to the radio. need to re-book	565440
879	08/22/2015	542929	CCTV (None) - not recording at all	no interface for this newly installed thoreb unit	565440
879	08/22/2015	542115	Consumables		565760
879	08/22/2015	542115	Body - drivers seat weight suspension dial sticks and jams	removed and fitted driver's seat assy	564959
879	08/21/2015	542115	SEAT ASSY ISRI 6008 AIR LUMBA	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O154774 Receiving #:160285 Date :2015-08-21	565760
879	08/20/2015	542115	Body - drivers seat does not raise high enough to provide a		564959
879	08/20/2015	542115	Body- driver seat lower lumbar not working		564959
879	08/15/2015	539838	Steering - n/s tie rod end u/s	replaced n/s tie rod end. adjust and checked wheel alignment - ok.	564273
879	08/15/2015	541262	A/C Heating no power to climate control.	removed batterys terminal to reset air due to bus having low voltage at one point . maybe flat batterys	564273
879	08/14/2015	539838	BALL JOINT	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O154560 Receiving #:160006 Date :2015-08-14 MM 49L1214	564273
879	08/10/2015	540067	Engine wont start	jump start bus	562387
879	08/09/2015	539591	Consumables		563216
879	08/09/2015	539591	Complete Campaign 6/15 A3 Marketing Poster Change	carried out campaign as required	562387
879	08/07/2015	539785		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	562576
879	08/07/2015	539785		VEHICLE SAFETY INSPECTION	562576
879	08/07/2015	539838	FITTING		562576
879	08/07/2015	539838	AIR SPRING FRONT SCANIA L94 K'SR SP0002A 35CMG0250HD		562576
879	08/07/2015	539838	AIR SPRING REAR SCANIA L94 K'SR SP0003A 35CMG0252HD		562576
879	08/07/2015	539838	Suspension - n/s/r/f air bag leaking	replaced n/s/r front airbag. refit mug guard. secured airlines with cable ties.	562576
879	08/07/2015	539838	both front airbags leaking	replaced n/s and o/s front airbag. replaced air fittings and air hose.	562576
879	08/07/2015	539838	air filter u/s	replaced air filter	562576
879	08/07/2015	539838	air filter u/s		562576
879	08/07/2015	539838	GLOBE 24V 2W 2663		562576
879	08/07/2015	539838	STOP BUTTON FLAT		562576
879	08/07/2015	539838	FILTER AIR OUTER SCANIA SR3 SR4 (395773)(0395773)		562576
879	08/07/2015	539838	front pax stop bell button n/w	replaced pax stop bell button	562576
879	08/07/2015	539838	o/s/f park light n/w	replaced globe	562576
879	08/07/2015	539838	front pax stop bell button n/w	replaced pax bell x 1.	562576
879	08/07/2015	539838	o/s/f park light n/w		562576
879	08/07/2015	539838	Consumables		562925
879	08/07/2015	539838	air dryer bracket bolt missing	refit bolt nut and spring washer. secured air drier frame bracket.	562576
879	08/07/2015	539838	o/s/r side hatch lock u/s	fabricate plate and drill to align hatch lock. checked for operation - ok.	562576
879	08/07/2015	539785	Consumables		562925
879	08/07/2015	539785	Consumables		562925
879	08/07/2015	539785		A SERVICE AS PER CHECK LIST	562576
879	08/01/2015	533488	AIR PRESSURE SWITCH 16BAR	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01	561784
879	08/01/2015	533488	VALVE RELAY REAR SCANIA L94U	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01	561784
879	08/01/2015	533488	VALVE FOUR WAY SCANIA	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01	561784
879	07/18/2015	536343	A/C Heating Not Heating - No air coming out of vents.	repaired broken a/c compressor earth wire. road test. heaters now working	557891
879	07/17/2015	536163	Elec and Light Interior Lights - 3 rear saloon lights not	check saloon lights operation found driver was not using switch for rear lights he was only using the front saloon light switch their is too switches	557891
879	07/13/2015	535301	Mechanic entered - Engine Other wont start.	could not fault.	556973
879	07/11/2015	535233	GLOBE 24V 2W 2663		556973
879	07/11/2015	535233	GLOBE 24V 75/70W H4		556973
879	07/11/2015	535233	Drv entered - Elec and Light Exterior Lights	double entry/disregard	556973
879	07/11/2015	535233	Elec and Light Exterior Lights - OFFSIDE HEADLIGHT IS OUT	fitted os head light globe and park light globe	556973
879	07/02/2015	533488	Dash Guages Not Working - pressue gauge number 2 always co	FIT NEW RELAY AND 4WAY PROTECTION VALVES.	554671
879	07/02/2015	533488	Body Front_Door Operation Faulty - keeps getting stuck	fit reed switch front door front leaf and wire in . doors now operating ok . pti bus.	554671
879	07/02/2015	533488	Brakes Warning Light On - hand brake lights on dash board	FIT HANDBRAKE AIR SWITCH.	554671
879	07/02/2015	533488	Mechanic entered - Air System Warning Light On front door no	FIT NEW REED SWITCH TO F/DOOR R/LEAF.	554671
879	07/01/2015	533488	Dash Guages Not Working - pressue gauge number 2 always c	tracefound relay and 4 way protection valves u/sremoveorder new.	554671
879	07/01/2015	533488	Body Front_Door Operation Faulty - keeps getting stuck		554671
879	07/01/2015	533488	Mechanic entered - Air System Warning Light On front door no	trace wiringfound reed switch u/s. order part.	554671
879	06/30/2015	533488	Brakes Warning Light On - hand brake lights on dash board	warning light pressure switch u/s order new switch.	554671
879	06/30/2015	533488	Mechanic entered - Air System Warning Light On front door no	isolate door brakes. parked on sickbay. requires further check.	554671
879	06/27/2015	529596	frt D rubbers us	replaced front 'D' rubbers.	554671
879	06/26/2015	529596	BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010		554671
879	06/22/2015	529596	Mechanic entered - Elec and Light Other	carried out pti	552764
879	06/22/2015	531935	Brakes - Brakes are very sharp (Sensitive)	found retarder was turned off. turned backo;road tested brakes ok.	552764
879	06/22/2015	531935	Air System - After lowing the bus takes a long time to rais	checked air bags for leaks; could not locate a leak. no faults found during road test.	552764
879	06/19/2015	531935	Elec and Light Next Stop Button - Some next stop buttons	Repaired two pax stop switches and re-fitted	552764
879	06/19/2015	531935	SEATBELT TO SUIT 6008 SEAT		552764
879	06/19/2015	531935	BodySeat belt not working it locks	fitted a seat belt	552764
879	06/19/2015	531935	Body - Driver seat base cushioin and shockers worn off. Sho	fitted a driver's seat supplied	552764
879	06/19/2015	531935	Brakes - Brakes are very sharp (Sensitive)	noisy brakes but not bad. retarder not working.	552764
879	06/19/2015	531935	Noisy Brakes and grabbing	road test and brake test. front and rear brakes noisy but not bad. retarder not working.	552764
879	06/19/2015	531935	Noisy Brakes and grabbing	adjusted frt and rear brakes; feel retarder n/w. need re-booking	552764
879	06/19/2015	529596	Mechanic entered - Air System Air Not Building_Up air compre	refit air compressor hose line.	552764
879	06/09/2015	530012	Air System won'y raise or lower and loses air pressure.	due to lack of air pressure	551011
879	06/09/2015	530012	Air System - Bus losing air air gauges dropped below six.	repaired signal line to compressor . road tested . now building to correct pressure	551011
879	06/04/2015	529527		TRANSMISSION CHECK AS PER CHECK LIST	550704
879	06/04/2015	529527		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	550704
879	06/04/2015	529527		VEHICLE SAFETY INSPECTION	550704
879	06/04/2015	529596	frt D rubbers us		550704
879	06/04/2015	529596	'GIVE WAY' DECAL 240MM X 225MM	Repaired the cut wire at ac compressor	550704
879	06/04/2015	529596	A/C compressor earth wire cut		550704
879	06/04/2015	529596	Hose 10mm silicone per cm.		550704
879	06/04/2015	529596	Engine coolant leak	replaced coolant hose. replaced hose clamps. top up coolant and checked for leak.	550704
879	06/04/2015	529596	GLOBE 24V 21W SINGLE CONTACT		550704
879	06/04/2015	529596	LENS TO SUIT 2402/03/43		550704
879	06/04/2015	529596	rev/light lens cracked	replaced 2 reverse lens and globes.	550704
879	06/04/2015	529596	give way decal us	replaced decal.	550704
879	06/04/2015	529527	Consumables		551011

879	06/04/2015	529527	Consumables			551011
879	06/04/2015	529527	Consumables			551011
879	06/04/2015	529527		B SERVICE AS PER CHECK LIST		550704
879	06/04/2015	529527	FILTER FUEL SCANIA K SERIES EURO4 E57KPD73			550704
879	06/04/2015	529527	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)			550704
879	06/04/2015	529527	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			550704
879	06/04/2015	529527	FILTER FUEL SCANIA L94UAB (H7090WK30)			550704
879	06/04/2015	529527	O-RING LARGE SPINNER FILTER SCANIA (1769799)			550704
879	06/04/2015	529527	O-RING SPINNER FILTER SCANIA (1769798)			550704
879	06/04/2015	529527	Consumables			551011
879	06/04/2015	529527	Consumables			551011
879	06/04/2015	529527	Consumables			551011
879	06/04/2015	529527		A SERVICE AS PER CHECK LIST		550704
879	05/27/2015	524788	Washer	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:156039 Date :2015-05-27		548619
879	05/19/2015	526714	STOP/TAIL LAMP			546862
879	05/19/2015	526714	Elec and Light - O/S top tail light not working	replaced stop/tail LED		546862
879	05/09/2015	525314	Consumables			545140
879	05/09/2015	525314	Wheels and Tyres - full retorque on all wheels	carried out retorque		545027
879	05/09/2015	524788	Bearing Front Wheel Series 4	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:155086 Date :2015-05-09		545140
879	05/08/2015	524788	Direct Purchase - MECHANICAL	Creditor #:\VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:O151197 Receiving #:155255 Date :2015-05-13 radius grind brakes and machine drums as required		545140
879	05/08/2015	524788	brakes noisy	fit front and wheels adjust all brakes . road test brake test - ok . torque all wheels nuts all around		545027
879	05/07/2015	524788	TYRE RECAP 295/80R22.5			545027
879	05/07/2015	524788	Drum Scania 8 inch			545027
879	05/07/2015	524788	BRAKE RETURN SPRING (1309465)			545027
879	05/07/2015	524788	Brakes noisy	refit new front wheel bearings. refit new front drums. refit new rear drums. replaced o/s rear tyres. prepared front brakes for relining.		545027
879	05/06/2015	524788	Lining Scania 8 inch			545027
879	05/06/2015	524788	BRAKE DRUM			545027
879	05/06/2015	524788	LOCK RING BRAK SHOE PIN 0804782			545027
879	05/06/2015	524788	O RING			545027
879	05/06/2015	524788	10 BRAKE LINNING ASB FREE			545027
879	05/06/2015	524788	Brakes noisy	road test. front and rear brakes noisy. removed front wheel hub and rear drums and brake linings. refit new front and rear brake linings. refit rear drums. front wheel hub and drums to replaced then send for machining.		545027
879	05/05/2015	524489		reyorque both rear wheel nuts.		544649
879	05/01/2015	524079	Consumables			544352
879	05/01/2015	524079	Wheels and Tyres - o/s/r tyres u/s	replaced n/s/r tyres. torque wheel nuts. refit valve ext. refit links.		544352
879	05/01/2015	524079	AIR SPRING (SP0003A)			544352
879	05/01/2015	524079	Suspension - rear air bag u/s	replaced n/s/r airbags. secured air lines.		544352
879	05/01/2015	524079	GLOBE 24V X 150W SCHOOL LIGHT			544352
879	05/01/2015	524079	TYRE RECAP 295/80R22.5			544352
879	05/01/2015	524079	DASH GLOBES			544352
879	05/01/2015	524079	TUBES FLUORESCENT 18W			544352
879	05/01/2015	524079	Elec and Light - o/s school light n/w	replaced rear school light globe. refit lens and secured frame.		544352
879	05/01/2015	524079	Elec and Light - dash lights n/w	replaced dash lights globe.		544352
879	05/01/2015	524079	Elec and Light - rear school light n/w	replaced floro tube on saloon light. refit lens cover.		544352
879	05/01/2015	524035	Consumables			544352
879	05/01/2015	524035	Consumables			544352
879	05/01/2015	524035		A SERVICE AS PER CHECK LIST		544352
879	04/24/2015	522928	GLOBE 24V 21W SINGLE CONTACT	fit new globe		542656
879	04/24/2015	522928	Elec and Light - n/s/f indicator n/w	serial G - 679858		542656
879	04/21/2015	521454	bic inpection	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O150408 Receiving #:154451 Date :2015-04-29 CARRY OUT RSI AS REQUIRED		540410
879	04/16/2015	521454	ROAD WORTHY INSPECTION	RSI CARRIED OUT BY FLEET CHECK PO O150408		543460
879	04/16/2015	521454	ANNUAL SAFETY INSPECTION (RWC #)	carried out pre rsi check		540410
879	04/16/2015	521454	PRE ANNUAL SAFETY INSPECTION CHECK	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		540410
879	04/13/2015	520792		VEHICLE SAFETY INSPECTION		539631
879	04/13/2015	520792				539631
879	04/13/2015	520852	GLOBE FESTOON 24V 5W	replaced globe		539631
879	04/13/2015	520852	n/s/f top parker light n/w	carried out fire safety inspection as per check list		539631
879	04/13/2015	520792		FIRE SAFETY INSPECTION AS PER CHECK LIST		539631
879	04/09/2015	520226	GLOBE 24V 75/70W H4			538997
879	04/09/2015	520226	Elec and Light Exterior Lights - near side headlight is o	replaced globe		538997
879	03/29/2015	518266	Replace See Something Say Something Poster	complete audit as required		535974
879	03/12/2015	515831	Security CCTV System Faulty hasn't recorded since 26/1	checked and found a blown fuse. replaced fuse ok		533001
879	03/03/2015	514164	Brakes Shuddering			530065
879	03/03/2015	514164	Brakes Noisy	wheel alignment was carried out by air anywhere on order - O148988		530065
879	03/02/2015	514104	Air System Leaking air from under drivers seat.	removed driver seat base and repaired air leak tested ok.		530065
879	03/01/2015	498702	DIRECT PURCHASE - TOWING	Creditor #:\VB-EAGTOW Eagle Towing & Salvage P/O #:O146092 Receiving #:152513 Date :2015-03-19 Tow Bus 879		534465
879	02/28/2015	513852	Wheel nut retention - both front retorque	retentioned front wheel nuts as required		530065
879	02/28/2015	513515	Steering - drag link u/s	replaced drag link. road tested ok		530065
879	02/28/2015	513852	One of the pax stop button is not working	checked operation of all pax buzzers could not fault		530065
879	02/27/2015	513515	GLOBE 24V 21W SINGLE CONTACT			530065
879	02/27/2015	513515	Mechanic entered - Elec & Light Indicators n/s/f side blink	fit globe.		530065
879	02/26/2015	513428		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		530065
879	02/26/2015	513428		VEHICLE SAFETY INSPECTION		530065
879	02/26/2015	513515	Whls & Tyres - both front tyres u/s	replaced FRONT BOTHSIDE TYRES.		530065
879	02/26/2015	513515	TYRE NEW 295/80R22.5			530065
879	02/26/2015	513515	SWAYBAR LINK			530065
879	02/26/2015	513515	Suspension - o/s/f sway bar ball joint u/s	replaced O/S/F SWAY BAR BALL JOINT.		530065
879	02/26/2015	513515	SWITCH- STOP-YELLOW			530065
879	02/26/2015	513515	passenger buzzer stop switch u/s	replaced PASSENGER BUZZER SWITCH.		530065
879	02/26/2015	513515	DRAG LINK SCANIA 40L2227ZF	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151446 Date :2015-02-26		530617
879	02/26/2015	513515	FLUORESCENT TUBES 18W			530065
879	02/26/2015	513515	front saloon light globe n/w	replaced SALOON LIGHT GLOBE.		530065
879	02/26/2015	513515	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706			530065
879	02/26/2015	513515	dash light globes u/s			530065
879	02/26/2015	513515	n/s/r top window strip u/s	FIXED N/S/R TOP WINDOW STRIP.		530065
879	02/26/2015	513428	USE ONLY PART NUMBER L814 TEXAMATIC 1888			530617
879	02/26/2015	513428	Consumables			530617
879	02/26/2015	513428	Consumables			530065
879	02/26/2015	513428	USE ONLY PART # L807 BP MULTIFLEET /Ltr			530065
879	02/26/2015	513428	O-RING LARGE SPINNER FILTER SCANIA (1769799)			530065
879	02/26/2015	513428	O-RING SPINNER FILTER SCANIA (1769798)			530065
879	02/26/2015	513428	FILTER FUEL SCANIA SR4(H17WK04)			530065

879	02/26/2015	513428	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)		530065
879	02/26/2015	513428	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		530065
879	02/26/2015	513428		B SERVICE AS PER CHECKLIST	530065
879	02/26/2015	513428	FILTER FUEL SCANIA L94UAB (H7090WK30)		530065
879	02/26/2015	513428	Consumables		530617
879	02/26/2015	513428	Consumables		530617
879	02/26/2015	513428		A SERVICE AS PER CHECKLIST	530065
879	02/25/2015	513272	BELT		530065
879	02/25/2015	513272	Air Cond Belt ReplacementOnly one belt	fit new a/c belts .	530065
879	01/29/2015	508842	Engine W'ring Light appearing on dash and bus losing po	remove fit original throttlevaive road test ok.	524222
879	01/17/2015	507245	Body & Acc Drivers Seat Cushion - Drivers seat base cushi	fit new drivers seat base checked operation of drivers seat ok	521627
879	01/14/2015		0 Imported Service History	Imported Service History	521364
879	01/14/2015	506614		Perform Safety Inspection as per checklist	521364
879	01/14/2015	506673	BUSH REAR SWAY BAR K94 SCANIA		521364
879	01/14/2015	506673	Suspension - rear D rubber u/s	replaced rear D rubber.	521364
879	01/14/2015	506673	Air Cond - mount u/s	replaced A/C comperssor mount.	521364
879	01/14/2015	506673	Mount A/C Large		521364
879	01/14/2015	506673	driver top light n/w	replaced driver top light globe.	521364
879	01/14/2015	506673	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706		521364
879	01/14/2015	506673	GLOBE 24V 5W		521364
879	01/14/2015	506673	driver top light n/w	replaced driver top light globe.	521364
879	01/14/2015	506673	dash light globes u/s	replaced dash switch globe.	521364
879	01/14/2015	506614	USE ONLY PART # L807 BP MULTIFLEET /Ltr		521364
879	01/14/2015	506614	USE ONLY PART # L816 GREASE LIPLEX HD2 (LU5)		521364
879	01/14/2015	506614	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST		521364
879	01/14/2015	506673	front brake hose has a loose union as required	carried out campaign as required	521364
879	01/14/2015	506614	Consumables	tightened front bothside brake hoses.	521364
879	01/14/2015	506614	Consumables		521364
879	01/14/2015	506614		Tension ALL Wheel Nuts to OEM Specs	521364
879	01/14/2015	506614		A - Service & Bus Safety Inspection	521364
879	12/31/2014	499727	Hose	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O146550 Receiving #:149052 Date :2014-12-31	518446
879	12/30/2014	504167	FUEL FILTER (H17WK11)		517971
879	12/30/2014	504167	Fuel Leaking	change leaking fuel filter .	517971
879	12/23/2014	499727	Mechanic entered - Engine Stalling loosing throttle .	refitting loomscable tie into position . finish cable tying looms secure all roof panels .	516451
879	12/18/2014	499727	Mechanic entered - Engine Stalling loosing throttle .	road tested bus could not fault	516451
879	12/17/2014	502684	Body & Acc Interior : air con vent loose.	Incorrect bus entered.	516451
879	12/15/2014	502085	A3 Poster Change	Fit by Fleet Support Staff	516451
879	12/12/2014	496779	Superslim Plastic Base	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O146060 Receiving #:148482 Date :2014-12-12	516451
879	12/02/2014	499727	Mechanic entered - Engine Stalling loosing throttle .	trace wiring . stilltraceing fault . still tracing wiring .	516451
879	12/01/2014	496779	Dipstick Scania	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O145560 Receiving #:147959 Date :2014-11-28 MM	516394
879	12/01/2014	498702	SCANIA L94UAB ACC PEDAL SENSOR	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O145560 Receiving #:147959 Date :2014-11-28 40V2203	516394
879	12/01/2014	498702	no pwr no acceleration. bus towed in 25/11/2014	trace wiring found rubbed through wire rapair refit all looms and cable tie .	516394
879	11/26/2014	498702	no pwr no acceleration. bus towed in 25/11/2014	REFIT AXLE CONNECT LAPTOP SUSPECT THROTTLE SWITCH NIL STOCK WOP /.	516394
879	11/25/2014	498654	Attend breakdown crn Halifax & Hampton st.	Attend Oakleigh breakdown in Brighton check report of no throttledisconnect batteries to reset system didn't fix problem. Check for fuse boxcouldn't rectify fault. Remove half shaft so bus could be towed.	516394
879	11/20/2014	493995	o/s/f jumper seat bottom cover missing	removed pax seat & fitted seat coverok.	515149
879	11/18/2014	496779	PLUG H/CAP L94UAB		515149
879	11/18/2014	497356	GLOBE FESTOON 24V 5W		515149
879	11/18/2014	497356	INDICATOR SWITCH SCANIA L94UAB 40v4703		515149
879	11/18/2014	497356	Elec & Light Indicators indicator stalk not canceling whe	replace indiator switch o/s top globe dash globe drivers seat cushion.	515149
879	11/18/2014	497441	Body & Acc Drivers Seat Cushion - driver seat base cushion	replaced drivers seat cushion	515149
879	11/18/2014	497439	Body & Acc - cabinet over driver head needs to be closed and	repaired tighten bolt	515149
879	11/18/2014	497202	Remove Legacy Poster and replace with See Something Say So	Replaced poster as required	515149
879	11/15/2014	496779	Engine dip stick stuck half way out.	REPLACED DIPSTICK	514604
879	11/07/2014	495161	Seat shock absorbers do not support maximum weight.Seat b	could not fault	512296
879	11/05/2014	494465	retensioned all wheel nuts	retorque all wheel nuts .	511460
879	11/01/2014	493995	DASH GLOBES		512079
879	10/31/2014	493995	Whls & Tyres - n/s/r tyre u/s	replaced tyre	511460
879	10/31/2014	493995	Suspension - n/s/f torque rod bolt loose	repaired tighten bolt	511460
879	10/31/2014	493995	Suspension - o/s/r/f air bag leaking air	replaced air bag	511460
879	10/31/2014	493995	Passenger Doors - rear door sensitive edge n/w	adjusted air pressure	511460
879	10/31/2014	493995	rev counter meter light u/s	replaced globe	511460
879	10/31/2014	493995	n/s inner over head a/c outlet panel u/s	replaced SCREW	511460
879	10/31/2014	493995	inside rear veiw mirror loose	tighten bolt	511460
879	10/31/2014	493995	o/s/f jumper seat bottom cover missing	wop	511460
879	10/30/2014	493667	USE ONLY PART NUMBER L814 TEXAMATIC 1888		511460
879	10/30/2014	493667	USE ONLY PART # L807 BP MULTIFLEET /Ltr		511460
879	10/30/2014	493667	FILTER ZF TRANS		511460
879	10/30/2014	493667	OIL FILTER SC S4 & K (H200W02/1117285)		511460
879	10/30/2014	493667	FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)		511460
879	10/30/2014	493667	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		511460
879	10/30/2014	493667		Perform Safety Inspection as per checklist	511460
879	10/30/2014	493667	Complete AM/FM radio saloon speaker modification		511460
879	10/30/2014	493667	Consumables		0
879	10/30/2014	493667	Consumables		0
879	10/30/2014	493667	GLOBE 24V 4W S/C		511460
879	10/30/2014	493667			511460
879	10/30/2014	493667	O-RING		511460
879	10/30/2014	493667	O-RING		511460
879	10/30/2014	493667			511460
879	10/30/2014	493667		Tension ALL Wheel Nuts to OEM Specs	511460
879	10/30/2014	493667		A - Service & Bus Safety Inspection	511460
879	10/30/2014	493667	Consumables		0
879	10/30/2014	493667	Consumables		0
879	10/30/2014	493667		Tension ALL Wheel Nuts to OEM Specs	511460
879	10/30/2014	493667		A - Service & Bus Safety Inspection	511460
879	10/03/2014	489192	Remove old decal and fit new Authorised Officers Decal DO N	Completed as required	505687
879	09/19/2014	486658	SIDE INDICATOR R/H		502229
879	09/19/2014	486658	Elec & Light Indicators - O/S Indicator light and lens br	replaced blinker assembly and globe	502229
879	09/19/2014	486658	GLOBE 24V 21W SINGLE CONTACT		502229
879	09/16/2014	485917		Perform Safety Inspection as per checklist	501756
879	09/16/2014	486012	FLUORESCENT TUBES 18W		501756
879	09/16/2014	486012	ST SCR C/S PHL 7982 ZN 3.5X16		501756
879	09/16/2014	486012	WIPER BLADE ASSEMBLY		501756

879	09/16/2014	486012	n/s and o/s wipers n/w		replaced n/s o/s wipers	501756
879	09/16/2014	486012	ROLLER			501756
879	09/16/2014	486012	pax bell n/w		replaced screw	501756
879	09/16/2014	486012	Engine belt ider u/s		replaced idler	501756
879	09/16/2014	486012	GLOBE FESTOON 24V 5W LONG			501756
879	09/16/2014	486012	o/s/f top park light n/w		replaced globe	501756
879	09/16/2014	486012	saloon light n/w x 1		replaced globe	501756
879	09/16/2014	486012	BOLT HX HD 6X25			501756
879	09/16/2014	486012	WASHER FLAT 6mm			501756
879	09/16/2014	486012	drivers panel loose			501756
879	09/16/2014	485917	BP DIFF OIL HYPOGEAR 85W140 EP (205LTS)		replaced bolts & tighten bolts	501756
879	09/16/2014	485917	OILBP MULTIFLEET /Ltr			501756
879	09/16/2014	485917	FILTER K124EB HYD COOLING FAN			501756
879	09/16/2014	485917	POWER STEERING FILTER VOLVO			501756
879	09/16/2014	485917			Service as per check list	501756
879	09/16/2014	485917	GREASE ENERGREASE LC2-T			501756
879	09/16/2014	485917	OIL AUTO TRANS ATF H/DUTY			501756
879	09/16/2014	485917			Tension ALL Wheel Nuts to OEM Specs	501756
879	09/16/2014	485917			A - Service & Bus Safety Inspection	501756
879	09/09/2014	484691	Lamp SWF Switch LED 1.2W LED (17040 E-596WLED47706			500157
879	09/09/2014	484691	Elec & Light - The following switches/buttons need new ligh		fitted wedges to the switches. removed stg column covers fabricated a u piece and glued to the shaft. tested self cancelling ok.	500157
879	09/09/2014	484691	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			500157
879	09/09/2014	484691	Body & Acc Drivers Seat Cushion - Drivers seat base cushi			500157
879	09/09/2014	484813	carry out air con service 24 m			500157
879	09/09/2014	484812			R/R driver's seat base.	500157
879	09/09/2014	484813	O143333- cold drive		Creditor #:-VB-COLO04 COLD DRIVE AIR CONDITIONING P/O #:-O143333 Receiving #:145386 Date :2014-09-16	501756
879	09/09/2014	484813	O143333- cold drive		service carried out by cold drive on order number O143332	500157
879	09/09/2014	484813	O143333- cold drive		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	500157
879	09/09/2014	484813	O143333- cold drive		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	500157
879	09/09/2014	484813	O143333- cold drive		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	500157
879	09/09/2014	484813	O143333- cold drive		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	500157
879	09/09/2014	484813	O143333- cold drive		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	500157
879	09/09/2014	484813	O143333- cold drive		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	500157
879	09/09/2014	484813	O143333- cold drive		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	500157
879	09/09/2014	484813	O143333- cold drive		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	500157
879	09/09/2014	484813		#NAME?	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	500157
879	09/09/2014	484813	O143333- cold drive		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	500157
879	09/09/2014	484813			Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	500157
879	09/02/2014	483434	Remove old A3 poster & replace with Legacy or Penalty Fares		replaced poster as per campaign	499012
879	09/01/2014	480954	Drivers seat base		Creditor #:-VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-O142618 Receiving #:146055 Date :2014-10-03	505687
879	08/29/2014	482777	Suspension Kneeling System - raise and lower not working		road tested bus cleared fault code . checked operation ok	498213
879	08/29/2014	478513	CONSUMABLE DELIVERY CHARGE		Creditor #:-VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:-O142456 Receiving #:144769 Date :2014-08-29 Freight for 0485973	498560
879	08/29/2014	478513	Link		Creditor #:-VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:-O142456 Receiving #:144769 Date :2014-08-29	498560
879	08/25/2014	481853			adjust and checked valve tappets. re-fit air filter assy turbo pipes and hoses. road test and wash engine/radiator.	497097
879	08/25/2014	481853			Adjust Tappets	497097
879	08/20/2014	480954	Elec & Light Indicators do not cancel after turning		replaced indicator switch.ok	496460
879	08/20/2014	480954	Elec & Light Switches need new globes		replaced dash switch globe.ok	496460
879	08/20/2014	480954	INDICATOR SWITCH SCANIA L94UAB			496460
879	08/20/2014	480954	Lamp SWF Switch LED			496460
879	08/20/2014	480954	Body & Acc Drivers Seat Cushion lacks padding..can feel f			496460
879	08/08/2014	478513			removed Driver seat cushion. removed drivers seat cusion. sent away for repair	493588
879	08/08/2014	478513	BrakesWhen you take the foot off the brakes the bus rolls		found n/s/b LED blinker n/w - replaced blinker assembly traced and found o/s/r/b blinker LED and wiring u/s replaced LED and repaired wiring checked operation ok	493588
879	08/06/2014	478513	BrakesWhen you take the foot off the brakes the bus rolls		installed new kick-down linkage. road tested ok	493160
879	08/02/2014	477910	GLOBE 24V/21W FESTOON		traced and found kick-down linkage u/s	492244
879	08/02/2014	477910	Elec & Lightupper n/s front indicators n/w and the indi			492244
879	07/28/2014	476713			traced and found electrical short repaired wiring and replaced u.s globe checkedo operation ok	491108
879	07/26/2014	476675	replace tyres us as required		wheel nut tension	491108
879	07/26/2014	476675	TYRE VALVE EXTENSION 210mm LONG		osf tyre pressure pumped up. removed cover torqued the wheel nuts. fitted pointers. replaced osr tyres and valve ext. torqued wheel nuts	491108
879	07/26/2014	476675	Clamp Suit Tyre Valve			491108
879	07/25/2014	476505				491108
879	07/25/2014	476505	Fit Wheel Nut Pointers to all wheel nuts on the front axle		Perform Safety Inspection as per checklist	491108
879	07/25/2014	476505	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels		will be done when tyres replaced on monday	491108
879	07/25/2014	476505	Consumables		will be done when the tyres replaced on monday	491108
879	07/25/2014	476505				0
879	07/25/2014	476505			Tension ALL Wheel Nuts to OEM Specs	491108
879	07/25/2014	476505			A - Service & Bus Safety Inspection	491108
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505	OILBP MULTIFLEET /Ltr			491108
879	07/25/2014	476505	GREASE ENERGREASE LC2-T			491108
879	07/25/2014	476505	OIL AUTO TRANS ATF H/DUTY			491108
879	07/25/2014	476505	COOLANT PREMIX NF48			491108
879	07/25/2014	476505	FILTER			491108
879	07/25/2014	476505	FILTER ELE L94 & EARLY K230			491108
879	07/25/2014	476505	FILTER ZF TRANS			491108
879	07/25/2014	476505	O-RING			491108
879	07/25/2014	476505	O-RING			491108
879	07/25/2014	476505	OIL FILTER SC S4 & K (H200W02)			491108
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505			Tension ALL Wheel Nuts to OEM Specs	491108
879	07/25/2014	476505			A - Service & Bus Safety Inspection	491108
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505	Consumables			0
879	07/25/2014	476505	Consumables			0
879	07/19/2014	475369	Elec & Light - O/S Headlight Out		fitted globe	488922
879	07/19/2014	475387	Mechanic entered - Elec & Light Headlights O/S headlight N/W		double entry	488922
879	07/19/2014	475369	GLOBE 24V 75/70W H4			488922
879	07/17/2014	474908	Elec & Light front n/s parker not working change globes fo		fit globe n/s/f park .	488922
879	07/17/2014	472461	Elec & Light Indicators when after turning indicator do no		replace broken blink stalk make new striker plate and fit .	488922
879	07/17/2014	472461	INDICATOR SWITCH SCANIA L94UAB			488922
879	07/17/2014	474908	GLOBE 24V 4W S/C			488922
879	07/14/2014	471467	CUSHION PAN (DRIVERS SEAT)-(ct			488288
879	07/14/2014	471467	GLOBE 24V 75/70W H4		Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O140695 Receiving #:143024 Date :2014-07-14 A6008BASE	488288
879	07/11/2014	473677	Mechanic entered - Clean workshop		wrong entry	487323
879	07/08/2014	472461	Mechanic entered - Elec & Light Headlights o/s/headlight n/w		fit globe .	486565

879	07/08/2014	472461	GLOBE 24V 75/70W H4	Accident repaired at Knox	487655
879	07/02/2014	471997	Acc 39321 Accident O/S Front indicator broken.	replaced seat cushion. replaced head light globe on n/s	484940
879	06/30/2014	471467	Body & Acc Drivers Seat Cushion is very uncomfortable. Ie	Creditor #:-VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:-O140073 Receiving #:142465 Date :2014-06-27	484940
879	06/27/2014	470171	BATTERY 12V 800CC	a/c repaired by cold drive . no order number required	484210
879	06/25/2014	470547	Heat & Demist - no heaters demisters or climate control wor	repaired by cold drive no charge or order number required	483818
879	06/24/2014	470377	Ops Entered - Fault - Heat & Demist No Heaters - Route: 703	checked charge rate of batterys and conditions of batterys could not fault	483818
879	06/24/2014	470555	Elec & LightBattery light on the dash	jump start bus	483818
879	06/23/2014	470076	Engine Won't Start	load tested both batteries found one us replaced battery and checked chg rates 27.5V.	481940
879	06/23/2014	470171	Ops Entered - Fault - Elec & Light Battery Flat - Route: 7	road tested found n/s wheel bearing cover fallen off. resecured bearing cap	481940
879	06/20/2014	469722	Suspension NoisyClinking noise coming from the L/H fr	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O140776 Receiving #:142592 Date :2014-07-01	481940
879	06/19/2014	469286	Jump start @ Westall Station	resecured cover	481940
879	06/19/2014	469514	Elec & LightN/S Cover around head light loose	load tested batterys checked charge rate 28.4 volts ok	481940
879	06/18/2014	469286	Elec & Light Battery Flat or not charging	jump start bus	481940
879	06/17/2014	469021	Engine wont start	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	481940
879	06/16/2014	467731	SWITCH HAZARD 4 SERIES	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	467731	SIDE INDICATOR L/H	jump start bus checked charge rate - 28.5 volts	482455
879	06/16/2014	468745	Engine Won't Start	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	481940
879	06/16/2014	466565	O RING	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	LOCK RING	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	Lining Scania 8 inch	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	INDICATOR STALK SCANIA SERIES	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	SCREW PAN S/T PH 4.2X19	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	COOLANT PREMIX NF48	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	LED FRONT POSITION MARKER LIGH	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	TWO WAY JOINER	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	WASHER BODY 6 X 25	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	HX HD 5X20 BOLT	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	ST SCR PHD PHL 7981 ZN 4.2X22	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	LEMFOERDER REP. KIT LINK	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	THERMOSTAT SEAL	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	HOSE BEND	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	ALN CAP SCR 4 X 16	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	CENTRA CUSHION CLIP LH	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	SINGLE SEAT BASE	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	ROLLER	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/16/2014	466565	DASH GLOBES	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O139249 Receiving #:141929 Date :2014-06-16	482455
879	06/14/2014	468698	Heat & Demist - blowing cold air	found the frt cable come off refitted and tested ok.	481940
879	06/14/2014	468698	Security CCTV - not recording since 15th May	connected the external monitor and tested rec date/time and play back all good.	481940
879	06/13/2014	468495	Engine wont start	jump started bus	481940
879	06/10/2014	467764	Heat & Demist Demisters Bloew Cold AirClimate control	adjusted heater tap road tested ok	480599
879	06/10/2014	467731	hazard switch falling through dash bus wont start and n/s/	jump start bus fit new hazard switch fit new blinker assembly after drilling and repositioning blinker assembly	480599
879	06/10/2014	467768	Elec & LightN/S Headligh surround is loose	resecured headlight surround	480599
879	06/05/2014	467312	Engine oil leak from injector cover	rectify engine oil leak from cover. tight cover bolts.	479945
879	06/05/2014	467363	Mechanic entered - Engine Won't Stop jump started.ok	jump started bus	479945
879	06/05/2014	466565	front brakes low	cleaned front hubs installed front o/s n/s hubs installed front o/sn/s brakes linings tightened torque rench wheel nuts 606NMTightened torque rench front o/sn/s hub nuts100NM.ok Ali	479945
879	06/04/2014	466565	Engine oil leak from injector cover		479945
879	06/04/2014	466565	RADIUS GRIND BRAKE SHOE	Creditor #:-VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:-O139737 Receiving #:141695 Date :2014-06-10	481409
879	06/04/2014	466565	MACHINE DRUM	Creditor #:-VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:-O139737 Receiving #:141695 Date :2014-06-10	481409
879	06/04/2014	466565	front brakes low	removed front hubs removed front n/so/s linings replaced front n/so/s linings.	479945
879	06/03/2014	466565	front torque bushes u/s	replaced front o/s top torque rod.	479945
879	06/03/2014	466565	front torque bushes u/s	removed and refir n/s/f and o/s/f torque rod. replaced rubber bush. secured air line rubbing on frame. secured levelling valve clamps.	479945
879	06/03/2014	466565	2-way radio mount u/s	Maked 2-way radio bracket.ok	479945
879	06/03/2014	466565	2-way radio mount u/s	fabricate base plate for 2 way radio. secured with screws.	479945
879	06/03/2014	466565	number plate light n/w	r/r number plate lightok. fitted coolant pipe with new coolant hose & top up coolantok r/r indicator switchok washed engine & road testok.	479945
879	06/02/2014	466430		Perform Safety Inspection as per checklist	479945
879	06/02/2014	466565	n/s rear tyres u/s	replaced n/s/r tyres.	479945
879	06/02/2014	466565	front torque bushes u/s		479945
879	06/02/2014	466565	Engine belt roller idler u/s		479945
879	06/02/2014	466565	Engine oil leak from injector cover		479945
879	06/02/2014	466565	Engine belt roller idler u/s	replaced engine belt idler roller. checked and secured serpentine belt	479945
879	06/02/2014	466565	coolant leak at boost pump	removed thermostat housing.	479945
879	06/02/2014	466565	coolant leak at boost pump	replaced coolant hose. tighten hose clamps.	479945
879	06/02/2014	466407	Mechanic entered - Engine Won't Start	jump started checked chg ok	479945
879	06/02/2014	466565	saloon light n/w	replaced floro tube. replaced inverter and terminals.	479945
879	06/02/2014	466565	cctv showing wrong time	adjust cctv time.	479945
879	06/02/2014	466565	number plate light n/w		479945
879	06/02/2014	466565	dash lights n/w	replaced dash globes	479945
879	06/02/2014	466565	2-way radio mount u/s		479945
879	06/02/2014	466565	seat cushions torn	replaced seat base cushion.	479945
879	06/02/2014	466565	front brakes low		479945
879	06/02/2014	466430			479945
879	06/02/2014	466430			479945
879	05/29/2014	465744	No Water in the Wipers Washers	A - Service & Bus Safety Inspection	479594
879	05/26/2014	465062	Replace U/S condensor fans as	Tension ALL Wheel Nuts to OEM Specs	480446
879	05/26/2014	465062	Air Cond not cold enough	readjusted wipers and filled water bottle	479171
879	05/26/2014	465062	Air Cond Air Conditioner blowing hot air	Creditor #:-VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:-O139285 Receiving #:141453 Date :2014-06-04	479171
879	05/23/2014	462269	INDICATOR STALK SCANIA SERIES	a/c repaired by cold drive condensor fans replaced	478888
879	05/23/2014	462269	Direct Purchase - MECHANICAL	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O138652 Receiving #:141012 Date :2014-05-23	478888
879	05/18/2014	462852	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O138652 Receiving #:141012 Date :2014-05-23 A6008BASE - Driver Seat Base	476287
879	05/12/2014	462269	Air Cond - not working - displays Err	carried out A3 replacement as required	476195
879	05/12/2014	462269	Drv entered - Air Cond Other	checked ac system err1 message on display. disconnected battery and tested ok.	476195
879	05/12/2014	462269	Elec & Light - indicator does not cancel out after turning	checked the ac operation not cold enough. ph1 is on suspect low pressure or cond fans. need further checking	476195
879	05/12/2014	462269	Ops Entered - Fault - Elec & Light Interior Lights not work	checked indicator not cancelling. fabricated a 'u' piece and fitted. still the same fitted new stalk tested ok.	476195
879	05/12/2014	462269	Body & Acc Drivers Seat base cushion lacks support leans	checked interior lights all working. could not fault.	476195
879	04/22/2014	455200	GLOBE 24V 75/70W H4	replaced driver's seat cushion.	481409
879	04/22/2014	458728	CUSHION PAN (DRIVERS SEAT)-(ct	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O137110 Receiving #:141702 Date :2014-06-10	481409
879	04/22/2014	458724	BATTERY 12V 800CC	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O137110 Receiving #:141702 Date :2014-06-10	481409
879	04/21/2014	458455	Engine Won't Start	Creditor #:-VB-ECOAST EASTCOAST TRUCK & BUS P/O #:-O137110 Receiving #:141702 Date :2014-06-10	470830
879	04/19/2014	458728	Body & Acc Drivers Seat Cushion lacks support leans to on	jump start ign left on .	470830
879	04/19/2014	458724	Brakes does not seem to work as normal.The driver has to	FITTED NEW SEAT BASE A6008BASE	470830
879	04/17/2014	458455	carry out BIC inspection as re	adjusted brakes road tested ok. replaced one battery.N94P	470830
879	04/17/2014	458455		Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-O137915 Receiving #:139663 Date :2014-04-17	470830
879	04/17/2014	458454		Inspect vehicle as per RSI Checklist	470830
879	04/17/2014	458454		Inspect vehicle as per RSI Checklist	470830

879	04/17/2014	0	Imported Service History	Imported Service History	470830
879	04/15/2014	458051	GREASE ENERGREASE LC2-T		470091
879	04/15/2014	458051	FILTER		470091
879	04/15/2014	458051	O-RING		470091
879	04/15/2014	458051		Perform Safety Inspection as per checklist	470091
879	04/15/2014	458051	Perform Campaign 1_14 School Bus Light Globe Check Check	cannot find the 35w globes in store will be done later	470091
879	04/15/2014	458051	O-RING	Kit . filter Cent	470091
879	04/15/2014	458051	OIL FILTER	Filter Oil	470091
879	04/15/2014	458051	FILTER ZF TRANS	Filter ZF Trans	470091
879	04/15/2014	458051	FILTER ELE L94 & EARLY K230	Fuel Filter	470091
879	04/15/2014	458051	OILBP MULTIFLEET /Ltr	Engine Oil	470091
879	04/15/2014	458051		Tension ALL Wheel Nuts to OEM Specs	470091
879	04/15/2014	458051		A - Service & Bus Safety Inspection	470091
879	04/15/2014	458051		A - Service & Bus Safety Inspection	470091
879	04/15/2014	458051		Tension ALL Wheel Nuts to OEM Specs	470091
879	04/15/2014	458051		A - Service & Bus Safety Inspection	470091
879	04/15/2014	458051	HEADER TANK FILLER CAP		470091
879	04/15/2014	458051	AIR FILTER SCANIA L94UB{395773}		470091
879	04/15/2014	458051		Tension ALL Wheel Nuts to OEM Specs	470091
879	04/13/2014	456557	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	poster not fitted ran out of posters	467205
879	04/06/2014	455507	Fit Myki decals as requiredFit Recruitment decal as requi	carried out campaign as required	467205
879	04/01/2014	455257	Air Cond Air Conditioner not cooling.	close bott roof vents run a/c 1 hour a/c cooling ok .	467008
879	04/01/2014	455200	Elec & Light Headlights O/S headlight N/W.	fit globe .	467008
879	04/01/2014	448922	SCREW PAN S/T PH 4.2X16	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	DIAPHRAGM DEEP DISH	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	Mount A/C Small	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	Mount A/C Large	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	GLOBE 24V 21W SINGLE CONTACT	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	GLOBE WEDGE 24V 1.2W	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	04/01/2014	452257	SR4 BELT TENSIONER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	470091
879	03/26/2014	454172	Mechanic entered - Passenger Doors Other wont close	sweep out wheel chair ramp checked operation ok	465263
879	03/14/2014	452154		Perform Safety Inspection as per checklist	462615
879	03/14/2014	452257	Wipers & Washers u/s		462615
879	03/14/2014	452257	Wipers & Washers u/s	fixed wiper washer	462615
879	03/14/2014	452257	A/c mount u/s	r/r a/c two mounts	462615
879	03/14/2014	452257	Engine belt tensioner u/s	replaced engine belt tensioner	462615
879	03/14/2014	452257	indicators not conselling	removed stg cover and the u piece. cleaned the surface.	462615
879	03/14/2014	452257	indicators not conselling	fixed indicator switch	462615
879	03/14/2014	452257			462615
879	03/14/2014	452257	dash switch lights n/w		462615
879	03/14/2014	452257	top drivers light n/w	r/r globe r/r globe r/r globe	462615
879	03/14/2014	452257	dash switch lights n/w	r/r globe	462615
879	03/14/2014	452257	n/s/r brake booster u/s	replaced rear n/s brakes booster diaphram. ok	462615
879	03/14/2014	452257	n/s/r brake booster u/s		462615
879	03/14/2014	452154		Tension ALL Wheel Nuts to OEM Specs	462615
879	03/14/2014	452154		A - Service & Bus Safety Inspection	462615
879	03/05/2014	450140	Rear Passenger Doors Faulty	refit door and adjusted speeds and pressures checked operation of door ok	460326
879	03/05/2014	450661	Mechanic entered - Engine Won't Start	jump started	460326
879	03/05/2014	450600	Mechanic entered - Elec & Light Headlights	replaced indicator globe	460326
879	03/05/2014	450140	Body & AccHammer not attached with the wire by the rear do	reattached wire and fit hammer to cradle	460326
879	03/03/2014	450140	Rear Passenger Doors Faulty		460326
879	03/03/2014	450140	Body & AccHammer not attached with the wire by the rear do		460326
879	02/27/2014	449722	Mechanic entered - Passenger Doors Other rear door not closi	entered in wrong by oakleigh workshop disregard	460324
879	02/27/2014	448922	Body & Acc - rear door u/s		460324
879	02/27/2014	448922		Repaired rear door adjusted rear door .checked operation - ok	460324
879	02/27/2014	448922		repaired passenger seat base	460324
879	02/27/2014	448922	Body & Acc - rear door u/s		460324
879	02/27/2014	448922	Body & Acc - rear door u/s	installed repaired door bracket	460324
879	02/24/2014	448922	Body & Acc - rear door u/s	removed rear door bracket and sent away for repair	459684
879	02/20/2014	448400	Elec & Light Speedo no light behind speedo	replaced speedo light globes	458830
879	02/19/2014	448043	Mechanic entered - Elec & Light Interior Lights	replaced globe checked operation ok	458617
879	02/18/2014	447964	Elec & Light Dash Light light on speedo not working.	fit globe	458404
879	08/06/2013	0	Imported Service History	Imported Service History	420706
879	08/06/2013	0	Imported Service History	Imported Service History	420706
879	04/10/2013	0	Imported Service History	Imported Service History	396753
879	09/21/2012	0	Imported Service History	Imported Service History	356118
879	09/21/2012	0	Imported Service History	Imported Service History	356118
879	05/10/2012	0	Imported Service History	Imported Service History	331018
879	05/04/2012	0	Imported Service History	Imported Service History	0
879	05/04/2012	0	Imported Service History	Imported Service History	0
879	07/18/2008	0	Imported Service History	Imported Service History	308192
879	07/01/2008	0	Imported Service History	Imported Service History	305000
879	06/24/2008	0	Imported Service History	Imported Service History	303192
879	05/31/2008	0	Imported Service History	Imported Service History	298192
879	05/06/2008	0	Imported Service History	Imported Service History	293192
879	04/12/2008	0	Imported Service History	Imported Service History	288192
879	03/19/2008	0	Imported Service History	Imported Service History	283192
879	02/24/2008	0	Imported Service History	Imported Service History	278192
879	01/30/2008	0	Imported Service History	Imported Service History	273192
879	01/06/2008	0	Imported Service History	Imported Service History	268192
879	12/13/2007	0	Imported Service History	Imported Service History	263192
879	12/01/2007	0	Imported Service History	Imported Service History	0
879	11/19/2007	0	Imported Service History	Imported Service History	258192
879	10/25/2007	0	Imported Service History	Imported Service History	253192
879	10/01/2007	0	Imported Service History	Imported Service History	248192
879	09/07/2007	0	Imported Service History	Imported Service History	243192
879	08/13/2007	0	Imported Service History	Imported Service History	238192
879	07/20/2007	0	Imported Service History	Imported Service History	233192
879	06/26/2007	0	Imported Service History	Imported Service History	228192
879	06/02/2007	0	Imported Service History	Imported Service History	223192
879	05/08/2007	0	Imported Service History	Imported Service History	218192
879	04/14/2007	0	Imported Service History	Imported Service History	213192