

Veh#	Date	W/O#	Description	Notes	Odometer
881	09/06/2026	1366580		COMPLETED BY ATS 18/8/26	933567
881	08/28/2026	1365530	Decommission of Bus for Auction	DECOMITION FOR BUIS AUCTION	933567
881	08/03/2026	1356644		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - Bus to be sold N/A	933567
881	08/03/2026	1356644		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	933567
881	05/14/2026	1340805		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.	933567
881	05/14/2026	1340805		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist. ok.	933567
881	02/27/2026	1323790		COMPLETED BY ATS 22/2/26	933567
881	02/25/2026	1321942	DIRECT PURCHASE - BUS INSPECTI	Creditor #:MT-ROASAF ROAD SAFETY INSPECTIONS P/O #:M405132 Receiving #:431174 Date :2026-02-27	933567
881	02/20/2026	1321942		VEHICLE SAFETY INSPECTION	933567
881	02/20/2026	1321942		ANNUAL SAFETY INSPECTION SERIAL # RSI 073405 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	933567
881	02/16/2026	1320939	Consumables		933567
881	02/16/2026	1320939	Mechanic entered - Body Other RSI repairs	fixed emmergency exithammer alarm fixed air leak rear of the bus fixed rear modasty panel rattel secure front driver blind	933567
881	02/16/2026	1320485	N/S/R Brake chamber leaking	replaced n/s rear brake chamber	933567
881	02/13/2026	1320532	RSI STEAM CLEAN	done the steam cleaning and prepair for RSI	933567
881	02/13/2026	1320533	Consumables		933567
881	02/13/2026	1320533	RSI FINAL & REPAIRS	replaced the drain plugs on some air tnaks secure some electrical wires close to boost pump fixed the play of steering wheel and done the final check	933567
881	02/13/2026	1320485	BRAKE CHAMBER DRUM BRAKES SCAN	Creditor #:MT-MUL001 MULTISPARES LTD P/O #:M404661 Receiving #:430197 Date :2026-02-17	933567
881	02/12/2026	1317047	VALVE PARK BRAKE SCANIA K94 05	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403604-RET Receiving #:430017 Date :2026-02-17	933567
881	02/12/2026	1317047	1411244 Relay Valve	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403993-RET Receiving #:430016 Date :2026-02-17 Incorrect Item	933567
881	02/10/2026	1319675		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	933567
881	02/10/2026	1319675		VEHICLE SAFETY INSPECTION	933567
881	02/09/2026	1317047	GASKET DIPSTICK ZF (0501 310 134 01)		933567
881	02/05/2026	1317047	Consumables		933567
881	02/05/2026	1317047	BATTERY EXSN94SCMF 1450AAC EMFN150L		933567
881	02/04/2026	1317047	1411244 Relay Valve	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403993 Receiving #:429723 Date :2026-02-10	933567
881	02/04/2026	1317047	LIGHT INDICATOR SIDE L/H		933567
881	02/04/2026	1317047	RELAY VALVE	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403993 Receiving #:429723 Date :2026-02-10	933567
881	02/04/2026	1317047	1543187 Silencer	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403993 Receiving #:429435 Date :2026-02-05	933567
881	02/03/2026	1317047	O/S/F brake chamber leaking	retight the clamps and check with water no leak found after	933567
881	02/03/2026	1317047	Rectify rear brake air leaks	found the leaks from park brake valve waiting for parts	933567
881	02/02/2026	1317047	Replace front & rear sway bar bushes	replaced front and rear D bushes	933567
881	02/02/2026	1317047	Mechanic entered - Body Other Rsi repairs	repalced o/s rear booster secure all disable seats mounting bolts clean all the rust and repaint the battery tray clean and paint the under neath the bus clean and paint both mirror arms replaced n/s indicator gloube and unit replaced o/s front park brake light secre front modasty panel replaced both batteries	933567
881	02/02/2026	1317047	DIAPHRAGM TYPE 24 SHALLOW BRAKE BOOSTER VOLVO B12BLE		933567
881	02/01/2026	1317047	1919010 Sway Bar Bush - Front-	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403604 Receiving #:429275 Date :2026-02-03	933567
881	02/01/2026	1317047	40G2511wabco Rear Brake Chambe	Creditor #:MT-MUL001 MULTISPARES LTD P/O #:M403605 Receiving #:429272 Date :2026-02-03	933567
881	02/01/2026	1317047	469271 Park Brake Relay Valve	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403604 Receiving #:429275 Date :2026-02-03	933567
881	02/01/2026	1317047	BUSH SWAY BAR SCANIA K124IB K3	Creditor #:MT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:M403604 Receiving #:429275 Date :2026-02-03	933567
881	01/28/2026	1316759		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	933567
881	01/28/2026	1316759		PRE ANNUAL SAFETY INSPECTION CHECK done the pre RSI as per the check list	933567
881	12/12/2025	1308993	Rear sway bar bushes worn	Rebooked	933567
881	12/12/2025	1308993	Front & rear sway bar bushes worn	Rebooked	933567
881	12/12/2025	1308993	Front upper torque rods worn	checked front upper torque rods. still good	933567
881	12/12/2025	1308993	Front engine mounts worn	checked engine mounts. still good.	933567
881	12/12/2025	1308993	O/S/F brake chamber slight leak	Rebooked	933567
881	12/12/2025	1308993	Rectify rear brake air leak	Defect rebooked	933567
881	11/17/2025	1303333		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	933567
881	11/17/2025	1303333		VEHICLE SAFETY INSPECTION	933567
881	08/26/2025	1285516		VEHICLE SAFETY INSPECTION safety all done	933522
881	08/26/2025	1285516		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	933522
881	08/26/2025	1285574	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	cleaned wipers all working now	933522
881	08/26/2025	1285576	Consumables		933522
881	08/26/2025	1285576	Consumables		933522
881	08/26/2025	1285576	Mechanic entered - Body Drivers Seat Controls	readjusted drives seat suspension all ok	933522
881	08/12/2025	1281881	Service		933522
881	08/11/2025	1281882	Service		933522
881	08/06/2025	1279174	COMPLETE A-SERVICE	Creditor #:MT-22CELS 22 CELSIUS P/O #:M392228 Receiving #:417345 Date :2025-08-12 including cl4ean evaporator coils & replacing drier	933522
881	07/29/2025	1279174		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Completed by 22 Celsius	933522
881	06/23/2025	1251740	IGNITION BARREL WITH FIXED KEY & SWITCH SCANIA L94 UB	CREDITED ON PO G383448RET - MISSED W/O	933522
881	06/14/2025	1270443	Consumables		933251
881	06/14/2025	1270443	Mechanic entered - Elec and Light Other need check battirs a	check battires ok neaily new start it with jump pack charge ok need more run	933251
881	06/02/2025	1265795		VEHICLE SAFETY INSPECTION done the safety as per the check list	933251
881	06/02/2025	1267032		ns kin pin all done finished	933251
881	06/02/2025	1267805	Mechanic entered - Elec and Light Other ns head light n w	suply and fit new head light	933251
881	06/02/2025	1267805	GLOBE 24V H4 75/70W HALOGEN		933251
881	06/02/2025	1267805	Consumables		933251
881	06/02/2025	1267033	N/S/F window loose	put some secaflex in to the gap	933251
881	06/02/2025	1267033	Consumables		933251
881	05/30/2025	1267032	SHIM KING PIN TH=0.178MM SCANIA		933251
881	05/29/2025	1267031	SEAL REAR TRANS OUPUT SHAFT SCANIA SR 4 ZF 0734 319 052 01		933251
881	05/28/2025	1267032	N/S kingpin play	jack up bus remove ns front wheel brake drum hub assembly remove shoes remove dial plate remove bottom of kin pin plate put .178 shims added clean every thing start putting all back together	933251
881	05/28/2025	1267031	Gearbox out put seal leaking	remove old seal refit new one b	933251
881	05/28/2025	1267030	Front modesty poll loose	front modesty panal repair as needed	933251
881	05/28/2025	1267030	Consumables		933251
881	05/22/2025	1265795		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	933251
881	05/19/2025	1264937	Elec and Light check and replace battery breakdown on 6/5/2	Replaced batteries. ok.	933251
881	05/19/2025	1264937	BATTERY EXSN94SCMF 1350AAC EMFN150L		933251
881	05/19/2025	1264937	Consumables		933251
881	05/08/2025	1263021	LIGHT INDICATOR SIDE R/H		933251
881	05/08/2025	1263021	Mechanic entered - Elec and Light Exterior Lights o/s/f side	o/s side indicator bulb was burnt and the shell was broken replaced the bulb and shell used new screws washers and nuts side indicator turns on tightend everything up all good	933251
881	05/08/2025	1263021	Consumables		933251
881	05/07/2025	1262797	Fault#:39609 - Ops Entered - Fault - Breakdown Not Starting	Attended breakdown 6/5/2025 bus could crank but but not enough to start jump started bus good to drive back to depot.	933251
881	03/21/2025	1251740		Completed job started the bus. Need to be jump start	932991
881	03/20/2025	1251740		Assisted Indika with barrel repair.	932991
881	03/20/2025	1251740		Start to install C/O	932991
881	03/19/2025	1251740		Start to removed ignition switch. C/O	932991
881	03/19/2025	1251740	0581025 LOCK BARREL SET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G383563RET Receiving #:406881 Date :2025-03-19 RETURNED	932991
881	03/19/2025	1251740		assisted indika.	932991
881	03/18/2025	1251740	581025 IGNITION BARREL - COMMO	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G383563 Receiving #:406663 Date :2025-03-18	932991
881	03/18/2025	1251740	IGNITION BARREL WITH COMMON KE	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G383825 Receiving #:406664 Date :2025-03-18	932991
881	03/12/2025	1251740	PTI Tablet Entered -Engine - not starting	check and order faulty ignition switch	932991
881	03/12/2025	1251740	IGNITION BARREL C/W KEY & SWIT	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G383448 Receiving #:406358 Date :2025-03-12	932991
881	03/01/2025	1248282	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G382567 Receiving #:405888 Date :2025-03-05	932591

881	02/26/2025	1248282	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	932591
881	02/26/2025	1248282	VEHICLE SAFETY INSPECTION assist sisil.	932591
881	02/26/2025	1248282	Assist with RSI	932591
881	02/26/2025	1248282	ANNUAL SAFETY INSPECTION SERIAL #RSI 068597. PASS. 26/02/2025. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	932591
881	02/21/2025	1247040	Body Carry out final inspection for RSI	932591
881	02/21/2025	1247040	DECAL PLEASE HOLD ON BLACK ON YELLOW	932591
881	02/21/2025	1247040		932591
881	02/18/2025	1246097	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	932591
881	02/07/2025	1243366	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	932300
881	02/07/2025	1243127		932300
881	02/07/2025	1243368	Mechanic entered - Engine Other Engine hatch lining torn	932300
881	02/07/2025	1243367	Mechanic entered - Warning Lights Other Hammer alarm switch	932300
881	02/07/2025	1243367	Consumables	932300
881	02/06/2025	1242850		932300
881	02/06/2025	1243129	Mechanic entered - Vandalism Other Torn rear seat base	932300
881	02/06/2025	1243129	SEAT CUSH SINGLE CEN CVR CI	932300
881	02/06/2025	1243127	Mechanic entered - Engine Warning Light	932300
881	02/06/2025	1242880		932300
881	02/06/2025	1243126	Mechanic entered - Body Other Floor damages near wheel chair	932300
881	02/05/2025	1242692		932300
881	02/05/2025	1242692		932300
881	02/05/2025	1242692		932300
881	02/05/2025	1242850	SEAT CUSH SINGLE CEN CVR RA	932300
881	02/05/2025	1242850	Mechanic entered - Vandalism Other Torn seat base. NS front	932300
881	02/05/2025	1242847	Mechanic entered - Gearbox Driveline Other Oil wet mark on g	932300
881	02/05/2025	1242880	Mechanic entered - CCTV Server Connection	932300
881	01/30/2025	1241558		932300
881	01/30/2025	1241558		932300
881	01/30/2025	1241558		932300
881	01/30/2025	1241602	Mechanic entered - Body Other passenger fold down seats pin	932300
881	01/30/2025	1241605	Mechanic entered - Body Other passenger fold down seat cover	932300
881	01/30/2025	1241602	Consumables	932300
881	01/30/2025	1241605	Consumables	932300
881	01/22/2025	1240114		932300
881	01/15/2025	1238719		932300
881	01/15/2025	1238719		932300
881	11/07/2024	1225891		931286
881	11/07/2024	1225891		931286
881	11/07/2024	1225924	Mechanic entered - Elec and Light Reverse Buzzer not working	931286
881	11/07/2024	1225924	BUZZER REVERSING 102DB 12/24V	931286
881	11/07/2024	1225924	Consumables	931286
881	10/21/2024	1222266	Workshop Tablet Entered -driver seatbelt wears out	930528
881	10/21/2024	1222266		930528
881	10/21/2024	1222266		930528
881	10/11/2024	1220517	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WHE	930245
881	10/11/2024	1220492	Consumables	930245
881	10/11/2024	1220492	Consumables	930245
881	10/11/2024	1220492	Consumables	930245
881	10/11/2024	1220492	O-RING LOWER SPINNER FILTER SCANIA L94 K124	930245
881	10/11/2024	1220492	OIL SAMPLE TEST KIT	930245
881	10/11/2024	1220492		930245
881	10/11/2024	1220492	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081	930245
881	10/11/2024	1220492	O-RING LARGE UPPER SPINNER FILTER SCANIA	930245
881	10/11/2024	1220492	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS	930245
881	10/11/2024	1220492	FILTER FUEL SCANIA VARIOUS MODELS H17WK04	930245
881	10/11/2024	1220492	FILTER OIL SCANIA VARIOUS MODELS	930245
881	10/11/2024	1220492	OIL ENGINE ALL FLEET PLUS E900 15W-40	930245
881	10/11/2024	1220492	OIL ATF STEERING DEX-3 VALVOLINE	930245
881	09/03/2024	1205225	CONDENSOR OIL COLLECTOR AIR DRYER SCANIA(1733111)(1492038)	928700
881	08/16/2024	1208056		928509
881	08/14/2024	1207545		928509
881	08/14/2024	1207545		928509
881	08/14/2024	1207545		928509
881	08/06/2024	1205225		928380
881	08/05/2024	1205225	CONDENSOR OIL COLLECTOR AIR DRYER SCANIA(1733111)(1492038)	928380
881	08/05/2024	1205225		928380
881	08/05/2024	1205225		928380
881	08/05/2024	1205225		928380
881	08/05/2024	1205225	CONDENSOR / OIL COLLECTOR AIR	928380
881	07/25/2024	1203218	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR	927476
881	07/02/2024	1197703		927286
881	06/19/2024	1195168		926840
881	06/19/2024	1195168	AIR DRYER DENSO LD8I	926840
881	06/19/2024	1195168	OIL COMPRESSOR AIR CONDITIONING	926840
881	06/19/2024	1195168		926840
881	06/18/2024	1195087	Mechanic entered - Elec and Light Flat Batteries	926840
881	06/18/2024	1195087	Consumables	926840
881	06/12/2024	1192531	DIRECT PURCHASE - BODYWORK	926840
881	06/11/2024	1193699	windows need to reseal (glass x1 reseal and2ND glass from t	926734
881	06/11/2024	1193699	windows need to reseal (glass x1 reseal and2ND glass from t	926734
881	06/11/2024	1193699	Consumables	926734
881	06/04/2024	1192531	Mechanic entered - Body Windows Side 1x window requires re-	926734
881	05/21/2024	1189533		925177
881	05/21/2024	1189533		925177
881	04/19/2024	1169643	Driver Tablet not charging	923074
881	04/19/2024	1169643	Consumables	923074
881	04/10/2024	1181380	Mechanic entered - Elec and Light Flat Batteries	922519
881	04/10/2024	1181380	Consumables	922519
881	04/05/2024	1180382	Engine (None)wash radiator as required	922519
881	03/14/2024	1176376	jump start bus . check charge rate	921941
881	03/14/2024	1176376	Consumables	921941
881	03/08/2024	1175388	Mechanic entered - Elec and Light Flat Batteries	921941
881	03/08/2024	1175388	Consumables	921941
881	02/26/2024	1172247	VEHICLE SAFETY INSPECTION	921598

881	02/26/2024	1172247	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	921598
881	02/26/2024	1172247	ANNUAL SAFETY INSPECTION SERIAL # ____ RSI 059007 PASS _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	921598
881	02/26/2024	1172247	Creditor #:\VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O360068 Receiving #:380476 Date :2024-02-27	921729
881	02/23/2024	1171953	carried out OSR retorque	921598
881	02/23/2024	1171953		921598
881	02/23/2024	1171845	removed diff pinion seal and replaced diff pinion seal and diff pinion nut ok	921598
881	02/23/2024	1171845		921598
881	02/23/2024	1171845		921598
881	02/23/2024	1171845		921598
881	02/23/2024	1171845	removed o/s/r vandelisem	921598
881	02/23/2024	1171845		921598
881	02/14/2024	1169644	Removed the dual converter bus minder crimped the wires to connect new dual converter for bus minder. charged bus minder tablet in workshop . resintalled tablet all ok	921245
881	02/14/2024	1169644		921245
881	02/13/2024	1169253		921245
881	02/09/2024	1169253	connected SD2 and retrieved DTCs 22 foot valve had 255 counts. stop lights nw and the stop signal is not coming thru micro switch in the foot valve. Replaced foot valve and adjusted retarder severity. road/brake tested; no eng warning. all good	921245
881	02/08/2024	1167481	Refitted fuel tank. Secured in place. Fitted all fuel lines and filled with diesel. Washed tank and checked for leaks. All ok.	921235
881	02/08/2024	1167481	Creditor #:\VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:\O358824 Receiving #:379296 Date :2024-02-12 rectify leak in fuel tank as required	921245
881	02/06/2024	1167481		921235
881	02/06/2024	1167481	PO:\O358824 - repaired at auto cooling	921235
881	02/05/2024	1167174	PRE ANNUAL SAFETY INSPECTION CHECK	921235
881	02/05/2024	1167174	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	921235
881	02/05/2024	1167175	PRE ANNUAL SAFETY INSPECTION CHECK	921235
881	02/05/2024	1167175	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	921235
881	02/05/2024	1167209		921235
881	02/05/2024	1167209	removed leaking shocker replaced with new item from stock ok.	921235
881	02/05/2024	1167209	removed A/C Belts reomved worn drive belt replaced with new item from stock refitted A/C Belts and adjusted ok.	921235
881	02/05/2024	1167209		921235
881	02/05/2024	1167209	drilled out rivets removed bottom seat cover replaced cushion covers with new items from stock 4 seats require only2 cushion covers in stock replaced worst seats.	921235
881	02/05/2024	1167209		921235
881	02/05/2024	1167209		921235
881	02/05/2024	1167209	reseated disabled seat top pins	921235
881	02/05/2024	1167209	applied new decal to rear window of bus.	921235
881	02/05/2024	1167175		921235
881	02/05/2024	1167175	removed all old decals from bus.	921235
881	01/24/2024	1165266	checked and found rear door nw. there was no power to thr rear door node. 20A fuse missing at electrical box. fitted the fuse door was working.	921235
881	01/24/2024	1165266	door brakes nw. checked and found no power to the relay 31. also a wire has come off at RPD plug. repaired the wire and located another blown fuse to RPD. replaced fuse and door brakes started working. ok	921235
881	01/24/2024	1165266		921235
881	01/23/2024	1165103		921235
881	01/22/2024	1164644	removed filter assembly replaced filter fixed corner so is held together refitted to bus.	921235
881	01/22/2024	1164644	VEHICLE SAFETY INSPECTION	921235
881	01/22/2024	1164644	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	921235
881	01/22/2024	1164696	replaced both front bottom shock rubbers ok.	921235
881	01/22/2024	1164696		921235
881	01/22/2024	1164696	removed hydaulic hose and replaced hydaulic hose ok.	921235
881	01/22/2024	1164696	Creditor #:\VB-ENZED ENZED MOORABBIN P/O #:\O358018 Receiving #:377993 Date :2024-01-24 make and supply hydraulic hose as per sample	921235
881	01/22/2024	1164696	replaced n/s/middle pax switch ok.	921235
881	01/22/2024	1164696		921235
881	01/22/2024	1164696	front and middle under rust paintigb off and painting ok.	921235
881	01/22/2024	1164696	replaced o/s/front bus inside top panel screws ok.	921235
881	01/22/2024	1164696		921235
881	01/18/2024	1164162	N/A	920681
881	01/17/2024	1163858	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	920681
881	12/02/2023	1155628	cleaned and painted over int graffiti	920551
881	11/20/2023	1153159	complete	920004
881	10/31/2023	1149525	VEHICLE SAFETY INSPECTION	920004
881	10/31/2023	1149525	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	920004
881	10/31/2023	1149586		920004
881	10/31/2023	1149627		920004
881	10/31/2023	1149586	replaced n/s/f top park light globe ok.	920004
881	10/31/2023	1149627	replaced dash speedo light globe and R.P.M light globe ok.	920004
881	10/31/2023	1149627	replaced n/s/middle pax switch ok.	920004
881	10/31/2023	1149627		920004
881	10/31/2023	1149627	repaired rear modesty panel ok.	920004
881	10/31/2023	1149627	repaired driver seat back modesty ok.	920004
881	10/31/2023	1149627	repaired o/s and n/s middle seat ok.	920004
881	10/31/2023	1149627	replaced o/s/f bus inside top panel screws and tightened screws ok.	920004
881	10/25/2023	1148405	checked for air leaks and air building up . found servicable . could not fault	919530
881	10/21/2023	1147676		918968
881	10/21/2023	1147676	fit globe.	918968
881	10/11/2023	1144450		918099
881	10/11/2023	1144450	bus minder hand set installed into bus .	918099
881	10/05/2023	1144450	fixed the dash crack around the previously installed busminder base area. fitted holder and wired up. need a handset to be programmed.	918099
881	10/05/2023	1144450		918099
881	10/03/2023	1143875	e-tag was in position. replaced with a new tag on 03-10-2023 10.45am	918099
881	09/20/2023	1141592	Creditor #:\VB-GLA010 GLASSPROTECH MELBOURNE P/O #:\O351197 Receiving #:369944 Date :2023-09-21 18/9/23	917505
881	09/20/2023	1141854		917257
881	09/20/2023	1141854	Replaced O/S headlight globe. Checked all front lights all ok.	917257
881	09/20/2023	1141854		917257
881	09/19/2023	1141592		917257
881	09/18/2023	1140758	Removed both front tyres and removed Brake shoes to be sent away.	916962
881	09/18/2023	1140758	Cleaned hub fit back machined brake linings with anti seize fit hub back and tension hub nut fit hub cap backe	916962
881	09/18/2023	1140758	Assisted fitting back wheels tension hub nut adjusted brakes and road tested Checked for shuttering on steering wheel while braking. Brake tested. All ok. Checked temperature of drums after road test N/S/F - 44 deg O/S/F - 42 deg.	916962
881	09/18/2023	1140758		916962
881	09/18/2023	1140758	Creditor #:\VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:\O351031 Receiving #:369720 Date :2023-09-19 machine drums and replace linings as required	917257
881	09/14/2023	1137818	Adjusted front brakes. Road tested and brake tested with Sadid. Found that steering wheel wobbles when using foot brakes. Front brake shoes and drums need to be sent for machining.	916718
881	09/11/2023	1139771		915968
881	09/11/2023	1139771	retensioned both front wheel nuts	915968
881	09/08/2023	1139381	TRANSMISSION CHECK AS PER CHECK LIST carried out trans check as per check list	915968
881	09/08/2023	1139380		915968
881	09/08/2023	1139380		915968
881	09/08/2023	1139380	assisted to change frt tyres	915968
881	09/08/2023	1139380	replaced both frt tyres and put osf to runout stock. tensioned wheel nuts. rebooked for retension	915968
881	09/01/2023	1137818	carried out campaign	914515
881	08/28/2023	1136610		913531
881	08/28/2023	1136610	Replaced O/S/F top park light globe. Checked front lights all ok.	913531

881	08/26/2023	1136261	Vandalism	Vandalism/ Graffiti Interior	CLEANED AND PAINTED OVER INT GRAFFITI	913531
881	08/18/2023	1134339			CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	912284
881	08/17/2023	1133977			VEHICLE SAFETY INSPECTION	912284
881	08/17/2023	1133977			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	912284
881	08/17/2023	1134216	Consumables			912284
881	08/17/2023	1134216	Mechanic entered -	Body Other Few disable seat hinge pins co	Knock pins back	912284
881	08/17/2023	1134216	Mechanic entered -	Body Drivers Seat Leaning Cushion lacks p	Replaced seat cushion	912284
881	08/17/2023	1134216	SLACK ADJUSTER FRONT OUTER SIDE	1789567		912284
881	08/17/2023	1134216	Mechanic entered -	Brakes Other O/S/F SLACK ADJUSTER WEAK	Removed and replaced slack adjuster adjusted both front brakes	912284
881	08/17/2023	1134216	ASSEMBLY RETRIMMED BASE	6008		912284
881	08/04/2023	1131254	Mechanic entered -	Gearbox Driveline Other trans drain pluge	replaced trans pluge ok.	910146
881	08/04/2023	1131254	DRAIN PLUG M22 X 1.5 ECOMAT ZF 0636	100 824 01		910146
881	08/04/2023	1131254	Mechanic entered -	Engine Other engine air filter 1 year mor	replaced engine air filter ok.	910146
881	08/04/2023	1131254	FILTER AIR OUTER SCANIA SR 3 & 4 395773	AF25066		910146
881	08/04/2023	1131194	Consumables			910146
881	08/04/2023	1131194	Consumables			910146
881	08/04/2023	1131194	OIL SAMPLE KIT	AMPOL		910146
881	08/04/2023	1131194			CARRY OUT B SERVICE AS PER CHECK LIST	910146
881	08/04/2023	1131194	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			910146
881	08/04/2023	1131194	FILTER ZF ECOMAT GEARBOX 4139-298-038	1193281		910146
881	08/04/2023	1131194	FILTER FUEL SCANIA L94 (1372444)			910146
881	08/04/2023	1131194	FILTER OIL SCANIA K93 L94 1117285	2059778		910146
881	08/04/2023	1131194	PAPER SPINNER FILTER OIL INSERT SCANIA L94			910146
881	08/04/2023	1131194	O-RING SPINNER FILTER SCANIA L94			910146
881	08/01/2023	1082112	CHECK VALVE DOUBLE SCANIA L94UAB	40G4601		909411
881	07/31/2023	1130162	Consumables			908726
881	07/31/2023	1130162	PTI Tablet Entered -Elec and Light -	Indicators Not Working	Replaced N/S/F indicator globe. Checked all front lights all ok.	908726
881	07/31/2023	1129867	Consumables			908726
881	07/31/2023	1129867	Mechanic entered -	Body Windows Rear N/S/R Window Requires	checked all rear windows on bus . could not fault	908726
881	07/29/2023	1129644	Consumables			908726
881	07/29/2023	1129644	PTI Tablet Entered -Body -	Windows Front bus washed sa	complete	908726
881	07/14/2023	1126547	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES		complete	905763
881	07/13/2023	1124259	Vandalism Graffiti Interior	AU	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O346384 Receiving #:364826 Date :2023-07-14	905763
881	07/11/2023	1125601	AIR CONDITIONING REPAIR		Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O346717 Receiving #:365132 Date :2023-07-19 12 month service	906660
881	07/11/2023	1125601			CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O346717 - carried out by ben from cold drive	904697
881	07/08/2023	1125165	Mechanic entered -	Wheels and Tyres Wheel Nut Retension N/S/	RETORQUE ALL FRONT WHEEL NUTS.	904697
881	07/08/2023	1125165	Consumables			904697
881	07/06/2023	1124553			VEHICLE SAFETY INSPECTION carried out safety inspection	904558
881	07/06/2023	1124553			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	904558
881	07/06/2023	1124617	Mechanic entered -	Steering Excessive Play Tie Rod U/S	replaced worn tie rod with new item from stock new nuts and split pins.	904558
881	07/06/2023	1124617	TIE ROD ASSY SCANIA L94/K230/N310/K310	2146105		904558
881	07/06/2023	1124617	Mechanic entered -	Dash Dash_Lights Not Working 1x Dash Ligh	replace globe	904558
881	07/06/2023	1124617	Consumables			904558
881	07/06/2023	1124617	HANDLE HEIGHT & RAKE	ORANGE	replaced cover with new item from stock. replaced 1 x dash light with new item from stock.	904558
881	07/06/2023	1124617	Mechanic entered -	Body Drivers Seat Controls Seat Raise Cov		904558
881	07/06/2023	1124617	Consumables			904558
881	07/05/2023	1124259	Vandalism Graffiti Interior	AUDIT# 913 OAK 5/7/23		904376
881	06/26/2023	1122047			repaired n/s/f brake slack adjust and replaced both front brake linings and replaced both rear brake linings and replaced both rear brake durms and adjust all brake linings and retorqued both rear wheel nuts road tested all ok.	902414
881	06/26/2023	1122047	LOCK RING BRAKE SHOE PIN SCANIA L94UB	0804782		902414
881	06/26/2023	1122047	SPRING BRAKE RETURN SCANIA L94	1309465		902414
881	06/23/2023	1122047	Workshop Tablet Entered -Brakes -	Foot_Brakes Noisy	removed wheels drums and Brake Linings.	902414
881	06/23/2023	1122047	Workshop Tablet Entered -Brakes -	Foot_Brakes Pulling	double entry	902414
881	06/23/2023	1122047	front and rear brakes sent to commercial brake and clutch		O345543	902414
881	06/23/2023	1122047	DIRECT PURCHASE -	BRAKES	Creditor #:VB-COM100 COMMERCIAL BRAKE & CLUTCH P/O #:O345543 Receiving #:363366 Date :2023-06-26 reline brake linings x 4 machine drums replaced brake shoe rollers x 4 as required	902659
881	06/19/2023	1121197	Driver Tablet Entered -Brakes -	Foot_Brakes Noisyload squea	Wash all wheels brake dust adjusted brakes and road tested for noisy brakes found okay	901961
881	06/19/2023	1121197	Drv entered -	Brakes Foot_Brakes Noisy	Checked and carried out repairs	901961
881	06/16/2023	1120740	PTI Tablet Entered -Brakes -	Foot_Brakes Noisy	road tested bus . found brake noise to be servicable	901480
881	06/06/2023	1118792	When using indicators high beam comes on		fit new blinker stalk.	899742
881	06/06/2023	1118792	SWITCH INDICATOR STALK SCANIA L94	1402448		899742
881	06/06/2023	1118792	Consumables			899742
881	05/16/2023	1114705			VEHICLE SAFETY INSPECTION	896163
881	05/16/2023	1114705			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	896163
881	05/16/2023	1114763	Mechanic entered -	Engine Other engine belt pulley idler bea	replaced engine belt pulley idler bearing x2 ok.	896163
881	05/16/2023	1114763	PULLEY IDLER PLASTIC GROOVED SCANIA L94	1514087		896163
881	05/16/2023	1114763	PULLEY IDLER SCANIA (1413875)			896163
881	05/16/2023	1114763	Mechanic entered -	Elec and Light Other dash speedo light no	replaced dash speedo light globe ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Elec and Light Other dash switch light no	replaced dash switch light globe ok.	896163
881	05/16/2023	1114763	Consumables			896163
881	05/16/2023	1114763	Mechanic entered -	Body Other air dryer bracket bolt missing	replaced air dryer bracket bolt ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other o/s/f bus inside top panel scr	tightened o/s/f bus inside top panel screws ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other driver seat back modesty panel	tightened driver seat back modesty panel screws ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other n/s/middle seat bracket bolt l	tightened n/s middle seat bracket bolt ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other o/s middle seat top pins off.	put in o/s middle seat top pins ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other n/s/r modesty panel screws mis	replaced n/s/r modesty panel screws ok.	896163
881	05/16/2023	1114763	Mechanic entered -	Body Other n/s middle staunchion pole bol	tightened n/s middle staunchion pole bolts ok.	896163
881	05/15/2023	1114603	Workshop Tablet Entered -BusMinder -	Unable To Log Inconn	checked with Busminder/Linzee no faults	896163
881	05/15/2023	1114603	Consumables			896163
881	05/02/2023	1111705	PTI Tablet Entered -Elec and Light -	Exterior Lights ns rear	secured nsr clearence light	893506
881	05/02/2023	1111675	Mechanic entered -	Elec and Light Other rebook for battery t	checked load tested all ok and check battery all ok.	893506
881	05/02/2023	1111675	Consumables			893506
881	05/02/2023	1111705	Consumables			893506
881	05/01/2023	1111448	Mechanic entered -	Elec and Light Flat Batteries	jump started and rebooked for battery test	893506
881	05/01/2023	1111448	Consumables			893506
881	04/24/2023	1110369	Workshop Tablet Entered -brake air red displayed	can't get	CHECK AIR GAUGE ALL OK AND CHECK BRAKE PADS ALL 40% BRAKE AIR NOT LEAKS AND ADJUSTED BRAKE LININGS ROAD TESTED ALL OK AND BRAKE TESTED ALL OK. BRAKE TEMP IS N/S/F 20 AND O/S/F 19 AND N/S/R 18 O/S/R IS 17. PARK BRAKE AIR NOT is not leaking . all ok	892594
881	04/20/2023	1109930			test has been done on Feb 2023	892390
881	04/18/2023	1109492	PTI Tablet Entered -Elec and Light -	Exterior Lights os head	Replaced O/S headlight globe and O/S/F bottom park light globe. Checked front lights all ok.	891915
881	04/18/2023	1109492	GLOBE 24V H4 75/70W	HALOGEN		891915
881	04/13/2023	1108515	Mechanic entered -	Elec and Light Two Way Radio N/W.	TRACEFOUND INVERTER U/SFIT NEW INVERTER.	891021
881	04/13/2023	1108515	REDUCER VOLTAGE CONVERTER 24V-12V 7AMP (LARGE STYLE)			891021
881	04/13/2023	1108515	Ops Entered -	Fault - Elec and Light Two Way Radio - Route:	Double entry	891021
881	04/11/2023	1108172	Mechanic entered -	Wheels and Tyres Wheel Nut Retension All	Retensioned both N/S/F and O/S/F wheel nuts to 650nm.	890703
881	04/11/2023	1108172	Consumables			890703
881	04/08/2023	1107912	Mechanic entered -	Wheels and Tyres Other Front tyres need t	Removed front tyres and roated sides for sidewall wear.	890703

881	04/08/2023	1107912	Consumables			890703
881	04/08/2023	1107813		Removed intercooler pressure washed out intercooler and radiator. Refitted intercooler.		890703
881	04/08/2023	1107811		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist.		890703
881	04/08/2023	1107811	OIL SAMPLE KIT AMPOL			890703
881	04/08/2023	1107811	FILTER OIL SCANIA K93 L94 1117285 2059778			890703
881	04/08/2023	1107811	FILTER FUEL SCANIA L94(1372444)			890703
881	04/08/2023	1107811	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			890703
881	04/08/2023	1107811	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814			890703
881	04/08/2023	1107811	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			890703
881	04/08/2023	1107811	O-RING SPINNER FILTER SCANIA L94			890703
881	04/08/2023	1107811	PAPER SPINNER FILTER OIL INSERT SCANIA L94			890703
881	04/08/2023	1107811	WASHER SPIN FILTER SHAFT SCANIA L94			890703
881	04/08/2023	1107811	Consumables			890703
881	04/08/2023	1107811	Consumables			890703
881	04/04/2023	1107163	drivers window hard to open			890703
881	04/04/2023	1107163	Consumables			890703
881	04/04/2023	1107163	Accident REAR bumper bar sprungy.	paint wheels		890703
881	04/04/2023	1107163				890703
881	04/03/2023	1106326		finished fitting 4 wheel arch rubbers/brushes repaired and painted n/s/r bar corner orange started prepping wheels to be painted.		890703
881	04/03/2023	1106326	Consumables			890703
881	03/30/2023	1106326	BRUSH WHEELARCH 75mm 2.5M PER METRE			890703
881	03/30/2023	1106326	RUBBER W/ARCH EXTRUSION(040021)			890703
881	03/30/2023	1106326	WHEEL ARCH RUBBER BACKING P/LENGTH			890703
881	03/30/2023	1106326	Consumables			890703
881	03/30/2023	1106326	Consumables			890703
881	03/29/2023	1106326	Mechanic entered - Body Other n/s/f under rust.			890703
881	03/29/2023	1106326	Mechanic entered - Body Other front and rear door top panel	settop bus in paintshop grinded cracks and mig welded rear door cracks grinded again but cracks can still be seen so i asked gerald to get one of the guys to weldup.		890703
881	03/29/2023	1106326	Mechanic entered - Body Other o/s/r/f mudflap missing.			890703
881	03/29/2023	1106326		booked out 4 wheel arch rubbers brushes and backing strips fit 1 n/s/r.		890703
881	03/29/2023	1106326	Mechanic entered - Body Other front door top body pillar cra			890703
881	03/15/2023	1102973	Consumables			890213
881	03/15/2023	1102973	Body - test	test		890213
881	03/03/2023	1100694	indicators wont cancel	CHECK BLINK STALKOKNEEDS NEW STEERING WHEELSTRIKER WORN. FIT NEW STEERING WHEELBLINKS NOW CANCELLING.		888527
881	03/03/2023	1100694	WHEEL STEERING WHEEL NEW SC	Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O338735 Receiving #:355853 Date :2023-03-03		888868
881	03/02/2023	1098084	AIR CONDITIONING REPAIR	Creditor #.:VB-COLO04 COLD DRIVE PTY LTD P/O #:O337938 Receiving #:356716 Date :2023-03-17 A/C Heating - Not Cooling BUS # 881		890703
881	02/28/2023	1099413	DIRECT PURCHASE - BUS INSPECTI	Creditor #.:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O338326 Receiving #:355589 Date :2023-02-28		888320
881	02/27/2023	1099413		VEHICLE SAFETY INSPECTION		887780
881	02/27/2023	1099413		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		887780
881	02/27/2023	1099413		ANNUAL SAFETY INSPECTION SERIAL # ____ RSI 056564 PASS ____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		887780
881	02/23/2023	1098943	Mechanic entered - Suspension Other Front sway bar bushes wo	Removed and fitted new front sway bar bushes.		887780
881	02/23/2023	1098943	BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081			887780
881	02/23/2023	1098939	Consumables			887780
881	02/23/2023	1098939	Mechanic entered - Elec and Light Interior Lights 1x front s	Replaced fluoro tube. Checked saloon lights all working.		887780
881	02/23/2023	1098971	2nd PRE ASI check	Completed PRE RSI second check.		887780
881	02/20/2023	1098046	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	coldrive found 1 condensor had been crushed by fan he has ordered new parts has bypassed so remaining 3 still working		887124
881	02/20/2023	1098046	Ops Entered - Fault - A/C Heating Not Cooling - Route: 703	repaired by cold drive		887124
881	02/20/2023	1098084	A/C Heating Not Cooling	w/o 1098084 refers		887124
881	02/14/2023	1096493		PRE ANNUAL SAFETY INSPECTION CHECK		886287
881	02/14/2023	1096493		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		886287
881	02/14/2023	1096545	Mechanic entered - Suspension Other o/s/r/f air bag leaks.	removed o/s/r/f air bag and replaced o/s/r/f air bag ok.		886287
881	02/14/2023	1096545	AIRBAG REAR 16MM SCANIA K280UB K310 6714 NP02 40Y2222			886287
881	02/14/2023	1096545	Mechanic entered - Steering Other o/s/f tyre hit from dragli	Adjusted n/s/f axle stop bolt ok.		886287
881	02/14/2023	1096545	Mechanic entered - Body Other bus inside o/s/middle top pane	tightened o/s/middle top panel screws ok.		886287
881	02/14/2023	1096545	Mechanic entered - Body Other n/s/r break glass decal missin	replaced n/s/r break glass decal ok.		886287
881	02/14/2023	1096545	DECAL BREAK GLASS IN EMERGENCY HAMMER RED/CLEAR 120mm SQ			886287
881	02/14/2023	1096545	Mechanic entered - Body Other both middle seat loose.	repaired both middle seat ok.		886287
881	02/14/2023	1096545	Mechanic entered - Body Other rear modesty panel loose.	tightened rear modesty panel ok.		886287
881	02/13/2023	1096216		TRANSMISSION CHECK AS PER CHECK LIST CARRY OUT TRANS CHECK		886287
881	02/13/2023	1096214	Consumables			886287
881	02/13/2023	1096214	Driver Tablet Entered -Elec and Light - Indicators Not Worki	FIT NEW BLINKER STALK.		886287
881	02/13/2023	1096214	SWITCH INDICATOR STALK SCANIA L94 1402448			886287
881	02/04/2023	1084121	Consumables			885208
881	02/04/2023	1084121	Elec and Light (None) door brakes nw	Assisting		885208
881	02/03/2023	1094584	Consumables			885208
881	02/03/2023	1094584	Mechanic entered - Elec and Light Other rear emergency light	Removed cover removed light assembly replaced light assembly with new item from stock fitted new terminals checked for operation ok refitted cover ok.		885208
881	02/03/2023	1094584	LED HATCH ASSY BS200			885208
881	02/03/2023	1094584	o/s/f skid plate bent - LDM confirmed	removed O/S/F Corner lights and panelcut off mangled metal straightened beam as much as possible refitted skidplate tacked on fabricated steel pieces to fill holes and add strength welded all butt joints making several passes allowed to cool cleaned welds painted area allowed to dry refitted corner bumper and reconner		885208
881	02/03/2023	1094584	o/s/f skid plate bent - LDM confirmed	assisted		885208
881	02/03/2023	1094584	Brakes Foot_Brakes Noisy REF WO 1084143	checked for brakes noisey could not fault		885208
881	01/30/2023	1093610	Consumables			884144
881	01/30/2023	1093610	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	Completed retension		884144
881	01/28/2023	1093315		VEHICLE SAFETY INSPECTION		884144
881	01/28/2023	1093315		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		884144
881	01/28/2023	1093317	Consumables			884144
881	01/28/2023	1093321	Consumables			884144
881	01/28/2023	1093317	Mechanic entered - Wheels and Tyres Other both rear tyres ve	removed both rear tyres and replaced both rear tyres ok.		884144
881	01/28/2023	1093317	TYRE 295/80R22.5 RECAP			884144
881	01/28/2023	1093321	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	ok.		884144
881	01/28/2023	1093321	Mechanic entered - Steering Other o/s/f tyre hit from dragli	adjusted n/s front axle stop bolt ok.		884144
881	01/28/2023	1093321	Consumables			884144
881	01/28/2023	1093321	Mechanic entered - Elec and Light Other o/s/middle pax switc	replaced o/s/middle pax switch ok.		884144
881	01/28/2023	1093321	SWITCH STOP YELLOW (62628)(50V2242)			884144
881	01/28/2023	1093321	Mechanic entered - Elec and Light Other dash all light not w	replaced all dash light globe ok.		884144
881	01/28/2023	1093321	Mechanic entered - Body Other n/s/middle seat broken.	repaired n/s/middle seat ok.		884144
881	01/28/2023	1093321	Consumables			884144
881	01/28/2023	1093349		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list		884144
881	01/23/2023	1092392	Consumables			883353
881	01/23/2023	1084121	Elec and Light (None) door brakes nw	suspect shuttle valve for door/foot brake		883353
881	01/23/2023	1092392	Mechanic entered - Elec and Light Other n/s head light globe	replaced n/s/f park lighr globe and head light globe ok.		883353
881	01/23/2023	1092392	GLOBE 24V H4 75/70W HALOGEN			883353
881	01/23/2023	1084121	Consumables			885208
881	01/18/2023	1091655	Drv entered - A/C Heating Not Cooling	Checked A/C For Operation Belts in good order ran A/C started at 23 degrees on controller got temp down to 18 degrees unable to fault.		882688
881	01/12/2023	1084121	Elec and Light (None) door brakes nw	replaced shuttle valve for door brakes tested ok		881947

[illegible]

881	09/16/2022	1070166	Mechanic entered - Elec and Light Other both rear pax switch	replaced both rear pax switch ok.	868223
881	09/16/2022	1070166	YELLOW/RED STOP SWITCH (20485)		868223
881	09/16/2022	1070166	Mechanic entered - Elec and Light Other driver top light len	replaced driver top light lens ok.	868223
881	09/16/2022	1070166	LENS CLEAR HELIA DESIGNLINE LENS		868223
881	09/16/2022	1070210	Mechanic entered - Elec and Light Other dash r.p.m light not	replaced dash r.p.m light globe ok.	868223
881	09/16/2022	1070166	Consumables		868223
881	09/16/2022	1070210	Consumables		868223
881	09/16/2022	1070166	Consumables		868223
881	09/16/2022	1070210	Consumables		868223
881	09/16/2022	1070210	Mechanic entered - Body Other o/s/middle seat top pins off.	put in o/s/middle seat top pins ok.	868223
881	09/16/2022	1070210	Consumables		868223
881	09/05/2022	1067850	Mechanic entered - Body Other Rear passenger seat base plate	Removed n/s rear seat base assy weld both side broken mount plate fit back seat assy	866388
881	09/05/2022	1067850	Consumables		866388
881	09/05/2022	1067850	Consumables		866388
881	09/01/2022	1067217	Mechanic entered - Body Rear_Door Operation Faulty Gets stuc	Adjusted the top roller door alignment on the top lubricate bottom bearing tested found okay	866056
881	09/01/2022	1067217	Consumables		866056
881	09/01/2022	1067217	Consumables		866056
881	08/29/2022	1066426		complete	865340
881	08/22/2022	1064714	Consumables		863727
881	08/22/2022	1064714	Mechanic entered - Elec and Light Exterior Lights FRONT AND	REPLACED LENS X 2	863727
881	08/22/2022	1064714	LENS REVERSE / CLEARANCE LIGHT CLEAR		863727
881	08/22/2022	1064714	Consumables		863727
881	08/22/2022	1064689		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	863727
881	08/04/2022	1060227	Engine Low Power	removed accelerator pedal assy and replaced with new one. hooked up SD2 and had throttle 100% with kickdown as well. road tested and had eng power. all good.	861315
881	08/01/2022	1060227	ACCELERATOR PEDAL SCANIA L94	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O326098 Receiving #:342634 Date :2022-08-04	861315
881	08/01/2022	1060227	Ops Entered - Fault - Engine Low Power - Route: S1026 - Ce	PARTS ORDERED AS PER KPS REQUEST	860358
881	08/01/2022	1060272	Brakes (None) not good written up in pti sheet	done on wo1060206	860358
881	07/30/2022	1060280	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	860358
881	07/30/2022	1060227	Engine Low Power	checked and found throttle pedal does not go down fully to 100% only 70%. need throttle pedal assy	860358
881	07/30/2022	1060206	Ops Entered - Fault - Brakes Footbrakes Leaking Air - Route	adjust brakesroad and brake testok.	860358
881	07/29/2022	1059970		VEHICLE SAFETY INSPECTION	860358
881	07/29/2022	1059970		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	860358
881	07/29/2022	1060009	Mechanic entered - Suspension Other n/s/r/ air bag fitting l	removed n/s/r/r air bag fitting replaced n/s/r/r air bag fittingconnector.	860358
881	07/29/2022	1060009	Mechanic entered - Gearbox Driveline Other gearbox oil filte	replaced trans oilfilter ok.	860358
881	07/29/2022	1060009	ELBOW FITTING TWIN 16MM RR AIRBAG SCANIA L94UAB		860358
881	07/29/2022	1060009	CONNECTOR ELBOW-MALE SWIVEL 12MM x 16MM		860358
881	07/29/2022	1060009	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		860358
881	07/29/2022	1059970	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		860358
881	07/29/2022	1060009	Consumables		860358
881	07/29/2022	1060009	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok.	860358
881	07/29/2022	1060009	Consumables		860358
881	07/29/2022	1060009	Consumables		860358
881	07/29/2022	1060009	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		860358
881	07/29/2022	1060009	Mechanic entered - Body Other rear modesty panel loose.	repaired rear modesty panel ok.	860358
881	07/29/2022	1060009	Mechanic entered - Body Other driver seat belt buckle u/s.	replaced driver seat belt buckle ok.	860358
881	07/29/2022	1060009	Mechanic entered - Body Other n/so/s bus inside top panel s	tightened n/so/s top panel screws ok.	860358
881	07/29/2022	1060009	Consumables		860358
881	07/29/2022	1060009	Mechanic entered - Air System Other n/s/f air hose hit from	replaced n/s/f air hose fittingcable tie ok.	860358
881	07/16/2022	1057561		TRANSMISSION CHECK AS PER CHECK LIST CARRY OUT TRANS CHECK.	858194
881	07/02/2022	1054993	SWITCH INDICATOR STALK SCANIA L94 1402448		855527
881	07/02/2022	1054993	Mechanic entered - Elec and Light Other INDICATOR SWITCH U/S	replaced indicator stalk	855527
881	07/02/2022	1054995	Driver Tablet Entered -LEFT INDICATOR STALK SWITCH IS SO STI	double entry	855527
881	07/02/2022	1054993	Consumables		855527
881	07/02/2022	1054995	Consumables		855527
881	07/02/2022	1054993	Consumables		855527
881	07/02/2022	1054995	Consumables		855527
881	07/02/2022	1054986	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		855527
881	07/02/2022	1054986		CARRY OUT C SERVICE AS PER CHECK LIST	855527
881	07/02/2022	1054986	FILTER FUEL SCANIA L94(1372444)		855527
881	07/02/2022	1054986	FILTER AIR OUTER SCANIA SR 3 & 4(395773)(AF25066)		855527
881	07/02/2022	1054986	OIL SAMPLE KIT AMPOL		855527
881	07/02/2022	1054986	FILTER OIL SCANIA K93 L94(1117285)(2059778)		855527
881	07/02/2022	1054986	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		855527
881	07/02/2022	1054986	FILTER HYD COOLING FAN SCANIA SR3 4(1354074)		855527
881	07/02/2022	1054986	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)		855527
881	07/02/2022	1054986	FILTER AIR DRYER SCANIA VOLVO(1393551)(20546795)(20424148)		855527
881	07/02/2022	1054986	PAPER SPINNER FILTER OIL INSERT SCANIA L94		855527
881	07/02/2022	1054986	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814		855527
881	07/02/2022	1054986	O-RING SPINNER FILTER SCANIA L94		855527
881	07/02/2022	1054986	FILTER FUEL CHASSIS SCANIA L94 UB(1393640)(PSD470/1)		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	07/02/2022	1054986	Consumables		855527
881	06/28/2022	1054163		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O324064 carried out by cammy from cold drive	854734
881	06/28/2022	1054163	MOUNT A/C COMPRESSOR LARGE DENSO		854734
881	06/28/2022	1054163	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O324064 Receiving #:340380 Date :2022-07-01 24 month service	855527
881	06/28/2022	1054163		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O324064 carried out by cammy from cold drive	854734
881	06/27/2022	1053805	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque o/s/f wheel nuts.	854734
881	06/27/2022	1053805	Consumables		854734
881	06/27/2022	1053805	Consumables		854734
881	06/25/2022	1054029	Vandalism Vandalism/ Graffiti Interior	carried out vandelisem painting as required	854734
881	06/24/2022	1053692	Mechanic entered - Brakes Foot_Brakes Noisy	Checked front wheels for noisy adjusted both the brakes replaced pos 2 wheel as for wheel shudder Road tested and found okay	854734
881	06/24/2022	1053692	TYRE 295/80R22.5 NEW		854734

881	06/22/2022	1053304	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced headlight and park light globe. Checked all ok.	854264
881	06/22/2022	1053304	Consumables		854264
881	06/22/2022	1053304	Consumables		854264
881	06/21/2022	1052923	Glass Protect to complete Stage 2 on Audit 721	CARRIED OUT BY GLASS PROTECT - O323668	853910
881	06/21/2022	1052923	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O323668 Receiving #:339694 Date :2022-06-22 GLASS FILM REPLACEMENT AUDIT 721 - STAGE 2	854264
881	06/21/2022	1052412	Suspension (None) FRONT SWAY BAR TO REPLACE REF WO 1050760	removed worn sway bar replaced with new item replaced split pins and checked for tightness all ok roadtested checked for noises or anything untoward all passed.	853910
881	06/17/2022	1052412	SWAY (ANTI ROLL) BAR FRT SCA	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O323512 Receiving #:339474 Date :2022-06-20	853910
881	06/14/2022	1051776	Mechanic entered - Elec and Light Exterior Lights O/S/R clea	Checked bus found broken wire. Reconnected wire and checked all okay.	852765
881	06/14/2022	1051776	Consumables		852765
881	06/14/2022	1051776	Consumables		852765
881	06/10/2022	1051208	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque n/s/r wheel nuts.	852115
881	06/10/2022	1051208	Consumables		852115
881	06/10/2022	1051208	Consumables		852115
881	06/09/2022	1050760	AIRBAG FRONT SCANIA K310UB E5 40Y2248 40Y2223		852115
881	06/08/2022	1050920	Mechanic entered - Wheels and Tyres Damaged Pos 3 tyre side	Replaced pos 3 wheel with a run out wheel	852115
881	06/08/2022	1050920	Consumables		852115
881	06/08/2022	1050920	Consumables		852115
881	06/08/2022	1050895	Mechanic entered - Suspension Other V rod u/s.	Removed and fitted new V rod	852115
881	06/08/2022	1050895	V STAY ASSEMBLY SCANIA L94UAB		852115
881	06/08/2022	1050760		Assisted by - Sadid	852115
881	06/08/2022	1050760	Mechanic entered - Suspension Other n/s/f air bag air leaks.	Replaced n/s/f air bag with genuine one	852115
881	06/08/2022	1050895	BOLT V STAY ASSY CENTRE BUSH SCANIA L94		852115
881	06/08/2022	1050760	Mechanic entered - Suspension Other n/s/f air bag air leaks.	ordered	852115
881	06/08/2022	1050760	Mechanic entered - Suspension Other front sway bar u/s.	ordered	852115
881	06/07/2022	1050443		VEHICLE SAFETY INSPECTION	852115
881	06/07/2022	1050443		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	852115
881	06/07/2022	1050472	Mechanic entered - Suspension Other n/s/r/r shock oil leaks.	removed o/s/r/r shock replaced o/s/r/r shock ok.	852115
881	06/07/2022	1050472	SHOCK ABSORBER REAR SCANIA L94/K124 300 025 1478317		852115
881	06/07/2022	1050472	Mechanic entered - Steering Other dragline hit from to the b	adjusted dragline ok.	852115
881	06/07/2022	1050472	Mechanic entered - Engine Other engine belt tensioner u/s.	replaced engine belt tensioner.	852115
881	06/07/2022	1050472	TENSIONER BELT SCANIA SR4(1859654)(1503113)		852115
881	06/07/2022	1050472	SWITCH ENGINE BAY START INHIBITOR		852115
881	06/07/2022	1050472	Mechanic entered - Elec and Light Exterior Lights front step	replaced globe. all checked and tested ok	852115
881	06/07/2022	1050472	Mechanic entered - Elec and Light Interior Lights speedo lig	replaced globe. all checked and tested ok	852115
881	06/07/2022	1050472	Mechanic entered - Elec and Light Interior Lights rear saloo	replaced globe. all checked and tested ok	852115
881	06/07/2022	1050472	Mechanic entered - Elec and Light Other rear engine hatch sw	replaced engine hatch switch ok.	852115
881	06/07/2022	1050472	Consumables		852115
881	06/07/2022	1050472	Consumables		852115
881	06/07/2022	1050472	Mechanic entered - Body Other disabled seat top pin loose	refitted loose pin. all checked ok	852115
881	06/07/2022	1050472	Mechanic entered - Body Passenger Seat Torn rear seat ripped	replaced seat base. all checked ok	852115
881	06/07/2022	1050472	SEAT CUSH SINGLE CEN CRV CA		852115
881	06/07/2022	1050472	Mechanic entered - Body Other front door handle loose.	tightened front door handle screws ok.	852115
881	06/07/2022	1050472	Mechanic entered - Body Other disabled seat top pin loose	tightend	852115
881	06/07/2022	1050472	Mechanic entered - Body Other bus inside o/s top panel all s	replaced bus inside o/s top panel screws ok.	852115
881	06/07/2022	1050472	Mechanic entered - Body Other air dryer bracket bolt missing	replaced air dryer bracket boli ok.	852115
881	06/07/2022	1050472	Consumables		852115
881	06/01/2022	1040762	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		850884
881	05/28/2022	1048880	Mechanic entered - Engine Low Power	road testcould not fault.	849883
881	05/12/2022	1045928	Ops Entered - Fault - Engine Low Power - Route: 703 - Lunta	Double entry	847299
881	05/12/2022	1045928	Ops Entered - Fault - Brakes Foot_Brakes Leaking Air - Rout	Checked all the brake linings checked for air leaks adjusted all the brakes road tested found okay	847299
881	04/27/2022	1042567	Ops Entered - Fault - Body Drivers Seat Controls - Route:	Driver complained the seat is not high enough. Tested seat sinks under load. Changed stiffness setting on seat to hold height under load. Checked all ok.	844717
881	04/27/2022	1042567	Consumables		844717
881	04/27/2022	1042567	Consumables		844717
881	04/26/2022	1041915	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retoeque n/s/r wheel nuts.	844117
881	04/26/2022	1041918	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s/	retorque n/s/r wheel nuts.	844117
881	04/26/2022	1042177	Mechanic entered - Wheels and Tyres Wheel Nut Retension Both	Retensioned both front wheels to 650nm with Sadid.	844117
881	04/26/2022	1041915	Consumables		844117
881	04/26/2022	1041918	Consumables		844117
881	04/26/2022	1042177	Consumables		844117
881	04/26/2022	1041915	Consumables		844117
881	04/26/2022	1041918	Consumables		844117
881	04/26/2022	1042177	Consumables		844117
881	04/26/2022	1042208	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	complete	844117
881	04/22/2022	1041854	Mechanic entered - Wheels and Tyres Worn N/S/R inner tyre wo	Removed and fitted run out tyre for position 4. Tensioned all wheel nuts.	844117
881	04/22/2022	1041854	Consumables		844117
881	04/22/2022	1041854	Consumables		844117
881	04/22/2022	1041647	Body (None) INTERIOR MIRROR BROKEN	FITTED A SECOND HAND ONE OK	844117
881	04/22/2022	1041647	Consumables		844117
881	04/22/2022	1041647	Consumables		844117
881	04/14/2022	1040733		VEHICLE SAFETY INSPECTION	843580
881	04/14/2022	1040733		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	843580
881	04/14/2022	1040762	Mechanic entered - Wheels and Tyres Other Front wheel must r	Removed and swapped N/S and O/S tyres for sidewall wear. Refitted wheels and tensioned all wheel nuts.	843580
881	04/14/2022	1040762	Consumables		843580
881	04/14/2022	1040762	Consumables		843580
881	04/14/2022	1040762	Mechanic entered - Suspension Other N/S/R/R airbag and O/S/R	Removwed and fitted new airbags.	843580
881	04/14/2022	1040762	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290		843580
881	04/14/2022	1040762	Mechanic entered - Brakes Other N/S/R brake booster diaphrag	Removed and fitted new brake booster. Adjusted brakes and brake tested all okay.	843580
881	04/14/2022	1040762	BRAKE BOOSTER NSR SCANIA 4 SERIES(1446053)		843580
881	04/07/2022	1039637	thermostat cooler hose u/s	replaced hose . topped up coolant . road tested . all ok	842156
881	04/07/2022	1039637	HOSE COOLING SCANIA L94UAB 0481886		842156
881	03/07/2022	1033535	Elec and Light (None) front doorm buttons nw 50% of time -	replace front door botton switch ok.	836036
881	03/07/2022	1033535	SWITCH EMERGENCY PUSH BUTTON RED HINO FD240 55CXXX0282		836036
881	03/07/2022	1033535	Consumables		836036
881	03/07/2022	1033535	Consumables		836036
881	03/07/2022	1033733	Mechanic entered - Body Front_Door Operation Faulty Wont ope	Checked and replaced switch and found working okay	836036
881	03/07/2022	1033733	SWITCH DOOR CONTACT (NORMALLY OPEN)		836036
881	03/07/2022	1033733	Consumables		836036
881	03/07/2022	1033733	Consumables		836036
881	03/01/2022	1032146	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O316888 Receiving #:332509 Date :2022-03-02	835284
881	02/28/2022	1032146		VEHICLE SAFETY INSPECTION	835284
881	02/28/2022	1032146		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	835284
881	02/28/2022	1032146		ANNUAL SAFETY INSPECTION SERIAL # ___RSI 041096B GREEN SHEET _WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	835284
881	02/25/2022	1031818		complete	835018

881	02/25/2022	1031818		CARRY OUT FIRE EXTINGUISHER TEST & TAG		835018
881	02/24/2022	1030197	Consumables			834891
881	02/24/2022	1030197	Elec and Light	Indicators Not cancelling	fit new steering wheel.	834666
881	02/24/2022	1030197	Consumables			834891
881	02/24/2022	1031408	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S		complete	834666
881	02/22/2022	1030197	STEERING WHEEL SCANIA K N SERI		Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O316501 Receiving #:332041 Date :2022-02-24	834891
881	02/21/2022	1030197	Elec and Light	Indicators Not cancelling	steering striker worn needs a new wheel	834220
881	02/21/2022	1030068	Consumables			834220
881	02/21/2022	1030068	Consumables			834220
881	02/21/2022	1030068	OIL SAMPLE KIT AMPOL			834220
881	02/21/2022	1030068			CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order all check ok	834220
881	02/21/2022	1030068	FILTER FUEL SCANIA SR4(1372444)			834220
881	02/21/2022	1030068	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			834220
881	02/21/2022	1030068	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			834220
881	02/21/2022	1030068	O-RING SPINNER FILTER SCANIA L94			834220
881	02/21/2022	1030068	PAPER SPINNER FILTER OIL INSERT SCANIA L94			834220
881	02/21/2022	1030068	FILTER OIL SCANIA S4 & K			834220
881	02/21/2022	1030068	Consumables			834220
881	02/21/2022	1030068	Consumables			834220
881	02/21/2022	1030068	Consumables			834220
881	02/19/2022	1029934	Consumables			834220
881	02/19/2022	1029934	Mechanic entered - Elec and Light Exterior Lights o/s/f/t pa		fit globe.	834220
881	02/19/2022	1029934	Consumables			834220
881	02/16/2022	1029420	Consumables			833714
881	02/16/2022	1029420	Mechanic entered - Body Other Interior passenger mirror loos		Tightened mirror.	833714
881	02/16/2022	1029420	Consumables			833714
881	02/14/2022	1028540	Consumables			832751
881	02/14/2022	1028540	Mechanic entered - Elec and Light Other n/s head light globe		replaced n/s/head light globen/s/f park light globe ok.	832751
881	02/14/2022	1028540	GLOBE 24V H4 75/70W HALOGEN			832751
881	02/14/2022	1028540	Consumables			832751
881	02/12/2022	1028492	Consumables			832751
881	02/12/2022	1028492	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/		retorque o/s/f wheel nuts.	832751
881	02/12/2022	1028492	Consumables			832751
881	02/12/2022	1028494	Mechanic entered - Body Other inside mirror loose.		mirror clamp u/sfit good second hand mirror.	832751
881	02/12/2022	1028494	Consumables			832751
881	02/12/2022	1028494	Consumables			832751
881	02/11/2022	1028472	Consumables			832751
881	02/11/2022	1028472	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/		Retensioned O/S/F wheel nuts.	832751
881	02/11/2022	1028472	Consumables			832751
881	02/11/2022	1028471	Consumables			832751
881	02/11/2022	1028471	Mechanic entered - Body Other Interior mirror loose		Tightened mirror.	832751
881	02/11/2022	1028471	Consumables			832751
881	02/09/2022	1027662			VEHICLE SAFETY INSPECTION carried out safety inspection	832248
881	02/09/2022	1027662			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	832248
881	02/09/2022	1027681			PRE ANNUAL SAFETY INSPECTION CHECK Carried out Pre ASI	832248
881	02/09/2022	1027681			CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	832248
881	02/09/2022	1027805	Consumables			832248
881	02/09/2022	1027805	TYRE 295/80R22.5 NEW			832248
881	02/09/2022	1027805	Mechanic entered - Wheels and Tyres Worn O/S/F Tyre U/S - 3m		removed worn tyre replaced with new item from stock.	832248
881	02/09/2022	1027805	Consumables			832248
881	02/09/2022	1027773	BUSH RR SWAY BAR 50mm I/D SCANIA K93CRB(228483)			832248
881	02/09/2022	1027773	Mechanic entered - Suspension Other rear sway bar 'D' Bushes		removed worn 'D' Rubbers replaced with new items from stock.	832248
881	02/09/2022	1027773	Consumables			832248
881	02/09/2022	1027773	YELLOW/RED STOP SWITCH (20485)			832248
881	02/09/2022	1027773	Mechanic entered - Body Other 3x Pax Switches U/S - cracked		replaced 3 x cracked pax switches with new item from stock.	832

881	11/06/2021	1009791	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		815435
881	11/06/2021	1009791	Consumables		815435
881	11/06/2021	1009791	Consumables		815435
881	11/05/2021	1009558		VEHICLE SAFETY INSPECTION	815435
881	11/05/2021	1009558		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	815435
881	11/05/2021	1009581	Mechanic entered - Steering Other POWER STEERING PIPE HIT FR	put in hose tightened cable tie ok.	815435
881	11/05/2021	1009581	Mechanic entered - Fluid Leaks Other TRANSMISSION REAR BACK	removed transmission back cover replaced transmission back cover oring ok.	815435
881	11/05/2021	1009581	Mechanic entered - Elec and Light Other DASH R.P.M LIGHT NOT	replaced dash R.P.M light globe ok.	815435
881	11/05/2021	1009581	Mechanic entered - Elec and Light Other O/S/MIDDLE PAX SWITC	replaced o/s/middle pax switch ok.	815435
881	11/05/2021	1009581	YELLOW/RED STOP SWITCH (20485)		815435
881	11/05/2021	1009581	Consumables		815435
881	11/05/2021	1009581	Mechanic entered - Body Other O/S MIDDLE SEAT VERY LOOSE.	repaired o/s/middle seat ok.	815435
881	11/05/2021	1009581	Mechanic entered - Body Other REAR MODESTY PANEL SCREWS.	replaced rear modesty panel screws ok.	815435
881	11/03/2021	1009021	Mechanic entered - Elec and Light Other battery low.	checked battery is 10vt8vt.battery u/s please. brttery jumped.	815047
881	11/03/2021	1009155	Mechanic entered - Elec and Light Other Indicator not cancel	Steering wheel canceling spacer missing. Attached and secured a spare spacer. Checked now canceling.	815047
881	11/03/2021	1009120	Mechanic entered - Elec and Light Flat Batteries	Replaced flat battery. Checked and bus started.	815047
881	11/03/2021	1009120	BATTERY 1030CCA POS ON LHS(EMFN150L)		815047
881	11/03/2021	1009021	Consumables		815047
881	11/03/2021	1009120	Consumables		815047
881	11/03/2021	1009155	Consumables		815047
881	11/03/2021	1009152	Ops Entered - Fault - Air System Air Not Building_ Up - Rou	checked air system for leaks at compressor . checked brakes for air leaks. dumped air and built up air 10 times . road tested . could not fault air not building up	815047
881	10/29/2021	1008568	Mechanic entered - Vandalism Vandalism/ Graffiti Interior On	Masked around vandalism and spray painted over graffiti	814623
881	10/26/2021	1007801	Mechanic entered - Elec and Light Exterior Lights O/S/F top	Replaced globe	813849
881	10/26/2021	1007801	Consumables		813849
881	10/19/2021	1006444	Mechanic entered - Elec and Light Other Rear engine hatch sw		812361
881	10/19/2021	1006444	Consumables	Remove switch bump plate cut it short and rivet back	812361
881	10/06/2021	1003994	Mechanic entered - Body Other Rear door step mirror and mirr	Fitted 2nd hand mirror from spare parts. Fitted and check if mirror was at a correct angle.	809521
881	10/06/2021	1003994	Consumables		809521
881	09/28/2021	1002104	Consumables		807730
881	09/28/2021	1002104	Elec and Light Interior Lights dash gauges nw	fitted a second hand cluster that had electrical plug fault. tested ok	807730
881	09/23/2021	1001383	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	Completed retension	806940
881	09/23/2021	1001383	Consumables		806940
881	09/21/2021	1001100	Mechanic entered - Elec and Light Indicators Not Working O/S	Replaced led light assy	806694
881	09/21/2021	1001100	LAMP LED TURN		806694
881	09/21/2021	1001100	Consumables		806694
881	09/20/2021	1000507		VEHICLE SAFETY INSPECTION	806273
881	09/20/2021	1000507		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	806273
881	09/20/2021	1000547	Mechanic entered - Wheels and Tyres Worn Both o/s/r tires wo	chnaged both o/s/r tires with new ones	806273
881	09/20/2021	1000547	TYRE 295/80R22.5 RECAP		806273
881	09/20/2021	1000547	Consumables		806273
881	09/20/2021	1000547	AIRBAG FRT 14MM SCANIA K310UB E5 2024284 2809671 2024289		806273
881	09/20/2021	1000547	LINK FRT SWAY BAR SCANIA L94 1766014 0463245 20486 01		806273
881	09/20/2021	1000547	Mechanic entered - Suspension Other n/s/f sway bar link u/s.	removed n/s/f sway bar link replaced n/s/f sway bar link ok.	806273
881	09/20/2021	1000547	Mechanic entered - Suspension Other both front air bags u/s	removed both front air bag replaced both front air bags x2 ok.	806273
881	09/20/2021	1000547	Mechanic entered - Steering Other power steering oil tank ho	PO#: O307360 for Enzed; removed power steering hose replaced power steering hose ok.	806273
881	09/20/2021	1000547	make power steering hose as re	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O307360 Receiving #:322517 Date :2021-09-28 rectify/fabricate a PS hose as required	807979
881	09/20/2021	1000547	Mechanic entered - Elec and Light Next Stop Button 5 rear st	Replaced all broken stop button switch	806273
881	09/20/2021	1000547	YELLOW/RED STOP SWITCH (20485)		806273
881	09/20/2021	1000547	Mechanic entered - Elec and Light Other dash R.P.M gauge lig	replaced dash R.P.M light globe ok.	806273
881	09/20/2021	1000547	Consumables		806273
881	09/20/2021	1000547	Mechanic entered - Body Other REAR DOOR TOP LOOSE.	repaired rear door top ok.	806273
881	09/20/2021	1000547	Mechanic entered - Body Other n/s/mirror very loose.	repaired n/s/mirror bracket nut replaced n/s/mirror bracket bolts ok.	806273
881	09/20/2021	1000547	Mechanic entered - Body Other driver seat back modesty panel	repaired driver seat back modesty panel ok.	806273
881	09/20/2021	1000547	Mechanic entered - Body Other n/s/mirror loose.	repaired n/s/mirrr bracket nut replaced n/s/mirror bracket bolts ok.	806273
881	09/20/2021	1000547	Consumables		806273
881	09/16/2021	1000088	Ops Entered - Fault - Body Drivers Seat Controls - Route: 7	Removed cover found return spring for back rest control to be broken nil stock of spring replaced seat with item from bodyshop fitted seat replaced base cushion with original seat item and applied seat belt and buckle checked for operation all ok PO#: O307240 for RP uphols.	806103
881	09/16/2021	1000088	Consumables		806103
881	09/11/2021	998907		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	805128
881	09/07/2021	997624	Mechanic entered - Brakes Other pulling to right.	adjust brakesroad and brake testok.	804182
881	09/02/2021	996547	Mechanic entered - Air System Other	AIR COMPERSSOR TO AIR DRYER AIR FITTING HOSE OFF repaired AIR DRYER TO AIR COMPERSSOR FITTING OK. removed AIR DRYER replaced AIR DRYERCHECK AIR DRYER TO AIR COMPERSSOR HOSE AIR WORKING AFTER AIR DRYER AIR DUMPING OK. ROAD TESTED OK.	802841
881	09/02/2021	996547	AIR DRYER ASSY SCANIA 1743859 0470200		802841
881	09/01/2021	995899	Consumables		802841
881	09/01/2021	995899	Some sort of noise coming from the rear of the bus.	Removed and replaced air compressor replaced drier filter fixed signal line from drier to air compressor wash and road test	802841
881	09/01/2021	995899	FILTER AIR DRYER SCANIA VOLVO 1393551 20546795 20424148		802841
881	09/01/2021	995899	HOSE TO TOP COMPRESSOR L94UB(205118)		802841
881	09/01/2021	995899	Mechanic entered - Air System Other rear wheel noisy.	Noise from air drier due to blown signal line	802841
881	09/01/2021	995899	AIR COMPRESSOR - WITH REAR COVER PLATE		802841
881	09/01/2021	995899	BOLT COMPRESSOR GEAR SCANIA		802841
881	09/01/2021	995899	O-RING COMPRESSOR 11MM ID SCANIA L94UB 1871043 1376911		802841
881	09/01/2021	995899	SEAL O-RING COMPRESSOR MOUNT SCANIA L94 (323790)		802841
881	08/31/2021	995899	Mechanic entered - Air System Other rear wheel noisy.	road tested after check rear wheel all okcheck air comperssor noisy from to the air comperssor top pressure relief valve air comperssor head gasket air leaksair comperssor check valve hose burn.	802841
881	08/31/2021	996034	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	carried out campaign on 27/08/2021	802841
881	08/28/2021	995380	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Carried out Retorque	802841
881	08/28/2021	995390	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	DONE ON WO995380	802841
881	08/28/2021	995390	Consumables		802841
881	08/28/2021	995380	Consumables		802841
881	08/27/2021	995048	Mechanic entered - Wheels and Tyres Other n/s/f tyre u/s.	removed n/s/e tyre replaced n/s/f tyreretorqued n/s/f wheel nuts ok. road tested all ok.	802841
881	08/27/2021	995048	TYRE 295/80R22.5 NEW		802841
881	08/27/2021	995048	Consumables		802841
881	08/26/2021	994268	Mechanic entered - Air System Air_Leak Rear	fit new compressure signal line fitting and hoseroad testok.	802841
881	08/26/2021	994268	UNION ASSY		802841
881	08/24/2021	994268	Mechanic entered - Air System Air_Leak Rear	remove broken compressor signal line fittingorder part.	802495
881	08/20/2021	993616		CARRY OUT FIRE EXTINGUISHER TEST & TAG	802177
881	08/20/2021	993616		complete	802177
881	08/07/2021	990573		VEHICLE SAFETY INSPECTION	799325
881	08/07/2021	990573		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	799325
881	08/07/2021	990602	Mechanic entered - Vandalism Vandalism/ Graffiti Exterior n	film has been changed	799325
881	08/07/2021	990597	Dash speedo head globe not working x 1	replaced globe	799325
881	08/07/2021	990599	passenger stop button not working x 3	replaced stop button x 3	799325
881	08/07/2021	990599	YELLOW/RED STOP SWITCH (20485)		799325
881	08/07/2021	990600	saloon fluro not working x 1	replaced globe . checked operation all okay	799325
881	08/07/2021	990597	Consumables		799325
881	08/07/2021	990599	Consumables		799325

881	08/07/2021	990600	Consumables			799325
881	08/07/2021	990598	drivers modesty panel loose	secured with rivot		799325
881	08/07/2021	990601	disabled hinge pin off x 2	secured pins		799325
881	08/07/2021	990598	Consumables			799325
881	08/07/2021	990601	Consumables			799325
881	08/06/2021	990225				799325
881	07/29/2021	988576	Mechanic entered - Elec and Light Other N/S/R SALOON LIGHT N	TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.		797917
881	07/29/2021	988722	Mechanic entered - Elec and Light Interior Lights 1x N/S/R	replaced N/S/R SALOON LIGHT TUBE OK.		797917
881	07/29/2021	988576	Consumables	repaired on work order - 988576		797917
881	07/29/2021	988722	Consumables			797917
881	07/27/2021	985848	REVERSE INCORRECT CREDITOR COD	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:O302878REV Receiving #:317780 Date :2021-07-27		797647
881	07/26/2021	987690	Mechanic entered - Fluid Leaks Other trans oil leaks.	check trans difstick oil top drain trans oil after check ok. road tested ok. cleaned trans wash ok.		796982
881	07/19/2021	986571	Mechanic entered - Elec and Light Indicators Not Working O/S	Replaced globe		795895
881	07/19/2021	986571	Consumables			795895
881	07/19/2021	986341				795895
881	07/19/2021	986341	OIL SAMPLE KIT CALTEX	CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order all ok		795895
881	07/19/2021	986341	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			795895
881	07/19/2021	986341	FILTER FUEL FILTER SCANIA SR4 (1372444)			795895
881	07/19/2021	986341	FILTER OIL SCANIA S4 & K			795895
881	07/19/2021	986341	AIR FILTER OUTER SCANIA SR 3 & 4 395773 AF25066			795895
881	07/19/2021	986341	Consumables			795895
881	07/15/2021	984486	Vandalism/ Graffiti Interior G	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O302474 Receiving #:317482 Date :2021-07-22 bus 881 Completed 5/7/21		796714
881	07/15/2021	985848		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O302878 carried out by cold drive jimmy		795290
881	07/15/2021	985848	DIRECT PURCHASE - AIR CONDITIO	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:O302878 Receiving #:317499 Date :2021-07-22 carry out 12 month a.c service as required		796714
881	07/15/2021	985848	RE-ENTER WITH CORRECT CREDITOR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O302878A Receiving #:317782 Date :2021-07-27		797647
881	07/12/2021	984841	Mechanic entered - Engine Other dip stick tube not srcure.	secure dip stick tube.		794404
881	07/10/2021	984967	Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required		794404
881	07/09/2021	984584	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean as much as possiblerebook for tomorrow to paint.		794404
881	07/08/2021	984486	Vandalism Interior film Audit 509	O302474 - completed by glass protect		794404
881	06/25/2021	981975	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	retorque n/s/r wheel nuts.		792001
881	06/25/2021	981975	Consumables			792001
881	06/23/2021	981525		VEHICLE SAFETY INSPECTION		791456
881	06/23/2021	981525		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		791456
881	06/23/2021	981594	TYRE 295/80R22.5 RECAP			791456
881	06/23/2021	981594	Mechanic entered - Wheels and Tyres Worn N/S/R/O Tyre U/S -	Removed inner and outer tyre and fitted 2 Recaps from stock inner tyre has 7mm remaining added to runout rack		791456
881	06/23/2021	981594	Consumables			791456
881	06/23/2021	981594	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			791456
881	06/23/2021	981594	Mechanic entered - Suspension Other Front Sway Bar 'D' Bushe	replaced front sway Bar 'D' Rubbers with new items from stock.		791456
881	06/23/2021	981594	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940			791456
881	06/23/2021	981594	Mechanic entered - Engine Other Idler Pulley Noisy	removed drive belt removed old pulley replaced with new pulley from stock.		791456
881	06/23/2021	981594	Mechanic entered - Dash Dash_Lights Not Working 2x Dash Ligh	removed cluster replaced 2 x blown globes checked ok		791456
881	06/23/2021	981594	Mechanic entered - Elec and Light Exterior Lights O/S/F Park	removed headlight assembly replaced blown parker checked Re assembled		791456
881	06/23/2021	981594	Consumables			791456
881	06/23/2021	981594	Mechanic entered - Body Other Front Seat Covid Tape Missing	replaced tape for front seats.		791456
881	06/23/2021	981594	Consumables			791456
881	06/12/2021	979774	n/s headlight n/w	replaced globe. checked operation all okay		789601
881	06/12/2021	979774	Consumables			789601
881	06/08/2021	978878	Mechanic entered - Suspension Leaning	checked and found air system had water. drained and checked for dryer operation ok. rear valve block had noleak but osr leaning asn no air to the bags. suspected osr level control valve. found corrosion due to water entry. cleaned the plug and replaced control valve; tested ok.		788760
881	06/08/2021	978878	LEVEL SENSOR FRT SCANIA L94UAB 481829			788760
881	06/08/2021	978878	Mechanic entered - Suspension Leaning	assisted KPS to carry out job		788760
881	06/03/2021	978206	Ops Entered - Fault - Air System Air Not Building_Up - Rou	removed fitting from compressor head . checked shuttle valve - working ok . make a hose fitting for signal line. road tested . air pressue normal . all ok		787905
881	06/01/2021	977204	Ops Entered - Fault - Air System Air build up very high to 1	replaced 4 way protection valve air drain all air tank checked air bar is okcheck air no leaks ok road tested air gauge is all green okbrake tested ok.		787721
881	06/01/2021	977204	VALVE CIRCUIT PROTECTION SCANI	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O300050 Receiving #:313815 Date :2021-06-01		787905
881	05/31/2021	977204	AIR DRYER ASSY SCANIA 1743859 0470200			787721
881	05/31/2021	977204	Ops Entered - Fault - Air System Air build up very high to 1	CHECKED AIR COMPERSSOR CHECK VALVE AIR NOT LEAKSAIR COMPERSSOR IS OK ADJUSTED AIR DRYER AFTER CHECK AIR GAUGE 12BAR CHECK AIR DRYERBUS UNDER MIDDLE AIR LEAKS.		787721
881	05/31/2021	977204		removed AIR DRYER replaced AIR DRYER removed 4 WAY VALVE.		787721
881	05/29/2021	977204	Ops Entered - Fault - Air System Air build up very high to 1	replaced comperssor hose		787721
881	05/29/2021	977205	VALVE SOLENOID G/BOX ACCUM ZF 0501-318-457			787721
881	05/29/2021	977205	Air System - air gauges dropping to 0 pressure	replaced accum solenoid valve		787721
881	05/25/2021	976326	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG			786757
881	05/25/2021	976326	Mechanic entered - Engine Belts_Loose Noisy Missing altinato	fit new altinator belt.		786757
881	05/12/2021	973951	Mechanic entered - Air System Air_Leak Rear Near drier	Cut and fit joiner to the leaking hose		784182
881	05/06/2021	972779	Mechanic entered - Air System Air_Leak Rear Unloader hose fr	Fitted new nylon tubing to compressor		783268
881	05/01/2021	971620		VEHICLE SAFETY INSPECTION		782296
881	05/01/2021	971620		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		782296
881	05/01/2021	971632	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Be	Cleaned graffiti		782296
881	05/01/2021	971632	CAP CENTRA SEAT END CAP			782296
881	05/01/2021	971632	SLACK ADJUSTER FRONT NEAR SIDE (1789568)			782296
881	05/01/2021	971632	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113			782296
881	05/01/2021	971632	PULLEY IDLER SCANIA (1514087)			782296
881	05/01/2021	971632	CAP EXPANSION TANK 0.75BAR SCANIA K93 L113 1403954			782296
881	05/01/2021	971632	BELT MICRO V SERPENTINE BELT 8 RIB 2130mm LONG			782296
881	05/01/2021	971632	Mechanic entered - Fluid Leaks Rear of bus Leaking from head	replaced header tank cap		782296
881	05/01/2021	971632	Mechanic entered - Engine Other Main belt worn	Remove and replaced belt groove idler pulley and tensioner Fitted new cap		782296
881	05/01/2021	971632	Mechanic entered - Body Other N/S disable seat hinge pin com	Fit back pin		782296
881	05/01/2021	971632	Mechanic entered - Body Other One seat end cap missing	Fitted new cap		782296
881	05/01/2021	971632	Consumables			782296
881	05/01/2021	971632	Mechanic entered - Brakes Other N/S/F slack adjuster worn	Replaced slack adjuster		782296
881	04/08/2021	966692	Mechanic entered - A/C Heating Other n/werror code 1.	disconnectreconnect batterynow working ok.		777984
881	04/07/2021	966462		load tested batteries ok		777984
881	04/07/2021	966462	Mechanic entered - Elec and Light Flat Batteries battery che	double entry		777984
881	04/07/2021	966462	Consumables			777984
881	04/06/2021	966064	Mechanic entered - Elec and Light Flat Batteries	jump start.		777495
881	04/06/2021	966064	Consumables			777495
881	03/30/2021	964754	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	DONE		776797
881	03/26/2021	963756	Place new poster over the top attach hangers to hand rails	complete		776320
881	03/23/2021	962774	Mechanic entered - Vandalism Vandalism/ Graffiti Interior re	clean graffiti all check ok		775928
881	03/23/2021	962774	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean graffiti all check ok		775928
881	03/23/2021	962774	Mechanic entered - A/C Heating Belt Loose or_Missing	tensioned belt		775928
881	03/23/2021	962774	Mechanic entered - Fluid Leaks Rear of bus suspect rear main	carry out wash recheck not leaking as bad recomend insp nxt serv		775928
881	03/23/2021	962774	Mechanic entered - Engine Other spinner filter metal strange	reweld metal straner fitted part all check ok		775928
881	03/23/2021	962774	Mechanic entered - Engine Other hydraulic oil empty	retop up oil level insp for further leaks was no sign further leak		775928
881	03/23/2021	962522	OIL SAMPLE KIT CALTEX			775928

881	03/23/2021	962522		CARRY OUT B SERVICE AS PER CHECK LIST carry out as per work order check ok	775928
881	03/23/2021	962522	SPINNER FILTER KIT ALL SCANIA		775928
881	03/23/2021	962522	FILTER FUEL FILTER SCANIA SR4 (1372444)		775928
881	03/23/2021	962522	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		775928
881	03/23/2021	962522	FILTER OIL SCANIA S4 & K		775928
881	03/23/2021	962522	Consumables		775928
881	03/23/2021	962522	Consumables		775928
881	03/16/2021	959364	K525-10-22-960nm Gas Strut		774974
881	03/16/2021	959364	Consumables		774974
881	03/13/2021	959364	engine hatch struts u/s x 2	replaced struts	774437
881	03/13/2021	960356	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	carried out campaign as per instructions	774437
881	03/10/2021	959364	engine hatch struts u/s x 2	ordered	773969
881	03/05/2021	957790	Air System - air valve leaking	replaced air valve above the front door	773597
881	03/02/2021	958041		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	773060
881	03/02/2021	958041		VEHICLE SAFETY INSPECTION	773060
881	03/02/2021	958041	DIRECT PURCHASE - BUS INSPECTI	Creditor # :VB-FLE001 FLEETCHECK BUS PTY LTD P/O # :O294278 Receiving #:307650 Date :2021-03-04 carry out ASI as required	773332
881	03/02/2021	958041		ANNUAL SAFETY INSPECTION SERIAL# L158272 WORKSHOP SUPERVISOR/MANAGER NOTE:REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO0.25 done by Fleet Check PO#: O294278	773060
881	03/02/2021	958090	Mechanic entered - Elec and Light Exterior Lights N/S HeadLi	Removed Old Headlight assembly and replaced with new item replaced Globes and checked ok. reassembled.	773060
881	03/02/2021	958090	LAMP HEADLAMP MK3 VOLVO B10M		773060
881	03/02/2021	958090	Consumables		773060
881	03/02/2021	957790	Hel-D-Mini Air Valve		773782
881	03/02/2021	957790	Consumables		773782
881	03/01/2021	957731	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	washed engine & chassis for oil leak. tighten sump bolt & long drive testok.	772388
881	03/01/2021	957731	SWITCH INDICATOR SCANIA L94 1402448		772388
881	03/01/2021	957731	Mechanic entered - Elec and Light Indicators Not Working swi	r/r indicator light switchok.	772388
881	03/01/2021	957731	Consumables		772388
881	03/01/2021	957790	Mechanic entered - Body Other n/s/r disable seat bracket had	remove broken bolt retap new tread refit new bolt check ok	772388
881	03/01/2021	957731	Mechanic entered - Air System Air_Leak Rear leaking air from	removed air hose & refitted hoseok.	772388
881	03/01/2021	957790	Air System - air valve leaking	WOP	772388
881	02/25/2021	956828	Consumables		772202
881	02/25/2021	956828	Mechanic entered - Elec and Light Other n/s/f/top park light	replaced n/s/f/top park light globe ok	771580
881	02/24/2021	956546	Consumables		771918
881	02/24/2021	956575	Consumables		771918
881	02/24/2021	956546	Mechanic entered - Body Drivers Seat Controls height adjuste	recalibrate seat height adjusternow ok.	771580
881	02/24/2021	956575	Mechanic entered - Body Drivers Seat Controls not adjusting	recalibrate height adjuster.	771580
881	02/20/2021	955831		VEHICLE SAFETY INSPECTION Carry out safety inspection as required	771298
881	02/20/2021	955831		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	771298
881	02/20/2021	955875	Mechanic entered - Suspension Other Front levelling valve ro	Fit missing rubber packing on clamp	771298
881	02/20/2021	955875	Mechanic entered - Steering Other Power steering fluid leaki	Replaced copper washers for banjo bolt	771298
881	02/20/2021	955875	Consumables		771484
881	02/20/2021	955875	Mechanic entered - Body Other Intercooler cover screws missi	Fitted two new bolts	771298
881	02/20/2021	955875	Mechanic entered - Body Drivers Seat Controls Backrest adjus	Fit handle from a scrap bus	771298
881	02/20/2021	955875	Mechanic entered - Body Other Drivers myki machine rattles	Removed and fitted rubber cushion	771298
881	02/20/2021	955737	Leave old poster in and fit you must wear a maskover the	complete	771298
881	02/16/2021	954042		TRANSMISSION CHECK AS PER CHECK LIST Carried out Trans Check	770413
881	02/16/2021	954396	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM		770413
881	02/16/2021	954396	Mechanic entered - Suspension Other Front 'D' Rubbers U/S	replaced front sway bar 'D' Rubbers	770413
881	02/16/2021	954396	Consumables		770789
881	02/16/2021	954396	Mechanic entered - Elec and Light Other 'D' Gear Selector Bu	replaced button with good second hand part from spares	770413
881	02/16/2021	954396	Consumables		770789
881	02/16/2021	954396	Mechanic entered - Body Other N/S/F Modesty Panel Loose	added bolt washer and nut at base tightened and checked ok	770413
881	02/16/2021	954396	Mechanic entered - Body Other Disabled Seat Top Pins not sea	Re Seated Disabled pins	770413
881	02/16/2021	954396	Mechanic entered - Body Other O/S/F Seat Base Not retained	lifted seat found retainers to be missing used retainers from scrap Bus	770413
881	02/16/2021	954396	Mechanic entered - Body Other Rear Modesty Panel Loose	tightened loose screws in wall and added screws to retain	770413
881	02/15/2021	953777		complete	770413
881	02/15/2021	953777		CARRY OUT FIRE EXTINGUISHER TEST & TAG	770413
881	02/06/2021	951809	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over interior graffiti	768639
881	02/05/2021	951366	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	jhl has done on wo951205 on 04/02/2021	768639
881	02/05/2021	955677	Consumables		769013
881	02/05/2021	955677	Vehicle Mechanical Audit	Completed Audit	768639
881	02/05/2021	951502	Drv entered - Brakes Park_Brake Not Releasing	repaired on work order - 951398	768639
881	02/05/2021	951398	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866		768639
881	02/05/2021	951398	CHECK VALVE SCANIA L113CRL 2274810 448450		768639
881	02/05/2021	951398	Mechanic entered - Brakes Other PARK BRAKE DASH LIGHT ON	removed park brake valvecheck air leaks replaced parke brake valve ok check park brake shuttle valve removed shuttle valve top hose air leake top hose fitting park brake shuttle valve air leaks removed park valve shuttle valve replaced park shuttle valve ok after dash light off ok	768639
881	02/04/2021	951152		PRE ANNUAL SAFETY INSPECTION CHECK done	768639
881	02/04/2021	951152		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	768639
881	02/04/2021	951205	Mechanic entered - Vandalism Other advertising edging rubber	fixed advertising rubberok.	768639
881	02/04/2021	951142	Mechanic entered - Engine Noisy or Rattling eng belt tension	replaced engbelt tensioner idler and roller.	768639
881	02/04/2021	951205	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	fixed leaking oil from damperok.	768639
881	02/04/2021	951142	PULLEY IDLER SCANIA (1514087)		768639
881	02/04/2021	951142	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940		768639
881	02/04/2021	951142	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113		768639
881	02/04/2021	950976	Consumables		769013
881	02/04/2021	950976	LENS CLEAR TO SUIT 1406		768639
881	02/04/2021	950976	Mechanic entered - Elec and Light Other N/S/F step light bro	replaced step lens check ok	768639
881	02/04/2021	951205	Consumables		769013
881	02/04/2021	951205	Mechanic entered - Body Other loose engine bay chassis brake	tighten boltsok.	768639
881	01/30/2021	950017	Consumables		768096
881	01/30/2021	950017	Consumables		768096
881	01/30/2021	950017	Body rear door mirror fallen off and crack	removed mirror from 1179 and fitted ok	767906
881	01/30/2021	950014		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST LIST carried out as per check list	767906
881	01/29/2021	947482	DIRECT PURCHASE ACCIDENT	Creditor # :VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O # :O291425 Receiving #:305048 Date :2021-02-01 # 51629 repairs to n/s mid to rear of bus as required	768096
881	01/25/2021	948908	Mechanic entered - Air System Other front door air leaks	replaced air hose ok	766961
881	01/22/2021	948751	Removed N/S/F window COVID-19 & MYKI decals and reposition	complete	766961
881	01/19/2021	947806	Please fit A3 poster over COVID-19 poster and hangers to be	complete	766961
881	01/18/2021	947482	Accident # 51629 - damage to n/s mid to rear	O291425 - bus was repaired at the bodyshop	766961
881	01/15/2021	947225	Drv entered - Warning Lights Engine	Checked for engine check light could not fault	766649
881	01/14/2021	946563	Engine Low Power THROTTLE CUTS OUT AT TIMES	removefit new foot valveroad and brake testok.	766548
881	01/14/2021	946563	VALVE FOOT VALVE SCANIA SR3 & SR4 0469052 571136		766548
881	01/14/2021	946944	Consumables		766649
881	01/14/2021	946944	Consumables		766649
881	01/14/2021	946944	rear door step light lens cracked	replaced u.s globe and lens . checked operation of all lights with driver . all okay	766548
881	01/14/2021	946944	LENS CLEAR TO SUIT 1406		766548

881	01/13/2021	946563	Engine	Low Power THROTTLE CUTS OUT AT TIMES	CHECKED WITH SD2AND FOUND DTC 22 AND 24 RECORDED OVER 20TIMES. SUSPECT FOOT VALVE NEEDS REPLACING.	766548
881	01/08/2021	945528	Mechanic entered	- Suspension Soft FRONT	Tight up the leveling valve rod for the front suspension	765617
881	01/06/2021	944878	Consumables			765351
881	01/06/2021	944878	Consumables			765351
881	01/06/2021	944878	Mechanic entered	- Body Other O/S/F pax seat cushion came of	re fitted seat base and secured	765107
881	01/04/2021	944338	Consumables			764862
881	01/04/2021	944338	Consumables			764862
881	01/04/2021	944338	Mechanic entered	- Elec and Light Next Stop Button o/s/r/r	checked operation of all passenger bells . could not fault	764633
881	12/19/2020	942364	Mechanic entered	- Elec and Light Other 2XPAX BELLS N/W.	CHECK OPERATION OF ALL PAX BUTTONSCOULD NOT FAULT.	761832
881	12/19/2020	942364	Consumables			762351
881	12/18/2020	942093	Mechanic entered	- Wheels and Tyres Wheel Nut Retension N/S/	retorque all front wheel nuts.	761832
881	12/18/2020	942093	Consumables			762351
881	12/17/2020	941632	V STAY ASSEMBLY	SCANIA L94UAB		761832
881	12/17/2020	941632	BOLT V STAY ASSY	CENTRE BUSH SCANIA L94		761832
881	12/17/2020	941632	Mechanic entered	- Suspension Other V-Rod U/S	removed U/S V - Rod fitted new V - Rod Assembly from stock roadtested and checked ok	761832
881	12/17/2020	941632	Mechanic entered	- Body Other pdisable seat top pin out	reseated disable seat top pin	761832
881	12/17/2020	941632	Mechanic entered	- Body Other Front and rear door has up dow	Adjusted Door rollers to remove slop adjusted as best as possible ok	761832
881	12/17/2020	941632	Consumables			762124
881	12/16/2020	941565			VEHICLE SAFETY INSPECTION Carried out Safety Inspection	761832
881	12/16/2020	941565			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	761832
881	12/16/2020	941632	Mechanic entered	- Suspension Other N/S/F and O/S/F Upper To	Replaced Worn Torque Rods with Complete New Units from stock ok	761832
881	12/16/2020	941632	TORQUE ROD FRT	UPPER SCANIA K230UB 1438475 2055289		761832
881	12/16/2020	941632	Mechanic entered	- Suspension Other Front Sway Bar 'D' Bushe	replaced front 'D' Rubbers	761832
881	12/16/2020	941632	BUSH FRT SWAY BAR	SCANIA K230UB 0469081 1919010 40MM		761832
881	12/16/2020	941632	Mechanic entered	- Gearbox Driveline Other Pinion Seal U/S	replaced Diff Pinion Seal with new item from stock washed and reassembled checked ok	761832
881	12/16/2020	941632	SEAL DIFF PINION	SCANIA R660 1502385		761832
881	12/16/2020	941650	Mechanic entered	- Elec and Light Indicators Not Working n/s	fitted new light bulb check ok	761832
881	12/16/2020	941650	Mechanic entered	- Elec and Light Next Stop Button o/s/r/r &	replaced and check ok	761832
881	12/16/2020	941650	SWITCH- STOP-YELLOW	(62628)		761832
881	12/16/2020	941650	Consumables			762017
881	12/16/2020	941650	Mechanic entered	- Body Other n/s/ passenger backing seat ou	fitted screw ckeck ok	761832
881	12/16/2020	941650	Mechanic entered	- Body Other n/s/ f modesty panle loose	fitted rivet check ok	761832
881	12/16/2020	941650	Consumables			762017
881	12/11/2020	940775	Drv entered	- Body Front_Door Operation Faulty	checked operation of passenger doors. lubricated . checked okk	761381
881	12/11/2020	940775	Consumables			761647
881	12/10/2020	938716	Mechanic entered	- Suspension Other worn rear sway bar rubbe	replaced rear swaybar D bushes and also swaybar linkage bushes asrequired.	761290
881	12/10/2020	938716	BUSH RR SWAY BAR	D AXLE SCANIA L94UAB 2156626 1477867		761290
881	12/10/2020	938716	BUSH RR SWAY BAR	(50MM I/D) SCANIA K93CRB 228483		761290
881	12/10/2020	940535	Ops Entered	- Fault - A/C Heating Demister Not Heating - R	wrong entered bus	761290
881	12/10/2020	940673	Mechanic entered	- Dash Other D selector button broken	Replaced D button	761290
881	12/10/2020	940673	BUTTON GEAR SHIFT	D HORIZONTAL SERIES 3		761290
881	12/10/2020	940673	Consumables			761381
881	12/05/2020	939837	fit	751 key lock to cctv over head locker door as requi	fit good 2nd hand lock from 1179 to overhead locker cctv compartment of 881. locked cctv compartment. all okay	760594
881	12/05/2020	939837	Consumables			760594
881	12/04/2020	932546	INSERT PAPER OIL SPINNER FILTER	SCANIA (40A7720)		760517
881	12/04/2020	932546	SPINNER FILTER KIT - WIDE PAPER	(87MM) 2153365		760517
881	12/04/2020	932546	Consumables			760594
881	12/04/2020	932546	Consumables			760594
881	12/03/2020	939271	REGULATOR ALTERNATOR	BOSCH 140AMP MERC 0500LE 1197311315		760272
881	12/03/2020	939271	Mechanic entered	- Elec and Light Warning Light On Dash Batt	Found alternator not charging remove alternator back cover and replaced regulator . Fit back cover checked for charging rate charging 27 volts .	760272
881	12/03/2020	939271	Consumables			760517
881	12/02/2020	938789	Mechanic entered	- CCTV Other not secured	whole dvr is loose as not mounted to the over head cabin locker. fitted screws and mounted dvr and closed the door with screws as locks missing. checked cctv working good.	759934
881	11/26/2020	936529	DIRECT PURCHASE	- ELECTRICAL	Creditor #:VB-CSE001 CSE CROSSCOM PTY LTD P/O #:O288442 Receiving #:301128 Date :2020-11-30 fit new bnc connector to ariel system as required	759669
881	11/26/2020	936529	Consumables			759046
881	11/26/2020	936529	cse	to replace bnc connector	O288442 - cse crosscom completed this	759046
881	11/25/2020	936529	Ops Entered	- Fault - Elec and Light Two Way Radio - Route:	checked and found the two-wai antenna radio end detached from socket.	759046
881	11/25/2020	936530	Mechanic entered	- Elec and Light Other eng oil seperator wi	crimped wires and connected oikl seperator ok.	759046
881	11/25/2020	936530	Consumables			759046
881	11/25/2020	936608	PERFORM CAMPAIGN	27/20 UPDATED INTERNAL BUS NUMBER DECALS	complete	759046
881	11/20/2020	935579	Mechanic entered	- Elec and Light Exterior Lights O/S/F top	Replaced globe	758157
881	11/20/2020	935579	Consumables			758400
881	11/18/2020	934638	PERFORM CAMPAIGN	26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	complete	757628
881	11/18/2020	934366	Remove old poster and fit you must wear a face mask when t		complete	757628
881	11/18/2020	932546	KIT O-RING OIL SPINNER FILTER	SCANIA ABOVE ENG #6203050		757628
881	11/18/2020	932546	Consumables			757892
881	11/17/2020	933953	FILTER FUEL FILTER	SCANIA SR4 (1372444)		757389
881	11/17/2020	933953	Ops Entered	- Fault - Breakdown - Route: 703b - Clayton St	went to the breakdown . found fuel filter leaking . replaced fuel filter . cleaned up spilt oil . came back to the depot . bus all good	757389
881	11/14/2020	933164	Mechanic entered	- Elec and Light Other indicator switch no	checked operation . could not fault	756561
881	11/14/2020	933164	Consumables			756883
881	11/12/2020	932740	Mechanic entered	- Fluid Leaks Front of bus leaking coolant	tighten coolant hose clampsok.	756216
881	11/12/2020	932740	Mechanic entered	- Elec and Light Other rear number plate li	r/r lightok.	756216
881	11/12/2020	932740	Consumables			756561
881	11/12/2020	932740	Mechanic entered	- Body Other n/s/r side panel not secure.	tighten screwsok.	756216
881	11/12/2020	932740	Consumables			756561
881	11/12/2020	932546			CARRY OUT C SERVICE AS PER CHECK LIST	756216
881	11/12/2020	932546	FILTER FUEL FILTER	SCANIA SR4 (1372444)		756216
881	11/12/2020	932546	FILTER HYD COOLING FAN	SCANIA L94UAB 1354074		756216
881	11/12/2020	932546	FILTER ZF ECOMAT GEARBOX	4139-298-038 1193281		756216
881	11/12/2020	932546	Oil Filter	SCANIA S4 & K		756216
881	11/12/2020	932546	INSERT PAPER OIL SPINNER FILTER	SCANIA (40A7720)		756216
881	11/12/2020	932546	FILTER FUEL FILTER	SCANIA SR4 (1393640)		756216
881	11/12/2020	932546	FILTER STEERING FILTER	(153468)(0153468)(349619)		756216
881	11/12/2020	932546	OIL SAMPLE KIT	CALTEX		756216
881	11/12/2020	932546			CARRY OUT B SERVICE AS PER CHECK LIST done.	756216
881	11/12/2020	932546	Consumables			756561
881	10/30/2020	929906	Fit new Myki Decals & refit COVID-19 decals	new position f	complete	754534
881	10/21/2020	927665	Mechanic entered	- Elec and Light Exterior Lights o/s/f/t pa	fit globe.	753090
881	10/21/2020	927665	Consumables			753407
881	10/20/2020	927462	Mechanic entered	- Wheels and Tyres Wheel Nut Retension N/S	carried out retorque as required	753090
881	10/20/2020	927462	Consumables			753315
881	10/20/2020	927410	Mechanic entered	- Body Other front door non slip strip brok	drill out broken rivetsrerivet strip carrier to rampglue non strip into positionok.	753090
881	10/20/2020	927410	Consumables			753315
881	10/20/2020	927500	PERFORM CAMPAIGN	20/20 VEHICLE TOLLWAY ETAG FITMENT	fit etag	753090

881	10/17/2020	927052	VEHICLE SAFETY INSPECTION carried out safety inspection and all associated repairs	752648
881	10/17/2020	927052	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	752648
881	10/17/2020	927047	replaced globe	752648
881	10/17/2020	927052	replaced charger working ok	752648
881	10/17/2020	927052		752648
881	10/17/2020	927047		752892
881	10/17/2020	927052		752892
881	10/17/2020	927052	replaced flouro tube as required	752648
881	10/17/2020	927052	replaced airbag working ok	752648
881	10/17/2020	927052		752648
881	10/17/2020	927052		752892
881	09/28/2020	922607	complete	749695
881	09/28/2020	922607	CARRY OUT FIRE EXTINGUISHER TEST & TAG	749695
881	09/24/2020	922039	traced and found the dash globe blown . R&R dash clustor globe for the indicators/hazards	749050
881	09/24/2020	922039		749275
881	09/22/2020	921481	changed the bus over at Monash uni	748754
881	09/22/2020	921481	Assisting - removed the bearing caps and checked	748754
881	09/22/2020	921481	fit new bearings . adjusted front door road tested . all okay	748754
881	09/22/2020	921481	Creditor #:GB-BRE001 BRETT WALTON - VISA P/O #:284228 Receiving #:296458 Date :2020-09-22	748754
881	09/22/2020	921481		748754
881	09/09/2020	919136	replaced globe and can confirm light now works	746644
881	09/09/2020	919136		746885
881	09/02/2020	917752	lubricated linkages under throttle pedal for good measure road tested . could not fault bus lacking power	745305
881	09/02/2020	917752	double entry	745305
881	09/02/2020	917752	checked operation . could not fault	745305
881	09/02/2020	917752		745471
881	08/29/2020	916923	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list	744635
881	08/25/2020	915889	VEHICLE SAFETY INSPECTION done.	743875
881	08/25/2020	915889	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	743875
881	08/25/2020	916070	fixed coolant hoseok.	743875
881	08/25/2020	916070	fixed coverok.	743875
881	08/25/2020	916070	fixed panel lockerok.	743875
881	08/25/2020	916070	fixed panelok.	743875
881	08/25/2020	916070	fixed panelok.	743875
881	08/25/2020	916070		744140
881	08/22/2020	913845	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O281716 Receiving #:294378 Date :2020-08-24 Window Film Audit 418 completed 3/8/20 oakleigh	743875
881	08/14/2020	913845	Completed 3/8/20 refer email PB 13/8/20	742624
881	08/11/2020	913089	carried out by fleet support	742084
881	08/10/2020	912602	n/s/b park light not working	741653
881	08/10/2020	912602	Consumables	742084
881	08/07/2020	912195	Consumables	741653
881	08/07/2020	912195	Mechanic entered - Elec and Light Other headlight switch kno	741620
881	08/07/2020	912195	Knob Control (372621 0372621)	741620
881	08/05/2020	911074		741110
881	07/25/2020	909119	Vandalism - interior graffiti	739504
881	07/14/2020	906614	Mechanic entered - Fluid Leaks Rear of bus coolant leak back	737040
881	07/14/2020	906480		737040
881	07/14/2020	906480	OIL SAMPLE KIT CALTEX	737040
881	07/14/2020	906480	Oil Filter SCANIA S4 & K	737040
881	07/14/2020	906480	FILTER FUEL FILTER SCANIA SR4 (1372444)	737040
881	07/14/2020	906480	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)	737040
881	07/14/2020	906480	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050	737040
881	07/14/2020	906480	Consumables	737327
881	07/14/2020	906480	Consumables	737327
881	07/10/2020	905913		736520
881	07/10/2020	905913	BELT V-BELT COGGED TRI-POWER 17x2135mm	736520
881	07/10/2020	905913	AIR CONDITIONING REPAIR	737568
881	07/10/2020	905913		736520
881	07/07/2020	905209	Mechanic entered - Elec and Light Other Engine switching of	736203
881	07/07/2020	905209	Consumables	736276
881	07/01/2020	903904		734880
881	07/01/2020	903904		734880
881	07/01/2020	903904	Service	734880
881	07/01/2020	904047	BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483	734880
881	07/01/2020	904047	Mechanic entered - Suspension Other rear d-rubber bushes wor	734880
881	07/01/2020	904050	Consumables	735210
881	07/01/2020	904050	Mechanic entered - Dash Dash_Lights Not Working	734880
881	07/01/2020	904046	**to be deleted - entered in error**	734880
881	07/01/2020	904047	Consumables	735210
881	07/01/2020	904047	Mechanic entered - Body Other Disabled seat top pin missing	734880
881	06/29/2020	903570	o/s mirror smashed	734033
881	06/29/2020	903570	MIRROR R/H 380mm SHORT (UE51411D)	734033
881	06/29/2020	903570	Consumables	734880
881	06/13/2020	900719	Drv entered - Body Front_Door Operation Faulty	731717
881	06/13/2020	900719	Consumables	731960
881	06/09/2020	899449	O/S HEADLIGHT NOT WORKING	731010
881	06/09/2020	899449	Consumables	731292
881	06/09/2020	899329	Consumables	731292
881	06/09/2020	899329	Ops Entered - Fault - Body Front_Door Operation Faulty - R	731010
881	06/09/2020	899329	DIRECT PURCHASE - ELECTRICAL	731533
881	06/04/2020	898795	Mechanic entered - Elec and Light Next Stop Button N/S last	730765
881	06/04/2020	898795	SWITCH- STOP-YELLOW (62628)	730765
881	06/04/2020	898795	Consumables	731010
881	06/01/2020	896750	DIRECT PURCHASE - MECHANICAL G	731960
881	06/01/2020	897871	Mechanic entered - Elec and Light Other O/S front upper park	730100
881	06/01/2020	897871	Consumables	730489
881	06/01/2020	893338	DIRECT PURCHASE - BRAKES	734033
881	05/30/2020	897523	Mechanic entered - Elec and Light Flat Batteries	730100
881	05/30/2020	897523	BATTERY 1030CCA POS ON LHS	730100
881	05/30/2020	897523	Consumables	730160
881	05/29/2020	897491	Mechanic entered - Elec and Light Other vehicle fiat battery	730100
881	05/29/2020	897491	Consumables	730160
881	05/28/2020	896750	fuel tank leaking	729960
			Fit back repaired fuel tank	

881	05/26/2020	896750	fuel tank leaking	removed leaking fuel tank washed marked where leak is on tank - tank sent to auto cooling clayton -0276251	729960
881	05/20/2020	895477	battery check book back	check batteries as per instructed ok	728739
881	05/18/2020	895054	Mechanic entered - Elec and Light Flat Batteries wont start.	jump startok.	728254
881	05/18/2020	895054	Consumables		728497
881	05/18/2020	894866	Mechanic entered - Body Front_Door Operation Faulty keeps re	adjust air pressure to solenoidsnow ok.	728254
881	05/18/2020	894866	Consumables		728497
881	05/16/2020	894971	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting as requird	728496
881	05/14/2020	894475		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST CARRY OUT SERV AS PER WORK ORDER CHECK TESTED OK	728254
881	05/14/2020	894475		SERVICE MOISTURE EJECTOR CARRY OUT SERV AS PER WORK ORDER CHECK TESTED OK	728254
881	05/14/2020	894162	CABLE BATTERY BRIDGE SHORT (230MM)		728254
881	05/14/2020	894162		tested both batteries after an overnight charge. one was failed. replaced battery x 1 and jumper wire. checked charging 27.58volts ok	728254
881	05/14/2020	894162	BATTERY 1030CCA POS ON LHS		728254
881	05/13/2020	894162	battery check		728254
881	05/12/2020	893972	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	checked batteries and put on charge	727863
881	05/12/2020	893972	Consumables	retensioned both frt wheel nuts as per specs	728254
881	05/12/2020	893728	Mechanic entered - Elec and Light Flat Batteries		727863
881	05/12/2020	893728	Consumables	Jump Started Bus Informed driver to not switch off for 4 hours	728254
881	05/12/2020	892338	DIRECT PURCHASE - MECHANICAL G		728254
881	05/12/2020	892338	Consumables	Creditor #:VB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:0274662 Receiving #:286800 Date :2020-05-14 check and supply quote for driver seat repairs	728254
881	05/11/2020	893338	brakes	PO#: 0275106	727863
881	05/11/2020	893338	brake shudder	reinstalled front brakes . adjusted brakes . road tested . checked operation of retarder - all okay	727863
881	05/08/2020	893336	w/o created to create p/o for bwere - rectify throttle cutt		727863
881	05/08/2020	893336	Consumables		727863
881	05/08/2020	893338	Ops Entered - Fault - Brakes Warning Light On - Route: - A	removed front wheels drums & linings.	727863
881	05/05/2020	892338	Body driver seat weight adjuster us - TO REBOOK	fit reco drivers seat - seat sent away for repairs PO#: 0274662	727027
881	05/01/2020	893336	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:0246151-1 Receiving #:286479 Date :2020-05-08 check & rectify throttle cuts and doors playing up	727863
881	04/27/2020	890784	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	carried out wheel nut re tension both front wheels	725034
881	04/27/2020	890784	Consumables		725746
881	04/25/2020	890483		VEHICLE SAFETY INSPECTION	725034
881	04/25/2020	890483		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	725034
881	04/25/2020	890493	Mechanic entered - Wheels and Tyres Other both front tyres u	replaced both front tyres x2	725034
881	04/25/2020	890493	TYRE 295/80R22.5 NEW		725034
881	04/25/2020	890493	Consumables		725516
881	04/25/2020	890493	Mechanic entered - A/C Heating Other a/c mount u/s	replaced a/c mont x2 ok	725034
881	04/25/2020	890493	MOUNT A/C COMPRESSOR SMALL DENSO		725034
881	04/25/2020	890493	MOUNT A/C COMPRESSOR LARGE DENSO		725034
881	04/25/2020	890493	Mechanic entered - Elec and Light Other n/s saloon light not	replaced n/s/middle saloon light tube ok	725034
881	04/25/2020	890493	Consumables		725516
881	04/25/2020	890493	Mechanic entered - Body Other both middle seat all loose	repaired both middle seat ok	725034
881	04/25/2020	890493	Mechanic entered - Body Other o/s/middle bus inside top pane	repaired o/s/middle bus inside top panel ok	725034
881	04/25/2020	890493	Mechanic entered - Body Other o/s/f seat base cut	repaired o/s/f seat base ok	725034
881	04/25/2020	890493	Consumables		725516
881	04/24/2020	890287	Mechanic entered - Wheels and Tyres Other check tread n/s/f	could not faultover 4MM.	725034
881	04/24/2020	890287	Consumables		725516
881	04/24/2020	890284	Mechanic entered - Elec and Light Exterior Lights n/s/f/t pa	fit globe.	725034
881	04/24/2020	890284	Consumables		725516
881	04/22/2020	889773	Mechanic entered - Elec and Light Other ignition switch broke	removed bus number 1196 ignition switch after put back ingtion switch bus number is 881 ok	724078
881	04/22/2020	889773	Consumables		725034
881	04/21/2020	889519	Mechanic entered - Elec and Light Other bus minder chager ca	removed bus minde chager cable bus number is 834 after put back bus minder chager cable 881 ok	724078
881	04/21/2020	889519	Consumables		724884
881	04/18/2020	889291	Vandalism interior graffiti	cleaned and painted over int graffiti	724078
881	04/17/2020	888901	Mechanic entered - Elec and Light Interior Lights dash light	fit globes.	724078
881	04/17/2020	888901	Consumables		724435
881	04/14/2020	887810	Mechanic entered - Elec and Light Flat Batteries	jump start.	723476
881	04/14/2020	887810	Consumables		723854
881	04/09/2020	887487	A4 notification to be printed off in colour laminated and	carried out campaign as required	723476
881	04/08/2020	886875	Mechanic entered - Body Rear_Door Operation Faulty NOISV.	LUBE ROLLER GUIDESOK.	722994
881	04/08/2020	886875	Consumables		723476
881	04/07/2020	824791	VALVE FRT LVL CNTRL VALVE VOLVO B10BLE 9957009 481831		722994
881	04/07/2020	824791	SOLENOID VALVE FRONT		722994
881	03/31/2020	885171	Mechanic entered - Elec and Light Other engine bay stop swit	could not fault.	721196
881	03/31/2020	885171	Consumables		722064
881	03/30/2020	885091	Ops Entered - Fault - Passenger Doors - Route: 703 - Centr	checked operation of passenger doors . could not fault .	721196
881	03/30/2020	884838	Mechanic entered - Elec and Light Other engine bay stop swit	fit good second hand switchok.	721196
881	03/30/2020	884838	Consumables		721912
881	03/24/2020	883253	Tape off front Seats of All Route and Rail Buses with spec	carried out campaign as required	720521
881	03/24/2020	883532	Remove old poster and fit Reduce Your Risk of Coronavirus	carried out campaign as required	720521
881	03/23/2020	881853	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:0271521 Receiving #:282971 Date :2020-03-26 graffiti window film replacement - Audit 255 Stage 1	720914
881	03/20/2020	881853	Vandalism - Vandalism/ Graffiti Interior: Protective window	O271521 carried by glass protect	719630
881	03/11/2020	876989	Mechanic entered - Fluid Leaks Rear of bus leaking frm rear	gave under carrige wash and recheck next service	717613
881	03/11/2020	879732	Mechanic entered - Fluid Leaks Rear of bus coolant hose clam	gave hose clamp retighten check tested ok	717613
881	03/11/2020	879762	Mechanic entered - Body Water Leaks Roof front windscreen	tims stuff up	717613
881	03/11/2020	879762	Consumables		717841
881	03/11/2020	879603			717613
881	03/11/2020	879603	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)	CARRY OUT B SERVICE AS PER CHECK LIST carry out serv as per work order check tested ok	717613
881	03/11/2020	879603	FILTER FUEL FILTER SCANIA SR4 (1372444)		717613
881	03/11/2020	879603	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		717613
881	03/11/2020	879603	Oil Filter SCANIA S4 & K		717613
881	03/11/2020	879603	Consumables		717841
881	03/11/2020	879603	Consumables		717841
881	03/11/2020	879603	Consumables		717841
881	03/10/2020	879763	Mechanic entered - Body Water Leaks Roof front windscreen		717836
881	03/10/2020	879763	Consumables		717836
881	03/09/2020	879761	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/09/2020	879761	Consumables		717613
881	03/08/2020	879760	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/08/2020	879760	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/08/2020	879760	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/08/2020	879760	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/08/2020	879760	Mechanic entered - Body Water Leaks Roof front windscreen		717613
881	03/08/2020	879760	Consumables		717613
881	03/03/2020	878360	Mechanic entered - Elec and Light Other O/S headlight not wo	replaced globe ok	716656
881	03/03/2020	878360	Consumables		716877

881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Water Leaks Roof front windscreen		716877
881	03/03/2020	879758	Mechanic entered - Body Other		716877
881	03/03/2020	879758	Consumables		716877
881	03/02/2020	877933		VEHICLE SAFETY INSPECTION	716355
881	03/02/2020	877933		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	716355
881	03/02/2020	877933		ANNUAL SAFETY INSPECTION SERIAL # _____669572 GREENSHEET _____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	716355
881	03/02/2020	877933	DIRECT PURCHASE - BUS INSPECTI	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O270107 Receiving #:281104 Date :2020-03-02	716506
881	02/29/2020	877767	Mechanic entered - Elec and Light Other n/s head light not w	replaced n/s head light globe ok	716355
881	02/29/2020	877767	Consumables		716506
881	02/28/2020	877569		complete	716355
881	02/28/2020	877569		CARRY OUT FIRE EXTINGUISHER TEST & TAG	716355
881	02/26/2020	876988	Mechanic entered - Body Other disable seat pin n/s come loos	resecure pin bracket check ok	716098
881	02/26/2020	876988	Consumables		716112
881	02/26/2020	876988	Mechanic entered - Brakes Other rear slack adjuster not taki	carry out remove nipple clean refit nipple check tested ok	716098
881	02/22/2020	876208	Vandalism Vandalism/ Graffiti Interior. The rear interior	carried out interior vandelisem painting as required	715633
881	02/14/2020	874172	Mechanic entered - Elec and Light Indicators Not Working	reposition globe in holder at n/s/f side blink.	713824
881	02/14/2020	874172	Consumables		714292
881	02/11/2020	873498	Mechanic entered - Elec and Light Other O/S front upper park	replaced globe ok	713301
881	02/11/2020	873498	Consumables		713562
881	02/08/2020	873024	Vandalism interior graffiti	cleaned and painted over interior graffiti	713019
881	02/07/2020	872389		PRE ANNUAL SAFETY INSPECTION CHECK	712734
881	02/07/2020	872389		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	712734
881	02/03/2020	871048		TRANSMISSION CHECK AS PER CHECK LIST Carried Out Trans Check ok	711620
881	02/03/2020	871049		VEHICLE SAFETY INSPECTION Carried out safety inspection ok	711620
881	02/03/2020	871049		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	711620
881	02/03/2020	871166	Mechanic entered - Fluid Leaks Rear of bus Header Tank Leaki	Replaced Header Tank with one without coolant level sensor ok	711620
881	02/03/2020	871166	Mechanic entered - Engine Other Drive Belt U/S	Replaced Drive Belt and Adjusted A/C Belt	711620
881	02/03/2020	871166	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)		711620
881	02/03/2020	871166	EXPANSION TANK C/FILL 1731694/1896287		711620
881	02/03/2020	871166	Mechanic entered - Dash Dash_Lights Not Working 4x Dash Ligh	Replaced 4x Dash Light Globes and checked ok	711620
881	02/03/2020	871166	Consumables		712270
881	02/03/2020	871254	Drv entered - Body Drivers Seat Controls	old defect - fixed by CDF on wo867830	711620
881	02/03/2020	871166	Mechanic entered - Body Other Rear No Smoking Decal Missing	Replaced No Smoking Decal	711620
881	02/03/2020	871254	Drv entered - Body Drivers Seat Leaning	double entry	711620
881	02/03/2020	871166	Consumables		712270
881	02/03/2020	871254	Consumables		712270
881	02/03/2020	871251		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	711620
881	01/31/2020	870945	Mechanic entered - Elec and Light Other N/S side marker O/S	replaced parker globe repaired side marker ok	711620
881	01/31/2020	870945	Consumables		711844
881	01/23/2020	869324	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	carried out campaign as required	710049
881	01/20/2020	868360	Drv entered - Suspension Hard	ROAD TEST OPERATION OF SUSPENSIONCOULD NOT FAULT.	709461
881	01/20/2020	868363	Drv entered - Suspension Kneeel/ Raise	COULD NOT FAULT.	709461
881	01/20/2020	868364	Drv entered - Suspension Noisy	COULD NOT FAULT.	709461
881	01/17/2020	867830	Mechanic entered - Body Drivers Seat Controls n/w.	recalibrate seat weight adjuster.	708959
881	01/17/2020	867830	Consumables		709241
881	01/13/2020	866908	Mechanic entered - Elec and Light Flat Batteries	carry out jump start check ok	708470
881	01/13/2020	866908	Consumables		708735
881	01/11/2020	866576	Drv entered - Brakes Foot_Brakes Pulling	adjusted brakes road/braks test ok	707714
881	01/10/2020	866260	Mechanic entered - Elec and Light Flat Batteries	jump start.	707714
881	01/10/2020	866260	Consumables		708163
881	12/31/2019	864367	Mechanic entered - Body Other N/S MIRROR ARM LOOSE.	SECURE MIRROR ARM.	705328
881	12/31/2019	864367	Consumables		705498
881	12/16/2019	861965	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque n/s/r wheel nuts.	702661
881	12/16/2019	861965	Consumables		703098
881	12/14/2019	861873		VEHICLE SAFETY INSPECTION Carried out safety inspection ok	702661
881	12/14/2019	861873		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	702661
881	12/14/2019	861873	Mechanic entered - Wheels and Tyres Worn POS 3 TYRE WORN	Replaced worn pos 3 tyre and match pos 4 with new retreads	702661
881	12/14/2019	861873	TYRE 295/80R22.5 RECAP		702661
881	12/14/2019	861873	Consumables		703098
881	12/14/2019	861903	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Replaced Low water sender ok	702661
881	12/14/2019	861903	LOW WATER SENSOR K230UB (1374052)		702661
881	12/14/2019	861907	Mechanic entered - Fluid Leaks Rear of bus O Ring Level sens	replaced O'Ring ok	702661
881	12/14/2019	861907	O RING LOW LEVEL SENSOR CAP K230UB (1731095)		702661
881	12/14/2019	861927	Mechanic entered - Dash Dash_Lights Not Working 3 Dash Light	replaced 3 dash globes test ok	702661
881	12/14/2019	861927	CAP END CAP CENTRA SEAT END CAP		702661
881	12/14/2019	861927	Consumables		703098
881	12/14/2019	861927	Mechanic entered - Body Other Disabled seat top pins out	Re Seated Top pins ok	702661
881	12/14/2019	861927	Mechanic entered - Body Other N/S/F Passenger seat end cap m	Replaced end cap ok	702661
881	12/14/2019	861927	Mechanic entered - Body Other Overhead panels screws missing	Replaced Screws ok	702661
881	12/14/2019	861927	Consumables		703098
881	12/07/2019	860144	A3 Poster Frame Adhesive Decal Campaign please remove old	complete	701583
881	12/06/2019	859876		CARRY OUT FIRE EXTINGUISHER TEST & TAG	701583
881	12/06/2019	859876		completed	701583
881	12/04/2019	859309	Mechanic entered - Elec and Light Exterior Lights Both front	Replaced globe for both side	701135
881	12/04/2019	859309	Consumables		701359
881	11/25/2019	856728	Mechanic entered - Body Other n/s mirror arm broken.	fit new arm.	698715
881	11/25/2019	856728	CONSUMABLE - BODYWORK		698715
881	11/25/2019	856728	Consumables		699717
881	11/19/2019	855692	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	Completed retension	697828
881	11/19/2019	855692	Consumables		698264
881	11/18/2019	855159	Mechanic entered - Wheels and Tyres Other O/S/R/INNER TYRE U	replaced O/S/R/INNER TYRERETORQUED O/S/R WHEEL NUTS OK	697828
881	11/18/2019	855159	TYRE 295/80R22.5 RECAP		697828
881	11/18/2019	855159	Consumables		698034
881	11/18/2019	855159	Mechanic entered - Fluid Leaks Other COOLANT HEAD TANK BOTTO	replaced coolant head tank bottom oring ok	697828
881	11/18/2019	855159	O RING LOW LEVEL SENSOR CAP K230UB (1731095)		697828
881	11/18/2019	855159	Mechanic entered - Body Other MIDDLE SEAT TOP PINS OUT	put in middle seat top pins	697828
881	11/18/2019	855159	Mechanic entered - Body Other rear modesty panel loose	repaired rear modesty panel ok	697828

881	11/18/2019	855159	Consumables			698034
881	11/18/2019	855159	Mechanic entered - Brakes Other n/s/r brake booster u/s	replaced n/s/r brake booster ok		697828
881	11/18/2019	855159	SPR.BR.CYL R/R L94 N/S/R (3SCLE0010)			697828
881	11/18/2019	855139		CARRY OUT B SERVICE AS PER CHECK LIST		697828
881	11/18/2019	855139	Consumables			698034
881	11/18/2019	855139	Consumables			698034
881	11/18/2019	855139	Consumables			698034
881	11/15/2019	854882	Drv entered - BusMinder No Power	no faults found		697828
881	11/15/2019	854882	Consumables			697980
881	11/14/2019	846849	CONSUMABLE - DELIVERY CHARGE	Creditor #:VB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:O259699 Receiving #:272376 Date :2019-11-14		697548
881	11/14/2019	846849	SELECTOR SWITCH Vert RND	Creditor #:VB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:O259699 Receiving #:272376 Date :2019-11-14		697548
881	11/07/2019	853084	Drv entered - Body Drivers Seat Controls	checked all seat controlscould not fault.		696131
881	11/07/2019	853084	Consumables			696526
881	11/01/2019	852035		instructed to close off by fleet - ben willis via group e-mail		695630
881	11/01/2019	852035		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		695630
881	10/30/2019	851295	Consumables			695405
881	10/30/2019	851295	Mechanic entered - Elec and Light Flat Batteries	jump start.		695111
881	10/23/2019	849823	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	bus sent to volgren PO#: 0260887		695111
881	10/15/2019	848083	Consumables			694084
881	10/15/2019	848083	Elec and Light oil prs light nw	Refit new switch found broken wire reconnect new connector tested check ok also repaired the wiring at air dryer and oil seperator		693989
881	10/15/2019	848083	Switch Oil Pressure Scania Series 4 (1881260)			693989
881	10/11/2019	847369		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		693459
881	10/11/2019	847369		VEHICLE SAFETY INSPECTION Carried out Safety inspection		693459
881	10/11/2019	846849	PULLEY IDLER SCANIA (1514087)			693459
881	10/11/2019	846849	Mechanic entered - Engine Other Ribbed engine idler U/S	Replaced Engine idler pulley ok		693459
881	10/11/2019	846849	Mechanic entered - Fluid Leaks Rear of bus Coolant leak from	Tightened hose clamp Recheck @ Next service		693459
881	10/11/2019	846849	Mechanic entered - Fluid Leaks Rear of bus Fuel Tank Leaking	Removed drain Plug Added Plumbers tape to thread Re fitted plug and tightened ok		693459
881	10/11/2019	846849	Consumables			693774
881	10/11/2019	846849	Mechanic entered - Body Other Disabled seat Top pins out	Re seated top pins ok		693459
881	10/08/2019	846849	ZF selector u/s	replaced selector ok		693066
881	09/23/2019	843975	Consumables			690797
881	09/23/2019	843975	BRACKET MIRROR ARM LH			690688
881	09/23/2019	843975	n/s drivers mirror broken off	R&R mirror bracket		690688
881	09/09/2019	841052	Consumables			688486
881	09/09/2019	836307	Consumables			688486
881	09/09/2019	836307	NUT BRASS BATTERY TERMINAL POSITIVE (+) MA14HDP			688151
881	09/09/2019	836307	NUT BRASS BATTERY TERMINAL NEGATIVE (-) MA14HDN			688151
881	09/09/2019	841052	SWITCH- STOP-YELLOW (62628)			688151
881	09/09/2019	841052	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	FIT NEW PAX BUTTON.		688151
881	09/07/2019	840967	Consumables			688413
881	09/07/2019	840967	Ops Entered - Fault - Elec and Light Two Way Radio - Route	traced and found bnc connected disconnected . reconnected . carried out radio check with oakleigh opps. all working okay		688151
881	09/04/2019	840321	Consumables			687928
881	09/04/2019	840321	Mechanic entered - Body Other Fire extinguisher bracket came	Drill and fit bracket back		687777
881	09/01/2019	838870	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWEO01 BWERE ELECTRICS PTY LTD P/O #:O256746 Receiving #:267144 Date :2019-09-11 carry out cctv 6 month service		688486
881	09/01/2019	836307	Consumables			687291
881	09/01/2019	836307	SUPLERSLIM PLASTIC BASE	Creditor #:VB-MCCONSEA MCCONNELL SEATS AUSTRALIA P/O #:O255921Receiving #:266414 Date :2019-09-03		687291
881	09/01/2019	829461	make air line as required as p	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O253194 Receiving #:267896 Date :2019-09-20		690442
881	09/01/2019	838164	AIR CONDITIONING REPAIR	Creditor #:VB-COLO04 COLD DRIVE PTY LTD P/O #:O256486 Receiving #:267160 Date :2019-09-11 carry out 12 month service as required		688486
881	08/31/2019	836307	Consumables			687177
881	08/31/2019	836307	Mechanic entered - Body Other middle seat base bottom cover	fitted		686770
881	08/28/2019	838479	Ops Entered - Fault - Suspension Knee/ Raise - Route: 703b	front levelling arm loosesecuredroad test ok.		686368
881	08/27/2019	838870	CCTV - 6 months service	done by BW electrics johnny PO 0256746 on the 27/08/2019		686368
881	08/27/2019	838164		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - 0256486 - cold drive		686268
881	08/19/2019	836307	Mechanic entered - Body Other middle seat base bottom cover	ordered		684825
881	08/16/2019	835747		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		684452
881	08/16/2019	835747		VEHICLE SAFETY INSPECTION		684452
881	08/16/2019	835812	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			684452
881	08/16/2019	835812	Mechanic entered - Suspension Other Front 'D' Rubbers U/S	Replaced Front 'D' Rubbers		684452
881	08/16/2019	835851	Mechanic entered - Engine Other engine oil leaks	repaired engine bottom oil pipe fitting ok		684452
881	08/16/2019	835851	Mechanic entered - Engine Other fule leaks from fule pump st	repaired fuel pump stop solenoid valve ok		684452
881	08/16/2019	835812	Consumables			684693
881	08/16/2019	835812	Mechanic entered - Elec and Light Other Dash Globes X2 U/S	Replaced Dash Globes		684452
881	08/16/2019	835851	Consumables			684693
881	08/16/2019	835812	Consumables			684693
881	08/16/2019	835851	Mechanic entered - Body Other front door handle loose	tightened front door handle bolts ok		684452
881	08/16/2019	835851	Mechanic entered - Body Other middle seat top pins out	put in seat top pins ok		684452
881	08/16/2019	835812	Mechanic entered - Body Other Disabled Seat Top Hinge Bracke	Removed Seat Back Drilled old rivets and re rivetted		684452
881	08/05/2019	833303	Consumables			682614
881	08/05/2019	833303	2-way not working	double entry		682478
881	08/05/2019	833303	Two way radio is not working	checked two-way; antenna wire connection at plug faulty. need to get CSE crosscom to crimp antenna plug. also had an issue with pwr supply thru inverter. replaced the inverter with a second hand one. tested ok.		682478
881	07/30/2019	831927		TRANSMISSION CHECK AS PER CHECK LIST		681547
881	07/24/2019	830665	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorque all rear wheel nuts.		680315
881	07/24/2019	830665	Consumables			681547
881	07/24/2019	830866	Mechanic entered - Elec and Light Other two-way nw	double entry		680315
881	07/24/2019	830866	Consumables			681547
881	07/23/2019	830520	Consumables			680541
881	07/23/2019	830624	Mechanic entered - Wheels and Tyres Wheel Nut Retension rea	carried out on work order - 830520		680315
881	07/23/2019	830520	Wheels and Tyres Wheel Nut Retension - rears	retensioned rears as per specs		680315
881	07/23/2019	830624	Consumables			680541
881	07/18/2019	827828	PLUG SUMP DRAIN PLUG SCANIA 3 SERIES 1433641 1423608			679047
881	07/17/2019	827828	WASHER SUMP DRAIN PLUG SCANIA 3 SERIES 2419091 1439814			678889
881	07/17/2019	827828	Mechanic entered - Brakes Other n/s/r brake slack adjust u/s	assisted cdf to put the nsr s cam and parts		678889
881	07/17/2019	827828	reinstall sump	reinstalled sump . cleaned all surfaces. filled with oil.		678889
881	07/17/2019	829470	Consumables			679047
881	07/17/2019	829470	Mechanic entered - Elec and Light Two Way Radio n/w.	checked operation of 2-way with opps . SEN . working all good		678889
881	07/17/2019	827828	Mechanic entered - Brakes Other n/s/r Scam shaft u/s	replaced nsr s cam and accessories		678889
881	07/17/2019	829461	Air System leak at rear of bus	Removed air line for enzed to fix fit with clamps		678889
881	07/16/2019	827828	GASKET SPINNER HSG - ADAPTOR	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O252769 Receiving #:262173 Date :2019-07-18		679269
881	07/16/2019	827828	2025393 S Cam	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O252769 Receiving #:262173 Date :2019-07-18		679269
881	07/16/2019	827828	GASKET SPINNER HSG MTG SCANI	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O252769 Receiving #:262173 Date :2019-07-18		679269
881	07/15/2019	827828	DIRECT PURCHASE - ENGINE	Creditor #:VB-HMG001 HM GEM ENGINES P/O #:O252543 Receiving #:262392 Date :2019-07-22 please supply quote for eng oil sump repairs - go ahead only if approved		679269
881	07/13/2019	828669	Vandalism interior graffiti	cleaned and painted int graffiti		678889
881	07/11/2019	827828	Mechanic entered - A/C Heating Other a/c mount u/s	replaced a/c mount x2 ok		678889

881	07/11/2019	827828	Mechanic entered - Gearbox Driveline Other diff plug washer	replaced diff plug washer ok	678889
881	07/11/2019	827828	Mechanic entered - Engine Other head tank coolant glass u/s	replaced head tank coolant glass ok replaced coolant head tank glass hose ok	678889
881	07/11/2019	827828	Mechanic entered - Engine Other engine belt idler bearing u/	replaced engine idler bearing	678889
881	07/11/2019	828137	Consumables		678889
881	07/11/2019	828110	Consumables		678889
881	07/11/2019	827828	Consumables		678889
881	07/11/2019	828137	Elec and Light - desto nw and controller over heating	removed the controller sent away for repairs - fitted back ok PO#: Q252649	678889
881	07/11/2019	828110	LENS TO SUIT 2063 LAMP 85765		678889
881	07/11/2019	828110	Mechanic entered - Elec and Light Other n/s/f top park light	repaired park light wires replaced park light lens ok	678889
881	07/11/2019	827828	Mechanic entered - Elec and Light Other dash all light not w	replaced dash light all globe ok	678889
881	07/11/2019	827828	Consumables		678889
881	07/11/2019	827828	Mechanic entered - Body Other middle seat top pin out	PUT IN MIDDLE SEAT TOP PINS OK	678889
881	07/11/2019	827828	Mechanic entered - Brakes Other n/s/r brake slack adjust u/s	replaced n/s/r hub sealouter seal n/s/r hub put in grease	678889
881	07/11/2019	827828	Mechanic entered - Air System Other air hose hit from to the	replaced CABLE TIE OK	678889
881	07/10/2019	827966	Consumables		678889
881	07/10/2019	827828	Consumables		678889
881	07/10/2019	827828	TYRE 295/80R22.5 RECAP		678889
881	07/10/2019	827966	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	carried out retorque as required	678889
881	07/10/2019	827828	Mechanic entered - Wheels and Tyres Other o/s/r outer tyre	replaced o/s/r tyre ok	678889
881	07/10/2019	827828	WASHER SEALING SC SUMP (1356776)		678889
881	07/10/2019	827828	O ring accum end cap		678889
881	07/10/2019	827828	Piston accumulator		678889
881	07/10/2019	827828	GLASS SIGHT GLASS SCANIA (452123) (1931715)		678889
881	07/10/2019	827828	Mount A/C COMPRESSOR LARGE DENSO		678889
881	07/10/2019	827828	Idler PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		678889
881	07/10/2019	827828	Mechanic entered - Engine Other sump plug oil leaks	removed engine sump and sent away for repairs Q252543	678889
881	07/10/2019	827828	Mechanic entered - Fluid Leaks Other Accumulator Leaking	Replaced Accumulator Piston and O Ring	678889
881	07/10/2019	827918	Consumables		678889
881	07/10/2019	827918	Direct Purchase - BODYWORK	Creditor #:-VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:-Q252545 Receiving #:261625 Date :2019-07-12 fix driver's seat base	678889
881	07/10/2019	827918	Body - driver seat base us	removed sent away and fitted PO#: Q252545	678889
881	07/10/2019	827828	SEAL REAR AXLE CAP SCANIA 1765061 120310		678889
881	07/10/2019	827828	SEAL INNER REAR AXLE SCANIA 1740992		678889
881	07/10/2019	827828	SEAL OUTER REAR AXLE SCANIA 1409890		678889
881	07/10/2019	827828	LOCK WASHER REAR AXLE SCANIA 273023		678889
881	07/10/2019	827828	SLACK ADJUSTERAUTO-REAR N/SIDE (2009819) SERIES 4		678889
881	07/10/2019	827828	Mechanic entered - Brakes Other n/s/r brake slack adjust u/s	Fitted new slack adjuster and road test	678889
881	07/10/2019	827828	Mechanic entered - Brakes Other n/s/r Scam shaft u/s	removed Scam shaft	678889
881	07/10/2019	827790	Consumables		678889
881	07/10/2019	827790	Consumables		678889
881	07/10/2019	827790	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		678889
881	07/10/2019	827790			678889
881	07/10/2019	827790	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		678889
881	07/10/2019	827790	FILTER FUEL FILTER SCANIA SR4 (1372444)		678889
881	07/10/2019	827790	Oil Filter SCANIA S4 & K		678889
881	07/10/2019	827790		CARRY OUT B SERVICE AS PER CHECK LIST	678889
881	07/08/2019	828137	DIRECT PURCHASE - ELECTRICAL	Creditor #:-VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:-Q252649 Receiving #:261623 Date :2019-07-12 repair desto controller as required	678889
881	07/01/2019	801160	DIRECT PURCHASE - BUS INSPECTI	Creditor #:-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:-O242352 Receiving #:261915 Date :2019-07-16 carry out RSI as required	678889
881	06/24/2019	824700		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	675744
881	06/24/2019	824700		VEHICLE SAFETY INSPECTION done.	675744
881	06/24/2019	824791	Mechanic entered - Wipers and Washers Other wiper washer n/w	fixed wiper washerok.	675744
881	06/24/2019	824791	Consumables		675844
881	06/24/2019	824791	Consumables		675844
881	06/24/2019	824791	Mechanic entered - Body Other noisy from o/s/f modesty panel	fixed modesty panelok.	675744
881	06/24/2019	824791	Mechanic entered - Body Other front mirror loose.	tighnten mirrorok.	675744
881	06/24/2019	824791	Mechanic entered - Air System Air_Leak Front leaking air fro	r/r front levering contron valveok.	675744
881	06/24/2019	824791	SOLENOID VALVE FRONT		675744
881	06/12/2019	822512	Consumables		673871
881	06/12/2019	822512	Consumables		673871
881	06/12/2019	822512	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced H4 globe	673594
881	06/11/2019	822266	Consumables		673594
881	06/11/2019	822266	Consumables		673594
881	06/11/2019	822266	Mechanic entered - Elec and Light Interior Lights n/s/f park	r/r globeok.	672950
881	06/10/2019	822025	Consumables		673369
881	06/10/2019	822025	Consumables		673369
881	06/10/2019	822025	Elec and Light Two Way Radio not working.	Checked no power supply to radiochecked fuse all ok found loose connection wiring on inverter fixed ok	672950
881	06/05/2019	821182	When sitting at the lights or when the doors rea open the b	double entry	672337
881	06/05/2019	821182	Mechanic entered - Suspension Other O/S/F AirBag Leaking	Replaced O/S/F AirBag	672337
881	06/05/2019	821182	AIRBAG O/S/F SCANIA K230UB (2024284)		672337
881	06/05/2019	821182	Mechanic entered - Suspension Other N/S/F Air Bag Leaking	Replaced N/S/F AirBag	672337
881	06/05/2019	821182	Consumables		672724
881	06/05/2019	821182	Consumables		672724
881	06/05/2019	821182	Ops Entered - Fault - Elec and Light Horn - Route: 703b -	double entry	672337
881	06/05/2019	821182	ELECTRIC DISC HORN 24V(ACX5118)		672337
881	06/05/2019	821182	Horn is not working	REPAIR BROKEN WIREFIT NEW HORN.	672337
881	06/05/2019	821254	SLACK ADJUSTER AUTO-REAR O/SIDE (2009820) SERIES 4		672337
881	06/05/2019	821254	Brakes pull to the left	remove u/s o/s/r slack adjusteradjust allbrakesroad and brake test ok.	672337
881	05/29/2019	819828	Consumables		671551
881	05/29/2019	819828	Consumables		671551
881	05/29/2019	819828	BusMinder Unable To Log In	ok	671400
881	05/29/2019	819828	Ops Entered - Fault - BusMinder Missing - Route: 703 - Cen	fixed a new usb cable charging and operation ok	671400
881	05/28/2019	819483	Consumables		671400
881	05/28/2019	819483	Consumables		671400
881	05/28/2019	819483	Mechanic entered - Elec and Light Indicators Not Working N/S	FIT GLOBE.	670899
881	05/15/2019	816949	Consumables		669052
881	05/15/2019	816949	Consumables		669052
881	05/15/2019	816949	Elec and Light - busminder usb us	double entry	668860
881	05/12/2019	815340	Please remove all old poster and fit MYKI has gone mobil	fleet support completed this campaign	667705
881	05/04/2019	812833		CARRY OUT FIRE EXTINGUISHER TEST & TAG	666218
881	05/04/2019	812833		completed	666218
881	04/30/2019	812131	Consumables		666756
881	04/30/2019	812131	Elec and Light - speedo nw	replaced speedo sender; road tested ok	666218
881	04/30/2019	812131	SWITCH HAZARD 4 SERIES 1327015		666218
881	04/30/2019	812131	Mechanic entered - Dash Switches Not Working	Hazard switch broken replaced hazard switch checked operation of hazard switch ok.	666218

881	04/29/2019	812264	Consumables			666491
881	04/29/2019	812131	Consumables			666491
881	04/29/2019	812131	1853436 Speed sender	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O246509 Receiving #:254827 Date :2019-04-29 (VDO-2159.50)		666491
881	04/29/2019	812264	PULLEY IDLER SCANIA (1514087)			666218
881	04/29/2019	812264	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113			666218
881	04/27/2019	812223	Consumables			666218
881	04/27/2019	812223	Mechanic entered - Body Other	Replaced belt tensioner		666218
881	04/27/2019	812264	Mechanic entered - Body Other Belt tensioner pulley siezed	Replaced ribbed idle pulley		666218
881	04/27/2019	812264	Mechanic entered - Body Other Ribbed idle pulley slightly si	reconnected electrical connections for hammer alarm at rear door		666218
881	04/27/2019	812264	Mechanic entered - Body Other rear door hammer alarm not wor	Secured disabled seat pins		666218
881	04/27/2019	812264	Mechanic entered - Body Other Disabled seat pins loose	secured modesty pole		666218
881	04/27/2019	812264	Mechanic entered - Body Other ns mid modesty pole loose	secured stn pole		666218
881	04/27/2019	812264	Mechanic entered - Body Other osf stn pole loose	secured seat base		666218
881	04/27/2019	812131	Mechanic entered - Body Other	Speed sensor not working reconnected speed sensor road tested vehicle with gps to gauge accuracy of speedometer speedometer accurate within 2kmph. ok.		666218
881	04/26/2019	812223		Assisting		666218
881	04/26/2019	812223		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.		666218
881	04/26/2019	812223		VEHICLE SAFETY INSPECTION Carried out vehicle safety inspection as per checklist ok.		666218
881	04/26/2019	812131	Elec and Light - speedo nw	checked speedo fitted another head. still nw. removed the senser. need to order		666218
881	04/18/2019	810566	Engine - accelerator not working at times	BW fitted a diode to stop light signal to RPD. road tested and rectified speedo nw po for bw O246151		664737
881	04/18/2019	811189	CCTV repair	done by Johnny on 17/04/2019 PO#: O246165		664737
881	04/17/2019	811189	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O246165 Receiving #:254645 Date :2019-04-24 carry out cctv serice/repair as required		665958
881	04/16/2019	810566	Service	hooked SD2 and confirmed no faults with foot valve. suspected throttle sensor. rear doors still playing up. contacted BW elect.		664737
881	04/16/2019	810566	Engine - accelerator not working at times	checked and replaced throttle sensor.		664737
881	04/16/2019	810566	POTENTIOMETER ACCEL PEDAL SC	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O245958 Receiving #:254175 Date :2019-04-17		664737
881	04/15/2019	810480	DIRECT PURCHASE - TOWING	Creditor #:VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:O246582 Receiving #:255184 Date :2019-05-01 tow bus back to oakleigh depot as required		666756
881	04/15/2019	810480	Fault#:36486 - Ops Entered - Fault - Breakdown Low Engine Po	Attended breakdown of 881 found no power under acceleration reset vehicle in an attempt to gain acceleration accelerator not registering called tow truck removed n/s/r half shaft.		664737
881	03/28/2019	806926	Mechanic entered - Fluid Leaks Rear of bus leaking coolant.	r/r brether hose & long road testok.		661224
881	03/28/2019	806686	Mechanic entered - Air System Air_Leak Rear	check air leaksfound air comperssor cylinder air pluge bolt missingm check old air comperssor cylinder not found bolt check bolt engine roomput back bolttightened air comperssor cylinder air valve bolt.ok		661224
881	03/27/2019	806539	Consumables			661615
881	03/27/2019	804708	Consumables			661615
881	03/27/2019	804708	40A9901 Coolant Hose	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O244311 Receiving #:252737 Date :2019-03-29		661615
881	03/27/2019	806539	passenger door not working	reset benware door node system . checked operation of passenger doors all okay		661224
881	03/27/2019	804708	BOLT COMPRESSOR GEAR	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O244001 Receiving #:252594 Date :2019-03-27		661224
881	03/27/2019	804708	SEAL O-RING COMPRESSOR MOUNT	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O244001 Receiving #:252594 Date :2019-03-27		661224
881	03/27/2019	804708	O-RING COMPRESSOR 11MM ID SCA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O244001 Receiving #:252594 Date :2019-03-27		661224
881	03/27/2019	804708	40A9106Knorr Air Compressor	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O244001 Receiving #:252594 Date :2019-03-27		661224
881	03/26/2019	804708	coolant leak	r/r air compresureok.		661224
881	03/19/2019	804708	coolant leak	leaking coolant from header tank. need replace air compressor.		660323
881	03/04/2019	801684	Mechanic entered - Engine Other engine sump oil leaks	tightened bottom sump bolts okroad tested ok		657314
881	03/04/2019	801638	Consumables			657395
881	03/04/2019	801638	Mechanic entered - Body Other middle seat top pin out	put in middle seat top pins ok		657314
881	03/04/2019	801638	Mechanic entered - Body Other air dryer filter case hit from	grinding from a/c bracket ok		657314
881	03/04/2019	801638	Mechanic entered - Body Other n/s/f seat base cut	repaired n/s/f seat base ok		657314
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	FILTER AIR FILTER (395773) AF25066			657314
881	03/04/2019	801486	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)			657314
881	03/04/2019	801486	FILTER FUEL FILTER SCANIA SR4 (1393640)			657314
881	03/04/2019	801486	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)			657314
881	03/04/2019	801486	FILTER HYD COOLING FAN SCANIA SR3 (1354074)			657314
881	03/04/2019	801486		CARRY OUT C SERVICE AS PER CHECK LIST		657314
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	Consumables			657395
881	03/04/2019	801486	FILTER FUEL FILTER SCANIA SR4 (1372444)			657314
881	03/04/2019	801486	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			657314
881	03/04/2019	801486	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			657314
881	03/04/2019	801486	Oil Filter SC S4 & K			657314
881	03/04/2019	801486		CARRY OUT B SERVICE AS PER CHECK LIST		657314
881	03/04/2019	801486		CARRY OUT B SERVICE AS PER CHECK LIST		657314
881	03/01/2019	801160		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		657314
881	03/01/2019	801160		VEHICLE SAFETY INSPECTION		657314
881	03/01/2019	801160		ANNUAL SAFETY INSPECTIONSERIAL #J815674 WORKSHOP SUPERVISOR/MANAGERNOTE:REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TOO.25 done by Fleetcheck on 01/03/2019 PO#: O242352		657314
881	03/01/2019	801129	Consumables			657385
881	03/01/2019	801129	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque all n/s/r wheel nuts.		657314
881	03/01/2019	799857	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O241859 Receiving #:250945 Date :2019-03-07 johnny to rectify intermittant video loss as required		657807
881	02/27/2019	800261	Mechanic entered - Wipers and Washers Other	double entry		656717
881	02/27/2019	800212		Retension wheels top up diff and engine oil adjusted brakes wash engine diff and transmission road tested		656717
881	02/26/2019	800212	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O242120 Receiving #:250520 Date :2019-03-01 hub seal x 1		657314
881	02/26/2019	800212	LOCK WASHER REAR AXLE SCANIA 273023			656717
881	02/26/2019	800212	SEAL REAR AXLE CAP SCANIA 1765061 120310			656717
881	02/26/2019	800212	OUTER REAR HUB OIL SEAL L113CRB			656717
881	02/26/2019	800212		Assembled hub with seals and gaskets wash rims and fit back		656717
881	02/26/2019	800178		Replaced rocker cover gaskets and fit air cleaner housing and turbo hoses		656717
881	02/25/2019	800178		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		656717
881	02/25/2019	800178		VEHICLE SAFETY INSPECTION		656717
881	02/25/2019	800261	Mechanic entered - Wipers and Washers Other	Replaced leaking washer tank with motor		656717
881	02/25/2019	800212	Rear D rubbers to replace and n/s/r hub seal	Replaced rear D rubber bushes removed n/s/r hub and clean parts		656717
881	02/25/2019	800212	GASKET ROCKER COVER SCANIA SR4 DC9 (1425921)			656717
881	02/25/2019	800212	BUSH SWAY BAR FRONT SCANIA K SERIES (1880751) (47mmID)			656717
881	02/25/2019	800212	Replace leaking rocker cover gaskets	Remove air cleaner housing and change rocker cover gaskets		656717
881	02/25/2019	800067	Mechanic entered - Elec and Light Indicators Not Working n/s	fit globe.		656717
881	02/22/2019	799857	CCTV - rectify intermittant video loss as required	O241859 - carried out by johnny		656717
881	02/18/2019	798685	Consumables			656009
881	02/18/2019	798685	Nut Retension Retension pos 2 tyre	carried out retorque as required		655537
881	02/16/2019	798284		PRE ANNUAL SAFETY INSPECTION CHECK		655537
881	02/16/2019	798335	WIPER REFILL 1000mm MULTI FIT			655537
881	02/16/2019	798335	Mechanic entered - Wipers and Washers Other	Repaired leaking hose for washer and changed wiper refills		655537
881	02/16/2019	798284	Consumables			655764
881	02/16/2019	798331	Consumables			655764
881	02/16/2019	798284	Wheel Nut Retension Retension n/s/r wheels	carried out retorque as required		655537

881	02/16/2019	798331	TYRE 295/80R22.5 NEW			655537
881	02/16/2019	798331	Mechanic entered - Wheels and Tyres Worn	Replaced worn pos 2 tyre with new tyre fitted extension valve on pos 5 tyre Clenaed and painted rim		655537
881	02/16/2019	798336	BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)			655537
881	02/16/2019	798336	Mechanic entered - Suspension Other	Replaced front D rubber bushes		655537
881	02/16/2019	798332	Lamp Step White LED			655537
881	02/16/2019	798332	Mechanic entered - Elec and Light Interior Lights	Replaced rear door interior step light on the bottom and seaal from the back		655537
881	02/16/2019	798338	Consumables			655764
881	02/16/2019	798338	CAP END CAP CENTRA SEAT END CAP			655537
881	02/16/2019	798338	Mechanic entered - Body Other	Drill and fit screws to overhead panels drivers modesty panel front myki mount bar Replaced two broken seat end caps		655537
881	02/14/2019	798050	Consumables			655537
881	02/14/2019	798050	Mechanic entered - Wheels and Tyres Flat or Leaking	Replaced flat pos 4 tyre with a runout Removed near side drum to check oil leak		655307
881	02/08/2019	796488		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out firesafe as per check list		654461
881	02/07/2019	795018	fuel tank leaking	fit fuel tankfill with fuelbleed fuel systemstart busok.		654461
881	02/06/2019	795018	DIRECT PURCHASE - MECHANICAL G	Creditor #.:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #.:O240212 Receiving #.:248910 Date :2019-02-11 rectify fuel tank leaking as required		654920
881	02/01/2019	794825	DIRECT PURCHASE - TOWING	Creditor #.:VB-EAGTOW EAGLE TOWING & SALVAGE P/O #.:O240465 Receiving #.:248905 Date :2019-02-11 tow bus to oakleigh depot as required		654920
881	02/01/2019	794825	Breakdown#:36182 - Ops Entered - Breakdown - Breakdown Air S			654461
881	02/01/2019	794825	Breakdown#:36182 - Ops Entered - Breakdown - Breakdown Air S	fitted the nsr axle and removed the wood pieces for towee. fitted osr rear air bag that damaged by mud flap bracket. pushed the flap bracket into the position and secured air supply		654461
881	02/01/2019	794825	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			654461
881	02/01/2019	795018	fuel tank leaking	assisted craig to remove the fuel tank. steam washed the tank. sent away to auto cooling for leak repair		654461
881	01/31/2019	794825	Breakdown#:36182 - Ops Entered - Breakdown - Breakdown Air S	Attended breakdown at middle brighton found o/s/r/r air bag leaking remove axle and arrange tow		654461
881	01/29/2019	794113	Mechanic entered - Suspension Other o/s/r/r air bag u/s	replaced o/s/r/r air bag ok		654178
881	01/29/2019	794113	Ops Entered - Fault - Suspension Kneel/ Raise - Route: 703	replaced o/s/r/r air bag ok		654178
881	01/29/2019	794113	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			654178
881	01/18/2019	792289	low coolant level	tightend hose clamp. topped up coolant . rechecked for leaks . all okay		652857
881	01/18/2019	792122	CCTV - nw	done by Johnny - BW electrics PO O239153		652857
881	01/18/2019	792288	Please remove old 2018 fare decals and fit new 2019 fare de	carried out campaign as required		652857
881	01/17/2019	792122	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #.:O239153 Receiving #.:248182 Date :2019-01-31 check and rectify CCTV issues as required		654461
881	01/15/2019	790787	Body Front_Door Operation Faulty	fixed wiringok.		652280
881	01/15/2019	791027	DIRECT PURCHASE ACCIDENT	Creditor #.:VB-ECOAST EASTCOAST TRUCK & BUS P/O #.:O238757 Receiving #.:246802 Date :2019-01-15 repair accident damage as required Acc#47811 and 47795		652280
881	01/14/2019	791027	Accident#:47795 - Ops Entered - Accident - Bus Hitting Obje	done at body shop PO#: O238757		651988
881	01/14/2019	791027	Accident#:47811 - Ops Entered - Accident - Bus hits 3rd Par	done at body shop PO#: O238757		651988
881	01/12/2019	790863	Consumables			652280
881	01/12/2019	790863	Mechanic entered - Wheels and Tyres Other n/s tyre air valv			651988
881	01/11/2019	790734	Mechanic entered - Engine Other engine fan oil low	DOUBLE ENTRY		651988
881	01/11/2019	790702	Consumables	put in engine fan oil 3L		652280
881	01/11/2019	790702	Mechanic entered - Elec and Light Other n/s head light wires	repaired n/s head light wires ok		651988
881	01/01/2019	786419	DIRECT PURCHASE - ELECTRICAL	Creditor #.:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #.:O237120 Receiving #.:247373 Date :2019-01-22 johnny from bwere to carry out gen 5 uograde to bus 881 as required		653263
881	12/28/2018	788095		TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.		651988
881	12/21/2018	787514	DIPSTICK SCANIA SERIES 4 (1515996)			651256
881	12/21/2018	787514	Mechanic entered - Engine Other	Replaced damage dipstick		651256
881	12/17/2018	786419	CCTV - this bus has still got an old Ness system fitted; ne	O237120		649991
881	12/17/2018	786419	CCTV not connecting to wifi system	gen 5 upgrade carried out by johnny bwere - O237120		649991
881	12/06/2018	784133		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.		647426
881	12/06/2018	784133		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist. ok.		647426
881	12/06/2018	784180	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			647426
881	12/06/2018	784180	Mechanic entered - Engine Other Serpentine belt cracked	Found serpentine belt cracking replaced serpentine belt. ok.		647426
881	12/06/2018	784224	Consumables			647810
881	12/06/2018	784224	Mechanic entered - Elec and Light Other O/S bottem brake lig	Found broken wire repaired broken wire checked operation of lights.		647426
881	11/24/2018	781522	Mechanic entered - Fluid Leaks Rear of bus coolant	top up coolantcheck for leaks could not fault.		644459
881	11/23/2018	781303	Consumables			645011
881	11/23/2018	781303	Mechanic entered - Body Other horn pad wont secure.	fit horn pad from 884		644459
881	11/21/2018	780768	Mechanic entered - Fluid Leaks Rear of bus coolant	check for coolant leakscould not faulttop up coolantok.		642970
881	11/21/2018	780793	Consumables			644459
881	11/21/2018	780765	Consumables			644459
881	11/21/2018	780793	Body frt door not close/open reported by Geoff	checked by CDF wo780765		642970
881	11/21/2018	780765	Mechanic entered - Body Front_Door Operation Faulty	check operation front doorcould not fault.		642970
881	11/21/2018	780862	Accident#:47847 - Ops Entered - Accident - Bus Hitting Obje	Simon has checked and damage has been done and job has been taken offperformance monitor		642970
881	11/19/2018	780068	Consumables			643817
881	11/19/2018	780068	SOLID PLASTIC VALVE EXTENSION (150mm)			642970
881	11/16/2018	779923	CCTV not recording since 15/05/2018 please change to Thore	double entry		642970
881	11/16/2018	780068	Mechanic entered - Body Other	Drill out out rivets and replaced broken top hinge for drivers door		642970
881	11/16/2018	780068	HINGE 102mm BLACK			642970
881	11/15/2018	779648	Consumables			643432
881	11/15/2018	779648	Mechanic entered - Body Other graffiti.	clean graffiti off windowseat backs and inside panels.		642970
881	11/10/2018	778609	Consumables			642244
881	11/10/2018	778609	Body Drivers Seat Belt will not come out.	repositionsecure seat belt.		641896
881	11/02/2018	776695	Engine overheating and smoke from the breather pipe.	fitted new radiator intercooler ouil cooler & hoses. fitteed coolant hoses & fill up hydraulic oil. drive test & check ptik.		641160
881	11/02/2018	776695	THERMOSTAT 75/79 DEG - DOUBLE (40A3513)			641160
881	11/01/2018	776695	Engine overheating and smoke from the breather pipe.	removed thermostart need to order for thermostart. fitted new thermostart.		641160
881	10/31/2018	776695	DIRECT PURCHASE - MECHANICAL G	Creditor #.:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #.:O233315 Receiving #.:241185 Date :2018-11-02 supply new radiator as required		641160
881	10/30/2018	776695	Engine overheating and smoke from the breather pipe.	removed radiator.		641160
881	10/26/2018	775982	Body Water Leaks Roof leaking from drivers light onto MY	sealed around 2-way antenna checked for leaks all okay		640715
881	10/26/2018	775982	Consumables			640938
881	10/26/2018	775982	Consumables			640938
881	10/24/2018	775337	Mechanic entered - Elec and Light Exterior Lights n/s headli	fit globe.		639976
881	10/24/2018	775337	Consumables			640455
881	10/15/2018	773238	Consumables			638964
881	10/15/2018	773238	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retorque all n/s/r wheel nuts.		638265
881	10/12/2018	772959		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		638265
881	10/12/2018	772959		VEHICLE SAFETY INSPECTION done.		638265
881	10/12/2018	773070	Consumables			638265
881	10/12/2018	773070	INDICATOR CHECK LINK WHEEL NUT LOCK 33mm			638265
881	10/12/2018	773070	Mechanic entered - Wheels and Tyres Other worn wheel nut poi	r/r pointersok.		638265
881	10/12/2018	773070	Mechanic entered - Wheels and Tyres Worn worn n/s/r tyres.	r/r n/s/r tyresok.		638265
881	10/12/2018	773070	Consumables			638265
881	10/12/2018	773070	Mechanic entered - Elec and Light Interior Lights drivers li	r/r globeok.		638265
881	10/12/2018	773070	Consumables			638265
881	10/12/2018	773070	Consumables			638265
881	10/12/2018	773070	TYRE 295/80R22.5 RECAP			638265
881	10/12/2018	773070	Mechanic entered - Body Other fire extingusher u/s.	r/r fire extingusherok.		638265
881	10/12/2018	773070	Mechanic entered - Body Other loose drivers door hinge.	fixed door hingeok.		638265
881	10/12/2018	773070	Mechanic entered - Body Other noisy from a/c pod.	fitted new screws & tighten screwsok.		638265
881	10/12/2018	773070	Mechanic entered - Body Other loose interior mirror.	tighten mirrorok.		638265

881	10/12/2018	772959	Consumables			638265
881	10/12/2018	772959	Consumables			638265
881	10/12/2018	772959	Consumables			638265
881	10/12/2018	772959	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			638265
881	10/12/2018	772959	FILTER FUEL FILTER SCANIA SR4 (1372444)			638265
881	10/12/2018	772959	O-RING LARGE SPINNER FILTER SCANIA (1769799)			638265
881	10/12/2018	772959	O-RING SPINNER FILTER SCANIA (1769798)			638265
881	10/12/2018	772959	Oil Filter SC S4 & K			638265
881	10/12/2018	772959		CARRY OUT B SERVICE AS PER CHECK LIST done. done.		638265
881	10/05/2018	771181	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	carried out campaign as required		636874
881	10/03/2018	770500	Consumables			636636
881	10/03/2018	770500	Mechanic entered - Elec and Light Indicators Not Working TO	COULD NOT FAULT BLINKER.		636176
881	09/26/2018	769253		CARRY OUT FIRE EXTINGUISHER TEST & TAG		635452
881	09/26/2018	769253		closed off as completed as per instruction from paul bell		635452
881	09/24/2018	768649	Wipers and Washers - n/s wiper arm hitting on body	repositioned wiper arm all okay		635005
881	09/16/2018	766967	Consumables			633669
881	09/16/2018	766967	Body - n/s drivers mirror broken	fit 2nd hand mirror		633429
881	09/07/2018	764718	Consumables			632148
881	09/07/2018	764718	Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	carried out retorque as required		632148
881	09/07/2018	764745	Consumables			632148
881	09/07/2018	764745	Mechanic entered - Body Other damage n/s/r corner	R&R lens		632148
881	09/07/2018	764745	LENS ROUND NARVA (2.9800.09)			632148
881	09/06/2018	764454	Consumables			632148
881	09/06/2018	764428	Consumables			632148
881	09/06/2018	764428	Mechanic entered - Wheels and Tyres Other n/s/f tyre u/s	replaced n/s/f tyre ok retorqued n/s/f wheel nuts ok		631613
881	09/06/2018	764428	TYRE 295/80R22.5 NEW			631613
881	09/06/2018	764454	Mechanic entered - Wheels and Tyres Damaged	done on wo764428		631613
881	09/04/2018	763847	Consumables			631613
881	09/04/2018	763847	Ops Entered - Fault - Body Drivers Seat Leaning - Route:	recalibrated drivers seat . checked operation all okay		631423
881	08/27/2018	761682	807311 Washer	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O227987 Receiving #:235586 Date :2018-08-27		629582
881	08/27/2018	761682	2026123 Wear Indicator	Creditor #:\VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O227987 Receiving #:235586 Date :2018-08-27		629582
881	08/24/2018	761620		SERVICE MOISTURE EJECTOR		629393
881	08/24/2018	761620		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		629393
881	08/24/2018	761620		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		629393
881	08/24/2018	761620		VEHICLE SAFETY INSPECTION done.		629393
881	08/24/2018	761682	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	tighten hose clampok.		629393
881	08/24/2018	761682	Consumables			629398
881	08/24/2018	761682	Mechanic entered - Elec and Light Interior Lights drivers li	r/r globeok.		629393
881	08/24/2018	761682	Mechanic entered - Elec and Light Exterior Lights n/s/f scho	r/r globeok.		629393
881	08/24/2018	761682	Consumables			629398
881	08/24/2018	761682	Mechanic entered - Body Other pax seat grab u/s.	r/r grabok.		629393
881	08/24/2018	761682	Brakes - nsf slack adjuster bolt cap missing	ordered new - this part was fitted as Lee had a spare.		629393
881	08/24/2018	761682	Mechanic entered - Brakes Other s cam & slack adjuster wear	removed hubdrum & checked for s camok.		629393
881	08/20/2018	760505	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	carried out campaign as required		628156
881	08/18/2018	760186	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	installed DC5V outlet		628156
881	08/02/2018	756687	Consumables			625469
881	08/02/2018	756687	Mechanic entered - Body Drivers Seat Controls headrest missi	could not fault - these particular buses do not have head rests on drivers seat		624971
881	07/27/2018	755319	Consumables			624131
881	07/27/2018	755319	Mechanic entered - Body Other steer wheel cover loose	repaired cover all ok		623910
881	07/23/2018	746823	SLACK ADJUSTER FRONT NEAR SIDE (1789568)			622911
881	07/20/2018	753926	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	campaign completed		622443
881	07/20/2018	753925	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	campaign completed		622443
881	07/19/2018	753419	Consumables			622443
881	07/19/2018	753419	Body - frt door not closing need override switch pressed to	done by BW electrics on 19/07/2018 not requested for a PO		622309
881	07/17/2018	752916	AIR CONDITIONING REPAIR	Creditor #:\VB-COL004 COLD DRIVE PTY LTD P/O #:O224737 Receiving #:232791 Date :2018-07-25 carry out AC - B service as required		623886
881	07/17/2018	752916		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - done by cold drive PO#: O224737		622309
881	07/17/2018	752916		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		622309
881	07/11/2018	747997	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			621056
881	07/11/2018	747997	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)			621056
881	07/10/2018	751134	Consumables			621056
881	07/10/2018	751134	Mechanic entered - Elec and Light Other demister n/w.	fit new demister motor to demister housingfit housing to buswire indemister ok.		621002
881	07/09/2018	751106	Ops Entered - Fault - Heat & Demist - Route: 703 - Centre	repaired on work order - 751134		621002
881	07/09/2018	751134	Mechanic entered - Elec and Light Other demister n/w.	demister motor u/sin process removing demister motor.		621002
881	07/05/2018	750383	Vandalism Vandalism/ Graffiti Interior	Complete		620190
881	07/02/2018	749561	Consumables			619968
881	07/02/2018	749561	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	carried out retorqe as required		619703
881	06/29/2018	749092	Mechanic entered - Brakes Other brake shutter	adjusted brakes and road tested and braketested. all ok		619275
881	06/29/2018	748141	Brakes Foot_Brakes Noisy and the retarder is not working	assemble front brakes ns front with brendan lee assembled os front with brendan test driven ok		619275
881	06/28/2018	747997	Mechanic entered - Suspension Other rear both all air bags u	replaced rear all air bag replaced air bag hose fitting ok		619275
881	06/28/2018	748141	Direct Purchase - BODYWORK	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O223169 Receiving #:230760 Date :2018-06-29 refoam drivers seat base as required		619517
881	06/28/2018	748141	Consumables			619517
881	06/28/2018	748141	Consumables			619517
881	06/28/2018	748141	Drv entered - Body Drivers Seat Cover	fitted seat base		619275
881	06/28/2018	748141	LOCK RING BRAKE SHOE PIN 0804782			619275
881	06/28/2018	748141	O-RING BRAKE SHOE PIVOT (1338019)			619275
881	06/28/2018	748141	Drv entered - Brakes Foot_Brakes Pulling	assembled front brakes and wheel assembly adjusted front and rear brakes fitted rear wheels and tenstioned all wheel nuts / tenstioned front hub nuts to 1000nm test driven and brake tested		619275
881	06/28/2018	748141	Drv entered - Brakes Foot_Brakes Noisy	replaced rear o/s brake liningsdurmlock ringoring ok replaced n/s/r brakeliningsdurmlock ring ok		619275
881	06/27/2018	748141	Drv entered - Body Drivers Seat Cover	removed seat base		619275
881	06/27/2018	748141	DIRECT PURCHASE - BRAKES	Creditor #:\VB-COM100 Commercial Brake & Clutch P/O #:O223190 Receiving #:230826 Date :2018-06-29 replace all brake linings supply all 4 drums (2 rear and 2 front) . radius grind and machine supply brake return springs x 4 as required		619517
881	06/26/2018	747930		TRANSMISSION CHECK AS PER CHECK LIST		619275
881	06/26/2018	747930		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		619275
881	06/26/2018	747930		VEHICLE SAFETY INSPECTION		619275
881	06/26/2018	747997	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)			619275
881	06/26/2018	747997	Mechanic entered - Engine Other coolant collaht sickt crack	replaced coolant collaht sickt ok		619275
881	06/26/2018	747997	Consumables			619517
881	06/26/2018	747997	LAMP LED SIDE MARKER RED/AMBER			619275
881	06/26/2018	747997	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok		619275
881	06/26/2018	747997	Mechanic entered - Elec and Light Other n/s/r mark light not	replaced n/s/r mark light ok		619275
881	06/26/2018	747997	Mechanic entered - Elec and Light Other pax switch u/s	replaced pax switch ok		619275
881	06/26/2018	747997	BELL PUSH STOP BUTTON FLAT (571-0226) (11870)			619275
881	06/26/2018	747997	Mechanic entered - CCTV Other cctv not working	repaired cctv relay wires ok		619275
881	06/26/2018	747997	Consumables			619517
881	06/26/2018	747997	Consumables			619517

881	06/26/2018	747997	Mechanic entered - Body Other middle seat loose	replaced middle seat ok	619275
881	06/26/2018	747997	Mechanic entered - Body Other roof bolts loose	tightened roof bolts ok	619275
881	06/26/2018	748141	Brakes Foot_Brakes Noisy and the retarder is not working		619275
881	06/26/2018	748141	Drv entered - Brakes Foot_Brakes Noisy	removed rear both brake liningsdurms removed front both brakeliningsdurms	619275
881	06/26/2018	747997	Mechanic entered - Air System Other condenser drain valve fi	removed condenser drain valvecleaned condenser drain valve fittingtightened drain valve fitting ok	619275
881	06/26/2018	747997	Mechanic entered - Air System Other air dryer fitting air le	removed air dryer fittingtightened air dryer fitting ok	619275
881	06/23/2018	747548	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	fitted registration label as required	618498
881	06/21/2018	746833	Consumables		618498
881	06/21/2018	746833	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	retorqued o/s/r wheel nuts to OEM spec	618022
881	06/21/2018	746885	Engine - coolant leak at header tank as required	tighted fitting at header tank	618022
881	06/21/2018	746861	Mechanic entered - Brakes Foot_Brakes Noisy		746823 618022
881	06/21/2018	746823	brakes pulling	brakes where pulling adjusted all brakes and replaced n/s/f slack adjuster. road and brake tested all ok	618022
881	06/19/2018	746343	Consumables		618022
881	06/19/2018	746343	TYRE 295/80R22.5 RECAP		617788
881	06/19/2018	746343	Mechanic entered - Wheels and Tyres Other o/s/r tyres u/s	replaced o/s/r tyres ok	617788
881	06/19/2018	746195	Breakdown#:35079 - Ops Entered - Breakdown - Breakdown Overh	removed trans coolant hose order replaced coolant hoseput in coolant ok road tested okckcek coolant ok	617788
881	06/19/2018	746195	40N05101 Transmission Coolant	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O222568 Receiving #:230019 Date :2018-06-19	617937
881	06/19/2018	746343	Consumables		618022
881	06/19/2018	746343	Mechanic entered - Elec and Light Other button shift N u/s	replaced buttom shift N ok	617788
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191	Oil Filter SC S4 & K		617788
881	06/19/2018	746191	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		617788
881	06/19/2018	746191	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		617788
881	06/19/2018	746191	FILTER FUEL FILTER SCANIA SR4 (1372444)		617788
881	06/19/2018	746191		CARRY OUT B SERVICE AS PER CHECK LIST	617788
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191	Consumables		618022
881	06/19/2018	746191		CARRY OUT A SERVICE AS PER CHECK LIST	617788
881	05/29/2018	742013	Drv entered - Brakes Foot_Brakes Noisy	completed on work order - 741764	613101
881	05/29/2018	742013	Drv entered - Brakes Warning Light On	completed on work order - 741764	613101
881	05/29/2018	742013	Drv entered - Brakes Foot_Brakes Noisy	completed on work order - 741764	613101
881	05/29/2018	741764	Drv entered - Brakes Foot_Brakes Pulling	adjusted brakes and road tested and brake tested.	613101
881	05/29/2018	741764	Drv entered - Brakes Foot_Brakes Pulling	adjusted brakes and road tested and brake tested all ok	613101
881	05/26/2018	741419	Elec and Light Exterior Lights N/S/T/F park light not wo	R&R globe . checked operation all okay	613101
881	05/26/2018	741419	Consumables		613488
881	05/26/2018	741420	Body - rectify cracked mirror on bus as required		613101
881	05/26/2018	741420	Consumables	repaired on work order - 741067	613488
881	05/25/2018	741187	n/s/f top parklight lens fallen off		613101
881	05/25/2018	741187	Consumables	remove housingrefit lens.	613488
881	05/24/2018	741067	Mechanic entered - Engine Other coolant leaks	check coolantfound coolant head tank cap replaced coolant head tank cap ok	613101
881	05/24/2018	741067	HEADER TANK FILLER CAP 1403954		613101
881	05/24/2018	741067	MIRROR L/H 380mm SHORT (UES1411E)		613101
881	05/24/2018	741067	Mechanic entered - Body Other n/s mirror u/s	replaced n/s mirroradjusted mirror ok	613101
881	05/24/2018	741067	Consumables		613297
881	05/24/2018	741066	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	carried out campaign as required	613101
881	05/22/2018	740192	Consumables		612873
881	05/22/2018	740192	Mechanic entered - Elec and Light Exterior Lights n/s/f top	fit globe.	612497
881	05/22/2018	740236	KIT SWITCH OVERRIDE RPD		612497
881	05/22/2018	740236	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INST	installed wiring and the dash switcth. programmed the RPD node. checked all good.	612497
881	05/17/2018	739221	Consumables		612233
881	05/17/2018	739221	Mechanic entered - Body Drivers Seat Belt n/w/	repositionsecure.	611754
881	05/16/2018	739042	Ops Entered - Fault - A/C Heating Not Heating - Route: 703	no saloon heaters while the demisters working good. checked and found no pwr to the boost pump motor. checked the fuses ok. traced the wiring and found a broken wire that supplies pwr to boost pump. repaired and checked ok.	611754
881	05/16/2018	739042	Ops Entered - Fault - A/C Heating Not Heating - Route: 703	road tested and checked heaters ok	611754
881	05/15/2018	738650	Consumables		611754
881	05/15/2018	738650	Mechanic entered - Body Drivers Seat Belt	reposition and secure	611281
881	05/09/2018	737524	Consumables		610752
881	05/09/2018	737524	Mechanic entered - Elec and Light Exterior Lights n/s/f side	repositioned globe in holder	610342
881	05/07/2018	736810	VALVE FOOTBRAKE SR3 & SR4 SC 0469052		610117
881	05/04/2018	736613		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	609609
881	05/04/2018	736613		VEHICLE SAFETY INSPECTION	609609
881	05/04/2018	736684	Consumables		609830
881	05/04/2018	736684	VALVE EXTENSION-130mm Metal type		609609
881	05/04/2018	736684	Mechanic entered - Wheels and Tyres Other n/s/r tyre air val	replaced n/s/r tyre air valve ok	609609
881	05/04/2018	736684	Consumables		609830
881	05/04/2018	736684	Mechanic entered - Elec and Light Other dash all gauge light	replaced dash gauge all globe ok	609609
881	05/04/2018	736684	Consumables		609830
881	05/04/2018	736684	REFLECTOR AMBER 94mm X 44MM (84051)		609609
881	05/04/2018	736684	Mechanic entered - Body Other middle seat loose	repaired middle seat ok	609609
881	05/04/2018	736684	Mechanic entered - Body Other driver modesty panel bolt miss	replaced modesty panel bolt iok	609609
881	05/04/2018	736684	Mechanic entered - Body Other o/s reflector missing	replaced o/s reflector ok	609609
881	05/04/2018	736810	Mechanic entered - Brakes Other footbrake valve u/s	removed footbrake valve replaced footbrake valveok road testedbrake tested ok	609609
881	05/04/2018	736756		CARRY OUT A SERVICE AS PER CHECK LIST	609609
881	05/04/2018	736756	Consumables		609830
881	05/04/2018	736756	Consumables		609830
881	05/04/2018	736756	Consumables		609830
881	05/01/2018	726350	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O215642 Receiving #:228699 Date :2018-05-31 carry out RSI inspection x 1 as required	613981
881	04/28/2018	735397	Mechanic entered - Elec and Light Exterior Lights n/s headli	fit globes headlight and parker.	608273
881	04/28/2018	735397	Consumables		608731
881	04/20/2018	734028	Consumables		606904
881	04/20/2018	734028	Mechanic entered - Elec and Light Exterior Lights front door	fit globee	606434
881	04/17/2018	722216	Mechanic entered - Suspension Other v-rod bush us	replaced v rod taper bush	605905
881	04/17/2018	722216	Consumables		606209
881	04/17/2018	722216	Mechanic entered - Body Other fuel tank bracket us - very ba	tank was sent to Hallam truck centre for repair PO#: O214816	605905
881	04/17/2018	722216	Mechanic entered - Brakes Other osr booster leaking badly	R&R brake booster	605905
881	03/26/2018	729248	Consumables		602338
881	03/26/2018	729139	Consumables		602338
881	03/26/2018	729248	Mechanic entered - Body Other cleaned blood off floor. ok	cleaned blood of saloon floor	601901
881	03/26/2018	729139	Body seatbelt is not working	reposition and secure	601901
881	03/17/2018	727426	Vandalism interor graffiti	painted over interior graffiti	600346
881	03/14/2018	726411	RSI repairs - rectify transmission leak as required	replace o ring for cover below output yolk test driven vehiclh clean no leak	600346

881	03/13/2018	726350	VEHICLE SAFETY INSPECTION	600346
881	03/13/2018	726350	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	600346
881	03/13/2018	726350	ANNUAL SAFETY INSPECTION SERIAL # ____ RSI 012145 _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	600346
881	03/13/2018	726451 BUSH REAR SWAY BAR K94 SCANIA ID- (50 mmID)		600346
881	03/13/2018	726451 Mechanic entered - Suspension Noisy	replace rear sway bar bushes	600346
881	03/13/2018	726411 RSI repair - rectify transmission leak as required	traced and found small leak coming from engine side cover . tightend bolts for side cover . road tested all okay no more leaks	600346
881	03/13/2018	726411 RSI repairs - rectify transmission leak as required	steam clean transmission to establish were the leak is	600346
881	03/13/2018	726467 Consumables		600346
881	03/13/2018	726467 Mechanic entered - Elec and Light Exterior Lights	replace os marker lamp	600346
881	03/13/2018	726467 LAMP LED SIDE MARKER RED/AMBER		600346
881	03/13/2018	726324 Consumables		600346
881	03/13/2018	726324 Consumables		600346
881	03/13/2018	726324 Consumables		600346
881	03/13/2018	726324	CARRY OUT A SERVICE AS PER CHECK LIST a service completed + took vehiclle to seaford depot for rsi inspection 10:00am until 1:00 pm	600346
881	03/09/2018	722216 Consumables		600346
881	03/09/2018	722216 Mechanic entered - Body Other fuel tank bracket us - very ba	fit fuel tank fill diesel jump start bleed fuel system	600346
881	03/09/2018	722216 DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-HAL004 HALLAM TRUCK CENTRE P/O #:O214816 Receiving #:223592 Date :2018-03-22 repair the diesel tank leaking as required	601642
881	03/07/2018	722216 DIRECT PURCHASE - BODYWORK	Creditor #:VB-FAI100 FAIRFAB P/O #:O215496 Receiving #:222720 Date :2018-03-09 Fuel tank brackets - Heavy duty	600346
881	03/07/2018	722216 KIT BUSH V BAR SCANIA		600134
881	03/07/2018	722216 BUSH KITSCANIA L94UAB V STAY 40Y3318ZF 28772 01		600134
881	03/05/2018	724489 PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	carried out campaign as required	600134
881	03/01/2018	722216 BUSH KITSCANIA L94UAB V STAY 40Y3318ZF 28772 01		600134
881	02/28/2018	722216 40G2511WABCO 0/S/R BRAKE BOOST	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O214735 Receiving #:222246 Date :2018-03-05	600346
881	02/24/2018	722202	PRE ANNUAL SAFETY INSPECTION CHECK pre inspectione completed	600134
881	02/24/2018	722202 Drv entered - Wipers and Washers Wipers Not_Clearing Screen		600134
881	02/22/2018	721703 Consumables		600134
881	02/22/2018	721703 BATTERY 700CCA - POS ON RHS		599889
881	02/22/2018	721703 Mechanic entered - Elec and Light Flat Batteries	load tested batterrys . replaced both	599889
881	02/19/2018	720942 40V0200 STARTER MOTOR BOSCH	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O214202 Receiving #:222459 Date :2018-03-06 supply starter motor as required	600346
881	02/19/2018	720942 DIRECT PURCHASE - TOWING	Creditor #:VB-EAGTOW EAGLE TOWING & SALVAGE P/O #:O214981 Receiving #:222294 Date :2018-03-05 tow bus to oakleigh depot for starter motor u/s	600346
881	02/19/2018	720942 Engine starter motor u/s	R&R starter motor . road tested all okay	599049
881	02/19/2018	720989 Mechanic entered - Engine Other start motor u/s	replaced engine start motor okall check ok	599049
881	02/19/2018	720824 Engine - needs jump start	jump started	599049
881	02/13/2018	719624 Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	carried out campaign as required	598410
881	02/12/2018	718903 Consumables		598410
881	02/12/2018	718903 Mechanic entered - Elec and Light Next Stop Button hanging d	secure pax button.	597649
881	02/12/2018	719243	CARRY OUT FIRE EXTINGUISHER TEST & TAG	597649
881	02/12/2018	719231	CARRY OUT FIRE EXTINGUISHER TEST & TAG	597649
881	02/12/2018	719243	inspection carried out by ATS fire services - O213090	597649
881	02/12/2018	719231	inspection carried out by ATS fire services - O213090	597649
881	02/02/2018	716857	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list	596423
881	01/27/2018	714061 PULLEY IDLER SCANIA (1514087)		595198
881	01/27/2018	714061 SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		595198
881	01/23/2018	714980	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	594684
881	01/23/2018	714980	VEHICLE SAFETY INSPECTION done.	594684
881	01/23/2018	715027 Consumables		594889
881	01/23/2018	715027 Mechanic entered - Body Other noisy from o/s/f modesty panel	fixed for panelok.	594684
881	01/23/2018	715027 EDGE STEP EDGE YELLOW 43mm		594684
881	01/23/2018	715027 Mechanic entered - Body Other rear door strip rubber u/s.	fitted new rubber stripok.	594684
881	01/23/2018	715027 Mechanic entered - Body Other a/c filter cover loose.	fixed for coverok.	594684
881	01/19/2018	714578 Breakdown#:34390 - Ops Entered - Breakdown - Breakdown Overh	clean radiator test drive ok	594275
881	01/19/2018	714577 Mechanic entered - Engine Other	engine over heating steam clean raidiator test drive ok	594275
881	01/17/2018	714061 Mechanic entered - Engine Noisy or Rattling idle pully u/s.	r/r pullyok.	593771
881	01/17/2018	714061 SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		593771
881	01/17/2018	714061 Mechanic entered - Elec and Light Other pax bell u/s.	r/r pax bell switchok.	593771
881	01/17/2018	714061 Mechanic entered - Elec and Light Interior Lights dash switc	r/r globesok.	593771
881	01/17/2018	714061 SWITCH- STOP-YELLOW		593771
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004	CARRY OUT B SERVICE AS PER CHECK LIST done.	593771
881	01/17/2018	714004 FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		593771
881	01/17/2018	714004 O-RING LARGE SPINNER FILTER SCANIA (1769799)		593771
881	01/17/2018	714004 FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		593771
881	01/17/2018	714004 FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		593771
881	01/17/2018	714004 O-RING SPINNER FILTER SCANIA (1769798)		593771
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004 Consumables		594105
881	01/17/2018	714004	CARRY OUT A SERVICE AS PER CHECK LIST	593771
881	01/16/2018	712539 Consumables		594000
881	01/16/2018	712539 Body - drivers seat back rest adjustor u.s	seat removed from 785 fitted on to this bus and the one off this bus repaired and fitted on to 785.	593771
881	01/15/2018	712539 Direct Purchase - BODYWORK	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O211080 Receiving #:218711 Date :2018-01-17 repair drivers seat as required - back rest adjustor not working	594000
881	01/10/2018	712539 Body - drivers seat back rest adjustor u.s	O211080 - auto trimmers for repairs	592726
881	12/22/2017	709772	TRANSMISSION CHECK AS PER CHECK LIST	590431
881	12/20/2017	709225 Mechanic entered - Fluid Leaks Rear of bus n/s/r coolant le	tightend hose clamp on radiator hose . checked all ok - road tested . rechecked for leaks all ok	589984
881	12/02/2017	705584 Consumables		586992
881	12/02/2017	705584 Mechanic entered - Wheels and Tyres Worn n/s/r tires worn	removed and replaced worn tires with recaps. wheel nuts torqued to OEM spec. retorque booked	586991
881	12/02/2017	705584 TYRE 295/80R22.5 RECAP		586991
881	12/02/2017	705585 Consumables		586992
881	12/02/2017	705585 Mechanic entered - Elec and Light Interior Lights driver lig	fit globe and tested operation. all ok	586991
881	12/01/2017	705379 Consumables		586992
881	12/01/2017	705379 Elec and Light Two Way Radio - Not Transmitting	2-way reset at repeator by cim	586991
881	11/28/2017	692729 Consumables		586517
881	11/28/2017	692729 Mechanic entered - Body Other missing pax seat under cover.	resecurd	576624
881	11/25/2017	704144	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	585725
881	11/25/2017	704144	VEHICLE SAFETY INSPECTION safety completed	585725
881	11/22/2017	702611 BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)		585253
881	11/22/2017	702611 BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)		585253
881	11/18/2017	702611 Mechanic entered - Suspension Other	replace front D bushers	584526
881	11/18/2017	702610 Mechanic entered - Suspension Soft	replave rear rear ns air bag	584526
881	11/18/2017	702611 BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)		584526
881	11/18/2017	702610 AIRBAG REAR SCANIA K310		584526

881	11/18/2017	702592	Consumables			584792
881	11/18/2017	702592	Consumables			584792
881	11/18/2017	702592	Consumables			584792
881	11/18/2017	702592	Consumables			584792
881	11/18/2017	702592		CARRY OUT A SERVICE AS PER CHECK LIST a service completed		584526
881	10/30/2017	697955	Remove old poster and fit new A3 Posters and hangers	carried out campaign as required		580340
881	10/29/2017	697208	Please remove the 2 x Do Not Enter decals at the exterior	carried out campaign as required		580340
881	10/25/2017	692728	AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)			580132
881	10/25/2017	692728	AIRBAG FRONT SCANIA K230 (40Y2223)			580132
881	10/19/2017	695575	Mechanic entered - A/C Heating Not Cooling	run a/c for 1 hourcould not fault.		578727
881	10/17/2017	695145	Breakdown#:33857 - Ops Entered - Breakdown - Breakdown Road	coolant overfilled		578575
881	10/09/2017	692572		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		576624
881	10/09/2017	692572		safety inspection tension wheel nuts & road tesrok.		576624
881	10/09/2017	692728	SCANIA ALT BELT TENSIONER K1241B (40N0903)			576624
881	10/09/2017	692728	AIRBAG FRONT SCANIA K230 (40Y2223)			576624
881	10/09/2017	692728	Mechanic entered - Suspension Other leaking air from front a	r/r front air bagsok.		576624
881	10/09/2017	692728	Mechanic entered - Engine Noisy or Rattling belt tensioner u	r/r belt tensionerok.		576624
881	10/09/2017	692572	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	checked for door brakok.		576624
881	10/05/2017	691948	Mechanic entered - Elec and Light Exterior Lights O/S/FRONT	replaced globe . checked operation all ok		576357
881	10/04/2017	691413	Mechanic entered - Elec and Light Exterior Lights n/s headli	fit globe		575922
881	10/02/2017	690921	Mechanic entered - Elec and Light Indicators Not Working on	R&R globe . checked operation		574891
881	10/01/2017	689626	Remove old A3 Posters with Seniors Festival please leave	carried out campaign as required		574891
881	09/28/2017	690351	Consumables			575421
881	09/28/2017	690351	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE			575116
881	09/28/2017	690351	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	DECALS FITTED		575116
881	09/28/2017	690351	Consumables			575421
881	09/28/2017	690351	Consumables			575421
881	09/28/2017	690351	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			575116
881	09/28/2017	690351	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			575116
881	09/28/2017	690351		CARRY OUT B SERVICE AS PER CHECK LIST SERVICE COMPLETED		575116
881	09/28/2017	690351	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			575116
881	09/28/2017	690351	Consumables			575421
881	09/28/2017	690351	Consumables			575421
881	09/28/2017	690351		CARRY OUT A SERVICE AS PER CHECK LIST SERVICE COMPLETED		575116
881	09/22/2017	688299	Consumables			574627
881	09/22/2017	688299	FESTO DOOR VALVE MINI TYPE			574228
881	09/22/2017	688299	Body - front passenger door not working	replaced secondary passenger door reg adjusted pressure . checked operation of passneger doors all ok		574228
881	09/16/2017	687163	Vandalism Vandalism/ Graffiti Interior	carried out interior painting as required		573593
881	09/07/2017	685191	Consumables			572093
881	09/07/2017	685191	Elec and Light indicators are not working at the front	R&R globe . checked operation all ok		571723
881	09/01/2017	683867	Consumables			570870
881	09/01/2017	683867	Mechanic entered - Body Rear_Door Operation Faulty rear doo	secured passenger door handle . checked all ok		563030
881	08/31/2017	675276	Ops Entered - Fault - A/C Heating Not Heating - Route: -	solenoid nw		563030
881	08/29/2017	683091	Consumables			570198
881	08/29/2017	683091	Elec and Light Exterior Lights N/S top front indicator N	replaced globe . checked operation all ok		569630
881	08/29/2017	673034	AIR CONDITIONING REPAIR	Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:O197632 Receiving #:-209010 Date :2017-09-04 carry out 12 month a/c service as required		571234
881	08/24/2017	682385	Consumables			569366
881	08/24/2017	682385	Elec and Light indicators stay on when turning left but wo	R&R indicator stalk checked operation all ok		569157
881	08/24/2017	682385	INDICATOR STALK SCANIA SERIES 4 (1402448)			569157
881	08/22/2017	681620	Consumables			569157
881	08/22/2017	681620	Elec and Light Interior Lights drivers light N/W.	replaced globe . checked operation all ok		568046
881	08/21/2017	675276	SG447190-1130 AIR COMPRESSOR	Creditor #:-VB-DEN010 DENSO AUTOMOTIVE SYSTEMS P/O #:O200704 Receiving #:-208132 Date :2017-08-24		569157
881	08/18/2017	680273	Consumables			568514
881	08/18/2017	680273	INDICATOR STALK SCANIA SERIES 4 (1402448)			568046
881	08/18/2017	680273	SWITCH INDICATOR SCANIA (L94UAB) (40V4703)			568046
881	08/18/2017	680273	INVERTER 24 Volt 36 Watt MAN			568046
881	08/18/2017	680273	INVERTER 24V 15-36W (KIRG)			568046
881	08/15/2017	680229		Assisting		567450
881	08/15/2017	680229		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		567450
881	08/15/2017	680229		VEHICLE SAFETY INSPECTION safety inspection tension wheel nuts & road testok.		567450
881	08/15/2017	680108	Consumables			567844
881	08/15/2017	680273	Mechanic entered - Elec and Light Interior Lights rear saloo	fixed wiringok.		567450
881	08/15/2017	680273	Mechanic entered - Elec and Light Interior Lights drivers li	r/r globeok.		567450
881	08/15/2017	680273	Mechanic entered - Elec and Light Other indicator stalk u/s	removed old stalk and fit new. checked operation. all ok		567450
881	08/15/2017	680273	SWITCH INDICATOR SCANIA (L94UAB) (40V4703)			567450
881	08/15/2017	680108	Elec and Light offside headlight out	fitted a globe		567450
881	08/15/2017	680273	Consumables			567844
881	08/15/2017	680273	Mechanic entered - Body Other missing safety triangle.	r/r new safety triangleok.		567450
881	08/15/2017	680273	TRIANGLE SAFETY DOUBLE SIDED 3 BOX			567450
881	08/14/2017	679953	Please remove old posters and fit new one along with hangers	campaign has been done		567450
881	07/29/2017	676913	Consumables			565021
881	07/29/2017	676913	Consumables			565021
881	07/29/2017	676913	Consumables			565021
881	07/29/2017	676913		CARRY OUT A SERVICE AS PER CHECK LIST completed A service as per checklist. wheels torqued to OEM spec. road and brake tested all ok		564763
881	07/20/2017	675276	Drv entered - A/C Heating Not Heating	checked and found no pwr to the ac controller.		563030
881	07/11/2017	673034	Mechanic entered - A/C Heating Not Cooling	O197632 - carried out by cold drive - O197632		561563
881	07/11/2017	673034		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O197632 - cold drive		561563
881	07/04/2017	671272	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	carried out campaign by paul bell		560054
881	07/01/2017	671232	Consumables			560495
881	07/01/2017	671232	Drv entered - Elec and Light Interior Lights	fixed loose contact and tested operation of light. all ok		560054
881	06/30/2017	671169		TRANSMISSION CHECK AS PER CHECK LIST		560054
881	06/22/2017	669128	Consumables			558983
881	06/22/2017	669128	LAMP FLUORESCENT TUBE 18W			558455
881	06/22/2017	669128	Mechanic entered - Elec and Light Interior Lights rear salo	R&R globe checked operation of light all ok		558455
881	06/21/2017	668836	Consumables			558758
881	06/21/2017	668836	Remove old Green 2016/17 registration Label and/ or Blue EF	Complete		558455
881	06/20/2017	668286		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS DONE TENSION WHEEL NUTS		558455
881	06/20/2017	668286		VEHICLE SAFETY INSPECTION DONE ROAD/BRAKE TEST OK		558455
881	06/04/2017	664370	Consumables			555607
881	06/04/2017	664370	Fit A3 Poster/Hangers	carried out campaign as required		554736
881	06/02/2017	665238	Mechanic entered - A/C Heating Other a/c compressor bush u/s	replaced worn a/c bush. checked operation. all ok		554736
881	06/02/2017	665238	Mount A/C Large			554736
881	06/02/2017	665410	Mechanic entered - Engine Other air comperssor to the air dr	maked air comperssor hose oring.		554736

881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238		CARRY OUT C SERVICE AS PER CHECK LIST		554736
881	06/02/2017	665238	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			554736
881	06/02/2017	665238	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF2506			554736
881	06/02/2017	665238	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618-0_153468			554736
881	06/02/2017	665238	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			554736
881	06/02/2017	665238	FILTER FUEL FILTER SCANIA SR4 (H17WK04)			554736
881	06/02/2017	665238	FILTER FUEL FILTER SCANIA SR4 (1393640)			554736
881	06/02/2017	665238	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			554736
881	06/02/2017	665238	FILTER HYDRAULIC COOLING FAN SCANIA SR3 (E90HD149)			554736
881	06/02/2017	665238	FILTER AIR DRYER SCANIA SR4 (1393551) (49G8709HALDEX)			554736
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238		CARRY OUT B SERVICE AS PER CHECK LIST		554736
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238	Consumables			555568
881	06/02/2017	665238		CARRY OUT A SERVICE AS PER CHECK LIST		554736
881	05/31/2017	664725	Mechanic entered - Elec and Light Interior Lights front insi	FIT NEW FLURO .		554736
881	05/31/2017	664725	LAMP FLUORESCENT TUBE 18W			554736
881	05/31/2017	664725	Consumables			555411
881	05/30/2017	662538	Drv entered - Elec and Light Interior Lights	no faults found(slack adjusters done on wo662548) 20/05/2017		554736
881	05/30/2017	662538	Consumables			555206
881	05/26/2017	663585	Mechanic entered - Elec and Light Interior Lights step light	check operation step lightscould not fault.		554016
881	05/26/2017	663585	Consumables			554640
881	05/22/2017	662589	Mechanic entered - Elec and Light Exterior Lights N/S HEADLI	REFIT WIRING PLUG TO GLOBE.		553036
881	05/22/2017	662589	Consumables			553551
881	05/20/2017	662538	Mechanic entered - Elec and Light Other dash R.P.M light not	replaced dash R.P.M light globe ok		553036
881	05/20/2017	662538	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe ok		553036
881	05/20/2017	662548	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s	replaced o/s/r brake slack adjust kits x2		553036
881	05/20/2017	662538	Mechanic entered - Brakes Other o/s/r brake slack adjust u/s			553036
881	05/20/2017	662548	KIT REPAIR KIT SLACK ADJUSTER (1350817)			553036
881	05/20/2017	662538	KIT REPAIR KIT SLACK ADJUSTER (1350817)			553036
881	05/20/2017	662538	KIT REPAIR KIT SLACK ADJUSTER (1350817)			553036
881	05/20/2017	662505		CARRY OUT B SERVICE AS PER CHECK LIST		553036
881	05/20/2017	662505	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			553036
881	05/20/2017	662505	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			553036
881	05/20/2017	662505	FILTER FUEL FILTER SCANIA SR4 (H17WK04)			553036
881	05/20/2017	662505	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			553036
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505		CARRY OUT A SERVICE AS PER CHECK LIST		553036
881	05/20/2017	662505		CARRY OUT A SERVICE AS PER CHECK LIST		553036
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505	Consumables			553241
881	05/20/2017	662505	Consumables			553241
881	05/16/2017	661734	Consumables			552493
881	05/16/2017	661734	Campaign 14/16 Destination signs Setting and loadig Files.	COMPLETE		552329
881	05/04/2017	657740	Consumables			550595
881	05/04/2017	657740	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-SMC001 SMC PNEUMATICS (AUST) PTY LTD P/O #:O192364 Receiving #:199789 Date :2017-05-05 supply parts for door repairs as required		550595
881	04/28/2017	658372	Consumables			549393
881	04/28/2017	658372	Mechanic entered - Elec and Light Next Stop Button stays on	tracerepair wiring at n/spast rear door.		549370
881	04/28/2017	657740	Body Rear_Door Operation FaultyWHEN CLOSED IT OPENS ITSE	air pressure too high as main door reg missingorder and fit new reg check operation ok.		549370
881	04/24/2017	657740	Body Rear_Door Operation FaultyWHEN CLOSED IT OPENS ITSE	suspect electric system.smc supplied parts PO#: O192364		548929
881	04/15/2017	656413		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done		547574
881	04/15/2017	656413		VEHICLE SAFETY INSPECTION done wheel nut tension road/brake test ok external step lights not working changed both globes ok reverse buzzer not working r/r reverse buzzer		547574
881	04/15/2017	656413	GLOBE 24V SW BAYONET (17181)			547574
881	04/15/2017	656413	REVERSE ALARM 12-24v 72608			547574
881	04/10/2017	655644	Wheels and Tyres - carry out o/s/r retorque as required	carried out retorque as required		546985
881	04/08/2017	655376	VALVE EXTENSION-130mm Metal type			546507
881	04/08/2017	655376	TYRE 295/80R22.5 RECAP			546507
881	04/08/2017	655376	Mechanic entered - Wheels and Tyres Worn o/s/r tires worn	replaced worn tires. torqued wheel nuts to OEM spec. retorque booked. all ok		546507
881	04/07/2017	655216	Engine - leaking coolant	R&R o/s trans cooler hose		546507
881	04/07/2017	655216	HOSE (49N-001)			546507
881	04/05/2017	654775	Air System Air_Leak Doors loadad air noise as front door			546507
881	04/05/2017	654775	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-FES010 FESTO PTY LTD P/O #:O191020 Receiving #:197768 Date :2017-04-05 purchase door parts as required from festo		546507
881	04/01/2017	654209	Drv entered - Suspension Kneeel/ Raise	double entry; disregard		545896
881	04/01/2017	654209	Mechanic entered - Suspension Kneeel/ Raise kneel raise butt	road tested after replacing 4-way valve; suspension ok		545896
881	04/01/2017	654206	VALVE FOUR WAY SCANIA			545896
881	04/01/2017	654206	Mechanic entered - Air System Other four way valve u/s	replaced four way valve ok		545896
881	03/20/2017	651785	LABEL HEADLIGHTS 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL DURESS BUTTON 8x25mm RED/BLACK			543621
881	03/20/2017	651785	SWF SWITCH LABEL MASTER WHITE ON YELLOW 14x14mm			543621
881	03/20/2017	651785	LABEL PARK BRAKE 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL HAZARDS 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL DEMIST 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL STEP LIGHT 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL SALOON LIGHT 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL LOWER/RAISE 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL HIGH IDLE 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	LABEL KNEEL 8x25mm WHITE/BLACK			543621
881	03/20/2017	651785	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	carried out campaign as required		543621
881	03/18/2017	650678	BUSH TORQUE ROD BUSH SCANIA/MERCEDES (1517403) (2520801)			543621
881	03/18/2017	650678	Mechanic entered - Suspension Other o/s/f torgue rod bushing	replaced o/s/f torque rod bushing ok		543621
881	03/18/2017	651601	PAX BELL NW (BY GEOFF)	no faults found		543621
881	03/18/2017	650678	Mechanic entered - Brakes Other front bvoth brake slack adju	replaced o/s/f brake slack adjust ok		543621
881	03/17/2017	650678	BALANCE	Creditor #:VB-TYR002 TYRES4U P/O #:O189720 Receiving #:196361 Date :2017-03-20		543825
881	03/17/2017	650696	BUSH SWAY BAR			543621
881	03/17/2017	651440	FT LEVELLING CONTROL VALVE			543621

881	03/17/2017	651440	SOLENOID VALVE FRONT			543621
881	03/17/2017	651440	SOLENOID VALVE FRONT			543621
881	03/17/2017	651440	Air System - front suspension wont adjust and is collapsing	traced and found front leveling valve block u/s . R&R valve. road tested all ok		543621
881	03/16/2017	651168	GLOBE 24V 21W SINGLE CONTACT (HLR2421)			543621
881	03/16/2017	651168	INDICATOR SIDE INDICATOR R/H			543621
881	03/16/2017	651168	Elec and Light - n/s/f indicator not working	replaced light assembly . and globe . checked operation of light all ok		543621
881	03/15/2017	650942	Wheels and Tyres - carry out front retorque as required	carried out front retorque as required		542859
881	03/15/2017	650696	1435944 BUSH TORQUE ROD	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O189458 Receiving #:196087 Date :2017-03-15		543408
881	03/15/2017	650696	1789567 O/S/F SLACK ADJUSTER	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O189431 Receiving #:196058 Date :2017-03-15		543408
881	03/14/2017	650678	TYRE 295/80R22.5 NEW			542859
881	03/14/2017	650678	Mechanic entered - Wheels and Tyres Other front both tyres u	replaced front both tyres ok		542859
881	03/14/2017	650696	Suspension - front upper torque rod bushes u/s x 2	ordered		542859
881	03/14/2017	650696	Brakes front slack adjustors u.s	ordered		542859
881	03/14/2017	650678	Mechanic entered - Brakes Other front bvoth brake slack adju	replaced n/s/f brake slack adjust		542859
881	03/14/2017	650678	SLACK ADJUSTER FRONT NEAR SIDE			542859
881	03/14/2017	650628	Consumables			543416
881	03/14/2017	650628	Consumables			543416
881	03/14/2017	650628	Consumables			543416
881	03/14/2017	650628	Consumables			543416
881	03/14/2017	650628	Consumables			543416
881	03/06/2017	649188	DIRECT PURCHASE - BUS INSPECTI	CARRY OUT A SERVICE AS PER CHECK LIST		542859
881	03/04/2017	649188		Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O188896 Receiving #:195725 Date :2017-03-09		542859
881	03/04/2017	649188		ANNUAL SAFETY INSPECTION SERIAL # 098708		541994
881	03/04/2017	649188		PRE ANNUAL SAFETY INSPECTION CHECK- checked the bus and entered defects in TIMS		541994
881	03/04/2017	649179	GLOBE 24V 100/90W HALOGEN			541994
881	03/04/2017	649179	Mechanic entered - Elec and Light Exterior Lights o/s head I	removed old globe and fit new. tested operation all ok		541994
881	03/01/2017	610361	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O174953A Receiving #:195728 Date :2017-03-09		542859
881	02/25/2017	644104	DRIVER'S SIDE SUNBLIND US	resecured drivers sun blind checked operation all ok		540396
881	02/24/2017	647123	Please remove any old poster and fit either Good News for T	Campaign completed.		540396
881	02/23/2017	647203	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	Campaign complete.		540396
881	02/22/2017	646758	Consumables			540622
881	02/22/2017	646758	GLOBE DASH			540396
881	02/22/2017	646758	Warning Lights no hazards or indicator lights working on th	replaced globe . checked operation of light all working ok		540396
881	02/20/2017	644104	R16DB008 DRIVER SUN BLIND	Creditor #:VB-CUS001 CUSTOM CARE P/O #:O187896 Receiving #:194985 Date :2017-03-01		541603
881	02/13/2017	644104	DRIVERS SIDE SUNBLIND	Creditor #:VB-NOR001 NORTHCOAST BUS & COACH PTY LTD P/O #:O187321 Receiving #:193900 Date :2017-02-15 1300 X 500MM		539272
881	02/10/2017	643972		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		538140
881	02/10/2017	643972		VEHICLE SAFETY INSPECTION		538140
881	02/10/2017	644104	DRIVER'S SIDE SUNBLIND US	ORDERED SUNBLIND		538140
881	02/10/2017	643972		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list		538140
881	02/09/2017	643687	Consumables			538571
881	02/09/2017	643687	GLOBE 24V 21W FESTOON [BOX 10]			538140
881	02/09/2017	643687	Mechanic entered - Elec and Light Indicators Not Working o/s	fit globe.		538140
881	02/06/2017	642800	Body - driver door rubber stopper hitting drivers knee	resecured drivers rubber door stopper		537028
881	02/01/2017	639477	Consumables			536801
881	02/01/2017	639477	Consumables			536801
881	02/01/2017	639477	Consumables			536801
881	02/01/2017	639477	FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)			536537
881	02/01/2017	639477	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			536537
881	01/27/2017	580717	DIAPHRAGM TYPE 24 DEEP DISH BRAKE BOOSTER			535222
881	01/19/2017	639744	Wheels and Tyres - carry out retorque on o/s/r as required	carried out retorque as required		533714
881	01/18/2017	639612	Mechanic entered - Suspension Other front s way bar d rubber	r/r d rubbersok.		533714
881	01/18/2017	639612	Consumables			534451
881	01/18/2017	639612	Mechanic entered - Body Other n/s/f side mirror u/s.	r/r mirrorok.		533714
881	01/18/2017	639612	BUSH SWAY BAR FRONT SCANIA SR4 & K230 (40Y3408) (1919010)			533714
881	01/18/2017	639612	MIRROR L/H 440mm LONG SPLIT BM04			533714
881	01/18/2017	639612	TYRE 295/80R22.5 RECAP			533714
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			533714
881	01/18/2017	639477	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			533714
881	01/18/2017	639477	FILTER FUEL FILTER SCANIA SR4 (H17WK04)			533714
881	01/18/2017	639477	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			533714
881	01/18/2017	639477		a b tension wheel nuts & road testok.		533714
881	01/18/2017	639477		CARRY OUT B SERVICE AS PER CHECK LIST		533714
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477	Consumables			534451
881	01/18/2017	639477		CARRY OUT A SERVICE AS PER CHECK LIST		533714
881	01/16/2017	613993	Consumables			533902
881	01/16/2017	613993	Consumables			533902
881	01/16/2017	613993	Consumables			533902
881	01/16/2017	613993	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			533714
881	01/16/2017	613993	FILTER ZF ECOMAT TRANS (E39HD119) (1193281-1)			533714
881	01/16/2017	613993	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			533714
881	01/09/2017	637595		TRANSMISSION CHECK AS PER CHECK LIST		529642
881	01/09/2017	637576	Vandalism/ Graffiti Interior	carried out interior vandelisem painting as required		529642
881	01/08/2017	636780	Fit New 2107 Large and Small Fares Small Concessionand AO	Campaign complete.		529642
881	01/06/2017	637405	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		532543
881	01/05/2017	636780	DECAL AUTHORISED OFFICER			529642
881	01/05/2017	636780	DECAL 2017 PTV METRO MYKI DECAL SMALL 300x150mm			529642
881	01/05/2017	636780	DECAL 2017 PTV DECAL CONCESSION CARD TYPE 300x150mm			529642
881	12/29/2016	635876	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned		529642
881	12/29/2016	635601	Consumables			531321
881	12/29/2016	635601	INDICATOR SIDE INDICATOR R/H			529642
881	12/29/2016	635601	OS side indicator lence broken	replaced light assembly . checked operation ok		529642
881	12/20/2016	633467	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O183671 Receiving #:191257 Date :2017-01-10 carry out interior vandelisem painting as required		532730
881	12/20/2016	631708	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O183670 Receiving #:191259 Date :2017-01-10 knox bodyshop to repair unreported accident damage for unreported number - 44587		532730
881	12/15/2016	633622		SERVICE MOISTURE EJECTOR done		528811
881	12/15/2016	633622		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST done		528811
881	12/15/2016	633622		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done		528811
881	12/15/2016	633622		VEHICLE SAFETY INSPECTION safety inspection tension wheel nuts & road testok.		528811
881	12/14/2016	633467	Vandalism/ Graffiti Interior	interior vandelisem painting carried out by eastcoast bodyshop knox on order - O183671		528811
881	12/14/2016	633368	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O183623 Receiving #:190007 Date :2016-12-19 replace vandalised glass as required		529642

881	12/14/2016	633368	alpha glass to replace u/s vandalised glass required	O183623 - alpha glass replaced vandalised glass and film as required	528811
881	12/14/2016	631708	Accident - sent to knox bodyshop for unreported accident d	unreported accident damage repaired at knox on order - O183670	528811
881	12/05/2016	611145	PULLEY IDLER SCANIA		528811
881	12/05/2016	611145	SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		528811
881	12/05/2016	631497	GLOBE 24V 21W SINGLE CONTACT (HLR2421)		528811
881	12/05/2016	631497	Mechanic entered - Elec and Light Indicators Not Working O/S	FIT GLOBE.	528811
881	12/03/2016	611145	Consumables		529326
881	12/03/2016	611145	Consumables		529326
881	12/03/2016	611145	Consumables		529326
881	12/03/2016	611145	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF2506		528811
881	12/03/2016	611145	FILTER AIR FILTER OUTER SCANIA SR3 SR4 (395773) (0395773)		528811
881	12/01/2016	631115	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	528586
881	11/29/2016	630491	CAMERA INTERNAL 2.1mm LENS		528192
881	11/29/2016	630491	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a b	replaced driver's door camera with f2.1 and modified the wiring. repaired fwd facing camera wiring and adjusted time. checked recording all good	528192
881	11/28/2016	630212	clean/remove graffiti as required	removed cleaned and painted over graffiti as required on 26/11/2016	527904
881	11/26/2016	630064	INDICATOR SIDE INDICATOR R/H		527904
881	11/26/2016	630064	Mechanic entered - Elec and Light Exterior Lights o/s front	replaced osf side indicator light assy	527904
881	11/25/2016	629428	TYRE RECAP 295/80R22.5	Creditor #:VB-TYR002 TYRES4U P/O #:O182110 Receiving #:188483 Date :2016-11-25	527904
881	11/25/2016	629865	WIPER REFILL 1mt MULTI FIT		526594
881	11/25/2016	629865	Mechanic entered - Elec and Light Exterior Lights o/s and n	secured o/s/f blinker assembly replaced wiper refill	526594
881	11/25/2016	629865	Mechanic entered - Elec and Light Exterior Lights o/s front	repositioned globes in holders . checked operation ok	526594
881	11/24/2016	629617	Wheels and Tyres - carry out n/s/f retorque as required	carried out retorque as required	526594
881	11/24/2016	629615	Mechanic entered - Elec and Light Exterior Lights 881 n/s f	secured blinker assembly	526594
881	11/23/2016	629428	TYRE 295/80R22.5 RECAP		526594
881	11/23/2016	629428	Mechanic entered - Wheels and Tyres Worn n/s/r tires worn	removed worn tires and fit new recaps. wheel nuts torqued to spec.	526594
881	11/23/2016	629428	TYRE 295/80R22.5 RECAP		526594
881	11/22/2016	629150	Direct Purchase - MECHANICAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O181978 Receiving #:189014 Date :2016-12-02 L84868 FUEL TANK BRACKETS	528811
881	11/22/2016	629150	Engine belt missing	could not fault engine or a/c belts checked condition all ok	526594
881	11/22/2016	629150	Mechanic entered - Engine Other FUEL TANK BENT DOWN ON ANGL	R&R fuel tank brackets	526594
881	11/18/2016	628755	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	526594
881	10/29/2016	624850	Consumables		523298
881	10/29/2016	624850	Body -front door doesnt open or close when the bus is on a	frt door rear leaf bottom edge hitting the peeled off yellow strip. resecured the strip channel and glued the strip	522861
881	10/28/2016	624626	Mechanic entered - Air System Air_Leak Rear	replaced faulty diagnostic port ;)	522861
881	10/28/2016	624573	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced	522861
881	10/28/2016	624626	Consumables		523298
881	10/28/2016	624626	Consumables		523298
881	10/28/2016	624626	Consumables		523298
881	10/28/2016	624626		CARRY OUT A SERVICE AS PER CHECK LIST a service completed	522861
881	10/28/2016	624626		CARRY OUT A SERVICE AS PER CHECK LIST a service completed	522861
881	10/22/2016	623274		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheels tenstioned	521974
881	10/22/2016	623274		VEHICLE SAFETY INSPECTION safety completed	521974
881	10/10/2016	620286	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O178725 Receiving #:185499 Date :2016-10-14 carry out roll away campain as required - marioano	520212
881	10/06/2016	620286	DIRECT PURCHASE - BRAKES	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O178653 Receiving #:184873 Date :2016-10-06 40G2702WABCO Hand break Valve	519031
881	10/06/2016	620286	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	campaign carried out by marioanao on order - O178725	519031
881	10/06/2016	620245	Brakes- BRAKE LIGHT KEEPS COMING UP ON THE DASH	traced and found hand brake valve u/s . R&R hand brake valve . checked operation ok	519031
881	09/22/2016	617392	Consumables		517156
881	09/22/2016	617392	GLOBE 24V 75/70W H4		516609
881	09/22/2016	617392	Elec and Light Exterior Lights O/S headlight N/W.	replaced globe	516609
881	09/17/2016	614074	Suspension - rear shock absorber u/s	replaced n/s/r/r shock absorber ok	515875
881	09/17/2016	616492	Mechanic entered - Gearbox Driveline Other diff seal u/s	replaced diff seal ok road tested okcheck diff oil okno leake diff oil ok	515875
881	09/17/2016	614074	Consumables		516157
881	09/17/2016	614074	Body - passenger stop switch	replaced passenger stop switch ok	515875
881	09/15/2016	614074	Direct Purchase - MECHANICAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O176882 Receiving #:183328 Date :2016-09-15 1525988 DIFF PINION NUT	515609
881	09/12/2016	614074	SWITCH- STOP-YELLOW		514767
881	09/07/2016	614248	NR TYRE DISPOSAL	Creditor #:VB-TYR002 TYRES4U P/O #:O176398 Receiving #:182723 Date :2016-09-08	514502
881	09/07/2016	614248	295/80R22.5 BANDAG BITUMEN RET	Creditor #:VB-TYR002 TYRES4U P/O #:O176398 Receiving #:182723 Date :2016-09-08	514502
881	09/07/2016	614488	Mechanic entered - Wheels and Tyres Wheel Nut Retension ret	double entry entered in by kapilla - retorque has been done 1 day prior	513288
881	09/06/2016	614248	Wheels and Tyres - carry out n/s/r retorque as required	carried out retorque as required on n/s/r	513288
881	09/05/2016	614074	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-WHI002 WHITES DIESELS AUSTRALIA P/O #:O176349 Receiving #:183077 Date :2016-09-13 2Y3004 REAR SHOCK ABSORBER	514767
881	09/05/2016	614074	VALVE EXTENSION-130mm Metal type		513288
881	09/05/2016	614074	Mechanic entered - Wheels and Tyres Worn NSR outer tyre worn	fitted a used tyre from tyre room to match to the inner tyre wear and tread pattern and tensioned the wheel nuts.	513288
881	09/05/2016	614074	Suspension - rear shock absorber u/s		513288
881	09/05/2016	614074	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-WHI002 WHITES DIESELS AUSTRALIA P/O #:O176349 Receiving #:183077 Date :2016-09-13 2F2105 DIFF PINION SEAL	514767
881	09/05/2016	614073	Gearbox Driveline - diff pinion seal leaking	double entry entered into tims	513288
881	09/05/2016	614070	Mechanic entered - Gearbox Driveline Other rear transmission	replaced REAR TRANSMISSION COVER ORING OK	513288
881	09/05/2016	614074	transmission real main seal leaking	replaced seal on back of transmission . was not rear main but under plate on transmission	513288
881	09/05/2016	614055	Mechanic entered - Engine Other IDLER BEARING PLAY	replaced engine idler(W/O groove)	513288
881	09/05/2016	614055	ROLLER		513288
881	09/05/2016	614074	Body - passenger stop switch		513288
881	09/05/2016	614055	Slack Adjuster Auto		513288
881	09/05/2016	614055	Mechanic entered - Brakes Other n/s/r brake slack adjust u/s	replaced n/s/r brake slack adjuster	513288
881	09/05/2016	614074	Air System - air valve leaking	checked by LDM - air leak is ok repaired . auxiliary port . ok	513288
881	09/05/2016	613993	Consumables		514088
881	09/05/2016	613993	Consumables		514088
881	09/05/2016	613993	DECAL NO SMOKING GOVERNMENT REGULATIONS		513288
881	09/05/2016	613993	DECAL NO SMOKING		513288
881	09/05/2016	613993	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		513288
881	09/05/2016	613993	FILTER FUEL SCANIA SR4(H17WK04)		513288
881	09/05/2016	613993	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		513288
881	09/05/2016	613993	O-RING LARGE SPINNER FILTER SCANIA (1769799)		513288
881	09/05/2016	613993	O-RING SPINNER FILTER SCANIA (1769798)		513288
881	09/05/2016	613993		CARRY OUT B SERVICE AS PER CHECK LIST	513288
881	09/05/2016	613993	Consumables		514088
881	09/05/2016	613993	Consumables		514088
881	09/05/2016	613993		CARRY OUT A SERVICE AS PER CHECK LIST	513288
881	08/26/2016	612417	NS CNR of front bumper damaged(reported by refuellers)	entered into accidents coloum	512212
881	08/26/2016	612417	Consumables		512476
881	08/22/2016	611145		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	511509
881	08/22/2016	611145		VEHICLE SAFETY INSPECTION done	511509
881	08/22/2016	611145	SCANIA ARTIC ALT PULLEY GROVED PLASTIC 40N0904		511509
881	08/22/2016	611145	Mechanic entered - Engine Other belt idle pully u/s	r/r idle pullyok.	511509
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	Mechanic entered - Body Other pax pole braket bolt missing	fixed pax poleok.	511509

881	08/22/2016	611145	Mechanic entered - Body Other loose rear mud flap	fixed rear mud flapok.	511509
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	Consumables		511589
881	08/22/2016	611145	FILTER AIR OUTER SCANIA SR3 SR4 395773 0395773 E218L		511509
881	08/22/2016	611145		CARRY OUT A SERVICE AS PER CHECK LIST done	511509
881	08/18/2016	610565	Consumables		511230
881	08/18/2016	610565	GLOBE 24V 21W FESTOON [BOX 10]		511230
881	08/18/2016	610565	o/s/f/b indicator not working	replaced globe . checked operation of light . working ok	511230
881	08/17/2016	610361	Accident#:43767 - Ops Entered - Accident - Bus Hits Pedestr	PEEP GLASS REPLACED BY ALPHA GLASS ON 17/08/2016 PO O174953	511230
881	08/11/2016	609343	Consumables		510569
881	08/11/2016	609343	GLOBE 24V 21W FESTOON [BOX 10]		510206
881	08/11/2016	609343	Drv entered - Elec and Light Indicators Not Working	replaced globe	510206
881	08/09/2016	609121	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	509490
881	08/09/2016	608893	Consumables		510206
881	08/09/2016	608893	GLOBE 24V 21W SINGLE CONTACT [HLR2421]		509490
881	08/09/2016	608893	OS Front indictors n/w	replaced globe	509490
881	08/06/2016	608572	BOOSTER		509490
881	08/06/2016	608572	Air System -constantly loosing air	Checked for leaks. could not fault. regulator blowing off just above 6bar. adjusted reg. found a noise from nsf booster. replaced booster; road/brake tested ok	509490
881	08/01/2016	607448	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	new graffiti cleaned	508222
881	08/01/2016	606874	Consumables		508903
881	08/01/2016	606874	GLOBE 24V 75/70W H4		508222
881	08/01/2016	606874	OS Head Light n/w		508222
881	08/01/2016	605230	INVOICE RECEIVED TWICE IN ERRO	replaced globe	508222
881	08/01/2016	605230	DIRECT PURCHASE GLASS	Creditor #:#VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:#O172987REV Receiving #:#181383 Date :2016-08-23	511589
881	08/01/2016	603344	AIR CONDITIONING REPAIR	Creditor #:#VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:#O172987A Receiving #:#180541 Date :2016-08-10 SUPPLY AND INSTALL OFFSIDE WINDOW #7 ALONG WITH ANIT-GRAFFITI FILM	510206
881	07/27/2016	606251	Consumables	Creditor #:#VB-COL004 COLD DRIVE PTY LTD P/O #:#O172309 Receiving #:#182085 Date :2016-09-01 carry out 24 month a/c service as required	512821
881	07/27/2016	606251	SEAT BELT BUCKLE TWIN WIRE GREY (Use 340446)		508222
881	07/27/2016	606251	Seat Belt does not work		506043
881	07/23/2016	605632	CCTV is not working (The reader could be fauly)	replaced drivers seat belt anchor	506043
881	07/22/2016	605588	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	NESS EDR410 System unit is working. corrected the time and checked checked previous files. it's recording.	506043
881	07/22/2016	605230	DIRECT PURCHASE - VANDALISM	NEW GRAFFITI CLEANED	506043
881	07/22/2016	605230	Consumables	Creditor #:#VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:#O172987 Receiving #:#178968 Date :2016-07-22 replace smashed glass on n/s/r of bus as required	506043
881	07/21/2016	605230	Body -offside rear glass has a large crack through it		507487
881	07/17/2016	603147	Consumables	o/s/r glass replaced by alpha on order - O172987	505306
881	07/17/2016	603147	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER		506043
881	07/16/2016	603825	Consumables	carried out campaign as required	505306
881	07/16/2016	603825	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	carried out campaign as required	506043
881	07/12/2016	603312	Replace customer enquiry decal.	carried out campaign as required	505570
881	07/12/2016	603312	DECAL CUSTOMER ENQUIRY		505570
881	07/12/2016	603344		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O172309	505570
881	07/12/2016	603344		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O172309	505570
881	06/25/2016	600147	Mechanic entered - Vandalism Vandalism/ Graffiti Interior L	removed grafetit from inside bus	502754
881	06/24/2016	599932		TRANSMISSION CHECK AS PER CHECK LIST TRANS CHECK COMPLETED	502754
881	06/24/2016	599932		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS WHEELS TENSTIONED ALL	502754
881	06/24/2016	599932		VEHICLE SAFETY INSPECTION SAFETY INSPECTION COMPLETED	502754
881	06/24/2016	599932	Mechanic entered - Fluid Leaks Rear of bus	COOLANT LEAKING FROM TRANS COOLER NS HOSE CLAMP TIGHTEND CHECKED OK	502754
881	06/24/2016	599932	Consumables		502980
881	06/24/2016	599932	Consumables		502980
881	06/24/2016	599932	Consumables		502980
881	06/24/2016	599932		CARRY OUT A SERVICE AS PER CHECK LIST A SERVICE COMPLETED	502754
881	06/22/2016	599392	Power steering fluid low	topped up power steering oil	501975
881	06/21/2016	599202	Mechanic entered - Steering Other power steering oil leaks	check power steering oil leaksfound power steering oil pipe removed power steering pipe replaced power steering oil pipeput in oilroad tested ok	501975
881	06/21/2016	599206	Mechanic entered - Elec and Light Other o/s indicator not wo	fixed o/s/f indicator wires ok	501975
881	06/19/2016	598193	Please remove any old poster and fit new A3 poster and add	fleet support carried out campaign as required	501975
881	06/18/2016	598655	Dash - drivers radio is not working when calling the depot	checked operation of 2 - way radio . working ok	502238
881	06/18/2016	598655	Body Front_Door Operation FaultyOn opening the front do	checked operation of all passenger doors and operation . checked for high pitch noises . could not fault	502238
881	06/12/2016	597204	Mechanic entered - Body Rear_Door Operation Faulty bus wont	openclse rear doorbus nowmoves.	500837
881	05/30/2016	594492	Elec and Light back indicators not working	traced and repaired wiring at plug for indicator stalk. checked operation of indicators . working ok	478185
881	05/26/2016	554873	INDICATOR STALK SCANIA SERIES 4 1402448		467503
881	05/26/2016	554873	SWITCH INDICATOR SCANIA (L94UAB) (40V4703)		467503
881	05/26/2016	566952	CLEAR FRONT INDICATOR WRAP-AROUND		478185
881	05/26/2016	566952	SIDE INDICATOR R/H		478185
881	05/24/2016	593368	No indicators and no high beam	reconnect to loom for indicators stalk checked operation ok	497557
881	05/13/2016	591489	GLOBE 24V 21W SINGLE CONTACT HLR2421		495695
881	05/13/2016	591489	Dash 2/3RDS OF THE DASH LIGHTS ARE NOT WORKING	replaced globes	495695
881	05/13/2016	591489	Elec and Light - SIDE FRONT OFFSIDE INDICATOR NOT WORKING	fit globe	495695
881	05/13/2016	591489	Dash - LEFT HAND INDICATOR DOES NOT CANCEL OUT	make and fit new striker plate . checked operation of indicators working	495695
881	05/13/2016	591540	GLOBE 24V 2W 2663		495695
881	05/13/2016	591540	Mechanic entered - Elec and Light Exterior Lights osf bottom	replaced globe	495695
881	05/13/2016	591489	GLOBE DASH		495695
881	05/07/2016	590404	carry out front retorque as required	carried out retorque as required	494785
881	05/07/2016	590402	Mechanic entered - Air System Air_Leak Doors air leaking fr	removed faulty reg valve at front and bypassed . checked operation of door system working ok	494785
881	05/04/2016	589232	Direct Purchase - MECHANICAL	Creditor #:#VB-TRA020 TRADE BRAKE AND CLUTCH CO. P/O #:#O167322 Receiving #:#173562 Date :2016-05-11 radius grind brakes and machine drums as required	495466
881	05/04/2016	589232	KIT SLACK ADJUSTER REPAIR 1350	Creditor #:#VB-MUL001 MULTISPARES LTD P/O #:#O167438 Receiving #:#173506 Date :2016-05-11	495238
881	05/04/2016	589232	Brakes spongy	removed 1206 n/s/f brake slack adjustput back 881 n/s/f brake slack adjust. tightened n/s/f torque hub nut 1000Nm o/s/f hub nut 1000Nm adjusted front brake ok	493486
881	05/03/2016	589232	Brakes spongy	replaced front both brake liningsbrake durmshubs bearings.	493486
881	05/03/2016	589232	Brakes spongy	trade brake and clutch radius grind and machine brakes as required on order -O167307	493486
881	05/02/2016	588151	Direct Purchase - TYRES	Creditor #:#VB-TYR002 TYRES4U P/O #:#O169076 Receiving #:#174853 Date :2016-05-27 disposal	498010
881	05/02/2016	588151	Direct Purchase - TYRES	Creditor #:#VB-TYR002 TYRES4U P/O #:#O169076 Receiving #:#174853 Date :2016-05-27 295/80r22.5	498010
881	05/02/2016	589232	BRAKE DRUM	Creditor #:#VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:#O167184 Receiving #:#174672 Date :2016-05-25	497783
881	05/02/2016	589232	WHEEL BEARING	Creditor #:#VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:#O167184 Receiving #:#174672 Date :2016-05-25	497783
881	05/02/2016	589232	SLACK ADJ. N/S/F L94	Creditor #:#VB-MUL001 MULTISPARES LTD P/O #:#O167189 Receiving #:#173108 Date :2016-05-04	494477
881	05/02/2016	589232	SLACK ADJ. N/S/F L94	Creditor #:#VB-MUL001 MULTISPARES LTD P/O #:#O167189 Receiving #:#173108 Date :2016-05-04	494477
881	05/02/2016	589232	Brakes spongy	Strip out Front brakes remove wheel bearing drum and linning ready for new parts.	493486
881	05/02/2016	589232	Brakes spongy	removed n/s/f brake niningsdurmbrake slack adjusthub bearing. and all part order.	493486
881	04/30/2016	589232	Brakes spongy	Roadtest found brakes not very effective. carried out brake adjustment and check operation. re road test brakes better but still poor efficiency. found LHF slacker u/s poss req regrind. advise wheel alignment and front wheel balance. req further work. VOR	493486
881	04/29/2016	588958	Breakdown Road Defect Unffects Service indicators not wo	reconnect indicator stalk loom checked operation of blinkers . working ok	493486
881	04/29/2016	588958	Mechanic entered - Elec and Light Exterior Lights no indica	double entry	493486
881	04/27/2016	588464	o/s/r retorque	carried out retorque as required	493486
881	04/26/2016	588151		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	493486

881	04/26/2016	588151		VEHICLE SAFETY INSPECTION		493486
881	04/26/2016	588151	EXTENSION FLEXIBLE TYRE VALVE 210mm LONG			493486
881	04/26/2016	588151	TYRE RECAP 295/80R22.5			493486
881	04/26/2016	588151	Mechanic entered - Wheels and Tyres Other O/S/R TYRES U/S	replaced O/S/R TYRES X2		493486
881	04/26/2016	588151	Mechanic entered - Elec and Light Other GEAR SELECTER 'N' BU			493486
881	04/26/2016	588151	SWITCH- STOP-YELLOW			493486
881	04/26/2016	588151	Mechanic entered - Elec and Light Other	PAX STOP SWITCH U/S replaced PAX STOP SWITCT OK		493486
881	04/26/2016	588151	Mechanic entered - Elec and Light Other FRONT MYKE NOT WORK	for opps to organise with myki to be repaired		493486
881	04/26/2016	588151	FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1			493486
881	04/26/2016	588151	O-RING SPINNER FILTER SCANIA (1769798)			493486
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST		493486
881	04/26/2016	588151				493486
881	04/26/2016	588151	FILTER FUEL SCANIA SR4(H17WK04)			493486
881	04/26/2016	588151	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778))(H200W20)			493486
881	04/26/2016	588151	O-RING LARGE SPINNER FILTER SCANIA (1769799)			493486
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables			493973
881	04/26/2016	588151	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		493973
881	04/26/2016	588151				493486
881	04/21/2016	587634	GLOBE 24V 21W SINGLE CONTACT HLR2421			492978
881	04/21/2016	587634	Mechanic entered - Elec and Light Indicators Not Working DAS	FIT GLOBE TO O/S/F SIDE BLINK.		492978
881	04/18/2016	587036	Mechanic entered - Body Other middle seat broken	fixed middle seat ok		492542
881	04/12/2016	585846	GLOBE 24V 75/70W H4 48892			490116
881	04/12/2016	585846	Elec and Light Exterior Lights disregard previous should	double entry		490116
881	04/12/2016	585846	Mechanic entered - Elec and Light Exterior Lights O/S HEADL	replaced globe		490116
881	04/10/2016	584750	Mechanic entered - Vandalism Vandalism/ Graffiti Interior L	painted interior of bus over graffiti		490116
881	04/10/2016	584749	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	painted interior of bus over graffiti		490116
881	04/10/2016	584744	Mechanic entered - Vandalism Vandalism/ Graffiti Interior I	painted interior of bus over graffiti		490116
881	04/10/2016	584622	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	removed graffiti from inside bus		490116
881	04/01/2016	580717	AIR DRYER VALVE BLOCK (BLACK){	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O164112 Receiving #:173410 Date :2016-05-09		495013
881	04/01/2016	580717	VALVE	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O164112 Receiving #:173410 Date :2016-05-09		495013
881	03/10/2016	580717	DIAPHRAGM TYPE 24 DEEP DISH BRAKE BOOSTER			486808
881	03/10/2016	580717	Air leaking reported by refuellers	removed main air regulator and shuttle valve on the side of the regulator unit . replaced main regulator . removed and replaced brake diaphragm n/s/r . road tested ok		486808
881	03/07/2016	580057	ROAD WORTHY INSPECTION	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O163800 Receiving #:169615 Date :2016-03-09		486808
881	03/07/2016	580057		ANNUAL SAFETY INSPECTION SERIAL # serial H 199931		485818
881	03/07/2016	580057		PRE ANNUAL SAFETY INSPECTION CHECK		485818
881	03/07/2016	579945	GLOBE 24V 21W SINGLE CONTACT HLR2421			485818
881	03/07/2016	579945	LED FRONT POSITION MARKER LIGHT			485818
881	03/07/2016	579945	Mechanic entered - Elec and Light Exterior Lights	replaced number plate glob and indicator		485818
881	03/04/2016	574560	OIL COL CO Scania 40G0006HALDE	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O161880 Receiving #:169303 Date :2016-03-04		485818
881	03/01/2016	574560	OIL COL CO Scania 40G0006HALDE	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O163861 Receiving #:169452 Date :2016-03-08		486533
881	03/01/2016	574560	ENTERED WITHOUT GST	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O161880REV Receiving #:169450 Date :2016-03-08		486533
881	03/01/2016	576781	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O162711 Receiving #:169351 Date :2016-03-07 CHECK AND RECTIFY FWD FACING CAMERA NW		486046
881	02/27/2016	578532	Air System Air Not Building_Up air drops when front door	checked front door is okfront door open not air leaks.ok		484905
881	02/25/2016	576781	diff drain plugs u/s	replaced diff oil drain plug and washer		484636
881	02/20/2016	576671	The Campaign requires all Bus destinations systems to be in	campaign completed		483500
881	02/18/2016	576615		VEHICLE SAFETY INSPECTION saftey completed		483500
881	02/18/2016	576615		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		483500
881	02/18/2016	576781	diff oil drain plug us			483500
881	02/18/2016	576760	Dash - 2 way radio not working	could not find a fault		483500
881	02/18/2016	576781	PLUG MAGNETIC (2165310)	Creditor #:VB-MUL001 MULTISPARES LTD P/O #:O162616 Receiving #:168572 Date :2016-02-24		484636
881	02/18/2016	576781	fwd facing camera nw	FIXED BY LONSDALE ON 19/02/2016 PO#: O162711		483500
881	02/18/2016	576615	Consumables			483500
881	02/18/2016	576615	Consumables			483794
881	02/18/2016	576615		CARRY OUT A SERVICE AS PER CHECK LIST a service completed		483500
881	02/13/2016	575841	Air System leaking from oil seperator part ordered on wo5	replaced oil seperator assy and checked. ok		482528
881	02/11/2016	574560	LAMP LED TURN			482092
881	02/11/2016	574560	Elec and Light - top rear near side hazard light is out	FIT WIRE IN NEW L.E.D BLINKER.		482092
881	02/08/2016	574560	Air System - losing air constantly. low air light came up	FOUND OIL SEPERATOR LEAKINGDISCONNECT WIRING REBOOK.		480772
881	02/06/2016	574478	TUBES FLUORESCENT 18W			480772
881	02/06/2016	574478	GLOBE 24V 21W SINGLE CONTACT HLR2421			480772
881	02/06/2016	574478	SALOON LIGHT X 2 NW	FITTED 2XFLURO		480772
881	02/06/2016	574478	DRIVER'S LIGHT NW	FITTED GLOBE		480772
881	02/06/2016	574473		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		480772
881	01/31/2016	572627	Consumables			480315
881	01/31/2016	572723	Consumables			480315
881	01/31/2016	572723	Consumables			480315
881	01/31/2016	572627	Consumables			480315
881	01/31/2016	572723	Camapign 20/15 Audit & Update of Safety Decals.Requires a	carried out campaign as required		479269
881	01/31/2016	572627	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	carried out campaign as required		479269
881	01/28/2016	572572	Brakes Foot_Brakes Noisy	road tested rear litter noisy ok		479269
881	01/19/2016	570915	Elec and Light - n/s headlight n/w	repaired wiring to headlight globe		478535
881	01/07/2016	568719	Elec and Light - indicators not working	found indicator switch unplugged reconnected plug. checked ok		477257
881	01/06/2016	568505	Elec and Light Indicators still not fixed They will not t	adjusted striker plate on steering coloum. checked operation of indicators . ok		475185
881	01/03/2016	567500	Consumables			476624
881	01/03/2016	567500	Consumables			476624
881	01/03/2016	567500	Campaign 23_15 A3 Poster Change	carried out campaign as required		475185
881	01/01/2016	564639	Direct Purchase - MECHANICAL	Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:O159799 Receiving #:166460 Date :2016-01-20 rectify desto not working as required		478988
881	01/01/2016	566952	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O160535 Receiving #:166461 Date :2016-01-20 replace n/s mid side glass as required		478988
881	12/29/2015	567236	GLOBE 24V 75/70W H4 48892			475185
881	12/29/2015	567236	Elec and Light Exterior Lights N/S Headlight N/W.	replaced globe		475185
881	12/24/2015	566952	SIDE INDICATOR R/H			475185
881	12/24/2015	566952	CLEAR LENS			475185
881	12/24/2015	566952	Accident repairs	replaced lens and light light assembly		475185
881	12/21/2015	565892	bus requires jump start	jump start bus		474546
881	12/17/2015	565421	Direct Purchase - MECHANICAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O159656 Receiving #:165589 Date :2015-12-23 supply air pressure warning switch as required		475185
881	12/17/2015	565421	Air System - air warning light going off	fitled low air warning switch switch was ordered scania through LDM		474546

881	12/15/2015	563767	Engine hatch struts us	installed new engine hatch struts	474020
881	12/14/2015	564639	Dash - DESTO NOT WORKING	checked operation of desto could not fault	474220
881	12/11/2015	564013	Consumables		474294
881	12/11/2015	564013	Mechanic entered - Wheels and Tyres Other O/S/RP/S/F TORQUE	TIGHTENED O/S/RO/S/F WHEEL NUTS TORQUE.	474220
881	12/10/2015	563949	Elec and Light - DESTO NOT WORKING	LDM checked operation of desto working correctly	474220
881	12/10/2015	563949	Consumables		474240
881	12/10/2015	563949	Consumables		474240
881	12/10/2015	563949	Body - drivers mirror loose	drivers mirror tightened	474220
881	12/09/2015	564013	TYRE NEW 295/80R22.5		474020
881	12/09/2015	564013	Mechanic entered - Wheels and Tyres Other front tyres - mis	replaced o/s/f tyre. torque wheel nuts. refit pointers.	474020
881	12/09/2015	564013	Mechanic entered - Wheels and Tyres Worn o/s/r inner tyre -	replaced o/s/r inner tyre. used one that removed from o/s/f. refit links valve ext. torque wheel nuts.	474020
881	12/09/2015	564013	Direct Purchase - MECHANICAL	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY.LIMITED P/O #:O159265 Receiving #:164932 Date :2015-12-09 supply D Rubbers x 4 as required	474204
881	12/09/2015	564013	Mechanic entered - Suspension Noisy rear 'D' rubbers - u/s		474020
881	12/09/2015	563949	GLOBE 24V 21W SINGLE CONTACT HLR2421		474020
881	12/09/2015	563949	Elec and Light - right hand indicator not working	GLOBE FITTED	474020
881	12/09/2015	563949	Elec and Light - DESTO NOT WORKING	londsdaie for repair	474020
881	12/09/2015	563949	Body - drivers mirror loose	MIRRORS TIGHTENED	474020
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949			474020
881	12/09/2015	563949		CARRY OUT B SERVICE AS PER CHECK LIST B SERVICE COMPLETED	474020
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949	Consumables		474220
881	12/09/2015	563949			474020
881	12/09/2015	563949		CARRY OUT A SERVICE AS PER CHECK LIST A SERVICE COMPLETED	474020
881	12/08/2015	563760	Consumables		474204
881	12/08/2015	563760	Consumables		474204
881	12/08/2015	563760	Mechanic entered - Body Other CHECK PTI	CHECKED PTI.	474020
881	12/08/2015	562044	Decal Emergency Exit P/B under Panel		474020
881	12/08/2015	563789		COLD DRIVE CARRIED OUT A/C - A SERVICE ON 08/12/2015 PO#: O159194	474020
881	12/07/2015	562043	Vandalism graffiti - Clean / paint interior graffiti	Cleaned and painted rear of seats and side vents	474020
881	12/07/2015	562044	NO 7 WHITE 25MM		474020
881	12/07/2015	562044	PTV REBRAND - Method 3.	Rebrand	474020
881	12/07/2015	562044	PTV REBRAND - Method 3.	Rebrand	474020
881	12/07/2015	562044	PTV REBRAND - Method 3.	Rebrand	474020
881	12/07/2015	562044	DO NOT OVERTAKE DECAL		474020
881	12/07/2015	562044	'GIVE WAY' DECAL 240MM X 225MM		474020
881	12/07/2015	562044	NO 4 WHITE 25MM		474020
881	12/07/2015	562044	Decal VENTURA yellow on blue 480mm		474020
881	12/07/2015	562044	Ventura Rear Header Decal for Routebus		474020
881	12/07/2015	562044	DECAL EXIT ONLY YELLOW ON BLUE		474020
881	12/07/2015	562044	PLEASE KEEP CLEAR DECAL DOOR OPENS INWARDS		474020
881	12/07/2015	562044	wheelchair access ramp load rated 300 KG		474020
881	12/07/2015	562044	BODY SHOP SUPPLIES		474020
881	12/07/2015	562044	PAINT SUPPLIES		474020
881	12/07/2015	562041	2MM X 1200MM X 2400MM FLAT ALUMINIUM		474020
881	12/07/2015	563789	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O159194 Receiving #:165197 Date :2015-12-16 CARRY OUT AC-A SERVICE AS REQUIRED	474398
881	12/04/2015	562043	BODY SHOP SUPPLIES		474020
881	12/04/2015	562043	PAINT SUPPLIES		474020
881	12/04/2015	562044	PTV REBRAND - Method 3.	Rebrand	474020
881	12/04/2015	562044	PTV REBRAND - Method 3.	Rebrand	474020
881	12/04/2015	562041	Accident damage - O/S/R - Acc # OAK 42027. *THIRD PARTY A	Completed repairs and painted	474020
881	12/04/2015	562042	BODY SHOP SUPPLIES		474020
881	12/04/2015	562042	PAINT SUPPLIES		474020
881	12/03/2015	562044	PTV REBRAND - Method 3.	unmasked the entire bus roof sides tail lights head lights	474020
881	12/03/2015	562044	PTV REBRAND - Method 3.	cont prep work painted PTV orange	474020
881	12/03/2015	562041	BODY SHOP SUPPLIES		474020
881	12/03/2015	562041	PAINT SUPPLIES		474020
881	12/02/2015	562044	PTV REBRAND - Method 3.	painted white entire bus except rear hatch door area c/o	474020
881	12/02/2015	562041	Accident damage - O/S/R - Acc # OAK 42027. *THIRD PARTY AT	Continued with repairs	474020
881	12/02/2015	562041	Accident damage - O/S/R - Acc # OAK 42027. *THIRD PARTY A	Repairs and painting	474020
881	12/01/2015	562043	Vandalism graffiti - Clean / paint interior graffiti	Cleaned and painted rear wall	474020
881	12/01/2015	562044	PTV REBRAND - Method 3.		474020
881	12/01/2015	562042	UNREPORTED damages around vehicle in preparation for PTV Liv	Assisted repairs	474020
881	12/01/2015	562042	UNREPORTED damages around vehicle in preparation for PTV Liv	masked up the panels ns os and rear panels c/o	474020
881	12/01/2015	562041	Accident damage - O/S/R - Acc # OAK 42027. *THIRD PARTY A	Assisted repairs	474020
881	12/01/2015	562041	Accident damage - O/S/R - Acc # OAK 42027. *THIRD PARTY AT	Started repairs	474020
881	11/30/2015	562044	PTV REBRAND - Method 3.Remove all Advertising Decals.Pr	Removed all advertisement materials and decals sanded all panels ns os and ns os main rail front bumper bar front grill panel and corner sections of the roof c/o	474020
881	11/30/2015	562044	PTV REBRAND - Method 3.Remove all Advertising Decals.P	began prep work	474020
881	11/30/2015	562033	Ops Entered - Accident - Vehicle ran into Bus - Route: 703	Will be repaired with PTV	474020
881	11/30/2015	562033	Ops Entered - Accident - Collision In-Out of Bus Stop Mir	Will be repaired with PTV	474020
881	11/30/2015	562033	Acc #39305 Front - Damage to the off side front bumper and	Will be repaired with PTV	474020
881	11/27/2015	561755	Vandalism Vandalism/ Graffiti Interior	vandelisem repaired at knox bodyshop on order - O158693	474020
881	11/26/2015	561306	Elec and Light - desto not working	checked operation of desto light could not fault . all desto LEDS are working	473573
881	11/26/2015	561482	Brakes - door brakes on both doors are not working	this DVR is for 884 not 881	473573
881	11/23/2015	560418	Remove Old Poster and Fit new All Night Public Transport Po	carried out campaign as required	472858
881	11/23/2015	560418	Consumables		473311
881	11/21/2015	560269	Mechanic entered - Wheels and Tyres Other front tyres fitte	check front tyres tread is different using is ok	472858
881	11/21/2015	560269	Consumables		473084
881	11/21/2015	560269	Mechanic entered - Suspension Noisy o/s/f top torque rod bu	check o/s/f top torque rodbush ok	472858
881	11/21/2015	560269	Body - damage on the passenger side back bumper of the bus	photos already taken and supplied to fleet	472858
881	11/21/2015	560269	Consumables		473084
881	11/19/2015	559726			472778
881	11/19/2015	559726		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	472778
881	11/19/2015	559881	Mechanic entered - Engine Noisy or Rattling exhaust tail pip	VEHICLE SAFETY INSPECTION	472778
881	11/19/2015	559886	GLOBE 24V 4W S/C	tight and secured muffler brackets and tail pipe bracket holder.	472778
881	11/19/2015	559886	Mechanic entered - Elec and Light Exterior Lights o/s/f bott	replaced o/s/f bottom park light.	472778
881	11/19/2015	559884	TUBES FLUORESCENT 18W		472778
881	11/19/2015	559884	Mechanic entered - Elec and Light Interior Lights pax saloon	replaced floro tube. refit inverter terminals. refit lens.	472778
881	11/19/2015	559883	GLOBE FESTOON 24V 5W		472778
881	11/19/2015	559883	Mechanic entered - Elec and Light Exterior Lights o/s/f top	replaced festoon globe. refit lens holder. refit desto hatch.	472778
881	11/19/2015	559882	Mechanic entered - Body Other o/s hand rail top bracket - lo	refit pan head screw on o/s top-front rail holder mounting bracket. tight and secured allen bolts clamps.	472778

881	11/19/2015	559882	Consumables			472858
881	11/19/2015	559885	SLACK ADJUSTER			472778
881	11/19/2015	559885	Mechanic entered - Brakes Other rear brake slack adjuster -	replaced o/s/r slack adjuster. replaced shaft split pin. adjust rear brakes.		472778
881	11/14/2015	558856	L.E.D CLEARANCE LAMP			471838
881	11/14/2015	558856	Mechanic entered - Elec and Light Exterior Lights o/s/r widt	repair wiringfit new light.		471838
881	11/14/2015	558855	Elec and Light Indicators Not Working - Indicator stalk no	make fit new cancell striker arm.		471838
881	11/02/2015	556569		TRANSMISSION CHECK AS PER CHECK LIST		469634
881	11/02/2015	556569	TYRE NEW 295/80R22.5			469634
881	11/02/2015	556569	Mechanic entered - Wheels and Tyres Other n/s/f tyre u/s.	replaced N/S/F TYRE.		469634
881	11/02/2015	556569	Consumables			469839
881	10/31/2015	556493	Body - one of the passenger seats in the buses has come off	repaired disable seat pivot pin		469634
881	10/25/2015	554680	Complete task as instructed in Fleet Campaign 09/15	carried out campaign as required		467503
881	10/22/2015	554803	SEAL THERMOSTAT HOUSING K230 L94			467503
881	10/22/2015	554803	THERMOSTAT SCANIA K230 14014925			467503
881	10/22/2015	554803	Mechanic entered - Engine Other thermostat housing gasketth	replaced THERMOSTATTHERMOSTAT HOUSING GASKET.		467503
881	10/22/2015	554873	INDICATOR SWITCH SCANIA L94UAB 40V4703			467503
881	10/22/2015	554873	Mechanic entered - Elec and Light Indicators Not Working bli	fit new blinker stalk.		467503
881	10/22/2015	554744	SEATBELT ISRI A6008 RH			467503
881	10/22/2015	554744	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	carried out campaign as required replaced coat hook.		467503
881	10/22/2015	554744	SEAT BELT CLICK IS BROKEN	replace seat belt anchor checked operation ok		467503
881	10/22/2015	554854	Mechanic entered - Brakes Other BRAKE TEST	ROAD TESTEDBRAKE TESTED OK		467503
881	10/22/2015	554744	Consumables			467833
881	10/22/2015	554744	Consumables			467833
881	10/22/2015	554744	Consumables			467833
881	10/22/2015	554744				467503
881	10/11/2015	551188	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	A SERVICE AS PER CHECK LIST		462382
881	10/04/2015	550047	Replace A3 poster with Victorian Seniors Festival Poster	carried out campaign as required		462382
881	09/30/2015	550154		Completed 29/09/15		462382
881	09/30/2015	550154		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		462382
881	09/30/2015	550154		VEHICLE SAFETY INSPECTION		462382
881	09/30/2015	550154	Mechanic entered - CCTV Other cctv	checked& replaced fues		462382
881	09/30/2015	550154	KIT SLACK ADJUSTER REPAIR			462382
881	09/30/2015	550154	Mechanic entered - Brakes Other slack adjust	removed & replaced slack adjust kt		462382
881	09/24/2015	548725	LH Indicators will not turn off	fabricate and fit new striker plate to indicators . checked operation of indicators . could not fault		461347
881	09/19/2015	547112	VALVE FOOTBRAKE SR3 & SR4	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O155751 Receiving #:161316 Date :2015-09-19		460787
881	09/15/2015	547112	Front brakes needs looking into.It takes longer then othe	traced and found retarder n/w due to fault with retarder wiring in footbrake valve . replaced footbrake valve and retarder loom checked operation of retarder adjusted ratarder . road tested ok		459943
881	09/13/2015	546539	Audit Route buses for correct Decals and positions. Replace	carried out campaign as required		458932
881	09/08/2015	545685	retension nsr wheel nuts	retensioned nsr wheel nuts		457429
881	09/08/2015	545685	GLOBE 24V/21W FESTOON			457429
881	09/08/2015	545685	Dash - indicator on the dash board not on when turning right			457429
881	09/08/2015	545685	Body - front yellow light on right side top inside bus not	this is due to the blown globe		457429
881	09/07/2015	545449	EXTENSION FLEXIBLE TYRE VALVE 210mm LONG	fitted globe		457429
881	09/07/2015	545449	TYRE RECAP 295/80R22.5			457429
881	09/07/2015	545449	Mechanic entered - Wheels and Tyres Other n/s/r tyres u/s.	replaced N/S/R TYRES X2		457429
881	09/01/2015	540028	Direct Purchase - MECHANICAL	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O155039 Receiving #:160468 Date :2015-09-01 Scania Inv 33614831 Link 1766014		457202
881	08/31/2015	544240	Elec and Light Indicators Not Working - Can't use indicat	removed over sized striker plate from steering coloum checked operation of indicators . working ok		455713
881	08/28/2015	543967	INDICATOR STALK SCANIA SERIES 4 1402448			455713
881	08/28/2015	543967	Elec and Light - Indicator is not cancelling	fit new indicator stalk checked operation - ok		455713
881	08/26/2015	543614	TENSIONER SR4 MULTIRIB BELT 18S9654 38564			455499
881	08/26/2015	543614	FESTOON 24V 10W 7550			455499
881	08/26/2015	543614	coolant leaking from heater hose and heater motor	tighten hose clamp. need to order for hearter motor.		455499
881	08/26/2015	543614	Engine belt tensioner us	r/r tensionerok.		455499
881	08/26/2015	543614	os top park light nw	r/r globeok.		455499
881	08/26/2015	543614	Consumables			455713
881	08/26/2015	543614	front modesty panel loose	fixed modesty panelok.		455499
881	08/26/2015	543614	internal mirror loose	tighten mirrpr boltok.		455499
881	08/26/2015	543509	FILTER AIR DRYER SCANIA SR4 (1393551)(49G8709HALDEX)			455499
881	08/26/2015	543509	FILTER FUEL SCANIA L94UAB (H7090WK30)			455499
881	08/26/2015	543509	FILTER HYD COOLING FAN SCANIA SR3 (1354074)			455499
881	08/26/2015	543509	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			455499
881	08/26/2015	543509	FILTER FUEL SCANIA SR4(1372444)			455499
881	08/26/2015	543509	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)			455499
881	08/26/2015	543509	O-RING LARGE SPINNER FILTER SCANIA (1769799)			455499
881	08/26/2015	543509	O-RING SPINNER FILTER SCANIA (1769798)			455499
881	08/26/2015	543509		C SERVICE AS PER CHECK LIST donhe		455499
881	08/26/2015	543509	Consumables			455713
881	08/26/2015	543509	Consumables			455713
881	08/26/2015	543509		B SERVICE AS PER CHECK LIST		455499
881	08/26/2015	543509	Consumables			455713
881	08/26/2015	543509	Consumables			455713
881	08/26/2015	543509	Consumables			455499
881	08/26/2015	543509		A SERVICE AS PER CHECK LIST		455713
881	08/26/2015	543509	Consumables			455713
881	08/22/2015	540028	FITTING			454539
881	08/22/2015	540028	AIR SPRING FRONT SCANIA L94 K'SR SP0002A 35CMG0250HD			454539
881	08/22/2015	540028	Mechanic entered - Suspension Noisy front sway bar links - u	replaced o/s/f sway bar links. used old castle nuts no new nuts on links. replaced lock pins. replaced o/s/f airbag. replaced air hose joiner.		454539
881	08/19/2015	540028	Mechanic entered - Suspension Noisy front sway bar links -	part ordered		451340
881	08/14/2015	540028	SWAYBAR LINK	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O154560 Receiving #:160006 Date :2015-08-14 MM		452865
881	08/09/2015	539570	Consumables			451965
881	08/09/2015	539570	Complete Campaign 6/15 A3 Marketing Poster Change	carried out campaign as required		450736
881	08/08/2015	539976		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		451340
881	08/08/2015	539976		VEHICLE SAFETY INSPECTION		451340
881	08/08/2015	540017	BUSH SWAY BAR FRONT SCANIA SR4 & K230 40Y3408 1919010			451340
881	08/08/2015	540017	Mechanic entered - Suspension Noisy front 'D' rubbers - u/s	replaced front 'D' rubbers.		451340
881	08/08/2015	540010	GLOBE 24V 21W SINGLE CONTACT			451340
881	08/08/2015	540010	Mechanic entered - Elec and Light Exterior Lights o/s indica	replaced o/s front indicator globe.		451340
881	08/08/2015	540009	GLOBE FESTOON 24V 5W			451340
881	08/08/2015	540009	Mechanic entered - Elec and Light Exterior Lights o/s/f top	replaced o/s/f top parklight. refit desto hatch panel.		451340
881	08/08/2015	540002	DASH GLOBES			451340
881	08/08/2015	540002	Mechanic entered - Dash Dash_Lights Not Working	replaced dash ligh globes x 2.		451340
881	08/08/2015	539999	TUBES FLUORESCENT 18W			451340
881	08/08/2015	539999	Mechanic entered - Elec and Light Interior Lights	replaced floro tube. refit saloon light lens.		451340
881	08/08/2015	540023	Consumables			451682
881	08/08/2015	540004	Consumables			451682

881	08/08/2015	540000	Consumables			451682
881	08/08/2015	540023	Mechanic entered - Body Rear_Door Operation Faulty rear door	secured grab handle. fitted bolt and secured bracket frame.		451340
881	08/08/2015	540004	GAS STAY 600N- 501 MM (40059)			451340
881	08/08/2015	540004	Mechanic entered - Body Other n/s/r hatch gas struts - u/s	replaced n/s/r hatch gas struts x 2. replaced end links.		451340
881	08/08/2015	540000	REFLECTOR Amber small 70x28mm			451340
881	08/08/2015	540000	Mechanic entered - Body Other n/s/r amber reflector - missin	replaced n/s/r amber reflector x 1.		451340
881	08/08/2015	539976	Consumables			451682
881	08/08/2015	539976	Consumables			451682
881	08/08/2015	539976		A SERVICE AS PER CHECK LIST		451340
881	08/06/2015	539550	GLOBE 24V 21W SINGLE CONTACT			450736
881	08/06/2015	539550	OS Front indicator n/w and globes needed for:Raise/Kneel	replaced globes		450736
881	08/01/2015	536632	FESTO DOOR VALVE MINI TYPE	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:159380 Date :2015-08-01		450105
881	07/25/2015	536632	Air leak at the frt door upper panel	fitted air reg/valve		447308
881	07/20/2015	536351	SOLENOID VALVE FRONT	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O153236 Receiving #:158781 Date :2015-07-20		447448
881	07/20/2015	536351	Bus is riding high	fitted frt suspension height control solenoid valve; tested ok.		447308
881	07/18/2015	536351	Bus is riding high	found frt solenoid valve us/wop		446834
881	07/08/2015	534618	GLOBE 24V 75/70W H4			444121
881	07/08/2015	534618	Elec and Light Exterior Lights - Drivers side headlight n	replaced head light globe.		444121
881	07/08/2015	534618	Elec and Light Exterior Lights - offside headlight is out	checked ok		444121
881	07/08/2015	534655	Brakes Foot_Brakes Noisy brakes squeal and grab every now	inspected brakes and brakes linings . front 80% and rear 80% remaining . road tested bus for noisy brakes for 20 mins . could not fault brake noise . brake tested bus - passed . could not fault brake system .		444121
881	07/04/2015	534172	GLOBE 24V 75/70W H4			444121
881	07/04/2015	534172	NS Head light N/W	replaced globe		444121
881	06/29/2015	531536	Engine - fuel hand primer	r/r priming pumpok.		442408
881	06/26/2015	531536	Hand pump	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O152002 Receiving #:157634 Date :2015-06-26		442607
881	06/25/2015	531536	AIR SPRING REAR SCANIA L94 K'SR SP0003A 35CMG0252HD			442408
881	06/25/2015	531536	Suspension - n/s/r/r air bag leaking	replaced N/S/R/R AIR BAG.		442408
881	06/25/2015	531536	NO SMOKING DECAL			442408
881	06/25/2015	531536	SWITCH- STOP-YELLOW			442408
881	06/25/2015	531536	REVERSE ALARM 12-24v			442408
881	06/25/2015	531536	STOP BUTTON FLAT			442408
881	06/25/2015	531536	reverse buzzer n/w	replaced reverse buzzer. replaced terminals. checke for operation - ok		442408
881	06/25/2015	531536	inside grab handle bolt missing	refit bolts on n/s middle-top grab pole handle.		442408
881	06/25/2015	531536	Body - pax switch bell u/s	replaced pax bell x 2. refit terminals and checked for operation - ok.		442408
881	06/25/2015	531536	Body - pax switch bell loose	refit screw and secured wiring terminals on n/s 'next stop' pax bell.		442408
881	06/25/2015	531536	Body - passenger liscened to carry sticker missing	refit decal		442408
881	06/25/2015	531536	Body - no smoking decals missing x 2	refit 'No Smoking' decal x 1.		442408
881	06/20/2015	532027	GLOBE FESTOON 24V 5W LONG			440199
881	06/20/2015	532027	Suspension Kneel/ Raise - Cannot lower/raise bus	ROAD TEST AND COULD NOT FAULT SUSPENSION		440199
881	06/20/2015	532027	Elec and Light - N/S Top front clearance light N/W	REPLACED GLOBE		440199
881	06/17/2015	531436		TRANSMISSION CHECK AS PER CHECK LIST		440199
881	06/17/2015	531436		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		440199
881	06/17/2015	531436		VEHICLE SAFETY INSPECTION		440199
881	06/17/2015	531536	Engine - fuel hand primer	wop		440199
881	06/17/2015	531536	DIAPHRAM TYPE 24 BRAKE BOOSTER			440199
881	06/17/2015	531536	Brakes - o/s/r brake booster leaking	replaced O/S/RBRAKE BOOSTER DIAPHRAGM.		440199
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436	FILTER ZF TRANS ECOMAT ALL MODEL (4139-298-038)(E39HD119)			440199
881	06/17/2015	531436	FILTER FUEL SCANIA L94UAB (H7090WK30)			440199
881	06/17/2015	531436	FILTER FUEL SCANIA SR4(H17WK04)			440199
881	06/17/2015	531436	O-RING LARGE SPINNER FILTER SCANIA (1769799)			440199
881	06/17/2015	531436	O-RING SPINNER FILTER SCANIA (1769798)			440199
881	06/17/2015	531436	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			440199
881	06/17/2015	531436		B SERVICE AS PER CHECK LIST		440199
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436	Consumables			443859
881	06/17/2015	531436		A SERVICE AS PER CHECK LIST		440199
881	06/12/2015	530703	Body - driver side mirror loose	secure mirror		438822
881	06/08/2015	529940	Elec and Light - Flat Battery	JUMP START.		437294
881	05/30/2015	528747	GLOBE FESTOON 24V 5W LONG			435408
881	05/30/2015	528747	Elec and Light - N/S Top front park light N/W	DOUBLE ENTRY		435408
881	05/30/2015	528747	Elec and Light - N/S top park light N/W	FITTED GLOBE		435408
881	05/28/2015	518449	Retrimmed Base Assy 6008			435408
881	05/11/2015	525403	GASKET ROCKER COVER SCANIA SR4 DC9 (1425921)			430575
881	05/11/2015	525403		SERVICE MOISTURE EJECTOR		430575
881	05/11/2015	525403		VALVE ADJUSTMENT TURBO CHECK & INTERCOOLER/RADIATOR CLEAN adjusted engine valvecleaned intercooler.radiator.		430575
881	05/11/2015	525396	Consumables			431395
881	05/11/2015	525396	Wheels and Tyres - retorque n/s/r	carried out retorque as required		430575
881	05/06/2015	524611	osr inner flat tyre	replaced osr inner tyre r/r o/s/r/i tyre & road testok. checked for pti sheet.		430445
881	05/06/2015	524611	SLACK ADJUSTER LHF	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:154935 Date :2015-05-06		430575
881	05/06/2015	524611	KIT SLACK ADJUSTER REPAIR			430445
881	05/06/2015	524611	TYRE RECAP 295/80R22.5			430445
881	05/06/2015	524611	Brakes - n/s/f slack adjustor u/s	REKIT BOTH FRT SLACK ADJUSTERS		430445
881	05/05/2015	524578		VEHICLE SAFETY INSPECTION		430445
881	05/05/2015	524578		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		430445
881	05/05/2015	524611	Consumables			430445
881	05/05/2015	524611	Wheels and Tyres - n/s/r inner tyre needs to be checked	r/r tyreok. need wheel tention.		430445
881	05/05/2015	524611	transmission main seal leaking	replaced seal		430445
881	05/05/2015	524611	LOCK TAB REAR ZF 4HP500	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:154845 Date :2015-05-05		430445
881	05/05/2015	524611	REAR GEARBOX SEAL ZF 4HP500	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O150945 Receiving #:154845 Date :2015-05-05		430445
881	05/05/2015	524611	LOCK RING BRAK SHOE PIN 0804782			430445
881	05/05/2015	524611	10 BRAKE LINNING ASB FREE			430445
881	05/05/2015	524611	FESTOON 24V 10W 7550			430445
881	05/05/2015	524611	Elec and Light - front top park light n/w	replaced globes on n/s and o/s front-top parklights.		430445
881	05/05/2015	524611	Dash - 2 -way mount u.s	secured two way radio back plate mounting.		430445
881	05/05/2015	524611	pax stop light switch u.s	secured 2x pax next stop botton. refit screw and terminals.		430445
881	05/05/2015	524611	CCTV - displaying wrong time	adjust and reset cctv time and date.		430445
881	05/05/2015	524611	Body - no smoking decal missing	fitted decals		430445
881	05/05/2015	524611	Body - rear modesty panel needs tightening	refit modesty panel andfront top hatch.		430445
881	05/05/2015	524611	Brakes - n/s/f slack adjustor u/s	removed slack adjuster.found damaged on slack adjuster. need to order.		430445
881	05/05/2015	524611	Brakes - rear linings u/s	removed and replaced rear brake linings. refit and replaced circlips.		430445

881	05/05/2015	524578	Consumables		430445
881	05/05/2015	524578	Consumables		430445
881	05/05/2015	524578	Consumables		430445
881	05/05/2015	524578		A SERVICE AS PER CHECK LIST	430445
881	04/24/2015	522936	Step not lowering properly	checked operation of lowering operation could not fault	427276
881	04/07/2015	519950	BRACKET MIRROR- SHORT		422862
881	04/07/2015	519950	Near Side Mirror needs replaced	replaced mirror and straightend mirror arm	422862
881	04/04/2015	518725	Air Cond - a/c belt worn	removed a/c braket & replace a/c small rubber mountsok.	422438
881	04/04/2015	518725	indicator won't cancel	removed indicator switch but could not fault. found damaged on steering colume. made a patch& fitted itok.	422438
881	04/01/2015	518725	AIR CON.BELT TRI POWER S/4		420950
881	03/30/2015	518620		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	420950
881	03/30/2015	518620		VEHICLE SAFETY INSPECTION	420950
881	03/30/2015	518725	Mount A/C Small	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O149857 Receiving #:153083 Date :2015-03-30	421962
881	03/30/2015	518725	Suspension - n/s/r/r air bag u/s	r/r n/s/r/r air bagok.	420950
881	03/30/2015	518725	Suspension - o/s/f top torque rod bush u/s	r/r o/s/f/t torque rod bushsok.	420950
881	03/30/2015	518725	MULTI RIB BELT		420950
881	03/30/2015	518725	Mount A/C Large		420950
881	03/30/2015	518725	BUSH TORQUE ROD KIT		420950
881	03/30/2015	518725	Air Cond - mounts u/s x 4	r/r large a/c rubber mounts. need replace for small mount. fitted old parts without belts.	420950
881	03/30/2015	518725	Engine - engine belt worn	r/r engine beltsok.	420950
881	03/30/2015	518449	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O149850 Receiving #:153194 Date :2015-04-01 refoam drivers seat base as required	421962
881	03/29/2015	518262	Replace See Something Say Something Poster	complete audit as required	420950
881	03/28/2015	518449	Body & Acc Drivers Seat Cushion - seats base cushion not h	replaced driver seat cushion. drivers seat foam replaced by auto trimmers on order - O149850 reinstalled drivers seat base	421424
881	03/23/2015	517362	LAMP LED TURN		420099
881	03/23/2015	517362	o/s/b indicator n/w	replaced indicator assembly . checked operation ok	420099
881	03/19/2015	516691	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O149477 Receiving #:152500 Date :2015-03-19 overhaul driver seat as required with heavy duty kit	419833
881	03/18/2015	516691	Driver seat shock absorbers worn out it does not support m	removed and reinstalled reco drivers seat from auto trim	418924
881	03/18/2015	516691	Driver seat cushion padding worn off mainly centre and le	drivers seat overhauled by auto trimmers on order - O149477	418924
881	03/18/2015	516691	Seat base cushion not horizontal.The seat base sits on a l	Removed the driver's seat sent away for repairs.	418924
881	03/08/2015	514885	ROAD WORTHY INSPECTION	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O149163 Receiving #:152515 Date :2015-03-19 CARRY OUT BIC INSPECTION AS REQUIRED	419833
881	03/06/2015	514885	ANNUAL BUS SAFETY INSPECTION (RWC #)	CARRIED OUT ANNUAL BUS SAFETY INSPECTION BY FLEET CHECK PO O149163	416777
881	03/06/2015	514885	PRE ANNUAL BUS SAFETY INSPECTION CHECK	CARRIED OUT PRE ANNUAL BUS SAFETY INSPECTION CHECK	416777
881	02/27/2015	513637	NS Mirror loose	secured miror	415297
881	02/24/2015	513090	transmission leaking oil from filter housing	fixed trans oil leak ok	414684
881	02/24/2015	511987	INDICATOR STALK SCANIA SERIES	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151264 Date :2015-02-24	414982
881	02/24/2015	513090	o/s/r indicator n/w	fitted a second hand light still need to order as the part fitted is not the same as the other side	414684
881	02/24/2015	513090	number plate light n/w	fixed n/plate wiring	414684
881	02/24/2015	512906	Consumables		414982
881	02/24/2015	512906	Consumables		414982
881	02/24/2015	512906	USE ONLY PART # L816 GREASE LIPLEX HD2 (LU5)		414684
881	02/24/2015	512906	FILTER ZF TRANS ECOMAT(4139 298 038 01)(E39HD119)		414684
881	02/24/2015	512906	USE ONLY PART NUMBER L814 TEXAMATIC 1888		414684
881	02/24/2015	512906	FILTER FUEL SCANIA L94UAB (H7090WK30)		414684
881	02/24/2015	512906	USE ONLY PART # L807 BP MULTIFLEET /Ltr		414684
881	02/24/2015	512906	FILTER AIR OUTER SCANIA SR3 SR4 (395773)(0395773)		414684
881	02/24/2015	512906	COOLANT PREMIX NF48 (use L830) DO NOT USE		414684
881	02/24/2015	512906	FILTER FUEL SCANIA SR4(H17WK04)		414684
881	02/24/2015	512906	O-RING LARGE SPINNER FILTER SCANIA (1769799)		414684
881	02/24/2015	512906	O-RING SPINNER FILTER SCANIA (1769798)		414684
881	02/24/2015	512906		B SERVICE AS PER CHECKLIST	414684
881	02/24/2015	512906	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		414684
881	02/24/2015	512906	Consumables		414982
881	02/24/2015	512906	Consumables		414982
881	02/24/2015	512906		A SERVICE AS PER CHECKLIST	414684
881	02/20/2015	512388	COOLANT PREMIX NF48 (use L830)	TOP UP COOLANT.	413573
881	02/20/2015	512388	Eng Cool Coolant Low	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151101 Date :2015-02-19 40A5709	413836
881	02/19/2015	511156	O RING 11MM ID	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151101 Date :2015-02-19	413836
881	02/19/2015	511156	O RING 11MM ID	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151101 Date :2015-02-19	413836
881	02/19/2015	511156	O RING COMPRESSOR MOUNT SCANIA	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O147946 Receiving #:151101 Date :2015-02-19	413247
881	02/19/2015	511156	AIR COMPRESSOR SCANIA L94		413247
881	02/18/2015	511987	GLOBE&HOLDER GREY 1.2W	replaced indicator stalk	413247
881	02/18/2015	511987	FESTOON 24V 10W 7550	replaced O/S TPO PARK LIGHT GLOBE.	413247
881	02/18/2015	511987	Elec & Light IndicatorsIndicators do not cancel after t	FIXED O/S FRONT INDICATORS WIRES. replaced DASH INDICATORS LIGHT GLOBE.	413247
881	02/18/2015	511987	Elec & LightO/S Front indicator not working all the time	CHECK AIR SYSTEMFOUND AIR DRYER HOSE BROKENUNION IS BROKEN replaced OLD UNIONHOSE.	413247
881	02/18/2015	511987	Air System (None)Air Tank guages faulty 1 & 2	replaced all 8-blower motors tested a/c ok	413237
881	02/16/2015	510705	Air Cond not operating properly		413237
881	02/13/2015	511156	COOLANT PREMIX NF48 (use L830)		413237
881	02/13/2015	511156	SILICONE H/HOSE 3 PLY 15MM - 5/8ID CM		413237
881	02/13/2015	511156	HOSE SILICON 1/2 ID		413237
881	02/13/2015	511156	CLAMP HOSE 14-27		413237
881	02/13/2015	511156	Eng Coolant leaking around the res/tank area	refit air compressor. road test. checked air pressure from header tank. checked coolant leak oil leak - ok. top up coolant.	413207
881	02/12/2015	511156	Eng Coolant leaking around the res/tank area	air pressure from coolant header tank. checked and removed air compressor assy.	413207
881	02/12/2015	511156	Eng Coolant leaking around the res/tank area	CHECK COOLANT LEAKING AROUNDCHECKED AIR COMPERSSORFOUND AIR COMPERSSOR. removed air comperssor gear.	413207
881	02/12/2015	511107		ANNUAL BUS FIRE SAFETY INSPECTION	416454
881	02/10/2015	510705	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O148286 Receiving #:151661 Date :2015-03-03 repair aircon not working properly	413146
881	02/10/2015	510705	Air Cond not operating properly		413116
881	02/09/2015	510459	Body & Acc - rear door bar / handle on door has slipped down	fitted rear door handle needs dry out	412267
881	02/05/2015	493413	Sub-contracted - MECHANICAL	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O145043 Receiving #:150372 Date :2015-02-05 Carry out full overhaul on drivers seat as required with heavy duty kit and new seat base foam as required	411990
881	02/04/2015	509685	Wheel nut retention- both rears	carried out rear retention on both sides as required	411090
881	02/02/2015	509293			411090
881	02/02/2015	509293		Perform Safety Inspection as per checklist	411090
881	02/02/2015	509363	Whls & Tyres - n/s/r tyre worn		411090
881	02/02/2015	509364	o/s/r/inner tyre u/s	REMOVED FITTED NEW TYRES TORQUED WHEELNUTS	411090
881	02/02/2015	509364	Whls & Tyres - n/s/r tyre worn	REMOVED FITTED NEW TYRES TORQUED WHEELNUTS	411090
881	02/02/2015	509363	Engine coolant low		411090
881	02/02/2015	509364	COOLANT PREMIX NF48 (use L830)		411090
881	02/02/2015	509364	Engine coolant low	LOW ON COOLENT TOPPED UP.	411090
881	02/02/2015	509363	drivers step light u/s		411090
881	02/02/2015	509363	o/s/r reverse light lens cracked		411090
881	02/02/2015	509363	dash switch light globes u/s		411090
881	02/02/2015	509364	dash switch light globes u/s	LOOSE WIRE CONNECTION.	411090
881	02/02/2015	509364	LENS TO SUIT 2402/03/43		411090

881	02/02/2015	509364	o/s/r reverse light lens cracked	FITTED NEW LENS	411090
881	02/02/2015	509364	Whls & Tyres - n/s/r tyre worn	replaced osr inner tyre	411090
881	02/02/2015	509364	GLOBE 24V 21W SINGLE CONTACT		411090
881	02/02/2015	509364	drivers step light u/s	REFFITED NEW ONE	411090
881	02/02/2015	509352	BATTERY 12V 800CC		411090
881	02/02/2015	509352	Terminal Battery Positive		411090
881	02/02/2015	509352	rectify batteries u/s as required		411090
881	02/02/2015	509363	drivers side blind u/s	Replaced both batteries and the positive terminal. checked charging 28.7V	411090
881	02/02/2015	509364	drivers side blind u/s	secured sunblind	411090
881	02/02/2015	508751	Body & Acc drivers fan not operating at all.	traced wiring . found node in protection mode. repowered node. checked ok	411090
881	02/02/2015	509316	breakdown bus wont start	Traveled to Bentleigh jumpstart the bus.	411090
881	01/15/2015	506824	Wheel nut retention - o/s/r	carried out wheel nut retension as required	407729
881	01/10/2015	506068	Wheel nut retention - o/s/r	carried out wheel nut retention as required	406633
881	01/09/2015	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146971 Receiving #:\149271 Date :2015-01-09	406909
881	01/09/2015	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146971 Receiving #:\149271 Date :2015-01-09	406909
881	01/09/2015	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146971 Receiving #:\149271 Date :2015-01-09	406909
881	01/09/2015	505716	SOLONOID VALVE COMPLETE	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146971 Receiving #:\149271 Date :2015-01-09	406909
881	01/09/2015	505716	THERMOSTAT SEAL	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146971 Receiving #:\149271 Date :2015-01-09	406909
881	01/08/2015		0 Imported Service History	Imported Service History	406628
881	01/08/2015	505716	Whls & Tyres - o/s/r tyres u/s	replaced o/s/r tyres. torque and checked wheel nuts. refit wheel nuts link. refit valve extension.	406628
881	01/08/2015	505716	thermostat u/s	removed and replaced thermostat. secured coolant hoses and clamps. top up coolant.	406628
881	01/08/2015	505716	CLAMP HOSE 21-38		406628
881	01/08/2015	505716	Engine - coolant leak	rectify and replaced hose clamps. coolant leaking found on heater hose joiners clamps are loose.	406628
881	01/08/2015	505716	dash lights n/w	replaced dash globes.	406628
881	01/08/2015	505716	front park light n/w	replaced front-top parklights secured desto panel. replaced bottom parklights. replaced front-top indicator globes.	406628
881	01/08/2015	505716	COOLANT PREMIX NF48 (use L830)		406628
881	01/08/2015	505716	PUMP WIPER-WASHER 24 VOLT 80826		406628
881	01/08/2015	505716	FESTOON 24V 10W 7550		406628
881	01/08/2015	505716	GLOBE 24V 4W S/C		406628
881	01/08/2015	505716	rear modesty panel rattles	secured rear modesty glass panel with rivets and screws.	406628
881	01/08/2015	505716	seat cusion torn	replaced pax seat cushion x 1	406628
881	01/08/2015	505716	Wipers & Washers - n/w	replaced washer motor. secured washer hose.	406628
881	01/08/2015	505716	GLOBE FESTOON 24V 18W		406628
881	01/08/2015	505716	DASH GLOBES		406628
881	01/08/2015	505658	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	carried out audit campaign as required	406628
881	01/08/2015	505658	USE ONLY PART # L807 BP MULTIFLEET /Ltr		406628
881	01/08/2015	505658	USE ONLY PART # L816 GREASE LIPLEX HD2 (LUS)		406628
881	01/08/2015	505658	Consumables		406633
881	01/08/2015	505658	Consumables		406633
881	01/08/2015	505658		Tension ALL Wheel Nuts to OEM Specs	406628
881	01/08/2015	505658		A - Service & Bus Safety Inspection	406628
881	12/31/2014	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146550 Receiving #:\149052 Date :2014-12-31	405005
881	12/31/2014	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146550 Receiving #:\149052 Date :2014-12-31	405005
881	12/31/2014	501747	GASKET	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O146550 Receiving #:\149052 Date :2014-12-31	405005
881	12/15/2014	502087	A3 Poster Change	Fit by Fleet Support Staff	400946
881	12/15/2014	501747	COOLANT PREMIX NF48 (use L830)		400946
881	12/15/2014	501747	Mechanic entered - Engine Leaking	replaced oil cooler gasketx3 coolant water pump.	400946
881	12/12/2014	501715		disregard this defect it was a mistake	400946
881	12/12/2014	501747	BUSH SWAY BAR FRONT K230		400946
881	12/12/2014	501747	Suspension - front D rubbers u.s	removed & replaced front D lubbers.	400946
881	12/12/2014	501747	Pump Water Scania S4		400946
881	12/12/2014	501747	Mechanic entered - Engine Leaking	removed engine oil cooler...	400946
881	12/12/2014	501747	Engine oil leak	tighten tubo oil pipe.	400946
881	12/12/2014	501541		Creditor #:\VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:\O146475 Receiving #:\148891 Date :2014-12-23 rectify cctv n/w as required	401689
881	12/12/2014	501747	missing pax seat cover	rebooked	400946
881	12/12/2014	501223	Door Valve	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:\O146060 Receiving #:\148482 Date :2014-12-12 LR-D-MINI	401074
881	12/11/2014	501541	No Working - last recording on 14/11/2014.	cctv was repaired by lonsdale on order - O146475	400946
881	12/10/2014	501116	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:\O146414 Receiving #:\148882 Date :2014-12-23 carry out complete overhaul on drivers seat with heavy duty kit and refoam drivers seat as required	401689
881	12/10/2014	501116	Body & Acc Drivers Seat Back Rest very loose not supporti	fitted drivers seatok.	400440
881	12/10/2014	501116	Body & Acc Drivers Seat Back Rest very loose not support	removed driver seat from 334	400440
881	12/10/2014	501223	Air System - air leak at front door	fit new air reg checked operation of doors ok	400440
881	12/09/2014	500864	Hose trans cooling		400440
881	12/09/2014	500864	COOLANT PREMIX NF48 (use L830)		400440
881	12/09/2014	500864	Leaking coolant and over heated	replaced hose and refilled 15 litres of coolant road tested ok	400440
881	12/04/2014	500225	FESTOON 24V 10W 7550		399408
881	12/04/2014	500225	LED REAR STOP RED W/REFL.		399408
881	12/04/2014	500225	Mechanic entered - Elec & Light Park Lights	r/r o/s r & n/s/f/park lightsok.	399408
881	12/04/2014	500225	Mechanic entered - Elec & Light Stop lights		399408
881	12/01/2014	496786	DIRECT PURCHASE - MECHANICAL G	Creditor #:\VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:\O145603 Receiving #:\148107 Date :2014-12-03 repair pax seat bases as required	399408
881	12/01/2014	499385	Mechanic entered - Passenger Doors Not Operating rear door n	trace found door isolator on turn off.	398653
881	12/01/2014	482592	DIRECT PURCHASE - ELECTRICAL	Creditor #:\VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:\O142921 Receiving #:\148890 Date :2014-12-23 Rectify CCTV	401689
881	12/01/2014	496442	Door Valve	Creditor #:\VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:\O145560 Receiving #:\147959 Date :2014-11-28	398935
881	11/22/2014	496786	nsf hub cap plastic cover missing	REPLACED HUB PLASTIC COVER	395902
881	11/22/2014	498187	Body & Acc Drivers Seat Cushion - Driver's seats cushion	found a new base fitted on 29/09/2014 recalibrated the seat adjuster	395902
881	11/18/2014	497096	SWITCH- STOP-YELLOW		396173
881	11/18/2014	497096	Elec & LightTwo passenger bell buttons are NW	locate replace 2 pax switches .	396173
881	11/18/2014	497226	Remove Legacy Poster and replace with See Something Say So	Replaced poster as required	396173
881	11/15/2014	496786	GLOBE 24V 21W SINGLE CONTACT		395902
881	11/15/2014	496786	CATCH HOOK FOR SEAT		395902
881	11/15/2014	496786	FLUSH HINGE R/H		395902
881	11/15/2014	496786	FLUSH PIN HINGE L/H		395902
881	11/15/2014	496786	INDICATOR STALK SCANIA SERIES 4 1402448		395902
881	11/15/2014	496786	1MT MULTI FIT WIPER REFILL		395902
881	11/15/2014	496786	wiper rubber worn	replaced wiper rubbers	395902
881	11/15/2014	496786	Engine oil sump drain plug loose	secured sump plug	395902
881	11/15/2014	496786	nsf side indicator nw	replaced globe	395902
881	11/15/2014	496786	indicator won't cancell	replaced ind switch	395902
881	11/15/2014	496786	Eng Coolant leaking from hose near gear box	secured hose clamp	395902
881	11/15/2014	496786	pax seat cushio x 2 us	replaced seat cushion x2 PO O145603	395902
881	11/15/2014	496786	osr side hatch strut bar loose	secured strut bar	395902
881	11/14/2014	496442	CONSUMABLE DELIVERY CHARGE	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:\O145158 Receiving #:\147430 Date :2014-11-14 Freight for 40G0006	395902
881	11/14/2014	496442	OIL COL CO Scania	Creditor #:\VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:\O145158 Receiving #:\147430 Date :2014-11-14	395902
881	11/14/2014	496442	Air System Leaking not able to move bus	replaced main air reg at front door checked air leaks. ok	395902

881	11/14/2014	496442	Air System	Leaking not able to move bus	removed main air reg at frt door. water found in the reg. replaced air dryer filter.	395902
881	11/14/2014	496442	FILTER AIR DRYER	SCANIA K124EB (T350W)		395902
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713	FILTER ZF	TRANS		395902
881	11/14/2014	496713	O-RING			395902
881	11/14/2014	496713	O-RING			395902
881	11/14/2014	496713	FILTER ELE	L94 & EARLY K230		395902
881	11/14/2014	496713	OIL FILTER SC	S4 & K (H200W02/1117285)		395902
881	11/14/2014	496713	USE ONLY PART #	L816 GREASE LIPLEX HD2 (LU5)		395902
881	11/14/2014	496713	USE ONLY PART NUMBER	L814 TEXAMATIC 1888		395902
881	11/14/2014	496713	USE ONLY PART #	L807 BP MULTIFLEET /Ltr		395902
881	11/14/2014	496713		Tension ALL Wheel Nuts to OEM Specs		395902
881	11/14/2014	496713		A - Service & Bus Safety Inspection		395902
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713	Consumables			0
881	11/14/2014	496713		Tension ALL Wheel Nuts to OEM Specs		395902
881	11/14/2014	496713		A - Service & Bus Safety Inspection		395902
881	11/13/2014	496442	Air System	Leaking not able to move bus	replaced air oil seperator	395902
881	11/13/2014	496442	Air System	Leaking not able to move bus	found oil seperator leaking.	395902
881	11/08/2014	495343	Security CCTV	System Faulty - Front Camera is black not	checked cctv and found frt camera plugs disconnected reconnected and checked ok.	394602
881	11/03/2014	494390	Elec & Light	Wrong bus should be **Bus 880**Bell Butto	wrong entry disregard	392427
881	11/03/2014	494246	GLOBE 24V	75/70W H4		392427
881	11/03/2014	494246	Elec & Light	Headlights O/S headlight NW	fit globe .	392427
881	11/01/2014	494172	AIR CONDITIONING	REPAIR	Creditor #:VB-COL004 COLD DRIVE AIR CONDITIONING P/O #:O145177 Receiving #:147524 Date :2014-11-18 repair ac as required	396398
881	11/01/2014	494172	repair ac	as required	ac job was done by cold drive on 29/10/2014 po O145177	392427
881	11/01/2014	491107	HOSE		Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O144715 Receiving #:147057 Date :2014-10-31 MM	393321
881	10/29/2014	493413	Seat shock absorbers	do not support maximum weight.Seat b	fitted driver's seat and the air supply checked ok.	392427
881	10/29/2014	493413	Body & Acc	Drivers Seat Cushion -Cushion Base Not Horizon	removed driver seat.	392427
881	10/21/2014	492017	Body & Acc	Drivers Seat Mount Leans To The Left	checked operation of drivers seat and controls - ok checked condition of drivers seat base could not fault has been replaced on 12-9-14 could not fault	390365
881	10/20/2014	491724	Passenger Doors	- front wont close	adjust rebound switch checked operation of drivers seat ok	390365
881	10/17/2014	491107	SEALING RING	(OIL COOLER)	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM Units # 40A2605	390684
881	10/17/2014	491107	SEAL PINION	DIFF S/3	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM	390684
881	10/17/2014	491107	Drag Link	Scania	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM Units # 40L2227ZF	390684
881	10/17/2014	491107	GASKET		Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM	390684
881	10/17/2014	491107	GASKET		Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM	390684
881	10/17/2014	491107	Mount Engine	Scania	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM	390684
881	10/17/2014	491107	GASKET		Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O144485 Receiving #:146495 Date :2014-10-17 MM	390684
881	10/16/2014	491107	Steering-drag link	u/s	replaced steering drag link.	390249
881	10/16/2014	491107	COOLANT PREMIX	NF48 (use L830)		390249
881	10/16/2014	491107	O RING	COMPRESSOR		390249
881	10/16/2014	491107	Engine coolant	leak from engine	replaced engine oil cooler coolant gasketoil cooler gasket.	390249
881	10/16/2014	491107	Engine- mount	u/s x 2	replaced engine mounts x2	390249
881	10/16/2014	491107	Diff & Hubs- diff	leaking	replaced diff oil seal.	390249
881	10/15/2014	491082			Perform Safety Inspection as per checklist	390249
881	10/15/2014	491107	CLAMP HOSE	21-38		390249
881	10/15/2014	491107	Engine coolant	leak from engine	removed engine oil cooler. installed oil coolertightened oil pipescomperssor rearhose. replacedengine oil cooler coolant gasket cooler oil gasket.	390249
881	10/15/2014	491107	Engine coolant	hose leaking	tightened coolant clamps.	390249
881	10/15/2014	491107	BATTERY	TERMINAL		390249
881	10/15/2014	491107	GLOBE 24V	SW		390249
881	10/15/2014	491107	CLEAR	LENS		390249
881	10/15/2014	491107	CABLE LUG	70MMX8MM		390249
881	10/15/2014	491107	battery terminal	u/s	replaced battery terminlacable lug.	390249
881	10/15/2014	491107	cctv camera	showing wrong time	crret camear time ok	390249
881	10/15/2014	491107	rear step light	globe n/w	replaced rear door stap light globe.	390249
881	10/15/2014	491107	front step light	lens u/s	replaced front door stap light lens.	390249
881	10/15/2014	491107	middle pax seat	loose	tightened middle seat bolts.	390249
881	10/11/2014	490594	Elec & Light	- Outisde light cover broken - rear door light	fit second hand lens	389128
881	10/08/2014	489713	Complete AM/FM	radio saloon speaker modification	carried out speaker campaign modification as required	388474
881	10/03/2014	489201	Remove old decal	and fit new Authorised Officers Decal DO N	Completed as required	387490
881	10/01/2014	488611	Body & Acc	Drivers Seat Controls - - No up and down adjust	seat hasn't got air suspension. works normal	387118
881	10/01/2014	488611	Roof Hatch	has come off	fixed the wiring and fitted roof hatch.	387118
881	09/25/2014	487483				385958
881	09/24/2014	487462	Body & Acc	Drivers Seat Cushion - driver seat padding fla	removed drivers seat sent away for repairs to auto trim	385867
881	09/24/2014	487462	Body & Acc	Drivers Seat Back Rest - back of seat is loose	reinstalled rebuilt drivers seat checked operation ok	385867
881	09/24/2014	487462	MAJOR 12 MONTH	SERVICE	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487462	KIT PIVOT &	BUSH	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487462	SPRING	KIT	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487462	SHOCK	ABSORBER 517	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487462	SPEED CLIP	CUSHION PAN 515	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487462	BUSH	BACKREST PLASTIC 515 517	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O143876 Receiving #:145762 Date :2014-09-25	385958
881	09/24/2014	487483			A - Service & Bus Safety Inspection	385867
881	09/24/2014	487483			Tension ALL Wheel Nuts to OEM Specs need fitting drivers seat & road test.	385867
881	09/13/2014	485657	Elec & Light	Headlights Driver side: Too high - too br	adjusted both head lights checked operation ok	383282
881	09/13/2014	485657	Drv entered	- Comm Equip Other	checked operation of 2-way -could not fault	383282
881	09/11/2014	482372	Throttle	No Acceleration - Bus doesn't accelerate when sta	swap relays clean air brake switch fit good micro switch unit to foot valve road brake test ok .	383120
881	09/11/2014	482372	Mechanic entered	- Throttle Not Operating	road test could not fault .	383120
881	09/02/2014	483436	Remove old A3	poster & replace with Legacy or Penalty Fares	replaced poster as per campaign	381403
881	09/01/2014	482371	front engine	mounts u/s		379556
881	08/29/2014	480488	ROLLER		Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O142456 Receiving #:144769 Date :2014-08-29 UNITS 1433450	380550
881	08/29/2014	480488	ROLLER		Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O142456 Receiving #:144769 Date :2014-08-29 UNITS 1428940	380550
881	08/29/2014	479738	Lining	Scania 8 inch	Creditor #:VB-ECOAST217 EASTCOAST KNOXFIELD - 217 P/O #:O142456 Receiving #:144769 Date :2014-08-29	380550
881	08/28/2014	482592	Workshop	Pls contact Lonsdale Electric P/L to fix GPS unit	cctv repaired carried out on order number - 0142921	379984
881	08/27/2014	482319	TYRE VALVE	EXTENSION 180mm LONG		379556
881	08/27/2014	482319	Clamp	Suit Tyre Valve		379556
881	08/27/2014	482319			fitted air valveok.	379556
881	08/27/2014	482319			Perform Safety Inspection as per checklist	379556
881	08/27/2014	482372	WIPER BLADE	ASSEMBLY		379556
881	08/27/2014	482372	both wipers	u/s	replaced wipers	379556
881	08/27/2014	482371	WIPER BLADE	ASSEMBLY		379556
881	08/27/2014	482371	both wipers	u/s		379556

881	08/21/2014	481157	front door safety edges to be checked	adjusted rebound valve for front sensitive edge.. checked operation of door. could not fault	377936
881	08/20/2014	480488	Service	installed new header tank belt tensioner and belt idlerrollor	377936
881	08/19/2014	480753	Mechanic entered - Engine Leaking COOANT	replaced coolant tankengine belt tentioner.fully.	377936
881	08/19/2014	480488	SCANIA ALT BELT TENSIONER K1241B 40n0903 1869654		377936
881	08/19/2014	480488	EXPANSION CENTRE FIL		377936
881	08/18/2014	480488	Wheel nut retention front wheel nuts to be retensioned	retensioned wheel nuts	377936
881	08/18/2014	480488	Eng Coolant leaking	removed header tank and ordered	377936
881	08/18/2014	480488	Drivers seat leaning to the right	fitted driver's seat from 1183	377936
881	08/16/2014	479738	front brakes vibration	refit drums linings .adjusted breakes . road tested andbrake tested	377595
881	08/16/2014	479738	front brakes vibration	refit drums linings .adjusted breakes . road tested and brake tested	377595
881	08/15/2014	479738	front brakes vibration	removed and re-fit front brake linings.	377595
881	08/15/2014	479738	front brakes vibration	fitted new drums & relining.need send to machining shop.	377595
881	08/15/2014	479738	FILTER AIR DRYER SCANIA K124EB (T350W)		377595
881	08/14/2014	477807	FREIGHT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14 VOR FREIGHT 49Y3314	377595
881	08/14/2014	477807	BUSH TORQUE ROD SCANIA/MERC	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14	377595
881	08/14/2014	479738	VALVE	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14	377595
881	08/14/2014	479738	AIR DRYER VALVE BLOCK (BLACK)	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O141815 Receiving #:144279 Date :2014-08-14	377595
881	08/14/2014	479738	Air leaks from the compressor	replaced air hose	377595
881	08/13/2014	479738	front brakes vibration	road test. front bakes needs re-lining.	377441
881	08/08/2014	478882	Wheel nut retention front axle	retensioned frt wheel nuts as per instruction	376495
881	08/08/2014	478887	JOINER 4MM - 6MM		376495
881	08/08/2014	478887	UNION ASSY		376495
881	08/08/2014	478887	Air System Losing Air	replaced air hose &joines cut air valve .leaking main pipesto tighten tested all ok	376495
881	08/08/2014	478887	Air System Losing Air	fond leaking air from tube removed the tube and fitting.	376495
881	08/02/2014	477807	o/s/f tyre u/s		375667
881	08/02/2014	477807	o/s/f top torque rod bush u/s	replaced o/s/f torque rod bush.	375667
881	08/02/2014	477764	FILTER OIL K124 / L94UAB (H200W20)2059778		375667
881	08/01/2014	477807	BUSH TORQUE ROD KIT		375667
881	08/01/2014	477807	Lamp SWF Switch LED		375667
881	08/01/2014	477807	DECAL BGIE(hammer) 120mm SQ		375667
881	08/01/2014	477807	CONNECTOR 4MM & 5/32		375667
881	08/01/2014	477807	DECAL EMERGENCY EXIT		375667
881	08/01/2014	477807	DECAL BGIE(rock) 120mm SQ		375667
881	08/01/2014	477807	SINGLE SEAT BASE		375667
881	08/01/2014	477807	GLOBE FESTOON 24V 18W		375667
881	08/01/2014	477807	FESTOON 24V 10W 7550		375667
881	08/01/2014	477807	GLOBE 24V 4W S/C		375667
881	08/01/2014	477807	GLOBE 24V 75/70W H4		375667
881	08/01/2014	477764	Fit Wheel Nut Pointers to all wheel nuts on the front axle	fitted wheel nut pointers	375667
881	08/01/2014	477764	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	fitted valve extensions	375667
881	08/01/2014	477764	Clamp Suit Tyre Valve		375667
881	08/01/2014	477764	TYRE VALVE EXTENSION 210mm LONG		375667
881	08/01/2014	477807	o/s/f tyre u/s	replaced both front tyres booked for retorque	375667
881	08/01/2014	477807	dash switch lights n/w	replaced dash switch light globes with LED.	375667
881	08/01/2014	477807	n/s headlight n/w	replaced headlight globe	375667
881	08/01/2014	477807	n/s/t park light n/w	replaced festoon. secured base panel.	375667
881	08/01/2014	477807	o/s/f parklight n/w	replaced globe	375667
881	08/01/2014	477764	Fit Myki decals as requiredFit Recruitment decal as requi	no myki decals required already on the bus	375667
881	08/01/2014	477807	front rattles	secured front modesty panel and door leaf top panel.	375667
881	08/01/2014	477807	missing decals	refit decals.	375667
881	08/01/2014	477807	seat cushion torn	replaced pax seat base cushion.	375667
881	08/01/2014	477807	air leak on compressor hose	refit hose joiner. secured air line hose with cable ties.	375667
881	08/01/2014	477764	O-RING		375667
881	08/01/2014	477764	ZF GEARBOX FILTER		3

881	06/23/2014	470190	Suspension - n/s + o/s front upper torque rod bushes u/s	r/r n/s upper toque rod bushesok. r/r front sway bar linkok.	368893
881	06/23/2014	470175	dash globes out	replaced globe	368893
881	06/23/2014	470190	resecure pax pole bar inside bus as required	tighten pax brakedt boltsok.	368893
881	06/23/2014	470190	n/s/r gutter rail needs to be resecured with pop rivot	fixed cutter rail with rivetsok.	368893
881	06/21/2014	469990	Wipers & WashersWiper blades needs replacement and are be	could not fault wiper rubbers checked operation ok	368347
881	06/21/2014	469991	Elec & Lightn/s top clearance light n/w	replaced globe	368347
881	06/21/2014	469981	Body & AccDriver seat base cushion padding flat leans to	replaced seat base cusion	368347
881	06/16/2014	464967	Insert Green (Front Saloon)	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16	367685
881	06/16/2014	467649	GLOBE 24V 75/70W H4	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O139249 Receiving #:141929 Date :2014-06-16	367685
881	06/13/2014	468580	Perform Campaign 1_14 School Bus Light Globe Check Check	replaced osf school light with new globe. replaced globes for all other lights and tested ok.	366666
881	06/13/2014	468580	Elec & Light - AM/FM radio does not work.	adjusted volume to the driver's speaker balanced the speakers and tuned all am/fm stations.	366666
881	06/13/2014	468580	Security CCTV System Faulty Front facing camera too low	adjusted frt facing camera and the time. checked cctv ok	366666
881	06/10/2014	467767	Wipers & Washers Wipers intermittently work only work so	checked operation of wipers. could not fault	365133
881	06/10/2014	467766	Elec & Light Indicators - right indicator on dash doesn't	could not fault indicator	365133
881	06/07/2014	467689	Mechanic entered - Engine Won't Start	jump start bus	365133
881	06/07/2014	467649	Elec & Light Headlights - N/S Headlight out	replaced globe.	365133
881	06/06/2014	467434	Elec & Light Headlights - N/S Bottom tail light out.	repaired wiring to LED	365133
881	05/24/2014	464967	Heat & Demist Faulty Controls switches dont work also a/c	replaced demistor switch	362195
881	05/24/2014	464926	Elec & Light Bell Button stuck rear button on o/s	removed tooth pick from pax button. checked operation of pax bell ok	362195
881	05/21/2014	464252	Whls & Tyres - wires exposed on side wall near side rear ou	replaced tyre and tensioned wheel nuts	361517
881	05/21/2014	464252	Body & Acc - drivers side sun blind needs extending not lo	checked operation of sun blind could not fault	361517
881	05/18/2014	462853	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	carried out A3 replacement as required	360081
881	05/17/2014	463616	Body & Acc Mirrors Exterior - N/S mirror arm needs replac	job is done on wo 463610	360360
881	05/17/2014	463610	Body & Acc Mirrors ExteriorWrong arm on the mirror	new arm fitted to comply with drivers request .	360360
881	05/16/2014	463314	Elec & Light Headlights n/s HEADLIGHT OUT	refit plug to globe .	360360
881	05/09/2014	459535	SINGLE SEAT BASE	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	PENNY WASHER 5.3X20X1.25	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	WASHER BODY 6 X 25	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	NUT HX 5mm	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	HX HD 5X20 BOLT	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	GLOBE FESTOON 24V 18W	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	GLOBE 24V 4W S/C	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459535	AIR FILTER SCANIA L94UB(395773	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459713	Switch battery master	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	COOLANT PREMIX NF48	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	GREASE ENERGREASE LC2-T	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	VANELLIUS ECO 10W/40 FOR MAN	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	OIL AUTO TRANS ATF H/DUTY	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	BP DIFF OIL HYPGEAR 85W140 EP	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	FILTER KIT	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	FILTER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	FILTER OIL/CONT HYD FAN	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/09/2014	459513	FILTER POWER STEERING K124	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O138068 Receiving #:140417 Date :2014-05-09	359071
881	05/07/2014	461342	no electrical power	trace and replace fuse .	358086
881	05/01/2014	460318	Elec & Light Headlights n/s headlight n/w	fit globe .	356870
881	04/28/2014	459713	ignition batt isolator solenoid u/s	checked and found isolator us replaced isolatop solenoid tested ok.	356417
881	04/26/2014	459535	o/s/r inner tyre u/s	replaced o/s/r inner tyrte. fit air valve stem on inner tyre.	355494
881	04/26/2014	459535	Engine air filter u/s	replaced air filter	355494
881	04/26/2014	459535	n/s parklight n/w	replaced globe	355494
881	04/26/2014	459535	cctv showing wrong time	rectify and adjust CCTV time.	355494
881	04/26/2014	459535	dash lights n/w	replaced globe	355494
881	04/26/2014	459535	o/s top indicator light n/w	replaced festoon & lens. secured front-top panel.	355494
881	04/26/2014	459535	drivers top panel rattles	secured & refit bolt/nuts on panels.	355494
881	04/26/2014	459535	pax seat cusion torn	replaced 2 pax seat cushion. arrange seat base on colour.	355494
881	04/26/2014	459513		Service as per check list	355494
881	04/26/2014	459513		Tension ALL Wheel Nuts to OEM Specs	355494
881	04/26/2014	459513		A - Service & Bus Safety Inspection	355494
881	04/26/2014	459513		Tension ALL Wheel Nuts to OEM Specs	355494
881	04/26/2014	459513		A - Service & Bus Safety Inspection	355494
881	04/22/2014	457973	GLOBE 24V 75/70W H4	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	365988
881	04/22/2014	458759	BATTERY MERC.1078	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	365988
881	04/22/2014	454624	GLOBE 24V 75/70W H4	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:O137110 Receiving #:141702 Date :2014-06-10	365988
881	04/21/2014	458759	Elec & Light Battery Flat	fit new battery	354530
881	04/15/2014	457973	Elec & Light Headlights o/s headlight n/w	fit new globe	353553
881	04/13/2014	456523	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	carried out campaign as required	351747
881	04/10/2014	457230	Elec & Light Switches Battery isolater switch n/w	reposition switch in dash .	352252
881	04/05/2014	456364		Perform Safety Inspection as per checklist	351215
881	04/05/2014	456386	FILTER AIR DRYER SCANIA K124EB (T350W)		351215
881	04/05/2014	456386	Rectify starter motor niosy and not meshing properly	removed & replaced starter motor. secured wirings & bracket bolts/nuts.	351215
881	04/05/2014	456386	FESTOON 24V 10W 7550		351215
881	04/05/2014	456386	DASH GLOBES		351215
881	04/05/2014	456386	STARTER MOTOR SR4		351215
881	04/05/2014	456386	GLOBE WEDGE 24V 1.2W		351215
881	04/05/2014	456386	rectify NS Top park light n/w	replaced park & indicator lights on n/s/f top.	351215
881	04/05/2014	456386	rectify dash switch lights n/w	replaced wedge x 3. replaced dash globes x 4	351215
881	04/05/2014	456386	arrange the mismatched seat bases	marshced & arrange pax seat to colour.	351215
881	04/05/2014	456386	AIR DRYER VALVE BLOCK (BLACK)		351215
881	04/05/2014	456386	rectify the unloader valve leaking	removed & refit new unloader valve. secured airlines.	351215
881	04/01/2014	448854	AIR SPRING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453204	Drill	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453204	S/T SCR C/S PHL 7982 ZN 4.2X25	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453978	MIRROR LH 380mm long	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	448848	GLOBE 24V SW	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	WASHER COPPER 32X38	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	O-RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	O-RING	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	OIL FILTER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	FILTER	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	FILTER FUEL K124 / LU94A (14	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	04/01/2014	453133	FILTER ZF TRANS	Creditor #:VB-ECOAST205 EASTCOAST OAKLEIGH - 205 P/O #:O135332 Receiving #:139582 Date :2014-04-15	353923
881	03/28/2014	454624	Mechanic entered - Elec & Light Headlights o/s headlight n/w	fit new globe checked operation ok	349207
881	03/25/2014	453978	Body & Acc Mirrors Exterior - near side mirror - incorrect	checked and replaced mirror adjusted ok	348791
881	03/24/2014	453442	replaced u/s spinner filter as required	replaced oil spinner	347873

881	03/21/2014	453442	replaced u/s spinner filter as required	found wrong part	347873
881	03/20/2014	453204	repair spinner filter as required	repaired spinner filter bush.& order	347873
881	03/20/2014	453133	Mechanic entered - Body & Acc Interior inside side panel nee	resecured panel with screws	347873
881	03/20/2014	453133		Tension ALL Wheel Nuts to OEM Specs	347873
881	03/20/2014	453133		A - Service & Bus Safety Inspection	347873
881	03/20/2014	453133		Tension ALL Wheel Nuts to OEM Specs	347873
881	03/06/2014	450983		Inspect vehicle as per RSI Checklist	344690
881	03/06/2014	450983	carry out bic inspection as re	Creditor #:\VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O136062 Receiving #:137887 Date :2014-03-13	345984
881	03/06/2014	450983		replaced new head light	344690
881	03/06/2014	450983		filled washer bottle	344690
881	03/06/2014	450983		Inspect vehicle as per RSI Checklist	344690
881	03/06/2014	0	Imported Service History	Imported Service History	344690
881	02/27/2014	449658		replaced no smoking decal	342507
881	02/27/2014	449658	Carry out Pre BIC inspection as required	carried out inspection.Replaced rear no smoking decal and top n/s indicator globe.	342507
881	02/26/2014	449418	Mechanic entered - Gearbox No Gears	Switched off and restarted	342507
881	02/24/2014	448854		removed replaced o/s/r air bagadjust air bag hight	341934
881	02/24/2014	448854		Perform Safety Inspection as per checklist	341934
881	02/22/2014	448848	Accident Rear DAMAGE TO N/S REAR BOTTOM. LIGHT ON REAR DOO	Replaced smashed door lamp lens. Found both door lamps not to be working.removed covers checked for power power was present.Reemoved and replace globes tested and working.Put lens back on.	341934
881	02/18/2014	447900	Body & Acc Drivers Seat Cushion is good but leans to the	Secure Blind- Fitted Dash switch globe Checked and could not fault drivers seat	341202
881	08/01/2013	0	Imported Service History	Imported Service History	306518
881	08/01/2013	0	Imported Service History	Imported Service History	306518
881	12/07/2012	0	Imported Service History	Imported Service History	256970
881	09/25/2012	0	Imported Service History	Imported Service History	241506
881	09/25/2012	0	Imported Service History	Imported Service History	241506
881	06/14/2012	0	Imported Service History	Imported Service History	222817
881	02/16/2012	0	Imported Service History	Imported Service History	0
881	02/16/2012	0	Imported Service History	Imported Service History	0
881	07/09/2008	0	Imported Service History	Imported Service History	312566
881	07/01/2008	0	Imported Service History	Imported Service History	315000
881	06/17/2008	0	Imported Service History	Imported Service History	307566
881	05/26/2008	0	Imported Service History	Imported Service History	302566
881	05/04/2008	0	Imported Service History	Imported Service History	297566
881	04/12/2008	0	Imported Service History	Imported Service History	292566
881	03/21/2008	0	Imported Service History	Imported Service History	287566
881	02/28/2008	0	Imported Service History	Imported Service History	282566
881	02/06/2008	0	Imported Service History	Imported Service History	277566
881	01/14/2008	0	Imported Service History	Imported Service History	272566
881	12/23/2007	0	Imported Service History	Imported Service History	267566
881	12/01/2007	0	Imported Service History	Imported Service History	262566
881	12/01/2007	0	Imported Service History	Imported Service History	0
881	11/09/2007	0	Imported Service History	Imported Service History	257566
881	10/18/2007	0	Imported Service History	Imported Service History	252566
881	09/26/2007	0	Imported Service History	Imported Service History	247566
881	09/04/2007	0	Imported Service History	Imported Service History	242566
881	08/13/2007	0	Imported Service History	Imported Service History	237566
881	07/21/2007	0	Imported Service History	Imported Service History	232566
881	06/29/2007	0	Imported Service History	Imported Service History	227566
881	06/07/2007	0	Imported Service History	Imported Service History	222566
881	05/16/2007	0	Imported Service History	Imported Service History	217566