

Veh#	Date	W/O#	Description	Notes	Service	Odometer
203	01/04/2026	1331545	>>>VOR - SAFETY INSPECTION OUT OF DATE - BEN TO ADVISE <<<	Bus is "Pending Sale"	NSW-BSW	1212315
203	20/03/2026	1328719	Decommission of Bus for Sale	removed two way and busminder with microphone	NSW-BSW	1212315
203	20/03/2026	1328719	Decommission of Bus for Sale	removed ventura decals with heat gun and blade	NSW-BSW	1212315
203	19/03/2026	1328719	Decommission of Bus for Sale	Drilled out the rivets on number plates and fitted 2 screws each to hold it. Removed E-tag and fitted next to dash for easy removal.	NSW-BSW	1212315
203	19/03/2026	1328719	Decommission of Bus for Sale	Assisting	NSW-BSW	1212315
203	19/03/2026	1328719	Decommission of Bus for Sale	Jump start bus in the yard and brought up to sick bay	NSW-BSW	1212315
203	27/02/2026	1323755		Completed by ATS 15/2/26	FIRE EXT.	1212315
203	07/01/2026	1312912		VEHICLE SAFETY INSPECTION - Bus getting sold	SAF-INSP	1212315
203	24/10/2025	1296935	DIRECT PURCHASE - BUS INSPECTI	Creditor #:MT-ROASAF ROAD SAFETY INSPECTIONS P/O #:M397148 Receiving #:422414 Date :2025-10-27	RSI	1212315
203	16/10/2025	1296935		VEHICLE SAFETY INSPECTION	SAF-INSP	1212315
203	16/10/2025	1296935		ANNUAL SAFETY INSPECTION SERIAL # RSI 072805 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	RSI	1212315
203	16/10/2025	1297012	Consumables		NSW-E&L	1212315
203	16/10/2025	1297012	SWITCH BELL PUSH (340037)		NSW-E&L	1212315
203	16/10/2025	1297012	Mechanic entered - Elec and Light Other 1st 2 stop bell not	replaced 2 stop bells. all ok	NSW-E&L	1212315
203	03/10/2025	1294255	Mechanic entered - Body Rear_Door Operation Faulty	Rear door front leaf sensitive edge faulty replaced sensitive edge switch checked operation of rear door. ok.	NSW-BSW	1212315
203	30/09/2025	1291060	EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER		NSW-BSW	1212315
203	19/09/2025	1291622	Mechanic entered - A/C Heating Belt Loose or_Missing	Adjusted A/C belts. ok.	NSW-SCA	1212315
203	19/09/2025	1291623	Mechanic entered - Engine Other	Resecured coolant hose due to rubbing shielded and resecured coolant hose. ok.	NSW-ENG	1212315
203	19/09/2025	1291547	LAMP LED NUMBER PLATE & EXIT LIGHT 250120 27771		NSW-E&L	1212315
203	19/09/2025	1291547	Mechanic entered - Elec and Light Other	Replaced rear door emergency exit light checked operation of interior lights. ok.	NSW-E&L	1212315
203	19/09/2025	1291626	SWITCH SENSITIVE EDGE (RED)		NSW-BSW	1212315
203	19/09/2025	1291626	Mechanic entered - Body Rear_Door Operation Faulty	Replaced rear door sensitive edge checked operation of rear door sensitive edge ok.	NSW-BSW	1212315
203	19/09/2025	1291625	Mechanic entered - Body Other	Rust undercarriage near front door cleaned rust and repainted undercarriage at front door. ok.	NSW-BSW	1212315
203	19/09/2025	1291624	Mechanic entered - Brakes Other	Resecured rear N/S brake hose due to potential rubbing through resecured N/S brake hose. ok.	NSW-BRA	1212315
203	17/09/2025	1291059	Mechanic entered - Elec and Light Exterior Lights N/S headli	Replaced N/S headlight assembly. ok.	NSW-E&L	1212315
203	17/09/2025	1291059	LAMP HEAD INSERT HELLA 100MM L/FLOOR 0500 29204		NSW-E&L	1212315
203	17/09/2025	1290999	STRUT GAS STAY LIFT UP SEAT		NSW-BSW	1212315
203	17/09/2025	1290999	Mechanic entered - Body Other	Replaced O/S fold down seat strut. ok.	NSW-BSW	1212315
203	17/09/2025	1291060	Mechanic entered - Body Other	Replaced rear door yellow step trim. ok.	NSW-BSW	1212315
203	17/09/2025	1291060	EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER		NSW-BSW	1212315
203	10/09/2025	1289436		VEHICLE SAFETY INSPECTION done the inspection as per the check list	SAF-INSP	1212315
203	10/09/2025	1289436		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1212315
203	10/09/2025	1289435		PRE ANNUAL SAFETY INSPECTION CHECK done the Pre RSI check as per the check list	PRE RSI	1212315
203	10/09/2025	1289435		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1212315
203	14/08/2025	1282795	Drag link movement	checked draglink. all okay as new one is fitted.	NSW-S&E	1212315
203	14/08/2025	1282795	N/S double seat base metal showing	replaced the n/s double seat base to a new one all good	NSW-BSW	1212315
203	14/08/2025	1282795	SEAT CUSH DBL CEN 680 CVR - CL		NSW-BSW	1212315
203	14/08/2025	1282795	Consumables		NSW-BSW	1212315
203	14/08/2025	1282795	Consumables		NSW-BSW	1212315
203	11/08/2025	1281862		CARRY OUT FIRE EXTINGUISHER TEST & TAG	FIRE EXT.	1212268
203	02/07/2025	1274013	Reverse light & buzzer not working	Rectified reverse lights and buzzer not working cleaned electrical connections checked operation of reverse lights and buzzer. ok.	NSW-E&L	1212268
203	02/07/2025	1274013	Consumables		NSW-E&L	1212268
203	25/06/2025	1272611		VEHICLE SAFETY INSPECTION Carried out vehicle safety inspection as per checklist. ok.	SAF-INSP	1212268
203	25/06/2025	1272611		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.	SAF-INSP	1212268
203	11/06/2025	1269724	PTI Tablet Entered -drivers seat Leaking Air	checked and repaired air line under drives seat	NSW-BRA	1211925
203	13/05/2025	1264048		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service as per checklist	CCTV - A	1211925
203	01/04/2025	1256164		VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.	SAF-INSP	1211925
203	01/04/2025	1256164		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts.	SAF-INSP	1211925
203	01/04/2025	1256164		Assisting	SAF-INSP	1211925
203	01/04/2025	1256226	Mechanic entered - Elec and Light Other Oil pressure dash li	Removed dash. Replaced 2x dash globes. Refitted Dash. Checked all ok.	NSW-E&L	1211925
203	01/04/2025	1256226	Mechanic entered - Elec and Light Other 2x driver's control	Removed driver's control switches. Replaced 2x globes. Refitted switches onto dash. Checked all working.	NSW-E&L	1211925
203	01/04/2025	1256226	Mechanic entered - Body Other N/S front seat end cap broken.	Replaced N/S front seat end cap with new.	NSW-BSW	1211925
203	01/04/2025	1256226	CAP CENTRA SEAT END MCCONNELL		NSW-BSW	1211925
203	01/04/2025	1256226	Consumables		NSW-BSW	1211925
203	15/03/2025	1252582	NSF INDICATOR NOT WORKING	R/R GLOBE . CHECKED OPERATION ALL OK	NSW-E&L	1211733
203	15/03/2025	1252582	Consumables		NSW-E&L	1211733
203	15/03/2025	1252620	Mechanic entered - Air System Air_Leak Interior Driver seat	removed drivers seat base located split air feed line to seat cut line refitted to feed aired up bus checked for leaks all ok refitted seat base ok.	NSW-AIR	1211733
203	14/03/2025	1252477	Mechanic entered - Elec and Light Flat Batteries	JUMP START BUS	NSW-E&L	1211733
203	14/03/2025	1252517	Mechanic entered - Elec and Light Flat Batteries	Removed and fitted new batteries.	NSW-E&L	1211733
203	14/03/2025	1252517	BATTERY EXSN94SCMF 1350AAC EMFN150L		NSW-E&L	1211733
203	14/03/2025	1252517	Consumables		NSW-E&L	1211733
203	14/03/2025	1252477	Consumables		NSW-E&L	1211733
203	11/03/2025	1251416	Mechanic entered - Elec and Light Flat Batteries	Jump started.	NSW-E&L	1211714
203	11/03/2025	1251416	Consumables		NSW-E&L	1211714
203	07/03/2025	1251093		COMPLETED BY ATS 23/2/25	FIRE EXT.	1211714
203	17/02/2025	1245649	Mechanic entered - Elec and Light Flat Batteries	Jump started all ok.	NSW-E&L	1211714
203	17/02/2025	1245649	Consumables		NSW-E&L	1211714

203	12/02/2025	1244481	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	CAMPAIGN DOES NOT APPLY TO RAIL BUSES	CAMPAIGN	1211714
203	04/02/2025	1242559	Mechanic entered - Elec and Light Flat Batteries	Jump started all ok.	NSW-E&L	1211714
203	04/02/2025	1242559	Consumables		NSW-E&L	1211714
203	28/01/2025	1241050	Mechanic entered - Elec and Light Flat Batteries	Jump started ok.	NSW-E&L	1211714
203	28/01/2025	1241050	Consumables		NSW-E&L	1211714
203	20/01/2025	1239661		CARRY OUT A/C - A SERVICE AS PER CHECK LIST carried out by Jimmy Cold Drive PO#: O380027	AC-A	1211714
203	20/01/2025	1239661	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O380027 Receiving #:403530 Date :2025-01-30 carry out ac-a service as required	AC-A	1211714
203	09/01/2025	1237601		VEHICLE SAFETY INSPECTION Carried out safety inspection.	SAF-INSP	1211714
203	09/01/2025	1237601		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1211714
203	09/01/2025	1237697	Mechanic entered - Dash Dash_Lights Not Working 2x dash ligh	replaced 2x dash lights checked for operation ok.	NSW-E&L	1211714
203	09/01/2025	1237697	Consumables		NSW-E&L	1211714
203	09/01/2025	1237697	Mechanic entered - Body Other 2x rear no smoking decals miss	fitted 2x new decals from stock.	NSW-BSW	1211714
203	09/01/2025	1237697	Mechanic entered - Body Other seat end cap U/S	trimmed plastic to size fitted to seat ok.	NSW-BSW	1211714
203	09/01/2025	1237697	CAP CENTRA SEAT END MCCONNELL		NSW-BSW	1211714
203	09/01/2025	1237697	Mechanic entered - Body Other Rear Door Hand Rail Not fitted	drilled into door fitted handle with new bolts checked for security ok.	NSW-BSW	1211714
203	09/01/2025	1237697	Consumables		NSW-BSW	1211714
203	08/01/2025	1237571	Mechanic entered - Elec and Light Flat Batteries	Jump started bus and left bus to run for 2hrs.	NSW-E&L	1211714
203	08/01/2025	1237571	Consumables		NSW-E&L	1211714
203	03/12/2024	1231294	LAMP LED SIDE RED/AMBER PERE1 52-98002		NSW-E&L	1211381
203	03/12/2024	1231294	Mechanic entered - Elec and Light Exterior Lights N/S/R mark	Replaced marker light with new LED light. Checked lights all ok.	NSW-E&L	1211381
203	28/11/2024	1230223	A/C not working - to confirm 27-11-24 -ldm	double entry	NSW-SCA	1211137
203	28/11/2024	1230223	Workshop Tablet Entered -A/C not working at all / no power	road tested aircon is working; clutch is on and blowing cold air. could not fault as interior temp maintained at 21C while outside is 27C and humid	NSW-SCA	1211137
203	25/11/2024	1229234	Mechanic entered - Elec and Light Flat Batteries	JUMP STARTED OK	NSW-E&L	1210892
203	25/11/2024	1229234	Consumables		NSW-E&L	1210892
203	25/11/2024	1229375	Body Drivers Seat Controls seat air leaking	removed the seat base and fixed air leak ok	NSW-BSW	1210892
203	25/11/2024	1229369	Mechanic entered - Body Front_Door Operation Faulty both frt	checked and found no power to frt door node. checked fuses and found some wires at the back of the fuse box were loose. secured and re-connected ok	NSW-BSW	1210892
203	25/11/2024	1229369	Consumables		NSW-BSW	1210892
203	25/11/2024	1229375	Consumables		NSW-BSW	1210892
203	21/11/2024	1228690		complete	FIRE EXT.	1210892
203	07/11/2024	1225755	Retension pos 1 wheel nuts to 670Nm	retensioned nsf	NSW-W&T	1210892
203	07/11/2024	1225755	Consumables		NSW-W&T	1210892
203	21/10/2024	1221504	DIRECT PURCHASE - BUS INSPECTI	Creditor #:MT-ROASAF ROAD SAFETY INSPECTIONS P/O #:M374407 Receiving #:396987 Date :2024-10-22	RSI	1210716
203	17/10/2024	1221504		VEHICLE SAFETY INSPECTION	SAF-INSP	1210716
203	17/10/2024	1221504		ANNUAL SAFETY INSPECTION SERIAL # RSI 065853 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	RSI	1210716
203	16/10/2024	1220941	O/S/R lower torque rod worn	Replace toruqe rod as requested	NSW-SUS	1210716
203	16/10/2024	1220941	Rear sway bar bushes worn	Replace worn bushes	NSW-SUS	1210716
203	16/10/2024	1220941	Steering wheel worn	Replaced steering wheel	NSW-STE	1210716
203	16/10/2024	1220941	30Y0918 Torque Rod	Creditor #:MT-MUL001 MULTISPARES LTD P/O #:M374300 Receiving #:396568 Date :2024-10-16	NSW-ENG	1210716
203	15/10/2024	1220941	BUSH RR SWAY BAR 50MM VOLVO B7	Creditor #:MT-CMVTRU CMV TRUCK AND BUS P/L P/O #:M374263 Receiving #:396548 Date :2024-10-16	NSW-SUS	1210716
203	15/10/2024	1220941	STEERING WHEEL 450MM DIA VOLVO	Creditor #:MT-CMVTRU CMV TRUCK AND BUS P/L P/O #:M374263 Receiving #:396548 Date :2024-10-16	NSW-OPS	1210716
203	15/10/2024	1220941	RSI STEAM CLEAN	done the steam cleaning. underneath the bus for RSI	NSW-ENG	1210716
203	15/10/2024	1220941	Consumables		NSW-BSW	1210716
203	15/10/2024	1220941	Consumables		NSW-BSW	1210716
203	15/10/2024	1220941	RSI FINAL & REPAIRS	replaced the O/S high beam unit secure the bell poles fixed the air leak close to transmission area gears it adjust the brake and done the final	NSW-BSW	1210716
203	15/10/2024	1220941	HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525		NSW-BSW	1210716
203	15/10/2024	1220941		PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST done the air system check as per the check list	AIR-CHECK	1210716
203	15/10/2024	1220941	Consumables		A	1210716
203	15/10/2024	1220941		CARRY OUT A SERVICE AS PER CHECK LIST done the A services as requested	A	1210716
203	14/10/2024	1220939	Consumables		NSW-W&T	1210716
203	14/10/2024	1220939	Pos 1 tyre worn	Replace pos 1 tyre with run out torque wheel nuts to 670Nm	NSW-W&T	1210716
203	10/10/2024	1220152	Consumables		NSW-BSW	1210716
203	10/10/2024	1220152	Consumables		NSW-BSW	1210716
203	10/10/2024	1220152	RSI REAIRS	Complete rust removal around front cross memebers and finish repairs on rear door C channel.	NSW-BSW	1210716
203	10/10/2024	1220152		Started removing rust from under rear door floor board. Found excessive rust. Used angle grinder to remove welds then removed C channel. Cut new C channel to size and measured to drill	NSW-BSW	1210716
203	03/10/2024	1218393		PRE ANNUAL SAFETY INSPECTION CHECK carried out annual safety inspection	PRE RSI	1210716
203	03/10/2024	1218393		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST carried out b service as per check list	PRE RSI	1210716
203	01/10/2024	1217731	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLEW	Squirrels fitted	CAMPAIGN	1210716
203	25/09/2024	1216641		VEHICLE SAFETY INSPECTION carried out safety inspection	SAF-INSP	1210716
203	25/09/2024	1216641		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retension wheel nuts to spec	SAF-INSP	1210716
203	01/09/2024	1201761	FUEL & COOLANT MIXING	Creditor #:VB-CMVTRUC CMV TRUCK AND BUS P/L P/O #:O372450 Receiving #:394470 Date :2024-09-13 SPILL	NSW-ENG	1210716
203	16/08/2024	1201761	Engine OIL LARGE SPILL	Repaired by CMV Clayton.	NSW-ENG	1210716
203	01/08/2024	1201761	SEAFORD TO CLAYTON	Creditor #:PT-EAG001 EAGLE TOWING & SALVAGE P/O #:PE369672 Receiving #:391590 Date :2024-08-05	NSW-ENG	1210716
203	16/07/2024	1201761	Frankston Station to Seaford D	Creditor #:PT-EAG001 EAGLE TOWING & SALVAGE P/O #:PE368761 Receiving #:390484 Date :2024-07-19	NSW-ENG	1210716
203	16/07/2024	1201213	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED	correct sticker fitted.	CAMPAIGN	1210716
203	25/06/2024	1196335		VEHICLE SAFETY INSPECTION carry out safety inspection.	SAF-INSP	1210457
203	25/06/2024	1196335		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tighten all wheel nuts	SAF-INSP	1210457
203	25/06/2024	1196447	Mechanic entered - Elec and Light Exterior Lights n/s/r/b bl	fit new LED blinker.	NSW-E&L	1210457
203	25/06/2024	1196447	LAMP INDICATOR DURALED L.E.D 177 X 100		NSW-E&L	1210457

203	25/06/2024	1196447 Consumables			NSW-E&L	1210457
203	18/06/2024	1195093 Mechanic entered - Elec and Light Flat Batteries	Jump started bus and left bus running for 2hrs		NSW-E&L	1209412
203	18/06/2024	1195093 Consumables			NSW-E&L	1209412
203	28/05/2024	1190691 DIRECT PURCHASE - GLASS	Creditor #:VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:O365963 Receiving #:387330 Date :2024-05-31 WINDSCREEN U/S		NSW-BSW	1209412
203	27/05/2024	1190691 crack in centre of windscreen	PO:O365414 - REPLACED BY OBRIANS		NSW-BSW	1209079
203	20/05/2024	1189479 Mechanic entered - Elec and Light Exterior Lights N/S head l	Removed and replaced H1 globe changed ground corroded terminal Replaced park light globe		NSW-E&L	1208543
203	20/05/2024	1189479 GLOBE 24V 70W HALOGEN H1			NSW-E&L	1208543
203	18/05/2024	1189210 Mechanic entered - Elec and Light Exterior Lights O/S/F Uppe	replaced blown globe checked for operation ok.		NSW-E&L	1208282
203	09/05/2024	1187336	complete		FIRE EXT.	1207697
203	13/04/2024	1182035	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list		CCTV - A	1206912
203	02/04/2024	1179561	VEHICLE SAFETY INSPECTION		SAF-INSP	1206846
203	02/04/2024	1179561	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1206846
203	02/04/2024	1179561 Mechanic entered - Elec and Light Next Stop Button 1X pax sw	replaced cracked pax switch		NSW-E&L	1206846
203	02/04/2024	1179561 SWITCH STOP YELLOW (62628)(50V2242)			NSW-E&L	1206846
203	02/04/2024	1179561 Consumables			NSW-E&L	1206846
203	02/04/2024	1179561 Mechanic entered - Body Other 1x Seat backing not secured pr	re secured seat backing to frame.		NSW-BSW	1206846
203	02/04/2024	1179561 Consumables			NSW-BSW	1206846
203	02/04/2024	1179561 Consumables			NSW-BSW	1206846
203	29/02/2024	1173517 PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	completed		CAMPAIGN	1205529
203	20/02/2024	1169867 BEARING A/C CLUTCH I/D 50MM O/D 90MM W 30MM 3210 6210 RSR			NSW-SCA	1205272
203	20/02/2024	1169867 O RING AC THERMOKING			NSW-SCA	1205272
203	20/02/2024	1169867 BELT V COGGED TRI-POWER 17x1145mm			NSW-SCA	1205272
203	20/02/2024	1169867 BELT V COGGED TRI-POWER 17x1905mm SCANIA K230			NSW-SCA	1205272
203	20/02/2024	1169867			NSW-SCA	1205272
203	20/02/2024	1169867 AIR CON REFRIDGERANT			NSW-SCA	1205272
203	20/02/2024	1169867 FAN CONDENSOR A/C CITI-RT			NSW-SCA	1205272
203	16/02/2024	1169867 UNLOADER COIL LS391 THERMOKING	Creditor #:GB-QTK001 QTK GROUP P/O #:G359515 Receiving #:379724 Date :2024-02-19		NSW-SCA	1205272
203	15/02/2024	1169867 COMPRESSOR A/C THERMOKING SCREW COMPRESSOR			NSW-SCA	1205272
203	15/02/2024	1169867 Workshop Tablet Entered -A/C Heating - Not Cooling	Commission tested found compressor was not pumping reclaimed refrigerant and remove compressor waiting on unloader coils before new compressor can be fitted parts ordered carry on		NSW-SCA	1205272
203	17/01/2024	1163865 Mechanic entered - Elec and Light Other jump battery.	jumped battery ok.		NSW-E&L	1204906
203	17/01/2024	1164050 BATTERY EXSN94SCMF 1350AAC EMFN150L			NSW-E&L	1204906
203	17/01/2024	1164050 Mechanic entered - Elec and Light Flat Batteries	Load tested batteries in the yard found rear battery weak 9 volts only removed and replaced with new battery tested all okay		NSW-E&L	1204906
203	11/01/2024	1162956 PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	N/A		CAMPAIGN	1204787
203	10/01/2024	1162772 Accident # 56392 - NSR BUFF	Polished scuff marks on ns lower panels x 04 job completed at oakleigh depot on 10/01/2024		NSW-ACC	1204787
203	05/01/2024	1161835	VEHICLE SAFETY INSPECTION Carried out Safety Inspection as per checklist.		SAF-INSP	1204787
203	05/01/2024	1161835	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1204787
203	05/01/2024	1161875 Mechanic entered - Elec and Light Exterior Lights N/S/R clea	Removed and fitted new clearance light.		NSW-E&L	1204787
203	05/01/2024	1161875 LAMP LED SIDE RED/AMBER PEREI 52-98002			NSW-E&L	1204787
203	05/01/2024	1161875 Mechanic entered - Body Other Front door emergency exit butt	Fitted new cover.		NSW-BSW	1204787
203	05/01/2024	1161875 COVER EMERGENCY EXIT BUTTON			NSW-BSW	1204787
203	05/01/2024	1161875 Consumables			NSW-BSW	1204787
203	15/12/2023	1158271 AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O356293 Receiving #:376621 Date :2024-01-03 carry out 24 month service as required		AC-B	1204787
203	15/12/2023	1158271	CARRY OUT A/C - B SERVICE AS PER CHECK LIST - O356293 - carried out by ben from colddrive		AC-B	1204787
203	15/12/2023	1158271	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O356293 - carried out by ben from colddrive		AC-A	1204787
203	15/12/2023	1158271	CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O356293 - carried out by ben from colddrive		AC-A	1204787
203	04/12/2023	1155784 entered in by mistake	entered in by mistake		NSW-ENG	1204787
203	02/12/2023	1155629 Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti		NSW-VAN	1204787
203	01/12/2023	1147263 vacuum & washer tube	Creditor #:VB-ENZED ENZED MOORABBIN P/O #:O356661 Receiving #:376142 Date :2023-12-21 Service & Labour		NSW-AIR	1204787
203	01/11/2023	1147210 DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O352876 Receiving #:373452 Date :2023-11-13		RSI	1204787
203	31/10/2023	1147628	Fit back power steering pump with new O ring replaced banjo washers fit new fuel pump with new gasket replaced leaking fuel hose made by enzed wash and check for leaks fit guard bac		NSW-ENG	1204787
203	31/10/2023	1147628 GASKET FUEL PUMP VOLVO B12BLE	Creditor #:VB-CMVTRUC CMV TRUCK AND BUS P/L P/O #:O353559 Receiving #:373027 Date :2023-11-06		NSW-ENG	1204787
203	27/10/2023	1147628 FUEL PUMP DH12D VOLVO B12BLE 3	Creditor #:VB-CMVTRUC CMV TRUCK AND BUS P/L P/O #:O353369 Receiving #:372368 Date :2023-10-27		NSW-OPS	1204787
203	27/10/2023	1147628 O RING P/STRG PUMP VOLVO 30A73	Creditor #:VB-CMVTRUC CMV TRUCK AND BUS P/L P/O #:O353369 Receiving #:372368 Date :2023-10-27		NSW-ENG	1204787
203	27/10/2023	1147628 WASHER P/STEERING PUMP	Creditor #:VB-CMVTRUC CMV TRUCK AND BUS P/L P/O #:O353369 Receiving #:372368 Date :2023-10-27		NSW-ENG	1204787
203	20/10/2023	1147628 Fluid Leaks at front of engine	Removed hose guard under front pulley wash and road test to detect leak found fuel feed pump leaking from mid joint and power steering pump face O ring leaking Order new parts Remov		NSW-ENG	1204787
203	20/10/2023	1147576 Consumables			NSW-E&L	1204787
203	20/10/2023	1147576 BusMinder Missing	email sent to bus minder		NSW-E&L	1204787
203	19/10/2023	1147210	VEHICLE SAFETY INSPECTION		SAF-INSP	1204787
203	19/10/2023	1147210	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1204787
203	19/10/2023	1147210	ANNUAL SAFETY INSPECTION SERIAL # _____ RSI 054139 PASS _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O T RSI		SAF-INSP	1204787
203	19/10/2023	1147263 Mechanic entered - Air System Air_Leak Rear leak can be hear	checked and found air leaking from rear door ext air switch valve. removed the valve and replaced; ok		NSW-AIR	1204787
203	19/10/2023	1147263 VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON			NSW-AIR	1204787
203	11/10/2023	1145674	PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST Carried out Air System check as per checklist.		AIR-CHECK	1204787
203	09/10/2023	1145129 Consumables			NSW-W&T	1204386
203	09/10/2023	1145129 PIN SIDE BIN LOCK DRIVERS DOOR ( UES 600-0487)			NSW-W&T	1204386
203	09/10/2023	1145129 Mechanic entered - Wheels and Tyres Wheel Nut Retension n/s	Completed retension		NSW-W&T	1204386
203	09/10/2023	1145097 Breakdown Not Starting	breakdown carried out by andrew dyson . bus ran out of fuel . topped of fuel 40 litres .		NSW-OPS	1204386
203	09/10/2023	1144318	Fit back repaired fuel tank with new rubber strips connect fuel lines and sensor top up fuel bleed and start . Repaired fuel leak from filter line replaced banjo cooper washers road test and		NSW-ENG	1204386

203	09/10/2023	1144318	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-BUNNINGS BUNNINGS P/O #:O352216 Receiving #:371211 Date :2023-10-12 rubber stripping	NSW-ENG	1204787
203	09/10/2023	1145129	Driver Tablet Entered -Body - Drivers door jamming	Replaced worn out door latch pin checked and okay	NSW-BSW	1204386
203	06/10/2023	1144318	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-AUT006 AUTO COOLING CLAYTON PTY LTD P/O #:O352013 Receiving #:371004 Date :2023-10-09 rectify fuel tank leaking as required	NSW-ENG	1204386
203	05/10/2023	1144318	Service	O352013 - fuel tank sent to auto cooling clayton for repair	NSW-ENG	1204386
203	04/10/2023	1144318	Mechanic entered - Fluid Leaks Rear of bus Fuel Tank Leaking	Drained fuel and removed fuel tank.	NSW-ENG	1204386
203	25/09/2023	1142362		VEHICLE SAFETY INSPECTION	SAF-INSP	1204259
203	25/09/2023	1142362		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1204259
203	25/09/2023	1142362	Consumables		NSW-E&L	1204259
203	25/09/2023	1142426	Consumables		NSW-E&L	1204259
203	25/09/2023	1142495	Consumables		NSW-E&L	1204259
203	25/09/2023	1142362	GLOBE STEP LIGHT 24V 20W DOWNLIGHT (DICHROIC)		NSW-E&L	1204259
203	25/09/2023	1142495	Mechanic entered - Elec and Light Interior Lights Rear Insid	removed blown globe replaced with new item from stock checked for operation ok.	NSW-E&L	1204259
203	25/09/2023	1142426	Mechanic entered - Elec and Light Interior Lights N/S/F insi	removed cover found fluro to be blown replaced with new item from stock checked for operation ok refitted cover.	NSW-E&L	1204259
203	18/09/2023	1141149		complete	FIRE EXT.	1204259
203	15/09/2023	1140800		PRE ANNUAL SAFETY INSPECTION CHECK	PRE RSI	1204259
203	15/09/2023	1140800		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1204259
203	15/09/2023	1140909	Consumables		NSW-W&T	1204259
203	15/09/2023	1140909	Mechanic entered - Wheels and Tyres Other n/s/r tyres tread	removed n/s/r tyres and replaced n/s/r tyres ok.	NSW-W&T	1204259
203	15/09/2023	1140909	TYRE 295/80R22.5 RECAP		NSW-W&T	1204259
203	15/09/2023	1140857	Consumables		NSW-E&L	1204259
203	15/09/2023	1140857	LAMP LED SIDE RED/AMBER PEREI 52-98002		NSW-E&L	1204259
203	15/09/2023	1140857	Mechanic entered - Elec and Light Other dash all gauge light	replaced dash all gauge light globe ok.	NSW-E&L	1204259
203	15/09/2023	1140857	Mechanic entered - Elec and Light Other reversing buzzer and	repaired reversing buzzer wires all ok.	NSW-E&L	1204259
203	15/09/2023	1140857	Mechanic entered - Elec and Light Other n/s/r marker light c	replaced n/s/r marker light ok.	NSW-E&L	1204259
203	15/09/2023	1140857	Mechanic entered - Elec and Light Other dash switch light no	replaced dash switch light globe ok.	NSW-E&L	1204259
203	15/09/2023	1140857	Mechanic entered - Elec and Light Other saloon light cover c	replaced saloon light cover 3m ok.	NSW-E&L	1204259
203	15/09/2023	1140857	STRUT GAS STAY LIFT UP SEAT		NSW-BSW	1204259
203	15/09/2023	1140857	Mechanic entered - Body Other n/s/r seat top roll cut.	repaired n/s/r seat top roll cut.	NSW-BSW	1204259
203	15/09/2023	1140857	Mechanic entered - Body Other n/s/middle seat strut not work	replaced n/s/middle seat strut ok.	NSW-BSW	1204259
203	15/09/2023	1140857	CAP CENTRA SEAT END MCCONNELL		NSW-BSW	1204259
203	15/09/2023	1140857	Mechanic entered - Body Other o/s/f cap seat end missing.	replaced o/s/f cap centra end ok.	NSW-BSW	1204259
203	09/09/2023	1139713	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPIN	complete	CAMPAIGN	1204259
203	08/09/2023	1139478		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list	FIRE-SAFE	1204259
203	02/09/2023	1138072	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti	NSW-VAN	1204259
203	23/08/2023	1135347	Consumables		NSW-BSW	1204259
203	23/08/2023	1135347	Driver Tablet Entered -Body - Body DamageNear side lower b	check bus for damage . no damage found	NSW-BSW	1204259
203	19/07/2023	1127624	Elec and Light deininstall smart track	Completed	NSW-E&L	1203871
203	19/07/2023	1127624	Consumables		NSW-E&L	1203871
203	18/07/2023	1127407		Retensioned ALL front and rear wheel nuts.	TYR	1203654
203	18/07/2023	1127407		Assisted	TYR	1203654
203	17/07/2023	1127088	Ops Entered - Fault - Warning Lights Engine - Route: 850 -	Checked found engine oil level are low. Top up and drive tested ok.	NSW-ENG	1203479
203	17/07/2023	1127067	BRAKE PADS FRT VOLVO B12BLE 8550611 49G7503BERAL		NSW-BRA	1203479
203	17/07/2023	1127067	DISC PAD SET RR VOLVO B7RSA B12B 20918891 30G7502BERAL		NSW-BRA	1203479
203	17/07/2023	1127067	Mechanic entered - Warning Lights Brakes	Removed and replaced front and rear brake pads. Adjust all the brakes drive/brake tested and checked warning light on dash ok.	NSW-BRA	1203479
203	13/07/2023	1126373	Mechanic entered - Elec and Light Other saloon light lense b	checked bus and find rear saloon lense fallen. when checked find that lense is cracked. cutted some spare ones and fitted in. Complete.	NSW-E&L	1203060
203	13/07/2023	1126373		replace broken saloon lamp with spares from electrical room	NSW-E&L	1203060
203	13/07/2023	1126373	Consumables		NSW-E&L	1203060
203	12/07/2023	1125858	Myki 4G antenna install	Completed by Amtek	NSW-E&L	1202708
203	12/07/2023	1125858	Consumables		NSW-E&L	1202708
203	10/07/2023	1125448	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	Completed	CAMPAIGN	1202453
203	03/07/2023	1123641		VEHICLE SAFETY INSPECTION CARRIED out safety inspection as per check list and carried out changing 2 saloon light lights and straighten mirror arm.	SAF-INSP	1200930
203	03/07/2023	1123641		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned all wheel nuts with indika	SAF-INSP	1200930
203	03/07/2023	1123700	Mechanic entered - Elec and Light Reverse Buzzer not buzzing	carried out replacing with one off scrap bus 585	NSW-E&L	1200930
203	03/07/2023	1123701	Mechanic entered - Elec and Light Other reverse lightsd not	carried out diagnosing with feda and found node problem changed and wokring now	NSW-E&L	1200930
203	03/07/2023	1123701		checked all fuses and relays and checked power at the lights carried out found node problem changed and checked working fine now.	NSW-E&L	1200930
203	03/07/2023	1123700	Consumables		NSW-E&L	1200930
203	03/07/2023	1123701	Consumables		NSW-E&L	1200930
203	27/06/2023	1122793	Accident#55061 NEARSIDE-Middle	Cut and polish minor marks. No damage.	NSW-ACC	1200171
203	23/06/2023	1122072	Mechanic entered - Engine Low Power Accelerator pedal % faul	Removed and replaced accelerator pedal sensor deleted fault and took bus for long road test Worked great no more fault pedal working all the time now.	NSW-ENG	1199401
203	23/06/2023	1121349		Took bus to wash bay cleaned off oil from having rocker cover off took bus for long road test bus has full power no faults came up. Drives really well no smoke either.	NSW-ENG	1199401
203	23/06/2023	1122072	SENSOR POTENTIOMETER ACC PEDAL VOLVO B7R B12BLE 30C0107		NSW-ENG	1199401
203	22/06/2023	1121349	SEAL ROCKER CVR BOLT DH12D VOLVO B12BLE 3964604		NSW-ENG	1199383
203	22/06/2023	1121349		Assisted Matt with installing rocker arms and tensioned bolts.	NSW-ENG	1199383
203	22/06/2023	1121349		Installed rocker arm assembly all as last time in volvo specs carried out tune up service fit rocker cover panel work and muffler back. Connected tech tool and aslo actia tools to program sei	NSW-ENG	1199383
203	21/06/2023	1121349		Assisted matt with fitting injector back C/o	NSW-ENG	1199383
203	21/06/2023	1121349	SEAL KIT INJECTOR DH12D VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G345410 Receiving #:363091 Date :2023-06-21	NSW-ENG	1199383
203	21/06/2023	1121349	WASHER INJECTOR TIP D7E VOLVO B7RLE 30A6503		NSW-ENG	1199383
203	21/06/2023	1121349		Started to assemble back installed second hand injectors into cylinder 1 and 5 followed volvo specs all thru fit the rocker arm assembly back as per volvo specs. Started doing tune up when	NSW-ENG	1199383

203	20/06/2023	1121348	Ops Entered - Fault - Gearbox Driveline Clutch Slipping - R	Defected wrong issue is with the engine made new W/O: 1121349	NSW-GEA	1199383
203	20/06/2023	1121349	SEAL KIT INJECTOR DH12D VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G345331 Receiving #:362935 Date :2023-06-20	NSW-ENG	1199383
203	20/06/2023	1121349	WASHER INJECTOR TIP D7E VOLVO B7RLE 30A6503		NSW-ENG	1199383
203	20/06/2023	1121349		steam cleaned the bus and secured on the stand removed exhaust removed rocker cover removed injector no.1 and 5 C/o	NSW-ENG	1199383
203	20/06/2023	1121349	Mechanic entered - Engine Noisy or Rattling Injector 1 fault	Steam cleaned bus to start connected tech tool various faults in system main one being injector 1 not responding properly and accelerator pedal % reading wrong. Removed muffler and pan	NSW-ENG	1199383
203	08/06/2023	1119507		CARRY OUT A SERVICE AS PER CHECK LIST carried out a service as per check list. and tMensioned all wheel nuts with indi	A	1198153
203	08/06/2023	1119507		Assiest.	A	1198153
203	08/06/2023	1119507	Consumables		A	1198153
203	08/06/2023	1119507	Consumables		A	1198153
203	08/06/2023	1119507	Consumables		A	1198153
203	08/06/2023	1119507	Consumables		A	1198153
203	06/06/2023	1119032	Driver Tablet Entered -Elec and Light - Exterior Lights fron	Replaced globe.	NSW-E&L	1197729
203	06/06/2023	1119032	Consumables		NSW-E&L	1197729
203	31/05/2023	1115547	SENSOR LOW COOLANT VOLVO B7RLE B12BLE 30V4902		NSW-ENG	1196864
203	30/05/2023	1115547	FILTER HYD FAN VOLVO B12BLE 20801559		NSW-ENG	1196557
203	30/05/2023	1115547		reinstalled radiator covers and seats and floor hatches ran bus to ensure hydraulic fan was work drained hyraulic oil and removed and changed filters steam cleaned bus replaced coolant h	NSW-ENG	1196557
203	30/05/2023	1115547		fixed removal rest of parts. filled hydraulic oil fan working. Drain oil and replaced filter and fresh oil. Road tsted temp go under 86C	NSW-ENG	1196557
203	29/05/2023	1115547		Replaced Hydrolic pump. C/O.	NSW-ENG	1196557
203	26/05/2023	1115547		Checked Hydraulic oil pump pressru Not at all Check pressur sensur Omes 24+-6 C/O	NSW-ENG	1196557
203	26/05/2023	1115547		hydraulic fan not spinning pressure tested hydraulic fan pum with indika but show 0 pressure tested pressure sensor all good removed hydraulic filter and checked and found a lot of cooper	NSW-ENG	1196557
203	25/05/2023	1115547		Replaced air compressor feed line road tested Now fan dosen't work. Temp go over 95. C/O...	NSW-ENG	1196557
203	24/05/2023	1115547	OIL PIPE AIR COMPRESSOR VOLVO	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G343708 Receiving #:361319 Date :2023-05-24	NSW-ENG	1196557
203	24/05/2023	1115547		Replaced new air compressor and all other removal parts. Top up coolant and stated.found the oil spray Air compressor feed pipe. It has little cracked parts been order. C/O.	NSW-ENG	1196557
203	23/05/2023	1115547		Removed air compressor C/O.	NSW-ENG	1196557
203	23/05/2023	1115547		Assisted Inidka removed fittings for compressor and removed compressor. cleaned down surfaces for refit of new	NSW-ENG	1196557
203	23/05/2023	1115547	WASHER OIL PLUG		NSW-ENG	1196557
203	22/05/2023	1115547		Disconnect air compressor coolant line Bridge coolant line road tested. No pessurising the system Need to be change air compressor. C/O.	NSW-ENG	1196557
203	22/05/2023	1115547	WASHER OIL PLUG		NSW-ENG	1196557
203	22/05/2023	1115547	O RING WATER PUMP VOLVO B12BLE 948980		NSW-ENG	1196557
203	22/05/2023	1115547	SEAL RING WATER PUMP VOLVO B12BLE 925073		NSW-ENG	1196557
203	22/05/2023	1115547	SEAL COOLANT PIPES DH12D VOLVO B12BLE 1547254		NSW-ENG	1196557
203	19/05/2023	1115547		Top up coolant road tested. pressur build up tank Change pressur cap agane road tested still the same. c/o	NSW-ENG	1196557
203	18/05/2023	1115547	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 862	Attended breakdown coolant leak around radiator core topped up with water and driven back to depot.	NSW-ENG	1196557
203	08/05/2023	1113182	Mechanic entered - Elec and Light Exterior Lights front righ	Removed and replac H1 globe for O/S head light.	NSW-E&L	1194820
203	08/05/2023	1113182	Consumables		NSW-E&L	1194820
203	03/05/2023	1112263	Drv entered - Elec and Light Indicators Not Working	Replaced n/s bottom brake/park LED light.	NSW-E&L	1194249
203	03/05/2023	1112263	LAMP STOP/TAIL LED HELLA		NSW-E&L	1194249
203	03/05/2023	1112259	Mechanic entered - Elec and Light Indicators Not Working Lef	Replaced globe.	NSW-E&L	1194249
203	03/05/2023	1112259	Consumables		NSW-E&L	1194249
203	03/05/2023	1112263	Consumables		NSW-E&L	1194249
203	01/05/2023	1115547	AIR COMPRESSOR VOLVO B12BLE 30	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G343532 Receiving #:361866 Date :2023-05-31	NSW-ENG	1197062
203	01/05/2023	1115547	O RING COMPRESSOR MTG VOLVO B1	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G343532 Receiving #:361866 Date :2023-05-31	NSW-ENG	1197062
203	01/05/2023	1115547	SEAL RING COMPRESSOR 21 X 29 X	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G343532 Receiving #:361866 Date :2023-05-31	NSW-ENG	1197062
203	27/04/2023	1111065	PTI Tablet Entered -Elec and Light - Exterior Lights front l	Replaced globe	NSW-E&L	1193383
203	27/04/2023	1111065	GLOBE 24V 70W H1		NSW-E&L	1193383
203	27/04/2023	1111065	Consumables		NSW-E&L	1193383
203	24/04/2023	1109508	GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596FWLED	PARTS CONSUMABLE	NSW-E&L	1193046
203	24/04/2023	1109508	GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT	PARTS CONSUMABLE	NSW-E&L	1193046
203	24/04/2023	1109508	Consumables		NSW-E&L	1193046
203	20/04/2023	1109832	Mechanic entered - Fluid Leaks Other low coolant	carried out checking for coolant leak any sign of dry or dripping coolant none removed top floor hatch carried out top up coolant and road tested and come back to check and come out of o	NSW-ENG	1192465
203	18/04/2023	1109494		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1192093
203	18/04/2023	1109494		VEHICLE SAFETY INSPECTION Completed safety service.	SAF-INSP	1192093
203	18/04/2023	1109508	Mechanic entered - Elec and Light Interior Lights Interior	Replaced 3 floor tubes for saloon light and N/S/F top indicator and park light ect.	NSW-E&L	1192093
203	18/04/2023	1109508	GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596FWLED		NSW-E&L	1192093
203	18/04/2023	1109508	GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT		NSW-E&L	1192093
203	17/04/2023	1109064	Ops Entered - Fault - Elec and Light Reverse Buzzer - Route	check and fixed door warning buzzer	NSW-E&L	1192093
203	17/04/2023	1109064	Consumables		NSW-E&L	1192093
203	03/04/2023	1107024		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carry out cctv service	CCTV - A	1190574
203	29/03/2023	1106322		Tensioned wheel nuts all rear with Kuma.	TYR	1189897
203	29/03/2023	1106322	Service	KMalikarala@venturabus.com.au	TYR	1189897
203	28/03/2023	1106061	PTI Tablet Entered -Wheels and Tyres - Damaged tyre no 3 wal	Assisted Ben fitted good run-out tyres pos3456. Tensioned wheel nuts w/ ben.	NSW-W&T	1189696
203	28/03/2023	1106061	PTI Tablet Entered -Wheels and Tyres - Damaged tyre no 3 wal	Replaced all rear tyres.	NSW-W&T	1189696
203	28/03/2023	1106059	PTI Tablet Entered -tyre no 3 damage	Dfect entered twice.	NSW-W&T	1189696
203	28/03/2023	1106061	Consumables		NSW-W&T	1189696
203	28/03/2023	1106059	Consumables		NSW-W&T	1189696
203	20/03/2023	1104212	PTI Tablet Entered -Fluid Leaks -coolant low topped up	Checked no leak found.	NSW-ENG	1187998
203	16/03/2023	1103504	Mechanic entered - Air System Air_Leak Front	Replaced door air line joiner.	NSW-AIR	1187435
203	16/03/2023	1103504	FITTING TEE PIECE 6mm x 1/8 11080610		NSW-AIR	1187435



203	13/12/2022	1086208	Mechanic entered - Brakes Other rear brake pads low need rep	replaced brake pads rear axle. replaced damaged brake caliper piston covers and tappets.	NSW-BRA	1174645
203	13/12/2022	1086208	KIT TAPPET DUST CVR VOLVO B12BLE 30G8905		NSW-BRA	1174645
203	13/12/2022	1086208	DISC PAD SET RR VOLVO B7RSA B12B 23149531 30G7502BERAL		NSW-BRA	1174645
203	08/12/2022	1085494	Engine coolant low header tank cap too tight	Removed header tank cap and topped up little bit of coolant Removed intercooler and cleaned out radiator and intercooler with wash gun fit all parts back with Satheesh.	NSW-ENG	1174399
203	08/12/2022	1085494	Remove intercooler and clean radiator	Removed intercooler and cleaned out radiator and intercooler with wash gun fit back all parts with Satheesh.	NSW-ENG	1174399
203	08/12/2022	1085494	Remove intercooler and clean radiator	completed.	NSW-ENG	1174399
203	06/12/2022	1084538	Fault#:38517 - Ops Entered - Fault - Breakdown Overheating/C	putted back all floor hatch topped up coolant check and found alternator belt cracked replaced new alternator belt . replaced broken air pipe bracket and carried out P.T.I .	NSW-OPS	1173888
203	06/12/2022	1084538	BELT MICRO V SERPENTINE 8 RIB 1660mm LONG		NSW-OPS	1173888
203	06/12/2022	1084538	Fault#:38517 - Ops Entered - Fault - Breakdown Overheating/C	replaced broken alternator belt and air pipe bracket steam cleaned road tested ok	NSW-OPS	1173888
203	05/12/2022	1084538	Fault#:38517 - Ops Entered - Fault - Breakdown Overheating/C	check and found radiator fan hydraulic pump faulty replaced hydraulic pump from recondation room engine c/o	NSW-OPS	1173888
203	05/12/2022	1084538	SEAL O-RING HYDRAULIC PUMP VOLVO B12BLE		NSW-OPS	1173888
203	05/12/2022	1084538	SEAL O-RING HYDRAULIC HOSE TO TANK VOLVO B12BLE		NSW-OPS	1173888
203	05/12/2022	1084538	O RING HYD PUMP DH12D VOLVO B12BLE		NSW-OPS	1173888
203	05/12/2022	1084538	FILTER HYD FAN VOLVO B12BLE 20801559		NSW-OPS	1173888
203	05/12/2022	1084538	Fault#:38517 - Ops Entered - Fault - Breakdown Overheating/C	RADIATOR fan not working found hydrolic pump faulty changed the pump ( used one from Transmission room) cleaned inter cooler c/o	NSW-OPS	1173888
203	02/12/2022	1084538	Fault#:38517 - Ops Entered - Fault - Breakdown Overheating/C	Top up coolant and checked leaks no leaks found. Drive the bus slowly back to depot.	NSW-OPS	1173888
203	30/11/2022	1084027	Front door outside opening unit is loose.	Secured fitted two new rivets.	NSW-BSW	1173458
203	14/11/2022	1080612	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		TRANS-SERV	1171125
203	14/11/2022	1080612	OIL GEARBOX ZF SYNTHETIC ECOFLUID A PLUS		TRANS-SERV	1171125
203	12/11/2022	1080612		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	TRANS-SERV	1170927
203	12/11/2022	1080612		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	TRANS-SERV	1170927
203	25/10/2022	1077363		PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST carried out air system as per check list.	AIR-CHECK	1168252
203	18/10/2022	1076033	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING	Removed	CAMPAIGN	1167374
203	14/10/2022	1075372		CARRY OUT A SERVICE AS PER CHECK LIST completed as per the check list and Retensioned wheel nuts with neven.	A	1166842
203	14/10/2022	1075372	Consumables		A	1166842
203	14/10/2022	1075372	Consumables		A	1166842
203	14/10/2022	1075372	Consumables		A	1166842
203	14/10/2022	1075372	Consumables		A	1166842
203	13/10/2022	1074483	Annual safety inspection	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G330493 Receiving #:347379 Date :2022-10-14	RSI	1167050
203	12/10/2022	1075006		Tensioned wheel nuts 5 and 6 with Kuma.	TYR	1166632
203	12/10/2022	1075006		Assisted Rene.	TYR	1166632
203	11/10/2022	1074483		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1166476
203	11/10/2022	1074483		VEHICLE SAFETY INSPECTION	SAF-INSP	1166476
203	11/10/2022	1074483		Assisting carried out rsi and carried out removing pos 5 and 6 wheels to inspect brakes rotors 40-40.5mm and pads 10mm thickness checked with ranjith allgood. carried out tensioned all w	RSI	1166476
203	11/10/2022	1074483		ANNUAL SAFETY INSPECTION SERIAL #RSI 044193_ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	RSI	1166476
203	10/10/2022	1074156	Carry out final inspection for RSI	completed	NSW-BSW	1166150
203	06/10/2022	1073613	Mechanic entered - Body Other steam clean the bus	Cleaned under the bus and through rear hatch thoroughly	NSW-BSW	1165983
203	06/10/2022	1073613	Mechanic entered - Body Other steam clean the bus	Ben cleaned	NSW-BSW	1165983
203	05/10/2022	1073344	Fault#:38467 - Ops Entered - Fault - Breakdown Air System Fa	Attened breakdown found compressor main line blown off olive worn away flared out the end of the pipe so it could blow off fit back enough to get the bus moving bus still leaking need to rep	NSW-OPS	1165854
203	05/10/2022	1073344	Fault#:38467 - Ops Entered - Fault - Breakdown Air System Fa	Replaced pipe ferrule and bracket.	NSW-OPS	1165854
203	05/10/2022	1073344	Fault#:38467 - Ops Entered - Fault - Breakdown Air System Fa	assisted Abraham.	NSW-OPS	1165854
203	04/10/2022	1073082		Retensioned all front wheel nuts.	TYR	1165604
203	04/10/2022	1073082		Assisted	TYR	1165604
203	03/10/2022	1072032	Mechanic entered - Suspension Other Borth torque rod bushes	removed and replaced both rear diff torque rods and both rear sway bar bushes	NSW-SUS	1165593
203	03/10/2022	1072030	Mechanic entered - Suspension Other Borth side uper controla		NSW-SUS	1165593
203	03/10/2022	1072031	Mechanic entered - Suspension Other rear axle sway bar bush	replaced both bushes	NSW-SUS	1165593
203	03/10/2022	1072032	Mechanic entered - Suspension Other Borth torque rod bushes	replaced Borth torque rod top of the diff	NSW-SUS	1165593
203	03/10/2022	1072558	**EMAILED LISA** Mechanic entered - Body Other rear number pl	replacement plate fitted.	NSW-BSW	1165593
203	03/10/2022	1072644	Mechanic entered - Body Other secure o/r coner bumper bar	secured o/s/r coner bumper bar with new bolt and screw	NSW-BSW	1165593
203	03/10/2022	1072609	STONEGUARD BLACK AEROSOL 500ML		NSW-BSW	1165593
203	03/10/2022	1072645	Mechanic entered - Body Other steam clean bus	steam cleaned bus and brought back into to pit to fill up coolant	NSW-BSW	1165593
203	03/10/2022	1072650	Mechanic entered - Body Rear_Door Operation Faulty sensitive	repaired 30/09/2022	NSW-BSW	1165593
203	03/10/2022	1072609	Mechanic entered - Body Other Rust under front of the chassi	cleaned and painted	NSW-BSW	1165593
203	03/10/2022	1072609	Mechanic entered - Body Other Rust under front of the chassi	sanded rust spots and sealed	NSW-BSW	1165593
203	30/09/2022	1072030	Mechanic entered - Suspension Other Borth side uper controla	replaced O/F uper control bushes tensioned wheel nut borth front with Zube	NSW-SUS	1165593
203	30/09/2022	1072031	Mechanic entered - Suspension Other rear axle sway bar bush		NSW-SUS	1165593
203	30/09/2022	1072032	BOLT RR UPPER TORQUE ROD VOLVO	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G329807 Receiving #:346509 Date :2022-09-30	NSW-SUS	1165593
203	30/09/2022	1072032	NUT 16MM RR LWR TORQUE ROD VOL	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G329807 Receiving #:346509 Date :2022-09-30	NSW-SUS	1165593
203	30/09/2022	1072322	Mechanic entered - Body Passenger Seat Torn back row seat cu	removed the seat and fitted back properly	NSW-BSW	1165593
203	30/09/2022	1072322	Consumables		NSW-BSW	1165593
203	29/09/2022	1072004		PRE ANNUAL SAFETY INSPECTION CHECK completed	PRE RSI	1165593
203	29/09/2022	1072004		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1165593
203	29/09/2022	1072032	TORQUE ROD REAR UPPER VOLVO B12BLE 24426047 70313756		NSW-SUS	1165593
203	29/09/2022	1072032	Mechanic entered - Suspension Other Borth torque rod bushes		NSW-SUS	1165593
203	29/09/2022	1072030	BUSH & SPACER UPPER CONTROL ARM VOLVO B12BLE 85104649		NSW-SUS	1165593
203	29/09/2022	1072031	Mechanic entered - Suspension Other rear axle sway bar bush	C/O	NSW-SUS	1165593
203	29/09/2022	1072031	BUSH RR SWAY BAR 50MM VOLVO B7RSA B12BLE 9959304 9516523		NSW-SUS	1165593
203	29/09/2022	1072032	BOLT 16MM X 60MM RR UPPER TORQUE ROD VOLVO B12BLE		NSW-SUS	1165593

203	29/09/2022	1072032 BOLT RR UPPER TORQUE ROD VOLVO B12BLE		NSW-SUS	1165593
203	29/09/2022	1072030 Mechanic entered - Suspension Other Borth side uper controla	replaced N/F uper controlarm 4 bushes c/o	NSW-SUS	1165593
203	29/09/2022	1072120 Mechanic entered - Body Rear_Door Operation Faulty Rear door	fitted2 bait	NSW-BSW	1165593
203	29/09/2022	1072120 Consumables		NSW-BSW	1165593
203	29/09/2022	1072076 ALTERNATOR 24V 120AMP VOLVO B12BLE 85020826		ALT-REPLACE	1165593
203	29/09/2022	1072076		ALT-REPLACE	1165593
203	29/09/2022	1072076	REPLACE ALTERNATORS re-placed alternators and some wire condutes needs to be changed them and checked. checked by working ok. Complete.	ALT-REPLACE	1165593
203	20/09/2022	1070890 Drv entered - Engine Low Power	Road tested engine boost OK transmission shifting and fluid OK Engine temp. OK. Brake temp. OK checked air Filter OK no warning lights OK.	NSW-ENG	1164343
203	14/09/2022	1069840 Mechanic entered - Elec and Light Exterior Lights front r/h	Removed front drivers blind to replaced t/o/s top indicator globe.	NSW-E&L	1163458
203	14/09/2022	1069840 Consumables		NSW-E&L	1163458
203	13/09/2022	1069628 PTI Tablet Entered -Elec and Light - Exterior Lights Rear L	Replaced led light.	NSW-E&L	1163223
203	13/09/2022	1069628 LAMP LED SIDE RED/AMBER PERE(52-98002)		NSW-E&L	1163223
203	13/09/2022	1069628 Consumables		NSW-E&L	1163223
203	10/09/2022	1068982	VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts with matt. carried out fitting missing disabled priority sticker and knock in 3 seat ba	SAF-INSP	1162795
203	10/09/2022	1068982	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1162795
203	10/09/2022	1069015 Mechanic entered - Body Other rear door behind panel screw h	extracted screw and fit new screw	NSW-BSW	1162795
203	10/09/2022	1069015 Consumables		NSW-BSW	1162795
203	08/09/2022	1068540 BELT V-BELT COGGED TRI-POWER 17x1145mm		NSW-SCA	1162532
203	08/09/2022	1068540 BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230		NSW-SCA	1162532
203	08/09/2022	1068540 Mechanic entered - A/C Heating Noisy Belts missing	Remove belts align and adjust pitch to suit engine run up tested ok	NSW-SCA	1162532
203	08/09/2022	1068378 Fault#:38438 - Ops Entered - Fault - Breakdown Overheating/C	put floor hatch back on	NSW-OPS	1162532
203	08/09/2022	1068378 Fault#:38438 - Ops Entered - Fault - Breakdown Overheating/C	completed road tested and check for pressurize al good.	NSW-OPS	1162532
203	08/09/2022	1068719 Fault#:38437 - Ops Entered - Fault - Breakdown Air System F	OAKLEIGH attend for break down. 6-9-22.	NSW-OPS	1162532
203	07/09/2022	1068378 Fault#:38438 - Ops Entered - Fault - Breakdown Overheating/C	steam cleaned bus drained anf filled up coolant and tighten ac comperssor belts	NSW-OPS	1162532
203	07/09/2022	1068385 Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 843	Attendend breakdown at Endeavour Hills removed floor hatches coolant hose had burst for turbo cooler line replaced rubber hose and topped up bus with water driven back to depot washed	NSW-ENG	1162532
203	01/09/2022	1067095	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection complete.	FIRE-SAFE	1161570
203	23/08/2022	1065086	CARRY OUT FIRE EXTINGUISHER TEST & TAG	FIRE EXT.	1160159
203	23/08/2022	1065086	Completed by ATS	FIRE EXT.	1160159
203	20/08/2022	1064621 Fire extinguisher- reposition baracket	fitted new bracket	NSW-BSW	1159852
203	20/08/2022	1064621 Consumables		NSW-BSW	1159852
203	09/08/2022	1062137 PTI Tablet Entered -test defect tyre 1	Planing team testing new tablet	NSW-W&T	1157981
203	09/08/2022	1062137 PTI Tablet Entered -Wheels and Tyres - Damaged	Asabove	NSW-W&T	1157981
203	09/08/2022	1062137 Consumables		NSW-W&T	1157981
203	04/08/2022	1061144 Ops Entered - Fault - Elec and Light Horn - Route: - Take	checked the horn not working then checked for fuse it was ok then checked if horn having power or not. horn was having power checked the switch looks ok. took out the steering wheel and f	NSW-E&L	1157460
203	04/08/2022	1061144 CAM CANCEL INDICATOR VOLVO B10/B12BLE		NSW-E&L	1157460
203	04/08/2022	1061144 Consumables		NSW-E&L	1157460
203	25/07/2022	1059065 Consumables		NSW-E&L	1155730
203	25/07/2022	1059065 GLOBE 24V 70W H1		NSW-E&L	1155730
203	25/07/2022	1059065 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	checked all thelights working ok except driver side head light opened it and find out lighjt blown up. Re-placed with a new one and checked it working ok. Complete.	NSW-E&L	1155730
203	12/07/2022	1056580 Mechanic entered - Steering Excessive Play N/F Tio rod ball	replaced the rod tensioned all the nut road tested ok	NSW-STE	1153935
203	12/07/2022	1056580 TIE ROD OUTER COMPLETE VOLVO B10 -B12BLE 20497799		NSW-STE	1153935
203	09/07/2022	1056224	assisted	SAF-INSP	1153640
203	09/07/2022	1056224	VEHICLE SAFETY INSPECTION completed	SAF-INSP	1153640
203	09/07/2022	1056224	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Haysun	SAF-INSP	1153640
203	04/07/2022	1055183 Ops Entered - Fault - Elec and Light Flat Batteries - Route	carried out removing pulley by draining coolant and moving coolant pipe carried out fitting new pulley tranfered middle peice over and carried out installing new alternator belt and fit back.	NSW-E&L	1152734
203	04/07/2022	1055183 PULLEY IDLER DH12D VOLVO B12BLE 30N0947		NSW-E&L	1152734
203	04/07/2022	1055183 BELT MICRO V SERPENTINE BELT 8 RIB 1660mm LONG		NSW-E&L	1152734
203	04/07/2022	1055183 Consumables		NSW-E&L	1152734
203	30/06/2022	1054787	Retensioned all wheel nuts.	TYR	1152206
203	30/06/2022	1054787	Assisted	TYR	1152206
203	29/06/2022	1054477 Mechanic entered -Suspension Kneel/ Raise rear air bag 4 l	replaced N/R air bag . Sathees changed O/r air bag tensioned wheel nut with Sathees	NSW-SUS	1152117
203	29/06/2022	1054477 AIRBAG REAR ASSY B12B B12BLE B12 E4 20573108 30Y2218		NSW-SUS	1152117
203	29/06/2022	1054477 Mechanic entered - Suspension Kneel/ Raise rear air bag 4 l	Replaced O/S rear air bags.	NSW-SUS	1152117
203	29/06/2022	1053682 Mechanic entered - Brakes Other Front Axle rotors needs to b	replaced Front rooters pads rooter bolt tensioned wheel nut with Sathees	NSW-BRA	1152117
203	29/06/2022	1053682 Mechanic entered - Brakes Other Front Axle rotors needs to b	Assisted.	NSW-BRA	1152117
203	28/06/2022	1053682 Mechanic entered - Brakes Other Front brake pads worn.	strip the part	NSW-BRA	1152117
203	28/06/2022	1053682 SCREW FT BRAKE DISC MTG VOLVO B10 -B12BLE 30G0002		NSW-BRA	1152117
203	28/06/2022	1053682 BRAKE ROTOR DISC FRT VOLVO B10BLE B12BLE 3112965		NSW-BRA	1152117
203	24/06/2022	1053682 BRAKE PADS FRT VOLVO B10BLE B12BLE 8550611		NSW-BRA	1152117
203	24/06/2022	1053682 Mechanic entered - Brakes Other Front brake pads worn.		NSW-BRA	1152117
203	24/06/2022	1053682 Mechanic entered - Brakes Other Front Axle rotors needs to		NSW-BRA	1152117
203	24/06/2022	1053664	CARRY OUT A SERVICE AS PER CHECK LIST assist satheesh and tensioned all wheel nuts.	A	1152117
203	24/06/2022	1053664	completed as per the check list.	A	1152117
203	24/06/2022	1053664 Consumables		A	1152117
203	24/06/2022	1053664 Consumables		A	1152117
203	24/06/2022	1053664 Consumables		A	1152117
203	24/06/2022	1053664 Consumables		A	1152117
203	24/06/2022	1053664 Consumables		A	1152117
203	16/06/2022	1052276 PTI Tablet Entered -Elec and Light - Exterior Lights front r	Fitted new hi-beam bulb.	NSW-E&L	1150909

203	16/06/2022	1052276	GLOBE HEADLAMP 24V 70W H7 HLCA2470 48728 13972			NSW-E&L	1150909
203	16/06/2022	1052276	Consumables			NSW-E&L	1150909
203	16/06/2022	1050690	THINNER FAST(20 Ltr)			NSW-ACC	1150909
203	08/06/2022	1050690	PAINTSHOP - Accident# 53635 - Prepare and paint N/S top corn	perp maskup and paint	perp maskup and paint	NSW-ACC	1150146
203	06/06/2022	1050264	Accident#53635-Front	fibreglass holefinish with bodyfillerprimer done		NSW-ACC	1150146
203	03/06/2022	1050039	Mechanic entered - Elec and Light Exterior Lights. (indicate	checked the buschecked the Indicator lights working fine. then	Checked the dash and open it find out the globe on dash for Indicator lighth blown up. Re-placed with a new one and checked	NSW-E&L	1150146
203	03/06/2022	1050039	Consumables			NSW-E&L	1150146
203	20/05/2022	1047383	Mechanic entered - Elec and Light Exterior Lights front top	replaced ns top marker light globe		NSW-E&L	1147916
203	20/05/2022	1047383	Consumables			NSW-E&L	1147916
203	12/05/2022	1045858	drivers seat belt not engaging.	Adjusted the belt		NSW-BSW	1146896
203	12/05/2022	1045858	drivers seat belt not engaging.	Assited.		NSW-BSW	1146896
203	11/05/2022	1045484	Consumables			NSW-E&L	1146451
203	11/05/2022	1045484	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	replaced ns head light globe		NSW-E&L	1146451
203	11/05/2022	1045484	GLOBE 24V 70W H1			NSW-E&L	1146451
203	09/05/2022	1045148	SEAL RR HUB OUTER VOLVO B7RLE B12BLE 3199066			NSW-ENG	1146248
203	09/05/2022	1045148	Mechanic entered - Fluid Leaks Rear of bus near side rearax	removed and fitted new drive shaft seal washed rim ok		NSW-ENG	1146248
203	03/05/2022	1043853	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM			CAMPAIGN	1145407
203	02/05/2022	1043648		Tension wheel nuts all rear with Kumar.		TYR	1145316
203	02/05/2022	1043648		Assisted Rene.		TYR	1145316
203	02/05/2022	1043611	Consumables			NSW-E&L	1145316
203	02/05/2022	1043611	Elec and Light replace batteries.	Removed and replace battery fitted two new (N150 CMF). Test ok.		NSW-E&L	1145316
203	02/05/2022	1043611	Elec and Light replace batteries.	Assisting		NSW-E&L	1145316
203	02/05/2022	1043611	BATTERY 1030CCA POS ON RHS EMFN150R			NSW-E&L	1145316
203	29/04/2022	1043217		VEHICLE SAFETY INSPECTION Completed check list.		SAF-INSP	1145149
203	29/04/2022	1043217		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Kumar tension wheel nuts.		SAF-INSP	1145149
203	29/04/2022	1043228	DISC PAD SET RR VOLVO B7RSA B12B 23149531 30G7502BERAL			NSW-BRA	1145149
203	29/04/2022	1043228	Mechanic entered - Brakes Other Rear brake pad worn and brak	Removed and replace rear brake pads and adjusted brakes. Assisted by Kumar to calibrated brakes. Re fit all wheels and tensioned wheel nuts with Kumar. Brake test and roadstested check		NSW-BRA	1145149
203	29/04/2022	1043228	N/S/r brake pad come's off from metal plate.	assisted.		NSW-BRA	1145149
203	28/04/2022	1042806	Ops Entered - Fault - drivers seat not adjusting w/shop adv			NSW-BSW	1144940
203	28/04/2022	1042806	SEAT ASSY ISRI A6008 AIR LUMBAR CHANGE OVER			NSW-BSW	1144940
203	28/04/2022	1042806	Ops Entered - Fault - drivers seat not adjusting w/shop adv	replaced the seat back support moving back not staying on		NSW-BSW	1144940
203	28/04/2022	1042806	Ops Entered - Fault - drivers seat not adjusting w/shop adv	Fitted new seatbelt and buckle.connected Air line and secured.		NSW-BSW	1144940
203	27/04/2022	1042581	Fault#:38330 - Ops Entered - Fault - Breakdown Excessive Smo	Checked found blown coolant hose. Informed supervisor to tow the bus. Removed n/s axle. Replaced coolant hose and top up coolant. Refitted axle and top up diff oil. Steam cleaned and di		NSW-OPS	1144749
203	27/04/2022	1042581	after hours service to tow vol	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G320329 Receiving #:336431 Date :2022-05-04 TOW BUS 203 BANDON PARK TO DANDENONG DEPOT		NSW-OPS	1145837
203	08/04/2022	1039874	Mechanic entered - Gearbox Driveline Rough Gear Change gears	Checked for fault found out transmission oil level low. Top up oil and road test checed operation ok.		NSW-GEA	1142838
203	05/04/2022	1039123	Mechanic entered - Elec and Light Exterior Lights n/s/r mark	Replaced marker light and terminals and tested. Complete.		NSW-E&L	1142008
203	05/04/2022	1039123	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			NSW-E&L	1142008
203	05/04/2022	1039123	Consumables			NSW-E&L	1142008
203	02/04/2022	1038636		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Service complete as per checklist.		CCTV - A	1142008
203	03/03/2022	1031964	SUMP RING 24MM VOLVO B8RLE B12BLE 20579690			C	1137798
203	03/03/2022	1031964	Consumables			C	1137798
203	03/03/2022	1031964	Consumables			C	1137798
203	03/03/2022	1031964	Consumables			C	1137798
203	03/03/2022	1031964	Consumables			C	1137798
203	03/03/2022	1031964	Consumables			C	1137798
203	28/02/2022	1031964	Consumables			C	1137798
203	28/02/2022	1031964	Consumables			C	1137798
203	28/02/2022	1031964	Consumables			C	1137798
203	28/02/2022	1031964	Consumables			C	1137798
203	28/02/2022	1031964	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE TEXAMATIC			C	1137279
203	28/02/2022	1031964	SUMP PLUG WASHER VOLVO B12BLE 30Z1000			C	1137279
203	28/02/2022	1031964	SUMP RING 24MM VOLVO B8RLE B12BLE 20579690			C	1137279
203	25/02/2022	1032005	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	completed		CAMPAIGN	1137139
203	25/02/2022	1031964		CARRY OUT C SERVICE AS PER CHECK LIST C service completed and tensoned all wheel nuts w/ Jess.		C	1137139
203	25/02/2022	1031964	OIL ENGINE MOBIL DELVAC MODERN 15W-40 (MIN)			C	1137139
203	25/02/2022	1031964	FILTER OIL FILTER VOLVO B12BLE 478736			C	1137139
203	25/02/2022	1031964	FILTER FUEL FILTER VOLVO B12BLE 20430751			C	1137139
203	25/02/2022	1031964	FILTER FUEL / CHASSIS VOLVO B12BLE 20514654 20998637			C	1137139
203	25/02/2022	1031964	FILTER HYDRAULIC FILTER VOLVO B8RLEA E6 20801559			C	1137139
203	25/02/2022	1031964	FILTER AIR DRYER SCANIA VOLVO(20546795)(20424148)			C	1137139
203	25/02/2022	1031964	FILTER AIR OUTER VOLVO B10M4 B12 B12BLE(1544449)			C	1137139
203	25/02/2022	1031964	VALVE DRAIN CONDENSOR MERC O500LE(A0054327401)			C	1137139
203	25/02/2022	1031964	FILTER OIL FILTER BY-PASS VOLVO B12 (EARLY)			C	1137139
203	25/02/2022	1031964	Service	assisted.		C	1137139
203	25/02/2022	1031964		CARRY OUT B SERVICE AS PER CHECK LIST B service completed		B	1137139
203	25/02/2022	1031964	Consumables			B	1137139
203	25/02/2022	1031964	Consumables			B	1137139
203	25/02/2022	1031964	Consumables			B	1137139
203	25/02/2022	1031964	Service	CARRY OUT A SERVICE AS PER CHECK LIST A service completed		A	1137139
203	25/02/2022	1031964	Consumables			A	1137139

203	25/02/2022	1031964	Consumables			A	1137139
203	25/02/2022	1031964	Consumables			A	1137139
203	22/02/2022	1030753	Mechanic entered - Wheels and Tyres Damaged front left hand	Replaced wheel arc.		NSW-W&T	1136566
203	22/02/2022	1030753	WHEEL ARCH BRUSH 12065			NSW-W&T	1136566
203	22/02/2022	1030753	RUBBER WHEEL ARCH 41294			NSW-W&T	1136566
203	22/02/2022	1030753	Consumables			NSW-W&T	1136566
203	21/02/2022	1030271		CARRY OUT FIRE EXTINGUISHER TEST & TAG		FIRE EXT	1136401
203	21/02/2022	1030271		Completed by ATS		FIRE EXT	1136401
203	17/02/2022	1029482		VEHICLE SAFETY INSPECTION completed		SAF-INSP	1135890
203	17/02/2022	1029482		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Tayla		SAF-INSP	1135890
203	17/02/2022	1029482		Safety completed as per checklist. Wheel tension with Sisil		SAF-INSP	1135890
203	17/02/2022	1029530	Mechanic entered - Steering Steering Wheel Faulty not straigh	Straighted		NSW-STE	1135890
203	17/02/2022	1029586	Mechanic entered - Steering Other Steering wheel not straight	Removed steering wheel. fitted back straight		NSW-STE	1135890
203	17/02/2022	1029589	Mechanic entered - Engine Other Steqam clean engine	Steam cleaned engine		NSW-ENG	1135890
203	17/02/2022	1029555	Mechanic entered - Elec and Light Other some dash globe out	replaced 4 globes		NSW-E&L	1135890
203	17/02/2022	1029584	Mechanic entered - Elec and Light Other Dash switches not li	Fitted new globes. Tested okay		NSW-E&L	1135890
203	17/02/2022	1029587	Mechanic entered - Elec and Light Other 3 saloon lights u/s	Fitted new tube globes Tested okay		NSW-E&L	1135890
203	17/02/2022	1029584	Consumables			NSW-E&L	1135890
203	17/02/2022	1029587	Consumables			NSW-E&L	1135890
203	17/02/2022	1029555	Consumables			NSW-E&L	1135890
203	17/02/2022	1029581	Mechanic entered - Body Other Rust underneath front of bus.	Buffed back rusted area. Sprayed stone guard over the buffed area		NSW-BSW	1135890
203	17/02/2022	1029585	Mechanic entered - Body Other Vinyl near handbrake is torn	Removed old vinyl that was peeling back. Used vinyl tape to cover the damaged vinyl		NSW-BSW	1135890
203	17/02/2022	1029528	Mechanic entered - Body Other n/s/f wheel arch rubber and br	Fitted new wheel arch rubber and brush		NSW-BSW	1135890
203	17/02/2022	1029528	WHEEL ARCH BRUSH 12065			NSW-BSW	1135890
203	17/02/2022	1029528	RUBBER WHEEL ARCH 41294			NSW-BSW	1135890
203	17/02/2022	1029588	Mechanic entered - Body Other Steering wheel horn not workin	Relised that the indicator canceller wasn't sitting properly. Causing the horn contacts not to make contact. refitted indicator canceller and horn is making contact and works		NSW-BSW	1135890
203	04/02/2022	1026819	Indicator stalk broken	Fitted new Indicator lever.		NSW-E&L	1134157
203	04/02/2022	1026819	SWITCH INDICATOR / CRUISE VOLVO B12BLE 3172171			NSW-E&L	1134157
203	04/02/2022	1026819	Consumables			NSW-E&L	1134157
203	06/01/2022	1021104		Assisting - defect entered twice.		TYR	1129230
203	06/01/2022	1021104		defect entered twice.		TYR	1129230
203	06/01/2022	1021315		Retensioned all rear wheel nuts with Kuma.		TYR	1129230
203	05/01/2022	1020986	TYRE 295/80R22.5 RECAP			NSW-W&T	1129230
203	05/01/2022	1020986	Ops Entered - Wheels and Tyres - Flat or Leaking	carried out removing flat tyre position 3 and carried out inspecting all others and all rear on wear bar carried out removing and replacing all rear and tensioned all wheel nuts with haysun		NSW-W&T	1129230
203	05/01/2022	1020986	Consumables			NSW-W&T	1129230
203	04/01/2022	1020691	Air System - Air System leak	Air leaking from overflow valve and 4 way valve. replaced.		NSW-AIR	1129138
203	04/01/2022	1020691	VALVE CIRCUIT PROTECTION VOLVO B7RLE AE4604 3197588			NSW-AIR	1129138
203	04/01/2022	1020691	VALVE OVERFLOW 7.0BAR VOLVO B10BLE 49G1207 0481063041			NSW-AIR	1129138
203	03/01/2022	1020601	Mechanic entered - Body - Front Door Operation Faulty trip h	Secured door wheel chair ramp.		NSW-BSW	1129138
203	23/12/2021	1019492	FILTER DRYER AIR COND THERMO KING			AC-B	1128009
203	23/12/2021	1019492	COMPRESSOR OIL AIR CON			AC-B	1128009
203	23/12/2021	1019492		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		AC-B	1128009
203	23/12/2021	1019492		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list		AC-A	1128009
203	21/12/2021	1017228	DIRECT PURCHASE ACCIDENT #5278	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G312640 Receiving #:328698 Date :2021-12-24		NSW-ACC	1128411
203	17/12/2021	1018639	Mechanic entered - Body - Rear Door Operation Faulty	Adjusted safety edge.		NSW-BSW	1127730
203	17/12/2021	1018639	Consumables			NSW-BSW	1127730
203	17/12/2021	1017227	Accident #52788 - Panel scratch left side near rear wheels	East coast completed repair		NSW-ACC	1127730
203	17/12/2021	1017228	Accident #52788 - Paint Damage from rear door to back. Refl	East coast completed repair		NSW-ACC	1127730
203	10/12/2021	1017227	Accident #52788 - Panel scratch left side near rear wheels	Bus at east coast		NSW-ACC	1127730
203	10/12/2021	1017228	Accident #52788 - Paint Damage from rear door to back. Refl	Bus send to east coast		NSW-ACC	1127730
203	07/12/2021	1016397		VEHICLE SAFETY INSPECTION		SAF-INSP	1127180
203	07/12/2021	1016397		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1127180
203	07/12/2021	1016397		Assisting completed safety inspection as per checklist with nevan		SAF-INSP	1127180
203	07/12/2021	1016397	WHEEL ARCH BRUSH 12065			SAF-INSP	1127180
203	07/12/2021	1016397	RUBBER WHEEL ARCH 41294			SAF-INSP	1127180
203	07/12/2021	1016453	Mechanic entered - Body Rear_Door Operation Faulty	Adjusted		NSW-BSW	1127180
203	07/12/2021	1016453	Consumables			NSW-BSW	1127180
203	01/12/2021	1015289	Mechanic entered - Elec and Light Exterior Lights front top	r/r the globe		NSW-E&L	1126043
203	01/12/2021	1015289	Consumables			NSW-E&L	1126043
203	01/12/2021	1015109	O RING INTERCOOLER VOLVO B7RLE B12BLE 1675066			CAMPAIGN	1126043
203	01/12/2021	1015109	BELT TENSIONER VOLVO B12BLE B13R 3979979 21549016 20924200			CAMPAIGN	1126043
203	01/12/2021	1015109	CAP EXP TANK SMALL VOLVO B12BLE 3979593			CAMPAIGN	1126043
203	01/12/2021	1015109	BOLT FAN DRIVE CLUTCH			CAMPAIGN	1126043
203	01/12/2021	1015109	NUT FLANGED 10MM			CAMPAIGN	1126043
203	01/12/2021	1015109	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENAN	completed and replaced new belt tesioner as worn..		CAMPAIGN	1126043
203	01/12/2021	1015109	REFLECTOR AMBER HELLA 94x44mm			CAMPAIGN	1126043
203	06/11/2021	1009796		PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST		AIR-CHECK	1121814
203	05/11/2021	1009761	Mechanic entered - Elec and Light - Exterior Lights rear sid	Replaced r/n/s side marker and secured r/n/s wheel arc.		NSW-E&L	1121814

203	05/11/2021	1009761 LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		NSW-E&L	1121814
203	05/11/2021	1009761 Consumables		NSW-E&L	1121814
203	03/11/2021	1008820 Engine - Check all coolant hoses and replace if required	Road tested & steam cleaned	NSW-ENG	1121450
203	01/11/2021	1008820 HOSE G/BOX OIL COOLER VOLVO B12BLE 21461839 9956030		NSW-ENG	1121450
203	01/11/2021	1008820 HOSE COOLING / OIL COOLER VOLVO B12BLE 21461830 9517020		NSW-ENG	1121450
203	01/11/2021	1008820 Engine - Check all coolant hoses and replace if required	replaced 1 radeator hose & 2 Trannision coolent hose c/o	NSW-ENG	1121450
203	28/10/2021	1008335	CARRY OUT A SERVICE AS PER CHECK LIST Completed A service and tensioned wheel nuts w/ Haysun.	A	1121064
203	28/10/2021	1008335 Consumables		A	1121064
203	28/10/2021	1008335 Consumables		A	1121064
203	28/10/2021	1008335 Consumables		A	1121064
203	28/10/2021	1008335 Consumables		A	1121064
203	14/10/2021	1004929 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G308694 Receiving #:323751 Date :2021-10-15	RSI	1119105
203	12/10/2021	1004929	VEHICLE SAFETY INSPECTION	SAF-INSP	1118484
203	12/10/2021	1004929	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1118484
203	12/10/2021	1004929	ANNUAL SAFETY INSPECTION - RWC 038922 - PASSED - 12/10/2021 - WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO C	RSI	1118484
203	12/10/2021	1004929	Assisting	RSI	1118484
203	11/10/2021	1004868	Re-tensioned wheel nuts w/Kuma pos.12.	TYR	1118327
203	11/10/2021	1004699 Mechanic entered - Body - LH outer wheelchair decal is faded	replaced decal	NSW-BSW	1118327
203	11/10/2021	1004699 DECAL WHEELCHAIR ACCESS RAMP LOAD RATED 300kg		NSW-BSW	1118327
203	11/10/2021	1004684 Carry out final inspection for RSI	completed.	NSW-BSW	1118327
203	11/10/2021	1004684 Carry out final inspection for RSI	completed	NSW-BSW	1118327
203	11/10/2021	1004684 Consumables		NSW-BSW	1118327
203	11/10/2021	1004699 Consumables		NSW-BSW	1118327
203	08/10/2021	1004489 Mechanic entered - Wheels and Tyres Worn Tyre #2 worn out.	Assisted Sathesh. w/o #1004488	NSW-W&T	1118079
203	08/10/2021	1004488 Mechanic entered - Wheels and Tyres Worn tyre 1	Replaced with New tyres @ position 1 & 2 .position 2 B2R. Tesioned Wheel to OEM with Abraham.	NSW-W&T	1118079
203	08/10/2021	1004488 TYRE 295/80R22.5 NEW		NSW-W&T	1118079
203	08/10/2021	1004488 TYRE 295/80R22.5 NEW		NSW-W&T	1118079
203	08/10/2021	1004488 Consumables		NSW-W&T	1118079
203	08/10/2021	1004489 Consumables		NSW-W&T	1118079
203	27/09/2021	1001764	PRE ANNUAL SAFETY INSPECTION CHECK completed.	PRE RSI	1116084
203	27/09/2021	1001764	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1116084
203	27/09/2021	1001764	completed checkliat	PRE RSI	1116084
203	27/09/2021	1001875 Mechanic entered - Engine - Coolant leak from hose behin	tightened hose clamp	NSW-ENG	1116084
203	27/09/2021	1001869 Mechanic entered - Engine - Coolant leak from trans cool	tightened hose clamps	NSW-ENG	1116084
203	27/09/2021	1001875 Mechanic entered - Engine - Coolant leak from hose behin	secured hoses and clips.	NSW-ENG	1116084
203	27/09/2021	1001864 Consumables		NSW-E&L	1116084
203	27/09/2021	1001855 Consumables		NSW-E&L	1116084
203	27/09/2021	1001855 BELL PUSH FOR WHEEL CHAIR PASS ( 40792 )		NSW-E&L	1116084
203	27/09/2021	1001855 Mechanic entered - Elec and Light - RH passanger buzzer bro	fitted new buzzer.	NSW-E&L	1116084
203	27/09/2021	1001855 Mechanic entered - Elec and Light - RH passanger buzzer bro	replaced	NSW-E&L	1116084
203	27/09/2021	1001864 Mechanic entered - Elec and Light - LH saloon light defuser	fitted new defuser.	NSW-E&L	1116084
203	27/09/2021	1001864 DIFFUSER INTERIOR LIGHT (price per metre)		NSW-E&L	1116084
203	27/09/2021	1001870 Consumables		NSW-BSW	1116084
203	27/09/2021	1001872 Consumables		NSW-BSW	1116084
203	27/09/2021	1001865 Consumables		NSW-BSW	1116084
203	27/09/2021	1001867 Consumables		NSW-BSW	1116084
203	27/09/2021	1001868 Consumables		NSW-BSW	1116084
203	27/09/2021	1001873 Consumables		NSW-BSW	1116084
203	27/09/2021	1001874 Consumables		NSW-BSW	1116084
203	27/09/2021	1001870 Mechanic entered - Body - Rear door decal torn.	fitted new decal	NSW-BSW	1116084
203	27/09/2021	1001870 DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		NSW-BSW	1116084
203	27/09/2021	1001865 Mechanic entered - Body - RHR seat grab handle damaged	replaced grab handle	NSW-BSW	1116084
203	27/09/2021	1001865 PASS SEAT HANDGRIP CENTRA MK 2		NSW-BSW	1116084
203	27/09/2021	1001873 Mechanic entered - Body - Fit new outer l/h emergency decal.	fitted new decal	NSW-BSW	1116084
203	27/09/2021	1001873 DECAL EMERGENCY EXIT ROCK BLACK / SILVER 600 x 80MM		NSW-BSW	1116084
203	27/09/2021	1001872 Mechanic entered - Body - Roof grab handle scres missing.	replaced screws	NSW-BSW	1116084
203	27/09/2021	1001868 Mechanic entered - Body - Drivers blind clip missing.	fitted new clip	NSW-BSW	1116084
203	27/09/2021	1001868 Mechanic entered - Body - Drivers blind clip missing.	new clip fitted.	NSW-BSW	1116084
203	27/09/2021	1001874 Mechanic entered - Body - LHR wheel panel screw missin	replaced screw	NSW-BSW	1116084
203	27/09/2021	1001874 Mechanic entered - Body - LHR wheel panel screw missin	fitted new bolt and secured.	NSW-BSW	1116084
203	27/09/2021	1001867 Mechanic entered - Body - LH seat cushions damaged x2.	replaced both seat cushions	NSW-BSW	1116084
203	27/09/2021	1001867 SEAT CUSH SINGLE CEN CVR RA		NSW-BSW	1116084
203	27/09/2021	1001867 Mechanic entered - Body - LH seat cushions damaged x2.	new cushions fitted.	NSW-BSW	1116084
203	27/09/2021	1001871 Mechanic entered - Brakes - RHF mud flap missing.	new mud flap fitted.	NSW-BRA	1116084
203	27/09/2021	1001871 MUDFLAP 605MM X330MM		NSW-BRA	1116084
203	27/09/2021	1001871 Mechanic entered - Brakes - RHF mud flap missing.	replaced mud flap	NSW-BRA	1116084
203	16/09/2021	999729 REPLACE ANTI GRAFFITI CLEAR FI	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G307079 Receiving #:321828 Date :2021-09-20 REPLACE SDL & SDR	NSW-VAN	1115023
203	15/09/2021	999729 Vandalism - Replace Anti Graffiti Clear Film - SDL SDR	REPLACED BY GLASSPROTECH	NSW-VAN	1114213

203	09/09/2021	998601 Consumables			NSW-E&L	1113418
203	09/09/2021	998601 Mechanic entered - Elec and Light Exterior Lights front o/s	r/r the globe		NSW-E&L	1113418
203	09/09/2021	998601 GLOBE 24V 70W H1			NSW-E&L	1113418
203	04/09/2021	997237	VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts with sist carried out following repairs. 2 led dash globes 1 panel screw and tighten r		SAF-INSP	1112651
203	04/09/2021	997237	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1112651
203	02/09/2021	996544	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection complete.		FIRE-SAFE	1112256
203	02/09/2021	996544	Fire safety inspection complete.		FIRE-SAFE	1112256
203	02/09/2021	996544	fixed.		FIRE-SAFE	1112256
203	01/09/2021	996332 PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.		CAMPAIGN	1112256
203	01/09/2021	996332 PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.		CAMPAIGN	1112256
203	31/08/2021	996168 Mechanic entered - Elec and Light Exterior Lights front top	r/r the globe		NSW-E&L	1112035
203	31/08/2021	996168 Consumables			NSW-E&L	1112035
203	25/08/2021	994749	Done wth Abraham.		TYR	1111215
203	25/08/2021	994749	Assisted Rene.		TYR	1111215
203	24/08/2021	994050 key not working	Ensure RPD was not stopping the bus from switching off by resetting it. Removd ignition switch(electrical pert) and plug old switch into bus - Bus switching off correctly. Closer inspection si		NSW-E&L	1111074
203	24/08/2021	994050 Consumables			NSW-E&L	1111074
203	23/08/2021	994050 key not working			NSW-E&L	1111074
203	23/08/2021	994050 SWITCH STARTER VOLVO B7RLE B12BLE 30M2403			NSW-E&L	1111074
203	23/08/2021	994050 key not working	replaced ignition switch bus staying on with park brake on and key removed will check relay tomorrow		NSW-E&L	1111074
203	23/08/2021	993923 Mechanic entered - Brakes Other front brake pads worn	replaced front brake pads tesioned all wheelnuts		NSW-BRA	1111074
203	23/08/2021	993923 Mechanic entered - Brakes Other front brake pads worn	fitted new front brake pads.		NSW-BRA	1111074
203	23/08/2021	993923 BRAKE PADS FRT VOLVO B10BLE B12BLE 8550611			NSW-BRA	1111074
203	23/08/2021	994049 Mechanic entered - Brakes Other rear brake pads low	fitted new rear brake pads calibrated road tested ok.		NSW-BRA	1111074
203	23/08/2021	994049 Mechanic entered - Brakes Other rear brake pads low	replaced rear pads torqued bolt to 40mm tensioned all wheelnuts		NSW-BRA	1111074
203	23/08/2021	994049 BRAKE PADS RR VOLVO B7RSA B12BLE 20918891			NSW-BRA	1111074
203	17/08/2021	990441 CALIBRATE NEW DASH CULSTER	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G304759 Receiving #:319408 Date :2021-08-18		NSW-E&L	1110459
203	17/08/2021	990441 Consumables			NSW-E&L	1110459
203	13/08/2021	990441 Mechanic entered - Dash - Odometer Not Working Odometer num	CMV re calibrate instrument cluster		NSW-E&L	1109168
203	13/08/2021	990441 Mechanic entered - Dash - Odometer Not Working Odometer numb	Removed dash from bus and disassemble cluster replace odo/ speedo with new unit. Assemble and re-install for CMV to re-programme. Complete.		NSW-E&L	1109168
203	12/08/2021	991729 Mechanic entered - Air System Air Not Building_Up	Cleaned air dryer and replaced air dryer unloader valve and filter. Checked ok.		NSW-AIR	1109080
203	12/08/2021	991729 FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)			NSW-AIR	1109080
203	12/08/2021	991729 VOLVO UNLOADER VALVE HALDEX 12bar			NSW-AIR	1109080
203	10/08/2021	990441 SPEEDOMETER VOLVO B12BLE	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G304363 Receiving #:318903 Date :2021-08-10		NSW-E&L	1108880
203	06/08/2021	990441 Mechanic entered - Dash - Odometer Not Working Odometer num	Parts order and send email to Lee on 6/08/2021		NSW-E&L	1108036
203	03/08/2021	991969 Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		FIRE EXT	1107676
203	02/08/2021	989357 Mechanic entered - Elec and Light - Exterior Lights n/s rear	Replaced with new Lights.		NSW-E&L	1107222
203	02/08/2021	989357 LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			NSW-E&L	1107222
203	02/08/2021	989357 Consumables			NSW-E&L	1107222
203	30/07/2021	989013 Mechanic entered - Dash - Odometer Not Working unable to rea	Checked odometer and working fine. Take photo and send to refuellers and Michell and ask getthe photo and send to me.		NSW-E&L	1106990
203	30/07/2021	989013 Consumables			NSW-E&L	1106990
203	26/07/2021	987986 Drv entered - Elec and Light Exterior Lights	r/r park light globe		NSW-E&L	1106222
203	26/07/2021	987986 Consumables			NSW-E&L	1106222
203	22/07/2021	984372 DIRECT PURCHASE ACCIDENT #5227	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G302442 Receiving #:317954 Date :2021-07-29		NSW-ACC	1106990
203	22/07/2021	987378	CARRY OUT A SERVICE AS PER CHECK LIST Completed		A	1105903
203	22/07/2021	987378 Consumables			A	1105903
203	22/07/2021	987378 Consumables			A	1105903
203	22/07/2021	987378 Consumables			A	1105903
203	19/07/2021	986582 Mechanic entered - Elec and Light Exterior Lights front top	REplaced bulb and secured wire n/s top front parklight.		NSW-E&L	1105177
203	19/07/2021	986582 Consumables			NSW-E&L	1105177
203	15/07/2021	985055 HOSE G/BOX OIL COOLER VOLVO B12BLE 21461839 9956030			NSW-ENG	1104793
203	13/07/2021	985056 Mechanic entered - Suspension - Rear swaybar bushes worn	fitted new bushes.		NSW-SUS	1104323
203	13/07/2021	985056 BUSH RR SWAY BAR 50MM VOLVO B7RSA B12BLE 9959304 9516523			NSW-SUS	1104323
203	13/07/2021	985055 Mechanic entered - Engine - Both transmission hoses need cha	fitted new hoses topped up coolant. road tested ok.		NSW-ENG	1104323
203	12/07/2021	985039 Mechanic entered - Suspension - Draglink balljoint rubber br	fitted new draglink with alan		NSW-SUS	1104323
203	12/07/2021	985039 Mechanic entered - Suspension - Draglink balljoint rubber br	fitted new drag link.		NSW-SUS	1104323
203	12/07/2021	985039 DRAGLINK ASSY VOLVO B12BLE 20497800 (21271 01)			NSW-SUS	1104323
203	12/07/2021	985054 Mechanic entered - Elec and Light - Rear stop/start switchbo	fitted new switch.		NSW-E&L	1104323
203	12/07/2021	985054 SWITCH ISOLATER ENGINE START RR VOLVO B12BLE			NSW-E&L	1104323
203	12/07/2021	985054 Consumables			NSW-E&L	1104323
203	12/07/2021	985053 REFLECTOR AMBER HELLA 94x44mm			NSW-BSW	1104323
203	12/07/2021	985053 Mechanic entered - Body - NSF side reflector missing	fitted new reflector ok		NSW-BSW	1104323
203	12/07/2021	985057 Mechanic entered - Body - Yellow strip at rear door missing	replaced stripping		NSW-BSW	1104323
203	12/07/2021	985057 EDGE STEP EDGE INSERT YELLOW 40MM P/M 2B10378SER			NSW-BSW	1104323
203	12/07/2021	985067 Mechanic entered - Body - Rear door sensitive edge not worki	adjusted rear door switches.		NSW-BSW	1104323
203	12/07/2021	985053 Consumables			NSW-BSW	1104323
203	12/07/2021	985057 Consumables			NSW-BSW	1104323
203	12/07/2021	985067 Consumables			NSW-BSW	1104323
203	12/07/2021	984372 Accident # 52270 Damage to Corner at Rear at L/H/S	Completed by east coast		NSW-ACC	1104323

203	08/07/2021	984449	Completed	SAF-INSP	1104323
203	08/07/2021	984449	VEHICLE SAFETY INSPECTION Wheels tensioned to OEM spec with Sisil	SAF-INSP	1104323
203	08/07/2021	984449	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Safety completed Faults entered to tims	SAF-INSP	1104323
203	08/07/2021	984388	Fault#:37953 - Ops Entered - Breakdown - Not Starting	NSW-OPS	1104323
203	08/07/2021	984372	Accident # 52270 Damage to Corner at Rear on L/H/S	NSW-ACC	1104323
203	22/06/2021	981428	Air System - Air Not Building Up	NSW-AIR	1101700
203	22/06/2021	981428	Air System - Air Not Building Up	NSW-AIR	1101700
203	22/06/2021	981428	SUPPLY REAR BRAKE HOSE	NSW-AIR	1101720
203	21/06/2021	981099	Ops Entered - Suspension - Kneel/ Raise	NSW-SUS	1101606
203	21/06/2021	981099	Ops Entered - Fault - Suspension Kneel/ Raise - Route: 843	NSW-SUS	1101606
203	21/06/2021	981099	VALVE FT AXLE LVL CNTRL VOLV	NSW-SUS	1101606
203	21/06/2021	981254	Mechanic entered - Elec and Light Exterior Lights n/s headli	NSW-E&L	1101606
203	21/06/2021	981254	GLOBE 24V 70W H1	NSW-E&L	1101606
203	21/06/2021	981254	Consumables	NSW-E&L	1101606
203	16/06/2021	980142	bottom front right indicator	NSW-E&L	1100749
203	16/06/2021	980142	Consumables	NSW-E&L	1100749
203	11/06/2021	979572	Ops Entered - Fault - Elec and Light Interior Lights - Rout	NSW-E&L	1100336
203	11/06/2021	979572	Consumables	NSW-E&L	1100336
203	10/06/2021	979541	Mechanic entered - Elec and Light Exterior Lights Front R/H	NSW-E&L	1100336
203	10/06/2021	979541	Consumables	NSW-E&L	1100336
203	17/05/2021	973255	Fault#:37878 - Ops Entered - Fault - Breakdown Warning Light	NSW-OPS	1096104
203	17/05/2021	973255	BELT V-BELT COGGED TRI-POWER 17x1145mm	NSW-OPS	1096104
203	17/05/2021	973255	BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230	NSW-OPS	1096104
203	13/05/2021	973449	Mechanic entered - Suspension - Leaning O/s front air bag le	NSW-SUS	1096006
203	13/05/2021	973449	PISTON FRT AIRBAG VOLVO B10 - B12BLE 20535874 3118441	NSW-SUS	1096006
203	13/05/2021	973449	BUMPER HOLLOW SPRING 1134566	NSW-SUS	1096006
203	13/05/2021	973522	Mechanic entered - Fluid Leaks - Rear of bus Engine oil leak	NSW-ENG	1096006
203	11/05/2021	973449	AIRBAG AIR SPRING BELLOWS VOLVO B12BLE	NSW-SUS	1096006
203	11/05/2021	973449	Mechanic entered - Suspension - Leaning O/s front air bag le	NSW-SUS	1096006
203	11/05/2021	973522	PLUG INJECTOR LOOM DH12D VOLVO B12BLE	NSW-ENG	1096006
203	11/05/2021	973522	SEAL CABLE TERMINAL INJ LOOM DH12D VOLVO B12BLE	NSW-ENG	1096006
203	11/05/2021	973522	TERMINAL INJ LOOM DH12D VOLVO B12BLE	NSW-ENG	1096006
203	11/05/2021	973522	GASKET KIT ROCKER CVR DH12D VOLVO B12BLE 20710235	NSW-ENG	1096006
203	11/05/2021	973522	SEAL ROCKER CVR BOLT VOLVO B12BLE 3964604	NSW-ENG	1096006
203	11/05/2021	973522	Mechanic entered - Fluid Leaks - Rear of bus Engine oil leak	NSW-ENG	1096006
203	11/05/2021	973522	ADAPTOR ELBOW WIRING HARN	NSW-ENG	1096006
203	11/05/2021	973522	GROMMET	NSW-ENG	1096006
203	11/05/2021	973522	CAP NUT	NSW-ENG	1096006
203	11/05/2021	973522	CONN PLUG WIRE LOOM INJ HAR VOLVO B12BLE	NSW-ENG	1096006
203	11/05/2021	973522	SEAL O-RING TACHO SENDER+ VOLVO B12BLE CYL HEAD PLUG	NSW-ENG	1096006
203	11/05/2021	973522	ELBOW UNION	NSW-ENG	1096006
203	11/05/2021	973522	SLEEVE	NSW-ENG	1096006
203	11/05/2021	973522	NUT C/W TERMINAL VOLVO B12BLE	NSW-ENG	1096006
203	10/05/2021	973255	Fault#:37878 - Ops Entered - Fault - Breakdown Warning Ligh	NSW-OPS	1096006
203	10/05/2021	973255	BEARING A/C IDLER PULLEY A/C FAN CLUTCH 57J0701 6306NSE	NSW-OPS	1096006
203	10/05/2021	973255	Fault#:37878 - Ops Entered - Fault - Breakdown Warning Light	NSW-OPS	1096006
203	10/05/2021	973255	SPINDLE SHAFT ASSY AC IDLER P	NSW-OPS	1096006
203	05/05/2021	972435	VEHICLE SAFETY INSPECTION Completed with Satheesh.	SAF-INSP	1095295
203	05/05/2021	972435	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Satheesh	SAF-INSP	1095295
203	05/05/2021	972435	Assisted Rene.	SAF-INSP	1095295
203	05/05/2021	972435	INVERTER 24V 15-36W (KIRG)	SAF-INSP	1095295
203	05/05/2021	972476	Mechanic entered - Elec and Light - Interior Lights Saloon l	NSW-E&L	1095295
203	05/05/2021	972476	Consumables	NSW-E&L	1095295
203	05/05/2021	972466	Mechanic entered - Body - Rear Door Operation Faulty Door no	NSW-BSW	1095295
203	05/05/2021	972466	DOOR PIVOT PIN KIT	NSW-BSW	1095295
203	28/04/2021	971048	A/C Heating - Not Cooling - Blowing hot air	NSW-SCA	1094358
203	28/04/2021	971048	A/C Heating - Blowing hot air	NSW-SCA	1094358
203	28/04/2021	971134	Mechanic entered - Engine - Belts Loose Noisy Missing a/c pu	NSW-ENG	1094358
203	28/04/2021	971134	BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230	NSW-ENG	1094358
203	28/04/2021	971134	BELT V-BELT COGGED TRI-POWER 17x1145mm	NSW-ENG	1094358
203	27/04/2021	970850	Mechanic entered - Elec and Light - Exterior Lights rear top	NSW-E&L	1094172
203	27/04/2021	970850	LAMP STOP/TAIL LED HELLA	NSW-E&L	1094172
203	27/04/2021	970850	Consumables	NSW-E&L	1094172
203	15/04/2021	968397	Mechanic entered - Elec and Light - Exterior Lights front o/	NSW-E&L	1092199
203	15/04/2021	968397	Consumables	NSW-E&L	1092199
203	12/04/2021	967451	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete.	CCTV - A	1091487
203	09/04/2021	966977	CARRY OUT B SERVICE AS PER CHECK LIST carried out a and b service as per check list and tensioned all wheel nuts with indika androad tested to ensure no leaks and oil level all good.	B	1091197
203	09/04/2021	966977	FILTER OIL FILTER BY-PASS VOLVO B12 (EARLY)	B	1091197



203	04/12/2020	939537	Assisted.	TYR	1074324
203	04/12/2020	939537	Retensioned all rear wheel nuts with Nick.	TYR	1074324
203	03/12/2020	939264	Drv entered - Warning Lights Brakes	NSW-BRA	1074079
203	03/12/2020	939264	TYRE 295/80R22.5 RECAP	NSW-BRA	1074079
203	03/12/2020	939264	Drv entered - Warning Lights Brakes	NSW-BRA	1074079
203	03/12/2020	939264	BRAKE PADS VOLVO B7R (20918891 23149531) [LATE MODELS]	NSW-BRA	1074079
203	27/11/2020	937441	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECAL	CAMPAIGN	1073018
203	19/11/2020	934806	completed.	AIR-CHECK	1071813
203	16/11/2020	933576	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	CAMPAIGN	1071165
203	12/11/2020	932935	Remove old poster and fit you must wear a face mask when t	CAMPAIGN	1070976
203	30/10/2020	929990	Fit new Myki Decals & refit COVID-19 decals new position fo	CAMPAIGN	1068845
203	30/10/2020	929990	Fit new Myki Decals & refit COVID-19 decals new position fo	CAMPAIGN	1068845
203	26/10/2020	928657	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	CAMPAIGN	1068019
203	15/10/2020	925820	DIRECT PURCHASE - BUS INSPECTI	RSI	1068845
203	14/10/2020	926356	Ops Entered - Fault - Body Rear_Door Operation Faulty - Rou	NSW-BSW	1066534
203	14/10/2020	926356	Consumables	NSW-BSW	1066714
203	13/10/2020	925820	VEHICLE SAFETY INSPECTION	SAF-INSP	1066534
203	13/10/2020	925820	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1066534
203	13/10/2020	925820	ANNUAL SAFETY INSPECTION - RWC 023317 - PASSED - 13/10/2020 -WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.2	RSJ	1066534
203	13/10/2020	925820	Assisting	RSI	1066534
203	13/10/2020	925890	Mechanic entered - Elec and Light - Interior Lights severat	NSW-E&L	1066534
203	13/10/2020	925890	Consumables	NSW-E&L	1066534
203	12/10/2020	925557	Mechanic entered - Elec and Light Exterior Lights	NSW-E&L	1066534
203	12/10/2020	925557	GLOBE 24V 70W H1	NSW-E&L	1066534
203	12/10/2020	925557	VENT JOLLY ROGER VENT	NSW-E&L	1066534
203	12/10/2020	925557	Consumables	NSW-E&L	1066534
203	12/10/2020	925606	Vehicle Mechanical Audit	NSW-BSW	1066534
203	12/10/2020	925606	Vehicle Mechanical Audit	NSW-BSW	1066534
203	12/10/2020	925606	Vehicle Mechanical Audit	NSW-BSW	1066534
203	12/10/2020	925606	Vehicle Mechanical Audit	NSW-BSW	1066534
203	12/10/2020	925606	Consumables	NSW-BSW	1066534
203	09/10/2020	925373	LAMP LED SIDE LAMP RED/AMBER PERE (52-98002)	NSW-E&L	1066280
203	09/10/2020	925373	Mechanic entered - Elec and Light Exterior Lights Side clear	NSW-E&L	1066280
203	09/10/2020	925373	Consumables	NSW-E&L	1066534
203	09/10/2020	925365	Body Water Leaks Windows carry out finaln check for RSI	NSW-BSW	1066280
203	09/10/2020	925365	Body Water Leaks Windows carry out finaln check for RSI	NSW-BSW	1066280
203	09/10/2020	925365	Consumables	NSW-BSW	1066534
203	08/10/2020	924936	Mechanic entered - Elec and Light - Exterior Lights brken n/	NSW-E&L	1066120
203	08/10/2020	924936	LAMP LED SIDE LAMP RED/AMBER PERE (52-98002)	NSW-E&L	1066120
203	08/10/2020	924936	Consumables	NSW-E&L	1066280
203	08/10/2020	924910	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Repair & replace part of the wiring loom conduit and re-tape. completed	FIRE-SAFE	1066120
203	29/09/2020	921758	REPAIR SINGLE SEAT BASE	NSW-BSW	1064932
203	25/09/2020	922278	Assisting - retention pos 2 & 3 -4 wheel nuts with kuma.	TYR	1064619
203	25/09/2020	922278	retension pos 2 & 3 -4 wheel nuts with Abraham.	TYR	1064619
203	25/09/2020	921761	Mechanic entered - Steering - NS kingpin play.	NSW-STE	1064619
203	25/09/2020	922155	Mechanic entered - Body - Drivers Seat Leaning	NSW-BSW	1064619
203	25/09/2020	922155	SEAT FOAM CUSHION PAN DRIVERS SEAT ISRI A6008BASE	NSW-BSW	1064619
203	25/09/2020	922242	Mechanic entered - Body Other passenger back rest worn.	NSW-BSW	1064619
203	24/09/2020	921761	Mechanic entered - Steering - NS kingpin play.	NSW-STE	1064619
203	24/09/2020	921761	BEARING KING PIN VOLVO B10BL	NSW-STE	1064619
203	24/09/2020	921761	KING PIN KIT VOLVO B10BLE B12	NSW-STE	1064619
203	23/09/2020	921661	PRE ANNUAL SAFETY INSPECTION CHECK completed as per check list and tension all wheels with Ryan..	PRE RSI	1064619
203	23/09/2020	921661	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1064619
203	23/09/2020	921757	Mechanic entered - Wheels and Tyres Other NSR inner tyre wor	NSW-W&T	1064619
203	23/09/2020	921757	Consumables	NSW-W&T	1064619
203	23/09/2020	921759	Mechanic entered - Fluid Leaks Other coolant leak above gear	NSW-ENG	1064619
203	23/09/2020	921760	Mechanic entered - Fluid Leaks Other oil leak underneath eng	NSW-ENG	1064619
203	23/09/2020	921754	Mechanic entered - Elec and Light Other saloon light out.	NSW-E&L	1064619
203	23/09/2020	921755	Mechanic entered - Elec and Light Other OSR park light out.	NSW-E&L	1064619
203	23/09/2020	921756	Mechanic entered - Elec and Light Other NSF park light out.	NSW-E&L	1064619
203	23/09/2020	921754	Consumables	NSW-E&L	1064619
203	23/09/2020	921755	Consumables	NSW-E&L	1064619
203	23/09/2020	921756	Consumables	NSW-E&L	1064619
203	23/09/2020	921758	Mechanic entered - Body Other passenger seat torn.	NSW-BSW	1064619
203	23/09/2020	921762	Mechanic entered - Body Other steam clean underbody..	NSW-BSW	1064619
203	10/09/2020	919180	you are travelling on mis	NSW-BSW	1062910
203	09/09/2020	918948	Ops Entered - Fault - Body Drivers Seat Controls - Route: 8	NSW-BSW	1062910
203	09/09/2020	918948	Ops Entered - Fault - Body Drivers Seat Controls - Route: 8	NSW-BSW	1062910
203	04/09/2020	919180	DECAL YOU ARE TRAVELLING ON B	NSW-BSW	1063483

203	01/09/2020	915745	Engine - Rear of bus oil leak underneath engine front cover.	Assemble timing cover and all other part road tested and all ok	NSW-ENG	1061685
203	28/08/2020	915745	Engine - Rear of bus oil leak underneath engine front cover.	refitted all other parts attach to the front cover. refit rocker cover and muffler. one of the sender plug still leaking inform Ranjith and will repair monday..	NSW-ENG	1061418
203	28/08/2020	916644		CARRY OUT A SERVICE AS PER CHECK LIST completed as per check list and tension wheel nuts with Jason..	A	1061418
203	28/08/2020	916644	Consumables		A	1061429
203	28/08/2020	916644	Consumables		A	1061429
203	28/08/2020	916644	Consumables		A	1061429
203	28/08/2020	916644	Consumables		A	1061429
203	26/08/2020	915745	Engine - Rear of bus oil leak underneath engine front cover.	refit top cover and assemble all parts attach to it still waiting for the tool to fit the crank pulley continue tomorrow..	NSW-ENG	1061418
203	26/08/2020	915745	TERMINAL INJ LOOM DH12D VOLV	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282424 Receiving #:294753 Date :2020-08-27	NSW-ENG	1061418
203	25/08/2020	915745	PLUG INJECTOR LOOM DH12D VOLVO B12BLE		NSW-ENG	1061418
203	25/08/2020	915745	SEAL O-RING TACHO SENDER+ VOLVO B12BLE CYL HEAD PLUG		NSW-ENG	1061418
203	25/08/2020	915745	SEAL CABLE TERMINAL INJ LOOM DH12D VOLVO B12BLE		NSW-ENG	1061418
203	25/08/2020	915745	SILICONE ADHESIVE PISTON LINER	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282236 Receiving #:294508 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	O RING COMPRESSOR MTG VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G282332 Receiving #:294525 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	SEAL TIMING CHEST TOP DH12D	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282236 Receiving #:294508 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	TERMINAL INJ LOOM DH12D VOLVO B12BLE		NSW-ENG	1061418
203	25/08/2020	915745	PLUG INJECTOR LOOM DH12D VOL	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282330 Receiving #:294504 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	SEAL CABLE TERMINAL INJ LOOM	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282330 Receiving #:294504 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	SEAL FRT CRANKSHAFT DH12D VO	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282236 Receiving #:294508 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	GASKET TIMING CHEST CVR DH12D	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282236 Receiving #:294508 Date :2020-08-25	NSW-ENG	1061418
203	25/08/2020	915745	SEAL TIMING CHEST DH12D VOLV	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G282236 Receiving #:294508 Date :2020-08-25	NSW-ENG	1061418
203	24/08/2020	915745	Engine Rear of bus oil leak underneath engine front cover.	removed rocker cover and rear end of engine	NSW-ENG	1061418
203	24/08/2020	915745	Engine Rear of bus oil leak underneath engine front cover.	remove every parts attach to the front engine timing cover and remove timing cocer..	NSW-ENG	1061418
203	24/08/2020	915745	O RING WATER PUMP VOLVO B12BLE 948980		NSW-ENG	1061418
203	24/08/2020	915745	SEAL O RING WATER PUMP VOLVO B12BLE 925073		NSW-ENG	1061418
203	24/08/2020	915745	SEAL COOLANT PIPE GEARBOX TO THERMOSTAT HOUSING VOLVO B71		NSW-ENG	1061418
203	24/08/2020	915745	GASKET FUEL PUMP VOLVO B12BLE 3964833		NSW-ENG	1061418
203	24/08/2020	915745	GASKET KIT ROCKER CVR DH12D VOLVO B12BLE 20710235		NSW-ENG	1061418
203	24/08/2020	915745	SEAL ROCKER CVR BOLT VOLVO B12BLE		NSW-ENG	1061418
203	20/08/2020	910552	Mechanic entered - Rear of bus oil leak undernea	inspect and job was given to someone else.	NSW-ENG	1061091
203	20/08/2020	910552	Service	this job not completed and oper another DVR 835943	NSW-ENG	1061091
203	20/08/2020	915263	Mechanic entered - Body Other seat belt buckle broken.	replaced.	NSW-BSW	1061091
203	20/08/2020	915263	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		NSW-BSW	1061091
203	14/08/2020	913944	Mechanic entered - Elec and Light Exterior Lights front L/H	R/R globe.	NSW-E&L	1060247
203	14/08/2020	913944	Consumables		NSW-E&L	1060424
203	06/08/2020	912814	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	FIRE EXT	1059107
203	03/08/2020	910542		VEHICLE SAFETY INSPECTION completed as per check list. and tension all wheels.	SAF-INSP	1058402
203	03/08/2020	910542		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1058402
203	03/08/2020	910542		Completed safetyasa per check sheet and fixed defects found	SAF-INSP	1058402
203	03/08/2020	910552	Mechanic entered - Rear of bus oil leak underneath engine fr	cleaned road test and check found engine front cover leaking inform Ranjith and rebook for repairs.	NSW-ENG	1058402
203	03/08/2020	910546	DIFFUSER INTERIOR LIGHT (price per metre)		NSW-E&L	1058402
203	03/08/2020	910546	Mechanic entered -Saloon light cover broken	Fitted new saloon light cover	NSW-E&L	1058402
203	03/08/2020	910553	Mechanic entered - Saloon light out.	tayla replaced lights.	NSW-E&L	1058402
203	03/08/2020	910556	Mechanic entered - Saloon light cover cracked.	Tayla replaced light cover.	NSW-E&L	1058402
203	03/08/2020	910553	Consumables		NSW-E&L	1058432
203	03/08/2020	910556	Consumables		NSW-E&L	1058432
203	03/08/2020	910546	Consumables		NSW-E&L	1058432
203	03/08/2020	910554	Mechanic entered - Vehicle Mechanical Audit	accidently press.	NSW-BSW	1058402
203	03/08/2020	910555	Mechanic entered - Rear door emergency button cover missing.	Tayla replaced missing cover.	NSW-BSW	1058402
203	03/08/2020	910545	Mechanic entered - Emergency cover broken off	Fitted new emergency cover	NSW-BSW	1058402
203	03/08/2020	910545	COVER EMERGENCY EXIT BUTTON 16906		NSW-BSW	1058402
203	03/08/2020	910545	Mechanic entered - Body Other emergency cover broken off	Fitted new emergency cover	NSW-BSW	1058402
203	03/08/2020	910568	Mechanic entered - Brakes Other front brakes low.	replaced front brakes.and tension wheel nuts with Tayla.	NSW-BRA	1058402
203	03/08/2020	910568	DISC PAD SET B7R EARLY (8550611-1)		NSW-BRA	1058402
203	31/07/2020	910171	Remove old A3 Poster and fit with You can no longer top up	Completed by Refuelers	CAMPAIGN	1058162
203	30/07/2020	910014	Consumables		NSW-E&L	1058162
203	30/07/2020	910014	Mechanic entered - Elec and Light Exterior Lights Front L/H	Fitted new park light globe.	NSW-E&L	1057889
203	27/06/2020	903073	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G278177 Receiving #:290196 Date :2020-06-29 REPLACE L1 MOD R2	NSW-VAN	1051967
203	25/06/2020	903073	Vandalism - Replace anti graffiti film - L1 MOD R2	Replaced by Glassprotech	NSW-VAN	1051516
203	25/06/2020	903265	Driver claims there is no acceleration	Checked the system for active fault no fault. Delete inactive fault drive tested and checked the performance of the engine normal for diesel engine.	NSW-ENG	1051516
203	22/06/2020	902277		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Replaced oil and filter Checked level while bus was running okay roadtested By Neven	TRANS-SERV	1050917
203	22/06/2020	902277	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		TRANS-SERV	1050917
203	22/06/2020	902277	ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR		TRANS-SERV	1050917
203	11/06/2020	900150	Fit A3 Poster in poster frame and fit decals as requested i	Completed	CAMPAIGN	1049331
203	10/06/2020	899897		VEHICLE SAFETY INSPECTION	SAF-INSP	1049114
203	10/06/2020	899897		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1049114
203	10/06/2020	899897		Completed.	SAF-INSP	1049114
203	06/06/2020	899078	Elec and Light - L/H headlight blown	Check OK	NSW-E&L	1048193



203	06/03/2020	879138	Retension pos1 wheel nuts with abraham	TYR	1036045
203	05/03/2020	878688	Ops Entered - Fault - Steering Pulling - Route: 814 - Waver replaced N/F brake caliper tensioned wheel nut with Darsi	NSW-STE	1036045
203	05/03/2020	878688	CALIPER BRAKE FRT L/H VOLVO B10 - B12BLE 70311512	NSW-SITE	1036045
203	05/03/2020	878836	Mechanic entered - Elec and Light Other 5 dash globe out replaced 5 globe	NSW-E&L	1036045
203	05/03/2020	878836	GLOBE DASH 24V 1.2W GREY	NSW-E&L	1036045
203	05/03/2020	878836	Consumables	NSW-E&L	1036045
203	05/03/2020	878836	Consumables	NSW-E&L	1036045
203	21/02/2020	875939	Mechanic entered - Engine Other Remove intercooler and clean Steam cleaned intercooler and radiator.	NSW-ENG	1033334
203	21/02/2020	875939	Mechanic entered - Engine Other Remove intercooler and clean Assisted	NSW-ENG	1033334
203	13/02/2020	874125	Retensioned wheel nuts position 5 and 6 with Nick.	TYR	1032070
203	13/02/2020	874125	Assisted	TYR	1032070
203	13/02/2020	876679	Completed by ATS CARRY OUT FIRE EXTINGUISHER TEST & TAG	FIRE EXT	1032205
203	12/02/2020	873611	Mechanic entered - Wheels and Tyres Flat or Leaking Replaced tyre position 5 with Hayson and tensioned all wheel nuts	NSW-W&T	1031962
203	12/02/2020	873611	TYRE 295/80R22.5 RECAP	NSW-W&T	1031962
203	12/02/2020	873611	Consumables	NSW-W&T	1032070
203	12/02/2020	873583	CARRY OUT A SERVICE AS PER CHECK LIST A Service completed secured wiper arm and tensioned all wheel nuts with Hayson	A	1031962
203	12/02/2020	873583	Consumables	A	1032070
203	12/02/2020	873583	Consumables	A	1032070
203	12/02/2020	873583	Consumables	A	1032070
203	12/02/2020	873583	Consumables	A	1032070
203	12/02/2020	873583	Consumables	A	1032070
203	06/02/2020	872378	Assisted	TYR	1030907
203	06/02/2020	872378	All wheel nuts tensioned w/ Nick	TYR	1030907
203	06/02/2020	872364	Wheels and Tyres - Check hub oil level on pos 1 Top up pos 1 wheel hub.	NSW-W&T	1030907
203	06/02/2020	872364	Consumables	NSW-W&T	1031152
203	05/02/2020	871504	Mechanic entered - Suspension Other O/s rear of rear front a replaced OD rear front airbag Hayson and Darcy tension wheel nuts	NSW-SUS	1030718
203	05/02/2020	871504	AIRBAG REAR VOLVO B12B/B12BLE (20573108) (70376911)	NSW-SUS	1030718
203	05/02/2020	871412	REPAIR SINGLE SEAT BASE	NSW-BSW	1030907
203	04/02/2020	871504	Mechanic entered - Suspension Other O/s rear of rear front a Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G267998 Receiving #:278959 Date :2020-02-06 c/o	NSW-SUS	1030718
203	04/02/2020	871504	KING PIN KIT VOLVO B10BLE B12BLE 30L1106	NSW-STE	1030718
203	04/02/2020	871504	Mechanic entered - Steering Other N/s front kingpin excessiv we had problem removing kingpin as siezed tried everything but still no luck will continue tomorrow.. completed replacing front NS kingpin and tension wheel nut	NSW-STE	1030718
203	04/02/2020	871412	SINGLE SEAT BASE	NSW-BSW	1030718
203	03/02/2020	871396	VEHICLE SAFETY INSPECTION Completed check list with Rene.	SAF-INSP	1030718
203	03/02/2020	871396	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Rene.	SAF-INSP	1030718
203	03/02/2020	871396	Completed check list with Abraham.	SAF-INSP	1030718
203	03/02/2020	871411	Mechanic entered - Elec and Light Other Saloon light plastic Remove and replace plastic cover (light defuser).	NSW-E&L	1030718
203	03/02/2020	871411	DIFFUSER INTERIOR LIGHT (price per metre)	NSW-E&L	1030718
203	03/02/2020	871411	Consumables	NSW-E&L	1030718
203	03/02/2020	871412	SINGLE SEAT BASE	NSW-BSW	1030718
203	03/02/2020	871412	Mechanic entered - Body Passenger Seat Torn Remove and fitted new.	NSW-BSW	1030718
203	20/01/2020	868329	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO completed	CAMPAIGN	1028222
203	17/01/2020	868013	EDGE SENSITIVE EDGE DOOR SWITCH DW40	NSW-AIR	1028040
203	17/01/2020	868013	Ops Entered - Fault - Air System Air_Leak Rear - Route: 815 checked bus found no air leak but faulty rear doors causing valve to go of via sensitive edge. Tried to adjust but no good so removed and replaced sensitive edgw valves. checked and ok.	NSW-AIR	1028040
203	10/01/2020	866481	Drv entered - Body Rear_Door Operation Faulty Checked up bus could not find fault. Door open and closes all okay. Speed is okay and safety edges all okay.	NSW-BSW	1026723
203	02/01/2020	864616	Mechanic entered - Elec and Light Exterior Lights n/s headli Replaced failed globe	NSW-E&L	1025880
203	02/01/2020	864616	GLOBE 24V 70W H1	NSW-E&L	1025880
203	02/01/2020	864616	Consumables	NSW-E&L	1026069
203	02/01/2020	864549	FILTER DRYER AIR COND THERMO KING	AC-B	1025880
203	02/01/2020	864549	COMPRESSOR OIL AIR CON	AC-B	1025880
203	02/01/2020	864549	AIR CON REFRIDGERANT	AC-B	1025880
203	02/01/2020	864549	BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230	AC-B	1025880
203	02/01/2020	864549	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	AC-B	1025880
203	02/01/2020	864549	BELT V-BELT COGGED TRI-POWER 17x1145mm	AC-B	1025880
203	02/01/2020	864549	AIR CON REFRIDGERANT	AC-B	1025880
203	02/01/2020	864549	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list replaced belst rplaced failed oring suction service valve top up refrigerant replaced return air filter medium	AC-A	1025880
203	30/12/2019	864047	Ops Entered - Fault - Gearbox Driveline Rough Gear Change - check fault codes clear all road tested bus ok.	NSW-GEA	1025006
203	27/12/2019	863984	Engine Over-rewving Hard acceleration occurring as a resul reset faulte corde	NSW-GEA	1024106
203	20/12/2019	863225	Mechanic entered - Engine Other Over heating Pressure washed engine bay radiator and intercooler.	NSW-ENG	1023454
203	20/12/2019	863225	Mechanic entered - Engine Other Over heating Drove bus to wash bay and parked bus.	NSW-ENG	1023454
203	18/12/2019	862131	REMOVE GRAFITTI	NSW-VAN	1023003
203	16/12/2019	862212	HAMMER EMERGENCY WITH BRACKET (274-0037)	NSW-BSW	1022530
203	16/12/2019	862212	Mechanic entered - Body Other E/E hammer missing. replaced.	NSW-BSW	1022530
203	14/12/2019	862131	Near side rear window and off side second window from the r Completed by ECTB	NSW-VAN	1022530
203	14/12/2019	862131	Near side rear window and off side second window from the r Assisting	NSW-VAN	1022530
203	09/12/2019	860680	Body - Replace damaged windscreen	NSW-BSW	1021336
203	05/12/2019	859062	DIRECT PURCHASE - BUS INSPECTI	RSI	1023914
203	05/12/2019	859564	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed by b. were (johnny).	CCTV - A	1020793
203	05/12/2019	859564	CCTV 6 MONTHLY SERVICE/VIDEO L	CCTV - A	1022530
203	05/12/2019	859564	CCTV 6 MONTHLY SERVICE/VIDEO L Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G265131 Receiving #:275253 Date :2019-12-18 CLEAN AND PAINT AS REQUIRED		
			Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G264015 Receiving #:275692 Date :2019-12-23 ANNUAL INSPECTION		
			Creditor #:GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G264201 Receiving #:275043 Date :2019-12-16 REPAIR AS REQUIRED		

203	04/12/2019	859062	VEHICLE SAFETY INSPECTION	SAF-INSP	1020559
203	04/12/2019	859062	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	1020559
203	04/12/2019	859062	ANNUAL SAFETY INSPECTION - RWC 017518 - PASSED - 04/12/19WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	RSI	1020559
203	04/12/2019	859062	Assisting	RSI	1020559
203	03/12/2019	858779	A3 Poster Frame Adhesive Decal Campaign please remove old	CAMPAIGN	1020333
203	02/12/2019	857499	Steam clean under the bus	NSW-BSW	1020045
203	27/11/2019	857499	Mechanic entered - Steering Other both steering idlers worn.	NSW-STE	1019697
203	27/11/2019	857499	Mechanic entered - Steering Other both steering idlers worn.	NSW-STE	1019697
203	27/11/2019	857499	COVER PLATE STRG IDLER VOLVO	NSW-STE	1019840
203	27/11/2019	857499	CASTLE NUT	NSW-STE	1019840
203	27/11/2019	857499	THRUST WASHER STRG IDLER VOL	NSW-STE	1019840
203	27/11/2019	857499	RETAINING RING STRG IDLER VO	NSW-STE	1019840
203	27/11/2019	857499	BEARING STRG IDLER VOLVO B10	NSW-STE	1019840
203	27/11/2019	857499	SEALING RING STRG IDLER VOLV	NSW-STE	1019840
203	27/11/2019	857499	PIN STRG IDLER VOLVO B10 - B	NSW-STE	1019840
203	27/11/2019	857499	FLANGE BOLT STRG IDLER VOLVO	NSW-STE	1019840
203	26/11/2019	857080	PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST completed.	AIR-CHECK	1019467
203	21/11/2019	856113	Ops Entered - Fault - Desto Signs - Route: 627 - Moorabbin	NSW-E&L	1018445
203	21/11/2019	856113	UNIT CONTROL UNIT ICU 402	NSW-E&L	1018445
203	21/11/2019	856113	Consumables	NSW-E&L	1018559
203	18/11/2019	855207	TORQUE ROD LH REAR LWR VOLVO B12BLE 9955949 24426046	NSW-SUS	1017884
203	18/11/2019	855207	Suspension - Replace n/s rear lower torque rod.	NSW-SUS	1017884
203	18/11/2019	854797	Suspension - Replace rear sway bar bushes.	NSW-SUS	1017884
203	18/11/2019	855206	Suspension - Replace OS rear lower torque rod.	NSW-SUS	1017884
203	18/11/2019	855206	TORQUE ROD RH REAR LWR VOLVO B12BLE 70301436	NSW-SUS	1017884
203	18/11/2019	855310	Suspension - NS front lower control arm bush cracked.	NSW-SUS	1017884
203	18/11/2019	855321	Suspension - OS front lower control arm bush cracked.	NSW-SUS	1017884
203	18/11/2019	855320	Suspension - Replace rear sway bar link rod.	NSW-SUS	1017884
203	18/11/2019	855316	Steering - NS front upper control arm bush cracked.	NSW-STE	1017884
203	18/11/2019	855323	Engine - Steam clean for RSI	NSW-ENG	1017884
203	18/11/2019	855312	Elec and Light - Replace saloon light	NSW-E&L	1017884
203	18/11/2019	855314	Elec and Light - Replace dash switch globe.	NSW-E&L	1017884
203	18/11/2019	855312	Consumables	NSW-E&L	1017976
203	18/11/2019	855314	Consumables	NSW-E&L	1017976
203	18/11/2019	855291	Body - Replace n/s front wheel arch brush.	NSW-BSW	1017884
203	18/11/2019	855291	WHEEL ARCH RUBBER	NSW-BSW	1017884
203	18/11/2019	855291	WHEEL ARCH BRUSH 12065	NSW-BSW	1017884
203	18/11/2019	855311	Body - Replace worn hand rail grabs.	NSW-BSW	1017884
203	18/11/2019	855318	Body - Repair driver's door lock.	NSW-BSW	1017884
203	18/11/2019	855319	Body - Replace o/s front wheel arch brush.	NSW-BSW	1017884
203	15/11/2019	854826	Suspension - OS front upper control arm bush cracked.	NSW-SUS	1017576
203	15/11/2019	854826	LEVELLING SENSOR (20850557)	NSW-SUS	1017576
203	15/11/2019	854826	UPPER CONTROL ARM BUSH&SPACER WASHER B12BLE (85104649)	NSW-SUS	1017576
203	15/11/2019	854904	CALIPER BRAKE FRT R/H VOLVO B10 - B12BLE 70311513	NSW-BRA	1017576
203	15/11/2019	854904	Brakes - Replace o/s/front brake caliper.	NSW-BRA	1017576
203	14/11/2019	854718	Retensioned wheel nuts with Kuma.	TYR	1017381
203	13/11/2019	854393	PRE ANNUAL SAFETY INSPECTION CHECK Completed.	PRE RSI	1017198
203	13/11/2019	854393	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	PRE RSI	1017198
203	13/11/2019	854444	TYRE 295/80R22.5 RECAP	NSW-W&T	1017198
203	13/11/2019	854444	Mechanic entered - Wheels and Tyres Worn Pos 5 & 6 Tyres worn	NSW-W&T	1017198
203	13/11/2019	854444	Consumables	NSW-W&T	1017381
203	13/11/2019	854392	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	A	1017198
203	13/11/2019	854392	Consumables	A	1017381
203	13/11/2019	854392	Consumables	A	1017381
203	13/11/2019	854392	Consumables	A	1017381
203	13/11/2019	854392	Consumables	A	1017381
203	13/11/2019	854392	Consumables	A	1017381
203	06/11/2019	852712	Bwere doing ATM	CCTV - A	1015723
203	31/10/2019	851749	Consumables	NSW-E&L	1015516
203	31/10/2019	851749	Mechanic entered - Elec and Light Exterior Lights Front L/H	NSW-E&L	1015305
203	30/10/2019	851394	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST washed under engine and trans and on top and fire checked and ok.	FIRE-SAFE	1015059
203	28/10/2019	850799	Consumables	NSW-E&L	1014815
203	28/10/2019	850799	Mechanic entered - Elec and Light Exterior Lights front	NSW-E&L	1014579
203	17/10/2019	848519	Consumables	NSW-E&L	1012787
203	17/10/2019	848519	Drv entered - Elec and Light AM-FM Radio	NSW-E&L	1012600
203	08/10/2019	846789	Consumables	NSW-E&L	1011248
203	08/10/2019	846789	Elec and Light - O/s front radio speaker cover damage.	NSW-E&L	1011026
203	04/10/2019	846174	Tension all rear wheel nuts with Kuma.	TYR	1010780

203	03/10/2019	845841			SAF-INSP	1010581
203	03/10/2019	845841	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done Assisted by Kumar for wheel nut tension.		SAF-INSP	1010581
203	03/10/2019	845841	VEHICLE SAFETY INSPECTION Completed check list.		SAF-INSP	1010581
203	03/10/2019	845861	Consumables		NSW-W&T	1010780
203	03/10/2019	845848	Consumables		NSW-W&T	1010780
203	03/10/2019	845861	Mechanic entered - Wheels and Tyres Worn Position 3 and 4 ty	Remove and fitted two new recap tyre 295/80R22.5 Tension wheel nuts Assisted by Kumar.	NSW-W&T	1010581
203	03/10/2019	845861	TYRE 295/80R22.5 RECAP		NSW-W&T	1010581
203	03/10/2019	845848	Mechanic entered - Wheels and Tyres Worn Tyre position 6 wor	Remove tyre position 6 and fitted second hand run out tyre. Tension wheel nuts Assisted by Kumar.	NSW-W&T	1010581
203	03/10/2019	845869	Consumables		NSW-E&L	1010780
203	03/10/2019	845869	Mechanic entered - Elec and Light Other Rear o/s saloon ligh	Remove and replace flouru tube and re fit cover.	NSW-E&L	1010581
203	03/10/2019	845867	PLASTIC TRIANGLE HANDSTRAP GREY		NSW-BSW	1010581
203	03/10/2019	845867	Mechanic entered - Body Other Passenger handstrap (grab hand	Remove and fitted three new handstrap.	NSW-BSW	1010581
203	03/10/2019	845891	Mechanic entered - Body Other [Passenger door bush worn (piv	Remove and replace secured.	NSW-BSW	1010581
203	03/10/2019	845851	BRAKE PADS VOLVO B7R (20918891) [LATE MODELS]		NSW-BRA	1010581
203	03/10/2019	845851	Mechanic entered - Brakes Other Rear brake pad worn.	Remove and replace brake pads. Adjust brakes Kumar calibrate and Assisted by Kumar for wheel nut tension.Roadtest check brake operation ok. Check temperature ok. Temperature 37 o/s	NSW-BRA	1010581
203	18/09/2019	843143	Consumables		NSW-E&L	1007945
203	18/09/2019	843143	Mechanic entered - Elec and Light Exterior Lights Front R/H	Replaced globe.	NSW-E&L	1007747
203	17/09/2019	842784	Consumables		NSW-E&L	1007747
203	17/09/2019	842784	Ops Entered - Fault - Elec and Light Two Way Radio - Activa	Replaced duress button to see if it fixes the problem Ranji said send bus on the road.	NSW-E&L	1007570
203	17/09/2019	842784	SWITCH EMERGENCY PUSH SWITCH		NSW-E&L	1007570
203	03/09/2019	839881	Ops Entered - Fault - A/C Heating Not Cooling - Route: RAIL	Replaced faied boost pump fuse commission tested ok	NSW-SCA	1005070
203	30/08/2019	838955	Ops Entered - Fault - Suspension Knee/ Raise - Route: 858	Removed and replaced the alternators.Suspension still playing up but batt light out.Tracked down to a faulty relay so rrmoved and replaced.	NSW-SUS	1003985
203	30/08/2019	838955	RELAY VOLVO H/LIGHT DIODE PROTECTED		NSW-SUS	1003985
203	30/08/2019	838955	ALTERNATOR 24V 120AMP VOLVO B12BLE		NSW-SUS	1003985
203	29/08/2019	838955	Ops Entered - Fault - Suspension Knee/ Raise - Route: 858	Check cleand ramp out as reported dbrake sticking on.Found that suspension light and battery saver light on.Checked alternators found one no good.Need to remove and replace them.park	NSW-SUS	1003985
203	22/08/2019	836988	Mechanic entered - Elec and Light Other front left top corne	checked - working o.k.	NSW-E&L	1002617
203	22/08/2019	836988	Consumables		NSW-E&L	1003009
203	19/08/2019	836090	Consumables		B	1002390
203	19/08/2019	836090	Consumables		B	1002390
203	19/08/2019	836090	CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklist washed engine bay and took bus for road test. Drives well.		B	1002036
203	19/08/2019	836090	FILTER OIL FILTER VOLVO B7R		B	1002036
203	19/08/2019	836090	FILTER OIL FILTER BY-PASS VOLVO B12 (EARLY)		B	1002036
203	19/08/2019	836090	FILTER FUEL FILTER		B	1002036
203	19/08/2019	836090	FILTER FUEL FILTER VOLVO (20430751)		B	1002036
203	19/08/2019	836090	Consumables		B	1002390
203	19/08/2019	836090	Consumables		B	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	19/08/2019	836090	Consumables		A	1002390
203	11/08/2019	838036	Completed by ATS		A	1002390
203	08/08/2019	834378	CARRY OUT FIRE EXTINGUISHER TEST & TAG		FIRE EXT	1001211
203	07/08/2019	833838	Done with Sadid		TYR	1000771
203	07/08/2019	833838	VEHICLE SAFETY INSPECTION Safety Inspection Completed		SAF-INSP	1000761
203	07/08/2019	833838	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	1000761
203	07/08/2019	833838	VEHICLE SAFETY INSPECTION Safety Inspection Completed		SAF-INSP	1000761
203	07/08/2019	833918	Consumables		NSW-W&T	1000771
203	07/08/2019	833918	Mechanic entered - Wheels and Tyres Worn Tyre position 5 wor	Replaced tyre position 5 (runout)and tensioned all wheel nuts with Tayle	NSW-W&T	1000761
203	07/08/2019	833945	NUT UPPER+LOWER SUSPENSION ARM (990944)		NSW-SUS	1000761
203	07/08/2019	833945	NUT UPPER+LOWER SUSPENSION ARM		NSW-SUS	1000761
203	07/08/2019	833945	AIRBAG AIR SPRING BELLOWS VOLVO B12BLE		NSW-SUS	1000761
203	07/08/2019	833945	Mechanic entered - Suspension Other N/S/F airbag leaking	Replaced N/S/F air bag	NSW-SUS	1000761
203	07/08/2019	833942	Mechanic entered - Suspension Other N/S upper control arm bu	Replaced N/S upper control arm bushes.removed and fit N/S/F tyres and tensioned all wheel nuts with Ranjith	NSW-SUS	1000761
203	07/08/2019	833942	UPPER CONTROL ARM BUSH&SPACER WASHER B12BLE (85104649)		NSW-SUS	1000761
203	07/08/2019	833888	AIRBAG REAR VOLVO B12B/B12BLE (20573108) (70376911)		NSW-SUS	1000761
203	07/08/2019	833888	Mechanic entered -Suspension Other O/S/R Rear air bag leaki	Replaced O/S/R rear airbag	NSW-SUS	1000761
203	07/08/2019	833917	Consumables		NSW-E&L	1000771
203	07/08/2019	833917	Mechanic entered - Elec and Light Other Bus Stopping Light G	Check bus stopping light and some hasreplaced globe	NSW-E&L	1000761
203	07/08/2019	834018	Consumables		NSW-BSW	1000771
203	07/08/2019	834018	Mechanic entered - Body Other Fleet number sticker missing	Check Ok	NSW-BSW	1000761
203	07/08/2019	834016	Mechanic entered - Brakes Other O/S/F brake calliper faulty	Inspect N/S/F brake calliper and adjust with Ranjith. Check OK and perform Break Test.	NSW-BRA	1000761
203	05/08/2019	833259	Consumables		NSW-E&L	1000550
203	05/08/2019	833259	LAMP STOP/TAIL LED HELLA		NSW-E&L	1000267
203	05/08/2019	833259	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	replaced os rear led light assy	NSW-E&L	1000267
203	02/08/2019	833097	Drv entered - Brakes Foot_Brakes Pulling	Drive test found brakes puling at left. Inspect brake pads ok. Adjust front brake and performed brake test. drive tested ok.	NSW-BRA	999938
203	09/07/2019	827530	Consumables		NSW-E&L	995227
203	09/07/2019	827530	Consumables		NSW-E&L	995227
203	09/07/2019	827530	Ops Entered - Fault - Desto Signs - Route: 627 - Moorabbin	check desto and reprogramme desto ok.	NSW-E&L	994962

203	05/07/2019	826872 Consumables		NSW-BSW	994735
203	05/07/2019	826872 Consumables		NSW-BSW	994735
203	05/07/2019	826872 HINGE DRIVERS DOORS/S 60mmX60mm (12205)(802505)		NSW-BSW	994271
203	05/07/2019	826872 Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	replaced cabin door hinges and lock assy bus ok.	NSW-BSW	994271
203	05/07/2019	826872 Mechanic entered - Body Other drivers entry door jarm;	replaced cabin door hinges and lock assy bus ok.	NSW-BSW	994271
203	05/07/2019	826872 R/H ANTIBURST LOCK		NSW-BSW	994271
203	28/06/2019	825599 POTENTIOMETER ACC PEDAL VOLVO B12BLE 30C0107		NSW-ENG	993330
203	27/06/2019	825599 Ops Entered - Fault - Engine Low Power - Route: - Arrive	replaced accalarater padal potentiometer	NSW-ENG	993175
203	25/06/2019	823364 REPLACE FRONT BUMPER CORNER	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G251185 Receiving #:260034 Date :2019-06-25	NSW-BSW	992721
203	21/06/2019	824412 B12BLE OIL+TEMP SENDER 4 PIN (30V2804)		NSW-ENG	992390
203	21/06/2019	824412 Mechanic entered - Engine Other oil gauge faulty	replace oil pressure switch	NSW-ENG	992390
203	20/06/2019	823363 Mechanic entered - Engine Other Engine oil leak need to rect		NSW-ENG	992158
203	20/06/2019	823364 Mechanic entered - Body Other Front n/s bumper damage unrepo	Replaced N/S front bumper by east coast	NSW-BSW	992158
203	20/06/2019	823364 Mechanic entered - Body Other Front n/s bumper damage unrepo	Bus send to east coast	NSW-BSW	992158
203	19/06/2019	823363 Mechanic entered - Engine Other Engine oil leak need to rect	Removed and replaced fitting.Steam cleaned engine thoroughly and then went on a long road test.Checked when got back and ok.	NSW-ENG	992158
203	19/06/2019	823951 Ops Entered - Fault - Body Drivers Seat Belt - Route: 709 -	check seatbelt and oki.	NSW-BSW	992158
203	18/06/2019	823363 TEST NIPPLE	Creditor #:GB-CM001 CMV TRUCK AND BUS P/L P/O #:G250573 Receiving #:259497 Date :2019-06-20	NSW-ENG	992158
203	17/06/2019	823081		TYR	991723
203	17/06/2019	823081	Done with Kumar.	TYR	991723
203	17/06/2019	823363 Mechanic entered - Engine Other Engine oil leak need to rect	Rectify oil leak steam clean engine Remove old oil seating at top of engine. Remove dirt and make sure spot less no oil remain seating at top of engine. Done a good roadtest re check for oil l	NSW-ENG	991723
203	17/06/2019	823364 Mechanic entered - Body Other Front n/s bumper damage unrepo	Accidentally log in this job This is for body shop job.	NSW-BSW	991723
203	14/06/2019	823081	Assisting	TYR	990903
203	14/06/2019	823081		TYR	990903
203	13/06/2019	822750		SAF-INSP	990740
203	13/06/2019	822750	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Sadid	SAF-INSP	990740
203	13/06/2019	822750	VEHICLE SAFETY INSPECTION Completed with Sadid.	SAF-INSP	990740
203	13/06/2019	822758 Consumables		NSW-W&T	990903
203	13/06/2019	822758 TYRE 295/80R22.5 NEW		NSW-W&T	990740
203	13/06/2019	822758 Mechanic entered - Wheels and Tyres Worn Front position one(	Assisting Sadid.	NSW-W&T	990740
203	13/06/2019	822758 Mechanic entered - Wheels and Tyres Worn Front position one(	Remove and replace tyre Tension wheel nuts Assisted by Rene.	NSW-W&T	990740
203	13/06/2019	822760 CAP END CAP CENTRA SEAT END CAP		NSW-BSW	990740
203	13/06/2019	822760 Mechanic entered - Body Other Seat end caps broken.	Remove and replace seat end caps.	NSW-BSW	990740
203	13/06/2019	822759 CAP END CAP CENTRA SEAT END CAP		NSW-BSW	990740
203	13/06/2019	822759 Mechanic entered - Body Other Rear door sensitive edge not w	Check re position wire works ok.	NSW-BSW	990740
203	27/05/2019	819572 CCTV 6 MONTHLY SERVICE	Creditor #:GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G249088 Receiving #:258030 Date :2019-05-31 SERVICE AS REQUIRED	NSW-COM	988910
203	27/05/2019	819572 CCTV 6 month service	Completed by Johnny	NSW-COM	988116
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		A	987599
203	24/05/2019	819117 GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596FWLED		A	987599
203	24/05/2019	819117	CARRY OUT A SERVICE AS PER CHECK LIST replaced dash light and o/s/f park light.	A	987599
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	24/05/2019	819117 Consumables		A	987875
203	22/05/2019	818365 PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	did the upload	CAMPAIGN	987031
203	02/05/2019	813213 Check and repair pressurising cooling system	fit new air compressor new air drier unit new water separator check turbook drain air tankstop up coolantroad tested ok.	NSW-ECO	983749
203	02/05/2019	813213 SEAL COOLANT PIPE GEARBOX TO THERMOSTAT HOUSING VOLVO B7L		NSW-ECO	983749
203	01/05/2019	813213 SEAL COMPRESSOR MK4	Creditor #:GB-CM001 CMV TRUCK AND BUS P/L P/O #:G246766 Receiving #:255774 Date :2019-05-08	NSW-ENG	984570
203	01/05/2019	813213 AIR COMPRESSOR VOLVO B12BLE	Creditor #:GB-CM001 CMV TRUCK AND BUS P/L P/O #:G246766 Receiving #:255774 Date :2019-05-08	NSW-ENG	984570
203	01/05/2019	813213 VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		NSW-ENG	983749
203	01/05/2019	813213 SEAL O RING WATER PUMP VOLVO B12BLE 925073		NSW-ENG	983749
203	01/05/2019	813213 O RING WATER PUMP VOLVO B12BLE 948980		NSW-ENG	983749
203	01/05/2019	813213 O RING COMPRESSOR MTG VOLVO B12BLE 49A9438		NSW-ENG	983749
203	01/05/2019	813213 Check and repair pressurising cooling system	remove compressor.	NSW-ENG	983749
203	01/05/2019	813213 Check and repair pressurising cooling system	Removed the compesser with Alan.	NSW-ENG	983749
203	01/05/2019	813213 AIR DRYER ASSY VOLVO B12BLE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G246837 Receiving #:255265 Date :2019-05-02	NSW-AIR	983749
203	01/05/2019	813087 Please remove all old poster and fit MYKI has gone mobil	Completed by Refuellers	CAMPAIGN	983749
203	30/04/2019	812793 Ops Entered - Fault - Etec and Light Warning Light On Dash	Loe coolant and top up coolant	NSW-E&L	983533

203	30/04/2019	812793 Consumables		NSW-E&L	983749
203	27/04/2019	812252 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		NSW-E&L	983100
203	27/04/2019	812252 LIGHT SIDE INDICATOR L/H		NSW-E&L	983100
203	27/04/2019	812252 Mechanic entered - Elec and Light Exterior Lights Front R/H	Replaced O/S front clearance light and park light globe	NSW-E&L	983100
203	27/04/2019	812252 Consumables		NSW-E&L	983326
203	24/04/2019	811750 GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT		NSW-E&L	982697
203	24/04/2019	811750 Off side front indicator is out	completed changed top indicator globe.	NSW-E&L	982697
203	24/04/2019	811750 Consumables		NSW-E&L	983100
203	15/04/2019	810443 Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 844	checked cooling system road tested ok.	NSW-ENG	981569
203	12/04/2019	810157 FRONT BRAKE HOSE B10L		NSW-OPS	980890
203	12/04/2019	810157 Fault#:36475 - Ops Entered - Fault - Breakdown Air System Fa	Checked found air leaks @ rear axle flexible hose. Removed floor hatch and temporary repair the hose. Sent back the bus back to depot. ( Brake hose require replacing) R/R brake hose and cl	NSW-OPS	980890
203	11/04/2019	809650 CAP END CAP CENTRA SEAT END CAP		SAF-INSP	980890
203	11/04/2019	809650 INVERTER 15-58W 24V T8 (49V2706)		SAF-INSP	980890
203	11/04/2019	809650		SAF-INSP	980890
203	11/04/2019	809650 BOSCH TWIN WINDSCREEN WASHER JET		SAF-INSP	980890
203	11/04/2019	809650 LAMP CLEAR FRT INDICATOR WRAP-AROUND		SAF-INSP	980890
203	11/04/2019	809650	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tentioned wheel nuts with Zubz	SAF-INSP	980890
203	11/04/2019	809650	VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list booked all found jobs and tentioned wheel nuts with Zubz. Completed brake test.	SAF-INSP	980890
203	11/04/2019	809861 Mechanic entered - Wipers and Washers Washers Not Working Wa	changed wipers washer jets.	NSW-W&W	980890
203	11/04/2019	809735 Mechanic entered - Steering Excessive Play Grease both Kingp	Grease both kingpins now no play.	NSW-STE	980890
203	11/04/2019	809738 Mechanic entered - Fluid Leaks Rear of bus Hydraulic pump o-	fitted two new o ring behind the hydraulic pump with zubz	NSW-ENG	980890
203	11/04/2019	809738 Mechanic entered - Fluid Leaks Rear of bus Hydraulic pump o-	changed hydraulic pump 2 o-rings.	NSW-ENG	980890
203	11/04/2019	809738 SEAL O-RING HYDRAULIC PUMP		NSW-ENG	980890
203	11/04/2019	809886 Mechanic entered - Engine Other Check crank case position se	replaced new sensor with zubz	NSW-ENG	980890
203	11/04/2019	809886 Mechanic entered - Engine Other Check crank case position se	assisted	NSW-ENG	980890
203	11/04/2019	809863 Mechanic entered - Engine Other Steam clean engine	steam cleaned full engine area	NSW-ENG	980890
203	11/04/2019	809886 SENSOR CRANKCASE PRESSURE VOLVO B12BLE 30V2809		NSW-ENG	980890
203	11/04/2019	810010 Consumables		NSW-E&L	981160
203	11/04/2019	809870 Consumables		NSW-E&L	981160
203	11/04/2019	809864 Consumables		NSW-E&L	981160
203	11/04/2019	809737 Consumables		NSW-E&L	981160
203	11/04/2019	809734 Consumables		NSW-E&L	981160
203	11/04/2019	809870 LAMP WHITE		NSW-E&L	980890
203	11/04/2019	809870 GLOBE 24V 10W SINGLE CONTACT		NSW-E&L	980890
203	11/04/2019	809870 Mechanic entered - Elec and Light Exterior Lights O/S/F Top	changed blown globe and replaced damaged lamp - (osf) top marker light.	NSW-E&L	980890
203	11/04/2019	809737 Mechanic entered - Elec and Light Exterior Lights O/S/F lowe	Replaced lower park light globe.	NSW-E&L	980890
203	11/04/2019	809734 Drv entered - Elec and Light Exterior Lights		NSW-E&L	980890
203	11/04/2019	809734 Mechanic entered - Elec and Light Exterior Lights O/S/F Head	Replaced headlight globe	NSW-E&L	980890
203	11/04/2019	809734 GLOBE 24V 70W H1		NSW-E&L	980890
203	11/04/2019	810011 Consumables		NSW-E&L	981160
203	11/04/2019	810011 Mechanic entered - Dash Dash_Lights Not Working Multiple das	changed dash globes.	NSW-E&L	980890
203	11/04/2019	810010 Mechanic entered - Elec and Light Other Emergency Hammer ala	changed emercy alarm housing and re wired some wires to connect working now	NSW-E&L	980890
203	11/04/2019	809864 Mechanic entered - Elec and Light Interior Lights One saloon	changed one saloon light and inverter	NSW-E&L	980890
203	11/04/2019	809864 INVERTER 24V 15-36W (KIRG)		NSW-E&L	980890
203	11/04/2019	810009 Consumables		NSW-BSW	981160
203	11/04/2019	809862 Consumables		NSW-BSW	981160
203	11/04/2019	809862 Mechanic entered - Body Other One seat back loose	completed put back back seat and secured	NSW-BSW	980890
203	11/04/2019	810012 Consumables		NSW-BSW	981160
203	11/04/2019	810012 Mechanic entered - Body Other Secure front modesty panel	completed and secured modesty panel	NSW-BSW	980890
203	11/04/2019	810009 Mechanic entered - Body Rear_Door Operation Faulty Rear sens	completed sensitive edge.	NSW-BSW	980890
203	11/04/2019	809862 EMERGENCY HAMMER HOLDER WITH SENSOR		NSW-BSW	980890
203	08/04/2019	808775 Consumables		NSW-E&L	980658
203	08/04/2019	808775 GLOBE 24V 70W H1		NSW-E&L	980100
203	08/04/2019	808775 Mechanic entered - Elec and Light Exterior Lights L/H headli	changed blown globe and replaced damaged electrical crimp connectors (ns) low beam headlight.	NSW-E&L	980100
203	02/04/2019	807723 Ops Entered - Fault - Warning Lights Engine - Route: - Tak	clean pressure sensor clear fault codes bus ok.	NSW-ENG	979444
203	29/03/2019	807086 TRANS DROPPING OUT OF GEARS . THEN CANNOT SELECT GEAR	check fault codes replaced protensiometer fixed CAN wire road tested bus ok.	NSW-GEA	979041
203	29/03/2019	807086 POTENTIOMETER ACC PEDAL VOLVO B12BLE 30C0107		NSW-GEA	979041
203	27/03/2019	806662 Consumables		NSW-E&L	979041
203	27/03/2019	806662 Drv entered - Elec and Light Exterior Lights	Checked - ok.	NSW-E&L	978740
203	21/03/2019	805120	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed.	TUNE-UP	977460
203	21/03/2019	805120	Helped Alan eith Tune up Service.	TUNE-UP	977460
203	21/03/2019	805120 SEAL ROCKER CVR BOLT VOLVO B12BLE		TUNE-UP	977460
203	21/03/2019	805120 GASKET ROCKER CVR KIT B12BLE 20710235		TUNE-UP	977460
203	07/03/2019	802955 Breakdown#:36332 - Ops Entered - Breakdown - Breakdown Air	ref to w/o #802530	NSW-OPS	975530
203	07/03/2019	802530 Ops Entered - Fault - Air System Air_Leak Rear - Route: 814	Rectify air leak found broken air dryer filter housing. Temporary repair and send the bus back to depot. Removed broken air dryer filter housing and checked air leaks ok. (fitted old parts only)	NSW-AIR	975380
203	01/03/2019	794356 CHECK WHY TECH TOOL NOT CONECT	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G240647 Receiving #:251390 Date :2019-03-13	NSW-BRA	976020
203	22/02/2019	794356 VALVE EBS MODULATOR RR VOLVO B12BLE 30G4005KNORR		NSW-BRA	972726
203	21/02/2019	794356 Steering - Steering wheel u/s (ordered) Both Head light Ass	fixed steering wheel outer cushion	NSW-STE	972726



203	15/11/2018	779226	Steering - Replace middle tie rod	Remove and fitted new tie rod.	NSW-STE	959540
203	15/11/2018	779222	Engine - Repair engine oil leak	Roadtested rectify Engine leak found water pump leaking oil and coolant leak at top of the Engine. Job to continue c/o.	NSW-ENG	959540
203	15/11/2018	779232	Engine - Remove flow hatches and clean	Steam clean Engine and trans plus under carriage.	NSW-ENG	959540
203	15/11/2018	779227	Consumables		NSW-E&L	959763
203	15/11/2018	779227	Elec and Light - replace interior fluoro	Remove and replace flouru tube.	NSW-E&L	959540
203	15/11/2018	779233	VALVE RELAY SCANIA/VOLVO (04	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G234306 Receiving #:242240 Date :2018-11-15	NSW-BRA	959763
203	15/11/2018	779233	Brakes - Replace park brake relay valve	Replace relay valve.	NSW-BRA	959540
203	15/11/2018	779223	Air System - Air leaking on top of g/box	Rectify air leak found leaking at retarder valve fittings retightened fittings re check for leak ok.	NSW-AIR	959540
203	14/11/2018	779226	TIE ROD CENTRE VOLVO B10 / B1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G234197 Receiving #:242140 Date :2018-11-15	NSW-STE	959763
203	14/11/2018	778567	SECURE SIDE WINDOWS 2nd & 6th	Creditor #:GB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:G234056-A Receiving #:242183 Date :2018-11-15	NSW-BSW	959763
203	14/11/2018	779231	Body - Adjust rear door sensitive edge	Adjust sensitive edge.	NSW-BSW	959540
203	14/11/2018	779224	Body - Refit rear door rubber	Refit door rubber.	NSW-BSW	959540
203	14/11/2018	779218	BUSH Z CAM LEVER BRAKE		NSW-BRA	959540
203	14/11/2018	779218	FORK HALF Z CAM BRAKE		NSW-BRA	959540
203	14/11/2018	779218	FORK HALF BRAKE Z CAM BRAKE		NSW-BRA	959540
203	14/11/2018	779218	Brakes - Check NS front brake caliper	Replace brake booster yoke assembly and bush. Fitted new brake pads adjust brake and refit wheel.	NSW-BRA	959540
203	14/11/2018	779220	SEAL OIL SEAL FRONT HUB VOLVO B7R (30L0304)		NSW-BRA	959540
203	14/11/2018	779220	DISC PAD SET B7R EARLY (8550611-1)		NSW-BRA	959540
203	14/11/2018	779220	DISC BRAKE DISC FRONT VOLVO B7R		NSW-BRA	959540
203	14/11/2018	779220	Brakes - Replace both front brake disc	Fitted hub assembly and tensioned hub nut. refit hub cover andf topped-up oil. Refit caliper replace brake booster yoke assembly and bush. Fitted new pads o/s adjust brake and refit wheel	NSW-BRA	959540
203	14/11/2018	779218	LOCK NUT 10MM		NSW-BRA	959540
203	14/11/2018	779218	ALLEN KEY BOLT		NSW-BRA	959540
203	14/11/2018	779218	CALIPER BRAKE FRT L/H VOLVO B10 - B12BLE 70311512		NSW-BRA	959540
203	13/11/2018	779221	Steering - Replace NS kingpin bush	Remove and replace king pin n/s refit hub and topped-up hub oil grease king pin.	NSW-STE	959540
203	13/11/2018	779221	KING PIN KIT VOLVO B10BLE B12BLE		NSW-STE	959540
203	13/11/2018	779220	Brakes - Replace both front brake disc	Remove caliper rotor and hub assembly Replace rotor caliper and hub seal n/s/sand o/s replace rotor and hub seal o/s.job to continue. O/s rotor remove by Damon.	NSW-BRA	959540
203	13/11/2018	779218	Brakes - Check NS front brake caliper	Replace caliper job to continue.	NSW-BRA	959540
203	12/11/2018	778567	Body - Secure NS 2nd & 6th windows	Completed by alpha	NSW-BSW	959540
203	09/11/2018	778423		PRE ANNUAL SAFETY INSPECTION CHECK	PRE RSI	959540
203	07/11/2018	779379	Vandalism - Remove interior graffiti	Removed by fleet support	NSW-VAN	959540
203	30/10/2018	776604	Mechanic entered - Fluid Leaks Rear of bus Water pump leakin	R&R waterpump. top up coolant. sisil for road test. all good.	NSW-ENG	957943
203	30/10/2018	776604	WATER PUMP B12B DH12D	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G233107 Receiving #:240846 Date :2018-10-30	NSW-ECO	957943
203	29/10/2018	776431		Re tensioned all rear wheels.	TYR	957881
203	29/10/2018	776431		Assisting	TYR	957881
203	27/10/2018	776151	Consumables		NSW-W&T	957881
203	27/10/2018	776151	TYRE 295/80R22.5 RECAP		NSW-W&T	957659
203	27/10/2018	776151	Mechanic entered - Wheels and Tyres Worn Pos: 34 and 56	Helped with tyres changed all rear tyres and tensioned wheel nut with Crege	NSW-W&T	957659
203	27/10/2018	776151	Mechanic entered - Wheels and Tyres Worn Pos: 34 and 56	R/R Pos: 34 and 56 -> Tensioned All Wheel Nuts	NSW-W&T	957659
203	27/10/2018	776124	Consumables		C	957881
203	27/10/2018	776124	FILTER OIL FILTER VOLVO B7R		C	957659
203	27/10/2018	776124	FILTER OIL FILTER VOLVO B7R		C	957659
203	27/10/2018	776124	FILTER OIL FILTER VOLVO B7R		C	957659
203	27/10/2018	776124		Completed C service	C	957659
203	27/10/2018	776124		CARRY OUT C SERVICE AS PER CHECK LIST Completed C service	C	957659
203	27/10/2018	776124	Consumables		C	957881
203	27/10/2018	776124	Consumables		C	957881
203	27/10/2018	776124	Consumables		C	957881
203	27/10/2018	776124	VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		C	957659
203	27/10/2018	776124	SUMP RING 24MM VOLVO B12BLE 20579690		C	957659
203	27/10/2018	776124	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		C	957659
203	27/10/2018	776124	FILTER AIR FILTER VOLVO B10M Mk4/B12 (AF4560) (1544449-0)		C	957659
203	27/10/2018	776124	FILTER HYDRAULIC FILTER VOLVO B8RLEA E6 (20801559)		C	957659
203	27/10/2018	776124	FILTER FUEL FILTER		C	957659
203	27/10/2018	776124	FILTER FUEL FILTER VOLVO (20430751)		C	957659
203	27/10/2018	776124	FILTER OIL FILTER BY-PASS VOLVO B12 (EARLY)		C	957659
203	27/10/2018	776124	Consumables		B	957881
203	27/10/2018	776124		Completed B service	B	957659
203	27/10/2018	776124	Consumables		B	957881
203	27/10/2018	776124	Consumables		B	957881
203	27/10/2018	776124	Consumables		B	957881
203	27/10/2018	776124	Consumables		B	957881
203	27/10/2018	776124	Consumables		A	957881
203	27/10/2018	776124		Completed A service completed	A	957659
203	27/10/2018	776124	Consumables		A	957881
203	27/10/2018	776124	Consumables		A	957881
203	27/10/2018	776124	Consumables		A	957881
203	26/10/2018	776047	Consumables		NSW-E&L	957832
203	26/10/2018	776047	Mechanic entered - Elec and Light Other alternator wires cra	removed wires from alt taped up the heat shrunk over then conduited.hookedback up and secured.Checked and ok.	NSW-E&L	957659
203	26/10/2018	776046		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST washed under bus and engineer did the fire safety.	FIRE-SAFE	957659

203	25/10/2018	775531 Consumables			NSW-E&L	957659
203	25/10/2018	775531 SWITCH IGNITION SWITCH			NSW-E&L	957132
203	25/10/2018	775531 DIRECT PURCHASE - ELECTRICAL			NSW-E&L	957132
203	24/10/2018	775531 DIRECT PURCHASE - ELECTRICAL			NSW-E&L	957132
203	24/10/2018	775531 Mechanic entered - Elec and Light Other key turning all the	removed covers and ignition switch checked and no spring back soi removed and fitted new one.check and ok.		NSW-E&L	957132
203	20/10/2018	774759	re-tensioned all steer wheel nuts with kumar.		TYR	956380
203	19/10/2018	774507	tensioned wheel nuts.		SAF-INSP	956380
203	19/10/2018	774507	VEHICLE SAFETY INSPECTION Replaced missing pull down cover on rear door. Clean graffiti of back of rear seats and windows clean graffiti of back on rear seats and windows		SAF-INSP	956380
203	19/10/2018	774507 EMERGENCY EXIT BUTTON PULL COVER (16906)			SAF-INSP	956380
203	19/10/2018	774507 SINGLE SEAT BASE			SAF-INSP	956380
203	19/10/2018	774655 Consumables			NSW-W&T	956651
203	19/10/2018	774655 Mechanic entered - Wheels and Tyres Other Removed 2 check br	Removed LHF wheel to check brakes		NSW-W&T	956380
203	16/10/2018	772155 rear floor hatch repairs x2	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G231787 Receiving #:240601 Date :2018-10-26 repaired by eastcoast		NSW-BSW	957659
203	15/10/2018	773308 Drv entered - A/C Heating Demister Not Heating	Replaced failed fuses and condenser fans 1 hour went to moving buses		NSW-SCA	955001
203	09/10/2018	772155 Mechanic entered - Body Other engine floor hatch centre at	Bus send to east coast		NSW-BSW	954822
203	09/10/2018	772155 Mechanic entered - Body Other engine floor hatch centre at			NSW-BSW	954822
203	01/10/2018	769826 REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers		CAMPAIGN	953226
203	14/09/2018	766675 Ops Entered - Fault - Warning Lights Temperature - Route:	Removed intercooler and cleaned radiator - ok.		NSW-ENG	949957
203	13/09/2018	766116 Mechanic entered - Vandalism Other Upper and lower seat cush	already been replaced.		NSW-VAN	948900
203	13/09/2018	766111 SINGLE SEAT BACK REST			NSW-BSW	948900
203	13/09/2018	766111 Mechanic entered - Body Passenger Seat Torn	replaced missing pax. seat back cushion.		NSW-BSW	948900
203	13/09/2018	766061 Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		FIRE EXT	948900
203	12/09/2018	762953 Consumables			NSW-W&T	949684
203	12/09/2018	762953 TYRE 295/80R22.5 RECAP			NSW-W&T	948900
203	11/09/2018	765299 Consumables			NSW-E&L	949425
203	11/09/2018	765299 LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND			NSW-E&L	948900
203	11/09/2018	765299 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)			NSW-E&L	948900
203	11/09/2018	765299 GLOBE 24V 70W H1			NSW-E&L	948900
203	11/09/2018	765299 Drv entered - Elec and Light Exterior Lights	changed blown globes and replaced broken lamps both (nsf) and (osf) bottom park / indicator lights. changed blown globe and repaired broken / damaged wires (osf) low beam head light.		NSW-E&L	948900
203	07/09/2018	762951 Suspension Suspension R/H/rear top torx rod bush circlip of	check rear os upper torque rod lock ok bus serviceable		NSW-SUS	948580
203	04/09/2018	763761 Consumables			NSW-W&T	947997
203	04/09/2018	763761 Mechanic entered - Wheels and Tyres Wheel Nut Retension N/R	re-tensioned all wheel nuts with dulkitih.		NSW-W&T	946798
203	04/09/2018	762951 TORQUE ROD ASSY RR UPPER VOLVO B12BLE 24426047			NSW-SUS	946798
203	04/09/2018	763836 TOW BUS FROM CAUFIELD TO DAND	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G228717 Receiving #:236293 Date :2018-09-04		NSW-OPS	947997
203	04/09/2018	763836 Breakdown#:35406 - Ops Entered - Breakdown - Breakdown Elec	Office call tow truck and tow bus to dandenong 18/08/18 and 20/08/18ndulkitih repair the light (no one attend brake down j) another same brake down job enteredand clear under 760495 w/c		NSW-OPS	946798
203	02/09/2018	763563 Breakdown#:35488 - Ops Entered - Breakdown - Breakdown Not	Jump started bus		NSW-OPS	946798
203	01/09/2018	762951 Suspension Suspension R/H/rear top torx rod bush circlip of	replaced the bush and serclip to get bus going new rod ordered in to replace 30/08/18		NSW-SUS	947440
203	01/09/2018	762545 TOW BUS NOBLE PARK TO DANDENONG	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G228708 Receiving #:236294 Date :2018-09-04		NSW-OPS	947440
203	31/08/2018	763363 Consumables			NSW-W&T	947047
203	31/08/2018	763363 Mechanic entered - Wheels and Tyres Wheel Nut Retension O/R	Tension wheel nuts tyre pos 5&6 with Elias.		NSW-W&T	946798
203	31/08/2018	763363 Mechanic entered - Wheels and Tyres Wheel Nut Retension O/R	Retensioned O/S Rear tyers		NSW-W&T	946798
203	31/08/2018	762950 Suspension Suspension O/S/F bottom control arm bushes worn	replaced 4 bushes and road tested completed		NSW-SUS	946798
203	31/08/2018	762950 BUSH LOWER CONTROL ARM BUSH VOLVO B12BLE (70308541)			NSW-SUS	946798
203	31/08/2018	762954 BrakesBrakes L/H rear brake booster faulty	replaced Brake booster pos3 tyre and tensioned wheel nut with matt		NSW-BRA	946798
203	31/08/2018	763313 PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHE	completed		CAMPAIGN	946798
203	30/08/2018	762950 Suspension Suspension O/S/F bottom control arm bushes worn			NSW-SUS	946798
203	30/08/2018	762951 KIT TORQUE ROD BUSH KIT VOLVO B12BLE (3093467)			NSW-SUS	946798
203	30/08/2018	762953 AIRBAG REAR VOLVO B12B/B12BLE (20573108) (70376911)			NSW-SUS	946798
203	30/08/2018	762953 Suspension Suspension O/S/R front air bag leaks	changed the air bag also changed pos 5 tyre and tensioned wheel nut with Mark		NSW-SUS	946798
203	30/08/2018	762946 Suspension O/S/F bottom control arm bushes worn	Wrong bus number must be bus 203		NSW-SUS	946798
203	30/08/2018	762952 VALVE FRT MODULATOR VOLVO B1	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G228354 Receiving #:235865 Date :2018-08-30		NSW-BRA	946798
203	30/08/2018	762954 BrakesBrakes L/H rear brake booster faulty			NSW-BRA	946798
203	30/08/2018	762954 BRAKE BOOSTER REAR NEAR SIDE VOLVO B12BLE 3177336			NSW-BRA	946798
203	30/08/2018	762952 Brakes Brakes Front ?l modulator valve leaks	replaced the valve		NSW-BRA	946798
203	29/08/2018	762818	Assisting completed ande tensioned wheel nut with Nevan		SAF-INSP	946798
203	29/08/2018	762818	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	946798
203	29/08/2018	762818	VEHICLE SAFETY INSPECTION		SAF-INSP	946798
203	29/08/2018	762817 -Bus has been towed to depot	Found switch in engine bay has been in neutral position		NSW-OPS	946798
203	28/08/2018	762545 Breakdown#:35457 - Ops Entered - Breakdown - Breakdown Not	Attended break down at Corner Princess highway Etonera road. Check for fault check belts ok check wiring ok. Jump start bus still won't start reported to Shalen situation and Shalen organis		NSW-OPS	946798
203	21/08/2018	760583 Consumables			NSW-E&L	945666
203	21/08/2018	760583 Elec and Light - Rectify no dash lights working.	removed fuse panel and braket checked behind bracket and ok.Check behind fuse panel and fount battery feed wire loose and terminal burnt out.Crimped new terminal and checked pos 21		NSW-E&L	945666
203	20/08/2018	760583 RELAY VOLVO H/LIGHT DIODE PROTECTED			NSW-E&L	945547
203	20/08/2018	760583 Elec and Light - Rectify no dash lights working.	Hi + Low beam + Parkers not working and all internal body builder accoorries.Found 3 blown mini blade fuses replaced still no good.Found one bury relay replaced still no good.Checked noc		NSW-E&L	945547
203	16/08/2018	759549 WHEEL ARCH BRUSH 2.5MTR 12065			NSW-BSW	944830
203	16/08/2018	759549 BRUSH RUBBER WHEEL ARCH BRUSH [price per metre] (41249)			NSW-BSW	944830
203	15/08/2018	759549 AIRBAG AIR SPRING BELLOWS VOLVO B12BLE			NSW-SUS	944830
203	15/08/2018	759549 AIRBAG AIR SPRING BELLOWS VOLVO B12BLE			NSW-SUS	944830
203	15/08/2018	759549 Mechanic entered - Suspension Other O/S/F air bag leaking	Remove air bag and found out rubber bump stop worn remove rubber bump stop bolt to remove need to remove panel and checked plate at top of air bag inside of bus. Fitted new air bag ant		NSW-SUS	944830

203	15/08/2018	759549 Consumables			NSW-E&L	945050
203	15/08/2018	759549 LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)			NSW-E&L	944830
203	15/08/2018	759549 Mechanic entered - Elec and Light Other 1 plate number light	Remove and replace LED number plate light secured wire.		NSW-E&L	944830
203	15/08/2018	759549 Mechanic entered - Body Other 2 wheel arc brush missing	Assemble new rubber and brush fitted new wheel arch rubber and brush o/s and n/s.		NSW-BSW	944830
203	13/08/2018	758810 Consumables			A	944422
203	13/08/2018	758810 Consumables			A	944422
203	13/08/2018	758810 Consumables			A	944422
203	13/08/2018	758810 Consumables			A	944422
203	13/08/2018	758810	CARRY OUT A SERVICE AS PER CHECK LIST A service completed and adjust front brake with Dulkit		A	943533
203	01/08/2018	762951 TORQUE ROD ASSY RR UPPER VOL	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G228386 Receiving #:236178 Date :2018-09-03		NSW-SUS	947440
203	31/07/2018	756052 PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Checked by Refuellers and this job has been done		CAMPAIGN	941505
203	30/07/2018	755885 Breakdown#:35307 - Ops Entered - Breakdown - Breakdown Elec	Checked found transmission data link communication faulty. Reset the system and follow the bus back to depot. Inspect transmission wire connector ok. Delete all the fault drive tested and		NSW-OPS	941242
203	27/07/2018	755341 REMOVE OLD POSTER AND REPLACE WITH BUS TIMES ARE CHANGING	Replaced by Refuellers		CAMPAIGN	940710
203	20/07/2018	754151 PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	completed		CAMPAIGN	939464
203	20/07/2018	753737 FUSE BLADE 10 AMP (NR52810)			CAMPAIGN	939464
203	20/07/2018	753737 PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	complete		CAMPAIGN	939464
203	03/07/2018	749892	Assisting		SAF-INSP	935919
203	03/07/2018	749892	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	935919
203	03/07/2018	749892	VEHICLE SAFETY INSPECTION		SAF-INSP	935919
203	29/06/2018	749031 Mechanic entered - Steering Other	added power steering fluid - low.		NSW-STE	934221
203	29/06/2018	749019 Consumables			NSW-E&L	934754
203	29/06/2018	749019 Mechanic entered - Elec and Light Exterior Lights Near side	changed blown globe (nsf) top marker light.		NSW-E&L	934221
203	29/06/2018	749019 Mechanic entered - Elec and Light Exterior Lights Front L/H	already been fixed.		NSW-E&L	934221
203	29/06/2018	749086 PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	Replaced		CAMPAIGN	934221
203	19/06/2018	746193 Consumables			NSW-E&L	932657
203	19/06/2018	746193 Drv entered - Elec and Light Exterior Lights	changed blown globes both (nsf) and (osf) bottom park lights.		NSW-E&L	932100
203	19/06/2018	746193 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)			NSW-E&L	932100
203	15/06/2018	745541 KIT SWITCH OVERRIDE RPD			CAMPAIGN	931623
203	14/06/2018	745541 PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH	did the campaign.		CAMPAIGN	931623
203	13/06/2018	745208 Mechanic entered - Gearbox Driveline Other	Mistake in entry nothing wrong.		NSW-GEA	931390
203	13/06/2018	745225 Consumables			NSW-E&L	931623
203	13/06/2018	745225 GLOBE 24V 70W H1	R/R n/s headlight globe. Found wirings burnt. Asked Elias to secure wirings.		NSW-E&L	931390
203	13/06/2018	745225 Mechanic entered - Elec and Light Other l / h low beam - out	R/R n/s headlight globe. Found wirings burnt. Asked Elias to secure wirings.		NSW-E&L	931390
203	13/06/2018	745225 Mechanic entered - Elec and Light Other	repair terminals on wires. to headlights.		NSW-E&L	931390
203	12/06/2018	744451 Consumables			NSW-E&L	931390
203	12/06/2018	744451 GLOBE 24V 3W INSTRUMENT			NSW-E&L	930740
203	08/06/2018	744451 Mechanic entered - Elec and Light Exterior Lights Front L/H	R/R globe.		NSW-E&L	930740
203	29/05/2018	741851 CRANK CASE PRESSURE SENSOR			NSW-OPS	928383
203	29/05/2018	741851 Breakdown#:34971 - Ops Entered - Breakdown - Breakdown Warn	Replaced sender		NSW-OPS	928383
203	29/05/2018	741851 Breakdown#:34971 - Ops Entered - Breakdown - Breakdown Warn	Found warning light on dash and unable to move i fixed temporarily and bought bus back to depot		NSW-OPS	928383
203	29/05/2018	741765 Consumables			NSW-E&L	928840
203	29/05/2018	741765 GLOBE 24V 10W SINGLE CONTACT			NSW-E&L	928383
203	29/05/2018	741765 Mechanic entered - Elec and Light Exterior Lights Frot R/H u	replaced os top park light globe		NSW-E&L	928383
203	29/05/2018	741950 Consumables			NSW-BSW	928840
203	29/05/2018	741922 Consumables			NSW-BSW	928840
203	29/05/2018	741950 Body - Replace pax seat	Replaced		NSW-BSW	928383
203	29/05/2018	741922 SINGLE SEAT BASE			NSW-BSW	928383
203	29/05/2018	741922 Consumables			A	928840
203	29/05/2018	741922 Consumables			A	928840
203	29/05/2018	741922 Consumables			A	928840
203	29/05/2018	741922 Consumables			A	928840
203	29/05/2018	741922	CARRY OUT A SERVICE AS PER CHECK LIST		A	928383
203	28/05/2018	741682 Ops Entered - Fault - temp going	CLEAN RADIATOR - ROAD TESTED ok		NSW-ENG	928383
203	18/05/2018	739902 PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed		CAMPAIGN	926168
203	17/05/2018	739229 PLUG CYL HEAD B12BLE (PLASTIC)			NSW-ENG	925700
203	17/05/2018	739229 Fluid Leaks - Engine coolant leak O/R	Drained coolant Replaced leaking plug on bottom of engine topped up coolant and road test bus.		NSW-ENG	925700
203	17/05/2018	739229 CCTV - Time stamp wrong on camera	Changed time stamp to correct time		NSW-COM	925700
203	17/05/2018	739229 Consumables			NSW-BSW	926168
203	17/05/2018	739229 Body - Cracked windscreen	Fitted windscreen chip repair dots onto the chip		NSW-BSW	925700
203	17/05/2018	739229 Mechanic entered - Body Other windscreen stonechip	Fitted windscreen chip repair dots on chip.		NSW-BSW	925700
203	15/05/2018	738688	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with sadid		SAF-INSP	925393
203	15/05/2018	738688	VEHICLE SAFETY INSPECTION completed		SAF-INSP	925393
203	15/05/2018	738688	Carried out safety with sisil and matt. torqued all wheel nuts.		SAF-INSP	925393
203	15/05/2018	738688	Carried out safety with sisil and sadin. torqued all wheel nuts.		SAF-INSP	925393
203	15/05/2018	738710 BELT V-BELT COGGED TRI-POWER 17x1145mm			NSW-SCA	925393
203	15/05/2018	738710 Mechanic entered - A/C Heating Other belt missing	Matt Tognazzini fitted new belt		NSW-SCA	925393
203	15/05/2018	738710 Consumables			NSW-E&L	925700
203	15/05/2018	738710 Mechanic entered - Dash Dash_Lights Not Working 5 dash globe	Replaced 5 dash globes now work.		NSW-E&L	925393

203	15/05/2018	738710	GLOBE DASH 24V 1.2W BEIGE			NSW-E&L	925393
203	15/05/2018	738746	PERFORM CAMPAIGN 12/18 VOLVO B12BLE 120AMP ALTERNATOR UP	Refer to Alternator Replacement Service		CAMPAIGN	925393
203	15/05/2018	738746	BELT MICRO V SERPENTINE BELT 8 RIB 1660mm LONG			ALT-REPLACE	925393
203	15/05/2018	738746	BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230			ALT-REPLACE	925393
203	15/05/2018	738746		REPLACE ALTERNATORS		ALT-REPLACE	925393
203	08/05/2018	737467		Assisting		TYR	924116
203	08/05/2018	737467		Tensioned all rear tyres.		TYR	924116
203	08/05/2018	738746	B12BLE IDLER BRACKET PULLEY		Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G219418 Receiving #:227863 Date :2018-05-22	ALT-REPLACE	927170
203	08/05/2018	738746	TENSIONER ALTERNATOR BELT VO		Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G219418 Receiving #:227863 Date :2018-05-22	ALT-REPLACE	927170
203	08/05/2018	738746	ALTERNATOR 24V 120AMP VOLVO B		Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G219418 Receiving #:227863 Date :2018-05-22	ALT-REPLACE	927170
203	07/05/2018	737167	Consumables			NSW-E&L	924116
203	07/05/2018	737167	Mechanic entered - Elec and Light Other ABS warning light gl	Fit new globe		NSW-E&L	924070
203	07/05/2018	736035	Drv entered - Warning Lights Brakes	N/S/R brake assembly completed	callibrate rear brakeperform brake testroad test to check warning lightall OK and tensioned all rear wheel nuts with Alan	NSW-BRA	924070
203	07/05/2018	736035	GLOBE DASH 24V 1.2W BEIGE			NSW-BRA	924070
203	07/05/2018	736035	GLOBE DASH 24V 1.2W BEIGE			NSW-BRA	924070
203	05/05/2018	736909	Drv entered - Vandalism Vandalism/ Graffiti Interior	completed.		NSW-VAN	924070
203	04/05/2018	736035	SEAL HUB WHEEL REAR OUTER B12			NSW-BRA	924070
203	04/05/2018	736035	SEAL OIL SEAL INNER HUB (1076656)			NSW-BRA	924070
203	04/05/2018	736035	BRAKE BOOSTER REAR NEAR SIDE VOLVO B12BLE			NSW-BRA	924070
203	04/05/2018	736035	BOLT RR BRAKE CALIPER MTG VO		Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G219303 Receiving #:226680 Date :2018-05-04	NSW-BRA	924070
203	04/05/2018	736035	Drv entered - Warning Lights Brakes	O/S/R brake assembly completed.	Replaced N/S/R brake rotor and calliper C/O	NSW-BRA	924070
203	03/05/2018	736035	SEAL OIL SEAL INNER HUB (1076656)			NSW-BRA	924070
203	03/05/2018	736035	SEAL HUB WHEEL REAR OUTER B12			NSW-BRA	924070
203	03/05/2018	736035	Drv entered - Warning Lights Brakes	Replaced O/S/R brake calliperrotor and booster C/O		NSW-BRA	924070
203	03/05/2018	736035	DISC PADS REAR VOLVO B12BLE+B7RSA (20918891)(30G7502BERAL)			NSW-BRA	924070
203	03/05/2018	736035	DISC ROTOR MOUNTING KIT			NSW-BRA	924070
203	03/05/2018	736035	BRAKE DISC REAR VOLVO			NSW-BRA	924070
203	03/05/2018	736035	BRAKE BOOSTER REAR OUTER SIDE VOLVO B12BLE			NSW-BRA	924070
203	02/05/2018	736035	CALIPER BRAKE CALIPER REAR		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G219014 Receiving #:226558 Date :2018-05-03	NSW-BRA	924070
203	01/05/2018	736035	LHR BRAKE CALIPER B12BLE		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G219014 Receiving #:226572 Date :2018-05-03	NSW-BRA	924070
203	01/05/2018	736035	Drv entered - Warning Lights Brakes	removed rear wheel & N/R brake pads some one will continue		NSW-BRA	924070
203	30/04/2018	735581		CARRY OUT FIRE EXTINGUISHER TEST & TAG		FIRE EXT	923580
203	30/04/2018	735581		COMPLETED ON 15/02/18		FIRE EXT	923580
203	17/04/2018	733290	Consumables			NSW-E&L	921941
203	17/04/2018	733290	Consumables			NSW-E&L	921941
203	17/04/2018	733290	BELT MICRO V SERPENTINE BELT 8 RIB 1650mm LONG			NSW-E&L	921840
203	17/04/2018	733290	Elec and Light Flat Batteries	check replaced alternator belt idler pully bearing belt adjusted a/c beltes road test bus ok need to check rear brakes		NSW-E&L	921840
203	17/04/2018	733290	BEARING B12BLE IDLER PULLEY		Creditor #:GB-ST A101 STATEWIDE BEARINGS P/O #:G217969 Receiving #:225237 Date :2018-04-17	NSW-E&L	921840
203	17/04/2018	733318	DECAL PARK BRAKE/ NO WINDOW ACCES NEW			CAMPAIGN	921840
203	17/04/2018	733318	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BR	CHECKED HAS BEEN DONE ALREADY		CAMPAIGN	921840
203	03/04/2018	730395	Rectify Vandalism damage reported by refuelers	Done		NSW-VAN	917816
203	03/04/2018	730395	Vandalism Vandalism/ Graffiti InteriorGraffiti on rear	Cleaned		NSW-VAN	917816
203	29/03/2018	728506	Consumables			NSW-E&L	917570
203	29/03/2018	728506	RADIO AM/FM 12-24VOL (AX1503BT)			NSW-E&L	916952
203	29/03/2018	728506	Ops Entered - Fault - Elec and Light AM-FM Radio - Route: 8	fitted new radio		NSW-E&L	916952
203	22/03/2018	728519		re tensioned required wheels with Sadid.		TYR	915485
203	22/03/2018	728383	Consumables			NSW-E&L	915930
203	22/03/2018	728506	Ops Entered - Fault - Elec and Light AM-FM Radio - Route: 8	waiting for parts fitted new radio		NSW-E&L	915485
203	22/03/2018	728506	RADIO AM/FM 12-24VOLT (AX1503B)		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G216415 Receiving #:223590 Date :2018-03-22	NSW-E&L	915711
203	22/03/2018	728383	INDICATOR SIDE INDICATOR R/H			NSW-E&L	915485
203	22/03/2018	728383	LENS REVERSING & INT LIGHT			NSW-E&L	915485
203	22/03/2018	728384	DISC PADS FRONT VOLVO B7R/B10L/B12BLE (EARLY MODELS)			NSW-BRA	915485
203	21/03/2018	728359		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	915485
203	21/03/2018	728359		VEHICLE SAFETY INSPECTION		SAF-INSP	915485
203	21/03/2018	728382	Consumables			NSW-W&T	915711
203	21/03/2018	728382	TYRE 295/80R22.5 NEW			NSW-W&T	915485
203	21/03/2018	728382	Mechanic entered - Wheels and Tyres Worn Tyre pos 1 worn.	R/R pos 1 & 2 tyres. Pos 2 tyre back to rack. Tension the wheel nuts with Craig.		NSW-W&T	915485
203	21/03/2018	728383	Mechanic entered - Elec and Light Exterior Lights side f/o/s	R/R indicator and reverse light lenses. (with Craig)		NSW-E&L	915485
203	21/03/2018	728384	Mechanic entered - Brakes Other Front brake pads worn.	R/R front brake pads. Brake test and drive tested. Checked brake temp after road test. ok. (tension all the wheel nuts with Craig)		NSW-BRA	915485
203	19/03/2018	727474	Consumables			NSW-E&L	915229
203	19/03/2018	727474	GLOBE 24V 10W SINGLE CONTACT			NSW-E&L	914590
203	19/03/2018	727474	Mechanic entered - Elec and Light Exterior Lights Front RHS	replaced the globe		NSW-E&L	914590
203	14/03/2018	726121	Consumables			B	914223
203	14/03/2018	726121	Consumables			B	914223
203	14/03/2018	726121	Consumables			B	914223
203	14/03/2018	726121	Consumables			B	914223
203	14/03/2018	726121	SUMP PLUG WASHER B12B 30Z1000			B	913972
203	14/03/2018	726121	FILTER OIL FILTER VOLVO B7R			B	913972

203	14/03/2018	726121	FILTER FUEL FILTER			B	913972
203	14/03/2018	726121	FILTER FUEL FILTER VOLVO (20430751)			B	913972
203	14/03/2018	726121	FILTER OIL FILTER BYPASS VOLVO B10M+B7R (LF3654)(H200WN01)			B	913972
203	10/03/2018	726121		CARRY OUT B SERVICE AS PER CHECK LIST B Service Completed and tensioned all wheel nuts Mark J.		B	912681
203	10/03/2018	726121	Consumables			A	913125
203	10/03/2018	726121	Consumables			A	913125
203	10/03/2018	726121	Consumables			A	913125
203	10/03/2018	726121	Consumables			A	913125
203	10/03/2018	726121		CARRY OUT A SERVICE AS PER CHECK LIST		A	912681
203	02/03/2018	723931	Body - Windscreen chips	REPAIRED BY ALPHA		NSW-BSW	911438
203	27/02/2018	722891	Please remove any old poster and fit new ones multi choice	Fitted by Refuellers		CAMPAIGN	910722
203	16/02/2018	720300	DECAL SPECIAL NEEDS PASSENGER			NSW-BSW	908313
203	16/02/2018	720300	DECAL WHEELCHAIR			NSW-BSW	908313
203	16/02/2018	720300	Body Both disabled stickers in the disabled area need repla	replaced faded and damaged decals as reported. (waiting on more stock of special needs decals) to complete job.		NSW-BSW	908313
203	16/02/2018	720507	Brakes rear pads low	Assisting		NSW-BRA	908313
203	16/02/2018	720507	Brakes rear pads low	Replaced - calibrated - road tested OK		NSW-BRA	908313
203	16/02/2018	720507	DISC PADS REAR VOLVO B12BLE+B7RSA (20918891)(30G7502BERAL)			NSW-BRA	908313
203	02/02/2018	716264	HOSE -RETARDER B12BLE (30N0526)			NSW-ENG	905914
203	30/01/2018	716247				SAF-INSP	905325
203	30/01/2018	716247		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	905325
203	30/01/2018	716247		VEHICLE SAFETY INSPECTION		SAF-INSP	905325
203	30/01/2018	716264	Mechanic entered - Fluid Leaks Other Coolant hose leaking.	Assisting.		NSW-ENG	905325
203	30/01/2018	716264	Mechanic entered - Fluid Leaks Other Coolant hose leaking.	Drop the coolant and replaced coolant hose in the back aof transmission. Filled coolant drive tested and check coolant level and leaks Ok.		NSW-ENG	905325
203	25/01/2018	715538	Vandalism/ Graffiti Interior back of rear seat	Doubled up ref to defect #676825		NSW-VAN	904389
203	18/01/2018	714383	Consumables			NSW-E&L	903414
203	18/01/2018	714383	Consumables			NSW-E&L	903414
203	18/01/2018	714383	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)			NSW-E&L	903168
203	18/01/2018	714383	Mechanic entered - Elec and Light Exterior Lights side marke	removed old smashed led and wired in new one.		NSW-E&L	903168
203	14/01/2018	712367	AIR CONDITIONING SERVICE	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G211088 Receiving #:218529 Date :2018-01-15		AC-B	902631
203	10/01/2018	712367	Found faulty evap fans R & R 5 evap fans. Repair wiring. re	CARRY OUT A/C - A SERVICE AS PER CHECK LIST		AC-A	901444
203	09/01/2018	712367	FILTER DRYER AIR COND THERMO KING			AC-B	901444
203	09/01/2018	712367	Serviced by Coachair (Karu)	CARRY OUT A/C - B SERVICE AS PER CHECK LIST		AC-B	901444
203	09/01/2018	712367	COMPRESSOR OIL AIR CON			AC-B	901444
203	08/01/2018	712348	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	Fitted		CAMPAIGN	901444
203	03/01/2018	711275	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			TRANS-SERV	901087
203	03/01/2018	711275				TRANS-SERV	901087
203	03/01/2018	711275		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST		TRANS-SERV	901087
203	20/12/2017	709281	REPLACE DOT FILM ON MODESTY PA	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G210049 Receiving #:217240 Date :2017-12-21 REPLACED		NSW-VAN	899633
203	20/12/2017	709281	Vandalism - Replace DOT film on Modesty panel	Replaced		NSW-VAN	899367
203	18/12/2017	708638	A/C Heating - Air con n/w	Commission tested unable to fault		NSW-SCA	898160
203	15/12/2017	708428	Consumables			A	898359
203	15/12/2017	708428	Consumables			A	898359
203	15/12/2017	708428	Consumables			A	898359
203	15/12/2017	708428		CARRY OUT A SERVICE AS PER CHECK LIST A Service completed		A	898160
203	15/12/2017	708428		Assisted in A service		A	898160
203	14/12/2017	708091	Consumables			NSW-W&T	898160
203	14/12/2017	708091	Wheels and Tyres - Wheel indicators not aligned at front	re-tensioned all steer wheel nuts with neven as a precaution. nut pointers on both wheels re-aligned.		NSW-W&T	897651
203	11/12/2017	707346	Consumables			NSW-E&L	897415
203	11/12/2017	707346	GLOBE 24V 70W H1			NSW-E&L	897156
203	11/12/2017	707346	Mechanic entered - Elec and Light Exterior Lights Drivers si	replaced globe		NSW-E&L	897156
203	07/12/2017	706711		PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST		AIR-CHECK	896277
203	04/12/2017	704561	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G208323 Receiving #:216711 Date :2017-12-15 Anual RSI		RSI	898160
203	01/12/2017	705429	MUDFLAP 605MMX330MM			NSW-BSW	894627
203	01/12/2017	705429	Mechanic entered - Body Other	removed damaged (ost) mudflap. re-modelled new one and fitted. (ex. R.S.I.)		NSW-BSW	894627
203	01/12/2017	701919	REPAIR AIR GAUGE NOT WORKING	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G207275 Receiving #:216142 Date :2017-12-08		NSW-AIR	896446
203	01/12/2017	702076	REPAIR REAR CORNER OF THE BUS	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G207320 Receiving #:216043 Date :2017-12-07		NSW-ACC	896277
203	29/11/2017	704561		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	894627
203	29/11/2017	704561		VEHICLE SAFETY INSPECTION		SAF-INSP	894627
203	29/11/2017	704561		ANNUAL SAFETY INSPECTION SERIAL #		RSI	894627
203	29/11/2017	704995	Consumables			NSW-E&L	895122
203	29/11/2017	704995	GLOBE 24V 70W H1			NSW-E&L	894627
203	29/11/2017	704995	Elec and Light Exterior Lights - N/S headlight out.	removed head light found wires broken and terminal on earth melted so cut terminats crimped new ones and put new head light globe.checked and ok.		NSW-E&L	894627
203	28/11/2017	704628	Consumables			NSW-W&T	894831
203	28/11/2017	704628	Wheels and Tyres retension pos 12/34. wheelnuts.21/11/17	re-tensioned all drive wheel nuts with dulkith.		NSW-W&T	894627
203	28/11/2017	704630	Consumables			NSW-E&L	894831
203	28/11/2017	704630	GLOBE DASH 24V 1.2W BEIGE			NSW-E&L	894627
203	28/11/2017	704630	LED NO PLATE+EXIT LIGHT (26674)			NSW-E&L	894627
203	28/11/2017	704630		changed blown globes - dash and warning lights.		NSW-E&L	894627

203 28/11/2017	704630	replaced broken (osr) no. plate light.	NSW-E&L	894627
203 28/11/2017	704630 HALOGEN GLOBE 24V 20W (LAW/HAN)		NSW-E&L	894627
203 28/11/2017	704630 Mechanic entered - Elec and Light Interior Lights	changed blown globe - cab light.	NSW-E&L	894627
203 27/11/2017	704296 Consumables		NSW-W&T	894627
203 27/11/2017	704296 TYRE 295/80R22.5 RECAP		NSW-W&T	893914
203 27/11/2017	704296 Mechanic entered - Wheels and Tyres Worn	changed all drive tyres (worn). 295's fitted. all drive wheel nuts tensioned with dulkuith.	NSW-W&T	893914
203 20/11/2017	702076 Accident#:46279 - Ops Entered - Accident - Bus Hitting Obj	Completed by east coast	NSW-ACC	892495
203 17/11/2017	701919 Check and repair one air gauge not working	Repaired by lonsdale electrical	NSW-AIR	892444
203 13/11/2017	701073	PRE ANNUAL SAFETY INSPECTION CHECK	PRE RSI	891555
203 13/11/2017	701099 Consumables		NSW-E&L	892444
203 13/11/2017	701097 Consumables		NSW-E&L	892444
203 13/11/2017	701099 Elec and Light Interior light dull	fitted three new flurpo globes	NSW-E&L	891555
203 13/11/2017	701097 GLOBE DASH 24V 1.2W BEIGE		NSW-E&L	891555
203 13/11/2017	701097 Elec and Light Dash lights U/S	fitted two new globes	NSW-E&L	891555
203 13/11/2017	701101 Body Secure side panels	Secured	NSW-BSW	891555
203 13/11/2017	701101 Body Steam clean bus	Cleaned	NSW-BSW	891555
203 13/11/2017	701101 Body L/H/Side marker missing	Fitted	NSW-BSW	891555
203 13/11/2017	701101 BOLT BUMPER BAR BOLT SPECIAL		NSW-BSW	891555
203 13/11/2017	701101 REFLECTOR AMBER 94 X 44mm		NSW-BSW	891555
203 13/11/2017	701101 Please remove the 2 x Do Not Enter decals at the exterior	Done	CAMPAIGN	891555
203 10/11/2017	700688 Consumables		NSW-E&L	892345
203 10/11/2017	700688 Mechanic entered - Elec and Light Exterior Lights front park	Replaced N/S/F top park light globe	NSW-E&L	891555
203 06/11/2017	699818 CCTV Timestamp Incorrect Behind by approximately 1-2 hour	changed time parked bus	NSW-COM	891114
203 01/11/2017	698659 Vandalism - Replace Anti Graffiti film - L1	Replaced by Glassprotech	NSW-VAN	890568
203 01/11/2017	698974	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire safety	FIRE-SAFE	890568
203 31/10/2017	698659 REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G206267 Receiving #:213352 Date :2017-11-01 REPLACED L1	NSW-VAN	890568
203 30/10/2017	698144 Consumables		NSW-E&L	890110
203 30/10/2017	698144 Consumables		NSW-E&L	890110
203 30/10/2017	698144 Elec and Light - LH side corner clearance light missing	replaced (nsr) clearance light	NSW-E&L	889170
203 30/10/2017	698144 LAMP LED SIDE LAMP RED/AMBER PERE1 (52-98002)		NSW-E&L	889170
203 30/10/2017	697849 BUCKLE SEAT BELT TWIN WIRE GREY (SOB2123GY) (340446)		NSW-BSW	889170
203 30/10/2017	697849 Body Drivers Seat Belt broken	replaced broken driver's seat belt buckle.	NSW-BSW	889170
203 23/10/2017	695129 seat repairs	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT205517 Receiving #:212557 Date :2017-10-23	NSW-VAN	888149
203 18/10/2017	695139 Fluid Leaks - leaking coolant under the bus	ran bus for several minutes could not fault.	NSW-ENG	887349
203 17/10/2017	695129 Mechanic entered - Vandalism Vandalism/ Graffiti Interior 2	replaced 2 new seat base as needed	NSW-VAN	887349
203 17/10/2017	694993 Mechanic entered - Vandalism Vandalism/ Graffiti Interior on	preped and painted floor as needed	NSW-VAN	887349
203 17/10/2017	694877 Remove old poster and fit new A3 Posters and hangers	REPLACED BY REFUELLERS	CAMPAIGN	887349
203 14/10/2017	694190 PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	Completed	CAMPAIGN	887349
203 10/10/2017	693030 Consumables		NSW-E&L	886920
203 10/10/2017	693030 Consumables		NSW-E&L	886920
203 10/10/2017	693030 Mechanic entered - Elec and Light Exterior Lights front park	all lights checked - all o.k.	NSW-E&L	886698
203 10/10/2017	690890 Body - Fuel tank panel gas strut broken	replaced gas stays on last two panels (osr).	NSW-BSW	886698
203 05/10/2017	691752 AIRBAG AIR SPRING BELLOWS VOLVO B12BLE		NSW-SUS	885170
203 05/10/2017	691752 Suspension - NSF airbag leaking	replaced.	NSW-SUS	885170
203 05/10/2017	691752 Engine - Muffler tail pipe loose	remove and re fitted	NSW-ENG	885170
203 05/10/2017	690890 Body - Fuel tank panel gas strut broken	parts on order.	NSW-BSW	885170
203 05/10/2017	690890 GAS STRUT 500MM X 800NM	Creditor #:GB-MCN001 MCNAUGHTANS P/O #:G204156 Receiving #:211275 Date :2017-10-06	NSW-BSW	886203
203 02/10/2017	690774 Consumables		NSW-E&L	885527
203 02/10/2017	690774 Consumables		NSW-E&L	885527
203 02/10/2017	690774 Elec and Light - NSR indicator light needs to be secured	done.	NSW-E&L	885170
203 02/10/2017	690890 Accident#:46149 - Ops Entered - Accident - Bus Hitting Objec	replaced broken (nsf) exterior mirror.	NSW-ACC	885170
203 02/10/2017	690890 MIRROR LEFT HAND BRAZILIAN		NSW-ACC	885170
203 27/09/2017	690076	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	885070
203 27/09/2017	690076	VEHICLE SAFETY INSPECTION	SAF-INSP	885070
203 27/09/2017	690076	VEHICLE SAFETY INSPECTION	SAF-INSP	885070
203 26/09/2017	689586 PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	complete	NSW-BSW	884838
203 26/09/2017	689586 DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		NSW-BSW	884838
203 26/09/2017	689376	CARRY OUT FIRE EXTINGUISHER TEST & TAG	FIRE EXT	884583
203 26/09/2017	689376	Replaced by ATS on 24/09/17	FIRE EXT	884583
203 26/09/2017	689829 Remove old A3 Posters with Seniors Festival please leave	Replaced by Fleet Support	CAMPAIGN	884838
203 21/09/2017	688117 Drv entered - Body Drivers Seat Cover	secured loose driver's seat base cushion.	NSW-BSW	883980
203 13/09/2017	685716 DIRECT PURCHASE - VANDALISM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G202522 Receiving #:210048 Date :2017-09-18 CLEAN & PAINT AS REQUIRED	NSW-VAN	883433
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361 Consumables		A	882974
203 13/09/2017	686361	CARRY OUT A SERVICE AS PER CHECK LIST cCOMPLETE	A	882733

203	13/09/2017	686361	CARRY OUT A SERVICE AS PER CHECK LIST cCOMPLETE	A	882733
203	12/09/2017	686022	Accident#:46027 - Ops Entered - Accident - Bus is hit by 3r Completed on W/O 685284	NSW-ACC	882556
203	11/09/2017	685716	Vandalism Vandalism/ Graffiti Interior Repaired by ECTB	NSW-VAN	882277
203	11/09/2017	685716	Vandalism - Interior graffiti paint Repaired by ECTB	NSW-VAN	882277
203	08/09/2017	685285	Mechanic entered - Fluid Leaks Other added coolant - low.	NSW-ENG	881580
203	08/09/2017	685284	MIRROR RIGHT HAND BRAZILIAN	NSW-BSW	881580
203	08/09/2017	685284	Mechanic entered - Body Other OSF drivers side mirror broken replaced broken (osf) exterior mirror.	NSW-BSW	881580
203	07/09/2017	685048	Consumables	NSW-E&L	882004
203	07/09/2017	685048	GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)	NSW-E&L	881580
203	07/09/2017	685048	Mechanic entered - Elec and Light Exterior Lights park light replaced osf park light globe	NSW-E&L	881580
203	06/09/2017	684849	DIRECT PURCHASE - VANDALISM Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G202206 Receiving #:209385 Date :2017-09-07 REPLACED R2 REPLACED BY GLASSPROTECH 31/08/17	NSW-VAN	881859
203	06/09/2017	684849	Vandalism - Replace anti graffiti film - R2	NSW-VAN	881580
203	04/09/2017	684352	Consumables	NSW-E&L	881343
203	04/09/2017	684352	Mechanic entered - Elec and Light Exterior Lights OSF parkl Repaired wiring.	NSW-E&L	880430
203	04/09/2017	684173	AMBER REFLECTOR	NSW-BSW	880430
203	02/09/2017	684173	Body - Reflector near rear door missing Replaced	NSW-BSW	880430
203	25/08/2017	682706	Tensioned all rear tyres.	TYR	879361
203	25/08/2017	682706	Assisting.	TYR	879361
203	25/08/2017	682705	Consumables	NSW-E&L	879553
203	25/08/2017	682704	Consumables	NSW-E&L	879553
203	25/08/2017	682703	Consumables	NSW-E&L	879553
203	25/08/2017	682705	Mechanic entered - Elec and Light Exterior Lights front lef R/r globe	NSW-E&L	879361
203	25/08/2017	682704	Mechanic entered - Elec and Light Warning Light On Dash Checked - ok.	NSW-E&L	879361
203	25/08/2017	682703	Drv entered - Elec and Light Indicators Not Working R/R n/s /! globe	NSW-E&L	879361
203	24/08/2017	682356	Consumables	NSW-W&T	879361
203	24/08/2017	682356	Wheels and Tyres - NSR outer tyre low pressure changed tyres 3 (flat) and 6 (worn). all drive wheel nuts tensioned with ryan.	NSW-W&T	879168
203	22/08/2017	681865	Ops Entered - Fault - Warning Lights Temperature - Route; Checked cooling system. Steam cleaned intercooler / radiator and road tested - ok.	NSW-ENG	878625
203	18/08/2017	680586	GASKET ROCKER COVER GASKET VOLVO B12BLE (30A8519)	TUNE-UP	877305
203	18/08/2017	680586	GASKET ROCKER CVR KIT B12BLE 20710235	TUNE-UP	877305
203	18/08/2017	680886	B12BLE OIL+TEMP SENDER 4 PIN	NSW-ENG	877305
203	17/08/2017	680586		TUNE-UP	877305
203	17/08/2017	680586	GASKET ROCKER CVR KIT B12BLE 20710235	TUNE-UP	877305
203	17/08/2017	680586		TUNE-UP	877305
203	17/08/2017	680886	Engine - Oil pressure sender top of engine leaking oil Road tested bus for overheating - found ok. Turned on retarder switch.	NSW-ENG	877305
203	17/08/2017	680886	Engine - Oil pressure sender top of engine leaking oil Remove and replace oil pressure switch.	NSW-ENG	877305
203	14/08/2017	680053	Ops Entered - Fault - Warning Lights Temperature - Route; Checked and road tested bus - ok.	NSW-ENG	876855
203	03/08/2017	678059	Assisting	TYR	875130
203	03/08/2017	678059	retension pos 56 with phil.	TYR	875130
203	03/08/2017	677735	AIRBAG REAR VOLVO B12B/B12BLE (30Y2218) (70376911)	NSW-SUS	875130
203	03/08/2017	677735	FLOOR HATCH SCREWS 13405 + 30628	NSW-BSW	875130
203	02/08/2017	677727		SAF-INSP	875130
203	02/08/2017	677727	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	875130
203	02/08/2017	677727	VEHICLE SAFETY INSPECTION	SAF-INSP	875130
203	02/08/2017	677735	Consumables	NSW-W&T	875313
203	02/08/2017	677735	Wheels and Tyres - Replace tyres 56 Assisting	NSW-W&T	875130
203	02/08/2017	677735	Wheels and Tyres - Replace tyres 56 Replaced	NSW-W&T	875130
203	02/08/2017	677735	Suspension replace n/s rearair bages. R/R rear n/s front & rear air bags.	NSW-SUS	875130
203	02/08/2017	677728	Consumables	NSW-E&L	875313
203	02/08/2017	677728	Ops Entered - Fault - Elec and Light Indicators Not Working Assisted	NSW-E&L	875130
203	02/08/2017	677728	Ops Entered - Fault - Elec and Light Indicators Not Working Remove and replace o/s front side globe.	NSW-E&L	875130
203	02/08/2017	677735	Body - Floor hatch screw worn Fitted new screw	NSW-BSW	875130
203	27/07/2017	676423	Consumables	NSW-E&L	874257
203	27/07/2017	676423	Elec and Light Interior LightsFront Saloon is not workin fitted interior lights	NSW-E&L	874020
203	21/07/2017	675363	Consumables	NSW-E&L	873071
203	21/07/2017	675357	Consumables	NSW-E&L	873071
203	21/07/2017	675363	Mechanic entered - Elec and Light Exterior Lights O/S Top pa Checked OK	NSW-E&L	869468
203	21/07/2017	675357	GLOBE 24V 10W SINGLE CONTACT	NSW-E&L	869468
203	21/07/2017	675357	Drv entered - Elec and Light Exterior Lights found broken wire to park light plugs. Fitted male.female connectors and fitted new globe. Working fine.	NSW-E&L	869468
203	21/07/2017	675394	CCTV Timestamp Incorrect changed the time to the correct time	NSW-COM	869468
203	21/07/2017	675394	CCTV (None) fan is in view of driver camera needs to be pulled panel down removed fan drilled hole further to the right and resecured fan.Plugged up existing hole and put panel back up.Checked and ok also screen capped a photo.	NSW-COM	869468
203	21/07/2017	675394	Body - Rear RH side back seat rest broken re secured seat backs	NSW-BSW	869468
203	20/07/2017	671973	Consumables	NSW-E&L	872906
203	20/07/2017	671973	Elec and Light - OS front top park light u/s checked OK	NSW-E&L	869468
203	03/07/2017	671313	HOSE REDUCER HOSE 45 DEG SILICON 58x25mm 333	NSW-ECO	869111
203	01/07/2017	671313	Fluid Leaks - Replace leaking coolant hose. replaced two broken hoses road tested ok	NSW-ENG	869111
203	28/06/2017	670433	GLOBE 24V 70W H1	NSW-E&L	868433
203	28/06/2017	670433	Elec and Light - NS headlight out fitted new N/S headlight. Working ok.	NSW-E&L	868433
203	28/06/2017	670433	Consumables	NSW-E&L	868918

203	28/06/2017	670663	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	UPDATED		CAMPAIGN	868433
203	26/06/2017	669392	Elec and Light - water seperator n/w	checked impact. found vcds pro is needed to check function. now awaiting laptop to return from being updated. also would be handy if Ventura paid for access to correct wiring informatio		NSW-E&L	868306
203	26/06/2017	669392	Consumables			NSW-E&L	868433
203	22/06/2017	669392	Elec and Light - water seperator n/w	tested bus on road. seperator not receiving power. began tracing circuit. carry over.		NSW-E&L	868306
203	22/06/2017	669053	Remove old Green 2016/17 registration Label and/ or Blue EF	Replaced		NSW-BSW	868306
203	20/06/2017	668254	Consumables			NSW-E&L	868064
203	20/06/2017	668254	AMBER REFLECTOR			NSW-E&L	867550
203	20/06/2017	668254	Elec and Light - OSF top marker light n/w	replaced		NSW-E&L	867550
203	20/06/2017	668255	Consumables			C	868064
203	20/06/2017	668255	Consumables			C	868064
203	20/06/2017	668255	Consumables			C	868064
203	20/06/2017	668255		Assisting		C	867550
203	20/06/2017	668255		CARRY OUT C SERVICE AS PER CHECK LIST completed.		C	867550
203	20/06/2017	668255		Assisting		C	867550
203	20/06/2017	668255	FILTER AIR FILTER VOLVO B10M MK4 / B12 (AF4560) (E580L)			C	867550
203	20/06/2017	668255	KIT HALDEX CONDENSER KIT TOP (CYCLONE)			C	867550
203	20/06/2017	668255	KIT HALDEX COIL KIT MERCEDES 0500LE (49G0027)			C	867550
203	20/06/2017	668255	KIT CYCLONE CONDENSER VALVE KIT			C	867550
203	20/06/2017	668255	FILTER AIR DRYER SCANIA SR4 (1393551) (49G8709HALDEX)			C	867550
203	20/06/2017	668255	FILTER POWER STEER & HYD FAN VOLVO B12E (30M1602)			C	867550
203	20/06/2017	668255	Consumables			C	868064
203	20/06/2017	668255	Consumables			C	868064
203	20/06/2017	668255	Consumables			B	868064
203	20/06/2017	668255	Consumables			B	868064
203	20/06/2017	668255	Consumables			B	867550
203	20/06/2017	668255	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST		B	868064
203	20/06/2017	668255	Consumables			B	868064
203	20/06/2017	668255	Consumables			B	868064
203	20/06/2017	668255	Consumables			A	868064
203	20/06/2017	668255	Consumables			A	868064
203	20/06/2017	668255	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		A	867550
203	20/06/2017	668255	Consumables			A	868064
203	20/06/2017	668255	Consumables			A	868064
203	13/06/2017	667122		Tensioned pos 1 tyre.		TYR	865829
203	13/06/2017	667122		Assisting		TYR	865829
203	13/06/2017	666571	Consumables			NSW-W&T	866333
203	13/06/2017	666571	TYRE 11R22.5N NEW			NSW-W&T	865829
203	09/06/2017	666571	Wheels and Tyres - Tyre 1 worn	Replaced tyre pos1re-tensioned with Rene		NSW-W&T	865829
203	09/06/2017	666571	Suspension - LH upper control arm bushes worn	Removed tyre pos 1remove control arms fitted new bushesfitted armsfitted tyre and tensioed with Rene		NSW-SUS	865829
203	09/06/2017	666571	Suspension - LH lower control arm bushes worn	Tension all bolts on lower control arm n/slowered bus and removed hoists		NSW-SUS	865829
203	09/06/2017	666571	BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	865829
203	09/06/2017	666764	Consumables			B	866043
203	09/06/2017	666764	Consumables			B	866043
203	09/06/2017	666764	Consumables			B	866043
203	09/06/2017	666764	Consumables			B	866043
203	09/06/2017	666764	Consumables			B	866043
203	09/06/2017	666764	FILTER OIL FILTER BYPASS VOLVO B10M+B7R (LF3654)(H200WN01)			B	865829
203	09/06/2017	666764	SUMP PLUG WASHER B12B 30Z1000			B	865829
203	09/06/2017	666764	FILTER OIL FILTER LONG LIFE VOLVO B12BLE (H200W40)			B	865829
203	09/06/2017	666764	FILTER OIL FILTER LONG LIFE VOLVO B12BLE (H200W40)			B	865829
203	09/06/2017	666764	FILTER FUEL FILTER VOLVO B12BLE (H200WDK)			B	865829
203	09/06/2017	666764	FILTER OIL FILTER LONG LIFE VOLVO B12BLE (H200W40)			B	865829
203	09/06/2017	666764		CARRY OUT B SERVICE AS PER CHECK LIST		B	865829
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables			A	866043
203	09/06/2017	666764	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST		A	865829
203	08/06/2017	666571	Suspension - LH lower control arm bushes worn	Jack up bus with hoistsremove n/s lower control armsreplace bushes and fit new ones Fit control arms to bus c/o		NSW-SUS	865829
203	08/06/2017	666571	KIT BUSH KIT LOWER CONTROL ARM BUSHES VOLVO B10BLE			NSW-SUS	865829
203	02/06/2017	665300	Vandalism - Replace anti graffiti film - L124 R1	REPLACED		NSW-VAN	864915
203	01/06/2017	664951		VEHICLE SAFETY INSPECTION completed.		SAF-INSP	864741
203	01/06/2017	664951		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	864741
203	01/06/2017	664951		VEHICLE SAFETY INSPECTION completed.		SAF-INSP	864741
203	01/06/2017	665234	Drv entered - Warning Lights Brakes	Checked OK		NSW-BRA	864741
203	31/05/2017	664901		Assisting		TYR	864575

203	31/05/2017	664901	Tensioned all tyres.	TYR	864575
203	31/05/2017	664691 Wipers and Washers Wipers Not_Clearing Screen	Check OK	NSW-W&W	864575
203	31/05/2017	665300 REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G195085 Receiving #:202190 Date :2017-06-06 REPLACED L 124 R 1	NSW-VAN	865416
203	31/05/2017	664727 Consumables		NSW-E&L	864741
203	31/05/2017	664727 LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND		NSW-E&L	864575
203	31/05/2017	664727 GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)		NSW-E&L	864575
203	31/05/2017	664727 Drv entered - Elec and Light Exterior Lights	changed blown globe and replaced broken light fitting - (osf) bottom park / indicator light.	NSW-E&L	864575
203	31/05/2017	664663 DISC PADS FRONT VOLVO B7R/B10L/B12BLE (EARLY MODELS)		NSW-BRA	864575
203	31/05/2017	664663 DISC PADS REAR VOLVO B12BLE+B7RSA (20918891)(30G7502BERAL)		NSW-BRA	864575
203	30/05/2017	664663 Warning Lights Brakes	Assisting.	NSW-BRA	864575
203	30/05/2017	664663 Warning Lights Brakes	R/R all brake pads and tesnion wheel nuts with Phil.	NSW-BRA	864575
203	29/05/2017	663785 Consumables		NSW-E&L	864575
203	29/05/2017	663785 GLOBE 24V 21W SINGLE CONTACT (HLR2421)		NSW-E&L	864162
203	29/05/2017	663785 GLOBE 24V 3W INSTRUMENT		NSW-E&L	864162
203	26/05/2017	663785 Elec and Light - Rectify park lights and indicator lights n	R/R globes.	NSW-E&L	864007
203	26/05/2017	663785 Body - Rear door brackets loose.	Secured rear door bracket.	NSW-BSW	864007
203	23/05/2017	662922 Consumables		NSW-E&L	863516
203	23/05/2017	662922 Fit A3 Poster/Hangers	Fitted	NSW-E&L	863264
203	18/05/2017	662107 Consumables		NSW-E&L	862320
203	18/05/2017	662107 Elec and Light Indicators Not Working (Top LHS Indicator)	Check Ok	NSW-E&L	861771
203	13/05/2017	661057	re-tensioned nuts on wheels 5 and 6 with ranjith.	TYR	860997
203	12/05/2017	660907 Consumables		NSW-W&T	861088
203	12/05/2017	660907 Wheels and Tyres - TYRE 6 WORN	changed tyre 5 (wrong type of wheel) and 6 (worn). nuts tensioned with ryan.	NSW-W&T	860997
203	05/04/2017	654700 REFILL WIPER REFILL TO SUIT TX800 / TX900		SAF-INSP	854721
203	04/04/2017	654700	VEHICLE SAFETY INSPECTION	SAF-INSP	854721
203	04/04/2017	654700	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	854721
203	04/04/2017	654700	VEHICLE SAFETY INSPECTION	SAF-INSP	854721
203	10/03/2017	650376 CCTV Timestamp Incorrect behind by approx. 2hours	changed to correct time	NSW-COM	850480
203	09/03/2017	650262		TYR	849790
203	09/03/2017	650262	Tensioned pos 3 and 4 tyres	TYR	849790
203	09/03/2017	649993 Consumables		NSW-W&T	850480
203	09/03/2017	649993 Consumables		NSW-W&T	850480
203	09/03/2017	649993 TYRE 11R22.5R RECAP		NSW-W&T	849790
203	08/03/2017	649993 Mechanic entered - Wheels and Tyres Worn	Assisted	NSW-W&T	849790
203	08/03/2017	649993 Mechanic entered - Wheels and Tyres Worn	Replaced tyres position 3 and 4 and tensioned all wheel nuts with Alex	NSW-W&T	849790
203	08/03/2017	649821 AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G189085 Receiving #:196951 Date :2017-03-28	NSW-SCA	853126
203	08/03/2017	649821 A/C Heating - 1 evap blower motor faulty (Daniel 22c)	Replaced by Martin @ 22c	NSW-SCA	849790
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	850214
203	08/03/2017	649972 Consumables		A	849790
203	08/03/2017	649972	CARRY OUT A SERVICE AS PER CHECK LIST A Service Completed	A	849790
203	08/03/2017	649972	CARRY OUT A SERVICE AS PER CHECK LIST A Service Completed and tensioned all wheel nuts with Alex	A	849790
203	07/03/2017	649526 Fluid Leaks - Check for coolant leak	replaced transmission coolant hose road tested ok	NSW-ENG	849790
203	07/03/2017	649526 HOSE -RETARDER B12BLE		NSW-ENG	849790
203	07/03/2017	649526 Consumables		NSW-E&L	850213
203	07/03/2017	649526 Consumables		NSW-E&L	850213
203	07/03/2017	649526 GLOBE 24V 21W SINGLE CONTACT (HLR2421)		NSW-E&L	849790
203	07/03/2017	649526 Mechanic entered - Elec and Light Indicators Not Working O/F	replaced globe	NSW-E&L	849790
203	02/03/2017	648921 Ops Entered - Fault - Fluid Leaks Rear of bus - Route: -	R/R broken coolant hose. Top up coolant and steam washed the engine. Drive tested and check coolant level and leaks All ok.	NSW-ENG	849373
203	24/02/2017	647491 Consumables		NSW-E&L	848611
203	24/02/2017	647491 INVERTER 15-58W 24V T8 (49V2706)		NSW-E&L	848263
203	24/02/2017	647491 Elec and Light - Saloon fluoro lights some n/w	changed blown fluoro tube and replaced blown inverter - saloon lights.	NSW-E&L	848263
203	22/02/2017	646600 Consumables		NSW-E&L	848263
203	22/02/2017	646600 GLOBE 24V 21W SINGLE CONTACT (HLR2421)		NSW-E&L	847735
203	22/02/2017	646600 Mechanic entered - Elec and Light Indicators Not Working	changed blown globe (nsf) side indicator.	NSW-E&L	847735
203	20/02/2017	646141 Please remove any old poster and fit either Good News for T	Fitted by Fleet Support	CAMPAIGN	847488
203	17/02/2017	645559 PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE / DCC FITTED - YES TIME DISPLAYED - YES		CAMPAIGN	847333
203	15/02/2017	644800 AIR CONDITIONING SERVICE	Creditor #:GB-22C001 22 CELSIUS P/O #:G187565 Receiving #:194597 Date :2017-02-23 A SERVICE	AC-A	848263
203	15/02/2017	644800 DANIEL @ 22C - OPENED CLOSED WATER TAP	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	AC-A	846640
203	10/02/2017	644145	Assisted	TYR	845609
203	10/02/2017	644145	Tensioned pos 3 and 4 tyres	TYR	845609
203	10/02/2017	642387 SUPPLIES BODY SHOP SUPPLIES		NSW-ACC	845609
203	10/02/2017	642387 PAINT SUPPLIES		NSW-ACC	845609

203	09/02/2017	642387	Accident damage - O/S/F and Front - Acc # DAN 44890. THIRD P	Dismantled damaged front bar and os head light surround fibre repaired front bar and sanded painted 2 pac primer and white solid fitted to the bus fitted number plate and door valve replac	NSW-ACC	845609
203	08/02/2017	643451	Consumables		NSW-W&T	845609
203	08/02/2017	643451	Mechanic entered - Wheels and Tyres Wheel Nut Retension		NSW-W&T	844334
203	08/02/2017	643451	BRAKE BOOSTER REAR NEAR SIDE VOLVO B12BLE		NSW-BRA	844334
203	08/02/2017	643451	Brakes - NSR booster leak	fit new U/r brake booster.	NSW-BRA	844334
203	08/02/2017	642387	Accident damage - O/S/F and Front - Acc # DAN 44890. THIRD		NSW-ACC	844334
203	08/02/2017	642387	Accident damage -O/S/F and front Acc # 44890. *THIRD PARTY		NSW-ACC	844334
203	07/02/2017	643357		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	844334
203	07/02/2017	643357		VEHICLE SAFETY INSPECTION	SAF-INSP	844334
203	07/02/2017	643357			SAF-INSP	844334
203	02/02/2017	642306	Mechanic entered - Fluid Leaks Other	added coolant - low.	NSW-ENG	844334
203	02/02/2017	642306	Consumables		NSW-E&L	844574
203	02/02/2017	642352	Consumables		NSW-E&L	844574
203	02/02/2017	642306	HALOGEN GLOBE 24V 20W (LAW/HAN)		NSW-E&L	844334
203	02/02/2017	642306	Mechanic entered - Elec and Light Interior Lights	changed blown globe - centre door step light and fixed loose electrical connection - driver's cab light.	NSW-E&L	844334
203	02/02/2017	642352	Elec and Light - 1 saloon light out	changed blown fluro tube.	NSW-E&L	844334
203	02/02/2017	642306	Accident damage -O/S/F and front Acc # 44890. *THIRD PARTY	rebooked	NSW-ACC	844334
203	01/02/2017	628473	REPAIR GEAR BOX AS REQUIRE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G182635 Receiving #:194598 Date :2017-02-23	NSW-GEA	848263
203	01/02/2017	619332	Consumables		NSW-E&L	844574
203	01/02/2017	619332	SUPPLY ROLLAWAY RETROFIT	Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G182510 Receiving #:193531 Date :2017-02-10	NSW-E&L	845609
203	26/01/2017	641007		re-tensioned nuts on wheels 3 and 4 with dulkit.	TYR	843211
203	25/01/2017	640741	Consumables		NSW-W&T	843577
203	25/01/2017	640741	Wheels and Tyres - Tyre 3 worn	changed tyre #3 (worn). nuts tensioned with dulkit. steam cleaned dirty wheel.	NSW-W&T	843211
203	21/01/2017	636810	Mechanic entered - Wipers and Washers Washers Not Working	filled 'mt' washer bottle. fitted new washer pump - missing. operation checked - o.k.	NSW-W&W	842607
203	21/01/2017	636810	PUMP WIPER-WASHER 24 VOLT (80826TRICO)		NSW-W&W	842607
203	19/01/2017	639685	Consumables		NSW-E&L	842607
203	19/01/2017	639685	LED FRONT POSITION MARKER LIGHT		NSW-E&L	842153
203	19/01/2017	639685	Elec and Light - Emergency exit light not working	replaced dull / not working exit lights.	NSW-E&L	842153
203	16/01/2017	636810	DIRECT PURCHASE - AIR CONDITIONING	reversing incorrect d-ac entered	NSW-SCA	841831
203	16/01/2017	636810	DIRECT PURCHASE - AIR CONDITIONING		NSW-SCA	841831
203	16/01/2017	636810	BEARING		NSW-SCA	841831
203	16/01/2017	639059	Warning Lights Coolant	fit new trans cooler coolant hoseset up coolantroad tested ok.	NSW-ENG	841831
203	16/01/2017	639059	HOSE -RETARDER B12BLE		NSW-ENG	841831
203	13/01/2017	638679	Consumables		NSW-E&L	841831
203	13/01/2017	638679	GLOBE 24V 70W H1		NSW-E&L	839572
203	13/01/2017	638679	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	changed blown globe (os) low beam headlight.	NSW-E&L	839572
203	12/01/2017	636810	Ops Entered - Fault - A/C Heating Not Cooling - Route: 845	Remove and replaced weeping compressor hed to pull compressor outagain due to a striped compressor mont bolt helicoil all mount bolts and refit compressor pressure tested and vac c	NSW-SCA	839572
203	12/01/2017	636810	FIELD COIL CLUTCH AIR CON	Creditor #:GB-QTK001 QTK GROUP P/O #:G185254 Receiving #:191505 Date :2017-01-13	NSW-SCA	841831
203	12/01/2017	636810	BELT V-BELT COGGED TRI-POWER 17x1905mm SCANIA K230		NSW-SCA	841446
203	12/01/2017	636810	BELT V-BELT COGGED TRI-POWER 17x1145mm		NSW-SCA	841446
203	10/01/2017	636810	COMPRESSOR CHANGE OVER THERMOKING SCREW COMPRESSOR		NSW-SCA	840922
203	09/01/2017	637672	Consumables		NSW-E&L	840922
203	09/01/2017	637672	Ops Entered - Fault - Elec and Light Flat Batteries - Rout		NSW-E&L	840805
203	09/01/2017	637672	Elec and Light Flat Batteries	fitted new batteries. starting and holding charge fine/	NSW-E&L	840805
203	09/01/2017	637672	Elec and Light Flat Batteries	remove old batteries u/s. new ones to be fitted.	NSW-E&L	840805
203	09/01/2017	637672	BATTERY MAINTENANCE FREE N150 (EMFN150)		NSW-E&L	840805
203	09/01/2017	637707	LABEL HEADLIGHTS 8x25mm WHITE/BLACK		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL DOOR 1 WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL DOOR 1 WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	LABEL PARK BRAKE 8x25mm WHITE/BLACK		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL RETARDER WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL HAZARDS WHITE ON RED 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL DRIVERS FAN WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL DEMIST WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL SALOON LIGHT WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL STEP LIGHT WHITE ON GREEN 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	LABEL DURESS BUTTON 8x25mm RED/BLACK		CAMPAIGN	840805
203	09/01/2017	637707	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	fitted all dash labels/	CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL LOWER/RAISE WHITE ON YELLOW 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL KNEEL WHITE ON YELLOW 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	SWF SWITCH LABEL MASTER WHITE ON YELLOW 14x14mm		CAMPAIGN	840805
203	09/01/2017	637707	LABEL AIR CONDITIONING 8x25mm WHITE/BLACK		CAMPAIGN	840805
203	06/01/2017	636810	CONDENSOR FAN A/C CITI-RT		NSW-SCA	839676
203	06/01/2017	637200	Brakes - Noisy brake while brake application	check front brake pad clean road test bus ok.	NSW-BRA	839676
203	06/01/2017	637266	A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE CAMPAIGN A	REPLACED	CAMPAIGN	839676
203	05/01/2017	636810	Ops Entered - Fault - A/C Heating Not Cooling - Route: 845	Commission tested unit found that the right out side condensor fan motor had failed remove and replace tested ok compressor failed the performance teste and will need to be replaced	NSW-SCA	839572
203	04/01/2017	636600	Consumables		NSW-E&L	839572
203	04/01/2017	636600	check and repair doors not working	found body supply solenoid faulty. supervised pascal replacing solenoid. works ok. parked bus.	NSW-E&L	839409

203	04/01/2017	636600 SOLINOID 24V CONT. DUTY (SILVER CONTACT)ST88		NSW-E&L	839409
203	04/01/2017	636845 Fit New 2107 Large and Small Fares Small Concessionand AO	REPLACED	CAMPAIGN	839572
203	19/12/2016	634215 Consumables		NSW-E&L	837618
203	19/12/2016	634215 SWITCH INDICATOR CRUISE SUIT B12BLE VOLVO 30V4706		NSW-E&L	837383
203	19/12/2016	634215 Ops Entered - Fault - Elec and Light Indicators Not Working	R/R indicator stalk.	NSW-E&L	837383
203	09/12/2016	632503	completed	AIR-CHECK	835491
203	09/12/2016	632503	PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST did air system check with sisil	AIR-CHECK	835491
203	08/12/2016	631151 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G182796 Receiving #:189363 Date :2016-12-08	RSI	835716
203	07/12/2016	629976 Vandalism - Interior graffiti paint	Assisting	NSW-VAN	834700
203	07/12/2016	629976 Vandalism - Interior graffiti paint	rebooked	NSW-VAN	834700
203	06/12/2016	631794	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed fire safety inspection.	FIRE-SAFE	835399
203	02/12/2016	631222	VEHICLE SAFETY INSPECTION	SAF-INSP	834700
203	02/12/2016	631222	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	834700
203	02/12/2016	631151	ANNUAL SAFETY INSPECTION - RWC008063 - PASSED - 02/12/16	RSI	834700
203	02/12/2016	631233 Wipers and Washers U/S	Replaced	NSW-W&W	834700
203	02/12/2016	631233 BLADE WIPER BLADE 32 INCH		NSW-W&W	834700
203	02/12/2016	631233 Consumables		NSW-BSW	835092
203	02/12/2016	631233 Body Passanger seats protection covers broken	Replaced	NSW-BSW	834700
203	02/12/2016	631233 CAP END CAP CENTRA SEAT END CAP		NSW-BSW	834700
203	01/12/2016	628473 Remove gearbox for repair	BEUFORD - c/o box using Ecofluid A life	NSW-GEA	834700
203	01/12/2016	631090 Gearbox Driveline - Clean under carriage for RSI.	Steam cleaned under the bus.	NSW-GEA	834700
203	16/11/2016	628473 Remove gearbox for repair	Assisting with Ryan	NSW-GEA	834700
203	16/11/2016	628473 Remove gearbox for repair	Removed gear box and steam clean for repair	NSW-GEA	834700
203	15/11/2016	627886 DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G181474 Receiving #:188441 Date :2016-11-25 Tow bus from Keysborough.	NSW-OPS	834700
203	15/11/2016	627886 Breakdown#:32970 - Ops Entered - Breakdown - Breakdown Road	attended breakdownfound bus could not select gearstrans faulty. tow truck called.	NSW-OPS	834700
203	14/11/2016	627320 LINK SWAY BAR VOLVO FRONT		NSW-SUS	834700
203	14/11/2016	627320 Mechanic entered - Suspension Noisy rear axle sway bar link	replaced	NSW-SUS	834700
203	14/11/2016	627320 Fluid Leaks Header tank wobbling	fitted new nut	NSW-ENG	834700
203	14/11/2016	627595 Consumables		NSW-E&L	834700
203	14/11/2016	627320 Consumables		NSW-E&L	834700
203	14/11/2016	627595 INVERTER 24V 15-36W (KIRG)		NSW-E&L	834700
203	14/11/2016	627595 GLOBE DASH B7L		NSW-E&L	834700
203	14/11/2016	627595 Mechanic entered - Elec and Light Warning Light On Dash 4 ou	replaced 4 globes	NSW-E&L	834700
203	14/11/2016	627595 Mechanic entered - Elec and Light Interior Lights 2 INT tub	replaced 2 tube and invater	NSW-E&L	834700
203	14/11/2016	627320 Elec and Light Top O/S/R brake light cracks	checked ok. it's servicable	NSW-E&L	834700
203	14/11/2016	627320 REPAIR DOUBLE SEAT BASE RETRI	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G181209 Receiving #:187462 Date :2016-11-14	NSW-BSW	834700
203	14/11/2016	627320 REPAIR SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G181209 Receiving #:187462 Date :2016-11-14	NSW-BSW	834700
203	14/11/2016	627320 Body One passanger seat plastik kap missing		NSW-BSW	834700
203	14/11/2016	627320 VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		NSW-BSW	834700
203	14/11/2016	627320 Body secure side panels	completed	NSW-BSW	834700
203	14/11/2016	627320 CENTRA SEAT END CAPS		NSW-BSW	834700
203	14/11/2016	627320 BUTTON CLIPPARD DOOR VALVE 4924811		NSW-BSW	834700
203	14/11/2016	627320 Body One passanger seat plastik kap missing	fitted new one	NSW-BSW	834700
203	14/11/2016	627320 Body	5 passanger seat torn replaced	NSW-BSW	834700
203	14/11/2016	627320 Body FrontBumper door switch leaking air	replaced borth switch	NSW-BSW	834700
203	14/11/2016	627595 Consumables		A	834700
203	14/11/2016	627595 Consumables		A	834700
203	14/11/2016	627595 Consumables		A	834700
203	14/11/2016	627595 Consumables		A	834700
203	14/11/2016	627595 Consumables		A	834700
203	11/11/2016	627249	CARRY OUT A SERVICE AS PER CHECK LIST completed and tensioned wheel nut with Nevan	A	834700
203	11/11/2016	627320 Body FrontBumper door switch leaking air	PRE ANNUAL SAFETY INSPECTION CHECK completed with Matt	PRE RSI	834700
203	11/11/2016	627320 Body Paint mirrors	Painted the mirrors black.	NSW-BSW	834700
203	11/11/2016	627320 Body Paint mirrors	completed	NSW-BSW	834700
203	11/11/2016	627320 Body Steam clean all bus	Matt odne	NSW-BSW	834700
203	11/11/2016	627320 Body Paint mirrors		NSW-BSW	834700
203	11/11/2016	627320 Body Steam clean all bus	Steamed cleaned whole bus	NSW-BSW	834700
203	06/11/2016	625987 Body Front_Door Operation Faulty: front door bar is loose	adjust front door and repaired front door grab bars. bus ok.	NSW-BSW	833104
203	24/10/2016	623753 Fit A3 poster to holder either Explore Melbourne or PTV Ap	Fleet Support Replaced	CAMPAIGN	831565
203	13/10/2016	621699 Suspension - OSR top torque rod bush worn	fit new torque rod bushes.	NSW-SUS	829256
203	13/10/2016	621699 KIT TORQUE ROD BUSH KIT VOLVO B12BLE		NSW-SUS	829256
203	13/10/2016	621812 Consumables		NSW-E&L	829408
203	13/10/2016	621812 Elec and Light Two Way Radio: not working	checked ok.	NSW-E&L	829256
203	13/10/2016	621812 Drv entered - Elec and Light AM-FM Radio	CHECKED OK	NSW-E&L	829256
203	04/10/2016	619712 Consumables		NSW-E&L	827678
203	04/10/2016	619712 GLOBE 24V 10W SINGLE CONTACT		NSW-E&L	827215
203	04/10/2016	619712 Drv entered - Elec and Light Exterior Lights	changed blown globe (osf) top marker light.	NSW-E&L	827215
203	29/09/2016	619333	Tensioned all wheel nuts	TYR	827102

203	29/09/2016	619332 Consumables			NSW-E&L	827168
203	29/09/2016	619332 PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RF COMPLETED			NSW-E&L	827102
203	27/09/2016	618560 Consumables			NSW-BSW	827102
203	27/09/2016	618560 DECAL CUSTOMER ENQUIRY			NSW-BSW	826794
203	26/09/2016	617974 Suspension- O/S/r top torque rod bolts worn	Tight bolts		NSW-SUS	825780
203	26/09/2016	618560 A3 Poster Change please remove old poster and fit Vitorian	Completed by Fleet Support		NSW-BSW	826794
203	26/09/2016	618560 Body - Replace 1300 decal	Completed by Fleet Support		NSW-BSW	826794
203	23/09/2016	617843			SAF-INSP	825780
203	23/09/2016	617843	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	825780
203	23/09/2016	617843	VEHICLE SAFETY INSPECTION		SAF-INSP	825780
203	23/09/2016	617847 Wipers and Washers - loose	Repaired wiper		NSW-W&W	825780
203	23/09/2016	617846 Consumables			NSW-W&T	825979
203	23/09/2016	617846 Wheels and Tyres - pos 3 tyre worn	Assisting		NSW-W&T	825780
203	23/09/2016	617846 Wheels and Tyres - pos 3 tyre worn	replaced with r/o		NSW-W&T	825780
203	23/09/2016	617846 Consumables			NSW-E&L	825979
203	23/09/2016	617846 Drv entered - Elec and Light Exterior Lights	checked ok		NSW-E&L	825780
203	23/09/2016	617667 Consumables			NSW-BSW	825979
203	23/09/2016	617667 Ops Entered - Fault - Body Drivers Seat Controls - Route:	Swapped out old drivers seat and put new one in 203.		NSW-BSW	825780
203	12/09/2016	615312 Consumables			NSW-BSW	823853
203	12/09/2016	615312 Drv entered - Body Passenger Seat Torn	re-fitted pax. seat back cushion - fallen off and replaced broken seat base cushion securing clip (used one used).		NSW-BSW	823360
203	08/09/2016	614912 Ops Entered - Fault - Warning Lights Engine - Route: 857 -	Cleared all faults and road tested - ok.		NSW-ENG	823135
203	08/09/2016	614745 Consumables			NSW-E&L	823360
203	08/09/2016	614745 Mechanic entered - Elec and Light Exterior Lights	replaced smashed (nsr) clearance light.		NSW-E&L	823135
203	07/09/2016	614575 Consumables			NSW-E&L	823135
203	07/09/2016	614575 GLOBE 24V 10W SINGLE CONTACT			NSW-E&L	822868
203	07/09/2016	614575 Drv entered - Elec and Light Exterior Lights	changed blown globe (nsf) top marker light.		NSW-E&L	822868
203	30/08/2016	613021	re-tensioned all steer wheel nuts.		TYR	820981
203	29/08/2016	612092 BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	820769
203	29/08/2016	612092 Suspension - OS top torque rod bush worn	Replaced		NSW-SUS	820769
203	29/08/2016	612092 Consumables			NSW-E&L	820981
203	29/08/2016	612092 Check ABS light stay on	removed pos 2 wheel and fitted back also tention wheel nuts with sisit		NSW-E&L	820769
203	29/08/2016	612092 ABS SENSOR REAR DISC B12BLE			NSW-E&L	820769
203	29/08/2016	612092 Check ABS light stay on	Replace wheel speed sensor - road tested OK		NSW-E&L	820769
203	25/08/2016	612092 AIRBAG REAR VOLVO B12B / B12BLE (30Y2218)			NSW-SUS	820769
203	25/08/2016	612092 Suspension - N/S/R/R and O/S/R airbag leaking minor.	replaced both rear rear air bags.		NSW-SUS	820769
203	25/08/2016	612092 check the engine oil	check oil leak topped up 5L of oil.		NSW-ENG	820769
203	25/08/2016	611950 UNREPORTED - Front bumper damaged	later		NSW-ACC	820769
203	19/08/2016	610953 SUMP PLUG WASHER B12B 30Z1000			B	819456
203	19/08/2016	610953 FILTER FUEL FILTER WATER SEPERATOR VOLVO B12BLE (H700WK)			B	819456
203	19/08/2016	610953 FILTER FUEL FILTER VOLVO B12BLE (H200WDK)			B	819456
203	19/08/2016	610953 FILTER OIL FILTER LONG LIFE VOLVO B12BLE (H200W40)			B	819456
203	19/08/2016	610953	CARRY OUT B SERVICE AS PER CHECK LIST		B	819456
203	19/08/2016	610953			B	819456
203	19/08/2016	610953 FILTER OIL FILTER BYPASS VOLVO B10M+B7R (LF3654)(H200WN01)			B	819456
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953 Consumables			B	819599
203	19/08/2016	610953	CARRY OUT A SERVICE AS PER CHECK LIST		A	819456
203	19/08/2016	610953 Consumables			A	819599
203	19/08/2016	610953 Consumables			A	819599
203	19/08/2016	610953 Consumables			A	819599
203	19/08/2016	610953 Consumables			A	819599
203	19/08/2016	610953 Consumables			A	819599
203	18/08/2016	610572 CCTV Timestamp Incorrect Adjust backwards by 1 hour.	time adjusted backwards onke hour. showing correct time.		NSW-COM	818989
203	16/08/2016	610033	re-tensioned all drive wheel nuts.		TYR	818662
203	15/08/2016	609885 Consumables			NSW-W&T	818791
203	15/08/2016	609885 TYRE 11R22.5R RECAP			NSW-W&T	818662
203	15/08/2016	609885 Wheels and Tyres - Worn out tyre 6	changed tyres 4; 5 and 6 (worn). all drive wheel nuts tensioned.		NSW-W&T	818662
203	15/08/2016	609886 Mechanic entered - Vandalism Vandalism/ Graffiti Exterior	removed.		NSW-VAN	818662
203	05/08/2016	608299	re-tensioned nuts on wheels 1 and 2.		TYR	816926
203	05/08/2016	608950 Consumables			NSW-E&L	817164
203	05/08/2016	608950 Elec and Light - Destination Upgrade	Completed		NSW-E&L	816926
203	03/08/2016	607921 Consumables			NSW-W&T	816926
203	03/08/2016	607921 TYRE 11R22.5N NEW			NSW-W&T	816846
203	03/08/2016	607921 Mechanic entered - Wheels and Tyres Worn	changed tyres 1 (worn) and 2 (rack). all steer wheel nuts tensioned.		NSW-W&T	816846
203	03/08/2016	607851 Fluid Leaks - Leaking oil	fixed oil leak from top of engine clean road test bus serviceble.		NSW-ENG	816846

203	03/08/2016	607909 Consumables			NSW-BSW	816926
203	03/08/2016	607909 Body - Remove till tray	done.		NSW-BSW	816846
203	01/08/2016	607008 Vandalism - Replace 6 x windows including tint (3 x O/S/R a	p/o is attached to w/o 603676		NSW-VAN	816223
203	01/08/2016	606869 Consumables			NSW-E&L	816619
203	01/08/2016	606869 Elec and Light - Bus wont start	replaced fire warning sensor and oil pipe near starter motor. pti'd fuelled and parked bus ok.		NSW-E&L	816223
203	01/08/2016	606869 INTERIOR LIGHT DIFFUSER PER METRE			NSW-E&L	816223
203	01/08/2016	606869 Mechanic entered - Elec and Light Interior Lights	replaced 2 globes and one broken light defuser. working ok		NSW-E&L	816223
203	01/08/2016	607509 Consumables			NSW-BSW	816619
203	01/08/2016	607509 Please remove old poster and fit Route 709 A3 POSTER	n/a		NSW-BSW	816223
203	29/07/2016	606869 B12BLE OIL FEED PIPE BLOCK TO	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G173599 Receiving #:179636 Date :2016-07-29		NSW-ENG	816493
203	29/07/2016	606869 Consumables			NSW-E&L	816493
203	29/07/2016	606869 STARTER MOTOR DH12D	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G173557 Receiving #:179719 Date :2016-08-02		NSW-E&L	816619
203	29/07/2016	606869 Elec and Light - Bus wont start	removed old starter fit new starter. temporarily fixed fire sensor. drove bus to a1 winscreens carry over.		NSW-E&L	816223
203	28/07/2016	603676 Vandalism - Replace 6 x windows including tint (3 x O/S/R a	/refer next job booked for the 29/07/2016		NSW-VAN	813936
203	28/07/2016	606869 Elec and Light - Bus wont start	Found starter n/w towed bus to red sq after getting more gas for towtag		NSW-E&L	816223
203	28/07/2016	606541 CAMERA INTERNAL 2.1mm LENS			NSW-COM	816223
203	28/07/2016	606541 In line with Campaign:1. Identify CCTV DVR type fitted to	CCTV DVR type is (X5 MII)		NSW-COM	816223
203	28/07/2016	606541 -Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	fitted new 2.1mm camera. working ok. checked angles and all is ok		NSW-COM	816223
203	27/07/2016	606293 CCTV Not working	found harddrive not locked in place. unit will not power up if the harddrive is not installed correctly. found one camera with video loss repaired power cable to camera working ok.		NSW-COM	816223
203	26/07/2016	606138 Consumables			NSW-E&L	816223
203	26/07/2016	605951 Consumables			NSW-E&L	816223
203	26/07/2016	606138 Ops Entered - Fault - Elec and Light Indicators Not Working	REAR N/S INDICATOR wasnt secured good. screwed it back into place and it it ok.		NSW-E&L	815878
203	26/07/2016	605951 GLOBE 24V 70W H1			NSW-E&L	815878
203	26/07/2016	605951 Mechanic entered - Elec and Light Exterior Lights	changed blown globe (ns) low beam headlight.		NSW-E&L	815878
203	25/07/2016	605833 Drv entered - Warning Lights Brakes	Clean inactive cods		NSW-BRA	815878
203	25/07/2016	605832 Brakes - ABS light staying on	Clean inactive cods - road tested OK		NSW-BRA	815878
203	21/07/2016	605332			NSW-BRA	815413
203	21/07/2016	605332	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	815413
203	21/07/2016	605332	VEHICLE SAFETY INSPECTION		SAF-INSP	815413
203	21/07/2016	605412 Consumables			NSW-E&L	815564
203	21/07/2016	605412 Elec and Light - replace fluro tube	Replaced		NSW-E&L	815413
203	05/07/2016	602172 PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	fleet support		NSW-BSW	812346
203	01/07/2016	603676 Vandalism - Replace 6 x window	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G172415 Receiving #:179674 Date :2016-08-01		NSW-VAN	816493
203	01/07/2016	606869 FIRE SENSOR	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G173635 Receiving #:179703 Date :2016-08-01		NSW-E&L	816619
203	30/06/2016	600895	re-tensioned nuts on wheels 1 and 2.		TYR	811295
203	28/06/2016	600575 Steering - Shaky steering while braking	ref to w/o 600594		NSW-STE	811108
203	28/06/2016	600263 Ops Entered - Fault - Body Windows Front - Route: 848 - Da			NSW-BSW	811108
203	28/06/2016	600263 Replace front screen	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G171026 Receiving #:177069 Date :2016-06-28		NSW-BSW	811108
203	28/06/2016	600594 DISC PADS FRONT VOLVO EARLY MODELS B7R B10L B12BLE			NSW-BRA	811108
203	28/06/2016	600594 CALIPER BRAKE CALIPER LH VOLVO B12BLE			NSW-BRA	811108
203	28/06/2016	600594 Brakes Replace front brake pads	assisted kuma		NSW-BRA	811108
203	28/06/2016	600594 Brakes Replace front brake pads	replaced front rake pads road tested		NSW-BRA	811108
203	15/06/2016	597542 WIPER REFILL SUIT TX800+TX900			NSW-W&W	808832
203	14/06/2016	597542 Drv entered - Wipers and Washers Wipers Not_Clearing Screen	replaced rubber wiper blades		NSW-W&W	808832
203	14/06/2016	597385 Please remove any old poster and fit new A3 poster and add	done by fleet support		NSW-BSW	808832
203	30/05/2016	594608 PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INS	Already fitted		NSW-BSW	806343
203	30/05/2016	594563 Consumables			A	806497
203	30/05/2016	594563 Consumables			A	806497
203	30/05/2016	594563 Consumables			A	806497
203	30/05/2016	594563 Consumables			A	806497
203	30/05/2016	594563	completed		A	806343
203	30/05/2016	594563	CARRY OUT A SERVICE AS PER CHECK LIST A service completed		A	806343
203	25/05/2016	593781			SAF-INSP	805138
203	25/05/2016	593781	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		SAF-INSP	805138
203	25/05/2016	593781	VEHICLE SAFETY INSPECTION		SAF-INSP	805138
203	25/05/2016	593810 Consumables			NSW-E&L	805363
203	25/05/2016	593783 Consumables			NSW-E&L	805363
203	25/05/2016	593810 Elec and Light - Replace interior globe	Replaced		NSW-E&L	805138
203	25/05/2016	593783 Elec and Light Interior light n/w	Replaced globe		NSW-E&L	805138
203	23/05/2016	593045 Consumables			NSW-E&L	804929
203	23/05/2016	593045 GLOBE 24V 21W SINGLE CONTACT HLR2421			NSW-E&L	804001
203	23/05/2016	593045 GLOBE WEDGE INSTRUMENT 24V 5W (17197)			NSW-E&L	804001
203	23/05/2016	593045 Mechanic entered - Elec and Light Exterior Lights	changed blown globes (osf) bottom park and indicator lights.		NSW-E&L	804001
203	18/05/2016	592250 Body Drivers Seat Belt: lap sash will not release	move position of seat belt mechanism and tighten. checked for operation - o.k.		NSW-BSW	803262
203	13/05/2016	591493	re-tensioned all drive wheel nuts.		TYR	802713
203	12/05/2016	591272 GLOBE H1 24V 70W			NSW-BSW	802713
203	12/05/2016	591272 Body R/H low beam out	changed blown globe (os) low beam headlight.		NSW-BSW	802713
203	12/05/2016	591418 Brakes calibrate rear brake.	done		NSW-BRA	802713

203	12/05/2016	591289 Brakes - Rear brake pad needs replacing	Replaced	NSW-BRA	802713
203	12/05/2016	591289 REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	802713
203	12/05/2016	591289 Brakes - Rear brake pad needs replacing	removed wheels checked brakes with ranjith replaced pads.got ranjith to check all ok.	NSW-BRA	802713
203	11/05/2016	588000 Body Driver seat cushion worn and back seat excessive play.	removed old seat and fitted new seat	NSW-BSW	802426
203	06/05/2016	588000 SEAT ASSY ISRI A6008 AIR LUMB	Creditor #:GB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:G167238 Receiving #:173319 Date :2016-05-06	NSW-BSW	801977
203	05/05/2016	589720 BEARING B12BLE IDLER PULLEY	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G167371 Receiving #:173350 Date :2016-05-09	NSW-ENG	801977
203	04/05/2016	589720 B12BLE BELT TENSIONER		NSW-ENG	801254
203	04/05/2016	589720 Ops Entered - Fault - Engine Belts_Loose Noisy Missing - Ro	replaced alternator idler pulley and tensioner. fit new alternator belt. working ok. completed p.t.i ok.	NSW-ENG	801254
203	04/05/2016	589720 BELT ALT BELT B12BLE		NSW-ENG	801254
203	28/04/2016	589337 SEAT ASSY ISRI A6008 AIR LUMB	Creditor #:GB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:G166739 Receiving #:172905 Date :2016-04-29	NSW-BSW	800589
203	22/04/2016	588000 Suspension rear sway bar Dbush worn.	D bushes still servicable	NSW-SUS	799862
203	22/04/2016	588000 Body Driver seat cushion worn and back seat excessive play.	Remove drivers seat n waiting for seat from knox depotwrong one delivered re-fit driver seatput back line one bus u/s	NSW-BSW	799862
203	18/04/2016	586887 Consumables		NSW-E&L	799174
203	18/04/2016	586887 Elec and Light front top parking light out	changed blown globe (osf) top park light.	NSW-E&L	798672
203	18/04/2016	586887 GLOBE S/CONTACT 24V-10W		NSW-E&L	798672
203	18/04/2016	586887 Drv entered - Elec and Light Exterior Lights	changed blown globe (osf) top park light.	NSW-E&L	798672
203	24/03/2016	583083		NSW-E&L	794832
203	24/03/2016	583083	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	794832
203	24/03/2016	583083	VEHICLE SAFETY INSPECTION	SAF-INSP	794832
203	21/03/2016	582261 Consumables		NSW-E&L	794292
203	21/03/2016	582261 SWITCH INDICATOR CRUISE SUIT B12BLE VOLVO 30V4706		NSW-E&L	793418
203	21/03/2016	582261 Ops Entered - Fault - Elec and Light Indicators Not Working	removed indicator stalk.Had to go to moorabinn and pick up indicator stalk.Came back and fitted it.	NSW-E&L	793418
203	17/03/2016	580306 CCTV - Fit new CCTV upgrade	Creditor #:GB-TH0005 THOREB AUSTRALIA PTY LTD P/O #:G163931 Receiving #:170910 Date :2016-03-31	NSW-COM	795553
203	09/03/2016	580306 CCTV - Fit new CCTV upgrade	Picked bus from Volgren	NSW-COM	792084
203	09/03/2016	580306 CCTV - Fit new CCTV upgrade	completed by volgren 09/03/16	NSW-COM	792084
203	29/02/2016	578811 Consumables		A	790829
203	29/02/2016	578811 Consumables		A	790829
203	29/02/2016	578811 Consumables		A	790829
203	29/02/2016	578811 Consumables		A	790829
203	29/02/2016	578811		A	790747
203	29/02/2016	578811	CARRY OUT A SERVICE AS PER CHECK LIST Complete	A	790747
203	22/02/2016	575574 BODY SHOP SUPPLIES		NSW-VAN	787600
203	22/02/2016	575574 PAINT SUPPLIES		NSW-VAN	787600
203	20/02/2016	575574 Vandalism - Graffiti Inside of Bus / Fleet Support have atte	Painted over	NSW-VAN	787600
203	20/02/2016	575574 Drv entered - Vandalism Vandalism Graffiti Interior	Painted over	NSW-VAN	787600
203	11/02/2016	575574 Drv entered - Vandalism Vandalism Graffiti Interior	painted most of the bus still afew panels to be done ran out of rollers.	NSW-VAN	787600
203	11/02/2016	575286 Consumables		NSW-E&L	787838
203	11/02/2016	575286 AM/FM ANTENNA		NSW-E&L	787600
203	11/02/2016	575286 Drv entered - Elec and Light AM-FM Radio	removed and replaced am/fm radio and harness.found scratchy so replaced antenna as well as was broken.	NSW-E&L	787600
203	11/02/2016	575286 RADIO AM/FM 12-24VOLT (AV8141)		NSW-E&L	787600
203	03/02/2016	573805 Consumables		NSW-E&L	786601
203	03/02/2016	573805 GLOBE S/CONTACT 24V-10W		NSW-E&L	786372
203	03/02/2016	573805 Drv entered - Elec and Light Exterior Lights	change os top park light globe.	NSW-E&L	786372
203	22/01/2016	571835	VEHICLE SAFETY INSPECTION	SAF-INSP	784889
203	22/01/2016	571835	VEHICLE SAFETY INSPECTION	SAF-INSP	784889
203	22/01/2016	571835	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	784889
203	19/01/2016	568633 Consumables		NSW-E&L	784405
203	19/01/2016	568633 Drv entered - Elec and Light AM-FM Radio	Checked now OK	NSW-E&L	782402
203	19/01/2016	571049 DECAL PTV METRO MYKI DECAL LARGE 450x330mm		NSW-BSW	784405
203	19/01/2016	571732 The Campaign requires all Bus destinations systems to be in	16 X 100 N/A N/A	NSW-BSW	784405
203	19/01/2016	571049 PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS		NSW-BSW	784405
203	14/01/2016	569769 Consumables		NSW-E&L	783810
203	14/01/2016	569769 B12BLE BELT TENSIONER		NSW-E&L	783387
203	14/01/2016	569769 BELT ALT BELT B12BLE		NSW-E&L	783387
203	13/01/2016	569769 Elec and Light Alternator belt tensioner seased	Replaced alternator belt and tensioner. Drive tested... Ok	NSW-E&L	783387
203	07/01/2016	568608 Ops Entered - Fault - Body Front_Door Operation Faulty - R	Checked no fault found	NSW-BSW	782083
203	06/01/2016	568633 Elec and Light - Fuel pump door & interior lights u/s	Look for defect	NSW-E&L	782083
203	06/01/2016	568633 Drv entered - Elec and Light AM-FM Radio	No power to accessories c/o	NSW-E&L	782083
203	04/01/2016	566963 CONDENSOR FAN A/C CITI-RT		AC-B	781602
203	04/01/2016	566963 AIR CON REFRIDGERANT		AC-B	781602
203	04/01/2016	566963 COMPRESSOR OIL AIR CON		AC-B	781602
203	04/01/2016	566963 FILTER DRIER A/C THERMO KING		AC-B	781602
203	29/12/2015	566963	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	AC-B	780809
203	29/12/2015	566963 20AMP BLADE FUSE		AC-B	780809
203	29/12/2015	566963	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	AC-A	780809
203	12/12/2015	564563	PERFORM ANNUAL AIR SYSTEM CHECK AS PER CHECK LIST	AIR SYS CHEC	778796
203	07/12/2015	562320 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G158847 Receiving #:164976 Date :2015-12-10	RSI	778516
203	04/12/2015	562320 PLASTIC TRIANGLE HANDSTRAP GREY		NSW-BSW	776725

203	04/12/2015	562320	Mechanic entered - Body Other grab strap torn.	fit new strap.	NSW-BSW	776725
203	03/12/2015	562320		ANNUAL SAFETY INSPECTION - RWC 046243 - PASSED - 04/12/15	RSI	776725
203	03/12/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected Se	road tested and check a/c ok.	NSW-OPS	776725
203	03/12/2015	563049	steemclean for RSI		NSW-ENG	776725
203	03/12/2015	560643	V-BELT		NSW-ENG	776725
203	03/12/2015	560643	FANBELT V BELT 17 X 1100 COGGED		NSW-ENG	776725
203	03/12/2015	560643	Mechanic entered - Engine Belts_Loose Noisy Missing	Fit Ac Belts with Neven	NSW-ENG	776725
203	03/12/2015	563047	Body Driver compartment coner cover missing	manufactured new interior trim panel painted fitted job completed	NSW-BSW	776725
203	02/12/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected Se	replaced air dryer unloader valve clean air dryer housing recit water sepeter. steam clean engine and wheels road tested.	NSW-OPS	776725
203	02/12/2015	560643	CYCLONE CONDENSER VALVE KIT		NSW-AIR	776725
203	02/12/2015	560643	HALDEX CONDENSER KIT TOP(CYCLONE)		NSW-AIR	776725
203	02/12/2015	560643	VOLVO UNLOADER VALVE HALDEX 12bar		NSW-AIR	776725
203	02/12/2015	560643	FILTER AIR DRYER SCANIA SR4 (1393551)(49G8709HALDEX)		NSW-AIR	776725
203	01/12/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected Se		NSW-OPS	776725
203	30/11/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected Se	remove air compressor and wayer pump. fit air compressor and water pump topped up coolant.	NSW-OPS	777532
203	30/11/2015	560643	SEAL COOL PIPE G/BOX TO T/STAT HOUSING B7L		NSW-ECO	777532
203	30/11/2015	560643	O/RING W/PUMP B12BLE		NSW-ECO	777532
203	30/11/2015	560643	WATER PUMP O RING B12BLE		NSW-ECO	777532
203	30/11/2015	560643	VALVE SAFETY AIR DRYER		NSW-AIR	777532
203	30/11/2015	560643	O RING COMPRESSOR MOUNT SCANIA L94		NSW-AIR	777532
203	30/11/2015	560643	SEAL COMPRESSOR MK4		NSW-AIR	777532
203	26/11/2015	561376	DECAL MAKE YOUR MARK		NSW-BSW	777532
203	26/11/2015	561376	Camapign 20/15 Audit & Update of Safety Decals.Requires a		NSW-BSW	777532
203	24/11/2015	560643	VALVE SAFETY BLOW OFF 1.3MP 30G0308		NSW-OPS	777532
203	24/11/2015	560643	AIR COMPRESSOR B12BLE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G158492 Receiving #:164066 Date :2015-11-24	NSW-AIR	777532
203	23/11/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected S	Assisted Shalen in Traffic Management.	NSW-OPS	777532
203	23/11/2015	560643	Ops Entered - Breakdown - Breakdown Road Defect Unaffected S	Found A/C compressor bearing ran hotchopped belts.Also leaking air from purge tank.Arranged Tow.	NSW-OPS	777532
203	23/11/2015	560643	DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G158794 Receiving #:164323 Date :2015-12-01 FROM CNR OF WELLINGTON & JACKSONS RD TO DANDY DEPOT	NSW-OPS	777532
203	20/11/2015	559973	Remove Old Poster and Fit new All Night Public Transport Po	completed	NSW-BSW	777277
203	18/11/2015	559538		re-tensioned all wheel nuts with ranjith.	TYR	776725
203	18/11/2015	559350	RADIO/CD PLAYER 12V	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G158246 Receiving #:163922 Date :2015-11-18	NSW-E&L	776862
203	18/11/2015	559350	Consumables		NSW-E&L	776862
203	18/11/2015	559350	VOLVO UNLOADER VALVE HALDEX 12bar		NSW-AIR	776725
203	17/11/2015	559016	TYRE RECAP 11R22.5R	POS 3&4&5&6	NSW-W&T	776725
203	17/11/2015	559016	fit new tyres for pos 5 and 6	changed pos 5 and 6	NSW-W&T	776725
203	17/11/2015	559016	L/H rear inner tyre worn	Fitted new tyres for pos 3 and 4	NSW-W&T	776725
203	17/11/2015	559016	Consumables		NSW-W&T	776725
203	17/11/2015	559176	PERFORM CAMPAIGN 16/15 VOLVO STEERING COLUMN ADJUSTMENT	Not applicable	NSW-STE	776725
203	17/11/2015	559016	fit new coolant level sensor	replaced	NSW-ENG	776725
203	17/11/2015	559016	fit new coolant drain plug	replaced	NSW-ENG	776725
203	17/11/2015	559350	Drv entered - Elec and Light AM-FM Radio	removed radio running on 12volt system so order 12 volt radio.	NSW-E&L	776725
203	17/11/2015	559016	ENGINE DRAIN FITTING		NSW-ECO	776725
203	17/11/2015	559247	REPLACE DESTO GLASS	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G158209 Receiving #:163874 Date :2015-11-18	NSW-BSW	776725
203	17/11/2015	559016	steam clean bus for RSI	steamed clean bus	NSW-BSW	776725
203	17/11/2015	559016	enginr bay door struts worn/leaking	Fit new struts	NSW-BSW	776725
203	17/11/2015	559016	engine bay door hinge loose	secured hings	NSW-BSW	776725
203	17/11/2015	559016	Fit new rear emergency exit tickers (outer)	Fitted new sticker	NSW-BSW	776725
203	17/11/2015	559016	Secure L/H washer pipe	Secured pipe	NSW-BSW	776725
203	17/11/2015	559016	GAS STRUT 350NM X 565MM		NSW-BSW	776725
203	17/11/2015	559016	EMERGENCY EXIT DECAL 600MM X 80MM		NSW-BSW	776725
203	17/11/2015	559247	Body (None) desto cracked	As above	NSW-BSW	776725
203	17/11/2015	559247	Body (None) Desto screen cracked	Replaced by A-1 windscreen	NSW-BSW	776725
203	17/11/2015	559346		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	FIRE-SAFE	776725
203	17/11/2015	559346		did the inspection and secured alt wires	FIRE-SAFE	776725
203	16/11/2015	559016	L/H rear inner tyre worn		NSW-W&T	776725
203	16/11/2015	559016	Coolant leak from colant tank	fit new coolant tank.	NSW-ENG	776725
203	16/11/2015	559016	LOW WATER SENDER		NSW-ECO	776725
203	16/11/2015	559016	OVER FLOW TANK B7L+B12BLE		NSW-ECO	776725
203	16/11/2015	559016	enginr bay door struts worn/leaking		NSW-BSW	776725
203	16/11/2015	559016	engine bay door hinge loose		NSW-BSW	776725
203	16/11/2015	559016	Fit new rear emergency exit tickers (outer)		NSW-BSW	776725
203	16/11/2015	559016	Secure L/H washer pipe		NSW-BSW	776725
203	16/11/2015	559016	O RING F/WHEEL HUB CAP		NSW-BRA	776725
203	16/11/2015	559016	PLUG BRASS OIL HUB CAP VOLVO		NSW-BRA	776725
203	16/11/2015	559016	FRONT PADS VOLVO EARLY B7R+B10L+B12BLE		NSW-BRA	776725
203	16/11/2015	559016	BRAKE DISC FRONT B7R		NSW-BRA	776725
203	16/11/2015	559016	SEAL HUB OIL B7R FRONT (1089552-2)		NSW-BRA	776725
203	16/11/2015	559016	Frnrr brake pads need replace		NSW-BRA	776725

203	16/11/2015	559016	Front brake discs worn	fitted new front discsnew hub sealsnew hub cap annd plug seals.	NSW-BRA	776725
203	16/11/2015	559016	Fit new air regulator valve	Fitted new regulator valve	NSW-BRA	776725
203	13/11/2015	558708		Overhaul air seperator	PRE RSI	776725
203	13/11/2015	558708		Remove Intercooler Wash Intercooler and Raditor	PRE RSI	776725
203	13/11/2015	558708		Replace Fuel Filter	PRE RSI	776725
203	13/11/2015	558708		Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	PRE RSI	776725
203	13/11/2015	558708		Service A/C Air Return Filter	PRE RSI	776725
203	13/11/2015	558708		Replace Power Steering And Hydraulic Fan Oil Filter	PRE RSI	776725
203	13/11/2015	558708		Replace Air Dryer Canister	PRE RSI	776725
203	13/11/2015	558708		PRE ANNUAL SAFETY INSPECTION CHECK	PRE RSI	776725
203	13/11/2015	558708		Adjust Valve Clearance	PRE RSI	776725
203	13/11/2015	558708		Rekit Quick Release Valve	PRE RSI	776725
203	13/11/2015	558708		Replace Fuel Filter With Water Bowl	PRE RSI	776725
203	13/11/2015	558708	DIAPHRAGM QUICK RELEASE		PRE RSI	776725
203	13/11/2015	558708	FILTER FUEL WATER SEPERATOR VOLVO B12BLE (H700WK)		PRE RSI	776725
203	13/11/2015	558708	FILTER FUEL VOLVO B12BLE H200WDK		PRE RSI	776725
203	13/11/2015	558708	OIL AUTO TRANSMISSION TEXAMATIC OR DEXRON (LU2)	P/STEER TOP UP OIL	PRE RSI	776725
203	13/11/2015	558708	OIL MANUAL GEARBOX EP 80/90 (LU6 )	DIFF OIL	PRE RSI	776725
203	13/11/2015	558708	FILTER POWER STEER & HYD FAN VOLVO (30M1602)		PRE RSI	776725
203	13/11/2015	558708	FILTER AIR DRYER SCANIA SR4 (20546795)(49G8709HALDEX)		PRE RSI	776725
203	13/11/2015	558709	HALDEX CONDENSER KIT TOP(CYCLONE)		PRE RSI	776725
203	13/11/2015	558709	CYCLONE CONDENSER VALVE KIT		PRE RSI	776725
203	13/11/2015	558709	Service	Overhaul air seperator	PRE RSI	776725
203	13/11/2015	558709	ROCKER COVER GASKET B12BLE 30A8519		PRE RSI	776725
203	13/11/2015	558709	O RING B12BLE INTERCOOLER		PRE RSI	776725
203	13/11/2015	558709		Remove Intercooler Wash Intercooler and Raditor	PRE RSI	776725
203	13/11/2015	558709		Adjust Valve Clearance	PRE RSI	776725
203	13/11/2015	558709		Rekit Quick Release Valve	PRE RSI	776725
203	13/11/2015	558709		Replace Fuel Filter With Water Bowl	PRE RSI	776725
203	13/11/2015	558709		Replace Fuel Filter	PRE RSI	776725
203	13/11/2015	558709		Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	PRE RSI	776725
203	13/11/2015	558709	SEAL QUICK RELEASE VALVE		PRE RSI	776725
203	13/11/2015	558709	DIAPHRAGM QUICK RELEASE		PRE RSI	776725
203	13/11/2015	558709	FILTER FUEL WATER SEPERATOR VOLVO B12BLE (H700WK)		PRE RSI	776725
203	13/11/2015	558709	FILTER FUEL VOLVO B12BLE H200WDK		PRE RSI	776725
203	13/11/2015	558709	OIL AUTO TRANSMISSION TEXAMATIC OR DEXRON (LU2)	P/STEER TOP UP OIL	PRE RSI	776725
203	13/11/2015	558709	OIL MANUAL GEARBOX EP 80/90 (LU6 )	DIFF OIL	PRE RSI	776725
203	13/11/2015	558709		Service A/C Air Return Filter	PRE RSI	776725
203	13/11/2015	558709		Replace Power Steering And Hydraulic Fan Oil Filter	PRE RSI	776725
203	13/11/2015	558709		Replace Air Dryer Canister	PRE RSI	776725
203	13/11/2015	558709	FILTER POWER STEER & HYD FAN VOLVO (30M1602)		PRE RSI	776725
203	13/11/2015	558709	FILTER AIR DRYER SCANIA SR4 (20546795)(49G8709HALDEX)		PRE RSI	776725
203	13/11/2015	558709		PRE ANNUAL SAFETY INSPECTION CHECK	PRE RSI	776725
203	13/11/2015	558709	HALDEX COIL KIT 0500LE 49G0027HALDEX		PRE RSI	776725
203	13/11/2015	558708	ROCKER COVER GASKET B12BLE 30A8519		PRE RSI	776725
203	13/11/2015	558708	O RING B12BLE INTERCOOLER		PRE RSI	776725
203	13/11/2015	558708	SEAL QUICK RELEASE VALVE		PRE RSI	776725
203	06/11/2015	557295		re-tensioned nuts on wheels 1 and 2.	TYR	774730
203	06/11/2015	557392	Mechanic entered - Fluid Leaks Other	added coolant - low.	NSW-ENG	774730
203	05/11/2015	556932	REAR AIR BAG SUIT VOLVO B12B B12BLE 30Y2218		NSW-SUS	774730
203	04/11/2015	556923		CLEAN A/C FILTERS	SAF-INSP	774730
203	04/11/2015	556923		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	774730
203	04/11/2015	556923		VEHICLE SAFETY INSPECTION	SAF-INSP	774730
203	04/11/2015	556846	TYRE NEW 11R22.5N		NSW-W&T	774730
203	04/11/2015	556846	Mechanic entered - Wheels and Tyres Flat or Leaking	changed tyres 1 (flat) and 2 (to rack). all steer nuts tensioned with ryan.	NSW-W&T	774730
203	04/11/2015	556846	Consumables		NSW-W&T	775113
203	04/11/2015	556932	O/S front of rear air bag leak	Remove and replace air bag.	NSW-SUS	774730
203	04/11/2015	556981	Brakes N/F brake caliper leaking grease next to brake pads	Remove front n/s tyre check found too much grease remove excess grease clean and remove pads adjust and refit. refit tyre and tensioned with phil.	NSW-BRA	774730
203	30/10/2015	556448	Consumables		D	774730
203	30/10/2015	556448	Consumables		D	774730
203	30/10/2015	556448	Consumables		D	774730
203	30/10/2015	556448			D	774672
203	30/10/2015	556448	SUMP PLUG WASHER B12B		D	774672
203	30/10/2015	556448	FILTER OIL LONG LIFE VOLVO B12BLE (H200W40)		D	774672
203	30/10/2015	556448	FILTER AIR VOLVO B10M MK4 B12 (AF4560)(E580L)		D	774672
203	30/10/2015	556448	OIL ENGINE MINERAL 15W40 (LU18)	ENGINE OIL	D	774672
203	30/10/2015	556448	FILTER OIL BPASS VOLVO B10M+B7R (LF3654)(H200WN01)(477566-5)		D	774672
203	30/10/2015	556448		Remove V-Belts & Check Tensioner Bearings for Noise	D	774672

203	30/10/2015	556448	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	D	774672
203	30/10/2015	556448	D SERVICE & REPLACE ENGINE OIL completed	D	774672
203	30/10/2015	556448	Consumables	A	774730
203	30/10/2015	556448	Consumables	A	774730
203	30/10/2015	556448	Consumables	A	774730
203	30/10/2015	556448	Grease AC Compressor Clutch Bearing	A	774672
203	30/10/2015	556448	Tension ALL Wheel Nuts to OEM Specs done with Alex	A	774672
203	30/10/2015	556448	A Service completed	A	774672
203	23/10/2015	555060	Drv entered - Body Wheel Chair Ramp / Hook to raise ramp i	NSW-BSW	773265
203	23/10/2015	555060	Body - Rear LH side w/arch panel not in line	NSW-BSW	773265
203	05/10/2015	544173	HYDRAULIC TANK SENSOR B12BLE	NSW-ENG	769735
203	05/10/2015	544173	LEVEL SENSOR- HYD TANK B12BLE	NSW-ENG	769735
203	29/09/2015	550045	Replace A3 poster with Victorian Seniors Festival Poster	NSW-BSW	769175
203	28/09/2015	549530	Campaign 11/15. Fit 2 x Supplied Decals to Internal Salo	NSW-BSW	768856
203	24/09/2015	548836		TYR	768119
203	23/09/2015	548467	EXTENSION FLEXIBLE TYRE VALVE 210mm LONG	NSW-W&T	767817
203	23/09/2015	548467	Mechanic entered - Wheels and Tyres Flat or Leaking	NSW-W&T	767817
203	17/09/2015	546858	Consumables	NSW-E&L	767084
203	17/09/2015	546858	ALT BELT B12BLE	NSW-E&L	766912
203	17/09/2015	546858	Elec and Light repair or replace damage alternator.	NSW-E&L	766912
203	16/09/2015	546858	Elec and Light repair or replace damage alternator.	NSW-E&L	766912
203	14/09/2015	546858	Elec and Light repair or replace damage alternator.	NSW-E&L	766912
203	14/09/2015	546858	B12BLE ALTERNATOR 24V-110AMP (	NSW-E&L	766912
203	10/09/2015	546561	DIRECT PURCHASE - TOWING	NSW-OPS	766912
203	10/09/2015	546561	Ops Entered - Breakdown - Breakdown Road Defect Unaffected Se	NSW-OPS	766912
203	10/09/2015	546488	Breakdown (None)	NSW-BRE	766912
203	04/09/2015	545177	Consumables	NSW-E&L	766248
203	04/09/2015	545177	GLOBE WEDGE INSTRUMENT 24V 5W	NSW-E&L	765808
203	04/09/2015	545177	Mechanic entered - Elec and Light Exterior Lights	NSW-E&L	765808
203	04/09/2015	545177	CLEAR FRONT INDICATOR WRAP-AROUND	NSW-E&L	765808
203	03/09/2015	545080	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	NSW-BSW	765808
203	03/09/2015	545080	COAT HOOK DRIVERS WAS0004	NSW-BSW	765808
203	29/08/2015	544151	Service	SAF-INSP	764924
203	29/08/2015	544151	Service	SAF-INSP	764924
203	29/08/2015	544151	CLEAN A/C FILTERS	SAF-INSP	764924
203	29/08/2015	544151	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	SAF-INSP	764924
203	29/08/2015	544173	NUT HAND RAIL CLAMP (280010)	NSW-ENG	764924
203	29/08/2015	544173	SCREW HAND CLAMP(P/N 280010)	NSW-ENG	764924
203	29/08/2015	544173	GAS STRUT 500NM X 330MM	NSW-ENG	764924
203	29/08/2015	544173	LEVEL SENSOR- HYD TANK B12BLE	NSW-ENG	764924
203	29/08/2015	544173	Hydraulic tank sensor faulty	NSW-ENG	764924
203	29/08/2015	544173	Fluid Leak from hydraulic tank hose	NSW-ENG	764924
203	29/08/2015	544172	Consumables	NSW-E&L	765197
203	29/08/2015	544172	Complete task as instructed in Fleet Campaign 09/15	NSW-E&L	764924
203	29/08/2015	544172	D/ SIDED SAFETY TRIANGLE 3 BOX	NSW-E&L	764924
203	29/08/2015	544173	Rear door grab rail loose	NSW-BSW	764924
203	29/08/2015	544173	Body battery compartment hatch need gas stay	NSW-BSW	764924
203	24/08/2015	543006	Consumables	NSW-E&L	764187
203	24/08/2015	543006	LAMP CLEAR CLEARANCE LIGHT	NSW-E&L	763980
203	24/08/2015	543006	GLOBE S/CONTACT 24V-10W	NSW-E&L	763980
203	24/08/2015	543006	GLOBE 24V 21W SINGLE CONTACT	NSW-E&L	763980
203	24/08/2015	543006	GLOBE WEDGE INSTRUMENT 24V 5W	NSW-E&L	763980
203	24/08/2015	543006	Drv entered - Elec and Light Exterior Lights	NSW-E&L	763980
203	07/08/2015	539944	Consumables	NSW-E&L	761270
203	07/08/2015	539944	Elec and Light - NS headlight out	NSW-E&L	761034
203	07/08/2015	539944	GLOBE H1 24V 70W	NSW-E&L	761034
203	04/08/2015	539240	Suspension N/S/R/F air bag leaking	NSW-SUS	760384
203	04/08/2015	539240	REAR AIR BAG SUIT VOLVO B12B B12BLE 30Y2218	NSW-SUS	760384
203	04/08/2015	539229	Consumables	NSW-E&L	760582
203	04/08/2015	539229	Elec and Light N/S interior light needs new inverter	NSW-E&L	760384
203	04/08/2015	539229	INVERTER FLUORO 24V 15/40W	NSW-E&L	760384
203	04/08/2015	539229	Elec and Light N/S interior light needs new inverter	NSW-E&L	760384
203	03/08/2015	536577	Wipers and Washers - Intermittent Wiper Function not working	NSW-W&W	758872
203	03/08/2015	538982	Complete Campaign 6/15 A3 Marketing Poster Change	NSW-BSW	760299
203	30/07/2015	538479	Consumables	NSW-E&L	759810
203	30/07/2015	538479	Elec and Light Replaced x 3 interior fluros	NSW-E&L	759663
203	30/07/2015	538479	Elec and Light Replaced x 3 interior fluros	NSW-E&L	759663
203	30/07/2015	538455	Consumables	A	759810

203	30/07/2015	538455	Consumables			A	759810
203	30/07/2015	538455	Consumables			A	759810
203	30/07/2015	538455		Grease AC Compressor Clutch Bearing		A	759663
203	30/07/2015	538455		Tension ALL Wheel Nuts to OEM Specs		A	759663
203	30/07/2015	538455		A Service		A	759663
203	30/07/2015	538455				A	759663
203	29/07/2015	538074	Body (None) rear door brake	Checked door brake and it's working		NSW-BSW	758872
203	24/07/2015	536577	Wipers and Washers - Intermittent Wiper Function not working	Assisting Elias with wipers		NSW-W&W	758872
203	24/07/2015	536577	Wipers and Washers - Intermittent Wiper Function not working	checked bus with known woring wiper motors all stoll doing the same possible node issue need to contact trevor at volgren.		NSW-W&W	758872
203	22/07/2015	536924	NO 5 WHITE 25MM			NSW-BSW	758500
203	22/07/2015	536924	NO 7 WHITE 25MM			NSW-BSW	758500
203	22/07/2015	536924	DECAL VIDEO AND AUDIO SURVEILLANCE			NSW-BSW	758500
203	22/07/2015	536924	DECAL MAX SAFE CARRY WHITE ON CLEAR			NSW-BSW	758500
203	22/07/2015	536924	EMERGENCY PROCEDURE DECAL			NSW-BSW	758500
203	22/07/2015	536924	25mm BLACK NO 3			NSW-BSW	758500
203	22/07/2015	536924	25mm BLACK NO 0			NSW-BSW	758500
203	22/07/2015	536924	25mm BLACK NO 2			NSW-BSW	758500
203	22/07/2015	536924	Audit Route buses for correct Decals and positions. Replace			NSW-BSW	758500
203	20/07/2015	536577	Wipers and Washers - Intermittent Wiper Function not working	traced circuit. checked components for function. all seem to be working ok. tried another VECU to test and problem persists. parked bus on fuel bay.		NSW-W&W	758223
203	16/07/2015	535887	25AMP BLADE FUSE			NSW-BSW	757879
203	16/07/2015	535887	Mechanic entered - Body Front_Door Operation Faulty doors wo	problem with doors related to thoreb control unit. found resettable fuse to be faulty. replaced all resettable fuses with regular blade fuses. working ok. performed p.t.i on bus and parked.		NSW-BSW	757879
203	16/07/2015	535887	Body (None) desto pad not working	working ok.		NSW-BSW	757879
203	15/07/2015	535887	Mechanic entered - Body Front_Door Operation Faulty doors wo	check fuses reboot the system check fault cords		NSW-BSW	757879
203	14/07/2015	534744	Gearbox Driveline re fit new diff	fit drive axle back topped up dif oil road tested.		NSW-GEA	757670
203	14/07/2015	534744	Gearbox Driveline re fit new diff	Assist Sisil		NSW-GEA	757670
203	14/07/2015	534744	Gearbox Driveline re fit new diff	put new dif		NSW-GEA	757670
203	13/07/2015	534744	CORE CHARGE	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G153462RET Receiving #:158648 Date :2015-07-16		NSW-GEA	757879
203	13/07/2015	534744	CORE CHARGE	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G153462 Receiving #:158487 Date :2015-07-13		NSW-GEA	757860
203	13/07/2015	534744	EXC DIFF CENTRE 5.29/1	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G153462 Receiving #:158487 Date :2015-07-13		NSW-GEA	757860
203	07/07/2015	533105	Intermittent Wiper Function not working	Checked wiper function only intermitten not working but other two speed working( no need to replace wiper motor for only one action )		NSW-W&W	757670
203	03/07/2015	533105	Gearbox Driveline Noisy loud whining sound when above 50k	removed the diff		NSW-D&H	757670
203	29/06/2015	533181	Fluid Leaks Interior - COOLANT HAS MIXED WITH OIL	Accidently copy bus 643 defect		NSW-ENG	757670
203	27/06/2015	533105	Gearbox Driveline Noisy loud whining sound when above 50k	road tested and find diff noisy.		NSW-D&H	757670
203	23/06/2015	532248	Ops Entered - Fault - Gearbox Driveline Trouble selecting dr	remove gear selector clean and fixed same as road test bus ok.		NSW-GEA	756692
203	11/06/2015	530586	Consumables			NSW-W&T	755115
203	11/06/2015	530586	Retension OSR wheel	re-tensioned nuts on wheels 3; 4; 5 and 6.		NSW-W&T	754811
203	11/06/2015	530539	REAR AIR BAG SUIT VOLVO B12B B12BLE			NSW-SUS	754811
203	10/06/2015	530376		Completed with Sisil Completed with Sisil and change 1 rear air bag		SAF-INSP	754710
203	10/06/2015	530376		CLEAN A/C FILTERS		SAF-INSP	754710
203	10/06/2015	530376		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Ryan		SAF-INSP	754710
203	10/06/2015	530376		VEHICLE SAFETY INSPECTION completed		SAF-INSP	754710
203	10/06/2015	530539	Suspension - Replace ORR airbag	Replaced		NSW-SUS	754811
203	22/05/2015	527544	Drv entered - AC Heating Not Heating	assisted Elias		NSW-SCA	751611
203	22/05/2015	527544	Drv entered - AC Heating Not Heating	checked a/c boost pump and climate system working ok need bruce to show/look at it.		NSW-SCA	751611
203	22/05/2015	527394	Consumables			NSW-E&L	751894
203	22/05/2015	527394	GLOBE S/CONTACT 24V-10W			NSW-E&L	751611
203	22/05/2015	527394	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	change osf top parking light globe.		NSW-E&L	751611
203	22/05/2015	527544	Drv entered - Comm Equip	assisted Elias		NSW-COM	751611
203	22/05/2015	527544	Drv entered - Comm Equip	found am fm radio missingremoved dash and found it behind the dashtried to find face plate but couldnt then later found it missing in dash.Put it all together and no sound.tried different ra		NSW-COM	751611
203	22/05/2015	527544	Drv entered - Comm Equip	checked 2 way and ok		NSW-COM	751611
203	21/05/2015	527231	Service	Torqued 34		TYR	751611
203	20/05/2015	526924	Drv entered - Wipers and Washers Wipers Loose	adjusted and tightened loose (os) wiper arm.		NSW-W&W	751243
203	20/05/2015	527002	TYRE RECAP 11R22.5R			NSW-W&T	751243
203	20/05/2015	526925	Consumables			NSW-E&L	751611
203	20/05/2015	526925	GLOBE WEDGE INSTRUMENT 24V 5W			NSW-E&L	751243
203	20/05/2015	526925	Drv entered - Elec and Light Exterior Lights	changed blown globes - (osf) and (nsf) bottom park lights.		NSW-E&L	751243
203	19/05/2015	527002	Wheels and Tyres - Replace 34 tyres	Removed & replaced & tensioned w/nuts		NSW-W&T	751356
203	19/05/2015	526857				A&T	751243
203	19/05/2015	526857		REPLACE TRANSMISSION OIL & FILTER Completed with nick		A&T	751243
203	19/05/2015	526857	ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR			A&T	751243
203	19/05/2015	526857	FILTER TRANSMISSION ZF ( 4139-298-039)(4139 298 038 01)			A&T	751243
203	21/04/2015	522124	DRIVE BELT			NSW-SCA	746277
203	20/04/2015	522142	A/C Heating / Belt missing	done		NSW-SCA	746153
203	20/04/2015	522124	FAN BELT A/CON ARTIC 21/32X45			NSW-SCA	746153
203	20/04/2015	522124	A/C Heating / Belt missing	removed and replaced alternator and a/c belts replaced the tensioner.		NSW-SCA	746153
203	15/04/2015	521228	DIRECT PURCHASE ACCIDENT	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G150356 Receiving #:153945 Date :2015-04-17 rEPLACE n/s SIDE GLASS AS REQUIRED		NSW-ACC	745955
203	15/04/2015	521228	Accident report - N/S side glass - Acc # DAN 40987 and 4098	Arranged Sublet and paperwork etc		NSW-ACC	745545
203	09/04/2015	520178		already tensioned		TYR	744807

203	09/04/2015	520177	tensioned all ready		TYR	744807	
203	09/04/2015	520174	retensioned all wheel nuts		TYR	744807	
203	09/04/2015	520174	tensioned all wheels		TYR	744807	
203	08/04/2015	520045	Perform & Complete TSV Bus Safety Inspection Safety Inspection Completed		SAF-INSP	744807	
203	08/04/2015	520045	Perform & Complete TSV Bus Safety Inspection Safety Inspection Completed		SAF-INSP	744807	
203	08/04/2015	520045	Tension Wheel Nuts To Spec.		SAF-INSP	744807	
203	08/04/2015	520045	Clean A/C Filter.		SAF-INSP	744807	
203	08/04/2015	520104 TYRE RECAP 11R22.5R			NSW-W&T	744807	
203	08/04/2015	520104	Wheels and Tyres - Replace tyre pos 56	replaced	NSW-W&T	744807	
203	08/04/2015	520083	Consumables		NSW-E&L	744875	
203	08/04/2015	520083	GLOBE WEDGE INSTRUMENT 24V 5W		NSW-E&L	744807	
203	08/04/2015	520083	Elec and Light - Replace park light globe	Replaced	NSW-E&L	744807	
203	08/04/2015	520104	OSR BRAKE BOOSTER B12BLE		NSW-BRA	744807	
203	08/04/2015	520104	REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	744807	
203	08/04/2015	520104	FRONT PADS VOLVO EARLY B7R+B10L+B12BLE		NSW-BRA	744807	
203	08/04/2015	520104	Brakes - OSR brake booster leaking	fit new r/h/r brake booster.	NSW-BRA	744807	
203	08/04/2015	520104	Brakes - Rear brake pads worn	fit new rear brake pads.	NSW-BRA	744807	
203	08/04/2015	520104	Brakes - Front brake pads worn	fit new front brake pads.	NSW-BRA	744807	
203	08/04/2015	520044	Consumables		A	744875	
203	08/04/2015	520044	Consumables		A	744875	
203	08/04/2015	520044	A Service A Service Completed		A	744807	
203	08/04/2015	520044	Grease AC Compressor Clutch Bearing		A	744807	
203	08/04/2015	520044	Tension ALL Wheel Nuts to OEM Specs		A	744807	
203	08/04/2015	520044	A Service A Service Completed		A	744807	
203	30/03/2015	519002	Replace See Something Say Something Poster	fittd	NSW-I&T	743684	
203	04/03/2015	514535	Ops Entered - Fault - Gearbox Harsh / Thumping - Route: 80	Remove tailshaft and diff pinion nut and sealfit new seal and fit tailshaft	Replace diff oil and road test and steam clean diff area	NSW-GEA	739793
203	04/03/2015	514535	DIFF PINION NUT B12BLE		NSW-GEA	739793	
203	03/03/2015	513789	DIFF PINION NUT B12BLE		NSW-D&H	739793	
203	02/03/2015	514535	DIFF PINION OIL SEAL		NSW-GEA	739793	
203	27/02/2015	513789	DIFF PINION OIL SEAL		NSW-D&H	739362	
203	27/02/2015	513789	Assisted Phil.		NSW-D&H	739268	
203	27/02/2015	513789	Diff & Hubs - oil leak from diff pinion seal	Remove tail shaft nut and diff pinion flange and seal.Fit new sealrefit flange	tension nut and fit tailshaft	NSW-D&H	739268
203	24/02/2015	513069		Remove tail shaft nut and diff pinion flange and seal.Fit new sealrefit flange	tension nut and fit tailshaft	TYR	738261
203	23/02/2015	512573	TYRE RECAP 11R22.5R		NSW-W&T	738261	
203	21/02/2015	512573	Whls & Tyres - Tyre 3 needs replacing	Change tyres position # 3 with Kumar	NSW-W&T	737795	
203	21/02/2015	512573	Whls & Tyres - Tyre 3 needs replacing		NSW-W&T	737795	
203	09/02/2015	510451	Ops Entered - Fault - Air Cond Air Conditioner - Route: 811	check ok.serviseble.	NSW-SCA	735443	
203	05/02/2015	510034		Tension Wheel Nuts To Spec.	SAF-INSP	735161	
203	05/02/2015	510034		Clean A/C Filter.	SAF-INSP	735161	
203	05/02/2015	510034		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	735161	
203	05/02/2015	510034		Tension Wheel Nuts To Spec.	SAF-INSP	735161	
203	05/02/2015	510034		Clean A/C Filter.	SAF-INSP	735161	
203	05/02/2015	510034		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	735161	
203	05/02/2015	510232	Consumables		NSW-E&L	735443	
203	05/02/2015	510232	Elec & Light - Rear door exit light out	Repaired wires	NSW-E&L	735443	
203	05/02/2015	510232	Elec & Light - Rear door exit light out	Repaired wires	NSW-E&L	735443	
203	03/02/2015	509470	Consumables		NSW-E&L	734894	
203	03/02/2015	509470	GLOBE H1 24V 70W		NSW-E&L	734367	
203	03/02/2015	509470	Elec & Light Headlights	change os head light globe.	NSW-E&L	734367	
203	20/01/2015	507525	Vandalism - Graffiti on engine door	removed top surface only. unable to remove totally.	NSW-VAN	731784	
203	13/01/2015	506300	Consumables		NSW-E&L	731052	
203	13/01/2015	506300	B12BLE 80AMP ALTERNATOR		NSW-E&L	730768	
203	12/01/2015	504203	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GT-ROA002 ROAD SAFETY INSPECTION P/O #:G146945 Receiving #:149486 Date :2015-01-15	P	731362	
203	12/01/2015	506300	Vandalism Graffiti	attempted to remove. none of our solvents would penetrate the ink.	NSW-VAN	730768	
203	12/01/2015	506300	Air Cond Air Conditioner	checked. found alternator not charging. replaced alternators all working ok.	NSW-SCA	730768	
203	12/01/2015	506300	Elec & Light Interior Lights bit dim	checked after alt replacement. working ok.	NSW-E&L	730768	
203	12/01/2015	506300	Consumables		NSW-BSW	730768	
203	12/01/2015	506300	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	complete	NSW-BSW	730768	
203	09/01/2015	504203	Annual Licence	RWC 486522 - PASSED 09/01/15	P	728748	
203	09/01/2015	505965	Consumables		NSW-BSW	730616	
203	09/01/2015	505965	Body & Acc - Seat	replaced (osf) and (osr) - torn.	NSW-BSW	728748	
203	09/01/2015	505965	Mechanic entered - Body & Acc Passenger Seat Cushion	replaced (osf) and (osr) - torn.	NSW-BSW	728748	
203	08/01/2015	505689	REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	730404	
203	08/01/2015	505689	Mechanic entered - Suspension Leaking U/h/r rear air bag lea	fit new air bag.	NSW-SUS	730404	
203	07/01/2015	505406		D Service & Change Engine Oil done	D	730179	
203	07/01/2015	505406	FILTER AIR VOLVO B10M MK4 B12 (AF4560)(E580L)		D	730179	
203	07/01/2015	505406	OIL ENGINE DELO 400LE 15W40 (LU18)	ENGINE OIL	D	730179	
203	07/01/2015	505406	FILTER OIL BPASS VOLVO B10M+B7R (LF3654)(H200WN01)(477566-5)		D	730179	

203	07/01/2015	505406	SUMP PLUG WASHER B12B			D	730179
203	07/01/2015	505406		Remove V-Belts & Check Tensioner Bearings for Noise		D	730179
203	07/01/2015	505406		Tension ALL Wheel Nuts to OEM Specs		D	730179
203	07/01/2015	505406	FILTER OIL LONG LIFE VOLVO B12BLE (H200W40)			D	730179
203	07/01/2015	505406	Consumables			D	730404
203	07/01/2015	505406	Consumables			D	730404
203	07/01/2015	505406	Consumables			D	730404
203	07/01/2015	505442		Grease AC Compressor Clutch Bearing		A	730179
203	07/01/2015	505442		Tension ALL Wheel Nuts to OEM Specs done with Alex		A	730179
203	07/01/2015	505442		A Service complete		A	730179
203	07/01/2015	505442		cleaned AC filter cleaned radiator		A	730179
203	07/01/2015	505406		A Service		A	730179
203	07/01/2015	505406		Grease AC Compressor Clutch Bearing		A	730179
203	07/01/2015	505406		Tension ALL Wheel Nuts to OEM Specs		A	730179
203	07/01/2015	505442	Consumables			A	730404
203	07/01/2015	505442	Consumables			A	730404
203	07/01/2015	505442	Consumables			A	730404
203	07/01/2015	505406	Consumables			A	730404
203	07/01/2015	505406	Consumables			A	730404
203	07/01/2015	505406	Consumables			A	730404
203	05/01/2015	504951	GLOBE WEDGE INSTRUMENT 24V 5W			NSW-E&L	729664
203	05/01/2015	504951	LAMP CLEAR CLEARANCE LIGHT			NSW-E&L	729664
203	05/01/2015	504951	GLOBE S/CONTACT 24V-10W			NSW-E&L	729664
203	05/01/2015	504951	Etec & Light - Replace NSF park light	changed blown globe and fitted weather proof boots to indicator and park lights - missing. (used ones used).		NSW-E&L	729664
203	05/01/2015	504951	Etec & Light - Replace OSF top park light	replaced fitting - melted. repaired damaged electrical wires.		NSW-E&L	729664
203	05/01/2015	504951	Consumables			NSW-E&L	729910
203	18/12/2014	502820	A3 Poster Change	fitted		NSW-I&T	726709
203	17/12/2014	502734	Ops Entered - Breakdown - Breakdown Road Defect Unaffected S	Assist Gregg to fit unloader valve.at cowan st e/hills.Start job at 1.30 return at 3.30		NSW-BRE	726653
203	17/12/2014	502734	VOLVO UNLOADER VALVE HALDEX 12bar			NSW-BRE	726653
203	16/12/2014	502517		Perform Annual air system check as per Checklist done		AIR SYS CHEC	726413
203	15/12/2014	501842	Suspension - Replace NS front upper control arm bush	done.		NSW-SUS	726142
203	15/12/2014	501842	BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	726142
203	15/12/2014	501842	BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	726142
203	15/12/2014	501842	BUSH KIT LOWER CONTROL ARM BUSH B10BLE			NSW-SUS	726142
203	15/12/2014	502259	ZF ACCUMULATOR PISTON+SEALS KIT B10BLE 0501 218 028			NSW-GEA	726142
203	15/12/2014	502282	Gearbox - S/clean and check g/box oil leak	done		NSW-GEA	726142
203	15/12/2014	502277	Gearbox - Rekit g/box accumulator	done		NSW-GEA	726142
203	15/12/2014	502281	Engine - S/clean all bus	done		NSW-ENG	726142
203	15/12/2014	502259	Etec & Light - Fit indicator cancellor	cancellor found to be ok found stalk to be missing bolt causing looseness and missing striker plate.replaced missing bolt and re secured other loose one.		NSW-E&L	726142
203	15/12/2014	502259	Consumables			NSW-E&L	0
203	15/12/2014	502283	Consumables			NSW-BSW	0
203	15/12/2014	502280	Consumables			NSW-BSW	0
203	15/12/2014	502279	Consumables			NSW-BSW	0
203	15/12/2014	502278	Consumables			NSW-BSW	0
203	15/12/2014	502276	Consumables			NSW-BSW	0
203	15/12/2014	501842	Consumables			NSW-BSW	0
203	15/12/2014	502283	Body & Acc - Secure lower skirt	secured		NSW-BSW	726142
203	15/12/2014	502280	Body & Acc - Secure rear door hand rail	secured		NSW-BSW	726142
203	15/12/2014	502279	Body & Acc - Fit licensed to carry sticker inside	fitted		NSW-BSW	726142
203	15/12/2014	502278	Body & Acc - Retighten NS front stop bolt	secured		NSW-BSW	726142
203	15/12/2014	502276	Body & Acc - Repair floor hatch	repaired		NSW-BSW	726142
203	15/12/2014	501842	FLOOR HATCH SCREWS 13405 + 30628			NSW-BSW	726142
203	12/12/2014	501621		Tension Wheel Nuts To Spec.		SAF-INSP	726142
203	12/12/2014	501621		Clean A/C Filter.		SAF-INSP	726142
203	12/12/2014	501621		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	726142
203	12/12/2014	501842	RR LEVELLING VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G146498 Receiving #:148483 Date :2014-12-12		NSW-SUS	726269
203	12/12/2014	501842	Suspension - Replace rear suspension solenoid valve	Replaced		NSW-SUS	726142
203	12/12/2014	501842	Suspension - Replace OS front lower control arm bush	Replaced		NSW-SUS	726142
203	12/12/2014	501842	BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	726142
203	12/12/2014	501842	Suspension - Replace NS front upper control arm bush	done.		NSW-SUS	726142
203	11/12/2014	501027		Remove Intercooler Wash Intercooler and Raditor done		RSI	726142
203	11/12/2014	501027		Rekit Quick Release Valve replaced.		RSI	726142
203	10/12/2014	501027		Adjust Valve Clearance done		RSI	726142
203	09/12/2014	501027	O RING B12BLE INTERCOOLER			RSI	726142
203	09/12/2014	501027		Inspect Bus As Per Inspection Sheet		RSI	726142
203	09/12/2014	501027		Replace Fuel Filter With Water Bowl		RSI	726142
203	09/12/2014	501027		Replace Fuel Filter		RSI	726142
203	09/12/2014	501027		Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )		RSI	726142

203	09/12/2014	501027 SEAL QUICK RELEASE VALVE		RSI	726142
203	09/12/2014	501027 DIAPHRAGM QUICK RELEASE		RSI	726142
203	09/12/2014	501027 FUEL WATER FILTER B12BLE		RSI	726142
203	09/12/2014	501027 FUEL FILTER B12BLE H200WDK		RSI	726142
203	09/12/2014	501027 TEXAMATIC 1888 (LU2)	P/STEER TOP UP OIL	RSI	726142
203	09/12/2014	501027 RPM BORATE EP LUBE 220 80/90 (LU6)	DIFF OIL	RSI	726142
203	09/12/2014	501027	Service A/C Air Return Filter	RSI	726142
203	09/12/2014	501027	Replace Power Steering And Hydraulic Fan Oil Filter	RSI	726142
203	09/12/2014	501027	Replace Air Dryer Canister	RSI	726142
203	09/12/2014	501027 POWER STEER +HYD FAN FILTER 30m1602		RSI	726142
203	09/12/2014	501027 FILTER AIR DRYER SCANIA SR4 (20546795)(49G8709HALDEX)		RSI	726142
203	02/12/2014	499594	re-tensioned nuts on wheels 3 and 4.	TYR	724686
203	02/12/2014	499593	re-tensioned nuts on wheels 1 and 2.	TYR	724686
203	29/11/2014	499337 TYRE NEW 11R22.5N		NSW-W&T	724686
203	29/11/2014	499337	removed tyres 3 and 4. replaced leaking flexible valve ext. re-fitted wheels. inflated tyres to specs. nuts tensioned with dulkith.	NSW-W&T	724261
203	29/11/2014	499337 VALVE EXTENSION-130mm Metal type		NSW-W&T	724261
203	29/11/2014	499337 Mechanic entered - Whls & Tyres Worn	changed tyres 1 worn and 2 to rack. all steer nuts tensioned with dulkith.	NSW-W&T	724261
203	29/11/2014	499314 Consumables		NSW-BSW	0
203	29/11/2014	499314 Mechanic entered - Body & Acc Windows	re-inserted windscreen locking rubber strip (osf) top and bottom - not in place.	NSW-BSW	724261
203	10/11/2014	495539 Mechanic entered - Eng Cool Other	pressure clean radiator core and filter screen.	NSW-ECO	720825
203	29/10/2014	493755 Consumables		NSW-BSW	0
203	29/10/2014	493755 Remove Legacy Poster and replace with See Something Say So	N/A	NSW-BSW	719114
203	25/10/2014	492829 Consumables		NSW-BSW	0
203	25/10/2014	492829 Mechanic entered - Body & Acc Other	remove broken bolt from engine under cover and fixed new bolt fixed top side beading.bus ok.	NSW-BSW	718215
203	23/10/2014	492053 FIT FRONT CRANK OIL SEAL	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G144789 Receiving #:146771 Date :2014-10-27	NSW-ENG	718462
203	22/10/2014	492379 Vandalism - Graffiti on walls	Cleaned Graffiti as much as possible	NSW-VAN	717862
203	22/10/2014	492053 ENGINE MOUNTING B12BLE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G144807 Receiving #:146633 Date :2014-10-22	NSW-ENG	718008
203	22/10/2014	492053 B12BLE ALTERNATOR CRANK BELT		NSW-ENG	717862
203	22/10/2014	492053 B12BLE BELT TENSIONER		NSW-ENG	717862
203	22/10/2014	492053 FRT CRANKSHAFT OIL SEAL B12BLE		NSW-ENG	717862
203	22/10/2014	492381 Engine repair oil leak from engine	Removed bumper bars and chahsis frame to replace crank seal.Refit all accesories as required.Checked oil level - ok.washed engine and road test - ok.	NSW-ENG	717862
203	22/10/2014	492380 Diff oil seal start leak	Checked ok	NSW-D&H	717862
203	21/10/2014	492053 Fit engine front oil seal	Completed by CMV	NSW-ENG	717862
203	17/10/2014	491480 Consumables		NSW-BSW	0
203	17/10/2014	491480 SEAT BELT LEFT HAND		NSW-BSW	717862
203	16/10/2014	491480 Ops Entered - Fault - Body & Acc Drivers Seat Belt - Route:	Replaced seat belt and parked on the US line as directed.	NSW-BSW	717862
203	15/10/2014	491038 AIR BAG B12BLE 30Y2229 AFTER CHASSIS 013674		NSW-SUS	717625
203	15/10/2014	491038 Suspension N/S/F air bag Leaking and bump stop u/s	R/R bump stop and fitted air bag	NSW-SUS	717625
203	15/10/2014	491038 Suspension N/S/F air bag Leaking and bump stop u/s	R/R bump stop and fitted air bag	NSW-SUS	717625
203	15/10/2014	491038 Suspension N/S/F air bag Leaking and bump stop u/s	Removed air bag	NSW-SUS	717625
203	15/10/2014	491038 Suspension N/S/F air bag Leaking and bump stop u/s	Removed air bag	NSW-SUS	717625
203	15/10/2014	490971 Consumables		NSW-E&L	0
203	15/10/2014	490971 GLOBE S/CONTACT 24V-10W		NSW-E&L	717625
203	15/10/2014	491037 Consumables		NSW-BSW	0
203	15/10/2014	488837 Consumables		NSW-BSW	0
203	15/10/2014	488837 RED REFLECTOR 94X44MM 84052		NSW-BSW	717625
203	15/10/2014	488837 AMBER REFLECTOR		NSW-BSW	717625
203	15/10/2014	491037 Body & Acc Passenger Seat Cushion	Replaced 3 seat cushions	NSW-BSW	717625
203	14/10/2014	491027	Tension Wheel Nuts To Spec.Phil and Rene	SAF-INSP	717625
203	14/10/2014	491027	Clean A/C Filter.	SAF-INSP	717625
203	14/10/2014	491027	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	717625
203	14/10/2014	491027	Tension Wheel Nuts To Spec.Phil and Rene	SAF-INSP	717625
203	14/10/2014	491027	Clean A/C Filter.	SAF-INSP	717625
203	14/10/2014	491027	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	717625
203	14/10/2014	491027 Mechanic entered - Whls & Tyres Other	Painted wheels	NSW-W&T	717625
203	14/10/2014	491036 Consumables		NSW-E&L	0
203	14/10/2014	491036 Elec & Light o/s/f/i indicator light u/s	Replace o/s/f/i indicator	NSW-E&L	717625
203	14/10/2014	490971 LED FRONT POSITION MARKER LIGHT		NSW-E&L	717625
203	14/10/2014	490971 Elec & Light - Emer light over back door out	replaced emergency light	NSW-E&L	717625
203	14/10/2014	488837 PTV REBRAND - Method 2.	re-fit lights	NSW-BSW	717625
203	14/10/2014	488836 Accident damage - NSR - Acc # DAN 39714. *DRIVER AT FAULT* *	..	NSW-ACC	717625
203	14/10/2014	488836 BUMPER BOLT SPECIAL		NSW-ACC	717625
203	13/10/2014	488837 EMERGENCY EXIT (HAMMER)		NSW-BSW	717625
203	13/10/2014	488837 Bodyshop consumables and Spray Booth		NSW-BSW	717625
203	13/10/2014	488837 Paint materials		NSW-BSW	717625
203	13/10/2014	488837 wheelchair access ramp load rated 300 KG		NSW-BSW	717625
203	09/10/2014	490225 Consumables		NSW-E&L	0
203	09/10/2014	490225 Complete AM/FM radio saloon speaker modification	no radio	NSW-E&L	717625

203	08/10/2014	488837	PTV REBRAND - Method 2.			NSW-BSW	717625
203	07/10/2014	488837	PTV REBRAND - Method 2.	Masked up and painted etch primer primer and 2pac Orange coats c/o		NSW-BSW	717625
203	07/10/2014	488837	PTV REBRAND - Method 2.	o/s panels retap threads refit panels assist tudor with front bar maskup prep work ready for sharma PTV orange . .		NSW-BSW	717625
203	07/10/2014	488836	Accident damage - NSR - Acc # DAN 39714. *DRIVER AT FAULT* *	repairing		NSW-ACC	717625
203	07/10/2014	488836	Accident damage - NSR - Acc # DAN 39714. *DRIVER AT FAULT* *	Continued repairs on NS rear bumper corner and fitted to the bus Primered and painted. c/o		NSW-ACC	717625
203	06/10/2014	488837	PTV REBRAND - Method 2.	Rebrand		NSW-BSW	717625
203	06/10/2014	488837	PTV REBRAND - Method 2.	Prep & painted panels front bar full white		NSW-BSW	717625
203	06/10/2014	488836	Accident damage - NSR - Acc # DAN 39714. *DRIVER AT FAULT* *	Dismantled OS rear panel removed skin of the panel and replaced with new skin panel and Repaired fibre glass NS rear bumper corner c/o		NSW-ACC	717625
203	06/10/2014	488836	3MM X 1200MM X 2400MM FLAT ALUMINIUM			NSW-ACC	717625
203	03/10/2014	486522	Direct Purchase - ELECTRICAL	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G143823 Receiving #:146189 Date :2014-10-09 Fit new computer and program		NSW-SUS	717625
203	03/10/2014	488837	PTV REBRAND - Method 2.	Removed decals polished all OS and NS panels cleaned and washed polished panels.c/o		NSW-SUS	717625
203	03/10/2014	488837	PTV REBRAND - Method 2.	rebranding		NSW-BSW	717625
203	03/10/2014	488837	EXIT ONLY DECAL			NSW-BSW	717625
203	03/10/2014	488837	PLEASE KEEP CLEAR DECAL			NSW-BSW	717625
203	03/10/2014	488837	PTV REBRAND - Method 2.	Remove lights		NSW-BSW	717625
203	02/10/2014	488837	PTV REBRAND - Method 2.			NSW-BSW	717625
203	02/10/2014	488836	Accident damage - NSR - Acc # DAN 39714. *DRIVER AT FAULT* *			NSW-ACC	717625
203	30/09/2014	486522	ECAS ECU VOLVO B7RLE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G143463 Receiving #:145879 Date :2014-09-30		NSW-SUS	717254
203	30/09/2014	488643	Body & Acc - Seat base soaking wet	Replaced seat base		NSW-BSW	717254
203	25/09/2014	486522	Re program suspension ECU	Re programmed by CMV		NSW-SUS	716499
203	25/09/2014	487758	Mechanic entered - Elec & Light Headlights	Replace headlight globe		NSW-E&L	716499
203	25/09/2014	487758	GLOBE H1 24V 70W			NSW-E&L	716499
203	25/09/2014	487756	Security CCTV - Not checked in service tool check n/w	CHECKED		NSW-COM	716499
203	23/09/2014	486522	Suspension Hard - suspension won't raise warning symbols	take to cmv		NSW-SUS	716499
203	18/09/2014	486522	ELC HEIGHT SENSOR VOLVO			NSW-SUS	715889
203	18/09/2014	486522	Suspension Hard - suspension won't raise warning symbols	suspension n/w check air pressure electrical system change nsf lavalng value still same need swape ecu and check.		NSW-SUS	715889
203	18/09/2014	486522	Suspension Hard - suspension won't raise warning symbols	CHECKED OUT AND ORDERED PARTS		NSW-SUS	715889
203	16/09/2014	486103	Ops Entered - Fault - Engine Noisy - Route: 709 - King & T	CHECKED NO NOISE FAUND		NSW-ENG	715418
203	16/09/2014	486013		A Service		A	715418
203	16/09/2014	486013		Grease AC Compressor Clutch Bearing		A	715418
203	16/09/2014	486013		Tension ALL Wheel Nuts to OEM Specs		A	715418
203	16/09/2014	486013		A Service		A	715418
203	12/09/2014	485548	Suspension (None) wont release whilst raised or lowered p	checked suspenion working O/K		NSW-SUS	715008
203	11/09/2014	485288	DECAL AUTHORISED OFFICER			NSW-BSW	714733
203	11/09/2014	485288	Remove old decal and fit new Authorised Officers Decal DO N	REPLACED		NSW-BSW	714733
203	06/09/2014	484377	GLOBE DASH B7L			NSW-E&L	713727
203	06/09/2014	484377	Mechanic entered - Elec & Light Dash	changed blown globes.		NSW-E&L	713727
203	06/09/2014	484376	WEDGE GLOBE INSTRUMENT 24V 5W			NSW-E&L	713727
203	06/09/2014	484376	Mechanic entered - Elec & Light Park Lights	changed blown globe (nsf) bottom park.		NSW-E&L	713727
203	26/08/2014	482156	Mechanic entered - No Defect Recorded	Steam wash air dryer assembly remove unloader valve and safety valve and check air pressure		NSW-I&T	711926
203	26/08/2014	482156	REGULATOR KIT AIR DRYER HALDEX	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G142843 Receiving #:144617 Date :2014-08-26		NSW-AIR	711962
203	21/08/2014	481235	Mechanic entered - Suspension Kneeling System	Checked suspension wiring solenoid raised itself ok at the moment		NSW-SUS	711094
203	19/08/2014	480781	Remove old A3 poster & replace with Legacy or Penalty Fares	Replaced		NSW-EQU	710920
203	15/08/2014	480100	INVERTER FLUORO 24V 15/40W			NSW-E&L	710212
203	15/08/2014	480100	FLURO TUBE 36W			NSW-E&L	710212
203	15/08/2014	480100	Elec & Light - Interior light n/w	fit new inverter. working ok.		NSW-E&L	710212
203	15/08/2014	480100	Mechanic entered - Body & Acc Floor floor secured with screw	replaced damage floor mount screws		NSW-BSW	710212
203	15/08/2014	480100	FLOOR HATCH SCREWS 13405 + 30628			NSW-BSW	710212
203	15/08/2014	480100	Mechanic entered - Body & Acc Floor floor secured with screw	assisted tudor. parked bus and disconnected batteries for welding.		NSW-BSW	710212
203	11/08/2014	479356	Eng Cool - Accumalator valve leaking oil	drilled out floor bolts to remove floor hatch. steam cleaned gearbox and accumulator no leak apparent. roadtested bus to check for leaks. all looks good. temporarily secured floor with scr		NSW-ECO	709622
203	11/08/2014	479356	Security CCTV - Camera not working	checked. repositioned front camera working ok.		NSW-COM	709622
203	07/08/2014	478873	Service	Completed		TYR	709173
203	07/08/2014	478873	Service			TYR	709173
203	07/08/2014	478749	Clamp Suit Tyre Valve			NSW-W&T	709173
203	07/08/2014	478749	TYRE VALVE EXTENSION 210mm LONG			NSW-W&T	709173
203	07/08/2014	478749	WEDGE GLOBE INSTRUMENT 24V 5W			NSW-E&L	709173
203	07/08/2014	478749	FLURO TUBE 24V 18W 24'			NSW-E&L	709173
203	06/08/2014	478616		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	708965
203	06/08/2014	478616		Tension Wheel Nuts To Spec.		SAF-INSP	708965
203	06/08/2014	478616		Clean A/C Filter.		SAF-INSP	708965
203	06/08/2014	478616		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	708965
203	06/08/2014	478616		Tension Wheel Nuts To Spec.		SAF-INSP	708965
203	06/08/2014	478616		Clean A/C Filter.		SAF-INSP	708965
203	06/08/2014	478749	Whls & Tyres - NS rear pos 4 1mm left	Replaced tyres 34 checked all tyre pressures		NSW-W&T	709173
203	06/08/2014	478749	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Fitted		NSW-W&T	709173
203	06/08/2014	478749	Etec & Light - Replace 2 fluro tubes	Replaced		NSW-E&L	709173
203	06/08/2014	478749	Etec & Light - NS bottom parker n/w	Replaced		NSW-E&L	709173
203	30/07/2014	477196	Body shop consumables			NSW-VAN	707417

203	30/07/2014	477196	Vandalism Graffiti	Spray can light grey over graffiti on rear interior wall	NSW-VAN	707417
203	24/07/2014	476286	Elec & Light - Emer exit light over rear door	Check ok	NSW-E&L	706524
203	22/07/2014	475938	Ops Entered - Fault - Brakes Smoking / Smell - Route: - A	Put bus on the pit and checked all the brake pads and rotors - ok.Road tested bus to check brake smell.Could bnot fault.Checked for wheels to oveheat after road test - ok.Deleted inactive f	NSW-BRA	706108
203	03/07/2014	472401	Ops Entered - Fault - Elec & Light W'ring Light - Route:	Re-set speedo and test drive re-check computer	NSW-E&L	703135
203	25/06/2014	470582	33MM LOOSE WHEEL NUT INDICATOR		NSW-W&T	701964
203	25/06/2014	470582	Fit Wheel Nut Pointers to all wheel nuts on the front axle a	torqued wheel nuts fit cp33y	NSW-W&T	701964
203	25/06/2014	470582	B12BLE BELT TENSIONER		NSW-ENG	701964
203	25/06/2014	470582	B12BLE ALTERNATOR CRANK BELT		NSW-ENG	701964
203	25/06/2014	470582	Ops Entered - Fault - Engine W'ring Light - Route: 862 - D	found alt belt missing. replaced adjuster pulley and fit new belt.	NSW-ENG	701964
203	20/06/2014	469723	Drv entered - Other	???	NSW-ENG	701165
203	20/06/2014	469723	Drv entered - Other	No fault type	NSW-ENG	701165
203	17/06/2014	469072	CLEAR FRONT INDICATOR WRAP-AROUND		NSW-E&L	700662
203	17/06/2014	469072	GLOBE DASH B7L		NSW-E&L	700662
203	16/06/2014	468996	Suspension - Top torque rod bush u/s	R/R N/S/R top torque rod bushescleaned rod fitted and tightened bolts.	NSW-SUS	700549
203	16/06/2014	469072	Elec & Light - Replace OF park light globe	Replaced	NSW-E&L	700662
203	16/06/2014	468909		A Service	A	700549
203	16/06/2014	468909		Tension ALL Wheel Nuts to OEM Specs	A	700549
203	16/06/2014	468909		Grease AC Compressor Clutch Bearing	A	700549
203	16/06/2014	468909		Grease AC Compressor Clutch Bearing	A	700549
203	16/06/2014	468909		Tension ALL Wheel Nuts to OEM Specs	A	700549
203	16/06/2014	468909		A Service	A	700549
203	12/06/2014	468267	Mechanic entered - Eng Cool Coolant Low	added coolant.	NSW-ECO	699972
203	11/06/2014	468071		re-tensioned tyres 5 and 6 wheel nuts after change on 7/6/14 - o.k.	TYR	699972
203	11/06/2014	468071		retorque rear wheel nuts	TYR	699972
203	11/06/2014	467858	VOLVO - WORN FLAT - POS 456	Creditor #:GB-TYR002 TYRES4U P/O #:G139922 Receiving #:141767 Date :2014-06-11 REPAIR OR REPLACE WITH RECAP - 11R225B	NSW-W&T	699972
203	11/06/2014	468070	Elec & Light - Alt belt damaged	replaced belt and idler pulley. drained and refilled coolant. roadtested ok.	NSW-E&L	699972
203	11/06/2014	468070	B12BLE IDLER BRACKET PULLEY		NSW-E&L	699972
203	11/06/2014	468070	O/RING W/PUMP B12BLE		NSW-E&L	699972
203	11/06/2014	468070	B12BLE ALTERNATOR CRANK BELT		NSW-E&L	699972
203	10/06/2014	467858	Whls & Tyres - Replace tyre pos 456 - worn	Replaced	NSW-W&T	699576
203	10/06/2014	467931	WEDGE GLOBE INSTRUMENT 24V 5W		NSW-E&L	699576
203	10/06/2014	467931	Mechanic entered - Elec & Light Park Lights	CHANGED BLOWN GLOBE - (OSF) BOTTOM PARK LIGHT.	NSW-E&L	699576
203	07/06/2014	467631	Mechanic entered - Whls & Tyres Other 5 (flat) 6 (worn)	Change tyres position # 5&6 with Kumar	NSW-W&T	699576
203	07/06/2014	467631	Mechanic entered - Whls & Tyres Worn no 6 worn no5 flat.	replaced tyre tension wheel nuts 670 nm.	NSW-W&T	699576
203	06/06/2014	467631		Tension Wheel Nuts To Spec.	SAF-INSP	699576
203	06/06/2014	467631		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	699576
203	06/06/2014	467631		Tension Wheel Nuts To Spec.	SAF-INSP	699576
203	06/06/2014	467631		Clean A/C Filter.	SAF-INSP	699576
203	06/06/2014	467631		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	699576
203	06/06/2014	467845	Whls & Tyres - Tyre 6 needs replacing	Replaced	NSW-W&T	699699
203	06/06/2014	467845	Whls & Tyres - Tyre 6 needs replacing	Replaced	NSW-W&T	699699
203	04/06/2014	466968	Drv entered - Elec & Light Park Lights		NSW-E&L	698780
203	04/06/2014	466968	WEDGE GLOBE INSTRUMENT 24V 5W		NSW-E&L	698780
203	04/06/2014	466962	CLEAR FRONT INDICATOR WRAP-AROUND		NSW-E&L	698780
203	04/06/2014	466962	Mechanic entered - Elec & Light Indicators	Fit new indicator light and replace park light globe	NSW-E&L	698780
203	31/05/2014	466322	Mechanic entered - Eng Cool Coolant Low	added coolant.	NSW-ECO	698214
203	20/05/2014	463984	WEDGE GLOBE INSTRUMENT 24V 5W		NSW-E&L	696481
203	19/05/2014	463984	Ops Entered - Fault - Elec & Light Park Lights - Route: 813	changed parklight	NSW-E&L	696306
203	19/05/2014	463984	Ops Entered - Fault - Security CCTV System Faulty - Route:	re-calibrated time and date on cctv found drivers camera not working found faulty connections after investigation re soldered all ok.	NSW-COM	696306
203	16/05/2014	463520	Brakes - ABS light on	checked abs light not on test drove and did not come on.	NSW-BRA	695900
203	14/05/2014	462922	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	Replaced	NSW-BSW	695307
203	14/05/2014	462922	Fit Myki decals as requiredFit Recruitment decal as requi	Replaced	NSW-BSW	695307
203	14/05/2014	462922	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	Replaced	NSW-BSW	695307
203	13/05/2014	462573	Mechanic entered - Elec & Light Indicators	replaced (nsf) side indicator lamp - smashed.	NSW-E&L	695114
203	13/05/2014	462573	SIDE INDICATOR L/H		NSW-E&L	695114
203	13/05/2014	462573	GLOBE 24V 21W SINGLE CONTACT		NSW-E&L	695114
203	07/05/2014	461122	NEED REAR BRAKE CALIBRATION	Creditor #:GB-CMV001 CMV TRUCK AND BUS P/L P/O #:G138458 Receiving #:140688 Date :2014-05-15	NSW-BRA	695634
203	06/05/2014	461215	24V DRIVERS FAN (USE FASCO ONLY)		NSW-H&D	693789
203	06/05/2014	461215	Heat & Demist - Drivers fan no cover	replaced drivers fan and drove bus to cmv for brakes	NSW-H&D	693789
203	06/05/2014	461122	Need rear brake calibration	Completed CMV	NSW-CMV	693789
203	05/05/2014	460711	REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	693789
203	05/05/2014	461013	LHR BRAKE CALIPER B12BLE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G138416 Receiving #:140176 Date :2014-05-05	NSW-BRA	693789
203	05/05/2014	461013	Brakes replace N/S rearcaliper and both rear pads	R/tested	NSW-BRA	693789
203	05/05/2014	461013	REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	693789
203	05/05/2014	461013	Brakes replace N/S rearcaliper and both rear pads	replace rear ns caliper replace both rear pads torqued wheels with tudor test driven with kouma	NSW-BRA	693789
203	02/05/2014	460711	Suspension O/S rear air bag leaks		NSW-SUS	693789
203	30/04/2014	460106	Drv entered - Brakes Noisy	check brake pads ok.	NSW-BRA	693050
203	30/04/2014	460106	Drv entered - Brakes Noisy		NSW-BRA	693050

203	07/04/2014	456698	Tension Wheel Nuts To Spec.	SAF-INSP	688613
203	07/04/2014	456698	Clean A/C Filter.	SAF-INSP	688613
203	07/04/2014	456698	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	688613
203	07/04/2014	456938	Suspension - NSR radius bush worn - top of diff	NSW-SUS	688712
203	07/04/2014	456938	Elec & Light - Emer exit light very dull	NSW-E&L	688712
203	07/04/2014	456938	Diff & Hubs - Diff pinion seal leaking	NSW-D&H	688712
203	07/04/2014	456938	Comm Equip - Radio missing	NSW-COM	688712
203	03/04/2014	455840	Perform Campaign 1_14 School Bus Light Globe Check Check	NSW-E&L	687950
203	31/03/2014	454867	L.E.D SIDE MARKER PERE RED/AMBER	NSW-E&L	687500
203	31/03/2014	455065	Accident damage - N/S/R - Acc # DAN 38829. *To be repaired	NSW-ACC	687500
203	31/03/2014	453970	BODY SHOP SUPPLIES	NSW-ACC	687500
203	31/03/2014	453970	PAINT SUPPLIES	NSW-ACC	687500
203	29/03/2014	454867	Mechanic entered - Elec & Light Other LED marker light	NSW-E&L	687104
203	26/03/2014	453970	Mechanic entered - Accident Rear	NSW-ACC	686681
203	25/03/2014	453970	Mechanic entered - Accident Rear	NSW-ACC	686681
203	24/03/2014	453759	WEDGE GLOBE INSTRUMENT 24V 5W	NSW-E&L	686409
203	23/03/2014	453759	Drv entered - Elec & Light Park Lights	NSW-E&L	686409
203	22/03/2014	453753	Elec & Light - Bus wont start on fuel bay	NSW-E&L	686140
203	20/03/2014	453406	Elec & Light - Replace broken interior light cover	NSW-E&L	685829
203	20/03/2014	453299	SUMP PLUG WASHER B12B	D	685738
203	20/03/2014	453299	Remove V-Belts & Check Tensioner Bearings for Noise	D	685738
203	20/03/2014	453299	Tension ALL Wheel Nuts to OEM Specs	D	685738
203	20/03/2014	453299	D Service & Change Engine Oil	D	685738
203	20/03/2014	453299	OIL FILTER LONG LIFE B12BLE (VOLVO)	D	685738
203	20/03/2014	453299	FILTER AIR B10M MK4+B12 USE AF4560	D	685738
203	20/03/2014	453299	ENGINE OIL DELO 400LE 15W40	D	685738
203	20/03/2014	453299	OIL FILTER B10M +B7R BY PASS (VOLVO)	D	685738
203	20/03/2014	453299	Grease AC Compressor Clutch Bearing	A	685738
203	20/03/2014	453299	Tension ALL Wheel Nuts to OEM Specs	A	685738
203	20/03/2014	453299	A Service	A	685738
203	17/03/2014	452575	Passenger Doors rear not opening	NSW-PDO	685002
203	07/03/2014	451280	Mechanic entered - Passenger Doors Loose	NSW-PDO	683785
203	27/02/2014	449786	Grease AC Compressor Clutch Bearing complete	A	682523
203	27/02/2014	449786	Tension ALL Wheel Nuts to OEM Specs	A	682523
203	27/02/2014	449786	A Service	A	682523
203	12/02/2014	447171	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	679895
203	12/02/2014	447171	Tension Wheel Nuts To Spec.	SAF-INSP	679895
203	12/02/2014	447171	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	679895
203	12/02/2014	447171	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	679895
203	12/02/2014	447171	Clean A/C Filter.	SAF-INSP	679895
203	12/02/2014	447171	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	679895
203	04/02/2014	445844	Mechanic entered - Engine Lacking Power	NSW-ENG	677951
203	03/02/2014	444910	ANNUAL INSPECTION	P	678554
203	02/02/2014	444910	Annual Licence	P	676788
203	31/01/2014	445206	WORN - POS 1 - 11 R22.5 - NEW	NSW-W&T	677473
203	31/01/2014	445276	INTERIOR LIGHT DEFUSER	NSW-E&L	677473
203	30/01/2014	445266	Whls & Tyres - Tyre 1 low tread	NSW-W&T	677358
203	30/01/2014	445206	Whls & Tyres - REPLACE TYRE POS 1 - WORN	NSW-W&T	677358
203	30/01/2014	445281	Mechanic entered - Elec & Light Interior Lights	NSW-E&L	677358
203	30/01/2014	445276	TEKNOWARE INVERTER 15-40W (ACX7097 )	NSW-E&L	677358
203	30/01/2014	445276	Mechanic entered - Elec & Light Interior Lights	NSW-E&L	677358
203	30/01/2014	445275	WEDGE GLOBE INSTRUMENT 24V 5W	NSW-E&L	677358
203	30/01/2014	445275	Mechanic entered - Elec & Light Park Lights	NSW-E&L	677358
203	30/01/2014	445275	CLEAR FRONT INDICATOR WRAP-AROUND	NSW-E&L	677358
203	30/01/2014	445273	Mechanic entered - Elec & Light Dash	NSW-E&L	677358
203	24/01/2014	444608	Mechanic entered - Eng Cool Coolant Low	NSW-ECO	676460
203	10/01/2014	442631	Steering - Power steering over flowing	NSW-STE	673916
203	10/01/2014	442631	SOLENOID VALVE ZF AUTO	NSW-STE	673916
203	10/01/2014	442631	O RING VALVE TO RESERVOIR 7MM X 2MM ZF	NSW-STE	673916
203	10/01/2014	442631	B12BLE ALTERNATOR CRANK BELT	NSW-STE	673916
203	10/01/2014	442631	O RING F/WHEEL HUB CAP	NSW-STE	673916
203	10/01/2014	442631	PLUG BRASS OIL HUB CAP VOLVO	NSW-STE	673916
203	10/01/2014	442631	FRONT HUB CAP OIL HUB VOLVO	NSW-STE	673916
203	10/01/2014	442631	Steering - RH kingpin excessive movement	NSW-STE	673916
203	10/01/2014	442631	Gearbox - Transmission accumulator valve leaking air	NSW-GEA	673916
203	10/01/2014	442631	Elec & Light - Alternator belt starting to crack	NSW-E&L	673916
203	10/01/2014	442631	FRONT PADS VOLVO EARLY B7R+B10L+B12BLE	NSW-BRA	673916
203	10/01/2014	442631	Brakes - Front brake pads low	NSW-BRA	673916

203	09/01/2014	442346 ADAM DUSCOMBE	Service A/C Air Return Filter	RSI	673835
203	09/01/2014	442339 NO SMOKING GOV REG DECAL		P	673835
203	09/01/2014	442562 Vandalism - Clean graffiti - seats side walls - OSR	Cleaned	NSW-VAN	673835
203	09/01/2014	442562 Vandalism - RHR windows scratched up with graffiti	complited	NSW-VAN	673835
203	09/01/2014	442562 Vandalism - Graffiti throughout bus on seats & trimmings	Cleaned	NSW-VAN	673835
203	09/01/2014	442631 KINGPIN KIT (INC BEARING)		NSW-STE	673835
203	09/01/2014	442631 24V DRIVERS FAN (USE FASCO ONLY)		NSW-H&D	673835
203	09/01/2014	442631 Heat & Demist - No drivers fan in bus	ADAM DUSCOMBE - Fited new one	NSW-H&D	673835
203	09/01/2014	442675 Body & Acc - Secure all lower skirt panels	completed	NSW-BSW	673835
203	09/01/2014	442675 Body & Acc - Hand straps - secure or replace OSR	completed	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Remove G decals inside	Removed	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Replace fleet numbers - both sides front and r	Replaced	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Replace interior decals - No Smoking	Replaced	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Secure seat squabs - NS 511	Secured	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Retension LHS 4th hand rail mount	Replaced	NSW-BSW	673835
203	09/01/2014	442562 Body & Acc - Secure NS 1 seat frames	Replaced frame bolt	NSW-BSW	673835
203	09/01/2014	442562 PLASTIC TRIANGLE HANDSTRAP GREY		NSW-BSW	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Inspect Bus As Per Inspection Sheet	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Replace Fuel Filter With Water Bowl	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Replace Fuel Filter	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Remove Intercooler Wash Intercooler and Raditor	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE - not time	Adjust Valve Clearance	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Rekit Quick Release Valve	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Replace Air Dryer Canister	RSI	673835
203	08/01/2014	442346 POWER STEER +HYD FAN FILTER		RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	RSI	673835
203	08/01/2014	442346 FILTER AIR DRYER SCANIA K124EB (T350W)		RSI	673835
203	08/01/2014	442346 SEAL QUICK RELEASE VALVE		RSI	673835
203	08/01/2014	442346 DIAPHRAGM QUICK RELEASE		RSI	673835
203	08/01/2014	442346 FUEL WATER FILTER B12BLE		RSI	673835
203	08/01/2014	442346 FUEL FILTER B12BLE		RSI	673835
203	08/01/2014	442346 RPM BORATE EP LUBE 220	DIFF OIL	RSI	673835
203	08/01/2014	442346 ADAM DUSCOMBE	Replace Power Steering And Hydraulic Fan Oil Filter	RSI	673835
203	08/01/2014	442346 ROCKER COVER GASKET B12BLE		RSI	673835
203	08/01/2014	442346 O RING B12BLE INTERCOOLER		RSI	673835
203	08/01/2014	442346 TEXAMATIC 1888	P/STEER TOP UP OIL	RSI	673835
203	08/01/2014	442339 Annaut Body Inspection	INSPECTED	P	673835
203	08/01/2014	442631 KING PIN SET (INC BEARING)	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G133791 Receiving #:135323 Date :2014-01-09	NSW-STE	673835
203	23/12/2013	440205 Mechanic entered - Elec & Light Battery Flat	jump start p/i and road tested.	NSW-E&L	671760
203	19/12/2013	440205 Suspension - Rear LH top reaction rod bush u/s		NSW-SUS	671760
203	19/12/2013	440205 Suspension - NF lower control arm bush cracked	Replace N/S/F control arm bushes with Alan	NSW-SUS	671760
203	19/12/2013	440205 Suspension - NF lower control arm bush cracked	REPLACED	NSW-SUS	671760
203	19/12/2013	440205 BUSH KIT LOWER CONTROL ARM BUSH B10BLE		NSW-SUS	671760
203	18/12/2013	440097 Steering - OF Kingpin play noisy	Check Kingpin with Alan	NSW-STE	671760
203	15/12/2013	438923 Engine - Faulty oil pressure gauge	Has been done	NSW-ENG	670523
203	15/12/2013	438922 Elec & Light - OR interior light u/s (tube OK)	has been done	NSW-E&L	670523
203	14/12/2013	439417	Done	SAF-INSP	670683
203	14/12/2013	439417	Tension Wheel Nuts To Spec.	SAF-INSP	670683
203	14/12/2013	439417	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	670683
203	14/12/2013	439417	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	670683
203	14/12/2013	439417	Clean A/C Filter.	SAF-INSP	670683
203	14/12/2013	439417	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	670683
203	14/12/2013	439533 Eng Cool - Check for coolant leak	Repaired leak from bottom pipee of radiator	NSW-ECO	671094
203	14/12/2013	439533 Remove BTS Equipment Fuses	Removed	NSW-BSW	671094
203	14/12/2013	439418 Service	Perform Annual air system check as per Checklist	AIR SYS CHEC	670683
203	12/12/2013	439011 Remove A3 Hold On Poster and Fit A3 Catching a bus poster	REPLACED	NSW-BSW	670523
203	10/12/2013	438412 GLOBE H1 24V 70W		NSW-E&L	670063
203	09/12/2013	438412 n/s headlight out	replace globe and fix wiring	NSW-E&L	669833
203	05/12/2013	437863 Accident damage - Acc # DAN 38333 - *To be repaired at Dand	Cut and polished N/S/R corner and 3 panels.	NSW-ACC	669444
203	29/11/2013	436118 CAPPING	Creditor #:GB-BEA001 BEAUREPAIRS P/O #:G132202 Receiving #:134052 Date :2013-12-02 SCRAPPED	NSW-W&T	669015
203	25/11/2013	436444 Fit New Myki Decal as Per PTV fitting instructions	Fitted Myki decal to N/S/F exterior window.	NSW-BSW	667530
203	25/11/2013	436443 Perform Campaign as per Instructions Ensure that appropri	Completed.	NSW-BSW	667530
203	22/11/2013	436118 Whls & Tyres - SCRAP TYRE	CAPPING LIMIT SCRAPPED	NSW-W&T	667256
203	20/11/2013	435770	A Service complete complete	A	666893
203	20/11/2013	435770	Grease AC Compressor Clutch Bearing	A	666893
203	20/11/2013	435770	Tension ALL Wheel Nuts to OEM Specs	A	666893
203	20/11/2013	435770	A Service complete complete	A	666893
203	19/11/2013	435630 Waiting on Acc #.	Complete3d on W/O # 419794.	NSW-ACC	666679

203	12/11/2013	434761 Complete Campaign 16/12 as required - paint wheels	Checked Ok	NSW-W&T	665086
203	11/11/2013	434504 Replace Park Brake Valve	Replaced	NSW-BRA	665086
203	01/11/2013	427222 IMAGE RELATED REPAIRS TO BUSES	Creditor #:GB-TRA013 TRANSCAL P/O #:G128890 Receiving #:133274 Date :2013-11-13	NSW-BSW	665086
203	28/10/2013	432348 WORN - POS 4 - 11 R22.5 SP360	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G131227 Receiving #:132730 Date :2013-10-29 REPLACE WITH NEW	NSW-W&T	663063
203	28/10/2013	432348 Whls & Tyres - Replace tyre pos 4 - worn	Replaced	NSW-W&T	662582
203	26/10/2013	432234	done	SAF-INSP	662582
203	26/10/2013	432234	Tension Wheel Nuts To Spec.	SAF-INSP	662582
203	26/10/2013	432234	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	662582
203	26/10/2013	432234	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	662582
203	26/10/2013	432234	Clean A/C Filter.	SAF-INSP	662582
203	26/10/2013	432234	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	662582
203	26/10/2013	432366 Whls & Tyres - Replace tyre pos 4	Replaced	NSW-W&T	662582
203	25/10/2013	432135 BLADE WIPER 32INS		NSW-W&W	662582
203	24/10/2013	432135 Wipers & Washers - Check wipers	Replaced blades	NSW-W&W	662582
203	22/10/2013	431466 DRIVERS NO DEFECT CHECKLIST DECAL		NSW-BSW	662111
203	22/10/2013	431466 BY LAW PICKUP/SET DOWN DECAL		NSW-BSW	661843
203	22/10/2013	431466 CUSTOMER ENQUIRY DECAL		NSW-BSW	661843
203	22/10/2013	431466 PLEASE ASSIST DRIVER DECAL		NSW-BSW	661843
203	22/10/2013	431466 PASSENGERS REQUIRED BY LAW DECAL		NSW-BSW	661843
203	22/10/2013	431466 WARNING MAXIMUM HEIGHT DECAL		NSW-BSW	661843
203	22/10/2013	431466 EMERGENCY PROCEDURE DECAL		NSW-BSW	661843
203	22/10/2013	431466 LICENSED TO CARRY DECAL		NSW-BSW	661843
203	22/10/2013	431466 NO SMOKING DECAL		NSW-BSW	661843
203	22/10/2013	431466 CCTV SURVEILLANCE DECAL		NSW-BSW	661843
203	21/10/2013	430954 REJECT - SCRAP	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G130885 Receiving #:132428 Date :2013-10-22 SCRAPPED	NSW-W&T	661843
203	19/10/2013	431204 Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed by operations	NSW-BSW	661343
203	18/10/2013	430954 Whls & Tyres - Tyre reject	Scrapped	NSW-W&T	660665
203	14/10/2013	431466 Perform sticker audit on vehicles ensuring that correct sti	Removed & replaced	NSW-BSW	660094
203	09/10/2013	429331 Mechanic entered - Eng Cool Coolant Low	added coolant.	NSW-ECO	659178
203	29/09/2013	427222 Carry out campaign as per Fleet re-branding Procedure.	Completed	NSW-BSW	656493
203	18/09/2013	425942 SWITCH INDICATOR/CRUISE SUIT B12BLE VOLVO		NSW-E&L	654898
203	18/09/2013	425942 Elec & Light Indicator stalk broken	changed indicator stalk. OK.	NSW-E&L	654898
203	14/09/2013	424499 Brake Interlock Re-Install to be performed as per Campaign	Completed	NSW-BRA	653126
203	13/09/2013	425282	Tension Wheel Nuts To Spec.	SAF-INSP	653743
203	13/09/2013	425282	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	653743
203	13/09/2013	425282	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	653743
203	13/09/2013	425282	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	653743
203	13/09/2013	425282	Clean A/C Filter.	SAF-INSP	653743
203	13/09/2013	425443 Elec & Light - Replace dash light globe	Replaced	NSW-E&L	653743
203	11/09/2013	424853 Mechanic entered - Passenger Doors Not Operating	REPAIR and replace bolt on rear door	NSW-PDO	653211
203	09/09/2013	424455 Body & Acc Remove exterior decals and polish	Removed front sides & rear hatch door decals polished & washed the bus	NSW-BSW	652908
203	07/09/2013	423389 Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed	NSW-EQU	651186
203	06/09/2013	423760 WORN - POS 2 - 11 R22.5 - NEW	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G129156 Receiving #:130527 Date :2013-09-06 REPLACE WITH NEW	NSW-W&T	651919
203	05/09/2013	423760 Whls & Tyres - Replace tyre pos 2 - worn	Replaced	NSW-W&T	651414
203	04/09/2013	423605 Whls & Tyres - No 2 tyre low	done	NSW-W&T	651414
203	04/09/2013	423605 Whls & Tyres - No 2 tyre low	Change Tyre Position # 2	NSW-W&T	651414
203	04/09/2013	423648 GLOBE S/CONTACT 24V-10W		NSW-E&L	651414
203	04/09/2013	423648 Mechanic entered - Elec & Light Indicators	Replaced n/s/f top indicator light globe	NSW-E&L	651414
203	04/09/2013	423592	A & T Service Completed	A&T	651414
203	04/09/2013	423592	Service T Replace Transmission Oil & Filter done	A&T	651414
203	04/09/2013	423592 ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS		A&T	651414
203	04/09/2013	423592 FILTER TRANSMISSION ZF 4139-298-038E39HD119		A&T	651414
203	04/09/2013	423592	Grease AC Compressor Clutch Bearing done	A	651414
203	04/09/2013	423592	Tension ALL Wheel Nuts to OEM Specs done	A	651414
203	04/09/2013	423592	A Service done	A	651414
203	03/09/2013	423054 WORN - POS 1 - 11 R22.5 - NEW	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G128953 Receiving #:130339 Date :2013-09-03 REPLACE WITH NEW	NSW-W&T	651186
203	03/09/2013	423267 GLOBE S/CONTACT 24V-10W		NSW-E&L	650351
203	03/09/2013	423267 Mechanic entered - Elec & Light Park Lights	fit both top light globes	NSW-E&L	650351
203	02/09/2013	423054 Whls & Tyres - Replace tyre pos 1 - worn	Replaced	NSW-W&T	650351
203	02/09/2013	423019 GLOBE H1 24V 70W		NSW-E&L	650351
203	02/09/2013	423019 Mechanic entered - Elec & Light Cab Light	fit rhs headlamp	NSW-E&L	650351
203	31/08/2013	423044 Whls & Tyres - Replace tyre 1	Replaced & torqued w/nuts	NSW-W&T	650645
203	27/08/2013	422174 Mechanic entered - Eng Cool Coolant Low	add coolant.	NSW-ECO	649336
203	19/08/2013	420816 Mechanic entered - Brakes Noisy	All wheel steam cleaned.Road test ok.	NSW-BRA	647475
203	13/08/2013	419794 L.E.D SIDE MARKER PEREI RED/AMBER		NSW-E&L	646034
203	12/08/2013	419794 Elec & Light - Replace n/s/r clearance light	Replaced	NSW-E&L	646034
203	12/08/2013	419678 Elec & Light Altern Light replace alternator belt	Replace lens	NSW-E&L	646034
203	12/08/2013	419678 Elec & Light Indicators	Checked ok	NSW-E&L	646034

203	12/08/2013	419678	BELT ENGINE CUMMINS (8PK1640) 4cyl		NSW-E&L	646034
203	12/08/2013	419678	B12BLE BELT TENSIONER		NSW-E&L	646034
203	09/08/2013	419298	GLOBE DASH B7L		NSW-E&L	646034
203	09/08/2013	419364	Eng Cool - Add coolant	Added	NSW-ECO	646034
203	09/08/2013	419298	HOSE -RETARDER B12BLE		NSW-ECO	646034
203	09/08/2013	418560	REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	646034
203	09/08/2013	418560	Brakes - ABS light (red) stays on	Fitted rear pads & calibrated	NSW-BRA	646034
203	08/08/2013	419298	Elec & Light - Replace dash globes	Replaced	NSW-E&L	646160
203	08/08/2013	419298	Eng Cool - transmission coolant hose cracked	Replaced the hose r/tested OK	NSW-ECO	646160
203	05/08/2013	418540	4 WAY VALVE B12BLE (K/B AE4604)		NSW-AIR	645108
203	02/08/2013	418359		Tension Wheel Nuts To Spec.	SAF-INSP	644876
203	02/08/2013	418359		Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	644876
203	02/08/2013	418359		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	644876
203	02/08/2013	418359		Clean A/C Filter.	SAF-INSP	644876
203	02/08/2013	418359		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	644876
203	02/08/2013	418560	Brakes - ABS light (red) stays on	Check for light on (diff lining wear)needs retine	NSW-BRA	645108
203	02/08/2013	418540	Air System - Air leaking at 6way valve near rear axle	Changed 4way valve	NSW-AIR	644876
203	31/07/2013	417905	BATTERY 800CCA		NSW-E&L	644499
203	30/07/2013	417905	Elec & Light - Load test & check charge rate	Checked alt charge load tested batteries moved bus and changed batteries	NSW-E&L	644499
203	30/07/2013	417867	Elec & Light - Bus wont start	Jump started	NSW-E&L	644499
203	29/07/2013	417767	Elec & Light - Bus wont start	Jump started	NSW-E&L	644037
203	27/07/2013	417364	Elec & Light - Bus wont start	Jump started	NSW-E&L	644037
203	26/07/2013	417261	Elec & Light - Bus wont start	Jump started	NSW-E&L	643659
203	26/07/2013	417261	Elec & Light - Bus wont start	Jump started	NSW-E&L	643659
203	25/07/2013	417023	Heat & Demist - Driver fan missing	Removed broken base of drivers fan	NSW-H&D	643659
203	25/07/2013	417017	Elec & Light - Bus wont start	Jump started	NSW-E&L	643659
203	24/07/2013	416882	Elec & Light - Bus wont start	Jump started	NSW-E&L	643460
203	24/07/2013	416598	DOWN LIGHT LED		NSW-E&L	643243
203	23/07/2013	416660	Elec & Light - Bus wont start	Jump started	NSW-E&L	643243
203	23/07/2013	416660	Elec & Light - Bus wont start	Jump started	NSW-E&L	643243
203	23/07/2013	416598	Elec & Light - replace downlight	Replaced	NSW-E&L	643243
203	23/07/2013	416351	GLOBE 24V 21W SINGLE CONTACT		NSW-E&L	643039
203	22/07/2013	416353	Elec & Light - Bus wont start	Jump started	NSW-E&L	643039
203	22/07/2013	416351	Elec & Light - Replace OSF side indicator	Replaced	NSW-E&L	643039
203	21/07/2013	416266	Elec & Light - Bus wont start	Jump started	NSW-E&L	642817
203	20/07/2013	416247	Elec & Light - Bus wont start	Jump started	NSW-E&L	642817
203	19/07/2013	416157	Elec & Light - Bus wont start	Jump started	NSW-E&L	642657
203	19/07/2013	415821	3MM X 1200MM X 2400MM FLAT ALUMINIUM		NSW-ACC	642383
203	18/07/2013	415821	UNREPORTED - Front bumper middle bar damaged - hole	Dismantled front b/bar fibreglass repaired sanded primed painted b/bar yellow replaced emer exit decal fitted door valve bracket fitted rego plate jump started fuelled & parked	NSW-ACC	642211
203	14/07/2013	415203	Elec & Light - Bus wont start	Jump started	NSW-E&L	641482
203	10/07/2013	414421	SUMP PLUG WASHER B12B		D	640549
203	10/07/2013	414421		Remove V-Belts & Check Tensioner Bearings for Noise	D	640549
203	10/07/2013	414421		Tension ALL Wheel Nuts to OEM Specs	D	640549
203	10/07/2013	414421	OIL FILTER LONG LIFE B12BLE (VOLVO)		D	640549
203	10/07/2013	414421		D Service & Change Engine Oil	D	640549
203	10/07/2013	414421	FILTER AIR B10M MK4+B12 USE AF4560		D	640549
203	10/07/2013	414421	ENGINE OIL DELO 400LE 15W40	ENGINE OIL	D	640549
203	10/07/2013	414421	OIL FILTER B10M +B7R BY PASS (VOLVO)		D	640549
203	10/07/2013	414421		Grease AC Compressor Clutch Bearing	A	640549
203	10/07/2013	414421		Tension ALL Wheel Nuts to OEM Specs	A	640549
203	10/07/2013	414421		A Service	A	640549
203	08/07/2013	413918	V-BELT		NSW-SCA	639931
203	08/07/2013	414103	Elec & Light - Adjust hatch switch	Adjusted	NSW-E&L	640221
203	08/07/2013	414086	Elec & Light - Bus wont start	Jump started	NSW-E&L	640221
203	05/07/2013	413584	IMPACT BREAKS	Creditor #:GB-BEA001 BEAUREPAIRS P/O #:G126646 Receiving #:127917 Date :2013-07-09 SCRAPPED	NSW-W&T	640221
203	05/07/2013	413584	Whls & Tyres - Impact break	Scrapped	NSW-W&T	639387
203	05/07/2013	413918	Air Cond - Inner a/c belts need replacing	Replaced	NSW-SCA	639736
203	05/07/2013	413907	Eng Cool - Add coolant	Added	NSW-ECO	639736
203	04/07/2013	413327	REPL WINDSCREEN	Creditor #:GB-ELI001 ELITE WINDSCREENS P/O #:G126593 Receiving #:127705 Date :2013-07-05	NSW-B&W	639387
203	04/07/2013	413327	Body & Acc Windows - windscreen cracked		NSW-B&W	639288
203	28/06/2013	412826	Whls & Tyres - Replace w/nut indicator	Replaced	NSW-W&T	638253
203	24/06/2013	411309	WORN - POS 45 - 11 R22.5 SP36	Creditor #:GB-BEA001 BEAUREPAIRS P/O #:G126045 Receiving #:127189 Date :2013-06-25 REPLACE WITH RECAP	NSW-W&T	637141
203	21/06/2013	411309	Whls & Tyres - REPLACE TYRE POS 45 - WORN	REPLACED	NSW-W&T	636356
203	20/06/2013	411282	PTI	Tension Wheel Nuts To Spec.	SAF-INSP	636283
203	20/06/2013	411282		Tension Wheel Nuts To Spec.	SAF-INSP	636283
203	20/06/2013	411282		Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	636283
203	20/06/2013	411282		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	636283
203	20/06/2013	411282		Clean A/C Filter.	SAF-INSP	636283

203	20/06/2013	411282	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	636283
203	20/06/2013	411419	Whls & Tyres - Replace rear tyres	NSW-W&T	636356
203	20/06/2013	411253	Accident damage	NSW-BSW	636283
203	12/06/2013	406370	HINGE DRIVERS COMPARTMENT	NSW-BSW	636283
203	11/06/2013	406370	Body & Acc Drivers Seat Back Rest--cover behind drivers se	NSW-BSW	631844
203	11/06/2013	406370	Body & Acc Interior---front dor lock rattling.	NSW-BSW	631844
203	05/06/2013	409113	Eng Cool - Add coolant	NSW-ECO	634890
203	29/05/2013	407833	Accident Damaged #36425 R/R. n/s/r. tail/brake light ass.	NSW-ACC	633347
203	22/05/2013	406370	BUSH KIT UPPER CONTROL ARM B10BLE	NSW-SUS	631915
203	22/05/2013	406370	STEERING WHL B12BLE 450MM DIA	NSW-STE	631915
203	21/05/2013	406370	NUT UPPER+LOWER SUSPENSION ARM	NSW-SUS	631844
203	21/05/2013	406370	NUT UPPER+LOWER SUSPENSION ARM	NSW-SUS	631844
203	21/05/2013	406370	Suspension Worn L/H/S upper control arm bushes	NSW-SUS	631844
203	21/05/2013	406370	Suspension - Rear LH front airbag leaking	NSW-SUS	631844
203	21/05/2013	406370	Steering - Steering shaft worn (centre joint have more play)	NSW-STE	631844
203	21/05/2013	406370	Steering - Chunks missing out of steering wheel	NSW-STE	631844
203	21/05/2013	406370	Engine - Compressor passing oil	NSW-ENG	631844
203	21/05/2013	406370	Air System - Continous air leaking at air dryer bottom part	NSW-AIR	631844
203	20/05/2013	406518	Steering - Driver complain about steering	NSW-STE	631844
203	13/05/2013	405347	Eng Cool - Add coolant	NSW-ECO	630259
203	06/05/2013	404137	Elec & Light----fan is loose.	NSW-E&L	628713
203	01/05/2013	403444	checked fan. fan broken. ordered fan. cut old fan off to avoid safety hazard.carry over	SAF-INSP	627455
203	01/05/2013	403444	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	627455
203	01/05/2013	403444	Clean A/C Filter.	SAF-INSP	627455
203	01/05/2013	403444	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	627455
203	01/05/2013	403444	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	627455
203	01/05/2013	403444	Tension Wheel Nuts To Spec.	SAF-INSP	627455
203	01/05/2013	403444	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	627455
203	01/05/2013	403504	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	NSW-EQU	627455
203	30/04/2013	403232	AIR BAG B12BLE	NSW-SUS	627155
203	30/04/2013	403232	REAR AIR BAG SUIT VOLVO B12B B12BLE	NSW-SUS	627155
203	30/04/2013	403082	AIR BAG B12BLE	A	627155
203	29/04/2013	403306	Suspension - front both side airbags leaking	NSW-SUS	627155
203	29/04/2013	403232	Suspension - Replace NR airbag	NSW-SUS	627155
203	29/04/2013	403232	Suspension - Replace NR airbag	NSW-SUS	627155
203	29/04/2013	403082	Grease AC Compressor Clutch Bearing	A	626942
203	29/04/2013	403082	A Service	A	626942
203	29/04/2013	403082	Tension ALL Wheel Nuts to OEM Specs	A	626942
203	29/04/2013	403082	A Service	A	626942
203	24/04/2013	402615	Body & Acc - Repair loose rear hatch	NSW-BSW	626229
203	22/04/2013	402372	Eng Cool - Add coolant	NSW-ECO	626010
203	16/04/2013	401620	Elec & Light - No lights	NSW-E&L	624959
203	11/04/2013	400979	Elec & Light - OSF interior light out	NSW-E&L	623923
203	03/04/2013	398890	New tyre still rim 11R22.5 pos	NSW-W&T	621721
203	02/04/2013	399475	Elec & Light - Replace int fluro	NSW-E&L	621721
203	01/04/2013	399462	Elec & Light - Bus wont start	NSW-E&L	621509
203	28/03/2013	398890	Whls & Tyres Replace tyre pos 1	NSW-W&T	621222
203	27/03/2013	398987	Whls & Tyresreplace tyre pos. 1	NSW-W&T	621222
203	26/03/2013	398919	Whls & Tyres Replace tyres pos. 3. 4.	NSW-W&T	621071
203	22/03/2013	398207	GLOBE DASH B7L	NSW-E&L	619963
203	21/03/2013	398207	Elec & Light Dash light out	NSW-E&L	619963
203	19/03/2013	397630	FANBELT	NSW-SCA	619140
203	18/03/2013	397549	Elec & Light flat batteries	NSW-E&L	618837
203	18/03/2013	397741	Elec & Light Horn u/s	NSW-E&L	619140
203	15/03/2013	397217	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	618489
203	15/03/2013	397217	Clean A/C Filter.	SAF-INSP	618489
203	15/03/2013	397217	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	618489
203	15/03/2013	397217	Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	618489
203	15/03/2013	397217	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	618489
203	15/03/2013	397217	Tension Wheel Nuts To Spec.	SAF-INSP	618489
203	15/03/2013	397031	Whls & Tyres pos. 5. 6.worn	NSW-W&T	618489
203	15/03/2013	393193	Steering - Steering wheel needs to be changed	NSW-STE	618489
203	15/03/2013	393193	Steering - Steering wheel needs to be changed	NSW-STE	618489
203	15/03/2013	397487	Air Cond ourher belts cracks	NSW-SCA	618735
203	15/03/2013	397485	Elec & Light----wire hanging out-left foot drivers compart	NSW-E&L	618735
203	13/03/2013	397630	Air Cond belts worn	NSW-SCA	618222
203	13/03/2013	396734	GLOBE HIGH BEAM 24V70W H1	NSW-E&L	617982
203	11/03/2013	396734	Elec & Light head light out	NSW-E&L	617711
203	05/03/2013	394588	ROAD SAFETY INSPECTIONS	P	616527
			Creditor #:ROA001 Road Safety Inspections P/O #:G120822 Receiving #:121889 Date :2013-03-05		

203	04/03/2013	395611	Eng Cool - Add coolant	Added	NSW-ECO	616224
203	03/03/2013	394588	Annual Licence	RWC 818495 - Passed	P	615048
203	28/02/2013	395025	SEAT BELT BUCKLE TWIN WIRE GREY		NSW-BSW	615535
203	27/02/2013	395025	Body & Acc - Replace buckle	Replaced	NSW-BSW	615535
203	23/02/2013	394337	ADJUST VALVE CLEARANCES		NSW-ENG	614465
203	23/02/2013	394337	ADJUST VALVE CLEARANCES		NSW-ENG	614465
203	21/02/2013	393968	GLOBE S/CONTACT 24V-10W		NSW-E&L	613758
203	21/02/2013	393968	LENS TO SUIT 2029 (RED+AMBER)		NSW-E&L	613758
203	20/02/2013	393968	Etec & Light - Replace NSF upper park light	Replaced	NSW-E&L	613758
203	18/02/2013	393366	FILTER AIR CLEANED B10M MK4 +B12		RSI	613293
203	18/02/2013	393366	O RING B12BLE INTERCOOLER		RSI	613293
203	15/02/2013	393366	FILTER AIR DRYER SCANIA K124EB (T350W)		RSI	612744
203	15/02/2013	393366	POWER STEER +HYD FAN FILTER		RSI	612744
203	15/02/2013	393366		Replace Air Dryer Canister	RSI	612744
203	15/02/2013	393366		Replace Power Steering And Hydraulic Fan Oil Filter	RSI	612744
203	15/02/2013	393366		Service A/C Air Return Filter	RSI	612744
203	15/02/2013	393366	RPM BORATE EP LUBE 220	DIFF OIL	RSI	612744
203	15/02/2013	393366	TEXAMATIC 1888	P/STEER TOP UP OIL	RSI	612744
203	15/02/2013	393366	FUEL FILTER B12BLE		RSI	612744
203	15/02/2013	393366	FUEL WATER FILTER B12BLE		RSI	612744
203	15/02/2013	393366	DIAPHRAGM QUICK RELEASE		RSI	612744
203	15/02/2013	393366	SEAL QUICK RELEASE VALVE		RSI	612744
203	15/02/2013	393366		Remove Intercooler Wash Intercooler and Raditor	RSI	612744
203	15/02/2013	393366		Inspect Bus As Per Inspection Sheet	RSI	612744
203	15/02/2013	393366		Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	RSI	612744
203	15/02/2013	393366		Replace Fuel Filter	RSI	612744
203	15/02/2013	393366		Replace Fuel Filter With Water Bowl	RSI	612744
203	15/02/2013	393366		Rekit Quick Release Valve	RSI	612744
203	15/02/2013	393366		Adjust Valve Clearance	RSI	612744
203	15/02/2013	393366		Remove Intercooler Wash Intercooler and Raditor	RSI	612744
203	15/02/2013	393366		Inspect Bus As Per Inspection Sheet	RSI	612744
203	15/02/2013	393366	O RING B12BLE INTERCOOLER		RSI	612744
203	15/02/2013	393366	ROCKER COVER GASKET B12BLE		RSI	612744
203	15/02/2013	393366		Remove Intercooler Wash Intercooler and Raditor	RSI	612744
203	15/02/2013	393366		Replace Air Dryer Canister	RSI	612744
203	15/02/2013	393193	Steering - Steering wheel needs to be changed		NSW-STE	612744
203	14/02/2013	393193	WHEEL STEERING B10M MK2		NSW-STE	612744
203	06/02/2013	392218	Eng Cool - Clean radiator	Cleaned	NSW-ECO	611185
203	06/02/2013	392174	Body & Acc - Refit NR seat	Refitted	NSW-BSW	611185
203	06/02/2013	392093		A Service	A	610952
203	06/02/2013	392093		Tension ALL Wheel Nuts to OEM Specs	A	610952
203	06/02/2013	392093		Grease AC Compressor Clutch Bearing	A	610952
203	06/02/2013	392093		A Service	A	610952
203	29/01/2013	390825	Eng Cool - Add coolant	added	NSW-ECO	609506
203	25/01/2013	390445		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	609171
203	25/01/2013	390445		Clean A/C Filter.	SAF-INSP	609171
203	25/01/2013	390445		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	609171
203	25/01/2013	390445		Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	609171
203	25/01/2013	390445		Tension Wheel Nuts To Spec.	SAF-INSP	609171
203	25/01/2013	390445	REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	609171
203	25/01/2013	390445	Mechanic entered - Suspension Leaking	Fitted new air bag	NSW-SUS	609171
203	25/01/2013	390444	Brakes - Check brakes display on dash	Checked rear modulator valve wire broken fixed by Greg another code for rear brake pad	NSW-BRA	609171
203	25/01/2013	390444	Brakes - Check brakes display on dash	Repaired wires on brake modulator valve	NSW-BRA	609171
203	25/01/2013	390445	Mechanic entered - Brakes Brake Linings Worn	Fitted new brake pads & calibrated rear brakes	NSW-BRA	609171
203	25/01/2013	390445	REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	609171
203	22/01/2013	389840	GLOBE S/CONTACT 24V-10W		NSW-E&L	608334
203	21/01/2013	389840	Etec & Light - Replace NS front top park light globe	Replaced	NSW-E&L	608334
203	17/01/2013	389176	CLEAR LENS SUIT 1406		NSW-E&L	607251
203	16/01/2013	389176	Etec & Light - Replace front top upper clearance lens	Replaced	NSW-E&L	607251
203	15/01/2013	389118	Etec & Light - Adjust engine bay door switch	Adjusted	NSW-E&L	607045
203	14/01/2013	388652	GLOBE H1 24V 70W		NSW-E&L	606508
203	13/01/2013	388652	Etec & Light - Replace ns headlight globe	Replaced	NSW-E&L	606508
203	02/01/2013	386952	L.E.D.GLOBE FOR SWF SWITCH		NSW-E&L	603488
203	31/12/2012	386952	Etec & Light - Replace LED globe	Replaced	NSW-E&L	603316
203	27/12/2012	386159	WORN - POS 1 - 11 R22.5 - NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:K118283 Receiving #:118954 Date :2012-12-27 REPLACE WITH NEW	NSW-W&T	602125
203	24/12/2012	386365	Wipers & Washers - Top up wiper bottle	Added	NSW-W&W	602007
203	24/12/2012	386159	Whls & Tyres - Replace tyre pos 1 - worn	replaced	NSW-W&T	601762
203	21/12/2012	386224	Whls & Tyres - Tyre # 1 low	Replaced tyre	NSW-W&T	601380

203	21/12/2012	386224	Whls & Tyres - Tyre # 1 low	Replaced tyre & torqued w/nuts	NSW-W&T	601380
203	18/12/2012	385516		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	600340
203	18/12/2012	385516		Clean A/C Filter.	SAF-INSP	600340
203	18/12/2012	385516		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	600340
203	18/12/2012	385516		Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	600340
203	18/12/2012	385516		Tension Wheel Nuts To Spec.	SAF-INSP	600340
203	18/12/2012	385516		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	600340
203	18/12/2012	385646	Eng Cool - Clean radiator	cleaned	NSW-ECO	600563
203	17/12/2012	384509	EVAPORATOR FAN MOTOR		NSW-SCA	600146
203	11/12/2012	384509	Air Cond Other	Remove replace all evap fan motors tested OK	NSW-SCA	599217
203	10/12/2012	384509	Air Cond Other	Checked found one fan n/w	NSW-SCA	599217
203	04/12/2012	383574	LED SIDE INDICATOR LAMP amber		NSW-E&L	598218
203	03/12/2012	383574	Elec & Light - Replace NS clearance light	Replaced	NSW-E&L	598218
203	26/11/2012	382507	Eng Cool Leaking	Fixed coolant leak from heater hose & changed header tank cap	NSW-ECO	596753
203	26/11/2012	382352	HEADER TANK FILLER CAP		NSW-AIR	596673
203	26/11/2012	382352	Air System R/H/F modulator valve leaking	Assisted Michael to fix modulator valve & r/test	NSW-AIR	596673
203	26/11/2012	382352	FRT MODULATOR VALVE EBS	Creditor #:MUL001 MULTISPARES LTD P/O #:G117008 Receiving #:117584 Date :2012-11-26	NSW-AIR	596753
203	23/11/2012	381253	AIR CON IDLER PEDISTAL PIN/SLEEVE/ BUSH ASSEMBLY		NSW-SCA	596665
203	23/11/2012	381253	V-BELT CRANK-IDLER PULLEY		NSW-SCA	596665
203	23/11/2012	381253	FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	596665
203	23/11/2012	382507	Eng Cool Leaking	Changed both a/c boost pump coolant hoses r/tested	NSW-ECO	596753
203	22/11/2012	381253	Air Cond - Check belts	completed job	NSW-SCA	596561
203	21/11/2012	381253	BRG ALT+SPIGOT BRG G7		NSW-SCA	596561
203	21/11/2012	381253	Air Cond - Check belts	continued rebuilding c/o	NSW-SCA	596561
203	16/11/2012	373630	CALIBRATE SPEEDO	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G116399 Receiving #:117160 Date :2012-11-16	NSW-E&L	596561
203	15/11/2012	381253	Air Cond - Check belts	Removed a/c idler post start rebuilding c/o	NSW-SCA	596561
203	15/11/2012	381253	Air Cond - Check belts	Checked belts AC post worn	NSW-SCA	596561
203	15/11/2012	381253	Air Cond - Check belts	Removed a/c idler post continued rebuilding c/o	NSW-SCA	596561
203	15/11/2012	381037	GLOBE DASH B7L		NSW-E&L	596561
203	15/11/2012	381059	LED FRONT POSITION MARKER LIGHT		NSW-E&L	596561
203	15/11/2012	381059	L.E.D. BRAKE LIGHT		NSW-E&L	596561
203	14/11/2012	381037	Elec & Light - Replace warning light globe	Replaced	NSW-E&L	596561
203	14/11/2012	381059	Elec & Light - Replace both LED plate lights	Replaced	NSW-E&L	596561
203	14/11/2012	381059	Elec & Light - Replace NS stop/tail LED light	Replaced	NSW-E&L	596561
203	14/11/2012	381059	Eng Cool - Add coolant	Added	NSW-ECO	596561
203	09/11/2012	380489	Engine - Replace intake manifold sensor	Replaced and fitted clamp	NSW-ENG	596162
203	09/11/2012	373630	Elec & Light Odometer not working	replaced speedo head and dash loom	NSW-E&L	596162
203	09/11/2012	373630	Elec & Light Speedo Odo not working		NSW-E&L	596162
203	07/11/2012	373630	Direct Purchase - ELECTRICAL 7	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G114447 Receiving #:116766 Date :2012-11-07	NSW-E&L	596168
203	27/10/2012	377996	Security - Test and repair security camera system		NSW-COM	596162
203	26/10/2012	374218	Side wall damage - Scrap	Creditor #:BEA001 BEAUREPAIRS P/O #:G114443 Receiving #:116263 Date :2012-10-26	NSW-W&T	596168
203	26/10/2012	374218	Side wall damage - Scrap	Creditor #:BEA001 BEAUREPAIRS P/O #:G114443 Receiving #:116274 Date :2012-10-26	NSW-W&T	596168
203	24/10/2012	377254	Security - Test and repair security camera system	Repaired	NSW-COM	596162
203	23/10/2012	377996	Direct Purchase - ELECTRICAL	Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115560 Receiving #:116075 Date :2012-10-23	NSW-COM	596168
203	19/10/2012	377254	Test and repair security syste	Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115360 Receiving #:115890 Date :2012-10-19	NSW-COM	596168
203	12/10/2012	376558	Air Cond - Clean a/c filters	Cleaned	NSW-SCA	596162
203	10/10/2012	375762	Elec & Light - Dash warning light n/w	Checked OK	NSW-E&L	596162
203	10/10/2012	375762	Elec & Light - Dash warning light n/w	checked ok	NSW-E&L	596162
203	10/10/2012	375762	Elec & Light -IGNITION SWITCH HAS PROBLEM SOMETIMES N/W	tested extensively couldnt fault.	NSW-E&L	596162
203	09/10/2012	375996	Elec & Light - Bus wont start	Jump started	NSW-E&L	596162
203	09/10/2012	375762	Elec & Light -IGNITION SWITCH HAS PROBLEM SOMETIMES N/W		NSW-E&L	596162
203	07/10/2012	375044	Body & Acc Seat Moulding various seat through out the bus	could not fault	NSW-BSW	596162
203	27/09/2012	373630	Elec & Light Odometer not working	Checked to replace speedo head but need wire harness	NSW-E&L	596162
203	26/09/2012	374218	Whls & Tyres - Scrap tyre - sidewall damage	Scrapped	NSW-W&T	596162
203	26/09/2012	373630	Elec & Light Odometer not working	bus not hear	NSW-E&L	596162
203	24/09/2012	365722	Speedo	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G114210 Receiving #:114734 Date :2012-09-24	NSW-E&L	596162
203	20/09/2012	373350		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	596156
203	20/09/2012	373350		Clean A/C Filter.	SAF-INSP	596156
203	20/09/2012	373350		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	596156
203	20/09/2012	373350		Rotate Rear Axle Tyres Left to Right - MT & IBS only	SAF-INSP	596156
203	20/09/2012	373350		Tension Wheel Nuts To Spec.	SAF-INSP	596156
203	20/09/2012	373350		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	596156
203	20/09/2012	372396	BALD - POS 34 - 11 R22.5 SP36	Creditor #:BEA001 BEAUREPAIRS P/O #:G113861 Receiving #:114556 Date :2012-09-20 REPLACE WITH RECAP	NSW-W&T	596156
203	20/09/2012	372396	BALD - POS 34 - 11 R22.5 SP36	Creditor #:BEA001 BEAUREPAIRS P/O #:G113861 Receiving #:114557 Date :2012-09-20 REPLACE WITH RECAP	NSW-W&T	596156
203	20/09/2012	371679	FLATWORN - POS 56 - 11 R22.5	Creditor #:BEA001 BEAUREPAIRS P/O #:K113604 Receiving #:114565 Date :2012-09-20 REPAIR OR REPLACE WITH RECAP	NSW-W&T	596156
203	20/09/2012	373347	Random Vehicle Audit	Inspected	NSW-I&T	596156
203	20/09/2012	373488	Elec & Light - Replace interior fluoro	Replaced	NSW-E&L	596156
203	20/09/2012	373488	Eng Cool - Clean radiator	Cleaned	NSW-ECO	596156

203	19/09/2012	373249 Elec & Light - Replace fluro tube	Replaced	NSW-E&L	596156
203	19/09/2012	372172 Eng Cool - Check for coolant leak	Fit hose & topped up coolant	NSW-ECO	596155
203	16/09/2012	372752 Whls & Tyres - Check tyres	Checked OK	NSW-W&T	596156
203	14/09/2012	372396 Whls & Tyres - Replace tyre pos 34 - bald	Replaced	NSW-W&T	596156
203	14/09/2012	372641 Whls & Tyres - No 34 tyres low thread	Replaced 34 tyres & tesnioned w/nuts	NSW-W&T	596156
203	14/09/2012	372641 Whls & Tyres - Tyre # 4 tread low	Replaced 34 tyres & tesnioned w/nuts	NSW-W&T	596156
203	13/09/2012	372408 Eng Cool - Add coolant	Added	NSW-ECO	596156
203	11/09/2012	371939 GLOBE DASH B7L		NSW-E&L	596149
203	10/09/2012	371679 Whls & Tyres - Replace tyre pos 56 - flatworn	Replaced	NSW-W&T	596148
203	08/09/2012	371781 Body & Acc - OSF w/arch brush strip missing	replaced with used one	NSW-BSW	596147
203	07/09/2012	371939 Whls & Tyres - Replace tyres 56	Replaced & tensioned w/nuts	NSW-W&T	596147
203	07/09/2012	371939 Elec & Light - Replace dash light globes	Replaced	NSW-E&L	596147
203	27/08/2012	369866 WIPER REFILL SUIT TX800+TX900		NSW-W&W	596143
203	25/08/2012	369866 Wipers & Washers - Replace OS wiper refill	Replaced	NSW-W&W	596134
203	14/08/2012	368148 SIDE INDICATOR R/H		NSW-E&L	596116
203	14/08/2012	368152 GLOBE DASH B7L		NSW-E&L	596116
203	14/08/2012	368441 Elec & Light - Reverse buzzer n/w	Replaced	NSW-E&L	596117
203	13/08/2012	368148 Elec & Light - OS indicator broken	Replaced	NSW-E&L	596116
203	13/08/2012	368152 Elec & Light - Replace globes	Replaced dash light & os low beam h/light n/w fixed loose connection	NSW-E&L	596116
203	07/08/2012	367107 L.E.D SIDE MARKER PERE RED/AMBER		NSW-E&L	596116
203	07/08/2012	367266 Comm Equip - Stereo fallen into dash	Put back into position	NSW-COM	596116
203	06/08/2012	367107 Elec & Light - Replace smashed NSR clearance light globe	Replaced	NSW-E&L	596116
203	01/08/2012	365722 ODOMETER NOT WORKING	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G111567 Receiving #:112166 Date :2012-08-01	NSW-E&L	596116
203	01/08/2012	366422 Body & Acc - Check ramp	went to Gladstone Rd bus already left come back took bus for r/test OK checked ramp bracket loose (ramp light working checked - no supply)	NSW-BSW	596116
203	01/08/2012	366422 Body & Acc - Check ramp	R/tested with Subu to check ramp sensor	NSW-BSW	596116
203	27/07/2012	365386 24V INVERTER 4-13W		NSW-E&L	596116
203	27/07/2012	365386 INTERIOR LIGHT DEFUSER		NSW-E&L	596116
203	27/07/2012	365722 Elec & Light - Tacho n/w	Ref to w/o 373630	NSW-E&L	596116
203	27/07/2012	365722 Odometer not working	Ref to w/o 373630	NSW-E&L	596116
203	26/07/2012	365386 Elec & Light - Replace interior light globes	Replaced inverter and tube and lens for saloon lights	NSW-E&L	596116
203	26/07/2012	365386 Drv entered - Elec & Light Speedo	Checked out speedo n/w needs new (ref to w/o # 365722	NSW-E&L	596116
203	26/07/2012	365386 Ops Entered - Fault - Comm Equip Controls - Route: 861 - H	Has 594 radio in it	NSW-COM	596116
203	08/07/2012	362423 Whls & Tyres - Side Wall damage	Scraped	NSW-W&T	596112
203	05/07/2012	362264 Drv entered - Throttle Other - Brake light ondash	Check rear modulator air pressure - rese modulator value by tec. tool and road test OK	NSW-THR	596112
203	05/07/2012	362264 Drv entered - Throttle Other - Brake light ondash	Check rear modulator air pressure - rese modulator value by tec. tool and road test OK Assist to Dukith	NSW-THR	596112
203	04/07/2012	362290 Elec & Light Fault code on dash	Cleaned checked OK	NSW-E&L	596112
203	28/06/2012	361438	Clean A/C Filter.	SAF-INSP	596112
203	28/06/2012	361438	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	596112
203	28/06/2012	361438	Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	596112
203	28/06/2012	361438	Tension Wheel Nuts To Spec.	SAF-INSP	596112
203	28/06/2012	361438	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	596112
203	22/06/2012	360705 Elec & Light - Bus wont start	Checked and found that someone had pushed the emergency red button	NSW-E&L	596100
203	22/06/2012	360561 Ops Entered - Fault - Body & Acc Destination Blind - Route	TIMS Test	NSW-BSW	595848
203	22/06/2012	360562 Ops Entered - Fault - Body & Acc Destination Blind - Route	TIMS Test	NSW-BSW	595848
203	22/06/2012	360563 Body & Acc Destination Blind test	TIMS Test	NSW-BSW	595848
203	19/06/2012	360039 Elec & Light - Replace globes	Replaced interior light & changed fluro	NSW-E&L	595196
203	18/06/2012	359816 OIL FILTER B10M +B7R BY PASS (VOLVO)		D	595015
203	18/06/2012	359816 ENGINE OIL DELO 400LE 15W40	ENGINE OIL	D	595015
203	18/06/2012	359816 FILTER AIR B10M MK4+B12 USE AF4560		D	595015
203	18/06/2012	359816	D Service & Change Engine Oil	D	595015
203	18/06/2012	359816 OIL FILTER LONG LIFE B12BLE (VOLVO)		D	595015
203	18/06/2012	359816	Tension ALL Wheel Nuts to OEM Specs	D	595015
203	18/06/2012	359816	Remove V-Belts & Check Tensioner Bearings for Noise	D	595015
203	18/06/2012	359816 SUMP PLUG WASHER B12B		D	595015
203	18/06/2012	359816		D	595015
203	18/06/2012	359816	A Service	A	595015
203	18/06/2012	359816	Tension ALL Wheel Nuts to OEM Specs	A	595015
203	18/06/2012	359816	Grease AC Compressor Clutch Bearing	A	595015
203	13/06/2012	356993	Jump started for Dulkitih	NSW-E&L	594087
203	13/06/2012	356993 Brakes Front hubs leaking and putting rigt - ABS ligt on das	Checked out wiring on ABS	NSW-BRA	594087
203	13/06/2012	356993 Brakes Front hubs leaking and putting rigt - ABS ligt on das	Check modulator valve wire to RR brake wear sensor changed old R modulator cleared all fault code by tec tool r/tested bus OK	NSW-BRA	594087
203	08/06/2012	356993 Brakes Front hubs leaking and putting rigt - ABS ligt on das	change o/s brake calliper assemble bak pads change n/s hub oil seat top up hub oil adjust front brake need to chaeck r/n/s brake wear snser wirring	NSW-BRA	594087
203	08/06/2012	356993 PLUG BRASS OIL HUB CAP VOLVO		NSW-BRA	594087
203	07/06/2012	356993 Brakes Front hubs leaking and putting rigt - ABS ligt on das	change front o/s hub oil seal brake calliper assy c/o	NSW-BRA	594087
203	07/06/2012	356993 SEAL FRONT HUB BUS 80/86		NSW-BRA	594087
203	07/06/2012	356993 Ops Entered - Fault - Brakes ABS On - Route: 813 - Dandenon	change rear o/s brake calliper assy	NSW-BRA	594087
203	05/06/2012	358160 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	594087
203	05/06/2012	358161 Air Cond - Clean filter grills	Cleaned	NSW-SCA	594087

203	04/06/2012	356993 Brakes Front hubs leaking and pulling rigt - ABS ligt on das		NSW-BRA	594087
203	01/06/2012	356993 REAR CALIPER RH-VOLVO B12BLE	Creditor #:MUL001 MULTISPARES LTD P/O #:G109009 Receiving #:109361 Date :2012-06-01	NSW-BRA	594087
203	31/05/2012	356993 Ops Entered - Fault - Brakes ABS On - Route: 813 - Dandenon		NSW-BRA	594087
203	31/05/2012	356993 Brakes Front hubs leaking and pulling rigt - ABS ligt on das	Check front brak calliper o/s not woking order parts change rear o/s brake pad wear senser stil cant clear fault calliper n/w order part	NSW-BRA	594087
203	31/05/2012	356993 sensor brake 30g9022	Creditor #:MUL001 MULTISPARES LTD P/O #:G108984 Receiving #:109314 Date :2012-05-31	NSW-BRA	594087
203	31/05/2012	356993 brake caliper l/hand side 30G8	Creditor #:MUL001 MULTISPARES LTD P/O #:G108984 Receiving #:109314 Date :2012-05-31	NSW-BRA	594087
203	30/05/2012	356880 FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	594087
203	30/05/2012	356880 V-BELT		NSW-SCA	594087
203	30/05/2012	356993 Brakes Front hubs leaking and pulling rigt - ABS ligt on da		NSW-BRA	594087
203	29/05/2012	356880 A/C belts	Fit a/c belts & tighten bottom nut to a/c post	NSW-SCA	594087
203	29/05/2012	356880 Air CondWrong A/C belts has been fitted on bus	Replaced correct belts	NSW-SCA	594087
203	29/05/2012	356993 Ops Entered - Fault - Brakes ABS On - Route: 813 - Dandenon	R/tested and checked brakes its pulling left both front hub seal leak bus u/s	NSW-BRA	594087
203	25/05/2012	356339 Mechanic entered - Brakes ABS On	change rear brake modulator and road test bus ok.	NSW-BRA	593325
203	25/05/2012	355977 30g4007 rear module valve rear	Creditor #:MUL001 MULTISPARES LTD P/O #:G108672 Receiving #:108947 Date :2012-05-25	NSW-BRA	593325
203	24/05/2012	356339 Mechanic entered - Brakes ABS On	cheack brake warning on rear brake modulator value faulti order parts	NSW-BRA	593325
203	23/05/2012	354261 AIR DRYER KIT (black box)		NSW-BRA	593166
203	23/05/2012	355977 GLOBE+HOLDER INSTRUMENT (GREY)		NSW-BRA	593166
203	23/05/2012	355977 Mechanic entered - Brakes ABS On	fixe door brake abs warning light chaeck fault code by tc tool reboot brake and road test no fault code	NSW-BRA	593166
203	22/05/2012	355977 Mechanic entered - Brakes ABS On	rear n/s brake pad wear senser faulty remove clean and fix same as cl ear fault code by tec tool road test bus ok	NSW-BRA	592985
203	18/05/2012	355671 Body & Acc N/S mirror bended	Stright up	NSW-BSW	592521
203	18/05/2012	355481 Brakes ABS On	re set fault cord road tested.	NSW-BRA	592207
203	17/05/2012	355402 Breakdown in Mosgiel park drive - All belts gone. Use cable		NSW-BRE	592207
203	17/05/2012	355397 Air System Air leak L/H rear coner	Checked no leak found	NSW-AIR	592207
203	12/05/2012	354695 Elec & Light ind. light out	Replace globe	NSW-E&L	591498
203	10/05/2012	354261 Brakes Aie leak on mid.axle modulator valve	REKIT AIR UNLODER VALUE ADJUEEST AIR PRESSURE BY TEST GAUGE	NSW-BRA	591131
203	10/05/2012	354261	FIXED AIR LEAK FROM AIR DRYER AND ROAD TEST BUS OK	NSW-BRA	591131
203	08/05/2012	354304 Elec & Light Interior light U/S	Replace globe	NSW-E&L	591131
203	08/05/2012	354211 Air System Air leak	Check for air leak near air drayer - steam clean bus look eor parts C/O - still OK to drive	NSW-AIR	591131
203	04/05/2012	353457 CLEAR FRONT INDICATOR WRAP-AROUND		NSW-E&L	590275
203	04/05/2012	353457 WEDGE GLOBE INSTRUMENT 24V 3W		NSW-E&L	590275
203	04/05/2012	353457 Elec & Light - Replace globes	Replaced	NSW-E&L	590275
203	04/05/2012	353878 Breakdown inParkwille- BerWick - No air built in system -		NSW-BRE	590566
203	02/05/2012	350831 Direct Purchase - MECHANICAL	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G107010 Receiving #:107946 Date :2012-05-02 Supply and fit front crank seal	NSW-ENG	589673
203	02/05/2012	353239 Brakes - Stop brake failure	Check all sensors & cleared all codes r/tested	NSW-BRA	590065
203	30/04/2012	352684 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	589513
203	30/04/2012	353012 Breakdown - Loch Rd - OUT 1.30 pm BACK 2.30 pm - ABS light	VAN 619. Warning light on L & RH rear not same % changed rear pads calibrated & r/tested OK	NSW-BRE	589673
203	30/04/2012	352619 Ops Entered - Fault - Brakes - Route: 802 - Outlook Drive	Checked Ok	NSW-BRA	589513
203	30/04/2012	352619 REAR DISC PADS B12BLE+B7RSA FRONT+REAR(30G7502BERAL)		NSW-BRA	589513
203	30/04/2012	352619 Brakes - Sign keep coming up for brakes	Checked Ok	NSW-BRA	589513
203	30/04/2012	352619 Ops Entered - Fault - Brakes - Route: 850 - Dandenong Stat	Checked Ok	NSW-BRA	589513
203	22/04/2012	351697 Brakes - ABS warning light on	Checked brake warning cancelled fault code tested OK	NSW-BRA	588640
203	20/04/2012	348004 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G106085 Receiving #:107433 Date :2012-04-20	P	588484
203	20/04/2012	350007 FUSE BLADE 10AMP		NSW-COM	588335
203	19/04/2012	350831 Suspension - NS inkarm balljoint u/s	Replaced completed	NSW-SUS	588214
203	19/04/2012	350831 Engine - Engine oil leak at front crank seal	Assembled all the parts completed	NSW-ENG	588214
203	18/04/2012	350831 Engine - Engine oil leak at front crank seal	Removed crank pulley cleaned oil seal area	NSW-ENG	588214
203	17/04/2012	350831 Engine - Engine oil leak at front	Started to strip rear chassis members	NSW-ENG	588214
203	17/04/2012	350007 Comm Equip - Install wiring loom from fuse box to a/c duct	Fit wires and fuse box	NSW-COM	588214
203	11/04/2012	350007 Comm Equip - Install wiring loom from fuse box to a/c duct	Fitted hand rail	NSW-COM	588214
203	10/04/2012	350073 Passenger Doors - Adjust front door ramp	Adjusted & checked for oil leak	NSW-PDO	588214
203	05/04/2012	349734 Elec & Light - Adjust ramp switch	Bus wont move found ramp bent up	NSW-E&L	588214
203	05/04/2012	349734 Elec & Light - Adjust ramp switch	Adjusted switch & s/cleaned	NSW-E&L	588214
203	05/04/2012	349617 Ops Entered - Fault - Air System - Route: 814 - Waverley G	Towed in	NSW-AIR	588214
203	05/04/2012	349617 NO AIR PRESSURE	Creditor #:ASS001 ASSOCIATED TOWING P/O #:G106552 Receiving #:107313 Date :2012-04-18 TOWED BUS BACK TO DEPOT	NSW-AIR	588214
203	03/04/2012	349306 Elec & Light - Check fault code	Checked parked in line 4	NSW-E&L	587985
203	03/04/2012	349126 Body & Acc - Replace front door - refit door seal	REPLACED INSERT	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Secure all lower skirt panels	CHEAHED ALL BOLTS AND REPLACED MISSING BOLTS	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Polish exterior panels/headers & touch up paint	JOB COMPLETED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Paint exterior mirrors and arms	JOB COMPLETED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Secure front & rear door seals	REPLACED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Replace Exit Only on rear doors	JOB COMPLETED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Adjust rear doors - replace top rollers	JOB COMPLETED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Clean air condition filter secure vents	JOB COMPLETED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Secure seat frames - NS 3	TIGHTEN LOOSE BOLTS ON SEAT	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Front step edges - fit inserts	REPLACED	NSW-BSW	587576
203	03/04/2012	349126 Body & Acc - Front windscreen/drivers side window - tint		NSW-BSW	587576
203	03/04/2012	349126 UNREPORTED - Repair paint & secure rear b/bar	TIGHTEN ND PLACED MISSING BOLTS	NSW-ACC	587576
203	02/04/2012	348907 MUD FLAPS GENDAS MF60X30GRE RED		NSW-BSW	587439

203	02/04/2012	348878	Body & Acc - Paint wheels	Painted	NSW-BSW	587576
203	02/04/2012	348878	Body & Acc - Replace Licensed to carry (No) seat (No) adult	Removed old and replaced with new	NSW-BSW	587576
203	02/04/2012	348878	Body & Acc - Paint till stand	Painted	NSW-BSW	587576
203	02/04/2012	348878	Replace mud flap	Replaced with new	NSW-BSW	587576
203	02/04/2012	348878	Secure rear b/bar	Replaced missing bolts and secured	NSW-BSW	587576
203	01/04/2012	348004	Annual Licence	- DN 233666 - Passed	P	587090
203	31/03/2012	348594	Engine - Steamclean bus	Cleaned	NSW-ENG	587323
203	31/03/2012	348594	Brakes - Check for fault code	Fixed rear modulator and cleared fault code by tectool	NSW-BRA	587323
203	30/03/2012	348594	Diff & Hubs - NSF hub seal leak	Topped up oil	NSW-D&H	587323
203	30/03/2012	348907	Body & Acc - Replace mud flaps - NSF	Replaced	NSW-BSW	587439
203	29/03/2012	348464		done at RSI - 28/03/2012	SAF-INSP	587323
203	29/03/2012	348464		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	587323
203	29/03/2012	348464		Rotate Front Axle Tyres Left to Right - MT & IBS only	SAF-INSP	587323
203	29/03/2012	348464		Tension Wheel Nuts	SAF-INSP	587323
203	29/03/2012	348464		Perform & Complete TSV Bus Safety Inspection	SAF-INSP	587323
203	29/03/2012	348547	Elec & Light - NSR clearance lens cracked	hairline fracture - serviceable	NSW-E&L	587323
203	29/03/2012	348594	Diff & Hubs - NSF hub seal leak	Changed NSF hub seal c/o	NSW-D&H	587323
203	29/03/2012	348594	SEAL FRONT HUB BUS 80/86		NSW-D&H	587323
203	29/03/2012	348594	Diff & Hubs - NSF hub seal leak	Ass Dulkith	NSW-D&H	587323
203	27/03/2012	348321	Brakes - ABS light coming on/off again	Cleaned ABS sensors	NSW-BRA	587323
203	26/03/2012	346638	TYRE RECYCLE	Creditor #:BEA001 BEAUREPAIRES P/O #:G105709 Receiving #:106621 Date :2012-03-26	NSW-W&T	587090
203	23/03/2012	347563	Engine - adj valves	Adjusted	NSW-ENG	586354
203	22/03/2012	347563	ROCKER COVER GASKET B12BLE		NSW-ENG	586354
203	20/03/2012	346472	BALD - NEW 11.00R22.5 - POS 2	Creditor #:BEA001 BEAUREPAIRES P/O #:K105657 Receiving #:106220 Date :2012-03-20 REPLACE WITH NEW	NSW-W&T	585888
203	19/03/2012	346638	Whls & Tyres - Replace tyre 8 - sidewall damage	Discarded	NSW-W&T	585345
203	17/03/2012	346569		A Service	A	584941
203	17/03/2012	346569		A Service	A	584941
203	17/03/2012	346569		Tension ALL Wheel Nuts to OEM Specs	A	584941
203	17/03/2012	346569		Grease AC Compressor Clutch Bearing	A	584941
203	16/03/2012	346472	Whls & Tyres - Replace tyre pos 2 - low tread	Replaced	NSW-W&T	584894
203	15/03/2012	346811	Whls & Tyres - OSF tyre low tread	Replaced tyre & cleaned a/c filter	NSW-W&T	584894
203	12/03/2012	346211	Elec & Light - Reset rear engine stop switch	Remove & reset rear engine stop switch & jump started	NSW-E&L	584118
203	09/03/2012	344282	BALD - Recap 11.00R22.5 Pos 5	Creditor #:BEA001 BEAUREPAIRES P/O #:G104971 Receiving #:105880 Date :2012-03-09 Replace with recaps fitting	NSW-W&T	583293
203	08/03/2012	340106	Accident damage no 34805	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G103717 Receiving #:105818 Date :2012-03-08	NSW-ACC	583152
203	08/03/2012	340106	Accident damage no 34806	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G103717 Receiving #:105818 Date :2012-03-08	NSW-ACC	583152
203	07/03/2012	345290	PLASTIC YELLOW KNOB		NSW-BSW	582972
203	06/03/2012	344864	Annaut Body Inspection	Inspected	P	582863
203	06/03/2012	345088	Whls & Tyres - OSF tyre low tread	no defect	NSW-W&T	582863
203	06/03/2012	344753	HORN 24VLT		NSW-E&L	582863
203	06/03/2012	344753	Elec & Light - Check horn contact	Checked out for shorting wire unable to locate it ran a new wire tested OK put bus back together	NSW-E&L	582863
203	06/03/2012	345290	Body & Acc - Repair hand rails	Repaired	NSW-BSW	582972
203	06/03/2012	345290	Body & Acc - Replace licensed to carry	Replaced	NSW-BSW	582972
203	06/03/2012	345290	Body & Acc - Replace Licensed to carry (No) seat (No) adult	Replaced	NSW-BSW	582972
203	02/03/2012	344753	Elec & Light - Check horn contact	Could not fix	NSW-E&L	582863
203	02/03/2012	344753	Elec & Light - Check horn contact	Turned master switch on horn goes checking out wiring	NSW-E&L	582863
203	01/03/2012	344484	Whls & Tyres - Replace tyres 56	Move bus to w/shop replace tyres & tensioned w/nuts	NSW-W&T	582863
203	01/03/2012	344282	Whls & Tyres - Replace tyre pos 56 - worn		NSW-W&T	582863
203	01/03/2012	344310	V-BELT		NSW-SCA	582663
203	01/03/2012	344282	Brakes ABS On	Cleaned all wheel sensor light still on dash c/	NSW-BRA	582663
203	01/03/2012	344487	Brakes - ABS on	recalibrate rear brake and road test bus ok R/N/S 100% R/O/S84%	NSW-BRA	582863
203	29/02/2012	344191		Replace Fuel Filter With Water Bowl	RSI	582863
203	29/02/2012	344191	DIAPHRAGM QUICK RELEASE		RSI	582863
203	29/02/2012	344191		Service A/C Air Return Filter	RSI	582863
203	29/02/2012	344191		Replace Power Steering And Hydraulic Fan Oil Filter	RSI	582863
203	29/02/2012	344191		Replace Air Dryer Canister	RSI	582863
203	29/02/2012	344191	POWER STEER +HYD FAN FILTER		RSI	582863
203	29/02/2012	344191	FUEL WATER FILTER B12BLE		RSI	582863
203	29/02/2012	344191	TEXAMATIC 1888	P/STEER TOP UP OIL	RSI	582863
203	29/02/2012	344191	RPM BORATE EP LUBE 220	DIFF OIL	RSI	582863
203	29/02/2012	344191	FUEL FILTER B12BLE		RSI	582863
203	29/02/2012	344191		Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	RSI	582863
203	29/02/2012	344191		Replace Fuel Filter	RSI	582863
203	29/02/2012	344191		Rekit Quick Release Valve	RSI	582863
203	29/02/2012	344191		Adjust Valve Clearance	RSI	582863
203	29/02/2012	344191		Remove Intercooler Wash Intercooler and Raditor	RSI	582863
203	29/02/2012	344191		Inspect Bus As Per Inspection Sheet	RSI	582863
203	29/02/2012	344191	O RING B12BLE INTERCOOLER		RSI	582863
203	29/02/2012	344191	SEAL QUICK RELEASE VALVE		RSI	582863

203	29/02/2012	344310	Air Cond - Replace a/c belt	Replaced		NSW-SCA	582863
203	29/02/2012	344310	Elec & Light - Replace interior tube & light cover	Replaced		NSW-E&L	582863
203	29/02/2012	340998	Brakes - ABS light on dash & buzzer	Repaired		NSW-BRA	580690
203	28/02/2012	343831	Elec & Light - Replace alternators	Removed replaced with new checked OK		NSW-E&L	582663
203	28/02/2012	343831	ALTNATORS	Creditor #:MUL001MULTISPARES LTD P/O #:G104842 Receiving #:105418 Date :2012-02-28		NSW-E&L	582663
203	27/02/2012	343831	Elec & Light - Replace alternators	Alt remove need to order new test alt		NSW-E&L	582663
203	25/02/2012	343703	Etec & Light - Bus wont start	Jump started		NSW-E&L	582663
203	25/02/2012	343703	Etec & Light - Bus wont start	Jump started checked found batt light on need to replace alternators		NSW-E&L	582663
203	22/02/2012	342911	GLOBE DASH B7L			NSW-E&L	581827
203	21/02/2012	342911	Etec & Light - Replace dash light globe	Replaced		NSW-E&L	581827
203	21/02/2012	342933	Body & Acc - Secure fire extinguisher	Secured		NSW-BSW	581827
203	17/02/2012	342482	Air Cond - Clean a/c filters	Cleaned		NSW-SCA	581335
203	02/02/2012	340101	Body & Acc - Front windscreen started cracking from bottom	sent to Volgren - 02/02/2012		NSW-BSW	580690
203	02/02/2012	340101	SUB - Cracks in centre of windscreen	sent to Volgren - 02/02/2012		NSW-BSW	580690
203	02/02/2012	340101	Body & Acc - NSR wheel arch brush missing	sent to Volgren - 02/02/2012		NSW-BSW	580690
203	02/02/2012	340106	Accident - Accident No 34805 - Damage at front of bus	Repaired by Volgren		NSW-ACC	580690
203	02/02/2012	340106	Accident - Accident No 34806 - Damage at rear of bus	Repaired by Volgren		NSW-ACC	580690
203	02/02/2012	340101	Ops Entered - Accident - Ran into back of Other Vehicle -	sent to Volgren - 02/02/2012		NSW-ACC	580690
203	02/02/2012	340101	Ops Entered - Accident - Collision Whilst Reversing - Rout	sent to Volgren - 02/02/2012		NSW-ACC	580690
203	01/02/2012	340091	Breakdown - Accident - Glen Waverley Station - OUT 9.00 pm	Van 619. Returned to depot (to be repaired by Volgren)		NSW-BRE	580690
203	31/01/2012	339855	Etec & Light - Indicator arm may break any time very loose	Secured thread was stripped from holes attempted a few things before settling on bigger screws		NSW-E&L	580690
203	31/01/2012	339855	Etec & Light - Indicator arm loose	Secured thread was stripped from holes attempted a few things before settling on bigger screws		NSW-E&L	580690
203	24/01/2012	338988	Air Cond - Clean a/c filters	Cleaned		NSW-SCA	579375
203	23/01/2012	338573		Done at Roadworthy inspection - Doc 136205		SAF-INSP	578812
203	23/01/2012	338573		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	578812
203	23/01/2012	338573		Tension Wheel Nuts		SAF-INSP	578812
203	23/01/2012	338531	GLOBE INDICATOR 24V-18W SINGLE CONTACT			NSW-E&L	578812
203	20/01/2012	338531	Etec & Light - Replace OS front indicator globe	Replaced		NSW-E&L	578812
203	19/01/2012	338158	Etec & Light - Replace NS headlight globe	Removed & replaced with new		NSW-E&L	577820
203	19/01/2012	338158	HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500			NSW-E&L	577820
203	17/01/2012	337672	GLOBE INDICATOR 24V-18W SINGLE CONTACT			NSW-E&L	577359
203	17/01/2012	337597	GLOBE HIGH BEAM 24V70W H1			NSW-E&L	577359
203	16/01/2012	337672	Etec & Light - Replace NS indicator light globe	Replaced		NSW-E&L	577359
203	15/01/2012	337597	Etec & Light - Replace OSR headlight globe	Replaced		NSW-E&L	576932
203	13/01/2012	337330	GLOBE INDICATOR 24V-18W SINGLE CONTACT			NSW-E&L	576361
203	12/01/2012	337330	Etec & Light - Replace OSF top indicator globe	Replaced		NSW-E&L	576361
203	23/12/2011	334788	GLOBE INDICATOR 24V-18W SINGLE CONTACT			NSW-E&L	571966
203	22/12/2011	326482	SCRAP	Creditor #:BEA001 BEAUREPARES P/O #:G101913 Receiving #:103015 Date :2011-12-22		NSW-W&T	571739
203	22/12/2011	327624	SCRAP	Creditor #:BEA001 BEAUREPARES P/O #:G101913 Receiving #:103015 Date :2011-12-22		NSW-W&T	571739
203	22/12/2011	334788	Etec & Light - Replace front top park light globe	Replaced		NSW-E&L	571966
203	13/12/2011	332774	NUT UPPER+LOWER SUSPENSION ARM			NSW-BRA	569944
203	13/12/2011	332774	ROTOR BOLT	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G101678 Receiving #:102531 Date :2011-12-13		NSW-BRA	569944
203	13/12/2011	332774	NUT UPPER+LOWER SUSPENSION ARM			NSW-BRA	569944
203	13/12/2011	332774	BUSH KIT UPPER CONTROL ARM B10BLE			NSW-BRA	569944
203	13/12/2011	332774	Ops Entered - Fault - Brakes - Route: 811 - Springvale Sta	Rotor mounting bolts fitted w/nuts tensioned both side caliper greasing done hub oil topped up r/tested OK floor mopped and parked bus		NSW-BRA	569944
203	12/12/2011	332774	Brakes Pull Left	Front both side rotor mounting bolt head damaged welded removed hub cleaned hub nut and caliper mounting tensioned booster brake pad fitted brakes adjusted f/right upper control arm t		NSW-BRA	569944
203	12/12/2011	332774	SEAL FRONT HUB BUS 80/86			NSW-BRA	569944
203	12/12/2011	332774	FRONT PADS VOLVO B10L+B12BLE			NSW-BRA	569944
203	12/12/2011	332774	O RING F/WHEEL HUB CAP			NSW-BRA	569944
203	12/12/2011	332774	Ops Entered - Fault - Brakes - Route: 811 - Springvale Sta	Cleaned parts & assembled rotors bearings seal fit fit calipers Subu completed		NSW-BRA	569944
203	09/12/2011	332774	Whls & Tyres - OSF tyre low tread			NSW-W&T	569944
203	09/12/2011	332774	FRONT ROTOR+KIT	Creditor #:MUL001 MULTISPARES LTD P/O #:G101572 Receiving #:102428 Date :2011-12-09		NSW-W&T	569944
203	09/12/2011	332774	B12BLE FRONT L/H CALIPER	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G101546 Receiving #:102414 Date :2011-12-09		NSW-BRA	569944
203	09/12/2011	332774	B12BLE FRONT R/H CALIPER	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G101546 Receiving #:102414 Date :2011-12-09		NSW-BRA	569944
203	09/12/2011	332774	Brakes Pull Left	Front both side s/cleaned front right wheel removed disc measured low both side booster caliper hub removed		NSW-BRA	569944
203	09/12/2011	332879	done at last SAF INSP	Tension ALL Wheel Nuts to OEM Specs		A	569944
203	09/12/2011	332879	done at last SAF INSP	A Service		A	569944
203	09/12/2011	332879	done at last SAF INSP	Grease AC Compressor Clutch Bearing		A	569944
203	08/12/2011	332646	O RING B12BLE INTERCOOLER			SAF-INSP	569944
203	08/12/2011	332774	Brakes Pull Left	Cleaned all wheel sensors & fitted rear brake pads		NSW-BRA	569944
203	08/12/2011	332774	REAR DISC PADS B12BLE+B7RSA FRONT+REAR			NSW-BRA	569944
203	07/12/2011	332646		Tension Wheel Nuts		SAF-INSP	569944
203	07/12/2011	332646		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	569944
203	07/12/2011	332646		Perform & Complete TSV Bus Safety Inspection		SAF-INSP	569944
203	07/12/2011	332645	Random Vehicle Audit	Inspected		NSW-I&T	569944
203	02/12/2011	332265	Body & Acc - No broom	Broom already in bus		NSW-BSW	569458
203	02/12/2011	332265	Brakes - ABS light comes on	Checked OK light did not appear		NSW-BRA	569458
203	30/11/2011	331326	SWITCH INDICATOR/CRUISE SUIT B12BLE VOLVO			NSW-E&L	568067

203	28/11/2011	331326 Elec & Light - Replace indicator switch	Replaced	NSW-E&L	567779
203	25/11/2011	330839 24V INVERTER 4-13W		NSW-E&L	566927
203	24/11/2011	330839 Elec & Light - 1 interior light out	Replaced inverter	NSW-E&L	566927
203	24/11/2011	330662 ABS BRAKE SENSOR		NSW-BRA	566927
203	23/11/2011	330662 Brakes - ABS coming on/off	Replaced NSF ABS speed sensor r/tested OK	NSW-BRA	566946
203	21/11/2011	330446 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	566567
203	16/11/2011	329802 Wipers & Washers - Adjust wiper	Adjusted	NSW-W&W	565340
203	15/11/2011	329056 FAN BELT A/CON ARTIC 21/32X45		NSW-ECO	564884
203	15/11/2011	329401 BRAZILLIAN MIRROR RH		NSW-BSW	564884
203	14/11/2011	329056 Vandalism - Graffiti on window & panels	Cleaned	NSW-VAN	564791
203	14/11/2011	329056 Air Cond - A/C belt cracked	Replaced	NSW-SCA	564791
203	14/11/2011	329056 Engine - Oil leak around engine main pulley	S/cleaned checked OK	NSW-ENG	564791
203	14/11/2011	329056 Engine - Steam clean engine bay	Cleaned	NSW-ENG	564791
203	14/11/2011	329056 Eng Cool - Coolant leak Bottom radiator hose	Checked OK	NSW-ECO	564791
203	14/11/2011	329056 Body & Acc - Windscreen chipped	Checked OK	NSW-BSW	564791
203	14/11/2011	329401 Body & Acc - Replace mirror	Replaced	NSW-BSW	564884
203	14/11/2011	329056 Air System - Air leak at air dryer	Checked OK	NSW-AIR	564791
203	12/11/2011	329129 Brakes - Red ABS light on all time	Checked found no red light cleaned inactive wheel speed sensor code	NSW-BRA	564791
203	10/11/2011	328842 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	564601
203	10/11/2011	328703 Drv entered - Brakes	Removed front NS and rear OS wheel speed sensors cleaned fixed same as r/tested bus OK	NSW-BRA	564414
203	08/11/2011	327624 POS 1 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G100084 Receiving #:101032 Date :2011-11-08	NSW-W&T	564146
203	04/11/2011	327926 Whls & Tyres - Replace tyre pos 1	Moved bus to w/shop replaced & tensioned w/nuts	NSW-W&T	563519
203	04/11/2011	327624 Whls & Tyres Worn tyre pos 1	replaced	NSW-W&T	563349
203	02/11/2011	327417 Brakes - ABS light on	Cleaned all wheel sensors checked NS rear caliper	NSW-BRA	563068
203	29/10/2011	327018 Eng Cool - Add coolant	Added	NSW-ECO	562157
203	28/10/2011	326482 POS 3-4 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G99766 Receiving #:100675 Date :2011-10-28	NSW-W&T	561704
203	27/10/2011	326756 Whls & Tyres - Replace tyres 34	Move bus to w/shop replaced tyres & tensioned w/nuts	NSW-W&T	561704
203	27/10/2011	326482 Whls & Tyres Worn tyre pos 3-4	replaced	NSW-W&T	561522
203	22/10/2011	325703	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	560177
203	22/10/2011	325703	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	560177
203	22/10/2011	325703	Tension Wheel Nuts	SAF-INSP	560177
203	22/10/2011	325931 Brakes - Brake failure warning sign on all time	Checked NO faults	NSW-BRA	560395
203	21/10/2011	326124 Wipers & Washers - Clean washer bottle	Cleaned	NSW-W&W	560395
203	18/10/2011	325273 Body & Acc - Replace NS mirror arm	Replaced & painted the same	NSW-BSW	559728
203	27/09/2011	322001 Passenger Doors - secure door sliding bar bolts	Tightened bolts	NSW-PDO	559014
203	26/09/2011	321816 Elec & Light - replace OS interior tubelight and cover	Replaced	NSW-E&L	554832
203	16/09/2011	320313	Service T Replace Transmission Oil & Filter	A&T	552476
203	16/09/2011	320313 ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS		A&T	552476
203	16/09/2011	320313 FILTER TRANSMISSION ZF 4139-298-038E39HD119		A&T	552476
203	16/09/2011	320313	Tension ALL Wheel Nuts to OEM Specs	A	552476
203	16/09/2011	320313	Clean A/C filter.	A	552476
203	16/09/2011	320313	Grease AC Compressor Clutch Bearing	A	552476
203	16/09/2011	320313	A Service	A	552476
203	14/09/2011	319721 GLOBE DASH B7L		NSW-E&L	552004
203	13/09/2011	319627	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	551825
203	13/09/2011	319627	Tension Wheel Nuts	SAF-INSP	551825
203	13/09/2011	319627	Perform & Complete TSV Bus Safety Inspection	SAF-INSP	551825
203	13/09/2011	319721 Elec & Light - Replace interior light cover	Replaced	NSW-E&L	552004
203	13/09/2011	319721 Elec & Light - Replace interior light cover	Replaced	NSW-E&L	552004
203	13/09/2011	319721 Elec & Light - Replace 2 dash globes	Replaced	NSW-E&L	552004
203	12/09/2011	319430 Ticket Equip - Validator n/w	Checked with control room OK	NSW-TIC	551825
203	06/09/2011	306592 scrap	Creditor #:BEA001 BEAUREPARES P/O #:G97433 Receiving #:98355 Date :2011-09-06	NSW-W&T	550299
203	06/09/2011	318308 Elec & Light - check noise through audio system	Checked noise found smart unit faulty disconnected audio line from smart unit also r/tested	NSW-E&L	550299
203	06/09/2011	318308 Elec & Light - check noise through audio system	Ass Ranjith with noise diagnosis	NSW-E&L	550299
203	04/09/2011	318141 Gearbox - Transmission noisy	Checked transmission on r/test all OK noise coming from radio speakers	NSW-GEA	550181
203	01/09/2011	317816 Engine emmission control - Replace adblu tank	Replaced	NSW-ENG	549498
203	01/09/2011	317683 OIL FILTER B10M +B7R BY PASS (VOLVO)		D	549314
203	01/09/2011	317683 ENGINE OIL DELO 400LE 15W40	ENGINE OIL	D	549314
203	01/09/2011	317683 FILTER AIR CLEANED B10M MK4 +B12		D	549314
203	01/09/2011	317683	D Service	D	549314
203	01/09/2011	317683 OIL FILTER LONG LIFE B12BLE (VOLVO)		D	549314
203	01/09/2011	317683	Tension ALL Wheel Nuts to OEM Specs	D	549314
203	01/09/2011	317683	Remove V-Belts & Check Tensioner Bearings for Noise	D	549314
203	01/09/2011	317683 SUMP PLUG WASHER B12B		D	549314
203	01/09/2011	317683	A Service	A	549314
203	01/09/2011	317683	Tension ALL Wheel Nuts to OEM Specs	A	549314
203	01/09/2011	317683	Grease AC Compressor Clutch Bearing	A	549314
203	01/09/2011	317683	Clean A/C filter.	A	549314

203	30/08/2011	317157 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	548816
203	24/08/2011	316271 Wipers & Washers - Check wipers	Repaired wiper spray nozzles & tubes cleaned	NSW-W&W	547826
203	01/08/2011	312099 GLOBE S/CONTACT 24V-10W		NSW-E&L	541971
203	29/07/2011	312036	Perform & Complete PTSV Bus Safety Inspection	SAF-INSP	541087
203	29/07/2011	312036	Perform & Complete PTSV Bus Safety Inspection	SAF-INSP	541087
203	29/07/2011	312036	Tension Wheel Nuts	SAF-INSP	541087
203	29/07/2011	312099 Elec & Light - Replace park light globe	Replaced	NSW-E&L	541087
203	25/07/2011	311053 GLOBE HIGH BEAM 24V70W H1		NSW-E&L	540195
203	22/07/2011	311053 Elec & Light - Replace low beam globe	Replaced	NSW-E&L	539719
203	22/07/2011	302672 Replace Grenda decals x 4	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G93063 Receiving #:96488 Date :2011-07-22	NSW-BSW	539512
203	21/07/2011	310820 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	539512
203	12/07/2011	309213 Brakes Pull Left	Checked both front auto adjusters Ok r/tested	NSW-BRA	538487
203	11/07/2011	308826 REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	538487
203	09/07/2011	309068 Eng Cool - Add coolant	Added	NSW-ECO	538487
203	08/07/2011	308826 SUS - NSRR airbag leak	Replaced	NSW-SUS	538264
203	08/07/2011	308826 SUS - OSRR airbag leak	Replaced	NSW-SUS	538264
203	08/07/2011	308826 SUS - NSRR airbag leak	Replaced	NSW-SUS	538264
203	08/07/2011	308826 SUS - OSRR airbag leak	Replaced	NSW-SUS	538264
203	08/07/2011	308826 Drv entered - Passenger Doors Require Adjusted	Adjusted	NSW-PDO	538264
203	08/07/2011	308826 PD - rear door not closing properly	Adjusted	NSW-PDO	538264
203	08/07/2011	308826 EN - Oil leak around main pulley	S/cleaned checked OK	NSW-ENG	538264
203	07/07/2011	308599 ST - Bus pulling to the left	Adjusted front brake & r/tested	NSW-STE	537979
203	06/07/2011	308533 Air Cond - Clean a/c filters	Cleaned	NSW-SCA	537979
203	06/07/2011	308362 GLOBE S/CONTACT 24V-10W		NSW-E&L	537979
203	05/07/2011	308111 GLOBE S/CONTACT 24V-10W		NSW-E&L	537806
203	05/07/2011	308111 GLOBE INDICATOR 24V-18W SINGLE CONTACT		NSW-E&L	537806
203	05/07/2011	308362 Replace bus stop globes	Replaced	NSW-E&L	537979
203	05/07/2011	308238	A Service	A	537806
203	05/07/2011	308238	Tension ALL Wheel Nuts to OEM Specs	A	537806
203	05/07/2011	308238	Grease AC Compressor Clutch Bearing	A	537806
203	05/07/2011	308238	Clean A/C filter.	A	537806
203	05/07/2011	308238	A Service	A	537806
203	04/07/2011	308111 Replace globes	Replaced NSF top park & interior fluro	NSW-E&L	537806
203	02/07/2011	307978 Add coolant	Added	NSW-ECO	537275
203	01/07/2011	307789 Clean a/c filters	Cleaned	NSW-SCA	536810
203	27/06/2011	306592 POS 5-6 CAP	Creditor #:BEA001 BEAUREPARES P/O #:K94281 Receiving #:95311 Date :2011-06-27	NSW-W&T	535737
203	25/06/2011	306958 Replace fuse for headlights	Replaced	NSW-E&L	535729
203	24/06/2011	306592 Replace tyre pos 56 - low tread	Replaced	NSW-W&T	535189
203	22/06/2011	306591 WHL - OSR tyre low tread	Replaced both OSR tyres & cleaned all wheels	NSW-W&T	535018
203	11/06/2011	304812	Tension Wheel Nuts	SAF-INSP	532424
203	11/06/2011	304812	Perform & Complete PTSV Bus Safety Inspection	SAF-INSP	532424
203	04/06/2011	298572 ST - LH tie rod end worn - at wheel	Replaced NS tierod	NSW-STE	523093
203	04/06/2011	303994 Adjust a/c belts	Adjusted	NSW-SCA	531114
203	04/06/2011	303994 Adjust rear door	Adjusted	NSW-PDO	531114
203	02/06/2011	303748 Replace NSF tyre	Replaced	NSW-W&T	530522
203	01/06/2011	298572 tie rod end	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G93165 Receiving #:94126 Date :2011-06-01 203	NSW-STE	529935
203	01/06/2011	302929 TYPE 30 DIAPHRAM	Creditor #:MUL001 MULTISPARES LTD P/O #:G93210 Receiving #:94147 Date :2011-06-01 203	NSW-BRA	529935
203	30/05/2011	298572 ST - LH tie rod end worn - at wheel	Checked & ordered parts	NSW-STE	523093
203	30/05/2011	302929 BRK - ABS MIL coming on	Changed rear brake pads & calibrated	NSW-BRA	529525
203	30/05/2011	302929 REAR DISC PADS B12BLE+B7RSA FRONT+REAR		NSW-BRA	529525
203	27/05/2011	302672 Replace Grenda decal x 4	Replaced	NSW-BSW	529187
203	24/05/2011	301926 Service	Overhaul finished	REBUILD	528891
203	24/05/2011	301924 Service	Overhaul finished	REBUILD	528891
203	24/05/2011	301924 ALT BEARING		REBUILD	528891
203	24/05/2011	301924 ALTERNATOR BEARING		REBUILD	528891
203	24/05/2011	301926 ALT BEARING		REBUILD	528891
203	24/05/2011	301926 ALTERNATOR BEARING		REBUILD	528891
203	24/05/2011	301701 V-BELT		NSW-E&L	528009
203	24/05/2011	301701 FAN BELT A/CON ARTIC 21/32X45		NSW-E&L	528009
203	24/05/2011	301701 B12BLE ALTERNATOR 24V-110AMP (B/NEST)		NSW-E&L	528009
203	24/05/2011	301701 B12BLE ALTERNATOR CRANK BELT		NSW-E&L	528009
203	23/05/2011	301701 EL - check non charging	Replaced a/c belts r/tested check light and battery charging all OK	NSW-E&L	528009
203	21/05/2011	301701 EL - check non charging	Check alt warning light	NSW-E&L	528009
203	21/05/2011	301701 EL - check non charging	Removed alt idler pully and replaced alternator and pulley c/o	NSW-E&L	528009
203	21/05/2011	301701 EL - check non charging	Found alt belt off (bearings alternator bus u/s)	NSW-E&L	528009
203	18/05/2011	301112 GLOBE DASH B7L		NSW-E&L	527463
203	17/05/2011	301128 Clean a/c filters	Cleaned	NSW-SCA	527463
203	17/05/2011	301112 Replace dash light globe	Replaced	NSW-E&L	527463

203	14/05/2011	300861 Clean graffiti	Cleaned		NSW-VAN	526990
203	11/05/2011	296431 FILTER AIR DRYER KIT(HALDEX)			RSI	519246
203	11/05/2011	296431	Adjust Valve Clearance		RSI	519246
203	11/05/2011	296431	Service A/C Air Return Filter		RSI	519246
203	11/05/2011	296431	Replace Air Dryer Canister		RSI	519246
203	11/05/2011	296431	Service A/C Air Return Filter		RSI	519246
203	11/05/2011	296431	Adjust Valve Clearance		RSI	519246
203	11/05/2011	296431			RSI	519246
203	11/05/2011	296431			RSI	519246
203	11/05/2011	300243 VAN - Graffiti in back of bus	Cleaned		NSW-VAN	526016
203	11/05/2011	300243 EN - Oil leak around engine main pulley	S/cleaned checked OK		NSW-ENG	526016
203	11/05/2011	300243 EN - Steamclean bus	S/cleaned		NSW-ENG	526016
203	05/05/2011	299359 Reg. light out	Replace globe		NSW-E&L	524652
203	05/05/2011	299359 GLOBE S/CONTACT 24V-10W			NSW-E&L	524652
203	05/05/2011	299360 Park light out	Fixed		NSW-E&L	524652
203	05/05/2011	299360 HALOGEN GLOBE 24V20W			NSW-E&L	524652
203	04/05/2011	297855 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G91529 Receiving #:92838 Date :2011-05-04		P	524394
203	01/05/2011	297855 Annual License -	RWC 583114		P	521311
203	29/04/2011	298580 Replace A/C belts	replaced		NSW-AIR	523093
203	29/04/2011	298580 V-BELT			NSW-AIR	523093
203	28/04/2011	298245 CENTRA SEAT END CAPS			NSW-VAN	523093
203	27/04/2011	298245 BOD - NS 2nd last seat cut			NSW-VAN	523093
203	27/04/2011	298245 BOD - Polish exterior panels/headers & touch up paint work	Polished		NSW-VAN	523093
203	27/04/2011	298572 BOD - Paint till stand	Complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Clean air condition filter secure vents	complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Repair front step edges - replace/fit inserts	complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Paint exterior mirrors and arms	Complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Secure all lower skit panels	Complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Repair drivers blind - 1	Complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Fit end caps	Complited		NSW-BSW	523093
203	27/04/2011	298572 BOD - Replace/secure seat cushions - NS rear	Complited		NSW-BSW	523093
203	27/04/2011	298245 BOD - Paint wheels	Painted		NSW-BSW	523093
203	27/04/2011	298244	A Service & Bus Safety Inspection		A	522945
203	27/04/2011	298244	Tension ALL Wheel Nuts to OEM Specs		A	522945
203	27/04/2011	298244	Grease AC Compressor Clutch Bearing		A	522945
203	27/04/2011	298244	Clean A/C filter.		A	522945
203	27/04/2011	298244	A Service & Bus Safety Inspection		A	522945
203	16/04/2011	297658 Add coolant	Added		NSW-ECO	520974
203	14/04/2011	297612 Clean a/c filter	Cleaned		NSW-SCA	520533
203	11/04/2011	296702 SUS - LH top control arm bushes worn	Changed NS upper arm bushes		NSW-SUS	519859
203	11/04/2011	296702 BUSH KIT UPPER CONTROL ARM B10BLE			NSW-SUS	519859
203	11/04/2011	296702 PD - rear door sensitive edge u/s	Adjusted rear door sensitive edges		NSW-PDO	519859
203	11/04/2011	296955 Check g/box noise	Noise coming from planetary gears cannot do anything bus is OK to use checked oil OK		NSW-GEA	519859
203	09/04/2011	296756 very sharp high pitch sound from g/box	R/tested checked g/box oil OK still makes a noise from g/box planetary gears when driving 5 & 6 gears cant do anything bus OK to use		NSW-GEA	519817
203	08/04/2011	296516 BROOM HANDLE (8232715)			NSW-BSW	519314
203	07/04/2011	296431	Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )		RSI	519246
203	07/04/2011	296431	Replace Fuel Filter		RSI	519246
203	07/04/2011	296431	Replace Fuel Filter With Water Bowl		RSI	519246
203	07/04/2011	296431	Rekit Quick Release Valve		RSI	519246
203	07/04/2011	296431	Remove Intercooler Wash Intercooler and Raditor		RSI	519246
203	07/04/2011	296431	Inspect Bus As Per Inspection Sheet		RSI	519246
203	07/04/2011	296431 O RING B12BLE INTERCOOLER			RSI	519246
203	07/04/2011	296431 POWER STEER +HYD FAN FILTER			RSI	519246
203	07/04/2011	296431 TEXAMATIC 1888	P/STEER TOP UP OIL		RSI	519246
203	07/04/2011	296431	Replace Power Steering And Hydraulic Fan Oil Filter		RSI	519246
203	07/04/2011	296431 RPM BORATE EP LUBE 220	DIFF OIL		RSI	519246
203	07/04/2011	296431 FUEL FILTER B12BLE			RSI	519246
203	07/04/2011	296431 FUEL WATER FILTER B12BLE			RSI	519246
203	07/04/2011	296431 DIAPHRAGM QUICK RELEASE VALVE B58			RSI	519246
203	07/04/2011	296431 SEAL QUICK RELEASE VALVE			RSI	519246
203	07/04/2011	296349 ANN - Annual Body Inspection	Inspected		P	519246
203	07/04/2011	296516 Adjust a/c belt	Adjusted		NSW-SCA	519314
203	07/04/2011	296516 PD - Front door sensitive edge n/w	Checked OK		NSW-PDO	519314
203	07/04/2011	296516 Replace broom handle	Replaced		NSW-BSW	519314
203	01/04/2011	295634 HORN CONTACT B10M MK2			NSW-E&L	517713
203	31/03/2011	295634 EL - Left horn button causes horn to operate at the lightes	Fitted new horn push spring		NSW-E&L	517713
203	22/03/2011	293530 POS 3-4 CAP 11R	Creditor #:BEA001 BEAUREPARES P/O #:K89736 Receiving #:90971 Date :2011-03-22		NSW-W&T	515901
203	18/03/2011	293772 LIGHT SWITCH 3 POSITION			NSW-E&L	514757

203	16/03/2011	292209	ALTERNATOR BEARING			REBUILD	511460
203	16/03/2011	292209	ALT BEARING			REBUILD	511460
203	16/03/2011	292209	Service	Overhauled alternators		REBUILD	511460
203	16/03/2011	292209	B12BLE BOSCH ALT REGULATOR			REBUILD	511460
203	16/03/2011	293530	replace worn tyre pos 3-4	replace worn tyre pos 3-4		NSW-W&T	514184
203	16/03/2011	293483	SWITCH INDICATOR/CRUISE SUIT B12BLE VOLVO			NSW-E&L	513972
203	16/03/2011	293772	ELE - saloon lights not working	Went to GBS and got switch		NSW-E&L	514460
203	16/03/2011	293772	Left top tube light cover broken	Replaced cover		NSW-E&L	514460
203	16/03/2011	293772	EL - Interior light switch n/w	Replaced switch		NSW-E&L	514460
203	15/03/2011	293618	Replace tyres 34	Changed		NSW-W&T	514184
203	14/03/2011	293489	Add coolant	Added		NSW-ECO	513972
203	11/03/2011	293483	Replace switch	Replaced		NSW-E&L	513972
203	08/03/2011	292816	Secure panel	Secured		NSW-BSW	512530
203	07/03/2011	292400	HALOGEN GLOBE 24V20W			NSW-E&L	511933
203	07/03/2011	292466		A Service & Bus Safety Inspection		A	512144
203	07/03/2011	292466		Tension ALL Wheel Nuts to OEM Specs		A	512144
203	07/03/2011	292466		Clean A/C filter.		A	512144
203	07/03/2011	292466		Grease AC Compressor Clutch Bearing		A	512144
203	07/03/2011	292466		A Service & Bus Safety Inspection		A	512144
203	05/03/2011	292400	Replace front step light	Replaced		NSW-E&L	511933
203	04/03/2011	292209	Service	Pulled down alt ready for assembly		REBUILD	511460
203	01/03/2011	291589	24V INVERTER 4-13W			NSW-E&L	510929
203	01/03/2011	291589	INTERIOR LIGHT DEFUSER			NSW-E&L	510929
203	28/02/2011	291604	Clean a/c filters	Cleaned		NSW-SCA	510929
203	28/02/2011	291589	Replace inverter diffuser & fluro	Replaced		NSW-E&L	510929
203	25/02/2011	291165	GLOBE S/CONTACT 24V-10W			NSW-E&L	509801
203	25/02/2011	291433	Ops Entered - Fault - Air System - Route: 862 - Dandenong	Air leak from front of bus found drivers seat air pipe broken repaired air pipe		NSW-AIR	510714
203	24/02/2011	291119	GLOBE S/CONTACT 24V-10W			NSW-E&L	509801
203	24/02/2011	291165	Replace park light globe	Replaced		NSW-E&L	509801
203	23/02/2011	291039	Clean a/c filter	Cleaned		NSW-SCA	509801
203	23/02/2011	291119	EL - Stop light on dash - alarm bells it appears rear door	Checked NO fault found		NSW-E&L	509801
203	23/02/2011	291015	Check air leak under driver seat	Repaired		NSW-AIR	509801
203	22/02/2011	290872	EL - Door open warning light stay on	Checked warning lights NO faults found cruise control switch been off		NSW-E&L	509583
203	22/02/2011	290872	EL - Door open warning light stay on	Found door strut w/s replaced tested OK		NSW-E&L	509583
203	01/02/2011	287687	Accident Damaged # 32182 R/R. rear n/s. tail lights indica	Repaired by Volgren		NSW-ACC	509252
203	27/01/2011	286985	GLOBE S/CONTACT 24V-10W			NSW-E&L	507633
203	27/01/2011	287016	GLOBE S/CONTACT 24V-10W			NSW-E&L	507885
203	25/01/2011	287016	Top park light left n/w	Replaced		NSW-E&L	507885
203	24/01/2011	286860	EL - jump start	fixed		NSW-E&L	507633
203	24/01/2011	286985	Replace globe	Replaced		NSW-E&L	507633
203	22/01/2011	286735	EL - jump start	fixed		NSW-E&L	507150
203	18/01/2011	286099	Adjust a/c belts	Adjusted		NSW-SCA	506111
203	18/01/2011	285710	GLOBE S/CONTACT 24V-10W			NSW-E&L	505811
203	15/01/2011	285802	Add coolant	Added		NSW-ECO	505306
203	14/01/2011	285710	Left front light n/w	Replaced headlight		NSW-E&L	505051
203	11/01/2011	284112	POS 2 NEW	Creditor #:BEA001 BEAUREPARES P/O #:K86851 Receiving #:88162 Date :2011-01-11		NSW-W&T	504253
203	07/01/2011	284452	Ops Entered - Fault - Whls & Tyres - Route: - MEAL at New	Checked all tyres OK		NSW-W&T	502568
203	07/01/2011	284810	Reattach tyre brush strip	Reattached		NSW-BSW	502804
203	05/01/2011	284378	Tighten NSF control arm bolts	Tightened & r/tested		NSW-SUS	502387
203	05/01/2011	284332	OIL FILTER B10M +B7R BY PASS (VOLVO)			D	502387
203	05/01/2011	284332	ENGINE OIL DELO 400LE 15W40	ENGINE OIL		D	502387
203	05/01/2011	284332	FILTER AIR CLEANED B10M MK4 +B12			D	502387
203	05/01/2011	284332		D Service & Bus Safety Inspection		D	502387
203	05/01/2011	284332	OIL FILTER LONG LIFE B12BLE (VOLVO)			D	502387
203	05/01/2011	284332		Tension ALL Wheel Nuts to OEM Specs		D	502387
203	05/01/2011	284332		Remove V-Belts & Check Tensioner Bearings for Noise		D	502387
203	05/01/2011	284332	SUMP PLUG WASHER B12B			D	502387
203	05/01/2011	284332		A Service & Bus Safety Inspection		A	502387
203	05/01/2011	284332		Tension ALL Wheel Nuts to OEM Specs		A	502387
203	05/01/2011	284332		Grease AC Compressor Clutch Bearing		A	502387
203	05/01/2011	284332		Clean A/C filter.		A	502387
203	04/01/2011	284112	Replace tyre pos 2 - worn	Replaced		NSW-W&T	502088
203	03/01/2011	284105	Replace OS front tyre	Replaced		NSW-W&T	502088
203	29/12/2010	283539	GLOBE HIGH BEAM 24V70W H1			NSW-E&L	500038
203	23/12/2010	283272	AC - A/C drive belt starting to split	Fitted a/c belts		NSW-SCA	500148
203	23/12/2010	282778	REPLACE SIDE WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G86441 Receiving #:87588 Date :2010-12-23		NSW-BSW	500038
203	22/12/2010	283539	Replace RH headlight globe	Replaced		NSW-E&L	500038
203	20/12/2010	255894	ENGI - oil leaks from oil filters	Checked OK		NSW-ENG	456713

203	20/12/2010	255894	ENG C - coolant leak from water pump	Checked OK	NSW-ECO	456713
203	20/12/2010	282778	BOD - Smashed window NS rear window	Replaced by Elite	NSW-BSW	499712
203	16/12/2010	282450	Clean a/c filter	Cleaned	NSW-SCA	499458
203	07/12/2010	280337	BLADE WIPER 36INS		NSW-W&W	496968
203	03/12/2010	280337	WIP - windscreen wipers not clearing screen of rain	Fitted new wiper blades	NSW-W&W	496230
203	02/12/2010	280718	Add water to wipers	Added	NSW-W&W	495920
203	22/11/2010	278952	Add coolant	Added	NSW-ECO	493421
203	12/11/2010	277659	INTERIOR LIGHT DEFUSER		NSW-E&L	490310
203	11/11/2010	277659	Plastic light cover came down	Replaced diffuser	NSW-E&L	490310
203	10/11/2010	276571	HINGE AS SAMPLE	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G84232 Receiving #:85768 Date :2010-11-10 VG1882	NSW-PDO	489995
203	10/11/2010	277022	LED CLEARANCE LIGHT (RED AMBER)		NSW-E&L	489995
203	06/11/2010	277022	Drv entered - Accident	same as	NSW-ACC	489366
203	06/11/2010	277022	Ops Entered - Accident - Bus Hit Stationary Object - Route	Temp repairs and sent bus on road	NSW-ACC	489366
203	05/11/2010	276694	B12BLE ALTERNATOR 24V-110AMP (B/NEST)		NSW-E&L	489179
203	05/11/2010	276694	EL - check overcharging	Changed faulty alternator	NSW-E&L	489179
203	04/11/2010	276571	PD - Back door does not work properly - does not close	Checked door NO fault found	NSW-PDO	489179
203	04/11/2010	276571	Ops Entered - Fault - Passenger Doors - Route: 862 - Waver	same as	NSW-PDO	489179
203	04/11/2010	276694	EL - check overcharging	Checked alternators charge & battery load OK	NSW-E&L	489179
203	01/11/2010	276062	EL - Air cyclone seperator electric loom broken	Checked has been done	NSW-E&L	487701
203	01/11/2010	274769	COMPLETE HUB REARLHS	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G83778 Receiving #:85430 Date :2010-11-01	NSW-D&H	488391
203	01/11/2010	276387	BREAK - Breakdown Waverley Gardens. Out: 10:45 in 12:00.	Took 619 adjusted door ok.	NSW-BRE	488391
203	29/10/2010	274697	CUSHION FOAM 517		NSW-BSW	487582
203	29/10/2010	276062	Accident Damaged #31516 R/R. n/s/f. indicator assembly fro	Repaired NS rear corner & b/bar & painted all repaired panels	NSW-ACC	487701
203	29/10/2010	276062	Accident Damage # 31996 Repair n/s/r. lower panels No5 & N	Polished & touched up panels 56 & lower engine panel	NSW-ACC	487701
203	29/10/2010	276062	Accident Damaged #31516 R/R. n/s/f. indicator assembly fro	Repaired NS rear corner & b/bar & painted all repaired panels	NSW-ACC	487701
203	28/10/2010	274697	WATER PUMP exchange	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G83997 Receiving #:85275 Date :2010-10-28 203	NSW-ECO	487582
203	28/10/2010	274697	COOL - Water pump leak	Replaced water pump	NSW-ECO	487582
203	28/10/2010	274697	COOL - Coolant leak OR bottom of engine block	same as	NSW-ECO	487582
203	28/10/2010	274697	BOD - Till holder has sharp edges - need to replace till ho	Repaired	NSW-BSW	487582
203	28/10/2010	274697	BOD - fit new seat squab	Fitted	NSW-BSW	487582
203	28/10/2010	274697	BOD - Bad chip in windscreen	Secured with sticker	NSW-BSW	487582
203	27/10/2010	274697	GB - Transmission drive shaft seal leak (Checked 22/04/10	Assisted Nev with flange	NSW-GEA	487582
203	27/10/2010	274697	GB - Transmission drive shaft seal leak (Checked 22/04/10	Replaced seal	NSW-GEA	487582
203	27/10/2010	274697	GB - oil leak from gear box retarder (Checked on 28/07/10 s	S/cleaned no leaks found	NSW-GEA	487582
203	27/10/2010	274697	COOL - Water pump leak	same as	NSW-ECO	487582
203	27/10/2010	274697	SEAL REAR 4HP AND 5HP500 ZF		NSW-ECO	487582
203	27/10/2010	274697	LOCK TAB REAR ZF 4HP500		NSW-ECO	487582
203	27/10/2010	275828	Replace NSR brake caliper	Replaced	NSW-BRA	487582
203	26/10/2010	274769	B12BLE REAR HUB NUT		NSW-SUS	487582
203	26/10/2010	274697	PD - Both front & rear door sensitive edge n/w - needs new	Adjusted sensitive edge working.	NSW-PDO	487582
203	26/10/2010	275381	V-BELT		NSW-ECO	487582
203	26/10/2010	275381	B12BLE ALTERNATOR CRANK BELT		NSW-ECO	487582
203	26/10/2010	274769	N/S/rear hub and bearings collapsed	Fit new hub c/o	NSW-D&H	487582
203	25/10/2010	274769	FRONT ROTOR MACHINED	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G83776 Receiving #:85018 Date :2010-10-25	NSW-BRA	487582
203	22/10/2010	274769	SUS - NF upper control arm bush split	Changed upper left	NSW-SUS	487582
203	22/10/2010	274769	SUS - NF upper control arm bush split	Replaced	NSW-SUS	487582
203	22/10/2010	275381	Replace belts	Replaced	NSW-ECO	487582
203	22/10/2010	274769	BUSH KIT UPPER CONTROL ARM B10BLE		NSW-D&H	487582
203	22/10/2010	274769	N/S/rear hub and bearings collapsed	Cut broken bearings and cleaned up	NSW-D&H	487582
203	22/10/2010	274769	AXL - Diff pinion seal starting to leak needs to be cleaned	Checked OK no leaks	NSW-D&H	487582
203	21/10/2010	273587	POS 1 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G83345 Receiving #:84959 Date :2010-10-21	NSW-W&T	487582
203	21/10/2010	274769	N/S/rear hub and bearings collapsed	Removed NSR hub bearings collapsed	NSW-D&H	487582
203	21/10/2010	274769	BR - Front disc pads are low	Replaced	NSW-BRA	487582
203	21/10/2010	274769	FRONT PADS VOLVO B10L+B12BLE		NSW-BRA	487582
203	13/10/2010	273841	Replace No 2 tyre	Replaced & torqued w/nuts	NSW-W&T	485604
203	13/10/2010	273587	replace worn tyre pos 1	replace worn tyre pos 1	NSW-W&T	485604
203	11/10/2010	273432	Add coolant	Added	NSW-ECO	484744
203	11/10/2010	272833	FILTER AIR CLEANED B10M MK4 +B12		A	483449
203	10/10/2010	273336	Check light	Checked interior light fault	NSW-E&L	484465
203	10/10/2010	273336	Check light	Repaired lights	NSW-E&L	484465
203	08/10/2010	273237	Clean graffiti from inside & outside of bus	Cleaned	NSW-VAN	483804
203	08/10/2010	273279	Randoom vehikle audit	Inspected	NSW-I&T	483804
203	08/10/2010	272833		A Service & Bus Safety Inspection	A	483449
203	08/10/2010	272833		Tension ALL Wheel Nuts to OEM Specs	A	483449
203	08/10/2010	272833		Grease AC Compressor Clutch Bearing	A	483449
203	08/10/2010	272833		Clean A/C filter.	A	483449
203	08/10/2010	272833		A Service & Bus Safety Inspection	A	483449
203	05/10/2010	272613	VAN - Clean graffiti	Cleaned	NSW-VAN	483184

203	05/10/2010	272613	ELE - fluoro tubes u/s lh & rh	Checked OK	NSW-E&L	483184
203	01/10/2010	272210	Drivers door wont open from inside	Checked front door working	NSW-PDO	482388
203	29/09/2010	272054	Replace light diffuser	Replaced	NSW-E&L	482019
203	29/09/2010	272049	BOD - Drivers door wont open from inside	Temp repairs to drivers door	NSW-BSW	482019
203	27/09/2010	271760	Add coolant	Added	NSW-ECO	481264
203	24/09/2010	271331	REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	480366
203	24/09/2010	270670	SEAL HUB WHEEL REAR OUTER B12		NSW-D&H	480366
203	23/09/2010	271331	Replace NRF air bag	Changed air bag	NSW-SUS	480366
203	23/09/2010	270670	AXL - OS rear hub seal leaking	Replaced bearing kit cleaned the oily wheel caliper	NSW-D&H	480366
203	23/09/2010	270670	AXL - OS rear hub seal leaking	Fitted new bearings to RHR hub & refit hub and caliper to bus	NSW-D&H	480366
203	21/09/2010	268100	3092265 KIT RHS	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81576 Receiving #:83749 Date :2010-09-21 203	NSW-SUS	480366
203	21/09/2010	268100	3092269 KIT	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81576 Receiving #:83749 Date :2010-09-21 203	NSW-SUS	480366
203	21/09/2010	270670	SEAL HUB WHEEL REAR OUTER B12		NSW-D&H	480366
203	21/09/2010	270670	REAR HUB SEAL KIT B12BLE		NSW-D&H	480366
203	21/09/2010	270670	AXL - OS rear hub seal leaking	Strip the part	NSW-D&H	480366
203	20/09/2010	268100	calibrate rear brakes	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81859 Receiving #:83715 Date :2010-09-20	NSW-BRA	480366
203	18/09/2010	270670	AXL - OS rear hub seal leaking	Checked for oil leak found at rear OS hub bus u/s	NSW-D&H	480366
203	10/09/2010	269433	WHEEL NUT SQUIRREL		NSW-W&T	478643
203	10/09/2010	269521	Clean a/c filter	Cleaned	NSW-SCA	478776
203	10/09/2010	269498	Add coolant	Added	NSW-ECO	478776
203	10/09/2010	269498	Add coolant	Added	NSW-ECO	478776
203	09/09/2010	269433	Fit squirrels	Picked bus up from CMV checked rear w/nuts and fitted squirrels	NSW-W&T	478643
203	08/09/2010	268100	B12BLE REAR HUB NUT		NSW-BRA	478643
203	07/09/2010	268100	W/BRG GREASE X8	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81711 Receiving #:83064 Date :2010-09-07	NSW-BRA	478643
203	07/09/2010	268100	Repaire rear brakes and brake kallipers	Rekit OS rear caliper replaced OS rear wheel bearings and brake disc fitted hub and caliper replaced brake pads r/tested driven to CMV for brake calibration	NSW-BRA	478643
203	06/09/2010	267800	POS 5-6 11R CAP	Creditor #:BEA001 BEAUREPARES P/O #:G81473 Receiving #:83035 Date :2010-09-06	NSW-W&T	478643
203	06/09/2010	268100	21036050 REAR HUB BRG	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81711 Receiving #:83015 Date :2010-09-06	NSW-BRA	478643
203	06/09/2010	268100	21036050 REAR HUB BRG	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81711 Receiving #:83019 Date :2010-09-06	NSW-BRA	478643
203	06/09/2010	268100	REAR DISC PADS B12BLE+B7RSA FRONT+REAR		NSW-BRA	478643
203	06/09/2010	268100	Repaire rear brakes and brake kallipers	Fitted NS hub caliper brake pads fitted wheels. Start to rekit OSR caliper	NSW-BRA	478643
203	06/09/2010	268100	B12BLE REAR HUB NUT		NSW-BRA	478643
203	03/09/2010	268100	Repaire rear brakes and brake kallipers	Rebuilt NS rear caliper for 203 start to rebuild OSR	NSW-BRA	478643
203	03/09/2010	268100	REAR HUB SEAL KIT B12BLE		NSW-BRA	478643
203	03/09/2010	268100	B12BLE REAR BRAKE ROTOR		NSW-BRA	478643
203	03/09/2010	268100	SEAL HUB WHEEL REAR OUTER B12		NSW-BRA	478643
203	02/09/2010	268100	Replace NSR front airbag	Replaced	NSW-SUS	478643
203	02/09/2010	267672	Fit headlight and indicator lens	Replaced	NSW-E&L	478643
203	02/09/2010	268100	3092272 dust cover	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81591 Receiving #:82946 Date :2010-09-02	NSW-BRA	478643
203	02/09/2010	268100	3095631 BOLT	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G81591 Receiving #:82946 Date :2010-09-02	NSW-BRA	478643
203	02/09/2010	268100	Repaire rear brakes and brake kallipers	Finish rebuilding caliper off 207 RH rear then removed caliper from 149 and fit the one from 207 then strip from 149	NSW-BRA	478643
203	02/09/2010	268100	Repaire rear brakes and brake kallipers	Checked and found OSR caliper wont adjust auto removed OSR caliper fitted rebuilt caliper	NSW-BRA	478643
203	01/09/2010	268100	Repaire rear brakes and brake kallipers	Clean and order parts callipers bus 207 to go back on 203.	NSW-BRA	478643
203	01/09/2010	267672	PARK BRAKE VALVE VOLVO		NSW-BRA	478643
203	31/08/2010	268169	Repair broken water seperator wires	Repaired	NSW-ECO	478643
203	31/08/2010	268100	Repaire rear brakes and brake kallipers	Removed OSR brake caliper	NSW-BRA	478643
203	31/08/2010	268100	Repaire rear brakes and brake kallipers	Strip & clean rear calipers from bus 207 to go back on bus 203	NSW-BRA	478643
203	31/08/2010	267672	Handbrake not holding	R/tested & checked handbrake checked & found OSR caliper auto adjuster u/s	NSW-BRA	478643
203	30/08/2010	267800	replace worn tyre pos 5-6	replace worn tyre pos 5-6	NSW-W&T	478643
203	30/08/2010	267672	GLOBE+HOLDER INSTRUMENT (GREY)		NSW-E&L	478643
203	30/08/2010	267672	REPAIR KIT PARK BRAKE VALVE B10M+B10B		NSW-BRA	478643
203	30/08/2010	267672	Handbrake not holding	Checked park brake wont work rekitted & fitted park brake valve	NSW-BRA	478643
203	29/08/2010	267672	Handbrake not holding		NSW-BRA	478643
203	27/08/2010	267672	Hand brake not holding	Checked handbrake operation adjusted rear brakes replaced handbrake control lever replaced blown handbrake warning lght globe removed rear wheels to check for OS rear hub leaking oil	NSW-BRA	478643
203	25/08/2010	264765	3098017 plug	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G80400 Receiving #:82539 Date :2010-08-25 203	NSW-E&L	478353
203	19/08/2010	258459	CAN NOT HEAR	Creditor #:REB001 CIM CONCEPTS P/O #:G78746 Receiving #:82327 Date :2010-08-19	NSW-E&L	478913
203	17/08/2010	263686	POS 3-4 11R CAP	Creditor #:BEA001 BEAUREPARES P/O #:G80179 Receiving #:82225 Date :2010-08-17	NSW-W&T	476364
203	17/08/2010	266224	Clean graffiti off rear of bus	Cleaned	NSW-VAN	476364
203	17/08/2010	266208	Add coolant	Added	NSW-ECO	476364
203	16/08/2010	265913	BATTERY 800CCA		NSW-E&L	476087
203	16/08/2010	265913	GLOBE HIGH BEAM 24V70W H1		NSW-E&L	476087
203	14/08/2010	265913	EL - Load test & check charge rate	Tested battery they failed need to change	NSW-E&L	476087
203	14/08/2010	265913	Headlight passenger side n/w	Replaced globe	NSW-E&L	476087
203	14/08/2010	265913	EL - Load test & check charge rate	Repositioned battery cables & replaced batteries	NSW-E&L	476087
203	14/08/2010	265911	Bus wont start	Jump started	NSW-E&L	475518
203	13/08/2010	265850	Bus wont start	Jump started	NSW-E&L	475262
203	13/08/2010	265769	Flat batteries at Brighton Town hall	Drive to brighton and jump start bus. check alt belt ok. return to depot	NSW-E&L	475262
203	13/08/2010	265751	Bus wont start	Jump started	NSW-E&L	475262
203	12/08/2010	265571	Bus wont start	Jump started	NSW-E&L	474924

203	12/08/2010	265571	Bus wont start	Jump started	NSW-E&L	474924
203	11/08/2010	265502	Bus wont start	Jump started	NSW-E&L	474694
203	11/08/2010	265440	Add coolant	Added	NSW-ECO	474694
203	11/08/2010	265440	Add coolant	Added	NSW-ECO	474694
203	10/08/2010	265192	FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	474388
203	10/08/2010	265192	V-BELT		NSW-SCA	474388
203	09/08/2010	265192	Replace a/c belts	Put on belts running OK	NSW-SCA	474388
203	09/08/2010	265192	Replace a/c belts	Ass Matt with changing belts	NSW-SCA	474388
203	09/08/2010	265192	Replace a/c belts	Removed a/c belt idler post elongated mounting holes refitted and adjusted with new belts tested OK	NSW-SCA	474388
203	06/08/2010	264765	B12BLE ALTERNATOR CRANK BELT		NSW-E&L	474388
203	06/08/2010	264765	B12BLE ALTERNATOR 24V-110AMP (B/NEST)REBUILD		NSW-E&L	474388
203	06/08/2010	264765	V-BELT		NSW-E&L	474388
203	06/08/2010	264765	Replace alternators	Replaced alternator tensioner cont work on a/c post	NSW-E&L	474388
203	06/08/2010	264765	Replace alternators	Ass Dave with idler post	NSW-E&L	474388
203	06/08/2010	264765	Replace alternators	Replaced idler post pin bush on bus	NSW-E&L	474388
203	06/08/2010	264765	Replace alternators	Replaced idler post	NSW-E&L	474388
203	06/08/2010	264765	Replace alternators	Reassembled a/c idler post fitted and adjusted belts, tested and found still dropping off bent	NSW-E&L	474388
203	05/08/2010	264765	Replace alternators	Replaced but problem with alt idler & a/c post	NSW-E&L	474388
203	05/08/2010	264765	Replace alternators	Assist Matt with bus	NSW-E&L	474388
203	04/08/2010	264625	Called to a breakdown	Prepared to go to b/down but it was cancelled	NSW-I&T	474158
203	02/08/2010	264194	Add coolant	Added	NSW-ECO	473583
203	02/08/2010	264194	Add coolant	Added	NSW-ECO	473583
203	30/07/2010	263834	GLOBE INDICATOR 24V-18W SINGLE CONTACT		NSW-E&L	472945
203	29/07/2010	263686	replace worn tyres pos 3-4	replace worn tyres pos 3-4	NSW-W&T	472686
203	29/07/2010	263834	Change tyres 34	Replaced	NSW-W&T	472945
203	29/07/2010	263834	Change tyres 34	Replaced	NSW-W&T	472945
203	29/07/2010	263834	EL - OSF upper park light n/w	Changed	NSW-E&L	472945
203	29/07/2010	263834	EL - OSF upper park light n/w	Changed	NSW-E&L	472945
203	28/07/2010	263800	Check drivers compartment door	Checked & secured. Removed door lock and secured loose parts inside and refitted the door lock back to the door	NSW-BSW	472360
203	28/07/2010	263608		Clean A/C filter.	A	472360
203	28/07/2010	263608		Tension ALL Wheel Nuts to OEM Specs	A	472360
203	28/07/2010	263608		A Service & Bus Safety Inspection	A	472360
203	28/07/2010	263608		Grease AC Compressor Clutch Bearing	A	472360
203	28/07/2010	263608		A Service & Bus Safety Inspection	A	472360
203	21/07/2010	262164	AIR CON IDLER PEDISTAL PIN/SLEEVE/ BUSH ASSEMBLY		NSW-SCA	470362
203	21/07/2010	262714	Add coolant	Added	NSW-ECO	470556
203	21/07/2010	262714	Add coolant	Added	NSW-ECO	470556
203	20/07/2010	262164	Change alternator belt and idler pulley	Removed a/c belt adjuster pulley replaced new belt fitted new belt road tested.	NSW-ENG	470362
203	20/07/2010	262164	FAN BELT A/CON ARTIC 21/32X45		NSW-ENG	470362
203	20/07/2010	262164	V-BELT		NSW-ENG	470362
203	20/07/2010	262164	B12BLE ALTERNATOR CRANK BELT		NSW-ENG	470362
203	20/07/2010	262164		Fuelled & parked bus	NSW-ENG	470362
203	19/07/2010	262164	AC - Need to change AC belt and idler	Assist Sisil	NSW-SCA	470362
203	19/07/2010	262164	Change alternator belt and idler pulley	Fixed the alternator idler pulley filled coolant put all the belt but a/c small belt came off when a/c on	NSW-ENG	470362
203	19/07/2010	262250	B12BLE IDLER BRACKET PULLEY		NSW-E&L	470362
203	17/07/2010	262218	SUB - N/S front windscreen is damaged (Checked 18/06/10 ser	checked OK - serviceable HKS 17/07/10	NSW-BSW	470362
203	16/07/2010	262164	AC - Need to change AC belt and idler	Organize the parts and start the job	NSW-SCA	470362
203	16/07/2010	262164	Change alternator belt and idler pulley	Changed att belt & idler pulley	NSW-ENG	470362
203	16/07/2010	262250	Breakdown - Endeavour Hills - OUT 12.30 pm BACK 2.00 pm - A	Used van 619. Cut broken belt off and returned. (Changed belt and idler pulley)	NSW-BRE	470362
203	06/07/2010	260849	ENG C - top up coolant	topped up	NSW-ECO	467525
203	06/07/2010	260849	ENG C - top up coolant	topped up	NSW-ECO	467525
203	29/06/2010	259569	GLOBE INSTRUMENT PANEL		NSW-E&L	465409
203	25/06/2010	259569	Replace interior light globe	Replaced	NSW-E&L	464257
203	25/06/2010	259569	24V INVERTER 4-13W	Replaced	NSW-E&L	464257
203	25/06/2010	259569	GLOBE HIGH BEAM 24V70W H1		NSW-E&L	464257
203	25/06/2010	259569	Replace interior light globe	Replaced	NSW-E&L	464257
203	24/06/2010	259536	Add coolant	Added	NSW-ECO	463848
203	23/06/2010	258459	EL -Load test batteries & check charge rate	Checked OK	NSW-E&L	461575
203	23/06/2010	259247	LED CLEARANCE LIGHT (RED AMBER)		NSW-E&L	463377
203	22/06/2010	259247	ELE - change n/s led clearance light	changed light	NSW-E&L	463377
203	22/06/2010	259247	ELE - change n/s led clearance light	changed light	NSW-E&L	463377
203	20/06/2010	258459	2way radio is n/w	Changed the radio	NSW-COM	462822
203	19/06/2010	258905	Bus wont start	Jump started	NSW-E&L	462519
203	18/06/2010	253664	SUPPLY AND FIT DECALS	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G77319 Receiving #:79966 Date :2010-06-18 203	NSW-ACC	462376
203	18/06/2010	258743		A Service & Bus Safety Inspection	A	462376
203	18/06/2010	258743		Tension ALL Wheel Nuts to OEM Specs	A	462376
203	18/06/2010	258743		Grease AC Compressor Clutch Bearing	A	462376
203	18/06/2010	258743		Clean A/C filter.	A	462376

203	18/06/2010	258743	A Service & Bus Safety Inspection	A	462376
203	17/06/2010	258459	COM - 2way radio n/w	NSW-COM	461575
203	16/06/2010	258514	Add coolant	NSW-ECO	461820
203	16/06/2010	258514	Add coolant	NSW-ECO	461820
203	15/06/2010	255790	ROAD SAFETY INSPECTIONS	P	461575
203	15/06/2010	258459	COMM - 2way radio n/w	NSW-COM	461575
203	09/06/2010	257611	Drv entered - Ticket Equip VAL	NSW-TIC	460086
203	06/06/2010	257342	Bus wont start	NSW-E&L	459252
203	02/06/2010	256783	Bus wont start	NSW-E&L	458127
203	01/06/2010	256613	Bus wont start	NSW-E&L	457802
203	30/05/2010	255790	inspect for rsi	P	456713
203	30/05/2010	256338	Annual Inspection - BC 119750	P	457355
203	27/05/2010	255894	EBS MODULATOR VALVE KIT B12BLE	NSW-BRA	456713
203	27/05/2010	255894	BRK - DTC inicating RR modulator fault	NSW-BRA	456713
203	26/05/2010	254926	Remove Intercooler Wash Intercooler and Raditor	RSI	456452
203	26/05/2010	254926	Adjust Valve Clearance	RSI	456452
203	26/05/2010	255988	BODY - adjust rear door	NSW-BSW	456713
203	26/05/2010	255954	BODY - door sensitive edge needs adjusting	NSW-BSW	456713
203	25/05/2010	254926	V-BELT	NSW-SCA	456452
203	25/05/2010	254926	FAN BELT A/CON ARTIC 21/32X45	NSW-SCA	456452
203	24/05/2010	255645	BREAK - breakdown Springvale Station. Out 4pm In 5pm. Co	NSW-BRE	456713
203	24/05/2010	255423	BRAKES - recalibrate brakes	NSW-BRA	456713
203	21/05/2010	254926	Rekit Quick Release Valve	RSI	456452
203	21/05/2010	254926	Replace Fuel Filter With Water Bowl	RSI	456452
203	21/05/2010	254926	Replace Power Steering And Hydraulic Fan Oil Filter	RSI	456452
203	21/05/2010	254926	Replace Air Dryer Canister	RSI	456452
203	21/05/2010	254926	Replace Fuel Filter	RSI	456452
203	21/05/2010	254926	Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	RSI	456452
203	21/05/2010	255107	BUSH KIT UPPER CONTROL ARM B10BLE	NSW-STE	456713
203	21/05/2010	255422	ENGI - engine steam clean.	NSW-ENG	456713
203	21/05/2010	255421	ELEC - interior light globe needs replacing	NSW-E&L	456713
203	21/05/2010	255422	ENG C - coolant leak from header tank pipe	NSW-ECO	456713
203	21/05/2010	255107	REAR DISC PADS B12BLE+B7RSA FRONT+REAR	NSW-BRA	456713
203	21/05/2010	255423	BRAKES - recalibrate brakes	NSW-BRA	456713
203	20/05/2010	254926	SEAL QUICK RELEASE VALVE	RSI	456452
203	20/05/2010	254926	DIAPHRAGM QUICK RELEASE VALVE B58	RSI	456452
203	20/05/2010	254926	FUEL WATER FILTER B12BLE	RSI	456452
203	20/05/2010	254926	FUEL FILTER B12BLE	RSI	456452
203	20/05/2010	254926	TEXAMATIC 1888	RSI	456452
203	20/05/2010	254926	RPM BORATE EP LUBE 220	RSI	456452
203	20/05/2010	254926	POWER STEER +HYD FAN FILTER	RSI	456452
203	20/05/2010	254926	Service A/C Air Return Filter	RSI	456452
203	20/05/2010	254926	FILTER AIR DRYER KIT(HALDEX)	RSI	456452
203	20/05/2010	254926	O RING B12BLE INTERCOOLER	RSI	456452
203	20/05/2010	254926	Inspect Bus As Per Inspection Sheet	RSI	456452
203	20/05/2010	255107	SUS - Both side upper control arm bush split	NSW-SUS	456713
203	20/05/2010	255107	STEE - o/s upper control arm bush damage	NSW-STE	456713
203	20/05/2010	255107	ELE - n/s front saloon light n/w	NSW-E&L	456713
203	20/05/2010	255107	BRK - rear brake pads worn	NSW-BRA	456713
203	19/05/2010	253664	O/S REAR PUNCH PANEL	NSW-ACC	456452
203	18/05/2010	254831	ELE nearside lower front indicator not working	NSW-E&L	456124
203	13/05/2010	253664	LED CLEARANCE LIGHT (RED AMBER)	NSW-E&L	454707
203	13/05/2010	254216	Add coolant	NSW-ECO	454707
203	12/05/2010	253664	BOD - 2 floor latch bolts need tacking and replacing (Check	NSW-BSW	454707
203	12/05/2010	253664	BOD - paint NS top cant rail	NSW-BSW	454707
203	12/05/2010	253664	FLOOR HATCH SCREWS	NSW-BSW	454707
203	12/05/2010	253664	RED REFLECTOR 94X44MM	NSW-BSW	454707
203	12/05/2010	253664	AMBER REFLECTOR SIDE MOUNT	NSW-BSW	454707
203	12/05/2010	253664	Accident Damaged # 31017 R/R.n/s/r. clearance light Repair	NSW-ACC	454707
203	12/05/2010	253664	Accident Damaged # 31017 R/R.n/s/r. clearance light Repair	NSW-ACC	454707
203	12/05/2010	253664	Accident Damaged # 31017 R/R.n/s/r. clearance light Repair	NSW-ACC	454707
203	11/05/2010	253664	Ops Entered - Accident - Bus Hit Stationery Vehicle - Rout	NSW-ACC	454707
203	11/05/2010	253664	ACCIDENT DAMAGED # 30657 R/R. front bumper-barfront bumper	NSW-ACC	454707
203	11/05/2010	253664	WHEEL ARCH BRUSH 2.5MTR	NSW-ACC	454707
203	11/05/2010	253664	F/GLASS FRONT BUMPER	NSW-ACC	454707
203	11/05/2010	253664	Accident Damaged # 31121 R/R. front bumper-barfront bumper	NSW-ACC	454707
203	11/05/2010	253664	ACC - repair OS rear b/bar & paint	NSW-ACC	454707
203	11/05/2010	253664	Ops Entered - Accident - Collision while Turning - Route:	NSW-ACC	454707

203	11/05/2010	253664	Drv entered - Accident		NSW-ACC	454707
203	10/05/2010	253664	BOD - Replace emergency exit push button under b/bar	Replaced	NSW-BSW	454707
203	10/05/2010	253664	BOD - paint NS top cant rail	Sanded top cant rail to get ready for painting	NSW-BSW	454707
203	10/05/2010	253664	BOD - secure or replace side reflectors - NS OS	secured	NSW-BSW	454707
203	10/05/2010	253664	ACCIDENT DAMAGED # 30657 R/R. front bumper-barfront bumper	Disassembled broken front b/bar prepared new b/bar for paint work drilled new holes fitted to the bus for accuracy body filled chipped due to drilling holes sanded entire b/bar cleaned with	NSW-ACC	454707
203	10/05/2010	253664	ACCIDENT DAMAGED # 30657 R/R. front bumper-barfront bumper	Helped Shyman to fit up b/bar	NSW-ACC	454707
203	10/05/2010	253664	ACC - replace & paint OS 56789 panels & decals	Repaired & touched up Ok	NSW-ACC	454707
203	10/05/2010	253664	ACC - repair OS rear b/bar & paint	Polished & touched up	NSW-ACC	454707
203	10/05/2010	253664	Accident Damaged # 31017 R/R.n/s/r. clearance light Repair	Started fibreglass work	NSW-ACC	454707
203	10/05/2010	253664	Accident Damaged #30760 R/R. n/s.lower panel No4 safety dec	Painted panel NS 5 and replaced reflector	NSW-ACC	454707
203	07/05/2010	253346	BOD - Paint wheels	Painted & paint strip caps	NSW-BSW	454414
203	07/05/2010	253662	BOD - Polish exterior panels/headers & touch up paint work	Polished NS front/rear headers	NSW-BSW	454707
203	07/05/2010	253662	BOD - Replace drivers compartment door hinges	Replaced both door hinges & secured	NSW-BSW	454707
203	07/05/2010	253662	BOD - Repair & paint till stand	Removed till stand welded broken areas repainted & mounted to the stand	NSW-BSW	454707
203	07/05/2010	253662	BOD - Clean air condition filter secure vents	Cleaned	NSW-BSW	454707
203	07/05/2010	253662	BOD - Secure seat cushions - NS 1	Secured and replaced ripped cover	NSW-BSW	454707
203	07/05/2010	253662	BOD - Replace interior decals - priority seating	Replaced	NSW-BSW	454707
203	07/05/2010	253662	BOD - Replace emergency exit decals with safety hammers - r	Replaced	NSW-BSW	454707
203	07/05/2010	253662	BOD - Secure all lower skit panels	Secured	NSW-BSW	454707
203	07/05/2010	253662	BOD - Clean graffiti - floor seats & side walls	Cleaned	NSW-BSW	454707
203	07/05/2010	253662	BOD - Secure rear door handles	Secured	NSW-BSW	454707
203	07/05/2010	253662	BOD - Clean back seat - rubbish	Cleaned	NSW-BSW	454707
203	07/05/2010	253664	ACC - replace & paint OS 56789 panels & decals	Manufactured new panel No 5 NS painted etch primer and black (can paint) to the back of panel	NSW-ACC	454707
203	07/05/2010	253664	ACC - replace & paint OS 56789 panels & decals	Repaired & polished OS 56	NSW-ACC	454707
203	06/05/2010	253346	BOD - grendas name address and weight - OSF No 1 panel - r	Removed & polished	NSW-BSW	454414
203	06/05/2010	253346	BOD - Paint exterior mirrors and arms	Painted	NSW-BSW	454414
203	04/05/2010	252969	ANN - carry out annual inspection	Inspected	P	453932
203	04/05/2010	252951	AC - A/C very noisy inside has a loud whistle	Checked and found filter needed to be cleaned	NSW-SCA	453932
203	27/04/2010	252153	Clean a/c filter	Cleaned	NSW-SCA	452507
203	23/04/2010	251841	CLEAR FRONT INDICATOR WRAP-AROUND		NSW-E&L	451589
203	22/04/2010	251767	Clean a/c filter	Cleaned	NSW-SCA	451589
203	22/04/2010	250974	EL - load test and check charge rate	Load tested OK	NSW-E&L	449772
203	22/04/2010	250974	EL - Replace dash light globe	Checked OK	NSW-E&L	449772
203	22/04/2010	250974	EL - Replace interior light globe	Replaced globe	NSW-E&L	449772
203	22/04/2010	251841	Replace N/S/F indicator lens	Replaced	NSW-E&L	451589
203	22/04/2010	251841	Replace N/S/F indicator lens	Replaced	NSW-E&L	451589
203	22/04/2010	251733	OIL FILTER B10M +B7R BY PASS (VOLVO)		D	451589
203	22/04/2010	251733	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	ENGINE OIL	D	451589
203	22/04/2010	251733	FILTER AIR B10M MK4+B12 USE AF4560		D	451589
203	22/04/2010	251733		D Service & Bus Safety Inspection	D	451589
203	22/04/2010	251733	OIL FILTER LONG LIFE B12BLE (VOLVO)		D	451589
203	22/04/2010	251733		Tension ALL Wheel Nuts to OEM Specs	D	451589
203	22/04/2010	251733		Remove V-Belts & Check Tensioner Bearings for Noise	D	451589
203	22/04/2010	251733	FILTER TRANSMISSION ZF 4139-298-038E39HD119		D	451589
203	22/04/2010	251733	SUMP PLUG WASHER B12B		D	451589
203	22/04/2010	251734		Service T Replace Transmission Oil & Filter	A&T	451589
203	22/04/2010	251734		Bus Safety Inspection	A&T	451589
203	22/04/2010	251734	FILTER TRANSMISSION ZF 4139-298-038E39HD119		A&T	451589
203	22/04/2010	251734	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS		A&T	451589
203	22/04/2010	251733		Clean A/C filter.	A	451589
203	22/04/2010	251733		A Service & Bus Safety Inspection	A	451589
203	22/04/2010	251733		Tension ALL Wheel Nuts to OEM Specs	A	451589
203	22/04/2010	251733		Grease AC Compressor Clutch Bearing	A	451589
203	22/04/2010	251734		Clean A/C filter.	A	451589
203	22/04/2010	251734		A Service & Bus Safety Inspection	A	451589
203	22/04/2010	251734		Tension ALL Wheel Nuts to OEM Specs	A	451589
203	22/04/2010	251734		Grease AC Compressor Clutch Bearing	A	451589
203	16/04/2010	251101	Replace dash light globe	Replaced	NSW-E&L	449772
203	16/04/2010	251101	GLOBE+HOLDER INSTRUMENT (GREY)		NSW-E&L	449772
203	15/04/2010	250955	Clean a/c filter	Cleaned	NSW-SCA	449561
203	09/04/2010	250325	Adjust rear doors	Adjusted	NSW-PDO	447987
203	09/04/2010	250220	Add coolant	Added	NSW-ECO	447987
203	07/04/2010	249834	Clean a/c filter	Cleaned	NSW-SCA	447567
203	07/04/2010	249942	P/D - front door rubber come off	Checked OK	NSW-PDO	447746
203	07/04/2010	249944	The rubber on the front door loose	Refit both door rubbers	NSW-BSW	447567
203	07/04/2010	249942	BOD - Sun visor does not go up	Checked Ok	NSW-BSW	447746
203	01/04/2010	249589	Ops Entered - Fault - Eng Cool - Route: 888 - Brandon Park	Replaced rear heater hose	NSW-ECO	446196
203	01/04/2010	249590	Breakdown - Brandon Park Shopping Centre - OUT 1.05 pm - BA	Used van 619. Topped up coolant & returned to depot (replaced rear heater hose)	NSW-BRE	446196

203	31/03/2010	249339	Add coolant	Added	NSW-ECO	445936
203	31/03/2010	249429	Breakdown - Springvale & Cheltenham Rd - OUT 3.15 pm BACK 4	C/O bus 607. Returned to depot. (repaired air leak under seat)	NSW-BRE	445936
203	29/03/2010	249086	Add coolant	Added	NSW-ECO	445379
203	26/03/2010	248957	WIP - wiper washers just working	Cleaned washers OK	NSW-W&W	444848
203	26/03/2010	248875	Clean a/c filter	Cleaned	NSW-SCA	444628
203	26/03/2010	248957	ENG - Whining whistle coming through when accelerating	Microphone touching drivers seat - disconnected	NSW-ENG	444848
203	26/03/2010	248887	Add coolant	Added	NSW-ECO	444628
203	26/03/2010	248957	BRA - ABS warning light on	Removed rear wheels & checked brakes 20mm	NSW-BRA	444848
203	26/03/2010	248957	BRA - ABS warning light on	Removed rear wheels checked brake pads and cleaned sensor cleared codes & r/tested	NSW-BRA	444848
203	25/03/2010	248387	FOOT BRAKE 70313316	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G75866 Receiving #:77453 Date :2010-03-25 203	NSW-BRA	444414
203	24/03/2010	248387	BRK - re-calibrate brake system	replaced foot valve and roadtested.	NSW-BRA	444173
203	22/03/2010	248363	Add coolant	Added	NSW-ECO	444173
203	22/03/2010	248387	BRK - re-calibrate brake system	Recalibrate brakes with computer	NSW-BRA	444173
203	22/03/2010	248387	BRK - re-calibrate brake system	Attempted to recalibrate brakes but had computer problems	NSW-BRA	444173
203	19/03/2010	248138	Clean a/c filter	Cleaned	NSW-SCA	443742
203	19/03/2010	248138	Add coolant	Added	NSW-ENG	443742
203	15/03/2010	247564	Remove graffiti	Removed	NSW-VAN	442775
203	15/03/2010	247510	INDICATOR SWITCH B10M		NSW-E&L	442464
203	15/03/2010	247481		Clean A/C filter.	A	442775
203	15/03/2010	247481		A Service & Bus Safety Inspection	A	442775
203	15/03/2010	247481		Tension ALL Wheel Nuts to OEM Specs	A	442775
203	15/03/2010	247481		Grease AC Compressor Clutch Bearing	A	442775
203	14/03/2010	247510	Replace indicator switch	Replaced	NSW-E&L	442464
203	12/03/2010	247477	DEST - Desto n/w	Checked desto operation told control room nothing to do with workshop	NSW-E&L	442775
203	10/03/2010	247051	Clean a/c filter	Cleaned	NSW-SCA	441484
203	10/03/2010	247158	Breakdown - Pillars Rd & S/vale RD - OUT 1.00 pm BACK 2.00	C/O bus 237. Engine cover had fallen down removed it & returned to depot	NSW-BRE	441484
203	01/03/2010	362423	Scrap	Creditor #:BEA001 BEAUREPARES P/O #:G110613 Receiving #:111113 Date :2012-07-10	NSW-W&T	596112
203	01/03/2010	246043	Clean a/c filter	Cleaned	NSW-SCA	439184
203	26/02/2010	245748	SPIGOT BEARING ISUZU FSR+VOLVO ALT		NSW-E&L	437786
203	26/02/2010	245748	B12BLE ALTERNATOR CRANK BELT		NSW-E&L	437786
203	26/02/2010	245748	V-BELT		NSW-E&L	437786
203	26/02/2010	245748	FAN BELT A/CON ARTIC 21/32X45		NSW-E&L	437786
203	26/02/2010	245874	Add coolant	Added	NSW-ECO	438159
203	24/02/2010	245748	Replace idler pulley bearing	Replaced bearing	NSW-E&L	437786
203	24/02/2010	245748	Replace idler pulley bearing	Fixed alt belt & a/c belt put coolant - coolant started to leak from water pump housing. Removed again & redo job put coolant r/tested fuelled & parked	NSW-E&L	437786
203	24/02/2010	245748	Replace idler pulley bearing	Drop coolant ready to do idler pulley	NSW-E&L	437786
203	24/02/2010	245620	Indicators u/s		NSW-E&L	437786
203	18/02/2010	242736	POS 1 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G74398 Receiving #:76391 Date :2010-02-18	NSW-W&T	436200
203	18/02/2010	244989	Clean a/c filter	Cleaned	NSW-SCA	436200
203	10/02/2010	244047	Clean a/c filter	Cleaned	NSW-SCA	434021
203	09/02/2010	243991	remove graffiti	removed	NSW-VAN	433885
203	09/02/2010	243823	GLOBE S/CONTACT 24V-10W		NSW-E&L	433885
203	09/02/2010	243991	replace stopping globe	replaced	NSW-E&L	433885
203	09/02/2010	243903	Add coolant	Added	NSW-ECO	433885
203	09/02/2010	243823	MUD FLAPS GRENDA S MF60X30GRE RED		NSW-BSW	433885
203	09/02/2010	243991	Repair pass seat o/s rear	repaired	NSW-BSW	433885
203	09/02/2010	243991	Repaired o/s front mud guard	repaired	NSW-BSW	433885
203	09/02/2010	243991	Repair rear bumper bar bolt	repaired	NSW-BSW	433885
203	09/02/2010	243823		A Service & Bus Safety Inspection	A	433885
203	09/02/2010	243823		Tension ALL Wheel Nuts to OEM Specs	A	433885
203	09/02/2010	243823		Grease AC Compressor Clutch Bearing	A	433885
203	09/02/2010	243823		Clean A/C filter.	A	433885
203	08/02/2010	243716	Add coolant	Added	NSW-ECO	433470
203	01/02/2010	242736	Replace tyre pos 1 - side damage	Replaced	NSW-W&T	430995
203	30/01/2010	242822	Change front 2 tyres	Replaced	NSW-W&T	431295
203	30/01/2010	242822	REAR DISC PADS B12BLE+B7RSA FRONT		NSW-BRA	431574
203	30/01/2010	242822	Change rear brake pads	Changed	NSW-BRA	431295
203	29/01/2010	242748	Drv entered - Throttle Other	Checked OK	NSW-THR	430995
203	27/01/2010	242363	Clean a/c filter	Cleaned	NSW-SCA	430239
203	26/01/2010	242340	Chip windscreen	Checked OK	NSW-BSW	430025
203	20/01/2010	241757	Clean a/c filter	Cleaned	NSW-ECO	428480
203	13/01/2010	238679	POS 5 11R225 CAP FLAT	Creditor #:BEA001 BEAUREPARES P/O #:G73257 Receiving #:75411 Date :2010-01-13	NSW-W&T	426313
203	13/01/2010	241125	Replace amber reflector	Replaced	NSW-E&L	426313
203	13/01/2010	241125	AMBER REFLECTOR SIDE MOUNT		NSW-E&L	426313
203	12/01/2010	240970	Add coolant	Added	NSW-ECO	426071
203	11/01/2010	240799	clean a/c filters	cleaned filters	NSW-SCA	425822
203	05/01/2010	240261	steam clean radiator	cleaned	NSW-ECO	424340
203	05/01/2010	240285	FRONT PADS VOLVO B10L		NSW-BRA	424472

203	05/01/2010	240285	front brake pads need to change	remove n/s & o/s from wheel remove and fit new brake pads re fit wheels	NSW-BRA	424340
203	05/01/2010	240141		A Service & Bus Safety Inspection	A	424340
203	05/01/2010	240141		Tension ALL Wheel Nuts to OEM Specs	A	424340
203	05/01/2010	240141		Grease AC Compressor Clutch Bearing	A	424340
203	05/01/2010	240141		Clean A/C filter.	A	424340
203	05/01/2010	240141		A Service & Bus Safety Inspection	A	424472
203	04/01/2010	240003	remove graffitti	removed graffitti	NSW-VAN	424022
203	02/01/2010	239985	replace globe	replaced.	NSW-E&L	423856
203	02/01/2010	239985	GLOBE HIGH BEAM 24V70W H1		NSW-E&L	423856
203	29/12/2009	239591	Low coolant level sign comes on dashboard	R/tested & checked gauges OK	NSW-ECO	423194
203	29/12/2009	239591	Low coolant level sign comes on dashboard	Checked coolant OK	NSW-ECO	423055
203	29/12/2009	239591	Low coolant level sign comes on dashboard	Checked coolant OK	NSW-ECO	423055
203	21/12/2009	239118	Add coolant	Added	NSW-ECO	421466
203	18/12/2009	238955	Clean a/c filter	Cleaned	NSW-SCA	420712
203	16/12/2009	238706	Replace No 5 tyre	Replaced & torqued w/nuts	NSW-W&T	420406
203	16/12/2009	238706	Replace No 5 tyre	Replaced	NSW-W&T	420406
203	16/12/2009	238679	rpair flat tyre pos 5	Repaired	NSW-W&T	420406
203	13/12/2009	238415	Replace a/c belts	Replaced	NSW-SCA	419585
203	13/12/2009	238415	FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	419810
203	09/12/2009	238085	Check a/c belts	Checked belt damaged on outside	NSW-SCA	418702
203	09/12/2009	238072	GLOBE HIGH BEAM 24V70W H1		NSW-E&L	418702
203	09/12/2009	238072	Replace headlight globe	Replaced	NSW-E&L	418702
203	07/12/2009	237810	Adjust rear door	Adjusted	NSW-PDO	418236
203	07/12/2009	237810	Small crack in header tank	Pick up from CMV	NSW-ECO	418236
203	07/12/2009	237810	Small crack in header tank	Remove header tank	NSW-ECO	418305
203	07/12/2009	237810	Small crack in header tank	Replaced header tank	NSW-ECO	418236
203	07/12/2009	237810	MOUNTING BLOCK EXP TANK		NSW-ECO	418236
203	07/12/2009	237810	OVER FLOW TANK B7L+B12BLE		NSW-ECO	418236
203	04/12/2009	236578	POS 3-4-5-6 11R225 CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G72619 Receiving #:74404 Date :2009-12-04	NSW-W&T	417475
203	02/12/2009	237411	Bus very sluggish to set off	R/tested checked OK	NSW-ENG	416851
203	02/12/2009	237411	Driver side indicator light globe blown side of bus	Replaced the globe	NSW-E&L	416851
203	01/12/2009	237139	Clean a/c filter	Cleaned	NSW-SCA	416474
203	27/11/2009	236880	Adjust rear door	Adjusted sensitive edge in rear door	NSW-PDO	415656
203	27/11/2009	236749	Add coolant	Added	NSW-ECO	415656
203	26/11/2009	236578	replace worn tyres pos 3-4-5-6		NSW-W&T	415455
203	25/11/2009	236402	PUMP WIPER-WASHER 24 VOLT		NSW-W&W	415444
203	25/11/2009	236647	Change rear tyres	Changed	NSW-W&T	415444
203	25/11/2009	236647	Change rear tyres	Changed	NSW-W&T	415444
203	25/11/2009	236408	Check fuel lines for leaks and secure -check oil pipes for	Checked all	NSW-ENG	415136
203	25/11/2009	236408	Check fuel lines for leaks and secure -check oil pipes for	Checked OK	NSW-ENG	415136
203	25/11/2009	236632	Small coolant leak from plug above intercooler pipe under e	Tightened plug checked OK	NSW-ECO	415444
203	25/11/2009	236402		Grease AC Compressor Clutch Bearing	A	415136
203	25/11/2009	236402		Tension ALL Wheel Nuts to OEM Specs	A	415136
203	25/11/2009	236402		Clean A/C filter.	A	415136
203	25/11/2009	236402		A Service & Bus Safety Inspection	A	415455
203	25/11/2009	236402		A Service & Bus Safety Inspection	A	415136
203	21/11/2009	236321	Drv entered - Elec & Light Indicators	Checked OK	NSW-E&L	414285
203	14/11/2009	235464	Driver side indicator globe blown	Fitted globe	NSW-E&L	412122
203	13/11/2009	235347	Replace a/c belt	Replaced	NSW-SCA	411803
203	13/11/2009	235351	Replace dash lights	Replaced	NSW-E&L	411803
203	13/11/2009	235351	GLOBE DASH B7L		NSW-E&L	411803
203	12/11/2009	235211	Fit a/c belt	Fitted	NSW-SCA	411695
203	12/11/2009	235211	Fit a/c belt	Fitted	NSW-SCA	411695
203	12/11/2009	235211	FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	411695
203	12/11/2009	235226	Add coolant	Added	NSW-ECO	411695
203	11/11/2009	233422	pos 3 11r225 cap	Creditor #:BEA001 BEAUREPAIRES P/O #:G71682 Receiving #:73653 Date :2009-11-11	NSW-W&T	411305
203	06/11/2009	234699	Replace fluro	Replaced	NSW-E&L	409855
203	27/10/2009	233422	replace worn tyre pos 3		NSW-W&T	406658
203	26/10/2009	233398	REAR AIR BAG SUIT VOLVO B12B B12BLE		NSW-SUS	406658
203	26/10/2009	233398	N/S/R/R air bag is leaking	checked. ok.	NSW-SUS	406572
203	26/10/2009	233398	N/S/R/R air bag is leaking	Replaced rear rear air bag & r/tested	NSW-SUS	406658
203	26/10/2009	233398	Drv entered - Steering Pulls Left	checked. ok.	NSW-S&E	406572
203	26/10/2009	233368	Random vehicle audit	completed.	NSW-I&T	406572
203	26/10/2009	233368	Random vehicle audit	completed.	NSW-I&T	406658
203	26/10/2009	233398	Ops Entered - Fault - Brakes - Route: 857 - Bangholme	Replaced rear brake pads	NSW-BRA	406572
203	26/10/2009	233398	REAR DISC PADS B12BLE+B7RSA FRONT		NSW-BRA	406658
203	26/10/2009	233398	Ops Entered - Fault - Brakes - Route: 857 - Bangholme	Assist to replace rear brake pads	NSW-BRA	406658
203	26/10/2009	233398	air leak	Fixed air leak from air dryer air line	NSW-AIR	406572

203	26/10/2009	233398	air leak	Fixed water seperator wire	NSW-AIR	406572
203	26/10/2009	233366	Service	D Service & Bus Safety Inspection. completed.	D	406658
203	26/10/2009	233366	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	ENGINE OIL	D	406572
203	26/10/2009	233366	FILTER AIR B10M MK4+B12 USE AF4560		D	406572
203	26/10/2009	233366	Service	D Service & Bus Safety Inspection. completed.	D	406572
203	26/10/2009	233366	OIL FILTER LONG LIFE B12BLE (VOLVO)		D	406572
203	26/10/2009	233366		Tension ALL Wheel Nuts to OEM Specs	D	406572
203	26/10/2009	233366		Remove V-Belts & Check Tensioner Bearings for Noise	D	406572
203	26/10/2009	233366	SUMP PLUG WASHER B12B		D	406572
203	26/10/2009	233366	OIL FILTER B10M +B7R BY PASS (VOLVO)		D	406572
203	26/10/2009	233366		A Service & Bus Safety Inspection	A	406572
203	26/10/2009	233366		Tension ALL Wheel Nuts to OEM Specs	A	406572
203	26/10/2009	233366		Grease AC Compressor Clutch Bearing	A	406572
203	26/10/2009	233366		Clean A/C filter.	A	406572
203	22/10/2009	233449	Clean a/c filter	Cleaned	NSW-SCA	405618
203	20/10/2009	232919	brakes pulling heavily to the left (dangerously)	replace nut on clamp that clamps on to booster push rod and road test. o/s/f	NSW-BRA	405041
203	19/10/2009	232911	check suspension	checked suspension operation and roadtest.	NSW-SUS	404663
203	12/10/2009	231639	fit a/c belt	fitted a/c belt	NSW-SCA	403155
203	12/10/2009	231639	FAN BELT A/CON ARTIC 21/32X45		NSW-SCA	403463
203	09/10/2009	231737	change belts	changed belts	NSW-ENG	402292
203	01/10/2009	230889	A/C tension pooley seised	fixed and road tested ok.	NSW-SCA	400011
203	01/10/2009	230889	AIR CON IDLER PEDISTAL PIN/SLEEVE/ BUSH ASSEMBLY		NSW-SCA	400011
203	01/10/2009	230889	FAN BELT AIR/CON ARTIC VEE BELT B43	removed a/c belt idler post fixed new bushes idler post hose is cracked needs to be replaced.	NSW-SCA	400011
203	01/10/2009	230889	V-BELT		NSW-SCA	400011
203	30/09/2009	230720	Change & reline a/c belt	Changed & relined	NSW-SCA	399705
203	30/09/2009	230720	Change & reline a/c belt	Assist mech changing a/c belts	NSW-SCA	399705
203	30/09/2009	230720	V-BELT		NSW-SCA	399705
203	30/09/2009	230720	FAN BELT AIR/CON ARTIC VEE BELT B43		NSW-SCA	399705
203	29/09/2009	230593	Change a/c belts	Changed a/c belt & a/c crank	NSW-SCA	399349
203	29/09/2009	230593	Idler pulley belt cracked	Assist mech changing a/c & crank pulley belts	NSW-ENG	399349
203	29/09/2009	230593	FAN BELT AIR/CON ARTIC VEE BELT B43		NSW-ENG	399349
203	29/09/2009	230593	V-BELT		NSW-ENG	399349
203	22/09/2009	230021	replace fluroscent tubes	Replaced	NSW-E&L	397643
203	22/09/2009	230021	replace fluroscent tubes	Replaced	NSW-E&L	397638
203	22/09/2009	229935	Add coolant	Added	NSW-ECO	397643
203	22/09/2009	229882		A Service & Bus Safety Inspection	A	397643
203	22/09/2009	229882		Tension ALL Wheel Nuts to OEM Specs	A	397643
203	22/09/2009	229882		Grease AC Compressor Clutch Bearing	A	397643
203	22/09/2009	229882		Clean A/C filter.	A	397643
203	22/09/2009	229882		A Service & Bus Safety Inspection	A	397643
203	18/09/2009	229258	Vibration noisy came from g/box accumalator unit	Changed retarder valve	NSW-GEA	396216
203	16/09/2009	229258	O/S front or front control arm bush U/S	Replaced	NSW-SUS	396216
203	16/09/2009	229258	BUSH KIT UPPER CONTROL ARM B10BLE		NSW-SUS	396402
203	16/09/2009	229258	NUT UPPER+LOWER SUSPENSION ARM		NSW-SUS	396402
203	16/09/2009	229258	NUT UPPER+LOWER SUSPENSION ARM		NSW-SUS	396402
203	16/09/2009	229258	Vibration noisy came from g/box accumalator unit	Stripped had to fit back no parts in store	NSW-GEA	396216
203	16/09/2009	229258	ACCUMULATOR RETARDER VALVE		NSW-GEA	396402
203	16/09/2009	229258	Coolant leak from hose clamp top of coolant tank	Tightned	NSW-ECO	395902
203	16/09/2009	229258	Air leak next to G box retarder		NSW-AIR	396216
203	06/09/2009	228349	Engine cover needs fix screws missing	Secured engine cover	NSW-ENG	393667
203	03/09/2009	228128	Seat belt broken	Replaced buckle	NSW-BSW	392715
203	03/09/2009	228128	SEAT BELT BUCKLE TWIN WIRE GREY		NSW-BSW	392958
203	28/08/2009	227540	Blinker u/s upper left front	Changed globe	NSW-E&L	390823
203	28/08/2009	227540	GLOBE INDICATOR 24V-18W SINGLE CONTACT		NSW-E&L	390823
203	26/08/2009	227283	Add coolant	Added	NSW-ECO	390135
203	25/08/2009	227130	Add coolant	Added	NSW-ECO	389959
203	17/08/2009	226325	hack air leak next to G box retarder	Refer to work order no - 229860	NSW-AIR	388752
203	12/08/2009	225767	Accident damage #21779# Damiged rear bumper bar - R/H rear	Repaired by Volgren	NSW-ACC	388752
203	12/08/2009	225768	Accident Damaged # 21714 R/R.N/S. tail lightsn/s/r. fleet	Repaired by Volgren	NSW-ACC	388752
203	11/08/2009	225646	Replace tyre pos 3 and 4 -worn		NSW-W&T	388752
203	11/08/2009	225784	Breakdown - Accident Damage - OUT 6.15 pm BACK 7.15 pm - Re	C/O Bus 237. Returned to depot (sent to Volgren for repair)	NSW-BRE	388752
203	10/08/2009	225686	Changed tyre pos 3 and 4	Changed tyre pos 3 and 4	NSW-W&T	388522
203	10/08/2009	225686	Changed tyre pos 3 and 4	Changed tyre pos 3 and 4	NSW-W&T	388752
203	10/08/2009	225563		A Service & Bus Safety Inspection	A	388522
203	10/08/2009	225563		Tension ALL Wheel Nuts to OEM Specs	A	388522
203	10/08/2009	225563		Grease AC Compressor Clutch Bearing	A	388522
203	10/08/2009	225563		Clean A/C filter.	A	388522
203	10/08/2009	225563	Service	A service completed	A	388752

203	22/07/2009	223744	Replace top park globe	Replaced	NSW-E&L	383004
203	22/07/2009	223744	GLOBE S/CONTACT 24V-10W		NSW-E&L	383004
203	14/07/2009	222949	Add coolant	Added	NSW-ECO	381004
203	12/07/2009	222800	Indicator stalk loose it is very difficult to find the neut	Replaced indicator switch	NSW-E&L	380485
203	11/07/2009	222793	Chip in windscreen near the rsi sticker	Checked still servicable	NSW-BSW	380337
203	06/07/2009	222248		A Service & Bus Safety Inspection	A	379056
203	06/07/2009	222248		Tension ALL Wheel Nuts to OEM Specs	A	379056
203	06/07/2009	222248		Grease AC Compressor Clutch Bearing	A	379056
203	06/07/2009	222248		Clean A/C filter.	A	379056
203	06/07/2009	222248		A Service & Bus Safety Inspection	A	379374
203	27/06/2009	221571	Drv entered - Elec & Light Other	Checked OK	NSW-E&L	376699
203	26/06/2009	221443	Drv entered - Ticket Equip Other	Checked by Joe Zammit	NSW-TIC	376285
203	24/06/2009	221209	R/H headlight out	Changed globe	NSW-E&L	375662
203	24/06/2009	221209	GLOBE HIGH BEAM 24V70W H1		NSW-E&L	376056
203	18/06/2009	220596	Replace fluroscnet light	Replaced	NSW-E&L	373777
203	18/06/2009	220596	Replace fluroscnet light	Replaced	NSW-E&L	374052
203	18/06/2009	220596	Add coolant	Added	NSW-ECO	373777
203	15/06/2009	220283	Replace L/H/S clearance light	Replaced	NSW-E&L	372741
203	15/06/2009	220283	GLOBE S/CONTACT 24V-10W		NSW-E&L	372741
203	11/06/2009	219963	Add oil	Added	NSW-ENG	371879
203	05/06/2009	219538	Replace dash light	Replaced	NSW-E&L	370040
203	05/06/2009	219538	GLOBE DASH B7L		NSW-E&L	370040
203	04/06/2009	219531	Change rear brake pads	Changed & r/tested	NSW-BRA	369828
203	04/06/2009	219531	Change rear brake pads	Changed & r/tested	NSW-BRA	370040
203	04/06/2009	219531	FRONT PADS VOLVO B10L		NSW-BRA	370040
203	04/06/2009	219422		A Service & Bus Safety Inspection	A	369828
203	04/06/2009	219422		Tension ALL Wheel Nuts to OEM Specs	A	369828
203	04/06/2009	219422		Grease AC Compressor Clutch Bearing	A	369828
203	04/06/2009	219422		A Service & Bus Safety Inspection	A	370040
203	04/06/2009	219422		Clean A/C filter.	A	369828
203	02/06/2009	218553	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G67252 Receiving #:69116 Date :2009-06-02	P	369021
203	31/05/2009	218553	Annual Inspection - BC 134530	Annual Inspection - BC 134530	P	367445
203	29/05/2009	218873	Check interior light	Replace 2 fluroscnet tubes	NSW-E&L	367967
203	29/05/2009	218873	Check interior light	Replace 2 fluroscnet tubes	NSW-E&L	368271
203	28/05/2009	217509	POS 1-2 NEW 11R225	Creditor #:BEA001 BEAUREPARES P/O #:G66917 Receiving #:69002 Date :2009-05-28	NSW-W&T	367682
203	26/05/2009	218497	Replace headlight globe	Replaced	NSW-E&L	367143
203	26/05/2009	218497	GLOBE HIGH BEAM		NSW-E&L	367143
203	25/05/2009	218052	front indicator lights	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G66926 Receiving #:68859 Date :2009-05-25 203	NSW-BSW	366842
203	23/05/2009	218335	Drv entered - Engine Lacking Power	Checked OK	NSW-ENG	366394
203	23/05/2009	218335	drivers seat needs cleaning	Cleaned	NSW-BSW	366394
203	22/05/2009	218190	Accident Damaged No18383 Polish & touch-up o/s/r. lower pa	Completed Job	NSW-ACC	366148
203	21/05/2009	218052	Polish front bumper bar	Polished	NSW-BSW	366058
203	21/05/2009	218052	Wheel arch rubber and brush - N/S/R repair	Repaired. N/S/F had come out of rubber put back in as well	NSW-BSW	366058
203	21/05/2009	218052	Paint wheels	Painted	NSW-BSW	366058
203	21/05/2009	218052	Replace emergency exit button under front b/bar	Replaced button & decal	NSW-BSW	366058
203	21/05/2009	218052	Polish exterior panels/headers & touch up panels	Polished & touched up paint	NSW-BSW	366058
203	21/05/2009	218052	Polish & secure rear bumper bar	Polished & touched up	NSW-BSW	366058
203	21/05/2009	218052	S/clean wheel chair ramp	Cleaned	NSW-BSW	366058
203	21/05/2009	218052	Fuel & park bus	Fuelled & parked	NSW-BSW	366058
203	21/05/2009	218052	Accident damage no 19390 - Polish n/s panels 45	Polished & touched up paint	NSW-ACC	366058
203	21/05/2009	218052	Repair & paint N/S rear corner	Temp touched up paint	NSW-ACC	366058
203	20/05/2009	218023	Top front left park light out	Fit loose wire to globe	NSW-E&L	365758
203	19/05/2009	217049	50A0004 SUMP PLUG	Creditor #:MUL001 MULTISPARES LTD P/O #:G66357 Receiving #:68705 Date :2009-05-19 203	RSI	365520
203	19/05/2009	217049	50Z0116 WASHER	Creditor #:MUL001 MULTISPARES LTD P/O #:G66357 Receiving #:68705 Date :2009-05-19 203	RSI	365520
203	19/05/2009	217921	Ops Entered - Engine		NSW-ENG	365520
203	19/05/2009	217921	Ops Entered - Fault - Engine - Route: - Change over from	Checked for noise front end new bushes making noise	NSW-ENG	365520
203	18/05/2009	217478	NUMBER PLATE LIGHT LED	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G66809 Receiving #:68687 Date :2009-05-18 203	NSW-ENG	365139
203	18/05/2009	217753	Add coolant	Added	NSW-ECO	365139
203	15/05/2009	217509	replace worn tyres pos 1-2	Replaced	NSW-W&T	364436
203	15/05/2009	217478	N/S front upper control arm bushes cracked	Fit bushes & torqued w/nuts	NSW-SUS	364436
203	15/05/2009	217478	Steam clean bus	Cleaned	NSW-ENG	364436
203	15/05/2009	217478	Engine oil leak under engine s/clean & check	R/tested	NSW-ENG	364436
203	15/05/2009	217478	Need to put long engine breather pipe	Checked OK	NSW-ENG	364436
203	15/05/2009	217478	Steam clean bus	Cleaned	NSW-ENG	364436
203	15/05/2009	217478	Drv entered - Elec & Light Headlights	Checked OK	NSW-E&L	364169
203	15/05/2009	217478	O/S front indicator lens cracked	Replaced	NSW-E&L	364436
203	15/05/2009	217478	Front door downlight loose wiring to halogen connector	Secured	NSW-E&L	364436
203	15/05/2009	217478	N/S upper indicator lens cracked	Showed Nathan how to change LED indicators	NSW-E&L	364436

203	15/05/2009	217478 CLEAR FRONT INDICATOR WRAP-AROUND		NSW-E&L	364436
203	15/05/2009	217478 WEDGE GLOBE INSTRUMENT 24V 3W		NSW-E&L	364436
203	15/05/2009	217478 INDICATOR LAMP L.E.D.		NSW-E&L	364436
203	15/05/2009	217478 BUSH KIT UPPER CONTROL ARM B10BLE		NSW-E&L	364436
203	15/05/2009	217478 NUT UPPER+LOWER SUSPENSION ARM		NSW-E&L	364436
203	15/05/2009	217478 NUT UPPER+LOWER SUSPENSION ARM		NSW-E&L	364436
203	15/05/2009	217478 Front door downlight loose wiring to halogen connector	Secured	NSW-E&L	364630
203	15/05/2009	217478 N/S upper indicator lens cracked	Replaced	NSW-E&L	364436
203	15/05/2009	217478 Secure coolant hose under header tank	Secured	NSW-ECO	364436
203	15/05/2009	216915 FRONT DISC ROTOR B10L+B12BLE	Creditor #:MUL001 MULTISPARES LTD P/O #:G66864 Receiving #:68657 Date :2009-05-15 203	NSW-BRA	364436
203	15/05/2009	217478 Air leak near transmission (Checked on 24/3/09 servicable H	Checked needed new fitting	NSW-AIR	364436
203	13/05/2009	216915 N/S front tyre has flat spot	Replaced both front tyres	NSW-W&T	364047
203	13/05/2009	216915 N/S front tyre has flat spot	Replaced both front tyres	NSW-W&T	364047
203	13/05/2009	216915 Paint exterior mirrors and arms	Painted	NSW-BSW	363192
203	13/05/2009	216915 Paint exterior mirrors and arms	Painted	NSW-BSW	363192
203	13/05/2009	216915 FRONT PADS VOLVO B10L		NSW-BRA	364169
203	13/05/2009	216915 PLUG BRASS OIL HUB CAP VOLVO		NSW-BRA	364169
203	13/05/2009	216915 Front brake pads low	Replaced discs and pads	NSW-BRA	364169
203	13/05/2009	216915 Front brake pads low	Replaced discs and pads	NSW-BRA	364047
203	11/05/2009	217049 FILTER AIR DRYER KIT(HALDEX)		RSI	363590
203	11/05/2009	217049 POWER STEER +HYD FAN FILTER		RSI	363590
203	11/05/2009	217049	Replace Air Dryer Canister	RSI	363590
203	11/05/2009	217049	Replace Power Steering And Hydraulic Fan Oil Filter	RSI	363590
203	11/05/2009	217049	Service A/C Air Return Filter	RSI	363590
203	11/05/2009	217049 RPM BORATE EP LUBE 220	DIFF OIL	RSI	363590
203	11/05/2009	217049 TEXAMATIC 1888	P/STEER TOP UP OIL	RSI	363590
203	11/05/2009	217049 FUEL FILTER B12BLE		RSI	363590
203	11/05/2009	217049 FUEL WATER FILTER B12BLE		RSI	363590
203	11/05/2009	217049 DIAPHRAGM QUICK RELEASE VALVE B58		RSI	363590
203	11/05/2009	217049 SEAL QUICK RELEASE VALVE		RSI	363590
203	11/05/2009	217049	Replace Final Drive Oil ( NON SYNTHETIC OIL ONLY )	RSI	363590
203	11/05/2009	217049	Replace Fuel Filter	RSI	363590
203	11/05/2009	217049	Replace Fuel Filter With Water Bowl	RSI	363590
203	11/05/2009	217049	Rekit Quick Release Valve	RSI	363590
203	11/05/2009	217049	Adjust Valve Clearance	RSI	363590
203	11/05/2009	217049	Remove Intercooler Wash Intercooler and Raditor	RSI	363590
203	11/05/2009	217049	Inspect Bus As Per Inspection Sheet	RSI	363590
203	11/05/2009	217049 O RING B12BLE INTERCOOLER		RSI	363590
203	11/05/2009	217049	Remove Intercooler Wash Intercooler and Raditor	RSI	363590
203	11/05/2009	217049	Inspect Bus As Per Inspection Sheet	RSI	363741
203	08/05/2009	216915 Replace safety triangle decal - on d/shield new buses	Replaced	NSW-BSW	363192
203	08/05/2009	216915 Paint till stand	Painted	NSW-BSW	363192
203	08/05/2009	216915 Replace give way decal - O/S/R corner window	Replaced	NSW-BSW	363192
203	08/05/2009	216915 Fuel & park	Fuelled & parked	NSW-BSW	363362
203	08/05/2009	216915 Paint wheels	Painted	NSW-BSW	363192
203	08/05/2009	216915 Remove timetable holder	Removed & cleaned	NSW-BSW	363192
203	08/05/2009	216915 Secure all lower skit panels	Secured	NSW-BSW	363192
203	08/05/2009	216915 Replace emergency exit push button under panel	Replaced	NSW-BSW	363192
203	08/05/2009	216915 Replace licensed to carry (No) seat (No) adult passengers	Replaced	NSW-BSW	363192
203	08/05/2009	216915 Clean graffiti - seats side walls	Cleaned	NSW-BSW	363192
203	08/05/2009	216915 Clean air condition filter secure vents	Cleaned	NSW-BSW	363192
203	08/05/2009	216915 Hand rails secure rivet front N/S	Secured	NSW-BSW	363192
203	08/05/2009	216915 Wheel chair ramp - operation & clean	Cleaned	NSW-BSW	363192
203	07/05/2009	216033 POS 3-4-5-6 11R225 REAR CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G66431 Receiving #:68384 Date :2009-05-07	NSW-W&T	362924
203	07/05/2009	216798 Replace down light at front door	Replaced	NSW-E&L	362924
203	07/05/2009	216798 HALOGEN GLOBE 24V20W		NSW-E&L	362924
203	06/05/2009	216661 Add coolant	Added	NSW-ECO	362742
203	06/05/2009	211510 Door brake n/w	Checked found 2 pipes were wrong way around	NSW-BRA	349527
203	04/05/2009	216424 Replace downlight globe	Replaced	NSW-E&L	362501
203	30/04/2009	216027 Annual body inspection	Inspected	P	361292
203	30/04/2009	216079 Check tyre No 3	Fit No 34 tyres torque w/nuts & cleaned rims	NSW-W&T	361550
203	30/04/2009	216079 Check tyre No 3	Replaced 34	NSW-W&T	361550
203	30/04/2009	216079 Change O/S rear tyres	Changed	NSW-W&T	361550
203	30/04/2009	216033 Replace tyre pos 34 - worn out	Replaced	NSW-W&T	361292
203	30/04/2009	216079 Cracked a/c belt	Replaced a/c belt	NSW-SCA	361550
203	30/04/2009	216079 Cracked a/c belt	Replaced belt	NSW-SCA	361550
203	30/04/2009	216079 FAN BELT AIR/CON ARTIC VEE BELT B43		NSW-SCA	361550
203	30/04/2009	216079 Remove graffiti	Removed	NSW-BSW	361550

203	30/04/2009	216023	OIL FILTER LONG LIFE B12BLE (VOLVO)			D	361292
203	30/04/2009	216023	Tension ALL Wheel Nuts to OEM Specs			D	361292
203	30/04/2009	216023	Remove V-Belts & Check Tensioner Bearings for Noise			D	361292
203	30/04/2009	216023	SUMP PLUG WASHER B12B			D	361292
203	30/04/2009	216023	OIL FILTER B10M +B7R BY PASS (VOLVO)			D	361292
203	30/04/2009	216023	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	ENGINE OIL		D	361292
203	30/04/2009	216023	FILTER AIR B10M MK4+B12 USE AF4560			D	361292
203	30/04/2009	216023		D Service & Bus Safety Inspection		D	361292
203	30/04/2009	216023	Tension ALL Wheel Nuts to OEM Specs			A	361292
203	30/04/2009	216023	Grease AC Compressor Clutch Bearing			A	361292
203	30/04/2009	216023	Clean A/C filter.			A	361292
203	30/04/2009	216023	A Service & Bus Safety Inspection			A	361292
203	21/04/2009	215137	Add coolant	Added		NSW-ECO	359320
203	08/04/2009	214196	Replace a/c belts	Replaced		NSW-SCA	355197
203	08/04/2009	214196	FAN BELT AIR/CON ARTIC VEE BELT B43			NSW-SCA	355570
203	02/04/2009	213533	Replace fluroscent tube	Replaced		NSW-E&L	353709
203	02/04/2009	213533	Replace fluroscent tube	Replaced		NSW-E&L	353940
203	27/03/2009	212541	POS 2 11R225 NEW	Creditor #:BEA001 BEAUREPARES P/O #:G65427 Receiving #:67266 Date :2009-03-27		NSW-W&T	352374
203	25/03/2009	212541	Replace tyre pos 2 - bald	Replaced		NSW-W&T	351754
203	24/03/2009	212546	Change tyre pos 2	Changed		NSW-W&T	351609
203	24/03/2009	212546	Change tyre pos 2	Changed		NSW-W&T	351609
203	24/03/2009	212483	Add coolant	Added		NSW-ECO	351609
203	24/03/2009	211510	Door brake n/w	Checked out door brake		NSW-BRA	349527
203	24/03/2009	211510	Door brake n/w	Checked out door brake found valve to be leaking		NSW-BRA	349527
203	24/03/2009	212415	ZF GEARBOX FILTER			A&T	351609
203	24/03/2009	212415	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS			A&T	351609
203	24/03/2009	212415		Service T Replace Transmission Oil & Filter		A&T	351609
203	24/03/2009	212415				A	351754
203	24/03/2009	212415				A	351609
203	24/03/2009	212415	Tension ALL Wheel Nuts to OEM Specs			A	351609
203	24/03/2009	212415	Grease AC Compressor Clutch Bearing			A	351609
203	24/03/2009	212415	Clean A/C filter.			A	351609
203	17/03/2009	211510	DIAPHRAGM QUICK RELEASE VALVE B58			NSW-BRA	349527
203	17/03/2009	211510	SEAL QUICK RELEASE VALVE			NSW-BRA	349527
203	16/03/2009	211510	Door brake n/w	Checked out door brake air system at fault		NSW-BRA	349527
203	16/03/2009	211510	Door brake n/w	Adjusted front door sensors		NSW-BRA	349527
203	16/03/2009	211510	Door brake n/w	Assist with Greg to find problem		NSW-BRA	349527
203	14/03/2009	211510	Door brake n/w	Rekit quick release valve check relay but still n/w		NSW-BRA	349076
203	13/03/2009	211223	Door alarm dash light blinking also beck door brake inter	Found over ride switch had been turned off		NSW-PDO	348566
203	13/03/2009	211317	Drv entered - Elec & Light Hazard Lights	Found switch over ride had been turned off		NSW-E&L	348830
203	13/03/2009	211318	Drv entered - Elec & Light Indicators	Found override switch had been turned off		NSW-E&L	348830
203	13/03/2009	211319	Interior light u/s	Checked OK		NSW-E&L	348830
203	10/03/2009	210846	Front R/H indicator out	Replace globe		NSW-E&L	347697
203	10/03/2009	210846	GLOBE INDICATOR 24V-18W SINGLE CONTACT			NSW-E&L	347911
203	07/03/2009	210861	Check windscreen washer	Checked ok		NSW-W&W	347697
203	07/03/2009	210862	Check indicator	Check ok		NSW-E&L	347697
203	05/03/2009	210572	Add coolant	Added		NSW-ECO	347015
203	04/03/2009	210396	Replace dash light	Replaced		NSW-E&L	346697
203	04/03/2009	210396	Replace park light	Replaced		NSW-E&L	346697
203	04/03/2009	210396	LED CLEARANCE LIGHT (RED AMBER)			NSW-E&L	346697
203	04/03/2009	210396	GLOBE INSTRUMENT PANEL			NSW-E&L	346697
203	28/02/2009	210105	2way is not working at all	Checked working OK		NSW-COM	345715
203	20/02/2009	209444	Front door wont work properly	Adjust front door		NSW-PDO	343404
203	19/02/2009	209261	2 O/S rear air bag leaking	Replaced		NSW-SUS	343277
203	19/02/2009	209261	O/front of rear airbag leak	Replaced		NSW-SUS	343277
203	19/02/2009	209261	REAR AIR BAG SUIT VOLVO B12B B12BLE			NSW-SUS	343277
203	19/02/2009	209310	Adjust doors	Adjusted		NSW-PDO	343277
203	19/02/2009	209225				A	343277
203	19/02/2009	209225	Tension ALL Wheel Nuts to OEM Specs			A	343277
203	19/02/2009	209225	Grease AC Compressor Clutch Bearing			A	343277
203	19/02/2009	209225				A	343277
203	19/02/2009	209225	PUMP WIPER-WASHER 24 VOLT			A	343277
203	18/02/2009	209198	Add coolant	Added		NSW-ECO	342992
203	16/02/2009	208910	Add oil	Added		NSW-ENG	342396
203	14/02/2009	208872	A/C filter needs replacing	Cleaned tested OK		NSW-SCA	341943
203	13/02/2009	208782	Need water in washers (wiper blades)	Filled water		NSW-W&W	341627
203	11/02/2009	208543	Bus wont start	Jump started		NSW-E&L	341010
203	11/02/2009	208543	Bus wont start	Jump started		NSW-E&L	341312

203	05/02/2009	207975	Add coolant	Added	NSW-ECO	339566
203	04/02/2009	207827	Replace dash lights	Replaced	NSW-E&L	339310
203	04/02/2009	207827	GLOBE DASH B7L		NSW-E&L	339310
203	03/02/2009	207681	No r/h h/light	Replaced globe	NSW-E&L	339701
203	03/02/2009	207681	HEAD LIGHT GLOBE 24V 70/75W		NSW-E&L	339701
203	30/01/2009	207434	Refill coolant	Refilled	NSW-ECO	337989
203	20/01/2009	206725	Check belts	Checked need replacing	NSW-ENG	334882
203	20/01/2009	206725	Check belts	Replaced A/C belts	NSW-ENG	335128
203	20/01/2009	206725	FAN BELT AIR/CON ARTIC VEE BELT B43		NSW-ENG	335128
203	20/01/2009	206721	Add coolant	Added	NSW-ECO	334882
203	16/01/2009	206133			A	333295
203	16/01/2009	206133		Tension ALL Wheel Nuts to OEM Specs	A	333295
203	16/01/2009	206133		Grease AC Compressor Clutch Bearing	A	333295
203	16/01/2009	206133			A	334071
203	16/01/2009	206133	WEDGE GLOBE INSTRUMENT 24V 3W		A	334071
203	09/01/2009	205728	Replace dash light	Replaced	NSW-E&L	331849
203	09/01/2009	205728	GLOBE+HOLDER INSTRUMENT (GREY)		NSW-E&L	331849
203	09/01/2009	205716	Add coolant	Added	NSW-ECO	331849
203	24/12/2008	204532	Refill coolant	Refilled	NSW-ECO	327444
203	24/12/2008	204532	Refill coolant	Refilled	NSW-ECO	327444
203	18/12/2008	204204	Roadtest bus	R/tested	NSW-I&T	326006
203	18/12/2008	203454	W/CHAIR RAMP FOLD OUT TYPE	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G62592 Receiving #:64553 Date :2008-12-18 203	NSW-BSW	326006
203	17/12/2008	203047	POS 3+4+5+6 11R225 REAR CAPS	Creditor #:BEA001 BEAUREPAIRES P/O #:G62477 Receiving #:64515 Date :2008-12-17	NSW-W&T	325758
203	17/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Removed all sensors & plugs cleaned & checked all parts r/tested OK	NSW-BRA	325758
203	16/12/2008	203623	ABS SENSOR REAR DISC B12BLE	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G62710 Receiving #:64456 Date :2008-12-16	NSW-BRA	325758
203	16/12/2008	203623	ABS SENSOR REAR DISC B12BLE		NSW-BRA	325758
203	16/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Refitted and resealed O/S/R hub	NSW-BRA	325758
203	16/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	R/tested	NSW-BRA	325758
203	16/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Replaced N/S/R wheel sensor	NSW-BRA	325758
203	16/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Diagnosing fault codes	NSW-BRA	325758
203	16/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Replaced N/S/R wheel sensor	NSW-BRA	325758
203	15/12/2008	203623	BOLT REAR ROTOR MOUNTING		NSW-BRA	325758
203	15/12/2008	203623	REAR HUB SEAL KIT B12BLE		NSW-BRA	325758
203	15/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Replaced O/S/R speed sensor	NSW-BRA	325758
203	15/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Replaced O/S/R brake lining sensor	NSW-BRA	325758
203	15/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Stripped O/S/R hub assembly	NSW-BRA	325758
203	15/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	R/tested	NSW-BRA	325758
203	12/12/2008	203454	Wheelchair ramp bent	Replaced wheelchair ramp	NSW-BSW	325288
203	11/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Cleaned rear wheel sensor and surrounding	NSW-BRA	325758
203	11/12/2008	203623	Remove all rear wheels & check for faukty brake sensor/s.	Remove wheels & checked wheel sensors. r/tested found problem still exists	NSW-BRA	325758
203	09/12/2008	203454	Wheelchair ramp bent	Temp repairs on w/chair ramp removal ordered new one	NSW-BSW	325288
203	06/12/2008	203248	Lost gear in traffic whilst braking	Replaced g/box computer	NSW-GEA	324669
203	06/12/2008	203248	Lost gear in traffic whilst braking	Same as w/order # 203623	NSW-GEA	324871
203	05/12/2008	203047	Replace tyre pos 3456 - bald	Replaced	NSW-W&T	324149
203	05/12/2008	203193	Breakdown - Glen Waverly Station - OUT 8.45 pm BACK 10.30 p	Used van 619. Put 2 fuel cans in & bled system	NSW-BRE	324149
203	04/12/2008	203069	Replace 4 rear tyres	Replaced	NSW-W&T	324149
203	04/12/2008	202985	Random Vehicle Audit	Completed	NSW-I&T	324149
203	04/12/2008	202986	Replace gear box oil with ZF synthetic oil only at 324589 k	Changed at service	NSW-GEA	324149
203	04/12/2008	203069	Replace rear brake pads	Replaced	NSW-BRA	324149
203	04/12/2008	202984	FILTER TRANSMISSION ZF 4139-298-038		A&T	324149
203	04/12/2008	202984	TEXAMATIC 1888		A&T	324149
203	04/12/2008	202984	REAR DISC PADS B12BLE		A&T	324149
203	04/12/2008	202984		Service T Replace Transmission Oil & Filter	A&T	324149
203	04/12/2008	202984		Tension ALL Wheel Nuts to OEM Specs	A	324149
203	04/12/2008	202984		RYAN	A	324149
203	01/12/2008	201153	TINT W/SCRREN	Creditor #:TIN002 TINT FX P/O #:G61875 Receiving #:64086 Date :2008-12-01	NSW-BSW	323503
203	01/12/2008	200564	E.C.U.VOLVO 80%GOODWILL	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G61839 Receiving #:64088 Date :2008-12-01 203	NSW-BRA	323503
203	20/11/2008	200880	Gear box need to be checked	Fit new g. box ECU control unit reprogram with Stephan - road test OK	NSW-GEA	320523
203	13/11/2008	200880	Gear box need to be checked	removed e.c.u from 204 to check & was o/k. *now need to replace E.C.U	NSW-GEA	320369
203	12/11/2008	200564	Transmission U/S	Clean cods and road tested	NSW-GEA	320369
203	11/11/2008	200540	REPLACE A/C BELT		NSW-SCA	320043
203	11/11/2008	200564	A/C blowing hot air	Replaced belts	NSW-SCA	320369
203	11/11/2008	200564	V-BELT		NSW-SCA	320369
203	11/11/2008	200564	Brakes warning signal is on	Clean cods and road tested	NSW-BRA	320369
203	08/11/2008	201153	Tint windcreens	Completed by Tint FX	NSW-BSW	319906
203	27/10/2008	181883	Adjust door sensors	Adjusted	NSW-PDO	316445
203	27/10/2008	181889	Replace park light globe O/S/F	Replaced	NSW-E&L	316445
203	27/10/2008	181889	Repair front door ramp	Repaired	NSW-BSW	316445

203	27/10/2008	181806	D Service	D	316445
203	27/10/2008	181806	Tension ALL Wheel Nuts to OEM Specs	D	316445
203	27/10/2008	181806	Remove V-Belts & Check Tensioner Bearings for Noise	D	316445
203	27/10/2008	181806	SUMP PLUG WASHER B12B	D	316445
203	27/10/2008	181806	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	D	316445
203	27/10/2008	181806	OIL FILTER LONG LIFE B12BLE (VOLVO)	D	316445
203	27/10/2008	181806	FILTER AIR CLEANED B10M MK4 +B12	D	316445
203	27/10/2008	181806	WEDGE GLOBE INSTRUMENT 24V 3W	D	316445
203	27/10/2008	181806		A	316445
203	27/10/2008	181806	Tension ALL Wheel Nuts to OEM Specs	A	316445
203	20/10/2008	181035	Replace alternator belt	NSW-E&L	314429
203	20/10/2008	181035	V-BELT	NSW-E&L	314429
203	20/10/2008	181035	FAN BELT AIR/CON ARTIC VEE BELT B43	NSW-E&L	314429
203	20/10/2008	181035	B12BLE ALTERNATOR CRANK BELT	NSW-E&L	314429
203	20/10/2008	181079	Breakdown - Springvale & Princes Hwy - OUT 5.30 pm BACK 6.3	NSW-BRE	314159
203	17/10/2008	181079	Breakdown - Springvale & Princes Hwy - OUT 5.30 pm BACK 6.3	NSW-BRE	314159
203	29/09/2008	179368	Replace fluroscnet tube	NSW-E&L	308739
203	24/09/2008	179089	Replace dash lights	NSW-E&L	307482
203	22/09/2008	178888	Replace step light	NSW-E&L	306919
203	22/09/2008	178795		A	306919
203	22/09/2008	178795	Tension ALL Wheel Nuts to OEM Specs	A	306919
203	22/09/2008	178795		A	307113
203	22/09/2008	178795	HALOGEN GLOBE 24V20W	A	306919
203	19/09/2008	178734	Bus wont start	NSW-E&L	306103
203	12/09/2008	178051	Replace fluroscnet tube	NSW-E&L	303913
203	12/09/2008	178051	Replace fluroscnet tube	NSW-E&L	303913
203	11/09/2008	177934	Replace air con belt	NSW-SCA	303684
203	11/09/2008	177934	FAN BELT AIR/CON ARTIC VEE BELT B43	NSW-SCA	303913
203	11/09/2008	177934	Replace air con belt	NSW-SCA	303913
203	02/09/2008	175023	POTENTIOMETER ACC PEDAL B12BLE	NSW-ECO	301308
203	27/08/2008	176583	Replace wheel nut indicator	NSW-W&T	299527
203	27/08/2008	176583	Left w/nut indicator missing	NSW-W&T	299527
203	27/08/2008	176583	33MM LOOSE WHEEL NUT INDICATOR	NSW-W&T	299527
203	27/08/2008	176583	Replace position control for accelerator pedal	NSW-THR	299527
203	27/08/2008	176583	Check fault codes	NSW-E&L	299527
203	27/08/2008	176583	Drv entered - Comm Equip Faulty	NSW-COM	299527
203	26/08/2008	176516	Replace interior light	NSW-E&L	299527