

Plant & Vehicle Maintenance & Repairs

Asset Number:	CO283	Registration Number:	CC07SR	Serial Number:	JALFVZ34SE7000270
Make:	Isuzu	Model:	Vacuum Truck	Year of Manufacture:	2015
Date	Hr / Kms	Work Conducted			Responsible Person
02/24/2016		Refer to Airpower Invoice DUCS53380			Airpower
07/01/2016		Unblock suction valve at top of tank. Clean filters.			TG/GC
07/01/2016		Identify IVMS tracker IMEI # 358683060260503			TG/GC
07/30/2016	803 hrs	Truck ran out of fuel. Bleed and restart.			TG/GC
09/16/2016		R/H Steering fault alarm (Code E192 (3)			TG
09/21/2016		Inspect air con operation.			GC
10/21/2016	923	Seat adjuster broken, disassemble and lock into position. (Airpower for Warranty work). (At later date).			TG
11/06/2017	39949	Top up coolant - low coolant alarm			SS
01/05/2018	64528	No fault codes on dash, no air leaks, UHF hand piece ordered			BO
01/31/2017		Refer to Airpower Invoice DUCS55972			Airpower
01/31/2017		Drop off at Airpower for 20,000 km service, seat and air con warranty.			TG
08/08/2017	6147	Remove pressure valve and reverse camera			GC
08/10/2017	6155	Fitted new clearance lights to left side			MM
08/17/2017		Change out air filters			
10/10/2017		Done - brakes squeaky, check reverse alarm, water pump losing power			MM
10/20/2017		Done - a/c cleaned, deflector in tank, brakes squeaky			MM
01/03/2018		Brakes squeaky - washed out			MM
03/13/2018	11303 km	Replaced wiper blades, inspect drivers seat belt, parts are on order			BO
02/14/2018		Fit new side door handle			
08/27/2018		Arnos invoice 171214 puncture repair			SS
08/28/2018	2243 hr / 12587 km	Repair puncture LH steer tyre, replace rear work light and vac truck tip switched, 250 hour service, repalce tank side entry valve			TG SS
08/27/2018		Puncture repair - Arnos inv 171214			SS
11/14/2018	2303	Replace top suction hose, replace boom suction hose, re(??) high pressure water hose reel hose. Supply 2 x new pressure washer lances. Fit new tap handle on tank drain. Supply 2 x 4 inch x4m suction hoses. Supply spare vac filters. Replace all hose and lance quick couplers back to standard specs			TG SS
05/22/2019	2349	Replaced pump controll solenoid			TG SS
07/25/2019	2423	Repair fitting at hose connector on hose reel, replace tank wash out tap and replace tank clean sprayer jets. Replace 1 clearance light			SS
04/27/2020	2543	500 hr service. Replaced engine oil and filter, fuel filters, and air filters, grease and wash			TG
09/05/2020	2577	Run and charge batteries. May need batteries soon			
10/16/2020	2607	Repaired tyre RH intermediate inner			SS
10/19/2020		Jump start at fuel farm, ordered new batteries. Terry to fit. 19/10 Ty replaced batteries			TG/TH

Plant & Vehicle Maintenance & Repairs

Asset Number:	CO283	Registration Number:	CC07SR	Serial Number:	JALFVZ34SE7000270
Make:	Isuzu	Model:	Vacuum Truck	Year of Manufacture:	2015
02/13/2021	2772	250 hour service (engine oil and fuel filters)			SS
03/11/2021	15664km	Replaced height control valve on drivers seat			SS
04/21/2021		Leaking and truck not holding air. Fit new booster to RH rear axle			TG
04/22/2021	2875	Found broken shut off cylinder, Hosepower made up new ram shaft; reassemble and test. OK (suction wasn't s			SS/Hosepower
09/07/2021	3009	Losing air pressure from air tanks when applying brake pedal. Faulty relay valve at rear of chassis, replaced with			SS JP
09/24/2021	3028	Complete 3000 hr service, repair RH clearance light & damaged wiring in rear chassis rail			TG/GC
03/30/2022		Fixed leaking			TG
02/09/2022		Airbag light Deleted with scan tool.			TG
04/28/2022	n/a	Reverse beeper too loud. How it is made - tested ok			TG
05/04/2022		Replaced retract pipe and suction hose on boom. Checked gate valve, requires further repairs in w/shop			SS
06/08/2022		JN#3082 - Rear LH taillight repaired			BO
06/09/2022	3460	500 hr service done, changed engine oil & filters, fuel filters, replaced LH glove, and rear parker cable			BO/GC
06/15/2022		Soldered wire to get remote working			
08/31/2022	3510	JN#3118 - Dropped of tyres to NT tyre, replaced all drive tyres - Refer to attached Inv 82775			NT Tyres
08/01/2022	3510	JN#3167 - Completed 500hr service. Changed eng oil & filters, fuel filters & air filters.			SS
08/09/2022		JN#3170 - Fault, blown drive tyre. Travelled to Jenkins Rd & removed/ replaced blown tyre.			TG
10/14/2022		JN#3117 - Re-sealed front right hub.			SS
01/23/2023		Replaced Jack			TG
07/02/2023	3630	Replaced top mine spec lights and repair clearance lights			SS
11/04/2023		Buy/attach vac hose to suck out Leachate pond water under liner			TG
21/03/2023		Strip & fit 2 x Equal Flexx Tyres as per att NTT Inv 84962			NTT
06/05/2023	3733	Replaced batteries with genuine Isuzu batteries from CJD refer att nv 2640131			CJD
09/13/2023	3763	250 hr service - oil & filter change			Workshop
25-Jan	3833	Replace wiper blades			Workshop
04/08/2024		Airleaks to drivers seat, replaced leading valves ref to ISRI Inv 10183 att			ISRI
05/22/2024		Truck losing air from seat air leaks, Graham from ISRI seats replaced air valve & air lines under seat, Indicator recorded in OBS-654 INS-1388, Call CJD regarding availability of transmission panel (waiting for reply) CJD cant supply transmission panel, contacted Maddi at Penski & she identified panel cover & ordered correct parts from Sydnev.			
10/16/2024		Repair cracked vacuum pump control position plate, inspect suction hoses, change engine oil & filters			Workshop
10/31/2024		Replace 3 clearance light LH side and RH side, fit 2 brake boosters rear left and front right bogie			Workshop
04/05/2025	4027	1000 hr service - change oil, change oil, air and fuel filters, claen A/C, grease, adjust brrakes.			Workshop
02/05/2025		Needs new top boom suction hose, removed turrett found leaks coming from around the slew - Cleaned gaskets from turret assy, tank & plates, replaced top turret hose & boom ext pvc pipe, cleaned filter boxes, welded new plates on LH side to accommodate clamp to hold new suction box back to the blower. Fit new gate valve 4" to rear LH side of tank			Serg



Plant & Vehicle Maintenance & Repairs

Asset Number: C0283

Registration Number: CC07SR

Serial Number: JALFVZ34SE7000270

Make: Isuzu

Model: Vacuum Truck

Year of Manufacture: 2015