

Plant & Vehicle Maintenance & Repairs

Asset Number: CO271		Registration Number: CB76IT	Serial Number: JAANPR75HE7105487
Make: Isuzu		Model: NPR300 Tray Truck	Year of Manufacture: 2015
Date	Hr/Kms	Work Conducted	Responsible Person
10/16/2015		Repair wiring for flashing light.	TG
09/26/2016		2 x HS70L batteries	GC
09/27/2016	11938	Fit 2 new batteries	GC
10/24/2016	12150	15,000 km service. Airpower. Pick up.	TG/GC
10/24/2016		Refer to Airpower Invoice DUCS55231	Airpower
07/03/2017	17105	Clean out a/c, fit screws in bottom of dash	MM
07/13/2017		Done - windscreen cracked	TG
08/12/2017	19720	Make new left hand rear mudguard brackets. Remove broken ones and fit new ones	GC
09/11/2017	20796	Adjust a/c belt, repair beacon wiring	SS TG
09/18/2017	20953	Replace strobe light u/s	SS
01/20/2018	26755	Fit new light globe to headlight RH	SS
01/24/2018	26855	Removed a/c fan, clean, I refitted noise gone, windscreen replaced by Windscreens Territory on invoice	BO
03/14/2018	28184	10,000 km service complete	
04/20/2018	29698	Replace LHF head light	BO
05/21/2018	31919	Repaired oil leak	SS
07/11/2018	33345	Replaced mine spec light assemblies x 2	GC SS
07/17/2018	33332	Service	TH TG
04/15/2019	34297	Clean out a/c evaporator and fan motor, clean out and wash cab	SS TG
05/27/2019	42503	43000km service, change engine oil, fuel and air filters, adjust belts, wash and clean engine bay	TG
09/05/2019		Batteries replaced - 2 x NS70L	MM
01/10/2020	50207	50000km service, changed oil & filter, fuel filters, air filters, repair welsh plug on bottom of RHS, kingpin came out while greasing.	TG SS
05/07/2020	50215	Repaired LH rear drop side tray and tailgate hinge	Falcon Engineering
08/31/2020	51964	Serg ordered parts CJD. Replaced window control switch	SS
09/30/2020	53373	Replaced R/H rear tail light lens	SS
11/24/2020	54077	No earth to relay, compressor got hot. Relieved gas from A/C. Repaired relay and topped up gas	SS
01/23/2021	54395	Gassed up A/C to diagnose leaking system	SS
02/06/2021	54407	Removed dash assy to replace unit, re-gassed	SS
05/15/2021	55041	Replaced UHF radio with a second hand one from Nebo, fitted new hand piece	SS
03/25/2022	57465	fault, front left tyre leaking, replaced tyre with spare. NT tyres fit new tyre	TG
05/10/2022	57505	Replaced LH tail light rear lens	SS
08/30/2022	59747	JN#3164 - Travelled to Tiger Brennan Road, changed flat tyre & replaced with new one. Reinstalled onto spare carrier.	SS

Plant & Vehicle Maintenance & Repairs

Asset Number: CO271		Registration Number: CB76IT	Serial Number: JAANPR75HE7105487
Make: Isuzu		Model: NPR300 Tray Truck	Year of Manufacture: 2015
09/02/2022		1 x Max 205/75R17.5 Tyre, Balance & dispose, refer attached Inv 82775	NTT
31/10/2022	60907	Completed 60,000km service - changed engine oil, oil filter, fuel filter, air filter, gear box diff oil, replace beacon light & front left headlight	SS TG
31/10/2022		Job#3184 - Straighten trailer plug bracket, replace LH rear indicator lens, taillight lens, repair top lights, replace seat covers & floormats	SS TG
01/03/2023		Fitted new Tyres from steer of CO277 onto spare rack	SS TG
06/02/2023	64040	Remove blown tyre and fit spare	SS TG
06/20/2023		New Tyre INF 205/75R17.5 PR F820 refer att NTT Inv 85940	NTT
12/08/2023		Drop off to Betapave for painting	Betapave
12/15/2023		Collect from Betapave	
02/27/2024		1 x DC 205/75R17.5 Tyre, strip, fit dispose refer att Inv 89196	NTT
03/06/2024	66825	OBS377 - Wiper blades replaced	Workshop
02/24/2024	66825	OBS378 - No jack or spare wheel brace	Workshop
03/07/2024	67007	Removed tray sides & straighten, replaced bushes & re-fit. Job complete	Workshop
03/21/2024		Replaced light. See Tez diary	Workshop
04/08/2024		Fitted new two stage jack & wheel brace handle to truck, job complete, 8/4/24 @ 67741km	
04/11/2024		Completed by NT testing, 11/4/24 (fire extinguisher)	NT Testing
01/07/2025	72424	Replaced batteries and 24V joining lead.Ref att CJD Inv 1173214	CJD/Workshop
03/18/2025	73264	Replaced fan and A/C belts	
03/25/2025		LH steer tyre, remove and take to NT tyres for puncture repair, refit to truck	Workshop
04/03/2025	73668	70,000km service-changed engine oil, oil filter, fuel filters and air filters, wash and detail truck.	Workshop