

## **Plant & Vehicle Maintenance & Repairs**

Asset Number: CO260 Registration Number: CB27VB Serial Number: JAANPS75HB7101210

Make: Isuzu Model: NPR300 Tray Truck Date of Manufacture: 2012

Make:	Isuzu	Model: NPR300 Tray Truck Date of Manufacture:	2012
Date	Hr/Kms	Work Conducted	Responsible Person
01/08/2016	15774	Replace batteries.	TG
01/19/2016		Replace windscreen.	TG/GC
02/05/2016		Replace batteries.	TG/GC
04/13/2016	18320	Replace A/C fan motor.	TG/GC
06/09/2017	19699	A/C Hoist Noisy	SS
09/05/2017		Fit spare wheel to rhf	GC
10/23/2017	23582	Change LH tyre on steer	MM
02/07/2018		Replace wiper blades	GC
02/08/2018		Arnos invoice 166708 - New 8.5R17.5 tyre	Arnos
02/13/2018		Arnos invoice 166783 - New 8.5R17.5 tyre	Arnos
03/05/2018		Replace globe LH headlight	MM
03/10/2018	30562	Inspect front diff, steering and hubs, all OK	
03/12/2018	30579	10,000km service complete	
03/27/2018	30870	Replaced RHR inner drive tyre. Arno's invoice 167632 for 8.5R17.5 tyre.	
03/29/2018		Fit new wheel to RHRand remove wheel to spare	GC
06/13/2019	36106	6 monthly service completed, fit 2 new integrity 85R 17.5 F820 steer tyres	TG
07/10/2019	36269	Fit four new driver tyres	TG
05/14/2020	37825	Remove and replace batteries. Refer NT Tyre Invoice attached # 69253	NTT
11/30/2021	39093	Replaced noisey AC belt	TG
12/15/2021	39231	Replaced wiper blades	TG
04/20/2022	40170	40000km service, CV joints OK	TG
05/06/2022		Brakes were travelling to floor, removed all drums and cleared out brakes replaced. Rear wheel cylinders & adjusted and	SS/TG/GC
10/31/2022		Strip & Fit Windscreen - refer WT Inv 792 att	WT
12/19/2022	42174	Replaced E-stop	SS
05/22/2023		Start to dissasemble front hubs	TG, SS
05/23/2023		Re-fit all wheels, take off jack stands, weld up water tank holes for painting	TG, SS
	42932	Assemble front hub bearings, wiper seals and boots, adjust king pin bearings, 31/5- finish reassemble front	
05/31/2023	42932	hubs, CVs and free wheeling hubs, adjust and bleed brakes, refit steering linkages, refill front diff oil	TG, SS
11/09/2023		Fixed headlight	Workshop

02/22/2024	43843	15.2.24 - prep for painting, remove toolboxes, needle gun tray, found rust holes, cut out section, prep to replace floor section.16.2.24 - SS & GA grinded out sect of floor, cut new piece of plate & welded into tray, paint tray with rust converter, prep ready for painting 19.2.24 dropped off to Andrew for painting, Serg grinded down welds on trap in prep for painting all completed 22.2.24 & dropped back to Nebo Rd	Betapave/SS
03/04/2024	43843	Tray sides fixed and re fitted.	Falcon/workshop
03/07/2024		Remove wheels, paint brake drums & hubs, wash & paint wheels, re-fit wheels.	Workshop
07/04/2024		Jump start and charge overnight.	Serg
07/09/2024		Replace 2 x Century NS70L MF Batteries refer att Inv 90926 NTT	NTT
04/16/2025	46267	Replaced speedo cluster used to test CO281	Workshop
04/06/2025		Unlocked brakes & re adjusted, removed rear drum waste, recharged battery tested OK	Serg
04/23/2025		Adj rear brakes on rear of crew cab, refit rubber grommets to back of backing plates	Serg
04/28/2025		Test drove & re- adjusted brakes tested all good	Serg