

Plant & Vehicle Maintenance & Repairs

Asset Number: CO226		Registration Number: CD28ZY	Serial Number: JALFVZ34PG7000831
Make: Isuzu		Model: FVZ 260-300	Year of Manufacture: 2018
Date	Hr / Kms	Work Conducted	Responsible Person
08/10/2018		MVR Rego, compliance check for 2 new tippers	TG SS
09/04/2018	28	Check PTO noise, all OK. Check tail gate swing operation, needs modifying	TG
09/26/2018	65	Repair tarp cover cables	TG SS
05/29/2019	233	250hr service, fit new rear mud flaps	TG SS
03/13/2020	393	Replaced mud flaps and support brackets	TG SS
03/25/2020	400/4763	Check brake air system fault, faulty ABS valve, replaced valve, test. OK.	TG SS
07/29/2020	4264	Checked camera. All ok.	SS
09/01/2020	6046	Fit new bracket	SS
09/12/2020		Reconnect cut wiring on IVMS and disconnect fuse ready for switching	SS
10/07/2020	524	500 hr service done at Nebo (all filters and grease)	SS
11/24/2020	6698 km	Repaired Broken air fitting on RH rear brake booster	SS
12/15/2021	6753 km	Replaced camera at rear of truck	SS
01/15/2021	685 hrs	Tightened screws on fuel tank sender unit on tank	SS
03/16/2021	783	250 hr service complete, oil and filter change, blow out air filter, grease truck	SS
04/09/2021		Fit new tipper valve (had crack on inlet port valve)	SS
04/16/2021	811	Inspect spool travel and ports for blockages, found all okay	TG
		27/5 - replaced tipper valve on body truck	SS
07/27/2021	1021	Repaired broken body on LH rear clearance light	SS
08/25/2021	1085	1000 hr service -changed eng and diff oils, trans oil and filters	TG
11/08/2021	1283	250 hr service done. Changed engine oil and filter	TG
02/10/2022	1445	Replaced RH headlight globe	TG
02/20/2022		Engine light was coming on. Deleted with scan tool.	SS
04/13/2022	1630	250hr service , engine oil & oil filler replaced with new fuel filters x 2. New air filter	SS
05/09/2022	1657	Fit new tipper control in cab	SS
05/20/2022	1720	Replaced rear mud flaps	RG

Plant & Vehicle Maintenance & Repairs

Asset Number: CO226		Registration Number: CD28ZY	Serial Number: JALFVZ34PG7000831
Make: Isuzu		Model: FVZ 260-300	Year of Manufacture: 2018
06/24/2022	1862	JN#3075 - Repair/replace front H/L right hand H4 Globes, replaced headlight fuse 10A	SS
07/02/2022	1895	JN#3095 - Replaced tipper valve & replaced with one ordered when the problem 1st occurred in the past	SS
07/02/2022	1902	JN#3096 - Changed over tipper valve with another valve off parts shelf	SS
07/16/2022	1920	JN#3076 - Replaced RH rear taillight assy, brake light was not functional	SS
09/06/2022	2029	JN#3123 - Completed 2000hrs service, changed eng oil & fuel filters, air filters, trans oil	SS
10/11/2022		JN#3098 - Replaced wiper blades.	SS
09/27/2022	2093	JN#3142 - Replaced headlight globe	SS
27/09/2022	2093	JN#3181 - Repair fire extinguisher bracket	SS
10/24/2022	2129	JN#3099 - Replaced tipper valve with re-sealed valve.	SS
10/24/2022	2129	JN#3168 - RH Hub Seal Replaced. Replaced tarp slides.	SS
12/12/2022	2249	Replaced ABS relay valve (wasn't building up air)	SS
02/01/2023		Replace 2 x 19.5UP Tyres refer att NTT Inv 84467	NTT
02/09/2023	2416	Refitted new retractable tarp motor to replace broken motor. Tyre has also been replaced	TG, SS, Glen
23/02/2023		Replaced 5 Watt, 80 Channell UHF radio & sound path speaker mic	SS
02/23/2023	2438	Completed 500 hr service. Changed engine oil and filters, changed fuel filters	
03/20/2023	2475	JN#3350 - Replaced rear left brake boost on drives	
05/03/2023	2530	Removed and replace O ring on primary fuel filter	TG
05/18/2023		Replace 8 x drive tyres RBL1 11R-22.5s	
06/06/2023	2554	Changed out front RH steer tyre with CO214 spare until new steer tyres arrive	SS
06/13/2023		Tyres arrived from NT tyres.	NT Tyres
06/19/2023		Drop off to NT Tyres for new steer tyres	NT Tyres
06/20/2023		Collect 2 new steer, 4 new 11R-22.5 trailer tyres and 2 puncture repairs	NT Tyres
10/17/2023	2697	Full grease over	Workshop
12/07/2023	2740	Remove tarp winder cables and replace cables, set up tarp and adjust cables, test operation. All ok	Workshop
12/18/2023	2745	Drop to NT Tyre service	NT Tyres

Plant & Vehicle Maintenance & Repairs

Asset Number: CO226		Registration Number: CD28ZY	Serial Number: JALFVZ34PG7000831
Make: Isuzu		Model: FVZ 260-300	Year of Manufacture: 2018
12/08/2023		Repair Drivers seat - valve height adjustment - refer att Inv ISRI 9880	ISRI
01/09/2024	2750	250 hours service, changed engine oil and filter, order parts for leaking front hubs	Workshop
01/10/2024	2750	Remove RH front wheel, wash down and clean, re-assemble with new hub cap, re-fill with new oil, 85/140 drain and replace LH hub cap and re-fill new oil	Workshop
03/08/2024	2835	Changed 8x tarp sliders, re-fitter rails onto bin, adjusted cables & tested ok.	Workshop
04/18/2024	2914	Inspected air leak & found split air line to PTO, replaced air line	Workshop
06/18/2024	2995	OBS-1468 Found batteries low charge, Jump start, found batteries not holding charge, replaced batteries	
07/01/2024	3011	Serg notified of air leak on tipper, found split air line on LH side of chassis, fit 6mm airline joiner and fixed issue with tailgate and tipping problem	Workshop
07/17/2024	3024	1000hr service at Cox - changed engine oil, oil filter, blew out all filters, greased truck	Serg
07/31/2024	3028	Notified at truck of air leak, found fitting snapped at booster on front L/H wheel, removed booster 24/30, fixed with new booster.	Serg
08/29/2024	3056	Replaced LH headlight globe.	Workshop
01/14/2025	3129	Paint truck at Betapave (paints provided by EAC). refer att Inv 2404 AB	Betapave
01/22/2025	3155	Replaced wheels on tipper after chassis and wheel paint	Workshop
02/11/2025	?	Started replace PTO airlines to cab that have been heat affected.	Workshop
02/13/2025		Remove battery isolator plate for painting	Workshop