

## **Plant & Vehicle Maintenance & Repairs**

Asset Number: CO229 Registration Number: CE12ET Serial Number: JALCXZ52LJ7000123

Make: IsuzuModel: CXZ GigaYear of Manufacture: 2020

Date	Hr / Kms	Work Conducted	<b>Responsible Person</b>
08/17/2020	57	Certificate of Modification	Queensland
09/04/2020	3623km	CJD pre delivery inspection	CJD
09/08/2020	3735km	Premobilisation paperwork, hook up side tipper and test operations. Check tare weight of truck with trailer. Can carry 13.3t on triazle and 9.35 on drive axles (total 22.65t)	TG
09/14/2020		Fit aftermarket hour meter. CO229/231 weights steer 5T drives 71.15t triaxle 6.7t	TG
09/19/2020	37 hrs	Disassemble pogo stick and inspect, found broken plastic bush inside. Warranty at 5000km service.	TG
09/19/2020	37 hrs	Travel to Aldebaran Quarry, found quick coupler had come disconnected, bleed off pressure and reconnect. OK.	TG
09/21/2020	37 hrs	Weekly inspection - check fluid levels, grease and adjust brakes	
09/29/2020	5000km	5000km service completed by CJD. Also changed gearbox and diff oils	CJD
10/28/2020	267 hrs	250 hr service, change oil, filters, adjust A/C and fan belts.	TG
12/07/2020	520	500 hr service completed.	TG
03/12/2021	802	250 HR SERVICE. Replace engine oil and filters	TG
04/02/2021	1010	1000hr service, engine oil, filters, fuel filters, air cleans	TG
04/09/2021	1010	Re-seal supply hose at tipper control valve	TG
06/19/2021	36000km	Replaced Front L/H headlight globe and 10A fuse	SS
07/15/2021	1278	250 hr service. Also rotate drive tyres	TG
08/30/2021	41,847km	Check tipper operation, changed wet lines at trailer	TG
09/28/2021	45,846km	Complete 500 hrs Service, change engine oil & filters	TG
11/17/2021	1725	Remove and replace fuel cap, refill 85-140 oil	TG
11/17/2021	1725	Replace screws with loctite to fix Missing bolts from air switch console	TG
02/23/2022		Fit Own Tyre ref att NT Tyre Inv 80119	NTT
02/25/2022	1870	Completed 250hr Service changed engine oil & filters, Cadilac carried out a wheel alignment refer to Inv #9093	TG/Cadillac

03/10/2022	53171	NT tyres fitted 2 x 295-80 R22.5 steer tyres. Cadilac/transport did wheel allignment.Refer att	NTT	
02/28/2022	n/a	Side tipper clearance lights faulting. Repair wiring to clearance lights	TG	
10/11/2022		JN#3115 - Replaced globe.	SS	
01/18/2023	2117	Took to Kaefers to weld up brace in bullbar	GA	
02/22/2023	2234	Completed 1000 hr service, changed engine oil and filters, fuel filters, changed gear box and diff oils	TG, SS	
02/23/2023	2234	Fit oil spill diversion for wet line connectors	CJD	
03/01/2023	2234	Cut out damaged section of rear chassis cross member, fabricate, fit & weld in new piece	TG	
05/24/2023	2250	Completed 250 hr service, changed oil and filters	TG, SS	
05/26/2023	2351	Replaced fuse as indicators werent working	SS	
07/10/2023	2390	Removed 1 drive tyre, drop to NT Tyres for puncture repair	workshop	
07/25/2023		Detail clean	Glen	
01/11/2024	2448	Cut out section from rear chassis rail and press, beat straight and flat, disconnect ba	t workshop	
01/30/2024	2455	Jump and charge batteries.	workshop	
03/06/2024	2511	Pick up from nt tyres & re-fit to truck (puncture repair)	workshop	
03/08/2024	2511	Remove & inspect park light globes, found bulbs blown, replaced bulbs, refitted & te	s workshop	
03/07/2024	2503	500 hrs service, changed engine oil & fuel filters, changed PCV filter, blow out air filter, greased, pumped up left rear inside tyre.	workshop	
03/18/2024		Replaced airline blower and line assembly	workshop	
05/23/2024	2668	NT Tyres replaced 8x drive tyres, @ 71572kms Ref Att Inv 90326 NTT	NT Tyres	
08/06/2024	2786	250 hr service, changed engine oil and filter, blow out air filters, grease, adjust fan a	nd a/c belts.	
08/16/2024	2804	Repair air leak into trailer air supply	workshop	
03/10/2025		Tested CO229's soleroid plugs for CO228, compatable.	workshop	
03/12/2025	3000	Replaced 3 x wiper blades, replaced driver rear seat cover, replaced hour meter	workshop	
03/12/2025	3141	Note - hour meter gone back to 0. need to add current hours of 3141 to ea Fi		
03/13/2025	3141	3000 hr service - changed engine oil and filter, replaced air filters, replaced fumes disworkshop		
05/19/2025	3169	Replace 2 Way Radio handpiece cable	SS	