

Plant & Vehicle Maintenance & Repairs

Asset Number:CO091Registration Number:TR1515Serial Number:6T9T25NTOPANUM040<a href="mailto:weight] <a href="mailto:weight] <a href="mailto:weight] <a href="mailto:weight]Model:Side Tipper - Vin:6T9T25NTOPANUM40Year of Manufacture:2023

Make: Tristar		Model: Side Tipper - Vin: 6T9T25NTOPANUM40 Year of Manufacture:	2023
Date	Hr / Kms	Work Conducted	Responsible Person
8/06/2023		Rego'ed	LC
06/15/2023	n/a	Tristar fitted compliance plates and number plates on side tippers and dollys	Tristar
06/22/2023	n/a	Fit skid plates, connections with straps and wear protection	TG, SS
08/24/2023	n/a	Repair air leaks at air bags, re-tension air tank mount bolts	Workshop
10/10/2023		Repair stay and bracket (new from Tristar). Paint stay, straighten bracket on chassis	Workshop
20/03/2025	n/a	Re-align and lighten tank mounts	Workshop
03/20/2025	n/a	Greased all tarps, re-tension toolbox latches	Workshop
27/03/2025	n/a	Straighten out tarp rods, replace non slip tape on tarp rollers	Workshop
28/03/2025	n/a	Glue on patches to all small holes	Workshop
31/03/2025	n/a	Weld roll over tarp end stoppers on to door side of rails to stop tarps falling off when tipping with tarp covers closed to tip off water	Workshop