



Plant & Vehicle Maintenance & Repairs

Asset Number: C0262		Registration Number: 09357C		Serial Number: CATOCW34CJ3H00129	
Make: Caterpillar		Model: CW34 Roller Multi Tyre		Date of Manufacture: 2013	
Date	Hr	Work Conducted		Responsible Person	
05/12/2016		Repair for warranty. Refer to Hasting Deering Invoice AS300037963		Hastings	
05/25/2016		Hastings. A/C fault. Refer to Hastings Deering Invoice AS300037948		TG/GC	
07/28/2016	1065	Inspect lock for swivel seat. Faulty linkage, lock seat in forward position.		TG/GC	
08/02/2016	1068	Replace clevis pin and circlip for seat rotation lock.		TG/GC	
08/24/2016	1086	Fit new R/H/R mirror.		GC	
08/25/2016	1089	Fit new air filters		GC	
08/25/2016		Refer to Hastings Deering Invoice 2010024427		Hastings	
10/05/2016	1149	Check water leaking into cabin, clean out A/C filters. Inspect A/C drain system.		TG/GC	
02/08/2017	1168	Replace seal on roof air conditioner lid. Clear air con. Drain tubes. Inspect roof area for water entering cab.		TG/GC	
02/09/2017	1168	Replace fuel cap breather. Remove seat and broken swivel cable.		TG/GC	
02/14/2017		1 x Rust Coat paint & 1 x Water Repelant - refer Repco Inv 3810761939		TG	
02/16/2017		1 x High Performance Battery 4WD 720CCA - refer Repco Inv 4150297677		TG	
03/28/2017	1174	Remove & replace purge valve, disconnect purge valve solenoid wiring		TG	
12/18/2017	1253	Change out tire inflation components front left, inspect charge fault, removed and replaced batteries		TG BO	
12/27/2017	1254	250hr service complete, oil sample taken, parts collected from Hastings		BO	
01/04/2018	1254	Changed R/H rear light globe		MM	
01/05/2018	1254	Fitted LH front wheel inflator fitted		BO	
03/07/2018	1323	Sealed up drain pipes and blown (??)		BO MM	
03/09/2018		Multi roller tyre issue front left inner			
03/28/2018	1345	Replace left front center wheel air fittings		BO	
05/21/2018	1356	Replaced leaking tyre valves		SS	
06/28/2018	1361	Replace tyre inflation swivel (??)		TH	
02/11/2019	1406	Remove type for repair, deliver to Arnos, refit to machine at site		SS TG	
07/25/2019	1414	Inspect a/c system, top up gas and charge with fluorescent dye, test OK		SS TG	
09/23/2019	1422	Wash and clean, remove top a/c access panel. Replace AC drain hoses, replace GPS tracker aerial and base. Replace AC filters, re fit access panel and seal. Test AC, OK		TG SS	
11/13/2019	1424	Replace air swivel on front RH wheel, check air supply line, check for leaks tested Ok		TG	
02/21/2020	1448	Fixed faulty UHF radio		TG	
05/19/2020	1495	500 hr service, change engine oil and fuel filters, change air filters		TG SS	
05/29/2020	1499	Hydraulic oil sample report. Result B		HD	
05/29/2020	1499	Primary oil sample report. Result A		HD	



Plant & Vehicle Maintenance & Repairs

Asset Number: C0262		Registration Number: 09357C		Serial Number: CATOCW34CJ3H00129	
Make: Caterpillar		Model: CW34 Roller Multi Tyre		Date of Manufacture: 2013	
06/25/2020	1517	Replace hose between axle swivel and tyre valve			TG
07/01/2020	1517	Replace 2 x tyre inflation hoses			TG
02/23/2021	1568	Check aircon fault. Low gas. Done.			TG SS
02/23/2021	1568	Remove LH front tyre, NT tyres fit new. Refit wheel.			TG SS NT Tyres
03/15/2021		Refit gas strut to door			TG
03/29/2021		Fitted new batteries to roller			TG
06/01/2021		Replace Tyre Strip/fit Grader/OTR/AGRI refer att NT Tyre Inv 76309			NT Tyre
26/10/2021	1631	Remove & replace water drain plug with poly plug			TG
10/19/2021		Strip & fit Grader/Otr Tyre refer NT Tyres Inv 78330			NTT
10/29/2021	1631	Replace 1 x swivel, inside RH front, replace 3 x front tyres, made up spacers, weld in place to stop tyres rubbing, replace leaking valve at air compressor			TG
06/29/2023	1670	A/C gas (600g)			SS
07/05/2023	1670	Remove flat L/H front tyre, drop off for repairs at NT tyres refer Inv below 86200			SS
07/07/2023		JN#3410 - Pump up LH front tyre, remove auto tyre inflators and blank off at axles			
07/13/2023		Top up engine oil			SS
08/17/2023		Jordan installed radio			
08/23/2023	1735	Cleaned aircon filters out			Workshop
09/20/2023	1753	NT Tyres for 2 new tyres refer NTT att Inv 87336			NT Tyre
09/20/2023	1753	Completed 250hr service (oil/filters)			Workshop
09/25/2023	1753	Swap over two LH rear tyres with two front LH tyres. Removed steering cylinder as its leaking and ordered new seal kit. Waiting for seal kit to put wheels back on			Workshop
09/25/2023	1753	Air con repairs to machine. Found 2 leaks at condensor, de-gassed A/C system and fitted new condensor, Dryer and hose. Vac down system and changed A/C system with 2.1 kg of R134a			Workshop
09/26/2023	1753	Remove scrapers from underside of roller and block water lines to stop debris entering system. Remove steering cylinder as found to be leaking.			Workshop
09/29/2023	1753	Rebuilt steering cylinder. New chrome rod by Hosepower - refer att inv 73344			Hosepower
10/16/2023	1753	Hastings warranty repair on grab handle			Hastings
11/01/2023	1753	Remove covers and steering strutt, remove actuator handle, refit onto new strutt, refit strutt and replace guards, tested. OK.			
01/23/2024		Re-seal around bottom panel of A/C evap cover on roof with Storm silicon, replace hood lining			Workshop
04/24/2024		Replace 2 x 30/18-20 Multi Tyres, strip, fit & dispose Ref Inv NTT Inv 89963			NTT
05/22/2024	1809	Replaced bulb & taillight lens, Job complete, @ 1809hrs.			

