

## Plant & Vehicle Maintenance & Repairs

<b>Asset Number:</b> CO280		<b>Registration Number:</b> CC10AO	<b>Serial Number:</b> JTFST22P100020898
<b>Make:</b> Toyota		<b>Model:</b> Hiace Bus	<b>Year of Manufacture:</b> 2014
Date	Hr / Kms	Work Conducted	Responsible Person
01/14/2016		Refer to Airpower Invoice APCS53061	Airpower
01/19/2016		Replace windscreen.	TG/GC
02/22/2016		Refer to Airpower Invoice APCS53499	Airpower
06/09/2016	36795	Replace windscreen	TG/GC
06/22/2016	3774	Check steering fault. Check tyre pressure. Faulty rear tyre.	
		Arno's Tyres fit 2 new tyres to rear wheels and rotate to front. Refer to Arno's Tyre Service Invoice 153107	TG/GC
07/04/2016	38675	Identify IVMS tracker IMEI # 352648062023205	TG
08/09/2016	41194	Arno's Tyres. Fit new rear tyres. Balance all wheels and wheel align. Refer to Arno's Tyre Service Invoice 154331	TG
08/15/2016	41748	Repair flashing light mouting.	TG/GC
01/23/2017	47800	Repair wiring at flashing beacon.	TG/GC
01/30/2017	48027	Replace flag pole assembly	TG
08/10/2017	61084	60000 km service, replace engine oil, oil filter, air con, cab filter, air filter	GC
08/18/2017		Clean out a/c	SS JL
09/04/2017		Remove front wheels, have new tyres fitted and refit. Spare fit under chassis	GC
09/18/2017	65245	Replace rh headlight globe	GC
10/20/2017		Done - clutch has shudder	MM
12/19/2017	7254	Change lhr wheel	GC TH
01/11/2018	73823	70,000km service	SS
01/17/2018		Noisy air con fixed	TG
02/03/2018	76702	Sliding door not opening, removed door card fixed rods	BO SS
02/26/2018	79354	Tighten up door striker	MM
02/28/2018	79589	Remove and replace alternator and belt, complete 10,000km service	BO MM
03/01/2018	79690	Replace wiper blades, remove and replace fire extinguisher bracket, adjust tyre pressure, top up wiper fluid	MM
04/21/2018		Organised tyre replacement. Arnos Invoice 168178 for 4 x 195R15c tyres	BO
06/25/2018	90203	90,000 km service and replace light bar lights	GC
08/03/2018		New rear window on Windscreens Territory inv 00016000	Windscreens
09/21/2018	96525	Remove, clean and refit a/c evaporator core, fit new floor mats, replace windscreen	SS
11/26/2018	102342	100,000km service Adjust door striker plate	SS
04/01/2019		Repairs carried out to fuel gauge, fault found in tank	SS

## Plant & Vehicle Maintenance & Repairs

Asset Number: CO280		Registration Number: CC10AO	Serial Number: JTFST22P100020898
Make: Toyota		Model: Hiace Bus	Year of Manufacture: 2014
04/01/2019		Repairs carried out to sliding door, new rollers fitted	SS
04/09/2019		Rewired reverse alarm to beacon light circuit	SS
05/20/2019	111647	110,000km service, replace battery, replace engine oil, cab and air filters	TG SS
06/22/2019	114307	Tyre dropped at Arno's, then refitted	TG SS
08/28/2019	120592	120,000 km service, change engine oil and filters, fuel and air filters, change diff and gearbox oils	TG
09/03/2019		Replace front windscreen, replace front and rear wiper blades. Fit and balance new steer tyres, Cadillac Transport for wheel alignment	TG
11/20/2018	125156	Top lock cut, 2 x new keys, advise to fit new immobilizer unit. Removed dash and fit new immobilizer unit, Top Lock NT, reprogrammed unit and tested. All okay. Refit dash unit.	SS TG
08/27/2021		<a href="#">Replaced Battery N70ZZLB 12V 4x4 &amp; SUV HP 20M refer att Inv 3810920926</a>	Repco
03/17/2022	125197	Replace Battery re fit	TG
10/31/2022		<a href="#">Strip &amp; Fit Windscreen - refer WT Inv 792</a>	WT
07/12/2023		Drop to Betapave to remove reflective tape	Betapave
02/22/2024	129424	130,000 km service, change engine oil and filters, fuel and air filters, replaced LH headlight globe	Workshop
03/13/2024	131504	Changed key chip into new key & took to toplock to cut key. Job completed	Workshop
04/24/2024		Supply & fit back Windscreen - Insurance -	WT
05/17/2024		<a href="#">2 x Mich Tyres 195R15C refer att: NTT Inv 90258</a>	NTT
07/12/2024		Repair broken key	
04/02/2025		Repair broken rear LH sliding door inner trim panel. Fibreglassed broken board which was catching on body were door was being opened, fitted new trim clips	Serg