EASTARN	√ I	Plant & Vehicle Maintenance & Repairs	
Asset Number: CO2	208	Serial Number: CAT0279DCSZ900559	
Make: Caterpillar		Model: 279D Skidsteer Date of Manufacture:	2021
Date	Hr/Kms	Work Conducted	Responsible person
		ERED C0208 20/5/22	
05/16/2022 10/11/2022	4.2	Premobilisation, transported to Larrakeyah JN#3097 - New 2 way radio was fitted by comm8, organised & paid for by hastings as it did not have a radio when delivered.	Comm8
04/06/2023	283	250 hrs service, changed engine oil and filter, blew out air filter, grease	TG, SS
04/20/2023		Replaced LH rear stop tail light assembly, repair wiring	
05/18/2023		Warranty expires. Goes into extended.	
12/05/2023		See AT1 re damaged coupler	Workshop
12/13/2023	502	500 Hr service, change engine oil and filter, fuel filter, air filter, A/C filters, final drive oils changed, replaced E stop	Workshop
12/15/2023	502	Load on float and go to Suzi Ceccons	
12/21/2023		Washed down by Edgie	Steven Edge
)2/07/2024	525	Replaced flashing light beacon, with after market magnetic base beacon	Workshop
04/03/2024	538	Found reverse camera faulty, replaced camera, job completed	Workshop
7/30/2024	680	Fit new cutting edge to bucket	Serg
08/19/2024		Track came off. Re-fit track.	Workshop
1/22/2024		Float back to Nebo	Workshop
1/28/2024		Refit lifting gracket mounts and prep for Port	Workshop
1/29/2024		Deliver to Port	Workshop
12/04/2024		Unload, set up in workshop with overhead crane at Nebo	Workshop
12/06/2024	750	250 hr service, change oil and filter, wash down and hose out belly plates	Workshop
02/19/2025	787	Load onto CO235 float, in CO228 truck to take to Port	
04/04/2025		Seal up holes in roof under flashing light	Workshop