

GRAND TOTAL



2001, 5101 46 Ave
Cold Lake, AB T9M 0C8
Ph: 825.723.0201

SERVICE REPORT

0156

☐ Call Out ☒ Shop ☐ Field

CUSTOMER:	DATE: April 19
ADDRESS:	TECHNICIAN:
	W.O. #:
	UNIT #: 90-804
CONTACT NAME:	MAKE / MODEL:
PHONE:	SERIAL #:
CUSTOMER SIGNATURE:	KM: 773007
	HOURS: 15506

COMPLAINT / TASK

Service due @ 15661

K101494

DATE	HOURS	WORK COMPLETED
		CUID
		Air leak through park brake valve \$POD
		AC not working
		light on box control not turning on
		✓ Beacon lights out on both sides ✓ cleaned ✓
		✓ Fuel cap Passenger side leaking. POD
		✓ DS / PS Steer Shocks. 65159 x 2 POD
		✓ 1st drive diff leaking oil from diff housing. 12cl Diff
		✓ Air leak on 5th wheel hoses. ✓
		Hydraulic leak on inlet line @ tank
		✓ 5th wheel rubbers ✓
		✓ Set brakes
		✓ grease unit
		✓ wheel nut indicators x 60
		oil leak on engine. Clean it then run it.
		✓ Replace fire extinguisher ✓
		Shocks too Short A2L POD
		✓ Both Cab Shocks
		✓ Dust Cover axle 2 L K101494
		✓ all drive Shocks monroe 65523 x 4
		✓ all drive air bags POD
		Steering • AIL Del Cve POD Eco drain leaking Service
Job Completed	☐ Yes ☐ No	OFFICE USE ONLY
Parts Used	☐ Yes ☐ No	TOTAL LABOUR HOURS
		Parts Order #:
		TOTAL PARTS
		GRAND TOTAL



Box 1980
Cold Lake, AB
T9M 1P4

Repair Order

Date: Oct 15, 2022

Unit # <u>90-804</u>	Starting Hours:
Unit Location # <u>Bonnyville Shop</u>	Completed Hours:

Concern Description:

- 1 -Service due HIZS 15311
- 2 -Air leak HMS 764083
- 3 -Step mirror loose
- 4 -Coolant leak
- 5 -Steady bearing
- 6 -A 312 Brake pot
- 7 -PS Convent mirror
- 8 -Spring pins.

Technician: Halmelton Hene.

Clocked Hours:

Parts Required:

QTY	STK	Order	Received Date
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	
	☐	☐	

Repair Description

- 1 -Completed Service on truck with grease "5 tubes"
- 2 Found air leak on Air fitting above transmission output. installed a new fitting and Air stopped leaking.
- 3 adjusted Step mirror so it wasn't loose
- 4 replaced hose clamps and tightened loose clamp to stop leak on PS
- 5 found steady bearing blown. removed and installed a new bearing.
- 6 Replaced A-312 brake pot due to broken max. spring
- 7 Replaced PS Convent mirror due to no heated mirror.
- 8 Removed and installed Rear steer axle spring pins.

Technician:

Clocked Hours:



Box 1980
Cold Lake, AB
T9M 1P4

Repair Order
Date: Oct 12, 2022.

Unit # 90-804	Starting Hours: 15307
Unit Location # Bonnyville	Completed Hours: 15307

Concern Description:

- A3L inner tire flat - on trailer.

Technician:

Parts Required:

Clocked Hours:

QTY	STK	Order	Received Date
-----	-----	-------	---------------

Repair Description

Unit came to shop and replaced it with a used spare tire. Off unit T930. Need to send the tire out for repair.

Technician:

Clocked Hours:



Box 1980
Cold Lake, AB
T9M 1P4

Repair Order

280

Unit # 90-804	Starting Hours: 15079
Unit Location #	Completed Hours: 15079

Concern Description:

Service

Technician:

Clocked Hours:

Parts Required:

QTY	STK	Order	Received Date
-----	-----	-------	---------------

change oil & Filter.

oil Filter:

2 1/2 pails of oil

- water separator.

Repair Description

Technician:

Clocked Hours:

Concern Description:

Technician:

Clocked Hours:

Parts Required:


QTY	STK	Order	Received Date
-----	-----	-------	---------------

Repair Description

Technician:

Clocked Hours:


Supervisor (Print): <i>Wayne S. Gray</i>	Signature: 
Approved by (Print):	Signature:



CUSTOMER Amc DATE April 16 20 22
ADDRESS _____ A.F.E NO. _____
JOB LOCATION Amc Shop 62220 RR 421 P.O. NO. 90-804
JOB NO. 2022-01

WORK DESCRIPTION Inspect 90-804 Tractor
Loose Exhaust Passenger side Build new Bracket
Check out Wires and Repair Bad wires

Supervisor (Print): <i>Wayne Schrey</i>	Signature: 
Approved by (Print):	Signature:



Box 1980
Cold Lake, AB T9M 1P4
Ph: 780.573.5837
Fx: 780.639.0808

1502

WORK DESCRIPTION oil change Air Filter Change

Supervisor (Print):	Signature:
Approved by (Print): <i>Wayne S. Brown</i>	Signature: <i>[Signature]</i>