



Work Order #: 2094

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	7 Jul 2026
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work

2026 CVIP Inspection for Sale - Pulled trailer into the shop for CVIP inspection. Replaced break drums. Removed steel plate and rubber mats off the deck. Removed wheels and fenders for polishing. Replaced cracked fender bracket. Installed wheels and fenders. Torque wheels to spec.

Summary of Labour

Date	Employee	Work Type	Description	Hours
14 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
16 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	2.00
13 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	6.00
21 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
10 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	6.00
8 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
20 Jul 2026	Nathan Tyshynski	Shop Mechanic	Repairs	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	10 Jun 2026
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work
Install new rubber mating RRHS - repair broken mud flap cover. RHR tires. Grease. Put on new flags

Summary of Labour				
Date	Employee	Work Type	Description	Hours
10 Jun 2026	Nathan Tyshynski	Shop Mechanic	Repairs	7.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

Work Order #: 1988

CREATED BY	DATE
Nick Kempton	27 May 2026
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work

Replace rubber matting bracket RRHS / Service - Replace rubber matting bracket RRHS. Greased trailer.

Summary of Labour

Date	Employee	Work Type	Description	Hours
27 May 2026	Nathan Tyshynski	Shop Mechanic	Repairs	6.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

Work Order #: 1923

CREATED BY	DATE
Nick Kempton	7 Apr 2026
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work

Repair fender brackets - replace 2 broken brackets on fenders passenger side. Remove front of fender and weld up cracks. Replace broken deck

Summary of Labour

Date	Employee	Work Type	Description	Hours
8 Apr 2026	Nathan Tyshynski	Shop Mechanic	Repairs	3.00
7 Apr 2026	Nathan Tyshynski	Shop Mechanic	Repairs	8.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	11 Feb 2026
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work
2026 CVIP Inspection and repairs - Complete CVIP. Remove wheels and drums. Clean wheel hubs. Put wheels on and torque. Fix broken lights. New orange flag holder. Fix broken swing arm. Tie up air lines under trailer. Rear light box spray foam. Drill out new staple holders. Swap out deck mats. RHS bolted down. Total hours 57

Summary of Labour				
Date	Employee	Work Type	Description	Hours
11 Feb 2026	Nathan Tyshynski	Shop Mechanic	Check over repairs	8.00
12 Feb 2026	Nathan Tyshynski	Shop Mechanic	Check over repairs	8.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	10 Oct 2025
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work
Weld Crack Air Tank Brackets - fix cracked air tank mounts. Cut wires off deck netting. Grease trailer and jeep. New flags. Dust cover on jeep

Summary of Labour				
Date	Employee	Work Type	Description	Hours
10 Oct 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	18 Aug 2025
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM
0.00	0.00

Description of Work
Replace cracked air tank / Cut matting cords - Replaced busted air tank. Welded up cracked hangers. Cut matting cords.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
18 Aug 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

Work Order #: 1376

CREATED BY	DATE
Nick Kempton	13 Jun 2025
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM

Description of Work

LHS Landing Gear Repairs - repair bent landing gear. Broken taillight. Deck staple. Swap out trailer spare tire. Torque wheel nuts to 500 ft. lbs. Grease trailer

Summary of Labour

Date	Employee	Work Type	Description	Hours
13 Jun 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	7 Feb 2025
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM

Description of Work

2025 CVIP Inspection - Pulled all the wheels off and measured and inspected brakes which passed. Replaced wheel seals and used grease instead of oil. Fabricated flat bar to hold the mats down that go over the tires. Installed mats that were missing. Installed steel plates and grouser bars in front of the front axle to prevent the matting to get damaged. Installed new flagging. Cut rear d-sign brackets down so they don't catch. Torque wheels to spec.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
11 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
12 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
13 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
10 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
7 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00
8 Feb 2025	Nathan Tyshynski	Shop Mechanic	Repairs	10.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	6 Sep 2024
MAKE	MANUF. S/N
TRIDEM TRAILER	2A9LB5039RN125205
MODEL / DESCRIPTION	UNIT #
TRIDEM TRAILER	T26
SERVICE METER	KM

Description of Work
Check over / Repairs - Brought trailer into the shop for a initial re-torque of the wheels and suspension group. Replaced broken fenders due to scraper parking on them. Replaced junction box as well that was damaged from the scraper.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
6 Sep 2024	Nathan Tyshynski	Shop Mechanic	Repairs	10.00