

G14-1  
FEB

## Service Records

Unit # 19 - International  
 Service Location Yangarra Shop - 13-35


 yangarra resources ltd.

Date	Request Made	Completed Status
11/19/2024	Unit 19 not outfitted with plug in since new motor. Needs plug in	Completed
2/21/2025	Fuel gauge stopped working	Completed
2/22/2025	Rubber fender needs to be fitted.	Completed
3/1/2025	Driver side inside steer fender crack worsening; Driver side fender on 1st axle has broken support; Driver side needs middle axle splash guard/mudflap re-done; Driver side work light broke off support; Washer Wiper spouts need replace guard.	Completed
3/15/2025	Front Shock on passenger side to be replaced	Completed
4/21/2025	Driver side door latch loose.	Completed
4/24/2025	Passenger side headlight not working (Moisture in casing); Driver side hood latch not secure on mount.	Completed
5/26/2025	Front Driver side Brake Pot leaking air.	Completed
5/28/2025	Tire Need Replacement; Passenger side Rear Air leaks under cab/Hydro leaks.	Completed
6/9/2025	Hoist Cylinder leak; Rear tires low on tread; Diff lock leaks air off.	Completed
7/31/2025	Side boards need replacement; Leathers pin hole leak; Diff locks leak.	Completed
8/17/2025	Cable supports for mud splash guards wearing through; Steering Wheel re-centered; Diff locks leak air badly, Kicks intermittently; Washer pump for wipers not pumping; Overheating (Rad Blown out); Tarp Reel binding/hard to move; Crack in wooden sideboard.	Completed
8/25/2025	Drivers side window down and won't come back up.	Completed
9/10/2025	Front Shocks missing; PTO Housing leaking (Speed sensor popped out?); Splash guard/mudflap guard bracket broken (driverside); AC pulley seizing; Tailgate bolts Stripped/warped.	Completed
10/7/2025	PTO needs attention.	Completed
11/12/2025	Driver side Door jam pin loose; Fuel Gauge works 1/4 of the time; Lift Axle not working; Driver Side Tarp Rib/half moon broken off cable.	Completed

\*Service Records recorded here do not include oil changes

## SCHEDULED MAINTENANCE

WORK ORDER #  
0730#1530, 715 - 5 Avenue SW, Calgary, AB T2P 2X6  
Ph 403-262-9558 Fax 403-262-8281

DATE: Sept 10 2025 UNIT: 19 HOURS: 1620 KMS: 453185

Power Train	OK	C	NA	ACTION/ REPAIR	Safety	OK	C	NA	ACTION/ REPAIR
Engine oil	/			Changed	Fire suppression	/			
Oil filter	/			Changed	Backup alarm	/			
Crankcase breather					CVIP	/			
Air filter primary	/				Fire ext (exp)	/			
Air filter (sec)	/				First aid	/			
Fuel filter primary	/			Out of Stock	Housekeeping	/			Needs thorough under carriage wash
Fuel filter (sec)	/			in stock will change when other one comes in	Horn	/			
Coolant level	/			Topped up	Seatbelts	/			
Belts/Tensioners	(/)			AC Pulley Hanging Tensioned up	Lamps	OK	C	NA	ACTION/ REPAIR
Hoses	-				Head lights	/			
Inspect intake	/				Work lights	/			
Power steering	/				Back up lights	/			
Inspect exhaust	/				Batteries	/			
Fluid analysis	/			Oil Sample Taken	Other				
Drive Train/Suspension	OK	C	NA	ACTION/ REPAIR	Body	OK	C	NA	ACTION/ REPAIR
Transmission oil	/			Oil good	Cab filter				
Diff oil #1	/			?	Window	/			
#2	/			3	Latches				
#3	/			Levels good	Panels				
Damper case oil					Ground engaging tools				
Final drive					Cylinder/cables				
Hub oils					OTHER	OK	C	NA	ACTION/ REPAIR
Hydraulic oil	/			Topped up	Grease	/			
Leaks					Set brakes				
Swing/swivel					Drain air tanks	/			
Drive shaft/Ujoints	/				Drain sediment				
Airbags	/				Grease 5 <sup>th</sup> wheel	/			
Springs	/				PTO				Housing leaking
Pivot shafts					Tech Name		Start	End	Hours
Tires /Tracks	OK	C	NA	ACTION/ REPAIR	Danton Andersen	1700	2015	3.25	
Track tension									
Track pads/bolts									
Tire pressure	/				Notes				
Tire condition	/				3 Grease Tubes				
Tire chains	/				P55 9000 Oil Filter				
Roller/Idlers					45 L Co-op 15w40 Semi-synthetic				
Rims	/				3 Grease Nipples				
					10 L hydraulic oil				1 Washer Fluid Jug

yangarra resources ltd.

## SCHEDULED MAINTENANCE

**WORK ORDER #**  
**0995**

11530, 715 - 5 Avenue SW, Calgary, AB T2P 2X6  
Ph 403-262-9558 Fax 403-262-8281

DATE: March 15/28 UNIT: 19 HOURS: 1200 KMS: 437601