

BSB: 034 059
ACC: 155 440

Email: debtors@brisbaneisuzu.com.au

CUSTOMER COPY

Copy Invoice Only

Service Tax Invoice

Date: 04/09/2025		Invoice No: 8109703					
Reg No.	13CFT	Stock No.	i20599	Advisor	JACINTA K	Order No.	
Current Klms	489903	Body No.	B25035	Wty Start Date	28/02/2020	Wty Expiry Date	27/02/2023
Vehicle Identification Number		JALFVZ34WG7000622		Build Date	01/20	Compliance Date	01/20
Contact No. Today	0427 936 683	Contact Today	CFT LOGISTICS &	Engine Number	6HK1220030	Selling Dealer	0720
Driver Name		Driver Phone		Driver Email Address		Radio/DVD Code	
CCard No.	21745	Home No.		Vehicle Description		Body Type	CHASSIS
Mobile No.	0427 936 683	Work No.		Model	FVY 240-300 LWB	Colour	ARC WHITE
Email Address	admin@cftlogistics.com.au	Booked	02/09/2025 04:30PM	Required	04/09/2025 11:15PM	Sale Klms	252
				Ext Wty Exp Date	27/02/2025	Ext Wty Exp KM	350,000

#/TYP JOB DESCRIPTION

1 / R CARRY OUT 480,000KM SERVICE AS PER SCHEDULE (480K)

CARRIED OUT 480,000KM SERVICE AS PER ISUZU SPECIFICATIONS. REMOVED AND REPLACED WORN WIPER INSERTS AS REQUIRED. FOUND RIGHT HAND SIDE HEAD LIGHT BULB BLOWN, REPLACED AS REQUIRED. FOUND BLOWN RIGHT SIDE TAIL LIGHT GLOBE, REPLACED AS REQUIRED. FOUND LED NUMBER PLATE LIGHT INOPERATIVE, REQUIRES WIRING REPAIRS. CARRIED OUT VALVE CLEARANCES AS REQUIRED. CARRIED OUT FRONT AND REAR WHEEL BEARING REPACK AS REQUIRED. CARRIED OUT SERVICE WASH AND ROAD TESTED. OPERATION ALL OKAY.

Labour 2328.30
CARRY OUT 480,000KM SERVICE AS PER SCHEDULE (480K)

Parts	
1 x (TP) ELEMENT; OIL FI (IG*8943910494)	74.95
1 x (TP) FILTER; FUEL,2 MICRON (IG*92956471)	24.70
1 x (TP) ELEMENT; FUEL FILTER (IG*8980924811)	124.56
1 x (TP) GASKET; PLUG,OIL DRAIN (IG*1096230570)	4.95
1 x (TP) GASKET; HD TO COVER (IG*8943913791)	68.78
1 x (TP) B'FLUID DOT 4 500ML (NN*92956076A)	9.59
1 x (TP) ISUZU CAB TILT (ISO68 ZAF)-1L (IG*92956078)	13.95
1 x (TP) REPAIR KIT; AIR (IG*8982263280)	369.76
1 x (TP) HOSE; RUBBER-SENSOR (IG*8980889400)	31.10
1 x (TP) HOSE; RUBBER-SENSOR (IG*8980889410)	31.10
1 x (TP) ELEMENT KIT; PCV (IG*8976063182)	35.58
1 x (TP) BRAKE CLEANER 840ML (NN*68098)	12.69
3 x (TP) WIPER INSERT 6MM X 600 (NN*0848070601)	15.66
1 x (TP) FILTER; ACL-INNER (IG*92956400)	39.99
1 x (TP) FILTER; ACL-OUTER (IG*92956398)	72.78
1 x (TP) HOSE CLAMP 6-16MM (NN*MH004P)	2.80
1 x (TP) 24V 21/5W BULB DUAL (NN*17925)	2.20
1 x (TP) 8-28V LED LIC .5 CABLE (NN*91674)	38.63
1 x (TP) 24V75/70W H4 HL GLOBE (NN*48892)	21.89

Sundry	
1.00 x ENVIRONMENTAL LEVY (EW)	45.00
1.00 x WORKSHOP SUPPLIES (WSI)	60.00
19.50 x VECTON 15W40 (NGEN)	228.74
13.33 x LSX 85W140 (85W140)	193.15

Amount (ex GST) **\$3850.85**

2 / R OUTPUT PINION SEAL

DURING INSPECTION FOUND OUTPUT PINION SEAL ON FIRST DRIVE DIFF TO BE LEAKING. REMOVED YOKE ON FIRST DIFF, CARRIED OUT REPLACEMENT OF SLINGER AND PINION SEAL AS REQUIRED. REINSTALLED

#/TYP	JOB DESCRIPTION	
	YOKE AS REQUIRED. CARRIED OUUT ROAD TEST AND TESTED OPERATION, NO LEAKS FOUND, ALL OKAY.	
	Labour	597.00
	OUTPUT PINION SEAL	
	Parts	
	1 x (TP) SEAL MLS (IG*A11205Y2729)	122.85
	1 x (TP) KIT PINION NUT 160 (IG*KIT2637)	39.62
		Amount (ex GST) \$759.47

3/r	GEARBOX TOP HAT	
	DURING SERVICE INSPECTION FOUND GEARBOX TOP HAT TO BE LEAKING. CARRIED OUT REMOVAL OF TOP HAT SEAL AND CARRIED OUT CLEAN AS REQUIRED. CARRIED OUT REPLACEMENT OF GEARBOX TOP HAT WITH NEW. TESTED OPERATION, ALL OKAY.	
	Labour	796.00
	GEARBOX TOP HAT	
	Parts	
	1 x (TP) GASKET (IG*132430701301)	20.99
	1 x (TP) BRAKE CLEANER 840ML (NN*68098)	12.69
	1 x (TP) LIQUID GASKET; 150G (IG*M40509)	35.02
		Amount (ex GST) \$864.70

Total Costs	
Total Invoice (excluding GST)	\$5475.02
Total Goods And Services Tax	\$547.50
Total Invoice (including GST)	\$6022.52

Payment Details

SubAcct	Ref No.	Date	Detail	Amount Due
21745	8109703	04/09/2025	CHARGE DEBTOR	6022.52

Next Service Details

Your NEXT SERVICE is due at 520696 Klms or on 27/10/2026, whichever comes first.
Please call our Service Dept on 33854311 when you wish to make a booking.

"N" DENOTES ANY NON-GENUINE PARTS, ACCESSORIES, PRODUCTS OR ADDITIVES SUPPLIED THAT ARE NOT APPROVED BY THE VEHICLE'S MANUFACTURER. AS SUCH THEY ARE NOT COVERED BY THE MANUFACTURER'S WARRANTIES. ADDITIONALLY, THE USE OF THESE PRODUCTS MAY IMPACT ON THE PERFORMANCE, SPECIFICATIONS OR QUALITY OF THE VEHICLE AND THE WARRANTY ATTACHED TO THE VEHICLE.

Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods. Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled: * to cancel your service contract with us; and *to a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service.

****BRISBANE ISUZU GUARANTEE - GENERAL WORKMANSHIP 6 MONTHS / 10,000 KLM. DEALER FITTED GENUINE ISUZU PARTS CARRY EXTENDED WARRANTY 36 MONTHS UNLIMITED KLM ****

ARC Lic AU00027. Inspection Station 7731

THANK YOU FOR HAVING YOUR TRUCK SERVICED AT BRISBANE ISUZU BURPENGARY
SERVICE HOURS: MONDAY TO FRIDAY 6.00AM TO MIDNIGHT AND SATURDAY BY APPOINTMENT

Administration
PO Box 1141
Archerfield, QLD 4108
A/C Receivable: 07 3632 0524
A/C Payable: 07 3632 0523

Archerfield
1121 Beaudesert Road
Archerfield QLD 4108
P: 07 3373 2400

Burpengary
Eastern Service Road
Burpengary QLD 4505
P: 07 3385 4300

Eagle Farm
208 Fison Avenue West
Eagle Farm QLD 4009
P: 07 3866 2200

Stapylton
183 Burnside Road
Stapylton QLD 4207
P: 07 3382 4600