

CERTIFICATE OF INSPECTION
FOR VEHICLES UNDER 4,500 KG

J.W. Zacharias Physical Damage
Research Centre
1981 Plessis Road
Box 45064
Winnipeg, R3C 5C7

Manitoba 03988940

Date Inspection Started: 24 04 25
Date Inspection Completed: 30 04 25
Inspection Expiry Date: 30 04 26

Inspection Result:
[X] Pass/Safe Vehicle
[X] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

TYPE OF VEHICLE: [X] Passenger Vehicle
Station Number: A5750
Mechanic Number: M9689
Vehicle Owner: Jeff Winter
Address: 50142 Mun 41 E Ste Genevieve, MB
Licence Number: 2C4R D G B G 3 G R / 53762
Odometer Reading: 298266

Mark the "R" box with a "X" when an item is rejected, "XX" if Hazardous. Mark the "P" box with an "X" when corrected or no defects found in the section.

Table with 3 columns: No., Item, Ref #. Rows include Vehicle Identification Number, Neutral Safety Switch, Accelerator Pedal, Sun Visors, Horn Operation, Mirrors, Windshield Wipers & Washers, Defroster, Speedometer, Odometer, Windshield and Windows, Switches, Clutch and Brake Pedal Pad, Parking Brake, Transmission, Power Brake Operation, Brake Failure Indicators, Brake Pedal Reserve, Steering Lash and Travel, Clutch Disengagement, Handlebars, Anti-lock Brake Indicator, Stability Control Indicator, Lamps, Seats and Restraint Systems, Supplemental Restraint Systems.

Table with 3 columns: No., Item, Ref #. Rows include Headlamp Operation, Driving Lamps, Fog Lamps/Auxiliary Lamps.

Table with 3 columns: No., Item, Ref #. Rows include Headlamp/Aux Lamp Aim, Turn Signal Lamps, Park, ID & Ctr Lamps, Side Marker Lamps, Reflex Reflectors, Back Up Lamps/Lic Plate Lamp, Tail Lamps, Stop Lamps, Hazard Lamps, Day Time Running Lamps, Body & Bumpers, Trunk, Doors and Door Latches, Kickstand.

Table with 3 columns: No., Item, Ref #. Rows include Flooring, Kingpins, Tires, Wheels & Clearance, Ball Joints, Steering Linkage, Steering Column Coupler, Frame & Unibody, Spring and Attachments, Shock Absorbers, Brake Lines & Hoses, Wheel Bearings, Fuel System, Exhaust System, MacPherson Strut, Constant Velocity Joints.

Table with 3 columns: No., Item, Ref #. Rows include Trailer Hitch, Aux Equipment.

Table with 3 columns: No., Item, Ref #. Rows include Front and Rear Disc Brakes, Front Brake Drums, Rear Brake Drums, Front Brake Lining, Rear Brake Lining, Wheel Cylinders, Mechanical Components.

Table with 3 columns: No., Item, Ref #. Rows include Hood and Safety Catch, Wiring and Battery, Vacuum/Hydraulic System, Brake Master Cylinder, Power Steering.

Table with 3 columns: No., Item, Ref #. Row includes All applicable items identified by the National Safety Code Standard 11 B.

Table with 3 columns: No., Item, Ref #. Rows include Tire Tread Depth measurements for Axle 1 and Axle 2 on Front and Rear.

Table with 3 columns: No., Item, Ref #. Rows include Brake Lining Thickness measurements for Axle 1 and Axle 2 on Front and Rear.

Table with 3 columns: No., Item, Ref #. Rows include Drum/Rotor Measurement for Axle 1 and Axle 2 on Front and Rear.

Table with 3 columns: No., Item, Ref #. Rows include Drum/Rotor Discard Limit for Front and Rear.

DEFECTS: x49 sec 2.5 B) Trailing arm bushings
x07 sec 8.9 a) Driver wiper, rear wiper.

REMARKS:

To determine if this vehicle has an open safety recall issued by the vehicle manufacturer, please search the Motor Vehicle Safety Recalls database on Transport Canada's website at http://www.tc.gc.ca/ or contact Transport Canada at 1-800-333-0510.

- THIS INSPECTION IS NOT A WARRANTY -
I am aware that this vehicle is unsafe and that this inspection addresses Standards of Safety and repair as prescribed by the Vehicle Equipment and Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.
Signature: Date: