03967855 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba

Vehicle Standards and I
Box 45064 Regent Postal
Winnipeg, MB. R2C 5C7
1-204-985-0920

Manitoba

A944806

Date Inspection Started: 15 / 05 / 26 (DAY / MO / YR)

Date Inspection Completed: 18 / 05 / 26 (DAY / MO / YR)

Inspection Expiry Date: 31 / 05 / 27 (DAY / MO / YR)

Station Number: A5287 Station Name: Frontline Auto City: Headingly

Mechanic Number: M03916 Mechanic Signature: [signature] Station Phone Number: 2048694106

Vehicle Owner: Jasmin Bakija

Address: City: Province: Postal Code: Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: CPY057 Prov.: MB NSC #: 2018573 Odometer Reading: 1327136 Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 4V4NC9EHXKN202659 Make: VOLVO Model: VNL Year: 19 Unit #: 325

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS ☒Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X	X	**Section 2 Suspension:** Defects (if any) SB #3 Rt AirBag leaking
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type 14A) #2 Rt Brake chamber leaking 15C) #2+#3 Axle shoes Beyond spec
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) 14 licence plate light inoperative
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C (D) E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	3/4	3/4	1.75	1.75		
2	27/32	27/32	16.561	16.566	1.50	1.50
3	27/32	27/32	16.549	16.569	1.50	1.50
4						
5						
	Final Measurement					

Axle	Tread Depth /32 Initial L		Initial R		Corrected L		Corrected R		Air Pressure Initial L		Initial R		Corrected L		Corrected R	
1	[illegible]	19	19	[illegible]	[illegible]					110	110	[illegible]	[illegible]			[illegible]
2	15	18	16	16					95	95	95	95				
3	15	14	13	17					95	95	95	95				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not [illegible] these [illegible] time.