03974612 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba T03-1

Vehicle Standards and Inspection, Box 48054 Regent Postal Outlet, Winnipeg, MB, R2C 5C7, 1-204-985-0920

DECAL Manitoba A967121

Date Inspection Started	22 (DAY)	04 (MO.)	25 (YR.)
Date Inspection Completed	23 (DAY)	04 (MO.)	25 (YR.)
Inspection Expiry Date	30 (DAY)	04 (MO.)	26 (YR.)

Station Number: A010410 Station Name: Trimac Transport Ta Tra City:

Mechanic Number: M03516 Mechanic Signature: Station Phone Number:

Vehicle Owner: Northern Resource Trucking Limited Partnership

Address: 2945 Miller Ave City: Saskatoon Province: SK Postal Code: S7K 6P6 Phone:

☐ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: 12R686 Prov.: SK NSC #: SK001494A Odometer Reading: 795,682 Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 1XPCDP9X44D719817 Make: Pete Model: 567 Year: 2004 Unit #: 101691

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ____ KGS X Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section
X	X	Section 1 - Power Train: Defects (if any) Transmission Yoke nut loose PTO U-Joint worn out.
		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type: All R/H/S Brake Shoe Broken
X	X	Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any) Washer pump not working
X	X	Section 6 - Lamps: Defects (if any) R/H/S Front marker light N/W
X	X	Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any) Cab air filter plugged.
X	X	Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any) 5th wheel adjust / grease.

Brake Inspection Type: A B (C) D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	5/8	5/8			1 1/2	1 1/4
2	New	9/16			1 1/2	1 1/4
3	9/16	9/16				
4						
5						
	Final Measurement					

Tread Depth 32nds

Axle	Initial L	Initial R	Initial L	Initial R	Corrected L	Corrected R	Corrected L	Corrected R
1	14	13						
2	21 19	19	19					
3	12 14	10	10					
4								
5								

Air Pressure

Axle	Initial L	Initial R	Initial L	Initial R	Corrected L	Corrected R	Corrected L	Corrected R
1						110	110	
2					100	100	100	100
3					100	100	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: (2)

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

Ce document peut être obtenu en français sur demande.

FVB0022-01-(R-09/15)

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION