

0412995

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



T03-1

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2G 5C7
1-204-985-0920

Manitoba



C097861

Date Inspection Started DAY 11 MO. 03 YR. 21	Station Number A101011	Station Name N.H. TRUCKING	City WINNIPEG
Date Inspection Completed DAY 11 MO. 03 YR. 21	Mechanic Number 1110111	Mechanic Signature [Signature]	Station Phone Number 204-388-4509
Inspection Expiry Date DAY 21 MO. 03 YR. 21	Vehicle Owner GUNNLAUGSON SPRAY ON		
	Address 2160 WILKES AVE WINNIPEG MB R3S 1A7		
	City Province Postal Code Phone		
☒ Pass/Safe Vehicle	Licence Number CWRTH40	Prov. MB	NSC #
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 1EDWHEH-63KDEAD321	Make FORD	Model E450
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle	Odometer Reading 181,357	Odom. Type ☒ km ☐ mi
		Year 2019	Unit # 4

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ GWSR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
✓		Section 1 - Power Train: Defects (if any)																																																																							
✓		Section 2 Suspension: Defects (if any)																																																																							
✓		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining (mm)</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>10</td> <td>1.575</td> <td>1.569</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>10</td> <td>10</td> <td>1.625</td> <td>1.632</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining (mm)		Drum/Rotor		Stroke		L	R	L	R	L	R	1	10	10	1.575	1.569			2	10	10	1.625	1.632			3							4							5							Final Measurement																						
Axle	Lining (mm)			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	10	10	1.575	1.569																																																																					
2	10	10	1.625	1.632																																																																					
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 7. WIPERS TOO SMALL 1. FIRE EXTINGUISHER																																																																							
✓		Section 6 - Lamps: Defects (if any)																																																																							
✓		Section 7 - Electrical System: Defects (if any)																																																																							
X	X	Section 8 - Body: Defects (if any) 21. RIGHT REAR BUMPER MOUNT CRACKED.																																																																							
✓	X	Section 9 - Tire & Wheel: Defects (if any) 6. WHEEL BEARING PLAY																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7</td> <td>6</td> <td></td> <td></td> <td>80</td> <td>80</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>5</td> <td>4</td> <td>10</td> <td>10</td> <td>80</td> <td>80</td> <td>80</td> <td>80</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	7	6			80	80			2	5	4	10	10	80	80	80	80	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	7	6			80	80																																																																			
2	5	4	10	10	80	80	80	80																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: ADVISE - 2 STONE CHIPS IN WINDSHIELD UNDER 13MM
ADVISE - #2L TIRES LOW TREAD BUT PASS AT THIS TIME

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: