



Vehicle Standards and Inspection

## Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A332673

Station #: 72049

Station Name: Mac D Services Ltd.

Technician #: 89173

Technician Name: Braden Mack

Signing Officer #: 90935

Signing Officer Name: Kami Brooks

### Customer Details:

Name: Simplot Grower Solutions

Address: Highway #31, Plenty, Saskatchewan, S0L2R0

Inspection Completed Date: 04Jun2026

Inspection Expiry Date: 31Dec2026

### Vehicle Details:

VIN: 1FUJA6CV74PM54957

Odometer Reading: 1329846 km

Year: 2004

Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE

Plate: 823IGV

Jurisdiction: Saskatchewan

Unit: 314

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 72049

Station Name: Mac D Services Ltd.

Technician #: 89173

Technician Name: Braden Mack

Signing Officer #: 90935

Signing Officer Name: Kami Brooks

**Customer Details:**

Name: Simplot Grower Solutions

Address: Highway #31, Plenty, Saskatchewan, S0L2R0

**Vehicle Details:**

VIN: 1FUJA6CV74PM54957

Odometer Reading: 1329846 km

Year: 2004

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	Both Windshields
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
		x		Clutch/Clutch Pedal (1)	Adjustment is needed

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	Right Front Signal Amber
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
		x		Trailer Hitch (10)	5th Wheel Adjustment
x				Cab Grab Handles/Steps (8)	
		x		Attached Equipment (8)	Left Step on Frame Rail Lower Gate Loose
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
			x	Mud Flaps/Fenders (8)	Right Front Inner Fender Cracked
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
		x		Air Suspended Cab (8)	Cab Air Bags Weathered
x				Cab Mounts (8)	
		x		Drive Belts (1)	Belts Cracking

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	Right Rear Inside Flat
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
			x	Suspension/Axles (2)	Right Rear Drive Bushing Close
		x		Drive Shaft/Universal Joints (1)	Rear Diff Input U-Joint
x				Exhaust/Emission System (1)	

### Brake/Tire Measurements

#### Axle 1-Pass

---

Wheel1-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 in

#### Axle 2-Pass

---

Wheel1 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 14 in

Brake(1): No Brake

N/A

#### Axle 3-Pass

---

Wheel1 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Cam Rotation: 20 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55.0 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A332673

Inspection Completed Date: 04Jun2026