04076130 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE** Manitoba

Vehicle Safety
Box 45064 Regent Postal O.
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C078491

Date Inspection Started	23 (DAY)	03 (MO.)	26 (YR.)	Station Number	1435
Date Inspection Completed	23 (DAY)	03 (MO.)	26 (YR.)	Mechanic Number	1741
Inspection Expiry Date	31 (DAY)	03 (MO.)	27 (YR.)		

Station Name: Wolverine Lx 200. City: Ste
Mechanic Signature: Station Phone Number: 204 325 4966.

Vehicle Owner: ESKIMO FARMS LTD.
Address: 1852N Wood Mills MB Province: R0C 1T0 Postal Code: Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: 1H1653/13 Prov. MB NSC #: Odometer Reading: Odom. Type ☐ km ☐ mi

Vehicle Identification Number: 1TDH430261511017295 Make: Timpte Model: Hopper Year: 1961 Unit #: —

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ___ KGS ___Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H (3A) Circle Brake Type. Defects (if any)
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 6-A Front sides Rails Cracked. 6-C: 1 Crossmember Rusted Through By landing Gear.
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	13/16	11/16	16.55	16.58	1½	1½
2	5/8	3/4	16.57	16.56	1½	1½
3						
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Initial R		Corrected L		Corrected R		Air Pressure Initial L		Initial R		Corrected L		Corrected R	
1	8	8	9	9					100	100	100	100				
2	6	5	5	5					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

FVS0003-01 (R-06/25) Ce document peut être obtenu en français sur demande

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION