04026858

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
Manitoba
C025484

Date Inspection Started	01 DAY	05 MO.	16 YR.	Station Number A5T1161	Station Name SASKATOON B X 3 LIBAU MB City
Date Inspection Completed	04 DAY	05 MO.	16 YR.	Mechanic Number M5T4716	Mechanic Signature 2047662394 Station Phone Number
Inspection Expiry Date	31 DAY	05 MO.	17 YR.		

Vehicle Owner: STRADA Recycling Inc.
Address: 6 Prairie Place City: St. Andrews Province: MB. Postal Code: Phone:

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: | Prov. MB. NSC #: | Odometer Reading: | Odom. Type ☐ km ☐ mi

Vehicle Identification Number: 1T1SWRT1098 Make: West Trail Model: Tarbo Year: 78 Unit #: 5717

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
		Section 2 Suspension: Defects (if any) Replace Equalizer Hanger Lhs.
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type — Left Front Brake Pot
X	X	**Section 4 - Steering:** Defects (if any)
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	34	34	16545	16558	134	134
2	34	34	16550	16555	134	134
3						
4						
5						
	Final Measurement					

Tread Depth 32 — Air Pressure 100

Axle	Initial L		Initial R		Corrected L		Corrected R		Initial L		Initial R		Corrected L		Corrected R	
1	14	16	9	14					100	100	100	100				
2	11	10	11	17					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE