04082708

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

T04-13

Manitoba C072565

Date Inspection Started	28 DAY	10 MO.	26 YR.
Date Inspection Completed	29 DAY	10 MO.	26 YR.
Inspection Expiry Date	31 DAY	10 MO.	27 YR.

Station Number: A010611 — Station Name: FORT TRANSPORT STAN — City
Mechanic Number: M5993 — Mechanic Signature — Station Phone Number: 204-785-9357

Vehicle Owner: STRADA RECYCLING INC

Address — City — Province — Postal Code — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: CPV843 — Prov.: MB — NSC #: MB1508393 — Odometer Reading: 251981 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 1GDL7S1EX3F515013 — Make: GMC — Model: 7500 — Year: 2003 — Unit #:

[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

X Truck — GVWR 99779 KGS — ___Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
V		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
Y		**Section 3 - Brake Systems:** (3H) 3A — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X	X	**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any) 8-A- BLOWER MOTOR NOT WORKING
X	X	**Section 6 - Lamps:** Defects (if any) 1-C- RIGHT TAIL LIGHT OUT
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	.629	.629	1.549	1.546		
2	.557	.557	1.548	1.545		
3						
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		16	16							95	95					
2	24	24	24	24					90	80	90	90		90		
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE