03993161

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

T04-2

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL NUMBER

Manitoba

A980204

Date Inspection Started	11 DAY	02 MO.	26 YR.
Date Inspection Completed	17 DAY	02 MO.	26 YR.
Inspection Expiry Date	28 DAY	02 MO.	27 YR.

Station Number: A0101611 — Station Name: LOFT TRANSPORT — City: STAE

Mechanic Number: M59193 — Mechanic Signature: C Dulf — Station Phone Number: 204-785-9357

Vehicle Owner: STRADA RECYCLING

Address — City — Province — Postal Code — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number — Prov. — NSC # — Odometer Reading — Odom. Type [ ] km [ ] mi

Vehicle Identification Number: 1FDWF37F163EA60579 — Make: FORD — Model: F350 — Year: 2009 — Unit #

[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

[X] Truck — GVWR — KGS — [ ] Truck Tractor — [ ] Trailer — [ ] Semi-Trailer — [ ] Bus — [ ] School Bus — [ ] Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	**Section 1 - Power Train:** Defects (if any) 3-A-CHECK ENGINE LAMP ON
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** (3H) 3A — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) 1-K-REVERSE LAMP/BACK UP ALARM NOT WORKING
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 4-A-A2 LEFT OUTER + A2 RIGHT OUTER LOW; A3 LEFT OUTER + A3 LEFT INNER LOW PRESSURE
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	3/8	3/8	1.494	1.481		
2	9/16	9/16	1.153	1.157		
3						
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		16	14							60	60					
2	8	9	7	14					30	50	50	40		50		50
3									20	50	30	50		50	50	
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE