04076137 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE** Manitoba

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C078498

Date Inspection Started	25 (DAY)	03 (MO.)	26 (YR.)	Station Number	415135
Date Inspection Completed	25 (DAY)	03 (MO.)	26 (YR.)	Mechanic Number	117741
Inspection Expiry Date	31 (DAY)	03 (MO.)	21 (YR.)		

Station Name: Wilderness Ford 2007 LTD
City: 204 325 4966
Mechanic Signature:
Station Phone Number:

Vehicle Owner: S/S KAMP FARMS INC.
Address: K182N
City: Lockhart MB
Province:
Postal Code: ROCITO
Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TL2626 Prov. MB NSC #: Odometer Reading: Odom. Type ☐ km ☐ mi

Vehicle Identification Number: 1JDH430225B107038 Make: Ford Model: Cooper Year: 2007 Unit #: 202

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ___ KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H 3A (Circle Brake Type) Defects (if any)
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) 6-A front side rails fail. 6-C crossmember in front of landing gear cracked
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	13/16	13/16	16.51	16.52	1 3/4	1 3/4
2	9/16	13/16	16.53	16.52	1 3/4	1 3/4
3						
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	6	7	6	6					100	100	100	100				
2	6	6	6	6					110	100	110	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature **Date:** _____

FVS0003-01 (R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED NOT FOR REGISTRATION