04082597

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba C026205

Date Inspection Started: 16 (DAY) 07 (MO.) 26 (YR.)
Date Inspection Completed: 16 (DAY) 07 (MO.) 26 (YR.)
Inspection Expiry Date: 31 (DAY) 07 (MO.) 27 (YR.)

Station Number: A010161 Station Name: FORT TRANSPORT ST. ANNE City:
Mechanic Number: M519193 Mechanic Signature: C. Duff 204-785-9357 Station Phone Number

Vehicle Owner: STRADA RECYCLING
Address: City: Province: Postal Code: Phone:

[X] Pass/Safe Vehicle
[ ] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: TC16195 Prov.: MB NSC #: Odometer Reading: Odom. Type [ ] km [ ] mi
Vehicle Identification Number: C9101410313K1A0168101031 Make: ATLAS Model: ROLL OFF Year: 1989 Unit #:
[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor ____Trailer _X_Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type. Defects (if any)
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	9/16	5/8	16.595	16.582	1.5	1.5
2	9/16	11/16	16.534	16.567	1.5	1.5
3	11/16	1/2	16.586	16.551	1.5	1.5
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Initial R		Tread Depth Corrected L		Corrected R		Air Pressure Initial L		Initial R		Corrected L		Corrected R	
1	7	6	4	6					90	90	90	90	100	100	100	100
2	16	16	11	12					90	90	80	75	100	100	100	100
3	11	14	16	16					90	90	90	90	100	100	100	100
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: REWRITE DUE TO INCORRECT EXPIRY YEAR

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-06/25)

PRESENT THIS COPY WHEN REGISTERING VEHICLE