



Commercial Vehicle Inspection Report

Decal Number: GK52553
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21475796

Inspection Result:
PASS

FACILITY: RJAMES WESTERN STAR / S7341 INSP. TYPE: Complete INSP. START: 2025-Aug-20 01:52 PM PDT
INSPECTOR: BELANGER, DOUGLAS STEFAN / 300675 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Aug-27 03:52 PM PDT
WORK ORDER #: KEL016983 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 01956902 VIN: 1HTWLADR74J089813
PLATE #: MC0275 UNIT/FLEET#: D4U04 OWNER/LESSEE NAME: DIGG'N 4U CONTRACTING LTD.,
DIGG'N 4U CONTRACTING LTD.
LICENCED GVW(kg): 17500 BODY STYLE: Dump Truck ADDRESS: 11815 OKANAGAN CENTER ROAD
EAST
Winfield, British Columbia
VEHICLE YEAR: 2004 ODOMETER: 328177 KM V4V1G3, Canada
MAKE: INTERNATNA HUB ODOMETER:
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	CUSTOMER REPAIRED LEFT REAR SIGNAL AND LEFT LOW BEAM INOP
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed with Caution	FRAME HAS RUST JACKING OVER 10MM. CUSTOMER REPAIRED BROKEN REAR TANK STRAP
Section 9A - Tires	Passed	CUSTOMER REPLACED RIGHT DRIVE TIRES
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	31.8	31.8	13			15	✓
2	Clamp	30	Automatic	31.8	31.8	6	10	11	5	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	35
2	30	20

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: BELANGER, DOUGLAS STEFAN Signature:

This Inspection Report was submitted to CVSE on 2025-Aug-27 03:55 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSED014

8/27/2025 3:55:14 PM PDT