

## Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GK52567 2026-Mar-31 21486218 Inspection Result:

2025-Sep-04 04:20 AM PDT INSP. START: FACILITY: RJAMES WESTERN STAR / S7341 INSP. TYPE: Complete 2025-Sep-05 09:09 AM PDT INSP. COMPLETE: Class 2 - Heavy Vehicle with LGVW INSPECTOR: KUNZ, TRENT ANTHONY / 111471 INSP. CLASS: 5501 kg or more KEL016964 WORK ORDER #: INSP. REASON: Semi-annual 1HTWLAZR65J003935 02609034 VIN: VEHICLE JUR: British Columbia REGI: DIGG'N 4U CONTRACTING LTD.. OWNER/LESSEE NAME: HY1532 UNIT/FLEET#: PLATE #: DIGG'N 4U CONTRACTING LTD. 11815 OKANAGAN CENTER RD EAST ADDRESS: BODY STYLE: **Dump Truck** LICENCED GVW(kg): 17500 Winfield, British Columbia ODOMETER: 337906 KM VEHICLE YEAR: 2005 V4V1G3, Canada HUB ODOMETER: MAKE: INTERNATNA BRAKE TYPE: MODEL: Air FUEL TYPE Vehicle Identification (VIN) Passed Passed Section 1 - Power Train Section 2 - Suspension Passed Section 3 - Brake System Passed Section 3A - Air Brakes Passed Section 3H - Hydraulic Brakes Not Applicable POWER STEERING BOX INPUT SHAFT LEAKING. Section 4 - Steering Repaired (same day) Section 5 - Instruments and Auxiliary Equipment Repaired (same day) LICENSE PLATE LIGHT. Section 6 - Lamps Section 7 - Electrical System Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	45	42	12			12	-
2	Clamp	30	Automatic	50	45	10	10	10	10	
Comment:						Comment:				
Air Brake Cam	shaft Rotatio	on (degrees)	Ві	rake Lining/F	Pad (mm)		Ro	otor Thickness or	Drum Inside Diame	eter (mm)
Avlac	1.5	off	Dight	Linin	a/Dad	Loft	Dight	Potor/Drum	loft	Dight

BOX LIFT CYLINDER WAS LEAKING.

Axies	Len	Right	Lining/Pad	Lett	Right	KOLOT/Drum	Leit	Right
1	80	45	Lining (Shoe)	12	18	Drum		
2	45	45	Lining (Shoe)	18	18	Drum		
Comment: Comment:						<b>Comment:</b> Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested?
Inspector: KUNZ, TRENT ANTHONY

Section 11 - Other Vehicle Components

Road Test Date: Signature:

Repaired (same day)

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-05 09:12 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAIP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/5/2025 9:12:43 AM PDT