



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	31000 kg	Brake Type:	Air
Owner Name:	FLUIDPRO OILFIELD SERVICES LTD		
Address:	9701 99 STREET		
City:	CLAIRMONT	Province:	AB
		Postal Code:	T8X 5A8
Telephone Number:	(780) 533-3338		
Vehicle Identification Number:	2H9DF9HG3DT002385		
Make:	Hutchinson	Model:	Tank
Year:	2013	Unit Number:	SB08A
Odometer:	KM	Licence Plate Number:	5XW749
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fluidpro Oilfield Services Ltd.	18788
Inspection Technician Name:	Technician Number:
Terrance Hammerschmidt	D2522
Inspection Technician Signature:	
Inspection Date:	2025/05/13

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train						
Component	P	F	NA	Component	P	F NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*		✓

NOTES:

APPENDIX "A"						
Component	P	F	NA	Component	P	F NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System		✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓			

NOTES:

Section 2 - Suspension						
Component	P	F	NA	Component	P	F NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓	
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle		✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓	
2.4. Spring & Spring Attachment			✓			

NOTES:

Section 3H - Hydraulic Brakes						
Component	P	F	NA	Component	P	F NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System		✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components		✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components		✓
3H.8. Vacuum System			✓	3H.19. Brake Performance		✓
3H.9. Air-Boosted Trailer Brake System			✓			

NOTES:

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	F NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓	
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)		✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components		✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓	
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)		✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓	
3A.15. Drum Brake System Components	✓					

NOTES:

ABS LIGHT ON-REPLACED FAULTY SENSOR

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle		✓
4.4. Kingpin			✓			

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION **TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

Section 5 - Instruments and Auxiliary Equipment						
Component	P	F	NA	Component	P	F NA
5.1. Fire Extinguisher	☒					

NOTES:
 EXPIRED-- REPLACED

Section 6 - Lamps						
Component	P	F	NA	Component	P	F NA
6.1. Required Lamps	☒			6.3. Retro-Reflective Marking	☒	
6.2. Reflex Reflector	☒					

NOTES:
 LED LESS THAN 50%-- REPLACED FAULTY LED LIGHTS

Section 7 - Electrical System						
Component	P	F	NA	Component	P	F NA
7.1. Wiring	☒			7.3. Trailer Cord (output to towed vehicle)	☒	
7.2. Battery	☒					

NOTES:

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
8.5. Cargo Body	☒			8.11. Refrigeration/Heater Unit Fuel System		☒
8.6. Frame Rails & Mounts	☒			8.21. Fender/Mud Flap	☒	
8.7. Utilized Body Elements	☒			8.22. Landing Gear on Trailer	☒	
8.8. Cab or Cargo Door	☒			8.23. Sliding Axle Assembly (Sliding Bogie)		☒
8.9. Cargo Tank or Vessel	☒			8.24. Aerodynamic Device & Attachment		☒
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	☒			8.25. Rear Impact Guard (RIG)	☒	

NOTES:

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tire Tread Depth	☒			9.7. Wheel/Rim	☒	
9.2. Tire Tread Condition	☒			9.8. Multi-Piece Wheel/Rim		☒
9.3. Tire Sidewall & Manufacturer Markings	☒			9.9. Spoke Wheel/Demountable Rim System		☒
9.4. Tire Inflation Pressure	☒			9.10. Disc Wheel System	☒	
9.5. Wheel Hub	☒			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	☒	
9.6. Wheel Bearing	☒					

NOTES:
 TIRES ARE WORN-- REPLACED AS NEEDED

Section 10 - Couplers and Hitches						
Component	P	F	NA	Component	P	F NA
10.1. Hitch Assembly, Structure & Attaching Components	☒			10.6. Automated Coupling Device		☒
10.2. Secondary Attachment (Safety Chain or Cable)			☒	10.7. Fifth Wheel Coupler		☒
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	☒			10.8. Oscillating Fifth Wheel Coupler	☒	
10.4. Ball Type Hitch			☒	10.9. Ball-Bearing Type Turntable on Trailer		☒
10.5. Roll-Coupling Hitch			☒			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

5TH WHEEL OSCILLATING NEEDS SHIMMING--PULLED; CLEANED SHIM & TESTED

Certification:

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8532326) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/05/13	D2522	18788	

Customer Acknowledgment:

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/05/13

Customer Signature