

03912972

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

66-15

Vehicle Standards and Inspection
Reg. 405.2 Reg. 405.3
Winnipeg, MB R3C 5C7
1-800-955-0000

Manitoba

A916005

Date Inspection Started: 018 012 215
Date Inspection Completed: 017 012 215
Inspection Expiry Date: 218 012 216

Station Number: A16121511 The Shop Truck and Trailer Rep
Mechanic Number: M518138
Vehicle Owner: Shortline Moving Solutions Inc
Address: 862 Dufferin Avenue City: Wpg Province: MB Postal Code: Phone: 204-694-1223

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: C4R8111 Prov: MB NSC #: MB140436 Odometer Reading: 160,721 Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 4ADL6C14E1A5F5111555 Make: GMC Model: CUBE Year: 2005 Unit #: C3

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

☒ Section 1 - Power Train: Defects (if any): X-1-10-AA Drive belt

☒ Section 2 Suspension: Defects (if any): X-2-7-CC Both front shocks

☒ Section 3 - Brake Systems: (3H) 3A
Defects (if any): Circle Brake Type
X-3H-13-8B Rear rotors
X-3H-13-FF Rear brake pads
X-3H-17-AA ABS light on
X-3H-17-EE RR speed sensor

☒ Section 4 - Steering: Defects (if any):

☒ Section 5 - Instruments & Auxiliary Equipment: Defects (if any):

☒ Section 6 - Lamps: Defects (if any):

☒ Section 7 - Electrical System: Defects (if any):

☒ Section 8 - Body: Defects (if any):

☒ Section 9 - Tire & Wheel: Defects (if any):

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	162.55	162.50	39.55	39.43		
2	5.000	5.000	40.03	40.03		
3						
4						
5						

Final Measurement

Tread Depth 32 Air Pressure PSI

Axle	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	16	16			90	90		
2	9	9	11	8	90	90	90	90
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any):

THIS INSPECTION IS NOT A WARRANTY.
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: wheels must be retorgued after 150 km

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection retester has re-inspected the vehicle. Operating a vehicle with a hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date:

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.