

T08-11



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10744
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21364135

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
N5398
INSPECTOR: TETACHUK, ALEXANDER / 201668
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2025-May-23 03:30 PM MST
INSP. COMPLETE: 2025-May-23 04:30 PM MST

VEHICLE JUR: British Columbia
PLATE #: 11822K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2013
MAKE: DOEPKER
MODEL:

REGI: 10611434
UNIT/FLEET#: 226
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2DELGZFZ31D1029783
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES, INC
ADDRESS: BOX 45
Moberly Lake, British Columbia
V0C1X0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) CUT BOTTOM STAKE OFF DAMAGED
Section 9A - Tires	Repaired (same day) REPLACE AXLE 2R TIRE
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	34
2	Clamp	30	Automatic	32	35
3	Clamp	30	Automatic	37	35

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	14	13	13	13	
2	10	10	14	14	
3	12	12	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	23	27
2	25	32
3	35	42

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	20	20
2	Lining (Shoe)	20	19
3	Lining (Shoe)	19	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:
Inspector: TETACHUK, ALEXANDER Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-26 09:55 AM MST

The Inspector's signature above is confirmation that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Co-Manager, ISOVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/26/2025 9:55:09 AM MST