T0816

BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10741
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21364099

Inspection Result: **PASS**

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	INSP. TYPE:	Complete	INSP. START:	2025-May-23 12:30 PM MST
INSPECTOR:	TETACHUK, ALEXANDER / 201668	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-May-23 01:30 PM MST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REG#:	12738059	VIN:	2DELGFM34J4038009
PLATE #:	90574J	UNIT/FLEET#:	199	OWNER/LESSEE NAME:	4 EVERGREEN RESOURCES, INC
LICENCED GVW(kg):	0	BODY STYLE:	LOGGING TRAILER	ADDRESS:	BOX 45
VEHICLE YEAR:	2018	ODOMETER:			Moberly Lake, British Columbia
MAKE:	DOEPKER	HUB ODOMETER:			V0C1X0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Repaired (same day)	AXLE 3 LINING BOTH SIDES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	30
2	Clamp	30	Automatic	29	27
3	Clamp	30	Automatic	30	31

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	10	9	10	
9	9	10	10	
12	12	12	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	81	76
2	69	71
3	96	103

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	13	14
Lining (Shoe)	10	9

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: TETACHUK, ALEXANDER Signature:

This Inspection Report was submitted to CVSE on 2025-May-26 09:41 AM MST
The inspector's signature above is confirmation that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on the forms is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0011

5/26/2025 9:41:49 AM MST