

108-3



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10787
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21371765

Inspection Result:
PASS

FACILITY:	NORTHERN B.C. TRUCKERS' / NS398	INSP. TYPE:	Complete	INSP. START:	2025-May-29 02:45 PM MST
INSPECTOR:	TETACHUK, ALEXANDER / 201658	INSP. CLASS:	Class 2 - Heavy Vehicle with L.G.W. 5501 kg or more	INSP. COMPLETE:	2025-May-29 03:45 PM MST
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13147574	VIN:	5KJRALD16LPKT6949
PLATE #:	RT6701	UNIT/FLEET#:	192	OWNER/LESSEE NAME:	4 EVERGREEN RESOURCES INC., N/A
LICENCED GVW(kg):	55300	BODY STYLE:	Truck Tractor	ADDRESS:	BOX 45
VEHICLE YEAR:	2020	ODOMETER:	426901 KM		Moberly Lake, British Columbia
MAKE:	WESTERN ST	HUB ODOMETER:			VOC1X0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) BOTH FRT BRAKE HOSES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	29	31
2	Clamp	30	Automatic	34	32
3	Clamp	30	Automatic	30	30
4	Clamp	30	Automatic	34	31

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
16			15	✓
9	9	7	7	
8	7	7	9	
10	10	8	8	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVP at the Commercial Vehicle Safety Enforcement.

CVSD014

202020 13:23 PM MST



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10787
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21371765

Inspection Result:

PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	48	42	Lining (Shoe)	18	18	Drum		
2	35	27	Lining (Shoe)	19	20	Drum		
3	51	46	Lining (Shoe)	18	18	Drum		
4	35	42	Lining (Shoe)	19	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: TETACHUK, ALEXANDER

Signature:

[Signature] Tester:

This Inspection Report was submitted to CVSE on 2025-May-30 01:37 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. registering carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, INSNP at the Commercial Vehicle Safety Enforcement.

CVSE0314

6/30/2025 1:37:23 PM MST