

Commercial Vehicle Inspection Report

Docal Number: PY08778
Docal Expiry Date: 2026-Mar-31
Inspection Number: 21494782

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
N5398
INSPECTOR: COX, JAMES EDWARD / 110895
WORK ORDER #:

INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSR. REASON: Semi-annual

INSR. START: 2025-Sep-12 11:05 AM MST
INSR. COMPLETE: 2025-Sep-12 12:05 PM MST

VEHICLE JUR: British Columbia
PLATE #: S18017
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2019
MAKE: WESTERN ST
MODEL:

REGI: 12879000
UNIT/FLEET#: 190
BODY STYLE: Logging Truck
ODOMETER: 393654 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 5KJRALD1XKPLH9087
OWNER/LESSEE NAME: 4 EVERGREEN RESOURCES INC.,
BOX 45
ADDRESS: Moberly Lake, British Columbia
V0C1X0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Lic plate lamp
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.
1	Clamp	24	Automatic
2	Clamp	30L	Automatic
3	Clamp	30L	Automatic
4	Clamp	30L	Automatic

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14			14	
22	22	22	22	
21	21	21	21	
21	21	21	20	


Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSD014

9/12/2025 12:06:10 PM LST



Commercial Vehicle Inspection Report

Decal Number: PY08778
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21494782

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axis	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	24	22	Lining (Shoe)	20	20	Drum		
2	80	92	Lining (Shoe)	13	11	Drum		
3	48	46	Lining (Shoe)	18	18	Drum		
4	62	70	Lining (Shoe)	16	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: COX, JAMES EDWARD Signature:

This Inspection Report was submitted to CVSE on 2025-Sep-12 12:06 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE014

9/12/2025 12:06:16 PM MST