Commercial Vehicle Inspection Report

Decal Number: GP86958
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21967093

Inspection Result: **PASS**

FACILITY:	STARLIGHT TRUCK REPAIR / S12430	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Oct-21 09:00 AM -07
INSPECTOR:	Walter, Reuben Jason / 200998	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Oct-21 11:00 AM -07
WORK ORDER #:	8631	**INSP. REASON:**	Semi-annual		

T09-1

VEHICLE JUR:	British Columbia	**REGI:**	02147901	**VIN:**	1XKDD40X54R975240
PLATE #:	JB5024	**UNIT/FLEET#:**	116	**OWNER/LESSEE NAME:**	Tidy Trucking Ltd, .
LICENCED GVW(kg):	46500	**BODY STYLE:**	Truck Tractor	**ADDRESS:**	Box 6767
VEHICLE YEAR:	2004	**ODOMETER:**	234177 KM		Fort St John, British Columbia
MAKE:	KENWORTH	**HUB ODOMETER:**			V1J 4J2, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	**Repaired (same day)**	Rear engine mounts
Section 2 - Suspension	**Repaired (same day)**	Axle 2 upper control arm bushings
Section 3 - Brake System	**Repaired (same day)**	Axle 2 brake hoses / axle 3 left brake hoses
Section 3A - Air Brakes	**Repaired (same day)**	Axle 2 brake chambers
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	Windshield
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm) / **Tire Tread Depth (mm)**

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	32	31	11			11	✔
2	Clamp	30	Automatic	35	36	16	15	16	16	
3	Clamp	30	Automatic	36	36	17	17	17	18	

Comment: **Comment:**

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	58	59
2	62	65
3	64	68

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	14
Lining (Shoe)	17	18
Lining (Shoe)	15	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: Walter, Reuben Jason **Signature:**

This Inspection Report was submitted to CVSE on 2026-Oct-25 09:56 PM -07
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014
10/25/2026 9:57:02 PM -07