

 RITCHIE BROS. Auctioneers**2022 International HX****Test Information**

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X3u21D1500F00000*80316854*0000000000
VIN	3HSPAAPT8NN305303
Driveline	Class 8 6x4
Body	Truck-Tractor
Test Time	Sept. 5, 2025, 4:02 p.m.
File Length	42.547 s

Usage

Label	Value	Units
Engine Odometer	293,249	mi
Odometer (Instrument Cluster #1)	293,166	mi
Engine Total Hours of Operation	8,809.5	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	84	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Transmission #1	Transmission Clutch Actuator	Not Responding Properly	1
Previous	Transmission #1	Manufacturer Assignable SPN	Voltage Below Normal	7
Previous	Transmission #1	Battery Potential / Power Input	Special Instruction	1
Previous	Shift Console - Primary	Source Address 0	Abnormal Update Rate	1
Previous	Shift Console - Primary	Source Address 3	Abnormal Update Rate	39
Previous	Passenger-Operator Climate Control #1	Manufacturer Assignable SPN	Voltage Above Normal	4
Previous	Body Controller	Source Address 58	Abnormal Update Rate	2
Previous	Body Controller	Source Address 3	Abnormal Update Rate	4
Previous	Body Controller	Kneeling Control Mode Request	Erratic, Intermittent, or Incorrect	7
Previous	Communications Unit, Radio	Source Address 0	Abnormal Update Rate	126
Previous	Communications Unit, Radio	Source Address 33	Abnormal Update Rate	40
Previous	Communications Unit, Radio	Source Address 55	Abnormal Update Rate	48
Previous	Communications Unit, Radio	Manufacturer Assignable SPN	Current Above Normal	8
Previous	Cab Display #2	Source Address 0	Abnormal Update Rate	1
Previous	Proprietary	Source Address 0	Abnormal Update Rate	126
Previous	Proprietary	Source Address 0	Abnormal Update Rate	126
Previous	Proprietary	Source Address 0	Abnormal Update Rate	126
Previous	Proprietary	Manufacturer Assignable SPN	Failure	1