



2019 International LT

Test Information

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X1u17D1500000000*80111091*0000000000
VIN	3HSDZAPR1KN415329
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Aug. 21, 2025, 12:18 p.m.
File Length	42.202 s

Usage

Label	Value	Units
Engine Odometer	438,454	mi
Odometer (Instrument Cluster #1)	438,251	mi
Engine Total Hours of Operation	11,303.4	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	22	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

DM	Controller Name	SPN Name	FMI Name	Count
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit 1	Voltage Above Normal	4
Previous	Transmission #1	Transmission Clutch 1 Temperature	High-most severe	1
Previous	Transmission #1	Transmission Air Tank Pressure	Low-most severe	1
Previous	Shift Console - Primary	Source Address 33	Abnormal Update Rate	1
Previous	Shift Console - Primary	Source Address 3	Abnormal Update Rate	2
Previous	Shift Console - Primary	Source Address 0	Abnormal Update Rate	2
Previous	Shift Console - Primary	Engine Retarder Selection	Out of Calibration	2
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Erratic, Intermittent, or Incorrect	127
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 2 Right	Low-most severe	1
Previous	Body Controller	Fifth Wheel Slider Lock Switch	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Source Address 153	Abnormal Update Rate	8
Previous	Body Controller	Source Address 152	Abnormal Update Rate	8
Previous	Body Controller	Engine Fan 1 Requested Percent Speed	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Disengage Differential Lock Request - Central Rear	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Kneeling Control Mode Request	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Unknown	High-most severe	29
Previous	Body Controller	Source Address 237	Abnormal Update Rate	8
Previous	Body Controller	ASR "Hill Holder" Switch	Erratic, Intermittent, or Incorrect	2
Previous	Lighting - Operator Controls	Manufacturer Assignable SPN (first entry)	Erratic, Intermittent, or Incorrect	9
Previous	Lighting - Operator Controls	Source Address 33	Abnormal Update Rate	4
Previous	Proprietary	Source Address 0	Abnormal Update Rate	126
Previous	Proprietary	Source Address 0	Abnormal Update Rate	126
Previous	Proprietary	Manufacturer Assignable SPN	Data Error	53
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit 1	Voltage Above Normal	4