

RITCHIE BROS. Diagnostic Report
 Auctioneers[®]

2020 Western Star Sleeper

Test Information

Engine	Detroit Diesel DD15 (14.8)
Engine Serial	DTDSC*472N16*472910S0658992
VIN	5KJJBHDR5LLLH6765
Driveline	Class 8 6x4
Body	Truck-Tractor
Test Time	Aug. 24, 2026, 8:10 a.m.
File Length	44.071 s

Usage

Label	Value	Units
Engine Odometer	16,681	mi
Odometer (Instrument Cluster #1)	554,775	mi
Engine Total Hours of Operation	16,476.65	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	95	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Engine #2	Engine Starter Motor Relay	Failure	33
Previous	Exhaust Emission Controller	Aftertreatment 1 SCR Conversion Efficiency	Low-least severe	5
Previous	Exhaust Emission Controller	Aftertreatment 1 Outlet NOx 1	Data Drifted High	8
Emissions Previous	Exhaust Emission Controller	Aftertreatment 1 SCR Conversion Efficiency	Low-least severe	5
Emissions Previous	Exhaust Emission Controller	Aftertreatment 1 Outlet NOx 1	Data Drifted High	8